Flow
Building our future, faster.

Central Brampton

Appendix C

Physical Environment

C1: Former OBR Environmental Site Assessment

C2: Geotechnical Desktop Study

C3: Contaminant Overview Study

AECOM

Peel Region

Flow
Building our future, faster.

Central Brampton

C1: Former OBR Environmental Site Assessment

AECOM

Peel Region

LIMITED PHASE II ENVIRONMENTAL SITE ASSESSMENT

FORMER ORANGEVILLE RAIL, MISSISSAUGA, BRAMPTON AND CALEDON, ONTARIO

REGION OF PEEL

PROJECT NO.: 211-10139-00
DATE: MAY 2022

WSP
2 INTERNATIONAL BOULEVARD, SUITE 201
TORONTO, ON
CANADA M9W 1A2

T: +1 416-798-0065

WSP.COM

WSP Canada Inc.

2 INTERNATIONAL BOULEVARD, SUITE 201
TORONTO, ON
CANADA M9W 1A2

T: +1 416-798-0065

WSP.COM

May 2, 2022

Mr. Ryan Grzesiak
REGION OF PEEL
10 Peel Centre Drive, Suite B
Brampton, Ontario
L6T 4B9

Subject: Limited Phase II Environmental Site Assessment
Former Orangeville Rail, Mississauga/Caledon/Brampton, Ontario
Project No.: 211-10139-00

WSP is pleased to present our finalized Limited Phase II Environmental Site Assessment report for the above-noted property. The report describes the interpreted environmental conditions at the property and addresses comments received by email on February 9 and March 4, 2022.

Thank you for the opportunity to provide our services.

Yours truly,



Christopher Johnston, M.A., P.Geo. (Limited), QP_{ESA}
Team Lead – Contaminated Lands, Toronto

WSP ref.: 211-10139-00

QUALITY MANAGEMENT

ISSUE/REVISION	FIRST ISSUE	REVISION 1	REVISION 2	REVISION 3
Remarks	Limited Phase II ESA	Limited Phase II ESA		
Date	January 17, 2022	April 29, 2022		
Prepared by	Joanna West	Joanna West		
Signature	DRAFT			
Authorised by	Christopher Johnston	Christopher Johnston		
Signature	DRAFT			
Project number	211-10139-00	211-10139-00		
Report number	01	02		
File reference	ORBY Limited Phase II ESA	ORBY Limited Phase II ESA		

SIGNATURES

PREPARED BY

Joanna West, GIT.
Environmental Technician

REVIEWED BY

Christopher Johnston, P.Geo. (Limited), QP$_{ESA}$
Team Lead – Contaminated Lands, Toronto



WSP Canada Inc. ("WSP") prepared this report solely for the use of the intended recipient, Region of Peel, in accordance with the professional services agreement between the parties. In the event a contract has not been executed, the parties agree that the WSP General Terms for Consultant shall govern their business relationship which was provided to you prior to the preparation of this report.

The report is intended to be used in its entirety. No excerpts may be taken to be representative of the findings in the assessment.

The conclusions presented in this report are based on work performed by trained, professional and technical staff, in accordance with their reasonable interpretation of current and accepted engineering and scientific practices at the time the work was performed.

The content and opinions contained in the present report are based on the observations and/or information available to WSP at the time of preparation, using investigation techniques and engineering analysis methods consistent with those ordinarily exercised by WSP and other engineering/scientific practitioners working under similar conditions, and subject to the same time, financial and physical constraints applicable to this project.

WSP disclaims any obligation to update this report if, after the date of this report, any conditions appear to differ significantly from those presented in this report; however, WSP reserves the right to amend or supplement this report based on additional information, documentation or evidence.

WSP makes no other representations whatsoever concerning the legal significance of its findings.

The intended recipient is solely responsible for the disclosure of any information contained in this report. If a third party makes use of, relies on, or makes decisions in accordance with this report, said third party is solely responsible for such use, reliance or decisions. WSP does not accept responsibility for damages, if any, suffered by any third party as a result of decisions made or actions taken by said third party based on this report.

WSP has provided services to the intended recipient in accordance with the professional services agreement between the parties and in a manner consistent with that degree of care, skill and diligence normally provided by members of the same profession performing the same or comparable services in respect of projects of a similar nature in similar circumstances. It is understood and agreed by WSP and the recipient of this report that WSP provides no warranty, express or implied, of any kind. Without limiting the generality of the foregoing, it

is agreed and understood by WSP and the recipient of this report that WSP makes no representation or warranty whatsoever as to the sufficiency of its scope of work for the purpose sought by the recipient of this report.

In preparing this report, WSP has relied in good faith on information provided by others, as noted in the report. WSP has reasonably assumed that the information provided is correct and WSP is not responsible for the accuracy or completeness of such information.

Benchmark and elevations used in this report are primarily to establish relative elevation differences between the specific testing and/or sampling locations and should not be used for other purposes, such as grading, excavating, construction, planning, development, etc.

WSP disclaims any responsibility for consequential financial effects on transactions or property values, or requirements for follow-up actions /or costs.

Overall conditions can only be extrapolated to an undefined limited area around these testing and sampling locations. The conditions that WSP interprets to exist between testing and sampling points may differ from those that actually exist. The accuracy of any extrapolation and interpretation beyond the sampling locations will depend on natural conditions, the history of Site development and changes through construction and other activities. In addition, analysis has been carried out for the identified chemical and physical parameters only, and it should not be inferred that other chemical species or physical conditions are not present. WSP cannot warrant against undiscovered environmental liabilities or adverse impacts off-Site.

The original of this digital file will be kept by WSP for a period of not less than 10 years. As the digital file transmitted to the intended recipient is no longer under the control of WSP, its integrity cannot be assured. As such, WSP does not guarantee any modifications made to this digital file subsequent to its transmission to the intended recipient.

This limitations statement is considered an integral part of this report.

TABLE OF CONTENTS

1 EXECUTIVE SUMMARY 1
2 INTRODUCTION 4
2.1 Site Description 4
2.2 Property Ownership 5
2.3 Current and Proposed Future Uses 5
2.4 Applicable Site Condition Standard 5
3 BACKGROUND INFORMATION 7
3.1 Physical Setting 7
4 SCOPE OF INVESTIGATION 9
4.1 Overview of Site Investigation 9
5 INVESTIGATION METHOD 10
5.1 General 10
5.2 Utility Locates 10
5.3 Drilling 10
5.4 Soil 11
5.4.1 Soil Sampling 11
5.4.2 Field Screening Measurements 11
5.5 Groundwater 12
5.5.1 Groundwater Monitoring and Well modification 12
5.5.2 Groundwater Field Measurement of Water Quality Parameters 12
5.5.3 Groundwater Sampling 12
5.6 Sediment Sampling 12
5.7 Analytical Testing 12
5.8 Residue Management Procedures 13
5.9 Elevation Survey 13
5.10 Quality Assurance and Quality Control Measures 13
6 REVIEW AND EVALUATION 14
6.1 Geology/Soil Stratigraphy 14
6.2 Hydrogeology 15
6.2.1 Elevations 15
6.3 Results of Analysis 15

6.3.1 Soil Texture Analysis 15
6.3.2 Field Screening 15
6.3.3 Soil Chemical Quality 15
6.3.4 Soil – Metals And Other Regulated Parameters 16
6.3.5 Soil – Petroleum Hydrocarbons And Btex 16
6.3.6 Soil – Volatile Organic Compounds 17
6.3.7 Soil – Polycyclic Aromatic Hydrocarbons 17
6.3.8 Soil – Polychlorinated Biphenyls 18
6.3.9 Soil – Organochlorine Pesticides 18
6.3.10 Groundwater Chemical Quality 18
6.3.11 Groundwater – Metals And Other Regulated Parameters 18
6.3.12 Groundwater - Petroleum Hydrocarbons And Btex 19
6.3.13 Groundwater– Volatile Organic Compounds 19
6.3.14 Groundwater– Polycyclic Aromatic Hydrocarbons 19
6.3.15 Groundwater– Polychlorinated Biphenyls 20
6.3.16 Groundwater– Organochlorine Pesticides 20
6.3.17 Sediment Quality 20

6.4 Quality Assurance and Quality Control Results 21

7 CONCLUSIONS & RECOMMENDATIONS 23

7.1 Qualifier 24

7.2 Qualifications of the Assessors 25

8 REFERENCES 26

TABLES *(APPENDED TO REPORT)*

Table 1	Monitoring Well Installation and Groundwater Levels
Table 2	Summary of Soil Samples Submitted for Chemical Analysis
Table 3	Summary of Groundwater Samples Submitted for Chemical Analysis
Table 4	Soil Analytical Results - Metals & ORPs
Table 5	Soil Analytical Results - PHCs & BTEX
Table 6	Soil Analytical Results - VOCs
Table 7	Soil Analytical Results - PAHs
Table 8	Soil Analytical Results – PCB & OCPs
Table 9	Groundwater Analytical Results - Metals & ORPs
Table 10	Groundwater Analytical Results - PHCs & BTEX
Table 11	Groundwater Analytical Results - VOCs
Table 12	Groundwater Analytical Results – PAHs
Table 13	Groundwater Analytical Results – PCBs
Table 14	Summary of Maximum Concentrations in Soil
Table 15	Summary of Maximum Concentrations in Groundwater

FIGURES *(APPENDED TO REPORT)*

Figure 1-1 to 1-64	Contaminant Overview Study Conceptual Site Model
Figure 2-1 to 2-64	Areas of Potential Environmental Concern and Borehole Location Plan
Figure 3-1 to 3-6	Chemical Exceedances in Soil – Metals and ORPs
Figure 4-2 to 4-4	Chemical Exceedances in Soil - PAHs
Figure 5-1 to 5-3	Chemical Exceedance in Soil – PHCs and BTEX
Figure 6-1 to 6-2	Chemical Exceedances in Groundwater- Metals and ORPs
Figure 7-1	Chemical Exceedances in Groundwater - PAHs
Figure 8	Contaminant Transport Diagram – Human Health

APPENDICES

TABLES
FIGURES
A BOREHOLE LOGS
B CERTIFICATES OF ANALYSIS

ACRONYMS AND ABBREVIATIONS

µm	micrometre(s)
APEC	area(s) of potential environmental concern as defined in O.Reg. 153/04, "the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through (a) identification of past or present uses on, in or under the phase one property, and (b) identification of potentially contaminating activity"
As	arsenic
B-HWS	boron (hot water soluble)
BTEX	benzene, toluene, ethylbenzene, and xylenes
CALA	Canadian Association for Laboratory Accreditation
Cl-	chlorine
CN-	cyanide
COPC	contaminant(s) of potential concern
Cr (VI)	hexavalent chromium
CSM	conceptual site model
DNAPL	dense non-aqueous phase liquid(s)
EC	electrical conductivity
ESA	environmental site assessment
ha	hectare(s)
Hg	mercury
ICC	Industrial/Commercial/Community
km	kilometre(s)
L	litre(s)
LNAPL	light non-aqueous phase liquid(s)
m	metre(s)
masl	metres above sea level
mbgs	metres below ground surface
MDL	method detection limit
MNRF	Ministry of Natural Resources and Forestry
MECP	Ministry of the Environment, Conservation and Parks
N/S	Not Specified
Na	sodium
O.Reg. 153/04	Ontario Regulation 153/04, as amended
O.Reg. 347	Ontario Regulation 347, as amended

O.Reg. 903	Ontario Regulation 903, as amended
ORPs	other regulated parameters
PAH	polycyclic aromatic hydrocarbon
PCA	potentially contaminating activity as defined in O.Reg. 153/04, “a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a Phase One study area”
PCB	polychlorinated biphenyls
PHC	petroleum hydrocarbon
PID	photoionization detector
PIN	property identification number
ppm	parts per million
QA	quality assurance
QC	quality control
QPESA	Qualified Person for ESAs according to MECP O.Reg. 153/04
RA	Risk Assessment
RDL	reporting detection limit
RPI	Residential/Parkland/Institution
RPIICC	Residential/Parkland/Institution/Industrial/Commercial/Community
RSC	Record of Site Condition
SAP	Sampling and Analysis Plan
SAR	sodium adsorption ratio
Sb	antimony
Se	selenium
SOP	standard operating procedure(s)
SCS	Site Condition Standard
THM	trihalomethane
TOV	total organic vapours
UST	underground storage tank
VOC	volatile organic compound

1 EXECUTIVE SUMMARY

WSP Canada Inc. was retained by the Region of Peel to conduct a Limited Phase II Environmental Site Assessment (ESA) of the former Orangeville Rail, beginning in Streetsville, Mississauga, continuing through Brampton, and terminating in Orangeville, Ontario (hereafter referred to as the "Phase II Property" or "Site"). It is WSP's understanding that this Phase II ESA was completed for due diligence purposes prior to a potential property transaction. This report considers elements of Ontario Regulation 153/04 but does not fulfill the prescribed reporting requirements under Schedule E. There is no current requirement identified for a Record of Site Condition (RSC) to be filed. Section 13 (1) of O. Reg. 153/04 provides an exemption for the change in use of a property from a railway line to a trail used for recreational activities, negating the need for an RSC.

The Site begins in Mississauga, continues through Brampton, and terminates in Orangeville, Ontario running through mixed commercial, residential, agricultural, and industrial areas. The Site is comprised of a single-track railroad right-of-way, approximately 55 km in length and 19.8 m in width. The Site was developed as a passenger/freight railroad track beginning in the 1860s. The Site historically included one (1) rail yard, located in Brampton, and eight (8) smaller junctions where CP Rail station buildings were historically located. These stations or junctions included: Churchville, Snelgrove, Cheltenham, Inglewood, Forks of the Credit, Cataract, Alton, and Melville. It is noted that historic underground and aboveground fuel storage tanks have been identified in the vicinity of Mayfield Road (Snelgrove Junction). Records reviewed indicate that these historic tanks have been removed, dating back to at least 1999. This area was investigated in this Limited Phase II ESA through investigation location BH21-25.

The Site is irregular in shape and occupies an area of approximately 125.5 ha (310 acres). The Site is currently used as a railway. The Site is proposed to be converted into a multi-purpose recreational trail.

The Contaminant Overview Study (COS) completed by WSP in June 2020 identified multiple on-Site and off-Site potentially contaminating activities (PCAs) that resulted in the identification of 113 areas of potential environmental concern (APECs). WSP notes that only select APECs (Forty (40)) were investigated as part of this Limited Phase II ESA at the authorization of the Client. APECs were selected to achieve as much geographical coverage as possible. The Limited Phase II ESA conducted by WSP involved the advancement of 45 boreholes and installation of 18 shallow-screened groundwater monitoring wells to investigate soil and (shallow and overburden) groundwater conditions across the Site.

Based on the Limited Phase II ESA, WSP presents the following conclusions and recommendations:

- There were no investigation locations (soil or groundwater) that reported concentrations / values in excess of the MECP Table 1 SCS within the Mississauga footprint of the Site. Therefore, no further assessment is considered warranted at this time within the Mississauga footprint of the Site.
- Three (3) soil samples collected within the Brampton footprint of the Site at a depth interval of 0.0 to 0.6 mgbs (BH21-7 SS1, BH21-8 SS1 and BH21-45 SS1) did not meet the applicable MECP Table 1 SCS for PAHs. Additional evaluation through Due Diligence Risk Assessment (DDRA) is recommended.

- Two (2) soil samples collected within the Brampton footprint of the Site at a depth interval of 0.0 to 0.6 mbgs (BH21-16 SS1 and BH21-20 SS1) did not meet the applicable MECP Table 1 SCS for metals. Additional evaluation through DDRA is recommended.
- One (1) soil sample collected within the Brampton footprint of the Site at a depth interval of 7.6 to 8.2 mbgs (BH21-45 SS8) did not meet the applicable Table 1 SCS for PHCs (F1) and BTEX (ethylbenzene and xylenes). Additional evaluation through DDRA is recommended.
- Shallow groundwater quality within the Brampton footprint of the Site did not meet the MECP Table 1 SCS as of December 7, 2021. In particular, contaminant exceedances were identified at BH21-6 (cobalt and chromium; WSP notes that elevated chloride at BH21-6 does not warrant further assessment per Section 49.1 of O. Reg. 153/04 as the standard is considered met), BH21-16 (molybdenum) and BH 21-45 (molybdenum and PAHs). At the request of the Client, resampling of BH21-16 (molybdenum) and BH21-45 (molybdenum and PAHs) was undertaken on February 11, 2022, using low-flow sampling techniques. Molybdenum was detected in both confirmatory samples from BH21-16 and BH21-45 at concentrations greater than the Table 1 SCS. PAHs were not detected in the confirmatory sample from BH21-45. It is therefore inferred that the PAHs measured in the original groundwater sample from BH21-45 may have been influenced by sediment in the sample and may not be representative of the groundwater quality in this monitoring well. Additional evaluation through DDRA is recommended[1].
- The risk potential for off-Site adverse effects relative to any migration of molybdenum via groundwater transport relative to concentrations observed in shallow groundwater monitoring wells BH21-16 and BH21-45 is considered low. The molybdenum concentrations are inferred to be related to the presence of clayey soil. Further, the Table 2 and 8 SCS were both met.
- The risk potential for off-Site adverse effects relative to any migration of chromium via groundwater transport relative to the concentration observed in shallow groundwater monitoring well BH21-6 is considered low. While there is insufficient information to draw conclusions on the nature (anthropogenic vs. naturally occurring) of this contaminant in shallow groundwater, the Table 2 and 8 SCS were both met.
- The risk potential for off-Site adverse effects relative to any migration of cobalt via groundwater transport relative to the concentration observed in shallow groundwater monitoring well BH21-6 is increased relative to molybdenum and/or chromium concentrations identified at BH21-6, BH21-6 and/or BH21-45 on the basis that the Table 2 and 8 SCS were not met. Additional evaluation through DDRA is recommended.
- Four (4) soil samples collected within the Caledon footprint of the Site at depth intervals of 0.0 to 0.6 mbgs (BH21-10 S1, BH21-32 SS1 and BH21-36 SS1) and 0.6 to 1.2 mbgs (BH21-41 S2) did not meet the applicable MECP Table 1 SCS for metals and/or mercury. Additional evaluation through DDRA is recommended.
- Two (2) soil samples collected within the Caledon footprint of the Site at depth intervals of 1.5 to 2.1 mbgs (BH21-9 SS3) and 1.2 to 1.8 mbgs (BH21-40 S3) did not meet the applicable MECP Table 1 SCS for PAHs. Additional evaluation through DDRA is recommended.

[1] The Brampton DDRA maintained a conservative approach and considered the PAH concentrations in the original groundwater sample from BH21-45 as a worst-case scenario.

- Two (2) soil samples collected within the Caledon footprint of the Site at depth intervals of 0.6 to 1.2 mbgs (BH21-31 S2) and 0.0 to 0.6 mbgs (BH21-41 S1) did not meet the applicable MECP Table 1 SCS for PHCs (F2; BH21-31 S2) or BTEX (xylenes; BH21-41 S1). Additional evaluation through DDRA is recommended.
- As an alternative to implementation of risk management measures within the Caledon footprint of the Site, the Client could consider additional assessment (to further characterize lateral and vertical extents of impact) and subsequent implementation of excavation and disposal of impacted soil identified at BH21-10, BH21-41 and BH21-36. Confirmatory soil sampling and testing would be required to confirm the appropriateness of remedial excavation limits.
- Once the groundwater wells are no longer required for monitoring or sampling purposes, these wells are recommended to be appropriately decommissioned by a licensed well contractor as required by O. Reg. 903.

2 INTRODUCTION

WSP Canada Inc. was retained by the Region of Peel to conduct a Limited Phase II Environmental Site Assessment (ESA) of the former Orangeville Rail, beginning in Streetsville, Mississauga, continuing through Brampton, and terminating in Orangeville, Ontario (hereafter referred to as the "Phase II Property" or "Site"). It is WSP's understanding that this Phase II ESA was completed for due diligence purposes prior to a potential property transaction. This report considers elements of Ontario Regulation 153/04 but does not fulfill the prescribed reporting requirements under Schedule E. There is no current requirement identified for a Record of Site Condition (RSC) to be filed. Section 13 (1) of O. Reg. 153/04 provides an exemption for the change in use of a property from a railway line to a trail used for recreational activities, negating the need for an RSC.

The Site is comprised of a single-track railroad right-of-way, approximately 55 km in length and 19.8 m in width. The Site was developed as a passenger/freight railroad track beginning in the 1860s. The Site historically included one (1) rail yard, located in Brampton, and eight (8) smaller junctions where CP Rail station buildings were historically located. These stations or junctions included: Churchville, Snelgrove, Cheltenham, Inglewood, Forks of the Credit, Cataract, Alton, and Melville.

For the purposes of this investigation, the Mississauga portion of the Site is defined as the southernmost section of the Property, between Atwood Lane and Highway 407. The Brampton portion of the Site is the length of railway between Highway 407 and Mayfield Road, and the Caledon portion runs between Mayfield Road north to Orangeville, between Townline and Dufferin Road 109.

2.1 SITE DESCRIPTION

Property information for the Site is provided in the table below:

Table 2.1 Property Information

CRITERION	DESCRIPTION
Municipal Address	No municipal address is associated with the Site.
Property Identification Numbers (PINs)	See WSP, 2020
Legal Description	Legal descriptions were not provided at the time of this investigation.

2.2 PROPERTY OWNERSHIP

Property ownership information for the Site is provided in the table below:

Table 2.2 Property Ownership Information

CRITERION	DESCRIPTION
Current Site Owner	Orangeville Railway Development Corporation (ORDC)
Region Representative	Mr. Ryan Grzesiak Region of Peel 2 Copper Road Brampton, Ontario L6T 4W5 Email: ryan.grzesiak@peelregion.ca

2.3 CURRENT AND PROPOSED FUTURE USES

The Site is currently utilized for industrial purposes as a railway. Proposed redevelopment of the Site for parkland use includes the conversion of the railway into a multi-purpose recreational trail.

2.4 APPLICABLE SITE CONDITION STANDARD

The Site as a whole, could incorporate the Table 1: Full Depth Background Site Condition Standards for residential /parkland / institutional / industrial / commercial / community (RPIICC) property use (soil) and all types of property use (groundwater), on the identified basis of environmentally significant areas located within 30 metres (m) of boundaries. Further, portions of the Site could incorporate the Table 8: Generic Site Condition Standards for Use within 30 m of a Water Body in a Potable Ground Water Condition for RPIICC property use (soil) and all types of property use (groundwater), on the identified basis of water bodies within 30 m of property boundaries.

Additionally, portions of the Site could incorporate the Table 2: Full Depth Generic Site Condition Standards in a Potable Ground Water Condition for RPI property use (soil) and all types of property use (groundwater), in areas of the railway corridor that have not identified environmentally sensitive areas or water bodies within 30 m of property boundaries.

WSP notes that the majority of boreholes are not within 30 m of an environmentally significant area or a water body. As permission to use non-potable standards was not sought, the Table 2 SCS could be considered for assessment purposes. However, there are portions of the railway corridor footprint that are located within 30 m of an environmentally significant area and a water body. Therefore, for the purposes of this report, comparisons to Tables 1, 2 and 8 have been applied to our appended tables. Tables 1, 2 and 8 are set forth in the Ministry of the Environment, Conservation and Parks (MECP) 2011 publication *"Soil, Ground Water and Sediment Standards for Use under Part XV.1 of the Environmental Protection Act"*.

With regards to the 2011 MECP Table 8 Generic Site Condition Standard (SCS) for Use within 30 m of a Water Body in a Potable Groundwater Condition for RPIICC property uses, the selection of this standard for specific portions of the Phase II Property for comparison purposes was based on the following:

- Groundwater is used as a potable water source in the vicinity of the Phase II Property;
- The Phase II Property is not considered an "environmentally sensitive" site, as defined by O.Reg. 153/04;
- The future use of the Phase II Property is considered parkland land use (e.g., multi-use recreational trail);
- A water body is situated within 30 m of the specified portions of the Phase II Property;
- The pH of the soil samples analysed during this investigation from forty-four (44) boreholes ranged from 7.04 to 7.91, which falls within the acceptable range stated in O.Reg. 153/04; and,
- Bedrock was not encountered within 2 m of the ground surface.

With regards to the 2011 MECP Table 2 Full Depth Generic SCS in a Potable Groundwater Condition for RPI property use in course textured soils, the evaluation standard was selected for specific portions of the Phase II Property for comparison purposes based on the following:

- Groundwater is used as a potable water source in the vicinity of the Phase II Property;
- The Phase II Property is not considered an "environmentally sensitive" site, as defined by O.Reg. 153/04;
- The future use of the Phase II Property is considered parkland land use (e.g., multi-use recreational trail);
- The portions of the Site are not situated within 30 m of a water body; and,
- The pH of the soil samples analysed during this investigation from forty-four (44) boreholes ranged from 7.04 to 7.91, which falls within the acceptable range stated in O.Reg. 153/04; and,
- Bedrock was not encountered within 2 m of the ground surface.

Tables 1, 2, and 8 are set forth in the Ministry of the Environment, Conservation and Parks (MECP) 2011b publication "*Soil, Ground Water and Sediment Standards for Use under Part XV.1 of the Environmental Protection Act*".

3 BACKGROUND INFORMATION

3.1 PHYSICAL SETTING

A summary of the Site's physical setting determined through the COS is included in table below:

Table 3.1 Summary of Physical Setting

CRITERIA	DESCRIPTION
i. Water Bodies	The following water bodies were identified within the Phase II Study Area: — The Site intersects Levi's Creek just south of the 407 Express Toll Route; — The Site intersects an unnamed creek south of Old School Road; — An unnamed creek runs parallel to Site south of the Brampton Airport, east adjacent to Site; — The Site intersects the Credit River north of Olde Base Line Road; — The Site intersects Caledon Creek north of Queen Street East, Alton; and, — An unnamed creek runs parallel to Site south of Route 109, Orangeville.
ii. Areas of Natural Significance	The following areas of natural significance were identified within the Contaminant Overview Study Area: — The Meadowvale Conservation Area was listed as an area of natural significance within 1 km of Site; — The Churchville-Norval Wetland Complex was listed as an area of natural significance within 1 km of Site; — A portion of the Site traverses the Green Belt; — A portion of the Site traverses the Niagara Escarpment Plan Protection Area; — A portion of the Site traverses the Forks of the Credit Provincial Park; and, — A portion of the Site traverses the Caledon meltwater deposits.

iii.	Topography and surface water drainage features on the Phase II property	The Site ranges in elevation from approximately 174 masl in Churchville to 427 masl in Orangeville. The topography in the vicinity of the Site generally slopes to the southeast towards Lake Ontario. Based on the regional topography, the inferred shallow groundwater flow direction regional across the Site is southeast. The groundwater flow direction on the Site can only be confirmed through long-term groundwater monitoring. The Site is situated within bevelled till plains, sand plains, drumlinized till plains, escarpment, and spillway physiographic regions. The Site intersects several surficial geological areas; however, the surficial geology in vicinity of the majority of the Site is described as clay to silt textured till derived from glaciolacustrine deposits or shale. Additional surficial geological units located within the vicinity of the Site include modern alluvial deposits consisting of clay, silt, sand, and gravel (which may contain organic remains), fine glaciolacustrine deposits consisting of silt and clay, minor sand and gravel, interbedded silt and clay and gritty, pebbly flow till and rainout deposits, Paleozoic bedrock in the vicinity of Inglewood Junction, Ice-contact stratified deposits consisting of sand and gravel, minor silt, clay and till, glaciofluvial deposits consisting of river deposits and delta topset facies, and organic deposits consisting of peat, muck, and marl in the vicinity of the Forks of the Credit Junction, Alton Junction, and Melville Junction. The underlying bedrock within the area generally consists of shale, limestone, dolostone, and siltstone of the Queenston Formation in the southern portion of Site, and moves into sandstone, shale, dolostone, and siltstone of the Clinton, Cataract Group, and Amabel Formation once north of the Forks of the Credit.
iv.	Well-head protection areas or other designation	Part of the Caledon portion of the Site falls within a well-head protection area. Based on the MECP Source Protection Information Atlas, the following boreholes fall within this area: BH21-9, BH21-10, BH21-11, BH21-13, BH21-14, BH21-15, BH21-33, BH21-34, BH21-36, BH21-37 and BH21-38. The Mississauga and Brampton portions of the Site are not situated within a well-head protection area.
v.	Municipal drinking water system	Caledon: The Town of Caledon obtains its potable water primarily potable groundwater sources, as well as from Lake Ontario. No water supply wells were observed on the Site, and several domestic water wells were identified within the Study Area. A reportable spill of potable water was included in the ERIS Spill Database, as reported in the COS (WSP, 2020). This spill pertains to a release of potable drinking water from the Region of Peel's Snelgrove Elevated Tank (water storage tower) directly to a storm sewer for a period of 37 minutes on September 29, 2011. This spill is not considered an environmental concern to the subject site. Brampton: The City of Brampton obtains its potable water primarily from Lake Ontario and also from some potable groundwater sources. The municipality supplies water to properties within the Study Area. No water supply wells were observed on the Site, and several domestic water wells were identified within the Study Area. Mississauga: The municipality supplies water to properties within the Study Area, and the primary potable water source is Lake Ontario. The Site itself is not serviced for water.
vi.	Well observations	No potable water wells or monitoring wells were observed on the Site.

4 SCOPE OF INVESTIGATION

4.1 OVERVIEW OF SITE INVESTIGATION

The Phase II ESA involved intrusive investigation in the areas determined in the COS to be APECs. The Phase II ESA was carried out in accordance with O. Reg. 153/04. The Site investigation activities were limited to visible and accessible locations of the Site. Subsurface investigations, testing, sampling, and laboratory analyses were completed based on findings of the WSP COS, accessibility to APECs, and Site observations.

The Site investigation program included the following:

- Clearance of public and private underground utilities and services prior to commencement of intrusive investigation activities.
- Preparation of a Health and Safety Plan and safe execution of all proposed work.
- Advancement of forty-five (45) boreholes on the Phase II Property, to an approximate maximum depth of 9.1 mbgs. Boreholes less than 2 mbgs in depth were advanced manually using a hand auger. Boreholes greater than 2 mbgs were advanced using a track-mounted rig. The soil lithology from each borehole was logged in the field and samples were screened for hexane with a combustible gas detector. The locations of the boreholes were selected to investigate select APECs (forty ((40)) identified during the Contaminant Overview Study.
- Based on field screening and visual/olfactory observations, worst-case/representative soil samples from the boreholes were submitted for laboratory testing of relevant COPC.
- Groundwater monitoring wells were installed within eighteen (18) boreholes to assess groundwater quality below the Site and determine the direction of groundwater flow.
- The groundwater levels in the wells were measured to determine the groundwater table elevation. The wells were surveyed to a geodetic benchmark to determine groundwater flow direction.
- The groundwater wells were purged to remove stagnant water and sampled for laboratory testing of relevant parameters of concern.
- Both soil and groundwater samples were submitted for chemical analysis by a CALA certified laboratory.

5 INVESTIGATION METHOD

5.1 GENERAL

This section provides a brief description of all methods employed in undertaking the current Phase II ESA investigation. Where the method differs from the associated standard operating procedure, a detailed description of the method used and a rationale for the change in method is provided in the appropriate subsection below.

5.2 UTILITY LOCATES

Ontario One Call was contacted for the public utilities locates for the investigation. Premier Locates was retained by WSP to locate private utilities on-Site for all the subsurface investigation work.

5.3 DRILLING

WSP staff inspected the Site and identified the preferred borehole locations to provide general site coverage and investigate select APECs identified in the WSP COS. The borehole locations are shown on Figures 2-1 through 2-64. The location of underground services and utilities within the Site were cleared prior to the commencement of the drilling program. WSP arranged for the service locates to be completed through Ontario One Call and Landshark Locating Services. A summary of the drilling events is presented in the table below.

Table 5-1 Summary of Drilling

INFORMATION PARAMETER	DETAILS
Name of Drilling Contractor	Davis Drilling
Drilling Equipment Used	CME55 (track-mounted) – Boreholes greater than 1.8 mbgs Hand auger – Boreholes less than 1.8 mbgs
Measures taken to minimize the potential for cross-contamination	A 50-mm stainless steel split spoon sampler was used to collect soil samples from the boreholes. The split spoon sampler was brushed clean of soil, washed in municipal water containing phosphate free detergent, rinsed in municipal water, and then rinsed with distilled water for each sampling interval in order to reduce the potential for cross contamination. The hand auger was rinsed with distilled water between each sampling interval.
Frequency of sample collection	CME55: every 0.6 m per 0.8 m for the first 3.1 m followed by 0.6 m per 1.5 m to the termination of the borehole. Hand Auger: every 0.6 m up to 1.8 mbgs

From October 27 to December 6, 2021, a total of forty-five (45) boreholes were drilled along select areas of the Phase II Property. Hand-augered boreholes were advanced to a maximum depth of 1.8 mbgs. Soil samples were collected manually from the auger threads. Boreholes drilled with the CME55 were advanced to a maximum depth of 9.1 mbgs. Soil samples were collected from the fill and native material and the upper bedrock contact using a 50-mm diameter, 0.61-m long stainless-steel split spoon sampler.

5.4 SOIL

5.4.1 SOIL SAMPLING

Disposable nitrile gloves were used during sample collection and changed between each sample to minimize the potential for cross-contamination. Soil samples were described in the field by WSP staff and observations were recorded in a dedicated field book. Soil samples were collected directly into laboratory-supplied 120-mL glass jars and 40-mL methanol-preserved vials and were stored at a temperature of less than 10°C. Samples selected for laboratory analysis were handled under standard chain of custody procedures until received at the laboratory. The soil samples selected for laboratory analysis were considered representative of worst-case conditions in the boreholes based on field screening results and visual and olfactory observations.

All soil samples were submitted to AGAT Laboratories in Mississauga, Ontario. The soil samples submitted for chemical analysis are summarized in Table 2, appended.

5.4.2 FIELD SCREENING MEASUREMENTS

Soil samples collected from the boreholes were field screened for combustible gases using an RKI Eagle 2 CGD. In addition to visual and olfactory observations, the results of field screening were used to determine worst-case samples in order to select those to submit to the laboratory for analysis of volatile parameters. Additional samples may have been analysed for delineation purposes, if required. A summary of field screening measurements is provided in the table below.

Table 5-2 Summary of Field Screening Information

CRITERIA		DESCRIPTION
i.	Make and Model of Field Screening Instrument	RKI Eagle 2 CGD, Serial Number E2G087
ii.	Chemicals that Field Screening Instrument Detects and Respective Detection Limits	Combustible Gas (Hexane) with dynamic range of 0 to 50,000 parts per million (ppm)
iii.	Precision of the Measurements	1 ppm
iv.	Accuracy of the Measurements	50 ppm or ± 5% display reading
v.	Calibration Reference Standards	Hexane

vi.	Calibration Procedures	The RKI Eagle 2 was calibrated prior to use.

Field screening measurements (CGD readings) are discussed in Section 6.3.1.2 and presented on the finalized borehole logs, included in **Appendix A.**

5.5 GROUNDWATER

5.5.1 GROUNDWATER MONITORING AND WELL MODIFICATION

A total of eighteen (18) monitoring wells were installed by WSP between November 8, 2021 and February 11, 2022, along the length of the Phase II property. Two (2) wells were installed in Mississauga, eight (8) in Brampton and eight (8) in Caledon. The wells were installed and sampled for groundwater characterization purposes, based on COPCs identified in the COS.

Monitoring well construction details are provided in the borehole logs in **Appendix A.**

5.5.2 GROUNDWATER FIELD MEASUREMENT OF WATER QUALITY PARAMETERS

Between November 22 and December 2, 2021, all wells on Site were purged using 13 mm LDPE Waterra tubing and an inertial pump (foot valve). The wells were purged by removing three well volumes or by purging the well dry three times. Field measurements of water quality parameters were collected using a Hanna multi-meter as part of this assessment including field pH, EC, and temperature. Field groundwater quality measurements were obtained after the removal of each well volume and were recorded in a dedicated field book. This data has been archived and is available upon request.

5.5.3 GROUNDWATER SAMPLING

Between November 23 and December 7, 2021, following purging, groundwater samples were collected from all wells on Site for the purpose of assessing both shallow groundwater quality at the Phase II Property. Additional re-sampling of two (2) wells occurred on February 11, 2022, based on exceedances identified in the 2021 sampling event.

The groundwater samples were collected in laboratory-supplied bottles and stored in an ice-filled cooler and submitted under proper chain of custody procedures to AGAT Laboratories in Mississauga for analysis of metals and inorganics, PAHs, PHCs, PCBs, OCPs and VOCs.

5.6 SEDIMENT SAMPLING

Sediment sampling was not conducted as part of this Phase II ESA.

5.7 ANALYTICAL TESTING

Soil and groundwater samples were submitted to AGAT Laboratories in Mississauga, Ontario, for chemical analysis for the above listed parameters. AGAT Laboratories is certified by CALA.

5.8 RESIDUE MANAGEMENT PROCEDURES

The management of residues such as soil cuttings, purged groundwater and fluids from equipment cleaning was conducted as indicated in the table below.

Table 5.3 Summary of Residue Management Procedures

RESIDUE		MANAGEMENT PROCEDURE
i.	Soil cuttings from drilling and excavations	Soil cuttings were scattered in the vicinity of the boreholes.
ii.	Water from well development and purging	Groundwater from the development, purging and sampling of the monitoring wells was discharged down gradient, away from the monitoring wells.
iii.	Fluids from equipment cleaning.	Equipment cleaning water was emptied onto the ground down gradient of the wells.

5.9 ELEVATION SURVEY

The existing ground surface and top of pipe (well casing) elevations of the groundwater monitoring wells were surveyed by WSP personnel. The ground surface elevations are included on the borehole logs in **Appendix A**.

5.10 QUALITY ASSURANCE AND QUALITY CONTROL MEASURES

Sample containers were labelled with unique sample identification, the project number, and the sampling date. A laboratory-supplied chain of custody was completed for each laboratory submission; one copy was retained for the project file, while the remaining copy accompanied the samples to the laboratory.

Nitrile gloves, used during sample handling, were replaced after each sample was collected to reduce the potential for cross-contamination of the samples. Field equipment was decontaminated and rinsed with de-ionized water between samples.

As part of the quality assurance/quality control (QA/QC) program for the project, a minimum of one (1) blind field duplicate sample for every ten samples was collected and analyzed for each parameter group in both soil and groundwater. The relative percent difference (RPD) between duplicate samples was calculated in accordance with the *Protocol for Analytical Methods Used in the Assessment of Properties under Part XV.1 of the Environmental Protection Act as amended July 1, 2011* (i.e., 2011 Protocol). The calculated RPD was assessed against the recommended performance criteria outlined in the 2011 Protocol where the measured concentration was greater than 5 times the laboratory reportable detection limit (RDL).

AGAT Laboratories also performed QA/QC procedures as outlined in their CALA procedures. These procedures included analysis of lab duplicates and blanks as well as analysis of surrogate recovery as outlined in the Certificates of Analysis provided in **Appendix B.**

6 REVIEW AND EVALUATION

6.1 GEOLOGY/SOIL STRATIGRAPHY

A brief summary of the subsurface conditions encountered at the Site is presented below. Detailed borehole logs are included in **Appendix A.**

Mississauga:

The Mississauga portion of the Phase II Property is located within a Bevelled Till Plains physiographic region.

Boreholes BH21-1, BH21-12, BH21-42, BH21-43 and BH21-44 were advanced through an initial layer of sandy silt to a max depth of 1.22 mbgs, underlain by clayey silt to a max depth of 1.83 mbgs. In BH21-12, BH21-42, BH21-43 and BH21-44, this was underlain by silty clay to clay, ranging in depth from 0.76 to 9.75 mbgs. Bedrock was not encountered in this portion of the investigation, and is expected at depths greater than 7.3 mbgs based on available MECP well records.

Brampton:

The northern part of the Brampton portion of the Site and Study Area is located within a Drumlinized Till Plains physiographic region (BH21-18 through BH21-24). The southern part is located within a Bevelled Till Plains physiographic region (BH21-2 though BH21-8, BH21-16, BH21-17 and BH21-45).

BH21-45, BH21-16, BH21-2, BH21-22 and BH21-3 were advanced through a layer of sandy silt to a max depth of 6.1 mbgs, underlain by clay ranging between 1.52 to 9.75 mbgs. The clay was underlain by silty sand ranging between 7.9 and 9.14 mbgs. This was in turn underlain by red shale ranging from 6.20 mbgs to borehole termination. Shallow boreholes BH21-18 through BH21-21 were advanced through sandy silt up to 2.6 mbgs, underlain by red shale ranging from 1.2 mbgs to borehole termination. Shallow boreholes BH21-17, BH21-4, BH21-5, BH21-23 and BH21-24 were all advanced through sandy silt or silt to borehole termination. In BH21-6, sandy silt was encountered to 3.15 mbgs, and underlain by sand and pulverized rock to 6.20 mbgs, at which point red shale was encountered to borehole termination.

Caledon:

The portion of the Study Area north of (and including) BH21-31 is located within a Spillway physiographic region. The southern portion is located within a Drumlinized Till Plains physiographic region.

Boreholes BH21-11. BH21-13, BH21-25, BH21-28, BH21-30 and BH21-31 were advanced through sandy silt ranging from surface to 6.1 mbgs. This was underlain by sand and gravel in BH21-11 and BH21-13 ranging from 0.7 to 9.14 mbgs. Beneath the initial sandy silt, clay was encountered in BH21-25, BH21-28, BH21-30 and BH21-31 ranging in depths from 1.27 to 9.75 mbgs. Shallow boreholes BH21-14, BH21-15, BH21-26, BH21-27, BH21-29 and BH21-37 to BH21-40 were advanced through sandy silt or silty sand to borehole termination. Pulverized rock was encountered in BH21-30, BH21-36 and BH21-32 ranging between 6.45 mbgs and 9.45 mbgs.

Bedrock was not encountered in this portion of the investigation and is expected at depths greater than 23 mbgs based on MECP well records.

6.2 HYDROGEOLOGY

6.2.1 ELEVATIONS

The groundwater levels in the monitoring wells ranged from surface to 6.6 mbgs across the Site on December 7, 2021. Corresponding groundwater elevations ranged from 169.0 to 421.0 masl. Regional groundwater flow direction is to the south/southeast towards Lake Ontario.

The water levels and corresponding elevations are included in Table 1, appended to this report.

Neither LNAPL nor DNAPL were found to be present in any of the monitoring wells on the Site.

6.3 RESULTS OF ANALYSIS

The results of the laboratory analysis are discussed in the following sub-sections.

6.3.1 SOIL TEXTURE ANALYSIS

Coarse-fine grained SCS were used (for Table 2) as a measure as the soil types most consisted of sandy silt to silty sand.

6.3.2 FIELD SCREENING

During WSP's 2021 investigation, a total of 244 soil samples were screened for combustible gas concentrations using an RKI Eagle 2. The combustible gas concentrations ranged from 0 to 10 ppm. The combustible vapor readings are included on the borehole logs included in **Appendix A**. The samples that were submitted for laboratory analysis of organic parameters (VOCs, PHCs, PCBs, OCPs or PAHs) are indicated in the borehole logs provided in **Appendix A.**

6.3.3 SOIL CHEMICAL QUALITY

The soil analytical results are presented in Tables 4 through Table 8. The chemical exceedances in soil are presented in Figures 3, 4 and 5. Analytical results are separated by City (Mississauga (A) /Brampton (B) /Caledon (C).

The Laboratory Certificates of Analysis for the soil analysis are provided in **Appendix B.**

6.3.4 SOIL – METALS AND OTHER REGULATED PARAMETERS

A total of fifty-two (52) soil samples, including four (4) blind field duplicates for QA/QC purposes, were collected and submitted for analysis of metals and ORPs. The soil analytical results for VOCs are provided in Table 4 A/B/C.

Laboratory analysis indicated the following parameter exceedances of Table 1 SCS for metals and other regulated parameters (also shown in Figures 3-1 to 3-6):

Table 6.1 Summary of Metal & ORP Exceedances in Soil

SAMPLE ID	DEPTH (MBGS)	PARAMETER	UNITS	TABLE 1 SCS	TABLE 2 SCS	TABLE 8 SCS	ANALYTICAL RESULT	MUNICIPALITY
BH21-16 SS2	0.0 – 0.6	Antimony	µg/g	1.3	7.5	1.3	2.8	Brampton
		Molybdenum	µg/g	2	6.9	2	3.7	
		Zinc	µg/g	290	340	290	468	
BH21-20	0.0 – 0.6	Nickel	µg/g	1.5	100	82	142	
BH21-10 S1	0.0 – 0.6	Antimony	µg/g	1.3	7.5	1.3	3.5	Caledon
		Arsenic	µg/g	18	18	18	24	
		Molybdenum	µg/g	2	6.9	2	11	
		Selenium	µg/g	1.5	2.4	1.5	2.1	
BH21-32 SS1	0.0 – 0.6	Antimony	µg/g	1.3	7.5	1.3	1.9	
		Mercury	µg/g	0.27	0.27	0.27	0.32	
BH21-36	0.0 – 0.6	Lead	µg/g	120	120	120	205	
BH21-41 S2	0.6 – 1.2	Arsenic	µg/g	18	18	18	26	
		Molybdenum	µg/g	2	6.9	2	2.1	

6.3.5 SOIL – PETROLEUM HYDROCARBONS AND BTEX

A total of forty-six (46) soil samples, including two (2) blind field duplicates for QA/QC purposes, were collected and submitted for analysis of PHCs and BTEX. The soil analytical results for VOCs are provided in Table 5 A/B/C.

Laboratory analysis indicated the following parameter exceedances of Table 1 SCS for PHCs and BTEX (also shown in Figures 5-1 to 5-3):

Table 6.2 Summary of PHC and BTEX exceedances in Soil

SAMPLE ID	DEPTH (MBGS)	PARAMETER	UNITS	TABLE 1 SCS	TABLE 2 SCS	TABLE 8 SCS	ANALYTICAL RESULT	MUNICIPALITY
BH21-45 SS8	7.6 – 8.2	Ethylbenzene	µg/g	0.05	1.1	0.05	0.9	Brampton
		Total Xylenes	µg/g	0.05	3.1	0.05	5.55	
		PHC F2	µg/g	10	98	10	51	
BH21-31 S2	0.6 – 1.2	PHC F2	µg/g	10	98	10	13	Caledon
BH21-41 S1	0.0 – 0.6	Total Xylenes	µg/g	0.05	3.1	0.05	0.22	

6.3.6 SOIL – VOLATILE ORGANIC COMPOUNDS

Twelve (12) soil samples were collected and submitted for analysis of VOCs.

The soil analytical results for VOCs are provided in Table 6 A/B/C and the results of the laboratory analyses indicated that all samples analysed met the applicable Table 1 SCS

6.3.7 SOIL – POLYCYCLIC AROMATIC HYDROCARBONS

A total of forty-six (46) soil samples, including four (4) blind field duplicates for QA/QC purposes, were collected and submitted for analysis of PAHs. The soil analytical results for VOCs are provided in Table 7 A/B/C.

Laboratory analysis indicated the following parameter exceedances of Table 1 SCS for PAHs (also shown in Figures 4-1 to 4-4):

Table 6.3 Summary of PAH Exceedances in Soil

SAMPLE ID	DEPTH (MBGS)	PARAMETER	UNITS	TABLE 1 SCS	TABLE 2 SCS	TABLE 8 SCS	ANALYTICAL RESULT	MUNICIPALITY
BH21-7 SS1	0.0 – 0.6	Anthracene	µg/g	0.16	0.67	0.22	0.18	Brampton
		Fluoranthene	µg/g	0.56	0.69	0.69	1.05	
		Benz(a)anthracene	µg/g	0.36	0.5	0.36	0.56	
		Benz(a)pyrene	µg/g	0.3	0.3	0.3	0.5	
		Benzo(b)fluoranthene	µg/g	0.47	0.78	0.47	0.6	
		Fluoranthene	µg/g	0.56	0.69	0.69	0.85	

BH21-8 SS1	0.0 – 0.6	Benz(a)anthracene	µg/g	0.36	0.5	0.36	0.46	
		Benz(a)pyrene	µg/g	0.3	0.3	0.3	0.4	
		Benzo(b)fluoranthene	µg/g	0.47	0.78	0.47	0.66	
		Indeno(1,2,3-	µg/g	0.23	0.38	0.23	0.26	
BH21-45 SS1	0.0 – 0.6	Fluoranthene	µg/g	0.56	0.69	0.69	0.57	
		Benz(a)anthracene	µg/g	0.36	0.5	0.36	0.39	
		Benz(a)pyrene	µg/g	0.3	0.3	0.3	0.33	
BH21-9	1.5 – 2.1	Anthracene	µg/g	0.16	0.67	0.22	0.18	Caledon
BH21-40 S2	1.2 – 1.8	Naphthalene	µg/g	0.09	0.6	0.09	0.1	
		Benzo(b)fluoranthene	µg/g	0.47	0.78	0.47	0.53	
		Benzo(k)fluoranthene	µg/g	0.48	0.78	0.48	0.5	

6.3.8 SOIL – POLYCHLORINATED BIPHENYLS

Thirty-two (32) soil samples, including three (3) blind field duplicates for QA/QC purposes, were collected and submitted for analysis of PCBs. The soil analytical results for PCBs are provided in Table 8 A/B/C and the results of the laboratory analyses indicated that all samples analysed met the applicable Table 1 SCS.

6.3.9 SOIL – ORGANOCHLORINE PESTICIDES

Thirty-two (32) soil samples, including three (3) blind field duplicates for QA/QC purposes were collected and submitted for analysis of OCPs. The soil analytical results for OCPs are provided in Table 8 A/B/C and the results of the laboratory analyses indicated that all samples analysed met the applicable Table 1 SCS.

6.3.10 GROUNDWATER CHEMICAL QUALITY

The groundwater analytical results are presented in Tables 9 through 13. The chemical exceedances in groundwater are presented in Figures 6-1, 6-2 and 7-1. Chemical exceedances in groundwater were only identified in the **Brampton** portion of the Phase II Property. (For the tables, A – Mississauga, B – Brampton, C- Caledon).

The Laboratory Certificates of Analysis for the groundwater analysis completed during the present Phase II ESA are provided in **Appendix B.**

6.3.11 GROUNDWATER – METALS AND OTHER REGULATED PARAMETERS

A total of sixteen (16) groundwater samples were collected and submitted for analysis of metals and ORPs, including one (1) blind field duplicate for QA/QC purposes. BH21-16 and BH21-45 were

resampled for molybdenum only using low flow sampling in February 2022. The groundwater analytical results for metals and ORPs are provided in Table 9 A/B/C and the results of the laboratory analyses indicated the following exceedances of the Table 1 SCS (also shown in Figures 6-1 and 6-2):

Table 6.4 Summary of Metal and ORP exceedances in Groundwater

SAMPLE ID	SCREEN DEPTH (MBGS)	PARAMETER	UNITS	TABLE 1 SCS	TABLE 2 SCS	TABLE 8 SCS	DATE	ANALYTICAL RESULT
BH21-6	3.1 – 6.1	Chloride	µg/L	790000	790000	790000	06-Dec-21	**1460000**
		Chromium	µg/L	11	50	50		**25.3**
		Cobalt	µg/L	3.8	3.8	3.8		**4.53**
BH21-16	6.1 – 9.1	Molybdenum	µg/L	23	70	70	06-Dec-21	**24.7**
							11-Feb-22	**32.1**
BH21-45	6.1 – 9.1	Molybdenum	µg/L	23	70	70	01-Dec-21	**28**
							11-Feb-22	**57.1**

Exceedances were identified for chloride in BH21-6. The section 49.1 exemption under O. Reg. 153/04 is being applied by the Qualified Person on the basis that de-icing agents have been historically applied to surfaces on adjacent properties for the safety of vehicular or pedestrian traffic under conditions of snow or ice or both. On this basis, chloride is not considered as a COPC.

6.3.12 GROUNDWATER - PETROLEUM HYDROCARBONS AND BTEX

Nineteen (19) groundwater samples, including three (3) blind field duplicates for QA/QC purposes, were collected and submitted for the analysis of PHCs and BTEX during the present investigation.

The groundwater analytical results for PHCs are provided in Table 10 A/B/C and the results of the laboratory analyses indicated that all samples analysed met the applicable Table 1 SCS.

6.3.13 GROUNDWATER– VOLATILE ORGANIC COMPOUNDS

Twelve (12) groundwater samples, including two (2) blind field duplicates for QA/QC purposes, were collected and submitted for the analysis of VOCs during the present investigation.

The groundwater analytical results for VOCs are provided in Table 11 A/B/C and the results of the laboratory analyses indicated that all samples analysed met the applicable Table 1 SCS.

6.3.14 GROUNDWATER– POLYCYCLIC AROMATIC HYDROCARBONS

A total of sixteen (16) groundwater samples, including two (2) blind field duplicates for QA/QC purposes, were collected and submitted for analysis of PAHs. The groundwater analytical results for PAHs are provided in Table 12 A/B/C and the results of the laboratory analyses indicated the following

exceedances of the Table 1 SCS (also shown in Figure 7-1):

Table 6.5 Summary of PAH exceedances in Groundwater

SAMPLE ID	SCREEN DEPTH (MBGS)	PARAMETER	UNITS	TABLE 1 SCS	TABLE 2 SCS	TABLE 8 SCS	DATE	ANALYTICAL RESULT
BH21-45	6.1 – 9.1	Anthracene	µg/L	0.1	2.4	1	01-Dec-21	**1.79**
		Benz(a)anthracene	µg/L	0.2	1	1		**2.4**
		Benz(a)pyrene	µg/L	0.01	0.01	0.01		**3.67**
		Benzo(b)fluoranthene	µg/L	0.1	0.1	0.1		**4.92**
		Benzo(g,h,i)perylene	µg/L	0.2	0.2	0.2		**2.48**
		Benzo(k)fluoranthene	µg/L	0.1	0.1	0.1		**2.19**
		Chrysene	µg/L	0.1	0.1	0.1		**5.59**
		Dibenz(a,h)anthracene	µg/L	0.2	0.2	0.2		**0.32**
		Fluoranthene	µg/L	0.4	0.41	0.41		**17.9**
		Indeno(1,2,3-cd)pyrene	µg/L	2	0.2	0.2		**1.8**
		Phenanthrene	µg/L	0.1	1	1		**1.2**
		Pyrene	µg/L	0.2	4.1	4.1		**14.6**

6.3.15 GROUNDWATER– POLYCHLORINATED BIPHENYLS

Eight (8) groundwater samples, including one (1) blind field duplicate for QA/QC purposes, were collected and submitted for analysis of PCBs. The groundwater analytical results for PCBs are provided in Table 13 A/B/C and the results of the laboratory analyses indicated that all samples analysed met the applicable Table 1 SCS.

6.3.16 GROUNDWATER– ORGANOCHLORINE PESTICIDES

Three (3) groundwater samples were collected and submitted for analysis of OCPs. The groundwater analytical results for OCPs are provided in Table 13 A/B and the results of the laboratory analyses indicated that all samples analysed met the applicable Table 1 SCS.

6.3.17 SEDIMENT QUALITY

Sediment testing was not a part of this scope of work.

6.4 QUALITY ASSURANCE AND QUALITY CONTROL RESULTS

Ten (10) blind field duplicate soil samples were submitted for analysis. The calculated RPDs largely met the recommended performance criteria outlined in the 2011 Protocol, indicating acceptable correlation between samples. However, WSP notes that the nickel result in BH21-20 could not be reproduced by the laboratory within the accepted range of ≤ 30%. This result is attributed to sample heterogeneity and is not necessarily an indication on data reliability.

Four (4) blind field duplicate groundwater samples were collected. The calculated RPDs largely met the recommended performance criteria outlined in the 2011 Protocol, indicating acceptable correlation between samples. However, WSP notes that the PAH results in BH21-45 could not be reproduced within the accepted range of ≤ 30%, and metals could not be reproduced within the accepted range of ≤ 20%. These results may be attributed to sediment bias. Additional sampling via low flow technique is recommended to further assess the PAH presence identified in groundwater sampled from BH21-45.

Soil and groundwater duplicates with their parent samples and analyzed parameters are outlined in **Table 6.6.**

Three (3) trip blanks (distilled water samples), prepared by the laboratory, travelled along with the November and December 2021 groundwater samples and were analyzed by the laboratory for VOCs. The concentrations were below the RDL, indicating no contamination from the sample containers, preservatives, and transportation and storage conditions.

Table 6.6 Summary of QA/QC Results

DATE	MEDIA	SAMPLE ID	FIELD DUPLICATE ID	PARAMETERS	QA/QC RESULTS
28-Oct-21	Soil	BH21-34 S1	QAQC-1	PCBs, OCPs	All results were within the 2011 Protocol criteria for RPD
		BH21-34 S2	QAQC-2	Metals & ORPs	All results were within the 2011 Protocol criteria for RPD
8-Nov-21		BH21-28 SS1	QAQC-3	Metals & ORPs	All results were within the 2011 Protocol criteria for RPD
28-Oct-21		BH21-34 S3	QAQC-3b	PAHs	All results were within the 2011 Protocol criteria for RPD
8-Nov-21		BH21-28 SS2	QAQC-4	PHCs, BTEX	All results were within the 2011 Protocol criteria for RPD
8-Nov-21		BH21-28 SS3	QAQC-5	PAHs, PCBs, OCPs	All results were within the 2011 Protocol criteria for RPD

23-Nov-21		BH21-20 SS1	QAQC-6	Metals & ORPs	The results for nickel exceeded the RPD criteria for metals in soil; sample heterogeneity is attributed to the disparity on reproducibility. All other results were within the 2011 Protocol criteria for RPD*
		BH21-20 SS2	QAQC-7	PAHs, PCBs, OCPs	All results were within the 2011 Protocol criteria for RPD
		BH21-20 SS3	QAQC-8	PHCs, BTEX	All results were within the 2011 Protocol criteria for RPD
1-Dec-21		BH21-16 SS2	QAQC-10	PAHs	All results were within the 2011 Protocol criteria for RPD
2-Dec-21		BH21-3 SS1	QAQC-12	Metals & ORPs	All results were within the 2011 Protocol criteria for RPD
1-Dec-21	Groundwater	BH21-45	QA/QC	PAHs, PCBs, OCPs, Metals & ORPs, PHCs, VOCs	The following parameters exceed the RPD criteria for PAHs and metals. Sample heterogeneity is attributed to the disparity on reproducibility. All other results were within the 2011 Protocol criteria for RPD*
6-Dec-21		BH21-16	QAQC-1	VOCs	All results were within the 2011 Protocol criteria for RPD
6-Dec-21		BH21-6	QAQC-2	PHCs/BTEX	All results were within the 2011 Protocol criteria for RPD
2-Dec-21		BH21-8	QAQC-2b	PAHs	All results were within the 2011 Protocol criteria for RPD

* With regards to the reliability of the results of BH21-20 (soil) and BH21-45 (groundwater), the reported concentrations are assumed valid.

AGAT Laboratories carried out internal QA/QC measures including process recoveries, blanks, and replicate samples. The laboratory QA/QC results are provided on the Certificates of Analysis in **Appendix B**. The results were acceptable and therefore suitable for interpretation. The laboratory QA/QC results are provided on the Certificates of Analysis in **Appendix B**.

7 CONCLUSIONS & RECOMMENDATIONS

Based on the Limited Phase II ESA conducted by WSP, the following conclusions are set forth:

- There were no investigation locations (soil or groundwater) that reported concentrations / values in excess of the MECP Table 1 SCS within Mississauga footprint of the Site. Therefore, no further assessment is considered warranted at this time within the Mississauga footprint of the Site.
- Three (3) soil samples collected within the Brampton footprint of the Site at a depth interval of 0.0 to 0.6 mgbs (BH21-7 SS1, BH21-8 SS1 and BH21-45 SS1) did not meet the applicable MECP Table 1 SCS for PAHs. Additional evaluation through Due Diligence Risk Assessment (DDRA) is recommended.
- Two (2) soil samples collected within the Brampton footprint of the Site at a depth interval of 0.0 to 0.6 mbgs (BH21-16 SS1 and BH21-20 SS1) did not meet the applicable MECP Table 1 SCS for metals. Additional evaluation through DDRA is recommended.
- One (1) soil sample collected within the Brampton footprint of the Site at a depth interval of 7.6 to 8.2 mbgs (BH21-45 SS8) did not meet the applicable Table 1 SCS for PHCs (F1) and BTEX (ethylbenzene and xylenes). Additional evaluation through DDRA is recommended.
- Shallow groundwater quality within the Brampton footprint of the Site did not meet the MECP Table 1 SCS as of December 7, 2021. In particular, contaminant exceedances were identified at BH21-6 (cobalt and chromium; WSP notes that elevated chloride at BH21-6 does not warrant further assessment per Section 49.1 of O. Reg. 153/04 as the standard is considered met), BH21-16 (molybdenum) and BH 21-45 (molybdenum and PAHs). At the request of the Client, resampling of BH21-16 (molybdenum) and BH21-45 (molybdenum and PAHs) was undertaken on February 11, 2022, using low-flow sampling techniques. Molybdenum was detected in both confirmatory samples from BH21-16 and BH21-45 at concentrations greater than the Table 1 SCS. PAHs were not detected in the confirmatory sample from BH21-45. It is therefore inferred that the PAHs measured in the original groundwater sample from BH21-45 may have been influenced by sediment in the sample and may not be representative of the groundwater quality in this monitoring well. Additional evaluation through DDRA is recommended[2].
- The risk potential for off-Site adverse effects relative to any migration of molybdenum via groundwater transport relative to concentrations observed in shallow groundwater monitoring wells BH21-16 and BH21-45 is considered low. The molybdenum concentrations are inferred to be related to the presence of clayey soil. Further, the Table 2 and 8 SCS were both met.
- The risk potential for off-Site adverse effects relative to any migration of chromium via groundwater transport relative to the concentration observed in shallow groundwater monitoring well BH21-6 is considered low. While there is insufficient information to draw conclusions on the nature (anthropogenic vs. naturally occurring) of this contaminant in shallow groundwater, the Table 2 and 8 SCS were both met.
- The risk potential for off-Site adverse effects relative to any migration of cobalt via groundwater transport relative to the concentration observed in shallow groundwater monitoring well BH21-6 is

[2] The Brampton DDRA maintained a conservative approach and considered the PAH concentrations in the original groundwater sample from BH21-45 as a worst-case scenario.

increased relative to molybdenum and/or chromium concentrations identified at BH21-6, BH21-6 and/or BH21-45 on the basis that the Table 2 and 8 SCS were not met. Additional evaluation through DDRA is recommended.

- Four (4) soil samples collected within the Caledon footprint of the Site at depth intervals of 0.0 to 0.6 mbgs (BH21-10 S1, BH21-32 SS1 and BH21-36 SS1) and 0.6 to 1.2 mbgs (BH21-41 S2) did not meet the applicable MECP Table 1 SCS for metals and/or mercury. Additional evaluation through DDRA is recommended.
- Two (2) soil samples collected within the Caledon footprint of the Site at depth intervals of 1.5 to 2.1 mbgs (BH21-9 SS3) and 1.2 to 1.8 mbgs (BH21-40 S3) did not meet the applicable MECP Table 1 SCS for PAHs. Additional evaluation through DDRA is recommended.
- Two (2) soil samples collected within the Caledon footprint of the Site at depth intervals of 0.6 to 1.2 mbgs (BH21-31 S2) and 0.0 to 0.6 mbgs (BH21-41 S1) did not meet the applicable MECP Table 1 SCS for PHCs (F2; BH21-31 S2) or BTEX (xylenes; BH21-41 S1). Additional evaluation through DDRA is recommended.
- As an alternative to implementation of risk-management measures within the Caledon footprint of the Site, the Client could consider additional assessment (to further characterize lateral and vertical extents of impact) and subsequent implementation of excavation and disposal of impacted soil identified at BH21-10, BH21-41 and BH21-36. Confirmatory soil sampling and testing would be required to confirm the appropriateness of remedial excavation limits.
- Once the groundwater wells are no longer required for monitoring or sampling purposes, these wells are recommended to be appropriately decommissioned by a licensed well contractor as required by O. Reg. 903.

7.1 QUALIFIER

This assignment is limited to the completion of a Limited Phase II ESA and analysis of potential contamination at the selected borehole locations. This report is prepared for the Region of Peel's sole use in the evaluation of the former Orangeville Rail property in Mississauga, Brampton and Caledon.

The Limited Phase II ESA, sampling, and laboratory analyses were completed as documented in the report. Extrapolation of data beyond the borehole locations assumes that homogenous conditions exist beyond the sampling locations, which may not be the case. Therefore, it is not feasible to state conclusively, that the subsurface conditions encountered during this investigation exist beyond the sampled locations.

The conclusions provided in this report reflect our best judgment in light of the information available at the time of report preparation. Any use, which a third party makes of this report, or any reliance on or any decisions to be made based on it, is the responsibility of such third parties. WSP accepts no responsibility for damages, if any, suffered by any third party because of decisions or actions taken, based on this report. Conclusions documented in this report do not apply to other land uses. It is understood that Site conditions, environmental or otherwise, are not static and that this report documents Site conditions at the time of the investigation.

7.2 QUALIFICATIONS OF THE ASSESSORS

This report was prepared by Ms. Joanna West, GIT, who is currently an Environmental Scientist in the Toronto, Ontario office of WSP Canada Inc. She obtained an Honours Bachelor of Science degree in geology and a Master of Earth Sciences degree from the University of Toronto and has experience in conducting Phase One and Two ESAs on numerous residential, commercial, and industrial properties.

The conduct of this Limited Phase II ESA was supervised / reviewed by Mr. Christopher (Chris) Johnston, M.A., P.Geo. (Limited), QP_{ESA}, currently the Toronto Area Team Lead for Contaminated Lands for WSP Canada Inc. Chris is licenced by Professional Geoscientists Ontario to practice in environmental site assessment and remediation, including contaminant hydrogeology, and is a Qualified Person for Environmental Site Assessment under Ontario Regulation 153/04. With 23 years of experience, Chris has conducted and managed hundreds of environmental investigations including Phase One ESAs, Phase II ESAs, and various site remediation projects across Ontario.

8 REFERENCES

- Ontario Ministry of the Environment, Conservation and Parks (MECP). 1996. Guidance on Sampling and Analytical Methods for Use at Contaminated Sites in Ontario. December 1996.
- Ontario Ministry of the Environment, Conservation and Parks (MECP). 2011b. Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act. July 1, 2011.
- Ontario Ministry of the Environment, Conservation and Parks (MECP). 2011c. Protocol for Analytical Methods Used in the Assessment of Properties under Past XV.1 of the Environmental Protection Act. July 1, 2011.
- Ontario Ministry of Northern Development and Mines (MNDM). 2016. Ontario Geological Society Maps. 2016.
- Ontario Ministry of the Environment, Conservation and Parks (MECP). 2016a. Environmental Monitoring and Reporting Branch Well Records. https://www.ontario.ca/environment-and-energy/map-well-records. Accessed January 4, 2021.
- Ontario Ministry of the Environment, Conservation and Parks (MECP). 2013. Ontario Regulation 903: "Wells." R.R.O. 1990, under the Ontario Water Resources Act, as amended by O.Reg. 331/13.
- Environmental Risk Information Services (ERIS) 2018. ERIS Database Report, ORDC, Mississauga to Orangeville, ON. Requested by WSP Canada Inc. on February 25, 2020.
- WSP Canada Inc. (WSP) *Contaminant Overview Study, Former Orangeville Rail, Mississauga, Brampton and Caledon, ON*. June 2020.

TABLES

Notes for Soil & Groundwater Summary Tables - Mississauga (A-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 1 RPIICC = Full Depth Background Site Condition Standards as contained in Table 1 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011

11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 1 SCS

Table 1A Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-12	BH21-44
Installed By			WSP	WSP
Installation Date			18-Nov-21	17-Nov-21
Well Status			Active	Active
Well Inner Diameter		(mm)	50	50
Casing Type (Flushmount / Monument)			Flushmount	Flushmount
Top of Pipe Elevation		(masl)	173.241	172.853
Ground Surface Elevation		(masl)	173.341	172.953
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	1.3	0.3
		(masl)	172.041	172.653
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	1.6	1.6
		(masl)	171.8	171.4
Top of Well Screen		(mbgs)	2.2	2.2
		(masl)	171.1	170.8
Screen Length		(m)	3.0	3.0
Bottom of Screen		(mbgs)	5.2	5.2
		(masl)	168.2	167.8
22-Nov-21	Depth of GW	(mbgs)	4.3	1.6
	GW Elevation	(masl)	169.0	171.4
23-Nov-21	Depth of GW	(mbgs)	4.3	1.8
	GW Elevation	(masl)	169.0	171.2
7-Dec-21	Depth of GW	(mbgs)	4.3	1.5
	GW Elevation	(masl)	169.0	171.4

See "Notes for Soil and Groundwater Summary

Table 2A Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-1	SS1	0.0 - 0.6	17-Nov-21	-	-	-	-	✓	✓	13, 14, 38, 98, 114
	SS2	0.6 - 1.2		✓	-	-	✓	-	-	
	SS3	1.2 - 1.8		-	✓	-	-	-	-	
BH21-12	SS1	0.0 - 0.6	18-Nov-21	-	-	-	✓	-	-	13, 14, 38, 114
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-42	SS1	0.0 - 0.6	18-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-43	SS1	0.0 - 0.6	17-Nov-21	-	-	-	✓	✓	✓	13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-44	SS1	0.0 - 0.6	17-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS4	2.3 - 2.9		-	✓	-	-	-	-	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3A Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-12	2.2 - 5.2	23-Nov-21	✓	✓	-	✓	✓	✓	13, 14, 38, 114
BH21-44	2.2 - 5.2	23-Nov-21	✓	✓	-	✓	✓	✓	13, 14, 38, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4A Soil Analytical Results - Metals & ORPs

Parameter		BH21-1 SS2	BH21-42 SS1	BH21-43 SS2	BH21-44 SS1
Date of Collection	Table 1 RPIICC	Nov 17, 2021	Nov 18, 2021	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 29, 2021	Nov 29, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831991	21T831518	21T831518
Antimony	1.3	<0.8	<0.8	<0.8	<0.8
Arsenic	18	5	7	3	9
Barium	220	55.6	49.2	28.8	37.7
Beryllium	2.5	<0.4	<0.4	<0.4	<0.4
Boron	36	6	7	<5	5
Boron (Hot Water Extractable)	NA	<0.10	<0.10	<0.10	0.10
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5
Chromium	70	17	19	8	13
Cobalt	21	9.1	9.2	3.1	6.2
Copper	92	20.3	35.3	7.2	28.4
Lead	120	7	15	4	14
Molybdenum	2	<0.5	<0.5	<0.5	<0.5
Nickel	82	17	20	6	12
Selenium	1.5	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	0.6	<0.50	<0.50	<0.50
Vanadium	86	22.2	25.3	15.5	18.9
Zinc	290	45	51	25	39
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.57	0.508	0.110	0.103	0.107
Sodium Adsorption Ratio	2.4	0.233	0.090	0.089	0.068
pH, 2:1 CaCl2 Extraction	*	7.67	7.62	7.53	7.63

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5A Soil Analytical Results - PHCs & BTEX

Parameter		BH21-1 SS3	BH21-12 SS3	BH21-42 SS3	BH21-43 SS6	BH21-44 SS4
Date of Collection	Table 1 RPIICC	Nov 17, 2021	Nov 18, 2021	Nov 18, 2021	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 26, 2021	Nov 29, 2021	Nov 29, 2021
Sampling Depth (mbgs)		1.5 - 2.1	1.5 - 2.1	1.5 - 2.1	4.6 - 5.2	2.3 - 2.9
Analytical Report Reference No.		21T831518	21T831991	21T831991	21T831518	21T831518
Benzene	0.02	<0.005	<0.005	<0.005	<0.005	<0.005
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.01	<0.01	<0.01	<0.01	<0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<10	<10	<10	<10	<10
F2 (C10 to C16)	10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	31	61	32	16	<10
F4 (C34 to C50)	120	11	22	12	15	<10

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 6A Soil Analytical Results - VOCs

Parameter		BH21-43 SS6
Date of Collection	Table 1 RPIICC	Nov 17, 2021
Date Reported		Nov 29, 2021
Sampling Depth (mbgs)		4.6 - 5.2
Analytical Report Reference No.		21T831518
Acetone	0.5	<0.1
Benzene	0.02	<0.005
Bromodichloromethane	0.05	<0.01
Bromoform	0.05	<0.01
Bromomethane	0.05	<0.01
Carbon Tetrachloride	0.05	<0.0005
Chlorobenzene	0.05	<0.01
Chloroform	0.05	<0.01
Dibromochloromethane	0.05	<0.01
Dichlorobenzene, 1,2-	0.05	<0.01
Dichlorobenzene, 1,3-	0.05	<0.01
Dichlorobenzene, 1,4-	0.05	<0.01
Dichlorodifluoromethane	0.05	<0.01
Dichloroethane, 1,1-	0.05	<0.01
Dichloroethane, 1,2-	0.05	<0.002
Dichloroethylene, 1,1-	0.05	<0.01
Dichloroethylene, Cis- 1,2-	0.05	<0.01
Dichloroethylene, Trans- 1,2-	0.05	<0.01
Dichloropropane, 1,2-	0.05	<0.01
1,3-Dichloropropene (Cis + Trans)	0.05	<0.01
Ethylbenzene	0.05	<0.01
Ethylene Dibromide	0.05	<0.01
Hexane, n-	0.05	-
Methyl Ethyl Ketone	0.5	<0.1
Methyl Isobutyl Ketone	0.5	<0.1
Methyl tert-butyl Ether	0.05	<0.01
Methylene Chloride	0.05	<0.01
Styrene	0.05	<0.01
Tetrachloroethane, 1,1,1,2-	0.05	<0.01
Tetrachloroethane, 1,1,2,2-	0.05	<0.01
Tetrachloroethylene	0.05	-
Toluene	0.2	<0.01
Trichloroethane, 1,1,1-	0.05	<0.01
Trichloroethane, 1,1,2-	0.05	<0.01
Trichloroethylene	0.05	<0.01
Trichlorofluoromethane	0.25	<0.01
Vinyl Chloride	0.02	<0.0002
Xylene mixture	0.05	<0.01

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7A Soil Analytical Results - PAHs

Parameter		BH21-1 SS1	BH21-12 SS1	BH21-43 SS1
Date of Collection	Table 1 RPIICC	Nov 17, 2021	Nov 18, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 29, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831991	21T831518
Naphthalene	0.09	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05
Fluorene	0.12	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05
Anthracene	0.16	<0.05	<0.05	<0.05
Fluoranthene	0.56	<0.05	0.06	0.07
Pyrene	1	<0.05	0.06	0.07
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05
Chrysene	2.8	<0.05	<0.05	0.06
Benzo(b)fluoranthene	0.47	<0.05	0.13	0.11
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	0.08	0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	0.09	0.06
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	0.11	0.07
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 8A Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-1 SS1	BH21-43 SS1
Date of Collection	Table 1 RPIICC	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 29, 2021
Sampling Depth (m bgs)		0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831518
Polychlorinated Biphenyls	0.3	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007
DDD	0.05	<0.007	<0.007
DDE	0.05	<0.007	<0.007
DDT	1.4	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005
Endrin	0.04	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005
Hexachlorobenzene	0.01	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9A Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-12	BH21-44
Date of Collection	Table 1 GW	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Antimony	1.5	<1.0	<1.0
Arsenic	13	7.8	2
Barium	610	119	101
Beryllium	0.5	<0.50	<0.50
Boron	1700	221	38
Cadmium	0.5	<0.20	<0.20
Chromium	11	<2.0	<2.0
Chromium VI	25	<2.0	<2.0
Cobalt	3.8	<0.50	0.67
Copper	5	1.7	<1.0
Cyanide	5	<2.0	<2.0
Lead	1.9	<0.50	<0.50
Mercury	0.1	<0.02	<0.02
Molybdenum	23	5.87	0.8
Nickel	14	1.9	<1.0
Selenium	5	1.6	3.3
Silver	0.3	<0.20	<0.20
Thallium	0.5	<0.30	<0.30
Uranium	8.9	1.74	1.65
Vanadium	3.9	0.78	1.01
Zinc	160	<5.0	<5.0
Sodium	490000	30100	8980
Chloride	790000	7260	7770

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 10A Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-12	BH21-44
Date of Collection	Table 1 GW	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Benzene	0.5	<0.20	<0.20
Toluene	0.8	<0.20	0.41
Ethylbenzene	0.5	<0.10	<0.10
Xylene Mixture	72	<0.20	<0.20
F1 (C6 to C10) minus BTEX	420	<25	<25
F2 (C10 to C16)	150	<100	<100
F3 (C16 to C34)	500	<100	<100
F4 (C34 to C50)	500	<100	<100

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 11A Groundwater Analytical Results - VOCs

NO MISSISSAUGA DATA

Table 12A Groundwater Analytical Results - PAHs

Parameter		BH21-12	BH21-44
Date of Collection	Table 1 GW	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Acenaphthene	4.1	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20
Anthracene	0.1	<0.10	<0.10
Benz(a)anthracene	0.2	<0.20	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10
Chrysene	0.1	<0.10	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20
Fluoranthene	0.4	<0.20	<0.20
Fluorene	120	<0.20	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20
Methyl Naphthalene, 2-and 1-	2	<0.20	<0.20
Naphthalene	7	<0.20	<0.20
Phenanthrene	0.1	<0.10	<0.10
Pyrene	0.2	<0.20	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 13A Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-12	BH21-44
Date of Collection	Table 1 GW	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Polychlorinated Biphenyls	0.2	<0.1	<0.1
Aldrin	0.01	<0.01	<0.01
Chlordane	0.06	<0.04	<0.04
DDD	1.8	<0.05	<0.05
DDE	10	<0.01	<0.01
DDT	0.05	<0.04	<0.04
Dieldrin	0.05	<0.02	<0.02
Endosulfan	0.05	<0.05	<0.05
Endrin	0.05	<0.05	<0.05
Heptachlor	0.01	<0.01	<0.01
Heptachlor Epoxide	0.01	<0.01	<0.01
Hexachlorobenzene	0.01	<0.01	<0.01
Hexachlorobutadiene	0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.01	<0.01
Hexachloroethane	0.01	<0.01	<0.01
Methoxychlor	0.05	<0.04	<0.04

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14A Summary of Maximum Concentrations in Soil

Group	Parameter	Table 1 RPIICC	Maximum Concentration	Location
BTEX	Benzene	0.02	<0.005	all samples
	Ethylbenzene	0.05	<0.01	all samples
	Toluene	0.2	<0.05	all samples
	Total Xylenes	0.05	<0.05	all samples
Metals	Barium	220	55.6	BH21-1 SS2
	Beryllium	2.5	<0.4	all samples
	Boron	36	7	BH21-42 SS1
	Cadmium	1.2	<0.5	all samples
	Chromium	70	19	BH21-42 SS1
	Cobalt	21	9.2	BH21-42 SS1
	Copper	92	35.3	BH21-42 SS1
	Lead	120	15	BH21-42 SS1
	Molybdenum	2	<0.5	all samples
	Nickel	82	20	BH21-42 SS1
	Silver	0.5	<0.5	all samples
	Thallium	1	<0.5	all samples
	Uranium	2.5	0.6	BH21-1 SS2
	Vanadium	86	25.3	BH21-42 SS1
	Zinc	290	51	BH21-42 SS1
As, Se, Sb	Antimony	1.3	<0.8	all samples
	Arsenic	18	9	BH21-44 SS1
	Selenium	1.5	<0.8	all samples
PAHs	Acenaphthene	0.072	<0.05	all samples
	Acenaphthylene	0.093	<0.05	all samples
	Anthracene	0.16	<0.05	all samples
	Benz(a)anthracene	0.36	<0.05	all samples
	Benzo(a)pyrene	0.3	0.08	BH21-12 SS1
	Benzo(b)fluoranthene	0.47	0.13	BH21-12 SS1
	Benzo(g,h,i)perylene	0.68	0.11	BH21-12 SS1
	Benzo(k)fluoranthene	0.48	<0.05	all samples
	Chrysene	2.8	0.06	BH21-43 SS1
	Dibenz(a,h)anthracene	0.1	<0.05	all samples
	Fluoranthene	0.56	0.07	BH21-43 SS1
	Fluorene	0.12	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.23	0.09	BH21-12 SS1
	Methylnaphthalene, 2-(1-)	0.59	<0.05	all samples
	Naphthalene	0.09	<0.05	all samples
	Phenanthrene	0.69	<0.05	all samples
	Pyrene	1	0.07	BH21-43 SS1
PHCs	F1 (C6 to C10) minus BTEX	25	<10	all samples
	F2 (C10 to C16)	10	<10	all samples
	F3 (C16 to C34)	240	61	BH21-12 SS3
	F4 (C34 to C50)	120	22	BH21-12 SS3
	Acetone	0.5	<0.1	all samples
	Bromodichloromethane	0.05	<0.01	all samples
	Bromoform	0.05	<0.01	all samples
	Bromomethane	0.05	<0.01	all samples
	Carbon Tetrachloride	0.05	<0.0005	all samples
	Chlorobenzene	0.05	<0.01	all samples
	Chloroform	0.05	<0.01	all samples
	Dibromochloromethane	0.05	<0.01	all samples
	Dichlorobenzene, 1,2-	0.05	<0.01	all samples

Table 14A Summary of Maximum Concentrations in Soil

Group	Parameter	Table 1 RPIICC	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	0.05	<0.01	all samples
	Dichlorobenzene, 1,4-	0.05	<0.01	all samples
	Dichlorodifluoromethane	0.05	<0.01	all samples
	Dichloroethane, 1,1-	0.05	<0.01	all samples
	Dichloroethane, 1,2-	0.05	<0.002	all samples
	Dichloroethylene, 1,1-	0.05	<0.01	all samples
	Dichloroethylene, Cis- 1,2-	0.05	<0.01	all samples
	Dichloroethylene, Trans- 1,2-	0.05	<0.01	all samples
	Dichloropropane, 1,2-	0.05	<0.01	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.01	all samples
	Ethylene Dibromide	0.05	<0.01	all samples
	Hexane, n-	0.05	-	all samples
	Methyl Ethyl Ketone	0.5	<0.1	all samples
	Methyl Isobutyl Ketone	0.5	<0.1	all samples
	Methyl tert-butyl Ether	0.05	<0.01	all samples
	Methylene Chloride	0.05	<0.01	all samples
	Styrene	0.05	<0.01	all samples
	Tetrachloroethane, 1,1,1,2-	0.05	<0.01	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.01	all samples
	Tetrachloroethylene	0.05	-	all samples
	Trichloroethane, 1,1,1-	0.05	<0.01	all samples
	Trichloroethane, 1,1,2-	0.05	<0.01	all samples
	Trichloroethylene	0.05	<0.01	all samples
	Trichlorofluoromethane	0.25	<0.01	all samples
	Vinyl Chloride	0.02	<0.0002	all samples
ORPs	Chromium, Hexavalent	0.66	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.57	0.508	BH21-1 SS2
	Mercury	0.27	<0.10	all samples
	Sodium Adsorption Ratio	2.4	0.233	BH21-1 SS2
	pH, 2:1 CaCl2 Extraction	*	7.67	BH21-1 SS2
PCBs	Polychlorinated Biphenyls	0.3	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15A Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 1 GW	Maximum Concentration	Location
BTEX	Benzene	0.5	<0.20	all samples
	Ethylbenzene	0.5	<0.10	all samples
	Toluene	0.8	0.41	BH21-44
	Xylene Mixture	72	<0.20	all samples
Metals	Barium	610	119	BH21-12
	Beryllium	0.5	<0.50	all samples
	Boron	1700	221	BH21-12
	Cadmium	0.5	<0.20	all samples
	Chromium	11	<2.0	all samples
	Cobalt	3.8	0.67	BH21-44
	Copper	5	1.7	BH21-12
	Lead	1.9	<0.50	all samples
	Molybdenum	23	5.87	BH21-12
	Nickel	14	1.9	BH21-12
	Silver	0.3	<0.20	all samples
	Thallium	0.5	<0.30	all samples
	Uranium	8.9	1.74	BH21-12
	Vanadium	3.9	1.01	BH21-44
	Zinc	160	<5.0	all samples
As, Se, Sb	Antimony	1.5	<1.0	all samples
	Arsenic	13	7.8	BH21-12
	Selenium	5	3.3	BH21-44
Na	Sodium	490000	30100	BH21-12
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	0.1	<0.10	all samples
	Benz(a)anthracene	0.2	<0.20	all samples
	Benzo(a)pyrene	0.01	<0.01	all samples
	Benzo(b)fluoranthene	0.1	<0.10	all samples
	Benzo(g,h,i)perylene	0.2	<0.20	all samples
	Benzo(k)fluoranthene	0.1	<0.10	all samples
	Chrysene	0.1	<0.10	all samples
	Dibenz(a,h)anthracene	0.2	<0.20	all samples
	Fluoranthene	0.4	<0.20	all samples
	Fluorene	120	<0.20	all samples
	Indeno(1,2,3-cd)pyrene	0.2	<0.20	all samples
	Methyl Naphthalene, 2-and 1-	2	<0.20	all samples
	Naphthalene	7	<0.20	all samples
	Phenanthrene	0.1	<0.10	all samples
	Pyrene	0.2	<0.20	all samples
PHCs	F1 (C6 to C10) minus BTEX	420	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	2	<0.20	all samples
	Bromoform	5	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.2	<0.20	all samples
	Chlorobenzene	0.5	<0.10	all samples
	Chloroform	2	<0.20	all samples

Table 15A Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 1 GW	Maximum Concentration	Location
VOCs	Dibromochloromethane	2	<0.10	all samples
	Dichlorobenzene, 1,2-	0.5	<0.10	all samples
	Dichlorobenzene, 1,3-	0.5	<0.10	all samples
	Dichlorobenzene, 1,4-	0.5	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	0.5	<0.30	all samples
	Dichloroethane, 1,2-	0.5	<0.20	all samples
	Dichloroethylene, 1,1-	0.5	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	0.5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	5	<0.20	all samples
	Methyl Ethyl Ketone	400	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	5	<0.30	all samples
	Styrene	0.5	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	0.5	<0.10	all samples
	Tetrachloroethylene	0.5	<0.20	all samples
	Trichloroethane, 1,1,1-	0.5	<0.30	all samples
	Trichloroethane, 1,1,2-	0.5	<0.20	all samples
	Trichloroethylene	0.5	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	7770	BH21-44
	Chromium VI	25	<2.0	all samples
	Cyanide	5	<2.0	all samples
	Mercury	0.1	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Notes for Soil & Groundwater Summary Tables - Mississauga (A-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 2 RPI CT = Full Depth Generic Site Condition Standards in a Potable Ground Water Condition with Coarse Textured Soils as contained in Table 2 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011
11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 2 SCS

Table 1A Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-12	BH21-44
Installed By			WSP	WSP
Installation Date			18-Nov-21	17-Nov-21
Well Status			Active	Active
Well Inner Diameter		(mm)	50	50
Casing Type (Flushmount / Monument)			Flushmount	Flushmount
Top of Pipe Elevation		(masl)	173.241	172.853
Ground Surface Elevation		(masl)	173.341	172.953
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	1.3	0.3
		(masl)	172.041	172.653
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	1.6	1.6
		(masl)	171.8	171.4
Top of Well Screen		(mbgs)	2.2	2.2
		(masl)	171.1	170.8
Screen Length		(m)	3.0	3.0
Bottom of Screen		(mbgs)	5.2	5.2
		(masl)	168.2	167.8
22-Nov-21	Depth of GW	(mbgs)	4.3	1.6
	GW Elevation	(masl)	169.0	171.4
23-Nov-21	Depth of GW	(mbgs)	4.3	1.8
	GW Elevation	(masl)	169.0	171.2
7-Dec-21	Depth of GW	(mbgs)	4.3	1.5
	GW Elevation	(masl)	169.0	171.4

See "Notes for Soil and Groundwater Summary

Table 2A Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-1	SS1	0.0 - 0.6	17-Nov-21	-	-	-	-	✓	✓	13, 14, 38, 98, 114
	SS2	0.6 - 1.2		✓	-	-	✓	-	-	
	SS3	1.2 - 1.8		-	✓	-	-	-	-	
BH21-12	SS1	0.0 - 0.6	18-Nov-21	-	-	-	✓	-	-	13, 14, 38, 114
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-42	SS1	0.0 - 0.6	18-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-43	SS1	0.0 - 0.6	17-Nov-21	-	-	-	✓	✓	✓	13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-44	SS1	0.0 - 0.6	17-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS4	2.3 - 2.9		-	✓	-	-	-	-	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3A Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-12	2.2 - 5.2	23-Nov-21	✓	✓	-	✓	✓	✓	13, 14, 38, 114
BH21-44	2.2 - 5.2	23-Nov-21	✓	✓	-	✓	✓	✓	13, 14, 38, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4A Soil Analytical Results - Metals & ORPs

Parameter		BH21-1 SS2	BH21-42 SS1	BH21-43 SS2	BH21-44 SS1
Date of Collection	Table 2 RPI CT	Nov 17, 2021	Nov 18, 2021	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 29, 2021	Nov 29, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831991	21T831518	21T831518
Antimony	7.5	<0.8	<0.8	<0.8	<0.8
Arsenic	18	5	7	3	9
Barium	390	55.6	49.2	28.8	37.7
Beryllium	4	<0.4	<0.4	<0.4	<0.4
Boron	120	6	7	<5	5
Boron (Hot Water Extractable)	1.5	<0.10	<0.10	<0.10	0.10
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5
Chromium	160	17	19	8	13
Cobalt	22	9.1	9.2	3.1	6.2
Copper	140	20.3	35.3	7.2	28.4
Lead	120	7	15	4	14
Molybdenum	6.9	<0.5	<0.5	<0.5	<0.5
Nickel	100	17	20	6	12
Selenium	2.4	<0.8	<0.8	<0.8	<0.8
Silver	20	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5
Uranium	23	0.6	<0.50	<0.50	<0.50
Vanadium	86	22.2	25.3	15.5	18.9
Zinc	340	45	51	25	39
Chromium, Hexavalent	8	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.508	0.110	0.103	0.107
Sodium Adsorption Ratio	5	0.233	0.090	0.089	0.068
pH, 2:1 CaCl2 Extraction	*	7.67	7.62	7.53	7.63

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5A Soil Analytical Results - PHCs & BTEX

Parameter		BH21-1 SS3	BH21-12 SS3	BH21-42 SS3	BH21-43 SS6	BH21-44 SS4
Date of Collection	Table 2 RPI CT	Nov 17, 2021	Nov 18, 2021	Nov 18, 2021	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 26, 2021	Nov 29, 2021	Nov 29, 2021
Sampling Depth (mbgs)		1.5 - 2.1	1.5 - 2.1	1.5 - 2.1	4.6 - 5.2	2.3 - 2.9
Analytical Report Reference No.		21T831518	21T831991	21T831991	21T831518	21T831518
Benzene	0.21	<0.005	<0.005	<0.005	<0.005	<0.005
Toluene	2.3	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.01	<0.01	<0.01	<0.01	<0.01
Total Xylenes	3.1	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	55	<10	<10	<10	<10	<10
F2 (C10 to C16)	98	<10	<10	<10	<10	<10
F3 (C16 to C34)	300	31	61	32	16	<10
F4 (C34 to C50)	2800	11	22	12	15	<10

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 6A Soil Analytical Results - VOCs

Parameter		BH21-43 SS6
Date of Collection	Table 2 RPI CT	Nov 17, 2021
Date Reported		Nov 29, 2021
Sampling Depth (mbgs)		4.6 - 5.2
Analytical Report Reference No.		21T831518
Acetone	16	<0.1
Benzene	0.21	<0.005
Bromodichloromethane	1.5	<0.01
Bromoform	0.27	<0.01
Bromomethane	0.05	<0.01
Carbon Tetrachloride	0.05	<0.0005
Chlorobenzene	2.4	<0.01
Chloroform	0.05	<0.01
Dibromochloromethane	2.3	<0.01
Dichlorobenzene, 1,2-	1.2	<0.01
Dichlorobenzene, 1,3-	4.8	<0.01
Dichlorobenzene, 1,4-	0.083	<0.01
Dichlorodifluoromethane	16	<0.01
Dichloroethane, 1,1-	0.47	<0.01
Dichloroethane, 1,2-	0.05	<0.002
Dichloroethylene, 1,1-	0.05	<0.01
Dichloroethylene, Cis- 1,2-	1.9	<0.01
Dichloroethylene, Trans- 1,2-	0.084	<0.01
Dichloropropane, 1,2-	0.05	<0.01
1,3-Dichloropropene (Cis + Trans)	0.05	<0.01
Ethylbenzene	1.1	<0.01
Ethylene Dibromide	0.05	<0.01
Hexane, n-	2.8	-
Methyl Ethyl Ketone	16	<0.1
Methyl Isobutyl Ketone	1.7	<0.1
Methyl tert-butyl Ether	0.75	<0.01
Methylene Chloride	0.1	<0.01
Styrene	0.7	<0.01
Tetrachloroethane, 1,1,1,2-	0.058	<0.01
Tetrachloroethane, 1,1,2,2-	0.05	<0.01
Tetrachloroethylene	0.28	-
Toluene	2.3	<0.01
Trichloroethane, 1,1,1-	0.38	<0.01
Trichloroethane, 1,1,2-	0.05	<0.01
Trichloroethylene	0.061	<0.01
Trichlorofluoromethane	4	<0.01
Vinyl Chloride	0.02	<0.0002
Xylene mixture	3.1	<0.01

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7A Soil Analytical Results - PAHs

Parameter		BH21-1 SS1	BH21-12 SS1	BH21-43 SS1
Date of Collection	Table 2 RPI CT	Nov 17, 2021	Nov 18, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 29, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831991	21T831518
Naphthalene	0.6	<0.05	<0.05	<0.05
Acenaphthylene	0.15	<0.05	<0.05	<0.05
Acenaphthene	7.9	<0.05	<0.05	<0.05
Fluorene	62	<0.05	<0.05	<0.05
Phenanthrene	6.2	<0.05	<0.05	<0.05
Anthracene	0.67	<0.05	<0.05	<0.05
Fluoranthene	0.69	<0.05	0.06	0.07
Pyrene	78	<0.05	0.06	0.07
Benz(a)anthracene	0.5	<0.05	<0.05	<0.05
Chrysene	7	<0.05	<0.05	0.06
Benzo(b)fluoranthene	0.78	<0.05	0.13	0.11
Benzo(k)fluoranthene	0.78	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	0.08	0.05
Indeno(1,2,3-cd)pyrene	0.38	<0.05	0.09	0.06
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	6.6	<0.05	0.11	0.07
Methylnaphthalene, 2-(1-)	0.99	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 8A Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-1 SS1	BH21-43 SS1
Date of Collection	Table 2 RPI CT	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 29, 2021
Sampling Depth (m bgs)		0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831518
Polychlorinated Biphenyls	0.35	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007
DDD	3.3	<0.007	<0.007
DDE	0.26	<0.007	<0.007
DDT	1.4	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005
Endrin	0.04	<0.005	<0.005
Heptachlor	0.15	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005
Hexachlorobenzene	0.52	<0.005	<0.005
Hexachlorobutadiene	0.012	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.056	<0.005	<0.005
Hexachloroethane	0.089	<0.01	<0.01
Methoxychlor	0.13	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9A Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-12	BH21-44
Date of Collection	Table 2 Potable GW CT	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Antimony	6	<1.0	<1.0
Arsenic	25	7.8	2
Barium	1000	119	101
Beryllium	4	<0.50	<0.50
Boron	5000	221	38
Cadmium	2.7	<0.20	<0.20
Chromium	50	<2.0	<2.0
Chromium VI	25	<2.0	<2.0
Cobalt	3.8	<0.50	0.67
Copper	87	1.7	<1.0
Cyanide	66	<2.0	<2.0
Lead	10	<0.50	<0.50
Mercury	0.29	<0.02	<0.02
Molybdenum	70	5.87	0.8
Nickel	100	1.9	<1.0
Selenium	10	1.6	3.3
Silver	1.5	<0.20	<0.20
Thallium	2	<0.30	<0.30
Uranium	20	1.74	1.65
Vanadium	6.2	0.78	1.01
Zinc	1100	<5.0	<5.0
Sodium	490000	30100	8980
Chloride	790000	7260	7770

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 10A Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-12	BH21-44
Date of Collection	Table 2 Potable GW CT	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Benzene	5	<0.20	<0.20
Toluene	24	<0.20	0.41
Ethylbenzene	2.4	<0.10	<0.10
Xylene Mixture	300	<0.20	<0.20
F1 (C6 to C10) minus BTEX	750	<25	<25
F2 (C10 to C16)	150	<100	<100
F3 (C16 to C34)	500	<100	<100
F4 (C34 to C50)	500	<100	<100

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 11A Groundwater Analytical Results - VOCs

NO MISSISSAUGA DATA

Table 12A Groundwater Analytical Results - PAHs

Parameter		BH21-12	BH21-44
Date of Collection	Table 2 Potable GW CT	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Acenaphthene	4.1	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20
Anthracene	2.4	<0.10	<0.10
Benz(a)anthracene	1	<0.20	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10
Chrysene	0.1	<0.10	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20
Fluoranthene	0.41	<0.20	<0.20
Fluorene	120	<0.20	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20
Methyl Naphthalene, 2-and 1-	3.2	<0.20	<0.20
Naphthalene	11	<0.20	<0.20
Phenanthrene	1	<0.10	<0.10
Pyrene	4.1	<0.20	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 13A Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-12	BH21-44
Date of Collection	Table 2 Potable GW CT	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Polychlorinated Biphenyls	3	<0.1	<0.1
Aldrin	0.35	<0.01	<0.01
Chlordane	7	<0.04	<0.04
DDD	10	<0.05	<0.05
DDE	10	<0.01	<0.01
DDT	2.8	<0.04	<0.04
Dieldrin	0.35	<0.02	<0.02
Endosulfan	1.5	<0.05	<0.05
Endrin	0.48	<0.05	<0.05
Heptachlor	1.5	<0.01	<0.01
Heptachlor Epoxide	0.048	<0.01	<0.01
Hexachlorobenzene	1	<0.01	<0.01
Hexachlorobutadiene	0.44	<0.01	<0.01
Hexachlorocyclohexane Gamma-	1.2	<0.01	<0.01
Hexachloroethane	2.1	<0.01	<0.01
Methoxychlor	6.5	<0.04	<0.04

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14A Summary of Maximum Concentrations in Soil

Group	Parameter	Table 2 RPI CT	Maximum Concentration	Location
BTEX	Benzene	0.21	<0.005	all samples
	Ethylbenzene	1.1	<0.01	all samples
	Toluene	2.3	<0.05	all samples
	Total Xylenes	3.1	<0.05	all samples
Metals	Barium	390	55.6	BH21-1 SS2
	Beryllium	4	<0.4	all samples
	Boron	120	7	BH21-42 SS1
	Cadmium	1.2	<0.5	all samples
	Chromium	160	19	BH21-42 SS1
	Cobalt	22	9.2	BH21-42 SS1
	Copper	140	35.3	BH21-42 SS1
	Lead	120	15	BH21-42 SS1
	Molybdenum	6.9	<0.5	all samples
	Nickel	100	20	BH21-42 SS1
	Silver	20	<0.5	all samples
	Thallium	1	<0.5	all samples
	Uranium	23	0.6	BH21-1 SS2
	Vanadium	86	25.3	BH21-42 SS1
	Zinc	340	51	BH21-42 SS1
As, Se, Sb	Antimony	7.5	<0.8	all samples
	Arsenic	18	9	BH21-44 SS1
	Selenium	2.4	<0.8	all samples
PAHs	Acenaphthene	7.9	<0.05	all samples
	Acenaphthylene	0.15	<0.05	all samples
	Anthracene	0.67	<0.05	all samples
	Benz(a)anthracene	0.5	<0.05	all samples
	Benzo(a)pyrene	0.3	0.08	BH21-12 SS1
	Benzo(b)fluoranthene	0.78	0.13	BH21-12 SS1
	Benzo(g,h,i)perylene	6.6	0.11	BH21-12 SS1
	Benzo(k)fluoranthene	0.78	<0.05	all samples
	Chrysene	7	0.06	BH21-43 SS1
	Dibenz(a,h)anthracene	0.1	<0.05	all samples
	Fluoranthene	0.69	0.07	BH21-43 SS1
	Fluorene	62	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.38	0.09	BH21-12 SS1
	Methylnaphthalene, 2-(1-)	0.99	<0.05	all samples
	Naphthalene	0.6	<0.05	all samples
	Phenanthrene	6.2	<0.05	all samples
	Pyrene	78	0.07	BH21-43 SS1
PHCs	F1 (C6 to C10) minus BTEX	55	<10	all samples
	F2 (C10 to C16)	98	<10	all samples
	F3 (C16 to C34)	300	61	BH21-12 SS3
	F4 (C34 to C50)	2800	22	BH21-12 SS3
	Acetone	16	<0.1	all samples
	Bromodichloromethane	1.5	<0.01	all samples
	Bromoform	0.27	<0.01	all samples
	Bromomethane	0.05	<0.01	all samples
	Carbon Tetrachloride	0.05	<0.0005	all samples
	Chlorobenzene	2.4	<0.01	all samples
	Chloroform	0.05	<0.01	all samples
	Dibromochloromethane	2.3	<0.01	all samples
	Dichlorobenzene, 1,2-	1.2	<0.01	all samples

Table 14A Summary of Maximum Concentrations in Soil

Group	Parameter	Table 2 RPI CT	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	4.8	<0.01	all samples
	Dichlorobenzene, 1,4-	0.083	<0.01	all samples
	Dichlorodifluoromethane	16	<0.01	all samples
	Dichloroethane, 1,1-	0.47	<0.01	all samples
	Dichloroethane, 1,2-	0.05	<0.002	all samples
	Dichloroethylene, 1,1-	0.05	<0.01	all samples
	Dichloroethylene, Cis- 1,2-	1.9	<0.01	all samples
	Dichloroethylene, Trans- 1,2-	0.084	<0.01	all samples
	Dichloropropane, 1,2-	0.05	<0.01	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.01	all samples
	Ethylene Dibromide	0.05	<0.01	all samples
	Hexane, n-	2.8	-	all samples
	Methyl Ethyl Ketone	16	<0.1	all samples
	Methyl Isobutyl Ketone	1.7	<0.1	all samples
	Methyl tert-butyl Ether	0.75	<0.01	all samples
	Methylene Chloride	0.1	<0.01	all samples
	Styrene	0.7	<0.01	all samples
	Tetrachloroethane, 1,1,1,2-	0.058	<0.01	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.01	all samples
	Tetrachloroethylene	0.28	-	all samples
	Trichloroethane, 1,1,1-	0.38	<0.01	all samples
	Trichloroethane, 1,1,2-	0.05	<0.01	all samples
	Trichloroethylene	0.061	<0.01	all samples
	Trichlorofluoromethane	4	<0.01	all samples
	Vinyl Chloride	0.02	<0.0002	all samples
ORPs	Chromium, Hexavalent	8	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.7	0.508	BH21-1 SS2
	Mercury	0.27	<0.10	all samples
	Sodium Adsorption Ratio	5	0.233	BH21-1 SS2
	pH, 2:1 CaCl2 Extraction	*	7.67	BH21-1 SS2
PCBs	Polychlorinated Biphenyls	0.35	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15A Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 2 Potable GW CT	Maximum Concentration	Location
BTEX	Benzene	5	<0.20	all samples
	Ethylbenzene	2.4	<0.10	all samples
	Toluene	24	0.41	BH21-44
	Xylene Mixture	300	<0.20	all samples
Metals	Barium	1000	119	BH21-12
	Beryllium	4	<0.50	all samples
	Boron	5000	221	BH21-12
	Cadmium	2.7	<0.20	all samples
	Chromium	50	<2.0	all samples
	Cobalt	3.8	0.67	BH21-44
	Copper	87	1.7	BH21-12
	Lead	10	<0.50	all samples
	Molybdenum	70	5.87	BH21-12
	Nickel	100	1.9	BH21-12
	Silver	1.5	<0.20	all samples
	Thallium	2	<0.30	all samples
	Uranium	20	1.74	BH21-12
	Vanadium	6.2	1.01	BH21-44
	Zinc	1100	<5.0	all samples
As, Se, Sb	Antimony	6	<1.0	all samples
	Arsenic	25	7.8	BH21-12
	Selenium	10	3.3	BH21-44
Na	Sodium	490000	30100	BH21-12
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	2.4	<0.10	all samples
	Benz(a)anthracene	1	<0.20	all samples
	Benzo(a)pyrene	0.01	<0.01	all samples
	Benzo(b)fluoranthene	0.1	<0.10	all samples
	Benzo(g,h,i)perylene	0.2	<0.20	all samples
	Benzo(k)fluoranthene	0.1	<0.10	all samples
	Chrysene	0.1	<0.10	all samples
	Dibenz(a,h)anthracene	0.2	<0.20	all samples
	Fluoranthene	0.41	<0.20	all samples
	Fluorene	120	<0.20	all samples
	Indeno(1,2,3-cd)pyrene	0.2	<0.20	all samples
	Methyl Naphthalene, 2-and 1-	3.2	<0.20	all samples
	Naphthalene	11	<0.20	all samples
	Phenanthrene	1	<0.10	all samples
	Pyrene	4.1	<0.20	all samples
PHCs	F1 (C6 to C10) minus BTEX	750	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	16	<0.20	all samples
	Bromoform	25	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.79	<0.20	all samples
	Chlorobenzene	30	<0.10	all samples
	Chloroform	2.4	<0.20	all samples

Table 15A Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 2 Potable GW CT	Maximum Concentration	Location
VOCs	Dibromochloromethane	25	<0.10	all samples
	Dichlorobenzene, 1,2-	3	<0.10	all samples
	Dichlorobenzene, 1,3-	59	<0.10	all samples
	Dichlorobenzene, 1,4-	1	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	5	<0.30	all samples
	Dichloroethane, 1,2-	1.6	<0.20	all samples
	Dichloroethylene, 1,1-	1.6	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	51	<0.20	all samples
	Methyl Ethyl Ketone	1800	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	50	<0.30	all samples
	Styrene	5.4	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	1	<0.10	all samples
	Tetrachloroethylene	1.6	<0.20	all samples
	Trichloroethane, 1,1,1-	200	<0.30	all samples
	Trichloroethane, 1,1,2-	4.7	<0.20	all samples
	Trichloroethylene	1.6	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	7770	BH21-44
	Chromium VI	25	<2.0	all samples
	Cyanide	66	<2.0	all samples
	Mercury	0.29	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Notes for Soil & Groundwater Summary Tables - Mississauga (A-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 8 RPIICC = Generic Site Condition Standards for Use within 30 m of a Water Body in a Potable Groundwater Condition as contained in Table 8 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011

11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 8 SCS

Table 1A Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-12	BH21-44
Installed By			WSP	WSP
Installation Date			18-Nov-21	17-Nov-21
Well Status			Active	Active
Well Inner Diameter		(mm)	50	50
Casing Type (Flushmount / Monument)			Flushmount	Flushmount
Top of Pipe Elevation		(masl)	173.241	172.853
Ground Surface Elevation		(masl)	173.341	172.953
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	1.3	0.3
		(masl)	172.041	172.653
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	1.6	1.6
		(masl)	171.8	171.4
Top of Well Screen		(mbgs)	2.2	2.2
		(masl)	171.1	170.8
Screen Length		(m)	3.0	3.0
Bottom of Screen		(mbgs)	5.2	5.2
		(masl)	168.2	167.8
22-Nov-21	Depth of GW	(mbgs)	4.3	1.6
	GW Elevation	(masl)	169.0	171.4
23-Nov-21	Depth of GW	(mbgs)	4.3	1.8
	GW Elevation	(masl)	169.0	171.2
7-Dec-21	Depth of GW	(mbgs)	4.3	1.5
	GW Elevation	(masl)	169.0	171.4

See "Notes for Soil and Groundwater Summary

Table 2A Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-1	SS1	0.0 - 0.6	17-Nov-21	-	-	-	-	✓	✓	13, 14, 38, 98, 114
	SS2	0.6 - 1.2		✓	-	-	✓	-	-	
	SS3	1.2 - 1.8		-	✓	-	-	-	-	
BH21-12	SS1	0.0 - 0.6	18-Nov-21	-	-	-	✓	-	-	13, 14, 38, 114
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-42	SS1	0.0 - 0.6	18-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-43	SS1	0.0 - 0.6	17-Nov-21	-	-	-	✓	✓	✓	13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-44	SS1	0.0 - 0.6	17-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS4	2.3 - 2.9		-	✓	-	-	-	-	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3A Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-12	2.2 - 5.2	23-Nov-21	✓	✓	-	✓	✓	✓	13, 14, 38, 114
BH21-44	2.2 - 5.2	23-Nov-21	✓	✓	-	✓	✓	✓	13, 14, 38, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4A Soil Analytical Results - Metals & ORPs

Parameter		BH21-1 SS2	BH21-42 SS1	BH21-43 SS2	BH21-44 SS1
Date of Collection	Table 8 RPIICC	Nov 17, 2021	Nov 18, 2021	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 29, 2021	Nov 29, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831991	21T831518	21T831518
Antimony	1.3	<0.8	<0.8	<0.8	<0.8
Arsenic	18	5	7	3	9
Barium	220	55.6	49.2	28.8	37.7
Beryllium	2.5	<0.4	<0.4	<0.4	<0.4
Boron	36	6	7	<5	5
Boron (Hot Water Extractable)	1.5	<0.10	<0.10	<0.10	0.10
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5
Chromium	70	17	19	8	13
Cobalt	22	9.1	9.2	3.1	6.2
Copper	92	20.3	35.3	7.2	28.4
Lead	120	7	15	4	14
Molybdenum	2	<0.5	<0.5	<0.5	<0.5
Nickel	82	17	20	6	12
Selenium	1.5	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	0.6	<0.50	<0.50	<0.50
Vanadium	86	22.2	25.3	15.5	18.9
Zinc	290	45	51	25	39
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.508	0.110	0.103	0.107
Sodium Adsorption Ratio	5	0.233	0.090	0.089	0.068
pH, 2:1 CaCl2 Extraction	*	7.67	7.62	7.53	7.63

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5A Soil Analytical Results - PHCs & BTEX

Parameter		BH21-1 SS3	BH21-12 SS3	BH21-42 SS3	BH21-43 SS6	BH21-44 SS4
Date of Collection	Table 8 RPIICC	Nov 17, 2021	Nov 18, 2021	Nov 18, 2021	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 26, 2021	Nov 29, 2021	Nov 29, 2021
Sampling Depth (mbgs)		1.5 - 2.1	1.5 - 2.1	1.5 - 2.1	4.6 - 5.2	2.3 - 2.9
Analytical Report Reference No.		21T831518	21T831991	21T831991	21T831518	21T831518
Benzene	0.02	<0.005	<0.005	<0.005	<0.005	<0.005
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.01	<0.01	<0.01	<0.01	<0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<10	<10	<10	<10	<10
F2 (C10 to C16)	10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	31	61	32	16	<10
F4 (C34 to C50)	120	11	22	12	15	<10

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 6A Soil Analytical Results - VOCs

Parameter		BH21-43 SS6
Date of Collection	Table 8 RPIICC	Nov 17, 2021
Date Reported		Nov 29, 2021
Sampling Depth (mbgs)		4.6 - 5.2
Analytical Report Reference No.		21T831518
Acetone	0.5	<0.1
Benzene	0.02	<0.005
Bromodichloromethane	0.05	<0.01
Bromoform	0.05	<0.01
Bromomethane	0.05	<0.01
Carbon Tetrachloride	0.05	<0.0005
Chlorobenzene	0.05	<0.01
Chloroform	0.05	<0.01
Dibromochloromethane	0.05	<0.01
Dichlorobenzene, 1,2-	0.05	<0.01
Dichlorobenzene, 1,3-	0.05	<0.01
Dichlorobenzene, 1,4-	0.05	<0.01
Dichlorodifluoromethane	0.05	<0.01
Dichloroethane, 1,1-	0.05	<0.01
Dichloroethane, 1,2-	0.05	<0.002
Dichloroethylene, 1,1-	0.05	<0.01
Dichloroethylene, Cis- 1,2-	0.05	<0.01
Dichloroethylene, Trans- 1,2-	0.05	<0.01
Dichloropropane, 1,2-	0.05	<0.01
1,3-Dichloropropene (Cis + Trans)	0.05	<0.01
Ethylbenzene	0.05	<0.01
Ethylene Dibromide	0.05	<0.01
Hexane, n-	0.05	-
Methyl Ethyl Ketone	0.5	<0.1
Methyl Isobutyl Ketone	0.5	<0.1
Methyl tert-butyl Ether	0.05	<0.01
Methylene Chloride	0.05	<0.01
Styrene	0.05	<0.01
Tetrachloroethane, 1,1,1,2-	0.05	<0.01
Tetrachloroethane, 1,1,2,2-	0.05	<0.01
Tetrachloroethylene	0.05	-
Toluene	0.2	<0.01
Trichloroethane, 1,1,1-	0.05	<0.01
Trichloroethane, 1,1,2-	0.05	<0.01
Trichloroethylene	0.05	<0.01
Trichlorofluoromethane	0.25	<0.01
Vinyl Chloride	0.02	<0.0002
Xylene mixture	0.05	<0.01

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7A Soil Analytical Results - PAHs

Parameter		BH21-1 SS1	BH21-12 SS1	BH21-43 SS1
Date of Collection	Table 8 RPIICC	Nov 17, 2021	Nov 18, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 26, 2021	Nov 29, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831991	21T831518
Naphthalene	0.09	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05
Fluorene	0.19	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05
Anthracene	0.22	<0.05	<0.05	<0.05
Fluoranthene	0.69	<0.05	0.06	0.07
Pyrene	1	<0.05	0.06	0.07
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05
Chrysene	2.8	<0.05	<0.05	0.06
Benzo(b)fluoranthene	0.47	<0.05	0.13	0.11
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	0.08	0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	0.09	0.06
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	0.11	0.07
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 8A Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-1 SS1	BH21-43 SS1
Date of Collection	Table 8 RPIICC	Nov 17, 2021	Nov 17, 2021
Date Reported		Nov 29, 2021	Nov 29, 2021
Sampling Depth (m bgs)		0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T831518	21T831518
Polychlorinated Biphenyls	0.3	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007
DDD	0.05	<0.007	<0.007
DDE	0.05	<0.007	<0.007
DDT	1.4	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005
Endrin	0.04	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005
Hexachlorobenzene	0.02	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9A Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-12	BH21-44
Date of Collection	Table 8 Potable GW	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Antimony	6	<1.0	<1.0
Arsenic	25	7.8	2
Barium	1000	119	101
Beryllium	4	<0.50	<0.50
Boron	5000	221	38
Cadmium	2.1	<0.20	<0.20
Chromium	50	<2.0	<2.0
Chromium VI	25	<2.0	<2.0
Cobalt	3.8	<0.50	0.67
Copper	69	1.7	<1.0
Cyanide	52	<2.0	<2.0
Lead	10	<0.50	<0.50
Mercury	0.29	<0.02	<0.02
Molybdenum	70	5.87	0.8
Nickel	100	1.9	<1.0
Selenium	10	1.6	3.3
Silver	1.2	<0.20	<0.20
Thallium	2	<0.30	<0.30
Uranium	20	1.74	1.65
Vanadium	6.2	0.78	1.01
Zinc	890	<5.0	<5.0
Sodium	490000	30100	8980
Chloride	790000	7260	7770

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 10A Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-12	BH21-44
Date of Collection	Table 8 Potable GW	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Benzene	5	<0.20	<0.20
Toluene	22	<0.20	0.41
Ethylbenzene	2.4	<0.10	<0.10
Xylene Mixture	300	<0.20	<0.20
F1 (C6 to C10) minus BTEX	420	<25	<25
F2 (C10 to C16)	150	<100	<100
F3 (C16 to C34)	500	<100	<100
F4 (C34 to C50)	500	<100	<100

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 11A Groundwater Analytical Results - VOCs

NO MISSISSAUGA DATA

Table 12A Groundwater Analytical Results - PAHs

Parameter		BH21-12	BH21-44
Date of Collection	Table 8 Potable GW	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Acenaphthene	4.1	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20
Anthracene	1	<0.10	<0.10
Benz(a)anthracene	1	<0.20	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10
Chrysene	0.1	<0.10	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20
Fluoranthene	0.41	<0.20	<0.20
Fluorene	120	<0.20	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20
Methyl Naphthalene, 2-and 1-	3.2	<0.20	<0.20
Naphthalene	11	<0.20	<0.20
Phenanthrene	1	<0.10	<0.10
Pyrene	4.1	<0.20	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 13A Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-12	BH21-44
Date of Collection	Table 8 Potable GW	Nov 23, 2021	Nov 23, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021
Screened Depth (mbgs)		2.2 - 5.2	2.2 - 5.2
Analytical Report Reference No.		21T834096	21T834096
Polychlorinated Biphenyls	0.2	<0.1	<0.1
Aldrin	0.35	<0.01	<0.01
Chlordane	0.06	<0.04	<0.04
DDD	1.8	<0.05	<0.05
DDE	10	<0.01	<0.01
DDT	0.05	<0.04	<0.04
Dieldrin	0.35	<0.02	<0.02
Endosulfan	0.56	<0.05	<0.05
Endrin	0.36	<0.05	<0.05
Heptachlor	0.038	<0.01	<0.01
Heptachlor Epoxide	0.038	<0.01	<0.01
Hexachlorobenzene	1	<0.01	<0.01
Hexachlorobutadiene	0.44	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.95	<0.01	<0.01
Hexachloroethane	2.1	<0.01	<0.01
Methoxychlor	0.3	<0.04	<0.04

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14A Summary of Maximum Concentrations in Soil

Group	Parameter	Table 8 RPIICC	Maximum Concentration	Location
BTEX	Benzene	0.02	<0.005	all samples
	Ethylbenzene	0.05	<0.01	all samples
	Toluene	0.2	<0.05	all samples
	Total Xylenes	0.05	<0.05	all samples
Metals	Barium	220	55.6	BH21-1 SS2
	Beryllium	2.5	<0.4	all samples
	Boron	36	7	BH21-42 SS1
	Cadmium	1.2	<0.5	all samples
	Chromium	70	19	BH21-42 SS1
	Cobalt	22	9.2	BH21-42 SS1
	Copper	92	35.3	BH21-42 SS1
	Lead	120	15	BH21-42 SS1
	Molybdenum	2	<0.5	all samples
	Nickel	82	20	BH21-42 SS1
	Silver	0.5	<0.5	all samples
	Thallium	1	<0.5	all samples
	Uranium	2.5	0.6	BH21-1 SS2
	Vanadium	86	25.3	BH21-42 SS1
	Zinc	290	51	BH21-42 SS1
As, Se, Sb	Antimony	1.3	<0.8	all samples
	Arsenic	18	9	BH21-44 SS1
	Selenium	1.5	<0.8	all samples
PAHs	Acenaphthene	0.072	<0.05	all samples
	Acenaphthylene	0.093	<0.05	all samples
	Anthracene	0.22	<0.05	all samples
	Benz(a)anthracene	0.36	<0.05	all samples
	Benzo(a)pyrene	0.3	0.08	BH21-12 SS1
	Benzo(b)fluoranthene	0.47	0.13	BH21-12 SS1
	Benzo(g,h,i)perylene	0.68	0.11	BH21-12 SS1
	Benzo(k)fluoranthene	0.48	<0.05	all samples
	Chrysene	2.8	0.06	BH21-43 SS1
	Dibenz(a,h)anthracene	0.1	<0.05	all samples
	Fluoranthene	0.69	0.07	BH21-43 SS1
	Fluorene	0.19	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.23	0.09	BH21-12 SS1
	Methylnaphthalene, 2-(1-)	0.59	<0.05	all samples
	Naphthalene	0.09	<0.05	all samples
	Phenanthrene	0.69	<0.05	all samples
	Pyrene	1	0.07	BH21-43 SS1
PHCs	F1 (C6 to C10) minus BTEX	25	<10	all samples
	F2 (C10 to C16)	10	<10	all samples
	F3 (C16 to C34)	240	61	BH21-12 SS3
	F4 (C34 to C50)	120	22	BH21-12 SS3
	Acetone	0.5	<0.1	all samples
	Bromodichloromethane	0.05	<0.01	all samples
	Bromoform	0.05	<0.01	all samples
	Bromomethane	0.05	<0.01	all samples
	Carbon Tetrachloride	0.05	<0.0005	all samples
	Chlorobenzene	0.05	<0.01	all samples
	Chloroform	0.05	<0.01	all samples
	Dibromochloromethane	0.05	<0.01	all samples
	Dichlorobenzene, 1,2-	0.05	<0.01	all samples

Table 14A Summary of Maximum Concentrations in Soil

Group	Parameter	Table 8 RPIICC	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	0.05	<0.01	all samples
	Dichlorobenzene, 1,4-	0.05	<0.01	all samples
	Dichlorodifluoromethane	0.05	<0.01	all samples
	Dichloroethane, 1,1-	0.05	<0.01	all samples
	Dichloroethane, 1,2-	0.05	<0.002	all samples
	Dichloroethylene, 1,1-	0.05	<0.01	all samples
	Dichloroethylene, Cis- 1,2-	0.05	<0.01	all samples
	Dichloroethylene, Trans- 1,2-	0.05	<0.01	all samples
	Dichloropropane, 1,2-	0.05	<0.01	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.01	all samples
	Ethylene Dibromide	0.05	<0.01	all samples
	Hexane, n-	0.05	-	all samples
	Methyl Ethyl Ketone	0.5	<0.1	all samples
	Methyl Isobutyl Ketone	0.5	<0.1	all samples
	Methyl tert-butyl Ether	0.05	<0.01	all samples
	Methylene Chloride	0.05	<0.01	all samples
	Styrene	0.05	<0.01	all samples
	Tetrachloroethane, 1,1,1,2-	0.05	<0.01	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.01	all samples
	Tetrachloroethylene	0.05	-	all samples
	Trichloroethane, 1,1,1-	0.05	<0.01	all samples
	Trichloroethane, 1,1,2-	0.05	<0.01	all samples
	Trichloroethylene	0.05	<0.01	all samples
	Trichlorofluoromethane	0.25	<0.01	all samples
	Vinyl Chloride	0.02	<0.0002	all samples
ORPs	Chromium, Hexavalent	0.66	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.7	0.508	BH21-1 SS2
	Mercury	0.27	<0.10	all samples
	Sodium Adsorption Ratio	5	0.233	BH21-1 SS2
	pH, 2:1 CaCl2 Extraction	*	7.67	BH21-1 SS2
PCBs	Polychlorinated Biphenyls	0.3	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15A Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 8 Potable GW	Maximum Concentration	Location
BTEX	Benzene	5	<0.20	all samples
	Ethylbenzene	2.4	<0.10	all samples
	Toluene	22	0.41	BH21-44
	Xylene Mixture	300	<0.20	all samples
Metals	Barium	1000	119	BH21-12
	Beryllium	4	<0.50	all samples
	Boron	5000	221	BH21-12
	Cadmium	2.1	<0.20	all samples
	Chromium	50	<2.0	all samples
	Cobalt	3.8	0.67	BH21-44
	Copper	69	1.7	BH21-12
	Lead	10	<0.50	all samples
	Molybdenum	70	5.87	BH21-12
	Nickel	100	1.9	BH21-12
	Silver	1.2	<0.20	all samples
	Thallium	2	<0.30	all samples
	Uranium	20	1.74	BH21-12
	Vanadium	6.2	1.01	BH21-44
	Zinc	890	<5.0	all samples
As, Se, Sb	Antimony	6	<1.0	all samples
	Arsenic	25	7.8	BH21-12
	Selenium	10	3.3	BH21-44
Na	Sodium	490000	30100	BH21-12
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	1	<0.10	all samples
	Benz(a)anthracene	1	<0.20	all samples
	Benzo(a)pyrene	0.01	<0.01	all samples
	Benzo(b)fluoranthene	0.1	<0.10	all samples
	Benzo(g,h,i)perylene	0.2	<0.20	all samples
	Benzo(k)fluoranthene	0.1	<0.10	all samples
	Chrysene	0.1	<0.10	all samples
	Dibenz(a,h)anthracene	0.2	<0.20	all samples
	Fluoranthene	0.41	<0.20	all samples
	Fluorene	120	<0.20	all samples
	Indeno(1,2,3-cd)pyrene	0.2	<0.20	all samples
	Methyl Naphthalene, 2-and 1-	3.2	<0.20	all samples
	Naphthalene	11	<0.20	all samples
	Phenanthrene	1	<0.10	all samples
	Pyrene	4.1	<0.20	all samples
PHCs	F1 (C6 to C10) minus BTEX	420	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	16	<0.20	all samples
	Bromoform	25	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.79	<0.20	all samples
	Chlorobenzene	30	<0.10	all samples
	Chloroform	2.4	<0.20	all samples

Table 15A Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 8 Potable GW	Maximum Concentration	Location
VOCs	Dibromochloromethane	25	<0.10	all samples
	Dichlorobenzene, 1,2-	3	<0.10	all samples
	Dichlorobenzene, 1,3-	59	<0.10	all samples
	Dichlorobenzene, 1,4-	1	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	5	<0.30	all samples
	Dichloroethane, 1,2-	1.6	<0.20	all samples
	Dichloroethylene, 1,1-	1.6	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	51	<0.20	all samples
	Methyl Ethyl Ketone	1800	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	50	<0.30	all samples
	Styrene	5.4	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	1	<0.10	all samples
	Tetrachloroethylene	1.6	<0.20	all samples
	Trichloroethane, 1,1,1-	200	<0.30	all samples
	Trichloroethane, 1,1,2-	4.7	<0.20	all samples
	Trichloroethylene	1.6	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	7770	BH21-44
	Chromium VI	25	<2.0	all samples
	Cyanide	52	<2.0	all samples
	Mercury	0.29	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Notes for Soil & Groundwater Summary Tables - Brampton (B-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 1 RPIICC = Full Depth Background Site Condition Standards as contained in Table 1 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011
11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 1 SCS

Table 1B Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-2	BH21-3	BH21-6	BH21-7	BH21-8	BH21-16	BH21-22	BH21-45
Installed By			WSP	WSP	WSP	WSP	WSP	WSP	WSP	WSP
Installation Date			2-Dec-21	2-Dec-21	1-Dec-21	29-Nov-21	29-Nov-21	1-Dec-21	22-Nov-21	22-Nov-21
Well Status			Active	Active	Active	Active	Active	Active	Active	Active
Well Inner Diameter		(mm)	50	50	50	50	50	50	50	50
Casing Type (Flushmount / Monument)			Monument	Monument	Flushmount	Monument	Monument	Flushmount	Monument	Flushmount
Top of Pipe Elevation		(masl)	184.852	187.353	216.625	218.769	220.065	218.014	244.619	218.032
Ground Surface Elevation		(masl)	183.942	186.453	216.805	217.859	219.165	218.114	243.709	218.122
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
		(masl)	183.642	186.153	216.505	217.559	218.865	217.814	243.409	217.822
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	2.2	3.7	2.5	2.2	5.5	5.5	2.8	5.5
		(masl)	181.8	182.8	214.3	215.7	213.7	212.6	240.9	212.6
Top of Well Screen		(mbgs)	2.8	4.3	3.1	2.8	6.1	6.1	3.4	6.1
		(masl)	181.1	182.2	213.7	215.1	213.1	212.0	240.3	212.0
Screen Length		(m)	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0
Bottom of Screen		(mbgs)	5.8	7.3	6.1	5.8	9.1	9.1	6.4	9.1
		(masl)	178.2	179.1	210.7	212.1	210.1	209.0	237.3	209.0
30-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	0.7	4.3
	GW Elevation	(masl)	-	-	-	-	-	-	243.0	213.8
1-Dec-21	Depth of GW	(mbgs)	-	-	-	1.3	2.4	-	-	5.3
	GW Elevation	(masl)	-	-	-	216.6	216.7	-	-	212.9
2-Dec-21	Depth of GW	(mbgs)	-	-	0.3	1.1	2.3	5.0	-	-
	GW Elevation	(masl)	-	-	216.5	216.7	216.9	213.2	-	-
6-Dec-21	Depth of GW	(mbgs)	2.4	DRY	-	-	-	-	-	-
	GW Elevation	(masl)	181.3	-	-	-	-	-	-	-
7-Dec-21	Depth of GW	(mbgs)	2.4	DRY	0.2	1.1	2.3	5.0	1.0	5.2
	GW Elevation	(masl)	181.6	-	216.6	216.8	216.9	213.2	242.7	212.9

See "Notes for Soil and Groundwater Summary

Table 2B Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-2	SS2	0.8 - 1.4	2-Dec-21	✓	-	-	✓	-	-	13, 14, 30, 38, 114
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
	QAQC-11			-	✓	-	-	-	-	
BH21-3	SS1	0.0 - 0.6	2-Dec-21	✓	-	-	-	-	-	13, 14, 38, 114
	QAQC-12			✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	-	-	-	-	
BH21-4	SS1	0.0 - 0.6	6-Dec-21	✓	-	-	✓	-	-	13, 14, 38, 44, 114
	SS2	0.6 - 1.2		-	-	-	-	✓	✓	
	SS3	1.2 - 1.8		-	✓	-	-	-	-	
BH21-5	SS1	0.0 - 0.6	6-Dec-21	✓	-	✓	-	-	-	13, 14, 38, 47, 114
	SS2	0.6 - 1.2		-	✓	-	-	-	-	
	SS3	1.2 - 1.8		-	-	-	-	✓	✓	
BH21-6	SS1	0.0 - 0.6	1-Dec-21	-	-	-	✓	-	-	10, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	-	-	-	-	
BH21-7	SS1	0.0 - 0.6	29-Nov-21	-	-	-	✓	✓	✓	4, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-8	SS1	0.0 - 0.6	29-Nov-21	-	-	-	✓	-	-	42, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS7	6.1 - 6.7		-	✓	✓	-	-	-	
BH21-16	SS1	0.0 - 0.6	1-Dec-21	✓	-	-	-	-	-	13, 14, 26, 38, 114
	SS2	0.8 - 1.4		-	-	-	✓	-	-	
	QAQC-10			-	-	-	✓	-	-	
	SS8	7.6 - 8.2		-	✓	✓	-	-	-	
BH21-17	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 49, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-18	SS1	0.0 - 0.6	24-Nov-21	✓	-	-	-	-	-	2, 13, 14, 38, 114
	SS2	0.8 - 1.4		-	✓	-	✓	✓	✓	
BH21-19	SS1	0.0 - 0.6	24-Nov-21	-	-	-	✓	-	-	8, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	✓	-	-	-	-	
BH21-20	SS1	0.0 - 0.6	23-Nov-21	✓	-	-	-	-	-	5, 13, 14, 38, 114
	QAQC-6			✓	-	-	-	-	-	
	SS2	0.8 - 1.4		-	-	-	✓	✓	✓	
	QAQC-7			-	-	-	✓	✓	✓	
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
	QAQC-8			-	✓	-	-	-	-	
	SS4	2.3 - 2.9		✓	-	-	-	-	-	
BH21-21	SS1	0.0 - 0.6	23-Nov-21	-	-	-	✓	✓	✓	13, 14, 20, 38, 114
	SS3	1.5 - 2.1		✓	✓	✓	-	-	-	
BH21-22	SS1	0.0 - 0.6	22-Nov-21	✓	-	-	-	-	-	13, 14, 27, 38, 114
	SS3	1.5 - 2.1		-	-	-	✓	✓	✓	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-23	S1	0.0 - 0.6	5-Nov-21	-	-	-	✓	-	-	13, 14, 38, 53, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	-	✓	✓	
BH21-24	S1	0.0 - 0.6	5-Nov-21	-	-	-	-	✓	✓	13, 14, 38, 56, 114
	S2	0.6 - 1.2		-	-	-	✓	-	-	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-45	SS1	0.0 - 0.6	22-Nov-21	-	-	-	✓	✓	✓	13, 14, 17, 38, 114
	SS2	0.8 - 1.4		✓	-	-	✓	-	-	
	SS8	7.6 - 8.2		-	✓	✓	-	-	-	
	SS9	9.1 - 9.8		-	✓	✓	-	-	-	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3B: Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-2	2.8 - 5.8	7-Dec-21	-	✓	-	-	-	-	13, 14, 30, 38, 114
BH21-6	3.1 - 6.1	6-Dec-21	✓	✓	-	-	-	-	10, 13, 14, 38, 114
BH21-7	2.8 - 5.8	2-Dec-21	✓	✓	✓	✓	✓	✓	4, 13, 14, 38, 114
BH21-8	6.1 - 9.1	2-Dec-21	✓	✓	✓	✓	-	-	42, 13, 14, 38, 114
BH21-16	6.1 - 9.1	6-Dec-21	✓	✓	✓	✓	-	-	13, 14, 26, 38, 114
BH21-22	3.4 - 6.4	1-Dec-21	✓	✓	✓	✓	-	-	13, 14, 27, 38, 114
BH21-45	6.1 - 9.1	1-Dec-21	✓	✓	✓	✓	✓	-	13, 14, 38, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-2 SS2	BH21-3 SS3	QAQC-12	BH21-4 SS1	BH21-5 SS1	BH21-6 SS2	BH21-7 SS2
Date of Collection	Table 1 RPIICC	Dec 02, 2021	Dec 02, 2021		Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021		Dec 18, 2021	Dec 18, 2021	Dec 23, 2021	Dec 14, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6		0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.8 - 1.4
Analytical Report Reference No.		21T839096	21T839096		21T840564	21T840564	21T839096	21T836919
Antimony	1.3	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	6	4	6	4	7	4	6
Barium	220	89.8	77.5	52.7	37.4	60	54.5	57.1
Beryllium	2.5	0.8	0.6	0.5	0.5	0.7	<0.4	0.7
Boron	36	10	8	7	<5	7	7	11
Boron (Hot Water Extractable)	NA	0.42	0.12	0.17	0.12	0.26	0.17	0.25
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	20	17	15	12	18	14	22
Cobalt	21	9.2	7.8	7.8	5.6	6.6	8.1	10.4
Copper	92	42.9	24.8	33.3	24.7	23.3	32	29.1
Lead	120	60	9	12	9	18	8	10
Molybdenum	2	0.6	<0.5	<0.5	<0.5	0.6	<0.5	<0.5
Nickel	82	19	17	22	12	14	15	21
Selenium	1.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	0.6	<0.50	<0.50	<0.50	<0.50	<0.50	0.59
Vanadium	86	30.4	25.5	22.4	20.4	28.1	23.8	31.9
Zinc	290	95	44	43	32	51	39	55
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.57	0.353	0.216	0.185	0.124	0.200	0.327	0.245
Sodium Adsorption Ratio	2.4	1.560	0.438	0.300	0.143	0.116	2.140	2.170
pH, 2:1 CaCl2 Extraction	*	7.29	7.25	7.32	7.19	7.04	7.61	7.19

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-8 SS2	BH21-16 SS1	BH21-17 S1	BH21-18 SS1	BH21-19 SS2	BH21-20 SS1	QAQC-6
Date of Collection	Table 1 RPIICC	Nov 29, 2021	Dec 01, 2021	Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021	
Date Reported		Dec 14, 2021	Dec 15, 2021	Nov 16, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6	
Analytical Report Reference No.		21T836919	21T839096	21T826519	21T834550	21T834550	21T834550	
Antimony	1.3	<0.8	**2.8**	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	6	8	7	6	6	6	5
Barium	220	57.4	88.5	62.8	94.5	82.7	71.9	71.5
Beryllium	2.5	0.5	0.5	0.6	0.6	0.6	<0.4	<0.4
Boron	36	10	9	9	7	11	<5	<5
Boron (Hot Water Extractable)	NA	0.21	0.50	0.66	0.26	0.11	0.21	0.22
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	19	35	20	25	25	20	20
Cobalt	21	10.0	10.6	7.9	11.5	13.3	16.5	11.8
Copper	92	31.5	69	28.8	33.4	25.2	48.7	25.8
Lead	120	12	79	22	10	11	18	17
Molybdenum	2	<0.5	**3.7**	0.7	<0.5	<0.5	0.6	0.6
Nickel	82	20	31	19	24	26	**142**	25
Selenium	1.5	<0.8	0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	<0.50	<0.50	<0.50	0.5	0.6	0.5	<0.50
Vanadium	86	28.4	33.8	29	35.1	35.8	30.9	30.7
Zinc	290	51	**468**	77	66	59	61	67
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	0.22	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.57	0.117	0.290	0.186	0.154	0.110	0.154	0.157
Sodium Adsorption Ratio	2.4	0.122	1.640	0.055	1.000	0.186	0.105	0.107
pH, 2:1 CaCl2 Extraction	*	7.12	7.50	7.16	7.55	7.56	7.44	7.36

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-20 SS4	BH21-21 SS3	BH21-22 SS1	BH21-23 S2	BH21-24 S3	BH21-45 SS2
Date of Collection	Table 1 RPIICC	Nov 23, 2021	Nov 23, 2021	Nov 22, 2021	Nov 05, 2021	Nov 05, 2021	Nov 22, 2021
Date Reported		Dec 20, 2021	Dec 03, 2021	Dec 03, 2021	Nov 16, 2021	Nov 16, 2021	Dec 03, 2021
Sampling Depth (mbgs)		2.3 - 2.9	1.5 - 2.1	0.0 - 0.6	0.6 - 1.2	1.2 - 1.8	0.8 - 1.4
Analytical Report Reference No.		21T841262	21T834550	21T834550	21T826519	21T826519	21T834550
Antimony	1.3	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	5	5	6	7	6	7
Barium	220	95.4	56.1	96.2	54.8	41.5	83
Beryllium	2.5	0.6	<0.4	0.5	0.6	0.4	0.5
Boron	36	24	8	9	10	7	9
Boron (Hot Water Extractable)	NA	0.26	<0.10	0.12	0.26	<0.10	0.44
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	25	14	24	22	16	25
Cobalt	21	14.8	7.6	11.9	11.2	9.8	15.3
Copper	92	10.6	23.4	29.7	36.6	34.8	33.8
Lead	120	12	10	10	9	7	11
Molybdenum	2	1.2	<0.5	<0.5	0.7	<0.5	<0.5
Nickel	82	27	13	23	25	20	33
Selenium	1.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	0.8	<0.50	0.6	0.5	<0.50	0.7
Vanadium	86	40.2	22.7	34.9	29.5	23.4	34
Zinc	290	63	35	57	63	53	68
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.57	0.125	0.088	0.125	0.157	0.103	0.314
Sodium Adsorption Ratio	2.4	0.344	0.095	0.182	0.370	0.095	1.200
pH, 2:1 CaCl2 Extraction	*	7.13	7.62	7.64	7.59	7.66	7.60

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTEX

Parameter		BH21-2 SS5	BH21-3 SS6	BH21-4 SS3	BH21-5 SS2	BH21-6 SS6	BH21-7 SS5	BH21-8 SS7	BH21-16 SS8
Date of Collection	Table 1 RPIICC	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021	Nov 29, 2021	Dec 01, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021	Dec 18, 2021	Dec 18, 2021	Dec 15, 2021	Dec 14, 2021	Dec 14, 2021	Dec 15, 2021
Sampling Depth (mbgs)		3.0 - 3.7	4.6 - 5.2	1.8 - 1.8	0.6 - 1.2	4.6 - 5.2	3.0 - 3.7	6.1 - 6.7	7.6 - 8.2
Analytical Report Reference No.		21T839096	21T839096	21T840564	21T840564	21T839096	21T836919	21T836919	21T839096
Benzene	0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<5	<5	<5	<5	<5	<5	<5	<5
F2 (C10 to C16)	10	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	<50	<50	<50	<50	<50	<50	<50	<50
F4 (C34 to C50)	120	<50	<50	<50	<50	<50	<50	<50	<50

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTE

Parameter		BH21-17 S2	BH21-18 SS2	BH21-19 SS2	BH21-20 SS3	QAQC-8	BH21-21 SS3	BH21-22 SS5	BH21-23 S3
Date of Collection	Table 1 RPIICC	Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021		Nov 23, 2021	Nov 22, 2021	Nov 05, 2021
Date Reported		Nov 30, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021		Dec 03, 2021	Dec 03, 2021	Nov 30, 2021
Sampling Depth (mbgs)		0.6 - 1.2	0.8 - 1.4	0.8 - 1.4	1.5 - 2.1		1.5 - 2.1	3.0 - 3.7	1.2 - 1.8
Analytical Report Reference No.		21T832162	21T834550	21T834550	21T834550		21T834550	21T834550	21T832162
Benzene	0.02	<0.005	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.005
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.01	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<10	<5	<5	<5	<5	<5	<5	<10
F2 (C10 to C16)	10	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	13	<50	<50	<50	<50	<50	<50	<10
F4 (C34 to C50)	120	<10	<50	<50	<50	<50	<50	<50	<10

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTE

Parameter		BH21-24 S3	BH21-45 SS8	BH21-45 SS9
Date of Collection	Table 1 RPIICC	Nov 05, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Nov 30, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		1.2 - 1.8	7.6 - 8.2	9.1 - 9.8
Analytical Report Reference No.		21T832162	21T834550	21T841262
Benzene	0.02	<0.005	<0.02	<0.02
Toluene	0.2	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.01	**0.9**	<0.05
Total Xylenes	0.05	<0.05	**5.55**	<0.05
F1 (C6 to C10) minus BTEX	25	<10	**51**	<5
F2 (C10 to C16)	10	<10	<10	<10
F3 (C16 to C34)	240	14	<50	<50
F4 (C34 to C50)	120	<10	<50	<50

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 6B Soil Analytical Results - VOCs

Parameter		BH21-7 SS5	BH21-8 SS7	BH21-16 SS8	BH21-21 SS3	BH21-22 SS5	BH21-45 SS8	BH21-45 SS9
Date of Collection	Table 1 RPIICC	Nov 29, 2021	Nov 29, 2021	Dec 01, 2021	Nov 23, 2021	Nov 22, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Dec 14, 2021	Dec 14, 2021	Dec 15, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		3.0 - 3.7	6.1 - 6.7	7.6 - 8.2	1.5 - 2.1	3.0 - 3.7	7.6 - 8.2	9.1 - 9.8
Analytical Report Reference No.		21T836919	21T836919	21T839096	21T834550	21T834550	21T834550	21T841262
Acetone	0.5	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Benzene	0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Bromodichloromethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Bromoform	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Bromomethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Carbon Tetrachloride	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chlorobenzene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chloroform	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Dibromochloromethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,2-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,3-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,4-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorodifluoromethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethane, 1,1-	0.05	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Dichloroethane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
Dichloroethylene, 1,1-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethylene, Cis- 1,2-	0.05	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Dichloroethylene, Trans- 1,2-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloropropane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	**0.9**	<0.05
Ethylene Dibromide	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Hexane, n-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methyl Ethyl Ketone	0.5	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Methyl Isobutyl Ketone	0.5	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Methyl tert-butyl Ether	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methylene Chloride	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Styrene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Tetrachloroethane, 1,1,2,2-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethylene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,1-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Trichloroethylene	0.05	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
Trichlorofluoromethane	0.25	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Vinyl Chloride	0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Xylene mixture	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	**5.55**	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		BH21-2 SS2	BH21-4 SS1	BH21-5 SS1	BH21-6 SS2	BH21-7 SS1	BH21-8 SS1
Date of Collection	Table 1 RPIICC	Dec 02, 2021	Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021	Nov 29, 2021
Date Reported		Dec 15, 2021	Dec 18, 2021	Dec 18, 2021	Dec 23, 2021	Dec 14, 2021	Dec 14, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T839096	21T840564	21T840564	21T839096	21T836919	21T836919
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.12	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	0.40	0.22
Anthracene	0.16	<0.05	<0.05	<0.05	<0.05	**0.18**	0.10
Fluoranthene	0.56	<0.05	<0.05	<0.05	<0.05	**1.05**	**0.89**
Pyrene	1	<0.05	<0.05	<0.05	<0.05	0.96	0.77
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	**0.56**	**0.46**
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	0.41	0.36
Benzo(b)fluoranthene	0.47	<0.05	<0.05	<0.05	<0.05	**0.60**	**0.66**
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05	<0.05	0.23	0.24
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	**0.40**	**0.40**
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	0.22	**0.26**
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	0.05	0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	0.27	0.34
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		BH21-16 SS2	QAQC-10	BH21-17 S3	BH21-18 SS2	BH21-19 SS1	BH21-20 SS2	QAQC-7
Date of Collection	Table 1 RPIICC	Dec 02, 2021		Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021	
Date Reported		Dec 15, 2021		Nov 16, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	
Sampling Depth (mbgs)		0.8 - 1.4		1.2 - 1.8	0.8 - 1.4	0.0 - 0.6	0.8 - 1.4	
Analytical Report Reference No.		21T839096		21T826519	21T834550	21T834550	21T834550	
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.12	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.16	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.56	<0.05	<0.05	<0.05	<0.05	0.14	<0.05	<0.05
Pyrene	1	<0.05	<0.05	<0.05	<0.05	0.16	<0.05	<0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	0.17	<0.05	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	0.07	<0.05	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	<0.05	<0.05	0.1	<0.05	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	0.07	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		BH21-21 SS1	BH21-22 SS3	BH21-23 S1	BH21-24 S2	BH21-45 SS1	BH21-45 SS2
Date of Collection	Table 1 RPIICC	Nov 23, 2021	Nov 22, 2021	Nov 05, 2021	Nov 05, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021	Nov 16, 2021	Nov 16, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	1.5 - 2.1	0.0 - 0.6	0.6 - 1.2	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T834550	21T834550	21T826519	21T826519	21T834550	21T841262
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	0.09	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.12	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	0.24	<0.05
Anthracene	0.16	<0.05	<0.05	<0.05	<0.05	0.13	<0.05
Fluoranthene	0.56	<0.05	<0.05	<0.05	<0.05	**0.57**	<0.05
Pyrene	1	<0.05	<0.05	<0.05	<0.05	0.6	<0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	**0.39**	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	0.35	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	0.09	<0.05	0.45	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	0.09	<0.05	0.19	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	0.05	<0.05	**0.33**	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	0.19	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	0.23	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	0.15	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 8B Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-4 SS2	BH21-5 SS3	BH21-7 SS1	BH21-17 S2	BH21-20 SS2	QAQC-7	BH21-23 S3	BH21-24 S1	BH21-45 SS1
Date of Collection	Table 1 RPIICC	Dec 06, 2021	Dec 06, 2021	Nov 29, 2021	Nov 05, 2021	Nov 23, 2021		Nov 05, 2021	Nov 05, 2021	Nov 22, 2021
Date Reported		Dec 18, 2021	Dec 18, 2021	Dec 14, 2021	Nov 16, 2021	Dec 03, 2021		Nov 16, 2021	Nov 16, 2021	Dec 03, 2021
Sampling Depth (m bgs)		0.6 - 1.6	1.2 - 1.8	0.0 - 0.6	0.6 - 1.2	0.8 - 1.4		1.2 - 1.8	0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T840564	21T840564	21T836919	21T826519	21T834550		21T826519	21T826519	21T834550
Polychlorinated Biphenyls	0.3	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9B Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-6	BH21-7	BH21-8	BH21-16		BH21-22	BH21-45	QA/QC	BH21-45
Date of Collection	Table 1 GW	Dec 06, 2021	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021	Feb 11, 2022	Dec 01, 2021	Dec 01, 2021		Feb 11, 2022
Date Reported		Dec 21, 2021	Dec 15, 2021	Dec 15, 2021	Dec 21, 2021	Feb 14, 2022	Dec 16, 2021	Dec 16, 2021		Feb 14, 2022
Screened Depth (mbgs)		3.1 - 6.1	2.8 - 5.8	6.1 - 9.1	6.1 - 9.1		3.4 - 6.4	6.1 - 9.1		
Analytical Report Reference No.		21T841270	21T839088	21T839088	21T841270	22T862998	21T838602	21T838602		22T862998
Antimony	1.5	<1.0	<1.0	<1.0	1.1	-	<1.0	<1.0	<1.0	-
Arsenic	13	4.7	<1.0	4.3	<1.0	-	1.1	4.7	1.6	-
Barium	610	271	254	109	63.9	-	91.9	80.5	62.4	-
Beryllium	0.5	<0.50	<0.50	<0.50	<0.50	-	<0.50	<0.50	<0.50	-
Boron	1700	279	362	131	1676	-	219	682	115	-
Cadmium	0.5	<0.20	<0.20	<0.20	<0.20	-	<0.20	<0.20	<0.20	-
Chromium	11	**25.3**	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Chromium VI	25	5.43	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Cobalt	3.8	**4.53**	0.52	0.63	<0.50	-	1.06	0.66	2.87	-
Copper	5	2.7	1.9	<1.0	<1.0	-	<1.0	<1.0	<1.0	-
Cyanide	5	<2.0	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Lead	1.9	0.93	<0.50	<0.50	<0.50	-	<0.50	<0.50	<0.50	-
Mercury	0.1	<0.02	<0.02	<0.02	<0.02	-	<0.02	<0.02	<0.02	-
Molybdenum	23	6.45	14.2	7.84	**24.7**	**32.1**	4.41	**28**	4.27	**57.1**
Nickel	14	6.9	2.8	9.7	1.1	-	1.9	4.7	4.2	-
Selenium	5	<1.0	<1.0	<1.0	1.6	-	<1.0	<1.0	<1.0	-
Silver	0.3	<0.20	<0.20	<0.20	<0.20	-	<0.20	<0.20	<0.20	-
Thallium	0.5	<0.30	<0.30	<0.30	<0.30	-	<0.30	<0.30	<0.30	-
Uranium	8.9	3.52	3.19	1.11	1.86	-	2.18	1.5	0.96	-
Vanadium	3.9	3.29	1.42	0.62	0.62	-	0.63	0.83	<0.40	-
Zinc	160	6.1	<5.0	<5.0	<5.0	-	<5.0	<5.0	<5.0	-
Sodium	490000	342000	417000	23000	210000	-	43800	205000	77700	-
Chloride	790000	**1460000**	768000	72700	286000	-	63300	326000	156000	-

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 10B Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-2	BH21-6	QAQC-2	BH21-7	QAQC-1	BH21-8	BH21-16	BH21-22	BH21-45	QA/QC
Date of Collection	Table 1 GW	Dec 07, 2021	Dec 06, 2021		Dec 02, 2021		Dec 02, 2021	Dec 06, 2021	Dec 01, 2021	Dec 01, 2021	
Date Reported		Dec 21, 2021	Dec 21, 2021		Dec 15, 2021		Dec 15, 2021	Dec 21, 2021	Dec 16, 2021	Dec 16, 2021	
Screened Depth (mbgs)		2.8 - 5.8	3.1 - 6.1		2.8 - 5.8		6.1 - 9.1	6.1 - 9.1	3.4 - 6.4	6.1 - 9.1	
Analytical Report Reference No.		21T841270	21T841270		21T839088		21T839088	21T841270	21T838602	21T838602	
Benzene	0.5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	0.8	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Ethylbenzene	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Xylene Mixture	72	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
F1 (C6 to C10) minus BTEX	420	<25	<25	<25	<25	<25	<25	<25	<25	<25	<25
F2 (C10 to C16)	150	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
F3 (C16 to C34)	500	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
F4 (C34 to C50)	500	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 11B Groundwater Analytical Results - VOCs

Parameter		BH21-7	BH21-8	BH21-16	QAQC-1	BH21-22	BH21-45	QA/QC	Trip Blank	Trip Blank	Trip Blank
Date of Collection	Table 1 GW	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021		Dec 01, 2021	Dec 01, 2021		Nov 23, 2021	Nov 30, 2021	Dec 04, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021	Dec 21, 2021		Dec 16, 2021	Dec 16, 2021		Dec 03, 2021	Dec 16, 2021	Dec 21, 2021
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1	6.1 - 9.1		3.4 - 6.4	6.1 - 9.1		-	-	-
Analytical Report Reference No.		21T839088	21T839088	21T841270		21T838602	21T838602		21T834096	21T838602	21T841270
Acetone	2700	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Benzene	0.5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Bromodichloromethane	2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Bromoform	5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Bromomethane	0.89	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Carbon Tetrachloride	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Chlorobenzene	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Chloroform	2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dibromochloromethane	2	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,2-	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,3-	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,4-	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorodifluoromethane	590	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethane, 1,1-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethane, 1,2-	0.5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, 1,1-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethylene, cis- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, trans- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropane, 1,2-	0.5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropene, 1,3-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Ethylbenzene	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	0.2	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Hexane, n-	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Ethyl Ketone	400	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl Isobutyl Ketone	640	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl tert-butyl ether	15	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methylene Chloride	5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Styrene	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,1,2-	1.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,2,2-	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	0.5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	0.8	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethane, 1,1,1-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Trichloroethane, 1,1,2-	0.5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethylene	0.5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	150	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40
Vinyl Chloride	0.5	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17
Xylene Mixture	72	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 12B Groundwater Analytical Results - PAHs

Parameter		BH21-7	BH21-8	QAQC-2	BH21-16	BH21-22	BH21-45	QA/QC	BH21-45
Date of Collection	Table 1 GW	Dec 02, 2021	Dec 02, 2021		Dec 06, 2021	Dec 01, 2021	Dec 01, 2021		Feb 11, 2022
Date Reported		Dec 15, 2021	Dec 15, 2021		Dec 21, 2021	Dec 16, 2021	Dec 16, 2021		Feb 14, 2022
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1		6.1 - 9.1	3.4 - 6.4	6.1 - 9.1		
Analytical Report Reference No.		21T839088	21T839088		21T841270	21T838602	21T838602		22T862998
Acenaphthene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Anthracene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**1.79**	**1**	<0.10
Benz(a)anthracene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**2.4**	**1.67**	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	**3.67**	**2.8**	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**4.92**	**3.29**	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**2.48**	**1.89**	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**2.19**	**1.86**	<0.10
Chrysene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**5.59**	**4.01**	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**0.32**	**0.21**	<0.20
Fluoranthene	0.4	<0.20	<0.20	<0.20	<0.20	<0.20	**17.9**	**11.2**	<0.20
Fluorene	120	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	0.56	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**1.8**	**1.35**	<0.20
Methyl Naphthalene, 2-and 1-	2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Naphthalene	7	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Phenanthrene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**12**	**9.08**	<0.10
Pyrene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**14.6**	**9.52**	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 13B Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-7	BH21-45	QA/QC
Date of Collection	Table 1 GW	Dec 02, 2021	Dec 01, 2021	
Date Reported		Dec 15, 2021	Dec 16, 2021	
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1	
Analytical Report Reference No.		21T839088	21T838602	
Polychlorinated Biphenyls	0.2	<0.1	<0.1	<0.1
Aldrin	0.01	<0.01	-	-
Chlordane	0.06	<0.04	-	-
DDD	1.8	<0.05	-	-
DDE	10	<0.01	-	-
DDT	0.05	<0.04	-	-
Dieldrin	0.05	<0.02	-	-
Endosulfan	0.05	<0.05	-	-
Endrin	0.05	<0.05	-	-
Heptachlor	0.01	<0.01	-	-
Heptachlor Epoxide	0.01	<0.01	-	-
Hexachlorobenzene	0.01	<0.01	-	-
Hexachlorobutadiene	0.01	<0.01	-	-
Hexachlorocyclohexane Gamma-	0.01	<0.01	-	-
Hexachloroethane	0.01	<0.01	-	-
Methoxychlor	0.05	<0.04	-	-

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14B Summary of Maximum Concentrations in Soil

Group	Parameter	Table 1 RPIICC	Maximum Concentration	Location
BTEX	Benzene	0.02	<0.02	all samples
	Ethylbenzene	0.05	0.9	BH21-45 SS8
	Toluene	0.2	<0.05	all samples
	Total Xylenes	0.05	5.55	BH21-45 SS8
Metals	Barium	220	96.2	BH21-22 SS1
	Beryllium	2.5	0.8	BH21-2 SS2
	Boron	36	24	BH21-20 SS4
	Cadmium	1.2	<0.5	all samples
	Chromium	70	35	BH21-16 SS1
	Cobalt	21	16.5	BH21-20 SS1
	Copper	92	69	BH21-16 SS1
	Lead	120	79	BH21-16 SS1
	Molybdenum	2	3.7	BH21-16 SS1
	Nickel	82	142	BH21-20 SS1
	Silver	0.5	<0.5	all samples
	Thallium	1	<0.5	all samples
	Uranium	2.5	0.79	BH21-20 SS4
	Vanadium	86	40.2	BH21-20 SS4
	Zinc	290	468	BH21-16 SS1
As, Se, Sb	Antimony	1.3	2.8	BH21-16 SS1
	Arsenic	18	8	BH21-16 SS1
	Selenium	1.5	0.8	BH21-16 SS1
PAHs	Acenaphthene	0.072	<0.05	all samples
	Acenaphthylene	0.093	0.09	BH21-45 SS1
	Anthracene	0.16	0.18	BH21-7 SS1
	Benz(a)anthracene	0.36	0.56	BH21-7 SS1
	Benzo(a)pyrene	0.3	0.4	BH21-7 SS1
	Benzo(b)fluoranthene	0.47	0.66	BH21-8 SS1
	Benzo(g,h,i)perylene	0.68	0.34	BH21-8 SS1
	Benzo(k)fluoranthene	0.48	0.24	BH21-8 SS1
	Chrysene	2.8	0.41	BH21-7 SS1
	Dibenz(a,h)anthracene	0.1	0.06	BH21-45 SS1
	Fluoranthene	0.56	1.05	BH21-7 SS1
	Fluorene	0.12	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.23	0.26	BH21-8 SS1
	Methylnaphthalene, 2-(1-)	0.59	0.15	BH21-45 SS1
	Naphthalene	0.09	<0.05	all samples
	Phenanthrene	0.69	0.4	BH21-7 SS1
	Pyrene	1	0.96	BH21-7 SS1
PHCs	F1 (C6 to C10) minus BTEX	25	51	BH21-45 SS8
	F2 (C10 to C16)	10	<10	all samples
	F3 (C16 to C34)	240	14	BH21-24 S3
	F4 (C34 to C50)	120	<50	all samples
	Acetone	0.5	<0.50	all samples
	Bromodichloromethane	0.05	<0.05	all samples
	Bromoform	0.05	<0.05	all samples
	Bromomethane	0.05	<0.05	all samples
	Carbon Tetrachloride	0.05	<0.05	all samples
	Chlorobenzene	0.05	<0.05	all samples
	Chloroform	0.05	<0.04	all samples
	Dibromochloromethane	0.05	<0.05	all samples
	Dichlorobenzene, 1,2-	0.05	<0.05	all samples

Table 14B Summary of Maximum Concentrations in Soil

Group	Parameter	Table 1 RPIICC	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	0.05	<0.05	all samples
	Dichlorobenzene, 1,4-	0.05	<0.05	all samples
	Dichlorodifluoromethane	0.05	<0.05	all samples
	Dichloroethane, 1,1-	0.05	<0.02	all samples
	Dichloroethane, 1,2-	0.05	<0.03	all samples
	Dichloroethylene, 1,1-	0.05	<0.05	all samples
	Dichloroethylene, Cis- 1,2-	0.05	<0.02	all samples
	Dichloroethylene, Trans- 1,2-	0.05	<0.05	BH21-45 SS8
	Dichloropropane, 1,2-	0.05	<0.03	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	BH21-45 SS8
	Ethylene Dibromide	0.05	<0.04	all samples
	Hexane, n-	0.05	<0.05	all samples
	Methyl Ethyl Ketone	0.5	<0.50	all samples
	Methyl Isobutyl Ketone	0.5	<0.50	all samples
	Methyl tert-butyl Ether	0.05	<0.05	all samples
	Methylene Chloride	0.05	<0.05	all samples
	Styrene	0.05	<0.05	all samples
	Tetrachloroethane, 1,1,1,2-	0.05	<0.04	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.05	all samples
	Tetrachloroethylene	0.05	<0.05	all samples
	Trichloroethane, 1,1,1-	0.05	<0.05	all samples
	Trichloroethane, 1,1,2-	0.05	<0.04	all samples
	Trichloroethylene	0.05	<0.03	all samples
	Trichlorofluoromethane	0.25	<0.05	all samples
	Vinyl Chloride	0.02	<0.02	all samples
ORPs	Chromium, Hexavalent	0.66	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.57	0.353	BH21-2 SS2
	Mercury	0.27	0.22	BH21-16 SS1
	Sodium Adsorption Ratio	2.4	2.17	BH21-7 SS2
	pH, 2:1 CaCl2 Extraction	*	7.66	BH21-24 S3
PCBs	Polychlorinated Biphenyls	0.3	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15B Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 1 GW	Maximum Concentration	Location
BTEX	Benzene	0.5	<0.20	all samples
	Ethylbenzene	0.5	<0.10	all samples
	Toluene	0.8	<0.20	all samples
	Xylene Mixture	72	<0.20	all samples
Metals	Barium	610	271	BH21-22
	Beryllium	0.5	<0.50	all samples
	Boron	1700	1676	BH21-16
	Cadmium	0.5	<0.20	all samples
	Chromium	11	25.3	all samples
	Cobalt	3.8	4.53	QA/QC
	Copper	5	2.7	all samples
	Lead	1.9	0.93	all samples
	Molybdenum	23	57.1	BH21-45
	Nickel	14	9.7	BH21-45
	Silver	0.3	<0.20	all samples
	Thallium	0.5	<0.30	all samples
	Uranium	8.9	3.52	BH21-22
	Vanadium	3.9	3.29	BH21-45
	Zinc	160	6.1	all samples
As, Se, Sb	Antimony	1.5	1.1	BH21-16
	Arsenic	13	4.7	BH21-45
	Selenium	5	1.6	BH21-16
Na	Sodium	490000	417000	BH21-16
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	0.1	1.79	BH21-45
	Benz(a)anthracene	0.2	2.4	BH21-45
	Benzo(a)pyrene	0.01	3.67	BH21-45
	Benzo(b)fluoranthene	0.1	4.92	BH21-45
	Benzo(g,h,i)perylene	0.2	2.48	BH21-45
	Benzo(k)fluoranthene	0.1	2.19	BH21-45
	Chrysene	0.1	5.59	BH21-45
	Dibenz(a,h)anthracene	0.2	0.32	BH21-45
	Fluoranthene	0.4	17.9	BH21-45
	Fluorene	120	0.56	QA/QC
	Indeno(1,2,3-cd)pyrene	0.2	1.8	BH21-45
	Methyl Naphthalene, 2-and 1-	2	<0.20	all samples
	Naphthalene	7	<0.20	all samples
	Phenanthrene	0.1	12	BH21-45
	Pyrene	0.2	14.6	BH21-45
PHCs	F1 (C6 to C10) minus BTEX	420	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	2	<0.20	all samples
	Bromoform	5	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.2	<0.20	all samples
	Chlorobenzene	0.5	<0.10	all samples
	Chloroform	2	<0.20	all samples
	Dibromochloromethane	2	<0.10	all samples

Table 15B Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 1 GW	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,2-	0.5	<0.10	all samples
	Dichlorobenzene, 1,3-	0.5	<0.10	all samples
	Dichlorobenzene, 1,4-	0.5	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	0.5	<0.30	all samples
	Dichloroethane, 1,2-	0.5	<0.20	all samples
	Dichloroethylene, 1,1-	0.5	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	0.5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	5	<0.20	all samples
	Methyl Ethyl Ketone	400	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	5	<0.30	all samples
	Styrene	0.5	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	0.5	<0.10	all samples
	Tetrachloroethylene	0.5	<0.20	all samples
	Trichloroethane, 1,1,1-	0.5	<0.30	all samples
	Trichloroethane, 1,1,2-	0.5	<0.20	all samples
	Trichloroethylene	0.5	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	1460000	BH21-45
	Chromium VI	25	5.43	all samples
	Cyanide	5	<2.0	all samples
	Mercury	0.1	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Notes for Soil & Groundwater Summary Tables - Brampton (B-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 2 RPI CT = Full Depth Generic Site Condition Standards in a Potable Ground Water Condition with Coarse Textured Soils as contained in Table 2 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011
11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 2 SCS

Table 1B Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-2	BH21-3	BH21-6	BH21-7	BH21-8	BH21-16	BH21-22	BH21-45
Installed By			WSP	WSP	WSP	WSP	WSP	WSP	WSP	WSP
Installation Date			2-Dec-21	2-Dec-21	1-Dec-21	29-Nov-21	29-Nov-21	1-Dec-21	22-Nov-21	22-Nov-21
Well Status			Active	Active	Active	Active	Active	Active	Active	Active
Well Inner Diameter		(mm)	50	50	50	50	50	50	50	50
Casing Type (Flushmount / Monument)			Monument	Monument	Flushmount	Monument	Monument	Flushmount	Monument	Flushmount
Top of Pipe Elevation		(masl)	184.852	187.353	216.625	218.769	220.065	218.014	244.619	218.032
Ground Surface Elevation		(masl)	183.942	186.453	216.805	217.859	219.165	218.114	243.709	218.122
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
		(masl)	183.642	186.153	216.505	217.559	218.865	217.814	243.409	217.822
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	2.2	3.7	2.5	2.2	5.5	5.5	2.8	5.5
		(masl)	181.8	182.8	214.3	215.7	213.7	212.6	240.9	212.6
Top of Well Screen		(mbgs)	2.8	4.3	3.1	2.8	6.1	6.1	3.4	6.1
		(masl)	181.1	182.2	213.7	215.1	213.1	212.0	240.3	212.0
Screen Length		(m)	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0
Bottom of Screen		(mbgs)	5.8	7.3	6.1	5.8	9.1	9.1	6.4	9.1
		(masl)	178.2	179.1	210.7	212.1	210.1	209.0	237.3	209.0
30-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	0.7	4.3
	GW Elevation	(masl)	-	-	-	-	-	-	243.0	213.8
1-Dec-21	Depth of GW	(mbgs)	-	-	-	1.3	2.4	-	-	5.3
	GW Elevation	(masl)	-	-	-	216.6	216.7	-	-	212.9
2-Dec-21	Depth of GW	(mbgs)	-	-	0.3	1.1	2.3	5.0	-	-
	GW Elevation	(masl)	-	-	216.5	216.7	216.9	213.2	-	-
6-Dec-21	Depth of GW	(mbgs)	2.4	DRY	-	-	-	-	-	-
	GW Elevation	(masl)	181.3	-	-	-	-	-	-	-
7-Dec-21	Depth of GW	(mbgs)	2.4	DRY	0.2	1.1	2.3	5.0	1.0	5.2
	GW Elevation	(masl)	181.6	-	216.6	216.8	216.9	213.2	242.7	212.9

See "Notes for Soil and Groundwater Summary

Table 2B Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-2	SS2	0.8 - 1.4	2-Dec-21	✓	-	-	✓	-	-	13, 14, 30, 38, 114
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
	QAQC-11			-	✓	-	-	-	-	
BH21-3	SS1	0.0 - 0.6	2-Dec-21	✓	-	-	-	-	-	13, 14, 38, 114
	QAQC-12			✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	-	-	-	-	
BH21-4	SS1	0.0 - 0.6	6-Dec-21	✓	-	-	✓	-	-	13, 14, 38, 44, 114
	SS2	0.6 - 1.2		-	-	-	-	✓	✓	
	SS3	1.2 - 1.8		-	✓	-	-	-	-	
BH21-5	SS1	0.0 - 0.6	6-Dec-21	✓	-	✓	-	-	-	13, 14, 38, 47, 114
	SS2	0.6 - 1.2		-	✓	-	-	-	-	
	SS3	1.2 - 1.8		-	-	-	-	✓	✓	
BH21-6	SS1	0.0 - 0.6	1-Dec-21	-	-	-	✓	-	-	10, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	-	-	-	-	
BH21-7	SS1	0.0 - 0.6	29-Nov-21	-	-	-	✓	✓	✓	4, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-8	SS1	0.0 - 0.6	29-Nov-21	-	-	-	✓	-	-	42, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS7	6.1 - 6.7		-	✓	✓	-	-	-	
BH21-16	SS1	0.0 - 0.6	1-Dec-21	✓	-	-	-	-	-	13, 14, 26, 38, 114
	SS2	0.8 - 1.4		-	-	-	✓	-	-	
	QAQC-10			-	-	-	✓	-	-	
	SS8	7.6 - 8.2		-	✓	✓	-	-	-	
BH21-17	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 49, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-18	SS1	0.0 - 0.6	24-Nov-21	✓	-	-	-	-	-	2, 13, 14, 38, 114
	SS2	0.8 - 1.4		-	✓	-	✓	✓	✓	
BH21-19	SS1	0.0 - 0.6	24-Nov-21	-	-	-	✓	-	-	8, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	✓	-	-	-	-	
BH21-20	SS1	0.0 - 0.6	23-Nov-21	✓	-	-	-	-	-	5, 13, 14, 38, 114
	QAQC-6			✓	-	-	-	-	-	
	SS2	0.8 - 1.4		-	-	-	✓	✓	✓	
	QAQC-7			-	-	-	✓	✓	✓	
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
	QAQC-8			-	✓	-	-	-	-	
	SS4	2.3 - 2.9		✓	-	-	-	-	-	
BH21-21	SS1	0.0 - 0.6	23-Nov-21	-	-	-	✓	✓	✓	13, 14, 20, 38, 114
	SS3	1.5 - 2.1		✓	✓	✓	-	-	-	
BH21-22	SS1	0.0 - 0.6	22-Nov-21	✓	-	-	-	-	-	13, 14, 27, 38, 114
	SS3	1.5 - 2.1		-	-	-	✓	✓	✓	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-23	S1	0.0 - 0.6	5-Nov-21	-	-	-	✓	-	-	13, 14, 38, 53, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	-	✓	✓	
BH21-24	S1	0.0 - 0.6	5-Nov-21	-	-	-	-	✓	✓	13, 14, 38, 56, 114
	S2	0.6 - 1.2		-	-	-	✓	-	-	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-45	SS1	0.0 - 0.6	22-Nov-21	-	-	-	✓	✓	✓	13, 14, 17, 38, 114
	SS2	0.8 - 1.4		✓	-	-	✓	-	-	
	SS8	7.6 - 8.2		-	✓	✓	-	-	-	
	SS9	9.1 - 9.8		-	✓	✓	-	-	-	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3B: Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-2	2.8 - 5.8	7-Dec-21	-	✓	-	-	-	-	13, 14, 30, 38, 114
BH21-6	3.1 - 6.1	6-Dec-21	✓	✓	-	-	-	-	10, 13, 14, 38, 114
BH21-7	2.8 - 5.8	2-Dec-21	✓	✓	✓	✓	✓	✓	4, 13, 14, 38, 114
BH21-8	6.1 - 9.1	2-Dec-21	✓	✓	✓	✓	-	-	42, 13, 14, 38, 114
BH21-16	6.1 - 9.1	6-Dec-21	✓	✓	✓	✓	-	-	13, 14, 26, 38, 114
BH21-22	3.4 - 6.4	1-Dec-21	✓	✓	✓	✓	-	-	13, 14, 27, 38, 114
BH21-45	6.1 - 9.1	1-Dec-21	✓	✓	✓	✓	✓	-	13, 14, 38, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-2 SS2	BH21-3 SS3	QAQC-12	BH21-4 SS1	BH21-5 SS1	BH21-6 SS2	BH21-7 SS2
Date of Collection	Table 2 RPI CT	Dec 02, 2021	Dec 02, 2021		Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021		Dec 18, 2021	Dec 18, 2021	Dec 23, 2021	Dec 14, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6		0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.8 - 1.4
Analytical Report Reference No.		21T839096	21T839096		21T840564	21T840564	21T839096	21T836919
Antimony	7.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	6	4	6	4	7	4	6
Barium	390	89.8	77.5	52.7	37.4	60	54.5	57.1
Beryllium	4	0.8	0.6	0.5	0.5	0.7	<0.4	0.7
Boron	120	10	8	7	<5	7	7	11
Boron (Hot Water Extractable)	1.5	0.42	0.12	0.17	0.12	0.26	0.17	0.25
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	160	20	17	15	12	18	14	22
Cobalt	22	9.2	7.8	7.8	5.6	6.6	8.1	10.4
Copper	140	42.9	24.8	33.3	24.7	23.3	32	29.1
Lead	120	60	9	12	9	18	8	10
Molybdenum	6.9	0.6	<0.5	<0.5	<0.5	0.6	<0.5	<0.5
Nickel	100	19	17	22	12	14	15	21
Selenium	2.4	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	20	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	23	0.6	<0.50	<0.50	<0.50	<0.50	<0.50	0.59
Vanadium	86	30.4	25.5	22.4	20.4	28.1	23.8	31.9
Zinc	340	95	44	43	32	51	39	55
Chromium, Hexavalent	8	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.353	0.216	0.185	0.124	0.200	0.327	0.245
Sodium Adsorption Ratio	5	1.560	0.438	0.300	0.143	0.116	2.140	2.170
pH, 2:1 CaCl2 Extraction	*	7.29	7.25	7.32	7.19	7.04	7.61	7.19

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-8 SS2	BH21-16 SS1	BH21-17 S1	BH21-18 SS1	BH21-19 SS2	BH21-20 SS1	QAQC-6
Date of Collection	Table 2 RPI CT	Nov 29, 2021	Dec 01, 2021	Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021	
Date Reported		Dec 14, 2021	Dec 15, 2021	Nov 16, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6	
Analytical Report Reference No.		21T836919	21T839096	21T826519	21T834550	21T834550	21T834550	
Antimony	7.5	<0.8	2.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	6	8	7	6	6	6	5
Barium	390	57.4	88.5	62.8	94.5	82.7	71.9	71.5
Beryllium	4	0.5	0.5	0.6	0.6	0.6	<0.4	<0.4
Boron	120	10	9	9	7	11	<5	<5
Boron (Hot Water Extractable)	1.5	0.21	0.50	0.66	0.26	0.11	0.21	0.22
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	160	19	35	20	25	25	20	20
Cobalt	22	10.0	10.6	7.9	11.5	13.3	16.5	11.8
Copper	140	31.5	69	28.8	33.4	25.2	48.7	25.8
Lead	120	12	79	22	10	11	18	17
Molybdenum	6.9	<0.5	3.7	0.7	<0.5	<0.5	0.6	0.6
Nickel	100	20	31	19	24	26	**142**	25
Selenium	2.4	<0.8	0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	20	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	23	<0.50	<0.50	<0.50	0.5	0.6	0.5	<0.50
Vanadium	86	28.4	33.8	29	35.1	35.8	30.9	30.7
Zinc	340	51	**468**	77	66	59	61	67
Chromium, Hexavalent	8	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	0.22	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.117	0.290	0.186	0.154	0.110	0.154	0.157
Sodium Adsorption Ratio	5	0.122	1.640	0.055	1.000	0.186	0.105	0.107
pH, 2:1 CaCl2 Extraction	*	7.12	7.50	7.16	7.55	7.56	7.44	7.36

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-20 SS4	BH21-21 SS3	BH21-22 SS1	BH21-23 S2	BH21-24 S3	BH21-45 SS2
Date of Collection	Table 2 RPI CT	Nov 23, 2021	Nov 23, 2021	Nov 22, 2021	Nov 05, 2021	Nov 05, 2021	Nov 22, 2021
Date Reported		Dec 20, 2021	Dec 03, 2021	Dec 03, 2021	Nov 16, 2021	Nov 16, 2021	Dec 03, 2021
Sampling Depth (mbgs)		2.3 - 2.9	1.5 - 2.1	0.0 - 0.6	0.6 - 1.2	1.2 - 1.8	0.8 - 1.4
Analytical Report Reference No.		21T841262	21T834550	21T834550	21T826519	21T826519	21T834550
Antimony	7.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	5	5	6	7	6	7
Barium	390	95.4	56.1	96.2	54.8	41.5	83
Beryllium	4	0.6	<0.4	0.5	0.6	0.4	0.5
Boron	120	24	8	9	10	7	9
Boron (Hot Water Extractable)	1.5	0.26	<0.10	0.12	0.26	<0.10	0.44
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	160	25	14	24	22	16	25
Cobalt	22	14.8	7.6	11.9	11.2	9.8	15.3
Copper	140	10.6	23.4	29.7	36.6	34.8	33.8
Lead	120	12	10	10	9	7	11
Molybdenum	6.9	1.2	<0.5	<0.5	0.7	<0.5	<0.5
Nickel	100	27	13	23	25	20	33
Selenium	2.4	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	20	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	23	0.8	<0.50	0.6	0.5	<0.50	0.7
Vanadium	86	40.2	22.7	34.9	29.5	23.4	34
Zinc	340	63	35	57	63	53	68
Chromium, Hexavalent	8	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.125	0.088	0.125	0.157	0.103	0.314
Sodium Adsorption Ratio	5	0.344	0.095	0.182	0.370	0.095	1.200
pH, 2:1 CaCl2 Extraction	*	7.13	7.62	7.64	7.59	7.66	7.60

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTEX

Parameter		BH21-2 SS5	BH21-3 SS6	BH21-4 SS3	BH21-5 SS2	BH21-6 SS6	BH21-7 SS5	BH21-8 SS7	BH21-16 SS8
Date of Collection	Table 2 RPI CT	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021	Nov 29, 2021	Dec 01, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021	Dec 18, 2021	Dec 18, 2021	Dec 15, 2021	Dec 14, 2021	Dec 14, 2021	Dec 15, 2021
Sampling Depth (mbgs)		3.0 - 3.7	4.6 - 5.2	1.8 - 1.8	0.6 - 1.2	4.6 - 5.2	3.0 - 3.7	6.1 - 6.7	7.6 - 8.2
Analytical Report Reference No.		21T839096	21T839096	21T840564	21T840564	21T839096	21T836919	21T836919	21T839096
Benzene	0.21	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Toluene	2.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Total Xylenes	3.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	55	<5	<5	<5	<5	<5	<5	<5	<5
F2 (C10 to C16)	98	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	300	<50	<50	<50	<50	<50	<50	<50	<50
F4 (C34 to C50)	2800	<50	<50	<50	<50	<50	<50	<50	<50

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTE

Parameter		BH21-17 S2	BH21-18 SS2	BH21-19 SS2	BH21-20 SS3	QAQC-8	BH21-21 SS3	BH21-22 SS5	BH21-23 S3
Date of Collection	Table 2 RPI CT	Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021		Nov 23, 2021	Nov 22, 2021	Nov 05, 2021
Date Reported		Nov 30, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021		Dec 03, 2021	Dec 03, 2021	Nov 30, 2021
Sampling Depth (mbgs)		0.6 - 1.2	0.8 - 1.4	0.8 - 1.4	1.5 - 2.1		1.5 - 2.1	3.0 - 3.7	1.2 - 1.8
Analytical Report Reference No.		21T832162	21T834550	21T834550	21T834550		21T834550	21T834550	21T832162
Benzene	0.21	<0.005	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.005
Toluene	2.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.01	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.01
Total Xylenes	3.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	55	<10	<5	<5	<5	<5	<5	<5	<10
F2 (C10 to C16)	98	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	300	13	<50	<50	<50	<50	<50	<50	<10
F4 (C34 to C50)	2800	<10	<50	<50	<50	<50	<50	<50	<10

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTE

Parameter		BH21-24 S3	BH21-45 SS8	BH21-45 SS9
Date of Collection	Table 2 RPI CT	Nov 05, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Nov 30, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		1.2 - 1.8	7.6 - 8.2	9.1 - 9.8
Analytical Report Reference No.		21T832162	21T834550	21T841262
Benzene	0.21	<0.005	<0.02	<0.02
Toluene	2.3	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.01	0.9	<0.05
Total Xylenes	3.1	<0.05	**5.55**	<0.05
F1 (C6 to C10) minus BTEX	55	<10	51	<5
F2 (C10 to C16)	98	<10	<10	<10
F3 (C16 to C34)	300	14	<50	<50
F4 (C34 to C50)	2800	<10	<50	<50

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 6B Soil Analytical Results - VOCs

Parameter		BH21-7 SS5	BH21-8 SS7	BH21-16 SS8	BH21-21 SS3	BH21-22 SS5	BH21-45 SS8	BH21-45 SS9
Date of Collection	Table 2 RPI CT	Nov 29, 2021	Nov 29, 2021	Dec 01, 2021	Nov 23, 2021	Nov 22, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Dec 14, 2021	Dec 14, 2021	Dec 15, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		3.0 - 3.7	6.1 - 6.7	7.6 - 8.2	1.5 - 2.1	3.0 - 3.7	7.6 - 8.2	9.1 - 9.8
Analytical Report Reference No.		21T836919	21T836919	21T839096	21T834550	21T834550	21T834550	21T841262
Acetone	16	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Benzene	0.21	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Bromodichloromethane	1.5	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Bromoform	0.27	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Bromomethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Carbon Tetrachloride	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chlorobenzene	2.4	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chloroform	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Dibromochloromethane	2.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,2-	1.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,3-	4.8	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,4-	0.083	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorodifluoromethane	16	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethane, 1,1-	0.47	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Dichloroethane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
Dichloroethylene, 1,1-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethylene, Cis- 1,2-	1.9	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Dichloroethylene, Trans- 1,2-	0.084	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloropropane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.05	<0.05	<0.05	<0.05	<0.05	0.9	<0.05
Ethylene Dibromide	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Hexane, n-	2.8	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methyl Ethyl Ketone	16	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Methyl Isobutyl Ketone	1.7	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Methyl tert-butyl Ether	0.75	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methylene Chloride	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Styrene	0.7	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	0.058	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Tetrachloroethane, 1,1,2,2-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethylene	0.28	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Toluene	2.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,1-	0.38	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Trichloroethylene	0.061	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
Trichlorofluoromethane	4	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Vinyl Chloride	0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Xylene mixture	3.1	<0.05	<0.05	<0.05	<0.05	<0.05	**5.55**	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		BH21-2 SS2	BH21-4 SS1	BH21-5 SS1	BH21-6 SS2	BH21-7 SS1	BH21-8 SS1
Date of Collection	Table 2 RPI CT	Dec 02, 2021	Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021	Nov 29, 2021
Date Reported		Dec 15, 2021	Dec 18, 2021	Dec 18, 2021	Dec 23, 2021	Dec 14, 2021	Dec 14, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T839096	21T840564	21T840564	21T839096	21T836919	21T836919
Naphthalene	0.6	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.15	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Acenaphthene	7.9	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	62	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	6.2	<0.05	<0.05	<0.05	<0.05	0.40	0.22
Anthracene	0.67	<0.05	<0.05	<0.05	<0.05	0.18	0.10
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	**1.05**	**0.89**
Pyrene	78	<0.05	<0.05	<0.05	<0.05	0.96	0.77
Benz(a)anthracene	0.5	<0.05	<0.05	<0.05	<0.05	**0.56**	0.46
Chrysene	7	<0.05	<0.05	<0.05	<0.05	0.41	0.36
Benzo(b)fluoranthene	0.78	<0.05	<0.05	<0.05	<0.05	0.60	0.66
Benzo(k)fluoranthene	0.78	<0.05	<0.05	<0.05	<0.05	0.23	0.24
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	**0.40**	**0.40**
Indeno(1,2,3-cd)pyrene	0.38	<0.05	<0.05	<0.05	<0.05	0.22	0.26
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	0.05	0.05
Benzo(g,h,i)perylene	6.6	<0.05	<0.05	<0.05	<0.05	0.27	0.34
Methylnaphthalene, 2-(1-)	0.99	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		BH21-16 SS2	QAQC-10	BH21-17 S3	BH21-18 SS2	BH21-19 SS1	BH21-20 SS2	QAQC-7
Date of Collection	Table 2 RPI CT	Dec 02, 2021		Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021	
Date Reported		Dec 15, 2021		Nov 16, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	
Sampling Depth (mbgs)		0.8 - 1.4		1.2 - 1.8	0.8 - 1.4	0.0 - 0.6	0.8 - 1.4	
Analytical Report Reference No.		21T839096		21T826519	21T834550	21T834550	21T834550	
Naphthalene	0.6	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.15	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	7.9	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	62	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	6.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.67	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	0.14	<0.05	<0.05
Pyrene	78	<0.05	<0.05	<0.05	<0.05	0.16	<0.05	<0.05
Benz(a)anthracene	0.5	<0.05	<0.05	<0.05	<0.05	0.17	<0.05	<0.05
Chrysene	7	<0.05	<0.05	<0.05	<0.05	0.07	<0.05	<0.05
Benzo(b)fluoranthene	0.78	<0.05	<0.05	<0.05	<0.05	0.1	<0.05	<0.05
Benzo(k)fluoranthene	0.78	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	0.07	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.38	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	6.6	<0.05	<0.05	<0.05	<0.05	0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.99	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		BH21-21 SS1	BH21-22 SS3	BH21-23 S1	BH21-24 S2	BH21-45 SS1	BH21-45 SS2
Date of Collection	Table 2 RPI CT	Nov 23, 2021	Nov 22, 2021	Nov 05, 2021	Nov 05, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021	Nov 16, 2021	Nov 16, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	1.5 - 2.1	0.0 - 0.6	0.6 - 1.2	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T834550	21T834550	21T826519	21T826519	21T834550	21T841262
Naphthalene	0.6	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.15	<0.05	<0.05	<0.05	<0.05	0.09	<0.05
Acenaphthene	7.9	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	62	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	6.2	<0.05	<0.05	<0.05	<0.05	0.24	<0.05
Anthracene	0.67	<0.05	<0.05	<0.05	<0.05	0.13	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	0.57	<0.05
Pyrene	78	<0.05	<0.05	<0.05	<0.05	0.6	<0.05
Benz(a)anthracene	0.5	<0.05	<0.05	<0.05	<0.05	0.39	<0.05
Chrysene	7	<0.05	<0.05	<0.05	<0.05	0.35	<0.05
Benzo(b)fluoranthene	0.78	<0.05	<0.05	0.09	<0.05	0.45	<0.05
Benzo(k)fluoranthene	0.78	<0.05	<0.05	0.09	<0.05	0.19	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	0.05	<0.05	**0.33**	<0.05
Indeno(1,2,3-cd)pyrene	0.38	<0.05	<0.05	<0.05	<0.05	0.19	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Benzo(g,h,i)perylene	6.6	<0.05	<0.05	<0.05	<0.05	0.23	<0.05
Methylnaphthalene, 2-(1-)	0.99	<0.05	<0.05	<0.05	<0.05	0.15	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 8B Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-4 SS2	BH21-5 SS3	BH21-7 SS1	BH21-17 S2	BH21-20 SS2	QAQC-7	BH21-23 S3	BH21-24 S1	BH21-45 SS1
Date of Collection	Table 2 RPI CT	Dec 06, 2021	Dec 06, 2021	Nov 29, 2021	Nov 05, 2021	Nov 23, 2021		Nov 05, 2021	Nov 05, 2021	Nov 22, 2021
Date Reported		Dec 18, 2021	Dec 18, 2021	Dec 14, 2021	Nov 16, 2021	Dec 03, 2021		Nov 16, 2021	Nov 16, 2021	Dec 03, 2021
Sampling Depth (m bgs)		0.6 - 1.6	1.2 - 1.8	0.0 - 0.6	0.6 - 1.2	0.8 - 1.4		1.2 - 1.8	0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T840564	21T840564	21T836919	21T826519	21T834550		21T826519	21T826519	21T834550
Polychlorinated Biphenyls	0.35	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	3.3	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.26	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.15	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.52	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.012	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.056	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.089	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.13	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9B Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-6	BH21-7	BH21-8	BH21-16		BH21-22	BH21-45	QA/QC	BH21-45
Date of Collection	Table 2 Potable GW CT	Dec 06, 2021	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021	Feb 11, 2022	Dec 01, 2021	Dec 01, 2021		Feb 11, 2022
Date Reported		Dec 21, 2021	Dec 15, 2021	Dec 15, 2021	Dec 21, 2021	Feb 14, 2022	Dec 16, 2021	Dec 16, 2021		Feb 14, 2022
Screened Depth (mbgs)		3.1 - 6.1	2.8 - 5.8	6.1 - 9.1	6.1 - 9.1		3.4 - 6.4	6.1 - 9.1		
Analytical Report Reference No.		21T841270	21T839088	21T839088	21T841270	22T862998	21T838602	21T838602		22T862998
Antimony	6	<1.0	<1.0	<1.0	1.1	-	<1.0	<1.0	<1.0	-
Arsenic	25	4.7	<1.0	4.3	<1.0	-	1.1	4.7	1.6	-
Barium	1000	271	254	109	63.9	-	91.9	80.5	62.4	-
Beryllium	4	<0.50	<0.50	<0.50	<0.50	-	<0.50	<0.50	<0.50	-
Boron	5000	279	362	131	1676	-	219	682	115	-
Cadmium	2.7	<0.20	<0.20	<0.20	<0.20	-	<0.20	<0.20	<0.20	-
Chromium	50	25.3	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Chromium VI	25	5.43	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Cobalt	3.8	**4.53**	0.52	0.63	<0.50	-	1.06	0.66	2.87	-
Copper	87	2.7	1.9	<1.0	<1.0	-	<1.0	<1.0	<1.0	-
Cyanide	66	<2.0	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Lead	10	0.93	<0.50	<0.50	<0.50	-	<0.50	<0.50	<0.50	-
Mercury	0.29	<0.02	<0.02	<0.02	<0.02	-	<0.02	<0.02	<0.02	-
Molybdenum	70	6.45	14.2	7.84	24.7	32.1	4.41	28	4.27	57.1
Nickel	100	6.9	2.8	9.7	1.1	-	1.9	4.7	4.2	-
Selenium	10	<1.0	<1.0	<1.0	1.6	-	<1.0	<1.0	<1.0	-
Silver	1.5	<0.20	<0.20	<0.20	<0.20	-	<0.20	<0.20	<0.20	-
Thallium	2	<0.30	<0.30	<0.30	<0.30	-	<0.30	<0.30	<0.30	-
Uranium	20	3.52	3.19	1.11	1.86	-	2.18	1.5	0.96	-
Vanadium	6.2	3.29	1.42	0.62	0.62	-	0.63	0.83	<0.40	-
Zinc	1100	6.1	<5.0	<5.0	<5.0	-	<5.0	<5.0	<5.0	-
Sodium	490000	342000	417000	23000	210000	-	43800	205000	77700	-
Chloride	790000	**1460000**	768000	72700	286000	-	63300	326000	156000	-

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 10B Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-2	BH21-6	QAQC-2	BH21-7	QAQC-1	BH21-8	BH21-16	BH21-22	BH21-45	QA/QC
Date of Collection	Table 2 Potable GW CT	Dec 07, 2021	Dec 06, 2021		Dec 02, 2021		Dec 02, 2021	Dec 06, 2021	Dec 01, 2021	Dec 01, 2021	
Date Reported		Dec 21, 2021	Dec 21, 2021		Dec 15, 2021		Dec 15, 2021	Dec 21, 2021	Dec 16, 2021	Dec 16, 2021	
Screened Depth (mbgs)		2.8 - 5.8	3.1 - 6.1		2.8 - 5.8		6.1 - 9.1	6.1 - 9.1	3.4 - 6.4	6.1 - 9.1	
Analytical Report Reference No.		21T841270	21T841270		21T839088		21T839088	21T841270	21T838602	21T838602	
Benzene	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	24	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Ethylbenzene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Xylene Mixture	300	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
F1 (C6 to C10) minus BTEX	750	<25	<25	<25	<25	<25	<25	<25	<25	<25	<25
F2 (C10 to C16)	150	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
F3 (C16 to C34)	500	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
F4 (C34 to C50)	500	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 11B Groundwater Analytical Results - VOCs

Parameter		BH21-7	BH21-8	BH21-16	QAQC-1	BH21-22	BH21-45	QA/QC	Trip Blank	Trip Blank	Trip Blank
Date of Collection	Table 2 Potable GW CT	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021		Dec 01, 2021	Dec 01, 2021		Nov 23, 2021	Nov 30, 2021	Dec 04, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021	Dec 21, 2021		Dec 16, 2021	Dec 16, 2021		Dec 03, 2021	Dec 16, 2021	Dec 21, 2021
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1	6.1 - 9.1		3.4 - 6.4	6.1 - 9.1		-	-	-
Analytical Report Reference No.		21T839088	21T839088	21T841270		21T838602	21T838602		21T834096	21T838602	21T841270
Acetone	2700	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Benzene	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Bromodichloromethane	16	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Bromoform	25	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Bromomethane	0.89	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Carbon Tetrachloride	0.79	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Chlorobenzene	30	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Chloroform	2.4	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dibromochloromethane	25	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,2-	3	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,3-	59	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,4-	1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorodifluoromethane	590	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethane, 1,1-	5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethane, 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, 1,1-	1.6	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethylene, cis- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, trans- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropane, 1,2-	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropene, 1,3-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Ethylbenzene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	0.2	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Hexane, n-	51	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Ethyl Ketone	1800	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl Isobutyl Ketone	640	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl tert-butyl ether	15	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methylene Chloride	50	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Styrene	5.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,1,2-	1.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,2,2-	1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	24	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethane, 1,1,1-	200	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Trichloroethane, 1,1,2-	4.7	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethylene	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	150	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40
Vinyl Chloride	0.5	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17
Xylene Mixture	300	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 12B Groundwater Analytical Results - PAHs

Parameter		BH21-7	BH21-8	QAQC-2	BH21-16	BH21-22	BH21-45	QA/QC	BH21-45
Date of Collection	Table 2 Potable GW CT	Dec 02, 2021	Dec 02, 2021		Dec 06, 2021	Dec 01, 2021	Dec 01, 2021		Feb 11, 2022
Date Reported		Dec 15, 2021	Dec 15, 2021		Dec 21, 2021	Dec 16, 2021	Dec 16, 2021		Feb 14, 2022
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1		6.1 - 9.1	3.4 - 6.4	6.1 - 9.1		
Analytical Report Reference No.		21T839088	21T839088		21T841270	21T838602	21T838602		22T862998
Acenaphthene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Anthracene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10	1.79	1	<0.10
Benz(a)anthracene	1	<0.20	<0.20	<0.20	<0.20	<0.20	**2.4**	**1.67**	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	**3.67**	**2.8**	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**4.92**	**3.29**	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**2.48**	**1.89**	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**2.19**	**1.86**	<0.10
Chrysene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**5.59**	**4.01**	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**0.32**	**0.21**	<0.20
Fluoranthene	0.41	<0.20	<0.20	<0.20	<0.20	<0.20	**17.9**	**11.2**	<0.20
Fluorene	120	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	0.56	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**1.8**	**1.35**	<0.20
Methyl Naphthalene, 2-and 1-	3.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Naphthalene	11	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Phenanthrene	1	<0.10	<0.10	<0.10	<0.10	<0.10	**12**	**9.08**	<0.10
Pyrene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	**14.6**	**9.52**	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 13B Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-7	BH21-45	QA/QC
Date of Collection	Table 2 Potable GW CT	Dec 02, 2021	Dec 01, 2021	
Date Reported		Dec 15, 2021	Dec 16, 2021	
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1	
Analytical Report Reference No.		21T839088	21T838602	
Polychlorinated Biphenyls	3	<0.1	<0.1	<0.1
Aldrin	0.35	<0.01	-	-
Chlordane	7	<0.04	-	-
DDD	10	<0.05	-	-
DDE	10	<0.01	-	-
DDT	2.8	<0.04	-	-
Dieldrin	0.35	<0.02	-	-
Endosulfan	1.5	<0.05	-	-
Endrin	0.48	<0.05	-	-
Heptachlor	1.5	<0.01	-	-
Heptachlor Epoxide	0.048	<0.01	-	-
Hexachlorobenzene	1	<0.01	-	-
Hexachlorobutadiene	0.44	<0.01	-	-
Hexachlorocyclohexane Gamma-	1.2	<0.01	-	-
Hexachloroethane	2.1	<0.01	-	-
Methoxychlor	6.5	<0.04	-	-

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14B Summary of Maximum Concentrations in Soil

Group	Parameter	Table 2 RPI CT	Maximum Concentration	Location
BTEX	Benzene	0.21	<0.02	all samples
	Ethylbenzene	1.1	0.9	BH21-45 SS8
	Toluene	2.3	<0.05	all samples
	Total Xylenes	3.1	5.55	BH21-45 SS8
Metals	Barium	390	96.2	BH21-22 SS1
	Beryllium	4	0.8	BH21-2 SS2
	Boron	120	24	BH21-20 SS4
	Cadmium	1.2	<0.5	all samples
	Chromium	160	35	BH21-16 SS1
	Cobalt	22	16.5	BH21-20 SS1
	Copper	140	69	BH21-16 SS1
	Lead	120	79	BH21-16 SS1
	Molybdenum	6.9	3.7	BH21-16 SS1
	Nickel	100	142	BH21-20 SS1
	Silver	20	<0.5	all samples
	Thallium	1	<0.5	all samples
	Uranium	23	0.79	BH21-20 SS4
	Vanadium	86	40.2	BH21-20 SS4
	Zinc	340	468	BH21-16 SS1
As, Se, Sb	Antimony	7.5	2.8	BH21-16 SS1
	Arsenic	18	8	BH21-16 SS1
	Selenium	2.4	0.8	BH21-16 SS1
PAHs	Acenaphthene	7.9	<0.05	all samples
	Acenaphthylene	0.15	0.09	BH21-45 SS1
	Anthracene	0.67	0.18	BH21-7 SS1
	Benz(a)anthracene	0.5	0.56	BH21-7 SS1
	Benzo(a)pyrene	0.3	0.4	BH21-7 SS1
	Benzo(b)fluoranthene	0.78	0.66	BH21-8 SS1
	Benzo(g,h,i)perylene	6.6	0.34	BH21-8 SS1
	Benzo(k)fluoranthene	0.78	0.24	BH21-8 SS1
	Chrysene	7	0.41	BH21-7 SS1
	Dibenz(a,h)anthracene	0.1	0.06	BH21-45 SS1
	Fluoranthene	0.69	1.05	BH21-7 SS1
	Fluorene	62	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.38	0.26	BH21-8 SS1
	Methylnaphthalene, 2-(1-)	0.99	0.15	BH21-45 SS1
	Naphthalene	0.6	<0.05	all samples
	Phenanthrene	6.2	0.4	BH21-7 SS1
	Pyrene	78	0.96	BH21-7 SS1
PHCs	F1 (C6 to C10) minus BTEX	55	51	BH21-45 SS8
	F2 (C10 to C16)	98	<10	all samples
	F3 (C16 to C34)	300	14	BH21-24 S3
	F4 (C34 to C50)	2800	<50	all samples
	Acetone	16	<0.50	all samples
	Bromodichloromethane	1.5	<0.05	all samples
	Bromoform	0.27	<0.05	all samples
	Bromomethane	0.05	<0.05	all samples
	Carbon Tetrachloride	0.05	<0.05	all samples
	Chlorobenzene	2.4	<0.05	all samples
	Chloroform	0.05	<0.04	all samples
	Dibromochloromethane	2.3	<0.05	all samples
	Dichlorobenzene, 1,2-	1.2	<0.05	all samples

Table 14B Summary of Maximum Concentrations in Soil

Group	Parameter	Table 2 RPI CT	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	4.8	<0.05	all samples
	Dichlorobenzene, 1,4-	0.083	<0.05	all samples
	Dichlorodifluoromethane	16	<0.05	all samples
	Dichloroethane, 1,1-	0.47	<0.02	all samples
	Dichloroethane, 1,2-	0.05	<0.03	all samples
	Dichloroethylene, 1,1-	0.05	<0.05	all samples
	Dichloroethylene, Cis- 1,2-	1.9	<0.02	all samples
	Dichloroethylene, Trans- 1,2-	0.084	<0.05	BH21-45 SS8
	Dichloropropane, 1,2-	0.05	<0.03	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	BH21-45 SS8
	Ethylene Dibromide	0.05	<0.04	all samples
	Hexane, n-	2.8	<0.05	all samples
	Methyl Ethyl Ketone	16	<0.50	all samples
	Methyl Isobutyl Ketone	1.7	<0.50	all samples
	Methyl tert-butyl Ether	0.75	<0.05	all samples
	Methylene Chloride	0.1	<0.05	all samples
	Styrene	0.7	<0.05	all samples
	Tetrachloroethane, 1,1,1,2-	0.058	<0.04	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.05	all samples
	Tetrachloroethylene	0.28	<0.05	all samples
	Trichloroethane, 1,1,1-	0.38	<0.05	all samples
	Trichloroethane, 1,1,2-	0.05	<0.04	all samples
	Trichloroethylene	0.061	<0.03	all samples
	Trichlorofluoromethane	4	<0.05	all samples
	Vinyl Chloride	0.02	<0.02	all samples
ORPs	Chromium, Hexavalent	8	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.7	0.353	BH21-2 SS2
	Mercury	0.27	0.22	BH21-16 SS1
	Sodium Adsorption Ratio	5	2.17	BH21-7 SS2
	pH, 2:1 CaCl2 Extraction	*	7.66	BH21-24 S3
PCBs	Polychlorinated Biphenyls	0.35	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15B Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 2 Potable GW CT	Maximum Concentration	Location
BTEX	Benzene	5	<0.20	all samples
	Ethylbenzene	2.4	<0.10	all samples
	Toluene	24	<0.20	all samples
	Xylene Mixture	300	<0.20	all samples
Metals	Barium	1000	271	BH21-22
	Beryllium	4	<0.50	all samples
	Boron	5000	1676	BH21-16
	Cadmium	2.7	<0.20	all samples
	Chromium	50	25.3	all samples
	Cobalt	3.8	4.53	QA/QC
	Copper	87	2.7	all samples
	Lead	10	0.93	all samples
	Molybdenum	70	57.1	BH21-45
	Nickel	100	9.7	BH21-45
	Silver	1.5	<0.20	all samples
	Thallium	2	<0.30	all samples
	Uranium	20	3.52	BH21-22
	Vanadium	6.2	3.29	BH21-45
	Zinc	1100	6.1	all samples
As, Se, Sb	Antimony	6	1.1	BH21-16
	Arsenic	25	4.7	BH21-45
	Selenium	10	1.6	BH21-16
Na	Sodium	490000	417000	BH21-16
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	2.4	1.79	BH21-45
	Benz(a)anthracene	1	2.4	BH21-45
	Benzo(a)pyrene	0.01	3.67	BH21-45
	Benzo(b)fluoranthene	0.1	4.92	BH21-45
	Benzo(g,h,i)perylene	0.2	2.48	BH21-45
	Benzo(k)fluoranthene	0.1	2.19	BH21-45
	Chrysene	0.1	5.59	BH21-45
	Dibenz(a,h)anthracene	0.2	0.32	BH21-45
	Fluoranthene	0.41	17.9	BH21-45
	Fluorene	120	0.56	QA/QC
	Indeno(1,2,3-cd)pyrene	0.2	1.8	BH21-45
	Methyl Naphthalene, 2-and 1-	3.2	<0.20	all samples
	Naphthalene	11	<0.20	all samples
	Phenanthrene	1	12	BH21-45
	Pyrene	4.1	14.6	BH21-45
PHCs	F1 (C6 to C10) minus BTEX	750	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	16	<0.20	all samples
	Bromoform	25	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.79	<0.20	all samples
	Chlorobenzene	30	<0.10	all samples
	Chloroform	2.4	<0.20	all samples
	Dibromochloromethane	25	<0.10	all samples

Table 15B Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 2 Potable GW CT	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,2-	3	<0.10	all samples
	Dichlorobenzene, 1,3-	59	<0.10	all samples
	Dichlorobenzene, 1,4-	1	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	5	<0.30	all samples
	Dichloroethane, 1,2-	1.6	<0.20	all samples
	Dichloroethylene, 1,1-	1.6	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	51	<0.20	all samples
	Methyl Ethyl Ketone	1800	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	50	<0.30	all samples
	Styrene	5.4	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	1	<0.10	all samples
	Tetrachloroethylene	1.6	<0.20	all samples
	Trichloroethane, 1,1,1-	200	<0.30	all samples
	Trichloroethane, 1,1,2-	4.7	<0.20	all samples
	Trichloroethylene	1.6	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	1460000	BH21-45
	Chromium VI	25	5.43	all samples
	Cyanide	66	<2.0	all samples
	Mercury	0.29	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Notes for Soil & Groundwater Summary Tables - Brampton (B-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 8 RPIICC = Generic Site Condition Standards for Use within 30 m of a Water Body in a Potable Groundwater Condition as contained in Table 8 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011
11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 8 SCS

Table 1B Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-2	BH21-3	BH21-6	BH21-7	BH21-8	BH21-16	BH21-22	BH21-45
Installed By			WSP	WSP	WSP	WSP	WSP	WSP	WSP	WSP
Installation Date			2-Dec-21	2-Dec-21	1-Dec-21	29-Nov-21	29-Nov-21	1-Dec-21	22-Nov-21	22-Nov-21
Well Status			Active	Active	Active	Active	Active	Active	Active	Active
Well Inner Diameter		(mm)	50	50	50	50	50	50	50	50
Casing Type (Flushmount / Monument)			Monument	Monument	Flushmount	Monument	Monument	Flushmount	Monument	Flushmount
Top of Pipe Elevation		(masl)	184.852	187.353	216.625	218.769	220.065	218.014	244.619	218.032
Ground Surface Elevation		(masl)	183.942	186.453	216.805	217.859	219.165	218.114	243.709	218.122
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
		(masl)	183.642	186.153	216.505	217.559	218.865	217.814	243.409	217.822
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	2.2	3.7	2.5	2.2	5.5	5.5	2.8	5.5
		(masl)	181.8	182.8	214.3	215.7	213.7	212.6	240.9	212.6
Top of Well Screen		(mbgs)	2.8	4.3	3.1	2.8	6.1	6.1	3.4	6.1
		(masl)	181.1	182.2	213.7	215.1	213.1	212.0	240.3	212.0
Screen Length		(m)	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0
Bottom of Screen		(mbgs)	5.8	7.3	6.1	5.8	9.1	9.1	6.4	9.1
		(masl)	178.2	179.1	210.7	212.1	210.1	209.0	237.3	209.0
30-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	0.7	4.3
	GW Elevation	(masl)	-	-	-	-	-	-	243.0	213.8
1-Dec-21	Depth of GW	(mbgs)	-	-	-	1.3	2.4	-	-	5.3
	GW Elevation	(masl)	-	-	-	216.6	216.7	-	-	212.9
2-Dec-21	Depth of GW	(mbgs)	-	-	0.3	1.1	2.3	5.0	-	-
	GW Elevation	(masl)	-	-	216.5	216.7	216.9	213.2	-	-
6-Dec-21	Depth of GW	(mbgs)	2.4	DRY	-	-	-	-	-	-
	GW Elevation	(masl)	181.3	-	-	-	-	-	-	-
7-Dec-21	Depth of GW	(mbgs)	2.4	DRY	0.2	1.1	2.3	5.0	1.0	5.2
	GW Elevation	(masl)	181.6	-	216.6	216.8	216.9	213.2	242.7	212.9

See "Notes for Soil and Groundwater Summary

Table 2B Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-2	SS2	0.8 - 1.4	2-Dec-21	✓	-	-	✓	-	-	13, 14, 30, 38, 114
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
	QAQC-11			-	✓	-	-	-	-	
BH21-3	SS1	0.0 - 0.6	2-Dec-21	✓	-	-	-	-	-	13, 14, 38, 114
	QAQC-12			✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	-	-	-	-	
BH21-4	SS1	0.0 - 0.6	6-Dec-21	✓	-	-	✓	-	-	13, 14, 38, 44, 114
	SS2	0.6 - 1.2		-	-	-	-	✓	✓	
	SS3	1.2 - 1.8		-	✓	-	-	-	-	
BH21-5	SS1	0.0 - 0.6	6-Dec-21	✓	-	✓	-	-	-	13, 14, 38, 47, 114
	SS2	0.6 - 1.2		-	✓	-	-	-	-	
	SS3	1.2 - 1.8		-	-	-	-	✓	✓	
BH21-6	SS1	0.0 - 0.6	1-Dec-21	-	-	-	✓	-	-	10, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS6	4.6 - 5.2		-	✓	-	-	-	-	
BH21-7	SS1	0.0 - 0.6	29-Nov-21	-	-	-	✓	✓	✓	4, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-8	SS1	0.0 - 0.6	29-Nov-21	-	-	-	✓	-	-	42, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS7	6.1 - 6.7		-	✓	✓	-	-	-	
BH21-16	SS1	0.0 - 0.6	1-Dec-21	✓	-	-	-	-	-	13, 14, 26, 38, 114
	SS2	0.8 - 1.4		-	-	-	✓	-	-	
	QAQC-10			-	-	-	✓	-	-	
	SS8	7.6 - 8.2		-	✓	✓	-	-	-	
BH21-17	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 49, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-18	SS1	0.0 - 0.6	24-Nov-21	✓	-	-	-	-	-	2, 13, 14, 38, 114
	SS2	0.8 - 1.4		-	✓	-	✓	✓	✓	
BH21-19	SS1	0.0 - 0.6	24-Nov-21	-	-	-	✓	-	-	8, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	✓	-	-	-	-	
BH21-20	SS1	0.0 - 0.6	23-Nov-21	✓	-	-	-	-	-	5, 13, 14, 38, 114
	QAQC-6			✓	-	-	-	-	-	
	SS2	0.8 - 1.4		-	-	-	✓	✓	✓	
	QAQC-7			-	-	-	✓	✓	✓	
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
	QAQC-8			-	✓	-	-	-	-	
	SS4	2.3 - 2.9		✓	-	-	-	-	-	
BH21-21	SS1	0.0 - 0.6	23-Nov-21	-	-	-	✓	✓	✓	13, 14, 20, 38, 114
	SS3	1.5 - 2.1		✓	✓	✓	-	-	-	
BH21-22	SS1	0.0 - 0.6	22-Nov-21	✓	-	-	-	-	-	13, 14, 27, 38, 114
	SS3	1.5 - 2.1		-	-	-	✓	✓	✓	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-23	S1	0.0 - 0.6	5-Nov-21	-	-	-	✓	-	-	13, 14, 38, 53, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	-	✓	✓	
BH21-24	S1	0.0 - 0.6	5-Nov-21	-	-	-	-	✓	✓	13, 14, 38, 56, 114
	S2	0.6 - 1.2		-	-	-	✓	-	-	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-45	SS1	0.0 - 0.6	22-Nov-21	-	-	-	✓	✓	✓	13, 14, 17, 38, 114
	SS2	0.8 - 1.4		✓	-	-	✓	-	-	
	SS8	7.6 - 8.2		-	✓	✓	-	-	-	
	SS9	9.1 - 9.8		-	✓	✓	-	-	-	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3B: Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-2	2.8 - 5.8	7-Dec-21	-	✓	-	-	-	-	13, 14, 30, 38, 114
BH21-6	3.1 - 6.1	6-Dec-21	✓	✓	-	-	-	-	10, 13, 14, 38, 114
BH21-7	2.8 - 5.8	2-Dec-21	✓	✓	✓	✓	✓	✓	4, 13, 14, 38, 114
BH21-8	6.1 - 9.1	2-Dec-21	✓	✓	✓	✓	-	-	42, 13, 14, 38, 114
BH21-16	6.1 - 9.1	6-Dec-21	✓	✓	✓	✓	-	-	13, 14, 26, 38, 114
BH21-22	3.4 - 6.4	1-Dec-21	✓	✓	✓	✓	-	-	13, 14, 27, 38, 114
BH21-45	6.1 - 9.1	1-Dec-21	✓	✓	✓	✓	✓	-	13, 14, 38, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-2 SS2	BH21-3 SS3	QAQC-12	BH21-4 SS1	BH21-5 SS1	BH21-6 SS2	BH21-7 SS2
Date of Collection	Table 8 RPIICC	Dec 02, 2021	Dec 02, 2021		Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021		Dec 18, 2021	Dec 18, 2021	Dec 23, 2021	Dec 14, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6		0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.8 - 1.4
Analytical Report Reference No.		21T839096	21T839096		21T840564	21T840564	21T839096	21T836919
Antimony	1.3	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	6	4	6	4	7	4	6
Barium	220	89.8	77.5	52.7	37.4	60	54.5	57.1
Beryllium	2.5	0.8	0.6	0.5	0.5	0.7	<0.4	0.7
Boron	36	10	8	7	<5	7	7	11
Boron (Hot Water Extractable)	1.5	0.42	0.12	0.17	0.12	0.26	0.17	0.25
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	20	17	15	12	18	14	22
Cobalt	22	9.2	7.8	7.8	5.6	6.6	8.1	10.4
Copper	92	42.9	24.8	33.3	24.7	23.3	32	29.1
Lead	120	60	9	12	9	18	8	10
Molybdenum	2	0.6	<0.5	<0.5	<0.5	0.6	<0.5	<0.5
Nickel	82	19	17	22	12	14	15	21
Selenium	1.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	0.6	<0.50	<0.50	<0.50	<0.50	<0.50	0.59
Vanadium	86	30.4	25.5	22.4	20.4	28.1	23.8	31.9
Zinc	290	95	44	43	32	51	39	55
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.353	0.216	0.185	0.124	0.200	0.327	0.245
Sodium Adsorption Ratio	5	1.560	0.438	0.300	0.143	0.116	2.140	2.170
pH, 2:1 CaCl2 Extraction	*	7.29	7.25	7.32	7.19	7.04	7.61	7.19

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-8 SS2	BH21-16 SS1	BH21-17 S1	BH21-18 SS1	BH21-19 SS2	BH21-20 SS1	QAQC-6
Date of Collection	Table 8 RPIICC	Nov 29, 2021	Dec 01, 2021	Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021	
Date Reported		Dec 14, 2021	Dec 15, 2021	Nov 16, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6	
Analytical Report Reference No.		21T836919	21T839096	21T826519	21T834550	21T834550	21T834550	
Antimony	1.3	<0.8	**2.8**	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	6	8	7	6	6	6	5
Barium	220	57.4	88.5	62.8	94.5	82.7	71.9	71.5
Beryllium	2.5	0.5	0.5	0.6	0.6	0.6	<0.4	<0.4
Boron	36	10	9	9	7	11	<5	<5
Boron (Hot Water Extractable)	1.5	0.21	0.50	0.66	0.26	0.11	0.21	0.22
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	19	35	20	25	25	20	20
Cobalt	22	10.0	10.6	7.9	11.5	13.3	16.5	11.8
Copper	92	31.5	69	28.8	33.4	25.2	48.7	25.8
Lead	120	12	79	22	10	11	18	17
Molybdenum	2	<0.5	**3.7**	0.7	<0.5	<0.5	0.6	0.6
Nickel	82	20	31	19	24	26	**142**	25
Selenium	1.5	<0.8	0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	<0.50	<0.50	<0.50	0.5	0.6	0.5	<0.50
Vanadium	86	28.4	33.8	29	35.1	35.8	30.9	30.7
Zinc	290	51	**468**	77	66	59	61	67
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	0.22	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.117	0.290	0.186	0.154	0.110	0.154	0.157
Sodium Adsorption Ratio	5	0.122	1.640	0.055	1.000	0.186	0.105	0.107
pH, 2:1 CaCl2 Extraction	*	7.12	7.50	7.16	7.55	7.56	7.44	7.36

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4B Soil Analytical Results - Metals & ORPs

Parameter		BH21-20 SS4	BH21-21 SS3	BH21-22 SS1	BH21-23 S2	BH21-24 S3	BH21-45 SS2
Date of Collection	Table 8 RPIICC	Nov 23, 2021	Nov 23, 2021	Nov 22, 2021	Nov 05, 2021	Nov 05, 2021	Nov 22, 2021
Date Reported		Dec 20, 2021	Dec 03, 2021	Dec 03, 2021	Nov 16, 2021	Nov 16, 2021	Dec 03, 2021
Sampling Depth (mbgs)		2.3 - 2.9	1.5 - 2.1	0.0 - 0.6	0.6 - 1.2	1.2 - 1.8	0.8 - 1.4
Analytical Report Reference No.		21T841262	21T834550	21T834550	21T826519	21T826519	21T834550
Antimony	1.3	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	5	5	6	7	6	7
Barium	220	95.4	56.1	96.2	54.8	41.5	83
Beryllium	2.5	0.6	<0.4	0.5	0.6	0.4	0.5
Boron	36	24	8	9	10	7	9
Boron (Hot Water Extractable)	1.5	0.26	<0.10	0.12	0.26	<0.10	0.44
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	25	14	24	22	16	25
Cobalt	22	14.8	7.6	11.9	11.2	9.8	15.3
Copper	92	10.6	23.4	29.7	36.6	34.8	33.8
Lead	120	12	10	10	9	7	11
Molybdenum	2	1.2	<0.5	<0.5	0.7	<0.5	<0.5
Nickel	82	27	13	23	25	20	33
Selenium	1.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	0.8	<0.50	0.6	0.5	<0.50	0.7
Vanadium	86	40.2	22.7	34.9	29.5	23.4	34
Zinc	290	63	35	57	63	53	68
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.125	0.088	0.125	0.157	0.103	0.314
Sodium Adsorption Ratio	5	0.344	0.095	0.182	0.370	0.095	1.200
pH, 2:1 CaCl2 Extraction	*	7.13	7.62	7.64	7.59	7.66	7.60

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTEX

Parameter		BH21-2 SS5	BH21-3 SS6	BH21-4 SS3	BH21-5 SS2	BH21-6 SS6	BH21-7 SS5	BH21-8 SS7	BH21-16 SS8
Date of Collection	Table 8 RPIICC	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021	Nov 29, 2021	Dec 01, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021	Dec 18, 2021	Dec 18, 2021	Dec 15, 2021	Dec 14, 2021	Dec 14, 2021	Dec 15, 2021
Sampling Depth (mbgs)		3.0 - 3.7	4.6 - 5.2	1.8 - 1.8	0.6 - 1.2	4.6 - 5.2	3.0 - 3.7	6.1 - 6.7	7.6 - 8.2
Analytical Report Reference No.		21T839096	21T839096	21T840564	21T840564	21T839096	21T836919	21T836919	21T839096
Benzene	0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<5	<5	<5	<5	<5	<5	<5	<5
F2 (C10 to C16)	10	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	<50	<50	<50	<50	<50	<50	<50	<50
F4 (C34 to C50)	120	<50	<50	<50	<50	<50	<50	<50	<50

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTE

Parameter		BH21-17 S2	BH21-18 SS2	BH21-19 SS2	BH21-20 SS3	QAQC-8	BH21-21 SS3	BH21-22 SS5	BH21-23 S3
Date of Collection	Table 8 RPIICC	Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021		Nov 23, 2021	Nov 22, 2021	Nov 05, 2021
Date Reported		Nov 30, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021		Dec 03, 2021	Dec 03, 2021	Nov 30, 2021
Sampling Depth (mbgs)		0.6 - 1.2	0.8 - 1.4	0.8 - 1.4	1.5 - 2.1		1.5 - 2.1	3.0 - 3.7	1.2 - 1.8
Analytical Report Reference No.		21T832162	21T834550	21T834550	21T834550		21T834550	21T834550	21T832162
Benzene	0.02	<0.005	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.005
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.01	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<10	<5	<5	<5	<5	<5	<5	<10
F2 (C10 to C16)	10	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	13	<50	<50	<50	<50	<50	<50	<10
F4 (C34 to C50)	120	<10	<50	<50	<50	<50	<50	<50	<10

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5B Soil Analytical Results - PHCs & BTE

Parameter		BH21-24 S3	BH21-45 SS8	BH21-45 SS9
Date of Collection	Table 8 RPIICC	Nov 05, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Nov 30, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		1.2 - 1.8	7.6 - 8.2	9.1 - 9.8
Analytical Report Reference No.		21T832162	21T834550	21T841262
Benzene	0.02	<0.005	<0.02	<0.02
Toluene	0.2	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.01	**0.9**	<0.05
Total Xylenes	0.05	<0.05	**5.55**	<0.05
F1 (C6 to C10) minus BTEX	25	<10	**51**	<5
F2 (C10 to C16)	10	<10	<10	<10
F3 (C16 to C34)	240	14	<50	<50
F4 (C34 to C50)	120	<10	<50	<50

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 6B Soil Analytical Results - VOCs

Parameter		BH21-7 SS5	BH21-8 SS7	BH21-16 SS8	BH21-21 SS3	BH21-22 SS5	BH21-45 SS8	BH21-45 SS9
Date of Collection	Table 8 RPIICC	Nov 29, 2021	Nov 29, 2021	Dec 01, 2021	Nov 23, 2021	Nov 22, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Dec 14, 2021	Dec 14, 2021	Dec 15, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		3.0 - 3.7	6.1 - 6.7	7.6 - 8.2	1.5 - 2.1	3.0 - 3.7	7.6 - 8.2	9.1 - 9.8
Analytical Report Reference No.		21T836919	21T836919	21T839096	21T834550	21T834550	21T834550	21T841262
Acetone	0.5	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Benzene	0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Bromodichloromethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Bromoform	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Bromomethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Carbon Tetrachloride	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chlorobenzene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chloroform	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Dibromochloromethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,2-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,3-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,4-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichlorodifluoromethane	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethane, 1,1-	0.05	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Dichloroethane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
Dichloroethylene, 1,1-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethylene, Cis- 1,2-	0.05	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Dichloroethylene, Trans- 1,2-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dichloropropane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	**0.9**	<0.05
Ethylene Dibromide	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Hexane, n-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methyl Ethyl Ketone	0.5	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Methyl Isobutyl Ketone	0.5	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Methyl tert-butyl Ether	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methylene Chloride	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Styrene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Tetrachloroethane, 1,1,2,2-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethylene	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,1-	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04	<0.04
Trichloroethylene	0.05	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03	<0.03
Trichlorofluoromethane	0.25	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Vinyl Chloride	0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02	<0.02
Xylene mixture	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	**5.55**	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		BH21-2 SS2	BH21-4 SS1	BH21-5 SS1	BH21-6 SS2	BH21-7 SS1	BH21-8 SS1	BH21-16 SS2
Date of Collection	Table 8 RPIICC	Dec 02, 2021	Dec 06, 2021	Dec 06, 2021	Dec 01, 2021	Nov 29, 2021	Nov 29, 2021	Dec 02
Date Reported		Dec 15, 2021	Dec 18, 2021	Dec 18, 2021	Dec 23, 2021	Dec 14, 2021	Dec 14, 2021	Dec 15
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	0.0 - 0.6	0.8 - 1.4	0.0 - 0.6	0.0 - 0.6	0.8 -
Analytical Report Reference No.		21T839096	21T840564	21T840564	21T839096	21T836919	21T836919	21T83
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	0.06	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	0.40	0.22	<0.05
Anthracene	0.22	<0.05	<0.05	<0.05	<0.05	0.18	0.10	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	**1.05**	**0.89**	<0.05
Pyrene	1	<0.05	<0.05	<0.05	<0.05	0.96	0.77	<0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	**0.56**	**0.46**	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	0.41	0.36	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	<0.05	<0.05	**0.60**	**0.66**	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05	<0.05	0.23	0.24	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	**0.40**	**0.40**	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	0.22	**0.26**	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	0.05	0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	0.27	0.34	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		QAQC-10	BH21-17 S3	BH21-18 SS2	BH21-19 SS1	BH21-20 SS2	QAQC-7
Date of Collection	Table 8 RPIICC	, 2021	Nov 05, 2021	Nov 24, 2021	Nov 24, 2021	Nov 23, 2021	
Date Reported		, 2021	Nov 16, 2021	Dec 03, 2021	Dec 03, 2021	Dec 03, 2021	
Sampling Depth (mbgs)		- 1.4	1.2 - 1.8	0.8 - 1.4	0.0 - 0.6	0.8 - 1.4	
Analytical Report Reference No.		39096	21T826519	21T834550	21T834550	21T834550	
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.22	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	0.14	<0.05	<0.05
Pyrene	1	<0.05	<0.05	<0.05	0.16	<0.05	<0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	0.17	<0.05	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	0.07	<0.05	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	<0.05	0.1	<0.05	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	0.07	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 7B Soil Analytical Results - PAHs

Parameter		BH21-21 SS1	BH21-22 SS3	BH21-23 S1	BH21-24 S2	BH21-45 SS1	BH21-45 SS2
Date of Collection	Table 8 RPIICC	Nov 23, 2021	Nov 22, 2021	Nov 05, 2021	Nov 05, 2021	Nov 22, 2021	Nov 22, 2021
Date Reported		Dec 03, 2021	Dec 03, 2021	Nov 16, 2021	Nov 16, 2021	Dec 03, 2021	Dec 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	1.5 - 2.1	0.0 - 0.6	0.6 - 1.2	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T834550	21T834550	21T826519	21T826519	21T834550	21T841262
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	0.09	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	0.24	<0.05
Anthracene	0.22	<0.05	<0.05	<0.05	<0.05	0.13	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	0.57	<0.05
Pyrene	1	<0.05	<0.05	<0.05	<0.05	0.6	<0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	**0.39**	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	0.35	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	0.09	<0.05	0.45	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	0.09	<0.05	0.19	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	0.05	<0.05	**0.33**	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	0.19	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	0.23	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	0.15	<0.05

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 8B Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-4 SS2	BH21-5 SS3	BH21-7 SS1	BH21-17 S2	BH21-20 SS2	QAQC-7	BH21-23 S3	BH21-24 S1	BH21-45 SS1
Date of Collection	Table 8 RPIICC	Dec 06, 2021	Dec 06, 2021	Nov 29, 2021	Nov 05, 2021	Nov 23, 2021		Nov 05, 2021	Nov 05, 2021	Nov 22, 2021
Date Reported		Dec 18, 2021	Dec 18, 2021	Dec 14, 2021	Nov 16, 2021	Dec 03, 2021		Nov 16, 2021	Nov 16, 2021	Dec 03, 2021
Sampling Depth (m bgs)		0.6 - 1.6	1.2 - 1.8	0.0 - 0.6	0.6 - 1.2	0.8 - 1.4		1.2 - 1.8	0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T840564	21T840564	21T836919	21T826519	21T834550		21T826519	21T826519	21T834550
Polychlorinated Biphenyls	0.3	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.02	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9B Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-6	BH21-7	BH21-8	BH21-16		BH21-22	BH21-45	QA/QC	BH21-45
Date of Collection	Table 8 Potable GW	Dec 06, 2021	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021	Feb 11, 2022	Dec 01, 2021	Dec 01, 2021		Feb 11, 2022
Date Reported		Dec 21, 2021	Dec 15, 2021	Dec 15, 2021	Dec 21, 2021	Feb 14, 2022	Dec 16, 2021	Dec 16, 2021		Feb 14, 2022
Screened Depth (mbgs)		3.1 - 6.1	2.8 - 5.8	6.1 - 9.1	6.1 - 9.1		3.4 - 6.4	6.1 - 9.1		
Analytical Report Reference No.		21T841270	21T839088	21T839088	21T841270	22T862998	21T838602	21T838602		22T862998
Antimony	6	<1.0	<1.0	<1.0	1.1	-	<1.0	<1.0	<1.0	-
Arsenic	25	4.7	<1.0	4.3	<1.0	-	1.1	4.7	1.6	-
Barium	1000	271	254	109	63.9	-	91.9	80.5	62.4	-
Beryllium	4	<0.50	<0.50	<0.50	<0.50	-	<0.50	<0.50	<0.50	-
Boron	5000	279	362	131	1676	-	219	682	115	-
Cadmium	2.1	<0.20	<0.20	<0.20	<0.20	-	<0.20	<0.20	<0.20	-
Chromium	50	25.3	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Chromium VI	25	5.43	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Cobalt	3.8	**4.53**	0.52	0.63	<0.50	-	1.06	0.66	2.87	-
Copper	69	2.7	1.9	<1.0	<1.0	-	<1.0	<1.0	<1.0	-
Cyanide	52	<2.0	<2.0	<2.0	<2.0	-	<2.0	<2.0	<2.0	-
Lead	10	0.93	<0.50	<0.50	<0.50	-	<0.50	<0.50	<0.50	-
Mercury	0.29	<0.02	<0.02	<0.02	<0.02	-	<0.02	<0.02	<0.02	-
Molybdenum	70	6.45	14.2	7.84	24.7	32.1	4.41	28	4.27	57.1
Nickel	100	6.9	2.8	9.7	1.1	-	1.9	4.7	4.2	-
Selenium	10	<1.0	<1.0	<1.0	1.6	-	<1.0	<1.0	<1.0	-
Silver	1.2	<0.20	<0.20	<0.20	<0.20	-	<0.20	<0.20	<0.20	-
Thallium	2	<0.30	<0.30	<0.30	<0.30	-	<0.30	<0.30	<0.30	-
Uranium	20	3.52	3.19	1.11	1.86	-	2.18	1.5	0.96	-
Vanadium	6.2	3.29	1.42	0.62	0.62	-	0.63	0.83	<0.40	-
Zinc	890	6.1	<5.0	<5.0	<5.0	-	<5.0	<5.0	<5.0	-
Sodium	490000	342000	417000	23000	210000	-	43800	205000	77700	-
Chloride	790000	**1460000**	768000	72700	286000	-	63300	326000	156000	-

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 10B Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-2	BH21-6	QAQC-2	BH21-7	QAQC-1	BH21-8	BH21-16	BH21-22	BH21-45	QA/QC
Date of Collection	Table 8 Potable GW	Dec 07, 2021	Dec 06, 2021		Dec 02, 2021		Dec 02, 2021	Dec 06, 2021	Dec 01, 2021	Dec 01, 2021	
Date Reported		Dec 21, 2021	Dec 21, 2021		Dec 15, 2021		Dec 15, 2021	Dec 21, 2021	Dec 16, 2021	Dec 16, 2021	
Screened Depth (mbgs)		2.8 - 5.8	3.1 - 6.1		2.8 - 5.8		6.1 - 9.1	6.1 - 9.1	3.4 - 6.4	6.1 - 9.1	
Analytical Report Reference No.		21T841270	21T841270		21T839088		21T839088	21T841270	21T838602	21T838602	
Benzene	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	22	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Ethylbenzene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Xylene Mixture	300	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
F1 (C6 to C10) minus BTEX	420	<25	<25	<25	<25	<25	<25	<25	<25	<25	<25
F2 (C10 to C16)	150	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
F3 (C16 to C34)	500	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100
F4 (C34 to C50)	500	<100	<100	<100	<100	<100	<100	<100	<100	<100	<100

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 11B Groundwater Analytical Results - VOCs

Parameter		BH21-7	BH21-8	BH21-16	QAQC-1	BH21-22	BH21-45	QA/QC	Trip Blank	Trip Blank	Trip Blank
Date of Collection	Table 8 Potable GW	Dec 02, 2021	Dec 02, 2021	Dec 06, 2021		Dec 01, 2021	Dec 01, 2021		Nov 23, 2021	Nov 30, 2021	Dec 04, 2021
Date Reported		Dec 15, 2021	Dec 15, 2021	Dec 21, 2021		Dec 16, 2021	Dec 16, 2021		Dec 03, 2021	Dec 16, 2021	Dec 21, 2021
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1	6.1 - 9.1		3.4 - 6.4	6.1 - 9.1		-	-	-
Analytical Report Reference No.		21T839088	21T839088	21T841270		21T838602	21T838602		21T834096	21T838602	21T841270
Acetone	2700	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Benzene	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Bromodichloromethane	16	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Bromoform	25	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Bromomethane	0.89	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Carbon Tetrachloride	0.79	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Chlorobenzene	30	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Chloroform	2.4	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dibromochloromethane	25	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,2-	3	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,3-	59	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,4-	1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorodifluoromethane	590	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethane, 1,1-	5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethane, 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, 1,1-	1.6	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethylene, cis- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, trans- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropane, 1,2-	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropene, 1,3-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Ethylbenzene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	0.2	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Hexane, n-	51	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Ethyl Ketone	1800	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl Isobutyl Ketone	640	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl tert-butyl ether	15	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methylene Chloride	50	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Styrene	5.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,1,2-	1.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,2,2-	1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	22	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethane, 1,1,1-	200	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Trichloroethane, 1,1,2-	4.7	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethylene	1.6	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	150	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40
Vinyl Chloride	0.5	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17
Xylene Mixture	300	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 12B Groundwater Analytical Results - PAHs

Parameter		BH21-7	BH21-8	QAQC-2	BH21-16	BH21-22	BH21-45	QA/QC	BH21-45
Date of Collection	Table 8 Potable GW	Dec 02, 2021	Dec 02, 2021		Dec 06, 2021	Dec 01, 2021	Dec 01, 2021		Feb 11, 2022
Date Reported		Dec 15, 2021	Dec 15, 2021		Dec 21, 2021	Dec 16, 2021	Dec 16, 2021		Feb 14, 2022
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1		6.1 - 9.1	3.4 - 6.4	6.1 - 9.1		
Analytical Report Reference No.		21T839088	21T839088		21T841270	21T838602	21T838602		22T862998
Acenaphthene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Anthracene	1	<0.10	<0.10	<0.10	<0.10	<0.10	**1.79**	1	<0.10
Benz(a)anthracene	1	<0.20	<0.20	<0.20	<0.20	<0.20	**2.4**	**1.67**	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	**3.67**	**2.8**	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**4.92**	**3.29**	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**2.48**	**1.89**	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**2.19**	**1.86**	<0.10
Chrysene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	**5.59**	**4.01**	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**0.32**	**0.21**	<0.20
Fluoranthene	0.41	<0.20	<0.20	<0.20	<0.20	<0.20	**17.9**	**11.2**	<0.20
Fluorene	120	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	0.56	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	**1.8**	**1.35**	<0.20
Methyl Naphthalene, 2-and 1-	3.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Naphthalene	11	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Phenanthrene	1	<0.10	<0.10	<0.10	<0.10	<0.10	**12**	**9.08**	<0.10
Pyrene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	**14.6**	**9.52**	<0.20

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 13B Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-7	BH21-45	QA/QC
Date of Collection	Table 8 Potable GW	Dec 02, 2021	Dec 01, 2021	
Date Reported		Dec 15, 2021	Dec 16, 2021	
Screened Depth (mbgs)		2.8 - 5.8	6.1 - 9.1	
Analytical Report Reference No.		21T839088	21T838602	
Polychlorinated Biphenyls	0.2	<0.1	<0.1	<0.1
Aldrin	0.35	<0.01	-	-
Chlordane	0.06	<0.04	-	-
DDD	1.8	<0.05	-	-
DDE	10	<0.01	-	-
DDT	0.05	<0.04	-	-
Dieldrin	0.35	<0.02	-	-
Endosulfan	0.56	<0.05	-	-
Endrin	0.36	<0.05	-	-
Heptachlor	0.038	<0.01	-	-
Heptachlor Epoxide	0.038	<0.01	-	-
Hexachlorobenzene	1	<0.01	-	-
Hexachlorobutadiene	0.44	<0.01	-	-
Hexachlorocyclohexane Gamma-	0.95	<0.01	-	-
Hexachloroethane	2.1	<0.01	-	-
Methoxychlor	0.3	<0.04	-	-

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14B Summary of Maximum Concentrations in Soil

Group	Parameter	Table 8 RPIICC	Maximum Concentration	Location
BTEX	Benzene	0.02	<0.02	all samples
	Ethylbenzene	0.05	0.9	BH21-45 SS8
	Toluene	0.2	<0.05	all samples
	Total Xylenes	0.05	5.55	BH21-45 SS8
Metals	Barium	220	96.2	BH21-22 SS1
	Beryllium	2.5	0.8	BH21-2 SS2
	Boron	36	24	BH21-20 SS4
	Cadmium	1.2	<0.5	all samples
	Chromium	70	35	BH21-16 SS1
	Cobalt	22	16.5	BH21-20 SS1
	Copper	92	69	BH21-16 SS1
	Lead	120	79	BH21-16 SS1
	Molybdenum	2	3.7	BH21-16 SS1
	Nickel	82	142	BH21-20 SS1
	Silver	0.5	<0.5	all samples
	Thallium	1	<0.5	all samples
	Uranium	2.5	0.79	BH21-20 SS4
	Vanadium	86	40.2	BH21-20 SS4
	Zinc	290	468	BH21-16 SS1
As, Se, Sb	Antimony	1.3	2.8	BH21-16 SS1
	Arsenic	18	8	BH21-16 SS1
	Selenium	1.5	0.8	BH21-16 SS1
PAHs	Acenaphthene	0.072	<0.05	all samples
	Acenaphthylene	0.093	0.09	BH21-45 SS1
	Anthracene	0.22	0.18	BH21-7 SS1
	Benz(a)anthracene	0.36	0.56	BH21-7 SS1
	Benzo(a)pyrene	0.3	0.4	BH21-7 SS1
	Benzo(b)fluoranthene	0.47	0.66	BH21-8 SS1
	Benzo(g,h,i)perylene	0.68	0.34	BH21-8 SS1
	Benzo(k)fluoranthene	0.48	0.24	BH21-8 SS1
	Chrysene	2.8	0.41	BH21-7 SS1
	Dibenz(a,h)anthracene	0.1	0.06	BH21-45 SS1
	Fluoranthene	0.69	1.05	BH21-7 SS1
	Fluorene	0.19	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.23	0.26	BH21-8 SS1
	Methylnaphthalene, 2-(1-)	0.59	0.15	BH21-45 SS1
	Naphthalene	0.09	<0.05	all samples
	Phenanthrene	0.69	0.4	BH21-7 SS1
	Pyrene	1	0.96	BH21-7 SS1
PHCs	F1 (C6 to C10) minus BTEX	25	51	BH21-45 SS8
	F2 (C10 to C16)	10	<10	all samples
	F3 (C16 to C34)	240	14	BH21-24 S3
	F4 (C34 to C50)	120	<50	all samples
	Acetone	0.5	<0.50	all samples
	Bromodichloromethane	0.05	<0.05	all samples
	Bromoform	0.05	<0.05	all samples
	Bromomethane	0.05	<0.05	all samples
	Carbon Tetrachloride	0.05	<0.05	all samples
	Chlorobenzene	0.05	<0.05	all samples
	Chloroform	0.05	<0.04	all samples
	Dibromochloromethane	0.05	<0.05	all samples
	Dichlorobenzene, 1,2-	0.05	<0.05	all samples

Table 14B Summary of Maximum Concentrations in Soil

Group	Parameter	Table 8 RPIICC	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	0.05	<0.05	all samples
	Dichlorobenzene, 1,4-	0.05	<0.05	all samples
	Dichlorodifluoromethane	0.05	<0.05	all samples
	Dichloroethane, 1,1-	0.05	<0.02	all samples
	Dichloroethane, 1,2-	0.05	<0.03	all samples
	Dichloroethylene, 1,1-	0.05	<0.05	all samples
	Dichloroethylene, Cis- 1,2-	0.05	<0.02	all samples
	Dichloroethylene, Trans- 1,2-	0.05	<0.05	BH21-45 SS8
	Dichloropropane, 1,2-	0.05	<0.03	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	BH21-45 SS8
	Ethylene Dibromide	0.05	<0.04	all samples
	Hexane, n-	0.05	<0.05	all samples
	Methyl Ethyl Ketone	0.5	<0.50	all samples
	Methyl Isobutyl Ketone	0.5	<0.50	all samples
	Methyl tert-butyl Ether	0.05	<0.05	all samples
	Methylene Chloride	0.05	<0.05	all samples
	Styrene	0.05	<0.05	all samples
	Tetrachloroethane, 1,1,1,2-	0.05	<0.04	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.05	all samples
	Tetrachloroethylene	0.05	<0.05	all samples
	Trichloroethane, 1,1,1-	0.05	<0.05	all samples
	Trichloroethane, 1,1,2-	0.05	<0.04	all samples
	Trichloroethylene	0.05	<0.03	all samples
	Trichlorofluoromethane	0.25	<0.05	all samples
	Vinyl Chloride	0.02	<0.02	all samples
ORPs	Chromium, Hexavalent	0.66	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.7	0.353	BH21-2 SS2
	Mercury	0.27	0.22	BH21-16 SS1
	Sodium Adsorption Ratio	5	2.17	BH21-7 SS2
	pH, 2:1 CaCl2 Extraction	*	7.66	BH21-24 S3
PCBs	Polychlorinated Biphenyls	0.3	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15B Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 8 Potable GW	Maximum Concentration	Location
BTEX	Benzene	5	<0.20	all samples
	Ethylbenzene	2.4	<0.10	all samples
	Toluene	22	<0.20	all samples
	Xylene Mixture	300	<0.20	all samples
Metals	Barium	1000	271	BH21-22
	Beryllium	4	<0.50	all samples
	Boron	5000	1676	BH21-16
	Cadmium	2.1	<0.20	all samples
	Chromium	50	25.3	all samples
	Cobalt	3.8	4.53	QA/QC
	Copper	69	2.7	all samples
	Lead	10	0.93	all samples
	Molybdenum	70	57.1	BH21-45
	Nickel	100	9.7	BH21-45
	Silver	1.2	<0.20	all samples
	Thallium	2	<0.30	all samples
	Uranium	20	3.52	BH21-22
	Vanadium	6.2	3.29	BH21-45
	Zinc	890	6.1	all samples
As, Se, Sb	Antimony	6	1.1	BH21-16
	Arsenic	25	4.7	BH21-45
	Selenium	10	1.6	BH21-16
Na	Sodium	490000	417000	BH21-16
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	1	1.79	BH21-45
	Benz(a)anthracene	1	2.4	BH21-45
	Benzo(a)pyrene	0.01	3.67	BH21-45
	Benzo(b)fluoranthene	0.1	4.92	BH21-45
	Benzo(g,h,i)perylene	0.2	2.48	BH21-45
	Benzo(k)fluoranthene	0.1	2.19	BH21-45
	Chrysene	0.1	5.59	BH21-45
	Dibenz(a,h)anthracene	0.2	0.32	BH21-45
	Fluoranthene	0.41	17.9	BH21-45
	Fluorene	120	0.56	QA/QC
	Indeno(1,2,3-cd)pyrene	0.2	1.8	BH21-45
	Methyl Naphthalene, 2-and 1-	3.2	<0.20	all samples
	Naphthalene	11	<0.20	all samples
	Phenanthrene	1	12	BH21-45
	Pyrene	4.1	14.6	BH21-45
PHCs	F1 (C6 to C10) minus BTEX	420	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	16	<0.20	all samples
	Bromoform	25	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.79	<0.20	all samples
	Chlorobenzene	30	<0.10	all samples
	Chloroform	2.4	<0.20	all samples
	Dibromochloromethane	25	<0.10	all samples

Table 15B Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 8 Potable GW	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,2-	3	<0.10	all samples
	Dichlorobenzene, 1,3-	59	<0.10	all samples
	Dichlorobenzene, 1,4-	1	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	5	<0.30	all samples
	Dichloroethane, 1,2-	1.6	<0.20	all samples
	Dichloroethylene, 1,1-	1.6	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	51	<0.20	all samples
	Methyl Ethyl Ketone	1800	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	50	<0.30	all samples
	Styrene	5.4	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	1	<0.10	all samples
	Tetrachloroethylene	1.6	<0.20	all samples
	Trichloroethane, 1,1,1-	200	<0.30	all samples
	Trichloroethane, 1,1,2-	4.7	<0.20	all samples
	Trichloroethylene	1.6	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	1460000	BH21-45
	Chromium VI	25	5.43	all samples
	Cyanide	52	<2.0	all samples
	Mercury	0.29	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Notes for Soil & Groundwater Summary Tables - Caledon (C-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 1 RPIICC = Full Depth Background Site Condition Standards as contained in Table 1 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011
11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 1 SCS

Table 1C Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-30	BH21-32	BH21-36
Installed By			WSP	WSP	WSP	WSP	WSP	WSP	WSP	WSP
Installation Date			4-Nov-21	4-Nov-21	15-Nov-21	16-Nov-21	8-Nov-21	8-Nov-21	15-Nov-21	16-Nov-21
Well Status			Active	Active	Active	Active	Active	Active	Active	Active
Well Inner Diameter		(mm)	50	50	50	50	50	50	50	50
Casing Type (Flushmount / Monument)			Monument	Monument	Monument	Monument	Monument	Flushmount	Monument	Monument
Top of Pipe Elevation		(masl)	423.843	397.847	404.757	255.396	282.313	286.873	274.654	326.921
Ground Surface Elevation		(masl)	422.953	396.937	403.897	256.306	281.403	286.973	273.744	326.001
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
		(masl)	422.653	396.637	403.597	256.006	281.103	286.673	273.444	325.701
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	1.3	4.9	3.1	4.0	5.5	5.5	2.4	4.0
		(masl)	421.7	392.0	400.8	252.3	275.9	281.5	271.4	322.0
Top of Well Screen		(mbgs)	1.9	5.5	3.7	4.6	6.1	6.1	3.0	4.6
		(masl)	421.1	391.4	400.2	251.7	275.3	280.9	270.7	321.4
Screen Length		(m)	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0
Bottom of Screen		(mbgs)	4.9	8.5	6.7	7.6	9.1	9.1	6.0	7.6
		(masl)	418.1	388.4	397.2	248.7	272.3	277.9	267.7	318.4
22-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	DRY	6.5
	GW Elevation	(masl)	-	-	-	-	-	-	-	319.5
23-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	DRY	6.6
	GW Elevation	(masl)	-	-	-	-	-	-	-	319.4
29-Nov-21	Depth of GW	(mbgs)	-	-	-	-	0.6	2.2	-	-
	GW Elevation	(masl)	-	-	-	-	280.8	284.8	-	-
30-Nov-21	Depth of GW	(mbgs)	-	-	-	2.2	-	-	-	-
	GW Elevation	(masl)	-	-	-	254.1	-	-	-	-
1-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
2-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
6-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
7-Dec-21	Depth of GW	(mbgs)	2.0	4.3	5.1	2.2	0.0	2.3	DRY	6.6
	GW Elevation	(masl)	421.0	392.6	398.8	254.1	281.7	284.7	-	319.4

See "Notes for Soil and Groundwater Summary

Table 2C Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-9	SS1	0.0 - 0.6	4-Nov-21	-	-	-	-	✓	✓	3, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS4	2.3 - 2.9		-	-	-	✓	-	-	
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
BH21-10	S1	0.0 - 0.6	27-Oct-21	✓	-	-	-	-	-	13, 14, 38, 105, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	✓	-	✓	-	-	
BH21-11	SS1	0.0 - 0.6	4-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS2	0.8 - 1.4		-	-	-	✓	✓	✓	
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
BH21-13	SS1	0.0 - 0.6	15-Nov-21	-	-	-	✓	-	-	13, 14, 38, 112, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-14	S1	0.0 - 0.6	27-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 96, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-15	S2	0.6 - 1.2	27-Oct-21	-	-	-	✓	✓	✓	13, 14, 38, 93, 114
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-25	SS1	0.0 - 0.6	16-Nov-21	-	-	-	✓	-	-	13, 14, 38, 108, 114
	SS2	0.8 - 1.4		✓	-	-	-	-		
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-26	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 60, 114
	S2	0.6 - 1.2		-	-	-	✓	-	-	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-27	S1	0.0 - 0.6	28-Oct-21	✓	-	-	-	-	-	13, 14, 38, 63, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-28	SS1	0.0 - 0.6	8-Nov-21	✓	-	-	-	-	-	1, 13, 14, 38, 114
	QAQC-3			✓	-	-	-	-	-	
	SS2	0.8 - 1.4		-	✓	-	-	-	-	
	QAQC-4			-	✓	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	✓	✓	
	QAQC-5			-	-	-	✓	✓	✓	
BH21-29	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 66, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-30	SS1	0.0 - 0.6	8-Nov-21	-	-	-	✓	✓	✓	13, 14, 33, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-31	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 69, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	✓	-	✓	-	-	
BH21-32	SS1	0.0 - 0.6	15-Nov-21	✓	-	-	-	-	-	13, 14, 38, 109, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS4	2.3 - 2.9		-	✓	✓	-	-	-	
BH21-33	S1	0.0 - 0.6	28-Oct-21	-	-	-	✓	-	-	13, 14, 38, 72, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-34	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 75, 114
	QAQC-1			-	-	-	-	✓	✓	
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	QAQC-S2			✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
	QAQC-S3			-	-	-	✓	-	-	

Table 2C Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-35	S1	0.0 - 0.6	27-Oct-21	✓	-	-	-	-	-	13, 14, 38, 78, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-36	SS1	0.0 - 0.6	16-Nov-21	✓	-	-	-	-	-	13, 14, 38, 110, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-37	S1	0.0 - 0.6	27-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 81, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-38	S1	0.0 - 0.6	27-Oct-21	-	-	-	✓	-	-	13, 14, 38, 84, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-39	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 111, 114
	S3	1.2 - 1.8		-	-	-	✓	✓	✓	
BH21-40	S1	0.0 - 0.6	27-Oct-21	-	-	-	✓	✓	✓	13, 14, 38, 87, 114
	S3	1.2 - 1.8		✓	-	-	✓	-	-	
BH21-41	S1	0.0 - 0.6	5-Nov-21	-	-	-	✓	-	-	13, 14, 38, 90, 114
	S2	0.6 - 1.2		✓	✓	-	-	✓	✓	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3C: Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-9	1.9 - 4.9	30-Nov-21	✓	✓	✓	✓	✓	-	3, 13, 14, 38, 114
BH21-11	5.5 - 8.5	30-Nov-21	✓	✓	-	✓	✓	-	13, 14, 38, 114
BH21-13	3.7 - 6.7	30-Nov-21	✓	✓	✓	✓	-	-	13, 14, 38, 112, 114
BH21-25	4.6 - 7.6	1-Dec-21	✓	✓	✓	✓	-	-	13, 14, 38, 108, 114
BH21-28	6.1 - 9.1	1-Dec-21	✓	✓	✓	✓	✓	-	1, 13, 14, 38, 114
BH21-30	6.1 - 9.1	1-Dec-21	-	✓	-	-	-	-	13, 14, 33, 38, 114
BH21-36	4.6 - 7.6	23-Nov-21	✓	✓	✓	✓	-	-	13, 14, 38, 110, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-9 SS2	BH21-10 S1	BH21-10 S3	BH21-11 SS1	BH21-13 SS2	BH21-14 S2	BH21-15 S3
Date of Collection	Table 1 RPIICC	Nov 04, 2021	Oct 27, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Oct 27, 2021
Date Reported		Nov 16, 2021	Nov 08, 2021	Dec 20, 2021	Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6	0.8 - 1.4	0.6 - 1.2	1.2 - 1.8
Analytical Report Reference No.		21T826519	21T822752		21T826519	21T830287	21T822752	21T822752
Antimony	1.3	<0.8	**3.5**	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	3	**24**	8	2	2	3	4
Barium	220	25.4	44.5	27	10.1	10.6	49.6	26.5
Beryllium	2.5	<0.4	1.4	<0.4	<0.4	<0.4	<0.4	<0.4
Boron	36	<5	12	8	<5	<5	<5	<5
Boron (Hot Water Extractable)	NA	0.18	0.37	0.21	<0.10	<0.10	0.13	<0.10
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	12	15	10	<5	5	14	7
Cobalt	21	4.6	9.3	5.2	1.9	1.7	4.6	3.3
Copper	92	8	64.7	23.7	9	3.4	8.6	17
Lead	120	7	52	15	2	3	8	5
Molybdenum	2	<0.5	**11**	1	<0.5	<0.5	<0.5	<0.5
Nickel	82	9	29	7	2	3	9	5
Selenium	1.5	<0.8	**2.1**	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	0.6	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	<0.50	0.7	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	24.7	26.7	15.3	10.4	10.9	26.6	14.4
Zinc	290	28	70	54	18	13	46	22
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	0.11	<0.10
Electrical Conductivity (2:1)	0.57	0.096	0.255	0.210	0.061	0.078	0.103	0.073
Sodium Adsorption Ratio	2.4	0.07	0.061	0.295	0.055	0.205	0.043	0.061
pH, 2:1 CaCl2 Extraction	*	7.29	7.24	7.39	7.82	7.77	7.27	7.80

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-25 SS2	BH21-26 S3	BH21-27 S1	BH21-28 SS1	QAQC-3	BH21-29 S2	BH21-30 SS2	BH21-31 S1
Date of Collection	Table 1 RPIICC	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021
Date Reported		Nov 26, 2021	Nov 08, 2021	Nov 08, 2021	Nov 20, 2021		Nov 08, 2021	Nov 20, 2021	Nov 16, 2021
Sampling Depth (mbgs)		0.8 - 1.4	1.2 - 1.8	0.0 - 0.6	0.0 - 0.6		0.6 - 1.2	0.8 - 1.4	0.0 - 0.6
Analytical Report Reference No.		21T830891	21T822752	21T822752	21T827359		21T822752	21T827359	21T826519
Antimony	1.3	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	8	4	12	10	10	5	6	8
Barium	220	85.3	47.6	54.2	73.4	65.4	99	147	58.8
Beryllium	2.5	0.5	<0.4	0.5	0.8	0.7	0.7	1.4	0.5
Boron	36	<5	5	6	12	10	9	12	7
Boron (Hot Water Extractable)	NA	0.35	<0.10	0.26	0.44	0.47	0.13	<0.10	0.12
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	23	16	19	23	21	26	32	17
Cobalt	21	12.6	9.4	6.8	16.3	6.8	11.1	14.1	10.0
Copper	92	35.5	37.1	24.7	40.9	31.3	26.1	28.4	28.5
Lead	120	12	7	15	29	26	9	12	9
Molybdenum	2	<0.5	<0.5	<0.5	0.7	0.6	<0.5	<0.5	<0.5
Nickel	82	26	18	15	31	17	24	33	21
Selenium	1.5	<0.8	<0.8	<0.8	0.9	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	0.5	<0.50	<0.50	0.6	<0.50	<0.50	0.6	<0.50
Vanadium	86	32.8	23	28.1	30.2	27.3	36.5	42.7	24.8
Zinc	290	70	47	58	92	81	57	71	51
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.57	0.174	0.106	0.192	0.342	0.336	0.129	0.165	0.107
Sodium Adsorption Ratio	2.4	0.267	0.084	0.103	0.396	0.393	0.105	0.458	0.060
pH, 2:1 CaCl2 Extraction	*	7.50	7.79	7.70	7.28	7.60	7.71	7.25	7.60

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-32 SS1	BH21-32 SS2	BH21-33 S3	BH21-34 S2	QAQC-2	BH21-35 S1	BH21-36 SS1	BH21-36 SS1
Date of Collection	Table 1 RPIICC	Nov 15, 2021	Nov 15, 2021	Oct 28, 2021	Oct 28, 2021		Oct 27, 2021	Nov 16, 2021	Nov 16, 2021
Date Reported		Nov 27, 2021	Dec 20, 2021	Nov 08, 2021	Nov 08, 2021		Nov 08, 2021	Nov 26, 2021	Dec 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	0.8 - 1.4	1.2 - 1.8	0.6 - 1.2		0.0 - 0.6	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T830287	21T839249	21T822752	21T822752		21T822752	21T830891	21T839249
Antimony	1.3	**1.9**	<0.8	<0.8	<0.8	<0.8	<0.8	1.1	<0.8
Arsenic	18	6	2	5	4	3	13	11	4
Barium	220	43.1	35.6	99.2	58.5	57	53.8	103	26.3
Beryllium	2.5	<0.4	<0.4	0.6	0.4	0.4	0.5	<0.4	<0.4
Boron	36	9	<5	9	10	11	21	6	7
Boron (Hot Water Extractable)	NA	0.40	0.16	<0.10	<0.10	<0.10	0.35	0.23	0.15
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	12	11	23	17	16	12	12	11
Cobalt	21	5.8	4.5	11.9	7.4	7.4	10.2	5.1	5.4
Copper	92	48.3	16.7	25.3	17.4	17	44.3	53.7	26.2
Lead	120	65	9	9	5	5	13	**205**	13
Molybdenum	2	1.4	<0.5	<0.5	<0.5	<0.5	1.1	1.2	<0.5
Nickel	82	21	9	24	14	13	19	11	9
Selenium	1.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	17.7	20.5	33.6	26.5	25.2	15.4	18.7	21.4
Zinc	290	67	34	52	38	36	63	179	39
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	**0.32**	<0.10	<0.10	<0.10	<0.10	<0.10	0.23	<0.10
Electrical Conductivity (2:1)	0.57	0.184	0.134	0.115	0.108	0.101	0.217	0.156	0.115
Sodium Adsorption Ratio	2.4	0.193	0.199	0.155	0.072	0.070	0.095	0.076	0.139
pH, 2:1 CaCl2 Extraction	*	7.60	7.15	7.80	7.87	7.91	7.87	7.70	7.08

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-37 S2	BH21-38 S3	BH21-39 S1	BH21-40 S3	BH21-41 S2
Date of Collection	Table 1 RPIICC	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (mbgs)		0.6 - 1.2	1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.6 - 1.2
Analytical Report Reference No.		21T822752	21T822752	21T826519	21T822752	21T826519
Antimony	1.3	1	<0.8	<0.8	<0.8	<0.8
Arsenic	18	12	3	6	6	**26**
Barium	220	41.3	16.9	40.7	29.6	18.3
Beryllium	2.5	<0.4	<0.4	0.4	<0.4	<0.4
Boron	36	7	<5	15	7	10
Boron (Hot Water Extractable)	NA	0.18	<0.10	0.36	0.20	0.13
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	11	6	14	11	23
Cobalt	21	5.4	2.5	6.3	4.5	8.3
Copper	92	25.1	9	12.3	27.2	24
Lead	120	18	4	7	20	52
Molybdenum	2	0.9	<0.5	<0.5	0.9	**2.1**
Nickel	82	11	4	13	10	8
Selenium	1.5	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	19.1	9.4	21.3	19.3	25.2
Zinc	290	33	14	48	33	121
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.57	0.136	0.082	0.210	0.328	0.152
Sodium Adsorption Ratio	2.4	0.036	0.051	0.758	0.025	0.121
pH, 2:1 CaCl2 Extraction	*	7.46	7.66	7.49	7.62	7.69

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-9 SS5	BH21-10 S3	BH21-11 SS5	BH21-13 SS5	BH21-14 S3	BH21-25 SS6	BH21-26 S3	BH21-27 S3
Date of Collection	Table 1 RPIICC	Nov 04, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021
Date Reported		Nov 16, 2021	Nov 30, 2021	Nov 16, 2021	Nov 27, 2021	Nov 30, 2021	Nov 26, 2021	Nov 30, 2021	Nov 30, 2021
Sampling Depth (mbgs)		3.0 - 3.7	1.2 - 1.8	3.0 - 3.7	3.0 - 3.7	1.2 - 1.8	4.6 - 5.2	1.2 - 1.8	1.2 - 1.8
Analytical Report Reference No.		21T826519	21T832162	21T826519	21T830287	21T832162	21T830891	21T832162	21T832162
Benzene	0.02	<0.02	<0.005	<0.02	<0.02	<0.005	<0.02	<0.005	<0.005
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.01	<0.05	<0.05	<0.01	<0.05	<0.01	<0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<5	<10	<5	<5	<10	<5	<10	<10
F2 (C10 to C16)	10	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	<50	42	<50	<50	14	<50	<10	<10
F4 (C34 to C50)	120	<50	<10	<50	<50	<10	<50	<10	<10

See "Notes for Soil and Groundwater Summary

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-28 SS2	QAQC-4	BH21-29 S3	BH21-30 SS3	BH21-31 S2	BH21-31 S3	BH21-32 SS4	BH21-33 S2
Date of Collection	Table 1 RPIICC	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021	Nov 05, 2021	Nov 15, 2021	Oct 28, 2021
Date Reported		Nov 20, 2021		Nov 30, 2021	Nov 20, 2021	Nov 08, 2021	Dec 20, 2021	Nov 27, 2021	Nov 30, 2021
Sampling Depth (mbgs)		0.8 - 1.4		1.2 - 1.8	1.5 - 2.1	0.6 - 1.2	1.2 - 1.8	2.3 - 2.9	0.6 - 1.2
Analytical Report Reference No.		21T827359		21T832162	21T827359	21T832162	21T839249	21T830287	21T832162
Benzene	0.02	<0.02	<0.02	<0.005	<0.02	<0.005	<0.02	<0.02	<0.005
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.05	<0.01	<0.05	<0.01	<0.05	<0.05	<0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<5	<5	<10	<5	<10	8	<5	<10
F2 (C10 to C16)	10	<10	<10	<10	<10	13	<10	<10	<10
F3 (C16 to C34)	240	<50	<50	17	<50	39	<50	<50	24
F4 (C34 to C50)	120	<50	<50	<10	<50	<10	<50	<50	<10

See "Notes for Soil and Groundwater Summary

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-34 S3	BH21-35 S2	BH21-36 SS6	BH21-37 S3	BH21-39 S3	BH21-41 S1
Date of Collection	Table 1 RPIICC	Oct 28, 2021	Nov 05, 2021	Nov 16, 2021	Oct 28, 2021	Nov 05, 2021	Nov 05, 2021
Date Reported		Nov 30, 2021	Nov 30, 2021	Nov 26, 2021	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021
Sampling Depth (mbgs)		1.2 - 1.8	0.6 - 1.2	4.6 - 5.2	1.2 - 1.8	1.2 - 1.8	0.0 - 0.6
Analytical Report Reference No.		21T832162	21T832162	21T830891	21T832162	21T832162	21T832162
Benzene	0.02	<0.005	<0.005	<0.02	<0.005	<0.005	0.006
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.01	<0.01	<0.05	<0.01	<0.01	0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	**0.22**
F1 (C6 to C10) minus BTEX	25	<10	<10	<5	<10	<10	10
F2 (C10 to C16)	10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	11	21	<50	15	24	75
F4 (C34 to C50)	120	<10	<10	<50	<10	<10	<10

See "Notes for Soil and Groundwater Summary

Table 6C Soil Analytical Results - VOCs

Parameter		BH21-13 SS5	BH21-25 SS6	BH21-32 SS4	BH21-36 SS6
Date of Collection	Table 1 RPIICC	Nov 15, 2021	Nov 16, 2021	Nov 15, 2021	Nov 16, 2021
Date Reported		Nov 27, 2021	Nov 26, 2021	Nov 27, 2021	Nov 26, 2021
Sampling Depth (mbgs)		3.0 - 3.7	4.6 - 5.2	2.3 - 2.9	4.6 - 5.2
Analytical Report Reference No.		21T830287	21T830891	21T830287	21T830891
Acetone	0.5	<0.50	<0.50	<0.50	<0.50
Benzene	0.02	<0.02	<0.02	<0.02	<0.02
Bromodichloromethane	0.05	<0.05	<0.05	<0.05	<0.05
Bromoform	0.05	<0.05	<0.05	<0.05	<0.05
Bromomethane	0.05	<0.05	<0.05	<0.05	<0.05
Carbon Tetrachloride	0.05	<0.05	<0.05	<0.05	<0.05
Chlorobenzene	0.05	<0.05	<0.05	<0.05	<0.05
Chloroform	0.05	<0.04	<0.04	<0.04	<0.04
Dibromochloromethane	0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,2-	0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,3-	0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,4-	0.05	<0.05	<0.05	<0.05	<0.05
Dichlorodifluoromethane	0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethane, 1,1-	0.05	<0.02	<0.02	<0.02	<0.02
Dichloroethane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03
Dichloroethylene, 1,1-	0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethylene, Cis- 1,2-	0.05	<0.02	<0.02	<0.02	<0.02
Dichloroethylene, Trans- 1,2-	0.05	<0.05	<0.05	<0.05	<0.05
Dichloropropane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03
1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.05	<0.05	<0.05
Ethylene Dibromide	0.05	<0.04	<0.04	<0.04	<0.04
Hexane, n-	0.05	<0.05	<0.05	<0.05	<0.05
Methyl Ethyl Ketone	0.5	<0.50	<0.50	<0.50	<0.50
Methyl Isobutyl Ketone	0.5	<0.50	<0.50	<0.50	<0.50
Methyl tert-butyl Ether	0.05	<0.05	<0.05	<0.05	<0.05
Methylene Chloride	0.05	<0.05	<0.05	<0.05	<0.05
Styrene	0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04
Tetrachloroethane, 1,1,2,2-	0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethylene	0.05	<0.05	<0.05	<0.05	<0.05
Toluene	0.2	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,1-	0.05	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04
Trichloroethylene	0.05	<0.03	<0.03	<0.03	<0.03
Trichlorofluoromethane	0.25	<0.05	<0.05	<0.05	<0.05
Vinyl Chloride	0.02	<0.02	<0.02	<0.02	<0.02
Xylene mixture	0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-9 SS3	BH21-9 SS4	BH21-10 S3	BH21-11 SS2	BH21-13 SS1	BH21-14 S3	BH21-15 S2
Date of Collection	Table 1 RPIICC	Nov 05, 2021	Nov 05, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Oct 27, 2021
Date Reported		Nov 16, 2021	Dec 20, 2021	Nov 08, 2021	Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (mbgs)		1.5 - 2.1	2.3 - 2.9	1.2 - 1.8	0.8 - 1.4	0.0 - 0.6	1.2 - 1.8	0.6 - 1.2
Analytical Report Reference No.		21T826519	21T839249	21T822752	21T826519	21T830287	21T822752	21T822752
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.12	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	0.1	0.22	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.16	**0.18**	0.07	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.56	0.19	0.44	<0.05	<0.05	<0.05	<0.05	<0.05
Pyrene	1	0.18	0.41	<0.05	<0.05	<0.05	<0.05	<0.05
Benz(a)anthracene	0.36	<0.05	0.2	<0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	2.8	<0.05	0.12	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	0.47	0.05	0.18	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	0.48	0.06	0.09	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	0.16	<0.05	<0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	0.07	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	0.08	<0.05	<0.05	<0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-25 SS1	BH21-26 S1	BH21-27 S2	BH21-28 SS3	QAQC-5	BH21-29 S1	BH21-30 SS1
Date of Collection	Table 1 RPIICC	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021
Date Reported		Nov 26, 2021	Nov 08, 2021	Nov 08, 2021	Nov 20, 2021		Nov 08, 2021	Nov 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	0.0 - 0.6	0.6 - 1.2	1.5 - 2.1		0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T830891	21T822752	21T822752	21T827359		21T822752	21T827359
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.12	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.16	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.56	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Pyrene	1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-31 S3	BH21-32 SS3	BH21-33 S1	BH21-34 S3	QAQC-3	BH21-35 S3	BH21-36 SS3
Date of Collection	Table 1 RPIICC	Nov 05, 2021	Nov 15, 2021	Oct 28, 2021	Oct 28, 2021		Oct 27, 2021	Nov 16, 2021
Date Reported		Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021		Nov 08, 2021	Nov 26, 2021
Sampling Depth (mbgs)		1.2 - 1.8	1.5 - 2.1	0.0 - 0.6	1.2 - 1.8		1.2 - 1.8	1.5 - 2.1
Analytical Report Reference No.		21T826519	21T830287	21T822752	21T822752		21T822752	21T830891
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.12	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.16	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.56	<0.05	<0.05	<0.05	<0.05	<0.05	0.25	<0.05
Pyrene	1	<0.05	<0.05	<0.05	<0.05	<0.05	0.18	<0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	<0.05	0.08	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	<0.05	0.14	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	<0.05	<0.05	<0.05	0.19	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05	<0.05	<0.05	0.17	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-37 S3	BH21-38 S1	BH21-39 S3	BH21-40 S1	BH21-40 S3	BH21-41 S1
Date of Collection	Table 1 RPIICC	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Dec 20, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (mbgs)		1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6
Analytical Report Reference No.		21T822752	21T822752	21T826519	21T839249	21T822752	21T826519
Naphthalene	0.09	<0.05	0.07	<0.05	**0.31**	**0.1**	0.08
Acenaphthylene	0.093	<0.05	<0.05	<0.05	**0.14**	0.06	0.08
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.12	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	0.07	<0.05	**0.78**	0.19	0.08
Anthracene	0.16	<0.05	0.05	<0.05	**0.27**	0.12	0.06
Fluoranthene	0.56	<0.05	0.14	<0.05	**2.11**	0.47	0.38
Pyrene	1	<0.05	0.12	<0.05	**1.94**	0.37	0.36
Benz(a)anthracene	0.36	<0.05	0.07	<0.05	**1.13**	0.19	0.18
Chrysene	2.8	<0.05	0.11	<0.05	1.25	0.16	0.14
Benzo(b)fluoranthene	0.47	<0.05	0.21	<0.05	**1.61**	**0.53**	0.25
Benzo(k)fluoranthene	0.48	<0.05	0.23	<0.05	**0.63**	**0.5**	0.24
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	**0.86**	0.09	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	0.09	<0.05	**0.48**	0.2	0.08
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	**0.13**	0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	0.13	<0.05	0.55	0.2	0.08
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	**0.82**	0.32	0.18

See "Notes for Soil and Groundwater Summary

Table 8C Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-9 SS1	BH21-10 S2	BH21-11 SS2	BH21-14 S1	BH21-15 S2	BH21-26 S1	BH21-27 S2
Date of Collection	Table 1 RPIICC	Nov 05, 2021	Oct 27, 2021	Nov 04, 2021	Oct 27, 2021	Oct 27, 2021	Oct 28, 2021	Oct 28, 2021
Date Reported		Nov 16, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 08, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (m bgs)		0.0 - 0.6	0.6 - 1.2	0.8 - 1.4	0.0 - 0.6	0.6 - 1.2	0.0 - 0.6	0.6 - 1.2
Analytical Report Reference No.		21T826519	21T822752	21T826519	21T822752	21T822752	21T822752	21T822752
Polychlorinated Biphenyls	0.3	<0.10	<0.10	-	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 8C Soil Analytical Results - PCBs and OC

Parameter		BH21-28 SS3	QAQC-5	BH21-29 S1	BH21-30 SS1	BH21-31 S2	BH21-33 S2	BH21-34 S1	QAQC-1
Date of Collection	Table 1 RPIICC	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021	Oct 28, 2021	Oct 28, 2021	
Date Reported		Nov 20, 2021		Nov 08, 2021	Nov 20, 2021	Nov 16, 2021	Nov 08, 2021	Nov 08, 2021	
Sampling Depth (m bgs)		1.5 - 2.1		0.0 - 0.6	0.0 - 0.6	0.6 - 1.2	0.6 - 1.2	0.0 - 0.6	
Analytical Report Reference No.		21T827359		21T822752	21T827359	21T826519	21T822752	21T822752	
Polychlorinated Biphenyls	0.3	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 8C Soil Analytical Results - PCBs and OC

Parameter		BH21-35 S2	BH21-37 S2	BH21-38 S3	BH21-39 S3	BH21-40 S1	BH21-41 SS2
Date of Collection	Table 1 RPIICC	Oct 27, 2021	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (m bgs)		0.6 - 1.2	0.6 - 1.2	1.2 - 1.8	1.2 - 1.8	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T822752	21T822752	21T822752	21T826519	21T822752	21T826519
Polychlorinated Biphenyls	0.3	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9C Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28
Date of Collection	Table 1 GW	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602
Antimony	1.5	<1.0	<1.0	<1.0	<1.0	<1.0
Arsenic	13	<1.0	<1.0	<1.0	<1.0	5.7
Barium	610	54	134	102	189	79.5
Beryllium	0.5	<0.50	<0.50	<0.50	<0.50	<0.50
Boron	1700	85	61	36	117	222
Cadmium	0.5	<0.20	<0.20	<0.20	<0.20	<0.20
Chromium	11	<2.0	<2.0	<2.0	<2.0	<2.0
Chromium VI	25	<2.0	<2.0	<2.0	<2.0	<2.0
Cobalt	3.8	2.06	<0.50	<0.50	<0.50	<0.50
Copper	5	<1.0	1.3	<1.0	<1.0	<1.0
Cyanide	5	<2.0	<2.0	<2.0	<2.0	<2.0
Lead	1.9	<0.50	<0.50	0.53	<0.50	<0.50
Mercury	0.1	<0.02	<0.02	<0.02	<0.02	<0.02
Molybdenum	23	3.5	<0.50	0.7	5.47	4.81
Nickel	14	3.9	1.2	<1.0	1.3	<1.0
Selenium	5	1	1.7	<1.0	<1.0	<1.0
Silver	0.3	<0.20	<0.20	<0.20	<0.20	<0.20
Thallium	0.5	<0.30	<0.30	<0.30	<0.30	<0.30
Uranium	8.9	0.73	<0.50	0.88	5.02	<0.50
Vanadium	3.9	<0.40	<0.40	<0.40	<0.40	<0.40
Zinc	160	<5.0	<5.0	<5.0	<5.0	<5.0
Sodium	490000	92000	135000	349000	18600	33000
Chloride	790000	162000	285000	557000	12800	17600

See "Notes for Soil and Groundwater Summary

Table 10C Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-30	BH21-36
Date of Collection	Table 1 GW	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021	Dec 13, 2021	Nov 23, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 15, 2021	Dec 03, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1	6.1 - 9.1	4.6 - 7.6
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602	21T843989	21T834096
Benzene	0.5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	0.8	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Ethylbenzene	0.5	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Xylene Mixture	72	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
F1 (C6 to C10) minus BTEX	420	<25	<25	<25	<25	<25	<25	<25
F2 (C10 to C16)	150	<100	<100	<100	<100	<100	<100	<100
F3 (C16 to C34)	500	<100	<100	<100	<100	<100	<100	<100
F4 (C34 to C50)	500	<100	<100	<100	<100	<100	<100	<100

See "Notes for Soil and Groundwater Summary

Table 11C Groundwater Analytical Results - VOCs

Parameter		BH21-36	BH21-9	BH21-13	BH21-25	BH21-28
Date of Collection	Table 1 GW	Nov 23, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021
Date Reported		Dec 03, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		4.6 - 7.6	1.9 - 4.9	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1
Analytical Report Reference No.		21T834096	21T838602	21T838602	21T838602	21T838602
Acetone	2700	<1.0	<1.0	<1.0	<1.0	<1.0
Benzene	0.5	<0.20	<0.20	<0.20	<0.20	<0.20
Bromodichloromethane	2	<0.20	<0.20	<0.20	<0.20	<0.20
Bromoform	5	<0.10	<0.10	<0.10	<0.10	<0.10
Bromomethane	0.89	<0.20	<0.20	<0.20	<0.20	<0.20
Carbon Tetrachloride	0.2	<0.20	<0.20	<0.20	<0.20	<0.20
Chlorobenzene	0.5	<0.10	<0.10	<0.10	<0.10	<0.10
Chloroform	2	<0.20	<0.20	<0.20	<0.20	<0.20
Dibromochloromethane	2	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,2-	0.5	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,3-	0.5	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,4-	0.5	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorodifluoromethane	590	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethane, 1,1-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethane, 1,2-	0.5	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, 1,1-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethylene, cis- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, trans- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropane, 1,2-	0.5	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropene, 1,3-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30
Ethylbenzene	0.5	<0.10	<0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	0.2	<0.10	<0.10	<0.10	<0.10	<0.10
Hexane, n-	5	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Ethyl Ketone	400	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl Isobutyl Ketone	640	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl tert-butyl ether	15	<0.20	<0.20	<0.20	<0.20	<0.20
Methylene Chloride	5	<0.30	<0.30	<0.30	<0.30	<0.30
Styrene	0.5	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,1,2-	1.1	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,2,2-	0.5	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	0.5	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	0.8	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethane, 1,1,1-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30
Trichloroethane, 1,1,2-	0.5	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethylene	0.5	<0.20	<0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	150	<0.40	<0.40	<0.40	<0.40	<0.40
Vinyl Chloride	0.5	<0.17	<0.17	<0.17	<0.17	<0.17
Xylene Mixture	72	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary

Table 12C Groundwater Analytical Results - PAHs

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-36
Date of Collection	Table 1 GW	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021	Nov 23, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 03, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1	4.6 - 7.6
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602	21T834096
Acenaphthene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Anthracene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Benz(a)anthracene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Chrysene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Fluoranthene	0.4	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Fluorene	120	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Naphthalene, 2-and 1-	2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Naphthalene	7	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Phenanthrene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Pyrene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary

Table 13C Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-9	BH21-11	BH21-28
Date of Collection	Table 1 GW	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	6.1 - 9.1
Analytical Report Reference No.		21T838602	21T838602	21T838602
Polychlorinated Biphenyls	0.2	<0.1	<0.1	<0.1
Aldrin	0.01	-	-	-
Chlordane	0.06	-	-	-
DDD	1.8	-	-	-
DDE	10	-	-	-
DDT	0.05	-	-	-
Dieldrin	0.05	-	-	-
Endosulfan	0.05	-	-	-
Endrin	0.05	-	-	-
Heptachlor	0.01	-	-	-
Heptachlor Epoxide	0.01	-	-	-
Hexachlorobenzene	0.01	-	-	-
Hexachlorobutadiene	0.01	-	-	-
Hexachlorocyclohexane Gamma-	0.01	-	-	-
Hexachloroethane	0.01	-	-	-
Methoxychlor	0.05	-	-	-

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14C Summary of Maximum Concentrations in Soil

Group	Parameter	Table 1 RPIICC	Maximum Concentration	Location
BTEX	Benzene	0.02	0.006	BH21-41 S1
	Ethylbenzene	0.05	0.01	BH21-41 S1
	Toluene	0.2	<0.05	all samples
	Total Xylenes	0.05	0.22	BH21-41 S1
Metals	Barium	220	147	BH21-30 SS2
	Beryllium	2.5	1.4	BH21-10 S1
	Boron	36	21	BH21-35 S1
	Cadmium	1.2	<0.5	all samples
	Chromium	70	32	BH21-30 SS2
	Cobalt	21	16.3	BH21-28 SS1
	Copper	92	64.7	BH21-10 S1
	Lead	120	205	BH21-36 SS1
	Molybdenum	2	11	BH21-10 S1
	Nickel	82	33	BH21-30 SS2
	Silver	0.5	<0.5	all samples
	Thallium	1	0.6	BH21-10 S1
	Uranium	2.5	0.73	BH21-10 S1
	Vanadium	86	42.7	BH21-30 SS2
	Zinc	290	179	BH21-36 SS1
As, Se, Sb	Antimony	1.3	3.5	BH21-10 S1
	Arsenic	18	26	BH21-41 S2
	Selenium	1.5	2.1	BH21-10 S1
PAHs	Acenaphthene	0.072	<0.05	all samples
	Acenaphthylene	0.093	0.14	BH21-40 S1
	Anthracene	0.16	0.27	BH21-40 S1
	Benz(a)anthracene	0.36	1.13	BH21-40 S1
	Benzo(a)pyrene	0.3	0.86	BH21-40 S1
	Benzo(b)fluoranthene	0.47	1.61	BH21-40 S1
	Benzo(g,h,i)perylene	0.68	0.55	BH21-40 S1
	Benzo(k)fluoranthene	0.48	0.63	BH21-40 S1
	Chrysene	2.8	1.25	BH21-40 S1
	Dibenz(a,h)anthracene	0.1	0.13	BH21-40 S1
	Fluoranthene	0.56	2.11	BH21-40 S1
	Fluorene	0.12	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.23	0.48	BH21-40 S1
	Methylnaphthalene, 2-(1-)	0.59	0.82	BH21-40 S1
	Naphthalene	0.09	0.31	BH21-40 S1
	Phenanthrene	0.69	0.78	BH21-40 S1
	Pyrene	1	1.94	BH21-40 S1
PHCs	F1 (C6 to C10) minus BTEX	25	10	BH21-41 S1
	F2 (C10 to C16)	10	13	BH21-31 S2
	F3 (C16 to C34)	240	75	BH21-41 S1
	F4 (C34 to C50)	120	<50	all samples
	Acetone	0.5	<0.50	all samples
	Bromodichloromethane	0.05	<0.05	all samples
	Bromoform	0.05	<0.05	all samples
	Bromomethane	0.05	<0.05	all samples
	Carbon Tetrachloride	0.05	<0.05	all samples
	Chlorobenzene	0.05	<0.05	all samples
	Chloroform	0.05	<0.04	all samples
	Dibromochloromethane	0.05	<0.05	all samples
	Dichlorobenzene, 1,2-	0.05	<0.05	all samples

Table 14C Summary of Maximum Concentrations in Soil

Group	Parameter	Table 1 RPIICC	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	0.05	<0.05	all samples
	Dichlorobenzene, 1,4-	0.05	<0.05	all samples
	Dichlorodifluoromethane	0.05	<0.05	all samples
	Dichloroethane, 1,1-	0.05	<0.02	all samples
	Dichloroethane, 1,2-	0.05	<0.03	all samples
	Dichloroethylene, 1,1-	0.05	<0.05	all samples
	Dichloroethylene, Cis- 1,2-	0.05	<0.02	all samples
	Dichloroethylene, Trans- 1,2-	0.05	<0.05	all samples
	Dichloropropane, 1,2-	0.05	<0.03	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	all samples
	Ethylene Dibromide	0.05	<0.04	all samples
	Hexane, n-	0.05	<0.05	all samples
	Methyl Ethyl Ketone	0.5	<0.50	all samples
	Methyl Isobutyl Ketone	0.5	<0.50	all samples
	Methyl tert-butyl Ether	0.05	<0.05	all samples
	Methylene Chloride	0.05	<0.05	all samples
	Styrene	0.05	<0.05	all samples
	Tetrachloroethane, 1,1,1,2-	0.05	<0.04	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.05	all samples
	Tetrachloroethylene	0.05	<0.05	all samples
	Trichloroethane, 1,1,1-	0.05	<0.05	all samples
	Trichloroethane, 1,1,2-	0.05	<0.04	all samples
	Trichloroethylene	0.05	<0.03	all samples
	Trichlorofluoromethane	0.25	<0.05	all samples
	Vinyl Chloride	0.02	<0.02	all samples
ORPs	Chromium, Hexavalent	0.66	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.57	0.342	BH21-28 SS1
	Mercury	0.27	0.32	BH21-32 SS1
	Sodium Adsorption Ratio	2.4	0.758	BH21-39 S1
	pH, 2:1 CaCl2 Extraction	*	7.91	QAQC-2
PCBs	Polychlorinated Biphenyls	0.3	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15C Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 1 GW	Maximum Concentration	Location
BTEX	Benzene	0.5	<0.20	all samples
	Ethylbenzene	0.5	<0.10	all samples
	Toluene	0.8	<0.20	all samples
	Xylene Mixture	72	<0.10	all samples
Metals	Barium	610	189	BH21-25
	Beryllium	0.5	<0.50	all samples
	Boron	1700	222	BH21-28
	Cadmium	0.5	<0.20	all samples
	Chromium	11	<2.0	all samples
	Cobalt	3.8	2.06	all samples
	Copper	5	1.3	all samples
	Lead	1.9	0.53	BH21-13
	Molybdenum	23	5.47	BH21-25
	Nickel	14	3.9	BH21-25
	Silver	0.3	<0.20	all samples
	Thallium	0.5	<0.30	all samples
	Uranium	8.9	5.02	BH21-25
	Vanadium	3.9	<0.40	all samples
	Zinc	160	<5.0	all samples
As, Se, Sb	Antimony	1.5	<1.0	all samples
	Arsenic	13	5.7	BH21-28
	Selenium	5	1.7	all samples
Na	Sodium	490000	349000	BH21-13
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	0.1	<0.10	all samples
	Benz(a)anthracene	0.2	<0.20	all samples
	Benzo(a)pyrene	0.01	<0.01	all samples
	Benzo(b)fluoranthene	0.1	<0.10	all samples
	Benzo(g,h,i)perylene	0.2	<0.20	all samples
	Benzo(k)fluoranthene	0.1	<0.10	all samples
	Chrysene	0.1	<0.10	all samples
	Dibenz(a,h)anthracene	0.2	<0.20	all samples
	Fluoranthene	0.4	<0.20	all samples
	Fluorene	120	<0.20	all samples
	Indeno(1,2,3-cd)pyrene	0.2	<0.20	all samples
	Methyl Naphthalene, 2-and 1-	2	<0.20	all samples
	Naphthalene	7	<0.20	all samples
	Phenanthrene	0.1	<0.10	all samples
	Pyrene	0.2	<0.20	all samples
PHCs	F1 (C6 to C10) minus BTEX	420	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	2	<0.20	all samples
	Bromoform	5	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.2	<0.20	all samples
	Chlorobenzene	0.5	<0.10	all samples
	Chloroform	2	<0.20	all samples
	Dibromochloromethane	2	<0.10	all samples

Table 15C Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 1 GW	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,2-	0.5	<0.10	all samples
	Dichlorobenzene, 1,3-	0.5	<0.10	all samples
	Dichlorobenzene, 1,4-	0.5	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	0.5	<0.30	all samples
	Dichloroethane, 1,2-	0.5	<0.20	all samples
	Dichloroethylene, 1,1-	0.5	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	0.5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	5	<0.20	all samples
	Methyl Ethyl Ketone	400	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	5	<0.30	all samples
	Styrene	0.5	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	0.5	<0.10	all samples
	Tetrachloroethylene	0.5	<0.20	all samples
	Trichloroethane, 1,1,1-	0.5	<0.30	all samples
	Trichloroethane, 1,1,2-	0.5	<0.20	all samples
	Trichloroethylene	0.5	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	557000	BH21-13
	Chromium VI	25	<2.0	all samples
	Cyanide	5	<2.0	all samples
	Mercury	0.1	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Notes for Soil & Groundwater Summary Tables - Caledon (C-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 2 RPI CT = Full Depth Generic Site Condition Standards in a Potable Ground Water Condition with Coarse Textured Soils as contained in Table 2 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011
11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 2 SCS

Table 1C Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-30	BH21-32	BH21-36
Installed By			WSP	WSP	WSP	WSP	WSP	WSP	WSP	WSP
Installation Date			4-Nov-21	4-Nov-21	15-Nov-21	16-Nov-21	8-Nov-21	8-Nov-21	15-Nov-21	16-Nov-21
Well Status			Active	Active	Active	Active	Active	Active	Active	Active
Well Inner Diameter		(mm)	50	50	50	50	50	50	50	50
Casing Type (Flushmount / Monument)			Monument	Monument	Monument	Monument	Monument	Flushmount	Monument	Monument
Top of Pipe Elevation		(masl)	423.843	397.847	404.757	255.396	282.313	286.873	274.654	326.921
Ground Surface Elevation		(masl)	422.953	396.937	403.897	256.306	281.403	286.973	273.744	326.001
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
		(masl)	422.653	396.637	403.597	256.006	281.103	286.673	273.444	325.701
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	1.3	4.9	3.1	4.0	5.5	5.5	2.4	4.0
		(masl)	421.7	392.0	400.8	252.3	275.9	281.5	271.4	322.0
Top of Well Screen		(mbgs)	1.9	5.5	3.7	4.6	6.1	6.1	3.0	4.6
		(masl)	421.1	391.4	400.2	251.7	275.3	280.9	270.7	321.4
Screen Length		(m)	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0
Bottom of Screen		(mbgs)	4.9	8.5	6.7	7.6	9.1	9.1	6.0	7.6
		(masl)	418.1	388.4	397.2	248.7	272.3	277.9	267.7	318.4
22-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	DRY	6.5
	GW Elevation	(masl)	-	-	-	-	-	-	-	319.5
23-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	DRY	6.6
	GW Elevation	(masl)	-	-	-	-	-	-	-	319.4
29-Nov-21	Depth of GW	(mbgs)	-	-	-	-	0.6	2.2	-	-
	GW Elevation	(masl)	-	-	-	-	280.8	284.8	-	-
30-Nov-21	Depth of GW	(mbgs)	-	-	-	2.2	-	-	-	-
	GW Elevation	(masl)	-	-	-	254.1	-	-	-	-
1-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
2-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
6-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
7-Dec-21	Depth of GW	(mbgs)	2.0	4.3	5.1	2.2	0.0	2.3	DRY	6.6
	GW Elevation	(masl)	421.0	392.6	398.8	254.1	281.7	284.7	-	319.4

See "Notes for Soil and Groundwater Summary

Table 2C Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-9	SS1	0.0 - 0.6	4-Nov-21	-	-	-	-	✓	✓	3, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS4	2.3 - 2.9		-	-	-	✓	-	-	
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
BH21-10	S1	0.0 - 0.6	27-Oct-21	✓	-	-	-	-	-	13, 14, 38, 105, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	✓	-	✓	-	-	
BH21-11	SS1	0.0 - 0.6	4-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS2	0.8 - 1.4		-	-	-	✓	✓	✓	
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
BH21-13	SS1	0.0 - 0.6	15-Nov-21	-	-	-	✓	-	-	13, 14, 38, 112, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-14	S1	0.0 - 0.6	27-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 96, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-15	S2	0.6 - 1.2	27-Oct-21	-	-	-	✓	✓	✓	13, 14, 38, 93, 114
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-25	SS1	0.0 - 0.6	16-Nov-21	-	-	-	✓	-	-	13, 14, 38, 108, 114
	SS2	0.8 - 1.4		✓	-	-	-	-		
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-26	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 60, 114
	S2	0.6 - 1.2		-	-	-	✓	-	-	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-27	S1	0.0 - 0.6	28-Oct-21	✓	-	-	-	-	-	13, 14, 38, 63, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-28	SS1	0.0 - 0.6	8-Nov-21	✓	-	-	-	-	-	1, 13, 14, 38, 114
	QAQC-3			✓	-	-	-	-	-	
	SS2	0.8 - 1.4		-	✓	-	-	-	-	
	QAQC-4			-	✓	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	✓	✓	
	QAQC-5			-	-	-	✓	✓	✓	
BH21-29	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 66, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-30	SS1	0.0 - 0.6	8-Nov-21	-	-	-	✓	✓	✓	13, 14, 33, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-31	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 69, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	✓	-	✓	-	-	
BH21-32	SS1	0.0 - 0.6	15-Nov-21	✓	-	-	-	-	-	13, 14, 38, 109, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS4	2.3 - 2.9		-	✓	✓	-	-	-	
BH21-33	S1	0.0 - 0.6	28-Oct-21	-	-	-	✓	-	-	13, 14, 38, 72, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-34	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 75, 114
	QAQC-1			-	-	-	-	✓	✓	
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	QAQC-S2			✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
	QAQC-S3			-	-	-	✓	-	-	

Table 2C Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-35	S1	0.0 - 0.6	27-Oct-21	✓	-	-	-	-	-	13, 14, 38, 78, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-36	SS1	0.0 - 0.6	16-Nov-21	✓	-	-	-	-	-	13, 14, 38, 110, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-37	S1	0.0 - 0.6	27-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 81, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-38	S1	0.0 - 0.6	27-Oct-21	-	-	-	✓	-	-	13, 14, 38, 84, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-39	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 111, 114
	S3	1.2 - 1.8		-	-	-	✓	✓	✓	
BH21-40	S1	0.0 - 0.6	27-Oct-21	-	-	-	✓	✓	✓	13, 14, 38, 87, 114
	S3	1.2 - 1.8		✓	-	-	✓	-	-	
BH21-41	S1	0.0 - 0.6	5-Nov-21	-	-	-	✓	-	-	13, 14, 38, 90, 114
	S2	0.6 - 1.2		✓	✓	-	-	✓	✓	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3C: Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-9	1.9 - 4.9	30-Nov-21	✓	✓	✓	✓	✓	-	3, 13, 14, 38, 114
BH21-11	5.5 - 8.5	30-Nov-21	✓	✓	-	✓	✓	-	13, 14, 38, 114
BH21-13	3.7 - 6.7	30-Nov-21	✓	✓	✓	✓	-	-	13, 14, 38, 112, 114
BH21-25	4.6 - 7.6	1-Dec-21	✓	✓	✓	✓	-	-	13, 14, 38, 108, 114
BH21-28	6.1 - 9.1	1-Dec-21	✓	✓	✓	✓	✓	-	1, 13, 14, 38, 114
BH21-30	6.1 - 9.1	1-Dec-21	-	✓	-	-	-	-	13, 14, 33, 38, 114
BH21-36	4.6 - 7.6	23-Nov-21	✓	✓	✓	✓	-	-	13, 14, 38, 110, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-9 SS2	BH21-10 S1	BH21-10 S3	BH21-11 SS1	BH21-13 SS2	BH21-14 S2	BH21-15 S3
Date of Collection	Table 2 RPI CT	Nov 04, 2021	Oct 27, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Oct 27, 2021
Date Reported		Nov 16, 2021	Nov 08, 2021	Dec 20, 2021	Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6	0.8 - 1.4	0.6 - 1.2	1.2 - 1.8
Analytical Report Reference No.		21T826519	21T822752		21T826519	21T830287	21T822752	21T822752
Antimony	7.5	<0.8	3.5	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	3	**24**	8	2	2	3	4
Barium	390	25.4	44.5	27	10.1	10.6	49.6	26.5
Beryllium	4	<0.4	1.4	<0.4	<0.4	<0.4	<0.4	<0.4
Boron	120	<5	12	8	<5	<5	<5	<5
Boron (Hot Water Extractable)	1.5	0.18	0.37	0.21	<0.10	<0.10	0.13	<0.10
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	160	12	15	10	<5	5	14	7
Cobalt	22	4.6	9.3	5.2	1.9	1.7	4.6	3.3
Copper	140	8	64.7	23.7	9	3.4	8.6	17
Lead	120	7	52	15	2	3	8	5
Molybdenum	6.9	<0.5	**11**	1	<0.5	<0.5	<0.5	<0.5
Nickel	100	9	29	7	2	3	9	5
Selenium	2.4	<0.8	2.1	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	20	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	0.6	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	23	<0.50	0.7	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	24.7	26.7	15.3	10.4	10.9	26.6	14.4
Zinc	340	28	70	54	18	13	46	22
Chromium, Hexavalent	8	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	0.11	<0.10
Electrical Conductivity (2:1)	0.7	0.096	0.255	0.210	0.061	0.078	0.103	0.073
Sodium Adsorption Ratio	5	0.07	0.061	0.295	0.055	0.205	0.043	0.061
pH, 2:1 CaCl2 Extraction	*	7.29	7.24	7.39	7.82	7.77	7.27	7.80

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-25 SS2	BH21-26 S3	BH21-27 S1	BH21-28 SS1	QAQC-3	BH21-29 S2	BH21-30 SS2	BH21-31 S1
Date of Collection	Table 2 RPI CT	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021
Date Reported		Nov 26, 2021	Nov 08, 2021	Nov 08, 2021	Nov 20, 2021		Nov 08, 2021	Nov 20, 2021	Nov 16, 2021
Sampling Depth (mbgs)		0.8 - 1.4	1.2 - 1.8	0.0 - 0.6	0.0 - 0.6		0.6 - 1.2	0.8 - 1.4	0.0 - 0.6
Analytical Report Reference No.		21T830891	21T822752	21T822752	21T827359		21T822752	21T827359	21T826519
Antimony	7.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	8	4	12	10	10	5	6	8
Barium	390	85.3	47.6	54.2	73.4	65.4	99	147	58.8
Beryllium	4	0.5	<0.4	0.5	0.8	0.7	0.7	1.4	0.5
Boron	120	<5	5	6	12	10	9	12	7
Boron (Hot Water Extractable)	1.5	0.35	<0.10	0.26	0.44	0.47	0.13	<0.10	0.12
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	160	23	16	19	23	21	26	32	17
Cobalt	22	12.6	9.4	6.8	16.3	6.8	11.1	14.1	10.0
Copper	140	35.5	37.1	24.7	40.9	31.3	26.1	28.4	28.5
Lead	120	12	7	15	29	26	9	12	9
Molybdenum	6.9	<0.5	<0.5	<0.5	0.7	0.6	<0.5	<0.5	<0.5
Nickel	100	26	18	15	31	17	24	33	21
Selenium	2.4	<0.8	<0.8	<0.8	0.9	<0.8	<0.8	<0.8	<0.8
Silver	20	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	23	0.5	<0.50	<0.50	0.6	<0.50	<0.50	0.6	<0.50
Vanadium	86	32.8	23	28.1	30.2	27.3	36.5	42.7	24.8
Zinc	340	70	47	58	92	81	57	71	51
Chromium, Hexavalent	8	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.174	0.106	0.192	0.342	0.336	0.129	0.165	0.107
Sodium Adsorption Ratio	5	0.267	0.084	0.103	0.396	0.393	0.105	0.458	0.060
pH, 2:1 CaCl2 Extraction	*	7.50	7.79	7.70	7.28	7.60	7.71	7.25	7.60

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-32 SS1	BH21-32 SS2	BH21-33 S3	BH21-34 S2	QAQC-2	BH21-35 S1	BH21-36 SS1	BH21-36 SS1
Date of Collection	Table 2 RPI CT	Nov 15, 2021	Nov 15, 2021	Oct 28, 2021	Oct 28, 2021		Oct 27, 2021	Nov 16, 2021	Nov 16, 2021
Date Reported		Nov 27, 2021	Dec 20, 2021	Nov 08, 2021	Nov 08, 2021		Nov 08, 2021	Nov 26, 2021	Dec 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	0.8 - 1.4	1.2 - 1.8	0.6 - 1.2		0.0 - 0.6	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T830287	21T839249	21T822752	21T822752		21T822752	21T830891	21T839249
Antimony	7.5	1.9	<0.8	<0.8	<0.8	<0.8	<0.8	1.1	<0.8
Arsenic	18	6	2	5	4	3	13	11	4
Barium	390	43.1	35.6	99.2	58.5	57	53.8	103	26.3
Beryllium	4	<0.4	<0.4	0.6	0.4	0.4	0.5	<0.4	<0.4
Boron	120	9	<5	9	10	11	21	6	7
Boron (Hot Water Extractable)	1.5	0.40	0.16	<0.10	<0.10	<0.10	0.35	0.23	0.15
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	160	12	11	23	17	16	12	12	11
Cobalt	22	5.8	4.5	11.9	7.4	7.4	10.2	5.1	5.4
Copper	140	48.3	16.7	25.3	17.4	17	44.3	53.7	26.2
Lead	120	65	9	9	5	5	13	**205**	13
Molybdenum	6.9	1.4	<0.5	<0.5	<0.5	<0.5	1.1	1.2	<0.5
Nickel	100	21	9	24	14	13	19	11	9
Selenium	2.4	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	20	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	23	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	17.7	20.5	33.6	26.5	25.2	15.4	18.7	21.4
Zinc	340	67	34	52	38	36	63	179	39
Chromium, Hexavalent	8	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	**0.32**	<0.10	<0.10	<0.10	<0.10	<0.10	0.23	<0.10
Electrical Conductivity (2:1)	0.7	0.184	0.134	0.115	0.108	0.101	0.217	0.156	0.115
Sodium Adsorption Ratio	5	0.193	0.199	0.155	0.072	0.070	0.095	0.076	0.139
pH, 2:1 CaCl2 Extraction	*	7.60	7.15	7.80	7.87	7.91	7.87	7.70	7.08

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-37 S2	BH21-38 S3	BH21-39 S1	BH21-40 S3	BH21-41 S2
Date of Collection	Table 2 RPI CT	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (mbgs)		0.6 - 1.2	1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.6 - 1.2
Analytical Report Reference No.		21T822752	21T822752	21T826519	21T822752	21T826519
Antimony	7.5	1	<0.8	<0.8	<0.8	<0.8
Arsenic	18	12	3	6	6	**26**
Barium	390	41.3	16.9	40.7	29.6	18.3
Beryllium	4	<0.4	<0.4	0.4	<0.4	<0.4
Boron	120	7	<5	15	7	10
Boron (Hot Water Extractable)	1.5	0.18	<0.10	0.36	0.20	0.13
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	160	11	6	14	11	23
Cobalt	22	5.4	2.5	6.3	4.5	8.3
Copper	140	25.1	9	12.3	27.2	24
Lead	120	18	4	7	20	52
Molybdenum	6.9	0.9	<0.5	<0.5	0.9	2.1
Nickel	100	11	4	13	10	8
Selenium	2.4	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	20	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	23	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	19.1	9.4	21.3	19.3	25.2
Zinc	340	33	14	48	33	121
Chromium, Hexavalent	8	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.136	0.082	0.210	0.328	0.152
Sodium Adsorption Ratio	5	0.036	0.051	0.758	0.025	0.121
pH, 2:1 CaCl2 Extraction	*	7.46	7.66	7.49	7.62	7.69

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-9 SS5	BH21-10 S3	BH21-11 SS5	BH21-13 SS5	BH21-14 S3	BH21-25 SS6	BH21-26 S3	BH21-27 S3
Date of Collection	Table 2 RPI CT	Nov 04, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021
Date Reported		Nov 16, 2021	Nov 30, 2021	Nov 16, 2021	Nov 27, 2021	Nov 30, 2021	Nov 26, 2021	Nov 30, 2021	Nov 30, 2021
Sampling Depth (mbgs)		3.0 - 3.7	1.2 - 1.8	3.0 - 3.7	3.0 - 3.7	1.2 - 1.8	4.6 - 5.2	1.2 - 1.8	1.2 - 1.8
Analytical Report Reference No.		21T826519	21T832162	21T826519	21T830287	21T832162	21T830891	21T832162	21T832162
Benzene	0.21	<0.02	<0.005	<0.02	<0.02	<0.005	<0.02	<0.005	<0.005
Toluene	2.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.05	<0.01	<0.05	<0.05	<0.01	<0.05	<0.01	<0.01
Total Xylenes	3.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	55	<5	<10	<5	<5	<10	<5	<10	<10
F2 (C10 to C16)	98	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	300	<50	42	<50	<50	14	<50	<10	<10
F4 (C34 to C50)	2800	<50	<10	<50	<50	<10	<50	<10	<10

See "Notes for Soil and Groundwater Summary

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-28 SS2	QAQC-4	BH21-29 S3	BH21-30 SS3	BH21-31 S2	BH21-31 S3	BH21-32 SS4	BH21-33 S2
Date of Collection	Table 2 RPI CT	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021	Nov 05, 2021	Nov 15, 2021	Oct 28, 2021
Date Reported		Nov 20, 2021		Nov 30, 2021	Nov 20, 2021	Nov 08, 2021	Dec 20, 2021	Nov 27, 2021	Nov 30, 2021
Sampling Depth (mbgs)		0.8 - 1.4		1.2 - 1.8	1.5 - 2.1	0.6 - 1.2	1.2 - 1.8	2.3 - 2.9	0.6 - 1.2
Analytical Report Reference No.		21T827359		21T832162	21T827359	21T832162	21T839249	21T830287	21T832162
Benzene	0.21	<0.02	<0.02	<0.005	<0.02	<0.005	<0.02	<0.02	<0.005
Toluene	2.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.05	<0.05	<0.01	<0.05	<0.01	<0.05	<0.05	<0.01
Total Xylenes	3.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	55	<5	<5	<10	<5	<10	8	<5	<10
F2 (C10 to C16)	98	<10	<10	<10	<10	13	<10	<10	<10
F3 (C16 to C34)	300	<50	<50	17	<50	39	<50	<50	24
F4 (C34 to C50)	2800	<50	<50	<10	<50	<10	<50	<50	<10

See "Notes for Soil and Groundwater Summary

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-34 S3	BH21-35 S2	BH21-36 SS6	BH21-37 S3	BH21-39 S3	BH21-41 S1
Date of Collection	Table 2 RPI CT	Oct 28, 2021	Nov 05, 2021	Nov 16, 2021	Oct 28, 2021	Nov 05, 2021	Nov 05, 2021
Date Reported		Nov 30, 2021	Nov 30, 2021	Nov 26, 2021	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021
Sampling Depth (mbgs)		1.2 - 1.8	0.6 - 1.2	4.6 - 5.2	1.2 - 1.8	1.2 - 1.8	0.0 - 0.6
Analytical Report Reference No.		21T832162	21T832162	21T830891	21T832162	21T832162	21T832162
Benzene	0.21	<0.005	<0.005	<0.02	<0.005	<0.005	0.006
Toluene	2.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.01	<0.01	<0.05	<0.01	<0.01	0.01
Total Xylenes	3.1	<0.05	<0.05	<0.05	<0.05	<0.05	0.22
F1 (C6 to C10) minus BTEX	55	<10	<10	<5	<10	<10	10
F2 (C10 to C16)	98	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	300	11	21	<50	15	24	75
F4 (C34 to C50)	2800	<10	<10	<50	<10	<10	<10

See "Notes for Soil and Groundwater Summary

Table 6C Soil Analytical Results - VOCs

Parameter		BH21-13 SS5	BH21-25 SS6	BH21-32 SS4	BH21-36 SS6
Date of Collection	Table 2 RPI CT	Nov 15, 2021	Nov 16, 2021	Nov 15, 2021	Nov 16, 2021
Date Reported		Nov 27, 2021	Nov 26, 2021	Nov 27, 2021	Nov 26, 2021
Sampling Depth (mbgs)		3.0 - 3.7	4.6 - 5.2	2.3 - 2.9	4.6 - 5.2
Analytical Report Reference No.		21T830287	21T830891	21T830287	21T830891
Acetone	16	<0.50	<0.50	<0.50	<0.50
Benzene	0.21	<0.02	<0.02	<0.02	<0.02
Bromodichloromethane	1.5	<0.05	<0.05	<0.05	<0.05
Bromoform	0.27	<0.05	<0.05	<0.05	<0.05
Bromomethane	0.05	<0.05	<0.05	<0.05	<0.05
Carbon Tetrachloride	0.05	<0.05	<0.05	<0.05	<0.05
Chlorobenzene	2.4	<0.05	<0.05	<0.05	<0.05
Chloroform	0.05	<0.04	<0.04	<0.04	<0.04
Dibromochloromethane	2.3	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,2-	1.2	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,3-	4.8	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,4-	0.083	<0.05	<0.05	<0.05	<0.05
Dichlorodifluoromethane	16	<0.05	<0.05	<0.05	<0.05
Dichloroethane, 1,1-	0.47	<0.02	<0.02	<0.02	<0.02
Dichloroethane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03
Dichloroethylene, 1,1-	0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethylene, Cis- 1,2-	1.9	<0.02	<0.02	<0.02	<0.02
Dichloroethylene, Trans- 1,2-	0.084	<0.05	<0.05	<0.05	<0.05
Dichloropropane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03
1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	1.1	<0.05	<0.05	<0.05	<0.05
Ethylene Dibromide	0.05	<0.04	<0.04	<0.04	<0.04
Hexane, n-	2.8	<0.05	<0.05	<0.05	<0.05
Methyl Ethyl Ketone	16	<0.50	<0.50	<0.50	<0.50
Methyl Isobutyl Ketone	1.7	<0.50	<0.50	<0.50	<0.50
Methyl tert-butyl Ether	0.75	<0.05	<0.05	<0.05	<0.05
Methylene Chloride	0.1	<0.05	<0.05	<0.05	<0.05
Styrene	0.7	<0.05	<0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	0.058	<0.04	<0.04	<0.04	<0.04
Tetrachloroethane, 1,1,2,2-	0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethylene	0.28	<0.05	<0.05	<0.05	<0.05
Toluene	2.3	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,1-	0.38	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04
Trichloroethylene	0.061	<0.03	<0.03	<0.03	<0.03
Trichlorofluoromethane	4	<0.05	<0.05	<0.05	<0.05
Vinyl Chloride	0.02	<0.02	<0.02	<0.02	<0.02
Xylene mixture	3.1	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-9 SS3	BH21-9 SS4	BH21-10 S3	BH21-11 SS2	BH21-13 SS1	BH21-14 S3	BH21-15 S2
Date of Collection	Table 2 RPI CT	Nov 05, 2021	Nov 05, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Oct 27, 2021
Date Reported		Nov 16, 2021	Dec 20, 2021	Nov 08, 2021	Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (mbgs)		1.5 - 2.1	2.3 - 2.9	1.2 - 1.8	0.8 - 1.4	0.0 - 0.6	1.2 - 1.8	0.6 - 1.2
Analytical Report Reference No.		21T826519	21T839249	21T822752	21T826519	21T830287	21T822752	21T822752
Naphthalene	0.6	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.15	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	7.9	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	62	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	6.2	0.1	0.22	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.67	0.18	0.07	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.69	0.19	0.44	<0.05	<0.05	<0.05	<0.05	<0.05
Pyrene	78	0.18	0.41	<0.05	<0.05	<0.05	<0.05	<0.05
Benz(a)anthracene	0.5	<0.05	0.2	<0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	7	<0.05	0.12	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	0.78	0.05	0.18	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	0.78	0.06	0.09	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	0.16	<0.05	<0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.38	<0.05	0.07	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	6.6	<0.05	0.08	<0.05	<0.05	<0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.99	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-25 SS1	BH21-26 S1	BH21-27 S2	BH21-28 SS3	QAQC-5	BH21-29 S1	BH21-30 SS1
Date of Collection	Table 2 RPI CT	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021
Date Reported		Nov 26, 2021	Nov 08, 2021	Nov 08, 2021	Nov 20, 2021		Nov 08, 2021	Nov 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	0.0 - 0.6	0.6 - 1.2	1.5 - 2.1		0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T830891	21T822752	21T822752	21T827359		21T822752	21T827359
Naphthalene	0.6	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.15	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	7.9	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	62	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	6.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.67	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Pyrene	78	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	0.05
Benz(a)anthracene	0.5	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	7	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	0.78	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	0.78	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.38	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	6.6	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.99	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-31 S3	BH21-32 SS3	BH21-33 S1	BH21-34 S3	QAQC-3	BH21-35 S3	BH21-36 SS3
Date of Collection	Table 2 RPI CT	Nov 05, 2021	Nov 15, 2021	Oct 28, 2021	Oct 28, 2021		Oct 27, 2021	Nov 16, 2021
Date Reported		Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021		Nov 08, 2021	Nov 26, 2021
Sampling Depth (mbgs)		1.2 - 1.8	1.5 - 2.1	0.0 - 0.6	1.2 - 1.8		1.2 - 1.8	1.5 - 2.1
Analytical Report Reference No.		21T826519	21T830287	21T822752	21T822752		21T822752	21T830891
Naphthalene	0.6	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.15	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	7.9	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	62	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	6.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.67	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	0.25	<0.05
Pyrene	78	<0.05	<0.05	<0.05	<0.05	<0.05	0.18	<0.05
Benz(a)anthracene	0.5	<0.05	<0.05	<0.05	<0.05	<0.05	0.08	<0.05
Chrysene	7	<0.05	<0.05	<0.05	<0.05	<0.05	0.14	<0.05
Benzo(b)fluoranthene	0.78	<0.05	<0.05	<0.05	<0.05	<0.05	0.19	<0.05
Benzo(k)fluoranthene	0.78	<0.05	<0.05	<0.05	<0.05	<0.05	0.17	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Indeno(1,2,3-cd)pyrene	0.38	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	6.6	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Methylnaphthalene, 2-(1-)	0.99	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-37 S3	BH21-38 S1	BH21-39 S3	BH21-40 S1	BH21-40 S3	BH21-41 S1
Date of Collection	Table 2 RPI CT	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Dec 20, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (mbgs)		1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6
Analytical Report Reference No.		21T822752	21T822752	21T826519	21T839249	21T822752	21T826519
Naphthalene	0.6	<0.05	0.07	<0.05	0.31	0.1	0.08
Acenaphthylene	0.15	<0.05	<0.05	<0.05	0.14	0.06	0.08
Acenaphthene	7.9	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	62	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	6.2	<0.05	0.07	<0.05	0.78	0.19	0.08
Anthracene	0.67	<0.05	0.05	<0.05	0.27	0.12	0.06
Fluoranthene	0.69	<0.05	0.14	<0.05	**2.11**	0.47	0.38
Pyrene	78	<0.05	0.12	<0.05	1.94	0.37	0.36
Benz(a)anthracene	0.5	<0.05	0.07	<0.05	**1.13**	0.19	0.18
Chrysene	7	<0.05	0.11	<0.05	1.25	0.16	0.14
Benzo(b)fluoranthene	0.78	<0.05	0.21	<0.05	**1.61**	0.53	0.25
Benzo(k)fluoranthene	0.78	<0.05	0.23	<0.05	0.63	0.5	0.24
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	**0.86**	0.09	<0.05
Indeno(1,2,3-cd)pyrene	0.38	<0.05	0.09	<0.05	**0.48**	0.2	0.08
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	**0.13**	0.05	<0.05
Benzo(g,h,i)perylene	6.6	<0.05	0.13	<0.05	0.55	0.2	0.08
Methylnaphthalene, 2-(1-)	0.99	<0.05	<0.05	<0.05	0.82	0.32	0.18

See "Notes for Soil and Groundwater Summary

Table 8C Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-9 SS1	BH21-10 S2	BH21-11 SS2	BH21-14 S1	BH21-15 S2	BH21-26 S1	BH21-27 S2
Date of Collection	Table 2 RPI CT	Nov 05, 2021	Oct 27, 2021	Nov 04, 2021	Oct 27, 2021	Oct 27, 2021	Oct 28, 2021	Oct 28, 2021
Date Reported		Nov 16, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 08, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (m bgs)		0.0 - 0.6	0.6 - 1.2	0.8 - 1.4	0.0 - 0.6	0.6 - 1.2	0.0 - 0.6	0.6 - 1.2
Analytical Report Reference No.		21T826519	21T822752	21T826519	21T822752	21T822752	21T822752	21T822752
Polychlorinated Biphenyls	0.35	<0.10	<0.10	-	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	3.3	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.26	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.15	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.52	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.012	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.056	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.089	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.13	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 8C Soil Analytical Results - PCBs and OC

Parameter		BH21-28 SS3	QAQC-5	BH21-29 S1	BH21-30 SS1	BH21-31 S2	BH21-33 S2	BH21-34 S1	QAQC-1
Date of Collection	Table 2 RPI CT	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021	Oct 28, 2021	Oct 28, 2021	
Date Reported		Nov 20, 2021		Nov 08, 2021	Nov 20, 2021	Nov 16, 2021	Nov 08, 2021	Nov 08, 2021	
Sampling Depth (m bgs)		1.5 - 2.1		0.0 - 0.6	0.0 - 0.6	0.6 - 1.2	0.6 - 1.2	0.0 - 0.6	
Analytical Report Reference No.		21T827359		21T822752	21T827359	21T826519	21T822752	21T822752	
Polychlorinated Biphenyls	0.35	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	3.3	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.26	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.15	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.52	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.012	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.056	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.089	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.13	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 8C Soil Analytical Results - PCBs and OC

Parameter		BH21-35 S2	BH21-37 S2	BH21-38 S3	BH21-39 S3	BH21-40 S1	BH21-41 SS2
Date of Collection	Table 2 RPI CT	Oct 27, 2021	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (m bgs)		0.6 - 1.2	0.6 - 1.2	1.2 - 1.8	1.2 - 1.8	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T822752	21T822752	21T822752	21T826519	21T822752	21T826519
Polychlorinated Biphenyls	0.35	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	3.3	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.26	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.15	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.52	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.012	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.056	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.089	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.13	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9C Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28
Date of Collection	Table 2 Potable GW CT	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602
Antimony	6	<1.0	<1.0	<1.0	<1.0	<1.0
Arsenic	25	<1.0	<1.0	<1.0	<1.0	5.7
Barium	1000	54	134	102	189	79.5
Beryllium	4	<0.50	<0.50	<0.50	<0.50	<0.50
Boron	5000	85	61	36	117	222
Cadmium	2.7	<0.20	<0.20	<0.20	<0.20	<0.20
Chromium	50	<2.0	<2.0	<2.0	<2.0	<2.0
Chromium VI	25	<2.0	<2.0	<2.0	<2.0	<2.0
Cobalt	3.8	2.06	<0.50	<0.50	<0.50	<0.50
Copper	87	<1.0	1.3	<1.0	<1.0	<1.0
Cyanide	66	<2.0	<2.0	<2.0	<2.0	<2.0
Lead	10	<0.50	<0.50	0.53	<0.50	<0.50
Mercury	0.29	<0.02	<0.02	<0.02	<0.02	<0.02
Molybdenum	70	3.5	<0.50	0.7	5.47	4.81
Nickel	100	3.9	1.2	<1.0	1.3	<1.0
Selenium	10	1	1.7	<1.0	<1.0	<1.0
Silver	1.5	<0.20	<0.20	<0.20	<0.20	<0.20
Thallium	2	<0.30	<0.30	<0.30	<0.30	<0.30
Uranium	20	0.73	<0.50	0.88	5.02	<0.50
Vanadium	6.2	<0.40	<0.40	<0.40	<0.40	<0.40
Zinc	1100	<5.0	<5.0	<5.0	<5.0	<5.0
Sodium	490000	92000	135000	349000	18600	33000
Chloride	790000	162000	285000	557000	12800	17600

See "Notes for Soil and Groundwater Summary

Table 10C Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-30	BH21-36
Date of Collection	Table 2 Potable GW CT	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021	Dec 13, 2021	Nov 23, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 15, 2021	Dec 03, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1	6.1 - 9.1	4.6 - 7.6
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602	21T843989	21T834096
Benzene	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	24	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Ethylbenzene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Xylene Mixture	300	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
F1 (C6 to C10) minus BTEX	750	<25	<25	<25	<25	<25	<25	<25
F2 (C10 to C16)	150	<100	<100	<100	<100	<100	<100	<100
F3 (C16 to C34)	500	<100	<100	<100	<100	<100	<100	<100
F4 (C34 to C50)	500	<100	<100	<100	<100	<100	<100	<100

See "Notes for Soil and Groundwater Summary

Table 11C Groundwater Analytical Results - VOCs

Parameter		BH21-36	BH21-9	BH21-13	BH21-25	BH21-28
Date of Collection	Table 2 Potable GW CT	Nov 23, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021
Date Reported		Dec 03, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		4.6 - 7.6	1.9 - 4.9	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1
Analytical Report Reference No.		21T834096	21T838602	21T838602	21T838602	21T838602
Acetone	2700	<1.0	<1.0	<1.0	<1.0	<1.0
Benzene	5	<0.20	<0.20	<0.20	<0.20	<0.20
Bromodichloromethane	16	<0.20	<0.20	<0.20	<0.20	<0.20
Bromoform	25	<0.10	<0.10	<0.10	<0.10	<0.10
Bromomethane	0.89	<0.20	<0.20	<0.20	<0.20	<0.20
Carbon Tetrachloride	0.79	<0.20	<0.20	<0.20	<0.20	<0.20
Chlorobenzene	30	<0.10	<0.10	<0.10	<0.10	<0.10
Chloroform	2.4	<0.20	<0.20	<0.20	<0.20	<0.20
Dibromochloromethane	25	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,2-	3	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,3-	59	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,4-	1	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorodifluoromethane	590	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethane, 1,1-	5	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethane, 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, 1,1-	1.6	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethylene, cis- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, trans- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropane, 1,2-	5	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropene, 1,3-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30
Ethylbenzene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	0.2	<0.10	<0.10	<0.10	<0.10	<0.10
Hexane, n-	51	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Ethyl Ketone	1800	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl Isobutyl Ketone	640	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl tert-butyl ether	15	<0.20	<0.20	<0.20	<0.20	<0.20
Methylene Chloride	50	<0.30	<0.30	<0.30	<0.30	<0.30
Styrene	5.4	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,1,2-	1.1	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,2,2-	1	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	24	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethane, 1,1,1-	200	<0.30	<0.30	<0.30	<0.30	<0.30
Trichloroethane, 1,1,2-	4.7	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethylene	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	150	<0.40	<0.40	<0.40	<0.40	<0.40
Vinyl Chloride	0.5	<0.17	<0.17	<0.17	<0.17	<0.17
Xylene Mixture	300	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary

Table 12C Groundwater Analytical Results - PAHs

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-36
Date of Collection	Table 2 Potable GW CT	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021	Nov 23, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 03, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1	4.6 - 7.6
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602	21T834096
Acenaphthene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Anthracene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Benz(a)anthracene	1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Chrysene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Fluoranthene	0.41	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Fluorene	120	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Naphthalene, 2-and 1-	3.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Naphthalene	11	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Phenanthrene	1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Pyrene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary

Table 13C Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-9	BH21-11	BH21-28
Date of Collection	Table 2 Potable GW CT	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	6.1 - 9.1
Analytical Report Reference No.		21T838602	21T838602	21T838602
Polychlorinated Biphenyls	3	<0.1	<0.1	<0.1
Aldrin	0.35	-	-	-
Chlordane	7	-	-	-
DDD	10	-	-	-
DDE	10	-	-	-
DDT	2.8	-	-	-
Dieldrin	0.35	-	-	-
Endosulfan	1.5	-	-	-
Endrin	0.48	-	-	-
Heptachlor	1.5	-	-	-
Heptachlor Epoxide	0.048	-	-	-
Hexachlorobenzene	1	-	-	-
Hexachlorobutadiene	0.44	-	-	-
Hexachlorocyclohexane Gamma-	1.2	-	-	-
Hexachloroethane	2.1	-	-	-
Methoxychlor	6.5	-	-	-

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14C Summary of Maximum Concentrations in Soil

Group	Parameter	Table 2 RPI CT	Maximum Concentration	Location
BTEX	Benzene	0.21	0.006	BH21-41 S1
	Ethylbenzene	1.1	0.01	BH21-41 S1
	Toluene	2.3	<0.05	all samples
	Total Xylenes	3.1	0.22	BH21-41 S1
Metals	Barium	390	147	BH21-30 SS2
	Beryllium	4	1.4	BH21-10 S1
	Boron	120	21	BH21-35 S1
	Cadmium	1.2	<0.5	all samples
	Chromium	160	32	BH21-30 SS2
	Cobalt	22	16.3	BH21-28 SS1
	Copper	140	64.7	BH21-10 S1
	Lead	120	205	BH21-36 SS1
	Molybdenum	6.9	11	BH21-10 S1
	Nickel	100	33	BH21-30 SS2
	Silver	20	<0.5	all samples
	Thallium	1	0.6	BH21-10 S1
	Uranium	23	0.73	BH21-10 S1
	Vanadium	86	42.7	BH21-30 SS2
	Zinc	340	179	BH21-36 SS1
As, Se, Sb	Antimony	7.5	3.5	BH21-10 S1
	Arsenic	18	26	BH21-41 S2
	Selenium	2.4	2.1	BH21-10 S1
PAHs	Acenaphthene	7.9	<0.05	all samples
	Acenaphthylene	0.15	0.14	BH21-40 S1
	Anthracene	0.67	0.27	BH21-40 S1
	Benz(a)anthracene	0.5	1.13	BH21-40 S1
	Benzo(a)pyrene	0.3	0.86	BH21-40 S1
	Benzo(b)fluoranthene	0.78	1.61	BH21-40 S1
	Benzo(g,h,i)perylene	6.6	0.55	BH21-40 S1
	Benzo(k)fluoranthene	0.78	0.63	BH21-40 S1
	Chrysene	7	1.25	BH21-40 S1
	Dibenz(a,h)anthracene	0.1	0.13	BH21-40 S1
	Fluoranthene	0.69	2.11	BH21-40 S1
	Fluorene	62	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.38	0.48	BH21-40 S1
	Methylnaphthalene, 2-(1-)	0.99	0.82	BH21-40 S1
	Naphthalene	0.6	0.31	BH21-40 S1
	Phenanthrene	6.2	0.78	BH21-40 S1
	Pyrene	78	1.94	BH21-40 S1
PHCs	F1 (C6 to C10) minus BTEX	55	10	BH21-41 S1
	F2 (C10 to C16)	98	13	BH21-31 S2
	F3 (C16 to C34)	300	75	BH21-41 S1
	F4 (C34 to C50)	2800	<50	all samples
	Acetone	16	<0.50	all samples
	Bromodichloromethane	1.5	<0.05	all samples
	Bromoform	0.27	<0.05	all samples
	Bromomethane	0.05	<0.05	all samples
	Carbon Tetrachloride	0.05	<0.05	all samples
	Chlorobenzene	2.4	<0.05	all samples
	Chloroform	0.05	<0.04	all samples
	Dibromochloromethane	2.3	<0.05	all samples
	Dichlorobenzene, 1,2-	1.2	<0.05	all samples

Table 14C Summary of Maximum Concentrations in Soil

Group	Parameter	Table 2 RPI CT	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	4.8	<0.05	all samples
	Dichlorobenzene, 1,4-	0.083	<0.05	all samples
	Dichlorodifluoromethane	16	<0.05	all samples
	Dichloroethane, 1,1-	0.47	<0.02	all samples
	Dichloroethane, 1,2-	0.05	<0.03	all samples
	Dichloroethylene, 1,1-	0.05	<0.05	all samples
	Dichloroethylene, Cis- 1,2-	1.9	<0.02	all samples
	Dichloroethylene, Trans- 1,2-	0.084	<0.05	all samples
	Dichloropropane, 1,2-	0.05	<0.03	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	all samples
	Ethylene Dibromide	0.05	<0.04	all samples
	Hexane, n-	2.8	<0.05	all samples
	Methyl Ethyl Ketone	16	<0.50	all samples
	Methyl Isobutyl Ketone	1.7	<0.50	all samples
	Methyl tert-butyl Ether	0.75	<0.05	all samples
	Methylene Chloride	0.1	<0.05	all samples
	Styrene	0.7	<0.05	all samples
	Tetrachloroethane, 1,1,1,2-	0.058	<0.04	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.05	all samples
	Tetrachloroethylene	0.28	<0.05	all samples
	Trichloroethane, 1,1,1-	0.38	<0.05	all samples
	Trichloroethane, 1,1,2-	0.05	<0.04	all samples
	Trichloroethylene	0.061	<0.03	all samples
	Trichlorofluoromethane	4	<0.05	all samples
	Vinyl Chloride	0.02	<0.02	all samples
ORPs	Chromium, Hexavalent	8	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.7	0.342	BH21-28 SS1
	Mercury	0.27	0.32	BH21-32 SS1
	Sodium Adsorption Ratio	5	0.758	BH21-39 S1
	pH, 2:1 CaCl2 Extraction	*	7.91	QAQC-2
PCBs	Polychlorinated Biphenyls	0.35	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15C Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 2 Potable GW CT	Maximum Concentration	Location
BTEX	Benzene	5	<0.20	all samples
	Ethylbenzene	2.4	<0.10	all samples
	Toluene	24	<0.20	all samples
	Xylene Mixture	300	<0.10	all samples
Metals	Barium	1000	189	BH21-25
	Beryllium	4	<0.50	all samples
	Boron	5000	222	BH21-28
	Cadmium	2.7	<0.20	all samples
	Chromium	50	<2.0	all samples
	Cobalt	3.8	2.06	all samples
	Copper	87	1.3	all samples
	Lead	10	0.53	BH21-13
	Molybdenum	70	5.47	BH21-25
	Nickel	100	3.9	BH21-25
	Silver	1.5	<0.20	all samples
	Thallium	2	<0.30	all samples
	Uranium	20	5.02	BH21-25
	Vanadium	6.2	<0.40	all samples
	Zinc	1100	<5.0	all samples
As, Se, Sb	Antimony	6	<1.0	all samples
	Arsenic	25	5.7	BH21-28
	Selenium	10	1.7	all samples
Na	Sodium	490000	349000	BH21-13
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	2.4	<0.10	all samples
	Benz(a)anthracene	1	<0.20	all samples
	Benzo(a)pyrene	0.01	<0.01	all samples
	Benzo(b)fluoranthene	0.1	<0.10	all samples
	Benzo(g,h,i)perylene	0.2	<0.20	all samples
	Benzo(k)fluoranthene	0.1	<0.10	all samples
	Chrysene	0.1	<0.10	all samples
	Dibenz(a,h)anthracene	0.2	<0.20	all samples
	Fluoranthene	0.41	<0.20	all samples
	Fluorene	120	<0.20	all samples
	Indeno(1,2,3-cd)pyrene	0.2	<0.20	all samples
	Methyl Naphthalene, 2-and 1-	3.2	<0.20	all samples
	Naphthalene	11	<0.20	all samples
	Phenanthrene	1	<0.10	all samples
	Pyrene	4.1	<0.20	all samples
PHCs	F1 (C6 to C10) minus BTEX	750	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	16	<0.20	all samples
	Bromoform	25	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.79	<0.20	all samples
	Chlorobenzene	30	<0.10	all samples
	Chloroform	2.4	<0.20	all samples
	Dibromochloromethane	25	<0.10	all samples

Table 15C Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 2 Potable GW CT	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,2-	3	<0.10	all samples
	Dichlorobenzene, 1,3-	59	<0.10	all samples
	Dichlorobenzene, 1,4-	1	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	5	<0.30	all samples
	Dichloroethane, 1,2-	1.6	<0.20	all samples
	Dichloroethylene, 1,1-	1.6	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	51	<0.20	all samples
	Methyl Ethyl Ketone	1800	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	50	<0.30	all samples
	Styrene	5.4	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	1	<0.10	all samples
	Tetrachloroethylene	1.6	<0.20	all samples
	Trichloroethane, 1,1,1-	200	<0.30	all samples
	Trichloroethane, 1,1,2-	4.7	<0.20	all samples
	Trichloroethylene	1.6	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	557000	BH21-13
	Chromium VI	25	<2.0	all samples
	Cyanide	66	<2.0	all samples
	Mercury	0.29	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Notes for Soil & Groundwater Summary Tables - Caledon (C-series)

1. mbgs = metres below ground surface
2. ORPs = other regulated parameters
3. PHCs = petroleum hydrocarbons
4. VOCs = volatile organic compounds
5. PAHs = polycyclic aromatic hydrocarbons
7. APEC = area of potential environmental concern
6. - = parameter not analyzed
7. * = pH criteria for surface soils (0 - 1.5 mbgs) is 5 to 9, for subsurface soil (below 1.5 mbgs) is 5 to 11
8. Units for all soil analyses are in µg/g (ppm) unless otherwise indicated
9. Units for all groundwater analyses are in µg/L (ppb) unless otherwise indicated
10. Table 8 RPIICC = Generic Site Condition Standards for Use within 30 m of a Water Body in a Potable Groundwater Condition as contained in Table 8 of the Soil, Ground Water and Sediment Standards for Use Under Part XV.1 of the Environmental Protection Act, published by the MECP on April 15, 2011
11. For soil and groundwater analytical results: **bold** = Concentration exceeds the 2011 MECP Table 8 SCS

Table 1C Monitoring Well Installation and Groundwater Levels

Monitoring Well ID			BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-30	BH21-32	BH21-36
Installed By			WSP	WSP	WSP	WSP	WSP	WSP	WSP	WSP
Installation Date			4-Nov-21	4-Nov-21	15-Nov-21	16-Nov-21	8-Nov-21	8-Nov-21	15-Nov-21	16-Nov-21
Well Status			Active	Active	Active	Active	Active	Active	Active	Active
Well Inner Diameter		(mm)	50	50	50	50	50	50	50	50
Casing Type (Flushmount / Monument)			Monument	Monument	Monument	Monument	Monument	Flushmount	Monument	Monument
Top of Pipe Elevation		(masl)	423.843	397.847	404.757	255.396	282.313	286.873	274.654	326.921
Ground Surface Elevation		(masl)	422.953	396.937	403.897	256.306	281.403	286.973	273.744	326.001
Bottom of Concrete Seal/Top of Bentonite Seal		(mbgs)	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
		(masl)	422.653	396.637	403.597	256.006	281.103	286.673	273.444	325.701
Bottom of Bentonite Seal/Top of Sand Pack		(mbgs)	1.3	4.9	3.1	4.0	5.5	5.5	2.4	4.0
		(masl)	421.7	392.0	400.8	252.3	275.9	281.5	271.4	322.0
Top of Well Screen		(mbgs)	1.9	5.5	3.7	4.6	6.1	6.1	3.0	4.6
		(masl)	421.1	391.4	400.2	251.7	275.3	280.9	270.7	321.4
Screen Length		(m)	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0
Bottom of Screen		(mbgs)	4.9	8.5	6.7	7.6	9.1	9.1	6.0	7.6
		(masl)	418.1	388.4	397.2	248.7	272.3	277.9	267.7	318.4
22-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	DRY	6.5
	GW Elevation	(masl)	-	-	-	-	-	-	-	319.5
23-Nov-21	Depth of GW	(mbgs)	-	-	-	-	-	-	DRY	6.6
	GW Elevation	(masl)	-	-	-	-	-	-	-	319.4
29-Nov-21	Depth of GW	(mbgs)	-	-	-	-	0.6	2.2	-	-
	GW Elevation	(masl)	-	-	-	-	280.8	284.8	-	-
30-Nov-21	Depth of GW	(mbgs)	-	-	-	2.2	-	-	-	-
	GW Elevation	(masl)	-	-	-	254.1	-	-	-	-
1-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
2-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
6-Dec-21	Depth of GW	(mbgs)	-	-	-	-	-	-	-	-
	GW Elevation	(masl)	-	-	-	-	-	-	-	-
7-Dec-21	Depth of GW	(mbgs)	2.0	4.3	5.1	2.2	0.0	2.3	DRY	6.6
	GW Elevation	(masl)	421.0	392.6	398.8	254.1	281.7	284.7	-	319.4

See "Notes for Soil and Groundwater Summary

Table 2C Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-9	SS1	0.0 - 0.6	4-Nov-21	-	-	-	-	✓	✓	3, 13, 14, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS4	2.3 - 2.9		-	-	-	✓	-	-	
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
BH21-10	S1	0.0 - 0.6	27-Oct-21	✓	-	-	-	-	-	13, 14, 38, 105, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	✓	-	✓	-	-	
BH21-11	SS1	0.0 - 0.6	4-Nov-21	✓	-	-	-	-	-	13, 14, 38, 114
	SS2	0.8 - 1.4		-	-	-	✓	✓	✓	
	SS5	3.0 - 3.7		-	✓	-	-	-	-	
BH21-13	SS1	0.0 - 0.6	15-Nov-21	-	-	-	✓	-	-	13, 14, 38, 112, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS5	3.0 - 3.7		-	✓	✓	-	-	-	
BH21-14	S1	0.0 - 0.6	27-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 96, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-15	S2	0.6 - 1.2	27-Oct-21	-	-	-	✓	✓	✓	13, 14, 38, 93, 114
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-25	SS1	0.0 - 0.6	16-Nov-21	-	-	-	✓	-	-	13, 14, 38, 108, 114
	SS2	0.8 - 1.4		✓	-	-	-	-		
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-26	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 60, 114
	S2	0.6 - 1.2		-	-	-	✓	-	-	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-27	S1	0.0 - 0.6	28-Oct-21	✓	-	-	-	-	-	13, 14, 38, 63, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-28	SS1	0.0 - 0.6	8-Nov-21	✓	-	-	-	-	-	1, 13, 14, 38, 114
	QAQC-3			✓	-	-	-	-	-	
	SS2	0.8 - 1.4		-	✓	-	-	-	-	
	QAQC-4			-	✓	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	✓	✓	
	QAQC-5			-	-	-	✓	✓	✓	
BH21-29	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 66, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-30	SS1	0.0 - 0.6	8-Nov-21	-	-	-	✓	✓	✓	13, 14, 33, 38, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	✓	-	-	-	-	
BH21-31	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 69, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	✓	-	✓	-	-	
BH21-32	SS1	0.0 - 0.6	15-Nov-21	✓	-	-	-	-	-	13, 14, 38, 109, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS4	2.3 - 2.9		-	✓	✓	-	-	-	
BH21-33	S1	0.0 - 0.6	28-Oct-21	-	-	-	✓	-	-	13, 14, 38, 72, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-34	S1	0.0 - 0.6	28-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 75, 114
	QAQC-1			-	-	-	-	✓	✓	
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	QAQC-S2			✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
	QAQC-S3			-	-	-	✓	-	-	

Table 2C Summary of Soil Samples Submitted for Chemical Analysis

Borehole	Sample	Depth	Date	Parameters						APEC #
				M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-35	S1	0.0 - 0.6	27-Oct-21	✓	-	-	-	-	-	13, 14, 38, 78, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-36	SS1	0.0 - 0.6	16-Nov-21	✓	-	-	-	-	-	13, 14, 38, 110, 114
	SS2	0.8 - 1.4		✓	-	-	-	-	-	
	SS3	1.5 - 2.1		-	-	-	✓	-	-	
	SS6	4.6 - 5.2		-	✓	✓	-	-	-	
BH21-37	S1	0.0 - 0.6	27-Oct-21	-	-	-	-	✓	✓	13, 14, 38, 81, 114
	S2	0.6 - 1.2		✓	-	-	-	-	-	
	S3	1.2 - 1.8		-	-	-	✓	-	-	
BH21-38	S1	0.0 - 0.6	27-Oct-21	-	-	-	✓	-	-	13, 14, 38, 84, 114
	S2	0.6 - 1.2		-	-	-	-	✓	✓	
	S3	1.2 - 1.8		✓	-	-	-	-	-	
BH21-39	S1	0.0 - 0.6	5-Nov-21	✓	-	-	-	-	-	13, 14, 38, 111, 114
	S3	1.2 - 1.8		-	-	-	✓	✓	✓	
BH21-40	S1	0.0 - 0.6	27-Oct-21	-	-	-	✓	✓	✓	13, 14, 38, 87, 114
	S3	1.2 - 1.8		✓	-	-	✓	-	-	
BH21-41	S1	0.0 - 0.6	5-Nov-21	-	-	-	✓	-	-	13, 14, 38, 90, 114
	S2	0.6 - 1.2		✓	✓	-	-	✓	✓	

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 3C: Summary of Groundwater Samples Submitted for Chemical Analysis

Monitoring Well ID	Screened Interval (mbgs)	Date	Parameters						APEC #
			M&ORP	PHCs	VOCs	PAHs	PCBs	OCPs	
BH21-9	1.9 - 4.9	30-Nov-21	✓	✓	✓	✓	✓	-	3, 13, 14, 38, 114
BH21-11	5.5 - 8.5	30-Nov-21	✓	✓	-	✓	✓	-	13, 14, 38, 114
BH21-13	3.7 - 6.7	30-Nov-21	✓	✓	✓	✓	-	-	13, 14, 38, 112, 114
BH21-25	4.6 - 7.6	1-Dec-21	✓	✓	✓	✓	-	-	13, 14, 38, 108, 114
BH21-28	6.1 - 9.1	1-Dec-21	✓	✓	✓	✓	✓	-	1, 13, 14, 38, 114
BH21-30	6.1 - 9.1	1-Dec-21	-	✓	-	-	-	-	13, 14, 33, 38, 114
BH21-36	4.6 - 7.6	23-Nov-21	✓	✓	✓	✓	-	-	13, 14, 38, 110, 114

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-9 SS2	BH21-10 S1	BH21-10 S3	BH21-11 SS1	BH21-13 SS2	BH21-14 S2	BH21-15 S3
Date of Collection	Table 8 RPIICC	Nov 04, 2021	Oct 27, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Oct 27, 2021
Date Reported		Nov 16, 2021	Nov 08, 2021	Dec 20, 2021	Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (mbgs)		0.8 - 1.4	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6	0.8 - 1.4	0.6 - 1.2	1.2 - 1.8
Analytical Report Reference No.		21T826519	21T822752		21T826519	21T830287	21T822752	21T822752
Antimony	1.3	<0.8	**3.5**	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	3	**24**	8	2	2	3	4
Barium	220	25.4	44.5	27	10.1	10.6	49.6	26.5
Beryllium	2.5	<0.4	1.4	<0.4	<0.4	<0.4	<0.4	<0.4
Boron	36	<5	12	8	<5	<5	<5	<5
Boron (Hot Water Extractable)	1.5	0.18	0.37	0.21	<0.10	<0.10	0.13	<0.10
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	12	15	10	<5	5	14	7
Cobalt	22	4.6	9.3	5.2	1.9	1.7	4.6	3.3
Copper	92	8	64.7	23.7	9	3.4	8.6	17
Lead	120	7	52	15	2	3	8	5
Molybdenum	2	<0.5	**11**	1	<0.5	<0.5	<0.5	<0.5
Nickel	82	9	29	7	2	3	9	5
Selenium	1.5	<0.8	**2.1**	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	0.6	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	<0.50	0.7	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	24.7	26.7	15.3	10.4	10.9	26.6	14.4
Zinc	290	28	70	54	18	13	46	22
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	0.11	<0.10
Electrical Conductivity (2:1)	0.7	0.096	0.255	0.210	0.061	0.078	0.103	0.073
Sodium Adsorption Ratio	5	0.07	0.061	0.295	0.055	0.205	0.043	0.061
pH, 2:1 CaCl2 Extraction	*	7.29	7.24	7.39	7.82	7.77	7.27	7.80

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-25 SS2	BH21-26 S3	BH21-27 S1	BH21-28 SS1	QAQC-3	BH21-29 S2	BH21-30 SS2	BH21-31 S1
Date of Collection	Table 8 RPIICC	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021
Date Reported		Nov 26, 2021	Nov 08, 2021	Nov 08, 2021	Nov 20, 2021		Nov 08, 2021	Nov 20, 2021	Nov 16, 2021
Sampling Depth (mbgs)		0.8 - 1.4	1.2 - 1.8	0.0 - 0.6	0.0 - 0.6		0.6 - 1.2	0.8 - 1.4	0.0 - 0.6
Analytical Report Reference No.		21T830891	21T822752	21T822752	21T827359		21T822752	21T827359	21T826519
Antimony	1.3	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	18	8	4	12	10	10	5	6	8
Barium	220	85.3	47.6	54.2	73.4	65.4	99	147	58.8
Beryllium	2.5	0.5	<0.4	0.5	0.8	0.7	0.7	1.4	0.5
Boron	36	<5	5	6	12	10	9	12	7
Boron (Hot Water Extractable)	1.5	0.35	<0.10	0.26	0.44	0.47	0.13	<0.10	0.12
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	23	16	19	23	21	26	32	17
Cobalt	22	12.6	9.4	6.8	16.3	6.8	11.1	14.1	10.0
Copper	92	35.5	37.1	24.7	40.9	31.3	26.1	28.4	28.5
Lead	120	12	7	15	29	26	9	12	9
Molybdenum	2	<0.5	<0.5	<0.5	0.7	0.6	<0.5	<0.5	<0.5
Nickel	82	26	18	15	31	17	24	33	21
Selenium	1.5	<0.8	<0.8	<0.8	0.9	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	0.5	<0.50	<0.50	0.6	<0.50	<0.50	0.6	<0.50
Vanadium	86	32.8	23	28.1	30.2	27.3	36.5	42.7	24.8
Zinc	290	70	47	58	92	81	57	71	51
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.174	0.106	0.192	0.342	0.336	0.129	0.165	0.107
Sodium Adsorption Ratio	5	0.267	0.084	0.103	0.396	0.393	0.105	0.458	0.060
pH, 2:1 CaCl2 Extraction	*	7.50	7.79	7.70	7.28	7.60	7.71	7.25	7.60

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-32 SS1	BH21-32 SS2	BH21-33 S3	BH21-34 S2	QAQC-2	BH21-35 S1	BH21-36 SS1	BH21-36 SS1
Date of Collection	Table 8 RPIICC	Nov 15, 2021	Nov 15, 2021	Oct 28, 2021	Oct 28, 2021		Oct 27, 2021	Nov 16, 2021	Nov 16, 2021
Date Reported		Nov 27, 2021	Dec 20, 2021	Nov 08, 2021	Nov 08, 2021		Nov 08, 2021	Nov 26, 2021	Dec 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	0.8 - 1.4	1.2 - 1.8	0.6 - 1.2		0.0 - 0.6	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T830287	21T839249	21T822752	21T822752		21T822752	21T830891	21T839249
Antimony	1.3	**1.9**	<0.8	<0.8	<0.8	<0.8	<0.8	1.1	<0.8
Arsenic	18	6	2	5	4	3	13	11	4
Barium	220	43.1	35.6	99.2	58.5	57	53.8	103	26.3
Beryllium	2.5	<0.4	<0.4	0.6	0.4	0.4	0.5	<0.4	<0.4
Boron	36	9	<5	9	10	11	21	6	7
Boron (Hot Water Extractable)	1.5	0.40	0.16	<0.10	<0.10	<0.10	0.35	0.23	0.15
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	12	11	23	17	16	12	12	11
Cobalt	22	5.8	4.5	11.9	7.4	7.4	10.2	5.1	5.4
Copper	92	48.3	16.7	25.3	17.4	17	44.3	53.7	26.2
Lead	120	65	9	9	5	5	13	**205**	13
Molybdenum	2	1.4	<0.5	<0.5	<0.5	<0.5	1.1	1.2	<0.5
Nickel	82	21	9	24	14	13	19	11	9
Selenium	1.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	17.7	20.5	33.6	26.5	25.2	15.4	18.7	21.4
Zinc	290	67	34	52	38	36	63	179	39
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	**0.32**	<0.10	<0.10	<0.10	<0.10	<0.10	0.23	<0.10
Electrical Conductivity (2:1)	0.7	0.184	0.134	0.115	0.108	0.101	0.217	0.156	0.115
Sodium Adsorption Ratio	5	0.193	0.199	0.155	0.072	0.070	0.095	0.076	0.139
pH, 2:1 CaCl2 Extraction	*	7.60	7.15	7.80	7.87	7.91	7.87	7.70	7.08

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 4C Soil Analytical Results - Metals & ORPs

Parameter		BH21-37 S2	BH21-38 S3	BH21-39 S1	BH21-40 S3	BH21-41 S2
Date of Collection	Table 8 RPIICC	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (mbgs)		0.6 - 1.2	1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.6 - 1.2
Analytical Report Reference No.		21T822752	21T822752	21T826519	21T822752	21T826519
Antimony	1.3	1	<0.8	<0.8	<0.8	<0.8
Arsenic	18	12	3	6	6	**26**
Barium	220	41.3	16.9	40.7	29.6	18.3
Beryllium	2.5	<0.4	<0.4	0.4	<0.4	<0.4
Boron	36	7	<5	15	7	10
Boron (Hot Water Extractable)	1.5	0.18	<0.10	0.36	0.20	0.13
Cadmium	1.2	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	70	11	6	14	11	23
Cobalt	22	5.4	2.5	6.3	4.5	8.3
Copper	92	25.1	9	12.3	27.2	24
Lead	120	18	4	7	20	52
Molybdenum	2	0.9	<0.5	<0.5	0.9	**2.1**
Nickel	82	11	4	13	10	8
Selenium	1.5	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	1	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	2.5	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	86	19.1	9.4	21.3	19.3	25.2
Zinc	290	33	14	48	33	121
Chromium, Hexavalent	0.66	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	0.051	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	0.27	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	0.7	0.136	0.082	0.210	0.328	0.152
Sodium Adsorption Ratio	5	0.036	0.051	0.758	0.025	0.121
pH, 2:1 CaCl2 Extraction	*	7.46	7.66	7.49	7.62	7.69

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-9 SS5	BH21-10 S3	BH21-11 SS5	BH21-13 SS5	BH21-14 S3	BH21-25 SS6	BH21-26 S3	BH21-27 S3
Date of Collection	Table 8 RPIICC	Nov 04, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021
Date Reported		Nov 16, 2021	Nov 30, 2021	Nov 16, 2021	Nov 27, 2021	Nov 30, 2021	Nov 26, 2021	Nov 30, 2021	Nov 30, 2021
Sampling Depth (mbgs)		3.0 - 3.7	1.2 - 1.8	3.0 - 3.7	3.0 - 3.7	1.2 - 1.8	4.6 - 5.2	1.2 - 1.8	1.2 - 1.8
Analytical Report Reference No.		21T826519	21T832162	21T826519	21T830287	21T832162	21T830891	21T832162	21T832162
Benzene	0.02	<0.02	<0.005	<0.02	<0.02	<0.005	<0.02	<0.005	<0.005
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.01	<0.05	<0.05	<0.01	<0.05	<0.01	<0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<5	<10	<5	<5	<10	<5	<10	<10
F2 (C10 to C16)	10	<10	<10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	<50	42	<50	<50	14	<50	<10	<10
F4 (C34 to C50)	120	<50	<10	<50	<50	<10	<50	<10	<10

See "Notes for Soil and Groundwater Summary

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-28 SS2	QAQC-4	BH21-29 S3	BH21-30 SS3	BH21-31 S2	BH21-31 S3	BH21-32 SS4	BH21-33 S2
Date of Collection	Table 8 RPIICC	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021	Nov 05, 2021	Nov 15, 2021	Oct 28, 2021
Date Reported		Nov 20, 2021		Nov 30, 2021	Nov 20, 2021	Nov 08, 2021	Dec 20, 2021	Nov 27, 2021	Nov 30, 2021
Sampling Depth (mbgs)		0.8 - 1.4		1.2 - 1.8	1.5 - 2.1	0.6 - 1.2	1.2 - 1.8	2.3 - 2.9	0.6 - 1.2
Analytical Report Reference No.		21T827359		21T832162	21T827359	21T832162	21T839249	21T830287	21T832162
Benzene	0.02	<0.02	<0.02	<0.005	<0.02	<0.005	<0.02	<0.02	<0.005
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.05	<0.01	<0.05	<0.01	<0.05	<0.05	<0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
F1 (C6 to C10) minus BTEX	25	<5	<5	<10	<5	<10	8	<5	<10
F2 (C10 to C16)	10	<10	<10	<10	<10	13	<10	<10	<10
F3 (C16 to C34)	240	<50	<50	17	<50	39	<50	<50	24
F4 (C34 to C50)	120	<50	<50	<10	<50	<10	<50	<50	<10

See "Notes for Soil and Groundwater Summary

Table 5C Soil Analytical Results - PHCs & BTEX

Parameter		BH21-34 S3	BH21-35 S2	BH21-36 SS6	BH21-37 S3	BH21-39 S3	BH21-41 S1
Date of Collection	Table 8 RPIICC	Oct 28, 2021	Nov 05, 2021	Nov 16, 2021	Oct 28, 2021	Nov 05, 2021	Nov 05, 2021
Date Reported		Nov 30, 2021	Nov 30, 2021	Nov 26, 2021	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021
Sampling Depth (mbgs)		1.2 - 1.8	0.6 - 1.2	4.6 - 5.2	1.2 - 1.8	1.2 - 1.8	0.0 - 0.6
Analytical Report Reference No.		21T832162	21T832162	21T830891	21T832162	21T832162	21T832162
Benzene	0.02	<0.005	<0.005	<0.02	<0.005	<0.005	0.006
Toluene	0.2	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.01	<0.01	<0.05	<0.01	<0.01	0.01
Total Xylenes	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	**0.22**
F1 (C6 to C10) minus BTEX	25	<10	<10	<5	<10	<10	10
F2 (C10 to C16)	10	<10	<10	<10	<10	<10	<10
F3 (C16 to C34)	240	11	21	<50	15	24	75
F4 (C34 to C50)	120	<10	<10	<50	<10	<10	<10

See "Notes for Soil and Groundwater Summary

Table 6C Soil Analytical Results - VOCs

Parameter		BH21-13 SS5	BH21-25 SS6	BH21-32 SS4	BH21-36 SS6
Date of Collection	Table 8 RPIICC	Nov 15, 2021	Nov 16, 2021	Nov 15, 2021	Nov 16, 2021
Date Reported		Nov 27, 2021	Nov 26, 2021	Nov 27, 2021	Nov 26, 2021
Sampling Depth (mbgs)		3.0 - 3.7	4.6 - 5.2	2.3 - 2.9	4.6 - 5.2
Analytical Report Reference No.		21T830287	21T830891	21T830287	21T830891
Acetone	0.5	<0.50	<0.50	<0.50	<0.50
Benzene	0.02	<0.02	<0.02	<0.02	<0.02
Bromodichloromethane	0.05	<0.05	<0.05	<0.05	<0.05
Bromoform	0.05	<0.05	<0.05	<0.05	<0.05
Bromomethane	0.05	<0.05	<0.05	<0.05	<0.05
Carbon Tetrachloride	0.05	<0.05	<0.05	<0.05	<0.05
Chlorobenzene	0.05	<0.05	<0.05	<0.05	<0.05
Chloroform	0.05	<0.04	<0.04	<0.04	<0.04
Dibromochloromethane	0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,2-	0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,3-	0.05	<0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,4-	0.05	<0.05	<0.05	<0.05	<0.05
Dichlorodifluoromethane	0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethane, 1,1-	0.05	<0.02	<0.02	<0.02	<0.02
Dichloroethane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03
Dichloroethylene, 1,1-	0.05	<0.05	<0.05	<0.05	<0.05
Dichloroethylene, Cis- 1,2-	0.05	<0.02	<0.02	<0.02	<0.02
Dichloroethylene, Trans- 1,2-	0.05	<0.05	<0.05	<0.05	<0.05
Dichloropropane, 1,2-	0.05	<0.03	<0.03	<0.03	<0.03
1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	0.05	<0.05	<0.05	<0.05	<0.05
Ethylene Dibromide	0.05	<0.04	<0.04	<0.04	<0.04
Hexane, n-	0.05	<0.05	<0.05	<0.05	<0.05
Methyl Ethyl Ketone	0.5	<0.50	<0.50	<0.50	<0.50
Methyl Isobutyl Ketone	0.5	<0.50	<0.50	<0.50	<0.50
Methyl tert-butyl Ether	0.05	<0.05	<0.05	<0.05	<0.05
Methylene Chloride	0.05	<0.05	<0.05	<0.05	<0.05
Styrene	0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04
Tetrachloroethane, 1,1,2,2-	0.05	<0.05	<0.05	<0.05	<0.05
Tetrachloroethylene	0.05	<0.05	<0.05	<0.05	<0.05
Toluene	0.2	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,1-	0.05	<0.05	<0.05	<0.05	<0.05
Trichloroethane, 1,1,2-	0.05	<0.04	<0.04	<0.04	<0.04
Trichloroethylene	0.05	<0.03	<0.03	<0.03	<0.03
Trichlorofluoromethane	0.25	<0.05	<0.05	<0.05	<0.05
Vinyl Chloride	0.02	<0.02	<0.02	<0.02	<0.02
Xylene mixture	0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-9 SS3	BH21-9 SS4	BH21-10 S3	BH21-11 SS2	BH21-13 SS1	BH21-14 S3	BH21-15 S2
Date of Collection	Table 8 RPIICC	Nov 05, 2021	Nov 05, 2021	Oct 27, 2021	Nov 04, 2021	Nov 15, 2021	Oct 27, 2021	Oct 27, 2021
Date Reported		Nov 16, 2021	Dec 20, 2021	Nov 08, 2021	Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (mbgs)		1.5 - 2.1	2.3 - 2.9	1.2 - 1.8	0.8 - 1.4	0.0 - 0.6	1.2 - 1.8	0.6 - 1.2
Analytical Report Reference No.		21T826519	21T839249	21T822752	21T826519	21T830287	21T822752	21T822752
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	0.1	0.22	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.22	0.18	0.07	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.69	0.19	0.44	<0.05	<0.05	<0.05	<0.05	<0.05
Pyrene	1	0.18	0.41	<0.05	<0.05	<0.05	<0.05	<0.05
Benz(a)anthracene	0.36	<0.05	0.2	<0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	2.8	<0.05	0.12	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	0.47	0.05	0.18	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	0.48	0.06	0.09	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	0.16	<0.05	<0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	0.07	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	0.08	<0.05	<0.05	<0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-25 SS1	BH21-26 S1	BH21-27 S2	BH21-28 SS3	QAQC-5	BH21-29 S1	BH21-30 SS1
Date of Collection	Table 8 RPIICC	Nov 16, 2021	Oct 28, 2021	Oct 28, 2021	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021
Date Reported		Nov 26, 2021	Nov 08, 2021	Nov 08, 2021	Nov 20, 2021		Nov 08, 2021	Nov 20, 2021
Sampling Depth (mbgs)		0.0 - 0.6	0.0 - 0.6	0.6 - 1.2	1.5 - 2.1		0.0 - 0.6	0.0 - 0.6
Analytical Report Reference No.		21T830891	21T822752	21T822752	21T827359		21T822752	21T827359
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.22	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Pyrene	1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-31 S3	BH21-32 SS3	BH21-33 S1	BH21-34 S3	QAQC-3	BH21-35 S3	BH21-36 SS3
Date of Collection	Table 8 RPIICC	Nov 05, 2021	Nov 15, 2021	Oct 28, 2021	Oct 28, 2021		Oct 27, 2021	Nov 16, 2021
Date Reported		Nov 16, 2021	Nov 27, 2021	Nov 08, 2021	Nov 08, 2021		Nov 08, 2021	Nov 26, 2021
Sampling Depth (mbgs)		1.2 - 1.8	1.5 - 2.1	0.0 - 0.6	1.2 - 1.8		1.2 - 1.8	1.5 - 2.1
Analytical Report Reference No.		21T826519	21T830287	21T822752	21T822752		21T822752	21T830891
Naphthalene	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	0.093	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	0.22	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	0.69	<0.05	<0.05	<0.05	<0.05	<0.05	0.25	<0.05
Pyrene	1	<0.05	<0.05	<0.05	<0.05	<0.05	0.18	<0.05
Benz(a)anthracene	0.36	<0.05	<0.05	<0.05	<0.05	<0.05	0.08	<0.05
Chrysene	2.8	<0.05	<0.05	<0.05	<0.05	<0.05	0.14	<0.05
Benzo(b)fluoranthene	0.47	<0.05	<0.05	<0.05	<0.05	<0.05	0.19	<0.05
Benzo(k)fluoranthene	0.48	<0.05	<0.05	<0.05	<0.05	<0.05	0.17	<0.05
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	<0.05	<0.05	<0.05	<0.05	0.06	<0.05
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05

See "Notes for Soil and Groundwater Summary

Table 7C Soil Analytical Results - PAHs

Parameter		BH21-37 S3	BH21-38 S1	BH21-39 S3	BH21-40 S1	BH21-40 S3	BH21-41 S1
Date of Collection	Table 8 RPIICC	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Dec 20, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (mbgs)		1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6	1.2 - 1.8	0.0 - 0.6
Analytical Report Reference No.		21T822752	21T822752	21T826519	21T839249	21T822752	21T826519
Naphthalene	0.09	<0.05	0.07	<0.05	**0.31**	**0.1**	0.08
Acenaphthylene	0.093	<0.05	<0.05	<0.05	**0.14**	0.06	0.08
Acenaphthene	0.072	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	0.69	<0.05	0.07	<0.05	**0.78**	0.19	0.08
Anthracene	0.22	<0.05	0.05	<0.05	**0.27**	0.12	0.06
Fluoranthene	0.69	<0.05	0.14	<0.05	**2.11**	0.47	0.38
Pyrene	1	<0.05	0.12	<0.05	**1.94**	0.37	0.36
Benz(a)anthracene	0.36	<0.05	0.07	<0.05	**1.13**	0.19	0.18
Chrysene	2.8	<0.05	0.11	<0.05	1.25	0.16	0.14
Benzo(b)fluoranthene	0.47	<0.05	0.21	<0.05	**1.61**	**0.53**	0.25
Benzo(k)fluoranthene	0.48	<0.05	0.23	<0.05	**0.63**	**0.5**	0.24
Benzo(a)pyrene	0.3	<0.05	<0.05	<0.05	**0.86**	0.09	<0.05
Indeno(1,2,3-cd)pyrene	0.23	<0.05	0.09	<0.05	**0.48**	0.2	0.08
Dibenz(a,h)anthracene	0.1	<0.05	<0.05	<0.05	**0.13**	0.05	<0.05
Benzo(g,h,i)perylene	0.68	<0.05	0.13	<0.05	0.55	0.2	0.08
Methylnaphthalene, 2-(1-)	0.59	<0.05	<0.05	<0.05	**0.82**	0.32	0.18

See "Notes for Soil and Groundwater Summary

Table 8C Soil Analytical Results - PCBs and OC Pesticides

Parameter		BH21-9 SS1	BH21-10 S2	BH21-11 SS2	BH21-14 S1	BH21-15 S2	BH21-26 S1	BH21-27 S2
Date of Collection	Table 8 RPIICC	Nov 05, 2021	Oct 27, 2021	Nov 04, 2021	Oct 27, 2021	Oct 27, 2021	Oct 28, 2021	Oct 28, 2021
Date Reported		Nov 16, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 08, 2021	Nov 08, 2021	Nov 08, 2021
Sampling Depth (m bgs)		0.0 - 0.6	0.6 - 1.2	0.8 - 1.4	0.0 - 0.6	0.6 - 1.2	0.0 - 0.6	0.6 - 1.2
Analytical Report Reference No.		21T826519	21T822752	21T826519	21T822752	21T822752	21T822752	21T822752
Polychlorinated Biphenyls	0.3	<0.10	<0.10	-	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.02	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 8C Soil Analytical Results - PCBs and OC

Parameter		BH21-28 SS3	QAQC-5	BH21-29 S1	BH21-30 SS1	BH21-31 S2	BH21-33 S2	BH21-34 S1	QAQC-1
Date of Collection	Table 8 RPIICC	Nov 08, 2021		Oct 28, 2021	Nov 08, 2021	Nov 05, 2021	Oct 28, 2021	Oct 28, 2021	
Date Reported		Nov 20, 2021		Nov 08, 2021	Nov 20, 2021	Nov 16, 2021	Nov 08, 2021	Nov 08, 2021	
Sampling Depth (m bgs)		1.5 - 2.1		0.0 - 0.6	0.0 - 0.6	0.6 - 1.2	0.6 - 1.2	0.0 - 0.6	
Analytical Report Reference No.		21T827359		21T822752	21T827359	21T826519	21T822752	21T822752	
Polychlorinated Biphenyls	0.3	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.02	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 8C Soil Analytical Results - PCBs and OC

Parameter		BH21-35 S2	BH21-37 S2	BH21-38 S3	BH21-39 S3	BH21-40 S1	BH21-41 SS2
Date of Collection	Table 8 RPIICC	Oct 27, 2021	Oct 27, 2021	Oct 27, 2021	Nov 05, 2021	Oct 27, 2021	Nov 05, 2021
Date Reported		Nov 08, 2021	Nov 08, 2021	Nov 08, 2021	Nov 16, 2021	Nov 08, 2021	Nov 16, 2021
Sampling Depth (m bgs)		0.6 - 1.2	0.6 - 1.2	1.2 - 1.8	1.2 - 1.8	0.0 - 0.6	0.8 - 1.4
Analytical Report Reference No.		21T822752	21T822752	21T822752	21T826519	21T822752	21T826519
Polychlorinated Biphenyls	0.3	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDD	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDE	0.05	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
DDT	1.4	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	0.04	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	0.02	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachlorocyclohexane Gamma-	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachloroethane	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Methoxychlor	0.05	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005

See "Notes for Soil and Groundwater Summary Tables" included at the begining of this Section

Table 9C Groundwater Analytical Results - Metals & ORPs

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28
Date of Collection	Table 8 Potable GW	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602
Antimony	6	<1.0	<1.0	<1.0	<1.0	<1.0
Arsenic	25	<1.0	<1.0	<1.0	<1.0	5.7
Barium	1000	54	134	102	189	79.5
Beryllium	4	<0.50	<0.50	<0.50	<0.50	<0.50
Boron	5000	85	61	36	117	222
Cadmium	2.1	<0.20	<0.20	<0.20	<0.20	<0.20
Chromium	50	<2.0	<2.0	<2.0	<2.0	<2.0
Chromium VI	25	<2.0	<2.0	<2.0	<2.0	<2.0
Cobalt	3.8	2.06	<0.50	<0.50	<0.50	<0.50
Copper	69	<1.0	1.3	<1.0	<1.0	<1.0
Cyanide	52	<2.0	<2.0	<2.0	<2.0	<2.0
Lead	10	<0.50	<0.50	0.53	<0.50	<0.50
Mercury	0.29	<0.02	<0.02	<0.02	<0.02	<0.02
Molybdenum	70	3.5	<0.50	0.7	5.47	4.81
Nickel	100	3.9	1.2	<1.0	1.3	<1.0
Selenium	10	1	1.7	<1.0	<1.0	<1.0
Silver	1.2	<0.20	<0.20	<0.20	<0.20	<0.20
Thallium	2	<0.30	<0.30	<0.30	<0.30	<0.30
Uranium	20	0.73	<0.50	0.88	5.02	<0.50
Vanadium	6.2	<0.40	<0.40	<0.40	<0.40	<0.40
Zinc	890	<5.0	<5.0	<5.0	<5.0	<5.0
Sodium	490000	92000	135000	349000	18600	33000
Chloride	790000	162000	285000	557000	12800	17600

See "Notes for Soil and Groundwater Summary

Table 10C Groundwater Analytical Results - PHCs&BTEX

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-30	BH21-36
Date of Collection	Table 8 Potable GW	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021	Dec 13, 2021	Nov 23, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 15, 2021	Dec 03, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1	6.1 - 9.1	4.6 - 7.6
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602	21T843989	21T834096
Benzene	5	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	22	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Ethylbenzene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Xylene Mixture	300	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
F1 (C6 to C10) minus BTEX	420	<25	<25	<25	<25	<25	<25	<25
F2 (C10 to C16)	150	<100	<100	<100	<100	<100	<100	<100
F3 (C16 to C34)	500	<100	<100	<100	<100	<100	<100	<100
F4 (C34 to C50)	500	<100	<100	<100	<100	<100	<100	<100

See "Notes for Soil and Groundwater Summary

Table 11C Groundwater Analytical Results - VOCs

Parameter		BH21-36	BH21-9	BH21-13	BH21-25	BH21-28
Date of Collection	Table 8 Potable GW	Nov 23, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021
Date Reported		Dec 03, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		4.6 - 7.6	1.9 - 4.9	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1
Analytical Report Reference No.		21T834096	21T838602	21T838602	21T838602	21T838602
Acetone	2700	<1.0	<1.0	<1.0	<1.0	<1.0
Benzene	5	<0.20	<0.20	<0.20	<0.20	<0.20
Bromodichloromethane	16	<0.20	<0.20	<0.20	<0.20	<0.20
Bromoform	25	<0.10	<0.10	<0.10	<0.10	<0.10
Bromomethane	0.89	<0.20	<0.20	<0.20	<0.20	<0.20
Carbon Tetrachloride	0.79	<0.20	<0.20	<0.20	<0.20	<0.20
Chlorobenzene	30	<0.10	<0.10	<0.10	<0.10	<0.10
Chloroform	2.4	<0.20	<0.20	<0.20	<0.20	<0.20
Dibromochloromethane	25	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,2-	3	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,3-	59	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorobenzene, 1,4-	1	<0.10	<0.10	<0.10	<0.10	<0.10
Dichlorodifluoromethane	590	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethane, 1,1-	5	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethane, 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, 1,1-	1.6	<0.30	<0.30	<0.30	<0.30	<0.30
Dichloroethylene, cis- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloroethylene, trans- 1,2-	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropane, 1,2-	5	<0.20	<0.20	<0.20	<0.20	<0.20
Dichloropropene, 1,3-	0.5	<0.30	<0.30	<0.30	<0.30	<0.30
Ethylbenzene	2.4	<0.10	<0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	0.2	<0.10	<0.10	<0.10	<0.10	<0.10
Hexane, n-	51	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Ethyl Ketone	1800	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl Isobutyl Ketone	640	<1.0	<1.0	<1.0	<1.0	<1.0
Methyl tert-butyl ether	15	<0.20	<0.20	<0.20	<0.20	<0.20
Methylene Chloride	50	<0.30	<0.30	<0.30	<0.30	<0.30
Styrene	5.4	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,1,2-	1.1	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethane, 1,1,2,2-	1	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	22	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethane, 1,1,1-	200	<0.30	<0.30	<0.30	<0.30	<0.30
Trichloroethane, 1,1,2-	4.7	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethylene	1.6	<0.20	<0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	150	<0.40	<0.40	<0.40	<0.40	<0.40
Vinyl Chloride	0.5	<0.17	<0.17	<0.17	<0.17	<0.17
Xylene Mixture	300	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary

Table 12C Groundwater Analytical Results - PAHs

Parameter		BH21-9	BH21-11	BH21-13	BH21-25	BH21-28	BH21-36
Date of Collection	Table 8 Potable GW	Nov 30, 2021	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021	Dec 01, 2021	Nov 23, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 16, 2021	Dec 03, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	3.7 - 6.7	4.6 - 7.6	6.1 - 9.1	4.6 - 7.6
Analytical Report Reference No.		21T838602	21T838602	21T838602	21T838602	21T838602	21T834096
Acenaphthene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Acenaphthylene	1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Anthracene	1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Benz(a)anthracene	1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Benzo(a)pyrene	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Benzo(b)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Benzo(g,h,i)perylene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Benzo(k)fluoranthene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Chrysene	0.1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Dibenz(a,h)anthracene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Fluoranthene	0.41	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Fluorene	120	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Indeno(1,2,3-cd)pyrene	0.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Naphthalene, 2-and 1-	3.2	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Naphthalene	11	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Phenanthrene	1	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Pyrene	4.1	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20

See "Notes for Soil and Groundwater Summary

Table 13C Groundwater Analytical Results - PCBs and OC Pesticides

Parameter		BH21-9	BH21-11	BH21-28
Date of Collection	Table 8 Potable GW	Nov 30, 2021	Nov 30, 2021	Dec 01, 2021
Date Reported		Dec 16, 2021	Dec 16, 2021	Dec 16, 2021
Screened Depth (mbgs)		1.9 - 4.9	5.5 - 8.5	6.1 - 9.1
Analytical Report Reference No.		21T838602	21T838602	21T838602
Polychlorinated Biphenyls	0.2	<0.1	<0.1	<0.1
Aldrin	0.35	-	-	-
Chlordane	0.06	-	-	-
DDD	1.8	-	-	-
DDE	10	-	-	-
DDT	0.05	-	-	-
Dieldrin	0.35	-	-	-
Endosulfan	0.56	-	-	-
Endrin	0.36	-	-	-
Heptachlor	0.038	-	-	-
Heptachlor Epoxide	0.038	-	-	-
Hexachlorobenzene	1	-	-	-
Hexachlorobutadiene	0.44	-	-	-
Hexachlorocyclohexane Gamma-	0.95	-	-	-
Hexachloroethane	2.1	-	-	-
Methoxychlor	0.3	-	-	-

See "Notes for Soil and Groundwater Summary Tables" included at the end of this Section

Table 14C Summary of Maximum Concentrations in Soil

Group	Parameter	Table 8 RPIICC	Maximum Concentration	Location
BTEX	Benzene	0.02	0.006	BH21-41 S1
	Ethylbenzene	0.05	0.01	BH21-41 S1
	Toluene	0.2	<0.05	all samples
	Total Xylenes	0.05	0.22	BH21-41 S1
Metals	Barium	220	147	BH21-30 SS2
	Beryllium	2.5	1.4	BH21-10 S1
	Boron	36	21	BH21-35 S1
	Cadmium	1.2	<0.5	all samples
	Chromium	70	32	BH21-30 SS2
	Cobalt	22	16.3	BH21-28 SS1
	Copper	92	64.7	BH21-10 S1
	Lead	120	205	BH21-36 SS1
	Molybdenum	2	11	BH21-10 S1
	Nickel	82	33	BH21-30 SS2
	Silver	0.5	<0.5	all samples
	Thallium	1	0.6	BH21-10 S1
	Uranium	2.5	0.73	BH21-10 S1
	Vanadium	86	42.7	BH21-30 SS2
	Zinc	290	179	BH21-36 SS1
As, Se, Sb	Antimony	1.3	3.5	BH21-10 S1
	Arsenic	18	26	BH21-41 S2
	Selenium	1.5	2.1	BH21-10 S1
PAHs	Acenaphthene	0.072	<0.05	all samples
	Acenaphthylene	0.093	0.14	BH21-40 S1
	Anthracene	0.22	0.27	BH21-40 S1
	Benz(a)anthracene	0.36	1.13	BH21-40 S1
	Benzo(a)pyrene	0.3	0.86	BH21-40 S1
	Benzo(b)fluoranthene	0.47	1.61	BH21-40 S1
	Benzo(g,h,i)perylene	0.68	0.55	BH21-40 S1
	Benzo(k)fluoranthene	0.48	0.63	BH21-40 S1
	Chrysene	2.8	1.25	BH21-40 S1
	Dibenz(a,h)anthracene	0.1	0.13	BH21-40 S1
	Fluoranthene	0.69	2.11	BH21-40 S1
	Fluorene	0.19	<0.05	all samples
	Indeno(1,2,3-cd)pyrene	0.23	0.48	BH21-40 S1
	Methylnaphthalene, 2-(1-)	0.59	0.82	BH21-40 S1
	Naphthalene	0.09	0.31	BH21-40 S1
	Phenanthrene	0.69	0.78	BH21-40 S1
	Pyrene	1	1.94	BH21-40 S1
PHCs	F1 (C6 to C10) minus BTEX	25	10	BH21-41 S1
	F2 (C10 to C16)	10	13	BH21-31 S2
	F3 (C16 to C34)	240	75	BH21-41 S1
	F4 (C34 to C50)	120	<50	all samples
	Acetone	0.5	<0.50	all samples
	Bromodichloromethane	0.05	<0.05	all samples
	Bromoform	0.05	<0.05	all samples
	Bromomethane	0.05	<0.05	all samples
	Carbon Tetrachloride	0.05	<0.05	all samples
	Chlorobenzene	0.05	<0.05	all samples
	Chloroform	0.05	<0.04	all samples
	Dibromochloromethane	0.05	<0.05	all samples
	Dichlorobenzene, 1,2-	0.05	<0.05	all samples

Table 14C Summary of Maximum Concentrations in Soil

Group	Parameter	Table 8 RPIICC	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,3-	0.05	<0.05	all samples
	Dichlorobenzene, 1,4-	0.05	<0.05	all samples
	Dichlorodifluoromethane	0.05	<0.05	all samples
	Dichloroethane, 1,1-	0.05	<0.02	all samples
	Dichloroethane, 1,2-	0.05	<0.03	all samples
	Dichloroethylene, 1,1-	0.05	<0.05	all samples
	Dichloroethylene, Cis- 1,2-	0.05	<0.02	all samples
	Dichloroethylene, Trans- 1,2-	0.05	<0.05	all samples
	Dichloropropane, 1,2-	0.05	<0.03	all samples
	1,3-Dichloropropene (Cis + Trans)	0.05	<0.05	all samples
	Ethylene Dibromide	0.05	<0.04	all samples
	Hexane, n-	0.05	<0.05	all samples
	Methyl Ethyl Ketone	0.5	<0.50	all samples
	Methyl Isobutyl Ketone	0.5	<0.50	all samples
	Methyl tert-butyl Ether	0.05	<0.05	all samples
	Methylene Chloride	0.05	<0.05	all samples
	Styrene	0.05	<0.05	all samples
	Tetrachloroethane, 1,1,1,2-	0.05	<0.04	all samples
	Tetrachloroethane, 1,1,2,2-	0.05	<0.05	all samples
	Tetrachloroethylene	0.05	<0.05	all samples
	Trichloroethane, 1,1,1-	0.05	<0.05	all samples
	Trichloroethane, 1,1,2-	0.05	<0.04	all samples
	Trichloroethylene	0.05	<0.03	all samples
	Trichlorofluoromethane	0.25	<0.05	all samples
	Vinyl Chloride	0.02	<0.02	all samples
ORPs	Chromium, Hexavalent	0.66	<0.2	all samples
	Cyanide, Free	0.051	<0.040	all samples
	Electrical Conductivity (2:1)	0.7	0.342	BH21-28 SS1
	Mercury	0.27	0.32	BH21-32 SS1
	Sodium Adsorption Ratio	5	0.758	BH21-39 S1
	pH, 2:1 CaCl2 Extraction	*	7.91	QAQC-2
PCBs	Polychlorinated Biphenyls	0.3	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

Table 15C Summary of Maximum Concentrations in Groundwater


Group	Parameter	Table 8 Potable GW	Maximum Concentration	Location
BTEX	Benzene	5	<0.20	all samples
	Ethylbenzene	2.4	<0.10	all samples
	Toluene	22	<0.20	all samples
	Xylene Mixture	300	<0.10	all samples
Metals	Barium	1000	189	BH21-25
	Beryllium	4	<0.50	all samples
	Boron	5000	222	BH21-28
	Cadmium	2.1	<0.20	all samples
	Chromium	50	<2.0	all samples
	Cobalt	3.8	2.06	all samples
	Copper	69	1.3	all samples
	Lead	10	0.53	BH21-13
	Molybdenum	70	5.47	BH21-25
	Nickel	100	3.9	BH21-25
	Silver	1.2	<0.20	all samples
	Thallium	2	<0.30	all samples
	Uranium	20	5.02	BH21-25
	Vanadium	6.2	<0.40	all samples
	Zinc	890	<5.0	all samples
As, Se, Sb	Antimony	6	<1.0	all samples
	Arsenic	25	5.7	BH21-28
	Selenium	10	1.7	all samples
Na	Sodium	490000	349000	BH21-13
PAHs	Acenaphthene	4.1	<0.20	all samples
	Acenaphthylene	1	<0.20	all samples
	Anthracene	1	<0.10	all samples
	Benz(a)anthracene	1	<0.20	all samples
	Benzo(a)pyrene	0.01	<0.01	all samples
	Benzo(b)fluoranthene	0.1	<0.10	all samples
	Benzo(g,h,i)perylene	0.2	<0.20	all samples
	Benzo(k)fluoranthene	0.1	<0.10	all samples
	Chrysene	0.1	<0.10	all samples
	Dibenz(a,h)anthracene	0.2	<0.20	all samples
	Fluoranthene	0.41	<0.20	all samples
	Fluorene	120	<0.20	all samples
	Indeno(1,2,3-cd)pyrene	0.2	<0.20	all samples
	Methyl Naphthalene, 2-and 1-	3.2	<0.20	all samples
	Naphthalene	11	<0.20	all samples
	Phenanthrene	1	<0.10	all samples
	Pyrene	4.1	<0.20	all samples
PHCs	F1 (C6 to C10) minus BTEX	420	<25	all samples
	F2 (C10 to C16)	150	<100	all samples
	F3 (C16 to C34)	500	<100	all samples
	F4 (C34 to C50)	500	<100	all samples
	Acetone	2700	<1.0	all samples
	Bromodichloromethane	16	<0.20	all samples
	Bromoform	25	<0.10	all samples
	Bromomethane	0.89	<0.20	all samples
	Carbon Tetrachloride	0.79	<0.20	all samples
	Chlorobenzene	30	<0.10	all samples
	Chloroform	2.4	<0.20	all samples
	Dibromochloromethane	25	<0.10	all samples


Table 15C Summary of Maximum Concentrations in Groundwater

Group	Parameter	Table 8 Potable GW	Maximum Concentration	Location
VOCs	Dichlorobenzene, 1,2-	3	<0.10	all samples
	Dichlorobenzene, 1,3-	59	<0.10	all samples
	Dichlorobenzene, 1,4-	1	<0.10	all samples
	Dichlorodifluoromethane	590	<0.20	all samples
	Dichloroethane, 1,1-	5	<0.30	all samples
	Dichloroethane, 1,2-	1.6	<0.20	all samples
	Dichloroethylene, 1,1-	1.6	<0.30	all samples
	Dichloroethylene, cis- 1,2-	1.6	<0.20	all samples
	Dichloroethylene, trans- 1,2-	1.6	<0.20	all samples
	Dichloropropane, 1,2-	5	<0.20	all samples
	Dichloropropene, 1,3-	0.5	<0.30	all samples
	Ethylene Dibromide	0.2	<0.10	all samples
	Hexane, n-	51	<0.20	all samples
	Methyl Ethyl Ketone	1800	<1.0	all samples
	Methyl Isobutyl Ketone	640	<1.0	all samples
	Methyl tert-butyl ether	15	<0.20	all samples
	Methylene Chloride	50	<0.30	all samples
	Styrene	5.4	<0.10	all samples
	Tetrachloroethane, 1,1,1,2-	1.1	<0.10	all samples
	Tetrachloroethane, 1,1,2,2-	1	<0.10	all samples
	Tetrachloroethylene	1.6	<0.20	all samples
	Trichloroethane, 1,1,1-	200	<0.30	all samples
	Trichloroethane, 1,1,2-	4.7	<0.20	all samples
	Trichloroethylene	1.6	<0.20	all samples
	Trichlorofluoromethane	150	<0.40	all samples
	Vinyl Chloride	0.5	<0.17	all samples
ORPs	Chloride	790000	557000	BH21-13
	Chromium VI	25	<2.0	all samples
	Cyanide	52	<2.0	all samples
	Mercury	0.29	<0.02	all samples
PCBs	Polychlorinated Biphenyls	0.2	<0.10	all samples

See "Notes for Soil and Groundwater Summary Tables" included at the beginning of this Section

FIGURES





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-1

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-2

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd



DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-3

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-4

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-5

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-6

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-7

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-8

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-9

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:


CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-10

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

	PROJECT NO.: 201-02174-00	REVIEWED BY: MB
	DATE: MAY 2020	FIGURE: 1-11

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.: 201-02174-00	REVIEWED BY: MB
DATE: MAY 2020	FIGURE: 1-12

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

	PROJECT NO.: 201-02174-00	REVIEWED BY: MB
	DATE: MAY 2020	FIGURE: 1-13

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-14

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:


CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-15

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE:	FIGURE:
MAY 2020	1-16

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-17

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-18

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE:	FIGURE:
MAY 2020	1-19

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-20

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

TITLE:
PHASE ONE CONCEPTUAL SITE MODEL


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-21

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd



POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-22

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

	PROJECT NO.: 201-02174-00	REVIEWED BY: MB
	DATE: MAY 2020	FIGURE: 1-23

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1_CSM_v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL

	PROJECT NO.: 201-02174-00	REVIEWED BY: MB
	DATE: MAY 2020	FIGURE: 1-24

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas



POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC


TITLE:
PHASE ONE CONCEPTUAL SITE MODEL


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-25

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE:	FIGURE:
MAY 2020	1-26

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:
PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-27

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-28

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:


CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-29

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-30

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd



POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-31

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:


CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:

REGION OF PEEL

wsp	PROJECT NO.: 201-02174-00	REVIEWED BY: MB
	DATE: MAY 2020	FIGURE: 1-32

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-33

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

	PROJECT NO.:	REVIEWED BY:
wsp	201-02174-00	MB
	DATE: MAY 2020	FIGURE: 1-34

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-35

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-36

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-37

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-38

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:


CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:

REGION OF PEEL

	PROJECT NO.:	REVIEWED BY:
wsp	201-02174-00	MB
	DATE: MAY 2020	FIGURE: 1-39

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-40

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM_v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-41

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:


REGION OF PEEL

	PROJECT NO.:	REVIEWED BY:
wsp	201-02174-00	MB
	DATE: MAY 2020	FIGURE: 1-42

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-43

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-44

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-45

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1_CSM_v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-46

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1_CSM_v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO

CLIENT:

REGION OF PEEL

	PROJECT NO.: 201-02174-00	REVIEWED BY: MB
	DATE: MAY 2020	FIGURE: 1-47

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen.Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE:	FIGURE:
MAY 2020	1-48

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO

CLIENT:

REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-49

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO

CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE:	FIGURE:
MAY 2020	1-50

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:
PHASE ONE CONCEPTUAL SITE MODEL


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-51

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:

REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-52

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-53

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:

REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-54

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:


CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:

REGION OF PEEL

	PROJECT NO.: 201-02174-00	REVIEWED BY: MB
	DATE: MAY 2020	FIGURE: 1-55

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-56

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE:	FIGURE:
MAY 2020	1-57

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1_CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-58

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-59

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-60

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: Ronsen Abbas





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:


CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:

REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-61

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:


REGION OF PEEL

	PROJECT NO.: 201-02174-00	REVIEWED BY: MB
	DATE: MAY 2020	FIGURE: 1-62

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:


REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-63

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd





POTENTIALLY CONTAMINATING ACTIVITIES (PCAS):

- (3) AIRSTRIPS AND HANGARS OPERATION
- (5) ASPHALT AND BITUMEN MANUFACTURING
- (8) CHEMICAL MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (14) CRUDE OIL REFINING, PROCESSING AND BULK STORAGE
- (19) ELECTRONIC AND COMPUTER EQUIPMENT MANUFACTURING
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (31) INK MANUFACTURING, PROCESSING AND BULK STORAGE
- (32) IRON AND STEEL MANUFACTURING AND PROCESSING
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (35) MINING, SMELTING AND REFINING; ORE PROCESSING; TAILINGS STORAGE
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (39) PAINTS MANUFACTURING, PROCESSING AND BULK STORAGE
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (45) PULP, PAPER AND PAPERBOARD MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (47) RUBBER MANUFACTURING AND PROCESSING
- (50) SOAP AND DETERGENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (53) TANNERY
- (54) TEXTILE MANUFACTURING AND PROCESSING
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (59) WOOD TREATING AND PRESERVATIVE FACILITY AND BULK STORAGE OF TREATED AND PRESERVED WOOD PRODUCTS
- (A) SPILLS
- (B) MISCELLANEOUS MANUFACTURING
- (C) COAL STORAGE
- (D) RAIL TIE PILE
- (E) PCB STORAGE
- (F) KNOWN CONTAMINATION

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- ANSI
- INFERRED GROUNDWATER FLOW DIRECTION
- 1m TOPOGRAPHIC CONTOUR
- RAIL
- Rivers
- MECP WATER WELL
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

TITLE:

PHASE ONE CONCEPTUAL SITE MODEL

PROJECT:

CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:


REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
201-02174-00	MB
DATE: MAY 2020	FIGURE: 1-64

Prepared By: Ronsen Abbas

C:\Users\ronsen.abbas\OneDrive - WSP O365\Desktop\ArcGIS\201-02174-00\201-02174-00 Figure 1 CSM v2.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 3
- APEC 105

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-1

\\corp.pbwan.net\ca\CAETC100\ca\to\3\ta\t01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-2

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\cato-3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-3

\\corp.pbwan.net\ca\CAETC100\ca\b\3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 23
- APEC 97

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-4

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\cato\3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- # PCA CONTRIBUTING TO APEC
- # PCA NOT CONTRIBUTING TO APEC

AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 23
- APEC 96
- APEC 104
- APEC 112

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-5

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\cabr3dat01\SPLToronto\Environmental\Environmental Staff\Drafting ProArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842


\\corp.pbwan.net\ca\CAETC100\ca\br3da\t01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd



DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC



AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 96

Note:
Please refer to Table 3 appended to the report for APECs


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-6

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 94
- APEC 95

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-7

\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 93

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-8

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\o3\at01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 37
- APEC 93

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-9

\\corp.pbwan.net\ca\CAETC100\ca\c3da\01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- # PCA CONTRIBUTING TO APEC
- # PCA NOT CONTRIBUTING TO APEC

AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-10

Prepared By: INRM02842
\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\o3da101\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 92

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

LEGEND:


- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-11





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-12

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\o-3da\01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 22

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-13

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca1c\3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 90
- APEC 91

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-14

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\to\3da\01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 90

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-15

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\to\3da\01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 85
- APEC 86
- APEC 87
- APEC 88
- APEC 89
- APEC 111

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-16

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\cab r3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 84
- APEC 111

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-17

\\corp.pbwan.net\ca\CAETC100\ca\b\3da\01\SPLTorontoIE\nvironmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 83
- APEC 84

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-18

\\corp.pbwan.net\ca\CAETC100\ca\to\3da\01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 81
- APEC 82
- APEC 83

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-19

\\corp.pbwan.net\ca\CAETC100\ca\c3dat01\SPLToronto\Environmental\Environmental Staff\Drafting ProArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-20


Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\b\3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\z3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 11
- APEC 79
- APEC 80
- APEC 110

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-21

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 11
- APEC 77
- APEC 78
- APEC 79

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-22

\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-23

\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 75
- APEC 76

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-24

\\corp.pbwan.net\ca\CAETC100\cator3\data01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 36
- APEC 73
- APEC 74

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-25

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\br3dat01\SPLToronto\Environmental\Environmental Staff\Drafting ProArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 35
- APEC 72

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-26

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\c3da\01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 70
- APEC 71
- APEC 72

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-27

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 70

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-28

\\corp.pbwan.net\ca\CAETC100\ca\b\3\dat01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\b\3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 21
- APEC 109

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

LEGEND:


- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-29





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-30

Prepared By: INRM02842

\\corp.pbw.an.net\ca\CAETC100\ca\r3da\01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-31

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\br3da\t01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 69

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-32

\\corp.pbwan.net\ca\CAETC100\ca\br3da\t01\SPLToronto\Environmental\Environmental Staff\Drafting ProArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 34

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-33

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 34

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-34

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\r3da\01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 68

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-35

\\corp.pbwan.net\ca\CAETC100\ca\fc3\at01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 33
- APEC 67

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-36

\\corp.pbwan.net\ca\CAETC100\ca\c3da101\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 33
- APEC 66

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-37

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\or3da101\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 1

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-38

\\corp.pbwan.net\ca\CAETC100\ca\to3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 64
- APEC 65

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE:	FIGURE:
APRIL 2022	2-39

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 62
- APEC 63
- APEC 64

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-40

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 61
- APEC 62

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-41

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\to\r3\data01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 60

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE:	FIGURE:
APRIL 2022	2-42

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\to3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 58

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO


CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-43

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\o-3da101\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- # PCA CONTRIBUTING TO APEC
- # PCA NOT CONTRIBUTING TO APEC

AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 57
- APEC 108

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
CALEDON, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-44

\\corp.pbwan.net\ca\CAETC100\ca\b\3\at01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\cator3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 54
- APEC 55
- APEC 56
- APEC 108

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- \# PCA CONTRIBUTING TO APEC
- \# PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE:	FIGURE:
APRIL 2022	2-45

Prepared By: INRM02842




DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC



AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 27
- APEC 53
- APEC 54

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-46

\\corp.pbwan.net\ca\CAETC100\ca\to3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting ProjArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 27
- APEC 52
- APEC 107

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-47

\\corp.pbwan.net\ca\CAETC100\ca\to3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- # PCA CONTRIBUTING TO APEC
- # PCA NOT CONTRIBUTING TO APEC

AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 18
- APEC 19
- APEC 20
- APEC 107

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-48

\\corp.pbwan.net\ca\CAETC100\cabr3dat01\SPLToronto\Environmental\Staff\Drafting ProArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 2
- APEC 5
- APEC 8
- APEC 18
- APEC 102
- APEC 103

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- (#) PCA CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-49

\\corp.pbwan.net\ca\CAETC100\ca1c\3at01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\cato-3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 2
- APEC 9
- APEC 102

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-50

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 49
- APEC 50
- APEC 51

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
BRAMPTON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-51

\\corp.pbwan.net\ca\CAETC100\ca\to3\dat01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 49

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-52

\\corp.pbwan.net\ca\CAETC100\ca\p3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 6
- APEC 16
- APEC 17
- APEC 26
- APEC 29
- APEC 113

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-53

\\corp.pbwan.net\ca\CAETC100\ca\c3\at01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 4
- APEC 6
- APEC 7
- APEC 10
- APEC 12
- APEC 24
- APEC 25
- APEC 28
- APEC 29
- APEC 31
- APEC 32
- APEC 39
- APEC 40
- APEC 41
- APEC 42
- APEC 48
- APEC 113

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-54

\\corp.pbwan.net\ca\CAETC100\ca\c3da\01\SPLTorontoIEnvironmentalIEnvironmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 4
- APEC 10
- APEC 47
- APEC 101

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-55

\\corp.pbwan.net\ca\CAETC100\ca\c3dat01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-56

\\corp.pbwan.net\ca\CAETC100\ca\br3da\t01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 46

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-57

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\to3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting ProArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 44
- APEC 45

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- # PCA CONTRIBUTING TO APEC
- # PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-58

\\corp.pbwan.net\ca\CAETC100\cator3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 15
- APEC 43
- APEC 44

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-59

\\corp.pbwan.net\ca\CAETC100\ca\fo3at01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 15
- APEC 30

DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

Note:
Please refer to Table 3 appended to the report for APECs

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO


CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-60

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\br3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842





DATA SOURCE:

0 25 50 100 150 200 Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- # PCA CONTRIBUTING TO APEC
- # PCA NOT CONTRIBUTING TO APEC

AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 106

Note:
Please refer to Table 3 appended to the report for APECs


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-61

\\corp.pbwan.net\ca\CAETC100\cato\3dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 59
- APEC 100

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-62


Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\to3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting ProjArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd

Prepared By: INRM02842

\\corp.pbwan.net\ca\CAETC100\ca\b\3\dat01\SPLToronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd





DATA SOURCE:

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

- APEC 13,14,38,114
- APEC 98
- APEC 99

Note:
Please refer to Table 3 appended to the report for APECs


TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN


PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-63

Prepared By: INRM02842





AREAS OF POTENTIAL ENVIORNMENTAL CONCERN (APEC):

APEC 13,14,38,114

Note:
Please refer to Table 3 appended to the report for APECs

DATA SOURCE:

0 25 50 100 150 200
Metres

LEGEND:

- 100m STUDY AREA
- SUBJECT SITE
- BUILDINGS
- RAIL
- RIVERS
- BOREHOLE
- MONITORING WELL
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC

TITLE:
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN

PROJECT:
CONTAMINANT OVERVIEW STUDY
FORMER ORANGEVILLE RAIL,
MISSISSAUGA, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: APRIL 2022	FIGURE: 2-64

\\corp.pbwan.net\ca\CAETC100\ca\o-3da\01\SPL\Toronto\Environmental\Environmental Staff\Drafting Pro\ArcGIS Backup\201-02174-00\201-02174-00 Figure 2 APEC.mxd


Figure 3 – Chemical Exceedances in Soil – Metals and ORPs

Figures 3-1 through 3-4: Caledon Study Area

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			27-Oct-21
BH21-10 S1	0.0 - 0.6	Antimony	**3.5**
		Arsenic	**24**
		Lead	52
		Mercury	<0.10
		Molybdenum	**8.2**
		Selenium	**2.1**
BH21-10 S3	0.0 - 0.6	Antimony	<0.8
		Arsenic	8
		Lead	15
		Mercury	<0.10
		Molybdenum	1
		Selenium	<0.8

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			4-Nov-21
BH21-9 SS2	0.8 - 1.4	Antimony	<0.8
		Arsenic	3
		Lead	7
		Mercury	<0.10
		Molybdenum	<0.5
		Selenium	<0.8



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 3
- APEC 105

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Antimony	1.3
Arsenic	18
Lead	120
Mercury	0.27
Molybdenum	2
Selenium	1.5

TITLE:
FIGURE SERIES 3: CHEMICAL EXCEEDANCES IN SOIL-METALS AND OTHER REGULATED PARAMETERS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO

CLIENT:
REGION OF PEEL


PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **3-1**

IMAGERY SOURCE: ESRI WORLD IMAGERY


0 50 100 150 Metres

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 3 Series\211-10139-00 Figure 3-1 Series Chemical Exceedances in Soil Metals and Other Regulated Parameters.mxd

Prepared By: INRM02842



Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			5-Nov-21
BH21-41 S2	0.6 - 1.2	Antimony	<0.8
		Arsenic	**26**
		Lead	52
		Mercury	<0.10
		Molybdenum	**2.1**
		Selenium	<0.8



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 90
- APEC 91

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Antimony	1.3
Arsenic	18
Lead	120
Mercury	0.27
Molybdenum	2
Selenium	1.5

TITLE:
FIGURE SERIES 3: CHEMICAL EXCEEDANCES IN SOIL-METALS AND OTHER REGULATED PARAMETERS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **3-2**

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 3 Series\211-10139-00 Figure 3-2 Series Chemical Exceedances in Soil Metals and Other Regulated Parameters.mxd

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			16-Nov-21
BH21-36 SS1	0.0 - 0.6	Antimony	1.1
		Arsenic	12
		Lead	**205**
		Mercury	0.23
		Molybdenum	1.2
		Selenium	<0.8
BH21-36 SS2	0.8 - 1.4	Antimony	<0.8
		Arsenic	4
		Lead	13
		Mercury	<0.10
		Molybdenum	<0.5
		Selenium	<0.8



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 11
- APEC 79
- APEC 80
- APEC 110

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Antimony	1.3
Arsenic	18
Lead	120
Mercury	0.27
Molybdenum	2
Selenium	1.5

TITLE:
FIGURE SERIES 3: CHEMICAL EXCEEDANCES IN SOIL-METALS AND OTHER REGULATED PARAMETERS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **3-3**


IMAGERY SOURCE: ESRI WORLD IMAGERY


0 50 100 150 Metres

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 3 Series\211-10139-00 Figure 3-3 Series Chemical Exceedances in Soil Metals and Other Regulated Parameters.mxd

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			15-Nov-21
BH21-32 SS1	0.0 - 0.6	Antimony	**1.9**
		Arsenic	6
		Lead	65
		Mercury	**0.32**
		Molybdenum	1.4
		Selenium	<0.8
BH21-32 SS2	0.8 - 1.4	Antimony	<0.8
		Arsenic	2
		Lead	9
		Mercury	<0.10
		Molybdenum	<0.5
		Selenium	<0.8





LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 21
- APEC 109

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Antimony	1.3
Arsenic	18
Lead	120
Mercury	0.27
Molybdenum	2
Selenium	1.5

TITLE:
FIGURE SERIES 3: CHEMICAL EXCEEDANCES IN SOIL-METALS AND OTHER REGULATED PARAMETERS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **3-4**

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 3 Series\211-10139-00 Figure 3-4 Series Chemical Exceedances in Soil Metals and Other Regulated Parameters.mxd

Figure 3 – Chemical Exceedances in Soil – Metals and ORPs

Figures 3-5 and 3-6: Brampton Study Area

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			24-Nov-21
BH21-19 SS2	0.8 - 1.4	Antimony	<0.8
		Molybdenum	<0.5
		Nickel	26
		Zinc	59

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			23-Nov-21
BH21-20 SS1	0.0 - 0.6	Antimony	<0.8
		Molybdenum	0.6
		Nickel	**142**
		Zinc	67
BH21-20 SS4	2.3 - 2.9	Antimony	<0.8
		Molybdenum	1.2
		Nickel	27
		Zinc	63

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			24-Nov-21
BH21-18 SS2	0.8 - 1.4	Antimony	<0.8
		Molybdenum	<0.5
		Nickel	24
		Zinc	66

RAILSIDE DR

IRONSIDE DR

BH21-20 BH21-19 BH21-18

Figure 3-48 Figure 3-49 Figure 3-50

0 100200 400 600 Meters

LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 2
- APEC 5
- APEC 8
- APEC 9
- APEC 18
- APEC 102
- APEC 103

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Antimony	1.3
Molybdenum	2
Nickel	82
Zinc	290

IMAGERY SOURCE: ESRI WORLD IMAGERY

0 50 100 150 Metres

TITLE:
FIGURE SERIES 3: CHEMICAL EXCEEDANCES IN SOIL-METALS AND OTHER REGULATED PARAMETERS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, BRAMPTON, ONTARIO


CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **3-5**

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 3 Series\211-10139-00 Figure 3-5 Series Chemical Exceedances in Soil Metals and Other Regulated Parameters.mxd


Prepared By: INRM02842

\\corp.pbwan.net\calenv_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 3 Series\211-10139-00 Figure 3-6 Series Chemical Exceedances in Soil Metals and Other Regulated Parameters.mxd



Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			22-Nov-21
BH21-45 SS2	0.8 - 1.4	Antimony	<0.8
		Molybdenum	<0.5
		Nickel	33
		Zinc	68

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			1-Dec-21
BH21-16 SS1	0.0 - 0.6	Antimony	**2.8**
		Molybdenum	**3.7**
		Nickel	31
		Zinc	**468**



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 6
- APEC 16
- APEC 17
- APEC 26
- APEC 29
- APEC 48
- APEC 113

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Antimony	1.3
Molybdenum	2
Nickel	82
Zinc	290

TITLE:
FIGURE SERIES 3: CHEMICAL EXCEEDANCES IN SOIL-METALS AND OTHER REGULATED PARAMETERS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **3-6**


Figure 4 – Chemical Exceedances in Soil – PAHs

Figures 4-1 through 4-3: Caledon Study Area

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			5-Nov-21
BH21-9 SS3	1.5 - 2.1	Naphthalene	<0.05
		Anthracene	**0.18**
		Benzo(b)fluoranthene	0.05
		Benzo(k)fluoranthene	0.06

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			27-Oct-21
BH21-10 S3	1.2 - 1.8	Naphthalene	<0.05
		Anthracene	<0.05
		Benzo(b)fluoranthene	0.05
		Benzo(k)fluoranthene	0.06



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 3
- APEC 105

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Naphthalene	0.09
Anthracene	0.16
Benzo(b)fluoranthene	0.47
Benzo(k)fluoranthene	0.48

TITLE:
FIGURE SERIES 4: CHEMICAL EXCEEDANCES IN SOIL-PAHS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **4-1**

IMAGERY SOURCE: ESRI WORLD IMAGERY


0 50 100 150 Metres

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 4 Series\211-10139-00 Figure 4-1 Series Chemical Exceedances in Soil_PAHs.mxd

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			5-Nov-21
BH21-39 S3	1.2 - 1.8	Naphthalene	<0.05
		Anthracene	<0.05
		Benzo(b)fluoranthene	<0.05
		Benzo(k)fluoranthene	<0.05

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			27-Oct-21
BH21-40 S3	1.2 - 1.8	Naphthalene	**0.1**
		Anthracene	0.12
		Benzo(b)fluoranthene	**0.53**
		Benzo(k)fluoranthene	**0.5**



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 85
- APEC 86
- APEC 87
- APEC 88
- APEC 89
- APEC 111

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Naphthalene	0.09
Anthracene	0.16
Benzo(b)fluoranthene	0.47
Benzo(k)fluoranthene	0.48

TITLE:
FIGURE SERIES 4: CHEMICAL EXCEEDANCES IN SOIL-PAHS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: 4-2

IMAGERY SOURCE: ESRI WORLD IMAGERY


0 50 100 150 Metres

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 4 Series\211-10139-00 Figure 4-2 Series Chemical Exceedances in Soil-PAHs.mxd

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			1-Dec-21
BH21-16 SS2	0.8 - 1.4	Anthracene	<0.05
		Fluoranthene	<0.05
		Benz(a)anthracene	<0.05
		Benz(a)pyrene	<0.05
		Benzo(b)fluoranthene	<0.05
		Indeno(1,2,3-cd)pyrene	<0.05

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			22-Nov-21
BH21-45 SS1	0.0 - 0.6	Anthracene	0.13
		Fluoranthene	**0.57**
		Benz(a)anthracene	**0.39**
		Benz(a)pyrene	**0.33**
		Benzo(b)fluoranthene	0.45
		Indeno(1,2,3-cd)pyrene	0.19
BH21-45 SS2	0.8 - 1.4	Anthracene	<0.05
		Fluoranthene	<0.05
		Benz(a)anthracene	<0.05
		Benz(a)pyrene	<0.05
		Benzo(b)fluoranthene	<0.05
		Indeno(1,2,3-cd)pyrene	<0.05



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 6
- APEC 16
- APEC 17
- APEC 26
- APEC 29
- APEC 48
- APEC 113

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Anthracene	0.16
Fluoranthene	0.56
Benz(a)anthracene	0.36
Benz(a)pyrene	0.3
Benzo(b)fluoranthene	0.47
Indeno(1,2,3-cd)pyrene	0.23

TITLE:
FIGURE SERIES 4: CHEMICAL EXCEEDANCES IN SOIL-PAHS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: 4-3

IMAGERY SOURCE: ESRI WORLD IMAGERY

0 50 100 150 Metres

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 4 Series\211-10139-00 Figure 4-3 Series Chemical Exceedances in Soil-PAHs.mxd

Figure 4 – Chemical Exceedances in Soil – PAHs


Figure 4-4: Brampton Study Area

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			29-Nov-21
BH21-8 SS1	0.0 - 0.6	Anthracene	0.1
		Fluoranthene	**0.85**
		Benz(a)anthracene	**0.46**
		Benz(a)pyrene	**0.4**
		Benzo(b)fluoranthene	**0.66**
		Indeno(1,2,3-cd)pyrene	**0.26**

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			1-Dec-21
BH21-6 SS1	0.0 - 0.6	Anthracene	<0.05
		Fluoranthene	<0.05
		Benz(a)anthracene	<0.05
		Benz(a)pyrene	<0.05
		Benzo(b)fluoranthene	<0.05
		Indeno(1,2,3-cd)pyrene	<0.05

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			29-Nov-21
BH21-7 SS1	0.0 - 0.6	Anthracene	**0.18**
		Fluoranthene	**1.05**
		Benz(a)anthracene	**0.56**
		Benz(a)pyrene	**0.4**
		Benzo(b)fluoranthene	**0.6**
		Indeno(1,2,3-cd)pyrene	0.22



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 4
- APEC 7
- APEC 10
- APEC 12
- APEC 25
- APEC 40
- APEC 41
- APEC 42
- APEC 101
- APEC 113

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Anthracene	0.16
Fluoranthene	0.56
Benz(a)anthracene	0.36
Benz(a)pyrene	0.3
Benzo(b)fluoranthene	0.47
Indeno(1,2,3-cd)pyrene	0.23

TITLE:
FIGURE SERIES 4: CHEMICAL EXCEEDANCES IN SOIL-PAHS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **4-4**

IMAGERY SOURCE: ESRI WORLD IMAGERY


0 50 100 150 Metres

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 4 Series\211-10139-00 Figure 4-4 Series Chemical Exceedances in Soil-PAHs.mxd

Figure 5 – Chemical Exceedances in Soil – PHCs and BTEX

Figure 5-1 and 5-2: Caledon Study Area


Prepared By: INRM02842



Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			28-Oct-21
BH21-41 S1	0.0 - 0.6	Total Xylenes	**0.22**
		PHC F2	0.12

IMAGERY SOURCE: ESRI WORLD IMAGERY

0 50 100 150 Metres



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 90
- APEC 91

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Total Xylenes	0.05
PHC F2	10

TITLE:
FIGURE SERIES 5: CHEMICAL EXCEEDANCES IN SOIL-PHCS & BTEX


PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **5-1**

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 5 Series\211-10139-00 Figure 5-1 Series Chemical Exceedances in Soil-PHCs & BTEX.mxd


Prepared By: INRM02842



Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			28-Oct-21
BH21-31 S2	0.6 - 1.2	Total Xylenes	<0.05
		PHC F2	**13**

IMAGERY SOURCE: ESRI WORLD IMAGERY

0 50 100 150 Metres



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 69

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Total Xylenes	0.05
PHC F2	10

TITLE:
FIGURE SERIES 5: CHEMICAL EXCEEDANCES IN SOIL-PHCS & BTEX

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, CALEDON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **5-2**

\\corp.pbwan.net\calenv_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 5 Series\211-10139-00 Figure 5-2 Series Chemical Exceedances in Soil-PHCs & BTEX.mxd


Figure 5 – Chemical Exceedances in Soil – PHCs and BTEX

Figure 5-3: Brampton Study Area

Prepared By: INRM02842

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			1-Dec-21
BH21-16 SS8	6.1 - 6.7	Ethylbenzene	<0.05
		Total Xylenes	<0.05
		PHC F2	<10

Sample ID	Depth (mbgs)	Parameter	Result (µg/g)
			22-Nov-21
BH21-45 SS8	7.6 - 8.2	Ethylbenzene	**0.9**
		Total Xylenes	**5.55**
		PHC F2	**51**
BH21-45 SS9	9.1 - 9.8	Ethylbenzene	<0.05
		Total Xylenes	<0.05
		PHC F2	<10



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 6
- APEC 16
- APEC 17
- APEC 26
- APEC 29
- APEC 48
- APEC 113

Parameter	MECP Table 1 RPIICC SCS (µg/g)
Ethylbenzene	0.05
Total Xylenes	0.05
PHC F2	10

TITLE:
FIGURE SERIES 5: CHEMICAL EXCEEDANCES IN SOIL-PHCS & BTEX

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **5-3**

IMAGERY SOURCE: ESRI WORLD IMAGERY

0 50 100 150 Metres

\\corp.pbwan.net\calenv_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 5 Series\211-10139-00 Figure 5-3 Series Chemical Exceedances in Soil_PHCs & BTEX.mxd


Figure 6 – Chemical Exceedances in Groundwater – Metals and ORPs

Figures 6-1 and 6-2: Brampton Study Area

Prepared By: INRM02842

Sample ID	Screened Depth (mbgs)	Parameter	Result (µg/L)	
			1-Dec-21	11-Feb-22
BH21-16	6.1 - 9.1	Molybdenum	**24.7**	**32.1**
		Chromium	<2.0	-
		Cobalt	<0.50	-
		Chloride	286000	-

Sample ID	Screened Depth (mbgs)	Parameter	Result (µg/L)	
			1-Dec-21	11-Feb-22
BH21-45	6.1 - 9.1	Molybdenum	**28**	**57.1**
		Chromium	<2.0	-
		Cobalt	0.66	-
		Chloride	326000	-



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 6
- APEC 16
- APEC 17
- APEC 26
- APEC 29
- APEC 48
- APEC 113

Parameter	MECP Table 1 SCS (µg/L)
Molybdenum	23
Chromium	11
Cobalt	3.8
Chloride	790000

TITLE: **FIGURE SERIES 6: CHEMICAL EXCEEDANCES IN GROUNDWATER- METALS AND OTHER REGULATED PARAMETERS**

PROJECT: LIMITED PHASE II ENVIRONMENTAL ASSESSMENT FORMER ORANGEVILLE RAIL, BRAMPTON, ONTARIO

CLIENT: REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: 6-1

IMAGERY SOURCE: ESRI WORLD IMAGERY

0 50 100 150 Metres


\\corp.pbwan.net\calenv_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 6 Series\211-10139-00 Figure 6-1 Series Chemical Exceedances in Groundwater-Metals and Other Regulated Parameter.mxd

Prepared By: INRM02842

Sample ID	Screened Depth (mbgs)	Parameter	Result (µg/L)
			2-Dec-21
BH21-8	6.1 - 9.1	Molybdenum	7.84
		Chromium	<2.0
		Cobalt	0.63
		Chloride	72700

Sample ID	Screened Depth (mbgs)	Parameter	Result (µg/L)
			6-Dec-21
BH21-6	3.1 - 6.1	Molybdenum	6.45
		Chromium	**25.3**
		Cobalt	**4.53**
		Chloride	**1460000**

Sample ID	Screened Depth (mbgs)	Parameter	Result (µg/L)
			2-Dec-21
BH21-7	2.8 - 5.8	Molybdenum	14.2
		Chromium	<2.0
		Cobalt	0.52
		Chloride	768000



LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 4
- APEC 7
- APEC 10
- APEC 12
- APEC 25
- APEC 40
- APEC 41
- APEC 42
- APEC 101
- APEC 113

Parameter	MECP Table 1 SCS (µg/L)
Molybdenum	23
Chromium	11
Cobalt	3.8
Chloride	790000

TITLE:
FIGURE SERIES 6:
CHEMICAL EXCEEDANCES IN GROUNDWATER-METALS AND OTHER REGULATED PARAMETERS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: **6-2**

IMAGERY SOURCE: ESRI WORLD IMAGERY

0 50 100 150 Metres

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage Inventory\MXD\Limited PH II\FEB 2022\Fig 6 Series\211-10139-00 Figure 6-2 Series Chemical Exceedances in Groundwater-Metals and Other Regulated Parameter.mxd


Figure 7 – Chemical Exceedances in Groundwater – PAHs


Figure 7-1: Brampton Study Area

Prepared By: INRM02842

Sample ID	Screened Depth (mbgs)	Parameter	Result (µg/g)
			6-Dec-21
BH21-16	6.1 - 9.1	Anthracene	<0.10
		Benz(a)anthracene	<0.20
		Benz(a)pyrene	<0.01
		Benzo(b)fluoranthene	<0.10
		Benzo(g,h,i)perylene	<0.20
		Benzo(k)fluoranthene	<0.10
		Chrysene	<0.10
		Dibenz(a,h)anthracene	<0.20
		Fluoranthene	<0.20
		Indeno(1,2,3-cd)pyrene	<0.20
		Phenanthrene	<0.10
		Pyrene	<0.20

Sample ID	Screened Depth (mbgs)	Parameter	Result (µg/L)	
			1-Dec-21	11-Feb-22
BH21-45	6.1 - 9.1	Anthracene	**1.79**	<0.10
		Benz(a)anthracene	**2.4**	<0.20
		Benz(a)pyrene	**3.67**	<0.01
		Benzo(b)fluoranthene	**4.92**	<0.10
		Benzo(g,h,i)perylene	**2.48**	<0.20
		Benzo(k)fluoranthene	**2.19**	<0.10
		Chrysene	**5.59**	<0.10
		Dibenz(a,h)anthracene	**0.32**	<0.20
		Fluoranthene	**17.9**	<0.20
		Indeno(1,2,3-cd)pyrene	**1.8**	<0.20
		Phenanthrene	**1.2**	<0.10
		Pyrene	**14.6**	<0.20





LEGEND:

- SITE BOUNDARY
- RAILWAY LINE
- BOREHOLE
- MONITORING WELL
- MEETS SCS
- EXCEEDS SCS
- PCA CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- INFERRED GROUNDWATER FLOW DIRECTION
- APEC 13,14,38,114
- APEC 6
- APEC 16
- APEC 17
- APEC 26
- APEC 29
- APEC 48
- APEC 113

Parameter	MECP Table 1 SCS (µg/L)
Anthracene	0.1
Benz(a)anthracene	0.2
Benz(a)pyrene	0.01
Benzo(b)fluoranthene	0.1
Benzo(g,h,i)perylene	0.2
Benzo(k)fluoranthene	0.1
Chrysene	0.1
Dibenz(a,h)anthracene	0.2
Fluoranthene	0.4
Indeno(1,2,3-cd)pyrene	2
Phenanthrene	0.1
Pyrene	0.2

TITLE:
FIGURE SERIES 7:
CHEMICAL EXCEEDANCES IN GROUNDWATER-PAHS

PROJECT:
LIMITED PHASE II ENVIRONMENTAL ASSESSMENT
FORMER ORANGEVILLE RAIL, BRAMPTON, ONTARIO

CLIENT:
REGION OF PEEL

PROJECT NO.:	REVIEWED BY:
211-10139-00	CJ
DATE: FEBRUARY 2022	FIGURE: 7-1


IMAGERY SOURCE: ESRI WORLD IMAGERY

0 50 100 150 Metres

\\corp.pbwan.net\ca\env_gis\PROJECTS\ON\2021\211-10139-00 ORBY Rail to Trail Natural Heritage InventoryMXD\Limited PH II\FEB 2022\Fig 7 Series\211-10139-00 Figure 7-1 Series Chemical Exceedances in Groundwater-PAHs.mxd

Contaminant Transport Diagram – Human Health

FIGURE 8



☒ Exposure pathway not evaluated in the DDRA
☑ Exposure pathway evaluated in the DDRA

Date: January 2022		Reviewed By: CJ
Project Number: 211-10139-00		Designed By: MP

APPENDIX

A BOREHOLE LOGS

BOREHOLE DRILLING RECORD : **BH21-1**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-17
Date (End):	2021-11-17
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Diesel Hammer
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	601719.802 m
Northing:	4831105.845 m
Surface Elevation:	173.727 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
173.73																
173.57		**TOPSOIL** : Some sandy silt and organics, dark brown, moist	*5*						SS1	96%	5	PCB OC Pest				
0.5		**SILT** : Sand, trace gravel, brown, moist														
			0						SS2	71%	8	Metals & Inorg. PAH				
1.0																
1.22																
172.51		**SILT** : Clay, trace sand, brown/grey, saturated	*0*						SS3	100%	5	PHC BTEX				
1.5																
1.83																
171.90																
2.0																
2.5																
3.0																
3.5																
4.0																
4.5																
5.0																
5.5																
6.0																
6.5																
7.0																
7.5																
8.0																
8.5																
9.0																
9.5																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-10**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-27
Date (End):	2021-10-27
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	573449.668 m
Northing:	4862380.629 m
Surface Elevation:	422.508 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
422.51																
0.70		**SILT** : Sand, some gravel, rocks, organics, black/brown, moist	*0*						MA1	33%		Metals & Inorg.				
421.81		**SAND** : some gravel, stones, pulverized rock, white/light brown	*0*						MA2	38%		PCB OC Pest				
		brown, trace silt, moist	*0*						MA3	33%		PAH				
1.83																
420.68																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-11**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-04
Date (End):	2021-11-04
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	575101.549 m
Northing:	4856998.492 m
Surface Elevation:	396.937 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
~~396.94~~												CONCRETE	
396.78		**SILT** : Sand, some gravel and organics. Black, moist	0			SS1	71%	7	Metals & Inorg.				
0.5													0.5
		SAND : Coarse sand with some gravel and rocks. Brown moist											
1.0		*Fine-medium sand, light brown*	0			SS2	79%	15	OC Pest PAH				1.0
1.5													1.5
			0			SS3	67%	20					
2.0													2.0
2.5			0			SS4	75%	32				BENTONITE	2.5
3.0		*Saturated*											3.0
3.5			0			SS5	88%	24					3.5
4.0													4.0
4.5		*Coarse sand, trace gravel*											4.5
5.0			0			SS6	29%	13					5.0
5.5													5.5
6.0													6.0
6.5			0			SS7	83%	10	PHC BTEX			SAND	6.5
7.0												SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	7.0
7.5													7.5
8.0			0			SS8	100%	14					8.0
8.5													8.5
9.0													9.0
9.14												BENTONITE	
387.79		**GRAVEL** : Some coarse sand and pebbles. Saturated	0			SS9	88%	17					9.5
9.75													
387.18													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-12**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-18
Date (End):	2021-11-18
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	601692.461 m
Northing:	4830853.444 m
Surface Elevation:	173.341 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product


SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE
0.05 / *173.29*		**SILT** : 50 mm Fill. Sand, some gravel and organics. Dark brown/black, moist	0						SS1	50%	3	PAH	
0.76 / *172.58*		**SILT** : Sand, trace gravel. Brown, moist											
		CLAY : Silt, trace sand. Brown/grey, moist to wet	5						SS2	67%	5		
			0						SS3	100%	3	PHC BTEX	
2.29 / *171.06*		**CLAY** : Grey, saturated	0						SS4	100%	0		
			0						SS5	83%	3		
			0						SS6	54%	6		
		trace sand, dry	0						SS7	92%	23		
		moist	0						SS8	100%	8		
		trace gravel	0						SS9	100%	13		
9.75 / *163.59*													

MONITORING WELL



REMARKS

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-13**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-15
Date (End):	2021-11-15
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	575272.383 m
Northing:	4860032.288 m
Surface Elevation:	403.897 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM / DESCRIPTION	REMARKS
403.90		**SILT** : Sand, trace gravel and organics. Brown, moist	0						SS1	54%	5	OC Pest PAH		CONCRETE	
0.84															
403.06		**SAND** : Light brown, moist	0						SS2	83%	3	Metals & Inorg.			
1.52														BENTONITE	
402.37		**SAND** : Silt, brown, moist to wet	0						SS3	79%	4				
			0						SS4	100%	9				
3.05															
400.85		**SILT** : sand, brown, moist to wet	0						SS5	100%	8	PHC BTEX			
4.57															
399.33		**GRAVEL** : Some pebbles, wet	0						SS6	50%	51			SAND	
6.10														SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	
397.80		**SAND** : Brown, saturated	0						SS7	54%	9				
7.62															
396.28		**ROCK FRAGMENTS** : Sand, crushed rock. Brown, wet	0						SS8	54%	38			BENTONITE	
		← *saturated*	0						SS9	71%	N/A				
9.60															
394.30															

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-14**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-27
Date (End):	2021-10-27
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	575353.347 m
Northing:	4859755.75 m
Surface Elevation:	404.795 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
404.80		**SILT** : Sand, some gravel, organics, brown, moist	0						MA1	21%		PCB OC Pest				
0.5		*no organics, moist to west*														
1.0			0						MA2	50%		Metals & Inorg.				
1.5		*light brown, dry*	0						MA3	29%		PAH				
1.83																
402.97																
2.0																
2.5																
3.0																
3.5																
4.0																
4.5																
5.0																
5.5																
6.0																
6.5																
7.0																
7.5																
8.0																
8.5																
9.0																
9.5																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-15**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-27
Date (End):	2021-10-27
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	574957.267 m
Northing:	4857434.773 m
Surface Elevation:	395.737 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	VISUAL S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
0.5		*No recovery*	0						MA1	0%						
395.13 1.0		**SAND** : Silt, trace gravel, brown, moist	0						MA2	29%		PCB OC Pest PAH				
1.5			0						MA3	29%		Metals & Inorg.				
1.83 *393.91* 2.0																
2.5																
3.0																
3.5																
4.0																
4.5																
5.0																
5.5																
6.0																
6.5																
7.0																
7.5																
8.0																
8.5																
9.0																
9.5																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-16**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-12-01
Date (End):	2021-12-01
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	599255.635 m
Northing:	4837772.699 m
Surface Elevation:	218.114 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR (L M S)	VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
218.11		*Dark brown/black, loose* **SILT** : Sand, some gravel. Light brown/grey, moist	0			SS1	58%	24	Metals & Inorg.			CONCRETE	
0.81													
217.30		**SILT** : Sand, trace gravel. Grey, moist, soft *Trace clay, brown* *dry*	10			SS2	79%	6	PAH	QAQC-10			
			0			SS3	100%	27					
			0			SS4	92%	56				BENTONITE	
			0			SS5	100%	53					
		very brittle/cracked, some gravel	0			SS6	100%	31					
6.10													
212.02		**CLAY** : Grey, moist, soft	0			SS7	75%	14					
7.72													
210.39		**SAND** : Silt, some gravel. Grey/brown, saturated	0			SS8	88%	52	PHC VOC	QAQC-9		SAND SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	
9.14												WATER MARKER Depth : 4.96 m Elev. : 213.154 m Date : 2021-12-02	
208.97												WATER MARKER Depth : 4.97 m Elev. : 213.144 m Date : 2021-12-06	
9.45		**RED SHALE** : Red shale chips, some gravel, wet	0			SS9	42%	N/A					
208.67													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-17**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-05
Date (End):	2021-11-05
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	598117.46 m
Northing:	4838582.606 m
Surface Elevation:	224.204 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
224.20		**SILT** : Sand, organics. Dark brown, moist	*0*						MA1	29%		Metals & Inorg.				
		Trace clay, trace gravel. Dry	*0*						MA2	33%		PCB OC Pest				
1.22 *222.98*		**SILT** : Clay, Trace gravel. Brown/grey, dry	*0*						MA3	79%		PAH				
1.83 *222.38*																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

BOREHOLE DRILLING RECORD : **BH21-18**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-24
Date (End):	2021-11-24
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	596964.585 m
Northing:	4839724.521 m
Surface Elevation:	238.096 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
238.10		**SILT** : Sand, trace gravel and organics. Dark brown, moist							SS1	67%	5	Metals & Inorg.				
1.22									SS2	96%	16	PHC BTEX PCB PAH OC Pest				
236.88		**RED SHALE** : Red shale chips, weathered, dry														
236.27 1.82									SS3	100%	N/A					

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

BOREHOLE DRILLING RECORD : **BH21-19**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-24
Date (End):	2021-11-24
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	596751.123 m
Northing:	4839932.696 m
Surface Elevation:	241.304 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
0.00 *241.30*																
241.23		**SILT** : Sand, some gravel and organics. Dark brown, moist							SS1	67%	3	PAH				
0.5		**SILT** : Sand, trace gravel. Brown, moist														0.5
1.0									SS2	96%	9	Metals & Inorg. PHC BTEX				1.0
		Red/brown														
1.52 *239.78*		*Trace gravel, pulverized rock and white dust, brittle red shale chips, dry*														
1.5									SS3	75%	38					1.5
2.0		**RED SHALE** : Red shale fragments, some gravel, dry														2.0
2.5									SS4	63%	>96					2.5
3.0																3.0
3.35 *237.95*									SS5	108%	N/A					
3.5																3.5
4.0																4.0
4.5																4.5
5.0																5.0
5.5																5.5
6.0																6.0
6.5																6.5
7.0																7.0
7.5																7.5
8.0																8.0
8.5																8.5
9.0																9.0
9.5																9.5

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-2**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-12-02
Date (End):	2021-12-02
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	599850.293 m
Northing:	483272.348 m
Surface Elevation:	183.942 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
183.94		**SILT** : Sand, organics, trace gravel. Brown, moist				SS1	83%	5				CONCRETE	
0.5		*Light brown, moist to dry*											0.5
1.0		*Gravel pocket, some sand, loose, dry*				SS2	67%	9	Metals & Inorg.			BENTONITE	1.0
1.5													1.5
2.0						SS3	63%	4					2.0
2.5												SAND	2.5
2.56 *181.38*		**CLAY** : Sand, grey/brown, moist, soft				SS4	71%	33					
3.0		*saturated*											3.0
3.5						SS5	100%		PHC BTEX	QAQC-11			3.5
4.0													4.0
4.5												SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	4.5
4.75 *179.19*		**CLAY** : Grey, wet				SS6	100%	3					
5.0													5.0
5.5													5.5
6.0		*2" sand seam, wet*				SS7	100%	5					6.0
6.5													6.5
7.0													7.0
7.5													7.5
8.0		*trace gravel*				SS8	100%	4				BENTONITE	8.0
8.5													8.5
9.0		*saturated, soft*										WATER MARKER Depth : 3.26 m Elev. : 180.682 m Date : 2021-12-07 WATER MARKER Depth : 3.29 m Elev. : 180.652 m Date : 2021-12-06	9.0
9.5						SS9	25%	1					9.5
9.75 *174.19*													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

BOREHOLE DRILLING RECORD : **BH21-20**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-23
Date (End):	2021-11-23
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	596594.066 m
Northing:	4840094.602 m
Surface Elevation:	243.416 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR (L M S)	VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
243.42 / 0.00													
243.24		**SAND** : Silt, some gravel and organics. Dark brown, moist	5			SS1	79%	5	Metals & Inorg.	QAQC-6			
0.5		**SILT** : Sand, trace gravel. Brown, moist, soft											0.5
1.0			0			SS2	88%	6	PCB PAH OC Pest	QAQC-7			1.0
1.5		*Trace clay, some oxidation*											1.5
2.0		*Pulverized rock*	0			SS3	92%	14	PHC BTEX	QAQC-8			2.0
2.29 / *241.13*		**RED SHALE** : Brittle shale chips, dry	0			SS4	67%	>79	Metals & ORPs				2.5
3.0		*Some white rocks/dust, dry*											3.0
3.20 / *240.22*			0			SS5	83%	N/A					3.5
4.0													4.0
4.5													4.5
5.0													5.0
5.5													5.5
6.0													6.0
6.5													6.5
7.0													7.0
7.5													7.5
8.0													8.0
8.5													8.5
9.0													9.0
9.5													9.5

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

BOREHOLE DRILLING RECORD : **BH21-21**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-23
Date (End):	2021-11-23
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	596176.169 m
Northing:	4840493.732 m
Surface Elevation:	244.742 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID / *CGD* (ppm)	ODOUR (L M S)	VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
0.00 / *244.69*		**GRAVEL** : Rocks, some organics, trace silt, moist	0			SS1	75%	4	PCB PAH OC Pest				
		SILT : Sand, trace gravel. Brown, moist/dry, soft											
		Some gravel, refusal on rocks	0			SS2	42%	>59					
			0			SS3	88%	12	Metals & Inorg. PHC VOC				
2.56 / *242.18*		**RED SHALE** : Red shale chips, dry	0			SS4	67%	>80					
3.20 / *241.54*			0			SS5	100%	N/A					

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-22**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-22
Date (End):	2021-11-22
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	595210.841 m
Northing:	4841438.197 m
Surface Elevation:	243.709 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID / *CGD* (ppm)	ODOUR (L M S)	VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM / DESCRIPTION	REMARKS
243.71		**SILT** : Sand, trace gravel. Light brown, soft, moist to dry	0			SS1	71%	5	Metals & Inorg.		CONCRETE	
0.5												0.5
1.0			0			SS2	100%	24				1.0
1.5		*Some gravel, moist*									BENTONITE	1.5
2.0			5			SS3	96%	23	PCB PAH OC Pest			2.0
2.34												
241.37		**CLAY** : Sand, trace silt and gravel. Grey, moist	0			SS4	88%	17				2.5
3.0												3.0
3.56			0			SS5	88%	36	PHC VOC			3.5
240.15		**SAND** : Silt, some gravel. Brown, soft, saturated										
4.0												4.0
4.5											SAND	4.5
5.0			0			SS6	50%	91			SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	5.0
5.5												5.5
6.0												6.0
6.5			0			SS7	58%	>50				6.5
7.0												7.0
7.5												7.5
7.62												
236.09		**SAND** : Some gravel and silt. Brown, soft, saturated	0			SS8	29%	N/A			BENTONITE	
8.0												8.0
8.5												8.5
9.0												9.0
9.14												
234.57		**SILT** : Sand, trace shale fragments, trace gravel. Reddish-brown, moist	0			SS9	92%	N/A				
9.45												
9.5												9.5
234.26											WATER MARKER Depth : 1.65 m Elev. : 242.059 m Date : 2021-11-30	

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-23**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-05
Date (End):	2021-11-05
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	595076.42 m
Northing:	4841580.422 m
Surface Elevation:	246.511 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID / *CGD* (ppm)	ODOUR (L M S)	VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
246.51													
0.61		**SILT** : Sand, trace gravel and organics. Brown, moist	*0*			MA1	42%		PAH				
245.90		**SILT** : Some gravel. Brown/grey, moist	*0*			MA2	46%		Metals & Inorg.				
1.83			*0*			MA3	88%		PCB OC Pest				
244.68													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-24**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-05
Date (End):	2021-11-05
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	594404.585 m
Northing:	4842223.603 m
Surface Elevation:	252.4 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
252.40																
0.70		**SILT** : Sand, trace gravel and organics. Brown, moist	*0*						MA1	42%		PCB OC Pest				
251.70		: No recovery	*0*						MA2	17%		PAH				
1.22																
251.18		**SILT** : Trace sand, trace gravel. Brown/grey, moist	*0*						MA3	71%		Metals & Inorg.				
1.83																
250.57																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-25**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-16
Date (End):	2021-11-16
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	594118.316 m
Northing:	4842529.619 m
Surface Elevation:	256.306 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
0.00 / *256.25*		**TOPSOIL** : 2" Topsoil with silt and gravel, some organics. Brown, dry	0			SS1	63%	21	OC Pest PAH			CONCRETE	
0.76 / *255.54*		**GRAVEL** : Sand, stones. White to light brown, moist											
		SILT : Sand, trace gravel. Black/brown, dry	0			SS2	79%	10	Metals & Inorg.				
		Trace clay											
			0			SS3	88%	20				BENTONITE	
			5			SS4	100%	28					
			0			SS5	100%	28					
4.57 / *251.73*		**CLAY** : Grey, moist to wet	0			SS6	100%	10	PHC VOC			SAND	
		Trace sand and gravel, moist to dry										SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	
		1" sand seam	0			SS7	100%	27					
7.62 / *248.69*		*Auger refusal*									WATER MARKER Depth : 3.11 m Elev. : 253.196 m Date : 2021-11-30		

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-26**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-28
Date (End):	2021-10-28
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	592761.742 m
Northing:	4842374.548 m
Surface Elevation:	260.076 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
260.08																
0.5		**SILT** : Trace sand, gravel, organics. Dark brown, moist	0						MA1	46%		PCB OC Pest				
1.0		*No organics*	0						MA2	58%		PAH				
1.5		*wet*	0						MA3	92%		Metals & Inorg.				
1.83																
258.25																
2.0																
2.5																
3.0																
3.5																
4.0																
4.5																
5.0																
5.5																
6.0																
6.5																
7.0																
7.5																
8.0																
8.5																
9.0																
9.5																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-27**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-28
Date (End):	2021-10-28
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	591431.505 m
Northing:	4844553.405 m
Surface Elevation:	269.879 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	LITHOLOGY / GEOLOGY: DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
269.88		**SILT** : Sand, some gravel, organics. Dark brown, moist	*0*			MA1	17%		Metals & Inorg.				
0.5		*Trace gravel, no organics, brown*											
1.0			*0*			MA2	38%		PCB OC Pest				
		Dry											
1.5			*0*			MA3	79%		PAH				
1.83													
268.05													
2.0													
2.5													
3.0													
3.5													
4.0													
4.5													
5.0													
5.5													
6.0													
6.5													
7.0													
7.5													
8.0													
8.5													
9.0													
9.5													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-28**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-08
Date (End):	2021-11-08
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	590337.644 m
Northing:	4845475.407 m
Surface Elevation:	281.403 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
281.40 0.20		**SILT** : Trace gravel, organics. Brown, dry										CONCRETE	
281.20		**SILT** : Sand, trace clay, trace gravel. Brown, dry	0			SS1	33%	3	Metals & Inorg.	QAQC-3			
1.0			10			SS2	79%	17	BTEX pH	QAQC-4			
2.0			0			SS3	92%	26	OC Pest PCB PAH	QAQC-5			
2.5			0			SS4	96%	25				BENTONITE	
3.05													
278.36		**CLAY** : Trace silt, trace gravel. Grey, moist	0			SS5	92%	19					
4.5		*saturated, trace sand*	0			SS6	100%	10					
6.5			0			SS7	88%	13					
7.5												SAND	
8.0			0			SS8	100%	23				SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	
9.0		*moist, dense*											
9.5			0			SS9	88%	23				BENTONITE WATER MARKER Depth : 0.61 m Elev. : 280.793 m Date : 2021-11-29	
9.75													
271.65													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-29**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-28
Date (End):	2021-10-28
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	589576.152 m
Northing:	4845657.51 m
Surface Elevation:	286.345 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	LITHOLOGY / GEOLOGY: DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	OBSERVATIONS: ODOUR (L M S)	OBSERVATIONS: VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	SAMPLES: % RECOVERY	SAMPLES: N (Blow/15cm)	SAMPLES: CHEMICAL ANALYSIS	SAMPLES: DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
286.35 0.20 *286.14*		**SILT** : Trace sand, organics. Brown, moist	0			MA1	33%		PCB OC Pest				
0.5		**SILT** : Sand, trace gravel. Brown, moist											
1.0		*Dry*	0			MA2	54%		Metals & Inorg.				
1.5			0			MA3	67%		PAH				
1.83 *284.52*													
2.0													
2.5													
3.0													
3.5													
4.0													
4.5													
5.0													
5.5													
6.0													
6.5													
7.0													
7.5													
8.0													
8.5													
9.0													
9.5													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-3**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS		SURVEY DETAILS		ODOUR	SAMPLE TYPE	CHEMICAL ANALYSIS	
Date (Start):	2021-12-02	Easting:	599498.283 m	L - Light	DC - Diamond Corer	Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Date (End):	2021-12-02	Northing:	4833071.687 m	M - Medium	SS - Split Spoon	Inorg.	Inorganic Compounds
Drilling Company:	Davis Drilling	Surface Elevation:	186.453 masl	S - Strong	MA - Manual Auger	PHC	Petroleum Hydrocarbons (F1-F4)
Drilling Equipment:	CME 55	Top of Well Elevation:	masl	VISUAL	TR - Trowel	BTEX	Benzene, Toluene, Ethylbenzene, Xylene
Drilling Method:	Hollow Stem Auger			D - Dispersed with Product	ST - Shelby Tube	VOC	Volatile Organic Compounds
Borehole Diameter:	203 mm			S - Saturated with Product	DT - Dual Tube	PAH	Polycyclic Aromatic Hydrocarbons
Drilling Fluid:	None				MC - Macro Core	PCB	Polychlorinated Biphenyl
					NR - No Recovery	D/F	Dioxins & Furans
						Phenol	Phenolic Compounds
						GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	LITHOLOGY / GEOLOGY: DESCRIPTION	OBSERVATIONS: PID / *CGD* (ppm)	OBSERVATIONS: ODOUR (L M S)	OBSERVATIONS: VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	SAMPLES: % RECOVERY	SAMPLES: N (Blow/15cm)	SAMPLES: CHEMICAL ANALYSIS	SAMPLES: DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
0.05 *186.40*		**SILT** : 2" Fill, sand and gravel, dark brown, organics, wet				SS1	75%	3	Metals & Inorg.	QAQC-12		CONCRETE	
0.76 *185.69*		**SILT** : Sand, trace gravel and organics. Brown, wet											
		SILT : Clay, grey/brown, wet				SS2	67%	9					
1.52 *184.93*		**CLAY** : Silt, brown/grey, moist, soft				SS3	88%	5				BENTONITE	
2.59 *183.86*		*Rock/gravel*				SS4	96%	13					
3.15 *183.30*		**CLAY** : Sand, trace gravel. Grey, dry, brittle				SS5	100%	7					
		CLAY : Grey, moist, soft											
		saturated				SS6	100%	5	PHC BTEX			SAND	
		moist				SS7	100%	6				SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	
		wet, soft				SS8	100%	9				BENTONITE	
						SS9	100%	2				WATER MARKER Depth : 8.32 m Elev. : 178.133 m Date : 2021-12-06	
9.75 *176.70*													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-30**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-08
Date (End):	2021-11-08
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	589518.806 m
Northing:	4845691.371 m
Surface Elevation:	286.973 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
0.00 / *286.97*															CONCRETE (FLUSH MOUNT)	
0.10 / *286.87*		**SAND** : Trace organics, gravel. Light brown, dry	0						SS1	79%	5	PCB OC Pest PAH				
0.5		**SILT** : Sand, trace gravel. Brown, dry														0.5
1.0			0						SS2	79%	6	Metals & Inorg.				1.0
1.52 / *285.45*		**SILT** : Clay, trace gravel and sand. Brown/grey, moist	5						SS3	75%	11	PHC BTEX				1.5
2.0																2.0
2.5			0						SS4	92%	22				BENTONITE	2.5
3.05 / *283.93*		**SILT** : Sand, some gravel. Brown, moist														3.0
3.5			0						SS5	92%	25					3.5
4.0																4.0
4.5																4.5
5.0			0						SS6	67%	80					5.0
5.5																5.5
6.10 / *280.88*		**CLAY** : Trace gravel. Grey, dry, brittle														6.0
6.5			0						SS7	96%	47					6.5
7.0																7.0
7.5		*wet*													SAND	7.5
8.0			0						SS8	100%	43				SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	8.0
8.5																8.5
9.0																9.0
9.17 / *277.80*																
9.45 / *277.52*		**ROCK** : Pulverized rock, limestone pieces. Some brown sandy silt, dry.	0						SS9	100%	N/A				BENTONITE	9.5

WATER MARKER
Depth : 2.17 m
Elev. : 284.803 m
Date : 2021-11-29

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-31**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-05
Date (End):	2021-11-05
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	586609.162 m
Northing:	4847307.111 m
Surface Elevation:	281.208 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	LITHOLOGY / GEOLOGY: DESCRIPTION	OBSERVATIONS: PID / *CGD* (ppm)	ODOUR (L M S)	VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
281.21		**SILT** : Sand, trace gravel and organics. Brown, moist	*0*			MA1	38%		Metals & Inorg.				
1.27			*0*			MA2	75%		PCB OC Pest				
279.94		**CLAY** : Silt, trace gravel. Grey/brown, moist	*0*			MA3	63%		PAH				
1.83													
279.38													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-32**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-15
Date (End):	2021-11-15
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	585943.467 m
Northing:	4849639.292 m
Surface Elevation:	273.744 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE
273.74		**SILT** : Sand, trace gravel and organics. Brown/black, moist	0						SS1	33%	2	Metals & Inorg.	
			0						SS2	79%	5		
			0						SS3	75%	4	OC Pest PAH	
			0						SS4	75%	4	PHC BTEX	
3.33 *270.42*		**SAND** : Ligth brown, moist to wet	0						SS5	75%	11		
			0						SS6	75%	27		
		Saturated											
6.45 *267.29*		**ROCK FRAGMENTS** : Pulverized rock, some sand and gravel, moist	0						SS7	83%	25		
			0						SS8	42%	N/A		
9.14 *264.60*		**SAND** : Trace silt. Brown, saturated	0						SS9	67%	>100		
9.60 *264.14*													

MONITORING WELL

DIAGRAM / DESCRIPTION

- CONCRETE
- BENTONITE
- SAND
- SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10
- BENTONITE
- WATER MARKER Depth : 6.1 m Elev. : 267.644 m Date : 2021-11-23

REMARKS

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-33**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-28
Date (End):	2021-10-28
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	584917.474 m
Northing:	4851058.052 m
Surface Elevation:	289.94 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
0.13 *289.81*		**TOPSOIL** : Some sandy silt, gravel, organics. Dark brown, moist	*0*						MA1	21%		PAH				
		SAND : Silt, trace gravel. Brown, moist	*0*						MA2	42%		PCB OC Pest				
1.83 *288.11*			*0*						MA3	33%		Metals & Inorg.				

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-34**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-28
Date (End):	2021-10-28
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	583329.038 m
Northing:	4851090.509 m
Surface Elevation:	306.709 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
0.00 / *306.71*																
306.63		**GRAVEL** : Some rocks and silt. Dark brown, wet	0						MA1	71%		PCB OC Pest	QAQC-1			
0.5		**SILT** : Sand, some gravel. Brown, wet														0.5
1.0			0						MA2	100%		Metals & Inorg.	QAQC-2			1.0
1.5		*Moist*	0						MA3	100%		PAH	QAQC-3			1.5
1.83 / *304.88*																
2.0																2.0
2.5																2.5
3.0																3.0
3.5																3.5
4.0																4.0
4.5																4.5
5.0																5.0
5.5																5.5
6.0																6.0
6.5																6.5
7.0																7.0
7.5																7.5
8.0																8.0
8.5																8.5
9.0																9.0
9.5																9.5

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-35**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-27
Date (End):	2021-10-27
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	584917.477 m
Northing:	4851058.087 m
Surface Elevation:	289.961 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR (L M S)	VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
289.96													
0.61		**SILT** : Sand, some gravel, rocks, organics, dark brown, moist *Light brown, dry*	*0*			MA1	58%		Metals & Inorg.				
289.35		**SILT** : Some gravel, trace sand, brown, moist *rocks*	*0*			MA2	54%		PCB OC Pest				
1.83			*0*			MA3	42%		PAH				
288.13													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-36**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-16
Date (End):	2021-11-16
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	580618.808 m
Northing:	4850400.306 m
Surface Elevation:	326.001 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
0.00 / *325.95*		**GRAVEL** : Some sand. Brown/black, dry										CONCRETE	
0.5		**SILT** : Trace gravel. Dark brown, moist	0			SS1	58%	7	Metals & Inorg.				
1.0			0			SS2	63%	9					
1.5 / 1.58 / *324.43*		**SAND** : Silt, light brown, moist	5			SS3	83%	8	PAH OC Pest			BENTONITE	
2.0		*Pulverized rock and gravel*	0			SS4	42%	9					
2.5													
3.0			0			SS5	63%	7					
3.5													
4.0													
4.5		*Light brown, wet*	0			SS6	92%	3	PHC VOC				
5.0													
5.5												SAND	
6.0			0			SS7	88%	25				SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	
6.5													
7.0													
7.5 / 7.71 / *318.29*		*dry*											
8.0		**ROCK FRAGMENTS** : Shale and limestone fragments, dry	0			SS8	25%	N/A					
8.5												BENTONITE	
9.0 / 9.14 / *316.86*												WATER MARKER Depth : 7.39 m Elev. : 318.611 m Date : 2021-11-22	
9.5 / *316.70*		**SILT** : Red/brown, moist, some rock chips	0			SS9	100%	N/A	WATER MARKER			Depth : 7.5 m Elev. : 318.501 m Date : 2021-11-23	

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-37**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-27
Date (End):	2021-10-27
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	m
Northing:	m
Surface Elevation:	masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	LITHOLOGY / GEOLOGY: DESCRIPTION	OBSERVATIONS: PID / *CGD* (ppm)	OBSERVATIONS: ODOUR (L M S)	OBSERVATIONS: VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	SAMPLES: % RECOVERY	SAMPLES: N (Blow/15cm)	SAMPLES: CHEMICAL ANALYSIS	SAMPLES: DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
0.5		**SILT** : Sand, trace gravel, organics, dark brown, moist	0			MA1	42%		PCB OC Pest				
1.0			0			MA2	33%		Metals & Inorg.				
1.5		*brown, no organics*	0			MA3	42%		PAH				
1.83													

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-38**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-27
Date (End):	2021-10-27
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	578555.328 m
Northing:	4852070.44 m
Surface Elevation:	365.999 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
366.00		**SAND** : Silt, trace gravel, organics/roots, dark brown, moist	*0*						MA1	33%		PAH				
			0						MA2	25%		PCB OC Pest				
1.27																
364.73		**SAND** : brown, moist to wet	*0*						MA3	58%		Metals & Inorg.				
1.83																
364.17																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-39**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-05
Date (End):	2021-11-05
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	578788.309 m
Northing:	4852893.463 m
Surface Elevation:	379.769 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
379.77 0.18																
379.59		**SILT** : Sand, some gravel and organics. Dark brown, moist	0						MA1	29%		Metals & Inorg.				
0.5		: No recovery														
			0						MA2	0%						
1.0																
1.22																
378.55		**SILT** : Clay, trace gravel. Brown, wet to moist	0						MA3	100%		PAH PCB OC Pest				
1.5																
1.83																
377.94																
2.0																
2.5																
3.0																
3.5																
4.0																
4.5																
5.0																
5.5																
6.0																
6.5																
7.0																
7.5																
8.0																
8.5																
9.0																
9.5																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-4**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-12-06
Date (End):	2021-12-06
Drilling Company:	Geotech Support Services
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	599341.718 m
Northing:	4833956.053 m
Surface Elevation:	196.991 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
196.99		**SILT** : Sand, organics, some gravel. Dark brown, moist, soft	*0*						MA1	29%		Metals & Inorg. PAH				
0.5		*Trace gravel, brown*														
1.0			*0*						MA2	25%		OC Pest PCB				
1.5		*moist to dry*	*0*						MA3	58%		PHC BTEX				
1.83																
195.16																
2.0																
2.5																
3.0																
3.5																
4.0																
4.5																
5.0																
5.5																
6.0																
6.5																
7.0																
7.5																
8.0																
8.5																
9.0																
9.5																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-40**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-10-27
Date (End):	2021-10-27
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	578937.278 m
Northing:	4853367.264 m
Surface Elevation:	382.315 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	MONITORING WELL: DESCRIPTION	REMARKS
382.32 0.20																
382.11		**SAND** : Silt, trace gravel, organics/roots, dark brown, moist	*0*						MA1	33%		PCB OC Pest PAH				
		: No recovery - Assumed Silty Sand							MA2	0%						
1.22 *381.10*		**SAND** : silt, trace gravel, light to dark brown, moist to wet	*0*						MA3	42%		Metals & Inorg. PAH				
1.83 *380.49*																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-41**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-05
Date (End):	2021-11-05
Drilling Company:	
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	82.5 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	578368.166 m
Northing:	4854298.288 m
Surface Elevation:	392.706 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
392.71 0.0																
0.61		**SILT** : Sand, trace gravel and organics. Dark brown, moist	*0*						MA1	38%		PAH				
392.10 1.0		**SAND** : Silt, some gravel. Light brown, moist	*5*						MA2	42%		Metals & Inorg. OC Pest PCB				
1.22																
391.49 1.5		: No recovery							MA3	0%						
1.83																
390.88 2.0																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

BOREHOLE DRILLING RECORD : **BH21-42**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-18
Date (End):	2021-11-18
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	601689.807 m
Northing:	4830813.835 m
Surface Elevation:	174.252 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
174.25 0.23																
174.02		**SILT** : Sand, organics, some gravel and rock fragments. Dark brown/black	*0*						SS1	67%	5	Metals & Inorg.				
0.5		**SILT** : Clay, trace sand. Brown/grey, moist														0.5
1.0		*grey, saturated*	*0*						SS2	75%	5	PCB PAH				1.0
1.5																1.5
2.0			*0*						SS3	88%	6	PHC BTEX				2.0
2.5			*0*						SS4	100%	3					2.5
3.0		*gravel*														3.0
3.5			*0*						SS5	100%	54					3.5
4.0																4.0
4.5																4.5
4.57 *169.68*		**CLAY** : Grey, saturated	*0*						SS6	100%	7					
5.0																5.0
5.5																5.5
6.0																6.0
6.10 *168.16*		**CLAY** : Sand, trace gravel. Grey, dry, brittle	*5*						SS7	83%	16					
6.5																6.5
7.0																7.0
7.5		*moist to wet*														7.5
8.0			*0*						SS8	100%	12					8.0
8.5																8.5
9.0		*lightly moist*														9.0
9.5			*0*						SS9	88%	19					9.5
9.75 *164.50*																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

BOREHOLE DRILLING RECORD : **BH21-43**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-17
Date (End):	2021-11-17
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	601685.523 m
Northing:	4830747.576 m
Surface Elevation:	172.817 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
0.05 / *172.77*		**SILT** : Sand, rocks, gravel, organics, dark brown, dry	0						SS1	33%	4	PCB OC Pest PAH				
0.5		**SAND** : Trace gravel, brown, dry														0.5
1.0		*moist*	0						SS2	79%	3	Metals & Inorg.				1.0
1.14 / *171.67*		**SAND** : Silt, trace gravel, black staining, moist														
1.5																1.5
1.55 / *171.27*		**SILT** : Sand, trace gravel, brown, moist to wet	0						SS3	75%	6					
2.0		*trace clay*														2.0
2.5			5						SS4	96%	10					2.5
3.0																3.0
3.5			0						SS5	100%	21					3.5
4.0																4.0
4.5																4.5
4.60 / *168.22*		**CLAY** : Trace gravel, grey, moist	0						SS6	92%	7	PHC BTEX				
5.0																5.0
5.5																5.5
6.0		*some gravel, dry*														6.0
6.5			0						SS7	96%	19					6.5
7.0																7.0
7.5																7.5
8.0			0						SS8	100%	10					8.0
8.5																8.5
9.0		*trace gravel, brittle*														9.0
9.5			0						SS9	100%	16					9.5
9.75 / *163.06*																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-44**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-17
Date (End):	2021-11-17
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	601697.384 m
Northing:	4830930.728 m
Surface Elevation:	172.953 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE
0.05 / *172.90*		**GRAVEL** : Silt, sand, rock fragments, organics, dark brown, dry	0						SS1	54%	8	Metals & Inorg.	
		SILT : Sand, trace clay, light brown, wet											
1.37 / *171.58*		: No recovery	0						SS2	75%	4	PCB PAH OC Pest	
									SS3	0%	5		
2.29 / *170.67*		**CLAY** : Grey, saturated	0						SS4	100%	0	PHC BTEX	
			0						SS5	100%	2		
			0						SS6	100%	1		
6.10 / *166.86*													
6.30 / *166.65*		**SAND** : some gravel, grey, saturated	0						SS7	75%	11		
		CLAY : Sand, trace gravel, grey, moist											
			0						SS8	88%	10		
		some gravel, saturated	0						SS9	67%	12		
9.75 / *163.20*													

MONITORING WELL

DIAGRAM	DESCRIPTION
	CONCRETE (FLUSH MOUNT)
	BENTONITE
	SAND
	SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10
	BENTONITE
	WATER MARKER Depth : 1.6 m Elev. : 171.353 m Date : 2021-11-22 WATER MARKER Depth : 1.79 m Elev. : 171.163 m Date : 2021-11-23

REMARKS

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-45**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-22
Date (End):	2021-11-22
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	599230.972 m
Northing:	4837798.759 m
Surface Elevation:	218.122 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	REMARKS
218.12		**SILT** : Sand, some gravel and rocks. Dark brown/black, wet	0			SS1	38%	13	PCB PAH OC Pest		
0.76											
217.36		**SILT** : Sand, trace gravel. Light brown/grey, moist	0			SS2	58%	6	Metals & Inorg.		
		dry	0			SS3	75%	20			
			0			SS4	96%	26			
			0			SS5	100%	17			
4.57											
213.55		**CLAY** : Sand, some gravel. Light brown/grey, dry	0			SS6	92%	11			
6.10											
212.03		**CLAY** : Trace sand, trace gravel. Grey, moist to wet	0			SS7	92%	10			
		Saturated	0			SS8	29%	>50	PHC VOC		
9.14											
208.98		**SAND** : Silt, some gravel. Brown/red, wet				SS9	100%	>50			
9.45											
208.67											

MONITORING WELL

DIAGRAM / DESCRIPTION:
- CONCRETE (FLUSH MOUNT)
- BENTONITE
- SAND
- SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10
- WATER MARKER Depth : 4.17 m Elev. : 213.952 m Date : 2021-11-30
- BENTONITE
- WATER MARKER Depth : 5.16 m Elev. : 212.962 m Date : 2021-12-01

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

AUGER MANUAL DRILLING RECORD : **BH21-5**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-12-06
Date (End):	2021-12-06
Drilling Company:	Geotech Support Services
Drilling Equipment:	Hand Auger
Drilling Method:	Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	599776.087 m
Northing:	4835898.209 m
Surface Elevation:	213.824 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
213.82																
0.5		**SILT** : Sand, organics, trace gravel. Dark brown, moist, soft	0						MA1	33%		Metals & Inorg. PAH				
1.0		←*brown*	0						MA2	58%		PHC BTEX				
1.5		←*dry, brittle*	0						MA3	33%		OC Pest PCB				
1.83																
212.00																
2.0																
2.5																
3.0																
3.5																
4.0																
4.5																
5.0																
5.5																
6.0																
6.5																
7.0																
7.5																
8.0																
8.5																
9.0																
9.5																

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-6**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-12-01
Date (End):	2021-12-01
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	599720.793 m
Northing:	4836847.647 m
Surface Elevation:	216.805 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
0.10 / *216.81*													
216.70		**SILT** : Sand, rocks, gravel (ballast). Dark brown/black, moist	0			SS1	58%	6	PAH			CONCRETE	
0.5		**SILT** : Sand, trace gravel, trace clay. Brown, moist											0.5
1.0		*dry, brittle*	0			SS2	96%	37	Metals & Inorg.			BENTONITE	1.0
1.5													1.5
2.0			0			SS3	71%	>82					2.0
2.5		*dark brown, moist*	0			SS4	88%	80					2.5
3.0													3.0
3.15 / *213.66*		**ROCK** : Pulverized rock and dust, dry. Refusal	0			SS5	38%	>92					3.5
3.66 / *213.15*		**SAND** : Silt, trace gravel. Brown, saturated										SAND	4.0
4.5												SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	4.5
5.03 / *211.78*		**ROCK** : Pulverized rock and gravel, dry	0			SS6	67%	>82	PHC BTEX				5.0
5.5													5.5
6.0													6.0
6.20 / *210.61*												BENTONITE	
6.40 / *210.40*		**RED SHALE** : Red shale chips and intact shale, layered, weathered, dry.	0			SS7	83%	N/A					6.5
7.0												WATER MARKER Depth : 0.23 m Elev. : 216.575 m Date : 2021-12-06 WATER MARKER Depth : 0.27 m Elev. : 216.535 m Date : 2021-12-02	7.0
7.5													7.5
8.0													8.0
8.5													8.5
9.0													9.0
9.5													9.5

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-7**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-29
Date (End):	2021-11-29
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	599718.378 m
Northing:	4836942.437 m
Surface Elevation:	217.859 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L M S	VISUAL D S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE
217.86 0.0		**SILT** : Sand, trace gravel and organics. Dark brown, moist	0			SS1	71%	4	PCB PAH OC Pest	
		trace clay. brown/grey, moist to dry, soft to brittle	0			SS2	88%	8	Metals & Inorg.	
		more gravel, less clay content. dry, brittle	5			SS3	96%	22		
			0			SS4	58%	>60		
3.05										
214.81		**SAND** : Silt, some rocks and gravel. Moist/wet	0			SS5	63%	>93	PHC VOC	
4.57										
213.29		**CLAY** : Sand, trace gravel. Grey, moist to dry	0			SS6	92%	32		
6.10										
211.76		**SAND** : Trace clay and gravel, rocks. Grey/brown, wet	0			SS7	63%	58		
6.71										
211.15		**RED SHALE** : Rel shale chips, dry, some gravel								
7.92			0			SS8	100%	N/A		
209.93										

MONITORING WELL

DIAGRAM / DESCRIPTION

- CONCRETE
- BENTONITE
- SAND
- SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10
- BENTONITE

WATER MARKER
Depth : 2.03 m
Elev. : 215.829 m
Date : 2021-12-01
WATER MARKER
Depth : 2.17 m
Elev. : 215.689 m
Date : 2021-12-02

REMARKS

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-8**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-29
Date (End):	2021-11-29
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	599706.937 m
Northing:	4837085.66 m
Surface Elevation:	219.165 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	STRATIGRAPHY	DESCRIPTION	PID / *CGD* (ppm)	ODOUR L	ODOUR M	ODOUR S	VISUAL D	VISUAL S	SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL DIAGRAM	MONITORING WELL DESCRIPTION	REMARKS
219.17 0.0		**SILT** : Sand, organics, trace gravel. Dark brown, moist, soft	5						SS1	33%	5	PAH			CONCRETE	
0.5																0.5
1.0			0						SS2	42%	14	Metals & Inorg.				1.0
1.5		*moist to dry*														1.5
2.0			0						SS3	92%	21					2.0
2.5		*dry, brittle*	0						SS4	100%	40				BENTONITE	2.5
3.0		*moist/dry, rocks*														3.0
3.5			0						SS5	92%	32					3.5
4.0																4.0
4.5 *4.57*																4.5
214.59 5.0		**CLAY** : Trace gravel, grey, moist/wet	0						SS6	96%	29					5.0
5.5																5.5
6.0 6.10																6.0
213.07 6.5 6.61		**SAND** : Trace gravel. Grey, saturated	0						SS7	100%	27	PHC VOC			SAND	6.5
212.55 7.0		**GRAVEL** : Rock fragments, some sand, wet														7.0
7.5 7.80															SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	7.5
211.36 8.0		**CLAY** : Sand, trace gravel. Grey, wet	0						SS8	100%	28					8.0
8.5																8.5
9.0		*rock fragments*													WATER MARKER	9.0
9.45			0						SS9	38%	N/A				Depth : 3.19 m Elev. : 215.975 m Date : 2021-12-02	
9.5 *209.72*														BENTONITE	Depth : 3.34 m Elev. : 215.825 m Date : 2021-12-01	9.5

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

OBSERVATION WELL DRILLING RECORD : **BH21-9**

Project Number: **211-10139-00**

Former Orangeville Rail
Limited Phase II Environmental Assessment
Region of Peel

DRILLING DETAILS

Date (Start):	2021-11-04
Date (End):	2021-11-04
Drilling Company:	Davis Drilling
Drilling Equipment:	CME 55
Drilling Method:	Hollow Stem Auger
Borehole Diameter:	203 mm
Drilling Fluid:	None

SURVEY DETAILS

Easting:	573372.335 m
Northing:	4862428.345 m
Surface Elevation:	422.953 masl
Top of Well Elevation:	masl

ODOUR
L - Light
M - Medium
S - Strong

VISUAL
D - Dispersed with Product
S - Saturated with Product

SAMPLE TYPE
DC - Diamond Corer
SS - Split Spoon
MA - Manual Auger
TR - Trowel
ST - Shelby Tube
DT - Dual Tube
MC - Macro Core
NR - No Recovery

CHEMICAL ANALYSIS

Metals	Sb As Ba Be B Cd Cr Co Cu Pb Mo Ni Se Ag Tl U V Zn
Inorg.	Inorganic Compounds
PHC	Petroleum Hydrocarbons (F1-F4)
BTEX	Benzene, Toluene, Ethylbenzene, Xylene
VOC	Volatile Organic Compounds
PAH	Polycyclic Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
D/F	Dioxins & Furans
Phenol	Phenolic Compounds
GSA	Grain-size Analysis

(m) DEPTH / *ELEVATION* (masl)	LITHOLOGY / GEOLOGY: STRATIGRAPHY	DESCRIPTION	OBSERVATIONS: PID *CGD* (ppm)	ODOUR (L M S)	VISUAL (D S)	SAMPLES: SAMPLE TYPE & No.	% RECOVERY	N (Blow/15cm)	CHEMICAL ANALYSIS	DUPLICATE	MONITORING WELL: DIAGRAM	DESCRIPTION	REMARKS
0.00 / *422.90*		**TOPSOIL** : Rootlets, organics, some gravel.	0			SS1	88%	6	PCB OC Pest			CONCRETE	
0.84 / *422.11*		**GRAVEL** : Sandy silt, rock fragments. Dark brown, dry										BENTONITE	
		SILT : Sand. Brown, moist	5			SS2	75%	4	Metals & Inorg.				
1.58 / *421.38*		**SAND** : Silt, some gravel, rock fragments. Brown, moist	0			SS3	79%	37	PAH				
		wet											
2.39 / *420.57*		**SILT** : Trace gravel, brown, wet	0			SS4	42%	N/A					
			0			SS5	63%	38	PHC BTEX			SAND	
												SCREEN Length: 3.05 m Diam.: 51 mm Slot: #10	
4.57 / *418.38*		**ROCK FRAGMENTS** : Gravel, pulverized rock (shale and limestone). Brown, wet	0			SS6	58%	12					
												BENTONITE	
6.16 / *416.80*		*Auger refusal*	0			SS7	83%	N/A					

Project : GINT LOGS ORBY.GPJ Report : WSP_EN_WELL-ENVIRONMENTAL 2022-1-5

Prepared by: Joanna West
Reviewed by: Chris Johnston

APPENDIX

B CERTIFICATES OF ANALYSIS

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Marsad Jafar
PROJECT: 211-10139-00 Phase 200 02
AGAT WORK ORDER: 21T843989
TRACE ORGANICS REVIEWED BY: Inga Kuzmina, Trace Organics Lab Manager
DATE REPORTED: Dec 15, 2021
PAGES (INCLUDING COVER): 5
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- *All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.*
- *All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.*
- *AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.*
- *This Certificate shall not be reproduced except in full, without the written approval of the laboratory.*
- *The test results reported herewith relate only to the samples as received by the laboratory.*
- *Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.*
- *All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.*

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T843989

PROJECT: 211-10139-00 Phase 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F2 - F4 (Water)

DATE RECEIVED: 2021-12-13

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-30
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-13
Parameter	Unit	G / S	RDL	3337872
F2 (C10 to C16)	µg/L	150	100	<100
F3 (C16 to C34)	µg/L	500	100	<100
F4 (C34 to C50)	µg/L	500	100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA
Sediment				No
Surrogate	Unit	Acceptable Limits		
Terphenyl	%	60-140		111

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3337872 The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and nC34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16 - C50 and are only determined if the chromatogram of the C34 - C50 Hydrocarbons indicated that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 2-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T843989

PROJECT: 211-10139-00 Phase 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F2 - F4 (Water)															
F2 (C10 to C16)	3285019		< 100	< 100	NA	< 100	102%	60%	140%	85%	60%	140%	95%	60%	140%
F3 (C16 to C34)	3285019		< 100	< 100	NA	< 100	106%	60%	140%	76%	60%	140%	86%	60%	140%
F4 (C34 to C50)	3285019		< 100	< 100	NA	< 100	85%	60%	140%	74%	60%	140%	87%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T843989

PROJECT: 211-10139-00 Phase 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC E3421	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC E3421	GC/FID
Sediment			

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP
Contact: Marsad Jafar
Address: 2 International Blvd
Phone: 437-233-2935 Fax:
Reports to be sent to:
1. Email: marsad.jafar@wsp.com
2. Email: vanessa.etinger@wsp.com

Project Information:

Project: 211-10139-00 Phase 200 02
Site Location: ORBY
Sampled By: Marsad Jafar
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☐ Ind/Com
☑ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use
☐ Sanitary ☐ Storm
____ (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition**? ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Laboratory Use Only

Work Order #: 21T843989
Cooler Quantity: 1 blue
Arrival Temperatures: 6.6 | 6.5
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: Free Jaf

Turnaround Time (TAT) Required:

Regular TAT ☐ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☑ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	BTEX, F1-F4 PHCs - Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558: Landfill Disposa Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-30	Dec 13/21	AM	2	GW	F1-F4 PHCs only				X								
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															

21 DEC 13 5:37 PM

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Marsad Jafar	12/13/2021	5:25 pm	NEAL G		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

Page 1 of 1

Nº: T 126742

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065

ATTENTION TO: Vanessa Oetinger

PROJECT: 211-10139-00

AGAT WORK ORDER: 21T822752

SOIL ANALYSIS REVIEWED BY: Jacky Zhu, Spectroscopy Technician

TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor

DATE REPORTED: Nov 08, 2021

PAGES (INCLUDING COVER): 21

VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-10-28

DATE REPORTED: 2021-11-08

SAMPLE DESCRIPTION:				BH21-10 S1	BH21-14 S2	BH21-15 S3	BH21-26 S3	BH21-27 S1	BH21-29 S2	BH21-33 S3	BH21-34 S2
SAMPLE TYPE:				Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
DATE SAMPLED:				2021-10-27	2021-10-27	2021-10-27	2021-10-28	2021-10-28	2021-10-28	2021-10-28	2021-10-28
Parameter	Unit	G / S	RDL	3146311	3146324	3146340	3146354	3146364	3146370	3146415	3146420
Antimony	µg/g	40	0.8	3.5	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	µg/g	18	1	24	3	4	4	12	5	5	4
Barium	µg/g	670	2.0	44.5	49.6	26.5	47.6	54.2	99.0	99.2	58.5
Beryllium	µg/g	8	0.4	1.4	<0.4	<0.4	<0.4	0.5	0.7	0.6	0.4
Boron	µg/g	120	5	12	<5	<5	5	6	9	9	10
Boron (Hot Water Soluble)	µg/g	2	0.10	0.37	0.13	<0.10	<0.10	0.26	0.13	<0.10	<0.10
Cadmium	µg/g	1.9	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	µg/g	160	5	15	14	7	16	19	26	23	17
Cobalt	µg/g	80	0.5	9.3	4.6	3.3	9.4	6.8	11.1	11.9	7.4
Copper	µg/g	230	1.0	64.7	8.6	17.0	37.1	24.7	26.1	25.3	17.4
Lead	µg/g	120	1	52	8	5	7	15	9	9	5
Molybdenum	µg/g	40	0.5	8.2	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Nickel	µg/g	270	1	29	9	5	18	15	24	24	14
Selenium	µg/g	5.5	0.8	2.1	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	µg/g	40	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	µg/g	3.3	0.5	0.6	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	µg/g	33	0.50	0.73	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	µg/g	86	0.4	26.7	26.6	14.4	23.0	28.1	36.5	33.6	26.5
Zinc	µg/g	340	5	70	46	22	47	58	57	52	38
Chromium, Hexavalent	µg/g	8	0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	µg/g	3.9	0.10	<0.10	0.11	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	1.4	0.005	0.255	0.103	0.073	0.106	0.192	0.129	0.115	0.108
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	12	N/A	0.061	0.043	0.061	0.084	0.103	0.105	0.155	0.072
pH, 2:1 CaCl2 Extraction	pH Units	5.0-9.0	NA	7.24	7.27	7.80	7.79	7.70	7.71	7.80	7.87

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy


O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-10-28

DATE REPORTED: 2021-11-08

		SAMPLE DESCRIPTION:		QAQC-2	BH21-35 S1	BH21-37 S2	BH21-38 S3	BH21-40 S3
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-10-28	2021-10-27	2021-10-27	2021-10-27	2021-10-27
Parameter	Unit	G / S	RDL	3146421	3146433	3146450	3146454	3146457
Antimony	µg/g	40	0.8	<0.8	<0.8	1.0	<0.8	<0.8
Arsenic	µg/g	18	1	3	13	12	3	6
Barium	µg/g	670	2.0	57.0	53.8	41.3	16.9	29.6
Beryllium	µg/g	8	0.4	0.4	0.5	<0.4	<0.4	<0.4
Boron	µg/g	120	5	11	21	7	<5	7
Boron (Hot Water Soluble)	µg/g	2	0.10	<0.10	0.35	0.18	<0.10	0.20
Cadmium	µg/g	1.9	0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	µg/g	160	5	16	12	11	6	11
Cobalt	µg/g	80	0.5	7.4	10.2	5.4	2.5	4.5
Copper	µg/g	230	1.0	17.0	44.3	25.1	9.0	27.2
Lead	µg/g	120	1	5	13	18	4	20
Molybdenum	µg/g	40	0.5	<0.5	1.1	0.9	<0.5	0.9
Nickel	µg/g	270	1	13	19	11	4	10
Selenium	µg/g	5.5	0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	µg/g	40	0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	µg/g	3.3	0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	µg/g	33	0.50	<0.50	<0.50	<0.50	<0.50	<0.50
Vanadium	µg/g	86	0.4	25.2	15.4	19.1	9.4	19.3
Zinc	µg/g	340	5	36	63	33	14	33
Chromium, Hexavalent	µg/g	8	0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	µg/g	3.9	0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	1.4	0.005	0.101	0.217	0.136	0.082	0.328
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	12	N/A	0.070	0.095	0.036	0.051	0.025
pH, 2:1 CaCl2 Extraction	pH Units	5.0-9.0	NA	7.91	7.87	7.46	7.66	7.62

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-10-28


DATE REPORTED: 2021-11-08

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3146311-3146457 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-10-28

DATE REPORTED: 2021-11-08

		SAMPLE DESCRIPTION:		BH21-10 S2	BH21-14 S1	BH21-15 S2	BH21-26 S1	BH21-27 S2	BH21-29 S1	BH21-33 S2	BH21-34 S1
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-10-27	2021-10-27	2021-10-27	2021-10-28	2021-10-28	2021-10-28	2021-10-28	2021-10-28
Parameter	Unit	G / S	RDL	3146319	3146323	3146330	3146342	3146367	3146369	3146399	3146416
Gamma-Hexachlorocyclohexane	µg/g	0.056	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	µg/g	0.19	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Aldrin	µg/g	0.088	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	µg/g	0.3	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDD	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDD	µg/g	4.6	0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDE	ug/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDE	µg/g	0.52	0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDT	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDT	µg/g	1.4	0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	µg/g	0.088	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Methoxychlor	µg/g	1.6	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	µg/g	0.66	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	µg/g	0.031	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachloroethane	µg/g	0.21	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Aroclor 1242	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1248	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1254	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1260	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Polychlorinated Biphenyls	µg/g	1.1	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-10-28

DATE REPORTED: 2021-11-08

SAMPLE DESCRIPTION:				BH21-10 S2	BH21-14 S1	BH21-15 S2	BH21-26 S1	BH21-27 S2	BH21-29 S1	BH21-33 S2	BH21-34 S1
SAMPLE TYPE:				Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
DATE SAMPLED:				2021-10-27	2021-10-27	2021-10-27	2021-10-28	2021-10-28	2021-10-28	2021-10-28	2021-10-28
Parameter	Unit	G / S	RDL	3146319	3146323	3146330	3146342	3146367	3146369	3146399	3146416
Moisture Content	%		0.1	4.5	28.0	5.1	19.2	13.4	22.5	12.1	15.2
wet weight OC/PCB	g		NA	10.58	10.26	10.72	10.49	10.61	10.43	10.23	10.39
Surrogate	Unit	Acceptable Limits									
TCMX	%	50-140		71	78	90	83	74	79	80	80
Decachlorobiphenyl	%	50-140		81	80	97	87	98	83	89	101

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-10-28

DATE REPORTED: 2021-11-08

		SAMPLE DESCRIPTION:		QAQC-1	BH21-35 S2	BH21-37 S1	BH21-38 S2	BH21-40 S1
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-10-28	2021-10-27	2021-10-27	2021-10-27	2021-10-27
Parameter	Unit	G / S	RDL	3146417	3146434	3146439	3146453	3146456
Gamma-Hexachlorocyclohexane	µg/g	0.056	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	µg/g	0.19	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Aldrin	µg/g	0.088	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	µg/g	0.3	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDD	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDD	µg/g	4.6	0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDE	ug/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDE	µg/g	0.52	0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDT	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDT	µg/g	1.4	0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	µg/g	0.088	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Methoxychlor	µg/g	1.6	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	µg/g	0.66	0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	µg/g	0.031	0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachloroethane	µg/g	0.21	0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Aroclor 1242	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1248	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1254	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1260	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Polychlorinated Biphenyls	µg/g	1.1	0.10	<0.10	<0.10	<0.10	<0.10	<0.10

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-10-28

DATE REPORTED: 2021-11-08

		SAMPLE DESCRIPTION:		QAQC-1	BH21-35 S2	BH21-37 S1	BH21-38 S2	BH21-40 S1
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-10-28	2021-10-27	2021-10-27	2021-10-27	2021-10-27
Parameter	Unit	G / S	RDL	3146417	3146434	3146439	3146453	3146456
Moisture Content	%		0.1	15.4	16.6	14.1	13.1	26.4
wet weight OC/PCB	g		NA	10.01	10.67	10.87	10.69	10.62
Surrogate	Unit	Acceptable Limits						
TCMX	%	50-140		66	76	77	86	80
Decachlorobiphenyl	%	50-140		95	87	82	106	92

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3146319-3146456 Results are based on the dry weight of the soil.
DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-10-28

DATE REPORTED: 2021-11-08

		SAMPLE DESCRIPTION:		BH21-10 S3	BH21-14 S3	BH21-15 S2	BH21-26 S2	BH21-27 S3	BH21-29 S3	BH21-33 S1	BH21-34 S3
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-10-27	2021-10-27	2021-10-27	2021-10-28	2021-10-28	2021-10-28	2021-10-28	2021-10-28
Parameter	Unit	G / S	RDL	3146321	3146326	3146330	3146344	3146368	3146397	3146398	3146426
Naphthalene	µg/g	9.6	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	µg/g	0.15	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	µg/g	96	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	µg/g	62	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	µg/g	12	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	µg/g	0.67	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	µg/g	9.6	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Pyrene	µg/g	96	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benz(a)anthracene	µg/g	0.96	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	µg/g	9.6	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	µg/g	0.96	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	µg/g	0.96	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.76	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	µg/g	9.6	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
1 and 2 Methlynaphthalene	µg/g	76	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Moisture Content	%		0.1	8.8	7.6	5.1	13.7	10.0	13.8	23.6	15.0
Surrogate	Unit	Acceptable Limits									
Naphthalene-d8	%	50-140		105	89	114	93	98	98	98	85
Acridine-d9	%	50-140		98	81	78	92	86	85	88	96
Terphenyl-d14	%	50-140		77	105	86	105	95	105	86	105

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-10-28

DATE REPORTED: 2021-11-08

		SAMPLE DESCRIPTION:		QAQC-3	BH21-35 S3	BH21-37 S3	BH21-38 S1	BH21-40 S3
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-10-28	2021-10-27	2021-10-27	2021-10-27	2021-10-27
Parameter	Unit	G / S	RDL	3146427	3146436	3146451	3146452	3146457
Naphthalene	µg/g	9.6	0.05	<0.05	<0.05	<0.05	0.07	0.10
Acenaphthylene	µg/g	0.15	0.05	<0.05	<0.05	<0.05	<0.05	0.06
Acenaphthene	µg/g	96	0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	µg/g	62	0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	µg/g	12	0.05	<0.05	<0.05	<0.05	0.07	0.19
Anthracene	µg/g	0.67	0.05	<0.05	<0.05	<0.05	0.05	0.12
Fluoranthene	µg/g	9.6	0.05	<0.05	0.25	<0.05	0.14	0.47
Pyrene	µg/g	96	0.05	<0.05	0.18	<0.05	0.12	0.37
Benz(a)anthracene	µg/g	0.96	0.05	<0.05	0.08	<0.05	0.07	0.19
Chrysene	µg/g	9.6	0.05	<0.05	0.14	<0.05	0.11	0.16
Benzo(b)fluoranthene	µg/g	0.96	0.05	<0.05	0.19	<0.05	0.21	0.53
Benzo(k)fluoranthene	µg/g	0.96	0.05	<0.05	0.17	<0.05	0.23	0.50
Benzo(a)pyrene	µg/g	0.3	0.05	<0.05	0.06	<0.05	<0.05	0.09
Indeno(1,2,3-cd)pyrene	µg/g	0.76	0.05	<0.05	0.06	<0.05	0.09	0.20
Dibenz(a,h)anthracene	µg/g	0.1	0.05	<0.05	<0.05	<0.05	<0.05	0.05
Benzo(g,h,i)perylene	µg/g	9.6	0.05	<0.05	0.06	<0.05	0.13	0.20
1 and 2 Methlynaphthalene	µg/g	76	0.05	<0.05	<0.05	<0.05	<0.05	0.32
Moisture Content	%		0.1	17.8	13.9	16.0	23.6	17.7
Surrogate	Unit	Acceptable Limits						
Naphthalene-d8	%	50-140		98	127	85	63	99
Acridine-d9	%	50-140		78	101	96	64	85
Terphenyl-d14	%	50-140		88	67	92	83	96

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3146321-3146457 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3146311	BH21-10 S1	ON T3 S ICC CT	O. Reg. 153(511) - Metals & Inorganics (Soil)	Arsenic	µg/g	18	24

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail


AGAT WORK ORDER: 21T822752
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Nov 08, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3146311	3146311	3.5	3.0	NA	< 0.8	98%	70%	130%	109%	80%	120%	83%	70%	130%
Arsenic	3146311	3146311	24	24	0.0%	< 1	99%	70%	130%	106%	80%	120%	101%	70%	130%
Barium	3146311	3146311	44.5	46.4	4.2%	< 2.0	118%	70%	130%	105%	80%	120%	98%	70%	130%
Beryllium	3146311	3146311	1.4	1.4	NA	< 0.4	97%	70%	130%	93%	80%	120%	89%	70%	130%
Boron	3146311	3146311	12	12	NA	< 5	100%	70%	130%	103%	80%	120%	86%	70%	130%
Boron (Hot Water Soluble)	3146311	3146311	0.37	0.35	NA	< 0.10	93%	60%	140%	103%	70%	130%	91%	60%	140%
Cadmium	3146311	3146311	<0.5	<0.5	NA	< 0.5	116%	70%	130%	108%	80%	120%	93%	70%	130%
Chromium	3146311	3146311	15	15	NA	< 5	101%	70%	130%	102%	80%	120%	97%	70%	130%
Cobalt	3146311	3146311	9.3	9.1	2.2%	< 0.5	97%	70%	130%	103%	80%	120%	94%	70%	130%
Copper	3146311	3146311	64.7	67.8	4.7%	< 1.0	98%	70%	130%	105%	80%	120%	100%	70%	130%
Lead	3146311	3146311	52	54	3.8%	< 1	88%	70%	130%	89%	80%	120%	87%	70%	130%
Molybdenum	3146311	3146311	8.2	8.7	5.9%	< 0.5	100%	70%	130%	117%	80%	120%	109%	70%	130%
Nickel	3146311	3146311	29	28	3.5%	< 1	101%	70%	130%	101%	80%	120%	91%	70%	130%
Selenium	3146311	3146311	2.1	2.0	NA	< 0.8	105%	70%	130%	109%	80%	120%	97%	70%	130%
Silver	3146311	3146311	<0.5	<0.5	NA	< 0.5	98%	70%	130%	115%	80%	120%	96%	70%	130%
Thallium	3146311	3146311	0.6	0.6	NA	< 0.5	100%	70%	130%	107%	80%	120%	103%	70%	130%
Uranium	3146311	3146311	0.73	0.72	NA	< 0.50	95%	70%	130%	110%	80%	120%	104%	70%	130%
Vanadium	3146311	3146311	26.7	27.5	3.0%	< 0.4	94%	70%	130%	101%	80%	120%	99%	70%	130%
Zinc	3146311	3146311	70	67	4.4%	< 5	107%	70%	130%	113%	80%	120%	113%	70%	130%
Chromium, Hexavalent	3146311	3146311	<0.2	<0.2	NA	< 0.2	95%	70%	130%	101%	80%	120%	72%	70%	130%
Cyanide, Free	3145525		<0.040	<0.040	NA	< 0.040	109%	70%	130%	109%	80%	120%	94%	70%	130%
Mercury	3146311	3146311	<0.10	<0.10	NA	< 0.10	118%	70%	130%	107%	80%	120%	103%	70%	130%
Electrical Conductivity (2:1)	3146311	3146311	0.255	0.266	4.2%	< 0.005	99%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3146311	3146311	0.061	0.058	5.0%	NA									
pH, 2:1 CaCl2 Extraction	3151125		8.17	8.20	0.4%	NA	98%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T822752
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Nov 08, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - OC Pesticides + PCBs (Soil)															
Gamma-Hexachlorocyclohexane	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	87%	50%	140%	89%	50%	140%	102%	50%	140%
Heptachlor	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	98%	50%	140%	101%	50%	140%
Aldrin	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	98%	50%	140%	107%	50%	140%	95%	50%	140%
Heptachlor Epoxide	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	103%	50%	140%	102%	50%	140%
Endosulfan I	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	91%	50%	140%	97%	50%	140%	106%	50%	140%
Endosulfan II	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	89%	50%	140%	99%	50%	140%	85%	50%	140%
Alpha-Chlordane	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	104%	50%	140%	82%	50%	140%
gamma-Chlordane	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	90%	50%	140%	105%	50%	140%	85%	50%	140%
op'-DDD	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	78%	50%	140%	109%	50%	140%	92%	50%	140%
pp'-DDD	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	86%	50%	140%	92%	50%	140%	102%	50%	140%
op'-DDE	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	86%	50%	140%	108%	50%	140%	95%	50%	140%
pp'-DDE	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	87%	50%	140%	107%	50%	140%	105%	50%	140%
op'-DDT	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	96%	50%	140%	106%	50%	140%	105%	50%	140%
pp'-DDT	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	87%	50%	140%	94%	50%	140%	106%	50%	140%
Dieldrin	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	109%	50%	140%	104%	50%	140%	99%	50%	140%
Endrin	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	84%	50%	140%	101%	50%	140%	106%	50%	140%
Methoxychlor	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	88%	50%	140%	106%	50%	140%	104%	50%	140%
Hexachlorobenzene	3146456	3146456	< 0.005	< 0.005	NA	< 0.005	102%	50%	140%	103%	50%	140%	95%	50%	140%
Hexachlorobutadiene	3146456	3146456	< 0.01	< 0.01	NA	< 0.01	106%	50%	140%	93%	50%	140%	89%	50%	140%
Hexachloroethane	3146456	3146456	< 0.01	< 0.01	NA	< 0.01	86%	50%	140%	83%	50%	140%	86%	50%	140%
Aroclor 1242	3146456	3146456	< 0.10	< 0.10	NA	< 0.10	102%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1248	3146456	3146456	< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1254	3146456	3146456	< 0.10	< 0.10	NA	< 0.10	97%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1260	3146456	3146456	< 0.10	< 0.10	NA	< 0.10	103%	50%	140%	NA	50%	140%	NA	50%	140%
Polychlorinated Biphenyls	3146456	3146456	< 0.10	< 0.10	NA	< 0.10	104%	50%	140%	102%	50%	140%	89%	50%	140%
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3138150		< 0.05	< 0.05	NA	< 0.05	74%	50%	140%	89%	50%	140%	105%	50%	140%
Acenaphthylene	3138150		< 0.05	< 0.05	NA	< 0.05	82%	50%	140%	93%	50%	140%	98%	50%	140%
Acenaphthene	3138150		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	92%	50%	140%	86%	50%	140%
Fluorene	3138150		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	98%	50%	140%	93%	50%	140%
Phenanthrene	3138150		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	98%	50%	140%	92%	50%	140%
Anthracene	3138150		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	105%	50%	140%	105%	50%	140%
Fluoranthene	3138150		< 0.05	< 0.05	NA	< 0.05	95%	50%	140%	98%	50%	140%	98%	50%	140%
Pyrene	3138150		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	86%	50%	140%	86%	50%	140%
Benz(a)anthracene	3138150		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	95%	50%	140%	93%	50%	140%
Chrysene	3138150		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	98%	50%	140%	92%	50%	140%
Benzo(b)fluoranthene	3138150		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	88%	50%	140%	105%	50%	140%
Benzo(k)fluoranthene	3138150		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	85%	50%	140%	78%	50%	140%
Benzo(a)pyrene	3138150		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	99%	50%	140%	88%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T822752
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Nov 08, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Indeno(1,2,3-cd)pyrene	3138150		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	96%	50%	140%	85%	50%	140%
Dibenz(a,h)anthracene	3138150		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	94%	50%	140%	96%	50%	140%
Benzo(g,h,i)perylene	3138150		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	98%	50%	140%	93%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan I	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan II	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Alpha-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
op'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
Dieldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Methoxychlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T822752

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
TCMX	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Decachlorobiphenyl	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
wet weight OC/PCB	ORG-91-5113		BALANCE
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only
Work Order #: 21T822752
Cooler Quantity: 1 LRG BLK
Arrival Temperatures: 7.5 | 7.7 | 8.0
Custody Seal Intact: ☐ Yes ☐ No ☑ N/A
Notes: FREE ICE

Report Information:
Company: WSP
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: 437-240-3868 Fax:
Reports to be sent to:
1. Email: Vanessa.oetinger@wsp.com
2. Email: MattLew.roy@wsp.com

Project Information:
Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis

Invoice Information:
Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:
(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
(Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
(Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:
Regular TAT ☑ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply):
Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*
For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend
B Biota
GW Ground Water
O Oil
P Paint
S Soil
SD Sediment
SW Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs, Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558 Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	Potentially Hazardous or High Concentration (Y/N)
BH21-10 S1	10/27/21	AM	1	S			X											
BH21-10 S2		AM	1	S							X						X	
BH21-10 S3		AM	1	S						X								
BH21-14 S1		AM	1	S							X						X	
BH21-14 S2		AM	1	S			X											
BH21-14 S3		AM	1	S						X								
BH21-15 S2		AM	2	S						X	X						X	
BH21-15 S3		AM	1	S			X											
BH21-26 S1	10/28/21	AM	1	S							X						X	
BH21-26 S2		AM	1	S						X								
BH21-26 S3		PM	1	S			X											

21 OCT 28 5:08PM

Samples Relinquished By (Print Name and Sign)	Date	Time	Samples Received By (Print Name and Sign)	Date	Time
Matthew Roy	10/28/21	1700	Adriana Bellavia ABellavia@		

Page 1 of 4

N°: T 126076

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712 5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company:
Contact: See Page 1
Address:
Phone: Fax:
Reports to be sent to:
1. Email:
2. Email:

Project Information:

Project:
Site Location:
Sampled By:
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email:

Regulatory Requirements:

(Please check all applicable boxes)

- ☑ Regulation 153/04 — Table 3 (Indicate One) — ☑ Ind/Com ☐ Res/Park ☐ Agriculture
- Soil Texture (Check One): ☑ Coarse ☐ Fine
- ☐ Excess Soils R406 — Table (Indicate One)
- ☐ Regulation 558
- ☐ CCME
- ☐ Sewer Use ☐ Sanitary ☐ Storm — Region
- ☐ Prov. Water Quality Objectives (PWQO)
- ☐ Other — Indicate One

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Laboratory Use Only

Work Order #:
Cooler Quantity:
Arrival Temperatures: see pg 1
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes:

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	BTEX, F1-F4 PHCs Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	Potentially Hazardous or High Concentration (Y/N)
BH21-27 S1	10/28/21	PM	1	S			X											
BH21-27 S2		PM	1	S							X						X	
BH21-27 S3		PM	1	S						X								
BH21-29 S1		AM	1	S							X						X	
BH21-29 S2		AM	1	S			X											
BH21-29 S3		AM	1	S						X								
BH21-33 S1		AM	1	S						X								
BH21-33 S2		AM	1	S							X						X	
BH21-33 S3		AM	1	S			X											
BH21-34 S1		AM	1	S							X						X	
~~BH21-34 S2~~ QAQC-1		AM	1	S							X						X	

Samples Relinquished By (Print Name and Sign)	Date	Time	Samples Received By (Print Name and Sign)	Date	Time
Matthew Roy	10/28/21	1700	A Bellanca		

Page 2 of 4

Nº: T 126077

Document ID: DW-78-1911-0211

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date issued: March 9, 2021

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company:
Contact:
Address: See Page 1
Phone: Fax:
Reports to be sent to:
1. Email:
2. Email:

Project Information:

Project:
Site Location:
Sampled By:
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email:

Regulatory Requirements:

(Please check all applicable boxes)

- ☑ Regulation 153/04 — Table 3 (Indicate One) — ☑ Ind/Com ☐ Res/Park ☐ Agriculture — Soil Texture (Check One): ☑ Coarse ☐ Fine
- ☐ Excess Soils R406 — Table (Indicate One)
- ☐ Regulation 558
- ☐ CCME
- ☐ Sewer Use ☐ Sanitary ☐ Storm — Region
- ☐ Prov. Water Quality Objectives (PWQO)
- ☐ Other — Indicate One

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Laboratory Use Only

Work Order #:
Cooler Quantity:
Arrival Temperatures: See pg 1
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes:

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs — Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach — SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	Potentially Hazardous or High Concentration (Y/N)
BH21-34 S2	10/26/21	AM	1	S			X											
QAQC-2	↓	AM	1	S			X											
BH21-34 S3		AM	1	S						X								
QAQC-3		AM	1	S						X								
BH21-35 S1	10/27/21	PM	1	S			X											
BH21-35 S2	↓	PM	1	S							X					X		
BH21-35 S3		PM	1	S						X								
BH21-37 S1		PM	1	S							X					X		
BH21-37 S2		PM	1	S			X											
BH21-37 S3		PM	1	S						X								
		AM PM																

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Matthew Roy	10/28/21	1700	ABellamia		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21OCT28 5:30pm

Page 3 of 4

N°: T 126078

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company:
Contact: See Page 1
Address:
Phone: Fax:
Reports to be sent to:
1. Email:
2. Email:

Project Information:

Project:
Site Location:
Sampled By:
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐

Company:
Contact:
Address:
Email:

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04 — Table 3 (Indicate One) — ☑ Ind/Com ☐ Res/Park ☐ Agriculture
Soil Texture (Check One): ☑ Coarse ☐ Fine

☐ Excess Soils R406 — Table (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm — (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other (Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Laboratory Use Only

Work Order #:
Cooler Quantity:
Arrival Temperatures: see pg 1
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes:

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs — Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach — SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	Potentially Hazardous or High Concentration (Y/N)
BH21-38 S1	10/27/21	AM	1	S						X								
BH21-38 S2	↓	AM	1	S							X						X	
BH21-38 S3		AM	1	S			X											
BH21-40 S1		AM	1	S							X						X	
BH21-40 S3		AM	2	S			X			X								

Samples Relinquished By (Print Name and Sign): Matthew Roy	Date 10/28/21	Time 1700	Samples Received By (Print Name and Sign): ABellanca	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 OCT 28 5:19 PM

Page 4 of 4

N°: T 126079

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065

ATTENTION TO: Vanessa Oetinger

PROJECT: 211-10139-00

AGAT WORK ORDER: 21T826519

SOIL ANALYSIS REVIEWED BY: Jacky Zhu, Spectroscopy Technician

TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor

DATE REPORTED: Nov 16, 2021

PAGES (INCLUDING COVER): 23

VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:


O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-05

DATE REPORTED: 2021-11-16

SAMPLE DESCRIPTION:				BH21-41 SS2	BH21-39 S1	BH21-31 S1	BH21-24 S3	BH21-23 S2	BH21-17 S1	BH21-9 SS2	BH21-11 SS1
SAMPLE TYPE:				Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
DATE SAMPLED:				2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-04	2021-11-04
Parameter	Unit	G / S	RDL	3176795	3176803	3176877	3176882	3176884	3176886	3176891	3176901
Antimony	µg/g	40	0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	µg/g	18	1	26	6	8	6	7	7	3	2
Barium	µg/g	670	2.0	18.3	40.7	58.8	41.5	54.8	62.8	25.4	10.1
Beryllium	µg/g	8	0.4	<0.4	0.4	0.5	0.4	0.6	0.6	<0.4	<0.4
Boron	µg/g	120	5	10	15	7	7	10	9	<5	<5
Boron (Hot Water Soluble)	µg/g	2	0.10	0.13	0.36	0.12	<0.10	0.26	0.66	0.18	<0.10
Cadmium	µg/g	1.9	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	µg/g	160	5	23	14	17	16	22	20	12	<5
Cobalt	µg/g	80	0.5	8.3	6.3	10.0	9.8	11.2	7.9	4.6	1.9
Copper	µg/g	230	1.0	24.0	12.3	28.5	34.8	36.6	28.8	8.0	9.0
Lead	µg/g	120	1	52	7	9	7	9	22	7	2
Molybdenum	µg/g	40	0.5	2.1	<0.5	<0.5	<0.5	0.7	0.7	<0.5	<0.5
Nickel	µg/g	270	1	8	13	21	20	25	19	9	2
Selenium	µg/g	5.5	0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	µg/g	40	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	µg/g	3.3	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	µg/g	33	0.50	<0.50	<0.50	<0.50	<0.50	0.52	<0.50	<0.50	<0.50
Vanadium	µg/g	86	0.4	25.2	21.3	24.8	23.4	29.5	29.0	24.7	10.4
Zinc	µg/g	340	5	121	48	51	53	63	77	28	18
Chromium, Hexavalent	µg/g	8	0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	µg/g	3.9	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	1.4	0.005	0.152	0.210	0.107	0.103	0.157	0.186	0.096	0.061
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	12	N/A	0.121	0.758	0.060	0.095	0.370	0.055	0.070	0.055
pH, 2:1 CaCl2 Extraction	pH Units	5.0-9.0	NA	7.69	7.49	7.60	7.66	7.59	7.16	7.29	7.82

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-05


DATE REPORTED: 2021-11-16

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3176795-3176901 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - OC Pesticides (Soil)

DATE RECEIVED: 2021-11-05

DATE REPORTED: 2021-11-16

		SAMPLE DESCRIPTION:		BH21-11 SS2
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-04
Parameter	Unit	G / S	RDL	3176902
Hexachloroethane	µg/g	0.21	0.01	<0.01
Gamma-Hexachlorocyclohexane	µg/g	0.056	0.005	<0.005
Heptachlor	µg/g	0.19	0.005	<0.005
Aldrin	µg/g	0.088	0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005
Endosulfan	µg/g	0.3	0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007
op'-DDE	ug/g		0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005
DDE	µg/g	0.52	0.007	<0.007
op'-DDD	µg/g		0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005
DDD	µg/g	4.6	0.007	<0.007
op'-DDT	µg/g		0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005
DDT (Total)	µg/g	1.4	0.007	<0.007
Dieldrin	µg/g	0.088	0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005
Methoxychlor	µg/g	1.6	0.005	<0.005
Hexachlorobenzene	µg/g	0.66	0.005	<0.005
Hexachlorobutadiene	µg/g	0.031	0.01	<0.01
Moisture Content	%		0.1	5.2
wet weight OC	g		0.01	10.58
Surrogate	Unit	Acceptable Limits		
TCMX	%	50-140		105
Decachlorobiphenyl	%	50-140		112

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - OC Pesticides (Soil)

DATE RECEIVED: 2021-11-05

DATE REPORTED: 2021-11-16

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3176902 Results are based on the dry weight of the soil.
DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-05

DATE REPORTED: 2021-11-16

		SAMPLE DESCRIPTION:		BH21-41 SS2	BH21-39 S3	BH21-31 S2	BH21-24 S1	BH21-23 S3	BH21-17 S2	BH21-9 SS1
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-04
Parameter	Unit	G / S	RDL	3176795	3176804	3176878	3176880	3176885	3176887	3176889
Gamma-Hexachlorocyclohexane	µg/g	0.056	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor	µg/g	0.19	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Aldrin	µg/g	0.088	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endosulfan	µg/g	0.3	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDD	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDD	µg/g	4.6	0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDE	ug/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDE	µg/g	0.52	0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
op'-DDT	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
DDT	µg/g	1.4	0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007	<0.007
Dieldrin	µg/g	0.088	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Methoxychlor	µg/g	1.6	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	µg/g	0.66	0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	µg/g	0.031	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Hexachloroethane	µg/g	0.21	0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
Aroclor 1242	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1248	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1254	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Aroclor 1260	µg/g		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Polychlorinated Biphenyls	µg/g	1.1	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-05

DATE REPORTED: 2021-11-16

		SAMPLE DESCRIPTION:		BH21-41 SS2	BH21-39 S3	BH21-31 S2	BH21-24 S1	BH21-23 S3	BH21-17 S2	BH21-9 SS1
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-04
Parameter	Unit	G / S	RDL	3176795	3176804	3176878	3176880	3176885	3176887	3176889
Moisture Content	%		0.1	18.9	22.8	14.4	20.0	12.8	14.6	17.6
wet weight OC/PCB	g		NA	10.86	10.69	10.36	10.52	10.66	10.22	10.23
Surrogate	Unit	Acceptable Limits								
TCMX	%	50-140		79	87	97	83	76	82	93
Decachlorobiphenyl	%	50-140		84	91	99	87	82	87	112

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3176795-3176889 Results are based on the dry weight of the soil.
DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-11-05

DATE REPORTED: 2021-11-16

		SAMPLE DESCRIPTION:		BH21-41 SS1	BH21-39 S3	BH21-31 S3	BH21-24 S2	BH21-23 S1	BH21-17 S3	BH21-9 SS3	BH21-11 SS2
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-05	2021-11-04	2021-11-04
Parameter	Unit	G / S	RDL	3176793	3176804	3176879	3176881	3176883	3176888	3176892	3176902
Naphthalene	µg/g	9.6	0.05	0.08	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	µg/g	0.15	0.05	0.08	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	µg/g	96	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	µg/g	62	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	µg/g	12	0.05	0.08	<0.05	<0.05	<0.05	<0.05	<0.05	0.10	<0.05
Anthracene	µg/g	0.67	0.05	0.06	<0.05	<0.05	<0.05	<0.05	<0.05	0.18	<0.05
Fluoranthene	µg/g	9.6	0.05	0.38	<0.05	<0.05	<0.05	<0.05	<0.05	0.19	<0.05
Pyrene	µg/g	96	0.05	0.36	<0.05	<0.05	<0.05	<0.05	<0.05	0.18	<0.05
Benz(a)anthracene	µg/g	0.96	0.05	0.18	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	µg/g	9.6	0.05	0.14	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	µg/g	0.96	0.05	0.25	<0.05	<0.05	<0.05	0.09	<0.05	0.05	<0.05
Benzo(k)fluoranthene	µg/g	0.96	0.05	0.24	<0.05	<0.05	<0.05	0.09	<0.05	0.06	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05	<0.05	<0.05	<0.05	<0.05	0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.76	0.05	0.08	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	µg/g	9.6	0.05	0.08	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
1 and 2 Methlynaphthalene	µg/g	76	0.05	0.18	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Moisture Content	%		0.1	22.5	22.8	12.2	19.8	16.8	13.3	9.9	5.2
Surrogate	Unit	Acceptable Limits									
Naphthalene-d8	%	50-140		81	<1	<1	<1	65	<1	102	78
Acridine-d9	%	50-140		62	<1	<1	<1	62	<1	61	88
Terphenyl-d14	%	50-140		110	<1	<1	<1	74	<1	73	74

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3176793-3176902 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-11-05

DATE REPORTED: 2021-11-16

		SAMPLE DESCRIPTION:		BH21-9 SS5	BH21-11
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-04	2021-11-04
Parameter	Unit	G / S	RDL	3176893	3176906
Benzene	µg/g	0.32	0.02	<0.02	<0.02
Toluene	µg/g	68	0.05	<0.05	<0.05
Ethylbenzene	µg/g	9.5	0.05	<0.05	<0.05
m & p-Xylene	µg/g		0.05	<0.05	<0.05
o-Xylene	µg/g		0.05	<0.05	<0.05
Xylenes (Total)	µg/g	26	0.05	<0.05	<0.05
F1 (C6 - C10)	µg/g	55	5	<5	<5
F1 (C6 to C10) minus BTEX	µg/g	55	5	<5	<5
F2 (C10 to C16)	µg/g	230	10	<10	<10
F3 (C16 to C34)	µg/g	1700	50	<50	<50
F4 (C34 to C50)	µg/g	3300	50	<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	3300	50	NA	NA
Moisture Content	%		0.1	14.7	17.7
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	60-140		91	93
Terphenyl	%	60-140		108	95

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-11-05


DATE REPORTED: 2021-11-16

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3176893-3176906 Results are based on sample dry weight.
The C6-C10 fraction is calculated using Toluene response factor.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.
Quality Control Data is available upon request.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3176795	BH21-41 SS2	ON T3 S ICC CT	O. Reg. 153(511) - Metals & Inorganics (Soil)	Arsenic	µg/g	18	26

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T826519
PROJECT: 211-10139-00
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:
SAMPLED BY:

Soil Analysis

RPT Date: Nov 16, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3170083		<0.8	<0.8	NA	< 0.8	134%	70%	130%	107%	80%	120%	106%	70%	130%
Arsenic	3170083		3	3	NA	< 1	116%	70%	130%	109%	80%	120%	116%	70%	130%
Barium	3170083		14.6	14.6	0.0%	< 2.0	110%	70%	130%	101%	80%	120%	106%	70%	130%
Beryllium	3170083		<0.4	<0.4	NA	< 0.4	107%	70%	130%	104%	80%	120%	89%	70%	130%
Boron	3170083		6	7	NA	< 5	101%	70%	130%	106%	80%	120%	97%	70%	130%
Boron (Hot Water Soluble)	3176795	3176795	0.13	0.12	NA	< 0.10	97%	60%	140%	103%	70%	130%	100%	60%	140%
Cadmium	3170083		<0.5	<0.5	NA	< 0.5	116%	70%	130%	105%	80%	120%	109%	70%	130%
Chromium	3170083		8	8	NA	< 5	91%	70%	130%	96%	80%	120%	97%	70%	130%
Cobalt	3170083		3.4	3.3	3.0%	< 0.5	94%	70%	130%	102%	80%	120%	101%	70%	130%
Copper	3170083		7.6	7.5	1.3%	< 1.0	106%	70%	130%	101%	80%	120%	98%	70%	130%
Lead	3170083		3	4	NA	< 1	112%	70%	130%	93%	80%	120%	84%	70%	130%
Molybdenum	3170083		<0.5	<0.5	NA	< 0.5	104%	70%	130%	108%	80%	120%	120%	70%	130%
Nickel	3170083		5	5	0.0%	< 1	98%	70%	130%	106%	80%	120%	101%	70%	130%
Selenium	3170083		<0.8	<0.8	NA	< 0.8	100%	70%	130%	112%	80%	120%	118%	70%	130%
Silver	3170083		<0.5	<0.5	NA	< 0.5	102%	70%	130%	107%	80%	120%	97%	70%	130%
Thallium	3170083		<0.5	<0.5	NA	< 0.5	88%	70%	130%	111%	80%	120%	102%	70%	130%
Uranium	3170083		0.56	0.53	NA	< 0.50	95%	70%	130%	103%	80%	120%	88%	70%	130%
Vanadium	3170083		17.7	15.6	12.6%	< 0.4	106%	70%	130%	105%	80%	120%	111%	70%	130%
Zinc	3170083		24	24	NA	< 5	110%	70%	130%	114%	80%	120%	113%	70%	130%
Chromium, Hexavalent	3190716		<0.2	<0.2	NA	< 0.2	102%	70%	130%	93%	80%	120%	88%	70%	130%
Cyanide, Free	3188795		<0.040	<0.040	NA	< 0.040	98%	70%	130%	109%	80%	120%	92%	70%	130%
Mercury	3170083		<0.10	<0.10	NA	< 0.10	114%	70%	130%	102%	80%	120%	101%	70%	130%
Electrical Conductivity (2:1)	3176795	3176795	0.152	0.155	2.0%	< 0.005	108%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3187468		4.92	4.95	0.6%	NA									
pH, 2:1 CaCl2 Extraction	3176891	3176891	7.29	7.29	0.0%	NA	101%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T826519
PROJECT: 211-10139-00
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:
SAMPLED BY:

Trace Organics Analysis

RPT Date: Nov 16, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	74%	50%	140%	89%	50%	140%	105%	50%	140%
Acenaphthylene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	82%	50%	140%	93%	50%	140%	98%	50%	140%
Acenaphthene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	92%	50%	140%	86%	50%	140%
Fluorene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	98%	50%	140%	93%	50%	140%
Phenanthrene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	98%	50%	140%	92%	50%	140%
Anthracene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	105%	50%	140%	105%	50%	140%
Fluoranthene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	95%	50%	140%	98%	50%	140%	98%	50%	140%
Pyrene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	86%	50%	140%	86%	50%	140%
Benz(a)anthracene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	95%	50%	140%	93%	50%	140%
Chrysene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	98%	50%	140%	92%	50%	140%
Benzo(b)fluoranthene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	88%	50%	140%	105%	50%	140%
Benzo(k)fluoranthene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	85%	50%	140%	78%	50%	140%
Benzo(a)pyrene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	99%	50%	140%	88%	50%	140%
Indeno(1,2,3-cd)pyrene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	96%	50%	140%	85%	50%	140%
Dibenz(a,h)anthracene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	94%	50%	140%	96%	50%	140%
Benzo(g,h,i)perylene	3176902	3176902	< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	98%	50%	140%	93%	50%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Soil)															
Gamma-Hexachlorocyclohexane	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	102%	50%	140%	104%	50%	140%	82%	50%	140%
Heptachlor	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	109%	50%	140%	108%	50%	140%	104%	50%	140%
Aldrin	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	98%	50%	140%	108%	50%	140%	102%	50%	140%
Heptachlor Epoxide	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	105%	50%	140%	107%	50%	140%	102%	50%	140%
Endosulfan I	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	102%	50%	140%	100%	50%	140%	102%	50%	140%
Endosulfan II	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	109%	50%	140%	114%	50%	140%	104%	50%	140%
Alpha-Chlordane	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	99%	50%	140%	112%	50%	140%	107%	50%	140%
gamma-Chlordane	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	101%	50%	140%	110%	50%	140%	105%	50%	140%
op'-DDD	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	115%	50%	140%	105%	50%	140%	118%	50%	140%
pp'-DDD	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	103%	50%	140%	108%	50%	140%	109%	50%	140%
op'-DDE	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	107%	50%	140%	112%	50%	140%
pp'-DDE	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	103%	50%	140%	104%	50%	140%
op'-DDT	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	100%	50%	140%	105%	50%	140%	114%	50%	140%
pp'-DDT	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	106%	50%	140%	104%	50%	140%	115%	50%	140%
Dieldrin	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	101%	50%	140%	107%	50%	140%
Endrin	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	106%	50%	140%	105%	50%	140%	109%	50%	140%
Methoxychlor	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	95%	50%	140%	109%	50%	140%	107%	50%	140%
Hexachlorobenzene	3176902	3176902	< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	93%	50%	140%	87%	50%	140%
Hexachlorobutadiene	3176902	3176902	< 0.01	< 0.01	NA	< 0.01	89%	50%	140%	92%	50%	140%	86%	50%	140%
Hexachloroethane	3176902	3176902	< 0.01	< 0.01	NA	< 0.01	87%	50%	140%	93%	50%	140%	106%	50%	140%
Aroclor 1242	3176902	3176902	< 0.10	< 0.10	NA	< 0.10	104%	50%	140%	NA	50%	140%	NA	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis (Continued)

RPT Date: Nov 16, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Aroclor 1248	3176902	3176902	< 0.10	< 0.10	NA	< 0.10	106%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1254	3176902	3176902	< 0.10	< 0.10	NA	< 0.10	102%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1260	3176902	3176902	< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	NA	50%	140%	NA	50%	140%
Polychlorinated Biphenyls	3176902	3176902	< 0.10	< 0.10	NA	< 0.10	96%	50%	140%	92%	50%	140%	102%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (Soil)															
F2 (C10 to C16)	3176906	3176906	< 10	< 10	NA	< 10	100%	60%	140%	109%	60%	140%	70%	60%	140%
F3 (C16 to C34)	3176906	3176906	< 50	< 50	NA	< 50	96%	60%	140%	106%	60%	140%	73%	60%	140%
F4 (C34 to C50)	3176906	3176906	< 50	< 50	NA	< 50	90%	60%	140%	119%	60%	140%	89%	60%	140%
O. Reg. 153(511) - PHCs F1 - F4 (Soil)															
Benzene	3176906		< 0.02	< 0.02	NA	< 0.02	96%	60%	140%	83%	60%	140%	83%	60%	140%
Toluene	3176906		< 0.05	< 0.05	NA	< 0.05	83%	60%	140%	87%	60%	140%	78%	60%	140%
Ethylbenzene	3176906		< 0.05	< 0.05	NA	< 0.05	80%	60%	140%	79%	60%	140%	100%	60%	140%
m & p-Xylene	3176906		< 0.05	< 0.05	NA	< 0.05	98%	60%	140%	94%	60%	140%	93%	60%	140%
o-Xylene	3176906		< 0.05	< 0.05	NA	< 0.05	82%	60%	140%	80%	60%	140%	88%	60%	140%
F1 (C6 - C10)	3176906		< 5	< 5	NA	< 5	119%	60%	140%	104%	60%	140%	88%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

RPT Date: Nov 16, 2021		REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Sample Id	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Antimony		134%	70%	130%	107%	80%	120%	106%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Hexachloroethane	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Gamma-Hexachlorocyclohexane	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Heptachlor	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Aldrin	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Endosulfan I	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Endosulfan II	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Endosulfan	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	CALCULATION
Alpha-Chlordane	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Chlordane	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	CALCULATION
op'-DDE	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
pp'-DDE	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
DDE	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
op'-DDD	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
pp'-DDD	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
DDD	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	CALCULATION
op'-DDT	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
pp'-DDT	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
DDT (Total)	ORG-91-5113	modified from EPA 3570, 3620C & 8081B	CALCULATION
Dieldrin	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Endrin	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Methoxychlor	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
TCMX	ORG-91-5112	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Decachlorobiphenyl	ORG-91-5113	modified from EPA 3570 & 3620C & 8081B	GC/ECD
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
wet weight OC	ORG-91-5113		BALANCE
Gamma-Hexachlorocyclohexane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan I	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan II	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Alpha-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
op'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
Dieldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Methoxychlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
TCMX	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Decachlorobiphenyl	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
wet weight OC/PCB	ORG-91-5113		BALANCE
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Toluene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Ethylbenzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
m & p-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
o-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T826519

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Xylenes (Total)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	P&T GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T826519

Cooler Quantity: 1 large

Arrival Temperatures: 6.4 | 6.2 | 8.1

Custody Seal Intact: ☐ Yes ☐ No ☐ N/A

Notes: Frozen

Report Information:

Company: WSP
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 (Indicate One)
☑ Ind/Com ☐ Res/Park ☐ Agriculture
Soil Texture (Check One): ☑ Coarse ☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
Region

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
Indicate One

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matt Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis

Invoice Information:

Bill To Same: Yes ☑ No ☐

Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC Y/N	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach	O. Reg 406: SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	Potentially Hazardous or High Concentration (Y/N)
BH21-41 S1	11/5/21	AM PM	1	S			X				X									
BH21-41 S2		AM PM	2	S			X					X							X	
BH21-39 S1		AM PM	1	S			X													
BH21-39 S3		AM PM	2	S							X	X							X	
BH21-31 S1		AM PM	1	S			X													
BH21-31 S2		AM PM	1	S								X							X	
BH21-31 S3		AM PM	1	S							X									
BH21-24 S1		AM PM	1	S								X							X	
BH21-24 S2		AM PM	1	S							X									
BH21-24 S3		AM PM	1	S			X													
		AM PM																		

21 NOV 5 5:35PM

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Matthew Roy	11/5/21	1600	NEAC G		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

Page 1 of 3

N°: T 126066

Document ID: DIV 76 3511 021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T826519

Cooler Quantity:

Arrival Temperatures: Seal pg1

Custody Seal Intact: ☐Yes ☐No ☐N/A

Notes:

Report Information:

Company:

Contact:

Address: See Page 1

Phone: Fax:

Reports to be sent to:

1. Email:

2. Email:

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04 — Table 3 (Indicate One) — ☑ Ind/Com ☐ Res/Park ☐ Agriculture — Soil Texture (Check One): ☑ Coarse ☐ Fine

☐ Excess Soils R406 — Table (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm — Region

☐ Prov. Water Quality Objectives (PWQO)

☐ Other — Indicate One

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT

**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Project Information:

Project: 21-10135-00

Site Location: ORBY Rayl

Sampled By: Matt Roy

AGAT Quote #: PO:

Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☑ No ☐

Company:

Contact:

Address:

Email: payables.ontario@wsp.com

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC Y/N	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	Potentially Hazardous or High Concentration (Y/N)
BH21-23 S1	11/5/21	AM PM	1	S							X								
BH21-23 S2		AM PM	1	S			X												
BH21-23 S3		AM PM	1	S								X						X	
BH21-17 S1		AM PM	1	S			X												
BH21-17 S2		AM PM	1	S								X						X	
BH21-17 S3		AM PM	1	S							X								
BH21-9 S1	11/4/21	AM PM	1	S								X						X	
BH21-9 S2		AM PM	1	S			X												
BH21-9 S3		AM PM	1	S							X								
BH21-9 S5		AM PM	3	S					X										
		AM PM																	

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Matt Roy	11/5/21	1600			
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 NOV 5 5:43PM

Page 2 of 3

Nº: T 126067

Document ID: DIV-78-1511-021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T826519

Cooler Quantity:

Arrival Temperatures: See Pg 1

Custody Seal Intact: ☐Yes ☐No ☐N/A

Notes:

Report Information:

Company:
Contact:
Address: See Page 1
Phone: Fax:
Reports to be sent to:
1. Email:
2. Email:

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 *Indicate One*
☑ Ind/Com ☐ Res/Park ☐ Agriculture
Soil Texture *(Check One)*: ☑ Coarse ☐ Fine

☐ Excess Soils R406
Table *Indicate One*

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
Region

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
Indicate One

Is this submission for a **Record of Site Condition**? ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Project Information:

Project: 21-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☑ No ☐

Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC Y/N	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs; Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach	O. Reg 406: Excess Soils SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides			HOLD			Potentially Hazardous or High Concentration (Y/N)
BH21-11 SS1	11/4/21	AM PM	1	S			X																	
BH21-11 SS2	↓	AM PM	1	S						X								X						
BH21-11 SS3		AM PM	1	S			X															X		
BH21-11		AM PM	3	S					X															
		AM PM																						
		AM PM																						
		AM PM																						
		AM PM																						
		AM PM																						
		AM PM																						
		AM PM																						

"21 NOV 5 5:30PM"

Samples Relinquished By (Print Name and Sign): Matthew Roy	Date: 11/5/21	Time: 1600	Samples Received By (Print Name and Sign):	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:

Page 3 of 3

Nº: T 126080

Document ID: DIV 78-1311.021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T827359
SOIL ANALYSIS REVIEWED BY: Jacky Zhu, Spectroscopy Technician
TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor
DATE REPORTED: Nov 20, 2021
PAGES (INCLUDING COVER): 18
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-08

DATE REPORTED: 2021-11-20

		SAMPLE DESCRIPTION:		BH21-30 SS2	BH21-28 SS1	QAQC-3
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-08	2021-11-08 12:00	2021-11-08 12:00
Parameter	Unit	G / S	RDL	3185854	3185864	3185865
Antimony	µg/g	40	0.8	<0.8	<0.8	<0.8
Arsenic	µg/g	18	1	6	10	10
Barium	µg/g	670	2.0	147	73.4	65.4
Beryllium	µg/g	8	0.4	1.4	0.8	0.7
Boron	µg/g	120	5	12	12	10
Boron (Hot Water Soluble)	µg/g	2	0.10	<0.10	0.44	0.47
Cadmium	µg/g	1.9	0.5	<0.5	<0.5	<0.5
Chromium	µg/g	160	5	32	23	21
Cobalt	µg/g	80	0.5	14.1	16.3	6.8
Copper	µg/g	230	1.0	28.4	40.9	31.3
Lead	µg/g	120	1	12	29	26
Molybdenum	µg/g	40	0.5	<0.5	0.7	0.6
Nickel	µg/g	270	1	33	31	17
Selenium	µg/g	5.5	0.8	<0.8	0.9	<0.8
Silver	µg/g	40	0.5	<0.5	<0.5	<0.5
Thallium	µg/g	3.3	0.5	<0.5	<0.5	<0.5
Uranium	µg/g	33	0.50	0.62	0.58	<0.50
Vanadium	µg/g	86	0.4	42.7	30.2	27.3
Zinc	µg/g	340	5	71	92	81
Chromium, Hexavalent	µg/g	8	0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040
Mercury	µg/g	3.9	0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	1.4	0.005	0.165	0.342	0.336
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	12	N/A	0.458	0.396	0.393
pH, 2:1 CaCl2 Extraction	pH Units	5.0-9.0	NA	7.25	7.28	7.60

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-08


DATE REPORTED: 2021-11-20

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3185854-3185865 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-08

DATE REPORTED: 2021-11-20

		SAMPLE DESCRIPTION:		BH21-30 SS1	BH21-28 SS3	QAQC-5
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-08	2021-11-08 12:00	2021-11-08 12:00
Parameter	Unit	G / S	RDL	3185851	3185868	3185869
Gamma-Hexachlorocyclohexane	µg/g	0.056	0.005	<0.005	<0.005	<0.005
Heptachlor	µg/g	0.19	0.005	<0.005	<0.005	<0.005
Aldrin	µg/g	0.088	0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005	<0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005	<0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005	<0.005	<0.005
Endosulfan	µg/g	0.3	0.005	<0.005	<0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007	<0.007	<0.007
op'-DDD	µg/g		0.005	<0.005	<0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005	<0.005	<0.005
DDD	µg/g	4.6	0.007	<0.007	<0.007	<0.007
op'-DDE	ug/g		0.005	<0.005	<0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005	<0.005	<0.005
DDE	µg/g	0.52	0.007	<0.007	<0.007	<0.007
op'-DDT	µg/g		0.005	<0.005	<0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005	<0.005	<0.005
DDT	µg/g	1.4	0.007	<0.007	<0.007	<0.007
Dieldrin	µg/g	0.088	0.005	<0.005	<0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005	<0.005	<0.005
Methoxychlor	µg/g	1.6	0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	µg/g	0.66	0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	µg/g	0.031	0.01	<0.01	<0.01	<0.01
Hexachloroethane	µg/g	0.21	0.01	<0.01	<0.01	<0.01
Aroclor 1242	µg/g		0.10	<0.10	<0.10	<0.10
Aroclor 1248	µg/g		0.10	<0.10	<0.10	<0.10
Aroclor 1254	µg/g		0.10	<0.10	<0.10	<0.10
Aroclor 1260	µg/g		0.10	<0.10	<0.10	<0.10

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-08

DATE REPORTED: 2021-11-20

				SAMPLE DESCRIPTION:	BH21-30 SS1	BH21-28 SS3	QAQC-5
				SAMPLE TYPE:	Soil	Soil	Soil
				DATE SAMPLED:	2021-11-08	2021-11-08 12:00	2021-11-08 12:00
Parameter	Unit	G / S	RDL		3185851	3185868	3185869
Polychlorinated Biphenyls	µg/g	1.1	0.10		<0.10	<0.10	<0.10
Moisture Content	%		0.1		8.9	14.2	11.3
wet weight OC/PCB	g		NA		10.74	10.11	10.54
Surrogate	Unit	Acceptable Limits					
TCMX	%	50-140			80	90	105
Decachlorobiphenyl	%	50-140			89	102	107

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3185851-3185869 Results are based on the dry weight of the soil.
DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-11-08

DATE REPORTED: 2021-11-20

				SAMPLE DESCRIPTION:	BH21-30 SS1	BH21-28 SS3	QAQC-5
				SAMPLE TYPE:	Soil	Soil	Soil
				DATE SAMPLED:	2021-11-08	2021-11-08 12:00	2021-11-08 12:00
Parameter	Unit	G / S	RDL		3185851	3185868	3185869
Naphthalene	µg/g	9.6	0.05		<0.05	<0.05	<0.05
Acenaphthylene	µg/g	0.15	0.05		<0.05	<0.05	<0.05
Acenaphthene	µg/g	96	0.05		<0.05	<0.05	<0.05
Fluorene	µg/g	62	0.05		<0.05	<0.05	<0.05
Phenanthrene	µg/g	12	0.05		<0.05	<0.05	<0.05
Anthracene	µg/g	0.67	0.05		<0.05	<0.05	<0.05
Fluoranthene	µg/g	9.6	0.05		<0.05	<0.05	<0.05
Pyrene	µg/g	96	0.05		0.05	<0.05	<0.05
Benz(a)anthracene	µg/g	0.96	0.05		<0.05	<0.05	<0.05
Chrysene	µg/g	9.6	0.05		<0.05	<0.05	<0.05
Benzo(b)fluoranthene	µg/g	0.96	0.05		<0.05	<0.05	<0.05
Benzo(k)fluoranthene	µg/g	0.96	0.05		<0.05	<0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05		<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.76	0.05		<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05		<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	µg/g	9.6	0.05		<0.05	<0.05	<0.05
1 and 2 Methlynaphthalene	µg/g	76	0.05		<0.05	<0.05	<0.05
Moisture Content	%		0.1		8.9	14.2	11.3
Surrogate	Unit	Acceptable Limits					
Naphthalene-d8	%	50-140			82	108	114
Acridine-d9	%	50-140			120	96	85
Terphenyl-d14	%	50-140			102	91	93

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3185851-3185869 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-11-08

DATE REPORTED: 2021-11-20

				SAMPLE DESCRIPTION:	BH21-30 SS3	BH21-28 SS2	QAQC-4
				SAMPLE TYPE:	Soil	Soil	Soil
				DATE SAMPLED:	2021-11-08	2021-11-08 12:00	2021-11-08 12:00
Parameter	Unit	G / S	RDL		3185858	3185866	3185867
Benzene	µg/g	0.32	0.02		<0.02	<0.02	<0.02
Toluene	µg/g	68	0.05		<0.05	<0.05	<0.05
Ethylbenzene	µg/g	9.5	0.05		<0.05	<0.05	<0.05
m & p-Xylene	µg/g		0.05		<0.05	<0.05	<0.05
o-Xylene	µg/g		0.05		<0.05	<0.05	<0.05
Xylenes (Total)	µg/g	26	0.05		<0.05	<0.05	<0.05
F1 (C6 - C10)	µg/g	55	5		<5	<5	<5
F1 (C6 to C10) minus BTEX	µg/g	55	5		<5	<5	<5
F2 (C10 to C16)	µg/g	230	10		<10	<10	<10
F3 (C16 to C34)	µg/g	1700	50		<50	<50	<50
F4 (C34 to C50)	µg/g	3300	50		<50	<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	3300	50		NA	NA	NA
Moisture Content	%		0.1		8.4	10.0	14.5
Surrogate	Unit	Acceptable Limits					
Toluene-d8	% Recovery	60-140			97	91	97
Terphenyl	%	60-140			74	72	97

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-11-08


DATE REPORTED: 2021-11-20

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3185858-3185867 Results are based on sample dry weight.
The C6-C10 fraction is calculated using Toluene response factor.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.
Quality Control Data is available upon request.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:

AGAT WORK ORDER: 21T827359
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matt Roy

Soil Analysis

RPT Date: Nov 20, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3194983		<0.8	<0.8	NA	< 0.8	130%	70%	130%	100%	80%	120%	93%	70%	130%
Arsenic	3194983		1	1	NA	< 1	111%	70%	130%	102%	80%	120%	104%	70%	130%
Barium	3194983		12.4	12.4	0.0%	< 2.0	99%	70%	130%	101%	80%	120%	94%	70%	130%
Beryllium	3194983		<0.4	<0.4	NA	< 0.4	130%	70%	130%	112%	80%	120%	121%	70%	130%
Boron	3194983		<5	<5	NA	< 5	95%	70%	130%	106%	80%	120%	109%	70%	130%
Boron (Hot Water Soluble)	3188832		0.26	0.25	NA	< 0.10	91%	60%	140%	99%	70%	130%	98%	60%	140%
Cadmium	3194983		<0.5	<0.5	NA	< 0.5	104%	70%	130%	99%	80%	120%	101%	70%	130%
Chromium	3194983		8	6	NA	< 5	101%	70%	130%	112%	80%	120%	89%	70%	130%
Cobalt	3194983		2.3	2.5	NA	< 0.5	104%	70%	130%	107%	80%	120%	101%	70%	130%
Copper	3194983		4.9	5.0	NA	< 1.0	92%	70%	130%	104%	80%	120%	93%	70%	130%
Lead	3194983		2	2	NA	< 1	102%	70%	130%	103%	80%	120%	91%	70%	130%
Molybdenum	3194983		<0.5	<0.5	NA	< 0.5	103%	70%	130%	109%	80%	120%	107%	70%	130%
Nickel	3194983		4	4	NA	< 1	101%	70%	130%	109%	80%	120%	101%	70%	130%
Selenium	3194983		<0.8	<0.8	NA	< 0.8	131%	70%	130%	97%	80%	120%	100%	70%	130%
Silver	3194983		<0.5	<0.5	NA	< 0.5	126%	70%	130%	104%	80%	120%	92%	70%	130%
Thallium	3194983		<0.5	<0.5	NA	< 0.5	105%	70%	130%	101%	80%	120%	91%	70%	130%
Uranium	3194983		<0.50	<0.50	NA	< 0.50	107%	70%	130%	103%	80%	120%	98%	70%	130%
Vanadium	3194983		12.3	12.9	4.8%	< 0.4	106%	70%	130%	98%	80%	120%	99%	70%	130%
Zinc	3194983		12	12	NA	< 5	105%	70%	130%	106%	80%	120%	107%	70%	130%
Chromium, Hexavalent	3185854	3185854	<0.2	<0.2	NA	< 0.2	96%	70%	130%	97%	80%	120%	87%	70%	130%
Cyanide, Free	3185854	3185854	<0.040	<0.040	NA	< 0.040	106%	70%	130%	109%	80%	120%	91%	70%	130%
Mercury	3194983		<0.10	<0.10	NA	< 0.10	99%	70%	130%	95%	80%	120%	93%	70%	130%
Electrical Conductivity (2:1)	3194209		0.158	0.166	4.9%	< 0.005	101%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3188909		0.747	0.678	9.7%	NA									
pH, 2:1 CaCl2 Extraction	3185854	3185854	7.25	7.29	0.6%	NA	99%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:

AGAT WORK ORDER: 21T827359
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matt Roy

Trace Organics Analysis

RPT Date: Nov 20, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F1 - F4 (Soil)															
Benzene	3185867		< 0.02	< 0.02	NA	< 0.02	85%	60%	140%	83%	60%	140%	85%	60%	140%
Toluene	3185867		< 0.05	< 0.05	NA	< 0.05	80%	60%	140%	88%	60%	140%	92%	60%	140%
Ethylbenzene	3185867		< 0.05	< 0.05	NA	< 0.05	92%	60%	140%	80%	60%	140%	79%	60%	140%
m & p-Xylene	3185867		< 0.05	< 0.05	NA	< 0.05	85%	60%	140%	93%	60%	140%	96%	60%	140%
o-Xylene	3185867		< 0.05	< 0.05	NA	< 0.05	79%	60%	140%	86%	60%	140%	84%	60%	140%
F1 (C6 - C10)	3185867		< 5	< 5	NA	< 5	114%	60%	140%	108%	60%	140%	88%	60%	140%
F2 (C10 to C16)	3188549		< 10	< 10	NA	< 10	98%	60%	140%	90%	60%	140%	61%	60%	140%
F3 (C16 to C34)	3188549		< 50	< 50	NA	< 50	95%	60%	140%	81%	60%	140%	62%	60%	140%
F4 (C34 to C50)	3188549		< 50	< 50	NA	< 50	95%	60%	140%	119%	60%	140%	81%	60%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Soil)															
Gamma-Hexachlorocyclohexane	3176902		< 0.005	< 0.005	NA	< 0.005	102%	50%	140%	104%	50%	140%	82%	50%	140%
Heptachlor	3176902		< 0.005	< 0.005	NA	< 0.005	109%	50%	140%	108%	50%	140%	104%	50%	140%
Aldrin	3176902		< 0.005	< 0.005	NA	< 0.005	98%	50%	140%	108%	50%	140%	102%	50%	140%
Heptachlor Epoxide	3176902		< 0.005	< 0.005	NA	< 0.005	105%	50%	140%	107%	50%	140%	102%	50%	140%
Endosulfan I	3176902		< 0.005	< 0.005	NA	< 0.005	102%	50%	140%	100%	50%	140%	102%	50%	140%
Endosulfan II	3176902		< 0.005	< 0.005	NA	< 0.005	109%	50%	140%	114%	50%	140%	104%	50%	140%
Alpha-Chlordane	3176902		< 0.005	< 0.005	NA	< 0.005	99%	50%	140%	112%	50%	140%	107%	50%	140%
gamma-Chlordane	3176902		< 0.005	< 0.005	NA	< 0.005	101%	50%	140%	110%	50%	140%	105%	50%	140%
op'-DDD	3176902		< 0.005	< 0.005	NA	< 0.005	115%	50%	140%	105%	50%	140%	118%	50%	140%
pp'-DDD	3176902		< 0.005	< 0.005	NA	< 0.005	103%	50%	140%	108%	50%	140%	109%	50%	140%
op'-DDE	3176902		< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	107%	50%	140%	112%	50%	140%
pp'-DDE	3176902		< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	103%	50%	140%	104%	50%	140%
op'-DDT	3176902		< 0.005	< 0.005	NA	< 0.005	100%	50%	140%	105%	50%	140%	114%	50%	140%
pp'-DDT	3176902		< 0.005	< 0.005	NA	< 0.005	106%	50%	140%	104%	50%	140%	115%	50%	140%
Dieldrin	3176902		< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	101%	50%	140%	107%	50%	140%
Endrin	3176902		< 0.005	< 0.005	NA	< 0.005	106%	50%	140%	105%	50%	140%	109%	50%	140%
Methoxychlor	3176902		< 0.005	< 0.005	NA	< 0.005	95%	50%	140%	109%	50%	140%	107%	50%	140%
Hexachlorobenzene	3176902		< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	93%	50%	140%	87%	50%	140%
Hexachlorobutadiene	3176902		< 0.01	< 0.01	NA	< 0.01	89%	50%	140%	92%	50%	140%	86%	50%	140%
Hexachloroethane	3176902		< 0.01	< 0.01	NA	< 0.01	87%	50%	140%	93%	50%	140%	106%	50%	140%
Aroclor 1242	3176902		< 0.10	< 0.10	NA	< 0.10	104%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1248	3176902		< 0.10	< 0.10	NA	< 0.10	106%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1254	3176902		< 0.10	< 0.10	NA	< 0.10	102%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1260	3176902		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	NA	50%	140%	NA	50%	140%
Polychlorinated Biphenyls	3176902		< 0.10	< 0.10	NA	< 0.10	96%	50%	140%	92%	50%	140%	102%	50%	140%
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3188273		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	70%	50%	140%	114%	50%	140%
Acenaphthylene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	75%	50%	140%	75%	50%	140%
Acenaphthene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	94%	50%	140%	96%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

Trace Organics Analysis (Continued)

RPT Date: Nov 20, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Fluorene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	85%	50%	140%	93%	50%	140%
Phenanthrene	3188273		< 0.05	< 0.05	NA	< 0.05	90%	50%	140%	78%	50%	140%	92%	50%	140%
Anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	74%	50%	140%	104%	50%	140%
Fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	109%	50%	140%	78%	50%	140%
Pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	86%	50%	140%	85%	50%	140%
Benz(a)anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	95%	50%	140%	93%	50%	140%
Chrysene	3188273		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	77%	50%	140%	92%	50%	140%
Benzo(b)fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	74%	50%	140%	71%	50%	140%	91%	50%	140%
Benzo(k)fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	85%	50%	140%	114%	50%	140%
Benzo(a)pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	93%	50%	140%	78%	50%	140%
Indeno(1,2,3-cd)pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	92%	50%	140%	95%	50%	140%
Dibenz(a,h)anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	104%	50%	140%	93%	50%	140%
Benzo(g,h,i)perylene	3188273		< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	77%	50%	140%	92%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

RPT Date: Nov 20, 2021

PARAMETER	Sample Id	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Selenium		131%	70%	130%	97%	80%	120%	100%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan I	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan II	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Alpha-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
op'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
Dieldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Methoxychlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
TCMX	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Decachlorobiphenyl	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
wet weight OC/PCB	ORG-91-5113		BALANCE
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Toluene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Ethylbenzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
m & p-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T827359

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:Matt Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
o-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Xylenes (Total)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	P&T GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905 712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matt Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 (Indicate One)
☑ Ind/Com ☐ Res/Park ☐ Agriculture
Soil Texture (Check One): ☑ Coarse ☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ (Region)

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Laboratory Use Only

Work Order #: 21T827359
Cooler Quantity: 1 LRG BLK
Arrival Temperatures: 7.7 | 8.3 | 9.1
Custody Seal Intact: ☐ Yes ☐ No ☑ N/A
Notes: FREE ICE

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	O. Reg 406: Salt - EC/SAR	OC Pesticides	HOLD SAMPLE						Potentially Hazardous or High Concentration (Y/N)
BH21-30 SS1	11/4/21	AM PM	2	S							X	X						X							
BH21-30 SS2		AM PM	2	S			X																		
BH21-30 SS3		AM PM	3	S					X																
BH21-30 SS4		AM PM	2	S			X												X						
BH21-30 SS8		AM PM	3	S					X										X						
BH21-28 SS1		AM PM	1	S			X																		
QAQC-3		AM PM	1	S			X																		
BH21-28 SS2		AM PM	3	S					X																
~~BH21-28~~ QAQC-4		AM PM	3	S					X																
BH21-28 SS3		AM PM	2	S							X	X						X							
QAQC-5		AM PM	2	S							X	X						X							

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Matthew Roy	11/8/21	1630	Adriana Bellavia		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 NOV 8 5:24pm

Page 1 of 2

N°: T 126069

Document ID: DIV 78 1511 021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2023

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company:
Contact:
Address: See Page 1
Phone: Fax:
Reports to be sent to:
1. Email:
2. Email:

Project Information:

Project: 211-10139-00
Site Location: ORBY Rw1
Sampled By: Matt Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐

Company:
Contact:
Address:
Email:

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture

Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ (Region)

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Laboratory Use Only

Work Order #:
Cooler Quantity:
Arrival Temperatures: see pg 1.
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes:

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs; Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ BaP ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Hold Samples	Potentially Hazardous or High Concentration (Y/N)
BH21-28 SS4	11/8/21	AM PM	1	S			X										X	
BH21-28 SS6	↓	AM PM	3	S					X								X	
		AM PM																
		AM PM																
		AM PM																
		AM PM																
		AM PM																
		AM PM																
		AM PM																
		AM PM																
		AM PM																
		AM PM																

Samples Relinquished By (Print Name and Sign): Matthew Roy	Date: 11/8/21	Time: 1630	Samples Received By (Print Name and Sign): D Bellavia	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 NOV 8 5:24PM

N°: T 126074

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T830287
SOIL ANALYSIS REVIEWED BY: Jacky Zhu, Spectroscopy Technician
TRACE ORGANICS REVIEWED BY: Inga Kuzmina, Trace Organics Lab Manager
DATE REPORTED: Nov 27, 2021
PAGES (INCLUDING COVER): 16
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-15

DATE REPORTED: 2021-11-27

				SAMPLE DESCRIPTION:	BH21-13 SS2	BH21-32 SS1
				SAMPLE TYPE:	Soil	Soil
				DATE SAMPLED:	2021-11-15 18:51	2021-11-15 18:51
Parameter	Unit	G / S	RDL		3211731	3211736
Antimony	µg/g	40	0.8		<0.8	1.9
Arsenic	µg/g	18	1		2	6
Barium	µg/g	670	2.0		10.6	43.1
Beryllium	µg/g	8	0.4		<0.4	<0.4
Boron	µg/g	120	5		<5	9
Boron (Hot Water Soluble)	µg/g	2	0.10		<0.10	0.40
Cadmium	µg/g	1.9	0.5		<0.5	<0.5
Chromium	µg/g	160	5		5	12
Cobalt	µg/g	80	0.5		1.7	5.8
Copper	µg/g	230	1.0		3.4	48.3
Lead	µg/g	120	1		3	65
Molybdenum	µg/g	40	0.5		<0.5	1.4
Nickel	µg/g	270	1		3	21
Selenium	µg/g	5.5	0.8		<0.8	<0.8
Silver	µg/g	40	0.5		<0.5	<0.5
Thallium	µg/g	3.3	0.5		<0.5	<0.5
Uranium	µg/g	33	0.50		<0.50	<0.50
Vanadium	µg/g	86	0.4		10.9	17.7
Zinc	µg/g	340	5		13	67
Chromium, Hexavalent	µg/g	8	0.2		<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040		<0.040	<0.040
Mercury	µg/g	3.9	0.10		<0.10	0.32
Electrical Conductivity (2:1)	mS/cm	1.4	0.005		0.078	0.184
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	12	N/A		0.205	0.193
pH, 2:1 CaCl2 Extraction	pH Units	5.0-9.0	NA		7.77	7.60

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-15


DATE REPORTED: 2021-11-27

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3211731-3211736 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-11-15

DATE REPORTED: 2021-11-27


				SAMPLE DESCRIPTION:	BH21-13 SS1	BH21-32 SS3
				SAMPLE TYPE:	Soil	Soil
				DATE SAMPLED:	2021-11-15 18:51	2021-11-15 18:51
Parameter	Unit	G / S	RDL		3211730	3211737
Naphthalene	µg/g	9.6	0.05		<0.05	<0.05
Acenaphthylene	µg/g	0.15	0.05		<0.05	<0.05
Acenaphthene	µg/g	96	0.05		<0.05	<0.05
Fluorene	µg/g	62	0.05		<0.05	<0.05
Phenanthrene	µg/g	12	0.05		<0.05	<0.05
Anthracene	µg/g	0.67	0.05		<0.05	<0.05
Fluoranthene	µg/g	9.6	0.05		<0.05	<0.05
Pyrene	µg/g	96	0.05		<0.05	<0.05
Benz(a)anthracene	µg/g	0.96	0.05		<0.05	<0.05
Chrysene	µg/g	9.6	0.05		<0.05	<0.05
Benzo(b)fluoranthene	µg/g	0.96	0.05		<0.05	<0.05
Benzo(k)fluoranthene	µg/g	0.96	0.05		<0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05		<0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.76	0.05		<0.05	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05		<0.05	<0.05
Benzo(g,h,i)perylene	µg/g	9.6	0.05		<0.05	<0.05
1 and 2 Methlynaphthalene	µg/g	76	0.05		<0.05	<0.05
Moisture Content	%		0.1		15.0	18.2
Surrogate	Unit	Acceptable Limits				
Naphthalene-d8	%	50-140			78	90
Acridine-d9	%	50-140			84	83
Terphenyl-d14	%	50-140			88	74

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3211730-3211737 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)

DATE RECEIVED: 2021-11-15

DATE REPORTED: 2021-11-27


				SAMPLE DESCRIPTION:	BH21-13 SS5	BH21-32 SS4
				SAMPLE TYPE:	Soil	Soil
				DATE SAMPLED:	2021-11-15 18:51	2021-11-15 18:51
Parameter	Unit	G / S	RDL		3211735	3211745
F1 (C6 - C10)	µg/g	55	5		<5	<5
F1 (C6 to C10) minus BTEX	µg/g	55	5		<5	<5
F2 (C10 to C16)	µg/g	230	10		<10	<10
F3 (C16 to C34)	µg/g	1700	50		<50	<50
F4 (C34 to C50)	µg/g	3300	50		<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	3300	50		NA	NA
Moisture Content	%		0.1		20.0	23.1
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140			90	92
Terphenyl	%	60-140			92	92

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3211735-3211745 Results are based on sample dry weight.
The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified without the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-11-15

DATE REPORTED: 2021-11-27

		SAMPLE DESCRIPTION:		BH21-13 SS5	BH21-32 SS4
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-15 18:51	2021-11-15 18:51
Parameter	Unit	G / S	RDL	3211735	3211745
Dichlorodifluoromethane	µg/g	16	0.05	<0.05	<0.05
Vinyl Chloride	ug/g	0.032	0.02	<0.02	<0.02
Bromomethane	ug/g	0.05	0.05	<0.05	<0.05
Trichlorofluoromethane	ug/g	4	0.05	<0.05	<0.05
Acetone	ug/g	16	0.50	<0.50	<0.50
1,1-Dichloroethylene	ug/g	0.064	0.05	<0.05	<0.05
Methylene Chloride	ug/g	1.6	0.05	<0.05	<0.05
Trans- 1,2-Dichloroethylene	ug/g	1.3	0.05	<0.05	<0.05
Methyl tert-butyl Ether	ug/g	11	0.05	<0.05	<0.05
1,1-Dichloroethane	ug/g	17	0.02	<0.02	<0.02
Methyl Ethyl Ketone	ug/g	70	0.50	<0.50	<0.50
Cis- 1,2-Dichloroethylene	ug/g	55	0.02	<0.02	<0.02
Chloroform	ug/g	0.47	0.04	<0.04	<0.04
1,2-Dichloroethane	ug/g	0.05	0.03	<0.03	<0.03
1,1,1-Trichloroethane	ug/g	6.1	0.05	<0.05	<0.05
Carbon Tetrachloride	ug/g	0.21	0.05	<0.05	<0.05
Benzene	ug/g	0.32	0.02	<0.02	<0.02
1,2-Dichloropropane	ug/g	0.16	0.03	<0.03	<0.03
Trichloroethylene	ug/g	0.91	0.03	<0.03	<0.03
Bromodichloromethane	ug/g	18	0.05	<0.05	<0.05
Methyl Isobutyl Ketone	ug/g	31	0.50	<0.50	<0.50
1,1,2-Trichloroethane	ug/g	0.05	0.04	<0.04	<0.04
Toluene	ug/g	68	0.05	<0.05	<0.05
Dibromochloromethane	ug/g	13	0.05	<0.05	<0.05
Ethylene Dibromide	ug/g	0.05	0.04	<0.04	<0.04
Tetrachloroethylene	ug/g	4.5	0.05	<0.05	<0.05
1,1,1,2-Tetrachloroethane	ug/g	0.087	0.04	<0.04	<0.04
Chlorobenzene	ug/g	2.4	0.05	<0.05	<0.05
Ethylbenzene	ug/g	9.5	0.05	<0.05	<0.05

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-11-15

DATE REPORTED: 2021-11-27


				SAMPLE DESCRIPTION:	BH21-13 SS5	BH21-32 SS4
				SAMPLE TYPE:	Soil	Soil
				DATE SAMPLED:	2021-11-15 18:51	2021-11-15 18:51
Parameter	Unit	G / S	RDL		3211735	3211745
m & p-Xylene	ug/g		0.05		<0.05	<0.05
Bromoform	ug/g	0.61	0.05		<0.05	<0.05
Styrene	ug/g	34	0.05		<0.05	<0.05
1,1,2,2-Tetrachloroethane	ug/g	0.05	0.05		<0.05	<0.05
o-Xylene	ug/g		0.05		<0.05	<0.05
1,3-Dichlorobenzene	ug/g	9.6	0.05		<0.05	<0.05
1,4-Dichlorobenzene	ug/g	0.2	0.05		<0.05	<0.05
1,2-Dichlorobenzene	ug/g	6.8	0.05		<0.05	<0.05
Xylenes (Total)	ug/g	26	0.05		<0.05	<0.05
1,3-Dichloropropene (Cis + Trans)	µg/g	0.18	0.04		<0.04	<0.04
n-Hexane	µg/g	46	0.05		<0.05	<0.05
Moisture Content	%		0.1		20.0	23.1
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140			93	97
4-Bromofluorobenzene	% Recovery	50-140			80	90

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3211735-3211745 The sample was analyzed using the high level technique. The sample was extracted using methanol, a small amount of the methanol extract was diluted in water and the purge & trap GC/MS analysis was performed. Results are based on the dry weight of the soil.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene + o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T830287
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Nov 27, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3211731	3211731	<0.8	<0.8	NA	< 0.8	129%	70%	130%	109%	80%	120%	99%	70%	130%
Arsenic	3211731	3211731	2	2	NA	< 1	116%	70%	130%	106%	80%	120%	103%	70%	130%
Barium	3211731	3211731	10.6	10.5	0.9%	< 2.0	109%	70%	130%	105%	80%	120%	104%	70%	130%
Beryllium	3211731	3211731	<0.4	<0.4	NA	< 0.4	111%	70%	130%	116%	80%	120%	112%	70%	130%
Boron	3211731	3211731	<5	<5	NA	< 5	83%	70%	130%	117%	80%	120%	105%	70%	130%
Boron (Hot Water Soluble)	3211731	3211731	<0.10	<0.10	NA	< 0.10	97%	60%	140%	101%	70%	130%	94%	60%	140%
Cadmium	3211731	3211731	<0.5	<0.5	NA	< 0.5	113%	70%	130%	108%	80%	120%	106%	70%	130%
Chromium	3211731	3211731	5	5	NA	< 5	108%	70%	130%	105%	80%	120%	105%	70%	130%
Cobalt	3211731	3211731	1.7	1.8	NA	< 0.5	102%	70%	130%	105%	80%	120%	99%	70%	130%
Copper	3211731	3211731	3.4	3.4	NA	< 1.0	96%	70%	130%	107%	80%	120%	102%	70%	130%
Lead	3211731	3211731	3	3	NA	< 1	108%	70%	130%	108%	80%	120%	107%	70%	130%
Molybdenum	3211731	3211731	<0.5	<0.5	NA	< 0.5	109%	70%	130%	108%	80%	120%	102%	70%	130%
Nickel	3211731	3211731	3	3	NA	< 1	98%	70%	130%	102%	80%	120%	96%	70%	130%
Selenium	3211731	3211731	<0.8	<0.8	NA	< 0.8	135%	70%	130%	113%	80%	120%	105%	70%	130%
Silver	3211731	3211731	<0.5	<0.5	NA	< 0.5	105%	70%	130%	110%	80%	120%	101%	70%	130%
Thallium	3211731	3211731	<0.5	<0.5	NA	< 0.5	115%	70%	130%	105%	80%	120%	103%	70%	130%
Uranium	3211731	3211731	<0.50	<0.50	NA	< 0.50	116%	70%	130%	107%	80%	120%	108%	70%	130%
Vanadium	3211731	3211731	10.9	11.5	5.4%	< 0.4	110%	70%	130%	103%	80%	120%	98%	70%	130%
Zinc	3211731	3211731	13	10	NA	< 5	107%	70%	130%	112%	80%	120%	110%	70%	130%
Chromium, Hexavalent	3220567		<0.2	<0.2	NA	< 0.2	105%	70%	130%	104%	80%	120%	90%	70%	130%
Cyanide, Free	3215870		<0.040	<0.040	NA	< 0.040	103%	70%	130%	106%	80%	120%	102%	70%	130%
Mercury	3211731	3211731	<0.10	<0.10	NA	< 0.10	115%	70%	130%	106%	80%	120%	105%	70%	130%
Electrical Conductivity (2:1)	3211731	3211731	0.078	0.085	8.6%	< 0.005	109%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3211731	3211731	0.205	0.199	3.0%	NA									
pH, 2:1 CaCl2 Extraction	3215870		7.86	7.80	0.8%	NA	101%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T830287
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Nov 27, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3230140		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	115%	50%	140%	101%	50%	140%
Acenaphthylene	3230140		< 0.05	< 0.05	NA	< 0.05	89%	50%	140%	74%	50%	140%	82%	50%	140%
Acenaphthene	3230140		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	93%	50%	140%	83%	50%	140%
Fluorene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	93%	50%	140%	94%	50%	140%
Phenanthrene	3230140		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	92%	50%	140%	98%	50%	140%
Anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	67%	50%	140%	64%	50%	140%	85%	50%	140%
Fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	87%	50%	140%	97%	50%	140%	105%	50%	140%
Pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	85%	50%	140%	78%	50%	140%
Benz(a)anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	96%	50%	140%	85%	50%	140%
Chrysene	3230140		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	105%	50%	140%	93%	50%	140%
Benzo(b)fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	78%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	88%	50%	140%	105%	50%	140%
Benzo(a)pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	96%	50%	140%	78%	50%	140%
Indeno(1,2,3-cd)pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	75%	50%	140%	92%	50%	140%	88%	50%	140%
Dibenz(a,h)anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	105%	50%	140%	96%	50%	140%
Benzo(g,h,i)perylene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	80%	50%	140%	93%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)															
F1 (C6 - C10)	3211735	3211735	<5	<5	NA	< 5	89%	60%	140%	110%	60%	140%	79%	60%	140%
F2 (C10 to C16)	3230140		< 10	< 10	NA	< 10	94%	60%	140%	83%	60%	140%	84%	60%	140%
F3 (C16 to C34)	3230140		< 50	< 50	NA	< 50	90%	60%	140%	76%	60%	140%	65%	60%	140%
F4 (C34 to C50)	3230140		< 50	< 50	NA	< 50	94%	60%	140%	79%	60%	140%	60%	60%	140%
O. Reg. 153(511) - VOCs (Soil)															
Dichlorodifluoromethane	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	75%	50%	140%	101%	50%	140%	86%	50%	140%
Vinyl Chloride	3211745	3211745	< 0.02	< 0.02	NA	< 0.02	103%	50%	140%	106%	50%	140%	108%	50%	140%
Bromomethane	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	101%	50%	140%	93%	50%	140%	91%	50%	140%
Trichlorofluoromethane	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	93%	50%	140%	88%	50%	140%
Acetone	3211745	3211745	< 0.50	< 0.50	NA	< 0.50	104%	50%	140%	99%	50%	140%	102%	50%	140%
1,1-Dichloroethylene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	98%	60%	130%	86%	50%	140%
Methylene Chloride	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	110%	60%	130%	113%	50%	140%
Trans- 1,2-Dichloroethylene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	90%	50%	140%	107%	60%	130%	84%	50%	140%
Methyl tert-butyl Ether	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	107%	50%	140%	77%	60%	130%	92%	50%	140%
1,1-Dichloroethane	3211745	3211745	< 0.02	< 0.02	NA	< 0.02	98%	50%	140%	116%	60%	130%	89%	50%	140%
Methyl Ethyl Ketone	3211745	3211745	< 0.50	< 0.50	NA	< 0.50	102%	50%	140%	101%	50%	140%	100%	50%	140%
Cis- 1,2-Dichloroethylene	3211745	3211745	< 0.02	< 0.02	NA	< 0.02	106%	50%	140%	120%	60%	130%	98%	50%	140%
Chloroform	3211745	3211745	< 0.04	< 0.04	NA	< 0.04	113%	50%	140%	108%	60%	130%	112%	50%	140%
1,2-Dichloroethane	3211745	3211745	< 0.03	< 0.03	NA	< 0.03	116%	50%	140%	108%	60%	130%	117%	50%	140%
1,1,1-Trichloroethane	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	112%	50%	140%	77%	60%	130%	109%	50%	140%
Carbon Tetrachloride	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	72%	50%	140%	90%	60%	130%	87%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T830287
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Nov 27, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Benzene	3211745	3211745	< 0.02	< 0.02	NA	< 0.02	94%	50%	140%	116%	60%	130%	94%	50%	140%
1,2-Dichloropropane	3211745	3211745	< 0.03	< 0.03	NA	< 0.03	81%	50%	140%	105%	60%	130%	82%	50%	140%
Trichloroethylene	3211745	3211745	< 0.03	< 0.03	NA	< 0.03	75%	50%	140%	94%	60%	130%	81%	50%	140%
Bromodichloromethane	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	90%	50%	140%	112%	60%	130%	85%	50%	140%
Methyl Isobutyl Ketone	3211745	3211745	< 0.50	< 0.50	NA	< 0.50	100%	50%	140%	100%	50%	140%	102%	50%	140%
1,1,2-Trichloroethane	3211745	3211745	< 0.04	< 0.04	NA	< 0.04	94%	50%	140%	103%	60%	130%	118%	50%	140%
Toluene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	103%	60%	130%	96%	50%	140%
Dibromochloromethane	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	99%	50%	140%	92%	60%	130%	98%	50%	140%
Ethylene Dibromide	3211745	3211745	< 0.04	< 0.04	NA	< 0.04	115%	50%	140%	101%	60%	130%	96%	50%	140%
Tetrachloroethylene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	89%	50%	140%	90%	60%	130%	97%	50%	140%
1,1,1,2-Tetrachloroethane	3211745	3211745	< 0.04	< 0.04	NA	< 0.04	111%	50%	140%	88%	60%	130%	98%	50%	140%
Chlorobenzene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	100%	50%	140%	90%	60%	130%	106%	50%	140%
Ethylbenzene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	70%	50%	140%	72%	60%	130%	71%	50%	140%
m & p-Xylene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	101%	50%	140%	93%	60%	130%	100%	50%	140%
Bromoform	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	120%	50%	140%	95%	60%	130%	113%	50%	140%
Styrene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	75%	50%	140%	77%	60%	130%	75%	50%	140%
1,1,2,2-Tetrachloroethane	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	114%	50%	140%	97%	60%	130%	90%	50%	140%
o-Xylene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	79%	60%	130%	111%	50%	140%
1,3-Dichlorobenzene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	113%	60%	130%	103%	50%	140%
1,4-Dichlorobenzene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	87%	50%	140%	112%	60%	130%	112%	50%	140%
1,2-Dichlorobenzene	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	107%	60%	130%	84%	50%	140%
n-Hexane	3211745	3211745	< 0.05	< 0.05	NA	< 0.05	73%	50%	140%	79%	60%	130%	71%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

RPT Date: Nov 27, 2021		REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Sample Id	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Selenium	3211731	135%	70%	130%	113%	80%	120%	105%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Dichlorodifluoromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Bromomethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trans- 1,2-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl tert-butyl Ether	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Cis- 1,2-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Dibromochloromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,1,2-Tetrachloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830287

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Bromoform	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene (Cis + Trans)	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5002	modified from EPA 5035A & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5002	modified from EPA 5035A & EPA 8260D	(P&T)GC/MS
Moisture Content	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis

Invoice Information:

Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
(Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
(Indicate One)

Is this submission for a Record of Site Condition? ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Laboratory Use Only

Work Order #: 21T830287
Cooler Quantity: 1 large
Arrival Temperatures: 13.1 | 13.2 | 14.1
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: Free Ice

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides		HOLD				Potentially Hazardous or High Concentration (Y/N)
BH21-13 SS1	11/15/21	AM PM	1	S							X							X						
BH21-13 SS2	↓	AM PM	1	S			X																	
BH21-13 SS4		AM PM	3	S	HOLD SAMPLE				X											X				
BH21-13 SS5		AM PM	3	S					X															
BH21-32 SS1		AM PM	1	S			X																	
BH21-32 SS3		AM PM	1	S							X							X						
BH21-32 SS4		AM PM	4	S	HOLD 250mL Jar (M/I)		X		X											X				
		AM PM																						
		AM PM																						
		AM PM																						
		AM PM																						

Samples Relinquished By (Print Name and Sign): Matthew Roy	Date 11/15/21	Time 1500	Samples Received By (Print Name and Sign): NEAL G	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21NOV15 3:11pm

Page 1 of 7

N°: T 126068

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T830891
SOIL ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer
TRACE ORGANICS REVIEWED BY: Neli Popnikolova, Senior Chemist
DATE REPORTED: Nov 26, 2021
PAGES (INCLUDING COVER): 16
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy


O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-16

DATE REPORTED: 2021-11-26

		SAMPLE DESCRIPTION:		BH21-36 SS1	BH21-25 SS2
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-16	2021-11-16 12:00
Parameter	Unit	G / S	RDL	3216079	3216087
Antimony	µg/g	40	0.8	1.1	<0.8
Arsenic	µg/g	18	1	11	8
Barium	µg/g	670	2.0	103	85.3
Beryllium	µg/g	8	0.4	<0.4	0.5
Boron	µg/g	120	5	6	<5
Boron (Hot Water Soluble)	µg/g	2	0.10	0.23	0.35
Cadmium	µg/g	1.9	0.5	<0.5	<0.5
Chromium	µg/g	160	5	12	23
Cobalt	µg/g	80	0.5	5.1	12.6
Copper	µg/g	230	1.0	53.7	35.5
Lead	µg/g	120	1	205	12
Molybdenum	µg/g	40	0.5	1.2	<0.5
Nickel	µg/g	270	1	11	26
Selenium	µg/g	5.5	0.8	<0.8	<0.8
Silver	µg/g	40	0.5	<0.5	<0.5
Thallium	µg/g	3.3	0.5	<0.5	<0.5
Uranium	µg/g	33	0.50	<0.50	0.50
Vanadium	µg/g	86	0.4	18.7	32.8
Zinc	µg/g	340	5	179	70
Chromium, Hexavalent	µg/g	8	0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040
Mercury	µg/g	3.9	0.10	0.23	<0.10
Electrical Conductivity (2:1)	mS/cm	1.4	0.005	0.156	0.174
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	12	N/A	0.076	0.267
pH, 2:1 CaCl2 Extraction	pH Units	5.0-9.0	NA	7.70	7.50

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-16

DATE REPORTED: 2021-11-26

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3216079-3216087 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-11-16

DATE REPORTED: 2021-11-26

				SAMPLE DESCRIPTION:	BH21-36 SS3	BH21-25 SS1
				SAMPLE TYPE:	Soil	Soil
				DATE SAMPLED:	2021-11-16	2021-11-16 12:00
Parameter	Unit	G / S	RDL		3216080	3216086
Naphthalene	µg/g	0.09	0.05		<0.05	<0.05
Acenaphthylene	µg/g	0.093	0.05		<0.05	<0.05
Acenaphthene	µg/g	0.072	0.05		<0.05	<0.05
Fluorene	µg/g	0.12	0.05		<0.05	<0.05
Phenanthrene	µg/g	0.69	0.05		<0.05	<0.05
Anthracene	µg/g	0.16	0.05		<0.05	<0.05
Fluoranthene	µg/g	0.56	0.05		<0.05	<0.05
Pyrene	µg/g	1	0.05		<0.05	<0.05
Benz(a)anthracene	µg/g	0.36	0.05		<0.05	<0.05
Chrysene	µg/g	2.8	0.05		<0.05	<0.05
Benzo(b)fluoranthene	µg/g	0.47	0.05		<0.05	<0.05
Benzo(k)fluoranthene	µg/g	0.48	0.05		<0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05		<0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.46	0.05		<0.05	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05		<0.05	<0.05
Benzo(g,h,i)perylene	µg/g	0.68	0.05		<0.05	<0.05
1 and 2 Methlynaphthalene	µg/g	0.59	0.05		<0.05	<0.05
Moisture Content	%		0.1		11.3	7.1
Surrogate	Unit	Acceptable Limits				
Naphthalene-d8	%	50-140			78	108
Acridine-d9	%	50-140			85	96
Terphenyl-d14	%	50-140			99	99

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3216080-3216086 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By: NPopowkolof

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)

DATE RECEIVED: 2021-11-16

DATE REPORTED: 2021-11-26

				SAMPLE DESCRIPTION:	BH21-36 SS6	BH21-25 SS6
				SAMPLE TYPE:	Soil	Soil
				DATE SAMPLED:	2021-11-16	2021-11-16 12:00
Parameter	Unit	G / S	RDL		3216085	3216089
F1 (C6 - C10)	µg/g	55	5		<5	<5
F1 (C6 to C10) minus BTEX	µg/g	55	5		<5	<5
F2 (C10 to C16)	µg/g	230	10		<10	<10
F3 (C16 to C34)	µg/g	1700	50		<50	<50
F4 (C34 to C50)	µg/g	3300	50		<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	3300	50		NA	NA
Moisture Content	%		0.1		17.4	15.3
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140			71	90
Terphenyl	%	60-140			94	87

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3216085-3216089 Results are based on sample dry weight.
The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified without the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-11-16

DATE REPORTED: 2021-11-26

		SAMPLE DESCRIPTION:		BH21-36 SS6	BH21-25 SS6
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-16	2021-11-16 12:00
Parameter	Unit	G / S	RDL	3216085	3216089
Dichlorodifluoromethane	µg/g	16	0.05	<0.05	<0.05
Vinyl Chloride	ug/g	0.032	0.02	<0.02	<0.02
Bromomethane	ug/g	0.05	0.05	<0.05	<0.05
Trichlorofluoromethane	ug/g	4	0.05	<0.05	<0.05
Acetone	ug/g	16	0.50	<0.50	<0.50
Dichloroethylene, 1,1-	ug/g	0.064	0.05	<0.05	<0.05
Methylene Chloride	ug/g	1.6	0.05	<0.05	<0.05
Dichloroethylene, Trans- 1,2-	ug/g	1.3	0.05	<0.05	<0.05
Methyl tert-butyl Ether	ug/g	11	0.05	<0.05	<0.05
Dichloroethane, 1,1-	ug/g	17	0.02	<0.02	<0.02
Methyl Ethyl Ketone	ug/g	70	0.50	<0.50	<0.50
Dichloroethylene, Cis- 1,2-	ug/g	55	0.02	<0.02	<0.02
Chloroform	ug/g	0.47	0.04	<0.04	<0.04
Dichloroethane, 1,2-	ug/g	0.05	0.03	<0.03	<0.03
Trichloroethane, 1,1,1-	ug/g	6.1	0.05	<0.05	<0.05
Carbon Tetrachloride	ug/g	0.21	0.05	<0.05	<0.05
Benzene	ug/g	0.32	0.02	<0.02	<0.02
Dichloropropane, 1,2-	ug/g	0.16	0.03	<0.03	<0.03
Trichloroethylene	ug/g	0.91	0.03	<0.03	<0.03
Bromodichloromethane	ug/g	18	0.05	<0.05	<0.05
Methyl Isobutyl Ketone	ug/g	31	0.50	<0.50	<0.50
Trichloroethane, 1,1,2-	ug/g	0.05	0.04	<0.04	<0.04
Toluene	ug/g	68	0.05	<0.05	<0.05
Dibromochloromethane	ug/g	13	0.05	<0.05	<0.05
Ethylene Dibromide	ug/g	0.05	0.04	<0.04	<0.04
Tetrachloroethylene	ug/g	4.5	0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	ug/g	0.087	0.04	<0.04	<0.04
Chlorobenzene	ug/g	2.4	0.05	<0.05	<0.05
Ethylbenzene	ug/g	9.5	0.05	<0.05	<0.05

Certified By: NPopowkolof

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-11-16

DATE REPORTED: 2021-11-26

				SAMPLE DESCRIPTION:	BH21-36 SS6	BH21-25 SS6
				SAMPLE TYPE:	Soil	Soil
				DATE SAMPLED:	2021-11-16	2021-11-16 12:00
Parameter	Unit	G / S	RDL		3216085	3216089
Bromoform	ug/g	0.61	0.05		<0.05	<0.05
Styrene	ug/g	34	0.05		<0.05	<0.05
Tetrachloroethane, 1,1,2,2-	ug/g	0.05	0.05		<0.05	<0.05
Dichlorobenzene, 1,3-	ug/g	9.6	0.05		<0.05	<0.05
Dichlorobenzene, 1,4-	ug/g	0.2	0.05		<0.05	<0.05
Dichlorobenzene, 1,2-	ug/g	6.8	0.05		<0.05	<0.05
Xylenes (Total)	ug/g	26	0.05		<0.05	<0.05
1,3-Dichloropropene (Cis + Trans)	µg/g	0.18	0.04		<0.04	<0.04
Hexane, n-	µg/g	46	0.05		<0.05	<0.05
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140			110	98
4-Bromofluorobenzene	% Recovery	50-140			79	76

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3216085-3216089 The sample was analyzed using the high level technique. The sample was extracted using methanol, a small amount of the methanol extract was diluted in water and the purge & trap GC/MS analysis was performed. Results are based on the dry weight of the soil.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene + o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By: N Popowkolof

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3216079	BH21-36 SS1	ON T3 S ICC CT	O. Reg. 153(511) - Metals & Inorganics (Soil)	Lead	µg/g	120	205

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T830891
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Nov 26, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3229207		<0.8	<0.8	NA	< 0.8	133%	70%	130%	105%	80%	120%	84%	70%	130%
Arsenic	3229207		4	4	NA	< 1	122%	70%	130%	111%	80%	120%	115%	70%	130%
Barium	3229207		84.6	80.5	5.0%	< 2.0	107%	70%	130%	109%	80%	120%	107%	70%	130%
Beryllium	3229207		0.4	<0.4	NA	< 0.4	74%	70%	130%	91%	80%	120%	80%	70%	130%
Boron	3229207		7	7	NA	< 5	70%	70%	130%	102%	80%	120%	86%	70%	130%
Boron (Hot Water Soluble)	3211731		<0.10	<0.10	NA	< 0.10	97%	60%	140%	101%	70%	130%	94%	60%	140%
Cadmium	3229207		<0.5	<0.5	NA	< 0.5	111%	70%	130%	104%	80%	120%	106%	70%	130%
Chromium	3229207		22	21	NA	< 5	102%	70%	130%	106%	80%	120%	NA	70%	130%
Cobalt	3229207		8.8	8.6	2.3%	< 0.5	103%	70%	130%	108%	80%	120%	104%	70%	130%
Copper	3229207		16.4	15.7	4.4%	< 1.0	95%	70%	130%	114%	80%	120%	91%	70%	130%
Lead	3229207		8	7	13.3%	< 1	105%	70%	130%	111%	80%	120%	97%	70%	130%
Molybdenum	3229207		<0.5	<0.5	NA	< 0.5	111%	70%	130%	112%	80%	120%	116%	70%	130%
Nickel	3229207		16	16	0.0%	< 1	102%	70%	130%	105%	80%	120%	97%	70%	130%
Selenium	3229207		<0.8	<0.8	NA	< 0.8	100%	70%	130%	108%	80%	120%	110%	70%	130%
Silver	3229207		<0.5	<0.5	NA	< 0.5	100%	70%	130%	101%	80%	120%	95%	70%	130%
Thallium	3229207		<0.5	<0.5	NA	< 0.5	105%	70%	130%	103%	80%	120%	93%	70%	130%
Uranium	3229207		0.61	0.59	NA	< 0.50	112%	70%	130%	109%	80%	120%	107%	70%	130%
Vanadium	3229207		32.9	32.6	0.9%	< 0.4	110%	70%	130%	103%	80%	120%	107%	70%	130%
Zinc	3229207		43	41	4.8%	< 5	107%	70%	130%	116%	80%	120%	95%	70%	130%
Chromium, Hexavalent	3216087	3216087	<0.2	<0.2	NA	< 0.2	93%	70%	130%	91%	80%	120%	87%	70%	130%
Cyanide, Free	3222492		<0.040	<0.040	NA	< 0.040	101%	70%	130%	102%	80%	120%	105%	70%	130%
Mercury	3229207		<0.10	<0.10	NA	< 0.10	113%	70%	130%	113%	80%	120%	108%	70%	130%
Electrical Conductivity (2:1)	3211731		0.078	0.085	8.6%	< 0.005	109%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3211731		0.205	0.199	3.0%	NA									
pH, 2:1 CaCl2 Extraction	3222492		7.65	7.63	0.3%	NA	99%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

Matrix spike NA: Spike level < native concentration. Matrix spike acceptance limits do not apply and are not calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T830891
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Nov 26, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3188273		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	70%	50%	140%	114%	50%	140%
Acenaphthylene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	75%	50%	140%	75%	50%	140%
Acenaphthene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	94%	50%	140%	96%	50%	140%
Fluorene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	85%	50%	140%	93%	50%	140%
Phenanthrene	3188273		< 0.05	< 0.05	NA	< 0.05	90%	50%	140%	78%	50%	140%	92%	50%	140%
Anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	74%	50%	140%	104%	50%	140%
Fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	109%	50%	140%	78%	50%	140%
Pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	86%	50%	140%	85%	50%	140%
Benz(a)anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	95%	50%	140%	93%	50%	140%
Chrysene	3188273		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	77%	50%	140%	92%	50%	140%
Benzo(b)fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	74%	50%	140%	71%	50%	140%	91%	50%	140%
Benzo(k)fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	85%	50%	140%	114%	50%	140%
Benzo(a)pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	93%	50%	140%	78%	50%	140%
Indeno(1,2,3-cd)pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	92%	50%	140%	95%	50%	140%
Dibenz(a,h)anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	104%	50%	140%	93%	50%	140%
Benzo(g,h,i)perylene	3188273		< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	77%	50%	140%	92%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)															
F1 (C6 - C10)	3223827		<5	<5	NA	< 5	91%	60%	140%	109%	60%	140%	87%	60%	140%
F2 (C10 to C16)	3230140		< 10	< 10	NA	< 10	94%	60%	140%	83%	60%	140%	84%	60%	140%
F3 (C16 to C34)	3230140		< 50	< 50	NA	< 50	90%	60%	140%	76%	60%	140%	65%	60%	140%
F4 (C34 to C50)	3230140		< 50	< 50	NA	< 50	94%	60%	140%	79%	60%	140%	60%	60%	140%
O. Reg. 153(511) - VOCs (Soil)															
Dichlorodifluoromethane	3217949		<0.05	<0.05	NA	< 0.05	113%	50%	140%	90%	50%	140%	73%	50%	140%
Vinyl Chloride	3217949		<0.02	<0.02	NA	< 0.02	99%	50%	140%	95%	50%	140%	86%	50%	140%
Bromomethane	3217949		<0.05	<0.05	NA	< 0.05	97%	50%	140%	88%	50%	140%	99%	50%	140%
Trichlorofluoromethane	3217949		<0.05	<0.05	NA	< 0.05	95%	50%	140%	96%	50%	140%	79%	50%	140%
Acetone	3217949		<0.50	<0.50	NA	< 0.50	83%	50%	140%	95%	50%	140%	88%	50%	140%
Dichloroethylene, 1,1-	3217949		<0.05	<0.05	NA	< 0.05	90%	50%	140%	94%	60%	130%	84%	50%	140%
Methylene Chloride	3217949		<0.05	<0.05	NA	< 0.05	93%	50%	140%	111%	60%	130%	110%	50%	140%
Dichloroethylene, Trans- 1,2-	3217949		<0.05	<0.05	NA	< 0.05	114%	50%	140%	96%	60%	130%	80%	50%	140%
Methyl tert-butyl Ether	3217949		<0.05	<0.05	NA	< 0.05	72%	50%	140%	79%	60%	130%	70%	50%	140%
Dichloroethane, 1,1-	3217949		<0.02	<0.02	NA	< 0.02	90%	50%	140%	94%	60%	130%	80%	50%	140%
Methyl Ethyl Ketone	3217949		<0.50	<0.50	NA	< 0.50	99%	50%	140%	85%	50%	140%	83%	50%	140%
Dichloroethylene, Cis- 1,2-	3217949		<0.02	<0.02	NA	< 0.02	76%	50%	140%	87%	60%	130%	95%	50%	140%
Chloroform	3217949		<0.04	<0.04	NA	< 0.04	71%	50%	140%	100%	60%	130%	105%	50%	140%
Dichloroethane, 1,2-	3217949		<0.03	<0.03	NA	< 0.03	83%	50%	140%	103%	60%	130%	99%	50%	140%
Trichloroethane, 1,1,1-	3217949		<0.05	<0.05	NA	< 0.05	100%	50%	140%	114%	60%	130%	77%	50%	140%
Carbon Tetrachloride	3217949		<0.05	<0.05	NA	< 0.05	73%	50%	140%	75%	60%	130%	80%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T830891
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Nov 26, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Benzene	3217949		<0.02	<0.02	NA	< 0.02	75%	50%	140%	85%	60%	130%	81%	50%	140%
Dichloropropane, 1,2-	3217949		<0.03	<0.03	NA	< 0.03	99%	50%	140%	105%	60%	130%	77%	50%	140%
Trichloroethylene	3217949		<0.03	<0.03	NA	< 0.03	85%	50%	140%	75%	60%	130%	94%	50%	140%
Bromodichloromethane	3217949		<0.05	<0.05	NA	< 0.05	81%	50%	140%	73%	60%	130%	85%	50%	140%
Methyl Isobutyl Ketone	3217949		<0.50	<0.50	NA	< 0.50	75%	50%	140%	98%	50%	140%	90%	50%	140%
Trichloroethane, 1,1,2-	3217949		<0.04	<0.04	NA	< 0.04	97%	50%	140%	104%	60%	130%	109%	50%	140%
Toluene	3217949		<0.05	<0.05	NA	< 0.05	100%	50%	140%	104%	60%	130%	80%	50%	140%
Dibromochloromethane	3217949		<0.05	<0.05	NA	< 0.05	94%	50%	140%	94%	60%	130%	108%	50%	140%
Ethylene Dibromide	3217949		<0.04	<0.04	NA	< 0.04	89%	50%	140%	117%	60%	130%	106%	50%	140%
Tetrachloroethylene	3217949		<0.05	<0.05	NA	< 0.05	88%	50%	140%	92%	60%	130%	90%	50%	140%
Tetrachloroethane, 1,1,1,2-	3217949		<0.04	<0.04	NA	< 0.04	117%	50%	140%	110%	60%	130%	101%	50%	140%
Chlorobenzene	3217949		<0.05	<0.05	NA	< 0.05	101%	50%	140%	109%	60%	130%	95%	50%	140%
Ethylbenzene	3217949		<0.05	<0.05	NA	< 0.05	72%	50%	140%	82%	60%	130%	80%	50%	140%
Bromoform	3217949		<0.05	<0.05	NA	< 0.05	93%	50%	140%	102%	60%	130%	102%	50%	140%
Styrene	3217949		<0.05	<0.05	NA	< 0.05	71%	50%	140%	80%	60%	130%	77%	50%	140%
Tetrachloroethane, 1,1,2,2-	3217949		<0.05	<0.05	NA	< 0.05	100%	50%	140%	87%	60%	130%	94%	50%	140%
Dichlorobenzene, 1,3-	3217949		<0.05	<0.05	NA	< 0.05	110%	50%	140%	107%	60%	130%	94%	50%	140%
Dichlorobenzene, 1,4-	3217949		<0.05	<0.05	NA	< 0.05	96%	50%	140%	96%	60%	130%	100%	50%	140%
Dichlorobenzene, 1,2-	3217949		<0.05	<0.05	NA	< 0.05	94%	50%	140%	100%	60%	130%	97%	50%	140%
Hexane, n-	3217949		<0.05	<0.05	NA	< 0.05	78%	50%	140%	108%	60%	130%	78%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By: N Popowkolof

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

RPT Date: Nov 26, 2021

PARAMETER	Sample Id	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Antimony		133%	70%	130%	105%	80%	120%	84%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

Matrix spike NA: Spike level < native concentration. Matrix spike acceptance limits do not apply and are not calculated.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Dichlorodifluoromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Vinyl Chloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromomethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T830891

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Acetone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, 1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methylene Chloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, Trans- 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl tert-butyl Ether	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethane, 1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, Cis- 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Chloroform	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethane, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethane, 1,1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Benzene	VOL-91-5002	modified from EPA 5035C and EPA 8260D	(P&T)GC/MS
Dichloropropane, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethylene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromodichloromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethane, 1,1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Toluene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dibromochloromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethane, 1,1,1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Chlorobenzene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Ethylbenzene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromoform	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Styrene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethane, 1,1,2,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichlorobenzene, 1,3-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichlorobenzene, 1,4-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichlorobenzene, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Xylenes (Total)	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
1,3-Dichloropropene (Cis + Trans)	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Hexane, n-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Toluene-d8	VOL-91-5002	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5002	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T830891

Cooler Quantity:

Arrival Temperatures: 17.2 | 17.2 | 17.4

Custody Seal Intact: ☐ Yes ☐ No ☐ N/A

Notes: free ice

Report Information:

Company: WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke

Phone: Fax:

Reports to be sent to:
1. Email: Vanessa.oetinger.com
2. Email: matt.roy@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture

Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use
☐ Sanitary ☐ Storm
Region

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
Indicate One

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
*TAT is exclusive of weekends and statutory holidays

For 'Same Day' analysis, please contact your AGAT CPM

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis

Invoice Information:

Bill To Same: Yes ☑ No ☐

Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC Y/N	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	HOLD SAMPLE					Potentially Hazardous or High Concentration (Y/N)
BH21-36 SS1	11/16/21	PM	1	S			X																
BH21-36 SS3		PM	1	S						X							X						
BH21-36 SS4		PM	1	S			X											X					
BH21-36 SS6		PM	4	S					X			X											
BH21-25 SS1		AM	1	S						X		X					X						
BH21-25 SS2		AM	1	S			X																
BH21-25 SS4		AM	3	S					X									X					
BH21-25 SS6		AM	4	S					X			X											
		AM PM																					
		AM PM																					
		AM PM																					

21NOV16 1447

Samples Relinquished By (Print Name and Sign)	Date	Time	Samples Received By (Print Name and Sign)	Date	Time
Matthew Roy	11/16/21	1500			

Page 1 of 1

№: T 127092

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Martin Gedeon
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T831518
SOIL ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer
TRACE ORGANICS REVIEWED BY: Elena Gorobets, Report Writer
DATE REPORTED: Dec 02, 2021
PAGES (INCLUDING COVER): 20
VERSION*: 2

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

VERSION 2:Version 2 supersedes work order 21T831518 , Version 1, issued November 29, 2021. VOCs included.

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

		SAMPLE DESCRIPTION:		BH21-43 SS2	BH21-44 SS1	BH21-1 SS2
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-17	2021-11-17	2021-11-17
Parameter	Unit	G / S	RDL	3221440	3221451	3221490
Antimony	µg/g	40	0.8	<0.8	<0.8	<0.8
Arsenic	µg/g	18	1	3	9	5
Barium	µg/g	670	2.0	28.8	37.7	55.6
Beryllium	µg/g	8	0.4	<0.4	<0.4	<0.4
Boron	µg/g	120	5	<5	5	6
Boron (Hot Water Soluble)	µg/g	2	0.10	<0.10	0.10	<0.10
Cadmium	µg/g	1.9	0.5	<0.5	<0.5	<0.5
Chromium	µg/g	160	5	8	13	17
Cobalt	µg/g	80	0.5	3.1	6.2	9.1
Copper	µg/g	230	1.0	7.2	28.4	20.3
Lead	µg/g	120	1	4	14	7
Molybdenum	µg/g	40	0.5	<0.5	<0.5	<0.5
Nickel	µg/g	270	1	6	12	17
Selenium	µg/g	5.5	0.8	<0.8	<0.8	<0.8
Silver	µg/g	40	0.5	<0.5	<0.5	<0.5
Thallium	µg/g	3.3	0.5	<0.5	<0.5	<0.5
Uranium	µg/g	33	0.50	<0.50	<0.50	0.60
Vanadium	µg/g	86	0.4	15.5	18.9	22.2
Zinc	µg/g	340	5	25	39	45
Chromium, Hexavalent	µg/g	8	0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040
Mercury	µg/g	3.9	0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	1.4	0.005	0.103	0.107	0.508
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	12	N/A	0.089	0.068	0.233
pH, 2:1 CaCl2 Extraction	pH Units	5.0-9.0	NA	7.53	7.63	7.67

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3221440-3221490 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

		SAMPLE DESCRIPTION:		BH21-43 SS1	BH21-1 SS1
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-17	2021-11-17
Parameter	Unit	G / S	RDL	3221417	3221488
Gamma-Hexachlorocyclohexane	µg/g	0.056	0.005	<0.005	<0.005
Heptachlor	µg/g	0.19	0.005	<0.005	<0.005
Aldrin	µg/g	0.088	0.005	<0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005	<0.005
Endosulfan	µg/g	0.3	0.005	<0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007	<0.007
op'-DDD	µg/g		0.005	<0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005	<0.005
DDD	µg/g	4.6	0.007	<0.007	<0.007
op'-DDE	ug/g		0.005	<0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005	<0.005
DDE	µg/g	0.52	0.007	<0.007	<0.007
op'-DDT	µg/g		0.005	<0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005	<0.005
DDT	µg/g	1.4	0.007	<0.007	<0.007
Dieldrin	µg/g	0.088	0.005	<0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005	<0.005
Methoxychlor	µg/g	1.6	0.005	<0.005	<0.005
Hexachlorobenzene	µg/g	0.66	0.005	<0.005	<0.005
Hexachlorobutadiene	µg/g	0.031	0.01	<0.01	<0.01
Hexachloroethane	µg/g	0.21	0.01	<0.01	<0.01
Aroclor 1242	µg/g		0.10	<0.10	<0.10
Aroclor 1248	µg/g		0.10	<0.10	<0.10
Aroclor 1254	µg/g		0.10	<0.10	<0.10
Aroclor 1260	µg/g		0.10	<0.10	<0.10
Polychlorinated Biphenyls	µg/g	1.1	0.10	<0.10	<0.10

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

		SAMPLE DESCRIPTION:		BH21-43 SS1	BH21-1 SS1
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-17	2021-11-17
Parameter	Unit	G / S	RDL	3221417	3221488
Moisture Content	%		0.1	13.5	12.4
wet weight OC/PCB	g		NA	10.12	10.45
Surrogate	Unit	Acceptable Limits			
TCMX	%	50-140		83	80
Decachlorobiphenyl	%	50-140		92	86

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3221417-3221488 Results are based on the dry weight of the soil.
DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

		SAMPLE DESCRIPTION:		BH21-43 SS1	BH21-1 SS2
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-17	2021-11-17
Parameter	Unit	G / S	RDL	3221417	3221490
Naphthalene	µg/g	9.6	0.05	<0.05	<0.05
Acenaphthylene	µg/g	0.15	0.05	<0.05	<0.05
Acenaphthene	µg/g	96	0.05	<0.05	<0.05
Fluorene	µg/g	62	0.05	<0.05	<0.05
Phenanthrene	µg/g	12	0.05	<0.05	<0.05
Anthracene	µg/g	0.67	0.05	<0.05	<0.05
Fluoranthene	µg/g	9.6	0.05	0.07	<0.05
Pyrene	µg/g	96	0.05	0.07	<0.05
Benz(a)anthracene	µg/g	0.96	0.05	<0.05	<0.05
Chrysene	µg/g	9.6	0.05	0.06	<0.05
Benzo(b)fluoranthene	µg/g	0.96	0.05	0.11	<0.05
Benzo(k)fluoranthene	µg/g	0.96	0.05	<0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05	0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.76	0.05	0.06	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05	<0.05	<0.05
Benzo(g,h,i)perylene	µg/g	9.6	0.05	0.07	<0.05
1 and 2 Methlynaphthalene	µg/g	76	0.05	<0.05	<0.05
Moisture Content	%		0.1	13.5	19.8
Surrogate	Unit	Acceptable Limits			
Naphthalene-d8	%	50-140		123	78
Acridine-d9	%	50-140		80	84
Terphenyl-d14	%	50-140		96	88

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3221417-3221490 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1-F4 (Soil)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

		SAMPLE DESCRIPTION:		BH21-43 SS6	BH21-44 SS4	BH21-1 SS3
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-17	2021-11-17	2021-11-17
Parameter	Unit	G / S	RDL	3221448	3221486	3221492
Benzene	µg/g		0.005	<0.005	<0.005	<0.005
Toluene	µg/g		0.05	<0.05	<0.05	<0.05
Ethylbenzene	µg/g		0.01	<0.01	<0.01	<0.01
m,p-Xylenes	ug/g		0.05	<0.05	<0.05	<0.05
o-Xylene	ug/g		0.05	<0.05	<0.05	<0.05
Xylenes	µg/g		0.05	<0.05	<0.05	<0.05
C6 - C10 (F1)	ug/g		10	<10	<10	<10
C6 - C10 (F1 minus BTEX)	ug/g		10	<10	<10	<10
C>10 - C16	ug/g		10	<10	<10	<10
C>16 - C34	ug/g		10	16	<10	31
C>34 - C50	ug/g		10	15	<10	11
Gravimetric Heavy Hydrocarbons	ug/g		1000	N/A	N/A	N/A
Moisture Content	%		1.00	20	26	24
Surrogate	Unit	Acceptable Limits				
Toluene-d8 (BTEX)	%	60-140		63	60	68
o-Terphenyl (F2-F4)	%	60-140		97	98	100

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1-F4 (Soil)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3221448-3221492 Results are based on the dry weight of the sample.
The C6-C10 (F1) fraction is calculated using toluene response factor.
The C10 - C16 (F2), C16 - C34 (F3), and C34 - C50 (F4) fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons (F4g) are not included in and cannot be added to the Total C6-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
Quality control data is available upon request.
Assistance in the interpretation of data is available upon request.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
The chromatogram returned to baseline by the retention time of nC50.
C6 –C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
C>10 – C16 (F2- Napthalene) is a calculated parameter. The calculated value is F2 - Napthalene (if requested). The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (if requested). The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylenes + o-Xylene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Extraction and holding times were met for this sample.

Analysis performed at AGAT Calgary (unless marked by *)

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

Volatile Organic Compounds in Soil (µg/g) (Methanol Field Stabilized)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

		SAMPLE DESCRIPTION:		BH21-43 SS6
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-17
Parameter	Unit	G / S	RDL	3221448
Chloromethane	µg/g		0.01	<0.01
Vinyl Chloride	µg/g		0.0002	<0.0002
Bromomethane	µg/g		0.01	<0.01
Chloroethane	µg/g		0.01	<0.01
Trichlorofluoromethane	µg/g		0.01	<0.01
Acetone	µg/g		0.1	<0.1
1,1-Dichloroethylene	µg/g		0.01	<0.01
Methylene Chloride	µg/g		0.01	<0.01
Methyl tert-Butyl Ether	µg/g		0.01	<0.01
Methyl Ethyl Ketone	µg/g		0.1	<0.1
trans-1,2-Dichloroethylene	µg/g		0.01	<0.01
1,1-Dichloroethane	µg/g		0.01	<0.01
cis-1,2-Dichloroethylene	µg/g		0.01	<0.01
Chloroform	µg/g		0.0010	<0.0010
1,2-Dichloroethane	µg/g		0.002	<0.002
1,1,1-Trichloroethane	µg/g		0.01	<0.01
Carbon Tetrachloride	µg/g		0.0005	<0.0005
Benzene	µg/g		0.005	<0.005
1,2-Dichloropropane	µg/g		0.01	<0.01
Trichloroethylene	µg/g		0.01	<0.01
Bromodichloromethane	µg/g		0.01	<0.01
trans-1,3-Dichloropropene	µg/g		0.01	<0.01
Methyl Isobutyl Ketone	µg/g		0.1	<0.1
cis-1,3-Dichloropropene	µg/g		0.01	<0.01
1,1,2-Trichloroethane	µg/g		0.01	<0.01
Toluene	µg/g		0.01	<0.01
2-Hexanone	µg/g		0.1	<0.1
Dibromochloromethane	µg/g		0.01	<0.01
Ethylene Dibromide	µg/g		0.01	<0.01
Tetrachloroethene	µg/g		0.010	<0.010

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

Volatile Organic Compounds in Soil (µg/g) (Methanol Field Stabilized)

DATE RECEIVED: 2021-11-17

DATE REPORTED: 2021-12-02

		SAMPLE DESCRIPTION:		BH21-43 SS6
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-17
Parameter	Unit	G / S	RDL	3221448
1,1,1,2-Tetrachloroethane	µg/g		0.01	<0.01
Chlorobenzene	µg/g		0.01	<0.01
Ethylbenzene	µg/g		0.01	<0.01
m,p-Xylenes	µg/g		0.01	<0.01
Bromoform	µg/g		0.01	<0.01
Styrene	µg/g		0.01	<0.01
1,1,2,2-Tetrachloroethane	µg/g		0.01	<0.01
o-Xylene	µg/g		0.01	<0.01
1,3-Dichlorobenzene	µg/g		0.01	<0.01
1,4-Dichlorobenzene	µg/g		0.01	<0.01
1,2-Dichlorobenzene	µg/g		0.01	<0.01
1,2,4-Trichlorobenzene	µg/g		0.01	<0.01
Total Xylenes	µg/g		0.01	<0.01
Surrogate	Unit	Acceptable Limits		
Toluene-d8	%	50-140		79

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

3221448 Results were obtained based on the dry weight of the sample.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylenes + o-Xylene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Calgary (unless marked by *)

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T831518
ATTENTION TO: Martin Gedeon
SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Dec 02, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3220744		<0.8	<0.8	NA	< 0.8	127%	70%	130%	104%	80%	120%	98%	70%	130%
Arsenic	3220744		3	3	NA	< 1	117%	70%	130%	103%	80%	120%	108%	70%	130%
Barium	3220744		16.8	16.6	1.2%	< 2.0	108%	70%	130%	103%	80%	120%	100%	70%	130%
Beryllium	3220744		<0.4	<0.4	NA	< 0.4	90%	70%	130%	110%	80%	120%	95%	70%	130%
Boron	3220744		6	6	NA	< 5	72%	70%	130%	110%	80%	120%	94%	70%	130%
Boron (Hot Water Soluble)	3220744		<0.10	<0.10	NA	< 0.10	94%	60%	140%	103%	70%	130%	102%	60%	140%
Cadmium	3220744		<0.5	<0.5	NA	< 0.5	111%	70%	130%	105%	80%	120%	102%	70%	130%
Chromium	3220744		7	7	NA	< 5	100%	70%	130%	102%	80%	120%	101%	70%	130%
Cobalt	3220744		2.9	2.9	0.0%	< 0.5	101%	70%	130%	104%	80%	120%	101%	70%	130%
Copper	3220744		13.0	14.0	7.4%	< 1.0	95%	70%	130%	107%	80%	120%	96%	70%	130%
Lead	3220744		17	20	16.2%	< 1	105%	70%	130%	104%	80%	120%	91%	70%	130%
Molybdenum	3220744		<0.5	<0.5	NA	< 0.5	107%	70%	130%	109%	80%	120%	112%	70%	130%
Nickel	3220744		5	4	NA	< 1	98%	70%	130%	102%	80%	120%	95%	70%	130%
Selenium	3220744		<0.8	<0.8	NA	< 0.8	118%	70%	130%	102%	80%	120%	105%	70%	130%
Silver	3220744		<0.5	<0.5	NA	< 0.5	104%	70%	130%	106%	80%	120%	94%	70%	130%
Thallium	3220744		<0.5	<0.5	NA	< 0.5	106%	70%	130%	101%	80%	120%	94%	70%	130%
Uranium	3220744		<0.50	<0.50	NA	< 0.50	109%	70%	130%	106%	80%	120%	102%	70%	130%
Vanadium	3220744		14.0	13.3	5.1%	< 0.4	104%	70%	130%	96%	80%	120%	103%	70%	130%
Zinc	3220744		83	85	2.4%	< 5	102%	70%	130%	105%	80%	120%	97%	70%	130%
Chromium, Hexavalent	3221490	3221490	<0.2	<0.2	NA	< 0.2	96%	70%	130%	90%	80%	120%	90%	70%	130%
Cyanide, Free	3225915		<0.040	<0.040	NA	< 0.040	105%	70%	130%	100%	80%	120%	102%	70%	130%
Mercury	3220744		<0.10	<0.10	NA	< 0.10	103%	70%	130%	106%	80%	120%	101%	70%	130%
Electrical Conductivity (2:1)	3225912		0.213	0.214	0.5%	< 0.005	102%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3225912		0.294	0.285	3.1%	NA									
pH, 2:1 CaCl2 Extraction	3242174		7.43	7.39	0.5%	NA	101%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T831518
ATTENTION TO: Martin Gedeon
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Dec 02, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3230140		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	115%	50%	140%	101%	50%	140%
Acenaphthylene	3230140		< 0.05	< 0.05	NA	< 0.05	89%	50%	140%	74%	50%	140%	82%	50%	140%
Acenaphthene	3230140		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	93%	50%	140%	83%	50%	140%
Fluorene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	93%	50%	140%	94%	50%	140%
Phenanthrene	3230140		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	92%	50%	140%	98%	50%	140%
Anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	67%	50%	140%	64%	50%	140%	85%	50%	140%
Fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	87%	50%	140%	97%	50%	140%	105%	50%	140%
Pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	85%	50%	140%	78%	50%	140%
Benz(a)anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	96%	50%	140%	85%	50%	140%
Chrysene	3230140		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	105%	50%	140%	93%	50%	140%
Benzo(b)fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	78%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	88%	50%	140%	105%	50%	140%
Benzo(a)pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	96%	50%	140%	78%	50%	140%
Indeno(1,2,3-cd)pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	75%	50%	140%	92%	50%	140%	88%	50%	140%
Dibenz(a,h)anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	105%	50%	140%	96%	50%	140%
Benzo(g,h,i)perylene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	80%	50%	140%	93%	50%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Soil)															
Gamma-Hexachlorocyclohexane	3223870		< 0.005	< 0.005	NA	< 0.005	90%	50%	140%	96%	50%	140%	92%	50%	140%
Heptachlor	3223870		< 0.005	< 0.005	NA	< 0.005	85%	50%	140%	85%	50%	140%	87%	50%	140%
Aldrin	3223870		< 0.005	< 0.005	NA	< 0.005	99%	50%	140%	109%	50%	140%	103%	50%	140%
Heptachlor Epoxide	3223870		< 0.005	< 0.005	NA	< 0.005	99%	50%	140%	108%	50%	140%	106%	50%	140%
Endosulfan I	3223870		< 0.005	< 0.005	NA	< 0.005	100%	50%	140%	106%	50%	140%	102%	50%	140%
Endosulfan II	3223870		< 0.005	< 0.005	NA	< 0.005	107%	50%	140%		50%	140%		50%	140%
Alpha-Chlordane	3223870		< 0.005	< 0.005	NA	< 0.005	98%	50%	140%	107%	50%	140%	104%	50%	140%
gamma-Chlordane	3223870		< 0.005	< 0.005	NA	< 0.005	95%	50%	140%	106%	50%	140%	105%	50%	140%
op'-DDD	3223870		< 0.005	< 0.005	NA	< 0.005	105%	50%	140%	107%	50%	140%	106%	50%	140%
pp'-DDD	3223870		< 0.005	< 0.005	NA	< 0.005	92%	50%	140%	109%	50%	140%	105%	50%	140%
op'-DDE	3223870		< 0.005	< 0.005	NA	< 0.005	91%	50%	140%	101%	50%	140%	102%	50%	140%
pp'-DDE	3223870		< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	102%	50%	140%	104%	50%	140%
op'-DDT	3223870		< 0.005	< 0.005	NA	< 0.005	101%	50%	140%	109%	50%	140%	108%	50%	140%
pp'-DDT	3223870		< 0.005	< 0.005	NA	< 0.005	103%	50%	140%	90%	50%	140%	92%	50%	140%
Dieldrin	3223870		< 0.005	< 0.005	NA	< 0.005	103%	50%	140%	112%	50%	140%	102%	50%	140%
Endrin	3223870		< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	105%	50%	140%	102%	50%	140%
Methoxychlor	3223870		< 0.005	< 0.005	NA	< 0.005	98%	50%	140%	88%	50%	140%	89%	50%	140%
Hexachlorobenzene	3223870		< 0.005	< 0.005	NA	< 0.005	98%	50%	140%	97%	50%	140%	92%	50%	140%
Hexachlorobutadiene	3223870		< 0.01	< 0.01	NA	< 0.01	88%	50%	140%	87%	50%	140%	84%	50%	140%
Hexachloroethane	3223870		< 0.01	< 0.01	NA	< 0.01	85%	50%	140%	86%	50%	140%	84%	50%	140%
Aroclor 1242	3223870		< 0.10	< 0.10	NA	< 0.10	104%	50%	140%	NA	50%	140%	NA	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T831518
ATTENTION TO: Martin Gedeon
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Dec 02, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Aroclor 1248	3223870		< 0.10	< 0.10	NA	< 0.10	106%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1254	3223870		< 0.10	< 0.10	NA	< 0.10	102%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1260	3223870		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	NA	50%	140%	NA	50%	140%
Polychlorinated Biphenyls	3223870		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	94%	50%	140%	92%	50%	140%
O. Reg. 153(511) - PHCs F1-F4 (Soil)															
Benzene	3631	3231634	0.012	0.013	NA	< 0.005	119%	60%	140%	107%	60%	140%	113%	60%	140%
Toluene	3631	3231634	< 0.05	< 0.05	NA	< 0.05	109%	60%	140%	113%	60%	140%	110%	60%	140%
Ethylbenzene	3631	3231634	0.02	0.02	NA	< 0.01	97%	60%	140%	134%	60%	140%	127%	60%	140%
m,p-Xylenes	3631	3231634	< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	121%	60%	130%	111%	50%	140%
o-Xylene	3631	3231634	< 0.05	< 0.05	NA	< 0.05	118%	50%	140%	121%	60%	130%	111%	50%	140%
Xylenes	3631	3231634	< 0.05	< 0.05	NA	< 0.05	112%	60%	140%	121%	60%	140%	111%	60%	140%
C6 - C10 (F1)	3631	3231634	20	20	NA	< 10	98%	60%	140%	106%	60%	140%	89%	60%	140%
C>10 - C16	7014	3221486	< 10	< 10	NA	< 10	92%	60%	140%	102%	60%	140%	103%	60%	140%
C>16 - C34	7014	3221486	<10	13	NA	< 10	95%	60%	140%	107%	60%	140%	108%	60%	140%
C>34 - C50	7014	3221486	< 10	< 10	NA	< 10	100%	60%	140%	102%	60%	140%	101%	60%	140%
Volatile Organic Compounds in Soil (µg/g) (Methanol Field Stabilized)															
Chloromethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	108%	50%	140%	97%	50%	140%	93%	50%	140%
Vinyl Chloride	4202	3264154	< 0.0002	< 0.0002	NA	< 0.0002	111%	50%	140%	100%	50%	140%	91%	50%	140%
Bromomethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	122%	50%	140%	107%	50%	140%	101%	50%	140%
Chloroethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	118%	50%	140%	114%	50%	140%	105%	50%	140%
Trichlorofluoromethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	86%	50%	140%	78%	60%	130%	70%	50%	140%
Acetone	4202	3264154	< 0.1	< 0.1	NA	< 0.1	127%	50%	140%	103%	50%	140%	125%	50%	140%
1,1-Dichloroethylene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	100%	50%	140%	91%	60%	130%	83%	50%	140%
Methylene Chloride	4202	3264154	< 0.01	< 0.01	NA	< 0.01	110%	50%	140%	109%	60%	130%	108%	50%	140%
Methyl tert-Butyl Ether	4202	3264154	< 0.01	< 0.01	NA	< 0.01	108%	50%	140%	105%	60%	130%	105%	50%	140%
Methyl Ethyl Ketone	4202	3264154	< 0.1	< 0.1	NA	< 0.1	96%	50%	140%	128%	50%	140%	138%	50%	140%
trans-1,2-Dichloroethylene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	113%	50%	140%	105%	60%	130%	95%	50%	140%
1,1-Dichloroethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	120%	50%	140%	110%	60%	130%	105%	50%	140%
cis-1,2-Dichloroethylene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	111%	50%	140%	110%	60%	130%	106%	50%	140%
Chloroform	4202	3264154	< 0.0010	< 0.0010	NA	< 0.0010	100%	50%	140%	97%	60%	130%	94%	50%	140%
1,2-Dichloroethane	4202	3264154	< 0.002	< 0.002	NA	< 0.002	113%	50%	140%	108%	60%	130%	108%	50%	140%
1,1,1-Trichloroethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	107%	50%	140%	101%	60%	130%	93%	50%	140%
Carbon Tetrachloride	4202	3264154	< 0.0005	< 0.0005	NA	< 0.0005	101%	50%	140%	96%	60%	130%	88%	50%	140%
Benzene	4202	3264154	< 0.005	< 0.005	NA	< 0.005	111%	50%	140%	106%	60%	130%	104%	50%	140%
1,2-Dichloropropane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	97%	50%	140%	96%	60%	130%	95%	50%	140%
Trichloroethylene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	108%	50%	140%	108%	60%	130%	86%	50%	140%
Bromodichloromethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	73%	50%	140%	77%	60%	130%	75%	50%	140%
trans-1,3-Dichloropropene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	85%	50%	140%	97%	60%	130%	93%	50%	140%

Comments: Duplicate NA: results are less than 5X the RDL and RDP will not be calculated.
The sample spikes and dups are not from the same sample ID.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Dec 02, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Methyl Isobutyl Ketone	4202	3264154	< 0.1	< 0.1	NA	< 0.1	89%	50%	140%	114%	50%	140%	120%	50%	140%
cis-1,3-Dichloropropene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	99%	50%	140%	105%	60%	130%	103%	50%	140%
1,1,2-Trichloroethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	85%	50%	140%	96%	60%	130%	95%	50%	140%
Toluene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	106%	50%	140%	105%	60%	130%	99%	50%	140%
2-Hexanone	4202	3264154	< 0.1	< 0.1	NA	< 0.1	111%	50%	140%	129%	50%	140%	139%	50%	140%
Dibromochloromethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	82%	50%	140%	95%	60%	130%	92%	50%	140%
Ethylene Dibromide	4202	3264154	< 0.01	< 0.01	NA	< 0.01	87%	50%	140%	97%	60%	130%	93%	50%	140%
Tetrachloroethene	4202	3264154	< 0.010	< 0.010	NA	< 0.010	93%	50%	140%	92%	60%	130%	83%	50%	140%
1,1,1,2-Tetrachloroethane	4202	3264154	< 0.01	< 0.01	NA	< 0.01	79%	50%	140%	97%	60%	130%	90%	50%	140%
Chlorobenzene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	92%	50%	140%	102%	60%	130%	97%	50%	140%
Ethylbenzene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	92%	50%	140%	96%	60%	130%	86%	50%	140%
m,p-Xylenes	4202	3264154	< 0.01	< 0.01	NA	< 0.01	97%	50%	140%	97%	60%	130%	88%	50%	140%
Bromoform	4202	3264154	< 0.01	< 0.01	NA	< 0.01	89%	50%	140%	108%	60%	130%	111%	50%	140%
Styrene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	88%	50%	140%	103%	60%	130%	101%	50%	140%
o-Xylene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	90%	50%	140%	88%	60%	130%	80%	50%	140%
1,3-Dichlorobenzene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	84%	50%	140%	104%	60%	130%	106%	50%	140%
1,4-Dichlorobenzene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	127%	50%	140%	128%	60%	130%	129%	50%	140%
1,2-Dichlorobenzene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	133%	50%	140%	126%	60%	130%	133%	50%	140%
1,2,4-Trichlorobenzene	4202	3264154	< 0.01	< 0.01	NA	< 0.01	107%	50%	140%	112%	60%	130%	121%	50%	140%
Total Xylenes	4202	3264154	< 0.01	< 0.01	NA	< 0.01	94%	50%	140%	93%	60%	130%	84%	50%	140%

Comments: Duplicate NA: results are less than 5X the RDL and RDP will not be calculated.
The sample spikes and dups are not from the same sample ID.

Certified By: Elena Gorobets

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan I	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan II	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Alpha-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
op'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
Dieldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Methoxychlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
TCMX	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Decachlorobiphenyl	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
wet weight OC/PCB	ORG-91-5113		BALANCE
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Toluene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Ethylbenzene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
m,p-Xylenes	TO-0543	EPA SW-846 5021 & 8260	GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
o-Xylene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Xylenes	TO-0543	EPA SW-846 5021 & 8260	GC/MS
C6 - C10 (F1)	TO-0543	CCME Tier 1 Method	GC/FID
C6 - C10 (F1 minus BTEX)	TO-0543	CCME Tier 1 Method	GC/FID
C>10 - C16	TO-0560	CCME Tier 1 Method	GC/FID
C>16 - C34	TO-0560	CCME Tier 1 Method	GC/FID
C>34 - C50	TO-0560	CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	TO-0560	CCME Tier 1 Method	GRAVIMETRIC
Moisture Content	TO-0560	CCME Tier 1 Method	GC/FID
Toluene-d8 (BTEX)	TO-0543	EPA SW-846 5021 & 8260	GC/MS
o-Terphenyl (F2-F4)	TO 0560	CCME Tier 1 Method	GC/FID
Chloromethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Vinyl Chloride	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Bromomethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Chloroethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Trichlorofluoromethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Acetone	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,1-Dichloroethylene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Methylene Chloride	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Methyl tert-Butyl Ether	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Methyl Ethyl Ketone	TO-0330	EPA SW-846 5030 & 8260	GC/MS
trans-1,2-Dichloroethylene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,1-Dichloroethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
cis-1,2-Dichloroethylene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Chloroform	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,2-Dichloroethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,1,1-Trichloroethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Carbon Tetrachloride	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Benzene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,2-Dichloropropane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Trichloroethylene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Bromodichloromethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
trans-1,3-Dichloropropene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Methyl Isobutyl Ketone	TO-0330	EPA SW-846 5030 & 8260	GC/MS
cis-1,3-Dichloropropene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,1,2-Trichloroethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Toluene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
2-Hexanone	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Dibromochloromethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Ethylene Dibromide	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Tetrachloroethene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,1,1,2-Tetrachloroethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Chlorobenzene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Ethylbenzene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
m,p-Xylenes	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Bromoform	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Styrene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,1,2,2-Tetrachloroethane	TO-0330	EPA SW-846 5030 & 8260	GC/MS
o-Xylene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,3-Dichlorobenzene	TO-0330	EPA SW-846 5030 & 8260	GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831518

PROJECT: 211-10139-00

ATTENTION TO: Martin Gedeon

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
1,4-Dichlorobenzene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,2-Dichlorobenzene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
1,2,4-Trichlorobenzene	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Total Xylenes	TO-0330	EPA SW-846 5030 & 8260	GC/MS
Toluene-d8	TO-0330	EPA SW-846 5030 & 8260	GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905 712.5100 Fax: 905 712.5122
webearth agatlabs com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T831518

Cooler Quantity: 1 large

Arrival Temperatures: 2.9 | 3.6 | 5.4

Custody Seal Intact: ☐ Yes ☐ No ☐ N/A

Notes: Free Def

Report Information:

Company: WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use
☐ Sanitary ☐ Storm
Region

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
Indicate One

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
*TAT is exclusive of weekends and statutory holidays

For 'Same Day' analysis, please contact your AGAT CPM

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Invoice Information:

Bill To Same: Yes ☑ No ☐

Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	Hold Sample	Potentially Hazardous or High Concentration (Y/N)
BH21-43 SS1	11/17/21	AM PM	2	S						X	X						X		
BH21-43 SS2		AM PM	1	S			X												
BH21-43 SS4		AM PM	3	S					X									X	
BH21-43 SS6		AM PM	3	S					X										
BH21-44 SS1		AM PM	1	S			X												
BH21-44 SS2		AM PM	2	S						X	X						X	X	
BH21-44 SS4		AM PM	3	S					X										
BH21-44 SS4		AM PM	1	S			X											X	
BH21-1 SS1		AM PM	1	S							X						X		
BH21-1 SS2		AM PM	2	S			X			X									
BH21-1 SS3		AM PM	3	S					X										

	Date	Time		Date	Time
Samples Relinquished By (Print Name and Sign): Matthew Roy	11/17/21	1530	Samples Received By (Print Name and Sign): NEAL		
Samples Relinquished By (Print Name and Sign):			Samples Received By (Print Name and Sign):		
Samples Relinquished By (Print Name and Sign):			Samples Received By (Print Name and Sign):		

21 NOV 17 5:43pm

Page 1 of 1

N°: T 126070

Document ID: DM-75-1511-021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T831991
SOIL ANALYSIS REVIEWED BY: Amanjot Bhela, Inorganic Lab Manager
TRACE ORGANICS REVIEWED BY: Neli Popnikolova, Senior Chemist
DATE REPORTED: Nov 26, 2021
PAGES (INCLUDING COVER): 12
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831991

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-18

DATE REPORTED: 2021-11-26

		SAMPLE DESCRIPTION:		BH21-42 SS1
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-18
Parameter	Unit	G / S	RDL	3224201
Antimony	µg/g	40	0.8	<0.8
Arsenic	µg/g	18	1	7
Barium	µg/g	670	2.0	49.2
Beryllium	µg/g	8	0.4	<0.4
Boron	µg/g	120	5	7
Boron (Hot Water Soluble)	µg/g	2	0.10	<0.10
Cadmium	µg/g	1.9	0.5	<0.5
Chromium	µg/g	160	5	19
Cobalt	µg/g	80	0.5	9.2
Copper	µg/g	230	1.0	35.3
Lead	µg/g	120	1	15
Molybdenum	µg/g	40	0.5	<0.5
Nickel	µg/g	270	1	20
Selenium	µg/g	5.5	0.8	<0.8
Silver	µg/g	40	0.5	<0.5
Thallium	µg/g	3.3	0.5	<0.5
Uranium	µg/g	33	0.50	<0.50
Vanadium	µg/g	86	0.4	25.3
Zinc	µg/g	340	5	51
Chromium, Hexavalent	µg/g	8	0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040
Mercury	µg/g	3.9	0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	1.4	0.005	0.110
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	12	N/A	0.090
pH, 2:1 CaCl2 Extraction	pH Units	5.0-9.0	NA	7.62

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831991

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-18

DATE REPORTED: 2021-11-26

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3224201 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831991

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-11-18

DATE REPORTED: 2021-11-26

		SAMPLE DESCRIPTION:		BH21-12 SS1
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-18
Parameter	Unit	G / S	RDL	3223983
Naphthalene	µg/g	9.6	0.05	<0.05
Acenaphthylene	µg/g	0.15	0.05	<0.05
Acenaphthene	µg/g	96	0.05	<0.05
Fluorene	µg/g	62	0.05	<0.05
Phenanthrene	µg/g	12	0.05	<0.05
Anthracene	µg/g	0.67	0.05	<0.05
Fluoranthene	µg/g	9.6	0.05	0.06
Pyrene	µg/g	96	0.05	0.06
Benz(a)anthracene	µg/g	0.96	0.05	<0.05
Chrysene	µg/g	9.6	0.05	<0.05
Benzo(b)fluoranthene	µg/g	0.96	0.05	0.13
Benzo(k)fluoranthene	µg/g	0.96	0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05	0.08
Indeno(1,2,3-cd)pyrene	µg/g	0.76	0.05	0.09
Dibenz(a,h)anthracene	µg/g	0.1	0.05	<0.05
Benzo(g,h,i)perylene	µg/g	9.6	0.05	0.11
1 and 2 Methlynaphthalene	µg/g	76	0.05	<0.05
Moisture Content	%		0.1	21.2
Surrogate	Unit	Acceptable Limits		
Naphthalene-d8	%	50-140		79
Acridine-d9	%	50-140		97
Terphenyl-d14	%	50-140		111

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 3: Full Depth Generic Site Condition Standards in a Non-Potable Ground Water Condition - Soil - Industrial/Commercial/Community Property Use - Coarse Textured Soils
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3223983 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By: NPopowkolof

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831991

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1-F4 (Soil)

DATE RECEIVED: 2021-11-18

DATE REPORTED: 2021-11-26

		SAMPLE DESCRIPTION:		BH21-12 SS3	BH21-42 SS3
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-18	2021-11-18
Parameter	Unit	G / S	RDL	3224132	3224217
Benzene	µg/g		0.005	<0.005	<0.005
Toluene	µg/g		0.05	<0.05	<0.05
Ethylbenzene	µg/g		0.01	<0.01	<0.01
m,p-Xylenes	ug/g		0.05	<0.05	<0.05
o-Xylene	ug/g		0.05	<0.05	<0.05
Xylenes	µg/g		0.05	<0.05	<0.05
C6 - C10 (F1)	ug/g		10	<10	<10
C6 - C10 (F1 minus BTEX)	ug/g		10	<10	<10
C>10 - C16	ug/g		10	<10	<10
C>16 - C34	ug/g		10	61	32
C>34 - C50	ug/g		10	22	12
Gravimetric Heavy Hydrocarbons	ug/g		1000	N/A	N/A
Moisture Content	%		1.00	25	22
Surrogate	Unit	Acceptable Limits			
Toluene-d8 (BTEX)	%	60-140		70	62
o-Terphenyl (F2-F4)	%	60-140		99	98

Certified By: N Popowkolof

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T831991

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1-F4 (Soil)

DATE RECEIVED: 2021-11-18

DATE REPORTED: 2021-11-26

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

3224132-3224217 Results are based on the dry weight of the sample.
The C6-C10 (F1) fraction is calculated using toluene response factor.
The C10 - C16 (F2), C16 - C34 (F3), and C34 - C50 (F4) fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons (F4g) are not included in and cannot be added to the Total C6-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
Quality control data is available upon request.
Assistance in the interpretation of data is available upon request.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
The chromatogram returned to baseline by the retention time of nC50.
C6 –C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
C>10 – C16 (F2- Napthalene) is a calculated parameter. The calculated value is F2 - Napthalene (if requested). The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (if requested). The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylenes + o-Xylene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Extraction and holding times were met for this sample.

Analysis performed at AGAT Calgary (unless marked by *)

Certified By: N Popowkolof

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail


AGAT WORK ORDER: 21T831991
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Nov 26, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3221432		<0.8	<0.8	NA	< 0.8	130%	70%	130%	105%	80%	120%	101%	70%	130%
Arsenic	3221432		3	3	NA	< 1	116%	70%	130%	104%	80%	120%	100%	70%	130%
Barium	3221432		32.3	32.8	1.5%	< 2.0	106%	70%	130%	101%	80%	120%	90%	70%	130%
Beryllium	3221432		<0.4	<0.4	NA	< 0.4	94%	70%	130%	113%	80%	120%	102%	70%	130%
Boron	3221432		6	6	NA	< 5	71%	70%	130%	114%	80%	120%	83%	70%	130%
Boron (Hot Water Soluble)	3220744		<0.10	<0.10	NA	< 0.10	94%	60%	140%	103%	70%	130%	102%	60%	140%
Cadmium	3221432		<0.5	<0.5	NA	< 0.5	110%	70%	130%	109%	80%	120%	107%	70%	130%
Chromium	3221432		10	10	NA	< 5	97%	70%	130%	103%	80%	120%	106%	70%	130%
Cobalt	3221432		4.8	4.8	0.0%	< 0.5	95%	70%	130%	106%	80%	120%	96%	70%	130%
Copper	3221432		11.4	11.3	0.9%	< 1.0	94%	70%	130%	112%	80%	120%	102%	70%	130%
Lead	3221432		8	7	13.3%	< 1	100%	70%	130%	100%	80%	120%	94%	70%	130%
Molybdenum	3221432		<0.5	<0.5	NA	< 0.5	107%	70%	130%	110%	80%	120%	118%	70%	130%
Nickel	3221432		9	9	0.0%	< 1	96%	70%	130%	103%	80%	120%	96%	70%	130%
Selenium	3221432		<0.8	<0.8	NA	< 0.8	99%	70%	130%	103%	80%	120%	110%	70%	130%
Silver	3221432		<0.5	<0.5	NA	< 0.5	95%	70%	130%	103%	80%	120%	104%	70%	130%
Thallium	3221432		<0.5	<0.5	NA	< 0.5	94%	70%	130%	102%	80%	120%	98%	70%	130%
Uranium	3221432		<0.50	<0.50	NA	< 0.50	106%	70%	130%	104%	80%	120%	103%	70%	130%
Vanadium	3221432		16.3	17.2	5.4%	< 0.4	96%	70%	130%	97%	80%	120%	100%	70%	130%
Zinc	3221432		28	30	6.9%	< 5	103%	70%	130%	110%	80%	120%	101%	70%	130%
Chromium, Hexavalent	3240500		<0.2	<0.2	NA	< 0.2	96%	70%	130%	90%	80%	120%	102%	70%	130%
Cyanide, Free	3225915		<0.040	<0.040	NA	< 0.040	105%	70%	130%	100%	80%	120%	102%	70%	130%
Mercury	3221432		<0.10	<0.10	NA	< 0.10	110%	70%	130%	102%	80%	120%	100%	70%	130%
Electrical Conductivity (2:1)	3225912		0.213	0.214	0.5%	< 0.005	102%	80%	120%	NA			NA		
Sodium Adsorption Ratio (2:1) (Calc.)	3225912		0.294	0.285	3.1%	N/A	NA			NA			NA		
pH, 2:1 CaCl2 Extraction	3242174		7.43	7.39	0.5%	NA	101%	80%	120%	NA			NA		

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T831991
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Nov 26, 2021

PARAMETER	Batch	Sample Id	DUPLICATE			Method Blank	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
			Dup #1	Dup #2	RPD		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3188273		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	70%	50%	140%	114%	50%	140%
Acenaphthylene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	75%	50%	140%	75%	50%	140%
Acenaphthene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	94%	50%	140%	96%	50%	140%
Fluorene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	85%	50%	140%	93%	50%	140%
Phenanthrene	3188273		< 0.05	< 0.05	NA	< 0.05	90%	50%	140%	78%	50%	140%	92%	50%	140%
Anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	74%	50%	140%	104%	50%	140%
Fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	109%	50%	140%	78%	50%	140%
Pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	86%	50%	140%	85%	50%	140%
Benz(a)anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	95%	50%	140%	93%	50%	140%
Chrysene	3188273		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	77%	50%	140%	92%	50%	140%
Benzo(b)fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	74%	50%	140%	71%	50%	140%	91%	50%	140%
Benzo(k)fluoranthene	3188273		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	85%	50%	140%	114%	50%	140%
Benzo(a)pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	93%	50%	140%	78%	50%	140%
Indeno(1,2,3-cd)pyrene	3188273		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	92%	50%	140%	95%	50%	140%
Dibenz(a,h)anthracene	3188273		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	104%	50%	140%	93%	50%	140%
Benzo(g,h,i)perylene	3188273		< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	77%	50%	140%	92%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

O. Reg. 153(511) - PHCs F1-F4 (Soil)															
Benzene	3630	3214069	< 0.005	< 0.005	NA	< 0.005	119%	60%	140%	112%	60%	140%	101%	60%	140%
Toluene	3630	3214069	< 0.05	< 0.05	NA	< 0.05	113%	60%	140%	119%	60%	140%	80%	60%	140%
Ethylbenzene	3630	3214069	< 0.01	< 0.01	NA	< 0.01	111%	60%	140%	139%	60%	140%	73%	60%	140%
m,p-Xylenes	3630	3214069	< 0.05	< 0.05	NA	< 0.05	112%	50%	140%	122%	60%	130%	70%	50%	140%
o-Xylene	3630	3214069	< 0.05	< 0.05	NA	< 0.05	110%	50%	140%	122%	60%	130%	70%	50%	140%
Xylenes	3630	3214069	< 0.05	< 0.05	NA	< 0.05	111%	60%	140%	122%	60%	140%	70%	60%	140%
C6 - C10 (F1)	3630	3214069	< 10	< 10	NA	< 10	113%	60%	140%	103%	60%	140%	69%	60%	140%
C>10 - C16	143	3214069	< 10	< 10	NA	< 10	91%	60%	140%	88%	60%	140%	94%	60%	140%
C>16 - C34	143	3214069	< 10	< 10	NA	< 10	95%	60%	140%	87%	60%	140%	93%	60%	140%
C>34 - C50	143	3214069	< 10	< 10	NA	< 10	91%	60%	140%	86%	60%	140%	92%	60%	140%

Comments: Duplicate NA: results are less than 5X the RDL and RDP will not be calculated.
The sample spikes and dups are not from the same sample ID.

Certified By: NPopowkolof

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831991

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831991

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
Benzene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Toluene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Ethylbenzene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
m,p-Xylenes	TO-0543	EPA SW-846 5021 & 8260	GC/MS
o-Xylene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Xylenes	TO-0543	EPA SW-846 5021 & 8260	GC/MS
C6 - C10 (F1)	TO-0543	CCME Tier 1 Method	GC/FID
C6 - C10 (F1 minus BTEX)	TO-0543	CCME Tier 1 Method	GC/FID
C>10 - C16	TO-0560	CCME Tier 1 Method	GC/FID
C>16 - C34	TO-0560	CCME Tier 1 Method	GC/FID
C>34 - C50	TO-0560	CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	TO-0560	CCME Tier 1 Method	GRAVIMETRIC

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T831991

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Moisture Content	TO-0560	CCME Tier 1 Method	GC/FID
Toluene-d8 (BTEX)	TO-0543	EPA SW-846 5021 & 8260	GC/MS
o-Terphenyl (F2-F4)	TO 0560	CCME Tier 1 Method	GC/FID

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

1 large

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only
Work Order #: 21T831991
Cooler Quantity:
Arrival Temperatures: 4.8 | 5.3 | 5.4
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: bagged ice

Report Information:
Company: WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Project Information:
Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:
Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:
(Please check all applicable boxes)

☑ Regulation 153/04
Table 3 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
(Region)

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
(Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:
Regular TAT ☑ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply):
Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*
For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend
B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	BTEX, F1-F4 PHCs	Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides		Hold Sample				Potentially Hazardous or High Concentration (Y/N)
BH21-12 SS1	11/18/21	PM	1	S							X									X				
BH21-12 SS1		PM	1	S								X								X				
BH21-12 SS2		PM	1	S			X													X				
BH21-12 SS3		PM	3	S					X															
BH21-12 SS4		PM	3	S					X											X				
BH21-42 SS1		AM	1	S			X																	
BH21-42 SS2		AM	2	S							X	X								X				
BH21-42 SS3		AM	3	S					X															
BH21-42 SS4		AM	1	S			X													X				
		AM PM																						
		AM PM																						

Samples Relinquished By (Print Name and Sign)	Date	Time	Samples Received By (Print Name and Sign)	Date	Time
Matthew Roy	11/18/21	1330	Dave Eastman		

Page 1 of 1

№: T 126071

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T832162
TRACE ORGANICS REVIEWED BY: Elena Gorobets, Report Writer
DATE REPORTED: Nov 30, 2021
PAGES (INCLUDING COVER): 8
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T832162

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:MR

O. Reg. 153(511) - PHCs F1-F4 (Soil)

DATE RECEIVED: 2021-11-18

DATE REPORTED: 2021-11-30

		SAMPLE DESCRIPTION:		BH21-34 S3	BH21-39 S3	BH21-29 S3	BH21-17 S2	BH21-41 S1	BH21-26 S3	BH21-27 S3	BH21-37 S3
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-10-28	2021-11-05	2021-10-28	2021-11-05	2021-11-05	2021-10-28	2021-10-28	2021-10-27
Parameter	Unit	G / S	RDL	3225539	3225563	3225564	3225565	3225566	3225567	3225568	3225569
Benzene	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	0.006	<0.005	<0.005	<0.005
Toluene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	µg/g		0.01	<0.01	<0.01	<0.01	<0.01	0.01	<0.01	<0.01	<0.01
m,p-Xylenes	ug/g		0.05	<0.05	<0.05	<0.05	<0.05	0.11	<0.05	<0.05	<0.05
o-Xylene	ug/g		0.05	<0.05	<0.05	<0.05	<0.05	0.11	<0.05	<0.05	<0.05
Xylenes	µg/g		0.05	<0.05	<0.05	<0.05	<0.05	0.22	<0.05	<0.05	<0.05
C6 - C10 (F1)	ug/g		10	<10	<10	<10	<10	10	<10	<10	<10
C6 - C10 (F1 minus BTEX)	ug/g		10	<10	<10	<10	<10	10	<10	<10	<10
C>10 - C16	ug/g		10	<10	<10	<10	<10	<10	<10	<10	<10
C>16 - C34	ug/g		10	11	24	17	13	75	<10	<10	15
C>34 - C50	ug/g		10	<10	<10	<10	<10	19	<10	<10	<10
Gravimetric Heavy Hydrocarbons	ug/g		1000	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Moisture Content	%		1.00	13	19	14	14	18	13	2.7	3.3
Surrogate	Unit	Acceptable Limits									
Toluene-d8 (BTEX)	%	60-140		112	104	96	106	104	106	92	88
o-Terphenyl (F2-F4)	%	60-140		96	93	94	96	92	98	93	92

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T832162

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:MR

O. Reg. 153(511) - PHCs F1-F4 (Soil)

DATE RECEIVED: 2021-11-18

DATE REPORTED: 2021-11-30

		SAMPLE DESCRIPTION:		BH21-23 S3	BH21-24 S3	BH21-35 S2	BH21-31 S3	BH21-14 S3	BH21-33 S2	BH21-10 S3
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-11-05	2021-11-05	2021-10-27	2021-11-05	2021-10-27	2021-10-28	2021-10-27
Parameter	Unit	G / S	RDL	3225570	3225571	3225572	3225573	3225574	3225576	3225577
Benzene	µg/g		0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005	<0.005
Toluene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Ethylbenzene	µg/g		0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01
m,p-Xylenes	ug/g		0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
o-Xylene	ug/g		0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Xylenes	µg/g		0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
C6 - C10 (F1)	ug/g		10	<10	<10	<10	<10	<10	<10	<10
C6 - C10 (F1 minus BTEX)	ug/g		10	<10	<10	<10	<10	<10	<10	<10
C>10 - C16	ug/g		10	<10	<10	<10	13	<10	<10	<10
C>16 - C34	ug/g		10	<10	14	21	39	14	24	42
C>34 - C50	ug/g		10	<10	<10	<10	<10	<10	<10	<10
Gravimetric Heavy Hydrocarbons	ug/g		1000	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Moisture Content	%		1.00	12	16	14	11	5.3	7.6	3.2
Surrogate	Unit	Acceptable Limits								
Toluene-d8 (BTEX)	%	60-140		99	88	75	98	130	132	109
o-Terphenyl (F2-F4)	%	60-140		96	96	91	93	96	95.9	94.2

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T832162

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:MR

O. Reg. 153(511) - PHCs F1-F4 (Soil)

DATE RECEIVED: 2021-11-18

DATE REPORTED: 2021-11-30

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

3225539-3225577 Results are based on the dry weight of the sample.
The C6-C10 (F1) fraction is calculated using toluene response factor.
The C10 - C16 (F2), C16 - C34 (F3), and C34 - C50 (F4) fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons (F4g) are not included in and cannot be added to the Total C6-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
Quality control data is available upon request.
Assistance in the interpretation of data is available upon request.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
The chromatogram returned to baseline by the retention time of nC50.
C6 –C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
C>10 – C16 (F2- Napthalene) is a calculated parameter. The calculated value is F2 - Napthalene (if requested). The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (if requested). The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylenes + o-Xylene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.

Sample holding time exceeded for F2-F4 analysis.

Analysis performed at AGAT Calgary (unless marked by *)

Certified By: Elena Gorobets

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T832162

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:MR

Trace Organics Analysis

RPT Date: Nov 30, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F1-F4 (Soil)															
Benzene	4195	3225563	< 0.005	< 0.005	NA	< 0.005	92%	60%	140%	89%	60%	140%	84%	60%	140%
Toluene	4195	3225563	< 0.05	< 0.05	NA	< 0.05	86%	60%	140%	91%	60%	140%	86%	60%	140%
Ethylbenzene	4195	3225563	< 0.01	< 0.01	NA	< 0.01	83%	60%	140%	99%	60%	140%	90%	60%	140%
m,p-Xylenes	4195	3225563	< 0.05	< 0.05	NA	< 0.05	83%	50%	140%	90%	60%	130%	83%	50%	140%
o-Xylene	4195	3225563	< 0.05	< 0.05	NA	< 0.05	83%	50%	140%	90%	60%	130%	83%	50%	140%
Xylenes	4195	3225563	< 0.05	< 0.05	NA	< 0.05	83%	60%	140%	90%	60%	140%	83%	60%	140%
C6 - C10 (F1)	4195	3225563	< 10	< 10	NA	< 10	114%	60%	140%	103%	60%	140%	103%	60%	140%
C>10 - C16	6567	3225563	< 10	< 10	NA	< 10	109%	60%	140%	90%	60%	140%	92%	60%	140%
C>16 - C34	6567	3225563	24	21	NA	< 10	110%	60%	140%	85%	60%	140%	86%	60%	140%
C>34 - C50	6567	3225563	< 10	< 10	NA	< 10	98%	60%	140%	78%	60%	140%	79%	60%	140%

Comments: Duplicate NA: results are less than 5X the RDL and RDP will not be calculated.
The sample spikes and dups are not from the same sample ID.

Certified By: Elena Gorobets

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T832162

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:MR

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Benzene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Toluene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Ethylbenzene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
m,p-Xylenes	TO-0543	EPA SW-846 5021 & 8260	GC/MS
o-Xylene	TO-0543	EPA SW-846 5021 & 8260	GC/MS
Xylenes	TO-0543	EPA SW-846 5021 & 8260	GC/MS
C6 - C10 (F1)	TO-0543	CCME Tier 1 Method	GC/FID
C6 - C10 (F1 minus BTEX)	TO-0543	CCME Tier 1 Method	GC/FID
C>10 - C16	TO-0560	CCME Tier 1 Method	GC/FID
C>16 - C34	TO-0560	CCME Tier 1 Method	GC/FID
C>34 - C50	TO-0560	CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	TO-0560	CCME Tier 1 Method	GRAVIMETRIC
Moisture Content	TO-0560	CCME Tier 1 Method	GC/FID
Toluene-d8 (BTEX)	TO-0543	EPA SW-846 5021 & 8260	GC/MS
o-Terphenyl (F2-F4)	TO 0560	CCME Tier 1 Method	GC/FID

Results relate only to the items tested. Results apply to samples as received.

1 large

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T832162

Cooler Quantity:
Arrival Temperatures: 13.9 | 14.1 | 14.2
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: large | ice

Report Information:

Company: WSP Canada Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Suite 201
Toronto, ON
Phone: 905-903-8405 Fax:
Reports to be sent to:
1. Email: Vanessa.Oetinger@wsp.com
2. Email:

Regulatory Requirements:

(Please check all applicable boxes)

☒ Regulation 153/04
Table 3 (Indicate One)
☒ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☒ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use
☐ Sanitary ☐ Storm
____ (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☐ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☐ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
*TAT is exclusive of weekends and statutory holidays

For 'Same Day' analysis, please contact your AGAT CPM

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: MR
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐

Company: WSP Canada Inc.
Contact:
Address:
Email: payables.ontario@wsp.com

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-34 S3	10/28/21	AM PM	2	S	limited hold time				X								
BH21-39 S3	11/5/21	AM PM	2	S					X								
BH21-29 S3	10/28/21	AM PM	2	S					X								
BH21-17 S2	11/5/21	AM PM	2	S					X								
BH21-41 S1	11/5/21	AM PM	2	S					X								
BH21-26 S3	10/28/21	AM PM	2	S					X								
BH21-27 S3	10/28/21	AM PM	2	S					X								
BH21-37 S3	10/29/21	AM PM	2	S					X								
BH21-23 S3	11/5/21	AM PM	2	S					X								
BH21-24 S3	11/5/21	AM PM	2	S					X								
BH21-35 S2	10/27/21	AM PM	2	S					X								

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Steven Andrachuk	11/18/21	4:00PM	Dave Eastman		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 NOV 18 4:59PM

Page 1 of 1

Nº: T 127116

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Document ID: DIV 76 1511 021

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: _____

Cooler Quantity: _____

Arrival Temperatures: _____ _____ _____ _____

Custody Seal Intact: ☐Yes ☐No ☐N/A

Notes: _____

Report Information:

Company: _____

Contact: _____

Address: _____

Phone: _____ Fax: _____

Reports to be sent to:

1. Email: _____

2. Email: See Page 1

Regulatory Requirements:

(Please check all applicable boxes)

☐ Regulation 153/04
Table _____ *Indicate One*
☐Ind/Com
☐Res/Park
☐Agriculture
Soil Texture *(Check One)*
☐Coarse
☐Fine

☐ Excess Soils R406
Table _____ *Indicate One*

☐ Regulation 558

☐ CCME

☐ Sewer Use
☐Sanitary ☐Storm
_____ *Region*

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
_____ *Indicate One*

Turnaround Time (TAT) Required:

Regular TAT ☐ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply): _____

Please provide prior notification for rush TAT

**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Project Information:

Project: _____

Site Location: _____

Sampled By: _____

AGAT Quote #: _____ PO: _____

Please note: If quotation number is not provided, client will be billed full price for analysis

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☐ Yes ☐ No

Invoice Information:

Bill To Same: Yes ☐ No ☐

Company: _____

Contact: _____

Address: _____

Email: _____

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC Y/N	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐CrVI, ☐Hg, ☐HWSB	O. Reg 153: BTEX, F1-F4 PHCs Analyze F4G if required ☐Yes ☐No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐M&I ☐VOCs ☐ABNs ☐B(a)P ☐PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐Metals ☐VOCs ☐SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-31 S3	11/5/21	AM PM	2	S	Limited hold time				X								
BH21-14 S3	10/29/21	AM PM	2	S					X								
BH21-33 S2	10/28/21	AM PM	2	S					X								
BH21-10 S3	10/29/21	AM PM	2	S					X								
		AM PM															
		AM PM															
		AM PM															
		AM PM															
		AM PM															
		AM PM															
		AM PM															

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
			Dave Eastman		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

'21 NOV 18 4:39PM

Page 2 of 2

N°: T 127117

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065

ATTENTION TO: Vanessa Oetinger

PROJECT: 211-1039-00

AGAT WORK ORDER: 21T834550

SOIL ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer

TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor

DATE REPORTED: Dec 03, 2021

PAGES (INCLUDING COVER): 26

VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy


O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-45 SS2	BH21-22 SS1	BH21-21 SS3	BH21-20 SS1	QAQC-6	BH21-19 SS2	BH21-18 SS1
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-11-22	2021-11-22	2021-11-23	2021-11-23	2021-11-23	2021-11-24	2021-11-24
Parameter	Unit	G / S	RDL	3248184	3248188	3248197	3248217	3248218	3248301	3248302
Antimony	µg/g	1.3	0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Arsenic	µg/g	18	1	7	6	5	6	5	6	6
Barium	µg/g	220	2.0	83.0	96.2	56.1	71.9	71.5	82.7	94.5
Beryllium	µg/g	2.5	0.4	0.5	0.5	<0.4	<0.4	<0.4	0.6	0.6
Boron	µg/g	36	5	9	9	8	<5	<5	11	7
Boron (Hot Water Soluble)	µg/g	NA	0.10	0.44	0.12	<0.10	0.21	0.22	0.11	0.26
Cadmium	µg/g	1.2	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	µg/g	70	5	25	24	14	20	20	25	25
Cobalt	µg/g	21	0.5	15.3	11.9	7.6	16.5	11.8	13.3	11.5
Copper	µg/g	92	1.0	33.8	29.7	23.4	48.7	25.8	25.2	33.4
Lead	µg/g	120	1	11	10	10	18	17	11	10
Molybdenum	µg/g	2	0.5	<0.5	<0.5	<0.5	0.6	0.6	<0.5	<0.5
Nickel	µg/g	82	1	33	23	13	142	25	26	24
Selenium	µg/g	1.5	0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8	<0.8
Silver	µg/g	0.5	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	µg/g	1	0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	µg/g	2.5	0.50	0.65	0.58	<0.50	0.51	<0.50	0.56	0.53
Vanadium	µg/g	86	0.4	34.0	34.9	22.7	30.9	30.7	35.8	35.1
Zinc	µg/g	290	5	68	57	35	61	67	59	66
Chromium, Hexavalent	µg/g	0.66	0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	µg/g	0.27	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	0.57	0.005	0.314	0.125	0.088	0.154	0.157	0.110	0.154
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	2.4	N/A	1.20	0.182	0.095	0.105	0.107	0.186	1.00
pH, 2:1 CaCl2 Extraction	pH Units		NA	7.60	7.64	7.62	7.44	7.36	7.56	7.55

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3248184-3248302 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-45 SS1	BH21-20 SS2	QAQC-7
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-22	2021-11-23	2021-11-23
Parameter	Unit	G / S	RDL	3248183	3248219	3248220
Gamma-Hexachlorocyclohexane	µg/g	0.01	0.005	<0.005	<0.005	<0.005
Heptachlor	µg/g	0.05	0.005	<0.005	<0.005	<0.005
Aldrin	µg/g	0.05	0.005	<0.005	<0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005	<0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005	<0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005	<0.005	<0.005
Endosulfan	µg/g	0.04	0.005	<0.005	<0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005	<0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007	<0.007	<0.007
op'-DDD	µg/g		0.005	<0.005	<0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005	<0.005	<0.005
DDD	µg/g	0.05	0.007	<0.007	<0.007	<0.007
op'-DDE	ug/g		0.005	<0.005	<0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005	<0.005	<0.005
DDE	µg/g	0.05	0.007	<0.007	<0.007	<0.007
op'-DDT	µg/g		0.005	<0.005	<0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005	<0.005	<0.005
DDT	µg/g	1.4	0.007	<0.007	<0.007	<0.007
Dieldrin	µg/g	0.05	0.005	<0.005	<0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005	<0.005	<0.005
Methoxychlor	µg/g	0.05	0.005	<0.005	<0.005	<0.005
Hexachlorobenzene	µg/g	0.01	0.005	<0.005	<0.005	<0.005
Hexachlorobutadiene	µg/g	0.01	0.01	<0.01	<0.01	<0.01
Hexachloroethane	µg/g	0.01	0.01	<0.01	<0.01	<0.01
Aroclor 1242	µg/g		0.10	<0.10	<0.10	<0.10
Aroclor 1248	µg/g		0.10	<0.10	<0.10	<0.10
Aroclor 1254	µg/g		0.10	<0.10	<0.10	<0.10
Aroclor 1260	µg/g		0.10	<0.10	<0.10	<0.10
Polychlorinated Biphenyls	µg/g	0.3	0.10	<0.10	<0.10	<0.10

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-45 SS1	BH21-20 SS2	QAQC-7
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-22	2021-11-23	2021-11-23
Parameter	Unit	G / S	RDL	3248183	3248219	3248220
Moisture Content	%		0.1	13.1	15.2	15.4
wet weight OC/PCB	g		NA	10.60	10.23	10.91
Surrogate	Unit	Acceptable Limits				
TCMX	%	50-140		89	88	83
Decachlorobiphenyl	%	50-140		105	86	89

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3248183-3248220 Results are based on the dry weight of the soil.
DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-45 SS1	BH21-22 SS3	BH21-21 SS1	BH21-20 SS2	QAQC-7	BH21-19 SS1	BH21-18 SS2
		SAMPLE TYPE:		Soil	Soil	Soil	Soil	Soil	Soil	Soil
		DATE SAMPLED:		2021-11-22	2021-11-22	2021-11-23	2021-11-23	2021-11-23	2021-11-24	2021-11-24
Parameter	Unit	G / S	RDL	3248183	3248189	3248196	3248219	3248220	3248227	3248305
Naphthalene	µg/g	0.09	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	µg/g	0.093	0.05	0.09	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	µg/g	0.072	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	µg/g	0.12	0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	µg/g	0.69	0.05	0.24	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	µg/g	0.16	0.05	0.13	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	µg/g	0.56	0.05	0.57	<0.05	<0.05	<0.05	<0.05	0.14	<0.05
Pyrene	µg/g	1	0.05	0.60	<0.05	<0.05	<0.05	<0.05	0.16	<0.05
Benz(a)anthracene	µg/g	0.36	0.05	0.39	<0.05	<0.05	<0.05	<0.05	0.17	<0.05
Chrysene	µg/g	2.8	0.05	0.35	<0.05	<0.05	<0.05	<0.05	0.07	<0.05
Benzo(b)fluoranthene	µg/g	0.47	0.05	0.45	<0.05	<0.05	<0.05	<0.05	0.10	<0.05
Benzo(k)fluoranthene	µg/g	0.48	0.05	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05	0.33	<0.05	<0.05	<0.05	<0.05	0.07	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.46	0.05	0.19	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05	0.06	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	µg/g	0.68	0.05	0.23	<0.05	<0.05	<0.05	<0.05	0.05	<0.05
1 and 2 Methlynaphthalene	µg/g	0.59	0.05	0.15	<0.05	<0.05	<0.05	<0.05	<0.05	<0.05
Moisture Content	%		0.1	13.1	12.1	16.4	15.2	15.4	23.9	14.2
Surrogate	Unit	Acceptable Limits								
Naphthalene-d8	%	50-140		98	102	74	107	105	77	78
Acridine-d9	%	50-140		96	78	86	82	97	97	85
Terphenyl-d14	%	50-140		108	84	95	99	88	83	99

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3248183-3248305 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-45 SS8	BH21-22 SS5	BH21-21 SS3
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-22	2021-11-22	2021-11-23
Parameter	Unit	G / S	RDL	3248186	3248195	3248197
F1 (C6 - C10)	µg/g	25	5	57	<5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	51	<5	<5
F2 (C10 to C16)	µg/g	10	10	<10	<10	<10
F3 (C16 to C34)	µg/g	240	50	<50	<50	<50
F4 (C34 to C50)	µg/g	120	50	<50	<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA	NA	NA
Moisture Content	%		0.1	10.0	12.3	10.0
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140		113	86	89
Terphenyl	%	60-140		72	78	75

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3248186-3248197 Results are based on sample dry weight.
The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified without the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-20 SS3	QAQC-8	BH21-19 SS2
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-23	2021-11-23	2021-11-24
Parameter	Unit	G / S	RDL	3248222	3248224	3248301
Benzene	µg/g	0.02	0.02	<0.02	<0.02	<0.02
Toluene	µg/g	0.2	0.05	<0.05	<0.05	<0.05
Ethylbenzene	µg/g	0.05	0.05	<0.05	<0.05	<0.05
m & p-Xylene	µg/g		0.05	<0.05	<0.05	<0.05
o-Xylene	µg/g		0.05	<0.05	<0.05	<0.05
Xylenes (Total)	µg/g	0.05	0.05	<0.05	<0.05	<0.05
F1 (C6 - C10)	µg/g	25	5	<5	<5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5	<5	<5
F2 (C10 to C16)	µg/g	10	10	<10	<10	<10
F3 (C16 to C34)	µg/g	240	50	<50	<50	<50
F4 (C34 to C50)	µg/g	120	50	<50	<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA	NA	NA
Moisture Content	%		0.1	11.4	11.3	9.6
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	60-140		94	88	77
Terphenyl	%	60-140		74	72	75

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-11-24


DATE REPORTED: 2021-12-03

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3248222-3248301 Results are based on sample dry weight.
The C6-C10 fraction is calculated using Toluene response factor.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.
Quality Control Data is available upon request.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-18 SS2
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-24
Parameter	Unit	G / S	RDL	3248305
Benzene	µg/g	0.02	0.02	<0.02
Toluene	µg/g	0.2	0.05	<0.05
Ethylbenzene	µg/g	0.05	0.05	<0.05
m & p-Xylene	µg/g		0.05	<0.05
o-Xylene	µg/g		0.05	<0.05
Xylenes (Total)	µg/g	0.05	0.05	<0.05
F1 (C6 - C10)	µg/g	25	5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5
F2 (C10 to C16)	µg/g	10	10	<10
F2 (C10 to C16) minus Naphthalene	µg/g		10	<10
F3 (C16 to C34)	µg/g	240	50	<50
F3 (C16 to C34) minus PAHs	µg/g		50	<50
F4 (C34 to C50)	µg/g	120	50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA
Moisture Content	%		0.1	14.2
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	60-140		72
Terphenyl	%	60-140		80

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3248305 Results are based on sample dry weight.
The C6-C10 fraction is calculated using toluene response factor.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

SAMPLE DESCRIPTION:				BH21-45 SS8	BH21-22 SS5	BH21-21 SS3
SAMPLE TYPE:				Soil	Soil	Soil
DATE SAMPLED:				2021-11-22	2021-11-22	2021-11-23
Parameter	Unit	G / S	RDL	3248186	3248195	3248197
Dichlorodifluoromethane	µg/g	0.05	0.05	<0.05	<0.05	<0.05
Vinyl Chloride	ug/g	0.02	0.02	<0.02	<0.02	<0.02
Bromomethane	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Trichlorofluoromethane	ug/g	0.25	0.05	<0.05	<0.05	<0.05
Acetone	ug/g	0.5	0.50	<0.50	<0.50	<0.50
Dichloroethylene, 1,1-	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Methylene Chloride	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Dichloroethylene, Trans- 1,2-	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Methyl tert-butyl Ether	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Dichloroethane, 1,1-	ug/g	0.05	0.02	<0.02	<0.02	<0.02
Methyl Ethyl Ketone	ug/g	0.5	0.50	<0.50	<0.50	<0.50
Dichloroethylene, Cis- 1,2-	ug/g	0.05	0.02	<0.02	<0.02	<0.02
Chloroform	ug/g	0.05	0.04	<0.04	<0.04	<0.04
Dichloroethane, 1,2-	ug/g	0.05	0.03	<0.03	<0.03	<0.03
Trichloroethane, 1,1,1-	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Carbon Tetrachloride	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Benzene	ug/g	0.02	0.02	<0.02	<0.02	<0.02
Dichloropropane, 1,2-	ug/g	0.05	0.03	<0.03	<0.03	<0.03
Trichloroethylene	ug/g	0.05	0.03	<0.03	<0.03	<0.03
Bromodichloromethane	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Methyl Isobutyl Ketone	ug/g	0.5	0.50	<0.50	<0.50	<0.50
Trichloroethane, 1,1,2-	ug/g	0.05	0.04	<0.04	<0.04	<0.04
Toluene	ug/g	0.2	0.05	<0.05	<0.05	<0.05
Dibromochloromethane	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Ethylene Dibromide	ug/g	0.05	0.04	<0.04	<0.04	<0.04
Tetrachloroethylene	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	ug/g	0.05	0.04	<0.04	<0.04	<0.04
Chlorobenzene	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Ethylbenzene	ug/g	0.05	0.05	0.90	<0.05	<0.05
Bromoform	ug/g	0.05	0.05	<0.05	<0.05	<0.05

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-11-24

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-45 SS8	BH21-22 SS5	BH21-21 SS3
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-11-22	2021-11-22	2021-11-23
Parameter	Unit	G / S	RDL	3248186	3248195	3248197
Styrene	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Tetrachloroethane, 1,1,2,2-	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,3-	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,4-	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Dichlorobenzene, 1,2-	ug/g	0.05	0.05	<0.05	<0.05	<0.05
Xylenes (Total)	ug/g	0.05	0.05	5.55	<0.05	<0.05
1,3-Dichloropropene (Cis + Trans)	µg/g	0.05	0.04	<0.04	<0.04	<0.04
Hexane, n-	µg/g	0.05	0.05	<0.05	<0.05	<0.05
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140		105	98	90
4-Bromofluorobenzene	% Recovery	50-140		81	76	99

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3248186-3248197 The sample was analyzed using the high level technique. The sample was extracted using methanol, a small amount of the methanol extract was diluted in water and the purge & trap GC/MS analysis was performed. Results are based on the dry weight of the soil.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene + o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3248183	BH21-45 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benz(a)anthracene	µg/g	0.36	0.39
3248183	BH21-45 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benzo(a)pyrene	µg/g	0.3	0.33
3248183	BH21-45 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Fluoranthene	µg/g	0.56	0.57
3248186	BH21-45 SS8	ON T1 S RPI/ICC	O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)	Ethylbenzene	µg/g	0.05	0.90
3248186	BH21-45 SS8	ON T1 S RPI/ICC	O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)	F1 (C6 - C10)	µg/g	25	57
3248186	BH21-45 SS8	ON T1 S RPI/ICC	O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)	F1 (C6 to C10) minus BTEX	µg/g	25	51
3248186	BH21-45 SS8	ON T1 S RPI/ICC	O. Reg. 153(511) - VOCs (Soil)	Ethylbenzene	ug/g	0.05	0.90
3248186	BH21-45 SS8	ON T1 S RPI/ICC	O. Reg. 153(511) - VOCs (Soil)	Xylenes (Total)	ug/g	0.05	5.55
3248217	BH21-20 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - Metals & Inorganics (Soil)	Nickel	µg/g	82	142

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-1039-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T834550
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3260700		<0.8	<0.8	NA	< 0.8	133%	70%	130%	110%	80%	120%	71%	70%	130%
Arsenic	3260700		4	4	NA	< 1	114%	70%	130%	107%	80%	120%	105%	70%	130%
Barium	3260700		128	126	1.6%	< 2.0	108%	70%	130%	105%	80%	120%	103%	70%	130%
Beryllium	3260700		0.7	0.7	NA	< 0.4	79%	70%	130%	100%	80%	120%	104%	70%	130%
Boron	3260700		9	9	NA	< 5	116%	70%	130%	101%	80%	120%	98%	70%	130%
Boron (Hot Water Soluble)	3259944		0.20	0.20	NA	< 0.10	99%	60%	140%	108%	70%	130%	114%	60%	140%
Cadmium	3260700		<0.5	<0.5	NA	< 0.5	91%	70%	130%	105%	80%	120%	108%	70%	130%
Chromium	3260700		31	32	3.2%	< 5	105%	70%	130%	106%	80%	120%	105%	70%	130%
Cobalt	3260700		11.3	11.4	0.9%	< 0.5	101%	70%	130%	107%	80%	120%	101%	70%	130%
Copper	3260700		20.5	20.7	1.0%	< 1.0	94%	70%	130%	106%	80%	120%	95%	70%	130%
Lead	3260700		15	14	6.9%	< 1	106%	70%	130%	110%	80%	120%	104%	70%	130%
Molybdenum	3260700		<0.5	<0.5	NA	< 0.5	103%	70%	130%	110%	80%	120%	106%	70%	130%
Nickel	3260700		24	23	4.3%	< 1	93%	70%	130%	101%	80%	120%	90%	70%	130%
Selenium	3260700		<0.8	<0.8	NA	< 0.8	98%	70%	130%	102%	80%	120%	102%	70%	130%
Silver	3260700		<0.5	<0.5	NA	< 0.5	102%	70%	130%	104%	80%	120%	97%	70%	130%
Thallium	3260700		<0.5	<0.5	NA	< 0.5	103%	70%	130%	104%	80%	120%	99%	70%	130%
Uranium	3260700		0.79	0.76	NA	< 0.50	113%	70%	130%	109%	80%	120%	106%	70%	130%
Vanadium	3260700		43.2	43.8	1.4%	< 0.4	107%	70%	130%	101%	80%	120%	105%	70%	130%
Zinc	3260700		75	71	5.5%	< 5	103%	70%	130%	105%	80%	120%	99%	70%	130%
Chromium, Hexavalent	3248684		<0.2	<0.2	NA	< 0.2	107%	70%	130%	90%	80%	120%	78%	70%	130%
Cyanide, Free	3248197	3248197	<0.040	<0.040	NA	< 0.040	97%	70%	130%	99%	80%	120%	95%	70%	130%
Mercury	3260700		<0.10	<0.10	NA	< 0.10	113%	70%	130%	107%	80%	120%	107%	70%	130%
Electrical Conductivity (2:1)	3255466		1.64	1.66	1.2%	< 0.005	107%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3255466		3.72	3.61	3.0%	NA									
pH, 2:1 CaCl2 Extraction	3259628		7.84	7.81	0.4%	NA	101%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-1039-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T834550
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3230140		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	115%	50%	140%	101%	50%	140%
Acenaphthylene	3230140		< 0.05	< 0.05	NA	< 0.05	89%	50%	140%	74%	50%	140%	82%	50%	140%
Acenaphthene	3230140		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	93%	50%	140%	83%	50%	140%
Fluorene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	93%	50%	140%	94%	50%	140%
Phenanthrene	3230140		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	92%	50%	140%	98%	50%	140%
Anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	67%	50%	140%	64%	50%	140%	85%	50%	140%
Fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	87%	50%	140%	97%	50%	140%	105%	50%	140%
Pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	85%	50%	140%	78%	50%	140%
Benz(a)anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	96%	50%	140%	85%	50%	140%
Chrysene	3230140		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	105%	50%	140%	93%	50%	140%
Benzo(b)fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	78%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3230140		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	88%	50%	140%	105%	50%	140%
Benzo(a)pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	96%	50%	140%	78%	50%	140%
Indeno(1,2,3-cd)pyrene	3230140		< 0.05	< 0.05	NA	< 0.05	75%	50%	140%	92%	50%	140%	88%	50%	140%
Dibenz(a,h)anthracene	3230140		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	105%	50%	140%	96%	50%	140%
Benzo(g,h,i)perylene	3230140		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	80%	50%	140%	93%	50%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Soil)															
Gamma-Hexachlorocyclohexane	3254478		< 0.005	< 0.005	NA	< 0.005	102%	50%	140%	86%	50%	140%	89%	50%	140%
Heptachlor	3254478		< 0.005	< 0.005	NA	< 0.005	88%	50%	140%	89%	50%	140%	80%	50%	140%
Aldrin	3254478		< 0.005	< 0.005	NA	< 0.005	108%	50%	140%	88%	50%	140%	104%	50%	140%
Heptachlor Epoxide	3254478		< 0.005	< 0.005	NA	< 0.005	109%	50%	140%	87%	50%	140%	106%	50%	140%
Endosulfan I	3254478		< 0.005	< 0.005	NA	< 0.005	112%	50%	140%	85%	50%	140%	102%	50%	140%
Endosulfan II	3254478		< 0.005	< 0.005	NA	< 0.005	106%	50%	140%	93%	50%	140%	87%	50%	140%
Alpha-Chlordane	3254478		< 0.005	< 0.005	NA	< 0.005	108%	50%	140%	86%	50%	140%	102%	50%	140%
gamma-Chlordane	3254478		< 0.005	< 0.005	NA	< 0.005	105%	50%	140%	85%	50%	140%	106%	50%	140%
op'-DDD	3254478		< 0.005	< 0.005	NA	< 0.005	105%	50%	140%	105%	50%	140%	102%	50%	140%
pp'-DDD	3254478		< 0.005	< 0.005	NA	< 0.005	106%	50%	140%	96%	50%	140%	103%	50%	140%
op'-DDE	3254478		< 0.005	< 0.005	NA	< 0.005	101%	50%	140%	95%	50%	140%	96%	50%	140%
pp'-DDE	3254478		< 0.005	< 0.005	NA	< 0.005	102%	50%	140%	89%	50%	140%	102%	50%	140%
op'-DDT	3254478		< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	86%	50%	140%	103%	50%	140%
pp'-DDT	3254478		< 0.005	< 0.005	NA	< 0.005	95%	50%	140%	106%	50%	140%	98%	50%	140%
Dieldrin	3254478		< 0.005	< 0.005	NA	< 0.005	107%	50%	140%	86%	50%	140%	102%	50%	140%
Endrin	3254478		< 0.005	< 0.005	NA	< 0.005	103%	50%	140%	105%	50%	140%	106%	50%	140%
Methoxychlor	3254478		< 0.005	< 0.005	NA	< 0.005	89%	50%	140%	86%	50%	140%	102%	50%	140%
Hexachlorobenzene	3254478		< 0.005	< 0.005	NA	< 0.005	104%	50%	140%	86%	50%	140%	105%	50%	140%
Hexachlorobutadiene	3254478		< 0.01	< 0.01	NA	< 0.01	84%	50%	140%	82%	50%	140%	106%	50%	140%
Hexachloroethane	3254478		< 0.01	< 0.01	NA	< 0.01	104%	50%	140%	80%	50%	140%	102%	50%	140%
Aroclor 1242	3254478		< 0.10	< 0.10	NA	< 0.10	106%	50%	140%	NA	50%	140%	NA	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-1039-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T834550
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Aroclor 1248	3254478		< 0.10	< 0.10	NA	< 0.10	102%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1254	3254478		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1260	3254478		< 0.10	< 0.10	NA	< 0.10	104%	50%	140%	NA	50%	140%	NA	50%	140%
Polychlorinated Biphenyls	3254478		< 0.10	< 0.10	NA	< 0.10	103%	50%	140%	90%	50%	140%	89%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)															
F1 (C6 - C10)	3248305	3248305	<5	<5	NA	< 5	107%	60%	140%	100%	60%	140%	109%	60%	140%
F2 (C10 to C16)	3274561		< 10	< 10	NA	< 10	110%	60%	140%	99%	60%	140%	79%	60%	140%
F3 (C16 to C34)	3274561		< 50	< 50	NA	< 50	93%	60%	140%	95%	60%	140%	79%	60%	140%
F4 (C34 to C50)	3274561		< 50	< 50	NA	< 50	93%	60%	140%	97%	60%	140%	79%	60%	140%
O. Reg. 153(511) - VOCs (Soil)															
Dichlorodifluoromethane	3257574		< 0.05	< 0.05	NA	< 0.05	80%	50%	140%	69%	50%	140%	71%	50%	140%
Vinyl Chloride	3257574		< 0.02	< 0.02	NA	< 0.02	98%	50%	140%	81%	50%	140%	73%	50%	140%
Bromomethane	3257574		< 0.05	< 0.05	NA	< 0.05	106%	50%	140%	106%	50%	140%	97%	50%	140%
Trichlorofluoromethane	3257574		< 0.05	< 0.05	NA	< 0.05	101%	50%	140%	100%	50%	140%	105%	50%	140%
Acetone	3257574		< 0.50	< 0.50	NA	< 0.50	110%	50%	140%	103%	50%	140%	99%	50%	140%
Dichloroethylene, 1,1-	3257574		< 0.05	< 0.05	NA	< 0.05	89%	50%	140%	75%	60%	130%	85%	50%	140%
Methylene Chloride	3257574		< 0.05	< 0.05	NA	< 0.05	94%	50%	140%	107%	60%	130%	106%	50%	140%
Dichloroethylene, Trans- 1,2-	3257574		< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	77%	60%	130%	97%	50%	140%
Methyl tert-butyl Ether	3257574		< 0.05	< 0.05	NA	< 0.05	89%	50%	140%	92%	60%	130%	77%	50%	140%
Dichloroethane, 1,1-	3257574		< 0.02	< 0.02	NA	< 0.02	105%	50%	140%	100%	60%	130%	114%	50%	140%
Methyl Ethyl Ketone	3257574		< 0.50	< 0.50	NA	< 0.50	107%	50%	140%	102%	50%	140%	96%	50%	140%
Dichloroethylene, Cis- 1,2-	3257574		< 0.02	< 0.02	NA	< 0.02	113%	50%	140%	83%	60%	130%	117%	50%	140%
Chloroform	3257574		< 0.04	< 0.04	NA	< 0.04	117%	50%	140%	93%	60%	130%	117%	50%	140%
Dichloroethane, 1,2-	3257574		< 0.03	< 0.03	NA	< 0.03	112%	50%	140%	119%	60%	130%	103%	50%	140%
Trichloroethane, 1,1,1-	3257574		< 0.05	< 0.05	NA	< 0.05	77%	50%	140%	98%	60%	130%	79%	50%	140%
Carbon Tetrachloride	3257574		< 0.05	< 0.05	NA	< 0.05	74%	50%	140%	76%	60%	130%	79%	50%	140%
Benzene	3257574		< 0.02	< 0.02	NA	< 0.02	104%	50%	140%	75%	60%	130%	107%	50%	140%
Dichloropropane, 1,2-	3257574		< 0.03	< 0.03	NA	< 0.03	87%	50%	140%	98%	60%	130%	95%	50%	140%
Trichloroethylene	3257574		< 0.03	< 0.03	NA	< 0.03	87%	50%	140%	110%	60%	130%	87%	50%	140%
Bromodichloromethane	3257574		< 0.05	< 0.05	NA	< 0.05	100%	50%	140%	76%	60%	130%	101%	50%	140%
Methyl Isobutyl Ketone	3257574		< 0.50	< 0.50	NA	< 0.50	99%	50%	140%	104%	50%	140%	101%	50%	140%
Trichloroethane, 1,1,2-	3257574		< 0.04	< 0.04	NA	< 0.04	93%	50%	140%	85%	60%	130%	105%	50%	140%
Toluene	3257574		< 0.05	< 0.05	NA	< 0.05	82%	50%	140%	86%	60%	130%	108%	50%	140%
Dibromochloromethane	3257574		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	100%	60%	130%	116%	50%	140%
Ethylene Dibromide	3257574		< 0.04	< 0.04	NA	< 0.04	76%	50%	140%	92%	60%	130%	102%	50%	140%
Tetrachloroethylene	3257574		< 0.05	< 0.05	NA	< 0.05	100%	50%	140%	80%	60%	130%	104%	50%	140%
Tetrachloroethane, 1,1,1,2-	3257574		< 0.04	< 0.04	NA	< 0.04	115%	50%	140%	98%	60%	130%	100%	50%	140%
Chlorobenzene	3257574		< 0.05	< 0.05	NA	< 0.05	118%	50%	140%	84%	60%	130%	106%	50%	140%
Ethylbenzene	3257574		< 0.05	< 0.05	NA	< 0.05	72%	50%	140%	87%	60%	130%	80%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-1039-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T834550
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Bromoform	3257574		< 0.05	< 0.05	NA	< 0.05	101%	50%	140%	108%	60%	130%	113%	50%	140%
Styrene	3257574		< 0.05	< 0.05	NA	< 0.05	81%	50%	140%	77%	60%	130%	74%	50%	140%
Tetrachloroethane, 1,1,2,2-	3257574		< 0.05	< 0.05	NA	< 0.05	116%	50%	140%	114%	60%	130%	94%	50%	140%
Dichlorobenzene, 1,3-	3257574		< 0.05	< 0.05	NA	< 0.05	83%	50%	140%	102%	60%	130%	82%	50%	140%
Dichlorobenzene, 1,4-	3257574		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	94%	60%	130%	98%	50%	140%
Dichlorobenzene, 1,2-	3257574		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	101%	60%	130%	74%	50%	140%
Hexane, n-	3257574		< 0.05	< 0.05	NA	< 0.05	103%	50%	140%	72%	60%	130%	71%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Soil)															
Benzene	3248305	3248305	<0.02	<0.02	NA	< 0.02	112%	60%	140%	110%	60%	140%	82%	60%	140%
Toluene	3248305	3248305	<0.05	<0.05	NA	< 0.05	95%	60%	140%	94%	60%	140%	96%	60%	140%
Ethylbenzene	3248305	3248305	<0.05	<0.05	NA	< 0.05	85%	60%	140%	85%	60%	140%	90%	60%	140%
m & p-Xylene	3248305	3248305	<0.05	<0.05	NA	< 0.05	90%	60%	140%	115%	60%	140%	96%	60%	140%
o-Xylene	3248305	3248305	<0.05	<0.05	NA	< 0.05	97%	60%	140%	82%	60%	140%	97%	60%	140%
F1 (C6 - C10)	3248305	3248305	<5	<5	NA	< 5	107%	60%	140%	100%	60%	140%	109%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

ATTENTION TO: Vanessa Oetinger

RPT Date: Dec 03, 2021		REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Sample Id	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Antimony		133%	70%	130%	110%	80%	120%	71%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan I	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan II	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Alpha-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
op'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
Dieldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Methoxychlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
TCMX	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Decachlorobiphenyl	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
wet weight OC/PCB	ORG-91-5113		BALANCE
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Benzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Toluene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Ethylbenzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
m & p-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
o-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Xylenes (Total)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	P&T GC/FID
F2 (C10 to C16) minus Naphthalene	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Dichlorodifluoromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Vinyl Chloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromomethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Acetone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, 1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methylene Chloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, Trans- 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl tert-butyl Ether	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethane, 1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, Cis- 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Chloroform	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethane, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethane, 1,1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Benzene	VOL-91-5002	modified from EPA 5035C and EPA 8260D	(P&T)GC/MS
Dichloropropane, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethylene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromodichloromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethane, 1,1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Toluene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dibromochloromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethane, 1,1,1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Chlorobenzene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Ethylbenzene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromoform	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Styrene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethane, 1,1,2,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichlorobenzene, 1,3-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichlorobenzene, 1,4-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834550

PROJECT: 211-1039-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Dichlorobenzene, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Xylenes (Total)	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
1,3-Dichloropropene (Cis + Trans)	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Hexane, n-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Toluene-d8	VOL-91-5002	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5002	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T834550. Large
Cooler Quantity:
Arrival Temperatures: 6.4 | 6.2 | 5.1
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: Free ICE

Report Information:

Company: WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: if quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04 — Table 1 (Indicate One) — ☑ Ind/Com ☐ Res/Park ☐ Agriculture
Soil Texture (Check One): ☑ Coarse ☐ Fine
☐ Excess Soils R406 — Table (Indicate One)
☐ Regulation 558
☐ CCME
☐ Sewer Use ☐ Sanitary ☐ Storm — Region
☐ Prov. Water Quality Objectives (PWQO)
☐ Other (Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
*TAT is exclusive of weekends and statutory holidays

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	BTEX, F1-F4 PHCs — Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach — SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides			HOLD SAMPLE		Potentially Hazardous or High Concentration (Y/N)
BH21-45 SS1	11/22/21	PM	2	S						X	X						X					
BH21-45 SS2		PM	1	S			X															
BH21-45 SS4		PM	2	S					X											X		
BH21-45 SS6		PM	2	S					X			X										
BH21-22 SS1		AM/PM	1	S			X															
BH21-22 ~~SS3~~ SS3		AM/PM	2	S						X	X						X					
BH21-22 SS4		AM/PM	1	S			X													X		
BH21-22 SS5		AM/PM	2	S					X			X										
BH21-21 SS1	11/23/21	PM	2	S						X	X						X					
BH21-21 SS3		PM	3	S			X		X			X										
BH21-21 SS4		PM	2	S					X											X		

23 NOV 24 1256PM

Samples Relinquished By (Print Name and Sign)	Date	Time	Samples Received By (Print Name and Sign)	Date	Time
Matthew Roy	11/24/21	1430	NEAL		

Page 1 of 2

N°: T 127100

Pink Copy - Client | Yellow Copy - AGAT | White Copy - AGAT

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only
Work Order #:
Cooler Quantity:
Arrival Temperatures: See Pg1
Custody Seal Intact: ☐Yes ☐No ☐N/A
Notes:

Report Information: See Page 1
Company:
Contact:
Address:
Phone: Fax:
Reports to be sent to:
1. Email:
2. Email:

Regulatory Requirements:
(Please check all applicable boxes)
☑ Regulation 153/04 — Table 1 (Indicate One) — ☑ Ind/Com ☐ Res/Park ☐ Agriculture
Soil Texture (Check One) ☑ Coarse ☐ Fine
☐ Excess Soils R406 — Table (Indicate One)
☐ Regulation 558
☐ CCME
☐ Sewer Use ☐ Sanitary ☐ Storm — (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other (Indicate One)

Turnaround Time (TAT) Required:
Regular TAT ☑ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply):
Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*
For 'Same Day' analysis, please contact your AGAT CPM

Project Information:
Project: 211-10139-00
Site Location: ORGY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Invoice Information: Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email:

Sample Matrix Legend
B Biota
GW Ground Water
O Oil
P Paint
S Soil
SD Sediment
SW Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	BTEX, F1-F4 PHCs — Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	HOLD SAMPLE	Potentially Hazardous or High Concentration (Y/N)
BH21-20 SS1	11/23/21	AM	1	S			X												
~~BH21-20~~ QAQC-6	1	AM	1	S			X												
BH21-20 SS2		AM	2	S						X	X						X		
QAQC-7		AM	2	S						X	X						X		
BH21-20 SS3		AM	2	S					X										
QAQC-8		AM	2	S					X										
BH21-20 SS3		AM	1	S			X											X	
BH21-19 SS1	11/24/21	PM	1	S						X									
BH21-19 SS2		PM	3	S			X		X										
BH21-18 SS1		AM	1	S			X												
BH21-18 SS2		AM	4	S					X	X	X						X		

Samples Relinquished By (Print Name and Sign)	Date	Time	Samples Received By (Print Name and Sign)	Date	Time
Matthew Roy	11/24/21	1430			

21 NOV 24 2:56pm

Page 2 of 2

N°: T 127099

Document ID: DIV 78 1511 021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065

ATTENTION TO: Vanessa Oetinger

PROJECT: 211-10139-00

AGAT WORK ORDER: 21T836979

SOIL ANALYSIS REVIEWED BY: Jacky Zhu, Spectroscopy Technician

TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor

DATE REPORTED: Dec 14, 2021

PAGES (INCLUDING COVER): 19

VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy


O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-29

DATE REPORTED: 2021-12-14

		SAMPLE DESCRIPTION:		BH21-7 SS2	BH21-8 SS2
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-29	2021-11-29
Parameter	Unit	G / S	RDL	3269234	3269312
Antimony	µg/g	1.3	0.8	<0.8	<0.8
Arsenic	µg/g	18	1	6	6
Barium	µg/g	220	2.0	57.1	57.4
Beryllium	µg/g	2.5	0.4	0.7	0.5
Boron	µg/g	36	5	11	10
Boron (Hot Water Soluble)	µg/g	NA	0.10	0.25	0.21
Cadmium	µg/g	1.2	0.5	<0.5	<0.5
Chromium	µg/g	70	5	22	19
Cobalt	µg/g	21	0.5	10.4	10.0
Copper	µg/g	92	1.0	29.1	31.5
Lead	µg/g	120	1	10	12
Molybdenum	µg/g	2	0.5	<0.5	<0.5
Nickel	µg/g	82	1	21	20
Selenium	µg/g	1.5	0.8	<0.8	<0.8
Silver	µg/g	0.5	0.5	<0.5	<0.5
Thallium	µg/g	1	0.5	<0.5	<0.5
Uranium	µg/g	2.5	0.50	0.59	<0.50
Vanadium	µg/g	86	0.4	31.9	28.4
Zinc	µg/g	290	5	55	51
Chromium, Hexavalent	µg/g	0.66	0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040
Mercury	µg/g	0.27	0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	0.57	0.005	0.245	0.117
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	2.4	N/A	2.17	0.122
pH, 2:1 CaCl2 Extraction	pH Units		NA	7.19	7.12

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-11-29


DATE REPORTED: 2021-12-14

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3269234-3269312 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy


O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-29

DATE REPORTED: 2021-12-14

		SAMPLE DESCRIPTION:		BH21-7 SS1
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-29
Parameter	Unit	G / S	RDL	3269233
Gamma-Hexachlorocyclohexane	µg/g	0.01	0.005	<0.005
Heptachlor	µg/g	0.05	0.005	<0.005
Aldrin	µg/g	0.05	0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005
Endosulfan	µg/g	0.04	0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007
op'-DDD	µg/g		0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005
DDD	µg/g	0.05	0.007	<0.007
op'-DDE	ug/g		0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005
DDE	µg/g	0.05	0.007	<0.007
op'-DDT	µg/g		0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005
DDT	µg/g	1.4	0.007	<0.007
Dieldrin	µg/g	0.05	0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005
Methoxychlor	µg/g	0.05	0.005	<0.005
Hexachlorobenzene	µg/g	0.01	0.005	<0.005
Hexachlorobutadiene	µg/g	0.01	0.01	<0.01
Hexachloroethane	µg/g	0.01	0.01	<0.01
Aroclor 1242	µg/g		0.10	<0.10
Aroclor 1248	µg/g		0.10	<0.10
Aroclor 1254	µg/g		0.10	<0.10
Aroclor 1260	µg/g		0.10	<0.10
Polychlorinated Biphenyls	µg/g	0.3	0.10	<0.10

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-11-29

DATE REPORTED: 2021-12-14

		SAMPLE DESCRIPTION:		BH21-7 SS1
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-29
Parameter	Unit	G / S	RDL	3269233
Moisture Content	%		0.1	22.1
wet weight OC/PCB	g		NA	10.05
Surrogate	Unit	Acceptable Limits		
TCMX	%	50-140		74
Decachlorobiphenyl	%	50-140		80

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3269233 Results are based on the dry weight of the soil.
DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-11-29

DATE REPORTED: 2021-12-14

		SAMPLE DESCRIPTION:		BH21-7 SS1	BH21-8 SS1
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-29	2021-11-29
Parameter	Unit	G / S	RDL	3269233	3269311
Naphthalene	µg/g	0.09	0.05	<0.05	<0.05
Acenaphthylene	µg/g	0.093	0.05	0.06	<0.05
Acenaphthene	µg/g	0.072	0.05	<0.05	<0.05
Fluorene	µg/g	0.12	0.05	<0.05	<0.05
Phenanthrene	µg/g	0.69	0.05	0.40	0.22
Anthracene	µg/g	0.16	0.05	0.18	0.10
Fluoranthene	µg/g	0.56	0.05	1.05	0.89
Pyrene	µg/g	1	0.05	0.96	0.77
Benz(a)anthracene	µg/g	0.36	0.05	0.56	0.46
Chrysene	µg/g	2.8	0.05	0.41	0.36
Benzo(b)fluoranthene	µg/g	0.47	0.05	0.60	0.66
Benzo(k)fluoranthene	µg/g	0.48	0.05	0.23	0.24
Benzo(a)pyrene	µg/g	0.3	0.05	0.40	0.40
Indeno(1,2,3-cd)pyrene	µg/g	0.46	0.05	0.22	0.26
Dibenz(a,h)anthracene	µg/g	0.1	0.05	0.05	0.05
Benzo(g,h,i)perylene	µg/g	0.68	0.05	0.27	0.34
1 and 2 Methlynaphthalene	µg/g	0.59	0.05	<0.05	<0.05
Moisture Content	%		0.1	22.1	23.9
Surrogate	Unit	Acceptable Limits			
Naphthalene-d8	%	50-140		109	109
Acridine-d9	%	50-140		109	83
Terphenyl-d14	%	50-140		96	99

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3269233-3269311 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)

DATE RECEIVED: 2021-11-29

DATE REPORTED: 2021-12-14

		SAMPLE DESCRIPTION:		BH21-7 SS5	BH21-8 SS7
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-29	2021-11-29
Parameter	Unit	G / S	RDL	3269235	3269313
F1 (C6 - C10)	µg/g	25	5	<5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5	<5
F2 (C10 to C16)	µg/g	10	10	<10	<10
F3 (C16 to C34)	µg/g	240	50	<50	<50
F4 (C34 to C50)	µg/g	120	50	<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA	NA
Moisture Content	%		0.1	10.0	10.1
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	50-140		54	107
Terphenyl	%	60-140		88	97

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3269235-3269313 Results are based on sample dry weight.
The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified without the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy


O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-11-29

DATE REPORTED: 2021-12-14

		SAMPLE DESCRIPTION:		BH21-7 SS5	BH21-8 SS7
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-29	2021-11-29
Parameter	Unit	G / S	RDL	3269235	3269313
Dichlorodifluoromethane	µg/g	0.05	0.05	<0.05	<0.05
Vinyl Chloride	ug/g	0.02	0.02	<0.02	<0.02
Bromomethane	ug/g	0.05	0.05	<0.05	<0.05
Trichlorofluoromethane	ug/g	0.25	0.05	<0.05	<0.05
Acetone	ug/g	0.5	0.50	<0.50	<0.50
Dichloroethylene, 1,1-	ug/g	0.05	0.05	<0.05	<0.05
Methylene Chloride	ug/g	0.05	0.05	<0.05	<0.05
Dichloroethylene, Trans- 1,2-	ug/g	0.05	0.05	<0.05	<0.05
Methyl tert-butyl Ether	ug/g	0.05	0.05	<0.05	<0.05
Dichloroethane, 1,1-	ug/g	0.05	0.02	<0.02	<0.02
Methyl Ethyl Ketone	ug/g	0.5	0.50	<0.50	<0.50
Dichloroethylene, Cis- 1,2-	ug/g	0.05	0.02	<0.02	<0.02
Chloroform	ug/g	0.05	0.04	<0.04	<0.04
Dichloroethane, 1,2-	ug/g	0.05	0.03	<0.03	<0.03
Trichloroethane, 1,1,1-	ug/g	0.05	0.05	<0.05	<0.05
Carbon Tetrachloride	ug/g	0.05	0.05	<0.05	<0.05
Benzene	ug/g	0.02	0.02	<0.02	<0.02
Dichloropropane, 1,2-	ug/g	0.05	0.03	<0.03	<0.03
Trichloroethylene	ug/g	0.05	0.03	<0.03	<0.03
Bromodichloromethane	ug/g	0.05	0.05	<0.05	<0.05
Methyl Isobutyl Ketone	ug/g	0.5	0.50	<0.50	<0.50
Trichloroethane, 1,1,2-	ug/g	0.05	0.04	<0.04	<0.04
Toluene	ug/g	0.2	0.05	<0.05	<0.05
Dibromochloromethane	ug/g	0.05	0.05	<0.05	<0.05
Ethylene Dibromide	ug/g	0.05	0.04	<0.04	<0.04
Tetrachloroethylene	ug/g	0.05	0.05	<0.05	<0.05
Tetrachloroethane, 1,1,1,2-	ug/g	0.05	0.04	<0.04	<0.04
Chlorobenzene	ug/g	0.05	0.05	<0.05	<0.05
Ethylbenzene	ug/g	0.05	0.05	<0.05	<0.05
Bromoform	ug/g	0.05	0.05	<0.05	<0.05

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-11-29

DATE REPORTED: 2021-12-14

		SAMPLE DESCRIPTION:		BH21-7 SS5	BH21-8 SS7
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-29	2021-11-29
Parameter	Unit	G / S	RDL	3269235	3269313
Styrene	ug/g	0.05	0.05	<0.05	<0.05
Tetrachloroethane, 1,1,2,2-	ug/g	0.05	0.05	<0.05	<0.05
Dichlorobenzene, 1,3-	ug/g	0.05	0.05	<0.05	<0.05
Dichlorobenzene, 1,4-	ug/g	0.05	0.05	<0.05	<0.05
Dichlorobenzene, 1,2-	ug/g	0.05	0.05	<0.05	<0.05
Xylenes (Total)	ug/g	0.05	0.05	<0.05	<0.05
1,3-Dichloropropene (Cis + Trans)	µg/g	0.05	0.04	<0.04	<0.04
Hexane, n-	µg/g	0.05	0.05	<0.05	<0.05
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	50-140		99	104
4-Bromofluorobenzene	% Recovery	50-140		76	74

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3269235-3269313 The sample was analyzed using the high level technique. The sample was extracted using methanol, a small amount of the methanol extract was diluted in water and the purge & trap GC/MS analysis was performed. Results are based on the dry weight of the soil.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene + o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3269233	BH21-7 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Anthracene	µg/g	0.16	0.18
3269233	BH21-7 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benz(a)anthracene	µg/g	0.36	0.56
3269233	BH21-7 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benzo(a)pyrene	µg/g	0.3	0.40
3269233	BH21-7 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benzo(b)fluoranthene	µg/g	0.47	0.60
3269233	BH21-7 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Fluoranthene	µg/g	0.56	1.05
3269311	BH21-8 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benz(a)anthracene	µg/g	0.36	0.46
3269311	BH21-8 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benzo(a)pyrene	µg/g	0.3	0.40
3269311	BH21-8 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benzo(b)fluoranthene	µg/g	0.47	0.66
3269311	BH21-8 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Fluoranthene	µg/g	0.56	0.89

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail


AGAT WORK ORDER: 21T836979
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Dec 14, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3281970		<0.8	<0.8	NA	< 0.8	128%	70%	130%	102%	80%	120%	77%	70%	130%
Arsenic	3281970		4	4	NA	< 1	106%	70%	130%	98%	80%	120%	96%	70%	130%
Barium	3281970		278	315	12.5%	< 2.0	103%	70%	130%	104%	80%	120%	106%	70%	130%
Beryllium	3281970		0.8	0.8	NA	< 0.4	105%	70%	130%	98%	80%	120%	92%	70%	130%
Boron	3281970		34	35	2.9%	< 5	99%	70%	130%	109%	80%	120%	114%	70%	130%
Boron (Hot Water Soluble)	3266366		2.40	2.48	3.3%	< 0.10	93%	60%	140%	99%	70%	130%	NA	60%	140%
Cadmium	3281970		<0.5	<0.5	NA	< 0.5	103%	70%	130%	101%	80%	120%	101%	70%	130%
Chromium	3281970		23	24	NA	< 5	100%	70%	130%	103%	80%	120%	110%	70%	130%
Cobalt	3281970		10.8	11.5	6.3%	< 0.5	94%	70%	130%	102%	80%	120%	98%	70%	130%
Copper	3281970		6.0	6.2	3.3%	< 1.0	92%	70%	130%	106%	80%	120%	93%	70%	130%
Lead	3281970		10	15	40.0%	< 1	105%	70%	130%	106%	80%	120%	98%	70%	130%
Molybdenum	3281970		0.9	1.0	NA	< 0.5	101%	70%	130%	104%	80%	120%	101%	70%	130%
Nickel	3281970		23	24	4.3%	< 1	93%	70%	130%	102%	80%	120%	97%	70%	130%
Selenium	3281970		<0.8	<0.8	NA	< 0.8	130%	70%	130%	94%	80%	120%	93%	70%	130%
Silver	3281970		<0.5	<0.5	NA	< 0.5	102%	70%	130%	102%	80%	120%	97%	70%	130%
Thallium	3281970		<0.5	<0.5	NA	< 0.5	107%	70%	130%	104%	80%	120%	98%	70%	130%
Uranium	3281970		0.73	0.76	NA	< 0.50	109%	70%	130%	108%	80%	120%	102%	70%	130%
Vanadium	3281970		28.4	30.5	7.1%	< 0.4	104%	70%	130%	99%	80%	120%	103%	70%	130%
Zinc	3281970		50	51	2.0%	< 5	96%	70%	130%	99%	80%	120%	96%	70%	130%
Chromium, Hexavalent	3270066		<0.2	<0.2	NA	< 0.2	103%	70%	130%	98%	80%	120%	91%	70%	130%
Cyanide, Free	3287123		<0.040	<0.040	NA	< 0.040	101%	70%	130%	103%	80%	120%	92%	70%	130%
Mercury	3281970		<0.10	<0.10	NA	< 0.10	106%	70%	130%	98%	80%	120%	90%	70%	130%
Electrical Conductivity (2:1)	3266366		2.07	2.13	2.9%	< 0.005	105%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3266366		0.191	0.196	2.6%	NA									
pH, 2:1 CaCl2 Extraction	3266373		6.99	7.06	1.0%	NA	99%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
Matrix spike: Spike level < native concentration. Matrix spike acceptance limits do not apply.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T836979
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Dec 14, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3257319		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	105%	50%	140%	105%	50%	140%
Acenaphthylene	3257319		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	83%	50%	140%	98%	50%	140%
Acenaphthene	3257319		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	92%	50%	140%	83%	50%	140%
Fluorene	3257319		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	94%	50%	140%	88%	50%	140%
Phenanthrene	3257319		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	98%	50%	140%	74%	50%	140%
Anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	86%	50%	140%	82%	50%	140%
Fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	68%	50%	140%	88%	50%	140%	91%	50%	140%
Pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	74%	50%	140%	107%	50%	140%
Benz(a)anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	80%	50%	140%	85%	50%	140%	87%	50%	140%
Chrysene	3257319		< 0.05	< 0.05	NA	< 0.05	95%	50%	140%	90%	50%	140%	85%	50%	140%
Benzo(b)fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	105%	50%	140%	96%	50%	140%
Benzo(k)fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	98%	50%	140%	105%	50%	140%
Benzo(a)pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	86%	50%	140%	98%	50%	140%
Indeno(1,2,3-cd)pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	88%	50%	140%	86%	50%	140%
Dibenz(a,h)anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	74%	50%	140%	88%	50%	140%
Benzo(g,h,i)perylene	3257319		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	82%	50%	140%	80%	50%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Soil)															
Gamma-Hexachlorocyclohexane	3287133		< 0.005	< 0.005	NA	< 0.005	94%	50%	140%	83%	50%	140%	80%	50%	140%
Heptachlor	3287133		< 0.005	< 0.005	NA	< 0.005	86%	50%	140%	83%	50%	140%	82%	50%	140%
Aldrin	3287133		< 0.005	< 0.005	NA	< 0.005	98%	50%	140%	89%	50%	140%	90%	50%	140%
Heptachlor Epoxide	3287133		< 0.005	< 0.005	NA	< 0.005	85%	50%	140%	86%	50%	140%	87%	50%	140%
Endosulfan I	3287133		< 0.005	< 0.005	NA	< 0.005	82%	50%	140%	84%	50%	140%	98%	50%	140%
Endosulfan II	3287133		< 0.005	< 0.005	NA	< 0.005	85%	50%	140%	98%	50%	140%	104%	50%	140%
Alpha-Chlordane	3287133		< 0.005	< 0.005	NA	< 0.005	82%	50%	140%	92%	50%	140%	92%	50%	140%
gamma-Chlordane	3287133		< 0.005	< 0.005	NA	< 0.005	89%	50%	140%	90%	50%	140%	96%	50%	140%
op'-DDD	3287133		< 0.005	< 0.005	NA	< 0.005	105%	50%	140%	80%	50%	140%	102%	50%	140%
pp'-DDD	3287133		< 0.005	< 0.005	NA	< 0.005	94%	50%	140%	82%	50%	140%	106%	50%	140%
op'-DDE	3287133		< 0.005	< 0.005	NA	< 0.005	86%	50%	140%	87%	50%	140%	80%	50%	140%
pp'-DDE	3287133		< 0.005	< 0.005	NA	< 0.005	94%	50%	140%	86%	50%	140%	89%	50%	140%
op'-DDT	3287133		< 0.005	< 0.005	NA	< 0.005	86%	50%	140%	80%	50%	140%	102%	50%	140%
pp'-DDT	3287133		< 0.005	< 0.005	NA	< 0.005	87%	50%	140%	84%	50%	140%	98%	50%	140%
Dieldrin	3287133		< 0.005	< 0.005	NA	< 0.005	85%	50%	140%	98%	50%	140%	104%	50%	140%
Endrin	3287133		< 0.005	< 0.005	NA	< 0.005	94%	50%	140%	102%	50%	140%	98%	50%	140%
Methoxychlor	3287133		< 0.005	< 0.005	NA	< 0.005	87%	50%	140%	96%	50%	140%	92%	50%	140%
Hexachlorobenzene	3287133		< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	92%	50%	140%	90%	50%	140%
Hexachlorobutadiene	3287133		< 0.01	< 0.01	NA	< 0.01	83%	50%	140%	86%	50%	140%	84%	50%	140%
Hexachloroethane	3287133		< 0.01	< 0.01	NA	< 0.01	82%	50%	140%	79%	50%	140%	78%	50%	140%
Aroclor 1242	3287133		< 0.10	< 0.10	NA	< 0.10	104%	50%	140%	NA	50%	140%	NA	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T836979
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Dec 14, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Aroclor 1248	3287133		< 0.10	< 0.10	NA	< 0.10	106%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1254	3287133		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1260	3287133		< 0.10	< 0.10	NA	< 0.10	102%	50%	140%	NA	50%	140%	NA	50%	140%
Polychlorinated Biphenyls	3287133		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	85%	50%	140%	80%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)															
F1 (C6 - C10)	3276907		<5	<5	NA	< 5	100%	60%	140%	98%	60%	140%	100%	60%	140%
F2 (C10 to C16)	3269313	3269313	< 10	< 10	NA	< 10	104%	60%	140%	96%	60%	140%	77%	60%	140%
F3 (C16 to C34)	3269313	3269313	< 50	< 50	NA	< 50	85%	60%	140%	78%	60%	140%	71%	60%	140%
F4 (C34 to C50)	3269313	3269313	< 50	< 50	NA	< 50	96%	60%	140%	108%	60%	140%	112%	60%	140%
O. Reg. 153(511) - VOCs (Soil)															
Dichlorodifluoromethane	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	79%	50%	140%	102%	50%	140%	103%	50%	140%
Vinyl Chloride	3269313	3269313	< 0.02	< 0.02	NA	< 0.02	98%	50%	140%	88%	50%	140%	100%	50%	140%
Bromomethane	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	81%	50%	140%	98%	50%	140%
Trichlorofluoromethane	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	77%	50%	140%	88%	50%	140%	97%	50%	140%
Acetone	3269313	3269313	< 0.50	< 0.50	NA	< 0.50	98%	50%	140%	101%	50%	140%	102%	50%	140%
Dichloroethylene, 1,1-	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	104%	50%	140%	85%	60%	130%	74%	50%	140%
Methylene Chloride	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	80%	50%	140%	106%	60%	130%	106%	50%	140%
Dichloroethylene, Trans- 1,2-	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	117%	50%	140%	105%	60%	130%	93%	50%	140%
Methyl tert-butyl Ether	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	72%	60%	130%	86%	50%	140%
Dichloroethane, 1,1-	3269313	3269313	< 0.02	< 0.02	NA	< 0.02	109%	50%	140%	108%	60%	130%	107%	50%	140%
Methyl Ethyl Ketone	3269313	3269313	< 0.50	< 0.50	NA	< 0.50	102%	50%	140%	99%	50%	140%	104%	50%	140%
Dichloroethylene, Cis- 1,2-	3269313	3269313	< 0.02	< 0.02	NA	< 0.02	101%	50%	140%	109%	60%	130%	109%	50%	140%
Chloroform	3269313	3269313	< 0.04	< 0.04	NA	< 0.04	104%	50%	140%	112%	60%	130%	105%	50%	140%
Dichloroethane, 1,2-	3269313	3269313	< 0.03	< 0.03	NA	< 0.03	102%	50%	140%	117%	60%	130%	118%	50%	140%
Trichloroethane, 1,1,1-	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	82%	50%	140%	83%	60%	130%	71%	50%	140%
Carbon Tetrachloride	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	90%	50%	140%	86%	60%	130%	81%	50%	140%
Benzene	3269313	3269313	< 0.02	< 0.02	NA	< 0.02	106%	50%	140%	105%	60%	130%	116%	50%	140%
Dichloropropane, 1,2-	3269313	3269313	< 0.03	< 0.03	NA	< 0.03	107%	50%	140%	87%	60%	130%	99%	50%	140%
Trichloroethylene	3269313	3269313	< 0.03	< 0.03	NA	< 0.03	109%	50%	140%	93%	60%	130%	89%	50%	140%
Bromodichloromethane	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	117%	50%	140%	98%	60%	130%	114%	50%	140%
Methyl Isobutyl Ketone	3269313	3269313	< 0.50	< 0.50	NA	< 0.50	100%	50%	140%	102%	50%	140%	99%	50%	140%
Trichloroethane, 1,1,2-	3269313	3269313	< 0.04	< 0.04	NA	< 0.04	112%	50%	140%	101%	60%	130%	98%	50%	140%
Toluene	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	115%	50%	140%	117%	60%	130%	115%	50%	140%
Dibromochloromethane	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	81%	50%	140%	108%	60%	130%	72%	50%	140%
Ethylene Dibromide	3269313	3269313	< 0.04	< 0.04	NA	< 0.04	98%	50%	140%	91%	60%	130%	107%	50%	140%
Tetrachloroethylene	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	112%	60%	130%	98%	50%	140%
Tetrachloroethane, 1,1,1,2-	3269313	3269313	< 0.04	< 0.04	NA	< 0.04	97%	50%	140%	116%	60%	130%	94%	50%	140%
Chlorobenzene	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	81%	50%	140%	112%	60%	130%	119%	50%	140%
Ethylbenzene	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	94%	50%	140%	79%	60%	130%	84%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T836979
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Dec 14, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Bromoform	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	107%	50%	140%	108%	60%	130%	95%	50%	140%
Styrene	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	87%	50%	140%	79%	60%	130%	77%	50%	140%
Tetrachloroethane, 1,1,2,2-	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	103%	50%	140%	82%	60%	130%	81%	50%	140%
Dichlorobenzene, 1,3-	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	95%	50%	140%	92%	60%	130%	84%	50%	140%
Dichlorobenzene, 1,4-	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	103%	60%	130%	84%	50%	140%
Dichlorobenzene, 1,2-	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	84%	60%	130%	86%	50%	140%
Hexane, n-	3269313	3269313	< 0.05	< 0.05	NA	< 0.05	114%	50%	140%	103%	60%	130%	117%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan I	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan II	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Alpha-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
op'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
Dieldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Methoxychlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T836979
PROJECT: 211-10139-00
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:ORBY Rail
SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
TCMX	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Decachlorobiphenyl	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
wet weight OC/PCB	ORG-91-5113		BALANCE
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T836979

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Dichlorodifluoromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Vinyl Chloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromomethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Acetone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, 1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methylene Chloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, Trans- 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl tert-butyl Ether	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethane, 1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethylene, Cis- 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Chloroform	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichloroethane, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethane, 1,1,1-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Benzene	VOL-91-5002	modified from EPA 5035C and EPA 8260D	(P&T)GC/MS
Dichloropropane, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethylene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromodichloromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Trichloroethane, 1,1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Toluene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dibromochloromethane	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethane, 1,1,1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Chlorobenzene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Ethylbenzene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Bromoform	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Styrene	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Tetrachloroethane, 1,1,2,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichlorobenzene, 1,3-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichlorobenzene, 1,4-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Dichlorobenzene, 1,2-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Xylenes (Total)	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
1,3-Dichloropropene (Cis + Trans)	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Hexane, n-	VOL-91-5002	EPA SW-846 5035 & 8260	(P&T)GC/MS
Toluene-d8	VOL-91-5002	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5002	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only 21T836979

Work Order #: 21T836976

Cooler Quantity: 1 large

Arrival Temperatures: 1.9 | 2.1 | 2.3

Custody Seal Intact: ☐ Yes ☐ No ☐ N/A

Notes: Received

Report Information:

Company: ~~WSP~~ WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: 437-240-3868 Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Project Information:

Project: 211-60139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis

Invoice Information:

Bill To Same: Yes ☑ No ☐

Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☑ Ind/Com ☐ Res/Park ☐ Agriculture
Soil Texture (Check One): ☑ Coarse ☐ Fine

☐ Excess Soils R406
Table (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
(Region)

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
(Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
*TAT is exclusive of weekends and statutory holidays

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC Y/N	O. Reg 153: Metals & Inorganics	Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	BTEX, F1-F4 PHCs Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides			Hold Sample				Potentially Hazardous or High Concentration (Y/N)
BH21-7 SS1	11/29/21	AM PM	2	S						X	X						X							
BH21-7 SS2		AM PM	1	S			X																	
BH21-7 SS5		AM PM	2	S					X			X												
BH21-7 SS7		AM PM	2	S					X			X									X			
BH21-8 SS1		AM PM	1	S						X														
BH21-8 SS1		AM PM	1	S							X						X				X			
BH21-8 SS2		AM PM	1	S			X																	
BH21-8 SS7		AM PM	2	S					X			X												
BH21-8 SS8		AM PM	2	S					X			X									X			
		AM PM																						
		AM PM																						

Samples Relinquished By (Print Name and Sign): Matthew Roy	Date: 11/29/21	Time: 1400	Samples Received By (Print Name and Sign): NEAL G	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:

21NOV29 6:45PM

Page 1 of 1

N°: T 126073

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Marsad Jafar
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T839088
TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor
WATER ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer
DATE REPORTED: Dec 15, 2021
PAGES (INCLUDING COVER): 20
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - OC Pesticides + PCBs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-02
Parameter	Unit	G / S	RDL	3296850
Gamma-Hexachlorocyclohexane	ug/L	0.01	0.01	<0.01
Heptachlor	ug/L	0.01	0.01	<0.01
Aldrin	ug/L	0.01	0.01	<0.01
Heptachlor Epoxide	ug/L	0.01	0.01	<0.01
Endosulfan I	µg/L		0.05	<0.05
Endosulfan II	µg/L		0.05	<0.05
Endosulfan	ug/L	0.05	0.05	<0.05
alpha - chlordane	µg/L		0.1	<0.1
gamma-Chlordane	µg/L		0.2	<0.2
Chlordane	ug/L	0.06	0.04	<0.04
op'-DDE	µg/L		0.01	<0.01
pp'-DDE	µg/L		0.01	<0.01
DDE	ug/L		0.01	<0.01
op'-DDD	µg/L		0.05	<0.05
pp'-DDD	µg/L		0.05	<0.05
DDD	ug/L	1.8	0.05	<0.05
op'-DDT	µg/L		0.04	<0.04
pp'-DDT	µg/L		0.05	<0.05
DDT	ug/L		0.04	<0.04
Dieldrin	ug/L	0.05	0.02	<0.02
Endrin	ug/L	0.05	0.05	<0.05
Methoxychlor	ug/L	0.05	0.04	<0.04
Hexachlorobenzene	ug/L	0.01	0.01	<0.01
Hexachlorobutadiene	ug/L	0.01	0.01	<0.01
Hexachloroethane	ug/L	0.01	0.01	<0.01
Aroclor 1242	ug/L		0.1	<0.1
Aroclor 1248	ug/L		0.1	<0.1
Aroclor 1254	ug/L		0.1	<0.1
Aroclor 1260	ug/L		0.1	<0.1
Polychlorinated Biphenyls	ug/L	0.2	0.1	<0.1

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - OC Pesticides + PCBs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:	BH21-7
		SAMPLE TYPE:	Water
		DATE SAMPLED:	2021-12-02
Surrogate	Unit	Acceptable Limits	3296850
TCMX	%	50-140	73
Decachlorobiphenyl	%	50-140	101

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850 DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PAHs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7	BH21-8	QAQC-2
		SAMPLE TYPE:		Water	Water	Water
		DATE SAMPLED:		2021-12-02	2021-12-02	2021-12-02
Parameter	Unit	G / S	RDL	3296850	3296853	3296858
Naphthalene	µg/L	7	0.20	<0.20	<0.20	<0.20
Acenaphthylene	µg/L	1	0.20	<0.20	<0.20	<0.20
Acenaphthene	µg/L	4.1	0.20	<0.20	<0.20	<0.20
Fluorene	µg/L	120	0.20	<0.20	<0.20	<0.20
Phenanthrene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Anthracene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Fluoranthene	µg/L	0.4	0.20	<0.20	<0.20	<0.20
Pyrene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Benzo(a)anthracene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Chrysene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Benzo(b)fluoranthene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Benzo(k)fluoranthene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Benzo(a)pyrene	µg/L	0.01	0.01	<0.01	<0.01	<0.01
Indeno(1,2,3-cd)pyrene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Dibenz(a,h)anthracene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Benzo(g,h,i)perylene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
2-and 1-methyl Naphthalene	µg/L	2	0.20	<0.20	<0.20	<0.20
Sediment				No	No	No
Surrogate	Unit	Acceptable Limits				
Naphthalene-d8	%	50-140		78	109	105
Acridine-d9	%	50-140		82	83	83
Terphenyl-d14	%	50-140		99	92	77

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850-3296858 Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&(j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7	BH21-8
		SAMPLE TYPE:		Water	Water
		DATE SAMPLED:		2021-12-02	2021-12-02
Parameter	Unit	G / S	RDL	3296850	3296853
F1 (C6-C10)	µg/L	420	25	<25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25	<25
F2 (C10 to C16)	µg/L	150	100	<100	<100
F2 (C10 to C16) minus Naphthalene	µg/L		100	<100	<100
F3 (C16 to C34)	µg/L	500	100	<100	<100
F3 (C16 to C34) minus PAHs	µg/L		100	<100	<100
F4 (C34 to C50)	µg/L	500	100	<100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA	NA
Sediment				NO	NO
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	50-140		101	71.2
Terphenyl	% Recovery	60-140		79	85

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850-3296853 The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1/BTEX (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		QAQC-1
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-02
Parameter	Unit	G / S	RDL	3296855
Benzene	µg/L	0.5	0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20
Ethylbenzene	µg/L	0.5	0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20
o-Xylene	µg/L		0.10	<0.10
Xylenes (Total)	µg/L	72	0.20	<0.20
F1 (C6-C10)	µg/L	420	25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	60-140		71.8

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296855 The C6-C10 fraction is calculated using Toluene response factor.
Total C6-C10 results are corrected for BTEX contributions.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
Extraction and holding times were met for this sample.
NA = Not Applicable

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

SAMPLE DESCRIPTION:				BH21-7	BH21-8
SAMPLE TYPE:				Water	Water
DATE SAMPLED:				2021-12-02	2021-12-02
Parameter	Unit	G / S	RDL	3296850	3296853
Dichlorodifluoromethane	µg/L	590	0.20	<0.20	<0.20
Vinyl Chloride	µg/L	0.5	0.17	<0.17	<0.17
Bromomethane	µg/L	0.89	0.20	<0.20	<0.20
Trichlorofluoromethane	µg/L	150	0.40	<0.40	<0.40
Acetone	µg/L	2700	1.0	<1.0	<1.0
1,1-Dichloroethylene	µg/L	0.5	0.30	<0.30	<0.30
Methylene Chloride	µg/L	5	0.30	<0.30	<0.30
trans- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20
Methyl tert-butyl ether	µg/L	15	0.20	<0.20	<0.20
1,1-Dichloroethane	µg/L	0.5	0.30	<0.30	<0.30
Methyl Ethyl Ketone	µg/L	400	1.0	<1.0	<1.0
cis- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20
Chloroform	µg/L	2	0.20	<0.20	<0.20
1,2-Dichloroethane	µg/L	0.5	0.20	<0.20	<0.20
1,1,1-Trichloroethane	µg/L	0.5	0.30	<0.30	<0.30
Carbon Tetrachloride	µg/L	0.2	0.20	<0.20	<0.20
Benzene	µg/L	0.5	0.20	<0.20	<0.20
1,2-Dichloropropane	µg/L	0.5	0.20	<0.20	<0.20
Trichloroethylene	µg/L	0.5	0.20	<0.20	<0.20
Bromodichloromethane	µg/L	2	0.20	<0.20	<0.20
Methyl Isobutyl Ketone	µg/L	640	1.0	<1.0	<1.0
1,1,2-Trichloroethane	µg/L	0.5	0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20
Dibromochloromethane	µg/L	2	0.10	<0.10	<0.10
Ethylene Dibromide	µg/L	0.2	0.10	<0.10	<0.10
Tetrachloroethylene	µg/L	0.5	0.20	<0.20	<0.20
1,1,1,2-Tetrachloroethane	µg/L	1.1	0.10	<0.10	<0.10
Chlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20	<0.20

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7	BH21-8
		SAMPLE TYPE:		Water	Water
		DATE SAMPLED:		2021-12-02	2021-12-02
Parameter	Unit	G / S	RDL	3296850	3296853
Bromoform	µg/L	5	0.10	<0.10	<0.10
Styrene	µg/L	0.5	0.10	<0.10	<0.10
1,1,2,2-Tetrachloroethane	µg/L	0.5	0.10	<0.10	<0.10
o-Xylene	µg/L		0.10	<0.10	<0.10
1,3-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
1,4-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
1,2-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
1,3-Dichloropropene	µg/L	0.5	0.30	<0.30	<0.30
Xylenes (Total)	µg/L	72	0.20	<0.20	<0.20
n-Hexane	µg/L	5	0.20	<0.20	<0.20
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	50-140		69	86
4-Bromofluorobenzene	% Recovery	50-140		101	96

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850-3296853 Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7		BH21-8
		SAMPLE TYPE:		Water		Water
		DATE SAMPLED:		2021-12-02		2021-12-02
Parameter	Unit	G / S	RDL	3296850	RDL	3296853
Dissolved Antimony	µg/L	1.5	1.0	<1.0	1.0	<1.0
Dissolved Arsenic	µg/L	13	1.0	<1.0	1.0	4.3
Dissolved Barium	µg/L	610	2.0	254	2.0	109
Dissolved Beryllium	µg/L	0.5	0.50	<0.50	0.50	<0.50
Dissolved Boron	µg/L	1700	10.0	362	10.0	131
Dissolved Cadmium	µg/L	0.5	0.20	<0.20	0.20	<0.20
Dissolved Chromium	µg/L	11	2.0	<2.0	2.0	<2.0
Dissolved Cobalt	µg/L	3.8	0.50	0.52	0.50	0.63
Dissolved Copper	µg/L	5	1.0	1.9	1.0	<1.0
Dissolved Lead	µg/L	1.9	0.50	<0.50	0.50	<0.50
Dissolved Molybdenum	µg/L	23	0.50	14.2	0.50	7.84
Dissolved Nickel	µg/L	14	1.0	2.8	1.0	9.7
Dissolved Selenium	µg/L	5	1.0	<1.0	1.0	<1.0
Dissolved Silver	µg/L	0.3	0.20	<0.20	0.20	<0.20
Dissolved Thallium	µg/L	0.5	0.30	<0.30	0.30	<0.30
Dissolved Uranium	µg/L	8.9	0.50	3.19	0.50	1.11
Dissolved Vanadium	µg/L	3.9	0.40	1.42	0.40	0.62
Dissolved Zinc	µg/L	160	5.0	<5.0	5.0	<5.0
Mercury	µg/L	0.1	0.02	<0.02	0.02	<0.02
Chromium VI	µg/L	25	2	<2	2	<2
Cyanide, Free	µg/L	5	2	<2	2	<2
Dissolved Sodium	µg/L	490000	250	417000	50	23000
Chloride	µg/L	790000	100	768000	100	72700
Electrical Conductivity	uS/cm	NA	2	2900	2	934
pH	pH Units		NA	7.97	NA	7.99

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850-3296853 Metals analysis completed on a filtered sample.

Dilution required, RDL has been increased accordingly.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)															
F1 (C6-C10)	3300342		<25	<25	NA	< 25	120%	60%	140%	106%	60%	140%	101%	60%	140%
F2 (C10 to C16)	3296850	3296850	< 100	< 100	NA	< 100	78%	60%	140%	74%	60%	140%	71%	60%	140%
F3 (C16 to C34)	3296850	3296850	< 100	< 100	NA	< 100	84%	60%	140%	76%	60%	140%	75%	60%	140%
F4 (C34 to C50)	3296850	3296850	< 100	< 100	NA	< 100	79%	60%	140%	75%	60%	140%	76%	60%	140%
O. Reg. 153(511) - PAHs (Water)															
Naphthalene	3253224		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	78%	50%	140%	77%	50%	140%
Acenaphthylene	3253224		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	82%	50%	140%	107%	50%	140%
Acenaphthene	3253224		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	71%	50%	140%	81%	50%	140%
Fluorene	3253224		< 0.20	< 0.20	NA	< 0.20	86%	50%	140%	92%	50%	140%	92%	50%	140%
Phenanthrene	3253224		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	88%	50%	140%	85%	50%	140%
Anthracene	3253224		< 0.10	< 0.10	NA	< 0.10	85%	50%	140%	93%	50%	140%	78%	50%	140%
Fluoranthene	3253224		< 0.20	< 0.20	NA	< 0.20	99%	50%	140%	96%	50%	140%	93%	50%	140%
Pyrene	3253224		< 0.20	< 0.20	NA	< 0.20	78%	50%	140%	96%	50%	140%	99%	50%	140%
Benzo(a)anthracene	3253224		< 0.20	< 0.20	NA	< 0.20	96%	50%	140%	94%	50%	140%	96%	50%	140%
Chrysene	3253224		< 0.10	< 0.10	NA	< 0.10	86%	50%	140%	114%	50%	140%	84%	50%	140%
Benzo(b)fluoranthene	3253224		< 0.10	< 0.10	NA	< 0.10	92%	50%	140%	76%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3253224		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	92%	50%	140%	78%	50%	140%
Benzo(a)pyrene	3253224		< 0.01	< 0.01	NA	< 0.01	78%	50%	140%	105%	50%	140%	101%	50%	140%
Indeno(1,2,3-cd)pyrene	3253224		< 0.20	< 0.20	NA	< 0.20	92%	50%	140%	108%	50%	140%	105%	50%	140%
Dibenz(a,h)anthracene	3253224		< 0.20	< 0.20	NA	< 0.20	95%	50%	140%	75%	50%	140%	72%	50%	140%
Benzo(g,h,i)perylene	3253224		< 0.20	< 0.20	NA	< 0.20	91%	50%	140%	85%	50%	140%	105%	50%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Water)															
Gamma-Hexachlorocyclohexane	3287115		< 0.01	< 0.01	NA	< 0.01	102%	50%	140%	98%	50%	140%	98%	50%	140%
Heptachlor	3287115		< 0.01	< 0.01	NA	< 0.01	110%	50%	140%	102%	50%	140%	102%	50%	140%
Aldrin	3287115		< 0.01	< 0.01	NA	< 0.01	103%	50%	140%	102%	50%	140%	112%	50%	140%
Heptachlor Epoxide	3287115		< 0.01	< 0.01	NA	< 0.01	109%	50%	140%	104%	50%	140%	104%	50%	140%
Endosulfan I	3287115		< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	102%	50%	140%	106%	50%	140%
Endosulfan II	3287115		< 0.05	< 0.05	NA	< 0.05	113%	50%	140%	99%	50%	140%	92%	50%	140%
alpha - chlordane	3287115		< 0.1	< 0.1	NA	< 0.1	103%	50%	140%	103%	50%	140%	114%	50%	140%
gamma-Chlordane	3287115		< 0.2	< 0.2	NA	< 0.2	105%	50%	140%	102%	50%	140%	112%	50%	140%
op'-DDE	3287115		< 0.01	< 0.01	NA	< 0.01	96%	50%	140%	108%	50%	140%	109%	50%	140%
pp'-DDE	3287115		< 0.01	< 0.01	NA	< 0.01	100%	50%	140%	101%	50%	140%	110%	50%	140%
op'-DDD	3287115		< 0.05	< 0.05	NA	< 0.05	113%	50%	140%	109%	50%	140%	109%	50%	140%
pp'-DDD	3287115		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	104%	50%	140%	112%	50%	140%
op'-DDT	3287115		< 0.04	< 0.04	NA	< 0.04	102%	50%	140%	107%	50%	140%	106%	50%	140%
pp'-DDT	3287115		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	92%	50%	140%	107%	50%	140%
Dieldrin	3287115		< 0.02	< 0.02	NA	< 0.02	102%	50%	140%	109%	50%	140%	113%	50%	140%
Endrin	3287115		< 0.05	< 0.05	NA	< 0.05	109%	50%	140%	103%	50%	140%	110%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis (Continued)

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Methoxychlor	3287115		< 0.04	< 0.04	NA	< 0.04	92%	50%	140%	88%	50%	140%	96%	50%	140%
Hexachlorobenzene	3287115		< 0.01	< 0.01	NA	< 0.01	97%	50%	140%	96%	50%	140%	98%	50%	140%
Hexachlorobutadiene	3287115		< 0.01	< 0.01	NA	< 0.01	92%	50%	140%	97%	50%	140%	94%	50%	140%
Hexachloroethane	3287115		< 0.01	< 0.01	NA	< 0.01	87%	50%	140%	103%	50%	140%	90%	50%	140%
Aroclor 1242	3287115		< 0.1	< 0.1	NA	< 0.1	NA	60%	140%	NA	60%	140%	NA	60%	140%
Aroclor 1248	3287115		< 0.1	< 0.1	NA	< 0.1	NA	60%	140%	NA	60%	140%	NA	60%	140%
Aroclor 1254	3287115		< 0.1	< 0.1	NA	< 0.1	NA	60%	140%	NA	60%	140%	NA	60%	140%
Aroclor 1260	3287115		< 0.1	< 0.1	NA	< 0.1	NA	60%	140%	NA	60%	140%	NA	60%	140%
Polychlorinated Biphenyls	3287115		< 0.1	< 0.1	NA	< 0.1	95%	60%	140%	89%	60%	140%	98%	60%	140%
O. Reg. 153(511) - VOCs (Water)															
Dichlorodifluoromethane	3268642		< 0.20	< 0.20	NA	< 0.20	91%	50%	140%	95%	50%	140%	94%	50%	140%
Vinyl Chloride	3268642		< 0.17	< 0.17	NA	< 0.17	96%	50%	140%	102%	50%	140%	85%	50%	140%
Bromomethane	3268642		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	83%	50%	140%	85%	50%	140%
Trichlorofluoromethane	3268642		< 0.40	< 0.40	NA	< 0.40	87%	50%	140%	79%	50%	140%	91%	50%	140%
Acetone	3268642		< 1.0	< 1.0	NA	< 1.0	96%	50%	140%	100%	50%	140%	103%	50%	140%
1,1-Dichloroethylene	3268642		< 0.30	< 0.30	NA	< 0.30	93%	50%	140%	73%	60%	130%	100%	50%	140%
Methylene Chloride	3268642		< 0.30	< 0.30	NA	< 0.30	120%	50%	140%	120%	60%	130%	84%	50%	140%
trans- 1,2-Dichloroethylene	3268642		< 0.20	< 0.20	NA	< 0.20	97%	50%	140%	120%	60%	130%	84%	50%	140%
Methyl tert-butyl ether	3268642		< 0.20	< 0.20	NA	< 0.20	95%	50%	140%	117%	60%	130%	87%	50%	140%
1,1-Dichloroethane	3268642		< 0.30	< 0.30	NA	< 0.30	85%	50%	140%	110%	60%	130%	73%	50%	140%
Methyl Ethyl Ketone	3268642		< 1.0	< 1.0	NA	< 1.0	98%	50%	140%	101%	50%	140%	97%	50%	140%
cis- 1,2-Dichloroethylene	3268642		< 0.20	< 0.20	NA	< 0.20	79%	50%	140%	107%	60%	130%	118%	50%	140%
Chloroform	3268642		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	101%	60%	130%	89%	50%	140%
1,2-Dichloroethane	3268642		< 0.20	< 0.20	NA	< 0.20	116%	50%	140%	97%	60%	130%	81%	50%	140%
1,1,1-Trichloroethane	3268642		< 0.30	< 0.30	NA	< 0.30	111%	50%	140%	85%	60%	130%	112%	50%	140%
Carbon Tetrachloride	3268642		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	120%	60%	130%	84%	50%	140%
Benzene	3268642		< 0.20	< 0.20	NA	< 0.20	87%	50%	140%	106%	60%	130%	94%	50%	140%
1,2-Dichloropropane	3268642		< 0.20	< 0.20	NA	< 0.20	111%	50%	140%	97%	60%	130%	100%	50%	140%
Trichloroethylene	3268642		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	98%	60%	130%	111%	50%	140%
Bromodichloromethane	3268642		< 0.20	< 0.20	NA	< 0.20	116%	50%	140%	107%	60%	130%	99%	50%	140%
Methyl Isobutyl Ketone	3268642		< 1.0	< 1.0	NA	< 1.0	109%	50%	140%	103%	50%	140%	100%	50%	140%
1,1,2-Trichloroethane	3268642		< 0.20	< 0.20	NA	< 0.20	117%	50%	140%	97%	60%	130%	78%	50%	140%
Toluene	3268642		< 0.20	< 0.20	NA	< 0.20	100%	50%	140%	75%	60%	130%	120%	50%	140%
Dibromochloromethane	3268642		< 0.10	< 0.10	NA	< 0.10	116%	50%	140%	110%	60%	130%	105%	50%	140%
Ethylene Dibromide	3268642		< 0.10	< 0.10	NA	< 0.10	111%	50%	140%	91%	60%	130%	93%	50%	140%
Tetrachloroethylene	3268642		< 0.20	< 0.20	NA	< 0.20	104%	50%	140%	91%	60%	130%	87%	50%	140%
1,1,1,2-Tetrachloroethane	3268642		< 0.10	< 0.10	NA	< 0.10	105%	50%	140%	86%	60%	130%	104%	50%	140%
Chlorobenzene	3268642		< 0.10	< 0.10	NA	< 0.10	89%	50%	140%	70%	60%	130%	97%	50%	140%
Ethylbenzene	3268642		< 0.10	< 0.10	NA	< 0.10	74%	50%	140%	87%	60%	130%	80%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839088
PROJECT: 211-10139-00
ATTENTION TO: Marsad Jafar
SAMPLING SITE:
SAMPLED BY:

Trace Organics Analysis (Continued)

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
m & p-Xylene	3268642		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	92%	60%	130%	90%	50%	140%
Bromoform	3268642		< 0.10	< 0.10	NA	< 0.10	106%	50%	140%	84%	60%	130%	88%	50%	140%
Styrene	3268642		< 0.10	< 0.10	NA	< 0.10	76%	50%	140%	82%	60%	130%	70%	50%	140%
1,1,2,2-Tetrachloroethane	3268642		< 0.10	< 0.10	NA	< 0.10	94%	50%	140%	77%	60%	130%	84%	50%	140%
o-Xylene	3268642		< 0.10	< 0.10	NA	< 0.10	78%	50%	140%	78%	60%	130%	79%	50%	140%
1,3-Dichlorobenzene	3268642		< 0.10	< 0.10	NA	< 0.10	95%	50%	140%	78%	60%	130%	73%	50%	140%
1,4-Dichlorobenzene	3268642		< 0.10	< 0.10	NA	< 0.10	101%	50%	140%	78%	60%	130%	81%	50%	140%
1,2-Dichlorobenzene	3268642		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	80%	60%	130%	78%	50%	140%
n-Hexane	3268642		< 0.20	< 0.20	NA	< 0.20	93%	50%	140%	95%	60%	130%	117%	50%	140%
Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).															
O. Reg. 153(511) - PHCs F1/BTEX (Water)															
Benzene	3300342		<0.20	<0.20	NA	< 0.20	90%	60%	140%	85%	60%	140%	104%	60%	140%
Toluene	3300342		<0.20	<0.20	NA	< 0.20	85%	60%	140%	81%	60%	140%	93%	60%	140%
Ethylbenzene	3300342		<0.10	<0.10	NA	< 0.10	85%	60%	140%	84%	60%	140%	96%	60%	140%
m & p-Xylene	3300342		<0.20	<0.20	NA	< 0.20	91%	60%	140%	103%	60%	140%	106%	60%	140%
o-Xylene	3300342		<0.10	<0.10	NA	< 0.10	104%	60%	140%	82%	60%	140%	119%	60%	140%
F1 (C6-C10)	3300342		<25	<25	NA	< 25	120%	60%	140%	106%	60%	140%	101%	60%	140%

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839088
PROJECT: 211-10139-00
ATTENTION TO: Marsad Jafar
SAMPLING SITE:
SAMPLED BY:

Water Analysis

RPT Date: Dec 15, 2021

PARAMETER	Batch	Sample Id	DUPLICATE Dup #1	DUPLICATE Dup #2	DUPLICATE RPD	Method Blank	REFERENCE MATERIAL Measured Value	REFERENCE MATERIAL Acceptable Limits Lower	REFERENCE MATERIAL Acceptable Limits Upper	METHOD BLANK SPIKE Recovery	METHOD BLANK SPIKE Acceptable Limits Lower	METHOD BLANK SPIKE Acceptable Limits Upper	MATRIX SPIKE Recovery	MATRIX SPIKE Acceptable Limits Lower	MATRIX SPIKE Acceptable Limits Upper
O. Reg. 153(511) - Metals & Inorganics (Water)															
Dissolved Antimony	3295669		< 1.0	< 1.0	0.0%	< 1.0	99%	70%	130%	105%	80%	120%	101%	70%	130%
Dissolved Arsenic	3295669		1.1	1.1	NA	< 1.0	95%	70%	130%	104%	80%	120%	108%	70%	130%
Dissolved Barium	3295669		268	264	1.5%	< 2.0	102%	70%	130%	104%	80%	120%	75%	70%	130%
Dissolved Beryllium	3295669		< 0.50	< 0.50	0.0%	< 0.50	106%	70%	130%	116%	80%	120%	112%	70%	130%
Dissolved Boron	3295669		126	121	4.6%	< 10.0	103%	70%	130%	114%	80%	120%	102%	70%	130%
Dissolved Cadmium	3295669		< 0.20	< 0.20	0.0%	< 0.20	100%	70%	130%	105%	80%	120%	108%	70%	130%
Dissolved Chromium	3295669		< 2.0	< 2.0	0.0%	< 2.0	100%	70%	130%	102%	80%	120%	105%	70%	130%
Dissolved Cobalt	3295669		5.36	4.56	16.1%	< 0.50	103%	70%	130%	102%	80%	120%	105%	70%	130%
Dissolved Copper	3295669		< 1.0	< 1.0	0.0%	< 1.0	100%	70%	130%	99%	80%	120%	108%	70%	130%
Dissolved Lead	3295669		< 0.50	< 0.50	0.0%	< 0.50	100%	70%	130%	103%	80%	120%	108%	70%	130%
Dissolved Molybdenum	3295669		< 0.50	< 0.50	0.0%	< 0.50	101%	70%	130%	106%	80%	120%	112%	70%	130%
Dissolved Nickel	3295669		8.5	7.9	7.3%	< 1.0	102%	70%	130%	107%	80%	120%	103%	70%	130%
Dissolved Selenium	3295669		< 1.0	< 1.0	0.0%	< 1.0	100%	70%	130%	111%	80%	120%	106%	70%	130%
Dissolved Silver	3295669		< 0.20	< 0.20	0.0%	< 0.20	100%	70%	130%	103%	80%	120%	109%	70%	130%
Dissolved Thallium	3295669		< 0.30	< 0.30	0.0%	< 0.30	98%	70%	130%	100%	80%	120%	104%	70%	130%
Dissolved Uranium	3295669		1.28	1.23	NA	< 0.50	105%	70%	130%	113%	80%	120%	115%	70%	130%
Dissolved Vanadium	3295669		<0.40	0.61	NA	< 0.40	101%	70%	130%	103%	80%	120%	105%	70%	130%
Dissolved Zinc	3295669		5.3	<5.0	NA	< 5.0	103%	70%	130%	99%	80%	120%	112%	70%	130%
Mercury	3295007		<0.02	<0.02	NA	< 0.02	104%	70%	130%	101%	80%	120%	93%	70%	130%
Chromium VI	3285019		<2	<2	NA	< 2	103%	70%	130%	104%	80%	120%	110%	70%	130%
Cyanide, Free	3275528		<2	<2	NA	< 2	107%	70%	130%	103%	80%	120%	87%	70%	130%
Dissolved Sodium	3296853	3296853	23000	23100	0.5%	< 50	97%	70%	130%	99%	80%	120%	97%	70%	130%
Chloride	3285316		120000	118000	1.5%	< 100	98%	70%	130%	103%	80%	120%	106%	70%	130%
Electrical Conductivity	3295423		976	964	1.2%	< 2	104%	90%	110%						
pH	3295423		7.68	7.78	1.3%	NA	102%	90%	110%						

Comments: NA signifies Not Applicable.
Duplicate NA: results are under 5X the RDL and will not be calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Heptachlor	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Aldrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan I	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan II	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
alpha - chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
Dieldrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Methoxychlor	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
TCMX	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Decachlorobiphenyl	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluorene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Chrysene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
2-and 1-methyl Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Sediment			
F1 (C6-C10)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
Toluene-d8	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F2 (C10 to C16) minus Naphthalene	VOL-91-5010	modified from MOE PHC-E3421	GC/FID

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC-E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Benzene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Toluene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F1 (C6-C10)	VOL-91-5010	modified from MOE E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE E3421	(P&T)GC/FID
Dichlorodifluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromomethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
trans- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl tert-butyl ether	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
cis- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Dibromochloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromoform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Water Analysis			
Dissolved Antimony	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Arsenic	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Barium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Beryllium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Boron	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cadmium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Chromium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cobalt	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Copper	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Lead	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Molybdenum	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Nickel	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Selenium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Silver	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Thallium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Uranium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Vanadium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Zinc	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Mercury	MET-93-6100	modified from EPA 245.2 and SM 3112 B	CVAAS
Chromium VI	INOR-93-6034	modified from SM 3500-CR B	LACHAT FIA
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Dissolved Sodium	MET-93-6105	modified from EPA 6010D	ICP/OES
Chloride	INOR-93-6004	modified from SM 4110 B	ION CHROMATOGRAPH
Electrical Conductivity	INOR-93-6000	SM 2510 B	PC TITRATE
pH	INOR-93-6000	modified from SM 4500-H+ B	PC TITRATE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP
Contact: Marsad Jafar
Address: 2 International Blvd, Toronto ON
Phone: 437-233-2935 Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: marsad.jafar@wsp.com

Project Information:

Project: 211-10139-00
Site Location: ORBY
Sampled By: Marsad Jafar
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☐ Ind/Com
☑ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☐ Yes ☐ No

Laboratory Use Only

Work Order #: 21T839088
Cooler Quantity: 1 large black
Arrival Temperatures: 9.4 | 7.0 | 8.3
Custody Seal Intact: ☐ Yes ☐ No ☑ N/A
Notes: free ice

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply):
Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*
For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	VOC	Potentially Hazardous or High Concentration (Y/N)
BH21-7	Dec 02/21	AM	19	GW	[redacted]		X		X		X	X	X					X	
BH21-8	Dec 02/21	AM	13	GW	VOC/BTEX limited sample		X		X		X		X						
QAQC-1	Dec 02/21	AM	3	GW					X										
QAQC-2	Dec 02/21	AM	2	GW							X								

21 DEC 2 3:47pm

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Marsad Jafar M.J	Dec 02/21	3:45 pm	Adriana Bellavia ABellavia		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

Page ____ of ____

N°: T 128321

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Document ID: DIV 78 1511 021

Date Issued: March 9, 2021

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T839096
SOIL ANALYSIS REVIEWED BY: Amanjot Bhela, Inorganic Lab Manager
TRACE ORGANICS REVIEWED BY: Inga Kuzmina, Trace Organics Lab Manager
DATE REPORTED: Dec 23, 2021
PAGES (INCLUDING COVER): 21
VERSION*: 2

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

VERSION 2:Version 2 supersedes work order 21T839096 , Version 1, issued December 15, 2021. 924 for PAHs and 925 for O. Reg 153 M&I.

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:


O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-23

SAMPLE DESCRIPTION:				BH21-2 SS2	BH21-3 SS1	QAQC-12	BH21-6 SS2	BH21-16 SS1
SAMPLE TYPE:				Soil	Soil	Soil	Soil	Soil
DATE SAMPLED:				2021-12-02	2021-12-02 12:00	2021-12-02 12:00	2021-12-01 12:00	2021-12-01
Parameter	Unit	G / S	RDL	3293886	3293919	3293920	3293925	3293929
Antimony	µg/g	1.3	0.8	<0.8	<0.8	<0.8	<0.8	2.8
Arsenic	µg/g	18	1	6	4	6	4	8
Barium	µg/g	220	2.0	89.8	77.5	52.7	54.5	88.5
Beryllium	µg/g	2.5	0.4	0.8	0.6	0.5	<0.4	0.5
Boron	µg/g	36	5	10	8	7	7	9
Boron (Hot Water Soluble)	µg/g	NA	0.10	0.42	0.12	0.17	0.17	0.50
Cadmium	µg/g	1.2	0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Chromium	µg/g	70	5	20	17	15	14	35
Cobalt	µg/g	21	0.5	9.2	7.8	7.8	8.1	10.6
Copper	µg/g	92	1.0	42.9	24.8	33.3	32.0	69.0
Lead	µg/g	120	1	60	9	12	8	79
Molybdenum	µg/g	2	0.5	0.6	<0.5	<0.5	<0.5	3.7
Nickel	µg/g	82	1	19	17	22	15	31
Selenium	µg/g	1.5	0.8	<0.8	<0.8	<0.8	<0.8	0.8
Silver	µg/g	0.5	0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Thallium	µg/g	1	0.5	<0.5	<0.5	<0.5	<0.5	<0.5
Uranium	µg/g	2.5	0.50	0.55	<0.50	<0.50	<0.50	<0.50
Vanadium	µg/g	86	0.4	30.4	25.5	22.4	23.8	33.8
Zinc	µg/g	290	5	95	44	43	39	468
Chromium, Hexavalent	µg/g	0.66	0.2	<0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040	<0.040	<0.040
Mercury	µg/g	0.27	0.10	<0.10	<0.10	<0.10	<0.10	0.22
Electrical Conductivity (2:1)	mS/cm	0.57	0.005	0.353	0.216	0.185	0.327	0.290
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	2.4	N/A	1.56	0.438	0.300	2.14	1.64
pH, 2:1 CaCl2 Extraction	pH Units		NA	7.29	7.25	7.32	7.61	7.50

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-23

Comments:	RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.
3293886-3293920	EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.
3293925	EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter. Cyanide analysis was performed beyond recommended hold time.
3293929	EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-23

SAMPLE DESCRIPTION:				BH21-2 SS2	BH21-6 SS1	BH21-16 SS2	QAQC-10
SAMPLE TYPE:				Soil	Soil	Soil	Soil
DATE SAMPLED:				2021-12-02	2021-12-01 12:00	2021-12-01	2021-12-01
Parameter	Unit	G / S	RDL	3293886	3293924	3293931	3293943
Naphthalene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthylene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Acenaphthene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Fluorene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Phenanthrene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Anthracene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Fluoranthene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Pyrene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Benz(a)anthracene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Chrysene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
1 and 2 Methlynaphthalene	µg/g		0.05	<0.05	<0.05	<0.05	<0.05
Moisture Content	%		0.1	20.3	13.2	17.9	15.8
Surrogate	Unit	Acceptable Limits					
Naphthalene-d8	%	50-140		78	78	108	106
Acridine-d9	%	50-140		93	84	75	93
Terphenyl-d14	%	50-140		92	77	96	94

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

3293886-3293943 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-23

		SAMPLE DESCRIPTION:		BH21-16 SS8
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-12-01
Parameter	Unit	G / S	RDL	3293947
F1 (C6 - C10)	µg/g	25	5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5
F2 (C10 to C16)	µg/g	10	10	<10
F3 (C16 to C34)	µg/g	240	50	<50
F4 (C34 to C50)	µg/g	120	50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA
Moisture Content	%		0.1	9.3
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		95
Terphenyl	%	60-140		104

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3293947 Results are based on sample dry weight.
The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified without the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-23

		SAMPLE DESCRIPTION:		BH21-2 SS5	BH21-3 SS6	BH21-6 SS6
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-12-02	2021-12-02 12:00	2021-12-01 12:00
Parameter	Unit	G / S	RDL	3293910	3293922	3293927
Benzene	µg/g	0.02	0.02	<0.02	<0.02	<0.02
Toluene	µg/g	0.2	0.05	<0.05	<0.05	<0.05
Ethylbenzene	µg/g	0.05	0.05	<0.05	<0.05	<0.05
m & p-Xylene	µg/g		0.05	<0.05	<0.05	<0.05
o-Xylene	µg/g		0.05	<0.05	<0.05	<0.05
Xylenes (Total)	µg/g	0.05	0.05	<0.05	<0.05	<0.05
F1 (C6 - C10)	µg/g	25	5	<5	<5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5	<5	<5
F2 (C10 to C16)	µg/g	10	10	<10	<10	<10
F3 (C16 to C34)	µg/g	240	50	<50	<50	<50
F4 (C34 to C50)	µg/g	120	50	<50	<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA	NA	NA
Moisture Content	%		0.1	22.0	17.6	12.7
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	60-140		90	99	108
Terphenyl	%	60-140		85	88	89

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-12-02


DATE REPORTED: 2021-12-23

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3293910-3293927 Results are based on sample dry weight.
The C6-C10 fraction is calculated using Toluene response factor.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.
Quality Control Data is available upon request.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:


O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-23

		SAMPLE DESCRIPTION:		BH21-16 SS8
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-12-01
Parameter	Unit	G / S	RDL	3293947
Dichlorodifluoromethane	µg/g	0.05	0.05	<0.05
Vinyl Chloride	ug/g	0.02	0.02	<0.02
Bromomethane	ug/g	0.05	0.05	<0.05
Trichlorofluoromethane	ug/g	0.25	0.05	<0.05
Acetone	ug/g	0.5	0.50	<0.50
1,1-Dichloroethylene	ug/g	0.05	0.05	<0.05
Methylene Chloride	ug/g	0.05	0.05	<0.05
Trans- 1,2-Dichloroethylene	ug/g	0.05	0.05	<0.05
Methyl tert-butyl Ether	ug/g	0.05	0.05	<0.05
1,1-Dichloroethane	ug/g	0.05	0.02	<0.02
Methyl Ethyl Ketone	ug/g	0.5	0.50	<0.50
Cis- 1,2-Dichloroethylene	ug/g	0.05	0.02	<0.02
Chloroform	ug/g	0.05	0.04	<0.04
1,2-Dichloroethane	ug/g	0.05	0.03	<0.03
1,1,1-Trichloroethane	ug/g	0.05	0.05	<0.05
Carbon Tetrachloride	ug/g	0.05	0.05	<0.05
Benzene	ug/g	0.02	0.02	<0.02
1,2-Dichloropropane	ug/g	0.05	0.03	<0.03
Trichloroethylene	ug/g	0.05	0.03	<0.03
Bromodichloromethane	ug/g	0.05	0.05	<0.05
Methyl Isobutyl Ketone	ug/g	0.5	0.50	<0.50
1,1,2-Trichloroethane	ug/g	0.05	0.04	<0.04
Toluene	ug/g	0.2	0.05	<0.05
Dibromochloromethane	ug/g	0.05	0.05	<0.05
Ethylene Dibromide	ug/g	0.05	0.04	<0.04
Tetrachloroethylene	ug/g	0.05	0.05	<0.05
1,1,1,2-Tetrachloroethane	ug/g	0.05	0.04	<0.04
Chlorobenzene	ug/g	0.05	0.05	<0.05
Ethylbenzene	ug/g	0.05	0.05	<0.05
m & p-Xylene	ug/g		0.05	<0.05

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-23

		SAMPLE DESCRIPTION:		BH21-16 SS8
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-12-01
Parameter	Unit	G / S	RDL	3293947
Bromoform	ug/g	0.05	0.05	<0.05
Styrene	ug/g	0.05	0.05	<0.05
1,1,2,2-Tetrachloroethane	ug/g	0.05	0.05	<0.05
o-Xylene	ug/g		0.05	<0.05
1,3-Dichlorobenzene	ug/g	0.05	0.05	<0.05
1,4-Dichlorobenzene	ug/g	0.05	0.05	<0.05
1,2-Dichlorobenzene	ug/g	0.05	0.05	<0.05
Xylenes (Total)	ug/g	0.05	0.05	<0.05
1,3-Dichloropropene (Cis + Trans)	µg/g	0.05	0.04	<0.04
n-Hexane	µg/g	0.05	0.05	<0.05
Moisture Content	%		0.1	9.3
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		94
4-Bromofluorobenzene	% Recovery	50-140		71

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3293947 The sample was analyzed using the high level technique. The sample was extracted using methanol, a small amount of the methanol extract was diluted in water and the purge & trap GC/MS analysis was performed. Results are based on the dry weight of the soil.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene + o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3293929	BH21-16 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - Metals & Inorganics (Soil)	Antimony	µg/g	1.3	2.8
3293929	BH21-16 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - Metals & Inorganics (Soil)	Molybdenum	µg/g	2	3.7
3293929	BH21-16 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - Metals & Inorganics (Soil)	Zinc	µg/g	290	468

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

Soil Analysis

RPT Date: Dec 23, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3296184		<0.8	<0.8	NA	< 0.8	134%	70%	130%	98%	80%	120%	92%	70%	130%
Arsenic	3296184		4	4	NA	< 1	113%	70%	130%	103%	80%	120%	107%	70%	130%
Barium	3296184		37.9	40.4	6.4%	< 2.0	112%	70%	130%	108%	80%	120%	108%	70%	130%
Beryllium	3296184		<0.4	<0.4	NA	< 0.4	102%	70%	130%	108%	80%	120%	109%	70%	130%
Boron	3296184		<5	<5	NA	< 5	89%	70%	130%	111%	80%	120%	112%	70%	130%
Boron (Hot Water Soluble)	3319050		0.40	0.39	NA	< 0.10	107%	60%	140%	105%	70%	130%	108%	60%	140%
Cadmium	3296184		0.7	0.8	NA	< 0.5	94%	70%	130%	102%	80%	120%	108%	70%	130%
Chromium	3296184		10	10	NA	< 5	99%	70%	130%	101%	80%	120%	110%	70%	130%
Cobalt	3296184		4.0	4.2	4.9%	< 0.5	103%	70%	130%	106%	80%	120%	106%	70%	130%
Copper	3296184		14.4	15.4	6.7%	< 1.0	100%	70%	130%	108%	80%	120%	110%	70%	130%
Lead	3296184		29	29	0.0%	< 1	103%	70%	130%	103%	80%	120%	99%	70%	130%
Molybdenum	3296184		<0.5	<0.5	NA	< 0.5	105%	70%	130%	104%	80%	120%	110%	70%	130%
Nickel	3296184		7	8	13.3%	< 1	101%	70%	130%	103%	80%	120%	102%	70%	130%
Selenium	3296184		<0.8	<0.8	NA	< 0.8	98%	70%	130%	98%	80%	120%	104%	70%	130%
Silver	3296184		<0.5	<0.5	NA	< 0.5	114%	70%	130%	102%	80%	120%	96%	70%	130%
Thallium	3296184		<0.5	<0.5	NA	< 0.5	99%	70%	130%	100%	80%	120%	96%	70%	130%
Uranium	3296184		<0.50	<0.50	NA	< 0.50	103%	70%	130%	100%	80%	120%	100%	70%	130%
Vanadium	3296184		17.6	19.0	7.7%	< 0.4	102%	70%	130%	101%	80%	120%	111%	70%	130%
Zinc	3296184		85	89	4.6%	< 5	102%	70%	130%	103%	80%	120%	112%	70%	130%
Chromium, Hexavalent	3309312		<0.2	<0.2	NA	< 0.2	102%	70%	130%	88%	80%	120%	81%	70%	130%
Cyanide, Free	3304561		<0.040	<0.040	NA	< 0.040	101%	70%	130%	97%	80%	120%	104%	70%	130%
Mercury	3296184		<0.10	<0.10	NA	< 0.10	103%	70%	130%	101%	80%	120%	101%	70%	130%
Electrical Conductivity (2:1)	3304572		0.176	0.163	7.7%	< 0.005	106%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3296184		0.060	0.062	3.3%	NA									
pH, 2:1 CaCl2 Extraction	3275481		6.60	6.84	3.6%	NA	101%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3347188		<0.8	<0.8	NA	< 0.8	123%	70%	130%	97%	80%	120%	78%	70%	130%
Arsenic	3347188		2	2	NA	< 1	105%	70%	130%	90%	80%	120%	97%	70%	130%
Barium	3347188		61.3	60.2	1.8%	< 2.0	96%	70%	130%	89%	80%	120%	89%	70%	130%
Beryllium	3347188		<0.4	<0.4	NA	< 0.4	87%	70%	130%	97%	80%	120%	80%	70%	130%
Boron	3347188		5	6	NA	< 5	73%	70%	130%	100%	80%	120%	86%	70%	130%
Boron (Hot Water Soluble)	3372103		0.70	0.71	1.4%	< 0.10	95%	60%	140%	95%	70%	130%	99%	60%	140%
Cadmium	3347188		<0.5	<0.5	NA	< 0.5	105%	70%	130%	100%	80%	120%	94%	70%	130%
Chromium	3347188		16	15	NA	< 5	99%	70%	130%	95%	80%	120%	99%	70%	130%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839096
PROJECT: 211-10139-00
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:
SAMPLED BY:


Soil Analysis (Continued)

RPT Date: Dec 23, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Cobalt	3347188		6.2	6.1	1.6%	< 0.5	103%	70%	130%	95%	80%	120%	97%	70%	130%
Copper	3347188		10.4	10.4	0.0%	< 1.0	91%	70%	130%	93%	80%	120%	86%	70%	130%
Lead	3347188		6	6	0.0%	< 1	105%	70%	130%	98%	80%	120%	90%	70%	130%
Molybdenum	3347188		<0.5	<0.5	NA	< 0.5	114%	70%	130%	105%	80%	120%	113%	70%	130%
Nickel	3347188		12	12	0.0%	< 1	100%	70%	130%	93%	80%	120%	93%	70%	130%
Selenium	3347188		0.9	<0.8	NA	< 0.8	96%	70%	130%	98%	80%	120%	101%	70%	130%
Silver	3347188		<0.5	<0.5	NA	< 0.5	98%	70%	130%	94%	80%	120%	87%	70%	130%
Thallium	3347188		<0.5	<0.5	NA	< 0.5	97%	70%	130%	96%	80%	120%	92%	70%	130%
Uranium	3347188		<0.50	<0.50	NA	< 0.50	107%	70%	130%	95%	80%	120%	100%	70%	130%
Vanadium	3347188		24.8	24.2	2.4%	< 0.4	103%	70%	130%	95%	80%	120%	101%	70%	130%
Zinc	3347188		30	29	3.4%	< 5	99%	70%	130%	99%	80%	120%	87%	70%	130%
Chromium, Hexavalent	3346586		<0.2	<0.2	NA	< 0.2	101%	70%	130%	103%	80%	120%	101%	70%	130%
Cyanide, Free	3293925	3293925	< 0.040	< 0.040	NA	< 0.040	102%	70%	130%	98%	80%	120%	99%	70%	130%
Mercury	3347188		<0.10	<0.10	NA	< 0.10	106%	70%	130%	98%	80%	120%	94%	70%	130%
Electrical Conductivity (2:1)	3348804		0.251	0.268	6.6%	< 0.005	109%	80%	120%	NA			NA		
Sodium Adsorption Ratio (2:1) (Calc.)	3336543		1.31	1.32	0.8%	N/A	NA			NA			NA		
pH, 2:1 CaCl2 Extraction	3372115		7.47	7.70	3.0%	NA	99%	80%	120%	NA			NA		

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis

RPT Date: Dec 23, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3257319		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	105%	50%	140%	105%	50%	140%
Acenaphthylene	3257319		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	83%	50%	140%	98%	50%	140%
Acenaphthene	3257319		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	92%	50%	140%	83%	50%	140%
Fluorene	3257319		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	94%	50%	140%	88%	50%	140%
Phenanthrene	3257319		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	98%	50%	140%	74%	50%	140%
Anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	86%	50%	140%	82%	50%	140%
Fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	68%	50%	140%	88%	50%	140%	91%	50%	140%
Pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	74%	50%	140%	107%	50%	140%
Benz(a)anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	80%	50%	140%	85%	50%	140%	87%	50%	140%
Chrysene	3257319		< 0.05	< 0.05	NA	< 0.05	95%	50%	140%	90%	50%	140%	85%	50%	140%
Benzo(b)fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	105%	50%	140%	96%	50%	140%
Benzo(k)fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	98%	50%	140%	105%	50%	140%
Benzo(a)pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	86%	50%	140%	98%	50%	140%
Indeno(1,2,3-cd)pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	88%	50%	140%	86%	50%	140%
Dibenz(a,h)anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	74%	50%	140%	88%	50%	140%
Benzo(g,h,i)perylene	3257319		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	82%	50%	140%	80%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (Soil)															
Benzene	3296192		<0.02	<0.02	NA	< 0.02	83%	60%	140%	87%	60%	140%	103%	60%	140%
Toluene	3296192		<0.05	<0.05	NA	< 0.05	100%	60%	140%	102%	60%	140%	81%	60%	140%
Ethylbenzene	3296192		<0.05	<0.05	NA	< 0.05	108%	60%	140%	112%	60%	140%	75%	60%	140%
m & p-Xylene	3296192		<0.05	<0.05	NA	< 0.05	98%	60%	140%	98%	60%	140%	105%	60%	140%
o-Xylene	3296192		<0.05	<0.05	NA	< 0.05	117%	60%	140%	105%	60%	140%	101%	60%	140%
F1 (C6 - C10)	3296192		<5	<5	NA	< 5	102%	60%	140%	99%	60%	140%	100%	60%	140%
F2 (C10 to C16)	3253580		47	44	NA	< 10	102%	60%	140%	85%	60%	140%	85%	60%	140%
F3 (C16 to C34)	3253580		870	650	28.9%	< 50	106%	60%	140%	86%	60%	140%	95%	60%	140%
F4 (C34 to C50)	3253580		170	790	NA	< 50	115%	60%	140%	78%	60%	140%	74%	60%	140%
O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)															
F1 (C6 - C10)	3303708		<5	<5	NA	< 5	85%	60%	140%	115%	60%	140%	103%	60%	140%
O. Reg. 153(511) - VOCs (Soil)															
Dichlorodifluoromethane	3290917		< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	73%	50%	140%	79%	50%	140%
Vinyl Chloride	3290917		< 0.02	< 0.02	NA	< 0.02	108%	50%	140%	80%	50%	140%	95%	50%	140%
Bromomethane	3290917		< 0.05	< 0.05	NA	< 0.05	94%	50%	140%	91%	50%	140%	96%	50%	140%
Trichlorofluoromethane	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	87%	50%	140%	99%	50%	140%
Acetone	3290917		< 0.50	< 0.50	NA	< 0.50	104%	50%	140%	103%	50%	140%	103%	50%	140%
1,1-Dichloroethylene	3290917		< 0.05	< 0.05	NA	< 0.05	113%	50%	140%	90%	60%	130%	107%	50%	140%
Methylene Chloride	3290917		< 0.05	< 0.05	NA	< 0.05	117%	50%	140%	119%	60%	130%	85%	50%	140%
Trans- 1,2-Dichloroethylene	3290917		< 0.05	< 0.05	NA	< 0.05	100%	50%	140%	92%	60%	130%	97%	50%	140%
Methyl tert-butyl Ether	3290917		< 0.05	< 0.05	NA	< 0.05	117%	50%	140%	108%	60%	130%	107%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839096
PROJECT: 211-10139-00
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:
SAMPLED BY:

Trace Organics Analysis (Continued)

RPT Date: Dec 23, 2021

PARAMETER	Batch	Sample Id	DUPLICATE			Method Blank	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
			Dup #1	Dup #2	RPD		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
1,1-Dichloroethane	3290917		< 0.02	< 0.02	NA	< 0.02	107%	50%	140%	88%	60%	130%	101%	50%	140%
Methyl Ethyl Ketone	3290917		< 0.50	< 0.50	NA	< 0.50	96%	50%	140%	102%	50%	140%	101%	50%	140%
Cis- 1,2-Dichloroethylene	3290917		< 0.02	< 0.02	NA	< 0.02	109%	50%	140%	113%	60%	130%	113%	50%	140%
Chloroform	3290917		< 0.04	< 0.04	NA	< 0.04	116%	50%	140%	112%	60%	130%	105%	50%	140%
1,2-Dichloroethane	3290917		< 0.03	< 0.03	NA	< 0.03	116%	50%	140%	112%	60%	130%	116%	50%	140%
1,1,1-Trichloroethane	3290917		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	96%	60%	130%	79%	50%	140%
Carbon Tetrachloride	3290917		< 0.05	< 0.05	NA	< 0.05	82%	50%	140%	80%	60%	130%	76%	50%	140%
Benzene	3290917		0.21	0.19	NA	< 0.02	118%	50%	140%	99%	60%	130%	111%	50%	140%
1,2-Dichloropropane	3290917		< 0.03	< 0.03	NA	< 0.03	102%	50%	140%	113%	60%	130%	87%	50%	140%
Trichloroethylene	3290917		< 0.03	< 0.03	NA	< 0.03	106%	50%	140%	96%	60%	130%	97%	50%	140%
Bromodichloromethane	3290917		< 0.05	< 0.05	NA	< 0.05	118%	50%	140%	117%	60%	130%	102%	50%	140%
Methyl Isobutyl Ketone	3290917		< 0.50	< 0.50	NA	< 0.50	94%	50%	140%	101%	50%	140%	97%	50%	140%
1,1,2-Trichloroethane	3290917		< 0.04	< 0.04	NA	< 0.04	111%	50%	140%	111%	60%	130%	116%	50%	140%
Toluene	3290917		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	104%	60%	130%	117%	50%	140%
Dibromochloromethane	3290917		< 0.05	< 0.05	NA	< 0.05	111%	50%	140%	110%	60%	130%	97%	50%	140%
Ethylene Dibromide	3290917		< 0.04	< 0.04	NA	< 0.04	110%	50%	140%	107%	60%	130%	108%	50%	140%
Tetrachloroethylene	3290917		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	77%	60%	130%	80%	50%	140%
1,1,1,2-Tetrachloroethane	3290917		< 0.04	< 0.04	NA	< 0.04	94%	50%	140%	97%	60%	130%	72%	50%	140%
Chlorobenzene	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	97%	60%	130%	89%	50%	140%
Ethylbenzene	3290917		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	75%	60%	130%	74%	50%	140%
m & p-Xylene	3290917		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	93%	60%	130%	94%	50%	140%
Bromoform	3290917		< 0.05	< 0.05	NA	< 0.05	115%	50%	140%	114%	60%	130%	92%	50%	140%
Styrene	3290917		< 0.05	< 0.05	NA	< 0.05	74%	50%	140%	71%	60%	130%	75%	50%	140%
1,1,2,2-Tetrachloroethane	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	95%	60%	130%	109%	50%	140%
o-Xylene	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	93%	60%	130%	88%	50%	140%
1,3-Dichlorobenzene	3290917		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	99%	60%	130%	113%	50%	140%
1,4-Dichlorobenzene	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	106%	60%	130%	115%	50%	140%
1,2-Dichlorobenzene	3290917		< 0.05	< 0.05	NA	< 0.05	117%	50%	140%	94%	60%	130%	103%	50%	140%
n-Hexane	3290917		< 0.05	< 0.05	NA	< 0.05	76%	50%	140%	88%	60%	130%	82%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

RPT Date: Dec 23, 2021		REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Sample Id	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Antimony		134%	70%	130%	98%	80%	120%	92%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Benzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Toluene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Ethylbenzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
m & p-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
o-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Xylenes (Total)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	P&T GC/FID
Dichlorodifluoromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Bromomethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trans- 1,2-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl tert-butyl Ether	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Cis- 1,2-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Dibromochloromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
1,1,1,2-Tetrachloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Bromoform	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene (Cis + Trans)	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5002	modified from EPA 5035A & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5002	modified from EPA 5035A & EPA 8260D	(P&T)GC/MS
Moisture Content	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: Vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ (Region)

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Laboratory Use Only

Work Order #: 21T839096.
Cooler Quantity: 1 large bulk
Arrival Temperatures: 3.8 | 1.9 | 4.5
Custody Seal Intact: ☐ Yes ☐ No ☑ N/A
Notes: free ice

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils SPLP: ☐ Metals	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Hold Samples	Potentially Hazardous or High Concentration (Y/N)
BH21-2 SS2	12/2/21	AM PM	2	S			X				X									
BH21-2 SS5		AM PM	2	S					X											
QAQC-11		AM PM	1	S	PHC Only				X											
BH21-2 SS6		AM PM	2	S														X		
BH21-3 SS1		AM PM	1	S			X													
QAQC-12		AM PM	1	S			X													
BH21-3 SS2		AM PM	1	S														X		
BH21-3 SS6		AM PM	2	S					X											
BH21-3 SS7		AM PM	2	S					X									X		
BH21-6 SS1	12/1/21	AM PM	1	S																
BH21-6 SS2		AM PM	1	S																

	Date	Time		Date	Time
Samples Relinquished By (Print Name and Sign): Matthew Roy	12/2/21	1500	Samples Received By (Print Name and Sign): Adriana Bellavia		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 DEC 2 3:42pm

Page 1 of 2

N°: T 126072

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712 5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: See Page 1
Contact:
Address:
Phone: Fax:
Reports to be sent to:
1. Email:
2. Email:

Project Information:

Project: ZLL-60139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email:

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ Region

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
____ Indicate One

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Laboratory Use Only

Work Order #:
Cooler Quantity: 1 large bag
Arrival Temperatures: 3.8 | 1.9 | 4.5
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: free ice

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR			Hold Sample				Potentially Hazardous or High Concentration (Y/N)
BH21-6 SS5	12/1/21	AM PM	2	S																X				
BH21-6 SS6	1	AM PM	2	S					X															
BH21-16 SS1		PM	1	S			X																	
BH21-16 SS2		PM	1	S							X													
QAQC-10		PM	1	S							X													
BH21-16 SS5		PM	2	S					X				X							X				
BH21-16 SS8		PM	2	S					X				X											
QAQC-9		PM	2	S																				
		AM PM																						
		AM PM																						
		AM PM																						

Samples Relinquished By (Print Name and Sign): Matthew Roy	Date: 12/2/21	Time: 1500	Samples Received By (Print Name and Sign): Adriana Bellavia Abellavia	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 DEC 2 7:40 PM

Page 2 of 2

N°: T 126075

Document ID: DIV 78 1511 0.21

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00 200 02
AGAT WORK ORDER: 21T839249
SOIL ANALYSIS REVIEWED BY: Jacky Zhu, Spectroscopy Technician
TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor
DATE REPORTED: Dec 20, 2021
PAGES (INCLUDING COVER): 14
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-20

SAMPLE DESCRIPTION:				BH21-10 SS3	BH21-32 SS2	BH21-36 SS2
SAMPLE TYPE:				Soil	Soil	Soil
DATE SAMPLED:				2021-10-27	2021-11-05	2021-11-06
Parameter	Unit	G / S	RDL	3291580	3291585	3291586
Antimony	µg/g	1.3	0.8	<0.8	<0.8	<0.8
Arsenic	µg/g	18	1	8	2	4
Barium	µg/g	220	2.0	27.0	35.6	26.3
Beryllium	µg/g	2.5	0.4	<0.4	<0.4	<0.4
Boron	µg/g	36	5	8	<5	7
Boron (Hot Water Soluble)	µg/g	NA	0.10	0.21	0.16	0.15
Cadmium	µg/g	1.2	0.5	<0.5	<0.5	<0.5
Chromium	µg/g	70	5	10	11	11
Cobalt	µg/g	21	0.5	5.2	4.5	5.4
Copper	µg/g	92	1.0	23.7	16.7	26.2
Lead	µg/g	120	1	15	9	13
Molybdenum	µg/g	2	0.5	1.0	<0.5	<0.5
Nickel	µg/g	82	1	7	9	9
Selenium	µg/g	1.5	0.8	<0.8	<0.8	<0.8
Silver	µg/g	0.5	0.5	<0.5	<0.5	<0.5
Thallium	µg/g	1	0.5	<0.5	<0.5	<0.5
Uranium	µg/g	2.5	0.50	<0.50	<0.50	<0.50
Vanadium	µg/g	86	0.4	15.3	20.5	21.4
Zinc	µg/g	290	5	54	34	39
Chromium, Hexavalent	µg/g	0.66	0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040
Mercury	µg/g	0.27	0.10	<0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	0.57	0.005	0.210	0.134	0.115
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	2.4	N/A	0.295	0.199	0.139
pH, 2:1 CaCl2 Extraction	pH Units		NA	7.39	7.15	7.08

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-20

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3291580-3291586 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-20

		SAMPLE DESCRIPTION:		BH21-9 SS4	BH21-40 SS1
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-11-04	2021-10-27
Parameter	Unit	G / S	RDL	3291568	3291574
Naphthalene	µg/g	0.09	0.05	<0.05	0.31
Acenaphthylene	µg/g	0.093	0.05	<0.05	0.14
Acenaphthene	µg/g	0.072	0.05	<0.05	<0.05
Fluorene	µg/g	0.12	0.05	<0.05	<0.05
Phenanthrene	µg/g	0.69	0.05	0.22	0.78
Anthracene	µg/g	0.16	0.05	0.07	0.27
Fluoranthene	µg/g	0.56	0.05	0.44	2.11
Pyrene	µg/g	1	0.05	0.41	1.94
Benz(a)anthracene	µg/g	0.36	0.05	0.20	1.13
Chrysene	µg/g	2.8	0.05	0.12	1.25
Benzo(b)fluoranthene	µg/g	0.47	0.05	0.18	1.61
Benzo(k)fluoranthene	µg/g	0.48	0.05	0.09	0.63
Benzo(a)pyrene	µg/g	0.3	0.05	0.16	0.86
Indeno(1,2,3-cd)pyrene	µg/g	0.46	0.05	0.07	0.48
Dibenz(a,h)anthracene	µg/g	0.1	0.05	<0.05	0.13
Benzo(g,h,i)perylene	µg/g	0.68	0.05	0.08	0.55
1 and 2 Methlynaphthalene	µg/g	0.59	0.05	<0.05	0.82
Moisture Content	%		0.1	10.5	19.6
Surrogate	Unit	Acceptable Limits			
Naphthalene-d8	%	50-140		92	108
Acridine-d9	%	50-140		100	91
Terphenyl-d14	%	50-140		75	106

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3291568-3291574 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-20

		SAMPLE DESCRIPTION:		BH21-31 SS3
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-05
Parameter	Unit	G / S	RDL	3291573
Benzene	µg/g	0.02	0.02	<0.02
Toluene	µg/g	0.2	0.05	<0.05
Ethylbenzene	µg/g	0.05	0.05	<0.05
m & p-Xylene	µg/g		0.05	<0.05
o-Xylene	µg/g		0.05	<0.05
Xylenes (Total)	µg/g	0.05	0.05	<0.05
F1 (C6 - C10)	µg/g	25	5	7.8
F1 (C6 to C10) minus BTEX	µg/g	25	5	8
F2 (C10 to C16)	µg/g	10	10	<10
F3 (C16 to C34)	µg/g	240	50	<50
F4 (C34 to C50)	µg/g	120	50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA
Moisture Content	%		0.1	10.0
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	60-140		91
Terphenyl	%	60-140		89

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-20

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3291573 Results are based on sample dry weight.
The C6-C10 fraction is calculated using Toluene response factor.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were not met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.
Quality Control Data is available upon request.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	1 and 2 Methlynaphthalene	µg/g	0.59	0.82
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Acenaphthylene	µg/g	0.093	0.14
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Anthracene	µg/g	0.16	0.27
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benz(a)anthracene	µg/g	0.36	1.13
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benzo(a)pyrene	µg/g	0.3	0.86
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benzo(b)fluoranthene	µg/g	0.47	1.61
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Benzo(k)fluoranthene	µg/g	0.48	0.63
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Dibenz(a,h)anthracene	µg/g	0.1	0.13
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Fluoranthene	µg/g	0.56	2.11
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Indeno(1,2,3-cd)pyrene	µg/g	0.46	0.48
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Naphthalene	µg/g	0.09	0.31
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Phenanthrene	µg/g	0.69	0.78
3291574	BH21-40 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - PAHs (Soil)	Pyrene	µg/g	1	1.94

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839249
PROJECT: 211-10139-00 200 02
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:
SAMPLED BY:

Soil Analysis

RPT Date: Dec 20, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3325188		<0.8	<0.8	NA	< 0.8	138%	70%	130%	106%	80%	120%	99%	70%	130%
Arsenic	3325188		<1	<1	NA	< 1	121%	70%	130%	104%	80%	120%	105%	70%	130%
Barium	3325188		34.2	35.0	2.3%	< 2.0	100%	70%	130%	99%	80%	120%	96%	70%	130%
Beryllium	3325188		<0.4	<0.4	NA	< 0.4	84%	70%	130%	99%	80%	120%	91%	70%	130%
Boron	3325188		<5	<5	NA	< 5	81%	70%	130%	102%	80%	120%	87%	70%	130%
Boron (Hot Water Soluble)	3296197		0.11	0.12	NA	< 0.10	86%	60%	140%	108%	70%	130%	104%	60%	140%
Cadmium	3325188		<0.5	<0.5	NA	< 0.5	115%	70%	130%	105%	80%	120%	106%	70%	130%
Chromium	3325188		9	9	NA	< 5	100%	70%	130%	99%	80%	120%	105%	70%	130%
Cobalt	3325188		4.2	4.1	2.4%	< 0.5	106%	70%	130%	99%	80%	120%	99%	70%	130%
Copper	3325188		16.7	16.3	2.4%	< 1.0	97%	70%	130%	99%	80%	120%	98%	70%	130%
Lead	3325188		1	1	NA	< 1	105%	70%	130%	98%	80%	120%	96%	70%	130%
Molybdenum	3325188		<0.5	<0.5	NA	< 0.5	116%	70%	130%	110%	80%	120%	110%	70%	130%
Nickel	3325188		6	6	0.0%	< 1	105%	70%	130%	100%	80%	120%	101%	70%	130%
Selenium	3325188		0.8	1.0	NA	< 0.8	95%	70%	130%	107%	80%	120%	108%	70%	130%
Silver	3325188		<0.5	<0.5	NA	< 0.5	105%	70%	130%	104%	80%	120%	101%	70%	130%
Thallium	3325188		<0.5	<0.5	NA	< 0.5	113%	70%	130%	110%	80%	120%	107%	70%	130%
Uranium	3325188		<0.50	<0.50	NA	< 0.50	112%	70%	130%	103%	80%	120%	101%	70%	130%
Vanadium	3325188		24.0	24.6	2.5%	< 0.4	107%	70%	130%	96%	80%	120%	100%	70%	130%
Zinc	3325188		16	16	NA	< 5	102%	70%	130%	102%	80%	120%	104%	70%	130%
Chromium, Hexavalent	3309312		<0.2	<0.2	NA	< 0.2	102%	70%	130%	88%	80%	120%	81%	70%	130%
Cyanide, Free	3304561		<0.040	<0.040	NA	< 0.040	101%	70%	130%	97%	80%	120%	104%	70%	130%
Mercury	3325188		<0.10	<0.10	NA	< 0.10	106%	70%	130%	105%	80%	120%	104%	70%	130%
Electrical Conductivity (2:1)	3291580	3291580	0.210	0.223	6.0%	< 0.005	106%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3291580	3291580	0.295	0.294	0.3%	NA									
pH, 2:1 CaCl2 Extraction	3296258		6.92	7.35	6.0%	NA	100%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839249
PROJECT: 211-10139-00 200 02
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:
SAMPLED BY:

Trace Organics Analysis

RPT Date: Dec 20, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3319161		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	86%	50%	140%	80%	50%	140%
Acenaphthylene	3319161		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	93%	50%	140%	89%	50%	140%
Acenaphthene	3319161		< 0.05	< 0.05	NA	< 0.05	82%	50%	140%	92%	50%	140%	89%	50%	140%
Fluorene	3319161		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	101%	50%	140%	80%	50%	140%
Phenanthrene	3319161		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	78%	50%	140%	85%	50%	140%
Anthracene	3319161		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	85%	50%	140%	111%	50%	140%
Fluoranthene	3319161		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	90%	50%	140%	99%	50%	140%
Pyrene	3319161		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	105%	50%	140%	86%	50%	140%
Benz(a)anthracene	3319161		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	98%	50%	140%	109%	50%	140%
Chrysene	3319161		< 0.05	< 0.05	NA	< 0.05	94%	50%	140%	86%	50%	140%	103%	50%	140%
Benzo(b)fluoranthene	3319161		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	77%	50%	140%	102%	50%	140%
Benzo(k)fluoranthene	3319161		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	85%	50%	140%	76%	50%	140%
Benzo(a)pyrene	3319161		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	93%	50%	140%	89%	50%	140%
Indeno(1,2,3-cd)pyrene	3319161		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	102%	50%	140%	75%	50%	140%
Dibenz(a,h)anthracene	3319161		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	98%	50%	140%	112%	50%	140%
Benzo(g,h,i)perylene	3319161		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	86%	50%	140%	97%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (Soil)															
Benzene	3308152		<0.02	<0.02	NA	< 0.02	94%	60%	140%	102%	60%	140%	103%	60%	140%
Toluene	3308152		0.07	0.08	NA	< 0.05	104%	60%	140%	102%	60%	140%	112%	60%	140%
Ethylbenzene	3308152		<0.05	0.06	NA	< 0.05	98%	60%	140%	96%	60%	140%	109%	60%	140%
m & p-Xylene	3308152		0.14	0.19	NA	< 0.05	102%	60%	140%	102%	60%	140%	101%	60%	140%
o-Xylene	3308152		0.11	<0.05	NA	< 0.05	91%	60%	140%	103%	60%	140%	98%	60%	140%
F1 (C6 - C10)	3308152		11	12	NA	< 5	84%	60%	140%	93%	60%	140%	73%	60%	140%
F2 (C10 to C16)	3276907		< 10	< 10	NA	< 10	89%	60%	140%	89%	60%	140%	84%	60%	140%
F3 (C16 to C34)	3276907		480	410	15.7%	< 50	85%	60%	140%	89%	60%	140%	85%	60%	140%
F4 (C34 to C50)	3276907		150	140	NA	< 50	87%	60%	140%	89%	60%	140%	84%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

RPT Date: Dec 20, 2021

PARAMETER	Sample Id	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Antimony		138%	70%	130%	106%	80%	120%	99%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
Benzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Toluene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Ethylbenzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
m & p-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
o-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Xylenes (Total)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	P&T GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839249

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID

Results relate only to the items tested. Results apply to samples as received.

1 med

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only
Work Order #: 21T839249
Cooler Quantity:
Arrival Temperatures: 2.8 | 2.9 | 3.7
Custody Seal Intact: ☐Yes ☐No ☐N/A
Notes:

Report Information:
Company: WSP Canada Inc.
Contact: Vanessa. Oetinger
Address: 2 International Blvd Toronto, ON
Phone: Fax:
Reports to be sent to:
1. Email: Vanessa.Oetinger@wsp.com
2. Email:

Regulatory Requirements:
(Please check all applicable boxes)
☒ Regulation 153/04 — Table 1 (Indicate One) — ☐Ind/Com ☒Res/Park ☐Agriculture
Soil Texture (Check One): ☒Coarse ☐Fine
☐ Excess Soils R406 — Table (Indicate One)
☐ Regulation 558
☐ CCME
☐ Sewer Use ☐Sanitary ☐Storm — (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other (Indicate One)

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☐ Yes ☐ No

Turnaround Time (TAT) Required:
Regular TAT ☐ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply):
Please provide prior notification for rush TAT
*TAT is exclusive of weekends and statutory holidays
For 'Same Day' analysis, please contact your AGAT CPM

Project Information:
Project: 211-10139-00 200 02
Site Location: ORBY Railway
Sampled By:
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information: Bill To Same: Yes ☐ No ☐
Company: WSP Canada Inc.
Contact:
Address:
Email: payables.ontario@wsp.com

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC Y/N	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐CrVI, ☐Hg, ☐HWSB	O. Reg 153: BTEX, F1-F4 PHCs — Analyze F4G if required ☐Yes ☐No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐M&I ☐VOCs ☐ABNs ☐B(a)P ☐PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐Metals ☐VOCs ☐SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-9 SS4	11/4/21	AM PM	1	S						X							
BH21-31 S3	11/5/21	AM PM	1	S	Limit holding time				X								
BH21-40 S1	10/27/21	AM PM	1	S						X							
BH21-10 S3	10/27/21	AM PM	1	S	Limited Sample		X										
BH21-41 S2	11/5/21	AM PM	1	S	Limit holding time				X								
BH21-32 SS2	11/5/21	AM PM	1	S			X										
BH21-36 SS2	11/6/21	AM PM	1	S			X										
		AM PM															
		AM PM															
		AM PM															
		AM PM															

Samples Relinquished By (Print Name and Sign)	Date	Time	Samples Received By (Print Name and Sign)	Date	Time
Steven Andrachuk	12/2/21	630PM	Dave Eastman		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21DEC 2 7:04pm
Page ____ of ____
Nº: T 127458

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065

ATTENTION TO: Vanessa Oetinger

PROJECT: 211-10139-00

AGAT WORK ORDER: 21T840564

SOIL ANALYSIS REVIEWED BY: Amanjot Bhela, Inorganic Lab Manager

TRACE ORGANICS REVIEWED BY: Inga Kuzmina, Trace Organics Lab Manager

DATE REPORTED: Dec 18, 2021

PAGES (INCLUDING COVER): 17

VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-06

DATE REPORTED: 2021-12-18

		SAMPLE DESCRIPTION:		BH21-4 SS1	BH21-5 SS1
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-12-06	2021-12-06
Parameter	Unit	G / S	RDL	3304637	3304642
Antimony	µg/g	1.3	0.8	<0.8	<0.8
Arsenic	µg/g	18	1	4	7
Barium	µg/g	220	2.0	37.4	60.0
Beryllium	µg/g	2.5	0.4	0.5	0.7
Boron	µg/g	36	5	<5	7
Boron (Hot Water Soluble)	µg/g	NA	0.10	0.12	0.26
Cadmium	µg/g	1.2	0.5	<0.5	<0.5
Chromium	µg/g	70	5	12	18
Cobalt	µg/g	21	0.5	5.6	6.6
Copper	µg/g	92	1.0	24.7	23.3
Lead	µg/g	120	1	9	18
Molybdenum	µg/g	2	0.5	<0.5	0.6
Nickel	µg/g	82	1	12	14
Selenium	µg/g	1.5	0.8	<0.8	<0.8
Silver	µg/g	0.5	0.5	<0.5	<0.5
Thallium	µg/g	1	0.5	<0.5	<0.5
Uranium	µg/g	2.5	0.50	<0.50	<0.50
Vanadium	µg/g	86	0.4	20.4	28.1
Zinc	µg/g	290	5	32	51
Chromium, Hexavalent	µg/g	0.66	0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040
Mercury	µg/g	0.27	0.10	<0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	0.57	0.005	0.124	0.200
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	2.4	N/A	0.143	0.116
pH, 2:1 CaCl2 Extraction	pH Units		NA	7.19	7.04

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-06

DATE REPORTED: 2021-12-18

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3304637-3304642 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy


O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-12-06

DATE REPORTED: 2021-12-18

		SAMPLE DESCRIPTION:		BH21-4 SS2	BH21-5 SS3
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-12-06	2021-12-06
Parameter	Unit	G / S	RDL	3304639	3304644
Gamma-Hexachlorocyclohexane	µg/g	0.01	0.005	<0.005	<0.005
Heptachlor	µg/g	0.05	0.005	<0.005	<0.005
Aldrin	µg/g	0.05	0.005	<0.005	<0.005
Heptachlor Epoxide	µg/g	0.05	0.005	<0.005	<0.005
Endosulfan I	µg/g		0.005	<0.005	<0.005
Endosulfan II	µg/g		0.005	<0.005	<0.005
Endosulfan	µg/g	0.04	0.005	<0.005	<0.005
Alpha-Chlordane	µg/g		0.005	<0.005	<0.005
gamma-Chlordane	µg/g		0.005	<0.005	<0.005
Chlordane	µg/g	0.05	0.007	<0.007	<0.007
op'-DDD	µg/g		0.005	<0.005	<0.005
pp'-DDD	µg/g		0.005	<0.005	<0.005
DDD	µg/g	0.05	0.007	<0.007	<0.007
op'-DDE	ug/g		0.005	<0.005	<0.005
pp'-DDE	µg/g		0.005	<0.005	<0.005
DDE	µg/g	0.05	0.007	<0.007	<0.007
op'-DDT	µg/g		0.005	<0.005	<0.005
pp'-DDT	µg/g		0.005	<0.005	<0.005
DDT	µg/g	1.4	0.007	<0.007	<0.007
Dieldrin	µg/g	0.05	0.005	<0.005	<0.005
Endrin	µg/g	0.04	0.005	<0.005	<0.005
Methoxychlor	µg/g	0.05	0.005	<0.005	<0.005
Hexachlorobenzene	µg/g	0.01	0.005	<0.005	<0.005
Hexachlorobutadiene	µg/g	0.01	0.01	<0.01	<0.01
Hexachloroethane	µg/g	0.01	0.01	<0.01	<0.01
Aroclor 1242	µg/g		0.10	<0.10	<0.10
Aroclor 1248	µg/g		0.10	<0.10	<0.10
Aroclor 1254	µg/g		0.10	<0.10	<0.10
Aroclor 1260	µg/g		0.10	<0.10	<0.10
Polychlorinated Biphenyls	µg/g	0.3	0.10	<0.10	<0.10

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - OC Pesticides + PCBs (Soil)

DATE RECEIVED: 2021-12-06

DATE REPORTED: 2021-12-18

		SAMPLE DESCRIPTION:		BH21-4 SS2	BH21-5 SS3
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-12-06	2021-12-06
Parameter	Unit	G / S	RDL	3304639	3304644
Moisture Content	%		0.1	14.6	12.6
wet weight OC/PCB	g		NA	10.03	10.12
Surrogate	Unit	Acceptable Limits			
TCMX	%	50-140		76	74
Decachlorobiphenyl	%	50-140		77	85

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3304639-3304644 Results are based on the dry weight of the soil.
DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-12-06

DATE REPORTED: 2021-12-18

		SAMPLE DESCRIPTION:		BH21-4 SS1	BH21-5 SS1
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-12-06	2021-12-06
Parameter	Unit	G / S	RDL	3304637	3304642
Naphthalene	µg/g	0.09	0.05	<0.05	<0.05
Acenaphthylene	µg/g	0.093	0.05	<0.05	<0.05
Acenaphthene	µg/g	0.072	0.05	<0.05	<0.05
Fluorene	µg/g	0.12	0.05	<0.05	<0.05
Phenanthrene	µg/g	0.69	0.05	<0.05	<0.05
Anthracene	µg/g	0.16	0.05	<0.05	<0.05
Fluoranthene	µg/g	0.56	0.05	<0.05	<0.05
Pyrene	µg/g	1	0.05	<0.05	<0.05
Benz(a)anthracene	µg/g	0.36	0.05	<0.05	<0.05
Chrysene	µg/g	2.8	0.05	<0.05	<0.05
Benzo(b)fluoranthene	µg/g	0.47	0.05	<0.05	<0.05
Benzo(k)fluoranthene	µg/g	0.48	0.05	<0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.46	0.05	<0.05	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05	<0.05	<0.05
Benzo(g,h,i)perylene	µg/g	0.68	0.05	<0.05	<0.05
1 and 2 Methlynaphthalene	µg/g	0.59	0.05	<0.05	<0.05
Moisture Content	%		0.1	14.7	19.6
Surrogate	Unit	Acceptable Limits			
Naphthalene-d8	%	50-140		78	109
Acridine-d9	%	50-140		84	86
Terphenyl-d14	%	50-140		88	99

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3304637-3304642 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-12-06

DATE REPORTED: 2021-12-18

		SAMPLE DESCRIPTION:		BH21-4 SS3	BH21-5 SS2
		SAMPLE TYPE:		Soil	Soil
		DATE SAMPLED:		2021-12-06	2021-12-06
Parameter	Unit	G / S	RDL	3304640	3304643
Benzene	µg/g	0.02	0.02	<0.02	<0.02
Toluene	µg/g	0.2	0.05	<0.05	<0.05
Ethylbenzene	µg/g	0.05	0.05	<0.05	<0.05
m & p-Xylene	µg/g		0.05	<0.05	<0.05
o-Xylene	µg/g		0.05	<0.05	<0.05
Xylenes (Total)	µg/g	0.05	0.05	<0.05	<0.05
F1 (C6 - C10)	µg/g	25	5	<5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5	<5
F2 (C10 to C16)	µg/g	10	10	<10	<10
F3 (C16 to C34)	µg/g	240	50	<50	<50
F4 (C34 to C50)	µg/g	120	50	<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA	NA
Moisture Content	%		0.1	14.0	20.1
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	60-140		75	86
Terphenyl	%	60-140		73	86

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-12-06


DATE REPORTED: 2021-12-18

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3304640-3304643 Results are based on sample dry weight.
The C6-C10 fraction is calculated using Toluene response factor.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.
Quality Control Data is available upon request.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail


SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Dec 18, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3303320		<0.8	<0.8	NA	< 0.8	133%	70%	130%	105%	80%	120%	83%	70%	130%
Arsenic	3303320		2	2	NA	< 1	117%	70%	130%	97%	80%	120%	97%	70%	130%
Barium	3303320		34.4	34.9	1.4%	< 2.0	99%	70%	130%	97%	80%	120%	98%	70%	130%
Beryllium	3303320		<0.4	<0.4	NA	< 0.4	104%	70%	130%	112%	80%	120%	108%	70%	130%
Boron	3303320		<5	<5	NA	< 5	88%	70%	130%	115%	80%	120%	101%	70%	130%
Boron (Hot Water Soluble)	3286879		0.14	0.14	NA	< 0.10	92%	60%	140%	101%	70%	130%	95%	60%	140%
Cadmium	3303320		<0.5	<0.5	NA	< 0.5	110%	70%	130%	102%	80%	120%	104%	70%	130%
Chromium	3303320		12	12	NA	< 5	101%	70%	130%	94%	80%	120%	98%	70%	130%
Cobalt	3303320		3.8	3.8	0.0%	< 0.5	111%	70%	130%	98%	80%	120%	97%	70%	130%
Copper	3303320		4.9	4.9	NA	< 1.0	93%	70%	130%	96%	80%	120%	92%	70%	130%
Lead	3303320		5	5	0.0%	< 1	102%	70%	130%	98%	80%	120%	94%	70%	130%
Molybdenum	3303320		<0.5	<0.5	NA	< 0.5	116%	70%	130%	108%	80%	120%	110%	70%	130%
Nickel	3303320		8	8	0.0%	< 1	108%	70%	130%	100%	80%	120%	97%	70%	130%
Selenium	3303320		<0.8	<0.8	NA	< 0.8	116%	70%	130%	102%	80%	120%	100%	70%	130%
Silver	3303320		<0.5	<0.5	NA	< 0.5	99%	70%	130%	97%	80%	120%	97%	70%	130%
Thallium	3303320		<0.5	<0.5	NA	< 0.5	114%	70%	130%	100%	80%	120%	99%	70%	130%
Uranium	3303320		<0.50	<0.50	NA	< 0.50	111%	70%	130%	98%	80%	120%	97%	70%	130%
Vanadium	3303320		19.2	19.4	1.0%	< 0.4	111%	70%	130%	95%	80%	120%	97%	70%	130%
Zinc	3303320		23	23	NA	< 5	104%	70%	130%	96%	80%	120%	94%	70%	130%
Chromium, Hexavalent	3321512		<0.2	<0.2	NA	< 0.2	106%	70%	130%	97%	80%	120%	87%	70%	130%
Cyanide, Free	3303310		<0.040	<0.040	NA	< 0.040	101%	70%	130%	99%	80%	120%	95%	70%	130%
Mercury	3303320		<0.10	<0.10	NA	< 0.10	101%	70%	130%	102%	80%	120%	101%	70%	130%
Electrical Conductivity (2:1)	3286879		0.260	0.261	0.4%	< 0.005	109%	80%	120%	NA			NA		
Sodium Adsorption Ratio (2:1) (Calc.)	3286879		3.22	3.15	2.2%	N/A	NA			NA			NA		
pH, 2:1 CaCl2 Extraction	3303699		6.59	6.84	3.7%	NA	100%	80%	120%	NA			NA		

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY Rail

AGAT WORK ORDER: 21T840564
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Dec 18, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3257319		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	105%	50%	140%	105%	50%	140%
Acenaphthylene	3257319		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	83%	50%	140%	98%	50%	140%
Acenaphthene	3257319		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	92%	50%	140%	83%	50%	140%
Fluorene	3257319		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	94%	50%	140%	88%	50%	140%
Phenanthrene	3257319		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	98%	50%	140%	74%	50%	140%
Anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	86%	50%	140%	82%	50%	140%
Fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	68%	50%	140%	88%	50%	140%	91%	50%	140%
Pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	74%	50%	140%	107%	50%	140%
Benz(a)anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	80%	50%	140%	85%	50%	140%	87%	50%	140%
Chrysene	3257319		< 0.05	< 0.05	NA	< 0.05	95%	50%	140%	90%	50%	140%	85%	50%	140%
Benzo(b)fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	105%	50%	140%	96%	50%	140%
Benzo(k)fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	98%	50%	140%	105%	50%	140%
Benzo(a)pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	86%	50%	140%	98%	50%	140%
Indeno(1,2,3-cd)pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	88%	50%	140%	86%	50%	140%
Dibenz(a,h)anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	74%	50%	140%	88%	50%	140%
Benzo(g,h,i)perylene	3257319		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	82%	50%	140%	80%	50%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Soil)															
Gamma-Hexachlorocyclohexane	3296567		< 0.005	< 0.005	NA	< 0.005	86%	50%	140%	90%	50%	140%	76%	50%	140%
Heptachlor	3296567		< 0.005	< 0.005	NA	< 0.005	82%	50%	140%	88%	50%	140%	85%	50%	140%
Aldrin	3296567		< 0.005	< 0.005	NA	< 0.005	96%	50%	140%	99%	50%	140%	80%	50%	140%
Heptachlor Epoxide	3296567		< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	98%	50%	140%	85%	50%	140%
Endosulfan I	3296567		< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	98%	50%	140%	82%	50%	140%
Endosulfan II	3296567		< 0.005	< 0.005	NA	< 0.005	98%	50%	140%	96%	50%	140%	83%	50%	140%
Alpha-Chlordane	3296567		< 0.005	< 0.005	NA	< 0.005	95%	50%	140%	97%	50%	140%	85%	50%	140%
gamma-Chlordane	3296567		< 0.005	< 0.005	NA	< 0.005	93%	50%	140%	96%	50%	140%	82%	50%	140%
op'-DDD	3296567		< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	106%	50%	140%	102%	50%	140%
pp'-DDD	3296567		< 0.005	< 0.005	NA	< 0.005	83%	50%	140%	99%	50%	140%	83%	50%	140%
op'-DDE	3296567		< 0.005	< 0.005	NA	< 0.005	92%	50%	140%	103%	50%	140%	80%	50%	140%
pp'-DDE	3296567		< 0.005	< 0.005	NA	< 0.005	89%	50%	140%	95%	50%	140%	84%	50%	140%
op'-DDT	3296567		< 0.005	< 0.005	NA	< 0.005	88%	50%	140%	105%	50%	140%	106%	50%	140%
pp'-DDT	3296567		< 0.005	< 0.005	NA	< 0.005	86%	50%	140%	88%	50%	140%	101%	50%	140%
Dieldrin	3296567		< 0.005	< 0.005	NA	< 0.005	97%	50%	140%	100%	50%	140%	86%	50%	140%
Endrin	3296567		< 0.005	< 0.005	NA	< 0.005	88%	50%	140%	101%	50%	140%	106%	50%	140%
Methoxychlor	3296567		< 0.005	< 0.005	NA	< 0.005	82%	50%	140%	90%	50%	140%	107%	50%	140%
Hexachlorobenzene	3296567		< 0.005	< 0.005	NA	< 0.005	89%	50%	140%	92%	50%	140%	89%	50%	140%
Hexachlorobutadiene	3296567		< 0.01	< 0.01	NA	< 0.01	85%	50%	140%	92%	50%	140%	81%	50%	140%
Hexachloroethane	3296567		< 0.01	< 0.01	NA	< 0.01	87%	50%	140%	98%	50%	140%	80%	50%	140%
Aroclor 1242	3296567		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	NA	50%	140%	NA	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T840564
PROJECT: 211-10139-00
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:ORBY Rail
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Dec 18, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Aroclor 1248	3296567		< 0.10	< 0.10	NA	< 0.10	106%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1254	3296567		< 0.10	< 0.10	NA	< 0.10	104%	50%	140%	NA	50%	140%	NA	50%	140%
Aroclor 1260	3296567		< 0.10	< 0.10	NA	< 0.10	92%	50%	140%	NA	50%	140%	NA	50%	140%
Polychlorinated Biphenyls	3296567		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	102%	50%	140%	95%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (Soil)															
Benzene	3304559		<0.02	<0.02	NA	< 0.02	104%	60%	140%	94%	60%	140%	104%	60%	140%
Toluene	3304559		<0.05	<0.05	NA	< 0.05	95%	60%	140%	87%	60%	140%	108%	60%	140%
Ethylbenzene	3304559		<0.05	<0.05	NA	< 0.05	99%	60%	140%	93%	60%	140%	95%	60%	140%
m & p-Xylene	3304559		<0.05	<0.05	NA	< 0.05	99%	60%	140%	105%	60%	140%	101%	60%	140%
o-Xylene	3304559		<0.05	<0.05	NA	< 0.05	114%	60%	140%	93%	60%	140%	91%	60%	140%
F1 (C6 - C10)	3304559		<5	<5	NA	< 5	90%	60%	140%	74%	60%	140%	80%	60%	140%
F2 (C10 to C16)	3308615		< 10	< 10	NA	< 10	101%	60%	140%	75%	60%	140%	85%	60%	140%
F3 (C16 to C34)	3308615		< 50	< 50	NA	< 50	110%	60%	140%	76%	60%	140%	87%	60%	140%
F4 (C34 to C50)	3308615		< 50	< 50	NA	< 50	115%	60%	140%	74%	60%	140%	89%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

RPT Date: Dec 18, 2021

PARAMETER	Sample Id	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Antimony		133%	70%	130%	105%	80%	120%	83%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan I	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan II	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endosulfan	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Alpha-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Chlordane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDD	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
op'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDE	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
op'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
pp'-DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
DDT	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	CALCULATION
Dieldrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Endrin	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Methoxychlor	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5113	modified from EPA SW-846 3570, 3620C & 8082A	GC/ECD
TCMX	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Decachlorobiphenyl	ORG-91-5113	modified from EPA SW-846 3541, 3620,8081	GC/ECD
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
wet weight OC/PCB	ORG-91-5113		BALANCE
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Toluene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Ethylbenzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
m & p-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T840564

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY Rail

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
o-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Xylenes (Total)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	P&T GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905 712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T840564

Cooler Quantity: 1 large blk
Arrival Temperatures: 3.4 | 4.9 | 5.0
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: bagged ice

Report Information:

Company: WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis

Invoice Information:

Bill To Same: Yes ☑ No ☐

Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ (Region)

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC Pesticides	Potentially Hazardous or High Concentration (Y/N)
BH21-4 SS1	12/6/21	AM PM	2	S			X				X								
BH21-4 SS2	↓	AM PM	1	S								X						X	
BH21-4 SS3		AM PM	2	S					X										
BH21-5 SS1		AM PM	2	S			X				X								
BH21-5 SS2		AM PM	2	S					X										
BH21-5 SS3		AM PM	1	S								X						X	
		AM PM																	
		AM PM																	
		AM PM																	
		AM PM																	
		AM PM																	

Samples Relinquished By (Print Name and Sign): Matthew Roy	Date: 12/6/21	Time: 1200	Samples Received By (Print Name and Sign): Adriana Bellavia	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:

RECEIVED 2021-12-07

N°: T 127090

Document ID: DIV 78-1515 021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00 200 02
AGAT WORK ORDER: 21T841262
SOIL ANALYSIS REVIEWED BY: Yris Verastegui, Report Reviewer
TRACE ORGANICS REVIEWED BY: Inga Kuzmina, Trace Organics Lab Manager
DATE REPORTED: Dec 20, 2021
PAGES (INCLUDING COVER): 16
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-20

		SAMPLE DESCRIPTION:		BH21-20 SS4
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-23
Parameter	Unit	G / S	RDL	3310262
Antimony	µg/g	1.3	0.8	<0.8
Arsenic	µg/g	18	1	5
Barium	µg/g	220	2.0	95.4
Beryllium	µg/g	2.5	0.4	0.6
Boron	µg/g	36	5	24
Boron (Hot Water Soluble)	µg/g	NA	0.10	0.26
Cadmium	µg/g	1.2	0.5	<0.5
Chromium	µg/g	70	5	25
Cobalt	µg/g	21	0.5	14.8
Copper	µg/g	92	1.0	10.6
Lead	µg/g	120	1	12
Molybdenum	µg/g	2	0.5	1.2
Nickel	µg/g	82	1	27
Selenium	µg/g	1.5	0.8	<0.8
Silver	µg/g	0.5	0.5	<0.5
Thallium	µg/g	1	0.5	<0.5
Uranium	µg/g	2.5	0.50	0.79
Vanadium	µg/g	86	0.4	40.2
Zinc	µg/g	290	5	63
Chromium, Hexavalent	µg/g	0.66	0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040
Mercury	µg/g	0.27	0.10	<0.10
Electrical Conductivity (2:1)	mS/cm	0.57	0.005	0.125
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	2.4	N/A	0.344
pH, 2:1 CaCl2 Extraction	pH Units		NA	7.13

Certified By: Iris Verástegui

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-20

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310262 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By: Iris Verástegui

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-20

		SAMPLE DESCRIPTION:		BH21-45 SS2
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-22
Parameter	Unit	G / S	RDL	3310265
Naphthalene	µg/g	0.09	0.05	<0.05
Acenaphthylene	µg/g	0.093	0.05	<0.05
Acenaphthene	µg/g	0.072	0.05	<0.05
Fluorene	µg/g	0.12	0.05	<0.05
Phenanthrene	µg/g	0.69	0.05	<0.05
Anthracene	µg/g	0.16	0.05	<0.05
Fluoranthene	µg/g	0.56	0.05	<0.05
Pyrene	µg/g	1	0.05	<0.05
Benz(a)anthracene	µg/g	0.36	0.05	<0.05
Chrysene	µg/g	2.8	0.05	<0.05
Benzo(b)fluoranthene	µg/g	0.47	0.05	<0.05
Benzo(k)fluoranthene	µg/g	0.48	0.05	<0.05
Benzo(a)pyrene	µg/g	0.3	0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g	0.46	0.05	<0.05
Dibenz(a,h)anthracene	µg/g	0.1	0.05	<0.05
Benzo(g,h,i)perylene	µg/g	0.68	0.05	<0.05
1 and 2 Methlynaphthalene	µg/g	0.59	0.05	<0.05
Moisture Content	%		0.1	14.8
Surrogate	Unit	Acceptable Limits		
Naphthalene-d8	%	50-140		115
Acridine-d9	%	50-140		90
Terphenyl-d14	%	50-140		94

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310265 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-20

		SAMPLE DESCRIPTION:		BH21-45 SS9
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-22
Parameter	Unit	G / S	RDL	3310271
F1 (C6 - C10)	µg/g	25	5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5
F2 (C10 to C16)	µg/g	10	10	<10
F3 (C16 to C34)	µg/g	240	50	<50
F4 (C34 to C50)	µg/g	120	50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA
Moisture Content	%		0.1	10.3
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		76
Terphenyl	%	60-140		96

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310271 Results are based on sample dry weight.
The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified without the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-20

		SAMPLE DESCRIPTION:		BH21-45 SS9
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-22
Parameter	Unit	G / S	RDL	3310271
Dichlorodifluoromethane	µg/g	0.05	0.05	<0.05
Vinyl Chloride	ug/g	0.02	0.02	<0.02
Bromomethane	ug/g	0.05	0.05	<0.05
Trichlorofluoromethane	ug/g	0.25	0.05	<0.05
Acetone	ug/g	0.5	0.50	<0.50
1,1-Dichloroethylene	ug/g	0.05	0.05	<0.05
Methylene Chloride	ug/g	0.05	0.05	<0.05
Trans- 1,2-Dichloroethylene	ug/g	0.05	0.05	<0.05
Methyl tert-butyl Ether	ug/g	0.05	0.05	<0.05
1,1-Dichloroethane	ug/g	0.05	0.02	<0.02
Methyl Ethyl Ketone	ug/g	0.5	0.50	<0.50
Cis- 1,2-Dichloroethylene	ug/g	0.05	0.02	<0.02
Chloroform	ug/g	0.05	0.04	<0.04
1,2-Dichloroethane	ug/g	0.05	0.03	<0.03
1,1,1-Trichloroethane	ug/g	0.05	0.05	<0.05
Carbon Tetrachloride	ug/g	0.05	0.05	<0.05
Benzene	ug/g	0.02	0.02	<0.02
1,2-Dichloropropane	ug/g	0.05	0.03	<0.03
Trichloroethylene	ug/g	0.05	0.03	<0.03
Bromodichloromethane	ug/g	0.05	0.05	<0.05
Methyl Isobutyl Ketone	ug/g	0.5	0.50	<0.50
1,1,2-Trichloroethane	ug/g	0.05	0.04	<0.04
Toluene	ug/g	0.2	0.05	<0.05
Dibromochloromethane	ug/g	0.05	0.05	<0.05
Ethylene Dibromide	ug/g	0.05	0.04	<0.04
Tetrachloroethylene	ug/g	0.05	0.05	<0.05
1,1,1,2-Tetrachloroethane	ug/g	0.05	0.04	<0.04
Chlorobenzene	ug/g	0.05	0.05	<0.05
Ethylbenzene	ug/g	0.05	0.05	<0.05
m & p-Xylene	ug/g		0.05	<0.05

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-20

		SAMPLE DESCRIPTION:		BH21-45 SS9
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-11-22
Parameter	Unit	G / S	RDL	3310271
Bromoform	ug/g	0.05	0.05	<0.05
Styrene	ug/g	0.05	0.05	<0.05
1,1,2,2-Tetrachloroethane	ug/g	0.05	0.05	<0.05
o-Xylene	ug/g		0.05	<0.05
1,3-Dichlorobenzene	ug/g	0.05	0.05	<0.05
1,4-Dichlorobenzene	ug/g	0.05	0.05	<0.05
1,2-Dichlorobenzene	ug/g	0.05	0.05	<0.05
Xylenes (Total)	ug/g	0.05	0.05	<0.05
1,3-Dichloropropene (Cis + Trans)	µg/g	0.05	0.04	<0.04
n-Hexane	µg/g	0.05	0.05	<0.05
Moisture Content	%		0.1	10.3
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		96
4-Bromofluorobenzene	% Recovery	50-140		90

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310271 The sample was analyzed using the high level technique. The sample was extracted using methanol, a small amount of the methanol extract was diluted in water and the purge & trap GC/MS analysis was performed. Results are based on the dry weight of the soil.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene + o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841262
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Soil Analysis

RPT Date: Dec 20, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3304656		<0.8	<0.8	NA	< 0.8	131%	70%	130%	100%	80%	120%	95%	70%	130%
Arsenic	3304656		3	3	NA	< 1	122%	70%	130%	101%	80%	120%	109%	70%	130%
Barium	3304656		26.3	26.3	0.0%	< 2.0	104%	70%	130%	100%	80%	120%	104%	70%	130%
Beryllium	3304656		<0.4	<0.4	NA	< 0.4	100%	70%	130%	108%	80%	120%	94%	70%	130%
Boron	3304656		<5	<5	NA	< 5	84%	70%	130%	110%	80%	120%	99%	70%	130%
Boron (Hot Water Soluble)	3315413		0.25	0.25	NA	< 0.10	94%	60%	140%	97%	70%	130%	98%	60%	140%
Cadmium	3304656		<0.5	<0.5	NA	< 0.5	113%	70%	130%	100%	80%	120%	99%	70%	130%
Chromium	3304656		<5	<5	NA	< 5	108%	70%	130%	104%	80%	120%	111%	70%	130%
Cobalt	3304656		2.6	2.6	0.0%	< 0.5	116%	70%	130%	103%	80%	120%	109%	70%	130%
Copper	3304656		22.1	22.5	1.8%	< 1.0	101%	70%	130%	103%	80%	120%	102%	70%	130%
Lead	3304656		8	8	0.0%	< 1	110%	70%	130%	96%	80%	120%	95%	70%	130%
Molybdenum	3304656		<0.5	<0.5	NA	< 0.5	121%	70%	130%	108%	80%	120%	115%	70%	130%
Nickel	3304656		3	3	NA	< 1	111%	70%	130%	103%	80%	120%	104%	70%	130%
Selenium	3304656		<0.8	0.8	NA	< 0.8	109%	70%	130%	103%	80%	120%	107%	70%	130%
Silver	3304656		<0.5	<0.5	NA	< 0.5	99%	70%	130%	98%	80%	120%	95%	70%	130%
Thallium	3304656		<0.5	<0.5	NA	< 0.5	110%	70%	130%	105%	80%	120%	100%	70%	130%
Uranium	3304656		0.91	0.91	NA	< 0.50	111%	70%	130%	99%	80%	120%	105%	70%	130%
Vanadium	3304656		7.9	8.1	2.5%	< 0.4	113%	70%	130%	99%	80%	120%	112%	70%	130%
Zinc	3304656		169	171	1.2%	< 5	110%	70%	130%	104%	80%	120%	114%	70%	130%
Chromium, Hexavalent	3328954		<0.2	<0.2	NA	< 0.2	106%	70%	130%	92%	80%	120%	83%	70%	130%
Cyanide, Free	3317042		<0.040	<0.040	NA	< 0.040	98%	70%	130%	94%	80%	120%	100%	70%	130%
Mercury	3304656		<0.10	<0.10	NA	< 0.10	105%	70%	130%	100%	80%	120%	101%	70%	130%
Electrical Conductivity (2:1)	3337822		0.162	0.166	2.4%	< 0.005	106%	80%	120%	NA			NA		
Sodium Adsorption Ratio (2:1) (Calc.)	3309969		0.630	0.631	0.2%	N/A	NA			NA			NA		
pH, 2:1 CaCl2 Extraction	3312912		6.54	6.89	5.2%	NA	100%	80%	120%	NA			NA		

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
QA Qualifier for metals – Antimony: For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

Certified By: Iris Verástegui

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841262
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis

RPT Date: Dec 20, 2021

PARAMETER	Batch	Sample Id	DUPLICATE			Method Blank	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
			Dup #1	Dup #2	RPD		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3319161		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	86%	50%	140%	80%	50%	140%
Acenaphthylene	3319161		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	93%	50%	140%	89%	50%	140%
Acenaphthene	3319161		< 0.05	< 0.05	NA	< 0.05	82%	50%	140%	92%	50%	140%	89%	50%	140%
Fluorene	3319161		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	101%	50%	140%	80%	50%	140%
Phenanthrene	3319161		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	78%	50%	140%	85%	50%	140%
Anthracene	3319161		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	85%	50%	140%	111%	50%	140%
Fluoranthene	3319161		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	90%	50%	140%	99%	50%	140%
Pyrene	3319161		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	105%	50%	140%	86%	50%	140%
Benz(a)anthracene	3319161		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	98%	50%	140%	109%	50%	140%
Chrysene	3319161		< 0.05	< 0.05	NA	< 0.05	94%	50%	140%	86%	50%	140%	103%	50%	140%
Benzo(b)fluoranthene	3319161		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	77%	50%	140%	102%	50%	140%
Benzo(k)fluoranthene	3319161		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	85%	50%	140%	76%	50%	140%
Benzo(a)pyrene	3319161		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	93%	50%	140%	89%	50%	140%
Indeno(1,2,3-cd)pyrene	3319161		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	102%	50%	140%	75%	50%	140%
Dibenz(a,h)anthracene	3319161		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	98%	50%	140%	112%	50%	140%
Benzo(g,h,i)perylene	3319161		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	86%	50%	140%	97%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)															
F1 (C6 - C10)	3304559		<5	<5	NA	< 5	90%	60%	140%	74%	60%	140%	80%	60%	140%
F2 (C10 to C16)	3335234		< 10	< 10	NA	< 10	116%	60%	140%	64%	60%	140%	110%	60%	140%
F3 (C16 to C34)	3335234		< 50	< 50	NA	< 50	110%	60%	140%	65%	60%	140%	97%	60%	140%
F4 (C34 to C50)	3335234		< 50	< 50	NA	< 50	83%	60%	140%	72%	60%	140%	116%	60%	140%
O. Reg. 153(511) - VOCs (Soil)															
Dichlorodifluoromethane	3340448		< 0.05	< 0.05	NA	< 0.05	77%	50%	140%	84%	50%	140%	80%	50%	140%
Vinyl Chloride	3340448		< 0.02	< 0.02	NA	< 0.02	87%	50%	140%	80%	50%	140%	106%	50%	140%
Bromomethane	3340448		< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	103%	50%	140%	75%	50%	140%
Trichlorofluoromethane	3340448		< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	98%	50%	140%	86%	50%	140%
Acetone	3340448		< 0.50	< 0.50	NA	< 0.50	106%	50%	140%	103%	50%	140%	101%	50%	140%
1,1-Dichloroethylene	3340448		< 0.05	< 0.05	NA	< 0.05	107%	50%	140%	75%	60%	130%	78%	50%	140%
Methylene Chloride	3340448		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	103%	60%	130%	115%	50%	140%
Trans- 1,2-Dichloroethylene	3340448		< 0.05	< 0.05	NA	< 0.05	80%	50%	140%	84%	60%	130%	89%	50%	140%
Methyl tert-butyl Ether	3340448		< 0.05	< 0.05	NA	< 0.05	89%	50%	140%	92%	60%	130%	77%	50%	140%
1,1-Dichloroethane	3340448		< 0.02	< 0.02	NA	< 0.02	102%	50%	140%	90%	60%	130%	83%	50%	140%
Methyl Ethyl Ketone	3340448		< 0.50	< 0.50	NA	< 0.50	97%	50%	140%	101%	50%	140%	101%	50%	140%
Cis- 1,2-Dichloroethylene	3340448		< 0.02	< 0.02	NA	< 0.02	102%	50%	140%	120%	60%	130%	116%	50%	140%
Chloroform	3340448		< 0.04	< 0.04	NA	< 0.04	113%	50%	140%	107%	60%	130%	99%	50%	140%
1,2-Dichloroethane	3340448		< 0.03	< 0.03	NA	< 0.03	117%	50%	140%	114%	60%	130%	99%	50%	140%
1,1,1-Trichloroethane	3340448		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	75%	60%	130%	79%	50%	140%
Carbon Tetrachloride	3340448		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	77%	60%	130%	74%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841262
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:Matthew Roy

Trace Organics Analysis (Continued)

RPT Date: Dec 20, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Benzene	3340448		< 0.02	< 0.02	NA	< 0.02	98%	50%	140%	114%	60%	130%	114%	50%	140%
1,2-Dichloropropane	3340448		< 0.03	< 0.03	NA	< 0.03	104%	50%	140%	95%	60%	130%	96%	50%	140%
Trichloroethylene	3340448		< 0.03	< 0.03	NA	< 0.03	101%	50%	140%	93%	60%	130%	102%	50%	140%
Bromodichloromethane	3340448		< 0.05	< 0.05	NA	< 0.05	107%	50%	140%	114%	60%	130%	113%	50%	140%
Methyl Isobutyl Ketone	3340448		< 0.50	< 0.50	NA	< 0.50	103%	50%	140%	104%	50%	140%	104%	50%	140%
1,1,2-Trichloroethane	3340448		< 0.04	< 0.04	NA	< 0.04	114%	50%	140%	106%	60%	130%	119%	50%	140%
Toluene	3340448		< 0.05	< 0.05	NA	< 0.05	99%	50%	140%	116%	60%	130%	96%	50%	140%
Dibromochloromethane	3340448		< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	106%	60%	130%	116%	50%	140%
Ethylene Dibromide	3340448		< 0.04	< 0.04	NA	< 0.04	91%	50%	140%	96%	60%	130%	108%	50%	140%
Tetrachloroethylene	3340448		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	103%	60%	130%	72%	50%	140%
1,1,1,2-Tetrachloroethane	3340448		< 0.04	< 0.04	NA	< 0.04	101%	50%	140%	116%	60%	130%	71%	50%	140%
Chlorobenzene	3340448		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	96%	60%	130%	90%	50%	140%
Ethylbenzene	3340448		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	92%	60%	130%	84%	50%	140%
m & p-Xylene	3340448		< 0.05	< 0.05	NA	< 0.05	106%	50%	140%	93%	60%	130%	105%	50%	140%
Bromoform	3340448		< 0.05	< 0.05	NA	< 0.05	96%	50%	140%	79%	60%	130%	112%	50%	140%
Styrene	3340448		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	78%	60%	130%	84%	50%	140%
1,1,2,2-Tetrachloroethane	3340448		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	110%	60%	130%	82%	50%	140%
o-Xylene	3340448		< 0.05	< 0.05	NA	< 0.05	99%	50%	140%	106%	60%	130%	78%	50%	140%
1,3-Dichlorobenzene	3340448		< 0.05	< 0.05	NA	< 0.05	112%	50%	140%	101%	60%	130%	110%	50%	140%
1,4-Dichlorobenzene	3340448		< 0.05	< 0.05	NA	< 0.05	106%	50%	140%	95%	60%	130%	112%	50%	140%
1,2-Dichlorobenzene	3340448		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	92%	60%	130%	102%	50%	140%
n-Hexane	3340448		< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	98%	60%	130%	92%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

RPT Date: Dec 20, 2021

PARAMETER	Sample Id	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Antimony		131%	70%	130%	100%	80%	120%	95%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.
QA Qualifier for metals – Antimony: For a multi-element scan for lab control standards and matrix spikes, up to 10% of analytes may exceed the quoted limits by up to 10% absolute and it is considered acceptable.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Dichlorodifluoromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Bromomethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trans- 1,2-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl tert-butyl Ether	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Cis- 1,2-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Dibromochloromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,1,2-Tetrachloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841262

PROJECT: 211-10139-00 200 02

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Matthew Roy

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Bromoform	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene (Cis + Trans)	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5002	modified from EPA 5035A & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5002	modified from EPA 5035A & EPA 8260D	(P&T)GC/MS
Moisture Content	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP
Contact: Vanessa Oetinger
Address: 2 International Blvd, Toronto ON
Phone: Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: marsad.jafar@wsp.com

Project Information:

Project: 211-10139-00 200 02
Site Location: ORBY
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☐ Ind/Com
☑ Res/Park
☐ Agriculture
Soil Texture (Check One)
☐ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
____ (Indicate One)

Is this submission for a Record of Site Condition? ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Laboratory Use Only

Work Order #: 21T841262
Cooler Quantity: 1 Blk (bagged ice)
Arrival Temperatures: 12.9 | 12.4 | 12.0
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes:

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-20 SS4	Nov 23/21	AM	1	S			X											
BH21-45 SS2	Nov 22/21	AM	1	S							X							
BH21-45 SS9	Nov 22/21	AM	3	S					X									
		AM/PM																
		AM/PM																
		AM/PM																
		AM/PM																
		AM/PM																
		AM/PM																
		AM/PM																
		AM/PM																

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Marsad Jafar M.J.	Dec 07/21	3:30 pm			
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

Page ____ of ____

№: T 128115

Document ID: DW 78 1511 021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Marsad Jafar
PROJECT: 211-10139-00 200 02
AGAT WORK ORDER: 21T841270
TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor
WATER ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer
DATE REPORTED: Dec 21, 2021
PAGES (INCLUDING COVER): 18
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PAHs (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-06
Parameter	Unit	G / S	RDL	3310367
Naphthalene	µg/L	7	0.20	<0.20
Acenaphthylene	µg/L	1	0.20	<0.20
Acenaphthene	µg/L	4.1	0.20	<0.20
Fluorene	µg/L	120	0.20	<0.20
Phenanthrene	µg/L	0.1	0.10	<0.10
Anthracene	µg/L	0.1	0.10	<0.10
Fluoranthene	µg/L	0.4	0.20	<0.20
Pyrene	µg/L	0.2	0.20	<0.20
Benzo(a)anthracene	µg/L	0.2	0.20	<0.20
Chrysene	µg/L	0.1	0.10	<0.10
Benzo(b)fluoranthene	µg/L	0.1	0.10	<0.10
Benzo(k)fluoranthene	µg/L	0.1	0.10	<0.10
Benzo(a)pyrene	µg/L	0.01	0.01	<0.01
Indeno(1,2,3-cd)pyrene	µg/L	0.2	0.20	<0.20
Dibenz(a,h)anthracene	µg/L	0.2	0.20	<0.20
Benzo(g,h,i)perylene	µg/L	0.2	0.20	<0.20
2-and 1-methyl Naphthalene	µg/L	2	0.20	<0.20
Sediment				No
Surrogate	Unit	Acceptable Limits		
Naphthalene-d8	%	50-140		120
Acridine-d9	%	50-140		98
Terphenyl-d14	%	50-140		85

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310367 Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&(j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-6	BH21-2	QAQC-2
		SAMPLE TYPE:		Water	Water	Water
		DATE SAMPLED:		2021-12-06	2021-12-07	2021-12-06
Parameter	Unit	G / S	RDL	3310483	3310484	3310486
Benzene	µg/L	0.5	0.20	<0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20	<0.20
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20	<0.20	<0.20
o-Xylene	µg/L		0.10	<0.10	<0.10	<0.10
Xylenes (Total)	µg/L	72	0.20	<0.20	<0.20	<0.20
F1 (C6 - C10)	µg/L	420	25	<25	<25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25	<25	<25
F2 (C10 to C16)	µg/L	150	100	<100	<100	<100
F3 (C16 to C34)	µg/L	500	100	<100	<100	<100
F4 (C34 to C50)	µg/L	500	100	<100	<100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA	NA	NA
Sediment				NO	NO	NO
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	60-140		79.5	78.2	123
Terphenyl	% Recovery	60-140		92	101	96

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21


Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310483-3310486 The C6-C10 fraction is calculated using Toluene response factor.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and nC34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16 - C50 and are only determined if the chromatogram of the C34 - C50 Hydrocarbons indicated that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6-C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153/04, results are considered valid without determining the PAH contribution if not requested by the client.
NA = Not Applicable

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-06
Parameter	Unit	G / S	RDL	3310367
F1 (C6-C10)	µg/L	420	25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25
F2 (C10 to C16)	µg/L	150	100	<100
F2 (C10 to C16) minus Naphthalene	µg/L		100	<100
F3 (C16 to C34)	µg/L	500	100	<100
F3 (C16 to C34) minus PAHs	µg/L		100	<100
F4 (C34 to C50)	µg/L	500	100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA
Sediment				NO
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		74.5
Terphenyl	% Recovery	60-140		84

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310367 The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar


O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16	QAQC-1	Trip Blank
		SAMPLE TYPE:		Water	Water	Water
		DATE SAMPLED:		2021-12-06	2021-12-06	2021-12-04
Parameter	Unit	G / S	RDL	3310367	3310485	3310488
Dichlorodifluoromethane	µg/L	590	0.20	<0.20	<0.20	<0.20
Vinyl Chloride	µg/L	0.5	0.17	<0.17	<0.17	<0.17
Bromomethane	µg/L	0.89	0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	µg/L	150	0.40	<0.40	<0.40	<0.40
Acetone	µg/L	2700	1.0	<1.0	<1.0	<1.0
1,1-Dichloroethylene	µg/L	0.5	0.30	<0.30	<0.30	<0.30
Methylene Chloride	µg/L	5	0.30	<0.30	<0.30	<0.30
trans- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20	<0.20
Methyl tert-butyl ether	µg/L	15	0.20	<0.20	<0.20	<0.20
1,1-Dichloroethane	µg/L	0.5	0.30	<0.30	<0.30	<0.30
Methyl Ethyl Ketone	µg/L	400	1.0	<1.0	<1.0	<1.0
cis- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20	<0.20
Chloroform	µg/L	2	0.20	<0.20	<0.20	<0.20
1,2-Dichloroethane	µg/L	0.5	0.20	<0.20	<0.20	<0.20
1,1,1-Trichloroethane	µg/L	0.5	0.30	<0.30	<0.30	<0.30
Carbon Tetrachloride	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Benzene	µg/L	0.5	0.20	<0.20	<0.20	<0.20
1,2-Dichloropropane	µg/L	0.5	0.20	<0.20	<0.20	<0.20
Trichloroethylene	µg/L	0.5	0.20	<0.20	<0.20	<0.20
Bromodichloromethane	µg/L	2	0.20	<0.20	<0.20	<0.20
Methyl Isobutyl Ketone	µg/L	640	1.0	<1.0	<1.0	<1.0
1,1,2-Trichloroethane	µg/L	0.5	0.20	<0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20	<0.20
Dibromochloromethane	µg/L	2	0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	µg/L	0.2	0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	µg/L	0.5	0.20	<0.20	<0.20	<0.20
1,1,1,2-Tetrachloroethane	µg/L	1.1	0.10	<0.10	<0.10	<0.10
Chlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20	<0.20	<0.20

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16	QAQC-1	Trip Blank
		SAMPLE TYPE:		Water	Water	Water
		DATE SAMPLED:		2021-12-06	2021-12-06	2021-12-04
Parameter	Unit	G / S	RDL	3310367	3310485	3310488
Bromoform	µg/L	5	0.10	<0.10	<0.10	<0.10
Styrene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
1,1,2,2-Tetrachloroethane	µg/L	0.5	0.10	<0.10	<0.10	<0.10
o-Xylene	µg/L		0.10	<0.10	<0.10	<0.10
1,3-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
1,4-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
1,2-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
1,3-Dichloropropene	µg/L	0.5	0.30	<0.30	<0.30	<0.30
Xylenes (Total)	µg/L	72	0.20	<0.20	<0.20	<0.20
n-Hexane	µg/L	5	0.20	<0.20	<0.20	<0.20
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140		88	107	82
4-Bromofluorobenzene	% Recovery	50-140		79	73	82

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310367-3310488 Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar


O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16		BH21-6
		SAMPLE TYPE:		Water		Water
		DATE SAMPLED:		2021-12-06		2021-12-06
Parameter	Unit	G / S	RDL	3310367	RDL	3310483
Dissolved Antimony	µg/L	1.5	1.0	1.1	1.0	<1.0
Dissolved Arsenic	µg/L	13	1.0	<1.0	1.0	4.7
Dissolved Barium	µg/L	610	2.0	63.9	2.0	271
Dissolved Beryllium	µg/L	0.5	0.50	<0.50	0.50	<0.50
Dissolved Boron	µg/L	1700	100.0	1676	10.0	279
Dissolved Cadmium	µg/L	0.5	0.20	<0.20	0.20	<0.20
Dissolved Chromium	µg/L	11	2.0	<2.0	2.0	25.3
Dissolved Cobalt	µg/L	3.8	0.50	<0.50	0.50	4.53
Dissolved Copper	µg/L	5	1.0	<1.0	1.0	2.7
Dissolved Lead	µg/L	1.9	0.50	<0.50	0.50	0.93
Dissolved Molybdenum	µg/L	23	0.50	24.7	0.50	6.45
Dissolved Nickel	µg/L	14	1.0	1.1	1.0	6.9
Dissolved Selenium	µg/L	5	1.0	1.6	1.0	<1.0
Dissolved Silver	µg/L	0.3	0.20	<0.20	0.20	<0.20
Dissolved Thallium	µg/L	0.5	0.30	<0.30	0.30	<0.30
Dissolved Uranium	µg/L	8.9	0.50	1.86	0.50	3.52
Dissolved Vanadium	µg/L	3.9	0.40	0.62	0.40	3.29
Dissolved Zinc	µg/L	160	5.0	<5.0	5.0	6.1
Mercury	µg/L	0.1	0.02	<0.02	0.02	<0.02
Chromium VI	µg/L	25	2	<2	2	5.43
Cyanide, Free	µg/L	5	2	<2	2	<2
Dissolved Sodium	µg/L	490000	250	210000	1000	342000
Chloride	µg/L	790000	100	286000	122	1460000
Electrical Conductivity	uS/cm	NA	2	1570	2	4940
pH	pH Units		NA	7.68	NA	7.72

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310367-3310483 Metals analysis completed on a filtered sample.

Dilution required, RDL has been increased accordingly.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3310367	BH21-16	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Dissolved Molybdenum	µg/L	23	24.7
3310483	BH21-6	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Chloride	µg/L	790000	1460000
3310483	BH21-6	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Dissolved Chromium	µg/L	11	25.3
3310483	BH21-6	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Dissolved Cobalt	µg/L	3.8	4.53

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841270
ATTENTION TO: Marsad Jafar
SAMPLED BY:Marsad Jafar

Trace Organics Analysis

RPT Date: Dec 21, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)															
F1 (C6-C10)	3296537		<25	<25	NA	< 25	108%	60%	140%	98%	60%	140%	109%	60%	140%
F2 (C10 to C16)	3304778		< 100	< 100	NA	< 100	102%	60%	140%	85%	60%	140%	78%	60%	140%
F3 (C16 to C34)	3304778		< 100	< 100	NA	< 100	110%	60%	140%	75%	60%	140%	75%	60%	140%
F4 (C34 to C50)	3304778		< 100	< 100	NA	< 100	115%	60%	140%	76%	60%	140%	74%	60%	140%
O. Reg. 153(511) - PAHs (Water)															
Naphthalene	3227991		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	78%	50%	140%	77%	50%	140%
Acenaphthylene	3227991		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	82%	50%	140%	107%	50%	140%
Acenaphthene	3227991		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	71%	50%	140%	81%	50%	140%
Fluorene	3227991		< 0.20	< 0.20	NA	< 0.20	86%	50%	140%	92%	50%	140%	92%	50%	140%
Phenanthrene	3227991		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	88%	50%	140%	85%	50%	140%
Anthracene	3227991		< 0.10	< 0.10	NA	< 0.10	85%	50%	140%	93%	50%	140%	78%	50%	140%
Fluoranthene	3227991		< 0.20	< 0.20	NA	< 0.20	99%	50%	140%	96%	50%	140%	93%	50%	140%
Pyrene	3227991		< 0.20	< 0.20	NA	< 0.20	78%	50%	140%	96%	50%	140%	99%	50%	140%
Benzo(a)anthracene	3227991		< 0.20	< 0.20	NA	< 0.20	96%	50%	140%	94%	50%	140%	96%	50%	140%
Chrysene	3227991		< 0.10	< 0.10	NA	< 0.10	86%	50%	140%	114%	50%	140%	84%	50%	140%
Benzo(b)fluoranthene	3227991		< 0.10	< 0.10	NA	< 0.10	92%	50%	140%	76%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3227991		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	92%	50%	140%	78%	50%	140%
Benzo(a)pyrene	3227991		< 0.01	< 0.01	NA	< 0.01	78%	50%	140%	105%	50%	140%	101%	50%	140%
Indeno(1,2,3-cd)pyrene	3227991		< 0.20	< 0.20	NA	< 0.20	92%	50%	140%	108%	50%	140%	105%	50%	140%
Dibenz(a,h)anthracene	3227991		< 0.20	< 0.20	NA	< 0.20	95%	50%	140%	75%	50%	140%	72%	50%	140%
Benzo(g,h,i)perylene	3227991		< 0.20	< 0.20	NA	< 0.20	91%	50%	140%	85%	50%	140%	105%	50%	140%
O. Reg. 153(511) - VOCs (Water)															
Dichlorodifluoromethane	3315412		<0.20	<0.20	NA	< 0.20	89%	50%	140%	103%	50%	140%	74%	50%	140%
Vinyl Chloride	3315412		<0.17	<0.17	NA	< 0.17	106%	50%	140%	83%	50%	140%	105%	50%	140%
Bromomethane	3315412		<0.20	<0.20	NA	< 0.20	96%	50%	140%	86%	50%	140%	95%	50%	140%
Trichlorofluoromethane	3315412		<0.40	<0.40	NA	< 0.40	107%	50%	140%	94%	50%	140%	94%	50%	140%
Acetone	3315412		<1.0	<1.0	NA	< 1.0	104%	50%	140%	102%	50%	140%	102%	50%	140%
1,1-Dichloroethylene	3315412		<0.30	<0.30	NA	< 0.30	93%	50%	140%	76%	60%	130%	107%	50%	140%
Methylene Chloride	3315412		<0.30	<0.30	NA	< 0.30	105%	50%	140%	89%	60%	130%	102%	50%	140%
trans- 1,2-Dichloroethylene	3315412		<0.20	<0.20	NA	< 0.20	88%	50%	140%	95%	60%	130%	70%	50%	140%
Methyl tert-butyl ether	3315412		<0.20	<0.20	NA	< 0.20	101%	50%	140%	97%	60%	130%	76%	50%	140%
1,1-Dichloroethane	3315412		<0.30	<0.30	NA	< 0.30	119%	50%	140%	96%	60%	130%	99%	50%	140%
Methyl Ethyl Ketone	3315412		<1.0	<1.0	NA	< 1.0	94%	50%	140%	99%	50%	140%	102%	50%	140%
cis- 1,2-Dichloroethylene	3315412		<0.20	<0.20	NA	< 0.20	106%	50%	140%	114%	60%	130%	80%	50%	140%
Chloroform	3315412		1.42	1.35	5.1%	< 0.20	98%	50%	140%	104%	60%	130%	62%	50%	140%
1,2-Dichloroethane	3315412		<0.20	<0.20	NA	< 0.20	111%	50%	140%	109%	60%	130%	95%	50%	140%
1,1,1-Trichloroethane	3315412		<0.30	<0.30	NA	< 0.30	79%	50%	140%	75%	60%	130%	71%	50%	140%
Carbon Tetrachloride	3315412		<0.20	<0.20	NA	< 0.20	116%	50%	140%	73%	60%	130%	77%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841270
ATTENTION TO: Marsad Jafar
SAMPLED BY:Marsad Jafar

Trace Organics Analysis (Continued)

RPT Date: Dec 21, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Benzene	3315412		<0.20	<0.20	NA	< 0.20	116%	50%	140%	102%	60%	130%	79%	50%	140%
1,2-Dichloropropane	3315412		<0.20	<0.20	NA	< 0.20	117%	50%	140%	82%	60%	130%	96%	50%	140%
Trichloroethylene	3315412		<0.20	<0.20	NA	< 0.20	111%	50%	140%	92%	60%	130%	73%	50%	140%
Bromodichloromethane	3315412		<0.20	<0.20	NA	< 0.20	113%	50%	140%	103%	60%	130%	87%	50%	140%
Methyl Isobutyl Ketone	3315412		<1.0	<1.0	NA	< 1.0	106%	50%	140%	98%	50%	140%	103%	50%	140%
1,1,2-Trichloroethane	3315412		<0.20	<0.20	NA	< 0.20	101%	50%	140%	119%	60%	130%	110%	50%	140%
Toluene	3315412		1.14	1.37	18.3%	< 0.20	97%	50%	140%	102%	60%	130%	76%	50%	140%
Dibromochloromethane	3315412		<0.10	<0.10	NA	< 0.10	97%	50%	140%	113%	60%	130%	111%	50%	140%
Ethylene Dibromide	3315412		<0.10	<0.10	NA	< 0.10	77%	50%	140%	118%	60%	130%	100%	50%	140%
Tetrachloroethylene	3315412		<0.20	<0.20	NA	< 0.20	109%	50%	140%	110%	60%	130%	81%	50%	140%
1,1,1,2-Tetrachloroethane	3315412		<0.10	<0.10	NA	< 0.10	95%	50%	140%	116%	60%	130%	71%	50%	140%
Chlorobenzene	3315412		<0.10	<0.10	NA	< 0.10	106%	50%	140%	116%	60%	130%	87%	50%	140%
Ethylbenzene	3315412		<0.10	<0.10	NA	< 0.10	119%	50%	140%	72%	60%	130%	74%	50%	140%
m & p-Xylene	3315412		<0.20	<0.20	NA	< 0.20	100%	50%	140%	96%	60%	130%	105%	50%	140%
Bromoform	3315412		<0.10	<0.10	NA	< 0.10	93%	50%	140%	105%	60%	130%	96%	50%	140%
Styrene	3315412		<0.10	<0.10	NA	< 0.10	96%	50%	140%	74%	60%	130%	73%	50%	140%
1,1,2,2-Tetrachloroethane	3315412		<0.10	<0.10	NA	< 0.10	104%	50%	140%	106%	60%	130%	87%	50%	140%
o-Xylene	3315412		<0.10	<0.10	NA	< 0.10	84%	50%	140%	102%	60%	130%	81%	50%	140%
1,3-Dichlorobenzene	3315412		<0.10	<0.10	NA	< 0.10	100%	50%	140%	89%	60%	130%	113%	50%	140%
1,4-Dichlorobenzene	3315412		<0.10	<0.10	NA	< 0.10	106%	50%	140%	100%	60%	130%	114%	50%	140%
1,2-Dichlorobenzene	3315412		<0.10	<0.10	NA	< 0.10	109%	50%	140%	103%	60%	130%	103%	50%	140%
n-Hexane	3315412		<0.20	<0.20	NA	< 0.20	94%	50%	140%	94%	60%	130%	76%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (Water)															
Benzene	3296537		<0.20	<0.20	NA	< 0.20	96%	60%	140%	89%	60%	140%	106%	60%	140%
Toluene	3296537		<0.20	<0.20	NA	< 0.20	82%	60%	140%	85%	60%	140%	86%	60%	140%
Ethylbenzene	3296537		<0.10	<0.10	NA	< 0.10	87%	60%	140%	96%	60%	140%	94%	60%	140%
m & p-Xylene	3296537		<0.20	<0.20	NA	< 0.20	99%	60%	140%	80%	60%	140%	94%	60%	140%
o-Xylene	3296537		<0.10	<0.10	NA	< 0.10	90%	60%	140%	104%	60%	140%	80%	60%	140%
F1 (C6 - C10)	3296537		<25	<25	NA	< 25	108%	60%	140%	98%	60%	140%	109%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841270
ATTENTION TO: Marsad Jafar
SAMPLED BY:Marsad Jafar

Water Analysis

RPT Date: Dec 21, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Water)															
Dissolved Antimony	3308730		<1.0	<1.0	NA	< 1.0	99%	70%	130%	101%	80%	120%	109%	70%	130%
Dissolved Arsenic	3308730		<1.0	2.6	NA	< 1.0	94%	70%	130%	103%	80%	120%	115%	70%	130%
Dissolved Barium	3308730		107	90.7	16.5%	< 2.0	102%	70%	130%	100%	80%	120%	108%	70%	130%
Dissolved Beryllium	3308730		<0.50	<0.50	NA	< 0.50	103%	70%	130%	107%	80%	120%	113%	70%	130%
Dissolved Boron	3308730		114	107	6.3%	< 10.0	101%	70%	130%	105%	80%	120%	110%	70%	130%
Dissolved Cadmium	3308730		<0.20	<0.20	NA	< 0.20	99%	70%	130%	100%	80%	120%	113%	70%	130%
Dissolved Chromium	3308730		<2.0	<2.0	NA	< 2.0	102%	70%	130%	100%	80%	120%	102%	70%	130%
Dissolved Cobalt	3308730		<0.50	<0.50	NA	< 0.50	96%	70%	130%	106%	80%	120%	107%	70%	130%
Dissolved Copper	3308730		<1.0	<1.0	NA	< 1.0	100%	70%	130%	105%	80%	120%	106%	70%	130%
Dissolved Lead	3308730		<0.50	<0.50	NA	< 0.50	99%	70%	130%	100%	80%	120%	107%	70%	130%
Dissolved Molybdenum	3308730		1.32	1.62	NA	< 0.50	99%	70%	130%	104%	80%	120%	113%	70%	130%
Dissolved Nickel	3308730		1.9	1.9	NA	< 1.0	98%	70%	130%	106%	80%	120%	108%	70%	130%
Dissolved Selenium	3308730		<1.0	<1.0	NA	< 1.0	99%	70%	130%	105%	80%	120%	119%	70%	130%
Dissolved Silver	3308730		<0.20	<0.20	NA	< 0.20	97%	70%	130%	106%	80%	120%	100%	70%	130%
Dissolved Thallium	3308730		<0.30	<0.30	NA	< 0.30	98%	70%	130%	99%	80%	120%	105%	70%	130%
Dissolved Uranium	3308730		<0.50	<0.50	NA	< 0.50	101%	70%	130%	108%	80%	120%	121%	70%	130%
Dissolved Vanadium	3308730		1.15	0.82	NA	< 0.40	97%	70%	130%	103%	80%	120%	103%	70%	130%
Dissolved Zinc	3308730		<5.0	<5.0	NA	< 5.0	100%	70%	130%	99%	80%	120%	111%	70%	130%
Mercury	3295856		<0.02	<0.02	NA	< 0.02	101%	70%	130%	96%	80%	120%	99%	70%	130%
Chromium VI	3315551		<2	2.02	NA	< 2	101%	70%	130%	105%	80%	120%	98%	70%	130%
Cyanide, Free	3319579		<2	<2	NA	< 2	104%	70%	130%	101%	80%	120%	109%	70%	130%
Dissolved Sodium	3293826		6250	6210	0.6%	< 50	95%	70%	130%	97%	80%	120%	99%	70%	130%
Chloride	3295003		551000	551000	0.0%	< 100	94%	70%	130%	103%	80%	120%	NA	70%	130%
Electrical Conductivity	3306912		1350	1340	0.7%	< 2	104%	90%	110%						
pH	3306912		7.78	7.78	0.0%	NA	102%	90%	110%						

Comments: NA signifies Not Applicable.
Duplicate NA: results are under 5X the RDL and will not be calculated.

Matrix spike NA: Spike level < native concentration. Matrix spike acceptance limits do not apply and are not calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluorene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Chrysene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
2-and 1-methyl Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Sediment			
Benzene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Toluene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Ethylbenzene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
m & p-Xylene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
o-Xylene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Xylenes (Total)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F1 (C6 - C10)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
Toluene-d8	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC-E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F1 (C6-C10)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
Toluene-d8	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F2 (C10 to C16) minus Naphthalene	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Dichlorodifluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromomethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
trans- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl tert-butyl ether	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
cis- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Dibromochloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromoform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Water Analysis			
Dissolved Antimony	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Arsenic	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Barium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Beryllium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Boron	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cadmium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Chromium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cobalt	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Copper	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Lead	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Molybdenum	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Nickel	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Selenium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Silver	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Thallium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Uranium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Vanadium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Zinc	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Mercury	MET-93-6100	modified from EPA 245.2 and SM 3112 B	CVAAS
Chromium VI	INOR-93-6034	modified from SM 3500-CR B	LACHAT FIA
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Dissolved Sodium	MET-93-6105	modified from EPA 6010D	ICP/OES
Chloride	INOR-93-6004	modified from SM 4110 B	ION CHROMATOGRAPH
Electrical Conductivity	INOR-93-6000	SM 2510 B	PC TITRATE
pH	INOR-93-6000	modified from SM 4500-H+ B	PC TITRATE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP
Contact: Marsad Jafar
Address: 2 International Blvd, Toronto ON
Phone: 437-233-2935 Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: marsad.jafar@wsp.com

Project Information:

Project: 211-10139-00 PH 200 02
Site Location: ORBY
Sampled By: Marsad Jafar
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☑ Ind/Com
☑ Res/Park
☐ Agriculture
Soil Texture (Check One)
☐ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use
☐ Sanitary ☐ Storm
Region
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
Indicate One

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Laboratory Use Only

Work Order #: 21T841270
Cooler Quantity: 1 Blk Chagged ice
Arrival Temperatures: 1.9 | 2.9 | 2.0
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes:

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply):
Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*
For 'Same Day' analysis, please contact your AGAT CPM

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-16	Dec 06/21	AM PM	16	GW		Y	X		X	X		X					
BH21-6	Dec 06/21	AM PM	11	GW		Y	X		X								
BH21-2	Dec 07/21	AM PM	5	GW		Y			X								
		AM PM															
QAQC-1	Dec 06/21	AM PM	3	GW		Y						X					
QAQC-2	Dec 06/21	AM PM	3.5	GW		Y			X								
		AM PM	4														
Trip Blank	-	AM PM	3	GW		-						X					
		AM PM															
		AM PM															
		AM PM															

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Marsad Jafar	Dec 07/21		Neil Ramnarain		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 DEC 7 0008

Page ____ of ____

Nº: T 128116

Document ID: DIV 78 1511 021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Marsad Jafar
PROJECT: 211-10139-00 Phase 200 02
AGAT WORK ORDER: 21T843989
TRACE ORGANICS REVIEWED BY: Inga Kuzmina, Trace Organics Lab Manager
DATE REPORTED: Dec 15, 2021
PAGES (INCLUDING COVER): 5
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T843989

PROJECT: 211-10139-00 Phase 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F2 - F4 (Water)

DATE RECEIVED: 2021-12-13

DATE REPORTED: 2021-12-15

				SAMPLE DESCRIPTION:	BH21-30
				SAMPLE TYPE:	Water
				DATE SAMPLED:	2021-12-13
Parameter	Unit	G / S	RDL		3337872
F2 (C10 to C16)	µg/L	150	100		<100
F3 (C16 to C34)	µg/L	500	100		<100
F4 (C34 to C50)	µg/L	500	100		<100
Gravimetric Heavy Hydrocarbons	µg/L		500		NA
Sediment					No
Surrogate	Unit	Acceptable Limits			
Terphenyl	%	60-140			111

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3337872 The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and nC34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16 - C50 and are only determined if the chromatogram of the C34 - C50 Hydrocarbons indicated that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 2-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T843989

PROJECT: 211-10139-00 Phase 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F2 - F4 (Water)															
F2 (C10 to C16)	3285019		< 100	< 100	NA	< 100	102%	60%	140%	85%	60%	140%	95%	60%	140%
F3 (C16 to C34)	3285019		< 100	< 100	NA	< 100	106%	60%	140%	76%	60%	140%	86%	60%	140%
F4 (C34 to C50)	3285019		< 100	< 100	NA	< 100	85%	60%	140%	74%	60%	140%	87%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T843989

PROJECT: 211-10139-00 Phase 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC E3421	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC E3421	GC/FID
Sediment			

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP
Contact: Marsad Jafar
Address: 2 International Blvd
Phone: 437-233-2935 Fax:
Reports to be sent to:
1. Email: marsad.jafar@wsp.com
2. Email: vanessa.etinger@wsp.com

Project Information:

Project: 211-10139-00 Phase 200 02
Site Location: ORBY
Sampled By: Marsad Jafar
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☐ Ind/Com
☑ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use
☐ Sanitary ☐ Storm
____ (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition**? ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Laboratory Use Only

Work Order #: 21T843989
Cooler Quantity: 1 blue
Arrival Temperatures: 6.6 | 6.5
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: Free Jaf

Turnaround Time (TAT) Required:

Regular TAT ☐ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☑ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	BTEX, F1-F4 PHCs - Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558: Landfill Disposa Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-30	Dec 13/21	AM	2	GW	F1-F4 PHCs only				X								
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															
		AM/PM															

21 DEC 13 5:37 PM

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Marsad Jafar	12/13/2021	5:25 pm	NEAL G		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

Page 1 of 1

Nº: T 126742

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vaness Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T834096
TRACE ORGANICS REVIEWED BY: Inga Kuzmina, Trace Organics Lab Manager
WATER ANALYSIS REVIEWED BY: Amanjot Bhela, Inorganic Lab Manager
DATE REPORTED: Dec 03, 2021
PAGES (INCLUDING COVER): 22
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - OC Pesticides + PCBs (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03

				SAMPLE DESCRIPTION:	BH21-12	BH21-44
				SAMPLE TYPE:	Water	Water
				DATE SAMPLED:	2021-11-23 09:00	2021-11-23 10:00
Parameter	Unit	G / S	RDL		3246761	3246768
Gamma-Hexachlorocyclohexane	ug/L	0.01	0.01		<0.01	<0.01
Heptachlor	ug/L	0.01	0.01		<0.01	<0.01
Aldrin	ug/L	0.01	0.01		<0.01	<0.01
Heptachlor Epoxide	ug/L	0.01	0.01		<0.01	<0.01
Endosulfan I	µg/L		0.05		<0.05	<0.05
Endosulfan II	µg/L		0.05		<0.05	<0.05
Endosulfan	ug/L	0.05	0.05		<0.05	<0.05
alpha - chlordane	µg/L		0.1		<0.1	<0.1
gamma-Chlordane	µg/L		0.2		<0.2	<0.2
Chlordane	ug/L	0.06	0.04		<0.04	<0.04
op'-DDE	µg/L		0.01		<0.01	<0.01
pp'-DDE	µg/L		0.01		<0.01	<0.01
DDE	ug/L		0.01		<0.01	<0.01
op'-DDD	µg/L		0.05		<0.05	<0.05
pp'-DDD	µg/L		0.05		<0.05	<0.05
DDD	ug/L	1.8	0.05		<0.05	<0.05
op'-DDT	µg/L		0.04		<0.04	<0.04
pp'-DDT	µg/L		0.05		<0.05	<0.05
DDT	ug/L		0.04		<0.04	<0.04
Dieldrin	ug/L	0.05	0.02		<0.02	<0.02
Endrin	ug/L	0.05	0.05		<0.05	<0.05
Methoxychlor	ug/L	0.05	0.04		<0.04	<0.04
Hexachlorobenzene	ug/L	0.01	0.01		<0.01	<0.01
Hexachlorobutadiene	ug/L	0.01	0.01		<0.01	<0.01
Hexachloroethane	ug/L	0.01	0.01		<0.01	<0.01
Aroclor 1242	ug/L		0.1		<0.1	<0.1
Aroclor 1248	ug/L		0.1		<0.1	<0.1
Aroclor 1254	ug/L		0.1		<0.1	<0.1
Aroclor 1260	ug/L		0.1		<0.1	<0.1

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - OC Pesticides + PCBs (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03

				SAMPLE DESCRIPTION:	BH21-12	BH21-44
				SAMPLE TYPE:	Water	Water
				DATE SAMPLED:	2021-11-23 09:00	2021-11-23 10:00
Parameter	Unit	G / S	RDL		3246761	3246768
Polychlorinated Biphenyls	ug/L	0.2	0.1		<0.1	<0.1
Surrogate	Unit	Acceptable Limits				
TCMX	%	50-140			80	104
Decachlorobiphenyl	%	50-140			98	112

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3246761-3246768 DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PAHs (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03

				SAMPLE DESCRIPTION:	BH21-12	BH21-44	BH21-36
				SAMPLE TYPE:	Water	Water	Water
				DATE SAMPLED:	2021-11-23 09:00	2021-11-23 10:00	2021-11-23 13:00
Parameter	Unit	G / S	RDL		3246761	3246768	3246774
Naphthalene	µg/L	7	0.20		<0.20	<0.20	<0.20
Acenaphthylene	µg/L	1	0.20		<0.20	<0.20	<0.20
Acenaphthene	µg/L	4.1	0.20		<0.20	<0.20	<0.20
Fluorene	µg/L	120	0.20		<0.20	<0.20	<0.20
Phenanthrene	µg/L	0.1	0.10		<0.10	<0.10	<0.10
Anthracene	µg/L	0.1	0.10		<0.10	<0.10	<0.10
Fluoranthene	µg/L	0.4	0.20		<0.20	<0.20	<0.20
Pyrene	µg/L	0.2	0.20		<0.20	<0.20	<0.20
Benzo(a)anthracene	µg/L	0.2	0.20		<0.20	<0.20	<0.20
Chrysene	µg/L	0.1	0.10		<0.10	<0.10	<0.10
Benzo(b)fluoranthene	µg/L	0.1	0.10		<0.10	<0.10	<0.10
Benzo(k)fluoranthene	µg/L	0.1	0.10		<0.10	<0.10	<0.10
Benzo(a)pyrene	µg/L	0.01	0.01		<0.01	<0.01	<0.01
Indeno(1,2,3-cd)pyrene	µg/L	0.2	0.20		<0.20	<0.20	<0.20
Dibenz(a,h)anthracene	µg/L	0.2	0.20		<0.20	<0.20	<0.20
Benzo(g,h,i)perylene	µg/L	0.2	0.20		<0.20	<0.20	<0.20
2-and 1-methyl Naphthalene	µg/L	2	0.20		<0.20	<0.20	<0.20
Sediment					No	No	No
Surrogate	Unit	Acceptable Limits					
Naphthalene-d8	%	50-140			78	102	82
Acridine-d9	%	50-140			96	83	94
Terphenyl-d14	%	50-140			95	92	78

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3246761-3246774 Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&(j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03

				SAMPLE DESCRIPTION:	BH21-36
				SAMPLE TYPE:	Water
				DATE SAMPLED:	2021-11-23 13:00
Parameter	Unit	G / S	RDL		3246774
F1 (C6-C10)	µg/L	420	25		<25
F1 (C6 to C10) minus BTEX	µg/L	420	25		<25
F2 (C10 to C16)	µg/L	150	100		<100
F2 (C10 to C16) minus Naphthalene	µg/L		100		<100
F3 (C16 to C34)	µg/L	500	100		<100
F3 (C16 to C34) minus PAHs	µg/L		100		<100
F4 (C34 to C50)	µg/L	500	100		<100
Gravimetric Heavy Hydrocarbons	µg/L		500		NA
Sediment					No
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	50-140			82.8
Terphenyl	% Recovery	60-140			90

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3246774 The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03

				SAMPLE DESCRIPTION:	BH21-12	BH21-44
				SAMPLE TYPE:	Water	Water
				DATE SAMPLED:	2021-11-23 09:00	2021-11-23 10:00
Parameter	Unit	G / S	RDL		3246761	3246768
Benzene	µg/L	0.5	0.20		<0.20	<0.20
Toluene	µg/L	0.8	0.20		<0.20	0.41
Ethylbenzene	µg/L	0.5	0.10		<0.10	<0.10
m & p-Xylene	µg/L		0.20		<0.20	<0.20
o-Xylene	µg/L		0.10		<0.10	<0.10
Xylenes (Total)	µg/L	72	0.20		<0.20	<0.20
F1 (C6-C10)	µg/L	420	25		<25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25		<25	<25
F2 (C10 to C16)	µg/L	150	100		<100	<100
F2 (C10 to C16) minus Naphthalene	µg/L		100		<100	<100
F3 (C16 to C34)	µg/L	500	100		<100	<100
F3 (C16 to C34) minus PAHs	µg/L		100		<100	<100
F4 (C34 to C50)	µg/L	500	100		<100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500		NA	NA
Sediment					No	No
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	60-140			85.0	81.2
Terphenyl	% Recovery	60-140			87	94

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03


Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3246761-3246768 The C6-C10 fraction is calculated using toluene response factor.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-36	Trip Blank
		SAMPLE TYPE:		Water	Water
		DATE SAMPLED:		2021-11-23 13:00	2021-11-23 13:00
Parameter	Unit	G / S	RDL	3246774	3246787
Dichlorodifluoromethane	µg/L	590	0.20	<0.20	<0.20
Vinyl Chloride	µg/L	0.5	0.17	<0.17	<0.17
Bromomethane	µg/L	0.89	0.20	<0.20	<0.20
Trichlorofluoromethane	µg/L	150	0.40	<0.40	<0.40
Acetone	µg/L	2700	1.0	<1.0	<1.0
1,1-Dichloroethylene	µg/L	0.5	0.30	<0.30	<0.30
Methylene Chloride	µg/L	5	0.30	<0.30	<0.30
trans- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20
Methyl tert-butyl ether	µg/L	15	0.20	<0.20	<0.20
1,1-Dichloroethane	µg/L	0.5	0.30	<0.30	<0.30
Methyl Ethyl Ketone	µg/L	400	1.0	<1.0	<1.0
cis- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20
Chloroform	µg/L	2	0.20	<0.20	<0.20
1,2-Dichloroethane	µg/L	0.5	0.20	<0.20	<0.20
1,1,1-Trichloroethane	µg/L	0.5	0.30	<0.30	<0.30
Carbon Tetrachloride	µg/L	0.2	0.20	<0.20	<0.20
Benzene	µg/L	0.5	0.20	<0.20	<0.20
1,2-Dichloropropane	µg/L	0.5	0.20	<0.20	<0.20
Trichloroethylene	µg/L	0.5	0.20	<0.20	<0.20
Bromodichloromethane	µg/L	2	0.20	<0.20	<0.20
Methyl Isobutyl Ketone	µg/L	640	1.0	<1.0	<1.0
1,1,2-Trichloroethane	µg/L	0.5	0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20
Dibromochloromethane	µg/L	2	0.10	<0.10	<0.10
Ethylene Dibromide	µg/L	0.2	0.10	<0.10	<0.10
Tetrachloroethylene	µg/L	0.5	0.20	<0.20	<0.20
1,1,1,2-Tetrachloroethane	µg/L	1.1	0.10	<0.10	<0.10
Chlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03


				SAMPLE DESCRIPTION:	BH21-36	Trip Blank
				SAMPLE TYPE:	Water	Water
				DATE SAMPLED:	2021-11-23 13:00	2021-11-23 13:00
Parameter	Unit	G / S	RDL		3246774	3246787
m & p-Xylene	µg/L		0.20		<0.20	<0.20
Bromoform	µg/L	5	0.10		<0.10	<0.10
Styrene	µg/L	0.5	0.10		<0.10	<0.10
1,1,2,2-Tetrachloroethane	µg/L	0.5	0.10		<0.10	<0.10
o-Xylene	µg/L		0.10		<0.10	<0.10
1,3-Dichlorobenzene	µg/L	0.5	0.10		<0.10	<0.10
1,4-Dichlorobenzene	µg/L	0.5	0.10		<0.10	<0.10
1,2-Dichlorobenzene	µg/L	0.5	0.10		<0.10	<0.10
1,3-Dichloropropene	µg/L	0.5	0.30		<0.30	<0.30
Xylenes (Total)	µg/L	72	0.20		<0.20	<0.20
n-Hexane	µg/L	5	0.20		<0.20	<0.20
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140			95	95
4-Bromofluorobenzene	% Recovery	50-140			102	99

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3246774-3246787 Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03

		SAMPLE DESCRIPTION:		BH21-12		BH21-44	BH21-36
		SAMPLE TYPE:		Water		Water	Water
		DATE SAMPLED:		2021-11-23 09:00		2021-11-23 10:00	2021-11-23 13:00
Parameter	Unit	G / S	RDL	3246761	RDL	3246768	3246774
Dissolved Antimony	µg/L	1.5	1.0	<1.0	1.0	<1.0	<1.0
Dissolved Arsenic	µg/L	13	1.0	7.8	1.0	2.0	<1.0
Dissolved Barium	µg/L	610	2.0	119	2.0	101	188
Dissolved Beryllium	µg/L	0.5	0.50	<0.50	0.50	<0.50	<0.50
Dissolved Boron	µg/L	1700	10.0	221	10.0	37.7	115
Dissolved Cadmium	µg/L	0.5	0.20	<0.20	0.20	<0.20	<0.20
Dissolved Chromium	µg/L	11	2.0	<2.0	2.0	<2.0	<2.0
Dissolved Cobalt	µg/L	3.8	0.50	<0.50	0.50	0.67	<0.50
Dissolved Copper	µg/L	5	1.0	1.7	1.0	<1.0	1.5
Dissolved Lead	µg/L	1.9	0.50	<0.50	0.50	<0.50	<0.50
Dissolved Molybdenum	µg/L	23	0.50	5.87	0.50	0.60	0.80
Dissolved Nickel	µg/L	14	1.0	1.9	1.0	<1.0	<1.0
Dissolved Selenium	µg/L	5	1.0	1.6	1.0	2.0	3.3
Dissolved Silver	µg/L	0.3	0.20	<0.20	0.20	<0.20	<0.20
Dissolved Thallium	µg/L	0.5	0.30	<0.30	0.30	<0.30	<0.30
Dissolved Uranium	µg/L	8.9	0.50	1.74	0.50	1.32	1.65
Dissolved Vanadium	µg/L	3.9	0.40	0.78	0.40	<0.40	1.01
Dissolved Zinc	µg/L	160	5.0	<5.0	5.0	<5.0	<5.0
Mercury	µg/L	0.1	0.02	<0.02	0.02	<0.02	<0.02
Chromium VI	µg/L	25	2.000	<2.000	2.000	<2.000	<2.000
Cyanide, Free	µg/L	5	2	<2	2	<2	<2
Dissolved Sodium	µg/L	490000	50	30100	100	8980	56000
Chloride	µg/L	790000	100	7260	100	7770	4740
Electrical Conductivity	uS/cm	NA	2	535	2	974	1000
pH	pH Units		NA	7.89	NA	7.60	7.65

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-11-23

DATE REPORTED: 2021-12-03

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3246761 Metals analysis completed on a filtered sample.

3246768-3246774 Metals analysis completed on a filtered sample.
Dilution required, RDL has been increased accordingly.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T834096
ATTENTION TO: Vaness Oetinger
SAMPLED BY:Marsad Jafar

Trace Organics Analysis

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Water)															
Naphthalene	3227991		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	78%	50%	140%	77%	50%	140%
Acenaphthylene	3227991		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	82%	50%	140%	107%	50%	140%
Acenaphthene	3227991		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	71%	50%	140%	81%	50%	140%
Fluorene	3227991		< 0.20	< 0.20	NA	< 0.20	86%	50%	140%	92%	50%	140%	92%	50%	140%
Phenanthrene	3227991		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	88%	50%	140%	85%	50%	140%
Anthracene	3227991		< 0.10	< 0.10	NA	< 0.10	85%	50%	140%	93%	50%	140%	78%	50%	140%
Fluoranthene	3227991		< 0.20	< 0.20	NA	< 0.20	99%	50%	140%	96%	50%	140%	93%	50%	140%
Pyrene	3227991		< 0.20	< 0.20	NA	< 0.20	78%	50%	140%	96%	50%	140%	99%	50%	140%
Benzo(a)anthracene	3227991		< 0.20	< 0.20	NA	< 0.20	96%	50%	140%	94%	50%	140%	96%	50%	140%
Chrysene	3227991		< 0.10	< 0.10	NA	< 0.10	86%	50%	140%	114%	50%	140%	84%	50%	140%
Benzo(b)fluoranthene	3227991		< 0.10	< 0.10	NA	< 0.10	92%	50%	140%	76%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3227991		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	92%	50%	140%	78%	50%	140%
Benzo(a)pyrene	3227991		< 0.01	< 0.01	NA	< 0.01	78%	50%	140%	105%	50%	140%	101%	50%	140%
Indeno(1,2,3-cd)pyrene	3227991		< 0.20	< 0.20	NA	< 0.20	92%	50%	140%	108%	50%	140%	105%	50%	140%
Dibenz(a,h)anthracene	3227991		< 0.20	< 0.20	NA	< 0.20	95%	50%	140%	75%	50%	140%	72%	50%	140%
Benzo(g,h,i)perylene	3227991		< 0.20	< 0.20	NA	< 0.20	91%	50%	140%	85%	50%	140%	105%	50%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Water)															
Gamma-Hexachlorocyclohexane	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	102%	50%	140%	103%	50%	140%	78%	50%	140%
Heptachlor	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	109%	50%	140%	107%	50%	140%	88%	50%	140%
Aldrin	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	103%	50%	140%	93%	50%	140%	91%	50%	140%
Heptachlor Epoxide	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	104%	50%	140%	102%	50%	140%	81%	50%	140%
Endosulfan I	3246774	3246774	< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	103%	50%	140%	75%	50%	140%
Endosulfan II	3246774	3246774	< 0.05	< 0.05	NA	< 0.05	94%	50%	140%	100%	50%	140%	79%	50%	140%
alpha - chlordane	3246774	3246774	< 0.1	< 0.1	NA	< 0.1	90%	50%	140%	97%	50%	140%	89%	50%	140%
gamma-Chlordane	3246774	3246774	< 0.2	< 0.2	NA	< 0.2	96%	50%	140%	89%	50%	140%	105%	50%	140%
op'-DDE	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	106%	50%	140%	91%	50%	140%	83%	50%	140%
pp'-DDE	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	109%	50%	140%	93%	50%	140%	87%	50%	140%
op'-DDD	3246774	3246774	< 0.05	< 0.05	NA	< 0.05	112%	50%	140%	104%	50%	140%	102%	50%	140%
pp'-DDD	3246774	3246774	< 0.05	< 0.05	NA	< 0.05	114%	50%	140%	108%	50%	140%	94%	50%	140%
op'-DDT	3246774	3246774	< 0.04	< 0.04	NA	< 0.04	102%	50%	140%	88%	50%	140%	87%	50%	140%
pp'-DDT	3246774	3246774	< 0.05	< 0.05	NA	< 0.05	104%	50%	140%	85%	50%	140%	84%	50%	140%
Dieldrin	3246774	3246774	< 0.02	< 0.02	NA	< 0.02	112%	50%	140%	104%	50%	140%	80%	50%	140%
Endrin	3246774	3246774	< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	101%	50%	140%	79%	50%	140%
Methoxychlor	3246774	3246774	< 0.04	< 0.04	NA	< 0.04	106%	50%	140%		50%	140%	102%	50%	140%
Hexachlorobenzene	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	104%	50%	140%	94%	50%	140%	93%	50%	140%
Hexachlorobutadiene	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	94%	50%	140%	102%	50%	140%	82%	50%	140%
Hexachloroethane	3246774	3246774	< 0.01	< 0.01	NA	< 0.01	83%	50%	140%	99%	50%	140%	79%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Water)															

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T834096
ATTENTION TO: Vaness Oetinger
SAMPLED BY:Marsad Jafar

Trace Organics Analysis (Continued)

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Benzene	3249261		<0.20	<0.20	NA	< 0.20	110%	60%	140%	95%	60%	140%	78%	60%	140%
Toluene	3249261		<0.20	<0.20	NA	< 0.20	107%	60%	140%	94%	60%	140%	83%	60%	140%
Ethylbenzene	3249261		<0.10	<0.10	NA	< 0.10	107%	60%	140%	82%	60%	140%	85%	60%	140%
m & p-Xylene	3249261		<0.20	<0.20	NA	< 0.20	104%	60%	140%	101%	60%	140%	100%	60%	140%
o-Xylene	3249261		<0.10	<0.10	NA	< 0.10	102%	60%	140%	87%	60%	140%	104%	60%	140%
F1 (C6-C10)	3249261		<25	<25	NA	< 25	93%	60%	140%	106%	60%	140%	105%	60%	140%
F2 (C10 to C16)	3260916		< 100	< 100	NA	< 100	109%	60%	140%	63%	60%	140%	80%	60%	140%
F3 (C16 to C34)	3260916		< 100	< 100	NA	< 100	106%	60%	140%	61%	60%	140%	69%	60%	140%
F4 (C34 to C50)	3260916		< 100	< 100	NA	< 100	99%	60%	140%	107%	60%	140%	87%	60%	140%
O. Reg. 153(511) - VOCs (Water)															
Dichlorodifluoromethane	3251511		<0.20	<0.20	NA	< 0.20	101%	50%	140%	84%	50%	140%	96%	50%	140%
Vinyl Chloride	3251511		<0.17	<0.17	NA	< 0.17	84%	50%	140%	82%	50%	140%	99%	50%	140%
Bromomethane	3251511		<0.20	<0.20	NA	< 0.20	103%	50%	140%	80%	50%	140%	81%	50%	140%
Trichlorofluoromethane	3251511		<0.40	<0.40	NA	< 0.40	78%	50%	140%	85%	50%	140%	88%	50%	140%
Acetone	3251511		<1.0	<1.0	NA	< 1.0	102%	50%	140%	98%	50%	140%	99%	50%	140%
1,1-Dichloroethylene	3251511		<0.30	<0.30	NA	< 0.30	80%	50%	140%	117%	60%	130%	110%	50%	140%
Methylene Chloride	3251511		<0.30	<0.30	NA	< 0.30	95%	50%	140%	98%	60%	130%	110%	50%	140%
trans- 1,2-Dichloroethylene	3251511		<0.20	<0.20	NA	< 0.20	88%	50%	140%	83%	60%	130%	106%	50%	140%
Methyl tert-butyl ether	3251511		<0.20	<0.20	NA	< 0.20	102%	50%	140%	119%	60%	130%	94%	50%	140%
1,1-Dichloroethane	3251511		<0.30	<0.30	NA	< 0.30	96%	50%	140%	87%	60%	130%	90%	50%	140%
Methyl Ethyl Ketone	3251511		<1.0	<1.0	NA	< 1.0	99%	50%	140%	103%	50%	140%	103%	50%	140%
cis- 1,2-Dichloroethylene	3251511		<0.20	<0.20	NA	< 0.20	114%	50%	140%	95%	60%	130%	81%	50%	140%
Chloroform	3251511		<0.20	<0.20	NA	< 0.20	115%	50%	140%	113%	60%	130%	86%	50%	140%
1,2-Dichloroethane	3251511		<0.20	<0.20	NA	< 0.20	120%	50%	140%	113%	60%	130%	71%	50%	140%
1,1,1-Trichloroethane	3251511		<0.30	<0.30	NA	< 0.30	103%	50%	140%	108%	60%	130%	88%	50%	140%
Carbon Tetrachloride	3251511		<0.20	<0.20	NA	< 0.20	97%	50%	140%	75%	60%	130%	95%	50%	140%
Benzene	3251511		<0.20	<0.20	NA	< 0.20	83%	50%	140%	82%	60%	130%	87%	50%	140%
1,2-Dichloropropane	3251511		<0.20	<0.20	NA	< 0.20	112%	50%	140%	112%	60%	130%	113%	50%	140%
Trichloroethylene	3251511		<0.20	<0.20	NA	< 0.20	117%	50%	140%	104%	60%	130%	84%	50%	140%
Bromodichloromethane	3251511		<0.20	<0.20	NA	< 0.20	110%	50%	140%	87%	60%	130%	115%	50%	140%
Methyl Isobutyl Ketone	3251511		<1.0	<1.0	NA	< 1.0	103%	50%	140%	101%	50%	140%	99%	50%	140%
1,1,2-Trichloroethane	3251511		<0.20	<0.20	NA	< 0.20	118%	50%	140%	118%	60%	130%	98%	50%	140%
Toluene	3251511		0.46	0.46	NA	< 0.20	116%	50%	140%	96%	60%	130%	50%	50%	140%
Dibromochloromethane	3251511		<0.10	<0.10	NA	< 0.10	111%	50%	140%	77%	60%	130%	120%	50%	140%
Ethylene Dibromide	3251511		<0.10	<0.10	NA	< 0.10	114%	50%	140%	110%	60%	130%	116%	50%	140%
Tetrachloroethylene	3251511		<0.20	<0.20	NA	< 0.20	83%	50%	140%	105%	60%	130%	109%	50%	140%
1,1,1,2-Tetrachloroethane	3251511		<0.10	<0.10	NA	< 0.10	109%	50%	140%	106%	60%	130%	109%	50%	140%
Chlorobenzene	3251511		<0.10	<0.10	NA	< 0.10	88%	50%	140%	107%	60%	130%	98%	50%	140%
Ethylbenzene	3251511		<0.10	<0.10	NA	< 0.10	73%	50%	140%	102%	60%	130%	83%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T834096
ATTENTION TO: Vaness Oetinger
SAMPLED BY:Marsad Jafar

Trace Organics Analysis (Continued)

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
m & p-Xylene	3251511		<0.20	<0.20	NA	< 0.20	100%	50%	140%	105%	60%	130%	88%	50%	140%
Bromoform	3251511		<0.10	<0.10	NA	< 0.10	88%	50%	140%	88%	60%	130%	97%	50%	140%
Styrene	3251511		<0.10	<0.10	NA	< 0.10	81%	50%	140%	86%	60%	130%	76%	50%	140%
1,1,2,2-Tetrachloroethane	3251511		<0.10	<0.10	NA	< 0.10	113%	50%	140%	116%	60%	130%	114%	50%	140%
o-Xylene	3251511		<0.10	<0.10	NA	< 0.10	75%	50%	140%	102%	60%	130%	87%	50%	140%
1,3-Dichlorobenzene	3251511		<0.10	<0.10	NA	< 0.10	72%	50%	140%	92%	60%	130%	80%	50%	140%
1,4-Dichlorobenzene	3251511		<0.10	<0.10	NA	< 0.10	86%	50%	140%	95%	60%	130%	90%	50%	140%
1,2-Dichlorobenzene	3251511		<0.10	<0.10	NA	< 0.10	83%	50%	140%	97%	60%	130%	85%	50%	140%
n-Hexane	3251511		<0.20	<0.20	NA	< 0.20	115%	50%	140%	99%	60%	130%	83%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)															
F1 (C6-C10)	3259635		<25	<25	NA	< 25	102%	60%	140%	99%	60%	140%	107%	60%	140%
O. Reg. 153(511) - VOCs (Water)															
Dichlorodifluoromethane	3251511		<0.20	<0.20	NA	< 0.20	101%	50%	140%	84%	50%	140%	96%	50%	140%
Vinyl Chloride	3251511		<0.17	<0.17	NA	< 0.17	84%	50%	140%	82%	50%	140%	99%	50%	140%
Bromomethane	3251511		<0.20	<0.20	NA	< 0.20	103%	50%	140%	80%	50%	140%	81%	50%	140%
Trichlorofluoromethane	3251511		<0.40	<0.40	NA	< 0.40	78%	50%	140%	85%	50%	140%	88%	50%	140%
Acetone	3251511		<1.0	<1.0	NA	< 1.0	102%	50%	140%	98%	50%	140%	99%	50%	140%
1,1-Dichloroethylene	3251511		<0.30	<0.30	NA	< 0.30	80%	50%	140%	117%	60%	130%	110%	50%	140%
Methylene Chloride	3251511		<0.30	<0.30	NA	< 0.30	95%	50%	140%	98%	60%	130%	110%	50%	140%
trans- 1,2-Dichloroethylene	3251511		<0.20	<0.20	NA	< 0.20	88%	50%	140%	83%	60%	130%	106%	50%	140%
Methyl tert-butyl ether	3251511		<0.20	<0.20	NA	< 0.20	102%	50%	140%	119%	60%	130%	94%	50%	140%
1,1-Dichloroethane	3251511		<0.30	<0.30	NA	< 0.30	96%	50%	140%	87%	60%	130%	90%	50%	140%
Methyl Ethyl Ketone	3251511		<1.0	<1.0	NA	< 1.0	99%	50%	140%	103%	50%	140%	103%	50%	140%
cis- 1,2-Dichloroethylene	3251511		<0.20	<0.20	NA	< 0.20	114%	50%	140%	95%	60%	130%	81%	50%	140%
Chloroform	3251511		<0.20	<0.20	NA	< 0.20	115%	50%	140%	113%	60%	130%	86%	50%	140%
1,2-Dichloroethane	3251511		<0.20	<0.20	NA	< 0.20	120%	50%	140%	113%	60%	130%	71%	50%	140%
1,1,1-Trichloroethane	3251511		<0.30	<0.30	NA	< 0.30	103%	50%	140%	108%	60%	130%	88%	50%	140%
Carbon Tetrachloride	3251511		<0.20	<0.20	NA	< 0.20	97%	50%	140%	75%	60%	130%	95%	50%	140%
Benzene	3251511		<0.20	<0.20	NA	< 0.20	83%	50%	140%	82%	60%	130%	87%	50%	140%
1,2-Dichloropropane	3251511		<0.20	<0.20	NA	< 0.20	112%	50%	140%	112%	60%	130%	113%	50%	140%
Trichloroethylene	3251511		<0.20	<0.20	NA	< 0.20	117%	50%	140%	104%	60%	130%	84%	50%	140%
Bromodichloromethane	3251511		<0.20	<0.20	NA	< 0.20	110%	50%	140%	87%	60%	130%	115%	50%	140%
Methyl Isobutyl Ketone	3251511		<1.0	<1.0	NA	< 1.0	103%	50%	140%	101%	50%	140%	99%	50%	140%
1,1,2-Trichloroethane	3251511		<0.20	<0.20	NA	< 0.20	118%	50%	140%	118%	60%	130%	98%	50%	140%
Toluene	3251511		0.46	0.46	NA	< 0.20	116%	50%	140%	96%	60%	130%	50%	50%	140%
Dibromochloromethane	3251511		<0.10	<0.10	NA	< 0.10	111%	50%	140%	77%	60%	130%	120%	50%	140%
Ethylene Dibromide	3251511		<0.10	<0.10	NA	< 0.10	114%	50%	140%	110%	60%	130%	116%	50%	140%
Tetrachloroethylene	3251511		<0.20	<0.20	NA	< 0.20	83%	50%	140%	105%	60%	130%	109%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T834096
ATTENTION TO: Vaness Oetinger
SAMPLED BY:Marsad Jafar

Trace Organics Analysis (Continued)

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
1,1,1,2-Tetrachloroethane	3251511		<0.10	<0.10	NA	< 0.10	109%	50%	140%	106%	60%	130%	109%	50%	140%
Chlorobenzene	3251511		<0.10	<0.10	NA	< 0.10	88%	50%	140%	107%	60%	130%	98%	50%	140%
Ethylbenzene	3251511		<0.10	<0.10	NA	< 0.10	73%	50%	140%	102%	60%	130%	83%	50%	140%
m & p-Xylene	3251511		<0.20	<0.20	NA	< 0.20	100%	50%	140%	105%	60%	130%	88%	50%	140%
Bromoform	3251511		<0.10	<0.10	NA	< 0.10	88%	50%	140%	88%	60%	130%	97%	50%	140%
Styrene	3251511		<0.10	<0.10	NA	< 0.10	81%	50%	140%	86%	60%	130%	76%	50%	140%
1,1,2,2-Tetrachloroethane	3251511		<0.10	<0.10	NA	< 0.10	113%	50%	140%	116%	60%	130%	114%	50%	140%
o-Xylene	3251511		<0.10	<0.10	NA	< 0.10	75%	50%	140%	102%	60%	130%	87%	50%	140%
1,3-Dichlorobenzene	3251511		<0.10	<0.10	NA	< 0.10	72%	50%	140%	92%	60%	130%	80%	50%	140%
1,4-Dichlorobenzene	3251511		<0.10	<0.10	NA	< 0.10	86%	50%	140%	95%	60%	130%	90%	50%	140%
1,2-Dichlorobenzene	3251511		<0.10	<0.10	NA	< 0.10	83%	50%	140%	97%	60%	130%	85%	50%	140%
n-Hexane	3251511		<0.20	<0.20	NA	< 0.20	115%	50%	140%	99%	60%	130%	83%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY


AGAT WORK ORDER: 21T834096
ATTENTION TO: Vaness Oetinger
SAMPLED BY:Marsad Jafar

Water Analysis

RPT Date: Dec 03, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Water)															
Dissolved Antimony	3249194		<1.0	<1.0	NA	< 1.0	99%	70%	130%	99%	80%	120%	98%	70%	130%
Dissolved Arsenic	3249194		<1.0	<1.0	NA	< 1.0	94%	70%	130%	99%	80%	120%	105%	70%	130%
Dissolved Barium	3249194		147	155	5.3%	< 2.0	99%	70%	130%	103%	80%	120%	107%	70%	130%
Dissolved Beryllium	3249194		<0.50	<0.50	NA	< 0.50	104%	70%	130%	110%	80%	120%	116%	70%	130%
Dissolved Boron	3249194		69.5	70.1	0.9%	< 10.0	100%	70%	130%	105%	80%	120%	115%	70%	130%
Dissolved Cadmium	3249194		<0.20	<0.20	NA	< 0.20	100%	70%	130%	104%	80%	120%	107%	70%	130%
Dissolved Chromium	3249194		4.5	3.0	NA	< 2.0	100%	70%	130%	105%	80%	120%	104%	70%	130%
Dissolved Cobalt	3249194		<0.50	<0.50	NA	< 0.50	102%	70%	130%	108%	80%	120%	107%	70%	130%
Dissolved Copper	3249194		5.1	5.1	0.0%	< 1.0	99%	70%	130%	105%	80%	120%	104%	70%	130%
Dissolved Lead	3249194		<0.50	<0.50	NA	< 0.50	97%	70%	130%	102%	80%	120%	102%	70%	130%
Dissolved Molybdenum	3249194		1.90	1.97	NA	< 0.50	99%	70%	130%	102%	80%	120%	106%	70%	130%
Dissolved Nickel	3249194		<1.0	<1.0	NA	< 1.0	104%	70%	130%	110%	80%	120%	105%	70%	130%
Dissolved Selenium	3249194		<1.0	<1.0	NA	< 1.0	105%	70%	130%	110%	80%	120%	117%	70%	130%
Dissolved Silver	3249194		<0.20	<0.20	NA	< 0.20	100%	70%	130%	105%	80%	120%	107%	70%	130%
Dissolved Thallium	3249194		<0.30	<0.30	NA	< 0.30	104%	70%	130%	108%	80%	120%	109%	70%	130%
Dissolved Uranium	3249194		<0.50	<0.50	NA	< 0.50	100%	70%	130%	103%	80%	120%	103%	70%	130%
Dissolved Vanadium	3249194		0.52	<0.40	NA	< 0.40	97%	70%	130%	101%	80%	120%	101%	70%	130%
Dissolved Zinc	3249194		93.0	97.8	5.0%	< 5.0	100%	70%	130%	105%	80%	120%	108%	70%	130%
Mercury	3245238		<0.02	<0.02	NA	< 0.02	102%	70%	130%	98%	80%	120%	92%	70%	130%
Chromium VI	3241136		<2.000	<2.000	NA	< 2	100%	70%	130%	98%	80%	120%	107%	70%	130%
Cyanide, Free	3229156		<2	<2	NA	< 2	96%	70%	130%	92%	80%	120%	98%	70%	130%
Dissolved Sodium	3246761	3246761	30100	30500	1.3%	< 50	101%	70%	130%	100%	80%	120%	101%	70%	130%
Chloride	3246768	3246768	7770	7680	1.2%	< 100	95%	70%	130%	102%	80%	120%	100%	70%	130%
Electrical Conductivity	3245263		1700	1710	0.6%	< 2	103%	90%	110%	NA			NA		
pH	3245263		7.61	7.73	1.6%	NA	103%	90%	110%	NA			NA		

Comments: NA Signifies Not Applicable
Duplicate NA: results are under 5X the RDL and will not be calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Heptachlor	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Aldrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan I	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan II	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
alpha - chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
Dieldrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Methoxychlor	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
TCMX	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Decachlorobiphenyl	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluorene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Chrysene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
2-and 1-methyl Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Sediment			
F1 (C6-C10)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
Toluene-d8	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F2 (C10 to C16) minus Naphthalene	VOL-91-5010	modified from MOE PHC-E3421	GC/FID

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC-E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Benzene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Toluene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Ethylbenzene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
m & p-Xylene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
o-Xylene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Xylenes (Total)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F1 (C6-C10)	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F2 (C10 to C16) minus Naphthalene	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC-E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Dichlorodifluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromomethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
trans- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl tert-butyl ether	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
cis- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
1,2-Dichloropropane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Dibromochloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromoform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T834096

PROJECT: 211-10139-00

ATTENTION TO: Vaness Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Water Analysis			
Dissolved Antimony	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Arsenic	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Barium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Beryllium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Boron	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cadmium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Chromium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cobalt	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Copper	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Lead	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Molybdenum	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Nickel	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Selenium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Silver	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Thallium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Uranium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Vanadium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Zinc	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Mercury	MET-93-6100	modified from EPA 245.2 and SM 3112 B	CVAAS
Chromium VI	INOR-93-6034	modified from SM 3500-CR B	LACHAT FIA
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Dissolved Sodium	MET-93-6105	modified from EPA 6010D	ICP/OES
Chloride	INOR-93-6004	modified from SM 4110 B	ION CHROMATOGRAPH
Electrical Conductivity	INOR-93-6000	SM 2510 B	PC TITRATE
pH	INOR-93-6000	modified from SM 4500-H+ B	PC TITRATE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Laboratory Use Only

Work Order #: 21T834096

Cooler Quantity:

Arrival Temperatures: 4.2 | 5.3 | 4.8

Custody Seal Intact: ☐ Yes ☐ No ☐ N/A

Notes: On Ice

Report Information:

Company: WSP
Contact: Vanessa Oetinger
Address: 2 International Blvd, Toronto, ON
Phone: 437-233-2935 Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: marsad.jafar@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04 — Table 1 (Indicate One) ☐ Ind/Com ☐ Res/Park ☐ Agriculture
Soil Texture (Check One) ☐ Coarse ☐ Fine
☐ Excess Soils R406 — Table (Indicate One)
☐ Regulation 558
☐ CCME
☐ Sewer Use ☐ Sanitary ☐ Storm — (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other (Indicate One)

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☐ Yes ☐ No

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
*TAT is exclusive of weekends and statutory holidays

For 'Same Day' analysis, please contact your AGAT CPM

Project Information:

Project: 211-10139-00
Site Location: ORBY
Sampled By: Marsad Jafar
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐

Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	OC	Potentially Hazardous or High Concentration (Y/N)
BH21-12	Nov 23/21	9:00 AM/PM	17	GW	Ignore sample date labels		X		X	X	X						X	
BH21-44	Nov 23/21	10:00 AM/PM	17	GW			X		X	X	X						X	
BH21-36	Nov 23/21	1:00 AM/PM	17	GW			X		X	X	X						X	
		AM/PM																
QAQC-1	Nov 23/21	— AM/PM	2	GW													X	
		AM/PM																
Trip Blank	Nov 23/21	— AM/PM	3	GW								X						
		AM/PM																
		AM/PM																
		AM/PM																
		AM/PM																

21 NOV 23 4:37 pm

Samples Relinquished By (Print Name and Sign): Marsad Jafar	Date: Nov 23/2021	Time: 3:30 pm	Samples Received By (Print Name and Sign):	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:

Page ____ of ____

N°: T 127455

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T838602
TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor
WATER ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer
DATE REPORTED: Dec 16, 2021
PAGES (INCLUDING COVER): 24
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - PAHs (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

		SAMPLE DESCRIPTION:		BH21-45	BH21-9	BH21-13	BH21-11	QA/QC	BH21-28	BH21-25	BH21-22
		SAMPLE TYPE:		Water	Water	Water	Water	Water	Water	Water	Water
		DATE SAMPLED:		2021-12-01	2021-11-30	2021-11-30	2021-11-30	2021-11-30	2021-12-01	2021-12-01	2021-12-01
Parameter	Unit	G / S	RDL	3285019	3285046	3285052	3285144	3285169	3285251	3285258	3285299
Naphthalene	µg/L	7	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Acenaphthylene	µg/L	1	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Acenaphthene	µg/L	4.1	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Fluorene	µg/L	120	0.20	<0.20	<0.20	<0.20	<0.20	0.56	<0.20	<0.20	<0.20
Phenanthrene	µg/L	0.1	0.10	12.0	<0.10	<0.10	<0.10	9.08	<0.10	<0.10	<0.10
Anthracene	µg/L	0.1	0.10	1.79	<0.10	<0.10	<0.10	1.00	<0.10	<0.10	<0.10
Fluoranthene	µg/L	0.4	0.20	17.9	<0.20	<0.20	<0.20	11.2	<0.20	<0.20	<0.20
Pyrene	µg/L	0.2	0.20	14.6	<0.20	<0.20	<0.20	9.52	<0.20	<0.20	<0.20
Benzo(a)anthracene	µg/L	0.2	0.20	2.4	<0.20	<0.20	<0.20	1.67	<0.20	<0.20	<0.20
Chrysene	µg/L	0.1	0.10	5.59	<0.10	<0.10	<0.10	4.01	<0.10	<0.10	<0.10
Benzo(b)fluoranthene	µg/L	0.1	0.10	4.92	<0.10	<0.10	<0.10	3.29	<0.10	<0.10	<0.10
Benzo(k)fluoranthene	µg/L	0.1	0.10	2.19	<0.10	<0.10	<0.10	1.86	<0.10	<0.10	<0.10
Benzo(a)pyrene	µg/L	0.01	0.01	3.67	<0.01	<0.01	<0.01	2.80	<0.01	<0.01	<0.01
Indeno(1,2,3-cd)pyrene	µg/L	0.2	0.20	1.80	<0.20	<0.20	<0.20	1.35	<0.20	<0.20	<0.20
Dibenz(a,h)anthracene	µg/L	0.2	0.20	0.32	<0.20	<0.20	<0.20	0.21	<0.20	<0.20	<0.20
Benzo(g,h,i)perylene	µg/L	0.2	0.20	2.48	<0.20	<0.20	<0.20	1.89	<0.20	<0.20	<0.20
2-and 1-methyl Naphthalene	µg/L	2	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Sediment				No	No	No	No	No	No	No	No
Surrogate	Unit	Acceptable Limits									
Naphthalene-d8	%	50-140		105	80	93	82	98	78	78	90
Acridine-d9	%	50-140		98	99	72	91	86	85	85	97
Terphenyl-d14	%	50-140		88	74	94	78	88	99	99	88

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3285019-3285299 Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&(j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

		SAMPLE DESCRIPTION:		BH21-45	BH21-9		BH21-13		QA/QC	BH21-28	BH21-25
		SAMPLE TYPE:		Water	Water		Water		Water	Water	Water
		DATE SAMPLED:		2021-12-01	2021-11-30		2021-11-30		2021-11-30	2021-12-01	2021-12-01
Parameter	Unit	G / S	RDL	3285019	3285046	RDL	3285052	RDL	3285169	3285251	3285258
F1 (C6-C10)	µg/L	420	25	<25	<25	25	<25	25	<25	<25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25	<25	25	<25	25	<25	<25	<25
F2 (C10 to C16)	µg/L	150	100	<100	<100	100	<100	100	<100	<100	<100
F2 (C10 to C16) minus Naphthalene	µg/L		100	<100	<100	100	<100	100	<100	<100	<100
F3 (C16 to C34)	µg/L	500	100	<100	<100	100	<100	100	<100	<100	<100
F3 (C16 to C34) minus PAHs	µg/L		100	<100	<100	100	<100	100	<100	<100	<100
F4 (C34 to C50)	µg/L	500	100	<100	<100	100	<100	100	<100	<100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA	NA	500	NA	500	NA	NA	NA
Sediment				No	No		No		No	No	No
Surrogate	Unit	Acceptable Limits									
Toluene-d8	% Recovery	50-140		83.5	73.5	1	90	1.00	76.8	124	103
Terphenyl	% Recovery	60-140		79	119		66		67	61	67

		SAMPLE DESCRIPTION:		BH21-22
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-01
Parameter	Unit	G / S	RDL	3285299
F1 (C6-C10)	µg/L	420	25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25
F2 (C10 to C16)	µg/L	150	100	<100
F2 (C10 to C16) minus Naphthalene	µg/L		100	<100
F3 (C16 to C34)	µg/L	500	100	<100
F3 (C16 to C34) minus PAHs	µg/L		100	<100
F4 (C34 to C50)	µg/L	500	100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA
Sediment				No
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		74.2
Terphenyl	% Recovery	60-140		101

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16


Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3285019-3285299 The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

		SAMPLE DESCRIPTION:		BH21-11
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-11-30
Parameter	Unit	G / S	RDL	3285144
Benzene	µg/L	0.5	0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20
Ethylbenzene	µg/L	0.5	0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20
o-Xylene	µg/L		0.10	<0.10
Xylenes (Total)	µg/L	72	0.20	<0.20
F1 (C6-C10)	µg/L	420	25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25
F2 (C10 to C16)	µg/L	150	100	<100
F2 (C10 to C16) minus Naphthalene	µg/L		100	<100
F3 (C16 to C34)	µg/L	500	100	<100
F3 (C16 to C34) minus PAHs	µg/L		100	<100
F4 (C34 to C50)	µg/L	500	100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA
Sediment				No
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	60-140		70.0
Terphenyl	% Recovery	60-140		76

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16


Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3285144 The C6-C10 fraction is calculated using toluene response factor.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - PHCs F1/BTEX (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

		SAMPLE DESCRIPTION:		BH21-30	Trip Blank
		SAMPLE TYPE:		Water	Water
		DATE SAMPLED:		2021-12-01	
Parameter	Unit	G / S	RDL	3285248	3285328
Benzene	µg/L	0.5	0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20	<0.20
o-Xylene	µg/L		0.10	<0.10	<0.10
Xylenes (Total)	µg/L	72	0.20	<0.20	<0.20
F1 (C6-C10)	µg/L	420	25	<25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25	<25
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	60-140		74.8	97.5

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3285248-3285328 The C6-C10 fraction is calculated using Toluene response factor.
Total C6-C10 results are corrected for BTEX contributions.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
Extraction and holding times were met for this sample.
NA = Not Applicable

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

SAMPLE DESCRIPTION:				BH21-45	BH21-9	BH21-13	QA/QC	BH21-28	BH21-25	BH21-22	Trip Blank
SAMPLE TYPE:				Water	Water	Water	Water	Water	Water	Water	Water
DATE SAMPLED:				2021-12-01	2021-11-30	2021-11-30	2021-11-30	2021-12-01	2021-12-01	2021-12-01	
Parameter	Unit	G / S	RDL	3285019	3285046	3285052	3285169	3285251	3285258	3285299	3285328
Dichlorodifluoromethane	µg/L	590	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Vinyl Chloride	µg/L	0.5	0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17	<0.17
Bromomethane	µg/L	0.89	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	µg/L	150	0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40	<0.40
Acetone	µg/L	2700	1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
1,1-Dichloroethylene	µg/L	0.5	0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Methylene Chloride	µg/L	5	0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
trans- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl tert-butyl ether	µg/L	15	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
1,1-Dichloroethane	µg/L	0.5	0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Methyl Ethyl Ketone	µg/L	400	1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
cis- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Chloroform	µg/L	2	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
1,2-Dichloroethane	µg/L	0.5	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
1,1,1-Trichloroethane	µg/L	0.5	0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Carbon Tetrachloride	µg/L	0.2	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Benzene	µg/L	0.5	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
1,2-Dichloropropane	µg/L	0.5	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Trichloroethylene	µg/L	0.5	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Bromodichloromethane	µg/L	2	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Methyl Isobutyl Ketone	µg/L	640	1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0
1,1,2-Trichloroethane	µg/L	0.5	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Dibromochloromethane	µg/L	2	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	µg/L	0.2	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	µg/L	0.5	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
1,1,1,2-Tetrachloroethane	µg/L	1.1	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Chlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

		SAMPLE DESCRIPTION:		BH21-45	BH21-9	BH21-13	QA/QC	BH21-28	BH21-25	BH21-22	Trip Blank
		SAMPLE TYPE:		Water	Water	Water	Water	Water	Water	Water	Water
		DATE SAMPLED:		2021-12-01	2021-11-30	2021-11-30	2021-11-30	2021-12-01	2021-12-01	2021-12-01	
Parameter	Unit	G / S	RDL	3285019	3285046	3285052	3285169	3285251	3285258	3285299	3285328
Bromoform	µg/L	5	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
Styrene	µg/L	0.5	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
1,1,2,2-Tetrachloroethane	µg/L	0.5	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
o-Xylene	µg/L		0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
1,3-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
1,4-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
1,2-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10	<0.10
1,3-Dichloropropene	µg/L	0.5	0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30	<0.30
Xylenes (Total)	µg/L	72	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
n-Hexane	µg/L	5	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20	<0.20
Surrogate	Unit	Acceptable Limits									
Toluene-d8	% Recovery	50-140		54	82	86	72	86	77	103	73
4-Bromofluorobenzene	% Recovery	50-140		86	94	104	97	100	105	108	88

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3285019-3285328 Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

Total PCBs (water)

DATE RECEIVED: 2021-12-01


DATE REPORTED: 2021-12-16

SAMPLE DESCRIPTION:				BH21-45	BH21-9	BH21-11	QA/QC	BH21-28
SAMPLE TYPE:				Water	Water	Water	Water	Water
DATE SAMPLED:				2021-12-01	2021-11-30	2021-11-30	2021-11-30	2021-12-01
Parameter	Unit	G / S	RDL	3285019	3285046	3285144	3285169	3285251
PCBs	µg/L	0.2	0.1	<0.1	<0.1	<0.1	<0.1	<0.1
Surrogate	Unit	Acceptable Limits						
Decachlorobiphenyl	%	60-130		93	88	89	76	103

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ


O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

SAMPLE DESCRIPTION:				BH21-45	BH21-9	BH21-13	BH21-11	QA/QC		BH21-28
SAMPLE TYPE:				Water	Water	Water	Water	Water		Water
DATE SAMPLED:				2021-12-01	2021-11-30	2021-11-30	2021-11-30	2021-11-30		2021-12-01
Parameter	Unit	G / S	RDL	3285019	3285046	3285052	3285144	3285169	RDL	3285251
Dissolved Antimony	µg/L	1.5	1.0	<1.0	<1.0	<1.0	<1.0	<1.0	1.0	<1.0
Dissolved Arsenic	µg/L	13	1.0	4.7	<1.0	<1.0	<1.0	1.6	1.0	5.7
Dissolved Barium	µg/L	610	2.0	80.5	54.0	102	134	62.4	2.0	79.5
Dissolved Beryllium	µg/L	0.5	0.50	<0.50	<0.50	<0.50	<0.50	<0.50	0.50	<0.50
Dissolved Boron	µg/L	1700	10.0	682	85.2	35.7	61.0	115	10.0	222
Dissolved Cadmium	µg/L	0.5	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	0.20	<0.20
Dissolved Chromium	µg/L	11	2.0	<2.0	<2.0	<2.0	<2.0	<2.0	2.0	<2.0
Dissolved Cobalt	µg/L	3.8	0.50	0.66	2.06	<0.50	<0.50	2.87	0.50	<0.50
Dissolved Copper	µg/L	5	1.0	<1.0	<1.0	<1.0	1.3	<1.0	1.0	<1.0
Dissolved Lead	µg/L	1.9	0.50	<0.50	<0.50	0.53	<0.50	<0.50	0.50	<0.50
Dissolved Molybdenum	µg/L	23	0.50	28.0	3.50	0.70	<0.50	4.27	0.50	4.81
Dissolved Nickel	µg/L	14	1.0	4.7	3.9	<1.0	1.2	4.2	1.0	<1.0
Dissolved Selenium	µg/L	5	1.0	<1.0	1.0	<1.0	1.7	<1.0	1.0	<1.0
Dissolved Silver	µg/L	0.3	0.20	<0.20	<0.20	<0.20	<0.20	<0.20	0.20	<0.20
Dissolved Thallium	µg/L	0.5	0.30	<0.30	<0.30	<0.30	<0.30	<0.30	0.30	<0.30
Dissolved Uranium	µg/L	8.9	0.50	1.50	0.73	0.88	<0.50	0.96	0.50	<0.50
Dissolved Vanadium	µg/L	3.9	0.40	0.83	<0.40	<0.40	<0.40	<0.40	0.40	<0.40
Dissolved Zinc	µg/L	160	5.0	<5.0	<5.0	<5.0	<5.0	<5.0	5.0	<5.0
Mercury	µg/L	0.1	0.02	<0.02	<0.02	<0.02	<0.02	<0.02	0.02	<0.02
Chromium VI	µg/L	25	2	<2	<2	<2	<2	<2	2	<2
Cyanide, Free	µg/L	5	2	<2	<2	<2	<2	<2	2	<2
Dissolved Sodium	µg/L	490000	250	205000	92000	349000	135000	77700	50	33000
Chloride	µg/L	790000	100	326000	162000	557000	285000	156000	100	17600
Electrical Conductivity	uS/cm	NA	2	1830	1330	2760	1740	1300	2	620
pH	pH Units		NA	7.82	7.72	7.80	7.75	7.72	NA	7.74

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

		SAMPLE DESCRIPTION:		BH21-25		BH21-22
		SAMPLE TYPE:		Water		Water
		DATE SAMPLED:		2021-12-01		2021-12-01
Parameter	Unit	G / S	RDL	3285258	RDL	3285299
Dissolved Antimony	µg/L	1.5	1.0	<1.0	1.0	<1.0
Dissolved Arsenic	µg/L	13	1.0	<1.0	1.0	1.1
Dissolved Barium	µg/L	610	2.0	189	2.0	91.9
Dissolved Beryllium	µg/L	0.5	0.50	<0.50	0.50	<0.50
Dissolved Boron	µg/L	1700	10.0	117	10.0	219
Dissolved Cadmium	µg/L	0.5	0.20	<0.20	0.20	<0.20
Dissolved Chromium	µg/L	11	2.0	<2.0	2.0	<2.0
Dissolved Cobalt	µg/L	3.8	0.50	<0.50	0.50	1.06
Dissolved Copper	µg/L	5	1.0	<1.0	1.0	<1.0
Dissolved Lead	µg/L	1.9	0.50	<0.50	0.50	<0.50
Dissolved Molybdenum	µg/L	23	0.50	5.47	0.50	4.41
Dissolved Nickel	µg/L	14	1.0	1.3	1.0	1.9
Dissolved Selenium	µg/L	5	1.0	<1.0	1.0	<1.0
Dissolved Silver	µg/L	0.3	0.20	<0.20	0.20	<0.20
Dissolved Thallium	µg/L	0.5	0.30	<0.30	0.30	<0.30
Dissolved Uranium	µg/L	8.9	0.50	5.02	0.50	2.18
Dissolved Vanadium	µg/L	3.9	0.40	<0.40	0.40	0.63
Dissolved Zinc	µg/L	160	5.0	<5.0	5.0	<5.0
Mercury	µg/L	0.1	0.02	<0.02	0.02	<0.02
Chromium VI	µg/L	25	2	<2	2	<2
Cyanide, Free	µg/L	5	2	<2	2	<2
Dissolved Sodium	µg/L	490000	100	18600	250	43800
Chloride	µg/L	790000	100	12800	100	63300
Electrical Conductivity	uS/cm	NA	2	872	2	1310
pH	pH Units		NA	7.80	NA	7.76

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-01

DATE REPORTED: 2021-12-16

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3285019-3285299 Metals analysis completed on a filtered sample.

Dilution required, RDL has been increased accordingly.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Dissolved Molybdenum	µg/L	23	28.0
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Anthracene	µg/L	0.1	1.79
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(a)anthracene	µg/L	0.2	2.4
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(a)pyrene	µg/L	0.01	3.67
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(b)fluoranthene	µg/L	0.1	4.92
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(g,h,i)perylene	µg/L	0.2	2.48
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(k)fluoranthene	µg/L	0.1	2.19
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Chrysene	µg/L	0.1	5.59
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Dibenz(a,h)anthracene	µg/L	0.2	0.32
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Fluoranthene	µg/L	0.4	17.9
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Indeno(1,2,3-cd)pyrene	µg/L	0.2	1.80
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Phenanthrene	µg/L	0.1	12.0
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Pyrene	µg/L	0.2	14.6
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Benzo(a)anthracene	µg/L	0.2	2.43
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Benzo(a)pyrene	µg/L	0.01	3.67
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Benzo(b)fluoranthene	µg/L	0.1	4.92
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Benzo(k)fluoranthene	µg/L	0.1	2.19
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Dibenzo(a,h)anthracene	µg/L	0.2	0.32
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Fluoranthene	µg/L	0.4	17.9
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Indeno(1,2,3-cd)pyrene	µg/L	0.2	1.80
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Phenanthrene	µg/L	0.1	12.0
3285019	BH21-45	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Pyrene	µg/L	0.2	14.6
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Anthracene	µg/L	0.1	1.00
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(a)anthracene	µg/L	0.2	1.67
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(a)pyrene	µg/L	0.01	2.80
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(b)fluoranthene	µg/L	0.1	3.29
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(g,h,i)perylene	µg/L	0.2	1.89
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Benzo(k)fluoranthene	µg/L	0.1	1.86
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Chrysene	µg/L	0.1	4.01
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Dibenz(a,h)anthracene	µg/L	0.2	0.21
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Fluoranthene	µg/L	0.4	11.2
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Indeno(1,2,3-cd)pyrene	µg/L	0.2	1.35
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Phenanthrene	µg/L	0.1	9.08
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PAHs (Water)	Pyrene	µg/L	0.2	9.52
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Benzo(a)anthracene	µg/L	0.2	1.67

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Benzo(a)pyrene	µg/L	0.01	2.80
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Benzo(b)fluoranthene	µg/L	0.1	3.30
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Benzo(k)fluoranthene	µg/L	0.1	1.86
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Dibenzo(a,h)anthracene	µg/L	0.2	0.21
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Fluoranthene	µg/L	0.4	11.2
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Indeno(1,2,3-cd)pyrene	µg/L	0.2	1.35
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Phenanthrene	µg/L	0.1	9.08
3285169	QA/QC	ON T1 GW	O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)	Pyrene	µg/L	0.2	9.52

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T838602
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:SA/MJ

Trace Organics Analysis

RPT Date: Dec 16, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)															
F1 (C6-C10)	3300342		<25	<25	NA	< 25	120%	60%	140%	106%	60%	140%	101%	60%	140%
F2 (C10 to C16)	3285019	3285019	< 100	< 100	NA	< 100	102%	60%	140%	85%	60%	140%	95%	60%	140%
F3 (C16 to C34)	3285019	3285019	< 100	< 100	NA	< 100	106%	60%	140%	76%	60%	140%	86%	60%	140%
F4 (C34 to C50)	3285019	3285019	< 100	< 100	NA	< 100	85%	60%	140%	74%	60%	140%	87%	60%	140%
O. Reg. 153(511) - PAHs (Water)															
Naphthalene	3227991		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	78%	50%	140%	77%	50%	140%
Acenaphthylene	3227991		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	82%	50%	140%	107%	50%	140%
Acenaphthene	3227991		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	71%	50%	140%	81%	50%	140%
Fluorene	3227991		< 0.20	< 0.20	NA	< 0.20	86%	50%	140%	92%	50%	140%	92%	50%	140%
Phenanthrene	3227991		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	88%	50%	140%	85%	50%	140%
Anthracene	3227991		< 0.10	< 0.10	NA	< 0.10	85%	50%	140%	93%	50%	140%	78%	50%	140%
Fluoranthene	3227991		< 0.20	< 0.20	NA	< 0.20	99%	50%	140%	96%	50%	140%	93%	50%	140%
Pyrene	3227991		< 0.20	< 0.20	NA	< 0.20	78%	50%	140%	96%	50%	140%	99%	50%	140%
Benzo(a)anthracene	3227991		< 0.20	< 0.20	NA	< 0.20	96%	50%	140%	94%	50%	140%	96%	50%	140%
Chrysene	3227991		< 0.10	< 0.10	NA	< 0.10	86%	50%	140%	114%	50%	140%	84%	50%	140%
Benzo(b)fluoranthene	3227991		< 0.10	< 0.10	NA	< 0.10	92%	50%	140%	76%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3227991		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	92%	50%	140%	78%	50%	140%
Benzo(a)pyrene	3227991		< 0.01	< 0.01	NA	< 0.01	78%	50%	140%	105%	50%	140%	101%	50%	140%
Indeno(1,2,3-cd)pyrene	3227991		< 0.20	< 0.20	NA	< 0.20	92%	50%	140%	108%	50%	140%	105%	50%	140%
Dibenz(a,h)anthracene	3227991		< 0.20	< 0.20	NA	< 0.20	95%	50%	140%	75%	50%	140%	72%	50%	140%
Benzo(g,h,i)perylene	3227991		< 0.20	< 0.20	NA	< 0.20	91%	50%	140%	85%	50%	140%	105%	50%	140%
Total PCBs (water)															
PCBs	3295989		< 0.1	< 0.1	NA	< 0.1	95%	50%	140%	89%	50%	140%	98%	50%	140%
O. Reg. 153(511) - VOCs (Water)															
Dichlorodifluoromethane	3268642		<0.20	<0.20	NA	< 0.20	91%	50%	140%	95%	50%	140%	94%	50%	140%
Vinyl Chloride	3268642		<0.17	<0.17	NA	< 0.17	96%	50%	140%	102%	50%	140%	85%	50%	140%
Bromomethane	3268642		<0.20	<0.20	NA	< 0.20	98%	50%	140%	83%	50%	140%	85%	50%	140%
Trichlorofluoromethane	3268642		<0.40	<0.40	NA	< 0.40	87%	50%	140%	79%	50%	140%	91%	50%	140%
Acetone	3268642		<1.0	<1.0	NA	< 1.0	96%	50%	140%	100%	50%	140%	103%	50%	140%
1,1-Dichloroethylene	3268642		<0.30	<0.30	NA	< 0.30	93%	50%	140%	73%	60%	130%	100%	50%	140%
Methylene Chloride	3268642		<0.30	<0.30	NA	< 0.30	120%	50%	140%	120%	60%	130%	84%	50%	140%
trans- 1,2-Dichloroethylene	3268642		<0.20	<0.20	NA	< 0.20	97%	50%	140%	120%	60%	130%	84%	50%	140%
Methyl tert-butyl ether	3268642		<0.20	<0.20	NA	< 0.20	95%	50%	140%	117%	60%	130%	87%	50%	140%
1,1-Dichloroethane	3268642		<0.30	<0.30	NA	< 0.30	85%	50%	140%	110%	60%	130%	73%	50%	140%
Methyl Ethyl Ketone	3268642		<1.0	<1.0	NA	< 1.0	98%	50%	140%	101%	50%	140%	97%	50%	140%
cis- 1,2-Dichloroethylene	3268642		<0.20	<0.20	NA	< 0.20	79%	50%	140%	107%	60%	130%	118%	50%	140%
Chloroform	3268642		<0.20	<0.20	NA	< 0.20	98%	50%	140%	101%	60%	130%	89%	50%	140%
1,2-Dichloroethane	3268642		<0.20	<0.20	NA	< 0.20	116%	50%	140%	97%	60%	130%	81%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T838602
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:SA/MJ

Trace Organics Analysis (Continued)

RPT Date: Dec 16, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
1,1,1-Trichloroethane	3268642		<0.30	<0.30	NA	< 0.30	111%	50%	140%	85%	60%	130%	112%	50%	140%
Carbon Tetrachloride	3268642		<0.20	<0.20	NA	< 0.20	98%	50%	140%	120%	60%	130%	84%	50%	140%
Benzene	3268642		<0.20	<0.20	NA	< 0.20	87%	50%	140%	106%	60%	130%	94%	50%	140%
1,2-Dichloropropane	3268642		<0.20	<0.20	NA	< 0.20	111%	50%	140%	97%	60%	130%	100%	50%	140%
Trichloroethylene	3268642		<0.20	<0.20	NA	< 0.20	105%	50%	140%	98%	60%	130%	111%	50%	140%
Bromodichloromethane	3268642		<0.20	<0.20	NA	< 0.20	116%	50%	140%	107%	60%	130%	99%	50%	140%
Methyl Isobutyl Ketone	3268642		<1.0	<1.0	NA	< 1.0	109%	50%	140%	103%	50%	140%	100%	50%	140%
1,1,2-Trichloroethane	3268642		<0.20	<0.20	NA	< 0.20	117%	50%	140%	97%	60%	130%	78%	50%	140%
Toluene	3268642		<0.20	<0.20	NA	< 0.20	100%	50%	140%	75%	60%	130%	120%	50%	140%
Dibromochloromethane	3268642		<0.10	<0.10	NA	< 0.10	116%	50%	140%	110%	60%	130%	105%	50%	140%
Ethylene Dibromide	3268642		<0.10	<0.10	NA	< 0.10	111%	50%	140%	91%	60%	130%	93%	50%	140%
Tetrachloroethylene	3268642		<0.20	<0.20	NA	< 0.20	104%	50%	140%	91%	60%	130%	87%	50%	140%
1,1,1,2-Tetrachloroethane	3268642		<0.10	<0.10	NA	< 0.10	105%	50%	140%	86%	60%	130%	104%	50%	140%
Chlorobenzene	3268642		<0.10	<0.10	NA	< 0.10	89%	50%	140%	70%	60%	130%	97%	50%	140%
Ethylbenzene	3268642		<0.10	<0.10	NA	< 0.10	74%	50%	140%	87%	60%	130%	80%	50%	140%
m & p-Xylene	3268642		<0.20	<0.20	NA	< 0.20	98%	50%	140%	92%	60%	130%	90%	50%	140%
Bromoform	3268642		<0.10	<0.10	NA	< 0.10	106%	50%	140%	84%	60%	130%	88%	50%	140%
Styrene	3268642		<0.10	<0.10	NA	< 0.10	76%	50%	140%	82%	60%	130%	70%	50%	140%
1,1,2,2-Tetrachloroethane	3268642		<0.10	<0.10	NA	< 0.10	94%	50%	140%	77%	60%	130%	84%	50%	140%
o-Xylene	3268642		<0.10	<0.10	NA	< 0.10	78%	50%	140%	78%	60%	130%	79%	50%	140%
1,3-Dichlorobenzene	3268642		<0.10	<0.10	NA	< 0.10	95%	50%	140%	78%	60%	130%	73%	50%	140%
1,4-Dichlorobenzene	3268642		<0.10	<0.10	NA	< 0.10	101%	50%	140%	78%	60%	130%	81%	50%	140%
1,2-Dichlorobenzene	3268642		<0.10	<0.10	NA	< 0.10	98%	50%	140%	80%	60%	130%	78%	50%	140%
n-Hexane	3268642		<0.20	<0.20	NA	< 0.20	93%	50%	140%	95%	60%	130%	117%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs) (Water)															
Benzene	3300342		<0.20	<0.20	NA	< 0.20	90%	60%	140%	85%	60%	140%	104%	60%	140%
Toluene	3300342		<0.20	<0.20	NA	< 0.20	85%	60%	140%	81%	60%	140%	93%	60%	140%
Ethylbenzene	3300342		<0.10	<0.10	NA	< 0.10	85%	60%	140%	84%	60%	140%	96%	60%	140%
m & p-Xylene	3300342		<0.20	<0.20	NA	< 0.20	91%	60%	140%	103%	60%	140%	106%	60%	140%
o-Xylene	3300342		<0.10	<0.10	NA	< 0.10	104%	60%	140%	82%	60%	140%	119%	60%	140%
O. Reg. 153(511) - PHCs F1/BTEX (Water)															
Benzene	3300342		<0.20	<0.20	NA	< 0.20	90%	60%	140%	85%	60%	140%	104%	60%	140%
Toluene	3300342		<0.20	<0.20	NA	< 0.20	85%	60%	140%	81%	60%	140%	93%	60%	140%
Ethylbenzene	3300342		<0.10	<0.10	NA	< 0.10	85%	60%	140%	84%	60%	140%	96%	60%	140%
m & p-Xylene	3300342		<0.20	<0.20	NA	< 0.20	91%	60%	140%	103%	60%	140%	106%	60%	140%
o-Xylene	3300342		<0.10	<0.10	NA	< 0.10	104%	60%	140%	82%	60%	140%	119%	60%	140%
F1 (C6-C10)	3300342		<25	<25	NA	< 25	120%	60%	140%	106%	60%	140%	101%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

PROJECT: 211-10139-00

SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T838602

ATTENTION TO: Vanessa Oetinger

SAMPLED BY:SA/MJ

Trace Organics Analysis (Continued)

RPT Date: Dec 16, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T838602
ATTENTION TO: Vanessa Oetinger
SAMPLED BY:SA/MJ

Water Analysis

RPT Date: Dec 16, 2021

PARAMETER	Batch	Sample Id	DUPLICATE			Method Blank	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
			Dup #1	Dup #2	RPD		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Water)															
Dissolved Antimony	3286010		<1.0	<1.0	NA	< 1.0	103%	70%	130%	101%	80%	120%	95%	70%	130%
Dissolved Arsenic	3286010		<1.0	<1.0	NA	< 1.0	98%	70%	130%	103%	80%	120%	108%	70%	130%
Dissolved Barium	3286010		527	528	0.2%	< 2.0	103%	70%	130%	102%	80%	120%	104%	70%	130%
Dissolved Beryllium	3286010		<0.50	<0.50	NA	< 0.50	105%	70%	130%	104%	80%	120%	117%	70%	130%
Dissolved Boron	3286010		85.3	92.5	8.1%	< 10.0	103%	70%	130%	101%	80%	120%	111%	70%	130%
Dissolved Cadmium	3286010		<0.20	<0.20	NA	< 0.20	100%	70%	130%	100%	80%	120%	101%	70%	130%
Dissolved Chromium	3286010		<2.0	<2.0	NA	< 2.0	101%	70%	130%	101%	80%	120%	98%	70%	130%
Dissolved Cobalt	3286010		0.79	0.81	NA	< 0.50	102%	70%	130%	105%	80%	120%	97%	70%	130%
Dissolved Copper	3286010		<1.0	<1.0	NA	< 1.0	101%	70%	130%	102%	80%	120%	95%	70%	130%
Dissolved Lead	3286010		0.78	0.68	NA	< 0.50	104%	70%	130%	97%	80%	120%	94%	70%	130%
Dissolved Molybdenum	3286010		4.75	5.36	12.1%	< 0.50	104%	70%	130%	104%	80%	120%	105%	70%	130%
Dissolved Nickel	3286010		3.4	3.7	NA	< 1.0	104%	70%	130%	103%	80%	120%	96%	70%	130%
Dissolved Selenium	3286010		2.4	<1.0	NA	< 1.0	101%	70%	130%	99%	80%	120%	115%	70%	130%
Dissolved Silver	3286010		<0.20	<0.20	NA	< 0.20	102%	70%	130%	104%	80%	120%	95%	70%	130%
Dissolved Thallium	3286010		<0.30	<0.30	NA	< 0.30	104%	70%	130%	103%	80%	120%	103%	70%	130%
Dissolved Uranium	3286010		2.13	2.02	NA	< 0.50	104%	70%	130%	105%	80%	120%	104%	70%	130%
Dissolved Vanadium	3286010		0.54	0.88	NA	< 0.40	101%	70%	130%	101%	80%	120%	101%	70%	130%
Dissolved Zinc	3286010		9.3	15.3	NA	< 5.0	102%	70%	130%	95%	80%	120%	100%	70%	130%
Mercury	3284500		<0.02	<0.02	NA	< 0.02	103%	70%	130%	101%	80%	120%	101%	70%	130%
Chromium VI	3285019	3285019	<2	<2	NA	< 2	103%	70%	130%	104%	80%	120%	110%	70%	130%
Cyanide, Free	3273743		<2	<2	NA	< 2	105%	70%	130%	96%	80%	120%	99%	70%	130%
Dissolved Sodium	3304482		167000	167000	0.0%	< 50	95%	70%	130%	98%	80%	120%	106%	70%	130%
Chloride	3283197		38900	39200	0.8%	< 100	97%	70%	130%	103%	80%	120%	108%	70%	130%
Electrical Conductivity	3284500		1290	1290	0.0%	< 2	102%	90%	110%						
pH	3284500		7.50	7.55	0.7%	NA	102%	90%	110%						

Comments: NA signifies Not Applicable.
Duplicate NA: results are under 5X the RDL and will not be calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluorene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Chrysene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
2-and 1-methyl Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Sediment			
F1 (C6-C10)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
Toluene-d8	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F2 (C10 to C16) minus Naphthalene	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC-E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Benzene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Toluene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Ethylbenzene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
m & p-Xylene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
o-Xylene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Xylenes (Total)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F1 (C6-C10)	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F2 (C10 to C16) minus Naphthalene	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC-E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Benzene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Toluene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F1 (C6-C10)	VOL-91-5010	modified from MOE E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE E3421	(P&T)GC/FID
Dichlorodifluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromomethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
trans- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl tert-butyl ether	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
cis- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
1,2-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Dibromochloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromoform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T838602

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:ORBY

SAMPLED BY:SA/MJ

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
4-Bromofluorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
PCBs	ORG-91-5112	EPA SW-846 3510 & 8082	GC/ECD
Decachlorobiphenyl	ORG-91-5112	EPA SW-846 3510 & 8082	GC/ECD
Water Analysis			
Dissolved Antimony	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Arsenic	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Barium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Beryllium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Boron	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cadmium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Chromium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cobalt	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Copper	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Lead	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Molybdenum	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Nickel	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Selenium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Silver	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Thallium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Uranium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Vanadium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Zinc	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Mercury	MET-93-6100	modified from EPA 245.2 and SM 3112 B	CVAAS
Chromium VI	INOR-93-6034	modified from SM 3500-CR B	LACHAT FIA
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Dissolved Sodium	MET-93-6105	modified from EPA 6010D	ICP/OES
Chloride	INOR-93-6004	modified from SM 4110 B	ION CHROMATOGRAPH
Electrical Conductivity	INOR-93-6000	SM 2510 B	PC TITRATE
pH	INOR-93-6000	modified from SM 4500-H+ B	PC TITRATE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP Canada Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd. Toronto, ON
Phone: Fax:
Reports to be sent to:
1. Email: Vanessa.Oetinger@wsp.com
2. Email:

Project Information:

Project: 21L-00139-00
Site Location: ORBY
Sampled By: SA/MJ
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company: WSP Canada Inc.
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

- ☒ Regulation 153/04 — Table 1 (Indicate One) — ☐ Ind/Com ☒ Res/Park ☐ Agriculture
- ☐ Excess Soils R406 — Table ____ (Indicate One)
- ☐ Regulation 558
- ☐ CCME
- ☐ Sewer Use ☐ Sanitary ☐ Storm — ____ (Region)
- ☐ Prov. Water Quality Objectives (PWQO)
- ☐ Other ____ (Indicate One)

Soil Texture (Check One): ☒ Coarse ☐ Fine

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☒ Yes ☐ No

Laboratory Use Only

Work Order #: 21T838602
Cooler Quantity: 6.3 6.4 6.10
Arrival Temperatures: 8.4 8.6 8.3 / 7.1 8.2 8.4
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: 3 Cooler/Freezer

Turnaround Time (TAT) Required:

Regular TAT ☐ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply): ____
Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*
For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	BTEX, F1-F4 PHCs	Analyze F4G if required ☐ Yes ☐ No	PAHs	PCBs	VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-45	12/1/21	AM PM	18	GW			X		X	X	X	X	X					
BH21-9	11/30/21	AM PM	19	GW			X		X	X	X	X	X					
BH21-13	11/30/21	AM PM	16	GW			X		X	X			X					
BH21-11	11/30/21	AM PM	15	GW			X		X	X	X							
QA/QC	11/30/21	AM PM	19	GW			X		X	X	X	X	X					
BH21-30	12/1/21	AM PM	3	GW					X									
BH21-28	12/1/21	AM PM	19	GW			X		X	X	X	X	X					
BH21-25	12/1/21	AM PM	16	GW			X		X	X	X		X					
BH21-22	12/1/21	AM PM	16	GW			X		X	X	X		X					
		AM PM																
		AM PM																

Samples Relinquished By (Print Name and Sign): Steven Androchuk	Date: 12/1/21	Time: 6:40 PM	Samples Received By (Print Name and Sign): UEAC	Date:	Time:	'21 DEC 1 6:47 PM	
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:	Page ____ of ____	
Samples Relinquished By (Print Name and Sign):	Date:	Time:	Samples Received By (Print Name and Sign):	Date:	Time:	N°: T 127950	

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Marsad Jafar
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T839088
TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor
WATER ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer
DATE REPORTED: Dec 15, 2021
PAGES (INCLUDING COVER): 20
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - OC Pesticides + PCBs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-02
Parameter	Unit	G / S	RDL	3296850
Gamma-Hexachlorocyclohexane	ug/L	0.01	0.01	<0.01
Heptachlor	ug/L	0.01	0.01	<0.01
Aldrin	ug/L	0.01	0.01	<0.01
Heptachlor Epoxide	ug/L	0.01	0.01	<0.01
Endosulfan I	µg/L		0.05	<0.05
Endosulfan II	µg/L		0.05	<0.05
Endosulfan	ug/L	0.05	0.05	<0.05
alpha - chlordane	µg/L		0.1	<0.1
gamma-Chlordane	µg/L		0.2	<0.2
Chlordane	ug/L	0.06	0.04	<0.04
op'-DDE	µg/L		0.01	<0.01
pp'-DDE	µg/L		0.01	<0.01
DDE	ug/L		0.01	<0.01
op'-DDD	µg/L		0.05	<0.05
pp'-DDD	µg/L		0.05	<0.05
DDD	ug/L	1.8	0.05	<0.05
op'-DDT	µg/L		0.04	<0.04
pp'-DDT	µg/L		0.05	<0.05
DDT	ug/L		0.04	<0.04
Dieldrin	ug/L	0.05	0.02	<0.02
Endrin	ug/L	0.05	0.05	<0.05
Methoxychlor	ug/L	0.05	0.04	<0.04
Hexachlorobenzene	ug/L	0.01	0.01	<0.01
Hexachlorobutadiene	ug/L	0.01	0.01	<0.01
Hexachloroethane	ug/L	0.01	0.01	<0.01
Aroclor 1242	ug/L		0.1	<0.1
Aroclor 1248	ug/L		0.1	<0.1
Aroclor 1254	ug/L		0.1	<0.1
Aroclor 1260	ug/L		0.1	<0.1
Polychlorinated Biphenyls	ug/L	0.2	0.1	<0.1

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - OC Pesticides + PCBs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:	BH21-7
		SAMPLE TYPE:	Water
		DATE SAMPLED:	2021-12-02
Surrogate	Unit	Acceptable Limits	3296850
TCMX	%	50-140	73
Decachlorobiphenyl	%	50-140	101

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850 DDT total is a calculated parameter. The calculated value is the sum of op'DDT and pp'DDT.
DDD total is a calculated parameter. The calculated value is the sum of op'DDD and pp'DDD.
DDE total is a calculated parameter. The calculated value is the sum of op'DDE and pp'DDE.
Endosulfan total is a calculated parameter. The calculated value is the sum of Endosulfan I and Endosulfan II.
Chlordane total is a calculated parameter. The calculated value is the sum of Alpha-Chlordane and Gamma-Chlordane.
PCB total is a calculated parameter. The calculated value is the sum of Aroclor 1242, Aroclor 1248, Aroclor 1254 and Aroclor 1260.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PAHs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7	BH21-8	QAQC-2
		SAMPLE TYPE:		Water	Water	Water
		DATE SAMPLED:		2021-12-02	2021-12-02	2021-12-02
Parameter	Unit	G / S	RDL	3296850	3296853	3296858
Naphthalene	µg/L	7	0.20	<0.20	<0.20	<0.20
Acenaphthylene	µg/L	1	0.20	<0.20	<0.20	<0.20
Acenaphthene	µg/L	4.1	0.20	<0.20	<0.20	<0.20
Fluorene	µg/L	120	0.20	<0.20	<0.20	<0.20
Phenanthrene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Anthracene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Fluoranthene	µg/L	0.4	0.20	<0.20	<0.20	<0.20
Pyrene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Benzo(a)anthracene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Chrysene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Benzo(b)fluoranthene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Benzo(k)fluoranthene	µg/L	0.1	0.10	<0.10	<0.10	<0.10
Benzo(a)pyrene	µg/L	0.01	0.01	<0.01	<0.01	<0.01
Indeno(1,2,3-cd)pyrene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Dibenz(a,h)anthracene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Benzo(g,h,i)perylene	µg/L	0.2	0.20	<0.20	<0.20	<0.20
2-and 1-methyl Naphthalene	µg/L	2	0.20	<0.20	<0.20	<0.20
Sediment				No	No	No
Surrogate	Unit	Acceptable Limits				
Naphthalene-d8	%	50-140		78	109	105
Acridine-d9	%	50-140		82	83	83
Terphenyl-d14	%	50-140		99	92	77

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850-3296858 Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&(j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7	BH21-8
		SAMPLE TYPE:		Water	Water
		DATE SAMPLED:		2021-12-02	2021-12-02
Parameter	Unit	G / S	RDL	3296850	3296853
F1 (C6-C10)	µg/L	420	25	<25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25	<25
F2 (C10 to C16)	µg/L	150	100	<100	<100
F2 (C10 to C16) minus Naphthalene	µg/L		100	<100	<100
F3 (C16 to C34)	µg/L	500	100	<100	<100
F3 (C16 to C34) minus PAHs	µg/L		100	<100	<100
F4 (C34 to C50)	µg/L	500	100	<100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA	NA
Sediment				NO	NO
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	50-140		101	71.2
Terphenyl	% Recovery	60-140		79	85

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850-3296853 The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1/BTEX (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		QAQC-1
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-02
Parameter	Unit	G / S	RDL	3296855
Benzene	µg/L	0.5	0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20
Ethylbenzene	µg/L	0.5	0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20
o-Xylene	µg/L		0.10	<0.10
Xylenes (Total)	µg/L	72	0.20	<0.20
F1 (C6-C10)	µg/L	420	25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	60-140		71.8

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296855 The C6-C10 fraction is calculated using Toluene response factor.
Total C6-C10 results are corrected for BTEX contributions.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
Extraction and holding times were met for this sample.
NA = Not Applicable

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

SAMPLE DESCRIPTION:				BH21-7	BH21-8
SAMPLE TYPE:				Water	Water
DATE SAMPLED:				2021-12-02	2021-12-02
Parameter	Unit	G / S	RDL	3296850	3296853
Dichlorodifluoromethane	µg/L	590	0.20	<0.20	<0.20
Vinyl Chloride	µg/L	0.5	0.17	<0.17	<0.17
Bromomethane	µg/L	0.89	0.20	<0.20	<0.20
Trichlorofluoromethane	µg/L	150	0.40	<0.40	<0.40
Acetone	µg/L	2700	1.0	<1.0	<1.0
1,1-Dichloroethylene	µg/L	0.5	0.30	<0.30	<0.30
Methylene Chloride	µg/L	5	0.30	<0.30	<0.30
trans- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20
Methyl tert-butyl ether	µg/L	15	0.20	<0.20	<0.20
1,1-Dichloroethane	µg/L	0.5	0.30	<0.30	<0.30
Methyl Ethyl Ketone	µg/L	400	1.0	<1.0	<1.0
cis- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20
Chloroform	µg/L	2	0.20	<0.20	<0.20
1,2-Dichloroethane	µg/L	0.5	0.20	<0.20	<0.20
1,1,1-Trichloroethane	µg/L	0.5	0.30	<0.30	<0.30
Carbon Tetrachloride	µg/L	0.2	0.20	<0.20	<0.20
Benzene	µg/L	0.5	0.20	<0.20	<0.20
1,2-Dichloropropane	µg/L	0.5	0.20	<0.20	<0.20
Trichloroethylene	µg/L	0.5	0.20	<0.20	<0.20
Bromodichloromethane	µg/L	2	0.20	<0.20	<0.20
Methyl Isobutyl Ketone	µg/L	640	1.0	<1.0	<1.0
1,1,2-Trichloroethane	µg/L	0.5	0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20
Dibromochloromethane	µg/L	2	0.10	<0.10	<0.10
Ethylene Dibromide	µg/L	0.2	0.10	<0.10	<0.10
Tetrachloroethylene	µg/L	0.5	0.20	<0.20	<0.20
1,1,1,2-Tetrachloroethane	µg/L	1.1	0.10	<0.10	<0.10
Chlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20	<0.20

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7	BH21-8
		SAMPLE TYPE:		Water	Water
		DATE SAMPLED:		2021-12-02	2021-12-02
Parameter	Unit	G / S	RDL	3296850	3296853
Bromoform	µg/L	5	0.10	<0.10	<0.10
Styrene	µg/L	0.5	0.10	<0.10	<0.10
1,1,2,2-Tetrachloroethane	µg/L	0.5	0.10	<0.10	<0.10
o-Xylene	µg/L		0.10	<0.10	<0.10
1,3-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
1,4-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
1,2-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10
1,3-Dichloropropene	µg/L	0.5	0.30	<0.30	<0.30
Xylenes (Total)	µg/L	72	0.20	<0.20	<0.20
n-Hexane	µg/L	5	0.20	<0.20	<0.20
Surrogate	Unit	Acceptable Limits			
Toluene-d8	% Recovery	50-140		69	86
4-Bromofluorobenzene	% Recovery	50-140		101	96

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850-3296853 Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-7		BH21-8
		SAMPLE TYPE:		Water		Water
		DATE SAMPLED:		2021-12-02		2021-12-02
Parameter	Unit	G / S	RDL	3296850	RDL	3296853
Dissolved Antimony	µg/L	1.5	1.0	<1.0	1.0	<1.0
Dissolved Arsenic	µg/L	13	1.0	<1.0	1.0	4.3
Dissolved Barium	µg/L	610	2.0	254	2.0	109
Dissolved Beryllium	µg/L	0.5	0.50	<0.50	0.50	<0.50
Dissolved Boron	µg/L	1700	10.0	362	10.0	131
Dissolved Cadmium	µg/L	0.5	0.20	<0.20	0.20	<0.20
Dissolved Chromium	µg/L	11	2.0	<2.0	2.0	<2.0
Dissolved Cobalt	µg/L	3.8	0.50	0.52	0.50	0.63
Dissolved Copper	µg/L	5	1.0	1.9	1.0	<1.0
Dissolved Lead	µg/L	1.9	0.50	<0.50	0.50	<0.50
Dissolved Molybdenum	µg/L	23	0.50	14.2	0.50	7.84
Dissolved Nickel	µg/L	14	1.0	2.8	1.0	9.7
Dissolved Selenium	µg/L	5	1.0	<1.0	1.0	<1.0
Dissolved Silver	µg/L	0.3	0.20	<0.20	0.20	<0.20
Dissolved Thallium	µg/L	0.5	0.30	<0.30	0.30	<0.30
Dissolved Uranium	µg/L	8.9	0.50	3.19	0.50	1.11
Dissolved Vanadium	µg/L	3.9	0.40	1.42	0.40	0.62
Dissolved Zinc	µg/L	160	5.0	<5.0	5.0	<5.0
Mercury	µg/L	0.1	0.02	<0.02	0.02	<0.02
Chromium VI	µg/L	25	2	<2	2	<2
Cyanide, Free	µg/L	5	2	<2	2	<2
Dissolved Sodium	µg/L	490000	250	417000	50	23000
Chloride	µg/L	790000	100	768000	100	72700
Electrical Conductivity	uS/cm	NA	2	2900	2	934
pH	pH Units		NA	7.97	NA	7.99

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3296850-3296853 Metals analysis completed on a filtered sample.

Dilution required, RDL has been increased accordingly.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)															
F1 (C6-C10)	3300342		<25	<25	NA	< 25	120%	60%	140%	106%	60%	140%	101%	60%	140%
F2 (C10 to C16)	3296850	3296850	< 100	< 100	NA	< 100	78%	60%	140%	74%	60%	140%	71%	60%	140%
F3 (C16 to C34)	3296850	3296850	< 100	< 100	NA	< 100	84%	60%	140%	76%	60%	140%	75%	60%	140%
F4 (C34 to C50)	3296850	3296850	< 100	< 100	NA	< 100	79%	60%	140%	75%	60%	140%	76%	60%	140%
O. Reg. 153(511) - PAHs (Water)															
Naphthalene	3253224		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	78%	50%	140%	77%	50%	140%
Acenaphthylene	3253224		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	82%	50%	140%	107%	50%	140%
Acenaphthene	3253224		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	71%	50%	140%	81%	50%	140%
Fluorene	3253224		< 0.20	< 0.20	NA	< 0.20	86%	50%	140%	92%	50%	140%	92%	50%	140%
Phenanthrene	3253224		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	88%	50%	140%	85%	50%	140%
Anthracene	3253224		< 0.10	< 0.10	NA	< 0.10	85%	50%	140%	93%	50%	140%	78%	50%	140%
Fluoranthene	3253224		< 0.20	< 0.20	NA	< 0.20	99%	50%	140%	96%	50%	140%	93%	50%	140%
Pyrene	3253224		< 0.20	< 0.20	NA	< 0.20	78%	50%	140%	96%	50%	140%	99%	50%	140%
Benzo(a)anthracene	3253224		< 0.20	< 0.20	NA	< 0.20	96%	50%	140%	94%	50%	140%	96%	50%	140%
Chrysene	3253224		< 0.10	< 0.10	NA	< 0.10	86%	50%	140%	114%	50%	140%	84%	50%	140%
Benzo(b)fluoranthene	3253224		< 0.10	< 0.10	NA	< 0.10	92%	50%	140%	76%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3253224		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	92%	50%	140%	78%	50%	140%
Benzo(a)pyrene	3253224		< 0.01	< 0.01	NA	< 0.01	78%	50%	140%	105%	50%	140%	101%	50%	140%
Indeno(1,2,3-cd)pyrene	3253224		< 0.20	< 0.20	NA	< 0.20	92%	50%	140%	108%	50%	140%	105%	50%	140%
Dibenz(a,h)anthracene	3253224		< 0.20	< 0.20	NA	< 0.20	95%	50%	140%	75%	50%	140%	72%	50%	140%
Benzo(g,h,i)perylene	3253224		< 0.20	< 0.20	NA	< 0.20	91%	50%	140%	85%	50%	140%	105%	50%	140%
O. Reg. 153(511) - OC Pesticides + PCBs (Water)															
Gamma-Hexachlorocyclohexane	3287115		< 0.01	< 0.01	NA	< 0.01	102%	50%	140%	98%	50%	140%	98%	50%	140%
Heptachlor	3287115		< 0.01	< 0.01	NA	< 0.01	110%	50%	140%	102%	50%	140%	102%	50%	140%
Aldrin	3287115		< 0.01	< 0.01	NA	< 0.01	103%	50%	140%	102%	50%	140%	112%	50%	140%
Heptachlor Epoxide	3287115		< 0.01	< 0.01	NA	< 0.01	109%	50%	140%	104%	50%	140%	104%	50%	140%
Endosulfan I	3287115		< 0.05	< 0.05	NA	< 0.05	108%	50%	140%	102%	50%	140%	106%	50%	140%
Endosulfan II	3287115		< 0.05	< 0.05	NA	< 0.05	113%	50%	140%	99%	50%	140%	92%	50%	140%
alpha - chlordane	3287115		< 0.1	< 0.1	NA	< 0.1	103%	50%	140%	103%	50%	140%	114%	50%	140%
gamma-Chlordane	3287115		< 0.2	< 0.2	NA	< 0.2	105%	50%	140%	102%	50%	140%	112%	50%	140%
op'-DDE	3287115		< 0.01	< 0.01	NA	< 0.01	96%	50%	140%	108%	50%	140%	109%	50%	140%
pp'-DDE	3287115		< 0.01	< 0.01	NA	< 0.01	100%	50%	140%	101%	50%	140%	110%	50%	140%
op'-DDD	3287115		< 0.05	< 0.05	NA	< 0.05	113%	50%	140%	109%	50%	140%	109%	50%	140%
pp'-DDD	3287115		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	104%	50%	140%	112%	50%	140%
op'-DDT	3287115		< 0.04	< 0.04	NA	< 0.04	102%	50%	140%	107%	50%	140%	106%	50%	140%
pp'-DDT	3287115		< 0.05	< 0.05	NA	< 0.05	91%	50%	140%	92%	50%	140%	107%	50%	140%
Dieldrin	3287115		< 0.02	< 0.02	NA	< 0.02	102%	50%	140%	109%	50%	140%	113%	50%	140%
Endrin	3287115		< 0.05	< 0.05	NA	< 0.05	109%	50%	140%	103%	50%	140%	110%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis (Continued)

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Methoxychlor	3287115		< 0.04	< 0.04	NA	< 0.04	92%	50%	140%	88%	50%	140%	96%	50%	140%
Hexachlorobenzene	3287115		< 0.01	< 0.01	NA	< 0.01	97%	50%	140%	96%	50%	140%	98%	50%	140%
Hexachlorobutadiene	3287115		< 0.01	< 0.01	NA	< 0.01	92%	50%	140%	97%	50%	140%	94%	50%	140%
Hexachloroethane	3287115		< 0.01	< 0.01	NA	< 0.01	87%	50%	140%	103%	50%	140%	90%	50%	140%
Aroclor 1242	3287115		< 0.1	< 0.1	NA	< 0.1	NA	60%	140%	NA	60%	140%	NA	60%	140%
Aroclor 1248	3287115		< 0.1	< 0.1	NA	< 0.1	NA	60%	140%	NA	60%	140%	NA	60%	140%
Aroclor 1254	3287115		< 0.1	< 0.1	NA	< 0.1	NA	60%	140%	NA	60%	140%	NA	60%	140%
Aroclor 1260	3287115		< 0.1	< 0.1	NA	< 0.1	NA	60%	140%	NA	60%	140%	NA	60%	140%
Polychlorinated Biphenyls	3287115		< 0.1	< 0.1	NA	< 0.1	95%	60%	140%	89%	60%	140%	98%	60%	140%
O. Reg. 153(511) - VOCs (Water)															
Dichlorodifluoromethane	3268642		< 0.20	< 0.20	NA	< 0.20	91%	50%	140%	95%	50%	140%	94%	50%	140%
Vinyl Chloride	3268642		< 0.17	< 0.17	NA	< 0.17	96%	50%	140%	102%	50%	140%	85%	50%	140%
Bromomethane	3268642		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	83%	50%	140%	85%	50%	140%
Trichlorofluoromethane	3268642		< 0.40	< 0.40	NA	< 0.40	87%	50%	140%	79%	50%	140%	91%	50%	140%
Acetone	3268642		< 1.0	< 1.0	NA	< 1.0	96%	50%	140%	100%	50%	140%	103%	50%	140%
1,1-Dichloroethylene	3268642		< 0.30	< 0.30	NA	< 0.30	93%	50%	140%	73%	60%	130%	100%	50%	140%
Methylene Chloride	3268642		< 0.30	< 0.30	NA	< 0.30	120%	50%	140%	120%	60%	130%	84%	50%	140%
trans- 1,2-Dichloroethylene	3268642		< 0.20	< 0.20	NA	< 0.20	97%	50%	140%	120%	60%	130%	84%	50%	140%
Methyl tert-butyl ether	3268642		< 0.20	< 0.20	NA	< 0.20	95%	50%	140%	117%	60%	130%	87%	50%	140%
1,1-Dichloroethane	3268642		< 0.30	< 0.30	NA	< 0.30	85%	50%	140%	110%	60%	130%	73%	50%	140%
Methyl Ethyl Ketone	3268642		< 1.0	< 1.0	NA	< 1.0	98%	50%	140%	101%	50%	140%	97%	50%	140%
cis- 1,2-Dichloroethylene	3268642		< 0.20	< 0.20	NA	< 0.20	79%	50%	140%	107%	60%	130%	118%	50%	140%
Chloroform	3268642		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	101%	60%	130%	89%	50%	140%
1,2-Dichloroethane	3268642		< 0.20	< 0.20	NA	< 0.20	116%	50%	140%	97%	60%	130%	81%	50%	140%
1,1,1-Trichloroethane	3268642		< 0.30	< 0.30	NA	< 0.30	111%	50%	140%	85%	60%	130%	112%	50%	140%
Carbon Tetrachloride	3268642		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	120%	60%	130%	84%	50%	140%
Benzene	3268642		< 0.20	< 0.20	NA	< 0.20	87%	50%	140%	106%	60%	130%	94%	50%	140%
1,2-Dichloropropane	3268642		< 0.20	< 0.20	NA	< 0.20	111%	50%	140%	97%	60%	130%	100%	50%	140%
Trichloroethylene	3268642		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	98%	60%	130%	111%	50%	140%
Bromodichloromethane	3268642		< 0.20	< 0.20	NA	< 0.20	116%	50%	140%	107%	60%	130%	99%	50%	140%
Methyl Isobutyl Ketone	3268642		< 1.0	< 1.0	NA	< 1.0	109%	50%	140%	103%	50%	140%	100%	50%	140%
1,1,2-Trichloroethane	3268642		< 0.20	< 0.20	NA	< 0.20	117%	50%	140%	97%	60%	130%	78%	50%	140%
Toluene	3268642		< 0.20	< 0.20	NA	< 0.20	100%	50%	140%	75%	60%	130%	120%	50%	140%
Dibromochloromethane	3268642		< 0.10	< 0.10	NA	< 0.10	116%	50%	140%	110%	60%	130%	105%	50%	140%
Ethylene Dibromide	3268642		< 0.10	< 0.10	NA	< 0.10	111%	50%	140%	91%	60%	130%	93%	50%	140%
Tetrachloroethylene	3268642		< 0.20	< 0.20	NA	< 0.20	104%	50%	140%	91%	60%	130%	87%	50%	140%
1,1,1,2-Tetrachloroethane	3268642		< 0.10	< 0.10	NA	< 0.10	105%	50%	140%	86%	60%	130%	104%	50%	140%
Chlorobenzene	3268642		< 0.10	< 0.10	NA	< 0.10	89%	50%	140%	70%	60%	130%	97%	50%	140%
Ethylbenzene	3268642		< 0.10	< 0.10	NA	< 0.10	74%	50%	140%	87%	60%	130%	80%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839088
PROJECT: 211-10139-00
ATTENTION TO: Marsad Jafar
SAMPLING SITE:
SAMPLED BY:

Trace Organics Analysis (Continued)

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
m & p-Xylene	3268642		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	92%	60%	130%	90%	50%	140%
Bromoform	3268642		< 0.10	< 0.10	NA	< 0.10	106%	50%	140%	84%	60%	130%	88%	50%	140%
Styrene	3268642		< 0.10	< 0.10	NA	< 0.10	76%	50%	140%	82%	60%	130%	70%	50%	140%
1,1,2,2-Tetrachloroethane	3268642		< 0.10	< 0.10	NA	< 0.10	94%	50%	140%	77%	60%	130%	84%	50%	140%
o-Xylene	3268642		< 0.10	< 0.10	NA	< 0.10	78%	50%	140%	78%	60%	130%	79%	50%	140%
1,3-Dichlorobenzene	3268642		< 0.10	< 0.10	NA	< 0.10	95%	50%	140%	78%	60%	130%	73%	50%	140%
1,4-Dichlorobenzene	3268642		< 0.10	< 0.10	NA	< 0.10	101%	50%	140%	78%	60%	130%	81%	50%	140%
1,2-Dichlorobenzene	3268642		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	80%	60%	130%	78%	50%	140%
n-Hexane	3268642		< 0.20	< 0.20	NA	< 0.20	93%	50%	140%	95%	60%	130%	117%	50%	140%
Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).															
O. Reg. 153(511) - PHCs F1/BTEX (Water)															
Benzene	3300342		<0.20	<0.20	NA	< 0.20	90%	60%	140%	85%	60%	140%	104%	60%	140%
Toluene	3300342		<0.20	<0.20	NA	< 0.20	85%	60%	140%	81%	60%	140%	93%	60%	140%
Ethylbenzene	3300342		<0.10	<0.10	NA	< 0.10	85%	60%	140%	84%	60%	140%	96%	60%	140%
m & p-Xylene	3300342		<0.20	<0.20	NA	< 0.20	91%	60%	140%	103%	60%	140%	106%	60%	140%
o-Xylene	3300342		<0.10	<0.10	NA	< 0.10	104%	60%	140%	82%	60%	140%	119%	60%	140%
F1 (C6-C10)	3300342		<25	<25	NA	< 25	120%	60%	140%	106%	60%	140%	101%	60%	140%

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839088
PROJECT: 211-10139-00
ATTENTION TO: Marsad Jafar
SAMPLING SITE:
SAMPLED BY:

Water Analysis

RPT Date: Dec 15, 2021

PARAMETER	Batch	Sample Id	DUPLICATE Dup #1	DUPLICATE Dup #2	DUPLICATE RPD	Method Blank	REFERENCE MATERIAL Measured Value	REFERENCE MATERIAL Acceptable Limits Lower	REFERENCE MATERIAL Acceptable Limits Upper	METHOD BLANK SPIKE Recovery	METHOD BLANK SPIKE Acceptable Limits Lower	METHOD BLANK SPIKE Acceptable Limits Upper	MATRIX SPIKE Recovery	MATRIX SPIKE Acceptable Limits Lower	MATRIX SPIKE Acceptable Limits Upper
O. Reg. 153(511) - Metals & Inorganics (Water)															
Dissolved Antimony	3295669		< 1.0	< 1.0	0.0%	< 1.0	99%	70%	130%	105%	80%	120%	101%	70%	130%
Dissolved Arsenic	3295669		1.1	1.1	NA	< 1.0	95%	70%	130%	104%	80%	120%	108%	70%	130%
Dissolved Barium	3295669		268	264	1.5%	< 2.0	102%	70%	130%	104%	80%	120%	75%	70%	130%
Dissolved Beryllium	3295669		< 0.50	< 0.50	0.0%	< 0.50	106%	70%	130%	116%	80%	120%	112%	70%	130%
Dissolved Boron	3295669		126	121	4.6%	< 10.0	103%	70%	130%	114%	80%	120%	102%	70%	130%
Dissolved Cadmium	3295669		< 0.20	< 0.20	0.0%	< 0.20	100%	70%	130%	105%	80%	120%	108%	70%	130%
Dissolved Chromium	3295669		< 2.0	< 2.0	0.0%	< 2.0	100%	70%	130%	102%	80%	120%	105%	70%	130%
Dissolved Cobalt	3295669		5.36	4.56	16.1%	< 0.50	103%	70%	130%	102%	80%	120%	105%	70%	130%
Dissolved Copper	3295669		< 1.0	< 1.0	0.0%	< 1.0	100%	70%	130%	99%	80%	120%	108%	70%	130%
Dissolved Lead	3295669		< 0.50	< 0.50	0.0%	< 0.50	100%	70%	130%	103%	80%	120%	108%	70%	130%
Dissolved Molybdenum	3295669		< 0.50	< 0.50	0.0%	< 0.50	101%	70%	130%	106%	80%	120%	112%	70%	130%
Dissolved Nickel	3295669		8.5	7.9	7.3%	< 1.0	102%	70%	130%	107%	80%	120%	103%	70%	130%
Dissolved Selenium	3295669		< 1.0	< 1.0	0.0%	< 1.0	100%	70%	130%	111%	80%	120%	106%	70%	130%
Dissolved Silver	3295669		< 0.20	< 0.20	0.0%	< 0.20	100%	70%	130%	103%	80%	120%	109%	70%	130%
Dissolved Thallium	3295669		< 0.30	< 0.30	0.0%	< 0.30	98%	70%	130%	100%	80%	120%	104%	70%	130%
Dissolved Uranium	3295669		1.28	1.23	NA	< 0.50	105%	70%	130%	113%	80%	120%	115%	70%	130%
Dissolved Vanadium	3295669		<0.40	0.61	NA	< 0.40	101%	70%	130%	103%	80%	120%	105%	70%	130%
Dissolved Zinc	3295669		5.3	<5.0	NA	< 5.0	103%	70%	130%	99%	80%	120%	112%	70%	130%
Mercury	3295007		<0.02	<0.02	NA	< 0.02	104%	70%	130%	101%	80%	120%	93%	70%	130%
Chromium VI	3285019		<2	<2	NA	< 2	103%	70%	130%	104%	80%	120%	110%	70%	130%
Cyanide, Free	3275528		<2	<2	NA	< 2	107%	70%	130%	103%	80%	120%	87%	70%	130%
Dissolved Sodium	3296853	3296853	23000	23100	0.5%	< 50	97%	70%	130%	99%	80%	120%	97%	70%	130%
Chloride	3285316		120000	118000	1.5%	< 100	98%	70%	130%	103%	80%	120%	106%	70%	130%
Electrical Conductivity	3295423		976	964	1.2%	< 2	104%	90%	110%						
pH	3295423		7.68	7.78	1.3%	NA	102%	90%	110%						

Comments: NA signifies Not Applicable.
Duplicate NA: results are under 5X the RDL and will not be calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Gamma-Hexachlorocyclohexane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Heptachlor	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Aldrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Heptachlor Epoxide	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan I	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan II	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endosulfan	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
alpha - chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
gamma-Chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Chlordane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDE	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDD	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
op'-DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
pp'-DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
DDT	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	CALCULATION
Dieldrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Endrin	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Methoxychlor	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachlorobenzene	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachlorobutadiene	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Hexachloroethane	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Aroclor 1242	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Aroclor 1248	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Aroclor 1254	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Aroclor 1260	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
Polychlorinated Biphenyls	ORG-91-5112	modified from EPA SW-846 3510C & 8082A	GC/ECD
TCMX	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Decachlorobiphenyl	ORG-91-5112	modified from EPA SW-846 3510C & 8081B	GC/ECD
Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluorene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Chrysene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
2-and 1-methyl Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Sediment			
F1 (C6-C10)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
Toluene-d8	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F2 (C10 to C16) minus Naphthalene	VOL-91-5010	modified from MOE PHC-E3421	GC/FID

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC-E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Benzene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Toluene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5010	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F1 (C6-C10)	VOL-91-5010	modified from MOE E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE E3421	(P&T)GC/FID
Dichlorodifluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromomethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
trans- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl tert-butyl ether	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
cis- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Dibromochloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromoform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839088

PROJECT: 211-10139-00

ATTENTION TO: Marsad Jafar

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Water Analysis			
Dissolved Antimony	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Arsenic	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Barium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Beryllium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Boron	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cadmium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Chromium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cobalt	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Copper	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Lead	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Molybdenum	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Nickel	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Selenium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Silver	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Thallium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Uranium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Vanadium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Zinc	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Mercury	MET-93-6100	modified from EPA 245.2 and SM 3112 B	CVAAS
Chromium VI	INOR-93-6034	modified from SM 3500-CR B	LACHAT FIA
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Dissolved Sodium	MET-93-6105	modified from EPA 6010D	ICP/OES
Chloride	INOR-93-6004	modified from SM 4110 B	ION CHROMATOGRAPH
Electrical Conductivity	INOR-93-6000	SM 2510 B	PC TITRATE
pH	INOR-93-6000	modified from SM 4500-H+ B	PC TITRATE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP
Contact: Marsad Jafar
Address: 2 International Blvd, Toronto ON
Phone: 437-233-2935 Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: marsad.jafar@wsp.com

Project Information:

Project: 211-10139-00
Site Location: ORBY
Sampled By: Marsad Jafar
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☐ Ind/Com
☑ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ (Region)
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☐ Yes ☐ No

Laboratory Use Only

Work Order #: 21T839088
Cooler Quantity: 1 large black
Arrival Temperatures: 9.4 | 7.0 | 8.3
Custody Seal Intact: ☐ Yes ☐ No ☑ N/A
Notes: free ice

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply):
Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*
For 'Same Day' analysis, please contact your AGAT CPM

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	VOC	Potentially Hazardous or High Concentration (Y/N)
BH21-7	Dec 02/21	AM	19	GW	[redacted]		X		X		X	X	X					X	
BH21-8	Dec 02/21	AM	13	GW	VOC/BTEX limited sample		X		X		X		X						
QAQC-1	Dec 02/21	AM	3	GW					X										
QAQC-2	Dec 02/21	AM	2	GW							X								

21 DEC 2 3:47pm

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Marsad Jafar M.J	Dec 02/21	3:45 pm	Adriana Bellavia ABellavia		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

Page ____ of ____

N°: T 128321

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Document ID: DIV 78 1511 021

Date Issued: March 9, 2021

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Vanessa Oetinger
PROJECT: 211-10139-00
AGAT WORK ORDER: 21T839096
SOIL ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer
TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor
DATE REPORTED: Dec 15, 2021
PAGES (INCLUDING COVER): 20
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:


O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

SAMPLE DESCRIPTION:				BH21-2 SS2	BH21-3 SS1	QAQC-12	BH21-16 SS1
SAMPLE TYPE:				Soil	Soil	Soil	Soil
DATE SAMPLED:				2021-12-02	2021-12-02 12:00	2021-12-02 12:00	2021-12-01
Parameter	Unit	G / S	RDL	3293886	3293919	3293920	3293929
Antimony	µg/g	1.3	0.8	<0.8	<0.8	<0.8	2.8
Arsenic	µg/g	18	1	6	4	6	8
Barium	µg/g	220	2.0	89.8	77.5	52.7	88.5
Beryllium	µg/g	2.5	0.4	0.8	0.6	0.5	0.5
Boron	µg/g	36	5	10	8	7	9
Boron (Hot Water Soluble)	µg/g	NA	0.10	0.42	0.12	0.17	0.50
Cadmium	µg/g	1.2	0.5	<0.5	<0.5	<0.5	<0.5
Chromium	µg/g	70	5	20	17	15	35
Cobalt	µg/g	21	0.5	9.2	7.8	7.8	10.6
Copper	µg/g	92	1.0	42.9	24.8	33.3	69.0
Lead	µg/g	120	1	60	9	12	79
Molybdenum	µg/g	2	0.5	0.6	<0.5	<0.5	3.7
Nickel	µg/g	82	1	19	17	22	31
Selenium	µg/g	1.5	0.8	<0.8	<0.8	<0.8	0.8
Silver	µg/g	0.5	0.5	<0.5	<0.5	<0.5	<0.5
Thallium	µg/g	1	0.5	<0.5	<0.5	<0.5	<0.5
Uranium	µg/g	2.5	0.50	0.55	<0.50	<0.50	<0.50
Vanadium	µg/g	86	0.4	30.4	25.5	22.4	33.8
Zinc	µg/g	290	5	95	44	43	468
Chromium, Hexavalent	µg/g	0.66	0.2	<0.2	<0.2	<0.2	<0.2
Cyanide, Free	µg/g	0.051	0.040	<0.040	<0.040	<0.040	<0.040
Mercury	µg/g	0.27	0.10	<0.10	<0.10	<0.10	0.22
Electrical Conductivity (2:1)	mS/cm	0.57	0.005	0.353	0.216	0.185	0.290
Sodium Adsorption Ratio (2:1) (Calc.)	N/A	2.4	N/A	1.56	0.438	0.300	1.64
pH, 2:1 CaCl2 Extraction	pH Units		NA	7.29	7.25	7.32	7.50

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - Metals & Inorganics (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3293886-3293929 EC was determined on the DI water extract obtained from the 2:1 leaching procedure (2 parts DI water:1 part soil). pH was determined on the 0.01M CaCl2 extract prepared at 2:1 ratio. SAR is a calculated parameter.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PAHs (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-2 SS2	BH21-16 SS2	QAQC-10
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-12-02	2021-12-01	2021-12-01
Parameter	Unit	G / S	RDL	3293886	3293931	3293943
Naphthalene	µg/g		0.05	<0.05	<0.05	<0.05
Acenaphthylene	µg/g		0.05	<0.05	<0.05	<0.05
Acenaphthene	µg/g		0.05	<0.05	<0.05	<0.05
Fluorene	µg/g		0.05	<0.05	<0.05	<0.05
Phenanthrene	µg/g		0.05	<0.05	<0.05	<0.05
Anthracene	µg/g		0.05	<0.05	<0.05	<0.05
Fluoranthene	µg/g		0.05	<0.05	<0.05	<0.05
Pyrene	µg/g		0.05	<0.05	<0.05	<0.05
Benz(a)anthracene	µg/g		0.05	<0.05	<0.05	<0.05
Chrysene	µg/g		0.05	<0.05	<0.05	<0.05
Benzo(b)fluoranthene	µg/g		0.05	<0.05	<0.05	<0.05
Benzo(k)fluoranthene	µg/g		0.05	<0.05	<0.05	<0.05
Benzo(a)pyrene	µg/g		0.05	<0.05	<0.05	<0.05
Indeno(1,2,3-cd)pyrene	µg/g		0.05	<0.05	<0.05	<0.05
Dibenz(a,h)anthracene	µg/g		0.05	<0.05	<0.05	<0.05
Benzo(g,h,i)perylene	µg/g		0.05	<0.05	<0.05	<0.05
1 and 2 Methlynaphthalene	µg/g		0.05	<0.05	<0.05	<0.05
Moisture Content	%		0.1	20.3	17.9	15.8
Surrogate	Unit	Acceptable Limits				
Naphthalene-d8	%	50-140		78	108	106
Acridine-d9	%	50-140		93	75	93
Terphenyl-d14	%	50-140		92	96	94

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

3293886-3293943 Results are based on the dry weight of the soil.
Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (-BTEX) (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-16 SS8
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-12-01
Parameter	Unit	G / S	RDL	3293947
F1 (C6 - C10)	µg/g	25	5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5
F2 (C10 to C16)	µg/g	10	10	<10
F3 (C16 to C34)	µg/g	240	50	<50
F4 (C34 to C50)	µg/g	120	50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA
Moisture Content	%		0.1	9.3
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		95
Terphenyl	%	60-140		104

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3293947 Results are based on sample dry weight.
The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified without the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-2 SS5	BH21-3 SS6	BH21-6 SS6
		SAMPLE TYPE:		Soil	Soil	Soil
		DATE SAMPLED:		2021-12-02	2021-12-02 12:00	2021-12-01 12:00
Parameter	Unit	G / S	RDL	3293910	3293922	3293927
Benzene	µg/g	0.02	0.02	<0.02	<0.02	<0.02
Toluene	µg/g	0.2	0.05	<0.05	<0.05	<0.05
Ethylbenzene	µg/g	0.05	0.05	<0.05	<0.05	<0.05
m & p-Xylene	µg/g		0.05	<0.05	<0.05	<0.05
o-Xylene	µg/g		0.05	<0.05	<0.05	<0.05
Xylenes (Total)	µg/g	0.05	0.05	<0.05	<0.05	<0.05
F1 (C6 - C10)	µg/g	25	5	<5	<5	<5
F1 (C6 to C10) minus BTEX	µg/g	25	5	<5	<5	<5
F2 (C10 to C16)	µg/g	10	10	<10	<10	<10
F3 (C16 to C34)	µg/g	240	50	<50	<50	<50
F4 (C34 to C50)	µg/g	120	50	<50	<50	<50
Gravimetric Heavy Hydrocarbons	µg/g	120	50	NA	NA	NA
Moisture Content	%		0.1	22.0	17.6	12.7
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	60-140		90	99	108
Terphenyl	%	60-140		85	88	89

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - PHCs F1 - F4 (Soil)

DATE RECEIVED: 2021-12-02


DATE REPORTED: 2021-12-15

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3293910-3293927 Results are based on sample dry weight.
The C6-C10 fraction is calculated using Toluene response factor.
Xylenes is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153, results are considered valid without determining the PAH contribution if not requested by the client.
Quality Control Data is available upon request.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:


O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-16 SS8
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-12-01
Parameter	Unit	G / S	RDL	3293947
Dichlorodifluoromethane	µg/g	0.05	0.05	<0.05
Vinyl Chloride	ug/g	0.02	0.02	<0.02
Bromomethane	ug/g	0.05	0.05	<0.05
Trichlorofluoromethane	ug/g	0.25	0.05	<0.05
Acetone	ug/g	0.5	0.50	<0.50
1,1-Dichloroethylene	ug/g	0.05	0.05	<0.05
Methylene Chloride	ug/g	0.05	0.05	<0.05
Trans- 1,2-Dichloroethylene	ug/g	0.05	0.05	<0.05
Methyl tert-butyl Ether	ug/g	0.05	0.05	<0.05
1,1-Dichloroethane	ug/g	0.05	0.02	<0.02
Methyl Ethyl Ketone	ug/g	0.5	0.50	<0.50
Cis- 1,2-Dichloroethylene	ug/g	0.05	0.02	<0.02
Chloroform	ug/g	0.05	0.04	<0.04
1,2-Dichloroethane	ug/g	0.05	0.03	<0.03
1,1,1-Trichloroethane	ug/g	0.05	0.05	<0.05
Carbon Tetrachloride	ug/g	0.05	0.05	<0.05
Benzene	ug/g	0.02	0.02	<0.02
1,2-Dichloropropane	ug/g	0.05	0.03	<0.03
Trichloroethylene	ug/g	0.05	0.03	<0.03
Bromodichloromethane	ug/g	0.05	0.05	<0.05
Methyl Isobutyl Ketone	ug/g	0.5	0.50	<0.50
1,1,2-Trichloroethane	ug/g	0.05	0.04	<0.04
Toluene	ug/g	0.2	0.05	<0.05
Dibromochloromethane	ug/g	0.05	0.05	<0.05
Ethylene Dibromide	ug/g	0.05	0.04	<0.04
Tetrachloroethylene	ug/g	0.05	0.05	<0.05
1,1,1,2-Tetrachloroethane	ug/g	0.05	0.04	<0.04
Chlorobenzene	ug/g	0.05	0.05	<0.05
Ethylbenzene	ug/g	0.05	0.05	<0.05
m & p-Xylene	ug/g		0.05	<0.05

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

O. Reg. 153(511) - VOCs (Soil)

DATE RECEIVED: 2021-12-02

DATE REPORTED: 2021-12-15

		SAMPLE DESCRIPTION:		BH21-16 SS8
		SAMPLE TYPE:		Soil
		DATE SAMPLED:		2021-12-01
Parameter	Unit	G / S	RDL	3293947
Bromoform	ug/g	0.05	0.05	<0.05
Styrene	ug/g	0.05	0.05	<0.05
1,1,2,2-Tetrachloroethane	ug/g	0.05	0.05	<0.05
o-Xylene	ug/g		0.05	<0.05
1,3-Dichlorobenzene	ug/g	0.05	0.05	<0.05
1,4-Dichlorobenzene	ug/g	0.05	0.05	<0.05
1,2-Dichlorobenzene	ug/g	0.05	0.05	<0.05
Xylenes (Total)	ug/g	0.05	0.05	<0.05
1,3-Dichloropropene (Cis + Trans)	µg/g	0.05	0.04	<0.04
n-Hexane	µg/g	0.05	0.05	<0.05
Moisture Content	%		0.1	9.3
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		94
4-Bromofluorobenzene	% Recovery	50-140		71

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Soil - Residential/Parkland/Institutional/Industrial/Commercial/Community Property Use
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3293947 The sample was analyzed using the high level technique. The sample was extracted using methanol, a small amount of the methanol extract was diluted in water and the purge & trap GC/MS analysis was performed. Results are based on the dry weight of the soil.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene + o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Vanessa Oetinger

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3293929	BH21-16 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - Metals & Inorganics (Soil)	Antimony	µg/g	1.3	2.8
3293929	BH21-16 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - Metals & Inorganics (Soil)	Molybdenum	µg/g	2	3.7
3293929	BH21-16 SS1	ON T1 S RPI/ICC	O. Reg. 153(511) - Metals & Inorganics (Soil)	Zinc	µg/g	290	468

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839096
PROJECT: 211-10139-00
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:
SAMPLED BY:

Soil Analysis

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)															
Antimony	3296184		<0.8	<0.8	NA	< 0.8	134%	70%	130%	98%	80%	120%	92%	70%	130%
Arsenic	3296184		4	4	NA	< 1	113%	70%	130%	103%	80%	120%	107%	70%	130%
Barium	3296184		37.9	40.4	6.4%	< 2.0	112%	70%	130%	108%	80%	120%	108%	70%	130%
Beryllium	3296184		<0.4	<0.4	NA	< 0.4	102%	70%	130%	108%	80%	120%	109%	70%	130%
Boron	3296184		<5	<5	NA	< 5	89%	70%	130%	111%	80%	120%	112%	70%	130%
Boron (Hot Water Soluble)	3319050		0.40	0.39	NA	< 0.10	107%	60%	140%	105%	70%	130%	108%	60%	140%
Cadmium	3296184		0.7	0.8	NA	< 0.5	94%	70%	130%	102%	80%	120%	108%	70%	130%
Chromium	3296184		10	10	NA	< 5	99%	70%	130%	101%	80%	120%	110%	70%	130%
Cobalt	3296184		4.0	4.2	4.9%	< 0.5	103%	70%	130%	106%	80%	120%	106%	70%	130%
Copper	3296184		14.4	15.4	6.7%	< 1.0	100%	70%	130%	108%	80%	120%	110%	70%	130%
Lead	3296184		29	29	0.0%	< 1	103%	70%	130%	103%	80%	120%	99%	70%	130%
Molybdenum	3296184		<0.5	<0.5	NA	< 0.5	105%	70%	130%	104%	80%	120%	110%	70%	130%
Nickel	3296184		7	8	13.3%	< 1	101%	70%	130%	103%	80%	120%	102%	70%	130%
Selenium	3296184		<0.8	<0.8	NA	< 0.8	98%	70%	130%	98%	80%	120%	104%	70%	130%
Silver	3296184		<0.5	<0.5	NA	< 0.5	114%	70%	130%	102%	80%	120%	96%	70%	130%
Thallium	3296184		<0.5	<0.5	NA	< 0.5	99%	70%	130%	100%	80%	120%	96%	70%	130%
Uranium	3296184		<0.50	<0.50	NA	< 0.50	103%	70%	130%	100%	80%	120%	100%	70%	130%
Vanadium	3296184		17.6	19.0	7.7%	< 0.4	102%	70%	130%	101%	80%	120%	111%	70%	130%
Zinc	3296184		85	89	4.6%	< 5	102%	70%	130%	103%	80%	120%	112%	70%	130%
Chromium, Hexavalent	3309312		<0.2	<0.2	NA	< 0.2	102%	70%	130%	88%	80%	120%	81%	70%	130%
Cyanide, Free	3304561		<0.040	<0.040	NA	< 0.040	101%	70%	130%	97%	80%	120%	104%	70%	130%
Mercury	3296184		<0.10	<0.10	NA	< 0.10	103%	70%	130%	101%	80%	120%	101%	70%	130%
Electrical Conductivity (2:1)	3304572		0.176	0.163	7.7%	< 0.005	106%	80%	120%						
Sodium Adsorption Ratio (2:1) (Calc.)	3296184		0.060	0.062	3.3%	NA									
pH, 2:1 CaCl2 Extraction	3275481		6.60	6.84	3.6%	NA	101%	80%	120%						

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

Trace Organics Analysis

RPT Date: Dec 15, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PAHs (Soil)															
Naphthalene	3257319		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	105%	50%	140%	105%	50%	140%
Acenaphthylene	3257319		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	83%	50%	140%	98%	50%	140%
Acenaphthene	3257319		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	92%	50%	140%	83%	50%	140%
Fluorene	3257319		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	94%	50%	140%	88%	50%	140%
Phenanthrene	3257319		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	98%	50%	140%	74%	50%	140%
Anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	86%	50%	140%	82%	50%	140%
Fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	68%	50%	140%	88%	50%	140%	91%	50%	140%
Pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	84%	50%	140%	74%	50%	140%	107%	50%	140%
Benz(a)anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	80%	50%	140%	85%	50%	140%	87%	50%	140%
Chrysene	3257319		< 0.05	< 0.05	NA	< 0.05	95%	50%	140%	90%	50%	140%	85%	50%	140%
Benzo(b)fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	88%	50%	140%	105%	50%	140%	96%	50%	140%
Benzo(k)fluoranthene	3257319		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	98%	50%	140%	105%	50%	140%
Benzo(a)pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	92%	50%	140%	86%	50%	140%	98%	50%	140%
Indeno(1,2,3-cd)pyrene	3257319		< 0.05	< 0.05	NA	< 0.05	105%	50%	140%	88%	50%	140%	86%	50%	140%
Dibenz(a,h)anthracene	3257319		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	74%	50%	140%	88%	50%	140%
Benzo(g,h,i)perylene	3257319		< 0.05	< 0.05	NA	< 0.05	86%	50%	140%	82%	50%	140%	80%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (Soil)															
Benzene	3296192		<0.02	<0.02	NA	< 0.02	83%	60%	140%	87%	60%	140%	103%	60%	140%
Toluene	3296192		<0.05	<0.05	NA	< 0.05	100%	60%	140%	102%	60%	140%	81%	60%	140%
Ethylbenzene	3296192		<0.05	<0.05	NA	< 0.05	108%	60%	140%	112%	60%	140%	75%	60%	140%
m & p-Xylene	3296192		<0.05	<0.05	NA	< 0.05	98%	60%	140%	98%	60%	140%	105%	60%	140%
o-Xylene	3296192		<0.05	<0.05	NA	< 0.05	117%	60%	140%	105%	60%	140%	101%	60%	140%
F1 (C6 - C10)	3296192		<5	<5	NA	< 5	102%	60%	140%	99%	60%	140%	100%	60%	140%
F2 (C10 to C16)	3253580		47	44	NA	< 10	102%	60%	140%	85%	60%	140%	85%	60%	140%
F3 (C16 to C34)	3253580		870	650	28.9%	< 50	106%	60%	140%	86%	60%	140%	95%	60%	140%
F4 (C34 to C50)	3253580		170	790	NA	< 50	115%	60%	140%	78%	60%	140%	74%	60%	140%
O. Reg. 153(511) - VOCs (Soil)															
Dichlorodifluoromethane	3290917		< 0.05	< 0.05	NA	< 0.05	97%	50%	140%	73%	50%	140%	79%	50%	140%
Vinyl Chloride	3290917		< 0.02	< 0.02	NA	< 0.02	108%	50%	140%	80%	50%	140%	95%	50%	140%
Bromomethane	3290917		< 0.05	< 0.05	NA	< 0.05	94%	50%	140%	91%	50%	140%	96%	50%	140%
Trichlorofluoromethane	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	87%	50%	140%	99%	50%	140%
Acetone	3290917		< 0.50	< 0.50	NA	< 0.50	104%	50%	140%	103%	50%	140%	103%	50%	140%
1,1-Dichloroethylene	3290917		< 0.05	< 0.05	NA	< 0.05	113%	50%	140%	90%	60%	130%	107%	50%	140%
Methylene Chloride	3290917		< 0.05	< 0.05	NA	< 0.05	117%	50%	140%	119%	60%	130%	85%	50%	140%
Trans- 1,2-Dichloroethylene	3290917		< 0.05	< 0.05	NA	< 0.05	100%	50%	140%	92%	60%	130%	97%	50%	140%
Methyl tert-butyl Ether	3290917		< 0.05	< 0.05	NA	< 0.05	117%	50%	140%	108%	60%	130%	107%	50%	140%
1,1-Dichloroethane	3290917		< 0.02	< 0.02	NA	< 0.02	107%	50%	140%	88%	60%	130%	101%	50%	140%
Methyl Ethyl Ketone	3290917		< 0.50	< 0.50	NA	< 0.50	96%	50%	140%	102%	50%	140%	101%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
AGAT WORK ORDER: 21T839096
PROJECT: 211-10139-00
ATTENTION TO: Vanessa Oetinger
SAMPLING SITE:
SAMPLED BY:

Trace Organics Analysis (Continued)

RPT Date: Dec 15, 2021

PARAMETER	Batch	Sample Id	DUPLICATE			Method Blank	REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
			Dup #1	Dup #2	RPD		Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Cis- 1,2-Dichloroethylene	3290917		< 0.02	< 0.02	NA	< 0.02	109%	50%	140%	113%	60%	130%	113%	50%	140%
Chloroform	3290917		< 0.04	< 0.04	NA	< 0.04	116%	50%	140%	112%	60%	130%	105%	50%	140%
1,2-Dichloroethane	3290917		< 0.03	< 0.03	NA	< 0.03	116%	50%	140%	112%	60%	130%	116%	50%	140%
1,1,1-Trichloroethane	3290917		< 0.05	< 0.05	NA	< 0.05	78%	50%	140%	96%	60%	130%	79%	50%	140%
Carbon Tetrachloride	3290917		< 0.05	< 0.05	NA	< 0.05	82%	50%	140%	80%	60%	130%	76%	50%	140%
Benzene	3290917		0.21	0.19	NA	< 0.02	118%	50%	140%	99%	60%	130%	111%	50%	140%
1,2-Dichloropropane	3290917		< 0.03	< 0.03	NA	< 0.03	102%	50%	140%	113%	60%	130%	87%	50%	140%
Trichloroethylene	3290917		< 0.03	< 0.03	NA	< 0.03	106%	50%	140%	96%	60%	130%	97%	50%	140%
Bromodichloromethane	3290917		< 0.05	< 0.05	NA	< 0.05	118%	50%	140%	117%	60%	130%	102%	50%	140%
Methyl Isobutyl Ketone	3290917		< 0.50	< 0.50	NA	< 0.50	94%	50%	140%	101%	50%	140%	97%	50%	140%
1,1,2-Trichloroethane	3290917		< 0.04	< 0.04	NA	< 0.04	111%	50%	140%	111%	60%	130%	116%	50%	140%
Toluene	3290917		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	104%	60%	130%	117%	50%	140%
Dibromochloromethane	3290917		< 0.05	< 0.05	NA	< 0.05	111%	50%	140%	110%	60%	130%	97%	50%	140%
Ethylene Dibromide	3290917		< 0.04	< 0.04	NA	< 0.04	110%	50%	140%	107%	60%	130%	108%	50%	140%
Tetrachloroethylene	3290917		< 0.05	< 0.05	NA	< 0.05	85%	50%	140%	77%	60%	130%	80%	50%	140%
1,1,1,2-Tetrachloroethane	3290917		< 0.04	< 0.04	NA	< 0.04	94%	50%	140%	97%	60%	130%	72%	50%	140%
Chlorobenzene	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	97%	60%	130%	89%	50%	140%
Ethylbenzene	3290917		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	75%	60%	130%	74%	50%	140%
m & p-Xylene	3290917		< 0.05	< 0.05	NA	< 0.05	93%	50%	140%	93%	60%	130%	94%	50%	140%
Bromoform	3290917		< 0.05	< 0.05	NA	< 0.05	115%	50%	140%	114%	60%	130%	92%	50%	140%
Styrene	3290917		< 0.05	< 0.05	NA	< 0.05	74%	50%	140%	71%	60%	130%	75%	50%	140%
1,1,2,2-Tetrachloroethane	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	95%	60%	130%	109%	50%	140%
o-Xylene	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	93%	60%	130%	88%	50%	140%
1,3-Dichlorobenzene	3290917		< 0.05	< 0.05	NA	< 0.05	102%	50%	140%	99%	60%	130%	113%	50%	140%
1,4-Dichlorobenzene	3290917		< 0.05	< 0.05	NA	< 0.05	98%	50%	140%	106%	60%	130%	115%	50%	140%
1,2-Dichlorobenzene	3290917		< 0.05	< 0.05	NA	< 0.05	117%	50%	140%	94%	60%	130%	103%	50%	140%
n-Hexane	3290917		< 0.05	< 0.05	NA	< 0.05	76%	50%	140%	88%	60%	130%	82%	50%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

QC Exceedance

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

RPT Date: Dec 15, 2021		REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Sample Id	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
			Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Soil)										
Antimony		134%	70%	130%	98%	80%	120%	92%	70%	130%

Comments: NA signifies Not Applicable.
pH duplicates QA acceptance criteria was met relative as stated in Table 5-15 of Analytical Protocol document.
Duplicate NA: results are under 5X the RDL and will not be calculated.

More than 90% of the elements met acceptance limits and overall data quality is acceptable for use. For a multi-element scan up to 10% of analytes may exceed the quoted limits by up to 10% absolute.

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Soil Analysis			
Antimony	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Arsenic	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Barium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Beryllium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Boron (Hot Water Soluble)	MET-93-6104	modified from EPA 6010D and MSA PART 3, CH 21	ICP/OES
Cadmium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Cobalt	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Copper	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Lead	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Molybdenum	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Nickel	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Selenium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Silver	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Thallium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Uranium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Vanadium	MET-93-6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Zinc	MET 93 -6103	modified from EPA 3050B and EPA 6020B and ON MOECC	ICP-MS
Chromium, Hexavalent	INOR-93-6068	modified from EPA 3060 and EPA 7196	SPECTROPHOTOMETER
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Mercury	MET-93-6103	modified from EPA 7471B and SM 3112 B	ICP-MS
Electrical Conductivity (2:1)	INOR-93-6036	modified from MSA PART 3, CH 14 and SM 2510 B	EC METER
Sodium Adsorption Ratio (2:1) (Calc.)	INOR-93-6007	modified from EPA 6010D & Analytical Protocol	ICP/OES
pH, 2:1 CaCl2 Extraction	INOR-93-6031	modified from EPA 9045D and MCKEAGUE 3.11	PH METER

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluorene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benz(a)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Chrysene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
1 and 2 Methlynaphthalene	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5106	modified from EPA 3570 and EPA 8270E	GC/MS
Moisture Content	VOL-91-5009	CCME Tier 1 Method	BALANCE
F1 (C6 - C10)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/FID
Toluene-d8	VOL-91-5009	modified from EPA SW-846 5030C & 8260D	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F3 (C16 to C34)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
F4 (C34 to C50)	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Gravimetric Heavy Hydrocarbons	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE
Terphenyl	VOL-91-5009	modified from CCME Tier 1 Method	GC/FID
Benzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Toluene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Ethylbenzene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
m & p-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
o-Xylene	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
Xylenes (Total)	VOL-91-5009	modified from CCME Tier 1 Method	(P&T)GC/MS
F1 (C6 to C10) minus BTEX	VOL-91-5009	modified from CCME Tier 1 Method	P&T GC/FID
Dichlorodifluoromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Bromomethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trans- 1,2-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl tert-butyl Ether	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Cis- 1,2-Dichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Trichloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Dibromochloromethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T839096

PROJECT: 211-10139-00

ATTENTION TO: Vanessa Oetinger

SAMPLING SITE:

SAMPLED BY:

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
1,1,1,2-Tetrachloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Bromoform	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene (Cis + Trans)	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5002	modified from EPA 5035A and EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5002	modified from EPA 5035A & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5002	modified from EPA 5035A & EPA 8260D	(P&T)GC/MS
Moisture Content	VOL-91-5009	modified from CCME Tier 1 Method	BALANCE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP Inc.
Contact: Vanessa Oetinger
Address: 2 International Blvd, Etobicoke
Phone: Fax:
Reports to be sent to:
1. Email: Vanessa.oetinger@wsp.com
2. Email: matt.roy@wsp.com

Project Information:

Project: 211-10139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture (Check One)
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
____ (Region)

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
____ (Indicate One)

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Laboratory Use Only

Work Order #: 21T839096.
Cooler Quantity: 1 large bulk
Arrival Temperatures: 3.8 | 1.9 | 4.5
Custody Seal Intact: ☐ Yes ☐ No ☑ N/A
Notes: free ice

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Hold Samples	Potentially Hazardous or High Concentration (Y/N)
BH21-2 SS2	12/2/21	AM PM	2	S			X				X								
BH21-2 SS5		AM PM	2	S					X										
QAQC-11		AM PM	1	S	PHC Only				X										
BH21-2 SS6		AM PM	2	S													X		
BH21-3 SS1		AM PM	1	S			X												
QAQC-12		AM PM	1	S			X												
BH21-3 SS2		AM PM	1	S													X		
BH21-3 SS6		AM PM	2	S					X										
BH21-3 SS7		AM PM	2	S					X								X		
BH21-6 SS1	12/1/21	AM PM	1	S															
BH21-6 SS2		AM PM	1	S															

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Matthew Roy	12/2/21	1500	Adriana Bellavia		

21 DEC 2 3:42pm

Page 1 of 2

N°: T 126072

Pink Copy - Client I Yellow Copy - AGAT I White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712 5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: See Page 1
Contact:
Address:
Phone: Fax:
Reports to be sent to:
1. Email:
2. Email:

Project Information:

Project: ZLL-60139-00
Site Location: ORBY Rail
Sampled By: Matthew Roy
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☑ No ☐
Company:
Contact:
Address:
Email:

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 *Indicate One*
☑ Ind/Com
☐ Res/Park
☐ Agriculture
Soil Texture *(Check One)*
☑ Coarse
☐ Fine

☐ Excess Soils R406
Table *Indicate One*

☐ Regulation 558

☐ CCME

☐ Sewer Use ☐ Sanitary ☐ Storm
Region

☐ Prov. Water Quality Objectives (PWQO)

☐ Other
Indicate One

Is this submission for a **Record of Site Condition?** ☑ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Laboratory Use Only

Work Order #:
Cooler Quantity: 1 large bag
Arrival Temperatures: 3.8 | 1.9 | 4.5
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes: free ice

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days

Rush TAT (Rush Surcharges Apply)

☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day

OR Date Required (Rush Surcharges May Apply):

Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*

For 'Same Day' analysis, please contact your AGAT CPM

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC Y/N	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs	O. Reg 153: Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR			Hold Sample				Potentially Hazardous or High Concentration (Y/N)
BH21-6 SS5	12/1/21	AM PM	2	S					X											X				
BH21-6 SS6	1	AM PM	2	S					X															
BH21-16 SS1		PM	1	S			X																	
BH21-16 SS2		PM	1	S						X														
QAQC-10		PM	1	S						X														
BH21-16 SS5		PM	2	S					X			X								X				
BH21-16 SS8		PM	2	S					X			X												
QAQC-9		PM	2	S																				
		AM PM																						
		AM PM																						
		AM PM																						

Samples Relinquished By (Print Name and Sign): Matthew Roy	Date: 12/2/21	Time: 1500	Samples Received By (Print Name and Sign): Adriana Bellavia Abellavia	Date:	Time:
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

2021 DEC 2 7:40 PM

Page 2 of 2

N°: T 126075

Document ID: DIV 78 1511 0.21

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

CLIENT NAME: WSP CANADA INC.
2 INTERNATIONAL BLVD SUITE 201
ETOBICOKE, ON M9W1A2
(416) 798-0065
ATTENTION TO: Marsad Jafar
PROJECT: 211-10139-00 200 02
AGAT WORK ORDER: 21T841270
TRACE ORGANICS REVIEWED BY: Oksana Gushyla, Trace Organics Lab Supervisor
WATER ANALYSIS REVIEWED BY: Nivine Basily, Inorganics Report Writer
DATE REPORTED: Dec 21, 2021
PAGES (INCLUDING COVER): 18
VERSION*: 1

Should you require any information regarding this analysis please contact your client services representative at (905) 712-5100

*Notes

Disclaimer:

- All work conducted herein has been done using accepted standard protocols, and generally accepted practices and methods. AGAT test methods may incorporate modifications from the specified reference methods to improve performance.
- All samples will be disposed of within 30 days after receipt unless a Long Term Storage Agreement is signed and returned. Some specialty analysis may be exempt, please contact your Client Project Manager for details.
- AGAT's liability in connection with any delay, performance or non-performance of these services is only to the Client and does not extend to any other third party. Unless expressly agreed otherwise in writing, AGAT's liability is limited to the actual cost of the specific analysis or analyses included in the services.
- This Certificate shall not be reproduced except in full, without the written approval of the laboratory.
- The test results reported herewith relate only to the samples as received by the laboratory.
- Application of guidelines is provided "as is" without warranty of any kind, either expressed or implied, including, but not limited to, warranties of merchantability, fitness for a particular purpose, or non-infringement. AGAT assumes no responsibility for any errors or omissions in the guidelines contained in this document.
- All reportable information as specified by ISO/IEC 17025:2017 is available from AGAT Laboratories upon request.

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)
Western Enviro-Agricultural Laboratory Association (WEALA)
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. Measurement Uncertainty is not taken into consideration when stating conformity with a specified requirement.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PAHs (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-06
Parameter	Unit	G / S	RDL	3310367
Naphthalene	µg/L	7	0.20	<0.20
Acenaphthylene	µg/L	1	0.20	<0.20
Acenaphthene	µg/L	4.1	0.20	<0.20
Fluorene	µg/L	120	0.20	<0.20
Phenanthrene	µg/L	0.1	0.10	<0.10
Anthracene	µg/L	0.1	0.10	<0.10
Fluoranthene	µg/L	0.4	0.20	<0.20
Pyrene	µg/L	0.2	0.20	<0.20
Benzo(a)anthracene	µg/L	0.2	0.20	<0.20
Chrysene	µg/L	0.1	0.10	<0.10
Benzo(b)fluoranthene	µg/L	0.1	0.10	<0.10
Benzo(k)fluoranthene	µg/L	0.1	0.10	<0.10
Benzo(a)pyrene	µg/L	0.01	0.01	<0.01
Indeno(1,2,3-cd)pyrene	µg/L	0.2	0.20	<0.20
Dibenz(a,h)anthracene	µg/L	0.2	0.20	<0.20
Benzo(g,h,i)perylene	µg/L	0.2	0.20	<0.20
2-and 1-methyl Naphthalene	µg/L	2	0.20	<0.20
Sediment				No
Surrogate	Unit	Acceptable Limits		
Naphthalene-d8	%	50-140		120
Acridine-d9	%	50-140		98
Terphenyl-d14	%	50-140		85

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310367 Note: The result for Benzo(b)Fluoranthene is the total of the Benzo(b)&(j)Fluoranthene isomers because the isomers co-elute on the GC column.
2- and 1-Methyl Naphthalene is a calculated parameter. The calculated value is the sum of 2-Methyl Naphthalene and 1-Methyl Naphthalene. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-6	BH21-2	QAQC-2
		SAMPLE TYPE:		Water	Water	Water
		DATE SAMPLED:		2021-12-06	2021-12-07	2021-12-06
Parameter	Unit	G / S	RDL	3310483	3310484	3310486
Benzene	µg/L	0.5	0.20	<0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20	<0.20
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20	<0.20	<0.20
o-Xylene	µg/L		0.10	<0.10	<0.10	<0.10
Xylenes (Total)	µg/L	72	0.20	<0.20	<0.20	<0.20
F1 (C6 - C10)	µg/L	420	25	<25	<25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25	<25	<25
F2 (C10 to C16)	µg/L	150	100	<100	<100	<100
F3 (C16 to C34)	µg/L	500	100	<100	<100	<100
F4 (C34 to C50)	µg/L	500	100	<100	<100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA	NA	NA
Sediment				NO	NO	NO
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	60-140		79.5	78.2	123
Terphenyl	% Recovery	60-140		92	101	96

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21


Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310483-3310486 The C6-C10 fraction is calculated using Toluene response factor.
Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX.
The calculated parameters are non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and nC34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16 - C50 and are only determined if the chromatogram of the C34 - C50 Hydrocarbons indicated that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6-C50 results are corrected for BTEX contribution.
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC6 and nC10 response factors are within 30% of Toluene response factor.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.
Fractions 1-4 are quantified with the contribution of PAHs. Under Ontario Regulation 153/04, results are considered valid without determining the PAH contribution if not requested by the client.
NA = Not Applicable

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16
		SAMPLE TYPE:		Water
		DATE SAMPLED:		2021-12-06
Parameter	Unit	G / S	RDL	3310367
F1 (C6-C10)	µg/L	420	25	<25
F1 (C6 to C10) minus BTEX	µg/L	420	25	<25
F2 (C10 to C16)	µg/L	150	100	<100
F2 (C10 to C16) minus Naphthalene	µg/L		100	<100
F3 (C16 to C34)	µg/L	500	100	<100
F3 (C16 to C34) minus PAHs	µg/L		100	<100
F4 (C34 to C50)	µg/L	500	100	<100
Gravimetric Heavy Hydrocarbons	µg/L		500	NA
Sediment				NO
Surrogate	Unit	Acceptable Limits		
Toluene-d8	% Recovery	50-140		74.5
Terphenyl	% Recovery	60-140		84

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310367 The C6-C10 fraction is calculated using toluene response factor.
C6–C10 (F1 minus BTEX) is a calculated parameter. The calculated value is F1 minus BTEX. The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.
The C10 - C16, C16 - C34, and C34 - C50 fractions are calculated using the average response factor for n-C10, n-C16, and n-C34.
Gravimetric Heavy Hydrocarbons are not included in the Total C16-C50 and are only determined if the chromatogram of the C34 - C50 hydrocarbons indicates that hydrocarbons >C50 are present.
The chromatogram has returned to baseline by the retention time of nC50.
Total C6 - C50 results are corrected for BTEX and PAH contributions.
C>10 – C16 (F2- Naphthalene) is a calculated parameter. The calculated value is F2 - Naphthalene.
C>16 - C34 (F3-PAH) is a calculated parameter. The calculated value is F3-PAH (PAH: sum of Phenanthrene, Benzo(a)anthracene, Benzo(b)fluoranthene, Benzo(k)fluoranthene, Benzo(a)pyrene, Fluoranthene, Dibenzo(a,h)anthracene, Indeno(1,2,3-c,d)pyrene and Pyrene).
This method complies with the Reference Method for the CWS PHC and is validated for use in the laboratory.
nC10, nC16 and nC34 response factors are within 10% of their average.
C50 response factor is within 70% of nC10 + nC16 + nC34 average.
Linearity is within 15%.
Extraction and holding times were met for this sample.

Sediment parameter is comment only based on visual inspection of the sample prior to extraction and is not an accredited test.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar


O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16	QAQC-1	Trip Blank
		SAMPLE TYPE:		Water	Water	Water
		DATE SAMPLED:		2021-12-06	2021-12-06	2021-12-04
Parameter	Unit	G / S	RDL	3310367	3310485	3310488
Dichlorodifluoromethane	µg/L	590	0.20	<0.20	<0.20	<0.20
Vinyl Chloride	µg/L	0.5	0.17	<0.17	<0.17	<0.17
Bromomethane	µg/L	0.89	0.20	<0.20	<0.20	<0.20
Trichlorofluoromethane	µg/L	150	0.40	<0.40	<0.40	<0.40
Acetone	µg/L	2700	1.0	<1.0	<1.0	<1.0
1,1-Dichloroethylene	µg/L	0.5	0.30	<0.30	<0.30	<0.30
Methylene Chloride	µg/L	5	0.30	<0.30	<0.30	<0.30
trans- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20	<0.20
Methyl tert-butyl ether	µg/L	15	0.20	<0.20	<0.20	<0.20
1,1-Dichloroethane	µg/L	0.5	0.30	<0.30	<0.30	<0.30
Methyl Ethyl Ketone	µg/L	400	1.0	<1.0	<1.0	<1.0
cis- 1,2-Dichloroethylene	µg/L	1.6	0.20	<0.20	<0.20	<0.20
Chloroform	µg/L	2	0.20	<0.20	<0.20	<0.20
1,2-Dichloroethane	µg/L	0.5	0.20	<0.20	<0.20	<0.20
1,1,1-Trichloroethane	µg/L	0.5	0.30	<0.30	<0.30	<0.30
Carbon Tetrachloride	µg/L	0.2	0.20	<0.20	<0.20	<0.20
Benzene	µg/L	0.5	0.20	<0.20	<0.20	<0.20
1,2-Dichloropropane	µg/L	0.5	0.20	<0.20	<0.20	<0.20
Trichloroethylene	µg/L	0.5	0.20	<0.20	<0.20	<0.20
Bromodichloromethane	µg/L	2	0.20	<0.20	<0.20	<0.20
Methyl Isobutyl Ketone	µg/L	640	1.0	<1.0	<1.0	<1.0
1,1,2-Trichloroethane	µg/L	0.5	0.20	<0.20	<0.20	<0.20
Toluene	µg/L	0.8	0.20	<0.20	<0.20	<0.20
Dibromochloromethane	µg/L	2	0.10	<0.10	<0.10	<0.10
Ethylene Dibromide	µg/L	0.2	0.10	<0.10	<0.10	<0.10
Tetrachloroethylene	µg/L	0.5	0.20	<0.20	<0.20	<0.20
1,1,1,2-Tetrachloroethane	µg/L	1.1	0.10	<0.10	<0.10	<0.10
Chlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
Ethylbenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
m & p-Xylene	µg/L		0.20	<0.20	<0.20	<0.20

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - VOCs (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16	QAQC-1	Trip Blank
		SAMPLE TYPE:		Water	Water	Water
		DATE SAMPLED:		2021-12-06	2021-12-06	2021-12-04
Parameter	Unit	G / S	RDL	3310367	3310485	3310488
Bromoform	µg/L	5	0.10	<0.10	<0.10	<0.10
Styrene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
1,1,2,2-Tetrachloroethane	µg/L	0.5	0.10	<0.10	<0.10	<0.10
o-Xylene	µg/L		0.10	<0.10	<0.10	<0.10
1,3-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
1,4-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
1,2-Dichlorobenzene	µg/L	0.5	0.10	<0.10	<0.10	<0.10
1,3-Dichloropropene	µg/L	0.5	0.30	<0.30	<0.30	<0.30
Xylenes (Total)	µg/L	72	0.20	<0.20	<0.20	<0.20
n-Hexane	µg/L	5	0.20	<0.20	<0.20	<0.20
Surrogate	Unit	Acceptable Limits				
Toluene-d8	% Recovery	50-140		88	107	82
4-Bromofluorobenzene	% Recovery	50-140		79	73	82

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310367-3310488 Xylenes total is a calculated parameter. The calculated value is the sum of m&p-Xylene and o-Xylene.
1,3-Dichloropropene total is a calculated parameter. The calculated value is the sum of Cis-1,3-Dichloropropene and Trans-1,3-Dichloropropene.
The calculated parameter is non-accredited. The parameters that are components of the calculation are accredited.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar


O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

		SAMPLE DESCRIPTION:		BH21-16		BH21-6
		SAMPLE TYPE:		Water		Water
		DATE SAMPLED:		2021-12-06		2021-12-06
Parameter	Unit	G / S	RDL	3310367	RDL	3310483
Dissolved Antimony	µg/L	1.5	1.0	1.1	1.0	<1.0
Dissolved Arsenic	µg/L	13	1.0	<1.0	1.0	4.7
Dissolved Barium	µg/L	610	2.0	63.9	2.0	271
Dissolved Beryllium	µg/L	0.5	0.50	<0.50	0.50	<0.50
Dissolved Boron	µg/L	1700	100.0	1676	10.0	279
Dissolved Cadmium	µg/L	0.5	0.20	<0.20	0.20	<0.20
Dissolved Chromium	µg/L	11	2.0	<2.0	2.0	25.3
Dissolved Cobalt	µg/L	3.8	0.50	<0.50	0.50	4.53
Dissolved Copper	µg/L	5	1.0	<1.0	1.0	2.7
Dissolved Lead	µg/L	1.9	0.50	<0.50	0.50	0.93
Dissolved Molybdenum	µg/L	23	0.50	24.7	0.50	6.45
Dissolved Nickel	µg/L	14	1.0	1.1	1.0	6.9
Dissolved Selenium	µg/L	5	1.0	1.6	1.0	<1.0
Dissolved Silver	µg/L	0.3	0.20	<0.20	0.20	<0.20
Dissolved Thallium	µg/L	0.5	0.30	<0.30	0.30	<0.30
Dissolved Uranium	µg/L	8.9	0.50	1.86	0.50	3.52
Dissolved Vanadium	µg/L	3.9	0.40	0.62	0.40	3.29
Dissolved Zinc	µg/L	160	5.0	<5.0	5.0	6.1
Mercury	µg/L	0.1	0.02	<0.02	0.02	<0.02
Chromium VI	µg/L	25	2	<2	2	5.43
Cyanide, Free	µg/L	5	2	<2	2	<2
Dissolved Sodium	µg/L	490000	250	210000	1000	342000
Chloride	µg/L	790000	100	286000	122	1460000
Electrical Conductivity	uS/cm	NA	2	1570	2	4940
pH	pH Units		NA	7.68	NA	7.72

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Certificate of Analysis

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

O. Reg. 153(511) - Metals & Inorganics (Water)

DATE RECEIVED: 2021-12-07

DATE REPORTED: 2021-12-21

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard: Refers to Table 1: Full Depth Background Site Condition Standards - Ground Water - All Types of Property Uses
Guideline values are for general reference only. The guidelines provided may or may not be relevant for the intended use. Refer directly to the applicable standard for regulatory interpretation.

3310367-3310483 Metals analysis completed on a filtered sample.

Dilution required, RDL has been increased accordingly.

Analysis performed at AGAT Toronto (unless marked by *)

Certified By:



Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Exceedance Summary

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

CLIENT NAME: WSP CANADA INC.

ATTENTION TO: Marsad Jafar

SAMPLEID	SAMPLE TITLE	GUIDELINE	ANALYSIS PACKAGE	PARAMETER	UNIT	GUIDEVALUE	RESULT
3310367	BH21-16	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Dissolved Molybdenum	µg/L	23	24.7
3310483	BH21-6	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Chloride	µg/L	790000	1460000
3310483	BH21-6	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Dissolved Chromium	µg/L	11	25.3
3310483	BH21-6	ON T1 GW	O. Reg. 153(511) - Metals & Inorganics (Water)	Dissolved Cobalt	µg/L	3.8	4.53

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841270
ATTENTION TO: Marsad Jafar
SAMPLED BY:Marsad Jafar

Trace Organics Analysis

RPT Date: Dec 21, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - PHCs F1 - F4 (with PAHs and VOC) (Water)															
F1 (C6-C10)	3296537		<25	<25	NA	< 25	108%	60%	140%	98%	60%	140%	109%	60%	140%
F2 (C10 to C16)	3304778		< 100	< 100	NA	< 100	102%	60%	140%	85%	60%	140%	78%	60%	140%
F3 (C16 to C34)	3304778		< 100	< 100	NA	< 100	110%	60%	140%	75%	60%	140%	75%	60%	140%
F4 (C34 to C50)	3304778		< 100	< 100	NA	< 100	115%	60%	140%	76%	60%	140%	74%	60%	140%
O. Reg. 153(511) - PAHs (Water)															
Naphthalene	3227991		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	78%	50%	140%	77%	50%	140%
Acenaphthylene	3227991		< 0.20	< 0.20	NA	< 0.20	98%	50%	140%	82%	50%	140%	107%	50%	140%
Acenaphthene	3227991		< 0.20	< 0.20	NA	< 0.20	105%	50%	140%	71%	50%	140%	81%	50%	140%
Fluorene	3227991		< 0.20	< 0.20	NA	< 0.20	86%	50%	140%	92%	50%	140%	92%	50%	140%
Phenanthrene	3227991		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	88%	50%	140%	85%	50%	140%
Anthracene	3227991		< 0.10	< 0.10	NA	< 0.10	85%	50%	140%	93%	50%	140%	78%	50%	140%
Fluoranthene	3227991		< 0.20	< 0.20	NA	< 0.20	99%	50%	140%	96%	50%	140%	93%	50%	140%
Pyrene	3227991		< 0.20	< 0.20	NA	< 0.20	78%	50%	140%	96%	50%	140%	99%	50%	140%
Benzo(a)anthracene	3227991		< 0.20	< 0.20	NA	< 0.20	96%	50%	140%	94%	50%	140%	96%	50%	140%
Chrysene	3227991		< 0.10	< 0.10	NA	< 0.10	86%	50%	140%	114%	50%	140%	84%	50%	140%
Benzo(b)fluoranthene	3227991		< 0.10	< 0.10	NA	< 0.10	92%	50%	140%	76%	50%	140%	92%	50%	140%
Benzo(k)fluoranthene	3227991		< 0.10	< 0.10	NA	< 0.10	98%	50%	140%	92%	50%	140%	78%	50%	140%
Benzo(a)pyrene	3227991		< 0.01	< 0.01	NA	< 0.01	78%	50%	140%	105%	50%	140%	101%	50%	140%
Indeno(1,2,3-cd)pyrene	3227991		< 0.20	< 0.20	NA	< 0.20	92%	50%	140%	108%	50%	140%	105%	50%	140%
Dibenz(a,h)anthracene	3227991		< 0.20	< 0.20	NA	< 0.20	95%	50%	140%	75%	50%	140%	72%	50%	140%
Benzo(g,h,i)perylene	3227991		< 0.20	< 0.20	NA	< 0.20	91%	50%	140%	85%	50%	140%	105%	50%	140%
O. Reg. 153(511) - VOCs (Water)															
Dichlorodifluoromethane	3315412		<0.20	<0.20	NA	< 0.20	89%	50%	140%	103%	50%	140%	74%	50%	140%
Vinyl Chloride	3315412		<0.17	<0.17	NA	< 0.17	106%	50%	140%	83%	50%	140%	105%	50%	140%
Bromomethane	3315412		<0.20	<0.20	NA	< 0.20	96%	50%	140%	86%	50%	140%	95%	50%	140%
Trichlorofluoromethane	3315412		<0.40	<0.40	NA	< 0.40	107%	50%	140%	94%	50%	140%	94%	50%	140%
Acetone	3315412		<1.0	<1.0	NA	< 1.0	104%	50%	140%	102%	50%	140%	102%	50%	140%
1,1-Dichloroethylene	3315412		<0.30	<0.30	NA	< 0.30	93%	50%	140%	76%	60%	130%	107%	50%	140%
Methylene Chloride	3315412		<0.30	<0.30	NA	< 0.30	105%	50%	140%	89%	60%	130%	102%	50%	140%
trans- 1,2-Dichloroethylene	3315412		<0.20	<0.20	NA	< 0.20	88%	50%	140%	95%	60%	130%	70%	50%	140%
Methyl tert-butyl ether	3315412		<0.20	<0.20	NA	< 0.20	101%	50%	140%	97%	60%	130%	76%	50%	140%
1,1-Dichloroethane	3315412		<0.30	<0.30	NA	< 0.30	119%	50%	140%	96%	60%	130%	99%	50%	140%
Methyl Ethyl Ketone	3315412		<1.0	<1.0	NA	< 1.0	94%	50%	140%	99%	50%	140%	102%	50%	140%
cis- 1,2-Dichloroethylene	3315412		<0.20	<0.20	NA	< 0.20	106%	50%	140%	114%	60%	130%	80%	50%	140%
Chloroform	3315412		1.42	1.35	5.1%	< 0.20	98%	50%	140%	104%	60%	130%	62%	50%	140%
1,2-Dichloroethane	3315412		<0.20	<0.20	NA	< 0.20	111%	50%	140%	109%	60%	130%	95%	50%	140%
1,1,1-Trichloroethane	3315412		<0.30	<0.30	NA	< 0.30	79%	50%	140%	75%	60%	130%	71%	50%	140%
Carbon Tetrachloride	3315412		<0.20	<0.20	NA	< 0.20	116%	50%	140%	73%	60%	130%	77%	50%	140%

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841270
ATTENTION TO: Marsad Jafar
SAMPLED BY:Marsad Jafar

Trace Organics Analysis (Continued)

RPT Date: Dec 21, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
Benzene	3315412		<0.20	<0.20	NA	< 0.20	116%	50%	140%	102%	60%	130%	79%	50%	140%
1,2-Dichloropropane	3315412		<0.20	<0.20	NA	< 0.20	117%	50%	140%	82%	60%	130%	96%	50%	140%
Trichloroethylene	3315412		<0.20	<0.20	NA	< 0.20	111%	50%	140%	92%	60%	130%	73%	50%	140%
Bromodichloromethane	3315412		<0.20	<0.20	NA	< 0.20	113%	50%	140%	103%	60%	130%	87%	50%	140%
Methyl Isobutyl Ketone	3315412		<1.0	<1.0	NA	< 1.0	106%	50%	140%	98%	50%	140%	103%	50%	140%
1,1,2-Trichloroethane	3315412		<0.20	<0.20	NA	< 0.20	101%	50%	140%	119%	60%	130%	110%	50%	140%
Toluene	3315412		1.14	1.37	18.3%	< 0.20	97%	50%	140%	102%	60%	130%	76%	50%	140%
Dibromochloromethane	3315412		<0.10	<0.10	NA	< 0.10	97%	50%	140%	113%	60%	130%	111%	50%	140%
Ethylene Dibromide	3315412		<0.10	<0.10	NA	< 0.10	77%	50%	140%	118%	60%	130%	100%	50%	140%
Tetrachloroethylene	3315412		<0.20	<0.20	NA	< 0.20	109%	50%	140%	110%	60%	130%	81%	50%	140%
1,1,1,2-Tetrachloroethane	3315412		<0.10	<0.10	NA	< 0.10	95%	50%	140%	116%	60%	130%	71%	50%	140%
Chlorobenzene	3315412		<0.10	<0.10	NA	< 0.10	106%	50%	140%	116%	60%	130%	87%	50%	140%
Ethylbenzene	3315412		<0.10	<0.10	NA	< 0.10	119%	50%	140%	72%	60%	130%	74%	50%	140%
m & p-Xylene	3315412		<0.20	<0.20	NA	< 0.20	100%	50%	140%	96%	60%	130%	105%	50%	140%
Bromoform	3315412		<0.10	<0.10	NA	< 0.10	93%	50%	140%	105%	60%	130%	96%	50%	140%
Styrene	3315412		<0.10	<0.10	NA	< 0.10	96%	50%	140%	74%	60%	130%	73%	50%	140%
1,1,2,2-Tetrachloroethane	3315412		<0.10	<0.10	NA	< 0.10	104%	50%	140%	106%	60%	130%	87%	50%	140%
o-Xylene	3315412		<0.10	<0.10	NA	< 0.10	84%	50%	140%	102%	60%	130%	81%	50%	140%
1,3-Dichlorobenzene	3315412		<0.10	<0.10	NA	< 0.10	100%	50%	140%	89%	60%	130%	113%	50%	140%
1,4-Dichlorobenzene	3315412		<0.10	<0.10	NA	< 0.10	106%	50%	140%	100%	60%	130%	114%	50%	140%
1,2-Dichlorobenzene	3315412		<0.10	<0.10	NA	< 0.10	109%	50%	140%	103%	60%	130%	103%	50%	140%
n-Hexane	3315412		<0.20	<0.20	NA	< 0.20	94%	50%	140%	94%	60%	130%	76%	50%	140%
O. Reg. 153(511) - PHCs F1 - F4 (Water)															
Benzene	3296537		<0.20	<0.20	NA	< 0.20	96%	60%	140%	89%	60%	140%	106%	60%	140%
Toluene	3296537		<0.20	<0.20	NA	< 0.20	82%	60%	140%	85%	60%	140%	86%	60%	140%
Ethylbenzene	3296537		<0.10	<0.10	NA	< 0.10	87%	60%	140%	96%	60%	140%	94%	60%	140%
m & p-Xylene	3296537		<0.20	<0.20	NA	< 0.20	99%	60%	140%	80%	60%	140%	94%	60%	140%
o-Xylene	3296537		<0.10	<0.10	NA	< 0.10	90%	60%	140%	104%	60%	140%	80%	60%	140%
F1 (C6 - C10)	3296537		<25	<25	NA	< 25	108%	60%	140%	98%	60%	140%	109%	60%	140%

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

Certified By:

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories
5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Quality Assurance

CLIENT NAME: WSP CANADA INC.
PROJECT: 211-10139-00 200 02
SAMPLING SITE:ORBY

AGAT WORK ORDER: 21T841270
ATTENTION TO: Marsad Jafar
SAMPLED BY:Marsad Jafar

Water Analysis

RPT Date: Dec 21, 2021			DUPLICATE				REFERENCE MATERIAL			METHOD BLANK SPIKE			MATRIX SPIKE		
PARAMETER	Batch	Sample Id	Dup #1	Dup #2	RPD	Method Blank	Measured Value	Acceptable Limits		Recovery	Acceptable Limits		Recovery	Acceptable Limits	
								Lower	Upper		Lower	Upper		Lower	Upper
O. Reg. 153(511) - Metals & Inorganics (Water)															
Dissolved Antimony	3308730		<1.0	<1.0	NA	< 1.0	99%	70%	130%	101%	80%	120%	109%	70%	130%
Dissolved Arsenic	3308730		<1.0	2.6	NA	< 1.0	94%	70%	130%	103%	80%	120%	115%	70%	130%
Dissolved Barium	3308730		107	90.7	16.5%	< 2.0	102%	70%	130%	100%	80%	120%	108%	70%	130%
Dissolved Beryllium	3308730		<0.50	<0.50	NA	< 0.50	103%	70%	130%	107%	80%	120%	113%	70%	130%
Dissolved Boron	3308730		114	107	6.3%	< 10.0	101%	70%	130%	105%	80%	120%	110%	70%	130%
Dissolved Cadmium	3308730		<0.20	<0.20	NA	< 0.20	99%	70%	130%	100%	80%	120%	113%	70%	130%
Dissolved Chromium	3308730		<2.0	<2.0	NA	< 2.0	102%	70%	130%	100%	80%	120%	102%	70%	130%
Dissolved Cobalt	3308730		<0.50	<0.50	NA	< 0.50	96%	70%	130%	106%	80%	120%	107%	70%	130%
Dissolved Copper	3308730		<1.0	<1.0	NA	< 1.0	100%	70%	130%	105%	80%	120%	106%	70%	130%
Dissolved Lead	3308730		<0.50	<0.50	NA	< 0.50	99%	70%	130%	100%	80%	120%	107%	70%	130%
Dissolved Molybdenum	3308730		1.32	1.62	NA	< 0.50	99%	70%	130%	104%	80%	120%	113%	70%	130%
Dissolved Nickel	3308730		1.9	1.9	NA	< 1.0	98%	70%	130%	106%	80%	120%	108%	70%	130%
Dissolved Selenium	3308730		<1.0	<1.0	NA	< 1.0	99%	70%	130%	105%	80%	120%	119%	70%	130%
Dissolved Silver	3308730		<0.20	<0.20	NA	< 0.20	97%	70%	130%	106%	80%	120%	100%	70%	130%
Dissolved Thallium	3308730		<0.30	<0.30	NA	< 0.30	98%	70%	130%	99%	80%	120%	105%	70%	130%
Dissolved Uranium	3308730		<0.50	<0.50	NA	< 0.50	101%	70%	130%	108%	80%	120%	121%	70%	130%
Dissolved Vanadium	3308730		1.15	0.82	NA	< 0.40	97%	70%	130%	103%	80%	120%	103%	70%	130%
Dissolved Zinc	3308730		<5.0	<5.0	NA	< 5.0	100%	70%	130%	99%	80%	120%	111%	70%	130%
Mercury	3295856		<0.02	<0.02	NA	< 0.02	101%	70%	130%	96%	80%	120%	99%	70%	130%
Chromium VI	3315551		<2	2.02	NA	< 2	101%	70%	130%	105%	80%	120%	98%	70%	130%
Cyanide, Free	3319579		<2	<2	NA	< 2	104%	70%	130%	101%	80%	120%	109%	70%	130%
Dissolved Sodium	3293826		6250	6210	0.6%	< 50	95%	70%	130%	97%	80%	120%	99%	70%	130%
Chloride	3295003		551000	551000	0.0%	< 100	94%	70%	130%	103%	80%	120%	NA	70%	130%
Electrical Conductivity	3306912		1350	1340	0.7%	< 2	104%	90%	110%						
pH	3306912		7.78	7.78	0.0%	NA	102%	90%	110%						

Comments: NA signifies Not Applicable.
Duplicate NA: results are under 5X the RDL and will not be calculated.

Matrix spike NA: Spike level < native concentration. Matrix spike acceptance limits do not apply and are not calculated.

Certified By:



AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation. RPDs calculated using raw data. The RPD may not be reflective of duplicate values shown, due to rounding of final results.

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Trace Organics Analysis			
Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acenaphthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluorene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Phenanthrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Chrysene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(b)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(k)fluoranthene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(a)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Indeno(1,2,3-cd)pyrene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Dibenz(a,h)anthracene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Benzo(g,h,i)perylene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
2-and 1-methyl Naphthalene	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Naphthalene-d8	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Acridine-d9	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Terphenyl-d14	ORG-91-5105	modified from EPA 3510C and EPA 8270E	GC/MS
Sediment			
Benzene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Toluene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Ethylbenzene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
m & p-Xylene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
o-Xylene	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
Xylenes (Total)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F1 (C6 - C10)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
Toluene-d8	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F2 (C10 to C16)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F4 (C34 to C50)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID

Results relate only to the items tested. Results apply to samples as received.

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Gravimetric Heavy Hydrocarbons	VOL-91-5010	modified from MOE PHC-E3421	BALANCE
Terphenyl	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F1 (C6-C10)	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/FID
F1 (C6 to C10) minus BTEX	VOL-91-5010	modified from MOE PHC-E3421	P&T GC/FID
Toluene-d8	VOL-91-5010	modified from MOE PHC-E3421	(P&T)GC/MS
F2 (C10 to C16) minus Naphthalene	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34)	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
F3 (C16 to C34) minus PAHs	VOL-91-5010	modified from MOE PHC-E3421	GC/FID
Dichlorodifluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Vinyl Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromomethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichlorofluoromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Acetone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methylene Chloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
trans- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl tert-butyl ether	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Ethyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
cis- 1,2-Dichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chloroform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Carbon Tetrachloride	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Benzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichloropropane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Trichloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromodichloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Methyl Isobutyl Ketone	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2-Trichloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Dibromochloromethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylene Dibromide	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Tetrachloroethylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,1,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Chlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Ethylbenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
m & p-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Bromoform	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Styrene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,1,2,2-Tetrachloroethane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
o-Xylene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,4-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,2-Dichlorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
1,3-Dichloropropene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Xylenes (Total)	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
n-Hexane	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
Toluene-d8	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS
4-Bromofluorobenzene	VOL-91-5001	modified from EPA 5030B & EPA 8260D	(P&T)GC/MS

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 COOPERS AVENUE
MISSISSAUGA, ONTARIO
CANADA L4Z 1Y2
TEL (905)712-5100
FAX (905)712-5122
http://www.agatlabs.com

Method Summary

CLIENT NAME: WSP CANADA INC.

AGAT WORK ORDER: 21T841270

PROJECT: 211-10139-00 200 02

ATTENTION TO: Marsad Jafar

SAMPLING SITE:ORBY

SAMPLED BY:Marsad Jafar

PARAMETER	AGAT S.O.P	LITERATURE REFERENCE	ANALYTICAL TECHNIQUE
Water Analysis			
Dissolved Antimony	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Arsenic	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Barium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Beryllium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Boron	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cadmium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Chromium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Cobalt	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Copper	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Lead	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Molybdenum	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Nickel	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Selenium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Silver	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Thallium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Uranium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Vanadium	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Dissolved Zinc	MET-93-6103	modified from EPA 200.8 and EPA 3005A	ICP-MS
Mercury	MET-93-6100	modified from EPA 245.2 and SM 3112 B	CVAAS
Chromium VI	INOR-93-6034	modified from SM 3500-CR B	LACHAT FIA
Cyanide, Free	INOR-93-6052	modified from ON MOECC E3015, SM 4500-CN- I, G-387	TECHNICON AUTO ANALYZER
Dissolved Sodium	MET-93-6105	modified from EPA 6010D	ICP/OES
Chloride	INOR-93-6004	modified from SM 4110 B	ION CHROMATOGRAPH
Electrical Conductivity	INOR-93-6000	SM 2510 B	PC TITRATE
pH	INOR-93-6000	modified from SM 4500-H+ B	PC TITRATE

Results relate only to the items tested. Results apply to samples as received.

AGAT Laboratories

5835 Coopers Avenue
Mississauga, Ontario L4Z 1Y2
Ph: 905.712.5100 Fax: 905.712.5122
webearth.agatlabs.com

Chain of Custody Record

If this is a Drinking Water sample, please use Drinking Water Chain of Custody Form (potable water consumed by humans)

Report Information:

Company: WSP
Contact: Marsad Jafar
Address: 2 International Blvd, Toronto ON
Phone: 437-233-2935 Fax:
Reports to be sent to:
1. Email: vanessa.oetinger@wsp.com
2. Email: marsad.jafar@wsp.com

Project Information:

Project: 211-10139-00 PH 200 02
Site Location: ORBY
Sampled By: Marsad Jafar
AGAT Quote #: PO:
Please note: If quotation number is not provided, client will be billed full price for analysis.

Invoice Information:

Bill To Same: Yes ☐ No ☐
Company:
Contact:
Address:
Email: payables.ontario@wsp.com

Regulatory Requirements:

(Please check all applicable boxes)

☑ Regulation 153/04
Table 1 (Indicate One)
☑ Ind/Com
☑ Res/Park
☐ Agriculture
Soil Texture (Check One)
☐ Coarse
☐ Fine

☐ Excess Soils R406
Table ____ (Indicate One)
☐ Regulation 558
☐ CCME

☐ Sewer Use
☐ Sanitary ☐ Storm
Region
☐ Prov. Water Quality Objectives (PWQO)
☐ Other
Indicate One

Is this submission for a **Record of Site Condition?** ☐ Yes ☐ No

Report Guideline on *Certificate of Analysis* ☑ Yes ☐ No

Sample Matrix Legend

B	Biota
GW	Ground Water
O	Oil
P	Paint
S	Soil
SD	Sediment
SW	Surface Water

Laboratory Use Only

Work Order #: 21T841270
Cooler Quantity: 1 Blk Chagged ice
Arrival Temperatures: 1.9 | 2.9 | 2.0
Custody Seal Intact: ☐ Yes ☐ No ☐ N/A
Notes:

Turnaround Time (TAT) Required:

Regular TAT ☑ 5 to 7 Business Days
Rush TAT (Rush Surcharges Apply)
☐ 3 Business Days ☐ 2 Business Days ☐ Next Business Day
OR Date Required (Rush Surcharges May Apply):
Please provide prior notification for rush TAT
**TAT is exclusive of weekends and statutory holidays*
For 'Same Day' analysis, please contact your AGAT CPM

Sample Identification	Date Sampled	Time Sampled	# of Containers	Sample Matrix	Comments/ Special Instructions	Field Filtered - Metals, Hg, CrVI, DOC (Y/N)	O. Reg 153: Metals & Inorganics	O. Reg 153: Metals - ☐ CrVI, ☐ Hg, ☐ HWSB	O. Reg 153: BTEX, F1-F4 PHCs Analyze F4G if required ☐ Yes ☐ No	O. Reg 153: PAHs	O. Reg 153: PCBs	O. Reg 153: VOC	O. Reg 558: Landfill Disposal Characterization TCLP: ☐ M&I ☐ VOCs ☐ ABNs ☐ B(a)P ☐ PCBs	O. Reg 406: Excess Soils SPLP Rainwater Leach SPLP: ☐ Metals ☐ VOCs ☐ SVOCs	O. Reg 406: Excess Soils Characterization Package pH, ICPMS Metals, BTEX, F1-F4	Salt - EC/SAR	Potentially Hazardous or High Concentration (Y/N)
BH21-16	Dec 06/21	AM PM	16	GW		Y	X		X	X		X					
BH21-6	Dec 06/21	AM PM	11	GW		Y	X		X								
BH21-2	Dec 07/21	AM PM	5	GW		Y			X								
		AM PM															
QAQC-1	Dec 06/21	AM PM	3	GW		Y						X					
QAQC-2	Dec 06/21	AM PM	3.5	GW		Y			X								
		AM PM	4														
Trip Blank	-	AM PM	3	GW		-						X					
		AM PM															
		AM PM															
		AM PM															

Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Marsad Jafar	Dec 07/21		Neil Ramnarain		
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time
Samples Relinquished By (Print Name and Sign):	Date	Time	Samples Received By (Print Name and Sign):	Date	Time

21 DEC 7 0008

Page ____ of ____

Nº: T 128116

Document ID: DIV 78 1511 021

Pink Copy - Client | Yellow Copy - AGAT | White Copy- AGAT

Date Issued: March 9, 2021

Flow
Building our future, faster.

Central Brampton

C2: Geotechnical Desktop Study

AECOM

Peel Region

ENVISION
CONSULTANTS LTD

DESKTOP GEOTECHNICAL STUDY – PROPOSED TRUNK SEWER ON KENNEDY RD., ORANGEVILLE-BRAMPTON RAILWAY, OLD SCHOOL RD., BOVAIRD DR., VODDEN ST. AND QUEEN ST E.

Brampton and Caledon, Peel Region

Project #: 24-0735b
Prepared for: Region of Peel
Date : February 10, 2026

Report Version: 03 (Final)

6415 Northwest Drive
Units 37-40
Mississauga, ON L4V 1X1

envisionconsultants.ca

February 10, 2026

Region of Peel
10 Peel Centre Drive, Suite B, 4th Floor
Brampton, ON L6T 4B9

Attention: Frank Pugliese, P.Eng., Manager, Contract Administration and Oversight

SUBJECT: DESKTOP GEOTECHNICAL STUDY – PROPOSED TRUNK SEWER ON KENNEDY RD., ORANGEVILLE- BRAMPTON RAILWAY, OLD SCHOOL RD., BOVAIRD DR., VODDEN ST. AND QUEEN ST E., BRAMPTON AND CALEDON, PEEL REGION

EnVision Consultants Ltd. is pleased to present the enclosed final Desktop Geotechnical Study – Proposed Trunk Sewer on Kennedy Rd., Orangeville- Brampton Railway, Old School Rd., Bovaird Dr., Vodden St. and Queen St E. for the above-noted project.

We thank you for utilizing EnVision for this assignment. If there are any questions regarding the enclosed report, please do not hesitate to contact us.

Yours sincerely,



Dhru Enright
Project Manager
denright@envisionconsultants.ca

QUALITY MANAGEMENT

ISSUE	FIRST ISSUE	REVISION 1	REVISION 2
PROJECT NUMBER	24-0735b	24-0735b	24-0735b
PROJECT REFERENCE	Desktop Geotechnical Study – Proposed Trunk Sewer on Kennedy Rd., Orangeville- Brampton Railway, Old School Rd., Bovaird Dr., Vodden St. and Queen St E., Brampton and Caledon, Peel Region	Desktop Geotechnical Study – Proposed Trunk Sewer on Kennedy Rd., Orangeville- Brampton Railway, Old School Rd., Bovaird Dr., Vodden St. and Queen St E., Brampton and Caledon, Peel Region	Desktop Geotechnical Study – Proposed Trunk Sewer on Kennedy Rd., Orangeville- Brampton Railway, Old School Rd., Bovaird Dr., Vodden St. and Queen St E., Brampton and Caledon, Peel Region
VERSION NO.	01	02	03
REMARKS	Draft Report	Final Report	Final Report
PREPARED BY	Chris Song	Chris Song	Chris Song
SIGNATURE	Draft		
REVIEWED BY	Scott Peaker	Scott Peaker	Scott Peaker
SIGNATURE	Draft		
DATE	August 5, 2025	August 27, 2025	February 10, 2026

The original of this digital file will be kept by EnVision for a period of not less than 10 years. As the digital file transmitted to the intended recipient is no longer under the control of EnVision, its integrity cannot be assured. As such, EnVision does not guarantee any modifications made to this digital file subsequent to its transmission to the intended recipient

TABLE OF CONTENTS

1 Introduction & Background 1

2 Sources Reviewed 2

3 Physiographic Setting & Regional Geology 3

3.1 Regional Geology 3

3.2 Groundwater Well Database 3

3.3 Route Description 4

4 Geo-Hazards & Recommendations for Site Investigation 6

4.1 Overview of Subsurface Conditions 6

4.2 Recommendations for Site Investigation 7

5 General Comments and Limitations of Report 10

5.1 Signatures 10

5.2 Qualifier 10

FIGURES

Figure 1	Study Area
Figure 2	Topography
Figure 3	Surficial Geology of the Study Area
Figure 4	Bedrock Geology and Overburden Thickness
Figures 5 to 10	MECP Water Well Locations
Figure 11	Profile of Existing Dundas St. E. and Inferred Bedrock Surface

LIST OF APPENDICES

APPENDIX A: MECP Water Well Inventory Water Well Data

1 INTRODUCTION & BACKGROUND

EnVision Consultants Ltd. (EnVision) was retained by the Region of Peel (the 'Client') to undertake a desktop geotechnical study in connection with a proposed trunk sewer along Kennedy Road, Orangeville-Brampton Railway (OBRY), Old School Road, Bovaird Drive, Vodden Street and Queen Street East. Collectively, these alignments form the study 'Site' in this report.

This report is an updated report of "Desktop Geotechnical Study – Proposed Trunk Sewer on Kennedy Rd. & Hurontario St. and Trunk Sewer / Watermain on Queen St., Brampton, Caledon, Peel Region", Project No. 24-0735 dated November 13, 2024, which considers an updated proposed alignment.

This desktop study project Site area is illustrated in the attached Figure 1.

The purpose of this desktop study is to review and broadly evaluate the geotechnical conditions along the Study route alignments based on existing published information and available data reports. This is to better understand the physiographic setting, the regional geology, and groundwater conditions along the project Site, to identify key geotechnical risks, and to assist in the scoping of future geotechnical and hydrogeological site investigation work. This desktop study report should be read in conjunction with EnVision's *Contaminant Overview Study*.

This report presents the results of our review of the available background information, which should be read in conjunction with the *General Comments and Limitations of Report* (Section 5). The readers' attention is specifically drawn to this information, as it is essential for the proper use and interpretation of this report. The interpretation and findings described in this report pertain to the specific project contemplated and are not applicable to any other project or site location.

2 SOURCES REVIEWED

Information regarding the local and regional subsurface ground and groundwater conditions was obtained from the Open Data Ontario public record GIS and the following sources:

1. Ontario Geological Survey 2010. Surficial Geology of Southern Ontario; Ontario Geological Survey, Miscellaneous Release--Data 128-REV.
2. Armstrong, D.K. and Dodge, J.E.P. 2007. Paleozoic Geology of Southern Ontario; Ontario Geological Survey, Miscellaneous Release-Data 219.
3. Gao, C., Shirota, J., Kelly, R. I., Brunton, F.R., van Haaften, S. 2006. Bedrock Topography and Overburden Thickness Mapping, Southern Ontario; Ontario Geological Survey, Miscellaneous Release-Data 207.
4. Ministry of Environment, Conservation and Parks (MECP). Map: Well records; Ontario Ministry of Environment, Conservation and Parks.

3 PHYSIOGRAPHIC SETTING & REGIONAL GEOLOGY

Chapman and Putnam (2007) indicates that the Site lies within the physiographic regions known as the South Slope at the northern portion of the Site (Orangeville-Brampton Railway (OBRY), Old School Road, Bovaird Drive) and the Peel Plain (Vodden Street, Kennedy Road and Queen Street) at the southern portion of the Site. The South Slope region extends from Niagara Escarpment to the Trent River which gently slopes downwards towards Lake Ontario. The upper overburden consists of lacustrine clay, moraine till and isolated silt and sand deposits, underlain by shale bedrock throughout this region. The Peel Plain characterized as an area of relatively low relief that features fine grained till underlain by Ordovician shale bedrock.

3.1 REGIONAL GEOLOGY

According to the Ontario Geological Survey mapping, as reproduced in Figure 3, the study area is dominated by glaciolacustrine-derived silty to clayey glacial till (geological unit 5D on Figure 3). This type of till is formed from sediments deposited in glacial lakes, often exhibiting a range of grain sizes from silt to clay. The presence of this till suggests the historical influence of glacial processes and subsequent lacustrine deposition within the study area.

Modern alluvium (geological unit 19 on Figure 3) has been deposited within the broad Etobicoke Creek floodplain, flanking Site area, which flows from the northwest to the southeast. Modern alluvium deposits are sedimentary accumulations actively deposited by fluvial processes within river channels, floodplains, and deltas. Composed of varying proportions of sands, silts, clays, gravels, cobbles and organic matter, these deposits reflect ongoing erosion upstream and the transport dynamics of rivers. They form through the continuous cycle of sediment erosion, transportation, and deposition, influenced by seasonal fluctuations in river discharge and interactions with slower-moving water bodies.

According to the Ontario Geological Survey mapping (Armstrong, 2007), the bedrock at the site is predominantly shale interbedded with limestone and siltstone of the Queenston Formation, as shown in Figure 4. The Queenston Formation is a red-brown mudstone to shale, interbedded with thin layers of limy, greenish-blue siltstone and limestone. The Queenston often lacks the fissility of a shale. The mudstone is typically a weak to medium strong rock (unconfined compressive strength of 5 to 50 MPa) under the International Society for Rock Mechanics strength convention, occasionally strong (50 – 100MPa).

3.2 GROUNDWATER WELL DATABASE

Regional groundwater flow moves from the northwest to the southeast towards Lake Ontario. Shallow groundwater flow is influenced by local topography, with recharge occurring in the upland areas and at the Canadian National Railway (CNR) crossing, and discharge occurring within the low-lying area of Etobicoke Creek.

Based on a review of the Ministry of the Environment, Conservation and Parks (MECP) water well database, over 450 water well records were identified within an approximately 250 m radius of the Site, with water levels reported varying as listed in Table 3.1 below. The approximate locations of these water wells near the proposed study area are shown in Figures 5 to 10. The well information is provided in Appendix A.

Table 3-1: Summary of groundwater level reported for each area in consideration

Area in Consideration for Study	Approx. groundwater Level (mbgs) reported in the Ministry of the Environment, Conservation and Parks (MECP) Water Well Database
Kennedy Road (Area 1A)	0.9m to 26.5m
Queen Street (Area 1B)	1.5m to 6.7m
Vodden Street (Area 1C)	1.5m to 14.6m
Orangeville – Brampton Railway (Area 1D)	0.1m to 54.9m
Bovaird Drive (Area 1E)	4.3m to 12.2m
Old School Road (Area 1F)	3.5m to 53.6m

The private wells that were purposed for water supply were found in over twenty-five (25) water well records, and the pumping water levels are ranging from 1.5mbgs to 42.7mbgs. More detailed study will be needed to assess if any of these wells remain in active use and might be interfered with as a result of localized construction dewatering operations.

3.3 ROUTE DESCRIPTION

The development surrounding the Study area is mostly heavily urbanized mixture of residential, commercial, and industrial areas. Commercial and industrial areas are primarily limited to the northeastern half of the alignment.

3.3.1 KENNEDY ROAD (AREA 1A)

Kennedy Road South, also referred to as Area 1A in this Study, pertains to the area from approximately 300m south of Hartford Trail to 100m north of Vodden Street East, where the trunk sewer system is planned to be installed. "Area 1A" is approximately 5.1km in length. Kennedy Road is a 4-lane undivided road with center turning lanes, constructed as an urban cross-section with catch basins and a concrete sidewalk. The road includes an overpass bridge for the Canadian National Railway (CNR) at a location approximately 165 meters south of Orenda Road.

3.3.1.1. Canadian National Railway (CNR)

A Canadian National Railway line is carried on an overpass bridge above Kennedy Road that is located approximately 165 meters south of Orenda Road. The elevation difference between Kennedy Road and the CNR track level is approximately 5 meters.

3.3.2 QUEEN STREET (AREA 1B)

Queen Street, also referred to as Area 1B in this Study, includes the area from Rutherford Road to Kennedy Road, where the trunk sewer is planned to be installed. Area 1B is approximately 0.9km in length. Queen Street is a 6-lane undivided road with center turning lanes, constructed as an urban cross-section with catch basins and a concrete sidewalk.

3.3.3 VODDEN STREET (AREA 1C)

Vodden Street, also referred to as Area 1C in this Study, includes the area from Kennedy Road to the Orangeville-Brampton Railway (OBRY), where the trunk sewer is planned to be installed. Area 1C is approximately 1.9km in length. Vodden Street is a 2-lane undivided road with and without center turning lanes, constructed as an urban cross-section with catch basins and a concrete sidewalk.

3.3.4 ORANGEVILLE-BRAMPTON RAILWAY (OBRY) (AREA 1D)

Orangeville-Brampton Railway (OBRY), also referred to as Area 1D in this Study, includes the area from Vodden Street to Old School Road, where trunk sewer is planned to be installed. Area 1D is approximately 9.5km in length. The OBRY is a former short line railway corridor acquired by Peel Region for conversion into a trail system.

3.3.5 BOVAIRD DRIVE (AREA 1E)

Bovaird Drive, also referred to as Area 1E in this Study, includes the area from OBRY to approximately 300m west of McLaughlin Road, where the trunk sewer is planned to be installed. Area 1E is approximately 1km in length. Bovaird Drive is a 6-lane divided road, constructed as an urban cross-section with catch basins and a concrete sidewalk.

3.3.6 OLD SCHOOL ROAD (AREA 1F)

Old School Road, also referred to as Area 1F in this Study, includes the area from OBRY to Hurontario Street, where the trunk sewer is planned to be installed. Area 1F is approximately 1.2km in length. Old School Road is a 2-lane undivided road, constructed as unurbanized cross-section with culverts.

4 GEO-HAZARDS & RECOMMENDATIONS FOR SITE INVESTIGATION

4.1 OVERVIEW OF SUBSURFACE CONDITIONS

The proposed trunk sewers will be installed along the aforementioned routes through a mostly heavily urbanized area with commercial and residential land use flanking the roadway.

Based on the available information at the time of writing this report, the subsurface conditions along the alignment are expected to include modern fill (as the area is a paved road or rail ballast, fill material would have been placed during its construction as well as for the bedding and backfilling of the multitude of existing wet and dry utilities), underlain by clayey or silty glacial till. Overconsolidated silty clay to clayey silt glacial till soils are typically favourable deposits for trenching with relatively moderate to low groundwater seepage rates. Occasional cobbles and boulders are expected to be present within the glacial till. The groundwater table is relatively shallow and lies a few metres below grade, generally mimicking the topography of the ground above. Perched groundwater would be expected to be present, trapped within bedding and backfill to existing utilities.

The bedrock of the Queenston Formation underlies the glacial till which consists of horizontally bedded shale / mudstone (weak to medium strong, locally strong), interbedded with limestone and siltstone (medium strong to very strong). The hard interbeds of siltstone and limestone can comprise 10% to 20% of the rock profile but typically not more than 10%. The shale is known to contain pockets of methane gas. The Queenston Formation has a high in-situ stress ratio and some swelling potential. Buried valleys and isolated shear zones have been intersected in the Queenston Formation in various areas of the Region of Peel; however, these features are not regionally mapped, and their distribution is poorly understood. There are preliminary indications of a bedrock valley along the Old School Road alignment. Therefore, the presence or absence of such features must be assessed by a thorough site investigation, typically conducted via seismic refraction survey along each full alignment.

The approximate ground surface, very approximate bedrock surface elevation and overburden thickness range are provided in Table 4.1 and are shown in profile in Figure 11-1 through 11-6.

Given the heavily urbanized nature of the roadways and railways, the extensive network of existing utilities in the right of way and rail corridor, the heavy vehicle traffic and rail traffic and without knowledge of the required hydraulic grades in most of the area, it seems very likely that the proposed trunk sewer may be constructed as a rock tunnel or a rock microtunnel in some or all areas of the alignment. It is not known if the trunk sewer will be constructed in open cut or in tunnel, or some combination thereof, but the latter scenario seems most likely. With this in mind, confirmation of the bedrock surface profile along the alignment is a critical issue, along with the characterization of overburden at the potential shaft locations and along any open-cut tie-ins. Some of the unique properties of the Queenston Formation must be carefully investigated through insitu and laboratory testing and these properties then need to be documented in a Geotechnical Data Report (GDR), then baselined in a Geotechnical Baseline Report (GBR).

Table 4-1: Summary of Approximate Ground Surface, Bedrock Surface Elevation and Overburden Thicknesses

Area in Consideration for Study	Approx. Ground Surface Elevation Range	Approx. Bedrock Surface Elevation Range	Approx. overburden thickness range
Kennedy Road (Area 1A)	El. 231m to El. 196m	El. 219m to El. 186m	4m to 13m
Queen Street (Area 1B)	El. 223m to El. 217m	El. 213m to El. 210m	7m to 11m
Vodden Street (Area 1C)	El. 230m to El. 216m	El. 218m to El. 214m	1m to 13m
Orangeville – Brampton Railway (Area 1D)	El. 268m to El. 220m	El. 249m to El. 214m	1m to 28m
Bovaird Drive (Area 1E)	El. 234m to El. 226m	El. 230m to El. 225m	1m to 5m
Old School Road (Area 1F)	El. 268m to El. 258m	El. 252m to El. 235m	15m to 34m

4.2 RECOMMENDATIONS FOR SITE INVESTIGATION

4.2.1 STAGE 1 SITE INVESTIGATION WORK

A *Stage 1* Site investigation for a rock tunnel/microtunnel would typically begin with an initial series of boreholes advanced at, say, approximately 200m to 250m intervals, plus at least one boring put down at potential shaft locations.

Typically, such borings would be sampled at continuous (0.76m intervals) through overburden (in conjunction with the Standard Penetration Test) and then core drilled through bedrock using double or triple tube HQ-sized core barrels, and the borings would be taken to at least 3 bore tunnel diameters (min. 6m) below proposed invert level. Given that the invert level could change at the early stages of design and the fact that the tunnel diameter could potentially increase (for example, if the bore were changed from microtunnel to conventional tunnel), conservatism is warranted in the setting of the borehole termination depths.

In consideration of the urbanized nature of the alignment, it is essential that the route be screened for historical landuse to identify past and present business operations that have the potential to have impacted soil, bedrock or overburden environmental quality. At the Stage 1 investigation stage, this work could be in the form of an APU (Assessment of Past Uses) as required under O.Reg. 406/19. Stage 1 boring locations should be added at locations where higher risk land use (such as past or present fuelling stations, automotive repair facilities, dry cleaners, etc.) is identified. Environmental soil quality testing is also required at each shaft location.

Since rock material mined from a tunnel is rendered soil-like during the excavation process, it should be evaluated as a soil material under the Excess Soil Regulation. Pulverized samples of rock core must be

tested under O.Reg 406/19. Previous studies have revealed that naturally occurring elevated levels of certain parameters further underscoring the need to test and document the baseline chemistry of bedrock samples. Detailed knowledge of such potential exceedances will be of benefit in determining appropriate disposal fate or beneficial reuse options (such as cement clinker) for rock spoils.

Installation of monitoring wells, screened both in the overburden and in the bedrock is recommended as part of Stage 1 site investigation work, with emphasis on installations located at the potential shaft sites and at locations identified as potentially contaminating activities in the APU. Monitoring of groundwater levels and fluctuations in groundwater level should be made in these wells at regular intervals over the course of one year, preferably using auto-reading transducers. Single well response testing should be carried out within each monitoring well in order to estimate the formation hydraulic conductivity. Each monitoring well should be also be sampled and tested for environmental quality relative to the prevailing storm and sanitary Sewer Use By Laws. The monitoring wells, along with the boreholes (between sampling intervals), should be screened for methane gas and hydrogen sulphide. In later Stage 2 site investigations, the type and concentration of gas should be determined using Summa collection canisters sealed onto dedicated collection ports on the wellhead of selected monitoring wells.

Stage 1 site investigations should include a laboratory testing program that includes index testing of soil samples (moisture content determinations, grain size analyses, Atterberg consistency limits) and some preliminary bedrock testing (unconfined compressive strength, Point Load Index strength, indirect tensile strength, slake durability, Cerchar Abrasiveness, mineralogy). More advanced testing, such as rock swelling potential (vertical and horizontal null swell, semi-confined swell, free swell, calcite content) can be reserved for Stage 2 investigations, provided the 100 day testing period is available in the project schedule.

A Stage 1 tunnel and shaft impact assessment is normally undertaken using simple closed form solutions, empirical estimations of zone of influence and ground displacement. Any potential impacts predicted due to temporary construction dewatering would be additive to these predictions. On the basis of stage 1 settlement estimates, a decision can be made as to whether more advanced Stage 2 analyses, using numerical modelling methods, are warranted.

At the culmination of Stage 1 site investigations, a preliminary GDR is prepared along with a preliminary Geotechnical Memorandum for Design (GMD). A preliminary Hydrogeological Investigation report and Assessment Report (HIAR), along with the APU should be produced. These documents will ultimately be superceded by, and updated by, revised GDR, GMD and HIAR reports prepared following completion of the Stage 2 site investigation work.

4.2.2 STAGE 2 SITE INVESTIGATIONS

Stage 2 Site investigations are normally directed at filling in geographical gaps in borehole coverage and to hone in on key issues affecting tunneling, shaft sinking, related temporary works (temporary dewatering, support of excavation), disposal of excess soils, rock and pre-treatment requirements for discharged groundwater.

The Stage 1 boring spacings are typically cut in half in Stage 2 (i.e., borings will now be spaced at a maximum of 100m to 125m intervals plus additional borings at shafts and at Potentially Contaminating Activity sites).

At this stage, the tunnel's horizontal alignment and vertical profile are assumed to be fixed, and shaft sites are identified. As such, the insitu and laboratory testing programs can be targeted to the specific tunnel horizon and shaft locations.

Shaft site temporary easements and allocated laydown areas can be investigated once the property limits have been defined. Pre-construction Phase 1 and Phase 2 ESA's should be done within these temporary construction compound sites.

Bedrock secondary permeability testing (Lugeon, or double packer water pressure acceptance testing) is conducted at shaft locations and within the tunnel horizon at selected locations in order to better predict tunnel and shaft seepage/dewatering rates. Monitoring wells that were identified in Stage 1 to have groundwater quality exceedances of the Sewer Use By-Law criteria should be purged, developed and resampled both for un-filtered and field-filtered samples to evaluate the effect of turbidity on groundwater chemistry.

Site-wide soil and pulverized rock testing should be conducted consistent with the minimum sample testing numbers as dictated by O.Reg. 406/19 based on the anticipated shaft/tunnel excavated volume.

If localized soil contamination was identified in Stage 1 borings, horizontal and vertical delineation of soil contamination should be carried out in Stage 2.

If the Stage 1 geophysical survey had identified anomalies that might be consistent with a buried valley, bedrock surface irregularity, or shear zone, supplementary geophysical surveys may be warranted, possibly combined with additional boreholes specific to the zone of anomalies.

Use of inclined boreholes may be warranted in bedrock to better assess fracture orientation, frequency and aperture. Inclined borings should be logged using the acoustic and optical televiewer in order to provide quantitative data on the discontinuity characteristics and enable preparation of discontinuity stereonets. These borings would typically be situated at several key shaft sites.

Additional geotechnical rock laboratory testing would be undertaken as part of Stage 2 work in order to provide a more statistically valid data set for key parameters such as UCS, indirect tensile strength, hard layer thickness distribution and percentages, abrasivity, plasticity of shale fines, swell potential, etc. These expanded data sets would be plotted as histograms and will be evaluated alongside regional data sets and previous experience when setting GBR Baselines.

Reports that will be prepared (or updated) once the stage 2 investigations are complete will include the revised GDR, HIAR, Environmental Soil Characterization Report and GMD. The preparation of the Geotechnical Baseline report (GBR) will likely be the final deliverable following Stage 2 work.

5 GENERAL COMMENTS AND LIMITATIONS OF REPORT

This is a high level, broad brush desktop geotechnical study intended to be used only in the relative assessment of candidate alignments. This report does not present design or construction recommendations. Detailed design stage site investigation work (boreholes, test pits, monitoring well installations, laboratory testing) and associated geotechnical analyses and reporting are required. This report in no way obviates the need for such future work.

This report is intended solely for the Client named. The material in it reflects our best judgment in light of the information available to EnVision at the time of preparation. Unless otherwise agreed in writing by EnVision Consultants Ltd. it shall not be used to express or imply warranty as to the fitness of the property for a particular purpose. No portion of this report may be used as a separate entity, it is written to be read in its entirety.

Any use which a third party makes of this report, or any reliance on or decisions to be made based on it, are the responsibility of such third parties. EnVision Consultants Ltd. accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report.

We accept no responsibility for any decisions made or actions taken as a result of this report unless we are specifically advised of and participate in such action, in which case our responsibility will be as agreed to at that time.

5.1 SIGNATURES

Prepared by



Chris Song, P.Eng.
Geotechnical Engineer
csong@envisionconsultants.ca

Reviewed by





Scott Peaker, M.A.Sc., P.Eng.
Geotechnical Lead
speaker@envisionconsultants.ca

5.2 QUALIFIER

EnVision prepared this report solely for the use of the intended recipient in accordance with the professional services agreement. In the event a contract has not been executed, the parties agree that

the EnVision General Terms and Conditions, which were provided prior to the preparation of this report, shall govern their business relationship.

The report is intended to be used in its entirety. No excerpts may be taken to be representative of the findings in the assessment. The conclusions presented in this report are based on work performed by trained, professional and technical staff, in accordance with their reasonable interpretation of current and accepted engineering and scientific practices at the time the work was performed.

The content and opinions contained in the report are based on the observations and/or information available to EnVision at the time of preparation, using investigation techniques and engineering analysis methods consistent with those ordinarily exercised by EnVision and other engineering/scientific practitioners working under similar conditions, and subject to the same time, financial and physical constraints applicable to this project.

EnVision disclaims any obligation to update this report if, after the date of this report, any conditions appear to differ significantly from those presented in this report; however, EnVision reserves the right to amend or supplement this report based on additional information, documentation or evidence.

EnVision makes no other representations whatsoever concerning the legal significance of its findings. The intended recipient is solely responsible for the disclosure of any information contained in this report. If a third party makes use of, relies on, or makes decisions in accordance with this report, said third party is solely responsible for such use, reliance or decisions. EnVision does not accept responsibility for damages, if any, suffered by any third party as a result of decisions made or actions taken by said third party based on this report.

EnVision has provided services to the intended recipient in accordance with the professional services agreement between the parties and in a manner consistent with that degree of care, skill and diligence normally provided by members of the same profession performing the same or comparable services in respect of projects of a similar nature in similar circumstances. It is understood and agreed by EnVision and the recipient of this report that EnVision provides no warranty, express or implied, of any kind. Without limiting the generality of the foregoing, it is agreed and understood by EnVision and the recipient of this report that EnVision makes no representation or warranty whatsoever as to the sufficiency of its scope of work for the purpose sought by the recipient of this report.

In preparing this report, EnVision has relied in good faith on information provided by others, as noted in the report. EnVision has reasonably assumed that the information provided is correct and EnVision is not responsible for the accuracy or completeness of such information.


Unless otherwise agreed in writing by EnVision, the Report shall not be used to express or imply warranty as to the suitability of the site for a particular purpose. EnVision disclaims any responsibility for consequential financial effects on transactions or property values, or requirements for follow-up actions /or costs.


This limitations statement is considered an integral part of this report.

FIGURES

Figure 1	Study Area
Figure 2	Topography
Figure 3	Surficial Geology of the Study Area
Figure 4	Bedrock Geology
Figures 5 to 10	MECP Water Well Locations
Figure 11	Profile of Area in Consideration for Study and Inferred Bedrock Surface

Prepared By: TanyaPeterson





LEGEND

- RAILWAY
- WATERCOURSE
- WATERBODY
- AREA 1A
- AREA 1B
- AREA 1C
- AREA 1D
- AREA 1E
- AREA 1F

TITLE

STUDY AREA

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE - BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	1

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735\MXD\Desktop Study\24-0735 Figure 1 Site Location.aprx

Prepared By: TanyaPeterson

N

LEGEND

- AREA 1A
- AREA 1B
- AREA 1C
- AREA 1D
- AREA 1E
- AREA 1F
- RAILWAY
- WATERCOURSE
- WATERBODY
- TOPOGRAPHIC CONTOURS (mASL)

Scale: 1:40,000

0 1,000 2,000 Metres

Data Source: Ontario

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12_GIS\Projects\2024\24-0735\APRX\Desktop Study\24-0735 Figure 2 Topography.aprx

TITLE

TOPOGRAPHY


PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE - BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	2



LEGEND

- AREA 1A
- AREA 1B
- AREA 1C
- AREA 1D
- AREA 1E
- AREA 1F
- RAILWAY
- WATERCOURSE
- WATERBODY
- 3: PALEOZOIC BEDROCK
- 5D: GLACIOLACUSTRINE-DERIVED SILTY TO CLAYEY TILL
- 8B: INTERBEDDED FLOW TILL, RAINOUT DEPOSITS AND SILT AND CLAY
- 9C: FORESHORE-BASINAL DEPOSITS
- 19: MODERN ALLUVIAL DEPOSITS
- 20: ORGANIC DEPOSITS
- OGS PIT

TITLE

SURFICIAL GEOLOGY OF THE STUDY AREA

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE - BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	3

Prepared By: TanyaPeterson

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735b\APRX\Desktop Study\24-0735 Figure 3 Surficial Geology.aprx

Prepared By: TanyaPeterson

N

LEGEND

- AREA 1A
- AREA 1B
- AREA 1C
- AREA 1D
- AREA 1E
- AREA 1F
- RAILWAY
- WATERCOURSE
- WATERBODY
- QUEENSTON FORMATION
- GEORGIAN BAY FORMATION
- OVERBURDEN THICKNESS (m)

Scale: 1:40,000

0 1,000 2,000 Metres

TITLE

BEDROCK GEOLOGY AND OVERBURDEN THICKNESS

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE - BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	4

Data Sources:
1. Ontario Open Data
2. Armstrong, D.K. and Dodge, J.E.P. 2007. Paleozoic geology of southern Ontario; Ontario Geological Survey, Miscellaneous Release--Data 219
3. Gao, C., Shirota, J., Kelly, R.I., Brunton, F.R., van Haaften, S. 2006. Bedrock topography and overburden thickness mapping, southern Ontario; Ontario Geological Survey, Miscellaneous Release--Data 207

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12_GIS\Projects\2024\24-0735\NAPRX\Desktop Study\24-0735 Figure 4 Overburden Thickness.aprx

Prepared By: TanyaPeterson

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12 - GIS\Projects\2024\24-0735\APRX\Desktop Study\24-0735 Figure 5A MECP Wells - Area 1A.aprx

7427804
7289348
7405881
7343527
7405884
7405882
7289349
7342255
7255217
7405883
7289347
7130495
7255990
7194865
7130495
7130495
7101708
7101729
7194893
7130495
7173018
7439639
4910212
7389904
4901151
7369447
7378843
7378841
7378840
7044209
7042134
7443862
7443861
7443863
4909795
7321507
4902352
7443655
7255001
7255002
7443656
7255003
7480583
7480582
4902350
4902356
4902355
7357551

RUTHERFORD ROAD SOUTH
KENNEDY ROAD SOUTH
STEELES AVENUE EAST
KENNEDY ROAD
1ST GULF BOULEVARD
ORCHARD DRIVE
BARTLEY BULL PARKWAY

N

Scale: 1:6,000
0 80 160 240 320
Metres

Data Source: Open Data Ontario

LEGEND

- AREA 1A
- RAILWAY
- WATERCOURSE
- WATERBODY

MECP WATER WELL:

- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- WATER SUPPLY
- UNKNOWN

TITLE

MECP WATER WELL LOCATIONS -
STUDY AREA 1A

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	5A



LEGEND

- AREA 1A
- RAILWAY
- WATERCOURSE

MECP WATER WELL:

- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- UNKNOWN

TITLE

MECP WATER WELL LOCATIONS -
STUDY AREA 1A

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	5B

Prepared By: TanyaPeterson

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735b\APRX\Desktop Study\24-0735 Figure 5B MECP Wells - Area 1A.aprx

Prepared By: TanyaPeterson

N

RUTHERFORD ROAD NORTH
QUEEN STREET EAST
ARCHDEKIN DRIVE
RUTHERFORD ROAD SOUTH
KENNEDY ROAD NORTH
HANSEN ROAD SOUTH
ORENDA ROAD
CHURCH STREET EAST
CENTRE STREET NORTH
EASTERN AVENUE
TRUEMAN STREET
JOHN STREET
KEN WHILLANS DRIVE
CENTRE STREET SOUTH
CLARENCE STREET

7359808
7312109
7219364
7219365
7312124
7219358
7308835
7233319
7308836
7298062
7308837
7298064
7298061
7401799
7369740
7401794
7298063
7369738
7369739
7401796
4906320
7283348
7445277
7267542
7445278
7267541
7229367
7267543
7445276
7229364
7229365
7283346
7366590
7229363
7382116
7218034
7229366
7382113
7382115
7382114
7413528
7358700
7110556
7276928
7358701
7276926
7358702
7315951
7240374
4900513
7418865
7219340
7240375
7304242
7312552
7301789
7304241
7304240
7174070
7274652
7174071
7459157
7174072
7217758
7204500
7217759
7257923
7315952
7217757
7204499
7315942
7204498
7315939
7238555
7204423
7198914
7315949
7238561
7204422
7315944
7315938
7198912
7315941
7276927
7301191
7315936
7238562
7315935
7315947
7315943
7315948
7218035
7257922
7198911
7315953
7198909
7238558
7050955
7380294
7198915
7380295
7315945
7238559
7198913
7408568
7133742
4900512
7307950
7352541
7309138
7325551
7473986
7473984
7473985
7468371
7473983
7468370
7468369
7468372
7279266
7444230
7468367
7287407
7468373
7459160
7468368
7214697
4900511
4900523
4900524
7052046

Data Source: Open Data Ontario

Scale: 1:6,000
0 80 160 240 320 Metres

LEGEND

- AREA 1A
- RAILWAY
- WATERCOURSE

MECP WATER WELL:

- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- WATER SUPPLY
- UNKNOWN

TITLE

MECP WATER WELL LOCATIONS -
STUDY AREA 1A

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	5C

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12_GIS\Projects\2024\24-0735\MXD\APRX\Desktop Study\24-0735 Figure 5C MECP Wells - Area 1A.aprx

Prepared By: TanyaPeterson

RUTHERFORD ROAD NORTH
QUEEN STREET EAST
ARCHDEKIN DRIVE
RUTHERFORD ROAD SOUTH
CLARK BOULEVARD
KENNEDY ROAD NORTH
CHURCH STREET EAST
KENNEDY ROAD SOUTH
EASTERN AVENUE
ORENDA ROAD

7110553
7215922
7215923
7198825
7206001
7206003
4900522
7206002
7198826
7441335
7432482
7240334
7440540
7240333
7351915
7216857
7216927
7119442
7478970
7216858
7449932
7479702
7353800
7447823
7351914
7440545
7440539
7473196
7473197
7351917
7449931
7447822
7440544
7473195
7473176
7391259
7441339
7351916
7391258
7441340
7479704
7473193
7473194
7122312
7351919
7441337
4910041
7298270
7447821
7391260
7479703
4910296
7052993
7122312
7391257
7298271
7353798
7298269
7306247
7353797
7391256
7035402
7327227
7298268
7353799
7298263
7245992
7298264
7327233
7435628
7298267
7435629
7416696
7122312
7122312
7245993
7119442
7122312
7435630
7298265
7203097
7315940
7298266
7198910
7238554
7416695
7416694
7327226
7217760
7203066
7194350
7162498
7363278
7358024
7122312
7412996
7203096
7445277
7267542
7315946
7195222
7475500
7445278
7238556
7203098
7267541
7204499
7201243
7134823
7229367
7204498
7203095
7143474
7267543
7315934
7195224
7315936
7217757
7195223
7445276
7198912
7315954
7315933
7229364
7315944
7238557
7238561
7217759
7220130
7229365
7276927
7315942
7419353
7382116
7204500
7315949
7229363
7217758
7204423
7238555
7301191
7382113
7315935
7204422
7229366
7198909
7315950
7218035
7238560
7413528
7315943
7315937
7315932
7382115
7198911
7315953
7276926
7238558
7382114
7198914
7380294
7050955
7315951
7198915
7358700
7240374
7198913
7240375
7315939
7315945
7358701
7276928
7315952
7238559
7358702
7110556
7315941
7219340
7380295
4900513
7418865
7257922
7238562
7315938
7315947
7257923
7315948
7133742
7304242
7301789
7304241
7304240

Data Source: Open Data Ontario

Scale: 1:4,500
0 80 160 240 Metres

N

LEGEND
- AREA 1B
- RAILWAY
- WATERCOURSE

MECP WATER WELL:
- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- UNKNOWN
- OTHER STATUS

TITLE
MECP WATER WELL LOCATIONS -
STUDY AREA 1B

PROJECT
GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT
REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	6

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12 - GIS\Projects\2024\24-0735\APRX\Desktop Study\24-0735 Figure 6 MECP Wells - Area 1B.aprx

Prepared By: TanyaPeterson

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735b\APRX\Desktop Study\24-0735 Figure 7 MECP Wells - Area 1C.aprx



N

LEGEND

- AREA 1C
- RAILWAY
- WATERCOURSE

MECP WATER WELL:

- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- WATER SUPPLY
- UNKNOWN

TITLE

MECP WATER WELL LOCATIONS -
STUDY AREA 1C

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	7



LEGEND

- AREA 1D
- RAILWAY
- WATERCOURSE
- WATERBODY

MECP WATER WELL:

- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- WATER SUPPLY
- UNKNOWN

TITLE

MECP WATER WELL LOCATIONS -
STUDY AREA 1D

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	8A

Prepared By: TanyaPeterson

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735\MAPRX\Desktop Study\24-0735 Figure 8A MECP Wells - Area 1D.aprx

Prepared By: TanyaPeterson

7043898
4901595
7468660
7170238
7468669
7167767
7468668
7468670
4908671
7390044
7359022
7405165
7395331
7390078
7354807
7390048
7354806
7390050
7359020
7405166
7407100
7359021
7390047
7405167
7405164
4908672
7114851
7114851
7122451
7122450
7439638
7117441
7123806
7114845
7114851
7133912
7122452
7114845
7246995
7247001
7246996
7246999
7247000
7246997
7277183
7467757
7219199
7429411
7335999
7429412
7342881
7217049
7423304
7423303
7423305
4908749
7205572
7449999
7283936
7306218
7117441
7117442
7246995
7247001
7246996
7246999
7247000
7246997
7277183
7467757
7219199
7429411
7335999
7429412
7342881
7217049
7423304
7423303
7423305
4908749
7205572
7449999
7283936
7306218

BRAIDWOOD LAKE ROAD
SANDALWOOD PARKWAY EAST
SUNFOREST DRIVE
HURONTARIO STREET
WAINLESS DRIVE
SANDALWOOD PARKWAY WEST
WHYBANK DRIVE
EARLSBRIDGE BOULEVARD
QUEEN MARY DRIVE
MCLAUGHLIN ROAD NORTH
VAN KIRK DRIVE

N

LEGEND
- AREA 1D
- RAILWAY
- WATERCOURSE
- WATERBODY

MECP WATER WELL:
- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- WATER SUPPLY
- UNKNOWN

Scale: 1:8,000
0 80 160 240 320 400 Metres

Data Source: Open Data Ontario

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735\MXD\Desktop Study\24-0735 Figure 8B MECP Wells - Area 1D.aprx

TITLE
MECP WATER WELL LOCATIONS -
STUDY AREA 1D

PROJECT
GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT
REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	8B



LEGEND

- AREA 1D
- RAILWAY
- WATERCOURSE
- WATERBODY

MECP WATER WELL:

- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- WATER SUPPLY
- UNKNOWN

TITLE

MECP WATER WELL LOCATIONS -
STUDY AREA 1D

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	8C

Prepared By: TanyaPeterson

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735\APRX\Desktop Study\24-0735 Figure 8C MECP Wells - Area 1D.aprx

Prepared By: TanyaPeterson



LEGEND

- AREA 1E
- RAILWAY
- WATERCOURSE

MECP WATER WELL:

- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- WATER SUPPLY
- UNKNOWN

TITLE

MECP WATER WELL LOCATIONS -
STUDY AREA 1E

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO


CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	9

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735b\APRX\Desktop Study\24-0735 Figure 9 MECP Wells - Area 1E.aprx

Prepared By: TanyaPeterson



LEGEND

- AREA 1F
- RAILWAY
- WATERCOURSE

MECP WATER WELL:

- ABANDONED
- MONITORING AND TEST HOLE
- OBSERVATION WELLS
- WATER SUPPLY
- UNKNOWN

TITLE

MECP WATER WELL LOCATIONS -
STUDY AREA 1F

PROJECT

GEOTECHNICAL DESKTOP STUDY
KENNEDY ROAD EA AND ORANGEVILLE -
BRAMPTON RAILWAY, PEEL REGION, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	TP	CS	10

C:\Users\TanyaPeterson\OneDrive - EnVision Consultants\Documents\12. GIS\Projects\2024\24-0735\MAPPX\Desktop Study\24-0735 Figure 10 MECP Wells - Area 1F.aprx

Drafted by: H.U.

Figure 11: Profile of Area in Consideration of Study and Inferred Bedrock Surface (Sheet No. 1 of 6)




LEGEND

- GROUND SURFACE
- INTERPOLATED BEDROCK SURFACE

C:\Users\HosenUlla\OneDrive - EnVision Consultants\Documents - EV 1\02. Projects\07. 2024\24-0735 Kennedy Road and Queen St\04. Tech Services\02. Geotechnical\6 Drawings\2025 Drawings\2025 Alignments\CAD 2025\24-0735 Area 1 - Kennedy Road N.dwg

Figure 11: Profile of Area in Consideration of Study and Inferred Bedrock Surface (Sheet No. 2 of 6)




LEGEND

- GROUND SURFACE
- INTERPOLATED BEDROCK SURFACE

Drafted by: H.U.
C:\Users\HosenUlla\OneDrive - EnVision Consultants\Documents - EV 1\02. Projects\07. 2024\24-0735 Kennedy Road and Queen St\04. Tech Services\02. Geotechnical\6.Drawings\2025 Alignments\2025 Alignments\CAD 2025\24-0735 Area 2 - Queen Street East.dwg

Figure 11: Profile of Area in Consideration of Study and Inferred Bedrock Surface (Sheet No. 3 of 6)



LEGEND

- GROUND SURFACE
- INTERPOLATED BEDROCK SURFACE

Drafted by: H.U.
C:\Users\HosenUlla\OneDrive - EnVision Consultants\Documents - EV 1\02. Projects\07. 2024\24-0735 Kennedy Road and Queen St\04. Tech Services\02. Geotechnical\6 Drawings\2025 Alignments\CAD 2025\24-0735 Area 3 -Vodden.dwg

Figure 11: Profile of Area in Consideration of Study and Inferred Bedrock Surface (Sheet No. 4 of 6)




LEGEND

- GROUND SURFACE
- INTERPOLATED BEDROCK SURFACE

Drafted by: H.U.
C:\Users\HosenUllah\OneDrive - EnVision Consultants\Documents - EV 1\02. Projects\07. 2024\24-0735 Kennedy Road and Queen St\04. Tech Services\02. Geotechnical\6 Drawings\2025 Alignments\CAD 2025\24-0735 Area 4 - Rail corridor.dwg

Drafted by: H.U.

Figure 11: Profile of Area in Consideration of Study and Inferred Bedrock Surface (Sheet No. 5 of 6)




LEGEND

- GROUND SURFACE
- INTERPOLATED BEDROCK SURFACE

C:\Users\HosenUllah\OneDrive - EnVision Consultants\Documents - EV \102. Projects\07. 2024\24-0735 Kennedy Road and Queen St\04. Tech Services\02. Geotechnical\6 Drawings\2025 Alignments\CAD 2025\24-0735 Area 5 - Bovaird Drive.dwg

Drafted by: H.U.

Figure 11: Profile of Area in Consideration of Study and Inferred Bedrock Surface (Sheet No. 6 of 6)



C:\Users\HosenUllah\OneDrive - EnVision Consultants\Documents - EV 1102. Projects\07. 2024\24-0735 Kennedy Road and Queen St\04. Tech Services\02. Geotechnical\6 Drawings\2025 Alignments\CAD 2025\24-0735 Area 6 - Old School.dwg

APPENDIX A:

MECP Water Well Inventory Water Well Data

MECP Water Well Records

Well Record #

4900510 Lot Conc **BRAMPTON CITY / PEEL**

Date 1951-11-20 DD/MM/YYYY | Elev (masl) | Easting 599590 | Northing 4839039

/ Domestic | Water Supply | UTM RC 9 unknown UTM

Water Found 14.6 (mbgs) (masl) FRESH

Casing Diameter 4 inch | Casing Material: STEEL

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL	3.7	(mbgs)	(masl)
Pumping WL	3.7	(mbgs)	(masl)
Pump Rate	18.2	(LPM)	4 / 0
Spec. Cap.	9,999.99	(LPM/m)	Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.1			CLAY / /
7.6			BOULDERS / GRAVEL /
12.2			HARDPAN / /
15.8		RED	SHALE / /

4900511 Lot Conc **BRAMPTON CITY / PEEL**

Date 1959-02-09 DD/MM/YYYY | Elev (masl) | Easting 601365 | Northing 4838290

/ Test Hole | UTM RC 9 unknown UTM

Water Found 8.8 (mbgs) (masl) FRESH

Casing Diameter 5 inch | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL		(mbgs)	(masl)
Pumping WL		(mbgs)	(masl)
Pump Rate		(LPM)	/
Spec. Cap.		(LPM/m)	Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3			TOPSOIL / /
4.3		BROWN	CLAY / BOULDERS /
7.3		BROWN	CLAY / GRAVEL /
8.2			MEDIUM SAND / GRAVEL / CLAY
8.8		BLUE	CLAY / /
10.4			MEDIUM SAND / GRAVEL / CLAY
11.0			SHALE / /

4900512 Lot Conc **BRAMPTON CITY / PEEL**

Date 1959-02-18 DD/MM/YYYY | Elev (masl) | Easting 601182 | Northing 4838699

/ Test Hole | UTM RC 9 unknown UTM

Water Found 6.1 (mbgs) (masl) FRESH

Casing Diameter 5 inch | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL		(mbgs)	(masl)
Pumping WL		(mbgs)	(masl)
Pump Rate		(LPM)	/
Spec. Cap.		(LPM/m)	Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3			TOPSOIL / /
3.0		BROWN	CLAY / GRAVEL /
3.7			MEDIUM SAND / GRAVEL / CLAY
6.1			MEDIUM SAND / GRAVEL / BOULDERS
10.7			MEDIUM SAND / GRAVEL / CLAY
14.9			SHALE / /

4900513 Lot Conc **BRAMPTON CITY / PEEL**

Date 1959-02-25 DD/MM/YYYY | Elev (masl) | Easting 600679 | Northing 4838771

/ Test Hole | UTM RC 9 unknown UTM

Water Found (mbgs) (masl)

Casing Diameter 5 inch | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL		(mbgs)	(masl)
Pumping WL		(mbgs)	(masl)
Pump Rate		(LPM)	/
Spec. Cap.		(LPM/m)	Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

Depth (m)	Color			
0.3		TOPSOIL /		/
2.1	GREY	CLAY /		/
2.7	RED	CLAY /		/
10.1		MEDIUM SAND /	GRAVEL	/ CLAY
11.9		SHALE /		/

4900522 Lot Conc **BRAMPTON CITY / PEEL**

Date 1961-09-19 DD/MM/YYYY

Elev (masl) Easting 601533 Northing 4839563

/ Test Hole UTM RC 9 unknown UTM

Water Found (mbgs) (masl)

Casing Diameter 5 inch Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Soil Descriptions			
3.4		GREY	CLAY /	STONES	/
6.1			MEDIUM SAND /	SILT	/
7.3			GRAVEL /	MEDIUM SAND	/ CLAY
9.1		GREY	CLAY /	STONES	/ BOULDERS
12.5		BLUE	SHALE /		/

4900523 Lot Conc **BRAMPTON CITY / PEEL**

Date 1961-09-20 DD/MM/YYYY

Elev (masl) Easting 600960 Northing 4838270

/ Test Hole UTM RC 9 unknown UTM

Water Found (mbgs) (masl)

Casing Diameter 5 inch Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Soil Descriptions			
0.3			TOPSOIL /		/
3.4		YELLOW	CLAY /	STONES	/
4.6		GREY	CLAY /	STONES	/ BOULDERS
6.4		RED	SHALE /		/

4900524 Lot Conc **BRAMPTON CITY / PEEL**

Date 1961-09-22 DD/MM/YYYY

Elev (masl) Easting 601092 Northing 4838276

/ Test Hole UTM RC 9 unknown UTM

Water Found (mbgs) (masl)

Casing Diameter 5 inch Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Soil Descriptions			
0.3			TOPSOIL /		/
4.3		YELLOW	CLAY /	STONES	/
6.1			MEDIUM SAND /	SILT	/
18.6		RED	SHALE /		/

4901072 Lot Conc **BRAMPTON CITY / PEEL**

Date 1951-05-21 DD/MM/YYYY

Elev (masl) Easting 599633 Northing 4839170

/ Domestic Water Supply UTM RC 9 unknown UTM

Water Found 14.6 (mbgs) (masl) FRESH

Casing Diameter 4 inch Casing Material: STEEL

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 1.5 (mbgs) (masl)

Pumping WL 1.5 (mbgs) (masl)

Pump Rate 18.2 (LPM) /

Spec. Cap. 9,999.99 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Soil Descriptions			

Well Record #

1.2			CLAY /		/
6.1			BOULDERS /	GRAVEL	/
12.8			HARDPAN /		/
15.2		RED	SHALE /		/

4901151 — Lot — Conc — BRAMPTON CITY / PEEL

Date 1950-03-03 (DD/MM/YYYY) — Elev (masl) — Easting 603030 — Northing 4836826 — / Domestic — Water Supply — UTM RC 9 unknown UTM

Water Found 26.5 (mbgs) (masl) FRESH

Casing Diameter 4 inch — Casing Material: STEEL

Top of Screen (mbgs) — Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL	6.1	(mbgs)	(masl)
Pumping WL	18.9	(mbgs)	(masl)
Pump Rate	18.2	(LPM)	5 / 0
Spec. Cap.	1.42	(LPM/m)	Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
3.0		BROWN	CLAY /		/
4.0			GRAVEL /	STONES	/
18.9			GRAVEL /		/
19.5			GRANITE /	STONES	/
26.5			GRAVEL /		/

4901581 — Lot 011 — Conc 01 — BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 1965-01-21 (DD/MM/YYYY) — Elev (masl) — Easting 597016 — Northing 4839411 — / Commerical — Water Supply — UTM RC 5 margin of error : 100 m - 300 m

Water Found 8.5 (mbgs) (masl) FRESH

Casing Diameter 24 inch — Casing Material: STEEL

Top of Screen (mbgs) — Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL	3.4	(mbgs)	(masl)
Pumping WL	6.7	(mbgs)	(masl)
Pump Rate	9.1	(LPM)	/
Spec. Cap.	2.71	(LPM/m)	Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
3.7		BROWN	CLAY /		/
4.9		RED	SHALE /		/
9.8		GREY	SHALE /		/

4901582 — Lot 011 — Conc 01 — BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 1967-04-17 (DD/MM/YYYY) — Elev (masl) — Easting 596970 — Northing 4839483 — / Industrial — Water Supply — UTM RC 5 margin of error : 100 m - 300 m

Water Found 7.9 (mbgs) (masl) FRESH

Casing Diameter 42 inch — Casing Material: CONCRETE

Top of Screen (mbgs) — Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL	3.0	(mbgs)	(masl)
Pumping WL	8.2	(mbgs)	(masl)
Pump Rate	4.5	(LPM)	3 / 0
Spec. Cap.	0.88	(LPM/m)	Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.3			TOPSOIL /		/
3.0		BROWN	CLAY /		/
13.1		RED	SHALE /		/

4901595 — Lot 016 — Conc 01 — BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 1966-06-11 (DD/MM/YYYY) — Elev (masl) — Easting 594968 — Northing 4841731 — / Commerical — Water Supply — UTM RC 5 margin of error : 100 m - 300 m

Water Found 7.6 (mbgs) (masl) FRESH

Casing Diameter 30 inch — Casing Material: CONCRETE

Top of Screen (mbgs) — Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL	1.8	(mbgs)	(masl)
Pumping WL		(mbgs)	(masl)
Pump Rate	22.7	(LPM)	/
Spec. Cap.		(LPM/m)	Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
3.0		BROWN	TOPSOIL /	CLAY	/
4.3		RED	CLAY /		/
7.6		RED	SHALE /		/

Well Record #

4901621 — Lot 021 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 1959-09-10 (DD/MM/YYYY) | Elev (masl) | Easting 592383 | Northing 4843367 | / Livestock | Water Supply | UTM RC 5 | margin of error : 100 m - 300 m

Water Found 3.7 (mbgs) (masl) FRESH

Casing Diameter 30 inch | Casing Material: CONCRETE

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 3.7 (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	CLAY / MEDIUM SAND /
6.1		BROWN	MEDIUM SAND / /

4901622 — Lot 021 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 1959-09-26 (DD/MM/YYYY) | Elev (masl) | Easting 592135 | Northing 4843600 | / Domestic | Water Supply | UTM RC 5 | margin of error : 100 m - 300 m

Water Found 4.6 (mbgs) (masl) FRESH

Casing Diameter 30 inch | Casing Material: CONCRETE

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 4.6 (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.9		BROWN	CLAY / MEDIUM SAND /
7.9		BROWN	MEDIUM SAND / /

4901623 — Lot 021 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 1964-09-08 (DD/MM/YYYY) | Elev (masl) | Easting 592249 | Northing 4843484 | / Domestic | Water Supply | UTM RC 5 | margin of error : 100 m - 300 m

Water Found 6.7 (mbgs) (masl) FRESH

Casing Diameter 7 inch | Casing Material: STEEL

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 5.8 (mbgs) (masl)

Pumping WL 16.8 (mbgs) (masl)

Pump Rate 4.5 (LPM) 26 / 0

Spec. Cap. 0.41 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BLACK	TOPSOIL / /
4.9		BROWN	CLAY / GRAVEL /
7.9		BLUE	CLAY / SILT /
11.3		BROWN	CLAY / GRAVEL /
14.9		GREY	CLAY / SILT / GRAVEL
15.8			GRAVEL / SHALE /
21.0		RED	SHALE / /

4901624 — Lot 021 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 1964-10-15 (DD/MM/YYYY) | Elev (masl) | Easting 592492 | Northing 4843263 | / Domestic | Water Supply | UTM RC 5 | margin of error : 100 m - 300 m

Water Found 16.2 (mbgs) (masl) FRESH

Casing Diameter 30 inch | Casing Material: CONCRETE

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 9.1 (mbgs) (masl)

Pumping WL 15.2 (mbgs) (masl)

Pump Rate 9.1 (LPM) 0 / 30

Spec. Cap. 1.49 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3			TOPSOIL / /
8.8		BROWN	HARDPAN / /
16.2		BLUE	CLAY / /
16.5			MEDIUM SAND / /

Well Record #

4901626 — **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1956-06-23 (DD/MM/YYYY) | Elev (masl) | Easting 591886 | Northing 4844417 | UTM RC 9 unknown UTM

/ Domestic | Water Supply

Water Found 12.8 (mbgs) (masl) FRESH

Casing Diameter 5 inch | Casing Material: STEEL

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 5.5 (mbgs) (masl)

Pumping WL 12.8 (mbgs) (masl)

Pump Rate 45.5 (LPM) /

Spec. Cap. 6.21 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
6.1		YELLOW	CLAY /		/
7.3		BLUE	CLAY /	MEDIUM SAND	/
12.8		BLUE	CLAY /		/
15.5			GRAVEL /		/

4901627 — **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1958-09-04 (DD/MM/YYYY) | Elev (masl) | Easting 592424 | Northing 4845122 | UTM RC 9 unknown UTM

/ Public | Water Supply

Water Found 21.3 (mbgs) (masl) FRESH

Casing Diameter 5 inch | Casing Material: STEEL

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 5.5 (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.6			TOPSOIL /		/
21.3			QUICKSAND /		/
21.6			GRAVEL /		/

4901628 — **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1962-08-13 (DD/MM/YYYY) | Elev (masl) | Easting 592016 | Northing 4843707 | UTM RC 5 margin of error : 100 m - 300 m

/ Domestic | Water Supply

Water Found 9.8 (mbgs) (masl) FRESH

Casing Diameter 30 inch | Casing Material: CONCRETE

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 6.4 (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate 0.0 (LPM) 1 / 0

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
4.6		BROWN	CLAY /	MEDIUM SAND	/
11.0		BLUE	CLAY /	MEDIUM SAND	/

4901629 — **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1963-09-10 (DD/MM/YYYY) | Elev (masl) | Easting 592046 | Northing 4844669 | UTM RC 5 margin of error : 100 m - 300 m

/ Domestic | Water Supply

Water Found 15.8 (mbgs) (masl) FRESH

Casing Diameter 7 inch | Casing Material: STEEL

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N

SWL 8.2 (mbgs) (masl)

Pumping WL 15.2 (mbgs) (masl)

Pump Rate 9.1 (LPM) 12 / 0

Spec. Cap. 1.30 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.6		BLACK	TOPSOIL /		/
3.4		BROWN	CLAY /		/
8.8		BROWN	MEDIUM SAND /		/
10.7		GREY	MEDIUM SAND /	SILT	/
11.6		GREY	CLAY /		/
17.1			CLAY /	GRAVEL	/

Well Record #

4901630 **Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1959-04-15 DD/MM/YYYY | Elev (masl) | Easting 592128 | Northing 4844823 | / Domestic | Water Supply | UTM RC 5 | margin of error : 100 m - 100 m | Water Found 12.2 (mbgs) (masl) FRESH | Casing Diameter 30 inch | Casing Material: CONCRETE | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 7.9 (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.8		BROWN	CLAY / /
12.2		BROWN	QUICKSAND / /

4901631 **Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1962-07-28 DD/MM/YYYY | Elev (masl) | Easting 592117 | Northing 4844825 | / Domestic | Water Supply | UTM RC 5 | margin of error : 100 m - 300 m | Water Found 9.8 (mbgs) (masl) FRESH | Casing Diameter 30 inch | Casing Material: CONCRETE | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 9.8 (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate 9.1 (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.6		BROWN	TOPSOIL / CLAY /
9.8		BROWN	MEDIUM SAND / /
12.8		BROWN	MEDIUM SAND / CLAY /

4901721 **Lot 021 Conc 02 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1964-06-03 DD/MM/YYYY | Elev (masl) | Easting 592396 | Northing 4843370 | / Domestic | Water Supply | UTM RC 5 | margin of error : 100 m - 300 m | Water Found 16.8 (mbgs) (masl) SALTY | Casing Diameter 7 inch | Casing Material: STEEL | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 3.7 (mbgs) (masl)
Pumping WL 21.3 (mbgs) (masl)
Pump Rate 9.1 (LPM) 4 / 0
Spec. Cap. 0.51 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	CLAY / MEDIUM SAND /
9.1			MEDIUM SAND / CLAY /
22.9		RED	SHALE / /

4901722 **Lot 021 Conc 02 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1964-11-19 DD/MM/YYYY | Elev (masl) | Easting 592125 | Northing 4843598 | / Domestic | Water Supply | UTM RC 5 | margin of error : 100 m - 300 m | Water Found 4.6 (mbgs) (masl) FRESH | Casing Diameter 30 inch | Casing Material: CONCRETE | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 4.6 (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate 9.1 (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.6		BROWN	TOPSOIL / CLAY /
8.2		BROWN	MEDIUM SAND / /
11.6		RED	CLAY / /
11.9		RED	SHALE / /

Well Record #

4901723 — **Lot 021 Conc 02 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1966-06-07 (DD/MM/YYYY) | Elev (masl) | Easting 592254 | Northing 4843469 | / Domestic | Water Supply | UTM RC 5 margin of error : 100 m - 300 m | Water Found 9.1 (mbgs) (masl) FRESH | Casing Diameter 30 inch | Casing Material: CONCRETE | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 2.4 (mbgs) (masl)
Pumping WL 6.1 (mbgs) (masl)
Pump Rate 9.1 (LPM) 1 / 0
Spec. Cap. 2.49 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
1.5		BROWN	CLAY /		/
7.6		BLUE	CLAY /		/
8.8			HARDPAN /		/
9.1			SILT /		/

4902350 — **Lot 014 Conc 01 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 1953-11-28 (DD/MM/YYYY) | Elev (masl) | Easting 603671 | Northing 4835957 | / Domestic | Water Supply | UTM RC 9 unknown UTM | Water Found 14.6 (mbgs) (masl) FRESH | Casing Diameter 4 inch | Casing Material: STEEL | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 6.4 (mbgs) (masl)
Pumping WL 11.6 (mbgs) (masl)
Pump Rate 4.5 (LPM) 2 / 0
Spec. Cap. 0.88 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.6			TOPSOIL /		/
6.1		RED	CLAY /		/
14.6		RED	SHALE /		/

4902351 — **Lot 014 Conc 01 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 1954-03-15 (DD/MM/YYYY) | Elev (masl) | Easting 603734 | Northing 4835928 | / Domestic | Water Supply | UTM RC 9 unknown UTM | Water Found 18.3 (mbgs) (masl) FRESH | Casing Diameter 4 inch | Casing Material: STEEL | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 7.6 (mbgs) (masl)
Pumping WL 13.4 (mbgs) (masl)
Pump Rate 18.2 (LPM) /
Spec. Cap. 3.14 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
2.7		YELLOW	MEDIUM SAND /		/
3.7		RED	CLAY /		/
4.3		RED	MEDIUM SAND /		/
4.9		RED	CLAY /		/
12.5		RED	SHALE /	CLAY	/
12.8		BLUE	SHALE /		/
18.3		RED	SHALE /		/

4902352 — **Lot 014 Conc 01 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 1956-05-17 (DD/MM/YYYY) | Elev (masl) | Easting 603442 | Northing 4836169 | / Domestic | Water Supply | UTM RC 9 unknown UTM | Water Found 19.8 (mbgs) (masl) FRESH | Casing Diameter 4 inch | Casing Material: STEEL | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 10.7 (mbgs) (masl)
Pumping WL 13.7 (mbgs) (masl)
Pump Rate 9.1 (LPM) /
Spec. Cap. 2.98 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
4.3			CLAY /		/
19.8		RED	SHALE /		/

Well Record #

4902355 — **Lot 014 Conc 01 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 1964-07-14 (DD/MM/YYYY) | Elev (masl) | Easting 603583 | Northing 4835954 | / Not Used | Test Hole | UTM RC 5 margin of error : 100 m - 300 m | Water Found 2.4 (mbgs) (masl) FRESH | Casing Diameter 5 inch | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.3			TOPSOIL /		/
2.1		YELLOW	CLAY /		/
2.4		BLUE	CLAY /	GRAVEL	/
7.0		BLUE	CLAY /		/
8.5		RED	CLAY /		/
18.9		RED	SHALE /		/
22.9		BLUE	SHALE /		/

4902356 — **Lot 014 Conc 01 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 1964-07-18 (DD/MM/YYYY) | Elev (masl) | Easting 603531 | Northing 4835939 | / Not Used | Test Hole | UTM RC 5 margin of error : 100 m - 300 m | Water Found 1.5 (mbgs) (masl) FRESH | Casing Diameter 7 inch | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.3			TOPSOIL /		/
1.5		YELLOW	CLAY /		/
1.8		BLUE	CLAY /	GRAVEL	/
3.7		BLUE	CLAY /		/
5.5		RED	CLAY /		/
15.2		RED	SHALE /		/
27.4		BLUE	SHALE /		/

4902899 — **Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1968-09-08 (DD/MM/YYYY) | Elev (masl) | Easting 592065 | Northing 4844903 | / Not Used | Abandoned-Quality | UTM RC 5 margin of error : 100 m - 300 m | Water Found 53.6 (mbgs) (masl) FRESH | Casing Diameter 7 inch | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N | SWL 9.1 (mbgs) (masl) | Pumping WL 36.6 (mbgs) (masl) | Pump Rate 40.9 (LPM) 15 / 0 | Spec. Cap. 1.49 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
3.7		BROWN	CLAY /		/
9.1			QUICKSAND /		/
16.2		BLUE	CLAY /		/
21.3			GRAVEL /		/
24.4			CLAY /	STONES	/
42.7		BLUE	CLAY /		/
43.6		RED	CLAY /		/
46.0			SILT /		/
53.6		RED	GRAVEL /	SILT	/
57.9		BLUE	SHALE /		/

Well Record #

4902900 — **Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1968-10-09 (DD/MM/YYYY)
Elev (masl) Easting 592065 Northing 4844848
Domestic / Livestock Water Supply UTM RC 5 margin of error : 100 m - 300 m
Water Found 17.7 (mbgs) (masl) FRESH
Casing Diameter 7 inch Casing Material: STEEL
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 8.5 (mbgs) (masl)
Pumping WL 12.2 (mbgs) (masl)
Pump Rate 45.5 (LPM) 3 / 0
Spec. Cap. 12.43 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.3		BROWN	CLAY / /
8.5			QUICKSAND / /
9.8		BLUE	CLAY / /
12.2			SILT / /
15.8		BLUE	CLAY / /
17.7			GRAVEL / /

4902901 — **Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1968-10-11 (DD/MM/YYYY)
Elev (masl) Easting 592135 Northing 4844793
Domestic / Livestock Water Supply UTM RC 5 margin of error : 100 m - 300 m
Water Found 16.8 (mbgs) (masl) FRESH
Casing Diameter 7 inch Casing Material: STEEL
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 9.8 (mbgs) (masl)
Pumping WL 11.3 (mbgs) (masl)
Pump Rate 68.2 (LPM) 3 / 0
Spec. Cap. 44.74 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
10.4			PREVIOUSLY DUG / /
12.2			SILT / /
14.3			GRAVEL / /
15.2		BLUE	CLAY / /
16.8			GRAVEL / /

4903777 — **Lot Conc BRAMPTON CITY / PEEL**

Date 1952-01-01 (DD/MM/YYYY)
Elev (masl) Easting 599235 Northing 4838523
/ Not Used Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 48 inch Casing Material: CONCRETE
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 1.5 (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
9.1			OVERBURDEN / /

4904066 — **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1972-10-13 (DD/MM/YYYY)
Elev (masl) Easting 591745 Northing 4843953
/ Domestic Water Supply UTM RC 4 margin of error : 30 m - 100 m
Water Found 14.6 (mbgs) (masl) FRESH
Casing Diameter 30 inch Casing Material: CONCRETE
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 7.9 (mbgs) (masl)
Pumping WL 16.5 (mbgs) (masl)
Pump Rate (LPM) 1 / 0
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BROWN	TOPSOIL / /
1.8		BROWN	CLAY / /
4.6		BROWN	SAND / /
4.9		GREY	SAND / /
6.1		GREY	CLAY / /
7.0		RED	CLAY / /

Well Record #

10.1	GREY	CLAY /	SILT	/	
13.1	RED	SAND /	CLAY	/	STONES
14.0	BROWN	CLAY /		/	
16.5	RED	SHALE /		/	

4904291 **Lot 020 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1973-12-15 (DD/MM/YYYY)
Elev (masl) Easting 592647 Northing 4843131
/ Domestic Water Supply UTM RC 6 margin of error : 300 m - 1 km
Water Found 19.8 (mbgs) (masl) Not stated
Casing Diameter 5 inch Casing Material: STEEL
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 6.1 (mbgs) (masl)
Pumping WL 36.6 (mbgs) (masl)
Pump Rate 4.5 (LPM) 4 / 0
Spec. Cap. 0.15 (LPM/m) Hour / Minute

Depth (m)	Color	Soil Descriptions		
0.0				
0.6	BROWN	TOPSOIL /		/
8.5	BROWN	CLAY /		/
16.8	BLUE	CLAY /	GRAVEL	/
23.8	BLUE	GRAVEL /		/
37.5	RED	SHALE /		/

4904378 **Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1974-01-16 (DD/MM/YYYY)
Elev (masl) Easting 591952 Northing 4844616
/ Domestic Water Supply UTM RC 4 margin of error : 30 m - 100 m
Water Found 6.1 (mbgs) (masl) FRESH
Casing Diameter 30 inch Casing Material: CONCRETE
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 6.1 (mbgs) (masl)
Pumping WL 8.8 (mbgs) (masl)
Pump Rate 27.3 (LPM) 1 / 1
Spec. Cap. 9.94 (LPM/m) Hour / Minute

Depth (m)	Color	Soil Descriptions		
0.0				
0.3	BROWN	TOPSOIL /		/
4.3	BROWN	CLAY /		/
5.5	BROWN	FINE SAND /	CLAY	/
7.0	BROWN	MEDIUM SAND /		/
9.1	GREY	SAND /	MUCK	/
12.2	GREY	CLAY /	SILT	/
13.7	BROWN	SAND /	STONES	/

4904556 **Lot 019 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1974-05-15 (DD/MM/YYYY)
Elev (masl) Easting 593042 Northing 4842930
/ Domestic Water Supply UTM RC 4 margin of error : 30 m - 100 m
Water Found 19.2 (mbgs) (masl) FRESH
Casing Diameter 5 inch Casing Material: STEEL
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 1.5 (mbgs) (masl)
Pumping WL 12.2 (mbgs) (masl)
Pump Rate 31.8 (LPM) 2 / 0
Spec. Cap. 2.98 (LPM/m) Hour / Minute

Depth (m)	Color	Soil Descriptions		
0.0				
0.6	BROWN	TOPSOIL /		/
6.1	BROWN	CLAY /		/
12.8	BLUE	CLAY /		/
19.2	RED	SAND /	GRAVEL	/
26.8	GREY	SAND /	GRAVEL	/
36.6	RED	SHALE /		/

Well Record #

4904563 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 1974-07-06 (DD/MM/YYYY)
Elev (masl) Easting 596926 Northing 4839058
/ Livestock Water Supply UTM RC 4 margin of error : 30 m - 100 m
Water Found 12.2 (mbgs) (masl) FRESH
Casing Diameter 5 inch Casing Material: STEEL
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 4.3 (mbgs) (masl)
Pumping WL 12.2 (mbgs) (masl)
Pump Rate 13.6 (LPM) 2 / 0
Spec. Cap. 1.72 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4		BROWN	CLAY / /
15.2		RED	SHALE / /

4906320 — **Lot 002 Conc 12 BRAMPTON CITY / PEEL**

Date 1985-08-01 (DD/MM/YYYY)
Elev (masl) Easting 600356 Northing 4839285
/ Domestic Water Supply UTM RC 3 margin of error : 10 - 30 m
Water Found 16.5 (mbgs) (masl) FRESH
Casing Diameter 6 inch Casing Material: STEEL
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 3.0 (mbgs) (masl)
Pumping WL 16.2 (mbgs) (masl)
Pump Rate 27.3 (LPM) 2 / 0
Spec. Cap. 2.08 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
5.2		BROWN	CLAY / DENSE /
7.3		BLUE	CLAY / STONES / DENSE
9.1		RED	CLAY / STONES / DENSE
18.3		BLUE	SHALE / HARD /

4906471 — **Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1985-09-23 (DD/MM/YYYY)
Elev (masl) Easting 592172 Northing 4844975
/ Domestic Water Supply UTM RC 5 margin of error : 100 m - 300 m
Water Found 6.1 (mbgs) (masl) Not stated
Casing Diameter 30 inch Casing Material: GALVANIZED
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 6.1 (mbgs) (masl)
Pumping WL 19.8 (mbgs) (masl)
Pump Rate (LPM) / 30
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BROWN	TOPSOIL / HARD /
6.1		BROWN	CLAY / HARD /
21.3		GREY	CLAY / SAND / LAYERED

4907265 — **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1989-12-15 (DD/MM/YYYY)
Elev (masl) Easting 592313 Northing 4844888
/ Domestic Water Supply UTM RC 2 margin of error : 3 - 10 m
Water Found 39.6 (mbgs) (masl) FRESH
Casing Diameter 6 inch Casing Material: STEEL
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing? N
SWL 8.2 (mbgs) (masl)
Pumping WL 13.7 (mbgs) (masl)
Pump Rate 54.6 (LPM) 12 / 0
Spec. Cap. 9.94 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.7		BROWN	CLAY / FINE SAND / DENSE
13.7		BLUE	CLAY / STONES / DENSE
22.3		GREY	CLAY / STONES / DENSE
37.5		BLUE	CLAY / DENSE /
41.1		BLUE	GRAVEL / COARSE SAND / LOOSE

Well Record #

4908096 **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 1995-03-16 DD/MM/YYYY | Elev (masl) | Easting 591886 | Northing 4843860 | / Domestic | Water Supply | UTM RC 3 margin of error : 10 - 30 m | Water Found 44.2 (mbgs) (masl) FRESH | Casing Diameter 6 inch | Casing Material: STEEL | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? N
SWL 5.2 (mbgs) (masl)
Pumping WL 42.7 (mbgs) (masl)
Pump Rate 9.1 (LPM) 2 / 0
Spec. Cap. 0.24 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	TOPSOIL / /
3.7		BROWN	CLAY / /
5.2		BLUE	CLAY / /
7.9		GREY	GRAVEL / CLAY /
9.8		GREY	CLAY / SAND / GRAVEL
15.8		BLUE	CLAY / /
16.8		GREY	GRAVEL / CLAY /
45.7		RED	SHALE / SOFT /

4908671 **Lot 016 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2000-12-01 DD/MM/YYYY | Elev (masl) | Easting 595102 | Northing 4841487 | / | Abandoned-Other | UTM RC 3 margin of error : 10 - 30 m | Water Found (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

4908672 **Lot 016 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2000-12-01 DD/MM/YYYY | Elev (masl) | Easting 595087 | Northing 4841429 | / | Abandoned-Other | UTM RC 3 margin of error : 10 - 30 m | Water Found (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

4908749 **Lot 013 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2000-12-05 DD/MM/YYYY | Elev (masl) | Easting 596218 | Northing 4840458 | / | Abandoned-Other | UTM RC 9 unknown UTM | Water Found (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

4909795 Lot Conc **BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2005-04-06 DD/MM/YYYY | Elev / (masl) | Easting 603690 | Northing 4836348 | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.9 cm | Casing Material: PLASTIC

Top of Screen 5.4 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 0.6 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	TOPSOIL / /
2.4		BROWN	SILT / GRAVEL /
3.3		BROWN	SAND / GRAVEL /
6.9		GREY	SHALE / LIMESTONE /

4910041 Lot Conc **BRAMPTON CITY / PEEL**

Date 2006-01-13 DD/MM/YYYY | Elev / (masl) | Easting 601199 | Northing 4839264 | Abandoned-Other | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

4910212 Lot Conc **BRAMPTON CITY / PEEL**

Date 2006-03-01 DD/MM/YYYY | Elev / (masl) | Easting 603045 | Northing 4836914 | Observation Wells | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 1.8 (mbgs) | Bottom of Screen 4.8 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.8		BROWN	FILL / /
4.8		BROWN	SAND / SILT / GRAVEL

4910296 Lot Conc **BRAMPTON CITY / PEEL**

Date 2006-07-31 DD/MM/YYYY | Elev / (masl) | Easting 601204 | Northing 4839259 | Observation Wells | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 5.3 cm | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 2.7 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.8		BLACK	FILL / /
2.7		GREEN	TILL / SILT /

4910336 Lot Conc **BRAMPTON CITY / PEEL**

Date 2006-08-16 DD/MM/YYYY | Elev / (masl) | Easting 602184 | Northing 4837597 | Observation Wells | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material:

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

7035402 Lot Conc BRAMPTON CITY / PEEL

Date 2006-07-10 DD/MM/YYYY

Elev (masl) Easting 600942 Northing 4839262 / UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 3.1 (m)

Flowing? / /

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BLACK	FILL / LOOSE /
2.4		BROWN	SAND / GRAVEL / DENSE
3.7		BROWN	SAND / TILL / DENSE
4.6		GREY	CLAY / SILT / DENSE

7041876 Lot Conc BRAMPTON CITY / PEEL

Date 2007-02-09 DD/MM/YYYY

Elev (masl) Easting 601801 Northing 4837707 / Observation Wells UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 4.2 (mbgs) Bottom of Screen 7.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BROWN	GRAVEL / SAND / FILL
3.6		BROWN	SILT / CLAY / SAND
7.2		GREY	SILT / SAND / CLAY

7042134 Lot Conc BRAMPTON CITY / PEEL

Date 2007-01-18 DD/MM/YYYY

Elev (masl) Easting 603041 Northing 4836633 / Not Used Observation Wells UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 5 cm Casing Material:

Top of Screen 3.8 (mbgs) Bottom of Screen 6.9 (mbgs)

Screen Interval 3.1 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.1		BROWN	CLAY / SILTY /
6.9		GREY	SAND / SILTY / CLAY

7043898 Lot 017 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2007-05-05 DD/MM/YYYY

Elev (masl) Easting 594400 Northing 4842005 / Not Used Abandoned-Other UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 76 cm Casing Material: CONCRETE

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL 2.6 (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

7044209 Lot Conc **BRAMPTON CITY / PEEL**

Date 2007-05-04 DD/MM/YYYY | Elev (masl) | Easting 603021 | Northing 4836625 | / | Abandoned-Other | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.1		/	/

7050955 Lot Conc **BRAMPTON CITY / PEEL**

Date 2007-09-15 DD/MM/YYYY | Elev (masl) | Easting 600777 | Northing 4838929 | / | Observation Wells | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: STEEL

Top of Screen 3.0 (mbgs) Bottom of Screen 7.6 (mbgs)

Screen Interval 4.6 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
7.6		RED	TILL / SHALE /

7052046 Lot Conc **BRAMPTON CITY / PEEL**

Date 2007-07-05 DD/MM/YYYY | Elev (masl) | Easting 601301 | Northing 4838265 | / Monitoring | Observation Wells | UTM RC 3 | margin of error : 10 - 30 m

Water Found 0.9 (mbgs) (masl) Not stated

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
		/	/

7052993 Lot Conc **BRAMPTON CITY / PEEL**

Date 2007-10-30 DD/MM/YYYY | Elev (masl) | Easting 601204 | Northing 4839259 | / Monitoring | Other Status | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.5		BROWN	MEDIUM SAND / FILL / PACKED

7101708 Lot Conc **BRAMPTON CITY / PEEL**

Date 2008-01-23 DD/MM/YYYY | Elev (masl) | Easting 602531 | Northing 4836994 | / Monitoring | Test Hole | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? N
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	GRAVEL / SAND / LOOSE
4.3		BROWN	SAND / GRAVEL /
7.3		BROWN	CLAY / TILL / HARD
7.9		GREY	SAND / CLAY / SOFT

Well Record #

7101729 Lot Conc BRAMPTON CITY / PEEL

Flowing? N

Date 2008-01-23 DD/MM/YYYY | Elev (masl) | Easting 602531 | Northing 4836989 | / Monitoring | Test Hole | UTM RC 3 | margin of error : 10 - 30 m

SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Water Found (mbgs) (masl)
Casing Diameter Casing Material:
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	GRAVEL / SAND / LOOSE
4.3		BROWN	SAND / GRAVEL / PACKED
6.1		BROWN	CLAY / TILL / HARD
6.7		GREY	SAND / CLAY / SOFT

7110553 Lot Conc BRAMPTON CITY / PEEL

Flowing?

Date 2008-04-15 DD/MM/YYYY | Elev (masl) | Easting 601444 | Northing 4839694 | / Monitoring and Te | UTM RC 3 | margin of error : 10 - 30 m

SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Water Found (mbgs) (masl)
Casing Diameter 1.5 inch Casing Material: PLASTIC
Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)
Screen Interval 3.0 (m)

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BLACK	/ /
2.4		BROWN	SILT / SAND / FILL
4.6		BLACK	SAND / / FILL

7110556 Lot Conc BRAMPTON CITY / PEEL

Flowing?

Date 2008-08-15 DD/MM/YYYY | Elev (masl) | Easting 600733 | Northing 4838800 | / Monitoring and Te | Monitoring and Test Hole | UTM RC 3 | margin of error : 10 - 30 m

SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Water Found (mbgs) (masl)
Casing Diameter 1.5 inch Casing Material: PLASTIC
Top of Screen 1.5 (mbgs) Bottom of Screen 3.0 (mbgs)
Screen Interval 1.5 (m)

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.5		BLACK	/ /
2.4		BROWN	SILT / CLAY / TILL
4.6		GREY	SILT / CLAY / TILL

7117441 Lot Conc BRAMPTON CITY / PEEL

Flowing?

Date 2008-12-11 DD/MM/YYYY | Elev (masl) | Easting 595629 | Northing 4841129 | / | UTM RC 4 | margin of error : 30 m - 100 m

SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Water Found (mbgs) (masl)
Casing Diameter 1.5 inch Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.9		BROWN	FILL / / LOOSE
6.1		BROWN	TILL / CLAY / DENSE

Well Record #

7122450 Lot Conc **BRAMPTON CITY / PEEL**

Date 2009-03-24 DD/MM/YYYY

Elev (masl) Easting 595729 Northing 4841201

/ Other Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2.6 cm Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7122451 Lot Conc **BRAMPTON CITY / PEEL**

Date 2009-03-24 DD/MM/YYYY

Elev (masl) Easting 595701 Northing 4841210

/ Other Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2.6 cm Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7122452 Lot Conc **BRAMPTON CITY / PEEL**

Date 2009-03-24 DD/MM/YYYY

Elev (masl) Easting 595668 Northing 4841100

/ Monitoring Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.2 cm Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7123806 Lot Conc **BRAMPTON CITY / PEEL**

Date 2009-05-25 DD/MM/YYYY

Elev (masl) Easting 595672 Northing 4841130

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7127670 Lot Conc **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2009-02-12 DD/MM/YYYY

Elev (masl) Easting 592327 Northing 4844738

/ Monitoring Test Hole UTM RC 3 margin of error : 10 - 30 m

Water Found 8.0 (mbgs) (masl) Not stated

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 6.0 (mbgs) Bottom of Screen 9.1 (mbgs)

Screen Interval 3.1 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL 5.0 (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /
/ /
/ /
/ /
/ /

Well Record #

7134823	Lot	Conc	BRAMPTON CITY / PEEL	

Date 2009-11-10 DD/MM/YYYY

Elev (masl) Easting 601193 Northing 4839050

/ Monitoring UTM RC 4 margin of error : 30 m - 100 m

Water Found 1.6 (mbgs) (masl) Other

Casing Diameter 5.2 cm Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.3		BROWN	SAND /	GRAVEL	/ LOOSE
0.8		GREY	SILT /	CLAY	/ STONES
3.0		GREY	SILT /	CLAY	/ STONES
5.3		BROWN	SILT /	TILL	/ STONES
5.6		GREY	CLAY /	SILT	/ STONES
6.1		GREY	SILT /	TILL	/ STONES

Well Record #

7143474 Lot Conc BRAMPTON CITY / PEEL

Date 2010-02-10 DD/MM/YYYY | Elev (masl) | Easting 601204 | Northing 4839032 | / Test Hole | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 2.3 (mbgs) | Bottom of Screen 3.8 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.7		BROWN	SILT / SAND / DENSE
1.5		BROWN	SILT / CLAY / GRAVEL
2.8		GREY	SILT / SAND / HARD
3.5		GREY	CLAY / SAND / HARD
3.8		GREY	ROCK / /

7145558 Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 2010-04-29 DD/MM/YYYY | Elev (masl) | Easting 591918 | Northing 4844542 | / | Abandoned-Other | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7147718 Lot Conc BRAMPTON CITY / PEEL

Date 2010-06-14 DD/MM/YYYY | Elev (masl) | Easting 599207 | Northing 4838526 | / Test Hole | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen 4.6 (mbgs) | Bottom of Screen 7.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.2		BROWN	FILL / / OTHER
4.3		BROWN	SILT / TILL / DRY
6.1		GREY	SILT / TILL / OTHER
7.6		GREY	SILT / CLAY / OTHER

7152491 Lot 004 Conc 01 BRAMPTON CITY / PEEL

Date 2010-08-13 DD/MM/YYYY | Elev (masl) | Easting 601352 | Northing 4838083 | / Monitoring | Observation Wells | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 3.1 (mbgs) | Bottom of Screen 6.2 (mbgs)

Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.1		BROWN	CLAY / SILT / PACKED
4.6		GREY	CLAY / SILT / SOFT
6.2		GREY	SILT / STONES / HARD

Well Record #

7152492 Lot 004 Conc 01 BRAMPTON CITY / PEEL

Date 2010-08-13 DD/MM/YYYY

Elev (masl) Easting 601418 Northing 4838094

/ Monitoring Observation Wells UTM RC 3 margin of error : 10 - 30 m

Water Found 3.1 (mbgs) (masl) FRESH

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 3.1 (mbgs) Bottom of Screen 6.2 (mbgs)

Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.1		BROWN	CLAY / SILT / PACKED
4.6		GREY	CLAY / SILT / SOFT
6.2		GREY	SILT / ROCK / HARD

7152493 Lot 004 Conc 01 BRAMPTON CITY / PEEL

Date 2010-08-13 DD/MM/YYYY

Elev (masl) Easting 601389 Northing 4838123

/ Monitoring Observation Wells UTM RC 3 margin of error : 10 - 30 m

Water Found 5.3 (mbgs) (masl) FRESH

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 3.1 (mbgs) Bottom of Screen 6.2 (mbgs)

Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.1		BROWN	CLAY / SILT / PACKED
4.6		GREY	CLAY / SILT / SOFT
6.2		GREY	SILT / STONES / HARD

7162498 Lot Conc BRAMPTON CITY / PEEL

Date 2011-03-17 DD/MM/YYYY

Elev (masl) Easting 601022 Northing 4839115

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.4		FILL /	SILT / SHALE

7164666 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2011-05-12 DD/MM/YYYY

Elev (masl) Easting 596768 Northing 4839775

/ UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
		/	/

7167767 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2010-04-01 DD/MM/YYYY

Elev (masl) Easting 595226 Northing 4841493

/ UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
		/	/

Well Record #

7169172 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2011-05-12 DD/MM/YYYY | Elev (masl) Easting 596768 Northing 4839775 UTM RC 3 margin of error : 10 - 30 m | / | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7170238 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2010-04-01 DD/MM/YYYY | Elev (masl) Easting 595220 Northing 4841492 UTM RC 3 margin of error : 10 - 30 m | / | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7170694 Lot Conc BRAMPTON CITY / PEEL

Date 2011-10-04 DD/MM/YYYY | Elev (masl) Easting 601667 Northing 4837980 UTM RC 3 margin of error : 10 - 30 m | / Monitoring and Te Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 1 inch Casing Material: PLASTIC | Top of Screen 0.6 (mbgs) Bottom of Screen 3.7 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.9		BROWN	GRAVEL / SAND / FILL
3.7		BROWN	SAND / GRAVEL / WATER-BEARING

7172051 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2011-10-24 DD/MM/YYYY | Elev (masl) Easting 596478 Northing 4839956 UTM RC 3 margin of error : 10 - 30 m | / Monitoring and Te Test Hole | Water Found (mbgs) (masl) | Casing Diameter 4.0 cm Casing Material: PLASTIC | Top of Screen 3.1 (mbgs) Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		GREY	GRAVEL / / LOOSE
1.5		BROWN	CLAY / SAND / SOFT
2.4		GREY	SHALE / / SOFT
3.7		RED	SHALE / / SOFT
6.1		GREY	SHALE / / SOFT

7172052 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2011-10-24 DD/MM/YYYY | Elev (masl) Easting 596478 Northing 4839956 UTM RC 3 margin of error : 10 - 30 m | / Monitoring and Te Test Hole | Water Found (mbgs) (masl) | Casing Diameter 4.0 cm Casing Material: PLASTIC | Top of Screen 2.1 (mbgs) Bottom of Screen 5.2 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

0.3	GREY	GRAVEL /		/ LOOSE
1.5	BROWN	CLAY /	SAND	/ SOFT
3.7	RED	SHALE /	SOFT	/ LAYERED
4.3	GREY	SHALE /	SOFT	/ LAYERED
5.2	RED	SHALE /	SOFT	/ LAYERED

7172053 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2011-10-24 DD/MM/YYYY

Elev (masl) Easting 596478 Northing 4839956 / Monitoring and Te Test Hole UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 4.0 cm Casing Material: PLASTIC

Top of Screen 4.0 (mbgs) Bottom of Screen 7.0 (mbgs)

Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.3		GREY	GRAVEL /		/ LOOSE
1.5		BROWN	CLAY /	SAND	/ STONES
4.6		GREY	SHALE /	SOFT	/ LAYERED
6.1		RED	SHALE /	SOFT	/ LAYERED
7.0		GREY	SHALE /	SOFT	/ LAYERED

7172054 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2011-10-25 DD/MM/YYYY

Elev (masl) Easting 596478 Northing 4839956 / Monitoring and Te Test Hole UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 4.0 cm Casing Material: PLASTIC

Top of Screen 3.1 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.3		GREY	GRAVEL /		/ LOOSE
1.5		BROWN	CLAY /	SAND	/ STONES
2.7		GREY	SHALE /	SOFT	/ LAYERED
4.0		RED	SHALE /	SOFT	/ LAYERED
5.2		GREY	SHALE /	SOFT	/ LAYERED
6.1		RED	SHALE /	SOFT	/ LAYERED

7172055 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2011-10-25 DD/MM/YYYY

Elev (masl) Easting 596478 Northing 4839956 / Monitoring and Te Test Hole UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 4.0 cm Casing Material: PLASTIC

Top of Screen 3.1 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.3		GREY	GRAVEL /		/ LOOSE
1.2		BROWN	CLAY /	SAND	/ SOFT
2.4		GREY	SHALE /	SOFT	/ LAYERED
4.0		RED	SHALE /	SOFT	/ LAYERED
6.1		GREY	SHALE /	SOFT	/ LAYERED

Well Record #

7172056 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2011-10-25 DD/MM/YYYY | Elev (masl) | Easting 596478 | Northing 4839956 | / Monitoring and Te Test Hole | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 4.0 cm | Casing Material: PLASTIC

Top of Screen 2.1 (mbgs) | Bottom of Screen 4.9 (mbgs)

Screen Interval 2.8 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		GREY	GRAVEL / / LOOSE
0.6		BROWN	SAND / CLAY / STONES
2.4		RED	SHALE / SOFT / LAYERED
4.0		GREY	SHALE / SOFT / LAYERED
4.9		RED	SHALE / SOFT / LAYERED

7172057 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2011-10-25 DD/MM/YYYY | Elev (masl) | Easting 596478 | Northing 4839956 | / Monitoring and Te Test Hole | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 4.0 cm | Casing Material: PLASTIC

Top of Screen 3.3 (mbgs) | Bottom of Screen 5.5 (mbgs)

Screen Interval 2.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		GREY	GRAVEL / / LOOSE
1.5		BROWN	CLAY / SAND / SOFT
2.1		BROWN	SAND / CLAY / STONES
3.7		GREY	SHALE / SOFT / LAYERED
4.3		RED	SHALE / SOFT / LAYERED
5.5		GREY	SHALE / SOFT / LAYERED

7172058 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2011-10-25 DD/MM/YYYY | Elev (masl) | Easting 596478 | Northing 4839956 | / Monitoring and Te Test Hole | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 4.0 cm | Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) | Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		GREY	GRAVEL / / LOOSE
1.5		BROWN	CLAY / SAND / STONES
4.9		GREY	SHALE / SOFT / LAYERED
5.5		RED	SHALE / SOFT / LAYERED

7172059 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2011-10-25 DD/MM/YYYY | Elev (masl) | Easting 596478 | Northing 4839956 | / Monitoring and Te Test Hole | UTM RC 3 | margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 4.0 cm | Casing Material: PLASTIC

Top of Screen 1.9 (mbgs) | Bottom of Screen 4.9 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		GREY	GRAVEL / LOOSE /
1.2		BROWN	CLAY / SAND / STONES
2.4		RED	SHALE / SOFT / LAYERED

Well Record #

			4.0	GREY	SHALE /	SOFT	/ LAYERED
			4.9	RED	SHALE /	SOFT	/ LAYERED

7172060 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2011-10-25 (DD/MM/YYYY) Elev (masl) Easting 596478 Northing 4839956 / Monitoring and Te Test Hole UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 4.0 cm Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Color	Soil Descriptions		
0.3		BROWN	TOPSOIL /	SOFT	/ LOOSE
1.8		BROWN	CLAY /	SAND	/ STONES
2.4		GREY	SHALE /	SOFT	/ LAYERED
4.0		RED	SHALE /	SOFT	/ LAYERED
5.5		GREY	SHALE /	SOFT	/ LAYERED

7173018 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-10-12 (DD/MM/YYYY) Elev (masl) Easting 602558 Northing 4836930 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Color	Soil Descriptions		
			/		/

7173096 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-01-06 (DD/MM/YYYY) Elev (masl) Easting 601829 Northing 4837724 / Monitoring and Te Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.7 (mbgs) (masl) FRESH

Casing Diameter 2 inch Casing Material:

Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Color	Soil Descriptions		
0.1			/		/
2.1		GREY	SILT /	CLAY	/ DENSE
4.6		GREY	SILT /	GRAVEL	/ DENSE

7173228 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-11-04 (DD/MM/YYYY) Elev (masl) Easting 601715 Northing 4838008 / Monitoring and Te Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Color	Soil Descriptions		
0.2		GREY	/		/
0.8		BROWN	SAND /	GRAVEL	/ LOOSE
4.3		BROWN	CLAY /	SILT	/ DENSE
6.1		GREY	CLAY /	SILT	/ DENSE

Well Record #

7173229 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-11-04 DD/MM/YYYY | Elev (masl) | Easting 601696 | Northing 4837971 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC | Top of Screen 2.7 (mbgs) | Bottom of Screen 5.8 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ /
0.6		BROWN	SAND / GRAVEL / LOOSE
3.7		BROWN	CLAY / SILT / DENSE
5.8		GREY	CLAY / SILT / DENSE

7173230 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-11-04 DD/MM/YYYY | Elev (masl) | Easting 601676 | Northing 4837980 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC | Top of Screen 2.7 (mbgs) | Bottom of Screen 5.8 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ /
0.6		BROWN	SAND / GRAVEL / LOOSE
3.7		BROWN	CLAY / SILT / DENSE
5.8		GREY	CLAY / SILT / DENSE

7173231 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-11-07 DD/MM/YYYY | Elev (masl) | Easting 601760 | Northing 4838083 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC | Top of Screen 2.3 (mbgs) | Bottom of Screen 5.3 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ /
1.2		BROWN	SAND / GRAVEL / LOOSE
3.7		BROWN	SILT / CLAY / DENSE
5.3		GREY	SILT / CLAY / DENSE

7173232 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-11-07 DD/MM/YYYY | Elev (masl) | Easting 601691 | Northing 4837966 | / Monitoring and Te | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC | Top of Screen 2.4 (mbgs) | Bottom of Screen 5.5 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		BLACK	/ /
0.9		BROWN	SAND / GRAVEL / LOOSE
3.7		BROWN	SILT / CLAY / DENSE
5.5		GREY	SILT / CLAY / DENSE

Well Record #

7173233 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-11-07 DD/MM/YYYY | Elev (masl) | Easting 601796 | Northing 4837958 | / Monitoring and Te | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC | Top of Screen 2.1 (mbgs) | Bottom of Screen 5.2 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		BROWN	TOPSOIL / / LOOSE
0.9		BROWN	SAND / GRAVEL / LOOSE
3.7		BROWN	SILT / CLAY / DENSE
5.2		GREY	SILT / CLAY / DENSE

7173234 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-11-07 DD/MM/YYYY | Elev (masl) | Easting 601854 | Northing 4838034 | / Monitoring and Te | UTM RC 3 margin of error : 10 - 30 m | Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC | Top of Screen 2.1 (mbgs) | Bottom of Screen 5.2 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		BROWN	SAND / GRAVEL / LOOSE
3.7		BROWN	SILT / CLAY / DENSE
5.2		GREY	SILT / CLAY / DENSE

7174070 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-10-14 DD/MM/YYYY | Elev (masl) | Easting 600957 | Northing 4838620 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 5.2 cm | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 4.5 (mbgs) | Screen Interval 1.5 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.0		BROWN	FILL / / LOOSE
4.5		BROWN	SILT / CLAY / DENSE

7174071 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-10-14 DD/MM/YYYY | Elev (masl) | Easting 600924 | Northing 4838568 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 5.2 cm | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 4.5 (mbgs) | Screen Interval 1.5 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.0		BROWN	FILL / / LOOSE
4.5		BROWN	SILT / CLAY / DENSE

Well Record #

7174072 Lot Conc **BRAMPTON CITY / PEEL**

Date 2011-10-14 DD/MM/YYYY

Elev (masl) Easting 601003 Northing 4838528

/ Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.2 cm Casing Material: PLASTIC

Top of Screen 7.6 (mbgs) Bottom of Screen 9.1 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	FILL / / LOOSE
6.0		BROWN	SILT / CLAY / DENSE
9.1		RED	SHALE / / HARD

7179434 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2012-03-01 DD/MM/YYYY

Elev (masl) Easting 597463 Northing 4839404

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7191501 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2012-10-30 DD/MM/YYYY

Elev (masl) Easting 597488 Northing 4839374

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7191502 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2012-10-30 DD/MM/YYYY

Elev (masl) Easting 597450 Northing 4839335

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7191503 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2012-10-30 DD/MM/YYYY

Elev (masl) Easting 597426 Northing 4839303

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

7191504 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2012-10-30 DD/MM/YYYY | Elev (masl) | Easting 597395 | Northing 4839332 | / Monitoring and Te Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7191505 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2012-10-30 DD/MM/YYYY | Elev (masl) | Easting 597433 | Northing 4839366 | / Monitoring and Te Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7191506 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2012-10-30 DD/MM/YYYY | Elev (masl) | Easting 597468 | Northing 4839404 | / Monitoring and Te Abandoned-Other | UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7192521 Lot Conc BRAMPTON CITY / PEEL

Date 2012-07-20 DD/MM/YYYY | Elev (masl) | Easting 601571 | Northing 4837910 | / | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7194350 Lot Conc BRAMPTON CITY / PEEL

Date 2012-11-26 DD/MM/YYYY | Elev (masl) | Easting 600943 | Northing 4839094 | / Monitoring and Te Monitoring and Test Hole | UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) Bottom of Screen 4.0 (mbgs)

Screen Interval 3.0 (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.1		BROWN	SAND / SILT /
4.0		GREY	SILT / SAND /

Well Record #

7194865 Lot Conc BRAMPTON CITY / PEEL

Date 2012-12-04 DD/MM/YYYY | Elev (masl) | Easting 602541 | Northing 4837041 | / Monitoring | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found 1.5 (mbgs) (masl) Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 5.5 (mbgs) | Bottom of Screen 8.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7194893 Lot Conc BRAMPTON CITY / PEEL

Date 2012-12-04 DD/MM/YYYY | Elev (masl) | Easting 602540 | Northing 4837042 | / | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7195222 Lot Conc BRAMPTON CITY / PEEL

Date 2012-12-13 DD/MM/YYYY | Elev (masl) | Easting 601030 | Northing 4839030 | / Monitoring and Te | Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) | Bottom of Screen 3.7 (mbgs)

Screen Interval 2.7 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		BLACK	/ /
0.3		BROWN	SAND / GRAVEL / LOOSE
3.7		BROWN	SILT / SAND / LOOSE

7195223 Lot Conc BRAMPTON CITY / PEEL

Date 2012-12-13 DD/MM/YYYY | Elev (masl) | Easting 601039 | Northing 4839014 | / Monitoring and Te | Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 4.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		BLACK	/ /
0.3		BROWN	SAND / GRAVEL / LOOSE
4.3		BROWN	SILT / SAND / LOOSE

7195224 Lot Conc BRAMPTON CITY / PEEL

Date 2012-12-13 DD/MM/YYYY | Elev (masl) | Easting 601037 | Northing 4839017 | / Monitoring and Te | Test Hole | UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 4.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		BLACK	/ /

Well Record #

						0.3	BROWN	SAND /	GRAVEL	/ LOOSE
						4.3	BROWN	SILT /	SAND	/ LOOSE
7198825	**Lot**	**Conc**		**BRAMPTON CITY / PEEL**				Flowing?		
Date 2012-11-09	Elev	(masl)	Easting 601416	Northing 4839570				SWL	(mbgs)	(masl)
DD/MM/YYYY	/ Monitoring	Observation Wells		UTM RC 4	margin of error : 30 m - 100 m			Pumping WL	(mbgs)	(masl)
	Water Found 4.9	(mbgs)	(masl)					Pump Rate	(LPM)	/
	Casing Diameter 2	inch	Casing Material: PLASTIC			Depth (m)	Elev (masl)	Spec. Cap.	(LPM/m)	Hour / Minute
	Top of Screen 2.1	(mbgs)	Bottom of Screen 5.2	(mbgs)		0.0	Color		Soil Descriptions	
	Screen Interval 3.0	(m)								
						0.1	BLACK	/		/
						0.6	BROWN	SAND /	GRAVEL	/
						3.7	BROWN	SILT /		/ TILL
						4.9	GREY	SILT /	FINE SAND	/ TILL
						5.2	GREY	SILT /		/
7198826	**Lot**	**Conc**		**BRAMPTON CITY / PEEL**				Flowing?		
Date 2012-11-09	Elev	(masl)	Easting 601441	Northing 4839548				SWL	(mbgs)	(masl)
DD/MM/YYYY	/ Monitoring	Observation Wells		UTM RC 4	margin of error : 30 m - 100 m			Pumping WL	(mbgs)	(masl)
	Water Found 4.9	(mbgs)	(masl)					Pump Rate	(LPM)	/
	Casing Diameter 2	inch	Casing Material: PLASTIC			Depth (m)	Elev (masl)	Spec. Cap.	(LPM/m)	Hour / Minute
	Top of Screen 2.1	(mbgs)	Bottom of Screen 5.2	(mbgs)		0.0	Color		Soil Descriptions	
	Screen Interval 3.0	(m)								
						0.1	BLACK	/		/
						0.6	BROWN	SAND /	GRAVEL	/
						3.7	BROWN	SILT /		/ TILL
						4.9	GREY	SILT /		/ TILL
						5.2	GREY	SILT /	FINE SAND	/
7198909	**Lot**	**Conc**		**BRAMPTON CITY / PEEL**				Flowing?		
Date 2012-02-27	Elev	(masl)	Easting 600957	Northing 4838946				SWL	(mbgs)	(masl)
DD/MM/YYYY	/ Monitoring and Te	Test Hole		UTM RC 4	margin of error : 30 m - 100 m			Pumping WL	(mbgs)	(masl)
	Water Found	(mbgs)	(masl)					Pump Rate	(LPM)	/
	Casing Diameter 1.5	inch	Casing Material: PLASTIC			Depth (m)	Elev (masl)	Spec. Cap.	(LPM/m)	Hour / Minute
	Top of Screen 1.2	(mbgs)	Bottom of Screen 3.7	(mbgs)		0.0	Color		Soil Descriptions	
	Screen Interval 2.4	(m)								
						2.7	BROWN	SILT /	SAND	/
						3.7	RED	SHALE /		/
7198910	**Lot**	**Conc**		**BRAMPTON CITY / PEEL**				Flowing?		
Date 2013-02-27	Elev	(masl)	Easting 600984	Northing 4839054				SWL	(mbgs)	(masl)
DD/MM/YYYY	/ Monitoring and Te	Test Hole		UTM RC 4	margin of error : 30 m - 100 m			Pumping WL	(mbgs)	(masl)
	Water Found	(mbgs)	(masl)					Pump Rate	(LPM)	/
	Casing Diameter 1.5	inch	Casing Material: PLASTIC			Depth (m)	Elev (masl)	Spec. Cap.	(LPM/m)	Hour / Minute
	Top of Screen 1.2	(mbgs)	Bottom of Screen 3.7	(mbgs)		0.0	Color		Soil Descriptions	
	Screen Interval 2.4	(m)								
						3.0	BROWN	SILT /	SAND	/
						3.7	RED	SHALE /		/

Well Record #

7198911 Lot Conc **BRAMPTON CITY / PEEL**

Date 2013-02-27 DD/MM/YYYY | Elev (masl) | Easting 600927 | Northing 4838923 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 4.0 (mbgs)

Screen Interval 2.7 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	SILT / SAND /
4.0		RED	SHALE / /

7198912 Lot Conc **BRAMPTON CITY / PEEL**

Date 2013-02-27 DD/MM/YYYY | Elev (masl) | Easting 600924 | Northing 4838987 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) | Bottom of Screen 3.8 (mbgs)

Screen Interval 2.9 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	SILT / SAND /
3.8		RED	SHALE / /

7198913 Lot Conc **BRAMPTON CITY / PEEL**

Date 2013-02-27 DD/MM/YYYY | Elev (masl) | Easting 601055 | Northing 4838873 | / Monitoring and Te Test Hole | UTM RC 3 margin of error : 10 - 30 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 3.7 (mbgs)

Screen Interval 2.4 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	SILT / SAND /
3.7		RED	SHALE / /

7198914 Lot Conc **BRAMPTON CITY / PEEL**

Date 2013-02-27 DD/MM/YYYY | Elev (masl) | Easting 600975 | Northing 4838952 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 3.7 (mbgs)

Screen Interval 2.4 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SILT / SAND /
3.7		RED	SHALE / /

7198915 Lot Conc **BRAMPTON CITY / PEEL**

Date 2013-02-27 DD/MM/YYYY | Elev (masl) | Easting 601062 | Northing 4838880 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 3.7 (mbgs)

Screen Interval 2.4 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	SILT / SAND /

Well Record #

								3.7	RED	SHALE /		/	

7199058 Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL — Flowing? N

Date 2012-09-04 (DD/MM/YYYY) | Elev (masl) | Easting 592411 | Northing 4845012 | SWL 6.4 (mbgs) (masl)

/ Domestic | Water Supply | UTM RC 4 margin of error : 30 m - 100 m | Pumping WL 14.8 (mbgs) (masl)

Water Found 40.0 (mbgs) (masl) FRESH | Pump Rate 15.1 (LPM) 6 /

Casing Diameter 16 cm | Casing Material: STEEL | Spec. Cap. 1.80 (LPM/m) Hour / Minute

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m)	Elev (masl)	Color				
0.0		Color	Soil Descriptions			
0.9		BROWN	TOPSOIL /		/	
4.9		BROWN	SAND /	GRAVEL	/	
6.4		GREY	SAND /	SILT	/	
28.0		GREY	CLAY /	SILT	/	GRAVEL
30.2		GREY	CLAY /	SILT	/	
35.0		RED	CLAY /	SILT	/	GRAVEL
42.7		RED	SHALE /	SHALE	/	

7199059 Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL — Flowing? N

Date 2012-09-08 (DD/MM/YYYY) | Elev (masl) | Easting 592413 | Northing 4845034 | SWL (mbgs) (masl)

/ | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Pumping WL (mbgs) (masl)

Water Found (mbgs) (masl) | Pump Rate (LPM) /

Casing Diameter 16 cm | Casing Material: STEEL | Spec. Cap. (LPM/m) Hour / Minute

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m)	Elev (masl)	Color				
0.0		Color	Soil Descriptions			
					/	/

7201243 Lot Conc BRAMPTON CITY / PEEL — Flowing?

Date 2012-12-13 (DD/MM/YYYY) | Elev (masl) | Easting 601043 | Northing 4839033 | SWL (mbgs) (masl)

/ Monitoring and Te | Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Pumping WL (mbgs) (masl)

Water Found (mbgs) (masl) | Pump Rate (LPM) /

Casing Diameter 1.5 inch | Casing Material: PLASTIC | Spec. Cap. (LPM/m) Hour / Minute

Top of Screen 0.9 (mbgs) | Bottom of Screen 4.0 (mbgs)

Screen Interval 3.0 (m)

Depth (m)	Elev (masl)	Color				
0.0		Color	Soil Descriptions			
0.2		BLACK	/		/	
0.3		BROWN	SAND /	GRAVEL	/	LOOSE
4.0		BROWN	SILT /	SAND	/	LOOSE

7203066 Lot Conc BRAMPTON CITY / PEEL — Flowing?

Date 2013-05-23 (DD/MM/YYYY) | Elev (masl) | Easting 601025 | Northing 4839007 | SWL (mbgs) (masl)

/ Monitoring and Te | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Pumping WL (mbgs) (masl)

Water Found (mbgs) (masl) | Pump Rate (LPM) /

Casing Diameter 1.5 inch | Casing Material: PLASTIC | Spec. Cap. (LPM/m) Hour / Minute

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m)	Elev (masl)	Color				
0.0		Color	Soil Descriptions			
					/	/

Well Record #

7203095 Lot Conc BRAMPTON CITY / PEEL

Date 2013-05-23 DD/MM/YYYY

Elev (masl) Easting 601035 Northing 4839023

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7203096 Lot Conc BRAMPTON CITY / PEEL

Date 2013-05-23 DD/MM/YYYY

Elev (masl) Easting 601028 Northing 4839037

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7203097 Lot Conc BRAMPTON CITY / PEEL

Date 2013-05-23 DD/MM/YYYY

Elev (masl) Easting 600991 Northing 4839048

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7203098 Lot Conc BRAMPTON CITY / PEEL

Date 2013-05-23 DD/MM/YYYY

Elev (masl) Easting 601037 Northing 4839030

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7204422 Lot Conc BRAMPTON CITY / PEEL

Date 2013-06-20 DD/MM/YYYY

Elev (masl) Easting 601017 Northing 4838956

/ Monitoring and Te Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 2.9 (mbgs) Bottom of Screen 5.9 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4		BROWN	SAND / FILL /
5.9		BROWN	TILL / ROCK /

Well Record #

7204423 Lot 005 Conc 02 BRAMPTON CITY / PEEL

Date 2013-06-20 DD/MM/YYYY | Elev (masl) | Easting 601009 | Northing 4838957 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4		BROWN	SAND / FILL /
4.6		BROWN	TILL / ROCK /

7204498 Lot Conc BRAMPTON CITY / PEEL

Date 2013-06-20 DD/MM/YYYY | Elev (masl) | Easting 600992 | Northing 4838976 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 2.9 (mbgs) | Bottom of Screen 5.9 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4		BROWN	SAND / FILL /
5.9		BROWN	TILL / ROCK /

7204499 Lot Conc BRAMPTON CITY / PEEL

Date 2013-06-20 DD/MM/YYYY | Elev (masl) | Easting 600995 | Northing 4838971 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 2.7 (mbgs) | Bottom of Screen 5.8 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4		BROWN	SAND / FILL /
5.8		BROWN	TILL / /

7204500 Lot Conc BRAMPTON CITY / PEEL

Date 2013-06-20 DD/MM/YYYY | Elev (masl) | Easting 601001 | Northing 4838962 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter inch | Casing Material: PLASTIC | Top of Screen 2.6 (mbgs) | Bottom of Screen 5.6 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4		BROWN	SAND / FILL /
5.6		BROWN	TILL / ROCK /

7205385 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2013-05-21 DD/MM/YYYY | Elev (masl) | Easting 597087 | Northing 4838974 | / | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

Well Record #

7205572 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2013-06-25 DD/MM/YYYY | Elev (masl) | Easting 596600 | Northing 4840300 | / Monitoring | Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl) | Untested

Casing Diameter 2 cm | Casing Material: PLASTIC | Top of Screen 4.6 (mbgs) | Bottom of Screen 7.6 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BROWN	TOPSOIL / /
0.7		BROWN	FILL / TOPSOIL / CLAY
1.5		BROWN	SAND / SILT / TILL
7.6		BROWN	SHALE / LIMESTONE / ROCK

7206001 Lot Conc **BRAMPTON CITY / PEEL**

Date 2013-05-27 DD/MM/YYYY | Elev (masl) | Easting 601423 | Northing 4839570 | / Monitoring | Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found 3.7 (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 2.3 (mbgs) | Bottom of Screen 5.3 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4			FILL / /
5.3		GREY	SILT / / SANDY

7206002 Lot Conc **BRAMPTON CITY / PEEL**

Date 2013-05-27 DD/MM/YYYY | Elev (masl) | Easting 601426 | Northing 4839554 | / Monitoring | Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found 3.7 (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 2.3 (mbgs) | Bottom of Screen 5.3 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4			FILL / /
5.3		GREY	SILT / / SANDY

7206003 Lot Conc **BRAMPTON CITY / PEEL**

Date 2013-05-27 DD/MM/YYYY | Elev (masl) | Easting 601424 | Northing 4839571 | / Monitoring | UTM RC 4 margin of error : 30 m - 100 m | Water Found 3.7 (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4			FILL / /
5.5		GREY	SILT / / SANDY
6.1		GREY	CLAY / SILT /

Well Record #

7207025 Lot Conc BRAMPTON CITY / PEEL

Date 2013-07-12 DD/MM/YYYY

Elev (masl) Easting 602033 Northing 4837669

/ Monitoring / Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 inch Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) Bottom of Screen 1.8 (mbgs)

Screen Interval 0.9 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7209680 Lot Conc BRAMPTON CITY / PEEL

Date 2013-09-23 DD/MM/YYYY

Elev (masl) Easting 602033 Northing 4837654

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) Bottom of Screen 2.7 (mbgs)

Screen Interval 1.8 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7209786 Lot Conc BRAMPTON CITY / PEEL

Date 2013-09-23 DD/MM/YYYY

Elev (masl) Easting 602023 Northing 4837650

/ Monitoring Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) Bottom of Screen 2.7 (mbgs)

Screen Interval 1.8 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7209787 Lot Conc BRAMPTON CITY / PEEL

Date 2013-09-23 DD/MM/YYYY

Elev (masl) Easting 602025 Northing 4837654

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) Bottom of Screen 2.7 (mbgs)

Screen Interval 1.8 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7209788 Lot Conc BRAMPTON CITY / PEEL

Date 2013-09-23 DD/MM/YYYY

Elev (masl) Easting 602031 Northing 4837660

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.5 inch Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) Bottom of Screen 2.7 (mbgs)

Screen Interval 1.8 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7209791 Lot Conc BRAMPTON CITY / PEEL

Date 2013-09-23 DD/MM/YYYY

Elev (masl) Easting 602110 Northing 4837746

/ Monitoring and Te Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7212254 Lot Conc BRAMPTON CITY / PEEL

Date 2012-05-04 DD/MM/YYYY

Elev (masl) Easting 601680 Northing 4837811

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 8.5 (mbgs) Bottom of Screen 11.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	CLAY / SILT / FILL
11.5		GREY	SILT / CLAY / DENSE

7214697 Lot Conc BRAMPTON CITY / PEEL

Date 2013-10-21 DD/MM/YYYY

Elev (masl) Easting 601162 Northing 4838326

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 2.1 (mbgs) Bottom of Screen 5.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7215922 Lot Conc BRAMPTON CITY / PEEL

Date 2013-11-27 DD/MM/YYYY

Elev (masl) Easting 601401 Northing 4839577

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1 inch Casing Material: PLASTIC

Top of Screen 2.1 (mbgs) Bottom of Screen 3.7 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1			OTHER / /
0.6			SAND / FILL /
3.7			SILT / TILL /

7215923 Lot Conc BRAMPTON CITY / PEEL

Date 2013-11-27 DD/MM/YYYY

Elev (masl) Easting 601402 Northing 4839577

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1 inch Casing Material: PLASTIC

Top of Screen 2.1 (mbgs) Bottom of Screen 3.7 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1			OTHER / /
0.6			SAND / FILL /

Well Record #

									3.7			SAND /		TILL	/
7216098	**Lot**		**Conc**			**BRAMPTON CITY / PEEL**						Flowing?			
Date	2013-12-20	Elev		(masl)	Easting	602024	Northing	4837681				SWL		(mbgs)	(masl)
	DD/MM/YYYY	/ Monitoring and Te			Monitoring and Test Hole		UTM RC	4	margin of error : 30 m - 100 m			Pumping WL		(mbgs)	(masl)
		Water Found		(mbgs)		(masl)						Pump Rate		(LPM)	/
		Casing Diameter	1.3	inch	Casing Material:	PLASTIC			Depth (m)	Elev (masl)		Spec. Cap.		(LPM/m)	Hour / Minute
		Top of Screen	2.9	(mbgs)	Bottom of Screen	5.9	(mbgs)		0.0		Color			Soil Descriptions	
		Screen Interval	3.0	(m)											
									1.2		BROWN	FILL /		LOOSE	/
									3.7		BROWN	SAND /		SILT	/
									5.5		GREY	CLAY /		SILT	/ DENSE
									5.9		GREY	CLAY /		SILT	/ WATER-BEARING
7216099	**Lot**		**Conc**			**BRAMPTON CITY / PEEL**						Flowing?			
Date	2013-12-20	Elev		(masl)	Easting	602149	Northing	4837695				SWL		(mbgs)	(masl)
	DD/MM/YYYY	/ Monitoring and Te			Monitoring and Test Hole		UTM RC	4	margin of error : 30 m - 100 m			Pumping WL		(mbgs)	(masl)
		Water Found		(mbgs)		(masl)						Pump Rate		(LPM)	/
		Casing Diameter	2	inch	Casing Material:	PLASTIC			Depth (m)	Elev (masl)		Spec. Cap.		(LPM/m)	Hour / Minute
		Top of Screen	3.0	(mbgs)	Bottom of Screen	6.1	(mbgs)		0.0		Color			Soil Descriptions	
		Screen Interval	3.0	(m)											
									2.4		BROWN	FILL /			/
									6.1		GREY	CLAY /		SILTY	/
7216100	**Lot**		**Conc**			**BRAMPTON CITY / PEEL**						Flowing?			
Date	2013-12-20	Elev		(masl)	Easting	602077	Northing	4837603				SWL		(mbgs)	(masl)
	DD/MM/YYYY	/ Monitoring and Te			Monitoring and Test Hole		UTM RC	4	margin of error : 30 m - 100 m			Pumping WL		(mbgs)	(masl)
		Water Found		(mbgs)		(masl)						Pump Rate		(LPM)	/
		Casing Diameter	2	inch	Casing Material:	PLASTIC			Depth (m)	Elev (masl)		Spec. Cap.		(LPM/m)	Hour / Minute
		Top of Screen	3.0	(mbgs)	Bottom of Screen	6.1	(mbgs)		0.0		Color			Soil Descriptions	
		Screen Interval	3.0	(m)											
									0.1		GREY	/			/
									1.5		BROWN	FILL /			/
									6.1		GREY	CLAY /		SILTY	/
7216101	**Lot**		**Conc**			**BRAMPTON CITY / PEEL**						Flowing?			
Date	2013-12-20	Elev		(masl)	Easting	602032	Northing	4837654				SWL		(mbgs)	(masl)
	DD/MM/YYYY	/ Monitoring and Te			Monitoring and Test Hole		UTM RC	4	margin of error : 30 m - 100 m			Pumping WL		(mbgs)	(masl)
		Water Found		(mbgs)		(masl)						Pump Rate		(LPM)	/
		Casing Diameter	2	inch	Casing Material:	PLASTIC			Depth (m)	Elev (masl)		Spec. Cap.		(LPM/m)	Hour / Minute
		Top of Screen	1.8	(mbgs)	Bottom of Screen	4.9	(mbgs)		0.0		Color			Soil Descriptions	
		Screen Interval	3.0	(m)											
									0.1		BLACK	/			/
									3.0		BROWN	FILL /			/
									4.9		GREY	CLAY /		SILTY	/

Well Record #

7216857 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-01-24 DD/MM/YYYY | Elev (masl) | Easting 601142 | Northing 4839452 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / / LOOSE
4.6		BROWN	SAND / SILT /
5.2		GREY	SILT / SAND / WATER-BEARING
6.1		GREY	CLAY / SILT / WATER-BEARING

7216858 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-01-24 DD/MM/YYYY | Elev (masl) | Easting 601182 | Northing 4839431 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / / LOOSE
4.6		BROWN	SAND / SILT /
5.2		GREY	SILT / SAND / WATER-BEARING
6.1		GREY	CLAY / SILT / DENSE

7216927 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-01-25 DD/MM/YYYY | Elev (masl) | Easting 601170 | Northing 4839432 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / / LOOSE
4.6		BROWN	SAND / SILT /
5.2		GREY	SILT / SAND / WATER-BEARING
6.1		GREY	CLAY / SILT / WATER-BEARING

7216991 Lot Conc **BRAMPTON CITY / PEEL**

Date 2012-05-03 DD/MM/YYYY | Elev (masl) / | Easting 601653 | Northing 4837784 | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

7217049 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2013-12-06 DD/MM/YYYY

Elev (masl) Easting 596303 Northing 4840654 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7217099 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-01-09 DD/MM/YYYY

Elev (masl) Easting 599276 Northing 4838697 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 7.6 (mbgs)

Screen Interval 6.1 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.3		BLACK	/		/
0.8		GREY	GRAVEL /	SAND	/
3.4		BROWN	SILT /	CLAY	/
7.6		GREY	SILT /	STONES	/

7217101 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-01-09 DD/MM/YYYY

Elev (masl) Easting 599285 Northing 4838732 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 3.1 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.3		BLACK	/		/
0.8		GREY	GRAVEL /		/
3.4		BROWN	SILT /	STONES	/
3.8		GREY	SAND /	SILT	/
6.1		GREY	SILT /		/

7217757 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-01-16 DD/MM/YYYY

Elev (masl) Easting 600992 Northing 4838976 / Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

7217758 Lot Conc BRAMPTON CITY / PEEL

Date 2014-01-16 DD/MM/YYYY | Elev (masl) | Easting 601001 | Northing 4838962 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7217759 Lot 005 Conc 02 BRAMPTON CITY / PEEL

Date 2014-01-16 DD/MM/YYYY | Elev (masl) | Easting 601009 | Northing 4838957 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7217760 Lot Conc BRAMPTON CITY / PEEL

Date 2014-01-16 DD/MM/YYYY | Elev (masl) | Easting 600984 | Northing 4839054 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7218034 Lot Conc BRAMPTON CITY / PEEL

Date 2014-02-02 DD/MM/YYYY | Elev (masl) | Easting 600391 | Northing 4838893 | / Monitoring and Te | Observation Wells | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.9		BLACK	/ /
2.1		BROWN	FILL / /
6.1		RED	SAND / SILT /

7218035 Lot Conc BRAMPTON CITY / PEEL

Date 2014-02-02 DD/MM/YYYY | Elev (masl) | Easting 600926 | Northing 4838926 | / Monitoring and Te | Observation Wells | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
		RED	SAND / SILT /
1.5		GREY	/ /
1.8		BROWN	FILL / /

Well Record #

7218851 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-14 DD/MM/YYYY

Elev (masl) Easting 596877 Northing 4838724

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 1.3 (mbgs) Bottom of Screen 4.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.7		BROWN	SAND / GRAVEL / FILL
2.8		GREY	CLAY / SILT /
4.3		GREY	CLAY / SILT /

7218852 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-14 DD/MM/YYYY

Elev (masl) Easting 596929 Northing 4838742

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 1.0 (mbgs) Bottom of Screen 4.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.7		BROWN	SAND / GRAVEL / FILL
2.8		GREY	CLAY / SILT /
4.0		GREY	CLAY / SILT /

7218853 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-13 DD/MM/YYYY

Elev (masl) Easting 596900 Northing 4838752

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 1.3 (mbgs) Bottom of Screen 4.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.7		BROWN	SAND / GRAVEL / FILL
2.8		BROWN	CLAY / SILT /
4.3		GREY	CLAY / SILT /

7218854 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-14 DD/MM/YYYY

Elev (masl) Easting 596890 Northing 4838754

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 1.0 (mbgs) Bottom of Screen 4.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.7		BROWN	SAND / GRAVEL / FILL
2.8		GREY	CLAY / SILT /
4.0		GREY	CLAY / SILT /

Well Record #

7218855 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-13 DD/MM/YYYY | Elev (masl) | Easting 596904 | Northing 4838734 | UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 1.3 (mbgs) | Bottom of Screen 4.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.7		BROWN	SAND / GRAVEL / FILL
2.8		BROWN	CLAY / SILT /
4.3		GREY	CLAY / SILT /

7218868 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-14 DD/MM/YYYY | Elev (masl) | Easting 596877 | Northing 4838724 | UTM RC 4 margin of error : 30 m - 100 m

/ Abandoned-Other

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7218869 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-14 DD/MM/YYYY | Elev (masl) | Easting 596929 | Northing 4838742 | UTM RC 4 margin of error : 30 m - 100 m

/ Abandoned-Other

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7218870 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-14 DD/MM/YYYY | Elev (masl) | Easting 596890 | Northing 4838754 | UTM RC 4 margin of error : 30 m - 100 m

/ Abandoned-Other

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7218871 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-03-13 DD/MM/YYYY | Elev (masl) | Easting 596900 | Northing 4838752 | UTM RC 4 margin of error : 30 m - 100 m

/ Abandoned-Other

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

7218872 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2013-03-14 (DD/MM/YYYY) | Elev (masl) | Easting 596904 | Northing 4838734 | / | Abandoned-Other | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7219199 Lot 013 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-02-24 (DD/MM/YYYY) | Elev (masl) | Easting 596155 | Northing 4840708 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 0.8 inch | Casing Material: PLASTIC

Top of Screen 3.8 (mbgs) | Bottom of Screen 5.3 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.6		BROWN	SAND / GRAVEL / WATER-BEARING
5.3		BROWN	CLAY / GRAVEL / WATER-BEARING

7219340 Lot Conc BRAMPTON CITY / PEEL

Date 2014-03-15 (DD/MM/YYYY) | Elev (masl) | Easting 601002 | Northing 4838941 | / Monitoring and Te | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 4.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	SILT / FILL /
3.0		GREY	SILT / /
4.3		RED	TILL / SILT /

7219358 Lot Conc BRAMPTON CITY / PEEL

Date 2014-03-07 (DD/MM/YYYY) | Elev (masl) | Easting 600047 | Northing 4839597 | / Monitoring and Te | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.2 cm | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / GRAVEL / LOOSE
1.5		BROWN	SILT / CLAY / DENSE
4.6		GREY	SILT / CLAY / DENSE

7219364 Lot Conc BRAMPTON CITY / PEEL

Date 2014-03-07 (DD/MM/YYYY) | Elev (masl) | Easting 600034 | Northing 4839621 | / Monitoring and Te | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.2 cm | Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) | Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

			0.6	BROWN	FILL /	GRAVEL	/ LOOSE
			2.4	BROWN	SILT /	CLAY	/ DENSE
			5.5	GREY	SILT /	CLAY	/ DENSE

7219365 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-03-07 (DD/MM/YYYY)
Elev (masl) Easting 600039 Northing 4839605
/ Monitoring and Te Test Hole UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 5.2 cm Casing Material: PLASTIC
Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)
Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.6		BROWN	FILL /	GRAVEL	/ LOOSE
1.5		BROWN	SILT /	CLAY	/ DENSE
4.6		GREY	SILT /	CLAY	/ DENSE

7220130 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-02-06 (DD/MM/YYYY)
Elev (masl) Easting 601146 Northing 4839000
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 5.2 cm Casing Material: PLASTIC
Top of Screen 2.5 (mbgs) Bottom of Screen 4.6 (mbgs)
Screen Interval 2.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.6		BROWN	FILL /	GRAVEL	/ LOOSE
4.6		BROWN	FINE SAND /		/ PACKED

7220338 Lot Conc **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2014-04-10 (DD/MM/YYYY)
Elev (masl) Easting 593901 Northing 4842807
/ Domestic Water Supply UTM RC 4 margin of error : 30 m - 100 m
Water Found 54.9 (mbgs) (masl) Untested
Casing Diameter 6.1 inch Casing Material: STEEL
Top of Screen 53.6 (mbgs) Bottom of Screen 54.9 (mbgs)
Screen Interval 1.2 (m)

Flowing?
SWL 41.5 (mbgs) (masl)
Pumping WL 42.7 (mbgs) (masl)
Pump Rate 36.4 (LPM) 1 / 0
Spec. Cap. 29.83 (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
54.9		BROWN	SAND /	GRAVEL	/ LOOSE

7229363 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-09-16 (DD/MM/YYYY)
Elev (masl) Easting 600734 Northing 4838949
/ Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 2.4 (mbgs) Bottom of Screen 5.5 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
		BROWN	SILT /	SAND	/
1.2		BLACK	OTHER /		/
1.8		BROWN	SAND /	GRAVEL	/
4.0		BROWN	SAND /	SILT	/

Well Record #

7229364 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-09-16 DD/MM/YYYY | Elev (masl) | Easting 600787 | Northing 4838995 | UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring and Te Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions			
0.0						
1.2		BLACK	OTHER /			/
4.6		BROWN	SAND /	SILT		/

7229365 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-09-16 DD/MM/YYYY | Elev (masl) | Easting 600767 | Northing 4838973 | UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring and Te Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions			
0.0						
0.1		BLACK	OTHER /			/
0.9		BROWN	SAND /			/
3.7		BROWN	SILT /	SAND		/
4.6		RED	SAND /	SILT		/

7229366 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-09-16 DD/MM/YYYY | Elev (masl) | Easting 600716 | Northing 4838921 | UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring and Te Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions			
0.0						
1.2		BLACK	OTHER /			/
4.3		BROWN	SILT /	SAND		/
6.1		RED	TILL /			/

7229367 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-09-18 DD/MM/YYYY | Elev (masl) | Easting 600813 | Northing 4839042 | UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring and Te Monitoring and Test Hole

Water Found (mbgs) (masl)

Casing Diameter 5.2 cm | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.1 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions			
0.0						
0.6		BROWN	FILL /	GRAVEL	/	LOOSE
1.5		BROWN	CLAY /	SILT	/	DENSE
3.7		BROWN	SAND /	SILT	/	SOFT
4.6		RED	SILT /	CLAY	/	DENSE

Well Record #

7233319 Lot Conc BRAMPTON CITY / PEEL

Date 2014-10-03 DD/MM/YYYY

Elev (masl) Easting 600000 Northing 4839561 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7238554 Lot Conc BRAMPTON CITY / PEEL

Date 2015-01-26 DD/MM/YYYY

Elev (masl) Easting 601001 Northing 4838987 / Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.3 inch Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) Bottom of Screen 2.7 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ /
1.2		BROWN	FILL / GRAVEL /
2.7		GREY	TILL / SILT / SAND

7238555 Lot Conc BRAMPTON CITY / PEEL

Date 2015-01-26 DD/MM/YYYY

Elev (masl) Easting 600995 Northing 4838963 / Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.3 inch Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 3.0 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ /
1.2		BROWN	FILL / /
3.0		GREY	SILT / SAND /

7238556 Lot Conc BRAMPTON CITY / PEEL

Date 2015-01-27 DD/MM/YYYY

Elev (masl) Easting 600968 Northing 4839033 / Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter inch Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) Bottom of Screen 4.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / GRAVEL / LOOSE
3.0		BROWN	SILT / CLAY / DENSE
4.3		RED	SILT / CLAY / DENSE

Well Record #

7238557 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-01-27 DD/MM/YYYY | Elev (masl) | Easting 601099 | Northing 4838993 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter inch | Casing Material: PLASTIC | Top of Screen 1.2 (mbgs) | Bottom of Screen 4.3 (mbgs) | Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / GRAVEL / LOOSE
3.0		BROWN	SILT / CLAY / DENSE
4.3		RED	SILT / CLAY / DENSE

7238558 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-01-27 DD/MM/YYYY | Elev (masl) | Easting 601078 | Northing 4838889 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter inch | Casing Material: PLASTIC | Top of Screen 1.5 (mbgs) | Bottom of Screen 3.0 (mbgs) | Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / GRAVEL / LOOSE
1.5		BROWN	SILT / CLAY / DENSE
3.0		RED	SILT / CLAY / DENSE

7238559 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-01-28 DD/MM/YYYY | Elev (masl) | Easting 601060 | Northing 4838853 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter inch | Casing Material: PLASTIC | Top of Screen 1.2 (mbgs) | Bottom of Screen 2.7 (mbgs) | Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / GRAVEL / LOOSE
2.7		BROWN	SILT / CLAY / DENSE

7238560 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-01-28 DD/MM/YYYY | Elev (masl) | Easting 601040 | Northing 4838944 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter inch | Casing Material: PLASTIC | Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs) | Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	GRAVEL / FILL / LOOSE
1.5		BROWN	SILT / CLAY / DENSE
4.6		RED	SILT / CLAY / DENSE

Well Record #

7238561 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-01-28 DD/MM/YYYY | Elev (masl) | Easting 600927 | Northing 4838981 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter inch | Casing Material: PLASTIC | Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / GRAVEL / LOOSE
1.5		BROWN	SILT / CLAY / DENSE
4.6		RED	SILT / CLAY / DENSE

7238562 Lot Conc **BRAMPTON CITY / PEEL**

Date 2014-01-28 DD/MM/YYYY | Elev (masl) | Easting 601022 | Northing 4838942 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter inch | Casing Material: PLASTIC | Top of Screen 1.2 (mbgs) | Bottom of Screen 4.3 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / GRAVEL / LOOSE
1.2		BROWN	SILT / CLAY / DENSE
4.3		RED	SILT / CLAY / DENSE

7239783 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-03-17 DD/MM/YYYY | Elev (masl) | Easting 602272 | Northing 4837485 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		BLACK	/ / HARD
4.6		BROWN	TILL / SILT / SOFT
6.1		GREY	SILT / TILL / SOFT

7239784 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-03-17 DD/MM/YYYY | Elev (masl) | Easting 602266 | Northing 4837470 | / Monitoring and Te Test Hole | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 5.2 cm | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.0 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1		BLACK	/ / SOFT
4.0		BROWN	SAND / GRAVEL / HARD
6.0		GREY	SILT / TILL / HARD

Well Record #

7240333 Lot Conc BRAMPTON CITY / PEEL

Date 2015-04-06 DD/MM/YYYY

Elev (masl) Easting 601381 Northing 4839501

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1		BLACK	OTHER / /
0.6		BROWN	SAND / GRAVEL /
4.6		BROWN	CLAY / SILT /
6.1		GREY	SHALE / / WEATHERED

7240334 Lot Conc BRAMPTON CITY / PEEL

Date 2015-04-06 DD/MM/YYYY

Elev (masl) Easting 601384 Northing 4839505

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BLACK	OTHER / GRAVEL /
4.3		BROWN	SAND / SILT / CLAY
6.1		GREY	SHALE / / WEATHERED

7240374 Lot Conc BRAMPTON CITY / PEEL

Date 2015-03-23 DD/MM/YYYY

Elev (masl) Easting 600997 Northing 4838944

/ Monitoring and Te Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found 1.5 (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) Bottom of Screen 1.5 (mbgs)

Screen Interval 0.6 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ GRAVEL / LOOSE
1.5		BROWN	SAND / SILT / LOOSE
3.0		BROWN	SILT / SAND / WATER-BEARING
4.6		RED	SILT / ROCK / DENSE

7240375 Lot Conc BRAMPTON CITY / PEEL

Date 2015-03-23 DD/MM/YYYY

Elev (masl) Easting 600997 Northing 4838944

/ Monitoring and Te Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.0 (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 0.9 (mbgs) Bottom of Screen 1.8 (mbgs)

Screen Interval 0.9 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ GRAVEL / LOOSE
0.9		BROWN	SAND / SILT / LOOSE
2.4		BROWN	SAND / / DENSE
4.9		RED	SILT / SAND / DENSE

Well Record #

7245992 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-07-28 DD/MM/YYYY | Elev (masl) | Easting 601237 | Northing 4839232 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 3.8 cm | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SAND / GRAVEL / LOOSE
4.5		BROWN	SILT / DENSE /

7245993 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-07-28 DD/MM/YYYY | Elev (masl) | Easting 601265 | Northing 4839204 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 3.8 cm | Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) | Bottom of Screen 4.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SAND / GRAVEL /
4.5		BROWN	SILT / /

7246995 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2015-07-15 DD/MM/YYYY | Elev (masl) | Easting 595847 | Northing 4841013 | / Monitoring and Te | Abandoned Monitoring and Test | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 6.1 (mbgs) | Bottom of Screen 9.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7246996 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2015-07-15 DD/MM/YYYY | Elev (masl) | Easting 595768 | Northing 4840947 | / | Abandoned-Other | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 4.9 (mbgs) | Bottom of Screen 7.9 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7246997 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2015-02-15 DD/MM/YYYY | Elev (masl) | Easting 595853 | Northing 4840834 | / Monitoring and Te | Abandoned Monitoring and Test | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 6.1 (mbgs) | Bottom of Screen 9.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

Well Record #

7246999 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2015-07-15 DD/MM/YYYY

Elev (masl) Easting 595946 Northing 4840867

/ Monitoring and Te Abandoned Monitoring and Test UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.4 (mbgs) Bottom of Screen 0.6 (mbgs)

Screen Interval -2.7 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7247000 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2015-07-15 DD/MM/YYYY

Elev (masl) Easting 596052 Northing 4840867

/ Monitoring and Te Test Hole UTM RC 5 margin of error : 100 m - 300 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 6.1 (mbgs) Bottom of Screen 9.1 (mbgs)

Screen Interval 3.0 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7247001 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2015-07-15 DD/MM/YYYY

Elev (masl) Easting 595946 Northing 4841015

/ Monitoring and Te Abandoned Monitoring and Test UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7248959 Lot 017 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2015-09-11 DD/MM/YYYY

Elev (masl) Easting 594170 Northing 4842307

/ Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.7 (mbgs) (masl) FRESH

Casing Diameter 15 cm Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7249563 Lot Conc BRAMPTON CITY / PEEL

Date 2015-09-17 DD/MM/YYYY

Elev (masl) Easting 599371 Northing 4838349

/ Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found 4.6 (mbgs) (masl) FRESH

Casing Diameter 90 cm Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7255001 **Lot 014 Conc 02 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2015-11-19 (DD/MM/YYYY) | Elev (masl) | Easting 603627 | Northing 4836155 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found 10.7 (mbgs) (masl) FRESH

Casing Diameter 90 cm | Casing Material: CONCRETE

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7255002 **Lot 014 Conc 02 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2015-11-19 (DD/MM/YYYY) | Elev (masl) | Easting 603634 | Northing 4836155 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found 1.3 (mbgs) (masl) FRESH

Casing Diameter 90 cm | Casing Material: OTHER

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7255003 **Lot 014 Conc 02 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2015-11-19 (DD/MM/YYYY) | Elev (masl) | Easting 603657 | Northing 4836120 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m

Water Found 2.3 (mbgs) (masl) FRESH

Casing Diameter 15 cm | Casing Material: STEEL

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7255009 **Lot Conc BRAMPTON CITY / PEEL**

Date 2015-12-02 (DD/MM/YYYY) | Elev (masl) | Easting 601892 | Northing 4837816 | / | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7255217 **Lot Conc BRAMPTON CITY / PEEL**

Date 2015-11-12 (DD/MM/YYYY) | Elev (masl) | Easting 602595 | Northing 4837081 | / Monitoring and Te | Monitoring and Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) Untested

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 4.0 (mbgs) | Bottom of Screen 7.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	SAND / GRAVEL / FILL
7.0		GREY	CLAY / SILT /

Well Record #

7255990 Lot Conc **BRAMPTON CITY / PEEL**

Date 2015-12-09 DD/MM/YYYY | Elev (masl) | Easting 602522 | Northing 4837041 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl) Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 1.0 (mbgs) | Bottom of Screen 4.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.0		BROWN	CLAY / SAND / LOOSE
3.0		BROWN	CLAY / SAND / DENSE
4.0		GREY	CLAY / SILT / DENSE

7257922 Lot Conc **BRAMPTON CITY / PEEL**

Date 2016-01-14 DD/MM/YYYY | Elev (masl) | Easting 601013 | Northing 4838934 | / Monitoring and Te | Monitoring and Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	SAND / SILT /
4.6		RED	SHALE / WEATHERED / DENSE

7257923 Lot Conc **BRAMPTON CITY / PEEL**

Date 2016-01-14 DD/MM/YYYY | Elev (masl) | Easting 601008 | Northing 4838949 | / Monitoring and Te | Monitoring and Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 5.6 (mbgs) | Bottom of Screen 8.7 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.2		BROWN	SAND / SILT / LOOSE
8.7		BROWN	SHALE / WEATHERED / DENSE

7262154 Lot Conc **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2016-03-04 DD/MM/YYYY | Elev (masl) | Easting 594027 | Northing 4842321 | / Monitoring and Te | Monitoring and Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 7.6 (mbgs) (masl) Untested

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 6.1 (mbgs) | Bottom of Screen 9.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
7.6		BROWN	CLAY / SILT / SAND
9.1		RED	CLAY / SILT / SHALE

7265666 Lot Conc **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2016-02-26 DD/MM/YYYY | Elev (masl) | Easting 593489 | Northing 4843054 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

							1.5	BROWN	FILL /		/
							4.6	BROWN	MEDIUM SAND /		/

7265669 Lot Conc CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 2016-02-26 DD/MM/YYYY

Elev (masl) Easting 592585 Northing 4843077

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 6.1 (mbgs) Bottom of Screen 9.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
				/	/

7266922 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2014-10-24 DD/MM/YYYY

Elev (masl) Easting 598996 Northing 4838630

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
				/	/

7267541 Lot Conc BRAMPTON CITY / PEEL

Date 2016-06-24 DD/MM/YYYY

Elev (masl) Easting 600804 Northing 4839055

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.2		BLACK	OTHER /		/ SOFT
4.6		BROWN	TILL /	SILT	/ SOFT

7267542 Lot Conc BRAMPTON CITY / PEEL

Date 2016-06-24 DD/MM/YYYY

Elev (masl) Easting 600811 Northing 4839059

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.2		BLACK	OTHER /		/ SOFT
4.6		BROWN	TILL /	SILT	/ SOFT

7267543 Lot Conc BRAMPTON CITY / PEEL

Date 2016-06-24 DD/MM/YYYY

Elev (masl) Easting 600810 Northing 4839005

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 1.3 inch Casing Material: PLASTIC

Top of Screen 0.6 (mbgs) Bottom of Screen 2.1 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
1.2			SAND /		/ LOOSE

Well Record #

2.1 / SILTY / LOOSE

7271205 Lot Conc BRAMPTON CITY / PEEL

Date DD/MM/YYYY / Elev (masl) Easting 601794 Northing 4837877 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				

/ /

7274652 Lot Conc BRAMPTON CITY / PEEL

Date 2015-05-06 DD/MM/YYYY / Elev (masl) Easting 601043 Northing 4838590 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				

/ /

7276926 Lot Conc BRAMPTON CITY / PEEL

Date 2016-11-02 DD/MM/YYYY / Monitoring and Te Elev (masl) Easting 600960 Northing 4838942 Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				
0.9		BLACK	/	/
4.0		BROWN	SILT / SAND	/ GRAVEL
4.6		RED	SHALE /	/ WEATHERED

7276927 Lot Conc BRAMPTON CITY / PEEL

Date 2016-11-02 DD/MM/YYYY / Monitoring and Te Elev (masl) Easting 600909 Northing 4838970 Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 4.6 (mbgs) Bottom of Screen 7.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				
0.9		BLACK	/	/
3.7		BROWN	SAND / SILT	/ GRAVEL
7.6		RED	SHALE /	/ WEATHERED

7276928 Lot Conc BRAMPTON CITY / PEEL

Date 2016-11-02 DD/MM/YYYY / Monitoring and Te Elev (masl) Easting 600913 Northing 4838847 Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				

Well Record #

			0.1	BLACK	/		/
			0.6	BROWN	SAND /	GRAVEL	/
			5.5	BROWN	SILT /	SAND	/ DENSE

7277183 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2016-11-03 (DD/MM/YYYY) Elev (masl) Easting 596031 Northing 4840853
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 0.7 inch Casing Material: PLASTIC
Top of Screen 4.6 (mbgs) Bottom of Screen 7.6 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.3			GRAVEL /		/
4.0		BROWN	CLAY /	FILL	/ SILT
7.6		BROWN	TILL /	GRAVEL	/ SILT

7277923 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2016-11-22 (DD/MM/YYYY) Elev (masl) Easting 596410 Northing 4839960
/ Monitoring and Te UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 2.7 (mbgs) Bottom of Screen 5.8 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.2		BLACK	/		/ CEMENTED
1.8		BROWN	SILT /	SAND	/
58.2		RED	SHALE /		/ WEATHERED

7277924 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2016-11-21 (DD/MM/YYYY) Elev (masl) Easting 596555 Northing 4839843
/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 2.7 (mbgs) Bottom of Screen 5.8 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.2		BLACK	/		/ CEMENTED
1.8		BROWN	SILT /	SAND	/
5.8		RED	SHALE /		/ WEATHERED

7279266 Lot Conc BRAMPTON CITY / PEEL

Date 2017-01-04 (DD/MM/YYYY) Elev (masl) Easting 601365 Northing 4838420
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 12.2 (mbgs) Bottom of Screen 15.2 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.3		BROWN	SAND /	SILT	/ SOFT
12.2		BROWN	SILT /	CLAY	/ GRAVEL
15.2		BLACK	SHALE /		/ HARD

Well Record #

7283323 Lot Conc **BRAMPTON CITY / PEEL**

Date 2016-08-15 DD/MM/YYYY | Elev (masl) | Easting 601817 | Northing 4837543 | Monitoring / Test Hole | Monitoring and Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found 4.5 (mbgs) (masl) Untested

Casing Diameter 5 cm | Casing Material: PLASTIC

Top of Screen 4.5 (mbgs) | Bottom of Screen 6.0 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1		BLACK	OTHER / / HARD
1.1		BROWN	SILT / SANDY / FILL
6.0		GREY	SILT / SANDY / DENSE

7283346 Lot Conc **BRAMPTON CITY / PEEL**

Date 2016-08-18 DD/MM/YYYY | Elev (masl) | Easting 600345 | Northing 4838929 | Monitoring / Test Hole | Monitoring and Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found 1.7 (mbgs) (masl) Untested

Casing Diameter 5 cm | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 1.6 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1		BLACK	OTHER / / HARD
2.1		BROWN	SAND / GRAVEL / FILL
4.6		BROWN	SILT / SANDY / DENSE

7283348 Lot Conc **BRAMPTON CITY / PEEL**

Date 2016-08-17 DD/MM/YYYY | Elev (masl) | Easting 600395 | Northing 4839123 | Monitoring / Test Hole | Monitoring and Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.0 (mbgs) (masl) Untested

Casing Diameter 5 cm | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 1.6 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1		BLACK	OTHER / / HARD
0.8		BROWN	SILT / CLAYEY / FILL
2.5		BROWN	SILT / SANDY / DENSE
4.6		GREY	SAND / SILT / DENSE

7283936 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2016-12-09 DD/MM/YYYY | Elev / (masl) | Easting 596770 | Northing 4840082 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

Well Record #

7284163 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2017-02-03 DD/MM/YYYY | Elev (masl) | Easting 597436 | Northing 4839435 | Monitoring / Test Hole | Monitoring and Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 4.6 (mbgs) | Bottom of Screen 1.5 (mbgs)

Screen Interval -3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	FILL / GRAVEL / LOOSE
2.7		BROWN	SILT / CLAY / WATER-BEARING
4.6		RED	SHALE / / HARD

7287407 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-05-11 DD/MM/YYYY | Elev (masl) | Easting 601133 | Northing 4838391 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 19.8 (mbgs) | Bottom of Screen 21.3 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.9		GREY	/ CEMENTED /
3.0		BROWN	SAND / SILT / PACKED
4.6		GREY	SHALE / TILL / HARD
21.3		GREY	SHALE / / HARD

7289347 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-03-24 DD/MM/YYYY | Elev (masl) | Easting 602590 | Northing 4837047 | / Test Hole | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.1			SILT / / SANDY

7289348 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-03-24 DD/MM/YYYY | Elev (masl) | Easting 602428 | Northing 4837208 | / Test Hole | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.1			SILT / / SANDY

7289349 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-03-30 DD/MM/YYYY | Elev (masl) | Easting 602514 | Northing 4837117 | / Test Hole | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.7 (mbgs) | Bottom of Screen 6.7 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

7291724 Lot Conc **BRAMPTON CITY / PEEL**

Date DD/MM/YYYY / Elev (masl) Easting 601860 Northing 4837858 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? / SWL (mbgs) (masl) / Pumping WL (mbgs) (masl) / Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

7292216 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-07-10 DD/MM/YYYY / Elev (masl) Easting 602164 Northing 4837562 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? / SWL (mbgs) (masl) / Pumping WL (mbgs) (masl) / Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

7294565 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2017-08-04 DD/MM/YYYY / Elev (masl) Easting 596500 Northing 4839957 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? / SWL (mbgs) (masl) / Pumping WL (mbgs) (masl) / Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

7298061 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-09-08 DD/MM/YYYY Elev (masl) Easting 600054 Northing 4839531 Monitoring / Test Hole Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 5.4 (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing? / SWL (mbgs) (masl) / Pumping WL (mbgs) (masl) / Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ /
0.3		GREY	GRAVEL / SAND /
4.5		BROWN	CLAY / SILTY / DENSE
6.0		BROWN	SILT / SANDY / WATER-BEARING

7298062 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-09-08 DD/MM/YYYY Elev (masl) Easting 599994 Northing 4839552 Monitoring / Test Hole Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 5.3 (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing? / SWL (mbgs) (masl) / Pumping WL (mbgs) (masl) / Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.2		GREY	/ /

Well Record #

			0.3	GREY	GRAVEL /	SAND	/
			4.5	BROWN	SILT /	SILTY	/ DENSE
			6.0	BROWN	SILT /	SILTY	/ WATER-BEARING

7298063 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-09-08 (DD/MM/YYYY)
Elev (masl) Easting 600040 Northing 4839526
Monitoring / Test Hole Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found 5.3 (mbgs) (masl)
Casing Diameter 5.1 cm Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.0 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Color	Soil Descriptions		
0.2		GREY	/		/
0.3		GREY	GRAVEL /	SAND	/
4.5		BROWN	CLAY /	SILTY	/ DENSE
6.0		BROWN	SILT /	SANDY	/ WATER-BEARING

7298064 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-09-08 (DD/MM/YYYY)
Elev (masl) Easting 600035 Northing 4839534
Monitoring / Test Hole Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found 4.5 (mbgs) (masl)
Casing Diameter 5.1 cm Casing Material: PLASTIC
Top of Screen 2.3 (mbgs) Bottom of Screen 5.3 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Color	Soil Descriptions		
0.2		GREY	/		/
3.0		GREY	GRAVEL /	SAND	/
4.5		BROWN	CLAY /	SILTY	/ DENSE
5.4		BROWN	SILT /	SILT	/ WATER-BEARING

7298263 Lot 005 Conc 02 **BRAMPTON CITY / PEEL**

Date 2017-10-19 (DD/MM/YYYY)
Elev (masl) Easting 601192 Northing 4839254
/ Monitoring Observation Wells UTM RC 3 margin of error : 10 - 30 m
Water Found (mbgs) (masl)
Casing Diameter 38 cm Casing Material: PLASTIC
Top of Screen 2.4 (mbgs) Bottom of Screen 3.9 (mbgs)
Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Color	Soil Descriptions		
3.9		BROWN	SAND /	GRAVEL	/ DENSE

7298264 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-19 (DD/MM/YYYY)
Elev (masl) Easting 601192 Northing 4839254
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 3.8 cm Casing Material: PLASTIC
Top of Screen 1.2 (mbgs) Bottom of Screen 2.7 (mbgs)
Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color			
0.0		Color	Soil Descriptions		
27.0		BROWN	SAND /	FILL	/ GRAVEL

Well Record #

7298265 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-19 DD/MM/YYYY | Elev (masl) | Easting 601326 | Northing 4839176 | / Monitoring Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 3.8 cm | Casing Material: PLASTIC | Top of Screen 2.4 (mbgs) | Bottom of Screen 3.9 (mbgs) | Screen Interval 1.5 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.9		BROWN	SAND / GRAVEL / DENSE

7298266 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-19 DD/MM/YYYY | Elev (masl) | Easting 601300 | Northing 4839182 | / Monitoring Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 3.8 cm | Casing Material: PLASTIC | Top of Screen 2.3 (mbgs) | Bottom of Screen 381.0 (mbgs) | Screen Interval 378.7 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
381.0		BROWN	SAND / GRAVEL / DENSE

7298267 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-19 DD/MM/YYYY | Elev (masl) | Easting 601325 | Northing 4839215 | / Monitoring Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 3.8 cm | Casing Material: PLASTIC | Top of Screen 1.8 (mbgs) | Bottom of Screen 3.3 (mbgs) | Screen Interval 1.5 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.3		BROWN	SAND / GRAVEL / DENSE

7298268 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-19 DD/MM/YYYY | Elev (masl) | Easting 601220 | Northing 4839238 | / Monitoring Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 3.8 cm | Casing Material: PLASTIC | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.9		BROWN	SAND / GRAVEL / DENSE

7298269 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-19 DD/MM/YYYY | Elev (masl) | Easting 601208 | Northing 4839254 | / Monitoring Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 3.8 cm | Casing Material: PLASTIC | Top of Screen 1.8 (mbgs) | Bottom of Screen 3.3 (mbgs) | Screen Interval 1.5 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.3		BROWN	SAND / GRAVEL / DENSE

Well Record #

7298270 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-19 DD/MM/YYYY

Elev (masl) Easting 601201 Northing 4839274

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 3.8 cm Casing Material: PLASTIC

Top of Screen 2.7 (mbgs) Bottom of Screen 4.2 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.2		BROWN	SAND / GRAVEL / DENSE

7298271 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-19 DD/MM/YYYY

Elev (masl) Easting 601196 Northing 4839270

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 3.8 cm Casing Material: PLASTIC

Top of Screen 2.3 (mbgs) Bottom of Screen 3.8 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.8		BROWN	SAND / GRAVEL / DENSE

7300300 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2017-11-15 DD/MM/YYYY

Elev (masl) Easting 592324 Northing 4844737

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 9.8 (mbgs) Bottom of Screen 12.2 (mbgs)

Screen Interval 2.4 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	TOPSOIL / /
12.2		BROWN	SAND / /

7300314 Lot 021 Conc 01 **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2017-11-14 DD/MM/YYYY

Elev (masl) Easting 592406 Northing 4843624

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.7 (mbgs) (masl) Untested

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.7 (mbgs) Bottom of Screen 5.2 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	TOPSOIL / /
6.1		GREY	SILT / SAND /
7.6		RED	TILL / /

7300315 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2017-11-15 DD/MM/YYYY

Elev (masl) Easting 592095 Northing 4844417

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 6.4 (mbgs) Bottom of Screen 7.9 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	TOPSOIL / /
7.6		GREY	SAND / /

Well Record #

										10.7		RED		CLAY /	TILL	/
7300664	Lot		Conc				BRAMPTON CITY / PEEL						Flowing?			
Date	2017-10-10	Elev		(masl)	Easting	601674		Northing	4837749				SWL		(mbgs)	(masl)
	DD/MM/YYYY	Monitoring / Test Hole			Observation Wells			UTM RC	4	margin of error : 30 m - 100 m			Pumping WL		(mbgs)	(masl)
		Water Found		(mbgs)		(masl)							Pump Rate		(LPM)	/
													Spec. Cap.		(LPM/m)	Hour / Minute
		Casing Diameter	2.5	inch	Casing Material:	PLASTIC				Depth (m)	Elev (masl)					
		Top of Screen	4.0	(mbgs)	Bottom of Screen	7.0	(mbgs)			0.0		Color		Soil Descriptions		
		Screen Interval	3.0	(m)												
										3.7		BROWN		SAND /	SILT	/
										7.6		GREY		CLAY /		/
7300665	Lot		Conc				BRAMPTON CITY / PEEL						Flowing?			
Date	2017-10-10	Elev		(masl)	Easting	601692		Northing	4837765				SWL		(mbgs)	(masl)
	DD/MM/YYYY	Monitoring / Test Hole			Observation Wells			UTM RC	4	margin of error : 30 m - 100 m			Pumping WL		(mbgs)	(masl)
		Water Found		(mbgs)		(masl)							Pump Rate		(LPM)	/
													Spec. Cap.		(LPM/m)	Hour / Minute
		Casing Diameter	1.3	inch	Casing Material:	PLASTIC				Depth (m)	Elev (masl)					
		Top of Screen	4.0	(mbgs)	Bottom of Screen	6.7	(mbgs)			0.0		Color		Soil Descriptions		
		Screen Interval	2.7	(m)												
										3.4		BROWN		SAND /	SILT	/
												BROWN		SAND /	SILT	/
										6.7		GREY		CLAY /		/
												GREY		CLAY /		/
7300666	Lot		Conc				BRAMPTON CITY / PEEL						Flowing?			
Date	2017-10-10	Elev		(masl)	Easting	601708		Northing	4837750				SWL		(mbgs)	(masl)
	DD/MM/YYYY	Monitoring / Test Hole			Observation Wells			UTM RC	4	margin of error : 30 m - 100 m			Pumping WL		(mbgs)	(masl)
		Water Found		(mbgs)		(masl)							Pump Rate		(LPM)	/
													Spec. Cap.		(LPM/m)	Hour / Minute
		Casing Diameter	1.3	inch	Casing Material:	PLASTIC				Depth (m)	Elev (masl)					
		Top of Screen	3.7	(mbgs)	Bottom of Screen	6.7	(mbgs)			0.0		Color		Soil Descriptions		
		Screen Interval	3.0	(m)												
										3.4		BROWN		SAND /	SILT	/
										6.7		GREY		CLAY /		/
7300667	Lot		Conc				BRAMPTON CITY / PEEL						Flowing?			
Date	2017-10-10	Elev		(masl)	Easting	601724		Northing	4837730				SWL		(mbgs)	(masl)
	DD/MM/YYYY	Monitoring / Test Hole			Observation Wells			UTM RC	4	margin of error : 30 m - 100 m			Pumping WL		(mbgs)	(masl)
		Water Found		(mbgs)		(masl)							Pump Rate		(LPM)	/
													Spec. Cap.		(LPM/m)	Hour / Minute
		Casing Diameter	1.3	inch	Casing Material:	PLASTIC				Depth (m)	Elev (masl)					
		Top of Screen	3.4	(mbgs)	Bottom of Screen	6.4	(mbgs)			0.0		Color		Soil Descriptions		
		Screen Interval	3.0	(m)												
										3.0		BROWN		SAND /	SILT	/
										6.4		GREY		CLAY /		/

Well Record #

7301191 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-11-08 DD/MM/YYYY

Elev (masl) Easting 601024 Northing 4838952

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7301789 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-13 DD/MM/YYYY

Elev (masl) Easting 600693 Northing 4838635

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7304240 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-12-13 DD/MM/YYYY

Elev (masl) Easting 600695 Northing 4838626

Monitoring / Test Hole Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 12.2 (mbgs) Bottom of Screen 15.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	SAND / SILT /
4.6		GREY	SILT / CLAY /
15.2		RED	SHALE / /

7304241 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-12-13 DD/MM/YYYY

Elev (masl) Easting 600732 Northing 4838641

Monitoring / Test Hole Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 12.2 (mbgs) Bottom of Screen 15.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
15.2		BROWN	SAND / SILT /

7304242 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-12-14 DD/MM/YYYY

Elev (masl) Easting 600679 Northing 4838674

Monitoring / Test Hole Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 13.7 (mbgs) Bottom of Screen 16.8 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	SAND / SILT /
4.6		GREY	SILT / CLAY /
16.8		RED	SHALE / /

Well Record #

7304523 Lot Conc **BRAMPTON CITY / PEEL**

Date DD/MM/YYYY / Elev (masl) Easting 602483 Northing 4837451 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7306218 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2018-01-19 DD/MM/YYYY / Elev (masl) Easting 596677 Northing 4840030 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7306247 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-01-09 DD/MM/YYYY / Elev (masl) Easting 601194 Northing 4839253 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7307950 Lot 005 Conc 02 **BRAMPTON CITY / PEEL**

Date 2017-11-22 DD/MM/YYYY / Elev (masl) Easting 601024 Northing 4838684 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7308412 Lot Conc **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2017-07-14 DD/MM/YYYY / Elev (masl) Easting 592914 Northing 4843345 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7308835 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-02-12 DD/MM/YYYY

Elev (masl) Easting 600038 Northing 4839567 / Municipal Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.1		BROWN	SAND / GRAVEL / SOFT
6.0		BROWN	SAND / SILT / GRAVEL

7308836 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-02-12 DD/MM/YYYY

Elev (masl) Easting 600045 Northing 4839550 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.1		BROWN	SAND / GRAVEL / SOFT
6.0		BROWN	SAND / SILT / GRAVEL

7308837 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-02-12 DD/MM/YYYY

Elev (masl) Easting 600037 Northing 4839548 / Municipal Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.1		BROWN	SAND / GRAVEL / SOFT
6.0		BROWN	SAND / SILT / GRAVEL

7309138 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-10-23 DD/MM/YYYY

Elev (masl) Easting 601310 Northing 4838531 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7312109 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-04-26 DD/MM/YYYY

Elev (masl) Easting 599985 Northing 4839627 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		GREY	OTHER / / HARD
6.1		BLUE	SILT / CLAY / DENSE

Well Record #

7312124 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-01-26 DD/MM/YYYY | Elev (masl) | Easting 599980 | Northing 4839594 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BROWN	TOPSOIL / / LOOSE
0.9		BROWN	FILL / GRAVEL / LOOSE
4.6		BROWN	CLAY / SILT / DENSE

7312128 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2018-01-26 DD/MM/YYYY | Elev (masl) | Easting 598215 | Northing 4838556 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 4.6 (mbgs) | Bottom of Screen 7.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BROWN	TOPSOIL / / LOOSE
7.6		BROWN	SILT / CLAY / SAND

7312145 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2018-02-27 DD/MM/YYYY | Elev (masl) | Easting 598202 | Northing 4838547 | / | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7312552 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-04-20 DD/MM/YYYY | Elev (masl) | Easting 600594 | Northing 4838635 | / | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7313575 Lot 020 Conc 02 **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2018-05-16 DD/MM/YYYY | Elev (masl) | Easting 592524 | Northing 4843141 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 9.1 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval -3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	SAND / GRAVEL / FILL
9.1		GREY	SILT / CLAY /

Well Record #

7315932 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 601079 | Northing 4838919 | UTM RC 4 margin of error : 30 m - 100 m

/ Test Hole | Abandoned-Other

Water Found 2.7 (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) 0.0 | Elev (masl)

Color | Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

7315933 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 601043 | Northing 4839003 | UTM RC 4 margin of error : 30 m - 100 m

/ Test Hole | Abandoned-Other

Water Found 3.7 (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) 0.0 | Elev (masl)

Color | Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

7315934 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 600983 | Northing 4839000 | UTM RC 4 margin of error : 30 m - 100 m

/ Test Hole | Abandoned-Other

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) 0.0 | Elev (masl)

Color | Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

7315935 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 600960 | Northing 4838956 | UTM RC 4 margin of error : 30 m - 100 m

/ Test Hole | Abandoned-Other

Water Found 2.7 (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) 0.0 | Elev (masl)

Color | Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

7315936 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 600951 | Northing 4838969 | UTM RC 4 margin of error : 30 m - 100 m

/ Test Hole | Abandoned-Other

Water Found 2.4 (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) 0.0 | Elev (masl)

Color | Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7315937 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 601059 | Northing 4838927 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 1.8 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) 0.0 | Elev (masl) | Color | Soil Descriptions

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

/ /

7315938 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 601011 | Northing 4838949 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 2.1 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) 0.0 | Elev (masl) | Color | Soil Descriptions

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

/ /

7315939 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 601002 | Northing 4838941 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 3.0 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) 0.0 | Elev (masl) | Color | Soil Descriptions

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

/ /

7315940 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 601001 | Northing 4838987 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 2.4 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) 0.0 | Elev (masl) | Color | Soil Descriptions

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

/ /

7315941 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 600997 | Northing 4838944 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 2.7 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) 0.0 | Elev (masl) | Color | Soil Descriptions

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7315942 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 601009 | Northing 4838957 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 3.7 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0 Color Soil Descriptions

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute / /

7315943 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 600926 | Northing 4838926 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 4.9 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0 Color Soil Descriptions

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute / /

7315944 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 600924 | Northing 4838987 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 2.1 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0 Color Soil Descriptions

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute / /

7315945 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-06-17 DD/MM/YYYY | Elev (masl) | Easting 601060 | Northing 4838853 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 1.5 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0 Color Soil Descriptions

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute / /

7315946 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 600968 | Northing 4839033 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 3.4 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0 Color Soil Descriptions

Flowing? SWL (mbgs) (masl) Pumping WL (mbgs) (masl) Pump Rate (LPM) / Spec. Cap. (LPM/m) Hour / Minute / /

Well Record #

7315947 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 601022 | Northing 4838942 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 2.7 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

7315948 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-17 DD/MM/YYYY | Elev (masl) | Easting 601013 | Northing 4838934 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 1.8 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

7315949 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 601017 | Northing 4838956 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 4.6 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

7315950 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 601040 | Northing 4838944 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 2.7 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

7315951 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 600994 | Northing 4838944 | / Test Hole | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 3.0 (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

Well Record #

7315952 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 601008 | Northing 4838949 | UTM RC 4 margin of error : 30 m - 100 m

/ Test Hole | Abandoned-Other | Water Found 6.7 (mbgs) (masl)

Casing Diameter | Casing Material: | Depth (m) 0.0 | Elev (masl)

Top of Screen (mbgs) | Bottom of Screen (mbgs) | Color | Soil Descriptions

Screen Interval (m)

Flowing? / SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

7315953 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 601078 | Northing 4838889 | UTM RC 4 margin of error : 30 m - 100 m

/ Test Hole | Abandoned-Other | Water Found 2.4 (mbgs) (masl)

Casing Diameter | Casing Material: | Depth (m) 0.0 | Elev (masl)

Top of Screen (mbgs) | Bottom of Screen (mbgs) | Color | Soil Descriptions

Screen Interval (m)

Flowing? / SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

7315954 Lot Conc **BRAMPTON CITY / PEEL**

Date 2017-08-18 DD/MM/YYYY | Elev (masl) | Easting 601099 | Northing 4838993 | UTM RC 4 margin of error : 30 m - 100 m

/ Test Hole | Abandoned-Other | Water Found 3.4 (mbgs) (masl)

Casing Diameter | Casing Material: | Depth (m) 0.0 | Elev (masl)

Top of Screen (mbgs) | Bottom of Screen (mbgs) | Color | Soil Descriptions

Screen Interval (m)

Flowing? / SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

7315989 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-06-20 DD/MM/YYYY | Elev (masl) | Easting 601932 | Northing 4837849 | UTM RC 4 margin of error : 30 m - 100 m

/ | Water Found (mbgs) (masl)

Casing Diameter | Casing Material: | Depth (m) 0.0 | Elev (masl)

Top of Screen (mbgs) | Bottom of Screen (mbgs) | Color | Soil Descriptions

Screen Interval (m)

Flowing? / SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

7319886 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-07-12 DD/MM/YYYY | Elev (masl) | Easting 601845 | Northing 4837795 | UTM RC 4 margin of error : 30 m - 100 m

/ | Water Found (mbgs) (masl)

Casing Diameter | Casing Material: | Depth (m) 0.0 | Elev (masl)

Top of Screen (mbgs) | Bottom of Screen (mbgs) | Color | Soil Descriptions

Screen Interval (m)

Flowing? / SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Well Record #

7319896 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-06-19 DD/MM/YYYY

Elev (masl) Easting 601592 Northing 4837982

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl)

0.0 Color Soil Descriptions

/ /

7321507 Lot Conc **BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2018-10-01 DD/MM/YYYY

Elev (masl) Easting 603645 Northing 4836227

Monitoring / Test Hole Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 13.7 (mbgs) Bottom of Screen 15.2 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl)

0.0 Color Soil Descriptions

/ /

7321774 Lot 019 Conc 01 **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2018-09-24 DD/MM/YYYY

Elev (masl) Easting 593482 Northing 4842947

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.9 (mbgs) (masl) Untested

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 4.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl)

0.0 Color Soil Descriptions

3.9 BROWN SILT / CLAYEY / GRAVEL

4.5 GREY SILT / CLAYEY / GRAVEL

7325551 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2018-09-26 DD/MM/YYYY

Elev (masl) Easting 601350 Northing 4838514

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl)

0.0 Color Soil Descriptions

/ /

7327226 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2018-10-18 DD/MM/YYYY

Elev (masl) Easting 601288 Northing 4839162

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl)

0.0 Color Soil Descriptions

/ /

Well Record #

7327227 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2018-10-18 DD/MM/YYYY

Elev (masl) Easting 601199 Northing 4839257 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7327233 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2018-10-16 DD/MM/YYYY

Elev (masl) Easting 601247 Northing 4839217 / Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 5.1 cm Casing Material: PLASTIC

Top of Screen 9.1 (mbgs) Bottom of Screen 12.2 (mbgs)

Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.1		BROWN	FILL / /
5.2		BROWN	SAND / GRAVEL / SILTY
12.2		GREY	SHALE / /

7329033 Lot Conc BRAMPTON CITY / PEEL

Date 2019-01-31 DD/MM/YYYY

Elev (masl) Easting 601610 Northing 4838083 / Test Hole Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.7 (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
		GREY	CLAY / SAND /
		GREY	SILT / TILL /
		BROWN	/ /

7329307 Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2018-12-19 DD/MM/YYYY

Elev (masl) Easting 597357 Northing 4839476 / Monitoring / Test Hole Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found 4.6 (mbgs) (masl) Untested

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 9.1 (mbgs) Bottom of Screen 10.7 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	SILT / SANDY / CLAY
2.6		BROWN	SILT / CLAYEY / SANDY
4.6		GREY	SILT / SANDY / GRAVEL
7.6		BROWN	SILT / SANDY / CLAYEY
10.7		BROWN	SHALE / WEATHERED / SILT

Well Record #

7335999 **Lot 013 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2019-05-28 DD/MM/YYYY | Elev (masl) | Easting 596199 | Northing 4840671 | UTM RC 4 margin of error : 30 m - 100 m | / | Water Found (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7336672 **Lot Conc BRAMPTON CITY / PEEL**

Date 2019-06-21 DD/MM/YYYY | Elev (masl) | Easting 601788 | Northing 4837908 | UTM RC 4 margin of error : 30 m - 100 m | / Monitoring Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 2 Inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5			CLAY / SILTY /
3.0		BROWN	CLAY / /
4.6		BROWN	CLAY / SILTY /
6.1		GREY	CLAY / /

7336692 **Lot Conc BRAMPTON CITY / PEEL**

Date 2019-06-26 DD/MM/YYYY | Elev (masl) | Easting 601751 | Northing 4837884 | UTM RC 4 margin of error : 30 m - 100 m | / Monitoring Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 2 Inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5			CLAY / SILTY /
3.0		BROWN	CLAY / /
4.6		BROWN	CLAY / SILTY /
6.1		GREY	CLAY / /

7336693 **Lot Conc BRAMPTON CITY / PEEL**

Date 2019-06-26 DD/MM/YYYY | Elev (masl) | Easting 601768 | Northing 4837900 | UTM RC 4 margin of error : 30 m - 100 m | / Monitoring Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 2 Inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5			CLAY / SILTY /
3.0		BROWN	CLAY / /
4.6		BROWN	CLAY / SILTY /
6.1		GREY	CLAY / /

Well Record #

7337548 Lot 011 Conc 02 BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2019-04-12 DD/MM/YYYY | Elev (masl) | Easting 596839 | Northing 4838782 | / Monitoring and Te | Monitoring and Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) | Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1		BLACK	OTHER / /
3.7		BROWN	CLAY / SILT /
5.5		GREY	CLAY / SILT /

7340226 Lot Conc BRAMPTON CITY / PEEL

Date 2018-10-03 DD/MM/YYYY | Elev (masl) | Easting 601675 | Northing 4837975 | / | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7342255 Lot Conc BRAMPTON CITY / PEEL

Date 2019-06-13 DD/MM/YYYY | Elev (masl) | Easting 602533 | Northing 4837101 | / Monitoring and Te | Monitoring and Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC

Top of Screen 3.4 (mbgs) | Bottom of Screen 6.4 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	SAND / SILT /
3.7		BROWN	SILT / SAND /
6.4		BROWN	SAND / SILT /

7342881 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2019-06-08 DD/MM/YYYY | Elev (masl) | Easting 596352 | Northing 4840653 | / Test Hole | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl) Untested

Casing Diameter 6.1 cm | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.1		BROWN	CLAY / SILT / SOFT
6.1		BROWN	CLAY / SILT / SHALE

7343527 Lot Conc BRAMPTON CITY / PEEL

Date 2019-06-13 DD/MM/YYYY | Elev (masl) | Easting 602483 | Northing 4837152 | / Monitoring and Te | Monitoring and Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC

Top of Screen 2.7 (mbgs) | Bottom of Screen 5.8 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

0.9	BROWN	SAND /	SILT	/	
4.0	BROWN	SILT /	SAND	/	
5.8	BROWN	SAND /	SILT	/	

7347856 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2019-08-27 DD/MM/YYYY

Elev (masl) Easting 596625 Northing 4839753

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 1.2 (mbgs) Bottom of Screen 4.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.2		BLACK	OTHER /		/ HARD
0.6		BROWN	SAND /	STONES	/ OTHER
2.1		GREY	TILL /		/ HARD
4.3		RED	SHALE /		/ HARD

7351914 Lot Conc **BRAMPTON CITY / PEEL**

Date 2019-08-19 DD/MM/YYYY

Elev (masl) Easting 601392 Northing 4839430

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.8			/		/ OTHER
4.6		BROWN	/		/ TILL
6.1		GREY	/		/ TILL

7351915 Lot Conc **BRAMPTON CITY / PEEL**

Date 2019-08-19 DD/MM/YYYY

Elev (masl) Easting 601335 Northing 4839481

/ Monitoring UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 4.0 (mbgs) Bottom of Screen 7.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.8			TOPSOIL /		/
3.8		BROWN	SAND /	SILTY	/
7.6		GREY	SAND /	GRAVEL	/

7351916 Lot Conc **BRAMPTON CITY / PEEL**

Date 2019-08-19 DD/MM/YYYY

Elev (masl) Easting 601215 Northing 4839357

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 4.6 (mbgs) (masl) Untested

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.8			/		/ OTHER
			/		/ OTHER
3.8		BROWN	/	TILL	/ HARD
		BROWN	/	TILL	/ HARD
4.6		GREY	/	TILL	/ WATER-BEARING

Well Record #

4.6	GREY	/	TILL	/	WATER-BEARING
6.1	GREY	/	TILL	/	WATER-BEARING
	GREY	/	TILL	/	WATER-BEARING

7351917 Lot Conc **BRAMPTON CITY / PEEL**

Date 2019-08-16 DD/MM/YYYY — Elev (masl) — Easting 601263 — Northing 4839386 — / Monitoring — Observation Wells — UTM RC 4 — margin of error : 30 m - 100 m

Water Found 4.6 (mbgs) (masl) — Untested

Casing Diameter 2 Inch — Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) — Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions			
0.0						
1.5			GRAVEL	/	FILL	/
4.6			GRAVEL	/	TILL	/ DENSE
7.6			SILT	/	CLAY	/ TILL

7351918 Lot Conc **BRAMPTON CITY / PEEL**

Date 2019-08-16 DD/MM/YYYY — Elev (masl) — Easting 601338 — Northing 4839411 — / Monitoring — Observation Wells — UTM RC 4 — margin of error : 30 m - 100 m

Water Found 4.6 (mbgs) (masl) — Untested

Casing Diameter 2 Inch — Casing Material: PLASTIC

Top of Screen 4.6 (mbgs) — Bottom of Screen 7.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions			
0.0						
1.5			GRAVEL	/	FILL	/
4.6			GRAVEL	/	TILL	/ DENSE
7.6			SILT	/	CLAY	/ TILL

7351919 Lot Conc **BRAMPTON CITY / PEEL**

Date 2019-08-16 DD/MM/YYYY — Elev (masl) — Easting 601324 — Northing 4839343 — / Monitoring — Observation Wells — UTM RC 4 — margin of error : 30 m - 100 m

Water Found 3.0 (mbgs) (masl) — Untested

Casing Diameter 2 Inch — Casing Material: PLASTIC

Top of Screen 2.1 (mbgs) — Bottom of Screen 5.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions			
0.0						
1.5			GRAVEL	/	FILL	/
3.0			SAND	/		/
4.6			SILT	/	SAND	/ WATER-BEARING
5.2			SAND	/	WATER-BEARING	/

7352541 Lot Conc **BRAMPTON CITY / PEEL**

Date 2018-09-26 DD/MM/YYYY — Elev (masl) — Easting 601328 — Northing 4838567 — / — UTM RC 4 — margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter — Casing Material:

Top of Screen (mbgs) — Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions			
0.0						
				/		/

Well Record #

7353563 Lot Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 2020-01-29 DD/MM/YYYY

Elev (masl) Easting 594106 Northing 4842446

/ Test Hole Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.3		BROWN	TOPSOIL / SILT / OTHER
4.6		BROWN	CLAY / SILT / GRAVEL

7353797 Lot Conc BRAMPTON CITY / PEEL

Date 2019-08-14 DD/MM/YYYY

Elev (masl) Easting 601293 Northing 4839271

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 1.8 (mbgs) (masl) Untested

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4			SAND / GRAVEL / FILL
4.6		BROWN	FILL / BOULDERS /
6.1			SHALE / /

7353798 Lot Conc BRAMPTON CITY / PEEL

Date 2019-08-14 DD/MM/YYYY

Elev (masl) Easting 601339 Northing 4839292

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.7 (mbgs) (masl) Untested

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4			SAND / GRAVEL / FILL
4.6		BROWN	FILL / BOULDERS /
6.1			SHALE / /

7353799 Lot Conc BRAMPTON CITY / PEEL

Date 2019-08-14 DD/MM/YYYY

Elev (masl) Easting 601352 Northing 4839251

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 1.8 (mbgs) (masl) Untested

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4			SAND / GRAVEL / FILL
4.6		BROWN	FILL / BOULDERS /
6.1			SHALE / /

Well Record #

7353800 Lot Conc **BRAMPTON CITY / PEEL**

Date 2019-08-14 DD/MM/YYYY

Elev (masl) Easting 601292 Northing 4839416 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.0 (mbgs) (masl) Untested

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.8 (mbgs) Bottom of Screen 6.9 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5			SAND / GRAVEL /
3.0			STONES / STONES /
4.6			SHALE / DRY /
6.9			SHALE / WATER-BEARING /

7354806 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2020-01-10 DD/MM/YYYY

Elev (masl) Easting 595541 Northing 4841437 / Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 5.2 (mbgs)

Screen Interval 2.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.1		BROWN	SAND / SILT /

7354807 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2020-01-10 DD/MM/YYYY

Elev (masl) Easting 595523 Northing 4841419 / Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 5.2 (mbgs)

Screen Interval 2.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.1		BROWN	SAND / SILT /

7355069 Lot Conc **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date DD/MM/YYYY

Elev (masl) Easting 592014 Northing 4844563 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7357551 Lot Conc **BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2020-01-07 DD/MM/YYYY

Elev (masl) Easting 603650 Northing 4835928 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

Well Record #

7358024 Lot Conc **BRAMPTON CITY / PEEL**

Date 2020-03-05 DD/MM/YYYY | Elev (masl) | Easting 601223 | Northing 4839123 | UTM RC 4 margin of error : 30 m - 100 m

/ | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7358700 Lot Conc **BRAMPTON CITY / PEEL**

Date 2020-03-31 DD/MM/YYYY | Elev (masl) | Easting 600685 | Northing 4838820 | UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring and Te Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 2 Inch Casing Material: PLASTIC | Top of Screen 2.6 (mbgs) Bottom of Screen 5.6 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	SAND / GRAVEL /
0.9		BLACK	OTHER / /
5.6		RED	SHALE / / WEATHERED

7358701 Lot Conc **BRAMPTON CITY / PEEL**

Date 2020-03-21 DD/MM/YYYY | Elev (masl) | Easting 600695 | Northing 4838811 | UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring and Te Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 2 Inch Casing Material: PLASTIC | Top of Screen 4.0 (mbgs) Bottom of Screen 7.0 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	SAND / GRAVEL /
0.9		BLACK	OTHER / /
7.0		BROWN	SHALE / / WEATHERED

7358702 Lot Conc **BRAMPTON CITY / PEEL**

Date 2020-03-31 DD/MM/YYYY | Elev (masl) | Easting 600707 | Northing 4838799 | UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring and Te Monitoring and Test Hole | Water Found (mbgs) (masl) | Casing Diameter 2 Inch Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	SAND / GRAVEL /
0.9		BLACK	OTHER / /
6.1		BROWN	SHALE / / WEATHERED

Well Record #

7359020 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2020-01-13 DD/MM/YYYY

Elev (masl) Easting 595542 Northing 4841413

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.2		GREY	OTHER /		/
0.9		BROWN	FILL /		/
3.0		BROWN	SILT /	SAND	/
5.5		GREY	SILT /	SAND	/

7359021 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2020-01-13 DD/MM/YYYY

Elev (masl) Easting 595592 Northing 4841384

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.2		GREY	OTHER /		/
0.9		BROWN	FILL /		/
3.0		BROWN	SILT /	SAND	/
5.5		GREY	SILT /	SAND	/

7359022 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2020-01-14 DD/MM/YYYY

Elev (masl) Easting 595335 Northing 4841475

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 1.8 (mbgs) Bottom of Screen 4.9 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.2		GREY	OTHER /		/
0.9		BROWN	FILL /		/
3.0		BROWN	SILT /	SAND	/
4.9		GREY	SILT /	SAND	/

7359808 Lot Conc **BRAMPTON CITY / PEEL**

Date 2020-03-19 DD/MM/YYYY

Elev (masl) Easting 600008 Northing 4839626

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
			/		/

Well Record #

7363278 Lot Conc **BRAMPTON CITY / PEEL**

Date 2020-06-26 DD/MM/YYYY

Elev (masl) Easting 601283 Northing 4839128

/ Test Hole Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found 5.0 (mbgs) (masl) Untested

Casing Diameter 5.2 cm Casing Material: PLASTIC

Top of Screen 10.6 (mbgs) Bottom of Screen 13.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.1		BLACK	OTHER / SAND / GRAVEL
1.5		BROWN	GRAVEL / SILT / LOOSE
6.1		BROWN	SILT / CLAY / SAND
13.6		GREY	SHALE / HARD /

7366590 Lot Conc **BRAMPTON CITY / PEEL**

Date 2020-03-23 DD/MM/YYYY

Elev (masl) Easting 600442 Northing 4838943

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7369447 Lot Conc **BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2020-08-27 DD/MM/YYYY

Elev (masl) Easting 603150 Northing 4836787

/ Monitoring and Te Monitoring and Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found 3.0 (mbgs) (masl) FRESH

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing? N
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	SAND / STONES / LOOSE
6.1		GREY	SAND / SILT / LOOSE

7369738 Lot Conc **BRAMPTON CITY / PEEL**

Date 2020-08-21 DD/MM/YYYY

Elev (masl) Easting 600027 Northing 4839510

/ Monitoring and Te Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 6.1 (mbgs) Bottom of Screen 3.0 (mbgs)

Screen Interval -3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /
0.2		GREY	OTHER / /
0.3		BROWN	SAND / / LOOSE
1.5		BROWN	SAND / / LOOSE
3.0		BROWN	SAND / / SILT
4.6		RED	SHALE / / LOOSE
6.1		GREY	SAND / / WATER-BEARING

Well Record #

7369739 Lot Conc BRAMPTON CITY / PEEL

Date 2020-08-21 DD/MM/YYYY | Elev (masl) | Easting 600034 | Northing 4839522 | / Monitoring and Te | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC | Top of Screen 6.1 (mbgs) | Bottom of Screen 3.0 (mbgs) | Screen Interval -3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.2		GREY	OTHER /	/	
0.3		BROWN	SAND /	/	LOOSE
1.5		BROWN	SAND /	/	LOOSE
3.0		BROWN	SAND /	/	SILT
4.6		RED	SHALE /	/	LOOSE
6.1		GREY	SAND /	/	WATER-BEARING

7369740 Lot Conc BRAMPTON CITY / PEEL

Date 2020-08-21 DD/MM/YYYY | Elev (masl) | Easting 600046 | Northing 4839531 | / Monitoring and Te | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC | Top of Screen 6.1 (mbgs) | Bottom of Screen 3.0 (mbgs) | Screen Interval -3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.2		GREY	OTHER /	/	LOOSE
0.3		BROWN	SAND /	/	LOOSE
1.5		BROWN	SAND /	/	SILT
3.0		BROWN	SAND /	/	LOOSE
4.6		RED	SHALE /	/	LOOSE
6.1		GREY	SAND /	/	WATER-BEARING

7371869 Lot 003 Conc 01 BRAMPTON CITY / PEEL

Date 2020-10-30 DD/MM/YYYY | Elev (masl) | Easting 601942 | Northing 4837530 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 4.0 (mbgs) | Bottom of Screen 5.5 (mbgs) | Screen Interval 1.5 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions		
0.0						
1.5		BROWN	SILT /	CLAY	/	
3.0		BROWN	SILT /	CLAY	/	
4.6		GREY	CLAY /		/	SANDY

7378685 Lot 018 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 2021-01-13 DD/MM/YYYY | Elev (masl) | Easting 594104 | Northing 4842526 | / | Abandoned-Other | UTM RC 4 | margin of error : 30 m - 100 m | Water Found 1.5 (mbgs) (masl) Untested

Casing Diameter 5 cm | Casing Material: PLASTIC | Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs) | Screen Interval 3.1 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
			/		/

Well Record #

7378694 **Lot 018 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2021-01-13 DD/MM/YYYY | Elev (masl) | Easting 594018 | Northing 4842358 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 1.2 (mbgs) (masl) Untested | Casing Diameter 5 cm | Casing Material: PLASTIC | Top of Screen 6.1 (mbgs) | Bottom of Screen 9.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

7378695 **Lot 018 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2021-01-13 DD/MM/YYYY | Elev (masl) | Easting 594032 | Northing 4842329 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl) | Casing Diameter 5 cm | Casing Material: PLASTIC | Top of Screen 3.1 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

7378696 **Lot 018 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2021-01-13 DD/MM/YYYY | Elev (masl) | Easting 594179 | Northing 4842404 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 0.0 (mbgs) (masl) Untested | Casing Diameter 5 cm | Casing Material: PLASTIC | Top of Screen 3.1 (mbgs) | Bottom of Screen 6.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

7378698 **Lot 018 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2021-01-13 DD/MM/YYYY | Elev (masl) | Easting 593952 | Northing 4842662 | / | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found 0.1 (mbgs) (masl) Untested | Casing Diameter 5 cm | Casing Material: PLASTIC | Top of Screen 4.5 (mbgs) | Bottom of Screen 7.6 (mbgs) | Screen Interval 3.1 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions | / /

7378801 **Lot 008 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2020-11-24 DD/MM/YYYY | Elev (masl) | Easting 598443 | Northing 4838556 | / Monitoring | Observation Wells | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl) | Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 3.7 (mbgs) | Bottom of Screen 5.2 (mbgs) | Screen Interval 1.5 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m) Elev (masl) 0.0 | Color | Soil Descriptions

5.2 | GREY | CLAY / SILT / PACKED

Well Record #

7378802 — **Lot 008 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2020-11-24 (DD/MM/YYYY) | Elev (masl) | Easting 598370 | Northing 4838633 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.6		GREY	CLAY / SILT / PACKED

7378803 — **Lot 009 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2020-11-24 (DD/MM/YYYY) | Elev (masl) | Easting 598185 | Northing 4838619 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 4.6 (mbgs) | Bottom of Screen 7.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
6.1		GREY	CLAY / SILT / PACKED
7.6			ROCK / / HARD

7378840 — **Lot 001 Conc 02 BRAMPTON CITY / PEEL**

Date 2020-11-25 (DD/MM/YYYY) | Elev (masl) | Easting 602947 | Northing 4836738 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 4.3 (mbgs) | Bottom of Screen 7.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	FILL / / SOFT
3.0		BROWN	CLAY / / SOFT
7.3		GREY	CLAY / TILL / DENSE

7378841 — **Lot 001 Conc 02 BRAMPTON CITY / PEEL**

Date 2020-11-25 (DD/MM/YYYY) | Elev (masl) | Easting 602953 | Northing 4836742 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 4.9 (mbgs) | Bottom of Screen 7.9 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	FILL / / SOFT
3.0		BROWN	CLAY / / SOFT
7.9		GREY	CLAY / TILL / DENSE

7378843 — **Lot 001 Conc 02 BRAMPTON CITY / PEEL**

Date 2020-11-25 (DD/MM/YYYY) | Elev (masl) | Easting 602946 | Northing 4836744 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

1.5	BROWN	FILL /		/ SOFT
3.0	BROWN	CLAY /		/ SOFT
6.1	GREY	CLAY /	TILL	/ DENSE

7380294 **Lot 005 Conc 02 BRAMPTON CITY / PEEL**

Date 2021-01-13 (DD/MM/YYYY) | Elev (masl) | Easting 601097 | Northing 4838867 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 3.2 cm | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Color	Soil Descriptions		
0.0				
0.2	GREY	/		/
4.6	BROWN	SILT /	CLAY	/

7380295 **Lot 005 Conc 02 BRAMPTON CITY / PEEL**

Date 2021-01-13 (DD/MM/YYYY) | Elev (masl) | Easting 601078 | Northing 4838846 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 3.2 cm | Casing Material: PLASTIC

Top of Screen 2.2 (mbgs) | Bottom of Screen 5.3 (mbgs)

Screen Interval 3.1 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Color	Soil Descriptions		
0.0				
0.2	GREY	/		/
5.3	BROWN	SILT /	CLAY	/

7380753 **Lot 008 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-01-07 (DD/MM/YYYY) | Elev (masl) | Easting 598653 | Northing 4838285 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Color	Soil Descriptions		
0.0				
1.5	BROWN	FILL /		/ LOOSE
4.6	GREY	CLAY /	SILT	/ PACKED

7380773 **Lot 008 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-01-27 (DD/MM/YYYY) | Elev (masl) | Easting 598266 | Northing 4838565 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 6.1 (mbgs) | Bottom of Screen 9.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Color	Soil Descriptions		
0.0				
0.6	BLACK	/		/ HARD
3.0	BROWN	FILL /		/ LOOSE
7.6	GREY	SAND /	SILT	/ PACKED
9.1		SHALE /		/

Well Record #

7380774 — **Lot 008 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-01-27 (DD/MM/YYYY) | Elev (masl) | Easting 598470 | Northing 4838448 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BLACK	/ / HARD
3.0		BROWN	FILL / / LOOSE
4.6		GREY	SAND / SILT / PACKED

7380784 — **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2021-01-25 (DD/MM/YYYY) | Elev (masl) | Easting 592649 | Northing 4845122 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 4.6 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.6		GREY	CLAY / SILT / PACKED
6.1		GREY	SAND / / PACKED

7382113 — **Lot 006 Conc 02 BRAMPTON CITY / PEEL**

Date 2020-11-04 (DD/MM/YYYY) | Elev (masl) | Easting 600758 | Northing 4838924 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) | Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4		GREY	TILL / /
5.5		RED	SHALE / /

7382114 — **Lot 006 Conc 02 BRAMPTON CITY / PEEL**

Date 2020-11-04 (DD/MM/YYYY) | Elev (masl) | Easting 600731 | Northing 4838891 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) | Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.4		GREY	TILL / /
5.5		RED	SHALE / /

7382115 — **Lot 006 Conc 02 BRAMPTON CITY / PEEL**

Date 2020-11-04 (DD/MM/YYYY) | Elev (masl) | Easting 600724 | Northing 4838891 | UTM RC 4 | margin of error : 30 m - 100 m

/ Monitoring Observation Wells | Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 2.4 (mbgs) | Bottom of Screen 5.5 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

									2.4	GREY	TILL /	/	
									5.5	RED	SHALE /	/	
7382116	**Lot** 006	**Conc** 02			**BRAMPTON CITY / PEEL**						**Flowing?**		
Date 2020-11-04	**Elev**	(masl)	**Easting** 600751		**Northing** 4838951						**SWL**	(mbgs)	(masl)
DD/MM/YYYY	/ Monitoring		Observation Wells		**UTM RC** 4	margin of error : 30 m - 100 m					**Pumping WL**	(mbgs)	(masl)
	Water Found	(mbgs)	(masl)								**Pump Rate**	(LPM)	/
	Casing Diameter 2	inch	**Casing Material:** PLASTIC						**Depth (m)**	**Elev (masl)**	**Spec. Cap.**	(LPM/m)	Hour / Minute
	Top of Screen 2.7	(mbgs)	**Bottom of Screen** 5.8	(mbgs)					0.0	**Color**		**Soil Descriptions**	
	Screen Interval 3.0	(m)											
									2.7	GREY	TILL /	/	
									5.8	RED	SHALE /	/	
7389904	**Lot**	**Conc**			**BRAMPTON CITY / PEEL**						**Flowing?**		
Date 2021-04-16	**Elev**	(masl)	**Easting** 602923		**Northing** 4836828						**SWL**	(mbgs)	(masl)
DD/MM/YYYY	/				**UTM RC** 4	margin of error : 30 m - 100 m					**Pumping WL**	(mbgs)	(masl)
	Water Found	(mbgs)	(masl)								**Pump Rate**	(LPM)	/
	Casing Diameter		**Casing Material:**						**Depth (m)**	**Elev (masl)**	**Spec. Cap.**	(LPM/m)	Hour / Minute
	Top of Screen	(mbgs)	**Bottom of Screen**	(mbgs)					0.0	**Color**		**Soil Descriptions**	
	Screen Interval	(m)											
											/	/	
7390044	**Lot**	**Conc**			**BRAMPTON CITY (CHINGUACOUSY) / PEEL**						**Flowing?** N		
Date 2021-05-07	**Elev**	(masl)	**Easting** 595337		**Northing** 4841479						**SWL**	(mbgs)	(masl)
DD/MM/YYYY	/				**UTM RC** 4	margin of error : 30 m - 100 m					**Pumping WL**	(mbgs)	(masl)
	Water Found	(mbgs)	(masl)								**Pump Rate**	(LPM)	/
	Casing Diameter		**Casing Material:**						**Depth (m)**	**Elev (masl)**	**Spec. Cap.**	(LPM/m)	Hour / Minute
	Top of Screen	(mbgs)	**Bottom of Screen**	(mbgs)					0.0	**Color**		**Soil Descriptions**	
	Screen Interval	(m)											
											/	/	
7390047	**Lot** 015	**Conc** 01			**BRAMPTON CITY (CHINGUACOUSY) / PEEL**						**Flowing?** N		
Date 2021-05-07	**Elev**	(masl)	**Easting** 595587		**Northing** 4841372						**SWL**	(mbgs)	(masl)
DD/MM/YYYY	/				**UTM RC** 4	margin of error : 30 m - 100 m					**Pumping WL**	(mbgs)	(masl)
	Water Found	(mbgs)	(masl)								**Pump Rate**	(LPM)	/
	Casing Diameter		**Casing Material:**						**Depth (m)**	**Elev (masl)**	**Spec. Cap.**	(LPM/m)	Hour / Minute
	Top of Screen	(mbgs)	**Bottom of Screen**	(mbgs)					0.0	**Color**		**Soil Descriptions**	
	Screen Interval	(m)											
											/	/	
7390048	**Lot**	**Conc**			**BRAMPTON CITY (CHINGUACOUSY) / PEEL**						**Flowing?** N		
Date 2021-05-07	**Elev**	(masl)	**Easting** 595530		**Northing** 4841418						**SWL**	(mbgs)	(masl)
DD/MM/YYYY	/				**UTM RC** 4	margin of error : 30 m - 100 m					**Pumping WL**	(mbgs)	(masl)
	Water Found	(mbgs)	(masl)								**Pump Rate**	(LPM)	/
	Casing Diameter		**Casing Material:**						**Depth (m)**	**Elev (masl)**	**Spec. Cap.**	(LPM/m)	Hour / Minute
	Top of Screen	(mbgs)	**Bottom of Screen**	(mbgs)					0.0	**Color**		**Soil Descriptions**	
	Screen Interval	(m)											
											/	/	

Well Record #

7390050 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Flowing? N

Date 2021-05-07 DD/MM/YYYY

Elev (masl) Easting 595536 Northing 4841432 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) /

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					/

7390078 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Flowing? N

Date 2021-05-07 DD/MM/YYYY

Elev (masl) Easting 595524 Northing 4841424 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) /

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					/

7391256 Lot 005 Conc 02 BRAMPTON CITY / PEEL

Flowing? N

Date 2021-05-11 DD/MM/YYYY

Elev (masl) Easting 601401 Northing 4839281 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) / Monitoring and Te Observation Wells

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 7.6 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval -3.0 (m)

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					/
0.2		GREY	OTHER /		/
0.3		BROWN	SAND /	LOOSE	/ SAND
3.0		BROWN	SAND /	SILT	/ DENSE
7.0		GREY	CLAY /	DENSE	/ WATER-BEARING

7391257 Lot 005 Conc 02 BRAMPTON CITY / PEEL

Flowing? N

Date 2021-05-11 DD/MM/YYYY

Elev (masl) Easting 601427 Northing 4839309 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) / Monitoring and Te Observation Wells

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 6.9 (mbgs) Bottom of Screen 3.5 (mbgs)

Screen Interval -3.4 (m)

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					/
0.2		GREY	OTHER /		/
0.3		BROWN	SAND /	LOOSE	/ SAND
1.5		BROWN	SAND /	FILL	/ SAND
3.7		BROWN	SAND /	CLAY	/ DENSE
6.9		GREY	SHALE /	DENSE	/ SHALE

Well Record #

7391258 **Lot 005 Conc 02** **BRAMPTON CITY / PEEL**

Date 2021-05-11 DD/MM/YYYY | Elev (masl) | Easting 601466 | Northing 4839355 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC

Top of Screen 7.6 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval -3.0 (m)

Flowing? N

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.2		GREY	OTHER /		/
0.3		BROWN	SAND /	LOOSE	/ SAND
1.5		BROWN	SAND /	SAND	/ SILT
3.0		BROWN	SAND /	DENSE	/ CLAY
7.6		GREY	SHALE /	DENSE	/ SILT

7391259 **Lot 005 Conc 02** **BRAMPTON CITY / PEEL**

Date 2021-05-12 DD/MM/YYYY | Elev (masl) | Easting 601429 | Northing 4839380 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC

Top of Screen 7.6 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval -3.0 (m)

Flowing? N

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.2		GREY	OTHER /		/
0.3		BROWN	SAND /	LOOSE	/ SAND
1.5		BROWN	SAND /	SILT	/ FILL
3.0		BROWN	SAND /	DENSE	/ CLAY
7.6		GREY	SHALE /	DENSE	/ SHALE

7391260 **Lot 005 Conc 02** **BRAMPTON CITY / PEEL**

Date 2021-05-12 DD/MM/YYYY | Elev (masl) | Easting 601374 | Northing 4839298 | / Monitoring and Te Observation Wells | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC

Top of Screen 7.6 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval -3.0 (m)

Flowing? N

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.1		GREY	OTHER /		/
0.3		BROWN	SAND /	LOOSE	/ SAND
3.0		BROWN	SAND /	DENSE	/ SAND
7.6		BROWN	SAND /	DENSE	/ WATER-BEARING

7395331 **Lot Conc** **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-08-04 DD/MM/YYYY | Elev (masl) | Easting 595537 | Northing 4841451 | / Test Hole Test Hole | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) Untested

Casing Diameter 2 Inch | Casing Material: PLASTIC

Top of Screen 8.5 (mbgs) | Bottom of Screen 11.6 (mbgs)

Screen Interval 3.0 (m)

Flowing? N

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
1.5		BROWN	SAND /	GRAVEL	/ FILL
5.2		BROWN	SILT /	TILL	/ SAND
6.1		BROWN	SILT /	TILL	/ CLAY
11.6		GREY	LIMESTONE /	SHALE	/

Well Record #

7396621 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-07-27 DD/MM/YYYY | Elev (masl) | Easting 596912 | Northing 4839467 | / Monitoring and Te | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch | Casing Material: PLASTIC

Top of Screen 2.7 (mbgs) | Bottom of Screen 5.8 (mbgs)

Screen Interval 3.0 (m)

Flowing? N
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.3		BLACK	OTHER /		/ HARD
2.1		BROWN	CLAY /	ROCK	/ HARD
5.8		RED	SHALE /		/ HARD

7401794 Lot 007 Conc 01 **BRAMPTON CITY / PEEL**

Date 2021-10-18 DD/MM/YYYY | Elev (masl) | Easting 600022 | Northing 4839515 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 4.7 (mbgs) (masl) Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
2.1		BROWN	SAND /	GRAVEL	/ FILL
4.5		BROWN	SILT /	CLAYEY	/ HARD
6.0		GREY	SAND /	GRAVELLY	/ DIRTY

7401796 Lot 007 Conc 01 **BRAMPTON CITY / PEEL**

Date 2021-10-18 DD/MM/YYYY | Elev (masl) | Easting 600031 | Northing 4839513 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 4.7 (mbgs) (masl) Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
0.6		BROWN	SAND /	GRAVEL	/ FILL
4.5		BROWN	SILT /	CLAYEY	/ HARD
6.0		GREY	SAND /	GRAVELLY	/ DENSE

7401799 Lot 007 Conc 01 **BRAMPTON CITY / PEEL**

Date 2021-10-18 DD/MM/YYYY | Elev (masl) | Easting 600011 | Northing 4839530 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 4.7 (mbgs) (masl) Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
2.4		BROWN	SAND /	GRAVEL	/ FILL
4.5		BROWN	SILT /	CLAYEY	/ HARD
6.0		GREY	SAND /	GRAVELLY	/ DENSE

Well Record #

7405164 **Lot 015 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-11-15 DD/MM/YYYY

Elev / (masl) Easting 595552 Northing 4841382
Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m
Water Found 1.5 (mbgs) (masl) Untested

Casing Diameter 5 cm Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 4.6 (mbgs)
Screen Interval 1.5 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7405165 **Lot 015 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-11-15 DD/MM/YYYY

Elev / (masl) Easting 595540 Northing 4841462
Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m
Water Found 1.7 (mbgs) (masl) Untested

Casing Diameter 5 cm Casing Material: PLASTIC
Top of Screen 8.5 (mbgs) Bottom of Screen 11.6 (mbgs)
Screen Interval 3.1 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7405166 **Lot 015 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-11-15 DD/MM/YYYY

Elev / (masl) Easting 595498 Northing 4841418
Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m
Water Found 1.5 (mbgs) (masl) Untested

Casing Diameter 5 cm Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7405167 **Lot 015 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-11-15 DD/MM/YYYY

Elev / (masl) Easting 595539 Northing 4841398
Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m
Water Found 1.5 (mbgs) (masl) Untested

Casing Diameter 5 cm Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7405881 **Lot Conc BRAMPTON CITY / PEEL**

Date 2021-10-13 DD/MM/YYYY

Elev / (masl) Easting 602466 Northing 4837166
Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing? N
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7405882 Lot Conc BRAMPTON CITY / PEEL

Date 2021-10-13 DD/MM/YYYY

Elev (masl) Easting 602506 Northing 4837130

/ Monitoring Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing? N

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7405883 Lot Conc BRAMPTON CITY / PEEL

Date 2021-10-13 DD/MM/YYYY

Elev (masl) Easting 602580 Northing 4837079

/ Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing? N

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7405884 Lot Conc BRAMPTON CITY / PEEL

Date 2021-10-13 DD/MM/YYYY

Elev (masl) Easting 602659 Northing 4837135

/ Monitoring Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 Inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing? N

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7406221 Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 2021-11-12 DD/MM/YYYY

Elev (masl) Easting 592533 Northing 4845341

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 4.9 (mbgs) (masl) Untested

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 2.7 (mbgs) Bottom of Screen 5.8 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
4.9		BROWN	SAND / / DRY
5.8		GREY	SAND / SILTY /

7406244 Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL

Date 2021-11-12 DD/MM/YYYY

Elev (masl) Easting 592561 Northing 4845366

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 5.2 (mbgs) (masl) Untested

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
5.2		BROWN	SAND / / DRY
6.1		GREY	SAND / SILTY /

Well Record #

7407100 **Lot 015 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2021-07-16 DD/MM/YYYY

Elev (masl) Easting 595501 Northing 4841412 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7408568 **Lot 005 Conc 02 BRAMPTON CITY / PEEL**

Date 2021-11-26 DD/MM/YYYY

Elev (masl) Easting 601187 Northing 4838786 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 7.2 (mbgs) Bottom of Screen 10.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
5.5		GREY	CLAY / FILL / PACKED
10.2		GREY	SHALE / / HARD

7408615 **Lot 018 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2021-12-02 DD/MM/YYYY

Elev (masl) Easting 594114 Northing 4842531 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 4.6 (mbgs) Bottom of Screen 7.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
7.6		GREY	CLAY / SILT / PACKED

7412996 **Lot Conc BRAMPTON CITY / PEEL**

Date 2021-10-18 DD/MM/YYYY

Elev (masl) Easting 601025 Northing 4839054 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7413528 **Lot 006 Conc 02 BRAMPTON CITY / PEEL**

Date 2022-02-17 DD/MM/YYYY

Elev (masl) Easting 600756 Northing 4838922 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 2.1 (mbgs) Bottom of Screen 5.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	SAND / GRAVEL /
3.7		GREY	TILL / /
5.2		RED	SHALE / /

Well Record #

7413637 — **Lot 023 Conc 02 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2021-09-28 (DD/MM/YYYY) — Elev (masl) — Easting 591525 — Northing 4844135 — UTM RC 4 — margin of error : 30 m - 100 m

/ Monitoring Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch — Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) — Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	GRAVEL / /
4.6		BLUE	CLAY / /

7416694 — **Lot Conc BRAMPTON CITY / PEEL**

Date 2022-03-07 (DD/MM/YYYY) — Elev (masl) — Easting 601156 — Northing 4839177 — UTM RC 4 — margin of error : 30 m - 100 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) — Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7416695 — **Lot Conc BRAMPTON CITY / PEEL**

Date 2022-03-07 (DD/MM/YYYY) — Elev (masl) — Easting 601133 — Northing 4839152 — UTM RC 4 — margin of error : 30 m - 100 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) — Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7416696 — **Lot Conc BRAMPTON CITY / PEEL**

Date 2022-03-07 (DD/MM/YYYY) — Elev (masl) — Easting 601135 — Northing 4839209 — UTM RC 4 — margin of error : 30 m - 100 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) — Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7418865 — **Lot 006 Conc 01 BRAMPTON CITY / PEEL**

Date 2022-05-04 (DD/MM/YYYY) — Elev (masl) — Easting 600704 — Northing 4838781 — UTM RC 4 — margin of error : 30 m - 100 m

/ Monitoring Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch — Casing Material: PLASTIC

Top of Screen 12.2 (mbgs) — Bottom of Screen 15.2 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		SAND /	GRAVEL / FILL
4.6		TILL /	/ HARD
6.1		SHALE /	/
15.2		ROCK /	/

Well Record #

7419353 Lot Conc **BRAMPTON CITY / PEEL**

Date 2022-05-17 DD/MM/YYYY

Elev (masl) Easting 601080 Northing 4838990 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7422761 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2022-05-02 DD/MM/YYYY

Elev (masl) Easting 597314 Northing 4839435 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7422764 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2022-05-02 DD/MM/YYYY

Elev (masl) Easting 597147 Northing 4839580 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7422765 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2022-05-02 DD/MM/YYYY

Elev (masl) Easting 597396 Northing 4839585 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7422766 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2022-05-02 DD/MM/YYYY

Elev (masl) Easting 597244 Northing 4839570 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7422767 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2022-05-02 DD/MM/YYYY | Elev / (masl) | Easting 597244 | Northing 4839571 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7422768 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2022-05-02 DD/MM/YYYY | Elev / (masl) | Easting 597277 | Northing 4839692 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7423303 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2022-06-03 DD/MM/YYYY | Elev / (masl) | Easting 596135 | Northing 4840518 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7423304 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2022-06-03 DD/MM/YYYY | Elev / (masl) | Easting 596093 | Northing 4840552 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7423305 Lot Conc BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2022-06-03 DD/MM/YYYY | Elev / (masl) | Easting 596204 | Northing 4840450 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7427804 Lot Conc **BRAMPTON CITY / PEEL**

Date 2022-06-24 DD/MM/YYYY

Elev (masl) Easting 602583 Northing 4837340 UTM RC 4 margin of error : 30 m - 100 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7429116 Lot Conc **BRAMPTON CITY / PEEL**

Date DD/MM/YYYY

Elev (masl) Easting 599382 Northing 4838447 UTM RC 5 margin of error : 100 m - 300 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7429411 Lot 013 Conc 01 **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2022-08-19 DD/MM/YYYY

Elev (masl) Easting 596242 Northing 4840697 UTM RC 4 margin of error : 30 m - 100 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7429412 Lot 013 Conc 01 **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2022-08-19 DD/MM/YYYY

Elev (masl) Easting 596287 Northing 4840662 UTM RC 4 margin of error : 30 m - 100 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7429875 Lot Conc **BRAMPTON CITY / PEEL**

Date DD/MM/YYYY

Elev (masl) Easting 599374 Northing 4838382 UTM RC 4 margin of error : 30 m - 100 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7432482 Lot Conc **BRAMPTON CITY / PEEL**

Date 2022-03-31 DD/MM/YYYY | Elev (masl) | Easting 601401 | Northing 4839539 | UTM RC 4 margin of error : 30 m - 100 m | / | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7435628 Lot 005 Conc 02 **BRAMPTON CITY / PEEL**

Date 2022-11-03 DD/MM/YYYY | Elev (masl) | Easting 601104 | Northing 4839217 | UTM RC 4 margin of error : 30 m - 100 m | / Monitoring Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 2 inch Casing Material: PLASTIC | Top of Screen 6.1 (mbgs) Bottom of Screen 9.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	FILL / / LOOSE
9.1		GREY	CLAY / TILL / PACKED

7435629 Lot 005 Conc 02 **BRAMPTON CITY / PEEL**

Date 2022-11-03 DD/MM/YYYY | Elev (masl) | Easting 601089 | Northing 4839179 | UTM RC 4 margin of error : 30 m - 100 m | / Monitoring Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 2 inch Casing Material: PLASTIC | Top of Screen 6.1 (mbgs) Bottom of Screen 9.1 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	FILL / / LOOSE
9.1		GREY	CLAY / TILL / PACKED

7435630 Lot 005 Conc 02 **BRAMPTON CITY / PEEL**

Date 2022-11-03 DD/MM/YYYY | Elev (masl) | Easting 601156 | Northing 4839178 | UTM RC 4 margin of error : 30 m - 100 m | / Monitoring Observation Wells | Water Found (mbgs) (masl) | Casing Diameter 2 inch Casing Material: PLASTIC | Top of Screen 4.6 (mbgs) Bottom of Screen 7.6 (mbgs) | Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
3.0		BROWN	FILL / / LOOSE
7.6		GREY	CLAY / TILL / PACKED

7435765 Lot 023 Conc 01 **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2022-11-22 DD/MM/YYYY | Elev (masl) | Easting 592558 | Northing 4845363 | UTM RC 4 margin of error : 30 m - 100 m | / Abandoned-Other | Water Found 3.6 (mbgs) (masl) Untested | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

7435766 — **Lot 023 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2022-11-22 (DD/MM/YYYY)
Elev (masl) Easting 592542 Northing 4845338
/ Abandoned-Other UTM RC 4 margin of error : 30 m - 100 m
Water Found 3.5 (mbgs) (masl) Untested
Casing Diameter Casing Material:
Top of Screen (mbgs) Bottom of Screen (mbgs)
Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				/ /

7439638 — **Lot 014 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-01-20 (DD/MM/YYYY)
Elev (masl) Easting 595819 Northing 4841198
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found 5.2 (mbgs) (masl) Untested
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				
2.3			/	/ FILL
3.0		BROWN	CLAY /	/ FILL
6.1		GREY	CLAY /	/ TILL

7439639 — **Lot 001 Conc 01 BRAMPTON CITY / PEEL**

Date 2022-12-13 (DD/MM/YYYY)
Elev (masl) Easting 602558 Northing 4836824
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 4.6 (mbgs)
Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				
1.5		BROWN	FILL /	/ LOOSE
4.6		GREY	TILL / SILT	/ PACKED

7440539 — **Lot 005 Conc 02 BRAMPTON CITY / PEEL**

Date 2023-02-07 (DD/MM/YYYY)
Elev (masl) Easting 601562 Northing 4839434
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				
2.4		BROWN	/	/ FILL
6.1		GREY	/	/ SILT

7440540 — **Lot 005 Conc 02 BRAMPTON CITY / PEEL**

Date 2023-02-07 (DD/MM/YYYY)
Elev (masl) Easting 601544 Northing 4839496
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions
0.0				
3.0		BROWN	/	/ FILL

Well Record #

						6.1	GREY	/		/	SILT

7440544 — Lot 005 Conc 02 — BRAMPTON CITY / PEEL

Date 2023-02-07 (DD/MM/YYYY) | Elev (masl) | Easting 601481 | Northing 4839405 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
2.1		BROWN	/		/ FILL
6.1		GREY	/	SILT	/

7440545 — Lot 005 Conc 02 — BRAMPTON CITY / PEEL

Date 2023-02-07 (DD/MM/YYYY) | Elev (masl) | Easting 601539 | Northing 4839430 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
2.7		BROWN	FILL /		/
6.1		GREY	/		/ SILT

7441335 — Lot 005 Conc 02 — BRAMPTON CITY / PEEL

Date 2023-02-08 (DD/MM/YYYY) | Elev (masl) | Easting 601584 | Northing 4839529 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 3.0 (mbgs) (masl) | Untested

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
1.5		BROWN	/	TILL	/ HARD
4.6		GREY	/	TILL	/ DENSE

7441337 — Lot 005 Conc 02 — BRAMPTON CITY / PEEL

Date 2023-02-06 (DD/MM/YYYY) | Elev (masl) | Easting 601518 | Northing 4839360 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
3.0		BROWN	/		/ FILL
6.1		GREY	/		/ CLAY

7441339 — Lot 005 Conc 02 — BRAMPTON CITY / PEEL

Date 2023-02-08 (DD/MM/YYYY) | Elev (masl) | Easting 601525 | Northing 4839394 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 4.6 (mbgs) (masl) | Untested

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					

Well Record #

			3.0	BROWN	/	TILL	/ HARD
			6.1	GREY	/	DENSE	/ TILL

7441340 **Lot 005 Conc 02 BRAMPTON CITY / PEEL**

Date 2023-02-06 DD/MM/YYYY

Elev (masl) Easting 601532 Northing 4839368 UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
3.0		BROWN	/		/ FILL
6.1		GREY	/		/ CLAY

7443533 **Lot 007 Conc 01 BRAMPTON CITY / PEEL**

Date 2023-03-16 DD/MM/YYYY

Elev (masl) Easting 599450 Northing 4838886 UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 2.3 (mbgs) Bottom of Screen 3.8 (mbgs)

Screen Interval 1.5 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
1.2		BLACK	/		/
3.8		BROWN	FILL /		/

7443655 **Lot 014 Conc 02 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2023-03-31 DD/MM/YYYY

Elev (masl) Easting 603523 Northing 4836161 UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 19.8 (mbgs) Bottom of Screen 22.9 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
3.0		BROWN	FILL /		/ LOOSE
6.1		GREY	CLAY /	SILT	/ PACKED
22.9		GREY	SHALE /		/ HARD

7443656 **Lot 014 Conc 02 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2023-03-31 DD/MM/YYYY

Elev (masl) Easting 603524 Northing 4836160 UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 4.9 (mbgs) Bottom of Screen 7.9 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color		Soil Descriptions	
0.0					
3.0		BROWN	FILL /		/ LOOSE
6.1		GREY	CLAY /	SILT	/ PACKED
7.9		GREY	SHALE /		/ HARD

Well Record #

7443713 — **Lot 007 Conc 01 BRAMPTON CITY / PEEL**

Date 2023-04-03 (DD/MM/YYYY) | Elev (masl) | Easting 599188 | Northing 4838522 | UTM RC 4 | margin of error : 30 m - 100 m
/ Monitoring Observation Wells
Water Found (mbgs) (masl)
Casing Diameter 2 inch | Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)
Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	FILL / / LOOSE
4.6		GREY	CLAY / SILT / PACKED

7443714 — **Lot 007 Conc 01 BRAMPTON CITY / PEEL**

Date 2023-04-03 (DD/MM/YYYY) | Elev (masl) | Easting 599287 | Northing 4838647 | UTM RC 4 | margin of error : 30 m - 100 m
/ Monitoring Observation Wells
Water Found (mbgs) (masl)
Casing Diameter 2 inch | Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)
Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	FILL / / LOOSE
4.6		GREY	CLAY / SILT / PACKED

7443861 — **Lot 015 Conc 02 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2023-01-12 (DD/MM/YYYY) | Elev (masl) | Easting 603438 | Northing 4836564 | UTM RC 4 | margin of error : 30 m - 100 m
/
Water Found (mbgs) (masl)
Casing Diameter | Casing Material:
Top of Screen (mbgs) | Bottom of Screen (mbgs)
Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7443862 — **Lot 015 Conc 02 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2023-01-11 (DD/MM/YYYY) | Elev (masl) | Easting 603414 | Northing 4836554 | UTM RC 4 | margin of error : 30 m - 100 m
/
Water Found (mbgs) (masl)
Casing Diameter | Casing Material:
Top of Screen (mbgs) | Bottom of Screen (mbgs)
Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7443863 — **Lot 015 Conc 02 BRAMPTON CITY (TORONTO TWP) / PEEL**

Date 2023-01-12 (DD/MM/YYYY) | Elev (masl) | Easting 603470 | Northing 4836523 | UTM RC 4 | margin of error : 30 m - 100 m
/
Water Found (mbgs) (masl)
Casing Diameter | Casing Material:
Top of Screen (mbgs) | Bottom of Screen (mbgs)
Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

7444230 Lot Conc **BRAMPTON CITY / PEEL**

Date 2022-05-10 DD/MM/YYYY

Elev (masl) Easting 601095 Northing 4838441

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)

0.0

Color Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

7445276 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-02-17 DD/MM/YYYY

Elev (masl) Easting 600782 Northing 4839012

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)

0.0

Color Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

7445277 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-02-16 DD/MM/YYYY

Elev (masl) Easting 600819 Northing 4839045

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)

0.0

Color Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

7445278 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-02-16 DD/MM/YYYY

Elev (masl) Easting 600806 Northing 4839052

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)

0.0

Color Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

7445934 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-02-02 DD/MM/YYYY

Elev (masl) Easting 596929 Northing 4839455

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)

0.0

Color Soil Descriptions

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7447520 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-02-16 (DD/MM/YYYY) | Elev (masl) | Easting 597012 | Northing 4839574 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 4.5 (mbgs) (masl) | Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 3.8 (mbgs) | Bottom of Screen 6.8 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.2		BROWN	SAND / GRAVEL / PACKED
3.0		BROWN	CLAY / TILL / DENSE
6.8		RED	SHALE / / LAYERED

7447521 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-02-10 (DD/MM/YYYY) | Elev (masl) | Easting 596987 | Northing 4839407 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 2.1 (mbgs) (masl) | Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 3.6 (mbgs) | Bottom of Screen 6.0 (mbgs)

Screen Interval 2.4 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.0		BROWN	SAND / GRAVEL / FILL
2.4		BROWN	SILT / CLAY / DENSE
6.0		BROWN	SHALE / / LAYERED

7447522 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-02-22 (DD/MM/YYYY) | Elev (masl) | Easting 597031 | Northing 4839472 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 8.0 (mbgs) (masl) | Untested

Casing Diameter 2 cm | Casing Material: PLASTIC

Top of Screen 8.0 (mbgs) | Bottom of Screen 18.0 (mbgs)

Screen Interval 10.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
5.0		BROWN	FILL / SAND / PACKED
7.0		GREY	TILL / / HARD
18.0		RED	SHALE / /

7447524 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-02-14 (DD/MM/YYYY) | Elev (masl) | Easting 596896 | Northing 4839498 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 3.3 (mbgs) (masl) | Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.0 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	SAND / GRAVEL / PACKED
3.3		BROWN	CLAY / SILT / DENSE
6.0		RED	SHALE / / LAYERED

Well Record #

7447531 **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-02-14 DD/MM/YYYY
Elev (masl) Easting 597024 Northing 4839491
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found 1.9 (mbgs) (masl) Untested
Casing Diameter 5.1 cm Casing Material: PLASTIC
Top of Screen 0.9 (mbgs) Bottom of Screen 2.1 (mbgs)
Screen Interval 1.2 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	SAND / GRAVEL / PACKED
2.1		BROWN	CLAY / TILL / DENSE

7447532 **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-02-13 DD/MM/YYYY
Elev (masl) Easting 596934 Northing 4839508
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found 2.1 (mbgs) (masl) Untested
Casing Diameter 5.1 cm Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.0 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.0		BROWN	SAND / GRAVEL / PACKED
2.4		BROWN	CLAY / TILL / DENSE
6.0		BROWN	SHALE / / LAYERED

7447534 **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-01-18 DD/MM/YYYY
Elev (masl) Easting 596755 Northing 4839629
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found 2.4 (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.2		BROWN	FILL / GRAVEL / PACKED
2.4		BROWN	TILL / SILT / HARD
6.1		RED	SHALE / / HARD

7447535 **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-01-23 DD/MM/YYYY
Elev (masl) Easting 596882 Northing 4839721
/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m
Water Found (mbgs) (masl)
Casing Diameter 2 inch Casing Material: PLASTIC
Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)
Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.2		BROWN	FILL / GRAVEL / PACKED
2.7		BROWN	TILL / SILT / HARD
6.1		RED	SHALE / / HARD

Well Record #

7447538 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-02-15 (DD/MM/YYYY) | Elev (masl) | Easting 596963 | Northing 4839568 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 3.6 (mbgs) (masl) | Untested

Casing Diameter 5.1 cm | Casing Material: PLASTIC

Top of Screen 3.8 (mbgs) | Bottom of Screen 6.8 (mbgs)

Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.8		BROWN	SAND / GRAVEL / PACKED
3.0		BROWN	CLAY / TILL / DENSE
6.8		RED	SAND / / LAYERED

7447539 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-02-21 (DD/MM/YYYY) | Elev (masl) | Easting 596961 | Northing 4839497 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 7.0 (mbgs) (masl) | Untested

Casing Diameter 2 cm | Casing Material: PLASTIC

Top of Screen 12.0 (mbgs) | Bottom of Screen 20.0 (mbgs)

Screen Interval 8.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
5.0		BROWN	FILL / SAND / GRAVEL
7.5		BROWN	TILL / /
20.0		RED	SHALE / /

7447540 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-01-19 (DD/MM/YYYY) | Elev (masl) | Easting 596870 | Northing 4839496 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found 2.4 (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.9			FILL / GRAVEL / PACKED
2.4			TILL / SILT / HARD
6.1		RED	SHALE / / HARD

7447544 — **Lot 011 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-01-23 (DD/MM/YYYY) | Elev (masl) | Easting 597030 | Northing 4839638 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing? | SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.2		BROWN	FILL / GRAVEL / PACKED
2.4		BROWN	TILL / SILT / HARD
6.1		RED	SHALE / / HARD

Well Record #

7447821 **Lot 005 Conc 02** **BRAMPTON CITY / PEEL**

Date 2023-05-02 DD/MM/YYYY

Elev (masl) Easting 601308 Northing 4839314

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 15.2 (mbgs) Bottom of Screen 18.3 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	FILL / / LOOSE
6.7		GREY	CLAY / / PACKED
9.1		BROWN	SAND / / PACKED
18.3		GREY	SHALE / / HARD

7447822 **Lot 005 Conc 02** **BRAMPTON CITY / PEEL**

Date 2023-05-02 DD/MM/YYYY

Elev (masl) Easting 601423 Northing 4839405

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 5.8 (mbgs) Bottom of Screen 8.8 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	FILL / / LOOSE
6.7		GREY	CLAY / / PACKED
8.8		BROWN	SAND / / PACKED

7447823 **Lot 005 Conc 02** **BRAMPTON CITY / PEEL**

Date 2023-05-02 DD/MM/YYYY

Elev (masl) Easting 601316 Northing 4839417

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	CLAY / / LOOSE
6.1		BROWN	SAND / / PACKED

7449931 **Lot Conc** **BRAMPTON CITY / PEEL**

Date 2023-04-19 DD/MM/YYYY

Elev (masl) Easting 601276 Northing 4839392

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

7449932 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-04-19 DD/MM/YYYY | Elev (masl) | Easting 601128 | Northing 4839409 | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Color Soil Descriptions

/ /

7449999 Lot Conc **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-03-30 DD/MM/YYYY | Elev (masl) | Easting 596225 | Northing 4840103 | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Color Soil Descriptions

/ /

7452394 Lot 007 Conc 01 **BRAMPTON CITY / PEEL**

Date 2023-07-04 DD/MM/YYYY | Elev (masl) | Easting 599185 | Northing 4838512 | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Color Soil Descriptions

/ /

7452395 Lot 007 Conc 01 **BRAMPTON CITY / PEEL**

Date 2023-07-04 DD/MM/YYYY | Elev (masl) | Easting 599278 | Northing 4838634 | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Color Soil Descriptions

/ /

7452396 Lot 007 Conc 01 **BRAMPTON CITY / PEEL**

Date 2023-07-04 DD/MM/YYYY | Elev (masl) | Easting 599448 | Northing 4838881 | Abandoned-Other | UTM RC 4 margin of error : 30 m - 100 m | Water Found (mbgs) (masl) | Casing Diameter Casing Material: | Top of Screen (mbgs) Bottom of Screen (mbgs) | Screen Interval (m)

Depth (m) Elev (masl) 0.0

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Color Soil Descriptions

/ /

Well Record #

7454698 Lot Conc BRAMPTON CITY / PEEL

Date 2023-04-04 DD/MM/YYYY

Elev (masl) Easting 596857 Northing 4839496 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7454699 Lot Conc BRAMPTON CITY / PEEL

Date 2023-03-31 DD/MM/YYYY

Elev (masl) Easting 596801 Northing 4839574 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7459157 Lot 005 Conc 01 BRAMPTON CITY / PEEL

Date 2023-09-18 DD/MM/YYYY

Elev (masl) Easting 600874 Northing 4838539 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 1.5 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6			FILL / /
4.6		BROWN	CLAY / /

7459158 Lot 004 Conc 01 BRAMPTON CITY / PEEL

Date 2023-09-20 DD/MM/YYYY

Elev (masl) Easting 601484 Northing 4838105 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found 4.9 (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 2.7 (mbgs) Bottom of Screen 5.8 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
5.8			SAND / GRAVEL /

7459159 Lot 003 Conc 01 BRAMPTON CITY / PEEL

Date 2023-09-20 DD/MM/YYYY

Elev (masl) Easting 601655 Northing 4837938 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 6.1 (mbgs)

Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6			FILL / /
3.0		BROWN	CLAY / /
6.1		GREY	CLAY / /

Well Record #

7459160 Lot 004 Conc 01 **BRAMPTON CITY / PEEL**

Date 2023-09-21 DD/MM/YYYY | Elev (masl) | Easting 601216 | Northing 4838366 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 2.1 (mbgs) | Bottom of Screen 4.6 (mbgs) | Screen Interval 2.4 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
3.0		BROWN	SAND /		/
4.6			ROCK /		/

7459193 Lot 003 Conc 01 **BRAMPTON CITY / PEEL**

Date 2023-09-20 DD/MM/YYYY | Elev (masl) | Easting 602056 | Northing 4837539 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs) | Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.6			FILL /		/
4.6		BROWN	CLAY /		/

7459194 Lot 002 Conc 01 **BRAMPTON CITY / PEEL**

Date 2023-09-20 DD/MM/YYYY | Elev (masl) | Easting 602110 | Northing 4837475 | / Monitoring | Observation Wells | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 1.5 (mbgs) | Bottom of Screen 4.6 (mbgs) | Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
0.6			FILL /		/
4.6		BROWN	CLAY /		/

7466680 Lot 019 Conc 01 **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2023-11-28 DD/MM/YYYY | Elev (masl) | Easting 593311 | Northing 4842757 | / Monitoring | Abandoned-Supply | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 4.6 (mbgs) | Bottom of Screen 7.6 (mbgs) | Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
				/	/
				/	/

7466681 Lot 019 Conc 01 **CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2023-11-28 DD/MM/YYYY | Elev (masl) | Easting 593417 | Northing 4842876 | / Monitoring | Abandoned-Supply | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 4.6 (mbgs) | Bottom of Screen 7.6 (mbgs) | Screen Interval 3.0 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions		
0.0					
				/	/

Well Record #

7467757 Lot 013 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL

Date 2023-10-25 DD/MM/YYYY

Elev (masl) Easting 596110 Northing 4840774 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? / /

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

7468148 Lot 007 Conc 01 BRAMPTON CITY / PEEL

Date 2024-01-08 DD/MM/YYYY

Elev (masl) Easting 599606 Northing 4839010 / Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 1.5 (m)

Flowing? / /

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	CLAY / SAND /
3.0		BROWN	CLAY / SAND /
4.6		BROWN	CLAY / SAND /

7468367 Lot 004 Conc 02 BRAMPTON CITY / PEEL

Date 2023-10-19 DD/MM/YYYY

Elev (masl) Easting 601262 Northing 4838446 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? / /

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

7468368 Lot Conc BRAMPTON CITY / PEEL

Date 2023-10-19 DD/MM/YYYY

Elev (masl) Easting 601239 Northing 4838416 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? / /

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

7468369 Lot Conc BRAMPTON CITY / PEEL

Date 2023-10-19 DD/MM/YYYY

Elev (masl) Easting 601276 Northing 4838449 / UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing? / /

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

7468370 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-10-15 DD/MM/YYYY

Elev (masl) Easting 601287 Northing 4838465 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7468371 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-10-18 DD/MM/YYYY

Elev (masl) Easting 601260 Northing 4838493 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7468372 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-10-15 DD/MM/YYYY

Elev (masl) Easting 601213 Northing 4838436 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7468373 Lot Conc **BRAMPTON CITY / PEEL**

Date 2023-10-24 DD/MM/YYYY

Elev (masl) Easting 601251 Northing 4838423 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7468660 Lot 015 Conc 01 **BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-10-27 DD/MM/YYYY

Elev (masl) Easting 595219 Northing 4841496 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

Well Record #

7468668 **Lot 015 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-10-27 DD/MM/YYYY

Elev (masl) Easting 595230 Northing 4841486 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7468669 **Lot 015 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-10-27 DD/MM/YYYY

Elev (masl) Easting 595225 Northing 4841486 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7468670 **Lot 015 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2023-10-27 DD/MM/YYYY

Elev (masl) Easting 595217 Northing 4841489 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7469058 **Lot 008 Conc 01 BRAMPTON CITY (CHINGUACOUSY) / PEEL**

Date 2024-01-22 DD/MM/YYYY

Elev (masl) Easting 599447 Northing 4839246 UTM RC 4 margin of error : 30 m - 100 m

/ Monitoring Observation Wells

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 4.6 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	CLAY / GRAVEL /
3.0		BROWN	CLAY / GRAVEL / HARD
4.6		BROWN	CLAY / SAND /

7470732 **Lot 021 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2023-10-19 DD/MM/YYYY

Elev (masl) Easting 592408 Northing 4843302 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

Well Record #

7470733 **Lot 022 Conc 01 CALEDON TOWN (CHINGUACOUSY) / PEEL**

Date 2023-10-16 DD/MM/YYYY

Elev (masl) Easting 591931 Northing 4844129

/ UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

7471142 **Lot 007 Conc 01 BRAMPTON CITY / PEEL**

Date 2024-01-18 DD/MM/YYYY

Elev (masl) Easting 599561 Northing 4839062

/ Monitoring Observation Wells UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 4.6 (mbgs) Bottom of Screen 7.6 (mbgs)

Screen Interval 3.0 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.1		BROWN	FILL / / LOOSE
7.6		GREY	CLAY / TILL / PACKED

7473176 **Lot Conc BRAMPTON CITY / PEEL**

Date 2024-03-06 DD/MM/YYYY

Elev (masl) Easting 601136 Northing 4839382

/ Monitoring Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 3.7 (mbgs)

Screen Interval 0.6 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SILT / SAND /
3.7		BROWN	SAND / /

7473193 **Lot 006 Conc 02 BRAMPTON CITY / PEEL**

Date 2024-03-06 DD/MM/YYYY

Elev (masl) Easting 601116 Northing 4839355

/ Monitoring Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 3.7 (mbgs)

Screen Interval 0.6 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SILT / SAND /
3.7		BROWN	SAND / /

7473194 **Lot 006 Conc 02 BRAMPTON CITY / PEEL**

Date 2024-03-06 DD/MM/YYYY

Elev (masl) Easting 601124 Northing 4839365

/ Monitoring Test Hole UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) Bottom of Screen 3.7 (mbgs)

Screen Interval 0.6 (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SILT / SAND /
3.7		BROWN	SAND / /

Well Record #

7473195 Lot 006 Conc 02 BRAMPTON CITY / PEEL

Date 2024-03-06 DD/MM/YYYY | Elev (masl) | Easting 601087 | Northing 4839382 | / Monitoring | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 3.7 (mbgs)

Screen Interval 0.6 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SILT / SAND /
3.7		BROWN	SAND / /

7473196 Lot 006 Conc 02 BRAMPTON CITY / PEEL

Date 2024-03-06 DD/MM/YYYY | Elev (masl) | Easting 601127 | Northing 4839387 | / Monitoring | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SILT / SAND /
4.6		BROWN	SAND / /

7473197 Lot 006 Conc 02 BRAMPTON CITY / PEEL

Date 2024-03-06 DD/MM/YYYY | Elev (masl) | Easting 601140 | Northing 4839390 | / Monitoring | Test Hole | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter 2 inch | Casing Material: PLASTIC

Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs)

Screen Interval 1.5 (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.7		BROWN	SILT / SAND /
4.6		BROWN	SAND / /

7473983 Lot Conc BRAMPTON CITY / PEEL

Date 2024-02-16 DD/MM/YYYY | Elev (masl) | Easting 601207 | Northing 4838474 | / | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

7473984 Lot Conc BRAMPTON CITY / PEEL

Date 2024-02-16 DD/MM/YYYY | Elev (masl) | Easting 601213 | Northing 4838482 | / | UTM RC 4 | margin of error : 30 m - 100 m

Water Found (mbgs) (masl)

Casing Diameter | Casing Material:

Top of Screen (mbgs) | Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
			/ /

Well Record #

7473985 Lot Conc **BRAMPTON CITY / PEEL**

Date 2024-02-29 DD/MM/YYYY | Elev (masl) | Easting 601205 | Northing 4838484 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

7473986 Lot Conc **BRAMPTON CITY / PEEL**

Date 2024-02-29 DD/MM/YYYY | Elev (masl) | Easting 601211 | Northing 4838488 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

7475500 Lot 005 Conc 02 **BRAMPTON CITY / PEEL**

Date 2024-04-11 DD/MM/YYYY | Elev (masl) | Monitoring | Easting 601187 | Test Hole | Northing 4839070 | UTM RC 4 margin of error : 30 m - 100 m

Water Found 5.9 (mbgs) (masl) Untested | Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 3.0 (mbgs) | Bottom of Screen 4.6 (mbgs) | Screen Interval 1.5 (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
1.5		BROWN	CLAY / SILT / HARD
3.0		GREY	CLAY / SILT /
4.6		GREY	SILT / SHALE /
9.1		GREY	/ /

7478970 Lot 006 Conc 02 **BRAMPTON CITY / PEEL**

Date 2024-05-06 DD/MM/YYYY | Elev (masl) | Monitoring | Easting 601180 | Observation Wells | Northing 4839433 | UTM RC 4 margin of error : 30 m - 100 m

Water Found 4.4 (mbgs) (masl) | Casing Diameter 2 inch | Casing Material: PLASTIC | Top of Screen 2.3 (mbgs) | Bottom of Screen 5.3 (mbgs) | Screen Interval 3.0 (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
2.1			CLAY / SILT / FILL
5.3		GREY	SILT / TILL /

7479702 Lot Conc **BRAMPTON CITY / PEEL**

Date 2024-05-09 DD/MM/YYYY | Elev (masl) | Easting 601102 | Northing 4839408 | UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) | Casing Diameter | Casing Material: | Top of Screen (mbgs) | Bottom of Screen (mbgs) | Screen Interval (m)

Flowing? SWL (mbgs) (masl) | Pumping WL (mbgs) (masl) | Pump Rate (LPM) / | Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

Well Record #

7479703 Lot Conc BRAMPTON CITY / PEEL

Date 2024-05-09 DD/MM/YYYY

Elev (masl) Easting 601093 Northing 4839285 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) /

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7479704 Lot Conc BRAMPTON CITY / PEEL

Date 2024-05-09 DD/MM/YYYY

Elev (masl) Easting 601073 Northing 4839355 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) /

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7480582 Lot Conc BRAMPTON CITY (TORONTO TWP) / PEEL

Date 2023-01-19 DD/MM/YYYY

Elev (masl) Easting 603720 Northing 4836027 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) /

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

7480583 Lot Conc BRAMPTON CITY (TORONTO TWP) / PEEL

Date 2023-01-19 DD/MM/YYYY

Elev (masl) Easting 603728 Northing 4836046 UTM RC 4 margin of error : 30 m - 100 m

Water Found (mbgs) (masl) /

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Depth (m) Elev (masl)
0.0

Color Soil Descriptions

Flowing?
SWL (mbgs) (masl)
Pumping WL (mbgs) (masl)
Pump Rate (LPM) /
Spec. Cap. (LPM/m) Hour / Minute

/ /

MECP Water Well Records

Well Record #

7114845 Lot Conc **BRAMPTON CITY / PEEL**

Date 2008-08-15 DD/MM/YYYY

Elev (masl) Easting 595811 Northing 4841109 UTM RC 3 margin of error : 10 - 30 m

/

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

/ /

/ /

7114851 Lot Conc **BRAMPTON CITY / PEEL**

Date 2008-10-02 DD/MM/YYYY

Elev (masl) Easting 595866 Northing 4841138 UTM RC 3 margin of error : 10 - 30 m

/ Monitoring Test Hole

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

/ /

/ /

7119442 Lot Conc **BRAMPTON CITY / PEEL**

Date 2009-01-18 DD/MM/YYYY

Elev (masl) Easting 600932 Northing 4839434 UTM RC 3 margin of error : 10 - 30 m

/ Monitoring

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			

/ /

/ /

7122312 Lot Conc **BRAMPTON CITY / PEEL**

Date 2009-03-13 DD/MM/YYYY

Elev (masl) Easting 601227 Northing 4839340 UTM RC 3 margin of error : 10 - 30 m

/ Monitoring Test Hole

Water Found (mbgs) (masl)

Casing Diameter Casing Material:

Top of Screen (mbgs) Bottom of Screen (mbgs)

Screen Interval (m)

Flowing?

SWL (mbgs) (masl)

Pumping WL (mbgs) (masl)

Pump Rate (LPM) /

Spec. Cap. (LPM/m) Hour / Minute

Depth (m)	Elev (masl)	Color	Soil Descriptions
0.0			
0.6		BROWN	GRAVEL / / PACKED
1.8		BLACK	CLAY / /
3.7		GREY	CLAY / /

/ /

/ /

/ /

/ /

/ /

/ /

Well Record #

										4.6	GREY	TILL /		/		
7130495	**Lot**	**Conc**			**BRAMPTON CITY / PEEL**							Flowing?				
Date 2009-09-18	Elev	(masl)	Easting 602543		Northing 4837038							SWL 2.6	(mbgs)		(masl)	
DD/MM/YYYY	/ Monitoring		Observation Wells		UTM RC 3		margin of error : 10 - 30 m					Pumping WL	(mbgs)		(masl)	
	Water Found 2.6	(mbgs)	(masl)		Not stated							Pump Rate	(LPM)		/	
	Casing Diameter 5.1	cm	Casing Material:	PLASTIC					Depth (m)	Elev (masl)		Spec. Cap.	(LPM/m)		Hour / Minute	
	Top of Screen	(mbgs)	Bottom of Screen	(mbgs)					0.0		Color		Soil Descriptions			
	Screen Interval	(m)														
												/		/		
												/		/		
												/		/		
									3.0		BROWN	SILT /	TILL	/		
									7.5		GREY	SILT /	TILL	/		
									8.5		GREY	SAND /	SILT	/		
7133742	**Lot**	**Conc**			**BRAMPTON CITY / PEEL**							Flowing?				
Date 2009-10-08	Elev	(masl)	Easting 601014		Northing 4838737							SWL	(mbgs)		(masl)	
DD/MM/YYYY	/ Test Hole		Test Hole		UTM RC 4		margin of error : 30 m - 100 m					Pumping WL	(mbgs)		(masl)	
	Water Found	(mbgs)	(masl)									Pump Rate	(LPM)		/	
	Casing Diameter		Casing Material:						Depth (m)	Elev (masl)		Spec. Cap.	(LPM/m)		Hour / Minute	
	Top of Screen 4.0	(mbgs)	Bottom of Screen	7.0 (mbgs)					0.0		Color		Soil Descriptions			
	Screen Interval 3.0	(m)														
									0.6		BROWN	FILL /	GRAVEL	/ SANDY		
									4.9		BROWN	CLAY /	SILTY	/		
									6.1		GREY	CLAY /	SILTY	/		
									7.0		BROWN	SHALE /	WEATHERED	/ DRY		
7133912	**Lot**	**Conc**			**BRAMPTON CITY / PEEL**							Flowing?				
Date 2009-10-20	Elev	(masl)	Easting 595865		Northing 4841132							SWL	(mbgs)		(masl)	
DD/MM/YYYY	/		Abandoned-Other		UTM RC 3		margin of error : 10 - 30 m					Pumping WL	(mbgs)		(masl)	
	Water Found	(mbgs)	(masl)									Pump Rate	(LPM)		/	
	Casing Diameter		Casing Material:						Depth (m)	Elev (masl)		Spec. Cap.	(LPM/m)		Hour / Minute	
	Top of Screen	(mbgs)	Bottom of Screen	(mbgs)					0.0		Color		Soil Descriptions			
	Screen Interval	(m)														
												/		/		
7139363	**Lot**	**Conc**			**BRAMPTON CITY / PEEL**							Flowing?				
Date 2009-09-15	Elev	(masl)	Easting 596897		Northing 4838750							SWL	(mbgs)		(masl)	
DD/MM/YYYY	/ Monitoring		Observation Wells		UTM RC 4		margin of error : 30 m - 100 m					Pumping WL	(mbgs)		(masl)	
	Water Found	(mbgs)	(masl)									Pump Rate	(LPM)		/	
	Casing Diameter		Casing Material:						Depth (m)	Elev (masl)		Spec. Cap.	(LPM/m)		Hour / Minute	
	Top of Screen	(mbgs)	Bottom of Screen	(mbgs)					0.0		Color		Soil Descriptions			
	Screen Interval	(m)														
												/		/		
												/		/		
												/		/		
												/		/		
									6.6		BROWN	CLAY /		/ SILTY		

Flow
Building our future, faster.

Central Brampton

C3: Contaminant Overview Study

AECOM

Peel Region

ENVISION
CONSULTANTS LTD

CONTAMINANT OVERVIEW STUDY

Old School Road, Orangeville-Brampton Railway, Bovaird Drive West, Vodden Street East/West, Kennedy Road North/South, Queen Street East, Caledon and Brampton, Ontario

Project #: 24-0735
Prepared for: Region of Peel
Date: August 27, 2025
Region of Peel Project #: 24-2593

Report Version: 03

6415 Northwest Drive
Units 37-40
Mississauga, ON L4V 1X1

envisionconsultants.ca

August 27, 2025

Region of Peel
10 Peel Centre Drive, Suite B, 4th Floor
Brampton, ON L6T 4B9

Attention: Greg Beams, Project Manager

SUBJECT: CONTAMINANT OVERVIEW STUDY, OLD SCHOOL ROAD, ORANGEVILLE-BRAMPTON RAILWAY, BOVAIRD DRIVE WEST, VODDEN STREET EAST/WEST, KENNEDY ROAD NORTH/SOUTH, QUEEN STREET EAST, CALEDON AND BRAMPTON, ONTARIO

EnVision Consultants Ltd. is pleased to present the enclosed Contaminant Overview Study for the above-noted project. The report describes the interpreted environmental conditions based on available information and observations and provides conclusions for your consideration.

This Contaminant Overview Study does not constitute an Assessment of Past Uses in accordance with Ontario Regulation 406/19 or a Phase One Environmental Site Assessment in accordance with Ontario Regulation 153/04.

We thank you for utilizing EnVision for this assignment. If there are any questions regarding the enclosed report, please do not hesitate to contact us.

Yours sincerely,



Dhru Enright
Director – Project Management
denright@envisionconsultants.ca

QUALITY MANAGEMENT

ISSUE	FIRST ISSUE	REVISION 1	REVISION 2
PROJECT NUMBER	24-0735	24-0735	24-0735
PROJECT REFERENCE	Contaminant Overview Study, Old School Road, Orangeville-Brampton Railway, Bovaird Drive West, Vodden Street East/West, Kennedy Road North/South, Queen Street East, Caledon and Brampton, Ontario	Contaminant Overview Study, Old School Road, Orangeville-Brampton Railway, Bovaird Drive West, Vodden Street East/West, Kennedy Road North/South, Queen Street East, Caledon and Brampton, Ontario	Contaminant Overview Study, Old School Road, Orangeville-Brampton Railway, Bovaird Drive West, Vodden Street East/West, Kennedy Road North/South, Queen Street East, Caledon and Brampton, Ontario
VERSION NO.	01	02	02
REMARKS	Draft Report	Final Report	Final Report
PREPARED BY	Ishita Patel	Ishita Patel	Ishita Patel
SIGNATURE	DRAFT		
REVIEWED BY	Maryanne Caluori	Maryanne Caluori	Maryanne Caluori
SIGNATURE	DRAFT		
REVIEWED BY	Rodney Obdeyn	Rodney Obdeyn	Rodney Obdeyn
SIGNATURE	DRAFT		
DATE	August 8, 2025	August 21, 2025	August 27, 2025

The original of this digital file will be kept by EnVision for a period of not less than 10 years. As the digital file transmitted to the intended recipient is no longer under the control of EnVision, its integrity cannot be assured. As such, EnVision does not guarantee any modifications made to this digital file subsequent to its transmission to the intended recipient.

TABLE OF CONTENTS

1. Executive Summary 1
2. Introduction 4
   2.1. Project Information 4
3. Overview of the nvestigation 6
   3.1. Objectives 6
   3.2. Scope 6
4. Records Review 7
   4.1. Preliminary Records Review 7
   4.2. General Records Review 7
   4.3. Environmental Source Information 8
   4.4. Physical Setting Sources 12
   4.5. Site Operating Records 14
5. Site Reconnaissance 15
   5.1. General Requirements 15
   5.2. Specific Observations Within the Project Area 16
   5.3. Observations Within the Study Area 17
6. Review And Evaluation of Information 20
   6.1. Conceptual Site Model 20
7. Closing 21
   7.1. Conclusions 21
   7.2. Qualifications of the Assessors 21
   7.3. Signatures 22
   7.4. Qualifier 22
8. References 24

LIST OF TABLES *(INCLUDED WITHIN THE REPORT)*

Table 2-1: Project Area Information 4

Table 4-1: Summary of the Preliminary Records Review 7

Table 4-2: Summary of Environmental Source Records Review 8

Table 4-3: Summary of Aerial Photograph and Satellite Imagery Review 13

Table 4-4: Summary of the Physical Setting Records Review 13

Table 5-1: Summary of General Requirements of the Site Reconnaissance 15

Table 5-2 Summary of Specific Observations within the Project Area 16

Table 5-3: Summary of Observations within the Study Area 18

Table 6-1: Summary of a Review and Evaluation of Information gathered during the Study 20

LIST OF TABLES *(ATTACHED TO THE REPORT)*

Table 1A Summary of Potentially Contaminating Activities – Old School Road Portion

Table 1B Summary of Potentially Contaminating Activities – Orangeville Brampton Railway Portion

Table 1C Summary of Potentially Contaminating Activities – Bovaird Drive West Portion

Table 1D Summary of Potentially Contaminating Activities – Vodden Street East/West Portion

Table 1E Summary of Potentially Contaminating Activities – Kennedy Road North/South Portion

Table 1F Summary of Potentially Contaminating Activities – Queen Street East Portion

Table 2A Areas of Potential Environmental Concern – Old School Road Portion

Table 2B Areas of Potential Environmental Concern – Orangeville Brampton Railway Portion

Table 2C Areas of Potential Environmental Concern – Bovaird Drive West Portion

Table 2D Areas of Potential Environmental Concern – Vodden Street East/West Portion

Table 2E Areas of Potential Environmental Concern – Kennedy Road North/South Portion

Table 2F Areas of Potential Environmental Concern – Queen Street East Portion

LIST OF FIGURES *(ATTACHED TO THE REPORT)*

Figure 1 Project Areas

Figure 2A Project Area Location Plan – Old School Road Portion

Figure 2B Project Area Location Plan – Orangeville Brampton Railway Portion

Figure 2C Project Area Location Plan – Bovaird Drive West Portion
Figure 2D Project Area Location Plan – Vodden Street East/West Portion
Figure 2E Project Area Location Plan – Kennedy Road North/South Portion
Figure 2F Project Area Location Plan – Queen Street East Portion
Figure 3A Areas of Potential Environmental Concern – Old School Road Portion
Figure 3B Areas of Potential Environmental Concern – Orangeville Brampton Railway Portion
Figure 3C Areas of Potential Environmental Concern – Bovaird Drive West Portion
Figure 3D Areas of Potential Environmental Concern – Vodden Street East/West Portion
Figure 3E Areas of Potential Environmental Concern – Kennedy Road North/South Portion
Figure 3F Areas of Potential Environmental Concern – Queen Street East Portion

LIST OF APPENDICES

APPENDIX A: ERIS Reports

APPENDIX B: Aerial Photographs

APPENDIX C: Site Photographs

GLOSSARY

TERM	DEFINITION
ABNs	Acid-base neutral compounds
APEC	area(s) of potential environmental concern as defined in O. Reg. 153/04, "the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through (a) identification of past or present uses on, in or under the phase one property, and (b) identification of potentially contaminating activity"
APU	Assessment of Past Uses
As	arsenic
AST	above ground storage tank
B-HWS	boron (hot water soluble)
BTEX	benzene, toluene, ethylbenzene, xylene
CA	Certificate of Approval
Ca	calcium
CN-	cyanide
COPC	contaminant(s) of potential concern
CPs	chlorophenols
Cr-	chromium
Cr (VI)	hexavalent chromium
CSM	conceptual site model
EASR	Environmental Activity and Sector Registry
EBR	Environmental Registry
EC	electrical conductivity
ECA	Environmental Compliance Approval
ERIS	Environmental Risk Information Services
ESA	environmental site assessment
FIP	fire insurance plan
FOI	freedom of information
ha	hectare(s)
Hg	mercury

TERM	DEFINITION
km	kilometre(s)
L	litre(s)
m	metre(s)
masl	metres above sea level
mbgs	metres below ground surface
Mg	magnesium
Metals	O. Reg. 153/04 regulated metals as per Protocol for Analytical Methods Used in the Assessment of Properties under Part XV.1 of the Environmental Protection Act
MNDM	Ministry of Northern Development and Mines
MNRF	Ministry of Natural Resources and Forestry
MECP	Ministry of Environment, Conservation and Parks
NPRI	National Pollutant Release Inventory
N/S	not specified in Table 2, Schedule D, of O. Reg. 153/04
Na+	sodium
OCs	organochlorine pesticides
O. Reg. 153/04	Ontario Regulation 153/04, as amended
O. Reg. 347	Ontario Regulation 347, as amended
O. Reg. 406/19	Ontario Regulation 406/19, as amended
ORPs	other regulated parameter(s) per Protocol for Analytical Methods Used in the Assessment of Properties under Part XV.1 of the Environmental Protection Act
PAH	polycyclic aromatic hydrocarbon
PCA	potentially contaminating activity as defined in O. Reg. 153/04, "a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a Phase One study area"
PCB	polychlorinated biphenyl
PHC	petroleum hydrocarbon
PIN	property identification number
PTTW	permission to take water
PUP	property underwriter plan
PUR	property underwriter report
QA/QC	quality assurance/quality control

TERM	DEFINITION
QP_{ESA}	Qualified Person for ESAs according to MECP (O. Reg. 153/04)
RA	risk assessment
RSC	Record of Site Condition
Rules Document	Rules for Soil Management and Excess Soil Quality Standards
SAP	Sampling and Analysis Plan
SAR	sodium adsorption ratio
Sb	antimony
SCR	Soil Characterization Report
SCS	Site Condition Standards
Se	selenium
THM	trihalomethane
TSSA	Technical Standards and Safety Authority
UST	underground storage tank
VOC	volatile organic compound
WWIS	water well information system

1. EXECUTIVE SUMMARY

EnVision Consultants Ltd. (EnVision) was retained by Region of Peel (the 'Client') to conduct a Contaminant Overview Study (the 'Study') for the following areas in Brampton, Ontario (the 'Project Area'):

- Kennedy Road North/South from 300 m south of Hartford Trail to 100 m north of Vodden Street East (approximately 5.1 km) ('Kennedy Portion');
- Queen Street East from Rutherford Road to Kennedy Road (approximately 0.9 km) ('Queen Portion');
- Vodden Street East/West from Kennedy Road to the Orangeville-Brampton Railway (OBRY) (approximately 1.9 km) ('Vodden Street East/West Portion');
- Orangeville-Brampton Railway from Vodden Street to Old School Road (approximately 9.5 km) ('OBRY Portion');
- Bovaird Drive West from OBRY to 300 m west of McLaughlin Road (approximately 1 km) ('Bovaird Portion'); and
- Old School Road from OBRY to Hurontario Street (approximately 1.2 km) ('Old School Portion').

It is our understanding that the Study was requested for due-diligence purposes to support the management of excess soil which may be generated during activities associated with construction of a proposed trunk sewer for the portions of the Project Area within the Region's Scope Area 1 (which include the areas summarized above).

The Project Area comprises five (5) municipal roadways and one (1) railway line corridor, as described above, in a mixed residential, commercial and industrial area in the City of Brampton. For simplicity in this report Kennedy Road North and Kennedy Road South are described to be oriented in a north-south direction, and Bovaird Drive West and Queen Street East are described to be oriented in an east-west direction.

The objective of the Study was to develop a preliminary determination of the likelihood that one or more contaminants have affected the Project Area through:

- Identification of Potentially Contaminating Activities (PCAs) within the Project Area and Study Area;
- Evaluation and determination if any portion of the Project Area where soil is proposed for excavation could have been affected by a PCA, resulting in the identification of an area of potential environmental concern (APEC) within the Project Area; and,
- If APECs are identified, determine the Contaminants of Potential Concern (COPCs) associated with each APEC, based on the contributing PCA(s).

Based on the records review, site reconnaissance, and evaluation of information, EnVision presents the following findings:

- The Project Area has been utilized as municipal roadways and a railway. Kennedy Road North/South (from Vodden Street East to Steeles Avenue East), Queen Street East, Vodden Street East/West, Bovaird Drive West and Old School Road were developed as municipal roadways and Orangeville-Brampton Railway was developed as a railway by 1877. The southern portion of Kennedy Street South was developed as a municipal roadway in 1954.
- The Project Area ranges in elevation from approximately 195 to 265 metres above sea level (masl). The regional topography in the vicinity of the Project Area generally slopes to the southeast. Based on the local topography, the inferred general shallow groundwater flow direction of the Study Area is anticipated to be to the southeast towards Lake Ontario. It is noted that the Project Area includes more than one (1) subwatershed. The north portion of the Project Area, just south of Old School Road (approximately half-way to Mayfield Road to the south) includes tributaries which feed into Etobicoke Creek, which generally flows southeast, east of - and approximately parallel to - Hurontario Street and crosses Vodden Street in the southern portion of the Project Area. The Project Area from north Mayfield Road to Vodden Street includes tributaries which feed into the Credit River subwatershed. Based on the size of the Project Area and the presence of numerous creeks and tributaries, the groundwater flow direction can only be confirmed through long-term groundwater monitoring.
- The surficial geology in the vicinity of the Project Area is mainly characterized by clay to silt-textured till (derived from glaciolacustrine deposits or shale). Some areas of the Project Area are classified as modern alluvial deposits. The bedrock in the Study Area is shale, limestone, dolostone, and siltstone of the Queenston Formation. Additional details regarding expected of soil, bedrock, and groundwater conditions in the Project Area are provided in EnVision's report entitled "Desktop Geotechnical Study – Proposed Trunk Sewer on Kennedy Rd. & Orangeville Brampton Railway, Old School Rd., Bovaird Dr., Vodden St. and Queen St. E" which is presented under separate cover.
- Several potable water wells were identified within the agricultural area within the northern portion of the Study Area near the Hurontario Portion of the Project Area.
- Provincially significant wetland, Credit Valley Conservation (CVC) regulated areas and Greenbelt – Urban River Valley areas were identified to be surrounding Etobicoke Creek and its tributaries both adjacent to and intersecting the Project Area.
- The following PCAs identified within the Project Area were determined to be contributing to APECs:
  - Fill materials of unknown environmental quality were anticipated to have been brought to the Project Area during construction and/or maintenance activities associated with the roadways and/or associated utilities (PCA 30). Further, it is anticipated that de-icing compounds are applied seasonally to the roadways within the Project Area for the purpose of vehicular safety (PCA E);
  - A rail line (Orangeville-Brampton Railway) was identified in the northern and central portion of the Project Area from as early as 1877, and the Toronto and Goderich Railway was identified in the southern portion of the Project Area from as early as 1856 (PCA 46); and

- Various spills were identified within the portions of the Project Area (PCA A).

- The following PCAs identified within the Study Area were determined to be contributing to APECs:
  - A total of 23 autobody and/or auto service garages (PCA 10 and 27), 17 properties with tank records (PCA 28), four (4) dry cleaners (PCA 37), one (1) transformer (PCA 55), various spills (PCA A) and various other industrial properties were identified within the Study Area as detailed further within this report.

Based on the information obtained through the Study, it was concluded that the above referenced PCAs resulted in the identification of 30 APECs within the Project Area. Based on the APECs identified, associated COPCs in soil include metals and other regulated parameters (ORPs), petroleum hydrocarbons (PHCs), and benzene, toluene, ethylbenzene, xylenes (collectively referred to as BTEX), volatile organic compounds (VOCs), polycyclic aromatic hydrocarbons (PAHs), semi-volatile organic compounds (sVOCs), and polychlorinated biphenyl (PCBs). Although not considered to be of significant concern, select sampling for organochlorine pesticides (OCs) (potentially associated with neighboring agricultural lands) is recommended as a conservative measure.

This Study was conducted to provide a general overview of the presence of potentially contaminating activities which could impact the environmental quality of soil or groundwater within the Project Area and to inform future investigations associated with the proposed infrastructure work. The scope of work associated with future investigations will be dependent on the design of the below grade infrastructure (i.e., particularly the depth). Once additional details regarding the design depth and location of the tunnel and shafts have been developed, an appropriate sampling and analysis plan can be completed to evaluate soil and/or bedrock quality for management under Ontario Regulation 406/19 and/or to evaluate groundwater quality for proper management/disposal during construction.

2. INTRODUCTION

EnVision Consultants Ltd. (EnVision) was retained by Region of Peel (the 'Client') to conduct a Contaminant Overview Study (the 'Study') for the following areas in Brampton, Ontario (the 'Project Area'):

- Kennedy Road North/South from 300 m south of Hartford Trail to 100 m north of Vodden Street East (approximately 5.1 km) ('Kennedy Portion');
- Queen Street East from Rutherford Road to Kennedy Road (approximately 0.9 km) ('Queen Portion');
- Vodden Street East/West from Kennedy Road to the Orangeville-Brampton Railway (OBRY) (approximately 1.9 km) ('Vodden Street East/West Portion');
- Orangeville-Brampton Railway from Vodden Street to Old School Road (approximately 9.5 km) ('OBRY Portion');
- Bovaird Drive West from OBRY to 300 m west of McLaughlin Road (approximately 1 km) ('Bovaird Portion'); and
- Old School Road from OBRY to Hurontario Street (approximately 1.2 km) ('Old School Portion').

2.1. PROJECT INFORMATION

The Project Area comprises five (5) municipal roadways and one (1) former railway line, as described above, in a mixed residential, commercial and industrial area in the City of Brampton. For simplicity in this report Kennedy Road North and Kennedy Road South are described to be oriented in a north-south direction, and Bovaird Drive West, Queen Street East, and Vodden Street are described to be oriented in an east-west direction.

It is our understanding that the Study was requested for due-diligence purposes to support the management of excess soil which may be generated during activities associated with a proposed trunk sewer for the portions of the Project Area within the Region's Scope Area 1.

An illustration of the entire Project Area is presented as Figure 1, attached. Project Area Location Plans and Areas of Potential Environmental Concern plans demonstrating these described features are presented as Figure 2A through Figure 2G and Figure 3A through Figure 3F, attached.

Additional information pertaining to the Project Area is provided in *Table 2-1,* below:

Table 2-1: Project Area Information

CRITERION	PROJECT AREA INFORMATION
MUNICIPAL ADDRESS(ES)	The Project Area is comprised of roadways and a railway line corridor, and as such, no municipal addresses area associated with this property.
LEGAL DESCRIPTION	A legal description of the Project Area was not provided at the time of this assessment.

CRITERION	PROJECT AREA INFORMATION
PROPERTY IDENTIFICATION NUMBER(S) (PIN)	PIN(s) and/or a Plan of Survey associated with the Project Area were not provided at the time of this assessment.
PROPERTY OWNER(S)	Inferred ownership of the various road segments of the Project Area is as follows: - Town of Caledon: Old School Road - Town of Brampton: Vodden Street East & West, Queen Street East - Region of Peel: Bovaird Drive West; Kennedy Road North and South The ownership of the former Orangeville-Brampton rail line parcel was not confirmed as part of this assessment.
GEOGRAPHICAL COORDINATES	599581.63 m E 4839046.23 m N
LEGAL INSRUMENTS	It is our understanding that at the time of this assessment, the Project Area is not subject to any legal instruments.
RECORD OF SITE CONDITION (RSC) AND/OR RISK ASSESSMENT (RA)	It is our understanding that at the time of this assessment, no RSCs have been filed for the Project Area, nor is an RSC intended to be filed. Further, an RA has not been conducted, nor is there any intention to conduct an RA at this time.

A plan of survey was not available for the Site.

3. OVERVIEW OF THE NVESTIGATION

3.1. OBJECTIVES

The general objectives of the Study include a preliminary determination of the likelihood that one or more contaminants have affected the Project Area through:

- Identification of PCAs within the Project Area and surrounding Study Area;
- Evaluation and determination if any portion of the Project Area where soil is proposed for excavation could have been affected by a PCA, resulting in the identification of an APEC within the Project Area; and,
- If an APEC is identified, determination of COPCs associated with each APEC based on the contributing PCA(s) to inform a Sampling and Analysis Plan.

3.2. SCOPE

The scope of the Study includes the following components:

- A records review of publicly available information;
- Site reconnaissance;
- A review and evaluation of the information gathered from the records review, and the site reconnaissance, including the preparation of a CSM; and,
- The preparation of a Contaminant Overview Study report.

The following key elements were completed as part of this assessment:

- Establishment of an appropriate search radius (the 'Study Area') to adequately evaluate adjacent and neighbouring properties;
- Request and review of:
  - Historical information (i.e., aerial photographs) to establish current and past land uses of the Project Area and identify PCAs at or affecting the Project Area;
  - Applicable physical setting sources and documents (i.e., maps, provincial/federal archives, etc.);
  - Applicable federal and provincial databases, including information available from the TSSA with regards to any storage tanks in the Project Area and/or on adjacent properties;
- Completion of a site reconnaissance; and,
- Documentation of the findings in tables and figures summarizing information of each PCA and APEC, as applicable.

4. RECORDS REVIEW

The records review was conducted to obtain and review records that relate to the Study Area, including both the current and past uses of the Project Area and the PCAs at or affecting the Project Area, in order to determine if an APEC exists within the Project Area.

4.1. PRELIMINARY RECORDS REVIEW

Preliminary records were reviewed to determine the history of development and land use of the Project Area and properties within the Study Area. The preliminary record sources and results of the review are provided in *Table 4-1*, below:

Table 4-1: Summary of the Preliminary Records Review

CRITERION	RECORDS REVIEW RESULTS
STUDY AREA	The Study Area for this undertaking included properties wholly, or partially, within 100 m of the Project Area boundary. Properties wholly beyond 100 m of the Project Area boundary were not added to the Study Area due to low potential to impact the environmental condition of the Project Area. The limits of the Study Area are presented on Figure 2A through Figure 2F, attached.
FIRST DEVELOPED USE OF THE PROJECT AREA	The first developed use of the Project Area was determined through a review of the 1877 Peel County Atlas and subsequent available aerial photographs from 1954 and 1994. Based on the Peel County Atlas and aerial photographs, a portion of Kennedy Road North/South (from Vodden Street East to Steeles Avenue East), Queen Street East, Vodden Street East/West, Bovaird Drive West and Old School Road were developed as municipal roadways and Orangeville-Brampton Railway was developed as a railway by 1877. The southern portion of Kennedy Street South was developed as a municipal roadway prior to the time of the 1954 aerial photograph.

4.2. GENERAL RECORDS REVIEW

As part of the records review, the QP made all reasonable inquiries to determine the following general information pertaining to the Project Area and properties within the Study Area, including inquiries to obtain reasonably accessible records pertaining to the current use(s) and all past uses of the Project Area. The general information sources and results of the review are provided in subsequent sections below.

4.2.1. Historical Insurance Information

Fire insurance plans were not assessed as part of this investigation.

4.2.2. Previous Reports

Previous reports pertaining to the Project Area were not provided for EnVision to review as part of this assessment.

4.3. ENVIRONMENTAL SOURCE INFORMATION

The QP made all reasonable inquiries to obtain information from publicly availably sources that pertains to the following subsections, as are reasonably accessible and pertain to the Project Area and properties within the Study Area.

A summary of the results of the Environmental Source record review is provided in *Table 4-2*, below.

Table 4-2: Summary of Environmental Source Records Review

CRITERION	
NATIONAL POLLUTANT RELEASE INVENTORY (NPRI)	The NPRI records database was not searched as part of this assessment.
ENVIRONMENTAL COMPLIANCE APPROVAL (ECA), CERTIFICATE OF APPROVAL (CA), PERMITS TO TAKE WATER (PTTW), AND CERTIFICATE OF PROPERTY USE (CPU)	The Access Environment Online Database did not identify MECP ECA, CA, PTTW, or CPU records for the Project Area. A total of 23 properties within the Study Area were identified with records, as summarized below: • Imperial Oil Ltd. at 140 Kennedy Road North was registered with approvals related to storm water management systems in 2008. • Petro-Canada at 121 Kennedy Road North was registered for an approval related to stormwater management in 2003. • Maple Leaf Foods Inc. at 32 Kennedy Road North was registered for approvals related to natural gas fired heaters, water heaters and boilers, in 2000 and 2002. • 134 Kennedy Road South was registered for approvals related to natural gas fired dryers in 2002 and 2005 and a storm drain sewer in 2001. • AT Plastics Inc. at 142 Kennedy Road South was registered for an approval related to natural gas combustion equipment for heating in 2008. • Benson & Hedges Inc. at 174 Kennedy Road South was registered with approvals relating to cooling towers, exhaust systems, wet scrubber, a natural gas fired thermal fume incinerator, a baghouse dust collector, and a natural gas fired boiler in 2000 and 2008. • Imperial Oil Ltd. at 7995 Kennedy Road South was registered with an approval related to stormwater management systems in 2008. • John Logan Chevrolet Oldsmobile at 241 Queen Street East was registered with an approval related to a spray booth, solvent preparation station, undercoating booth and paint mix room in 2004. • Colony Ford Lincoln Sales Inc. at 300 Queen Street East was registered with approvals related to two (2) spray paint booths and one (1) paint mix room exhaust in 2003. • Petro-Canada at 354 Queen Street East was registered with an approval related to sewage works in 2001. • Brampton Brick Limited/Richvale York Block Inc. at 225 Wanless Drive was registered with an approval related to industrial air (dust control system, concrete block plant) in 1988 and baghouse dust collector in 1993.

CRITERION	
	• City of Brampton at 130 Sandalwood Parkway West was registered with an approval related to air systems in 2017. • Hydro One at 175 Sandalwood Parkway West was registered with an approval related to air systems in 2006. • Industrial Thermo Polymers Limited at 153 Van Kirk Drive West was registered with an approval related to industrial air in 1996 and industrial sewage works in 2008 • The Butcher Engineering Enterprises Limited at 105 Van Kirk Drive was registered with an approval related to air in 2006. • Copperweld Canada, Sonco Steel Tube Div at 95 Van Krik Drive was registered with an approval for vent/hoods for welding operations in 1998. • GO a division of Metrolinx at 85 Van Kirk Drive was registered with an approval related to air in 2011. • Call Disposal Services Ltd. at 190 Bovaird Drive West was registered with an approval related to air in 2008 and waste management systems in 2012. • Regional Municipality of Peel (location along Vodden Street East) was registered with an approval related to municipal sewage in 1995. • City of Brampton at 75 Vodden Street East was registered with an approval related to air in 1995. • Imperial Oil Limited at 75 Vodden Street East was registered with an approval related to industrial sewage works in 2008. • Petro Canada at 121 Kennedy Road North was registered with an approval related to industrial sewage works in 2003. • Wallstar properties at 99 Kennedy Road North was registered with an approval related to industrial air in 1985.
INVENTORY OF COAL GASIFICATION PLANTS	The OGS Earth database of the Inventory of Coal Gasification Plants did not identify records of coal gasification plants or coal tar sites associated with the Project Area or properties within the Study Area.
WASTE MANAGEMENT RECORDS, INCLUDING CURRENT AND HISTORICAL WASTE STORAGE LOCATIONS, O. REG. 347 WASTE GENERATOR / RECEIVER SUMMARY RECORDS, AND MECP WASTE DISPOSAL INVENTORY	The ERIS report did not identify Waste Receiver Records for the Project Area or properties within the Study Area. No O. Reg. 347 Waste Generator Summary Records were identified for the Project Area. A total of 974 records were identified for the Study Area. The following addresses were identified with waste generation records which coincide with operations listed in other databases (i.e., Scott's Manufacturing Directory or Dry-Cleaning Facilities). • 105 Vankirk Drive; • 190 Bovaird Drive; • 225 Wanless Drive; • 175 Sandalwood Parkway West; • 190 Bovaird Drive; • 111 Van Kirk Drive; • 110 Canam Crescent; • 85 Van Kirk Drive;

CRITERION	
	• 130 Sandalwood Parkway; • 190 Highway 7 West; • 225 Wanless Drive; • 133 Vankirk Drive; • 195 Sandalwood Parkway West; • 95 Van Kirk Drive; • 153 Vankirk Drive; • 420 Railside Drive; • 190 Canam Crescent; • 10031 McLaughlin Road; • 9950, 10010, and 10021 McLaughlin Road; • 121 Kennedy Road; • 140 Kennedy Road; • 36 Vodden Street; • 32 Kennedy Road South; • 100 Kennedy Road South; • 110 Kennedy Road South; • 114 Kennedy Road South; • 134 Kennedy Road South; • 144 Kennedy Road South; • 158 Kennedy Road; • 174 Kennedy Road; • 365 Kennedy Road South; • 400 Steeles Avenue East; • 1 Wexford Road; • 255 Queen Street; • 174 Queen Street East; • 457 Queen Street East; and • 180 Hurontario Street. Further details of operations related to these addresses are described in Table 1A through Table 1F. Due to the nature of waste products (i.e., pathological and pharmaceutical wastes) identified or small quantity of wastes, the remaining properties identified in these databases were not anticipated to have impacted the environmental quality of the Project Area and are therefore not listed herein. Details pertaining to these additional records can be found in the ERIS report in Appendix A.
RECORDS OF FUEL STORAGE MAINTAINED BY TECHNICAL	The ERIS report did not identify records of fuel storage for the Project Area. A total of 207 records within the Study Area were identified, including the following addresses:

CRITERION	
STANDARDS AND SAFETY AUTHORITY (TSSA)	• A retail fuel storage tank was registered to Northwood Park Service Centre Inc. located at 190 Highway 7 West, east adjacent of the Project Area. • A retail fuel storage tank was registered to Butcher Engineering located at 105 Van kirk Drive, west adjacent of the Project Area. The tank is inferred to be located adjacent to the building approximately 40 m west of the Project Area. • 9950 McLaughlin Road (Husky), south adjacent to the Bovaird Portion of the Project Area, was listed with three (3) gasoline USTs. • 10010 McLaughlin Road (ESSO), north adjacent to the Bovaird Portion of the Project Area, was listed with three (3) gasoline USTs. • 10021 McLaughlin Road (Canadian Tire), north adjacent to the Bovaird Portion of the Project Area, was listed with two (2) gasoline and one (1) diesel USTs. • A gas station, ESSO Maximum, has been located at 140 Kennedy Road North, east adjacent to the Project Area since as early as 1981, and was listed with five (5) gasoline and one (1) diesel USTs. • A gas station, Petro Canada, has been located at 121 Kennedy Road North, west adjacent to the Project Area since as early as 2003, and was listed with three (3) gasoline and one (1) diesel USTs. • 140 Kennedey Road North (ESSO), east adjacent to the Kennedy Portion of the Project Area, was listed with five (5) gasoline and one (1) diesel USTs. • 121 Kennedey Road North (ESSO), west adjacent to the Kennedy Portion of the Project Area, was listed with three (3) gasoline and one (1) diesel USTs. • 10 Kennedey Road South (Parkinson Coach Lines), east adjacent to the Kennedy Portion of the Project Area, was listed with one (1) diesel UST in 1982. • 230 Queen Street East (Shell Canada), west adjacent to the Kennedy Portion of the Project Area, was listed with waste oil and bulk oil tanks. • 18 Kennedey Road South (ESSO), east adjacent to the Kennedy Portion of the Project Area, was listed with two (2) gasoline and two (2) diesel USTs. • 73 Kennedy Road South (Budget Rent-A-Car), west adjacent to the Kennedy Portion of the Project Area, was listed with one (1) gasoline and one (1) diesel UST. • 253 Kennedey Road South (Husky), west adjacent to the Kennedy Portion of the Project Area, was listed with three (3) gasoline and one (1) diesel USTs. • 7995 Kennedey Road South (ESSO), east adjacent to the Kennedy Portion of the Project Area, was listed with three (3) gasoline and one (1) diesel USTs. • One (1) gasoline and one (1) waste oil USTs were listed at John Logan Chevrolet Olds Inc., located at 241 Queen Street East, south adjacent to the Project Area, installed in 1984. • 252 Queen Street East (Canadian Tire), north adjacent to the Queen Portion of the Project Area, was listed with five (5) gasoline USTs and four (4) other tanks. Due to distance from the Project Area, the remaining properties identified in these databases were not anticipated to have impacted the environmental quality of the Project Area and are therefore not listed herein. Details pertaining to these additional records can be found in the ERIS report in Appendix A.

CRITERION	
NOTICES AND INSTRUMENTS, INCLUDING RECORDS OF SITE CONDITION (RSCS) POSTED ON THE SITE REGISTRY	The Site Registry did not identify records of Environmental Registrations for the Project Area, including RSCs. Five (5) RSCs were identified for properties within the Study Area, including: 10254 Hurontario street, located east adjacent to the Hurontario Portion of the Project Area, was registered with RSC # 225036, in September 2018: • A Phase One ESA was conducted for the property which identified nine (9) APECs, associated with PCAs including on-site fill materials, USTs and ASTs, off-site USTs and pesticides application. • A Phase Two ESA was conducted to investigate the identified APECs, and resulted in no found impacts in the soil and groundwater. 75 Van Kirk Drive, located in the west adjacent of the Project Area, was registered with RSC # 114530, in June 2011: • RSC was filed based on the Phase One ESA and Phase Two ESA. The remaining RSCs did not provide salient information which impacted the identification of APECs for the Project Area.
AREAS OF NATURAL SIGNIFICANCE MAINTAINED BY THE MINISTRY OF NATURAL RESOURCES AND FORESTRY (MNRF)	The Natural Heritage Areas database lists areas of natural significance including provincial parks, conservation reserves, areas of natural and scientific interest, wetlands environmentally significant areas, habitats of a threatened or endangered species, and wilderness areas. A review of this database listed the Eastern Meadowlark as a threatened species as well as Eastern Meadowlark, Bobolink, Redside Dace and Butternut as endangered within 1 km of the Project Area. As the Project Area consists of roadways and a non-operational railway line, these species are not anticipated to inhabit within the Site. If required, an environmental specialist could be retained to undertake a site-specific ecological assessment. For the purposes of this study, further assessment is not deemed warranted at this time. The Natural Heritage Areas database also identified the following areas of natural significance in the Study Area, as depicted on Figure 2A through Figure 2A. • Provincially significant wetland, CVC regulated areas and Greenbelt – Urban River Valley areas were identified to be surrounding Etobicoke Creek and its tributaries both adjacent to and intersecting the Project Area.

4.4. PHYSICAL SETTING SOURCES

4.4.1. Aerial Photographs and Satellite Imagery

Aerial photographs from the City of Brampton were reviewed as part of this assessment. The first available aerial photograph from 1954 was reviewed in order to determine early land use. Subsequent aerial photographs were obtained for review, as available (i.e., 1994, 2004, 2014, and 2024) in order to observe changes to the Project Area and Study Area over time. The County Atlas of Peel was utilized to obtain a more historical image from 1877.

Copies of the aerial photographs and Atlas are provided in Appendix B. Significant information depicted in these photographs is summarized in *Table 4-3*, below.

Table 4-3: Summary of Aerial Photograph and Satellite Imagery Review

YEAR	SUMMARY OF SALIENT INFORMATION
1877 PEEL COUNTY ATLAS	The Project Area was developed as municipal roadways (Kennedy Road North/South (from Vodden Street East to Steeles Avenue East), Queen Street East, Vodden Street East/West, Bovaird Drive West and Old School Road. Additionally, Orangeville-Brampton Railway was developed as a railway. A rail line was observed to intersect the central area of the Kennedy Portion of the Project Area in an east-west direction. The properties in the Study Area appeared to be utilized for agricultural and residential purposes. Etobicoke Creek appeared to run parallel and perpendicular and intersected the Project Area at various locations.
1954	The Project Area appeared similar to the 1877 County Atlas with the exception of the southern portion of Kennedy Street South which appeared to be developed as a municipal roadway. Properties within the surrounding Study Area appeared to be primarily used for residential or agricultural purposes.
1994	The Project Area appeared similar to the 1954 aerial photograph. Aerial photographs were not available for the northern portion of the OBRY and Old School Road and the surrounding areas. Properties within the surrounding Study Area appeared to be primarily used for residential or agricultural purposes, with the exception of central portion of the OBRY, eastern portion of Queen Street, and the central portion of Vodden Street which appeared to be used for commercial/industrial purposes. Due to poor image quality, a detailed description of the commercial, industrial, and residential properties is not possible.
2004 - 2024	Generally, the Project Area and Study Area appeared similar to the 1994 aerial photograph, and similar to present-day configuration.

4.4.2. Regional Topography, Physiography, Geology, and Hydrogeology

Mapping resources available from federal, provincial, and territorial agencies were reviewed to assess the physical settings of the Project Area. The findings of the review are summarized in *Table 4-4*, below:

Table 4-4: Summary of the Physical Setting Records Review

CRITERION	PHYSICAL SETTING RECORDS REVIEW RESULTS
TOPOGRAPHY	The Project Area ranges in elevation from approximately 195 to 265 masl. The regional topography in the vicinity of the Project Area generally slopes to the southeast. Based on the local topography, the inferred general shallow groundwater flow direction of the Study Area is anticipated to be to the southeast towards Lake Ontario. It is noted that the Project Area includes more than one (1) subwatershed. The north portion of the Project Area, just south of Old School Road (approximately half-way to Mayfield Road to the south) includes tributaries which feed into Etobicoke Creek, which generally flows southeast, east of - and approximately parallel to - Hurontario Street and crosses Vodden Street in the southern portion of the Project Area. The Project Area from north Mayfield Road to Vodden Street includes tributaries which feed into the Credit River subwatershed. Based on the size of the Project Area and the presence of numerous creeks and tributaries, the groundwater flow direction can only be confirmed through long-term groundwater monitoring. The

CRITERION	PHYSICAL SETTING RECORDS REVIEW RESULTS
	approximate topography and inferred groundwater flow direction within the Study Area is depicted on Figure 2A through Figure 2F.
PHYSIOGRAPHY	The northern portions of the Project Area (Old School, Orangeville Brampton railway, and Bovaird) are situated within drumlinized till plains. The southern portions of the Project Area (Kennedy and Queen and Vodden Portions) are situated within bevelled till plains.
MECP WELL RECORDS, GEOLOGY AND HYDROGEOLOGY	The surficial geology in the vicinity of the Project Area is mainly characterized by clay to silt-textured till (derived from glaciolacustrine deposits or shale). Some areas of the Project Area are classified as modern alluvial deposits. The bedrock in the Study Area is shale, limestone, dolostone, and siltstone of the Queenstone Formation. Additional details regarding expected of soil, bedrock, and groundwater conditions in the Project Area are provided in EnVision's report entitled "*Desktop Geotechnical Study – Proposed Trunk Sewer on Kennedy Rd. & Orangeville Brampton Railway, Old School Rd., Bovaird Dr., Vodden St. and Queen St. E*" which is presented under separate cover. Based on review of the MECP Well Records, several potable water wells were identified within the surrounding areas of Old Schol Road . The current status of these wells is unknown. The approximate well locations based on MECP well records are depicted on Figure 2A through Figure 2F.

4.5. SITE OPERATING RECORDS

To be classified as an enhanced investigation property, the Project Area must be used or have been used in whole or in part for any of the following uses:

- any industrial use;
- as a garage;
- as a bulk liquid dispensing facility, including a gasoline outlet; or,
- or the operation of dry-cleaning equipment.

Portions of the Project Area are comprised of municipal roadways and are not considered an enhanced investigation property. A portion of the Project Area comprises the former Orangeville-Brampton Rail line which is no longer operational. Operating records for the non-operational railway were not reviewed as it is the QP's opinion that such records cannot reasonably be expected to be available for a small closed section of a mainline railway.

5. SITE RECONNAISSANCE

A site reconnaissance of the Project Area was conducted to determine if any PCAs exist within the Project Area which would result in the identification of an APEC and to determine if potential contaminant pathways are present that could result in the presence of contaminants.

A written description documenting the observations and investigation of the Project Area and Study Area is provided in the following subsections.

5.1. GENERAL REQUIREMENTS

A summary of the general requirements of the site reconnaissance is provided in *Table 5-1*, below:

Table 5-1: Summary of General Requirements of the Site Reconnaissance

CRITERION	SUMMARY OF GENERAL DETAILS
DATE AND TIME	July 23, 2025, 12:30 – 16:30
WEATHER CONDITIONS	The temperature was approximately 42°C and weather conditions were clear.
LENGTH OF TIME	4 hours
WHETHER THE FACILITY WAS OPERATING AT THE TIME OF THE INVESTIGATION AS AN ENHANCED INVESTIGATION PROPERTY	At the time of the site reconnaissance, the Project Area was comprised of various municipal roadways and a former railway line. While railways are classified as enhanced investigation properties under O. Reg. 153/04, the line is no longer in operation. Operating records for the non-operational railway were not reviewed as it is the QP's opinion that such records cannot reasonably be expected to be available for a small closed section of a mainline railway. However, the absence of these records review is not considered a limitation to meeting the objectives of this assessment.
THE NAME AND QUALIFICATIONS OF THE INVESTIGATOR	The site reconnaissance was conducted by Ishita Patel. Ishita's qualifications are presented in Section 7.2.
LIMITATIONS	Due to the presence of significant weed overgrowth along some portions for the former rail line, physical inspection of the entire alignment was not feasible.

Select photographs taken during the Site reconnaissance, including a written description and explanation, are provided in Appendix C.

5.2. SPECIFIC OBSERVATIONS WITHIN THE PROJECT AREA

The reconnaissance included a visual inspection of the Project Area. A summary of the specific observations within the Project Area is provided in *Table 5-2*, below:

Table 5-2 Summary of Specific Observations within the Project Area

	CRITERION	SUMMARY OF SPECIFIC OBSERVATIONS
STRUCTURES	STRUCTURES AND OTHER IMPROVEMENTS, INCLUDING NUMBER AND AGE OF BUILDINGS AND BELOW-GROUND STRUCTURES	The Project Area is comprised of municipal roadways and a former railway and therefore does not contain any structures. It is noted that railway tracks remain in place along some portions of the former rail line while in other portions, the tracks have been removed.
	DETAILS OF ALL ASTS AND USTS, INCLUDING MATERIAL, METHOD OF CONSTRUCTION, AGE, CONTENTS, VOLUME, AND DETAILS OF USE	There was no evidence of ASTs or USTs observed within the Project Area during the site reconnaissance, including vent pipes, fill pipes, or soil depressions.
	POTABLE AND NON-POTABLE WATER SOURCES	As the Project Area is comprised of municipal roadways and a railway, it is not specifically serviced for water; however, the municipal roadways are underlain by watermains which supply surrounding neighbourhoods.
UTILITIES	UNDERGROUND UTILITIES AND CORRIDORS	Underground utilities and associated corridors are present at various locations within the roadways that comprise the Project Area. The presence of buried utilities along the railway line was not confirmed.
INTERIOR OF STRUCTURES	EXIT AND ENTRY POINTS	Not applicable, as the Project Area is comprised of municipal roadways and a former railway.
	DETAILS OF EXISTING AND FORMER HEATING AND COOLING SYSTEMS, INCLUDING FUEL SOURCE	Not applicable, as the Project Area is comprised of municipal roadways and a former railway.
	DETAILS OF DRAINS, PITS, AND SUMPS, INCLUDING CURRENT AND FORMER USE AND ANY EVIDENCED OF STAINING OR CORROSION	Not applicable, as the Project Area is comprised of municipal roadways and a former railways.
	DETAILS OF ANY UNIDENTIFIED SUBSTANCES	None identified.

	CRITERION	SUMMARY OF SPECIFIC OBSERVATIONS
MISCELLANEOUS	DETAILS AND LOCATIONS OF WELLS	No monitoring wells were observed during the reconnaissance.
	DETAILS OF SEWAGE WORKS, INCLUDING LOCATION	The portion of the Project Area occupied by municipal roadways contain buried storm and sanitary sewer lines and associated services for properties along the roadways.
	DETAILS OF GROUND SURFACE, INCLUDING TYPE OF COVER	The ground surface within the roadway portions of the Project Area generally comprises paved roadway with landscaped boulevards. The ground surface along the former rail line is generally gravel covered with some areas still containing rail tracks and other where the tracks have been removed. The overall rail line is generally overgrown with weeds.
	DETAILS OF CURRENT OR FORMER RAILWAYS LINES OR SPURS	As noted above, the former Orangeville-Brampton rail line comprises the north portion of the Project Area (south of Old School Road and north of Vodden Street) and additional rail spurs were identified in the central portion of the Project Area.
EXTERIOR OBSERVATIONS	AREAS OF STAINED SOIL, VEGETATION, OR PAVEMENT	No areas of stained soil, pavement, or vegetation were observed. The ground surface was wet due to inclement weather during the site reconnaissance so there is some inherent uncertainty.
	AREAS OF STRESSED VEGETATION	There was no evidence of stressed vegetation observed.
	AREAS WHERE FILL AND DEBRIS MATERIALS HAVE BEEN PLACED OR GRADED	Fill materials were not observed during the site reconnaissance; however, it is anticipated that fill materials were brought to the Project Area during the construction of the roadways, during repairs and/or during the installation of utilities and/or former rail line, as evidenced by the presence of gravel at surface along the railway line.
	POTENTIALLY CONTAMINATING ACTIVITY	The environmental quality of the above-mentioned fill anticipated to have been placed within the Project Area is not known (PCA 30). Further, it is anticipated that de-icing compounds are applied seasonally to the roadway portion of the Project Area for the purpose of vehicular safety (PCA E). The Orangeville-Brampton Railway was present in the north and central portion of the Project Area since 1856 (PCA 46.1).
	DETAILS OF UNIDENTIFIED SUBSTANCES	There were no unidentified substances observed within the Project Area.

5.3. OBSERVATIONS WITHIN THE STUDY AREA

The reconnaissance included a visual inspection of adjacent properties and properties located within the Study Area conducted from the boundary of the Project Area and from publicly accessible areas. A summary of the specific observations within the Study Area is provided in *Table 5-3*, below:

Table 5-3: Summary of Observations within the Study Area

CRITERION	SUMMARY OF OBSERVATIONS
ADJACENT LAND USES	Adjacent land uses relative to the Old School Road portion of the Project Area observed at the time of the site reconnaissance were noted as follows: North: Agricultural/ residential uses, South: Agricultural/ residential uses, East: Hurontario Street followed by agricultural land. West: Historical railway line followed by agricultural land. Adjacent land uses relative to the Orangeville Brampton Railway Portion of the Project Area observed at the time of the site reconnaissance were noted as follows: North: Agricultural/ residential uses, South: Primarily residential with some commercial uses. East: Industrial uses followed by residential uses. West: Residential and industrial uses. Adjacent land uses relative to the Bovaird Drive West Portion of the Project Area observed at the time of the site reconnaissance were noted as follows: North: Mix industrial and Commercial uses. South: Primarily residential uses. East: Primarily residential with some commercial uses. West: Mix industrial and Commercial uses. Adjacent land uses relative to the Kennedy Road Portion of the Project Area observed at the time of the site reconnaissance were noted as follows: North: Primarily residential with some commercial uses. South: A tributary of Etobicoke Creek, followed by commercial and community uses. East: Residential uses in the north and commercial uses in the south. West: Mixed industrial and Commercial uses. Adjacent land uses relative to the Queen Street Portion of the Project Area observed at the time of the site reconnaissance were noted as follows: North: Commercial uses followed by residential subdivisions. South: Primarily commercial uses. East: Commercial and/or industrial uses. West: Residential and commercial uses. A high-level summary of adjacent land uses is depicted on Figure 2A through Figure 2F.
POTENTIALLY CONTAMINATING ACTIVITY	Various commercial autobody shops and auto repair garages were observed north and south adjacent to the Project Area (PCA 10 and PCA 27). Various gasoline service stations were observed north and south adjacent to the Project Area (PCA 28). Various dry cleaners were observed within the Study Area (PCA 37). Agricultural fields were observed in the neighboring lands in the north portion of the Project Area. It is possible that pesticides were being used on these lands (PCA 40.1).

CRITERION	SUMMARY OF OBSERVATIONS
	The locations PCAs identified in the Study Area during the site reconnaissance are depicted on Figure 2A through Figure 2Fand further discussed in Table 1A through Table 1F, attached.
WATER BODIES	It is noted that the Project Area includes more than one (1) subwatershed. The north portion of the Project Area, just south of Old School Road (approximately half-way to Mayfield Road to the south) includes tributaries which feed into Etobicoke Creek, which generally flows southeast, east of - and approximately parallel to - Hurontario Street and crosses Vodden Street in the southern portion of the Project Area. The Project Area from north Mayfield Road to Vodden Street includes tributaries which feed into the Credit River subwatershed. Based on the size of the Project Area and the presence of numerous creeks and tributaries, the groundwater flow direction can only be confirmed through long-term groundwater monitoring.
AREAS OF NATURAL SIGNIFICANCE	Provincially significant wetland, CVC regulated areas and Greenbelt – Urban River Valley areas were identified to be surrounding the Etobicoke Creek and its tributaries both adjacent to and intersecting the Project Area

6. REVIEW AND EVALUATION OF INFORMATION

A review and evaluation of information gathered from the records review and site reconnaissance was conducted, as summarize in *Table 6-1*, below:

Table 6-1: Summary of a Review and Evaluation of Information gathered during the Study

CRITERION	SUMMARY OF REVIEW AND EVALUATION
POTENTIALLY CONTAMINATING ACTIVITY	PCAs identified within the Project Area and/or the Study Area, along with EnVision's assessment of the potential for these activities to impact the environmental quality of the Project Area are summarized in Table 1A through Table 1F, attached. PCAs, including the number and location of any ASTs and USTs (if known), are illustrated on Figure 2A through Figure 2F.
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN	Based on a review of the PCAs summarized in Table 2A through Table 2F, APECs were identified within the Project Area. The resulting APECs are depicted on Figure 3A through Figure 3F.

6.1. CONCEPTUAL SITE MODEL

Through analysis and interpretation of available information gathered during the Study, a CSM was developed for the Project Area, as depicted on Figure 2A through Figure 2F and Figure 3A through Figure 3F, attached, which includes:

- Existing buildings and structures within the Project Area;
- Roads, including names, within the Study Area;
- Uses of properties adjacent to the Project Area;
- Areas where PCAs have occurred, including the location of any tanks;
- Location of APECs;
- Water bodies located in whole, or in part, within the Study Area;
- Areas of natural significance located in whole, or in part, within the Study Area; and,
- Water wells within the Study Area.

7. CLOSING

7.1. CONCLUSIONS

Based on the information obtained through the Study, it was concluded that PCAs within the Project Area and within the Study Area resulted in the identification of 30 APECs within the Project Area, as outlined in detail in Table 2a through Table 2d.

Based on the APECs identified, associated COPCs in soil include metals and ORPs, PHCs, and BTEX, VOCs, PAHs, VOCs, ABNs and PCBs. Although not considered to be of significant concern, select sampling for organochlorine pesticides (OCs) (potentially associated with neighboring agricultural lands) is recommended as a conservative measure.

This Study was conducted to provide a general overview of the presence of potentially contaminating activities which could impact the environmental quality of soil or groundwater within the Project Area and to inform future investigations associated with the proposed infrastructure work. The scope of work associated with future investigations will be dependent on the design of the below grade infrastructure (i.e., particularly the depth). Once additional details regarding the design depth and location of the tunnel and shafts have been developed, an appropriate sampling and analysis plan can be completed to evaluate soil and/or bedrock quality for management under Ontario Regulation 406/19 and/or to evaluate groundwater quality for proper management/disposal during construction.

7.2. QUALIFICATIONS OF THE ASSESSORS

Ishita Patel, B.Sc., Project Coordinator

Ishita Patel is Project Coordinator with EnVision, with a strong background in environmental engineering. Ishita has 6 years of experience conducting environmental site assessments, including collecting soil, groundwater, and air samples, analyzing data, and reporting findings. Ishita has supported various projects involving remediation, risk assessment, excess soil management, Record of Site Condition (RSC) filing, and/or the conveyance of lands. She has demonstrated a proven ability to meet project goals while maintaining deadlines under circumstances involving multiple demands and conflicting priorities. Ishita's responsibilities include coordinating and conducting field activities, including borehole layout, supervising utility clearances, borehole drilling, and monitoring well installations, collecting soil and groundwater samples, sample management, and preliminary data analysis and reporting.

Maryanne Caluori, M.A.Sc., GIT, Project Manager – Environment

Maryanne Caluori is a Project Manager with EnVision Consultants Ltd. Maryanne has obtained a Bachelor of Science in Earth Sciences and a Master of Applied Science in Civil Engineering at McMaster University and is a Geoscientist-in-Training (GIT). Maryanne has four years of experience and has been involved in numerous environmental projects including Phase One and Phase Two Environmental Site Assessments (ESAs) in accordance with O. Reg. 153/04, as well as Excess Soil Management in accordance with O. Reg. 406/19. Maryanne has experience coordinating multidisciplinary projects,


maintaining, and tracking project schedules, overseeing, assisting with, and reviewing the execution of field services, as well as technical report writing.

Rodney Obdeyn, P.Eng., QP_{ESA}, Principal Engineer - Environment

Rodney Obdeyn is a Principal Engineer with EnVision Consultants Ltd., licensed in the Province of Ontario. Rodney obtained a Bachelor of Engineering Degree from McMaster University and has been involved with hundreds of Phase One and Phase wo Environmental Site Assessments for both private and public sector projects including residential, commercial, and industrial land uses as well as large infrastructure projects. He also possesses extensive experience in soil and groundwater remediation, Risk Assessment, Record of Site Conditions, and Excess Soil Management in accordance with O. Reg. 406/19 and is a Qualified Person (QP_{ESA}) under O. Reg. 153/04 and O. Reg 406/19.

7.3. SIGNATURES

Prepared by



Ishita Patel, B.Sc.
Project Coordinator – Environment
ipatel@envisionconsultants.ca

Reviewed by



Maryanne Caluori, M.A.Sc., GIT
Project Manager – Environment
mcaluori@envisionconsultants.ca

Reviewed by



Rodney Obdeyn, P.Eng., QP_{ESA}
Principal Engineer - Environment
robdeyn@envisionconsultants.ca

7.4. QUALIFIER

EnVision prepared this report solely for the use of the intended recipient in accordance with the professional services agreement. In the event a contract has not been executed, the parties agree that the EnVision General Terms and Conditions, which were provided prior to the preparation of this report, shall govern their business relationship.

The report is intended to be used in its entirety. No excerpts may be taken to be representative of the findings in the assessment. The conclusions presented in this report are based on work performed by

trained, professional and technical staff, in accordance with their reasonable interpretation of current and accepted engineering and scientific practices at the time the work was performed.

The content and opinions contained in the report are based on the observations and/or information available to EnVision at the time of preparation, using investigation techniques and engineering analysis methods consistent with those ordinarily exercised by EnVision and other engineering/scientific practitioners working under similar conditions, and subject to the same time, financial and physical constraints applicable to this project.

EnVision disclaims any obligation to update this report if, after the date of this report, any conditions appear to differ significantly from those presented in this report; however, EnVision reserves the right to amend or supplement this report based on additional information, documentation or evidence.

EnVision makes no other representations whatsoever concerning the legal significance of its findings. The intended recipient is solely responsible for the disclosure of any information contained in this report. If a third party makes use of, relies on, or makes decisions in accordance with this report, said third party is solely responsible for such use, reliance or decisions. EnVision does not accept responsibility for damages, if any, suffered by any third party as a result of decisions made or actions taken by said third party based on this report.

EnVision has provided services to the intended recipient in accordance with the professional services agreement between the parties and in a manner consistent with that degree of care, skill and diligence normally provided by members of the same profession performing the same or comparable services in respect of projects of a similar nature in similar circumstances. It is understood and agreed by EnVision and the recipient of this report that EnVision provides no warranty, express or implied, of any kind. Without limiting the generality of the foregoing, it is agreed and understood by EnVision and the recipient of this report that EnVision makes no representation or warranty whatsoever as to the sufficiency of its scope of work for the purpose sought by the recipient of this report.

In preparing this report, EnVision has relied in good faith on information provided by others, as noted in the report. EnVision has reasonably assumed that the information provided is correct and EnVision is not responsible for the accuracy or completeness of such information.

Unless otherwise agreed in writing by EnVision, the Report shall not be used to express or imply warranty as to the suitability of the site for a particular purpose. EnVision disclaims any responsibility for consequential financial effects on transactions or property values, or requirements for follow-up actions /or costs. This limitations statement is considered an integral part of this report.

8. REFERENCES

Environmental Risk Information Services (ERIS) 2024. ERIS Database Report, Bovaird HEIP, Brampton, ON. Requested by EnVision Consultants Ltd. on July 23, 2024.

Environmental Risk Information Services (ERIS) 2024. ERIS Database Report, Kennedy Rd HEIP, Brampton, ON. Requested by EnVision Consultants Ltd. on July 18, 2024.

Environmental Risk Information Services (ERIS) 2024. ERIS Database Report, Queen St (Centre to 410), Brampton, ON. Requested by EnVision Consultants Ltd. on July 23, 2024.

Environmental Risk Information Services (ERIS) 2025. ERIS Database Report, Kennedy STS, Brampton, ON. Requested by EnVision Consultants Ltd. on July 10, 2025

Google Earth (Google). 2019. Image © 2018 DigitalGlobe Image NASA.

Government of Ontario (Ontario). 2018. Brownfields Environmental Registry. https://www.ontario.ca/page/brownfields-redevelopment.

McGill University (McGill). 2001. The Canadian County Atlas Digital Project. http://digital.library.mcgill.ca/countyatlas/searchmapframes.php.

Ontario Ministry of the Environment, Conservation and Parks (MECP). 2010. Access Environment – Certificates of Approval. http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/GoSearch.action?search=basic.

Ontario Ministry of the Environment, Conservation and Parks (MECP). 2011. Ontario Regulation 153/04, as amended, Records of Site Condition – Part XV.1 of The Act, made under the Environmental Protection Act. July 1, 2011

Ontario Ministry of the Environment, Conservation and Parks (MECP). 2019. Ontario Regulation 406/19, as amended, On-Site and Excess Soil Management, made under the Environmental Protection Act. December 4, 2019.

Ontario Ministry of the Environment, Conservation and Parks (MECP). 2020. Rules for Soil Management and Excess Soil Quality Standards. December 8, 2020

Ontario Ministry of the Environment, Conservation and Parks (MECP). 2016a. Environmental Monitoring and Reporting Branch Well Records. https://www.ontario.ca/environment-and-energy/map-well-records.

Ontario Ministry of the Environment, Conservation and Parks (MECP). 2016b. Hazardous Waste Information Network. https://www.hwin.ca/hwin/index.jsp..

Ontario Ministry of the Environment, Conservation and Parks (MECP). 2016c. National Pollutant Release Inventory. https://www.ec.gc.ca/inrp-npri/.

Ontario Ministry of Natural Resources and Forestry (MNRF). 2008. Ontario Base Map Index. https://www.ontario.ca/data/ontario-base-map-index. =

Ontario Ministry of Natural Resources and Forestry (MNRF). 2015. Natural Heritage Areas. http://www.giscoeapp.lrc.gov.on.ca/Mamnh/Index.html?site=MNR_NHLUPS_NaturalHeritage&viewer=NaturalHeritage&locale=en-US..

Ontario Ministry of Northern Development and Mines (MNDM). 2016. Ontario Geological Society Maps. 2016

TABLES

Table 1A- Summary of Potentially Contaminating Activities (Old School Road Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Old School Road Portion of the Project Area.

Potentially Contaminating Activity		
30 .1	Importation of Fill Material of Unknown Quality	Project Area - It is anticipated that fill materials were brought to the Project Area during the construction of the roadway and/or during the installation of utilities. The environmental quality of the fill is not known (APEC 1).
40 .1	Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications	Study Area - Based on a review of aerial photographs and information obtained from the Site reconnaissance, agricultural fields were observed on neighboring lands of the Project Area. It is possible that these agricultural operations may have involved the use of pesticides; however, this is not considered a significant concern in relation to the proposed trunk sewere installation and, as such, is not considered to contribute to an APEC.
46 .1	Rail Yards, Tracks and Spurs	Project Area - The Orangeville-Brampton Railway was present in the western portion of the Project Area since 1856. (APEC 2)
A .1	Spills	Study Area - Based on review of the ERIS report, a spill of 50 L of diesel was reported on Hurontario Street approximately 100 m north of the Project Area. Due to distance form the Project Area and the small quantity, this PCA is not considered contributing to an APEC.
A .2	Spills	Project Area - Based on review of the ERIS report, various diesel spills (approximately 200 L and 500 L) were reported at the intersection of Hurontario Street and Old School Road, within the north portion of the Project Area. (APEC 3)
E .1	Application of De-Icing Compounds	Project Area - It is anticipated that de-icing compounds are applied to the Project Area seasonally for the purposes of vehicular safety. (APEC 4)

Notes:

1 - Potentially Contaminating Activity (PCA) means a use or activity set out in Column A of Table 2 of Schedule D of O.Reg 153/04

2 - A, B, C represent PCAs not specified in Table 2, Schedule D of O. Reg 153/04

3 - Red highlighting indicates that the PCA is considered contributing to an APEC

4 - PCAs have been made in reference to the Bovaird Portion of the Project Area.

Table 1B- Summary of Potentially Contaminating Activities (Orangeville Brampton Railway Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Orangeville Brampton Railway Portion of the Project Area.

Potentially Contaminating Activity		
10 .1	Commercial Autobody Shops	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance, Performance Collision Brampton, located at 105 Vankirk Drive, west adjacent of the Project Area was identified as an autobody repair facility. (APEC 5)
11 .1	Commercial Trucking and Container Terminals	Study Area - Based on review of the ERIS report, 190 Bovaird Drive, located in the east adjacent of the Project Area operated as a general freight trucking operation. (APEC 6)
12 .1	Concrete, Cement and Lime Manufacturing	Study Area - Based on review of the ERIS report, 225 Wanless Drive, located at the east adjacent of the Project Area was registered for the manufacturing of clay building material and refractory, brick, concrete, and concrete pipe brick and block. (APEC 7)
18 .1	Electricity Generation, Transformation and Power Stations	Study Area - Based on review of the ERIS report, Hydro One Brampton Networks Inc., located at 175 Sandalwood Parkway West, east adjacent of the Project Area was registered electricity power distribution company between 1992 to 2022. Operations included distribution lines and transformer stations, and dedicated generating stations. (APEC 8)
27 .1	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the ERIS report, an automotive service centre, located at 190 Bovaird Drive West was observed in the east adjacent of the Project Area. (APEC 6)
27 .2	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance, Attrell Hyundai, located at 100 Canam Crescent, west adjacent of the Project Area operated as a car dealership and an automotive service garage. (APEC 6)
27 .3	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance, Attrell Toyota, located at 110 Canam Crescent, west adjacent of the Project Area operated as a car dealership and an automotive service garage. (APEC 6)
27 .4	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the ERIS report, Brampton Transit maintenance facility was observed at 130 Sandalwood Parkway West, located in the east adjacent of the Project Area. (APEC 9)
27 .5	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the ERIS report, Brampton Go bus and Brampton Go service garage station and were located at 85 Van Kirk Drive, west adjacent of the Project Area. (APEC 5)

28 .1	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, a retail fuel storage tank was registered to Northwood Park Service Centre Inc., located at 190 Bovaird Drive West, east adjacent of the Project Area. (APEC 6)
28 .2	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, a retail fuel storage tank was registered to Butcher Engineering, located at 105 Vankirk Drive, west adjacent of the Project Area. The tank is inferred to be located adjacent to the building approximately 40 m west of the Project Area. (APEC 5)
28 .3	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, Brampton Hydro Electric/Hydro One Brampton Networks Inc., located at 175 Sandalwood Parkway West, east adjacent of the Project Area was registered under the retail fuel storage tank and fuel storage tank - historic databases for two (2) gasoline/diesel underground storage tanks (USTs). (APEC 8)
28 .4	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, Brampton Brick Limited and Roxy Construction Co Ltd., located at 225 Wanless Drive, east adjacent of the Project Area was registered under the private retail fuel storage tank, fuel storage tank and fuel storage tank - historic databases for two (2) fuel storage tank and two (2) diesel USTs. (APEC 7)
30 .1	Importation of Fill Material of Unknown Quality	Project Area - It is anticipated that fill materials were brought to the Project Area during the construction of the former railway line. The environmental quality of the fill is not known (APEC 1).
33 .1	Metal Treatment, Coating, Plating and Finishing	Study Area - Based on review of the ERIS report, The Peelle Company Limited, located at 195 Sandalwood Pky W, west adjacent of the Project Area was registered for metal window and door manufacturing between 1926 to 2022. (APEC 8)
33 .2	Metal Treatment, Coating, Plating and Finishing	Study Area - Based on review of the ERIS report, Butcher Engineering, located at 105 Vankirk Drive, west adjacent of the Project Area was registered for the manufacturing of transportation equipment. Operations included coating, engraving, heat treating and similarly processing metal, tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. (APEC 5)
34 .1	Metal Fabrication	Study Area - Based on review of the ERIS report, Sonco Steel Tube Ltd., located at 95 Vankirk Drive, west adjacent of the Project Area was registered as a steel pipe and tube fabrication company. (APEC 5)
34 .2	Metal Fabrication	Study Area - Based on review of the ERIS report, Dymin Steel Inc. located at 133 Van Kirk Drive, west adjacent of the Project Area was registered as a steel fabrication company. (APEC 8)

40 .1	Pesticides (including Herbicides, Fungicides and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage and Large-Scale Applications	Study Area - Based on a review of aerial photographs and information obtained from the Site reconnaissance, agricultural fields were observed in the north portion of the neighboring lands of the Project Area. It is possible that these agricultural operations may have involved the use of pesticides; however, this is not considered a significant concern in relation to the proposed trunk sewer installation and as such is not considered to contribute to an APEC.
43 .1	Plastics (including Fibreglass) Manufacturing and Processing	Study Area - Based on review of the ERIS report, Industrial Thermo Polymers Ltd. located at 153 Van Kirk Drive , west adjacent of the Project Area was registered for Plastic Film and Sheet Manufacturing, All Other Plastic Product Manufacturing, Doll, Toy and Game Manufacturing, Urethane and Other Foam Product (except Polystyrene) Manufacturing and Polystyrene Foam Product Manufacturing. (APEC 8)
43 .2	Plastics (including Fibreglass) Manufacturing and Processing	Study Area - Based on review a review of google satellite imagery and information obtained from the Site reconnaissance, Metelix Products Inc., located at 95 Vankirk Drive, west adjacent of the Project Area was registered as a plastic blow-moulding manufacturer. (APEC 5)
46 .1	Rail Yards, Tracks and Spurs	Project Area - The Orangeville Brampton Railway and associated spurs were present in the north and central portion of the Project Area since 1856. (APEC 2)
58 .1	Waste Disposal and Waste Management, including thermal treatment, landfilling and transfer of waste, other than use of biosoils as soil conditioners	Study Area - Based on review of the ERIS report, satellite imagery and information obtained from the Site reconnaissance, Region of Peel, located at 420 Railside Drive was registered as a recycling centre. The operation building is located 135 m east of the Project Area. Due to distance from the Project Area, this PCA was not considered to be contributing to an APEC.
58 .2	Waste Disposal and Waste Management, including thermal treatment, landfilling and transfer of waste, other than use of biosoils as soil conditioners	Study Area - Based on review of the ERIS report, Safety-Kleen (On-Site) Inc. located at 175 Sandalwood Parkway West, east adjacent of the Project Area was registered as a Class 2 mobile PCB destruction facility in 2001. The ERIS report indicated that the Site can process up to 10,000 litres of PCB-contaminated mineral oil. (APEC 8)
A .3	Spills	Study Area - Based on review of the ERIS report, a spill of ammonia and gasoline mixture was reported at 194 Ecclestone Drive, approximately 100 m east of the Project Area. Due to distance and small quantity, this PCA is not considered to be contributing to an APEC.
A .4	Spills	Study Area - Based on review of the ERIS report, two (2) 50 L spills of engine oil were reported at 110 Canam Crescent, located 50 m west of the Project Area. Due to distance and small quantity, this PCA is not considered to be contributing to an APEC.

A .5	Spills	Study Area - Based on review of the ERIS report, a 50 L varsol spill, a 250 L spill of tar and water mix, and a 200L petroleum based oil spill were reported at located at 95 Vankirk Drive, west adjacent of the Project Area (APEC 5)
A .6	Spills	Study Area - Based on review of the ERIS report, a 50 L paint or paint related N.O.S spill was reported to Butcher Engineering located at 105 Vankirk Drive, west adjacent of the Project Area. Due to the small quantity of this spill, this PCA is not consider contributing to an APEC. (APEC 5)
A .7	Spills	Study Area - Based on review of the ERIS report, a 150 L transformer oil spill was reported to Alectra Utilities located at 440 Railside Drive, east adjacent of the Project Area. Based on information obtained from the Site reconnaissance, the spill likely occurred in the vicinity of the transformer which located along Railside Drive approximately 175 m east of the Project Area. Due to distance from the Project Area, this PCA is not considered to be contributing to an APEC.
A .8	Spills	Study Area - Based on review of the ERIS report, approximately 0.5 L turbine lubricant oil spill was reported at 153 Vankirk Drive located in the west adjacent of the Project Area. Due to the small quantity, this PCA was not considered to be contributing to an APEC.
A .9	Spills	Study Area - Based on review of the ERIS report, various spills including approximately 40-50 L of diesel fuel oil, approximately 50 L of gasoline, approximately 900 L of glycol and water mix, and approximately 160 L of transformer were reported to Hydro One Brampton Networks Inc. located at 175 Sandalwood Pky W, east adjacent of the Project Area. (APEC 8)
A .10	Spills	Study Area - Based on review of the ERIS report, a spill of approximately 20 L of hydraulic oil was reported at 156 Twin Pine Crescent, located in the west adjacent of the Project Area. Due to the limited quantity, this PCA was not considered to be contributing to an APEC.
A .11	Spills	Study Area - Based on review of the ERIS report, various spills including approximately 2300 L of diesel fuel, approximately 15 L motor oil, and approximately 15 L of hydraulic oil were reported at 225 Wanless Drive located at the east adjacent of the Project Area. (APEC 7)
B .1	PCB Storage Site	Study Area - Based on review of the ERIS report, Hydro One Brampton Networks Inc. located at 175 Sandalwood Parkway West, east adjacent of the Project Area was registered for PCB storage between 1995 to 2004. (APEC 8)

Notes:

1 - Potentially Contaminating Activity (PCA) means a use or activity set out in Column A of Table 2 of Schedule D of O.Reg 153/04

2 - A, B, C represent PCAs not specified in Table 2, Schedule D of O. Reg 153/04

3 - Red highlighting indicates that the PCA is considered contributing to an APEC

4 - PCAs have been made in reference to the Bovaird Portion of the Project Area.

Table 1C- Summary of Potentially Contaminating Activities (Bovaird Drive West Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Bovaird Drive West Portion of the Project Area.

Potentially Contaminating Activity		
27 .6	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance, Brampton Chrysler Dodge Jeep Ram located at 190 Canam Crescent, north adjacent of the Project Area operated as a car dealership and an automotive service garage. The automotive service centre is located approximately 75 m north of the Project Area. Due to the distance from the Project Area, this PCA was not considered to be contributing to an APEC.
27 .7	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance an automotive service centre was located inside the Canadian Tire, at 10031 McLaughlin Road, north adjacent of the Project Area. The service centre was located approximately 150 m north of the Project Area. Due to the distance from the Project Area, this PCA was not considered to be contributing to an APEC.
.5 28 .6 .7	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, google satellite imagery and information obtained from the Site reconnaissance, gasoline service stations have been located at 9950, 10010, and 10021 McLaughlin Road, north and south of the Project Area since the early 2000s. Each gas station was listed with at least three (3) USTs, both gasoline and diesel. (APEC 10)
30 .1	Importation of Fill Material of Unknown Quality	Project Area - It is anticipated that fill materials were brought to the Project Area during the construction of the roadway and/or during the installation of utilities. The environmental quality of the fill is not known (APEC 1).
E .1	Application of De-Icing Compounds	Project Area - It is anticipated that de-icing compounds are applied to the Project Area seasonally for the purposes of vehicular safety. (APEC 4)

Notes:

1 - Potentially Contaminating Activity (PCA) means a use or activity set out in Column A of Table 2 of Schedule D of O.Reg 153/04

2 - A, B, C represent PCAs not specified in Table 2, Schedule D of O. Reg 153/04

3 - Red highlighting indicates that the PCA is considered contributing to an APEC

4 - PCAs have been made in reference to the Bovaird Portion of the Project Area.

Table 1D- Summary of Potentially Contaminating Activities (Vodden Street Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Vodden Street Portion of the Project Area.

Potentially Contaminating Activity		
27 .8	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the ERIS report, an oil change and lubrication service, Perfect Lube, was listed at 121 Kennedy Road North, west adjacent to the Project Area. (APEC 11)
28 .8	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconassiance, a gasoline service station, ESSO, has been located at 140 Kennedy Road North, east adjacent to the Project Area since as early as 1981, and was listed with five (5) gasoline and one (1) diesel USTs. (APEC 11)
28 .9	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconassiance during the site reconnaissance, a gas station, Petro Canada, has been located at 121 Kennedy Road North, west adjacent to the Project Area since as early as 2003, and was listed with three (3) gasoline and one (1) diesel USTs. (APEC 11)
30 .1	Importation of Fill Material of Unknown Quality	Project Area - It is anticipated that fill materials were brought to the Project Area during the construction of the roadway and/or during the installation of utilities. The environmental quality of the fill is not known (APEC 1).
58 .3	Waste Disposal and Waste Management, including thermal treatment, landfilling and transfer of waste, other than use of biosoils as soil conditioners	Study Area - Based on review of the ERIS report, a suspected dump was identified at the former Dale Estate, now located at 36 Vodden Street East. The ERIS report also noted that fires occurred at the site in both 1963 and 1971. According to an online article '*The Flowertown of Canada*' , the Dale Estate operated as a greenhouse business, where local residents could collect discarded flowers and plants that did not meet the company's quality standards. The dump site was not a formal landfill, but rather an area designated for disposing of excess plant material. The property has since been redeveloped into a commercial building. Based on the types of waste generated at the property as well as the redevelopment of the property, this PCA is not considered to be contributing to an APEC.
A .12	Spill	Study Area - Based on review of the ERIS report, a spill of approximately 2L of non-PCB oil was reported on the grass near the transformer box located at 47 Vodden Street East, south adjacent of the Project Area. The ERIS report noted that the spill was contained and cleaned. Based on the clean up measures taken as well as the minimal spill volume, this spill is not anticipated to be contributing to an APEC.
A .13	Spill	Study Area - Based on review of the ERIS report, a spill of approximately 50 L of mineral oil was reported at 36 Newby Court, approximately 55 m north of the Project Area. Due to distance from the Project Area, this spill is not considered to be contributing to an APEC.

E .1	Application of De-Icing Compounds	Project Area - It is anticipated that de-icing compounds are applied to the Project Area seasonally for the purposes of vehicular safety. (APEC 4)

Notes:

1 - Potentially Contaminating Activity (PCA) means a use or activity set out in Column A of Table 2 of Schedule D of O.Reg 153/04

2 - A, B, C represent PCAs not specified in Table 2, Schedule D of O. Reg 153/04

3 - Red highlighting indicates that the PCA is considered contributing to an APEC

4 - PCAs have been made in reference to the Bovaird Portion of the Project Area.

Table 1E- Summary of Potentially Contaminating Activities (Kennedy Road North/South Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Kennedy Road Portion of the Project Area.

Potentially Contaminating Activity		
2 .1	Adhesives and Resins Manufacturing, Processing and Bulk Storage	Study Area - Based on review of the ERIS report, an adhesive manufacturing facility, Mactac Canada Ltd., (and LTEE) has been located at 100 Kennedy Road South, east adjacent to the Project Area, since 1936. (APEC 12)
10 .2	Commercial Autobody Shops	Study Area - Based on review of google satellite imagery, an auto body shop, Able Auto Body, is located at 77 Kennedy Road South, west adjacent to the Project Area. (APEC 13)
27 .8	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the ERIS report, an oil change and lubrication service, Perfect Lube, was listed at 121 Kennedy Road North, west adjacent to the Project Area. (APEC 11)
27 .9	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance, auto service garages were located at 20 Kennedy Road South and 60 Eastern Avenue, east adjacent to the Project Area. (APEC 21)
27 .10	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance during the site reconnaissance, a gas station, Pauto service garages were located at 22 and 28 Kennedy Road South, east adjacent to the Project Area (APEC 20)
27 .11	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of Google Maps, Peel Auto Centre was located at 149 Clarence Street, west adjacent to the Project Area. (APEC 13)
27 .12 .13 .17 .21	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of Google Maps, various auto service garages have been located east adjacent (84 Kennedy Road South) and west adjacent (91, 95, and 99 Kennedy Road South) of the Project Area. (APEC 12)

Table 1E- Summary of Potentially Contaminating Activities (Kennedy Road North/South Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Kennedy Road Portion of the Project Area.

Potentially Contaminating Activity		
27 .14 .15 .18	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of Google Maps, various auto service garages have been located east adjacent (110 and 126 Kennedy Road South) and west adjacent (117 Kennedy Road South) of the Project Area. (APEC 14)
27 .16	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of Google Maps, an auto service garage, Thrive Auto Collision, was located at 134 Kennedy Road South, east adjacent to the Project Area. (APEC 15)
27 .19	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of Google Maps and observations during the site reconnaissance, an auto service garage was located at the Husky gas station at 253 Kennedy Road South, west adjacent to the Project Area. (APEC 16)
27 .20	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review RSC #224471, an auto service garage, AJ Trust Auto, was located at 38 Dean Street, approximately 80 m west of the Project Area. Due to distance, this PCA was not considered to be contributing to an APEC.
28 .8	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance, a gasoline service station, ESSO, has been located at 140 Kennedy Road North, east adjacent to the Project Area since as early as 1981, and was listed with five (5) gasoline and one (1) diesel USTs. (APEC 11)
28 .9	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the google satellite imagery and information obtained from the Site reconnaissance during the site reconnaissance, a gas station, Petro Canada, has been located at 121 Kennedy Road North, west adjacent to the Project Area since as early as 2003, and was listed with three (3) gasoline and one (1) diesel USTs. (APEC 11)
28 .10	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, a diesel UST was formerly listed at Parkinson Coach Lines George Murray located at 10 Kennedy Road South, east adjacent to the Project Area in 1982. The exact location of the UST is not known. (APEC 19)

Table 1E- Summary of Potentially Contaminating Activities (Kennedy Road North/South Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Kennedy Road Portion of the Project Area.

Potentially Contaminating Activity		
28 .11	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, Shell Canada Products was listed at 230 Queen Street East, west adjacent to the Project Area with waste oil and bulk oil tanks. (APEC 19)
28 .12	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, two (2) gasoline and two (2) diesel USTs were listed at Mel and Auto Centre Inc., located at 18 Kennedy Road South, east adjacent to the Project Area in 1980. (APEC 21)
28 .13	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, one (1) diesel UST was located at 32 Kennedy Road South, east adjacent to the Project Area, formerly GMF Transport (1981) and currently Maple Leaf Poultry. The location and specifications of the tank is not known. (APEC 22)
28 .14	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, one (1) gasoline and one (1) diesel USTs were listed at Budget Rent-A-Car located at 73 Kennedy Road South, west adjacent to the Project Area, in 1984. (APEC 13)
28 .15	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, a gas station, formerly Parkland Corp. and currently Husky, is located at 253 Kennedy Road South, west adjacent to the Project Area. The gas station was listed with three (3) gasoline and one (1) diesel USTs. (APEC 16)
28 .16	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, a gas station, formerly Mac's Convenience as early as 1985 and now currently ESSO was listed with at least three (3) gasoline and one (1) diesel USTs at 7995 Kennedy Road South, east adjacent to the Project Area. (APEC 17)
30 .1	Importation of Fill Material of Unknown Quality	Project Area - It is anticipated that fill materials were brought to the Project Area during the construction of the roadway and/or during the installation of utilities. The environmental quality of the fill is not known (APEC 1).
37 .1	Operation of Dry Cleaning Equipment (where chemicals are used)	Study Area - Based on review of the ERIS report, a dry cleaners, Premier Cleaners was located at 144 Kennedy Road South, east adjacent to the Project Area between 1988 and 2007. (APEC 18)

Table 1E- Summary of Potentially Contaminating Activities (Kennedy Road North/South Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Kennedy Road Portion of the Project Area.

Potentially Contaminating Activity		
37 .2	Operation of Dry Cleaning Equipment (where chemicals are used)	Study Area - Based on review of Google Maps, a dry cleaners, Total Laundry Care, was located at 30 Rambler Drive, approximately 40 m west of the Project Area. (APEC 23)
37 .3	Operation of Dry Cleaning Equipment (where chemicals are used)	Study Area - Based on review of the ERIS report, a dry cleaners, Tony's Custom Cleaners, was located at 400 Steeles Avenue East, wets adjacent to the Project Area between 1986 and 1998. (APEC 17)
37 .4	Operation of Dry Cleaning Equipment (where chemicals are used)	Study Area - Based on review of RSC #224471, a dry cleaners, was formerly located at 44 Deans Street, approximately 60 m west of the Project Area. (APEC 14)
43 .1	Plastics (including Fibreglass) Manufacturing and Processing	Study Area - Based on review of the ERIS report, a plastic manufacturing facility, AT Plastics Inc. was located at 134 and 142 Kennedy Road South, east adjacent to the Project Area between 1986 and 2011. This property was also listed for PCB storage. (APEC 15)
43 .2	Plastics (including Fibreglass) Manufacturing and Processing	Study Area - Based of review of RSC #224471, a plastic manufacturing facility was identified at 107 Kennedy Road South, west adjacent to the Project Area. (APEC 14)
46 .2	Rail Yards, Tracks and Spurs	Project Area - The Toronto and Goderich Railway intersects the central area of the Kennedy Road Portion of the Project Area since 1856. Although the railway currently is orientated above the roadway (Kennedy Road South), it is suspected that the railway was once at grade. (APEC 27)
51 .1	Solvent Manufacturing, Processing and Bulk Storage	Study Area - Based on review of the ERIS report, a solvent UST was registered to AT Plastics Inc. was located at 134 and 142 Kennedy Road South, east adjacent to the Project Area. The exact location of the UST is not known. (APEC 15)
51 .2	Solvent Manufacturing, Processing and Bulk Storage	Study Area - Based of review of RSC #224471, a former solvent handling facility was identified at 109 Kennedy Road South, at least 50 m west of the Project Area. (APEC 14)

Table 1E- Summary of Potentially Contaminating Activities (Kennedy Road North/South Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Kennedy Road Portion of the Project Area.

Potentially Contaminating Activity		
51 .3	Solvent Manufacturing, Processing and Bulk Storage	Study Area - Based on review of the ERIS report, a paint dip tank for the application of solvents was identified at the automotive manufacturing facility, Arvin Meritor Canada, located at 350 First Gulf Boulevard, east adjacent to the Project Area. (APEC 24)
52 .1	Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems	Study Area - Based on review of the ERIS report, an equipment repair facility, Stephenson's Rent-all Inc., was located at 26 Kennedy Road South, east adjacent to the Project Area. (APEC 20)
55 .1	Transformer Manufacturing, Processing and Use	Study Area - Based on observations during the site reconnaissance, a transformer was noted to be located on the boulevard between Kennedy Road South and the gas station at 7995 Kennedy Road South, east adjacent to the Project Area. (APEC 17)
57 .1	Vehicles and Associated Parts Manufacturing	Study Area - Based on review of the ERIS report, a motor vehicle body manufacturing facility, Grumman Olson Industries Inc., was located at 30 Kennedy Road South, east adjacent to the Project Area in 1970. (APEC 20)
57 .2	Vehicles and Associated Parts Manufacturing	Study Area - Based on review of the ERIS report, an automotive manufacturing facility, Arvin Meritor Canada, was located at 350 First Gulf Boulevard, east adjacent to the Project Area between at least 2004 and 2016. (APEC 24)
A .14	Spills	Study Area - Based on review pf the ERIS report, a solvent UST described to be below the water table, had leaked at 134 Kennedy Road South, east adjacent to the Project Area. The exact location of the UST is not known. (APEC 15)
A .15	Spills	Study Area - Based on review of the ERIS report, a spill of perchloroethylene to the ground and catch basin was reported at 144 Kennedy Road, east adjacent to the Project Area. (APEC 18)

Table 1E- Summary of Potentially Contaminating Activities (Kennedy Road North/South Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Kennedy Road Portion of the Project Area.

Potentially Contaminating Activity		
A .16	Spills	Study Area - Based on review of the ERIS report, a 91 L spill of diesel was reported to have spilled from a transport truck to the ground at 174 Kennedy Road South, east adjacent to the Project Area. Due to the unknowns about the location of the spill, the spill is considered to be contributing to an APEC as a conservative measure. (APEC 16)
A .17	Spills	Project Area - Based on review of the ERIS report, various diesel spills (greater than 150 L) were reported at the intersection of Kennedy Road South and Steeles Avenue East within the Project Area. (APEC 17)
A .18	Spills	Study Area - Based on review of the ERIS report, a spill of non-PCB mineral oil was reported by Electra Utilities Corp. at 78 Hartford Trail, approximately 75 m west of the Project Area. Due to distance, this PCA is not considered to be contributing to an APEC.
B .1	PCB Storage Site	Study Area - Based on review of the ERIS report, Canada Cup Inc. located at 228 Queen Street East, approximately 50 m west of the Project Area was listed as a PCB storage site. Due to the distance from the Project Area, the fact that the site is registered for PCB storage and there are no spill reports associated with this site, this PCA is not considered to be contributing to an APEC.
B .2	PCB Storage Site	Study Area - Based on review of the ERIS report, AT Plastics Inc. located at 134 and 142 Kennedy Road South, east adjacent to the Project Area was registered as a PCB storage site between 1990 and 1996. This property was identified as PCA 43.1 related to plastic manufacturing and considered to contribute to APEC 58. While impacts related to PCB storage is not considered likely, PCBs have been added as a COPC to (APEC 15)
B .3	PCB Storage Site	Study Area - Based on review of the ERIS report, AT Plastics Inc. located at 174 Kennedy Road South, east adjacent to the Project Area was registered as a PCB storage site between 1992 to 2008. (APEC 16)
C .1	Miscellaneous Manufacturing	Study Area - Based on review of the ERIS report, various manufacturing operations ere listed at 110 and 114 Kennedy Road South, east adjacent to the Project Area, including Peel Fence Systems Inc., and The Door Factory II, with waste generation records. (APEC 14)

Table 1E- Summary of Potentially Contaminating Activities (Kennedy Road North/South Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Kennedy Road Portion of the Project Area.

Potentially Contaminating Activity		
C .2	Miscellaneous Manufacturing	Study Area - Based on review of the ERIS report, a Tabacco manufacturing facility, Benson & Hedges Ltd., with various waste generation records, including halogenated solvents, petroleum distillates, and paints/pigments/coatings, was located at 174 Kennedy Road South between 1961 and 2014. This property was also listed a PCB storage site. (APEC 16)
C .3	Miscellaneous Manufacturing	Study Area - Based on review of the ERIS report, T.S.T. Enterprises, was listed for Showcase, Partition, Shelving and Locker Manufacturing, Sign Manufacturing, and All Other Miscellaneous Chemical Product Manufacturing, at 365 Kennedy Road South, west adjacent to the Study Area. (APEC 25)
D .1	Welding or Machine Shop	Study Area - Based on review of the ERIS report, a machine shop, E J Machine Co Ltd., was located at 158 Kennedy Road South, east adjacent to the Project Area. (APEC 26)
E .1	Application of De-Icing Compounds	Project Area - It is anticipated that de-icing compounds are applied to the Project Area (all six (6) portions) seasonally for the purposes of vehicular safety. (APEC 5)

Notes:

1 - Potentially Contaminating Activity (PCA) means a use or activity set out in Column A of Table 2 of Schedule D of O.Reg 153/04

2 - A, B, C represent PCAs not specified in Table 2, Schedule D of O. Reg 153/04

3 - Red highlighting indicates that the PCA is considered contributing to an APEC

4 - PCAs have been made in reference to the Bovaird Portion of the Project Area.

Table 1F- Summary of Potentially Contaminating Activities (Queen Street East Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Queen Street Portion of the Project Area.

Potentially Contaminating Activity		
10 .3	Commercial Autobody Shops	Study Area - Based on review of RSC #224566, an autobody shop with a spray booth was listed at 241 Queen Street East, south adjacent to the Project Area. Based on RSC #224566, a Phase Two was conducted on the property and identified PHC impacts within the autobody shop. A remedial excavation was completed on the property which concluded in confirmatory samples that met the applicable SCS, around the formerly impacted area. As such, the PCA is considered to have been investigated and is not considered to be contributing to an APEC for the Project Area.
10 .4	Commercial Autobody Shops	Study Area - Based on review of google satellite imagery, an auto body shop was located within the Ford auto sales business at 300 Queen Street East, north adjacent to the Project Area. (APEC 28)
27 .22	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of RSC #224566, an auto service garage was listed at 241 Queen Street East, south adjacent to the Project Area. Based on RSC #224566, a Phase Two was conducted on the property and identified PHC impacts within the auto service garage area. A remedial excavation was completed on the property which concluded in confirmatory samples that met the applicable SCS, around the formerly impacted area. As such, the PCA is considered to have been investigated and is not considered to be contributing to an APEC for the Project Area.
27 .23	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of Google Maps, an auto service garage, Speedy Auto, is located at 251 Queen Street East, south adjacent to the Project Area. (APEC 28)
27 .24	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	Study Area - Based on review of Google Maps, an auto service garage, Auto Park, is located at 320 Queen Street East, north adjacent to the Project Area. (APEC 29)
28 .10	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, a diesel UST was formerly listed at Parkinson Coach Lines George Murray located at 10 Kennedy Road South, approximately 50 m north of the Project Area in 1982. The exact location of the UST is not known. (APEC 19)
28 .11	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, Shell Canada Products was listed at 230 Queen Street East, north adjacent to the Project Area with waste oil and bulk oil tanks. (APEC 19)

Table 1F- Summary of Potentially Contaminating Activities (Queen Street East Portion)

(Refer to Table 2, Schedule D, O. Reg. 153/04)

PCAs have been made in reference to the Queen Street Portion of the Project Area.

Potentially Contaminating Activity		
28 .17	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, Canadian Tire Corp. Ltd., located at 252 Queen Street East, north adjacent to the Project Area was registered with five (5) gasoline and four (4) other USTs, which were installed as early as 1992. Although, evidence of a gas station was not observed in the aerial photographs at this location, the PCA is considered to contribute to an APEC as a conservative measure. (APEC 30)
28 .18	Gasoline and Associated Products Storage in Fixed Tanks	Study Area - Based on review of the ERIS report, one (1) gasoline and one (1) waste oil USTs were listed at John Logan Chevrolet Olds Inc., located at 241 Queen Street East, south adjacent to the Project Area, installed in 1984. Based on RSC #224566, soil and groundwater were tested in the vicinity of the tanks and no impacts were found. As such, the PCA is considered to have been investigated and is not considered to be contributing to an APEC for the Project Area.
30 .1	Importation of Fill Material of Unknown Quality	Project Area - It is anticipated that fill materials were brought to the Project Area (all six (6) portions) during the construction of the roadway and/or during the installation of utilities. The environmental quality of the fill is not known (APEC 1).
34 .3	Metal Fabrication	Study Area - Based on review of the ERIS report, a metal fabrication facility, Amsco Canada Ltd. was listed at 255 Queen Street East, south adjacent to the Project Area, between at least 1986 and 1998. (APEC 28)
B .1	PCB Storage Site	Study Area - Based on review of the ERIS report, Canada Cup Inc. located at 228 Queen Street East, approximately 50 m west of the Project Area was listed as a PCB storage site. Due to the distance from the Project Area and the low mobility of PCBs, this PCA is not considered to be contributing to an APEC.
E .1	Application of De-Icing Compounds	Project Area - It is anticipated that de-icing compounds are applied to the Project Area (all six (6) portions) seasonally for the purposes of vehicular safety. (APEC 4)

Notes:

1 - Potentially Contaminating Activity (PCA) means a use or activity set out in Column A of Table 2 of Schedule D of O.Reg 153/04

2 - A, B, C represent PCAs not specified in Table 2, Schedule D of O. Reg 153/04

3 - Red highlighting indicates that the PCA is considered contributing to an APEC

4 - PCAs have been made in reference to the Bovaird Portion of the Project Area.

Table 2A - Areas of Potential Environmental Concern (Old School Road Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Entire Project Area	30	Importation of Fill Material of Unknown Quality	on-site	M&ORPs, PHCs & BTEX, PAHs	Soil
APEC 2	West portion of the Project Area	46	Rail Yards, Tracks and Spurs	on-site	M&ORPs, PAHs, OCs, PCBs	Soil
APEC 3	East portion of the Project Area	A	Spills	on-site	PHCs, BTEX, VOCs	Soil
APEC 4	Entire Project Area	E	Application of De-Icing Compounds	on-site	electrical conductivity, SAR	Soil

Notes:

1 - Area of Potential Environmental Concern means the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through,
(a) identification of past or present uses on, in or under the phase one property, and
(b) identification of potentially contaminating activity.

2 - Potentially Contaminating Activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3 - When completing this column, identify all contaminants of potential concern using the Method Groups as identified in the Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:

ABNs - Acid Base Neutral Compounds
CPs - Chlorophenyls
1, 4 - Dioxane
Dioxins/Furans, PCDDs/PCDFs
OCs - Organochlorine Pesticides
PHCs - Petroleum Hydrocarbons
PCBs - Polychlorinated Biphenyls
PAHs - Polycyclic Aromatic Hydrocarbons
THMs - Trihalomethanes
VOCs - Volatile Organic Compounds
BTEX - Benzene, Toluene, Ethylbenzene, Xylenes
Ca, Mg - Calcium, Magnesium
Metals
As, Sb, Se - Arsenic, Antimony, Selenium
Electrical Conductivity
B-HWS - Boron (Hot Water Soluable)
Cr (VI) - Hexavalent Chromium
SAR - Sodium Adsorption Ratio
Na - Sodium
CN^- - Cyanide
Hg - Mercury
Methyl Mercury
High/Low pH

Table 2B - Areas of Potential Environmental Concern (Orangeville Brampton Railway Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Entire Project Area	30	Importation of Fill Material of Unknown Quality	on-site	M&ORPs, PHCs, BTEX, PAHs	Soil
APEC 2	Entire Project Area	46	Rail Yards, Tracks and Spurs	on-site	M&ORPs, PAHs, OCs, PCBs	Soil
APEC 5	South of Sandalwood Parkway West	10	Commercial Autobody Shops	off-site	M&ORPs, PHCs, BTEX, VOCs	Soil
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		33	Metal Treatment, Coating, Plating and Finishing		PHCs, BTEX, VOCs,	
		34	Metal Fabrication		PHCs, BTEX, sVOCs	
		43	Plastics (including Fibreglass) Manufacturing and Processing		PHCs, BTEX, VOCs, sVOCs	
		A	Spills		PHCs, BTEX, VOCs	
APEC 6	North of Bovaird Drive West	11	Commercial Trucking and Container Terminals	off-site	M&ORPs, PHCs, BTEX, PAHs	Soil
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	

Table 2B - Areas of Potential Environmental Concern (Orangeville Brampton Railway Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 7	South of Wanless Drive	12	Concrete, Cement and Lime Manufacturing	off-site	M&ORPs, PHCs, BTEX	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		A	Spills		PHCs, BTEX, VOCs	
APEC 8	South of Sandalwood Parkway West	18	Electricity Generation, Transformation and Power Stations	off-site	M&ORPs, PHCs, BTEX, VOCs, PCBs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		33	Metal Treatment, Coating, Plating and Finishing		PHCs, BTEX, VOCs,	
		34	Metal Fabrication		PHCs, BTEX, sVOCs	
		43	Plastics (including Fibreglass) Manufacturing and Processing		PHCs, BTEX, , VOCs, sVOCs	
		58	Waste Disposal and Waste Management, including thermal treatment, landfilling and transfer of waste, other than use of biosoils as soil conditioners		PCBs	
		A	Spills		PHCs, BTEX, VOCs	
		B	PCB Storage Site		PCBs	
APEC 9	North of Sandalwood Parkway West	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPS, PHCs, BTEX, VOCs, PAHs	Soil

Notes:

1 - Area of Potential Environmental Concern means the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through,

(a) identification of past or present uses on, in or under the phase one property, and

(b) identification of potentially contaminating activity.

2 - Potentially Contaminating Activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3 - When completing this column, identify all contaminants of potential concern using the Method Groups as identified in the Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:

ABNs - Acid Base Neutral Compounds
CPs - Chlorophenyls
1, 4 - Dioxane
Dioxins/Furans, PCDDs/PCDFs
OCs - Organochlorine Pesticides
PHCs - Petroleum Hydrocarbons
PCBs - Polychlorinated Biphenyls
PAHs - Polycyclic Aromatic Hydrocarbons
THMs - Trihalomethanes
VOCs - Volatile Organic Compounds
BTEX - Benzene, Toluene, Ethylbenzene, Xylenes
Ca, Mg - Calcium, Magnesium
Metals
As, Sb, Se - Arsenic, Antimony, Selenium
Electrical Conductivity
B-HWS - Boron (Hot Water Soluable)
Cr (VI) - Hexavalent Chromium
SAR - Sodium Adsorption Ratio
Na - Sodium
CN^- - Cyanide
Hg - Mercury
Methyl Mercury
High/Low pH

Table 2C - Areas of Potential Environmental Concern (Bovaird Drive West Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Entire Project Area	30	Importation of Fill Material of Unknown Quality	on-site	M&ORPs, PHCs, BTEX, PAHs	Soil
APEC 4	Entire Project Area	E	Application of De-Icing Compounds	on-site	electrical conductivity, SAR	Soil
APEC 10	East and west of McLaughlin Road North	28	Gasoline and Associated Products Storage in Fixed Tanks	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil

Notes:

1 - Area of Potential Environmental Concern means the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through,
(a) identification of past or present uses on, in or under the phase one property, and
(b) identification of potentially contaminating activity.

2 - Potentially Contaminating Activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3 - When completing this column, identify all contaminants of potential concern using the Method Groups as identified in the Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:

ABNs - Acid Base Neutral Compounds
CPs - Chlorophenyls
1, 4 - Dioxane
Dioxins/Furans, PCDDs/PCDFs
OCs - Organochlorine Pesticides
PHCs - Petroleum Hydrocarbons
PCBs - Polychlorinated Biphenyls
PAHs - Polycyclic Aromatic Hydrocarbons
THMs - Trihalomethanes
VOCs - Volatile Organic Compounds
BTEX - Benzene, Toluene, Ethylbenzene, Xylenes
Ca, Mg - Calcium, Magnesium
Metals
As, Sb, Se - Arsenic, Antimony, Selenium
Electrical Conductivity
B-HWS - Boron (Hot Water Soluable)
Cr (VI) - Hexavalent Chromium
SAR - Sodium Adsorption Ratio
Na - Sodium
CN^- - Cyanide
Hg - Mercury
Methyl Mercury
High/Low pH

Table 2D - Areas of Potential Environmental Concern (Vodden Street East/West Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Entire Project Area	30	Importation of Fill Material of Unknown Quality	on-site	M&ORPs, PHCs, BTEX, PAHs	Soil
APEC 5	Entire Project Area	E	Application of De-Icing Compounds	on-site	electrical conductivity, SAR	Soil
APEC 11	North and south of Vodden Street East	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	

Notes:

1 - Area of Potential Environmental Concern means the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through,
(a) identification of past or present uses on, in or under the phase one property, and
(b) identification of potentially contaminating activity.

2 - Potentially Contaminating Activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3 - When completing this column, identify all contaminants of potential concern using the Method Groups as identified in the Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:

ABNs - Acid Base Neutral Compounds
CPs - Chlorophenyls
1, 4 - Dioxane
Dioxins/Furans, PCDDs/PCDFs
OCs - Organochlorine Pesticides
PHCs - Petroleum Hydrocarbons
PCBs - Polychlorinated Biphenyls
PAHs - Polycyclic Aromatic Hydrocarbons
THMs - Trihalomethanes
VOCs - Volatile Organic Compounds
BTEX - Benzene, Toluene, Ethylbenzene, Xylenes
Ca, Mg - Calcium, Magnesium
Metals
As, Sb, Se - Arsenic, Antimony, Selenium
Electrical Conductivity
B-HWS - Boron (Hot Water Soluable)
Cr (VI) - Hexavalent Chromium
SAR - Sodium Adsorption Ratio
Na - Sodium
CN^- - Cyanide
Hg - Mercury
Methyl Mercury
High/Low pH

Table 2E - Areas of Potential Environmental Concern (Kennedy Road North/South Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Entire Project Area	30	Importation of Fill Material of Unknown Quality	on-site	M&ORPs, PHCs, BTEX, PAHs	Soil
APEC 5	Entire Project Area	E	Application of De-Icing Compounds	on-site	electrical conductivity, SAR	Soil
APEC 11	North and south of Vodden Street East	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		28	Gasoline and Associated Products Storage in Fixed Tanks	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	
APEC 12	North of Dean Street	2	Adhesives and Resins Manufacturing, Processing and Bulk Storage	off-site	PHCs, BTEX, VOCs	Soil
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
APEC 13	North and south of Clarence Street	10	Commercial Autobody Shops	off-site	M&ORPs, PHCs, BTEX, VOCs,	Soil
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	

Table 2E - Areas of Potential Environmental Concern (Kennedy Road North/South Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 13	North and south of Clarence Street	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	
APEC 14	Between Dean Street and Stafford Street	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		37	Operation of Dry Cleaning Equipment (where chemicals are used)		PHCs, BTEX, VOCs	
		43	Plastics (including Fibreglass) Manufacturing and Processing		PHCs, BTEX, VOCs, sVOCs	
		51	Solvent Manufacturing, Processing and Bulk Storage		PHCs, BTEX, VOCs	
		C	Miscellaneous Manufacturing		M&ORPs, PHCs, BTEX, VOCs, PAHs	
APEC 15	North and south of Tullamore Road	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		43	Plastics (including Fibreglass) Manufacturing and Processing		PHCs, BTEX, VOCs, sVOCs	
		51	Solvent Manufacturing, Processing and Bulk Storage		PHCs, BTEX, VOCs	

Table 2E - Areas of Potential Environmental Concern (Kennedy Road North/South Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 15	North and south of Tullamore Road	A	Spills	off-site	PHCs, BTEX, VOCs	Soil
		B	PCB Storage Site		PCBs	
APEC 16	North of Rambler Road	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	
		A	Spills		PHCs, BTEX, VOCs, PAHs	
		B	PCB Storage Site		PCBs	
		C	Miscellaneous Manufacturing		PHCs, BTEX, VOCs, PCBs	
APEC 17	North and south of Steeles Avenue East	28	Gasoline and Associated Products Storage in Fixed Tanks	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
		37	Operation of Dry Cleaning Equipment (where chemicals are used)		PHCs, BTEX, VOCs	
		55	Transformer Manufacturing, Processing and Use		PHCs, BTEX, PAHs, PCBs	
		A	Spills	on-site	PHCs, BTEX, VOCs	
APEC 18	South of Tullamore Court	37	Operation of Dry Cleaning Equipment (where chemicals are used)	off-site	PHCs, BTEX, VOCs	Soil
		A	Spills		VOCs	
APEC 19	East and west of Kennedy Road North, north and south of Queen Street East	28	Gasoline and Associated Products Storage in Fixed Tanks	off-site	M&ORPs, PHCs & BTEX, BTEX, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs & BTEX, BTEX, PAHs	

Table 2E - Areas of Potential Environmental Concern (Kennedy Road North/South Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 20	South of Eastern Avenue	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPs, PHCs & BTEX, BTEX, PAHs	Soil
		52	Storage, maintenance, fuelling and repair of equipment, vehicles, and material used to maintain transportation systems		M&ORPs, PHCs & BTEX, BTEX, VOCs, PAHs	
		57	Vehicles and Associated Parts Manufacturing		M&ORPs, PHCs & BTEX, BTEX, VOCs	
APEC 21	North and south of Hillcrest Avenue	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles	off-site	M&ORPs, PHCs & BTEX, BTEX, VOCs, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, VOCs, PAHs	
APEC 22	South of Orenda Road	28	Gasoline and Associated Products Storage in Fixed Tanks	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
APEC 23	South of Rambler Drive	37	Operation of Dry Cleaning Equipment (where chemicals are used)	off-site	PHCs, BTEX, VOCs	Soil
APEC 24	South of First Gulf Boulevard	51	Solvent Manufacturing, Processing and Bulk Storage	off-site	PHCs, BTEX, VOCs	Soil
		57	Vehicles and Associated Parts Manufacturing		M&ORPs, PHCs, BTEX, VOCs	
APEC 25	North of Scottsdale Court	C	Miscellaneous Manufacturing	off-site	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
APEC 26	South of Gilden	D	Welding or Machine Shop	off-site	M&ORPs, PHCs & BTEX, BTEX, VOCs	Soil
APEC 27	North of Clarence Street	46	Rail Yards, Tracks and Spurs	on-site	M&ORPs, PHCs & BTEX, PCBs	Soil

Notes:

Table 2E - Areas of Potential Environmental Concern (Kennedy Road North/South Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

1 - Area of Potential Environmental Concern means the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through,
(a) identification of past or present uses on, in or under the phase one property, and
(b) identification of potentially contaminating activity.

2 - Potentially Contaminating Activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3 - When completing this column, identify all contaminants of potential concern using the Method Groups as identified in the Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:

ABNs - Acid Base Neutral Compounds
CPs - Chlorophenyls
1, 4 - Dioxane
Dioxins/Furans, PCDDs/PCDFs
OCs - Organochlorine Pesticides
PHCs - Petroleum Hydrocarbons

PCBs - Polychlorinated Biphenyls
PAHs - Polycyclic Aromatic Hydrocarbons
THMs - Trihalomethanes
VOCs - Volatile Organic Compounds
BTEX - Benzene, Toluene, Ethylbenzene, Xylenes
Ca, Mg - Calcium, Magnesium

Metals
As, Sb, Se - Arsenic, Antimony, Selenium
Electrical Conductivity
B-HWS - Boron (Hot Water Soluable)
Cr (VI) - Hexavalent Chromium
SAR - Sodium Adsorption Ratio

Na - Sodium
CN^- - Cyanide
Hg - Mercury
Methyl Mercury
High/Low pH

Table 2F - Areas of Potential Environmental Concern (Queen Street East Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Area of Potential Environmental Concern (APEC)	Location of APEC	Potentially Contaminating Activity (PCA)		Location of PCA (on-site or off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Entire Project Area	30	Importation of Fill Material of Unknown Quality	on-site	M&ORPs, PHCs, BTEX, PAHs	Soil
APEC 5	Entire Project Area	E	Application of De-Icing Compounds	on-site	electrical conductivity, SAR	Soil
APEC 19	West portion of Queen Street East (east of Kennedy Road North)	28	Gasoline and Associated Products Storage in Fixed Tanks	off-site	M&ORPs, PHCs, BTEX, PAHs	Soil
		28	Gasoline and Associated Products Storage in Fixed Tanks		M&ORPs, PHCs, BTEX, PAHs	
APEC 28	East of Hansen Road North	10	Commercial Autobody Shops	off-site	M&ORPs, PHCs, BTEX, VOCs	Soil
		27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, VOCs	
		34	Metal Fabrication		M&ORPs, PHCs, BTEX, PAHs	
APEC 29	West of Rutherford Road North	27	Garages and Maintenance and Repair of Railcars, Marine Vehicles and Aviation Vehicles		M&ORPs, PHCs, BTEX, PAHs	Soil
APEC 30	East of Kennedy Road North	28	Gasoline and Associated Products Storage in Fixed Tanks	off-site	M&ORPs, PHCs, BTEX, PAHs	Soil

Notes:

1 - Area of Potential Environmental Concern means the area on, in or under a phase one property where one or more contaminants are potentially present, as determined through the phase one environmental site assessment, including through,
(a) identification of past or present uses on, in or under the phase one property, and
(b) identification of potentially contaminating activity.

2 - Potentially Contaminating Activity means a use or activity set out in Column A of Table 2 of Schedule D that is occurring or has occurred in a phase one study area

3 - When completing this column, identify all contaminants of potential concern using the Method Groups as identified in the

Table 2F - Areas of Potential Environmental Concern (Queen Street East Portion)

(Refer to clause 16(2)(a), Schedule D, O. Reg. 153/04)

Protocol for in the Assessment of Properties under Part XV.1 of the Environmental Protection Act, March 9, 2004, amended as of July 1, 2011, as specified below:

ABNs - Acid Base Neutral Compounds

CPs - Chlorophenyls

1, 4 - Dioxane

Dioxins/Furans, PCDDs/PCDFs

OCs - Organochlorine Pesticides

PHCs - Petroleum Hydrocarbons

PCBs - Polychlorinated Biphenyls

PAHs - Polycyclic Aromatic Hydrocarbons

THMs - Trihalomethanes

VOCs - Volatile Organic Compounds

BTEX - Benzene, Toluene, Ethylbenzene, Xylenes

Ca, Mg - Calcium, Magnesium

Metals

As, Sb, Se - Arsenic, Antimony, Selenium

Electrical Conductivity

B-HWS - Boron (Hot Water Soluable)

Cr (VI) - Hexavalent Chromium

SAR - Sodium Adsorption Ratio

Na - Sodium

CN^- - Cyanide

Hg - Mercury


Methyl Mercury

High/Low pH

FIGURES

Prepared By: KaitlynNg

C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure 1 Site Location.aprx



LEGEND

- OLD SCHOOL ROAD
- ORANGEVILLE BRAMPTON RAILWAY
- BOVAIRD DRIVE WEST
- VODDEN STREET EAST/WEST
- KENNEDY ROAD NORTH/SOUTH
- QUEEN STREET

TITLE

PROJECT AREAS


PROJECT


CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	1





POTENTIALLY CONTAMINATING ACTIVITIES (PCAs)

- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (46) RAIL YARDS, TRACKS AND SPURS
- (A) SPILLS
- (E) APPLICATION OF DE-ICING COMPOUNDS

LEGEND

- PROJECT AREA
- 100 m STUDY AREA
- 5 m TOPOGRAPHIC CONTOURS (mASL)
- INFERRED GROUNDWATER FLOW
- MECP WATER WELL
- RAILWAY
- WETLAND
- PROVINCIALLY SIGNIFICANT WETLAND
- TRCA REGULATION LIMIT
- WATERCOURSE
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- PCA CONTRIBUTING TO APEC

CLIENT
REGION OF PEEL


PROJECT
CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


TITLE
PROJECT AREA LOCATION PLAN -
OLD SCHOOL ROAD PORTION


PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	2A


Prepared By: KaitlynNg

C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12 - GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure 2A Project Area Location Plan Real.aprx











POTENTIALLY CONTAMINATING ACTIVITIES (PCAs)

- (10) COMMERCIAL AUTOBODY SHOPS
- (11) COMMERCIAL TRUCKING AND CONTAINER TERMINALS
- (12) CONCRETE, CEMENT AND LIME MANUFACTURING
- (18) ELECTRICITY GENERATION, TRANSFORMATION AND POWER STATIONS
- (27) GARAGES AND MAINTENANCE AND REPAIR OF RAILCARS, MARINE VEHICLES AND AVIATION VEHICLES
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (33) METAL TREATMENT, COATING, PLATING AND FINISHING
- (34) METAL FABRICATION
- (40) PESTICIDES (INCLUDING HERBICIDES, FUNGICIDES AND ANTI-FOULING AGENTS) MANUFACTURING, PROCESSING, BULK STORAGE AND LARGE-SCALE APPLICATIONS
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (A) SPILLS
- (B) PCB STORAGE SITE

LEGEND

- PROJECT AREA
- 100 m STUDY AREA
- 5 m TOPOGRAPHIC CONTOURS (mASL)
- INFERRED GROUNDWATER FLOW
- MECP WATER WELL
- RAILWAY
- WETLAND
- PROVINCIALLY SIGNIFICANT WETLAND
- WATERBODY
- WATERCOURSE
- GREENBELT - PROTECTED COUNTRYSIDE
- TRCA REGULATION LIMIT
- CVC REGULATION LIMIT
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- PCA CONTRIBUTING TO APEC

CLIENT: REGION OF PEEL


PROJECT: CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

TITLE: PROJECT AREA LOCATION PLAN -
ORANGEVILLE BRAMPTON RAILWAY PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	2B

Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12_GIS\Projects\2024\24-0735\APRX\Contaminant Overview Study\24-0735b Figure 2B Project Area Location Plan.aprx





POTENTIALLY CONTAMINATING ACTIVITIES (PCAs)

- (27) GARAGES AND MAINTENANCE AND REPAIR OF RAILCARS, MARINE VEHICLES AND AVIATION VEHICLES
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (E) APPLICATION OF DE-ICING COMPOUNDS

LEGEND

- PROJECT AREA
- 100 m STUDY AREA
- 5 m TOPOGRAPHIC CONTOURS (mASL)
- INFERRED GROUNDWATER FLOW
- MECP WATER WELL
- RAILWAY
- WATERCOURSE
- CVC REGULATION LIMIT
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC


CLIENT: REGION OF PEEL


PROJECT: CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET,
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

TITLE: PROJECT AREA LOCATION PLAN - BOVAIRD DRIVE WEST PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	2C

Prepared By: KaitlynNg
C:\Users\KaitlynN\OneDrive - EnVision Consultants\12_GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure 2C Project Area Location Plan.aprx





POTENTIALLY CONTAMINATING ACTIVITIES (PCAs)

- (27) GARAGES AND MAINTENANCE AND REPAIR OF RAILCARS, MARINE VEHICLES AND AVIATION VEHICLES
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (58) WASTE DISPOSAL AND WASTE MANAGEMENT, INCLUDING THERMAL TREATMENT, LANDFILLING AND TRANSFER OF WASTE, OTHER THAN USE OF BIOSOILS AS SOIL CONDITIONERS
- (A) SPILL
- (E) APPLICATION OF DE-ICING COMPOUNDS

LEGEND

- PROJECT AREA
- 100 m STUDY AREA
- 5 m TOPOGRAPHIC CONTOURS (mASL)
- INFERRED GROUNDWATER FLOW
- MECP WATER WELL
- RAILWAY
- WATERCOURSE
- GREENBELT - URBAN RIVER VALLEY
- TRCA REGULATION LIMIT
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC


CLIENT
REGION OF PEEL


PROJECT
CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


TITLE
PROJECT AREA LOCATION PLAN -
VODDEN STREET EAST/WEST PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	2D

Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure 2D Project Area Location Plan Real.aprx







POTENTIALLY CONTAMINATING ACTIVITIES (PCAs)

- (2) ADHESIVES AND RESINS MANUFACTURING, PROCESSING AND BULK STORAGE
- (10) COMMERCIAL AUTOBODY SHOPS
- (27) GARAGES AND MAINTENANCE AND REPAIR OF RAILCARS, MARINE VEHICLES AND AVIATION VEHICLES
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (37) OPERATION OF DRY CLEANING EQUIPMENT (WHERE CHEMICALS ARE USED)
- (43) PLASTICS (INCLUDING FIBREGLASS) MANUFACTURING AND PROCESSING
- (46) RAIL YARDS, TRACKS AND SPURS
- (51) SOLVENT MANUFACTURING, PROCESSING AND BULK STORAGE
- (52) STORAGE, MAINTENANCE, FUELLING AND REPAIR OF EQUIPMENT, VEHICLES, AND MATERIAL USED TO MAINTAIN TRANSPORTATION SYSTEMS
- (55) TRANSFORMER MANUFACTURING, PROCESSING AND USE
- (57) VEHICLES AND ASSOCIATED PARTS MANUFACTURING
- (A) SPILLS
- (B) PCB STORAGE SITE
- (C) MISCELLANEOUS MANUFACTURING
- (D) WELDING OR MACHINE SHOP
- (E) APPLICATION OF DE-ICING COMPOUNDS

LEGEND

- PROJECT AREA
- 100 m STUDY AREA
- 5 m TOPOGRAPHIC CONTOURS (mASL)
- INFERRED GROUNDWATER FLOW
- MECP WATER WELL
- RAILWAY
- WATERBODY
- WATERCOURSE
- GREENBELT - URBAN RIVER VALLEY
- TRCA REGULATION LIMIT
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- PCA CONTRIBUTING TO APEC

CLIENT: REGION OF PEEL

PROJECT: CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


TITLE: PROJECT AREA LOCATION PLAN -
KENNEDY ROAD NORTH/SOUTH PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	2E

Prepared By: KaitlynNg

C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12 - GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure 2E Project Area Location Plan.aprx





POTENTIALLY CONTAMINATING ACTIVITIES (PCAs)

- (10) COMMERCIAL AUTOBODY SHOPS
- (27) GARAGES AND MAINTENANCE AND REPAIR OF RAILCARS, MARINE VEHICLES AND AVIATION VEHICLES
- (28) GASOLINE AND ASSOCIATED PRODUCTS STORAGE IN FIXED TANKS
- (30) IMPORTATION OF FILL MATERIAL OF UNKNOWN QUALITY
- (34) METAL FABRICATION
- (B) PCB STORAGE SITE
- (E) APPLICATION OF DE-ICING COMPOUNDS

LEGEND

- PROJECT AREA
- 100 m STUDY AREA
- 5 m TOPOGRAPHIC CONTOURS (mASL)
- INFERRED GROUNDWATER FLOW
- MECP WATER WELL
- RAILWAY
- WATERCOURSE
- TRCA REGULATION LIMIT
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- (#) PCA NOT CONTRIBUTING TO APEC
- (#) PCA CONTRIBUTING TO APEC


CLIENT
REGION OF PEEL

PROJECT
CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

TITLE
PROJECT AREA LOCATION PLAN -
QUEEN STREET EAST PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	AUGUST 2025	KN	RO	2F

Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12_GIS\Projects\2024\24-0735b\MXD\Contaminant Overview Study\24-0735b Figure 2F Project Area Location Plan.aprx



AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs)

APEC	PCA	COPCs	Media
1	30 .1	M&ORPs, PHCs & BTEX, PAHs	Soil
2	46 .1	M&ORPs, PAHs, OCs, PCBs	Soil
3	A .2	PHCs, BTEX, VOCs	Soil
4	E .1	electrical conductivity, SAR	Soil

APEC 1 & 4
APEC 2
APEC 3

LEGEND

- PROJECT AREA
- BUILDING
- RAILWAY
- WETLAND
- PROVINCIALLY SIGNIFICANT WETLAND
- WATERCOURSE
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- PCA CONTRIBUTING TO APEC


CLIENT
REGION OF PEEL

PROJECT
CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

TITLE
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN -
OLD SCHOOL ROAD PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	AUGUST 2025	KN	RO	3A

Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12 - GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure 3A APEC.aprx



AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs)

APEC	PCA	COPCs	Media
2	46 .1	M&ORPs, PAHs, OCs, PCBs	Soil
5	10 .1 27 5 28 2 33 .3 34 .1 43 .2 A .5	M&ORPs, PHCs & BTEX, VOCs, sVOCs, PAHs	Soil
6	11 .1 27 .1 27 .2 27 .3 28 .1	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil
7	12 .1 28 .4 A .11	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil
8	18 .1 28 .3 33 .2 34 .2 43 .1 58 .2 A .9 B .1	M&ORPs, PHCs & BTEX, VOCs, sVOCs, PAHs, PCBs	Soil
9	27 .4	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil

- APEC 2
- APEC 5
- APEC 6
- APEC 7
- APEC 8
- APEC 9

LEGEND

- PROJECT AREA
- RAILWAY
- WATERBODY
- WATERCOURSE
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- PCA CONTRIBUTING TO APEC

CLIENT

REGION OF PEEL

PROJECT


CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

TITLE

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN -
ORANGEVILLE BRAMPTON RAILWAY PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	AUGUST 2025	KN	RO	3B

Prepared By: KaitlynNg



AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs)

APEC	PCA	COPCs	Media
1	30 .1	M&ORPs, PHCs, BTEX, PAHs	Soil
4	E .1	electrical conductivity, SAR	Soil
10	28 .5	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil
	28 .6		
	28 .7		

APEC 1 & 4

APEC 10

LEGEND

- PROJECT AREA
- BUILDING
- RAILWAY
- WATERCOURSE
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- # PCA NOT CONTRIBUTING TO APEC
- # PCA CONTRIBUTING TO APEC

CLIENT

REGION OF PEEL

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


TITLE

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN - BOVAIRD STREET PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	AUGUST 2025	KN	RO	3C

C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12 - GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure 3C APEC.aprx

Prepared By: KaitlynNg



AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs)

APEC	PCA	COPCs	Media
1	30 .1	M&ORPs, PHCs & BTEX, PAHs	Soil
4	E .1	electrical conductivity, SAR	Soil
11	27 .8	M&ORPs, PHCs, BTEX, VOCs, PAHs	Soil
	28 .8		
	28 .9		

APEC 1 & 4

APEC 11

LEGEND

- PROJECT AREA
- BUILDING
- RAILWAY
- WATERCOURSE
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- PCA CONTRIBUTING TO APEC

CLIENT

REGION OF PEEL

PROJECT


CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


TITLE

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN - VODDEN STREET PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	AUGUST 2025	KN	RO	3D

C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12_GIS\Projects\2024\24-0735\MXD\RPT\Contaminant Overview Study\24-0735b Figure 3D APEC.aprx





AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs)

	PCA	COPCs	Media
1	30 .1	M&ORPs, PHCs & BTEX, PAHs	Soil
5	E .1	electrical conductivity, SAR	Soil
11	27 .8 28 .8 28 .9	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil
12	2 .1 27 .12 27 .13 27 .17 27 .21	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil
13	10 .2 27 .11 28 .14	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil
14	27 .14 27 .15 27 .18 37 .4 43 .2 51 .2 C .1	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil
15	27 .16 43 .1 51 .1 A .14 B .2	M&ORPs, PHCs & BTEX, VOCs, sVOCs, PAHs, PCBs	Soil
16	27 .19 28 .15 A .16 B .3 C .2	M&ORPs, PHCs & BTEX, VOCs, PAHs, PCBs	Soil
17	28 .16 37 .3 55 .1 A .17	M&ORPs, PHCs & BTEX, VOCs, PAHs, PCBs	Soil
18	37 .1 A .15	PHCs & BTEX, VOCs	Soil
19	28 10 28 .11	M&ORPs, PHCs & BTEX, BTEX, PAHs	Soil
20	27 .10 52 .1 57 .1	M&ORPs, PHCs & BTEX, BTEX, PAHs	Soil
21	27 .9 28 .12	M&ORPs, PHCs & BTEX, BTEX, PAHs	Soil
22	28 .13	PHCs & BTEX, VOCs, PAHs	Soil
23	37 .2	PHCs & BTEX, VOCs	Soil
24	51 .3 57 .2	PHCs & BTEX, VOCs	Soil
25	C .3	M&ORPs, PHCs & BTEX, VOCs, PAHs	Soil
26	D .1	M&ORPs, PHCs & BTEX, BTEX	Soil
27	46 .2	M&ORPs, PHCs & BTEX, PCBs	Soil

APEC 1 & 4
APEC 11
APEC 12
APEC 13
APEC 14
APEC 15
APEC 16
APEC 17
APEC 18
APEC 19
APEC 20
APEC 21
APEC 22
APEC 23
APEC 24
APEC 25
APEC 26
APEC 27

LEGEND

PROJECT AREA
RAILWAY
WETLAND
WATERCOURSE
TANK NOT CONTRIBUTING TO APEC
TANK CONTRIBUTING TO APEC
PCA NOT CONTRIBUTING TO APEC
PCA CONTRIBUTING TO APEC


CLIENT
REGION OF PEEL

PROJECT
CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

TITLE
AREAS OF POTENTIAL ENVIRONMENTAL CONCERN - KENNEDY ROAD PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	AUGUST 2025	KN	RO	3E

Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\MXD\Contaminant Overview Study\24-0735b Figure 3E APEC.qprx



AREAS OF POTENTIAL ENVIRONMENTAL CONCERN (APECs)

	PCA	COPCs	Media
1	30 .1	M&ORPs, PHCs & BTEX, PAHs	Soil
5	E .1	electrical conductivity, SAR	Soil
19	28 .10	M&ORPs, PHCs & BTEX, BTEX, PAHs	Soil
	28 .11		
28	10 .4	M&ORPs, PHCs & BTEX, PAHs	Soil
	27 .23		
	34 .3		
29	27 .24	M&ORPs, PHCs & BTEX, PAHs	Soil
30	28 .17	M&ORPs, PHCs & BTEX, PAHs	Soil

- APEC 1 & 4
- APEC 19
- APEC 28
- APEC 29
- APEC 30

LEGEND

- PROJECT AREA
- BUILDING
- RAILWAY
- WATERCOURSE
- TANK NOT CONTRIBUTING TO APEC
- TANK CONTRIBUTING TO APEC
- PCA NOT CONTRIBUTING TO APEC
- PCA CONTRIBUTING TO APEC

CLIENT

REGION OF PEEL

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

TITLE

AREAS OF POTENTIAL ENVIRONMENTAL CONCERN -
QUEEN STREET EAST PORTION

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	AUGUST 2025	KN	RO	3F

Prepared By: KaitlynNg

C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12_GIS\Projects\2024\24-0735b\ARPX\Contaminant Overview Study\24-0735b Figure 3F APEC.aprx

APPENDIX A:

ERIS Reports

DATABASE REPORT

Project Property:	*Kennedy STS* *Kennedy STS* *Caledon ON L7C 2A1*
Project No:	*24-0735*
Report Type:	*Quote - Custom-Build Your Own Report*
Order No:	*25071000582*
Requested by:	*EnVision Consultants Ltd.*
Date Completed:	*July 10, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....112
Map.....233
Aerial.....234
Topographic Map.....235
Detail Report.....236
Unplottable Summary.....1776
Unplottable Report.....1787
Appendix: Database Descriptions.....1911
Definitions.....1921

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*Kennedy STS* *Kennedy STS Caledon ON L7C 2A1*
Project No:	*24-0735*

Order Information:

Order No:	*25071000582*
Date Requested:	*July 10, 2025*
Requested by:	*EnVision Consultants Ltd.*
Report Type:	*Quote - Custom-Build Your Own Report*

Historical/Products:

ERIS Xplorer	*ERIS Xplorer*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.25km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	1	1
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	2	2
BORE	Borehole	Y	0	19	19
CA	Certificates of Approval	Y	0	36	36
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	1	1
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	17	17
EASR	Environmental Activity and Sector Registry	Y	0	17	17
EBR	Environmental Registry	Y	0	26	26
ECA	Environmental Compliance Approval	Y	0	68	68
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	0	91	91
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	18	18
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	18	18
FSTH	Fuel Storage Tank - Historic	Y	0	7	7
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	506	506
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	1	1
HINC	TSSA Historic Incidents	Y	0	4	4

Database	Name	Searched	Project Property	Boundary to 0.25km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	4	4
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	1	1
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	8	8
NPR2	National Pollutant Release Inventory	Y	0	10	10
NPRI	National Pollutant Release Inventory - Historic	Y	0	9	9
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	13	13
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	103	103
PFAS	Ontario PFAS Spills	Y	0	0	0
PFCH	NPRI Reporters - PFAS Substances	Y	0	0	0
PFHA	Potential PFAS Handlers from NPRI	Y	0	1	1
PINC	Pipeline Incidents	Y	0	19	19
PPHA	Potential PFAS Handlers from EASR	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	0	7	7
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	5	5
RST	Retail Fuel Storage Tanks	Y	0	11	11
SCT	Scott's Manufacturing Directory	Y	0	56	56
SPL	Ontario Spills	Y	0	79	79
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	2	2

Database	Name	Searched	Project Property	Boundary to 0.25km	Total
WDSH	***Waste Disposal Sites - MOE 1991 Historical Approval Inventory***	*Y*	*0*	*0*	*0*
WWIS	***Water Well Information System***	*Y*	*1*	*164*	*165*
		Total:	*1*	*1,324*	*1,325*

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
334	WWIS		ON **Well ID:** 7355069	WNW/0.3	18.41	236

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	WWIS		225 WANLESS DR Brampton ON ***Well ID:*** 7359021	WSW/243.4	2.86	236
2	WWIS		225 Wanless Dr Brampton ON ***Well ID:*** 7354806	WSW/245.9	3.92	240
3	WWIS		225 WANLESS DR lot 15 con 1 Brampton ON ***Well ID:*** 7390047	SW/231.3	2.92	243
4	WWIS		225 WANLESS DR Brampton ON ***Well ID:*** 7390050	WSW/238.9	3.92	244
5	WWIS		225 WANLESS DR Brampton ON ***Well ID:*** 7359020	WSW/229.4	3.92	245
6	WWIS		225 WANLESS DR Brampton ON ***Well ID:*** 7390048	WSW/224.6	3.89	249
7	WWIS		225 WANLESS DR Brampton ON ***Well ID:*** 7390078	WSW/224.8	3.84	250
8	WWIS		225 Wanless Drive lot 15 con 1 Brampton ON ***Well ID:*** 7405164	WSW/214.1	4.01	251
9	WWIS		225 Wanless Drive lot 15 con 1 Brampton ON ***Well ID:*** 7405167	WSW/216.5	3.92	254
10	WWIS		225 Wanless Dr Brampton ON ***Well ID:*** 7354807	WSW/220.5	3.84	256
11	WWIS		225 Wanless Drive lot 15 con 1 Brampton ON ***Well ID:*** 7405166	WSW/202.3	4.57	259
12	WWIS		lot 15 con 1 ON	WSW/200.1	4.57	261

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7407100			
13	WWIS		120 SANDLEWOOD Brampton ON ***Well ID:*** 7122450	SSW/207.6	0.92	262
14	WWIS		120 SANDLEWOOD Brampton ON ***Well ID:*** 7122451	SSW/194.5	0.92	264
15	WWIS		120 SANDALWOOD PARKWAY Brampton ON ***Well ID:*** 7114845	S/198.7	-1.08	266
16	CA	BRAMPTON BRICK LIMITED	225 WANLESS DR. BRAMPTON CITY ON L7A 1E9	W/196.0	6.87	272
16	CA	PEEL BLOCK (1987) LIMITED DIV. BRAM. BRI	225 WANLESS DRIVE BRAMPTON CITY ON L7A 1E9	W/196.0	6.87	272
16	CA	RICHVALE YORK BLOCK INC.	225 WANLESS DRIVE BRAMPTON CITY ON L7A 1E9	W/196.0	6.87	273
16	PRT	ROXY CONSTRUCTION CO LTD	225 WANLESS DR BRAMPTON ON L7A 1E9	W/196.0	6.87	273
16	PRT	BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKET	225 WANLESS DR BRAMPTON ON L7A1E9	W/196.0	6.87	273
16	SCT	Brampton Brick Limited	225 Wanless Dr Brampton ON L7A 1E9	W/196.0	6.87	273
16	SCT	LAFARGE CANADA INC. - CONSTRUC	225 Wanless Rd Brampton ON L7A 1E9	W/196.0	6.87	274
16	SCT	Lafarge Canada Inc. - Construction Materials Group	225 Wanless Dr Brampton ON L7A 1E9	W/196.0	6.87	274
16	CA		225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	274
16	CA	Brampton Brick Limited - Brique Brampton Limitee	225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	274

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
16	EBR	Brampton Brick Limited	225 Wanless Drive CITY OF BRAMPTON ON	W/196.0	6.87	275
16	EBR	Brampton Brick Limited	225 Wanless Drive Brampton Ontario Brampton ON	W/196.0	6.87	275
16	EBR	Brampton Brick Limited	225 Wanless Drive Brampton Ontario Brampton ON	W/196.0	6.87	276
16	EBR	Brampton Brick Limited	225 Wanless Drive Brampton Ontario Brampton ON	W/196.0	6.87	276
16	GEN	RICHVALE YORK BLOCK INC.	O/A PEEL BLOCK 225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	276
16	GEN	ROXY CONSTRUCTION CO. LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	277
16	GEN	PEEL BLOCK CO. (1987) LTD.	DIV. OF BRAMPTON BRICK LTD. 225A WANLESS DR. BRAMPTON ON L7A 1E9	W/196.0	6.87	278
16	GEN	PEEL BLOCK CO. (1987) LIMITED	225A WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	278
16	GEN	PEEL BLOCK CO. (1987) LTD. 30-678	DIV. OF BRAMPTON BRICK LTD. 225A WANLESS DR. BRAMPTON ON L7A 1E9	W/196.0	6.87	278
16	GEN	PEEL BLOCK COMPANY (1987) LIMITED	225A WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	279
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	279
16	GEN	RICHVALE YORK BLOCK INC.	225A WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	280

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
16	FSTH	ROXY CONSTRUCTION CO LTD	225 WANLESS DR BRAMPTON ON L7A 1E9	W/196.0	6.87	280
16	EBR	Brampton Brick Limited	225 Wanless Drive Brampton Ontario Brampton ON	W/196.0	6.87	281
16	EBR	Roxy Construction Co. Limited	225 Wanless Drive Brampton Ontario Brampton ON	W/196.0	6.87	281
16	FSTH	ROXY CONSTRUCTION CO LTD	225 WANLESS DR BRAMPTON ON L7A 1E9	W/196.0	6.87	282
16	SPL	Brampton Brick Limited/Brique Brampton Limitee	225 Wanless Dr Brampton ON L7A 1E9	W/196.0	6.87	282
16	CA	Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	283
16	CA	Brampton Brick Limited / Brique Brampton Limitee	225 Wanless Dr Brampton ON L7A 1E9	W/196.0	6.87	283
16	CA	Medical Waste Management Inc.	225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	283
16	DTNK	BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKETING)	225 WANLESS DR BRAMPTON ON	W/196.0	6.87	284
16	DTNK	BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKETING)	225 WANLESS DR BRAMPTON ON	W/196.0	6.87	284
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	285
16	EHS		225 Wanless Dr Brampton ON L7A 1E9	W/196.0	6.87	286
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	286

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	287
16	FST	ROXY CONSTRUCTION CO LTD	225 WANLESS DR BRAMPTON ON	W/196.0	6.87	288
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	288
16	NPRI	LAFARGE CANADA INC.	225 WANLESS Drive BRAMPTON ON L7A1E9	W/196.0	6.87	289
16	EHS		225 Wanless Drive Brampton ON	W/196.0	6.87	291
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON	W/196.0	6.87	291
16	INC		225a Wanless Drive, Brampton ON	W/196.0	6.87	292
16	GHG	Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	293
16	SPL	Brampton Brick Limited	225 Wanless Dr Brampton ON L7A 1E9	W/196.0	6.87	300
16	ECA	Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	301
16	ECA	Brampton Brick Limited / Brique Brampton Limitee	225 Wanless Dr Brampton ON L7A 1E9	W/196.0	6.87	301
16	ECA	Medical Waste Management Inc.	225 Wanless Drive Brampton ON L6T 5R7	W/196.0	6.87	301
16	ECA	Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	301

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
16	ECA	Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	302
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	302
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	303
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	304
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	305
16	EHS		225 Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	306
16	SPL	Canada Cartage Systems Limited	225 Wanless Dr Brampton ON	W/196.0	6.87	307
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	308
16	SPL	Canada Cartage Limited	225 Wanless Drive Brampton ON	W/196.0	6.87	309
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	W/196.0	6.87	310
16	GEN	BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON	W/196.0	6.87	312
16	SPL	Brampton Brick Limited	225 Wanless Dr Brampton ON L7A 1E9	W/196.0	6.87	323
16	NPR2	BRAMPTON BRICK	225 WANLESS DRIVE BRAMPTON ON L7A1E9	W/196.0	6.87	324

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
16	EASR	BRAMPTON BRICK LIMITED/BRIQUE BRAMPTON LIMITEE	225a Wanless Drive Brampton ON L7A 1E9	W/196.0	6.87	373
17	WWIS		120 SANDALWOOD PARKWAY Brampton ON ***Well ID:*** 7123806	SSW/116.9	1.78	374
18	WWIS		225 WANLESS DR Brampton ON ***Well ID:*** 7390044	WSW/133.9	6.92	376
19	WWIS		225 WANLESS DR Brampton ON ***Well ID:*** 7359022	WSW/129.7	6.92	377
20	WWIS		120 SANDLEWOOD PARKWAY BRAMPTON ON ***Well ID:*** 7117441	SW/86.3	1.92	380
21	WWIS		120 SANDLEWOOD Brampton ON ***Well ID:*** 7122452	SSW/92.6	1.71	383
22	GEN	City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	S/246.1	-2.08	385
22	EBR	Giffels Associates for Brampton Transit	120 Sandalwood Pkwy Brampton Ontario L7W 1L2 Brampton ON	S/246.1	-2.08	385
22	WWIS		120 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7114851	S/246.1	-2.08	386
22	CA	The Corporation of the City of Brampton	120 Sandalwood Pky Brampton ON	S/246.1	-2.08	405
22	SPL	The Corporation of the City of Brampton	Steeles Ave and Kenndy Rd; 120 Sandalwood Pky W Brampton; Brampton ON L7A 1L2	S/246.1	-2.08	405
22	EASR	THE CORPORATION OF THE CITY OF BRAMPTON	120 SANDALWOOD PKWY WEST BRAMPTON ON L7A 1L2	S/246.1	-2.08	406

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
22	ECA	The Corporation of the City of Brampton	120 Sandalwood Pky W Brampton ON L7A 1L2	S/246.1	-2.08	406
22	DTNK	CITY OF BRAMPTON	120 SANDALWOOD PKWY W BRAMPTON ON	S/246.1	-2.08	407
22	GEN	City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	S/246.1	-2.08	407
22	GEN	City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	S/246.1	-2.08	407
22	GEN	City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	S/246.1	-2.08	408
22	GEN	City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	S/246.1	-2.08	408
22	FST	CITY OF BRAMPTON	120 SANDALWOOD PKWY W BRAMPTON ON	S/246.1	-2.08	409
22	FST	CITY OF BRAMPTON	120 SANDALWOOD PKWY W BRAMPTON ON	S/246.1	-2.08	409
22	GEN	City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	S/246.1	-2.08	409
22	GEN	City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	S/246.1	-2.08	410
22	GEN	City of Brampton	120 Sandalwood Parkway West Brampton ON	S/246.1	-2.08	410
22	ECA	The Corporation of the City of Brampton	120 Sandalwood Pky Brampton ON L6Y 4R2	S/246.1	-2.08	410
22	ECA	The Corporation of the City of Brampton	120 Sandalwood Pky W Brampton ON L6Y 4R2	S/246.1	-2.08	411

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
22	ECA	The Corporation of the City of Brampton	120 Sandalwood Pky W Brampton ON L6Y 4R2	S/246.1	-2.08	411
22	ECA	The Corporation of the City of Brampton	120 Sandalwood Pky W Brampton ON L6Y 4R2	S/246.1	-2.08	411
22	GEN	City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	S/246.1	-2.08	411
22	GEN	City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	S/246.1	-2.08	412
22	GEN	City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	S/246.1	-2.08	412
22	GEN	City of Brampton Public Works	120 Sandalwood Parkway West Brampton ON L7A 1L2	S/246.1	-2.08	413
22	GEN	City of Brampton Public Works	120 Sandalwood Parkway West Brampton ON L7A 1L2	S/246.1	-2.08	413
22	GEN	City of Brampton Public Works	120 Sandalwood Parkway West Brampton ON L7A 1L2	S/246.1	-2.08	414
22	GEN	City of Brampton	Roads - Fleet, 120 Sandalwood Parkway West Brampton ON	S/246.1	-2.08	414
22	SPL		120 Sandalwood Parkway West, Brampton ON BRAMPTON ON	S/246.1	-2.08	419
23	WWIS		130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7246995	S/154.9	-1.21	419
24	WWIS		130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7247001	S/225.3	-2.08	421
25	ECA	Mia Properties Limited	CON 1 WEST OF CENTRE ROAD Brampton ON M2P 2B7	WSW/10.8	5.92	423

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
25	ECA	Mia Properties Limited	CON 1 WEST OF CENTRE ROAD Brampton ON M2P 2B7	WSW/10.8	5.92	424
25	ECA	Petro-Canada Limited	West of Hurontario Street Brampton ON L6L 6N5	WSW/10.8	5.92	424
26	WWIS		ON ***Well ID:*** 7167767	W/66.6	7.92	424
27	WWIS		ON ***Well ID:*** 7170238	W/61.7	7.92	425
28	WWIS		130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7246996	SSW/52.5	-0.86	426
29	ECA	Mia Properties Limited	Brampton ON M2P 6O2	SSW/11.9	-1.08	428
29	ECA	Mia Properties Limited	Brampton ON M3B 2T5	SSW/11.9	-1.08	428
29	ECA	149259 Canada Limited	Lot 14, Concession 1 WHS Brampton ON M5P 3M2	SSW/11.9	-1.08	429
29	ECA	Mia Properties Limited	Brampton ON M2P 6O2	SSW/11.9	-1.08	429
29	ECA	Ciro Excavating & Grading Ltd.	Brampton ON L4L 3P6	SSW/11.9	-1.08	429
29	ECA	Ciro Excavating & Grading Ltd.	Brampton ON L4L 3P6	SSW/11.9	-1.08	429
29	ECA	149259 Canada Limited	Lot 14, Concession 1 WHS Brampton ON M5P 3M2	SSW/11.9	-1.08	430
29	ECA	Mia Properties Limited	Brampton ON M3B 2T5	SSW/11.9	-1.08	430

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
30	GEN	HOME ALONE PROPERTY MANAGEMENT LTD	8 MILKWEED CRESCENT BRAMPTON ON	WSW/140.3	3.92	430
31	PES	NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	WSW/143.7	3.92	431
31	PES	NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	WSW/143.7	3.92	431
31	PES		4 NARCISSUS GATE BRAMPTON ON L7A 1V9	WSW/143.7	3.92	431
31	PES		4 NARCISSUS GATE BRAMPTON ON L7A 1V9	WSW/143.7	3.92	432
31	PES	NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	WSW/143.7	3.92	432
31	PES	NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	WSW/143.7	3.92	433
31	PES	NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	WSW/143.7	3.92	433
31	PES	NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	WSW/143.7	3.92	433
32	WWIS		130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7246999	S/119.2	-2.08	434
33	WWIS		lot 16 con 1 ON ***Well ID:*** 4908671	W/24.1	7.92	436
34	PES	NH PEST CONTROL INC.	2 NARCISSUS GATE BRAMPTON ON L7A1V9	WSW/153.8	3.92	437
35	WWIS		130 SANDALWOOD PKWY WEST Brampton ON	SSE/193.0	-2.88	437

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7247000			
36	BORE		ON	W/36.5	6.92	439
37	WWIS		130 SANDALWOOD PKWY W BRAMPTON BUS DEPOT Brampton ON ***Well ID:*** 7277183	SSE/168.3	-2.07	441
38	WWIS		130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7246997	S/30.7	-2.08	444
39	WWIS		lot 16 con 1 ON ***Well ID:*** 4908672	W/76.1	7.14	446
40	PES	RATRO PEST CONTROL INC.	194 VAN SCOTT DR BRAMPTON ON L7A 1V8	SW/182.7	3.92	447
40	PES	RATRO PEST CONTROL INC.	194 VAN SCOTT DR BRAMPTON ON L7A 1V8	SW/182.7	3.92	448
41	GEN	ROXY CONSTRUCTION LTD.	180 VAN SCOTT DRIVE, UNIT B BRAMPTON ON L7A 1E4	SW/183.4	3.59	448
41	GEN	ROXY CONSTRUCTION LTD. (OUT OF BUSINESS)	180 VAN SCOTT DRIVE, UNIT B BRAMPTON ON L7A 1E4	SW/183.4	3.59	449
41	GEN	ROXY CONSTRUCTION LTD. (OUT OF BUSINESS)	180 VAN SCOTT DRIVE UNIT B BRAMPTON ON L7A 1E4	SW/183.4	3.59	449
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	S/102.1	-3.08	450
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	S/102.1	-3.08	450
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	S/102.1	-3.08	451
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	S/102.1	-3.08	451

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	S/102.1	-3.08	452
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON	S/102.1	-3.08	453
42	EASR	THE CORPORATION OF THE CITY OF BRAMPTON	130 Sandalwood PKY W Brampton ON L7A 1L2	S/102.1	-3.08	453
42	EASR	THE CORPORATION OF THE CITY OF BRAMPTON	130 Sandalwood PKY W Brampton ON L7A 1L2	S/102.1	-3.08	454
42	EBR	City of Brampton	130 Sandalwood Pkwy W, Brampton CITY OF BRAMPTON ON	S/102.1	-3.08	454
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A0L1	S/102.1	-3.08	455
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A0L1	S/102.1	-3.08	455
42	GEN	Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A0L1	S/102.1	-3.08	456
42	GEN	Corporation Of The City Of Brampton Works & Transportation	130 Sandalwood Pkwy West Brampton ON L7A0L1	S/102.1	-3.08	457
42	ECA	The Corporation of the City of Brampton	130 Sandalwood Pky W Brampton ON L6Y 4R2	S/102.1	-3.08	458
42	GEN	Corporation Of The City Of Brampton Works & Transportation	130 Sandalwood Pkwy West Brampton ON L7A0L1	S/102.1	-3.08	458
42	GEN	Corporation Of The City Of Brampton Works & Transportation	130 Sandalwood Pkwy West Brampton ON L7A0L1	S/102.1	-3.08	459

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
42	EASR	THE CORPORATION OF THE CITY OF BRAMPTON	130 Sandalwood PKY W Brampton ON L7A 1L2	S/102.1	-3.08	460
42	GEN	Belfor Property Restoration	130 Sandalwood Parkway West Brampton ON L7A 1A8	S/102.1	-3.08	460
42	GEN	City of Brampton	Brampton Transit - Sandalwood, 130 Sandalwood Pkwy West Brampton ON	S/102.1	-3.08	461
42	GEN	Brampton Transit	130 Sandalwood Parkway West Brampton ON	S/102.1	-3.08	468
43	SPL		34 Burnt Elm Dr, Brampton BRAMPTON ON	WSW/198.0	2.91	469
44	BORE		ON	W/26.8	5.92	470
45	PES	PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A 3J8	W/167.3	6.92	471
45	PES	PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A 3J8	W/167.3	6.92	471
45	PES	PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A3J8	W/167.3	6.92	472
45	PES	PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A3J8	W/167.3	6.92	472
45	PES	PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A3J8	W/167.3	6.92	472
46	GEN	The Corporation of The City og Brampton	95 Sandelwood Pkwy. Brampton ON	SSE/167.2	-2.80	473
47	WWIS		lot 16 con 1 ON ***Well ID:*** 4901595	W/57.3	5.92	473

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
48	GEN	PEELLE COMPANY LIMITED, THE	105 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	SSE/98.0	-4.08	476
49	SPL		156 Twin Pine Cres. Brampton ON	S/11.6	-4.08	476
50	PES	Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	S/16.7	-4.08	477
50	PES	Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	S/16.7	-4.08	477
50	PES	Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	S/16.7	-4.08	478
50	PES		154 Twin Pines Crescent Brampton ON L7A 1N2	S/16.7	-4.08	478
50	PES	Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	S/16.7	-4.08	479
50	PES	Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	S/16.7	-4.08	479
50	PES	Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	S/16.7	-4.08	479
50	PES	Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	S/16.7	-4.08	480
51	WWIS		175 SANDALWOOD PARKWAY W lot 13 con 1 BRAMPTON ON ***Well ID:*** 7219199	SSE/150.7	-3.67	480
52	ECA	Brampton West 6-2 Limited	Brampton ON M3B 2T5	W/19.8	5.92	483
52	ECA	Brampton West 6-2 Limited	Brampton ON M3B 2T5	W/19.8	5.92	483

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
52	ECA	Brampton West 6-2 Limited	Brampton ON M3B 2T5	W/19.8	5.92	483
52	ECA	Brampton West 6-2 Limited	McLaughlin Road (from Wanless Drive to approximately 240m south of Wanless Drive) Brampton ON M3B 2T5	W/19.8	5.92	484
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A 1N3	S/130.3	-3.62	484
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	S/130.3	-3.62	484
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	S/130.3	-3.62	485
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	S/130.3	-3.62	485
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	S/130.3	-3.62	486
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	S/130.3	-3.62	486
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	S/130.3	-3.62	486
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	S/130.3	-3.62	487
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	S/130.3	-3.62	487
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	S/130.3	-3.62	487
53	PES		11 TINSMITH ST brampton ON L7A 1N3	S/130.3	-3.62	488

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	S/130.3	-3.62	488
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	S/130.3	-3.62	489
53	PES	CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	S/130.3	-3.62	489
54	WWIS		lot 13 con 1 ON ***Well ID:*** 7335999	SSE/154.8	-4.22	489
55	EHS		175 Sandalwood Parkway West Brampton ON L7A 1E8	SSE/121.0	-4.53	490
55	EHS		175 Sandalwood Parkway West Brampton ON L7A 1E8	SSE/121.0	-4.53	490
56	SPL	BRAMPTON HYDRO-ELECTRIC COMMIS	175 SANDALWOOD PKWY WEST MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L7A 1E8	SSE/119.8	-4.90	491
56	SPL	BRAMPTON HYDRO-ELECTRIC COMMIS	175 SANDALWOOD PARKWAY WEST MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L7A 1E8	SSE/119.8	-4.90	491
56	PRT	BRAMPTON HYDRO ELECTRIC COMMISSION	175 SANDALWOOD PKWY W BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	492
56	SPL	BRAMPTON HYDRO-ELECTRIC COMMIS	175 SANDALWOOD PARKWAY BRAMPTON CITY ON	SSE/119.8	-4.90	493
56	NPCB	BRAMPTON HYDRO	175 SANDALWOOD PKWY SANDALWOOD PKWY BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	493
56	WDS	Safety-Kleen (On-Site) Inc.	175 Sandalwood Parkway West Brampton ON N1G 4P5	SSE/119.8	-4.90	494

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	OPCB	BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	495
56	OPCB	BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	495
56	OPCB	BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	496
56	OPCB	BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	497
56	GEN	BRAMPTON HYDRO 05-867	175 SANDALWOOD PARKWAY WEST BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	497
56	GEN	BRAMPTON HYDRO	175 SANDALWOOD PARKWAY WEST BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	499
56	GEN	BRAMPTON HYDRO-ELECTRIC COMMISSION	175 SANDALWOOD PARKWAY WEST BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	500
56	GEN	Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	501
56	NPCB	BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON	SSE/119.8	-4.90	503
56	NPCB	BRAMPTON HYDRO NETWORKS INC.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	503
56	OPCB	BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	503
56	FSTH	HYDRO ONE BRAMPTON NETWORKS INC	175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	504
56	EBR	Hydro One Brampton Networks Inc.	175 Sandalwood Parkway West Brampton Ontario L7A 1E8 Brampton ON	SSE/119.8	-4.90	504

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	SPL	Hydro One Brampton Networks Inc.	175 Sandalwood Pky W Brampton ON L7A 1E8	SSE/119.8	-4.90	505
56	FSTH	HYDRO ONE BRAMPTON NETWORKS INC	175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	506
56	NPCB	BRAMPTON HYDRO	175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	506
56	NPCB	BRAMPTON HYDRO NETWORKS INC.	175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	SSE/119.8	-4.90	507
56	CA	Hydro One Brampton Networks Inc.	175 Sandalwood Parkway West Brampton ON L7A 1E8	SSE/119.8	-4.90	508
56	GEN	Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	508
56	GEN	Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	509
56	GEN	Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	511
56	FST	HYDRO ONE BRAMPTON	175 SANDALWOOD PKY W BRAMPTON ON	SSE/119.8	-4.90	512
56	FST	HYDRO ONE BRAMPTON	175 SANDALWOOD PKY W BRAMPTON ON	SSE/119.8	-4.90	512
56	GEN	Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	513
56	EHS		175 Sandalwood Parkway West Brampton ON	SSE/119.8	-4.90	514
56	EHS		175 Sandalwood Pkwy Brampton ON	SSE/119.8	-4.90	514

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	GEN	Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON	SSE/119.8	-4.90	515
56	OPCB	Brampton Hydro	175 Sandalwood Pkwy Brampton ON L7A 1E8	SSE/119.8	-4.90	516
56	OPCB	Brampton Hydro	175 Sandalwood Pkwy Brampton ON L7A 1E8	SSE/119.8	-4.90	516
56	EASR	BRAMPTON HYDRO INC.	175 Sandalwood PKY W Brampton ON L7A 1E8	SSE/119.8	-4.90	516
56	SPL	Hydro One Brampton Networks Inc.	175 Sandalwood Pky W Brampton ON L7A 1E8	SSE/119.8	-4.90	517
56	ECA	Hydro One Brampton Networks Inc.	175 Sandalwood Parkway West Brampton ON L7A 1E8	SSE/119.8	-4.90	518
56	GEN	Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	518
56	GEN	Alectra Utilities Corp.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	520
56	GEN	Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	521
56	GEN	Alectra Utilities Corp.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	523
56	GEN	Alectra Utilities Corp.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	524
56	GEN	Alectra Utilities Corp.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	SSE/119.8	-4.90	525
56	GEN	Alectra Utilities Corporation	175 Sandalwood Pkwy. West Brampton ON	SSE/119.8	-4.90	526

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	NPR2	HYDRO ONE BRAMPTON	175 SANDALWOOD PKWY., WEST BRAMPTON ON L7A1E8	SSE/119.8	-4.90	533
56	GEN	City of Brampton	175 Sandalwood Parkway West Brampton ON	SSE/119.8	-4.90	565
56	GEN	City of Brampton	175 Sandalwood Parkway West Brampton ON	SSE/119.8	-4.90	566
56	GEN	City of Brampton	175 Sandalwood Parkway West Brampton ON	SSE/119.8	-4.90	567
57	WWIS		ON ***Well ID:*** 7217049	SSE/215.1	-5.46	567
58	SPL		22 Coppermill Drive Brampton ON L7A 1N4	SSW/249.3	-3.08	568
59	WWIS		10534 HURONTARIO ST Mississauga ON ***Well ID:*** 7342881	SSE/248.5	-6.08	569
60	EHS		20 Fisherman Drive Brampton ON	SSE/238.5	-6.47	572
61	SCT	THE PEELLE COMPANY LIMITED	195 SANDALWOOD PKY W MISSISSAUGA ON L7A 1J6	S/98.3	-4.08	573
61	SCT	The Peelle Company Limited	195 Sandalwood Pky W Brampton ON L7A 1J6	S/98.3	-4.08	573
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDAL WOOD PKWY WEST BRAMPTON ON L7A 1J6	S/98.3	-4.08	573
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	S/98.3	-4.08	574
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	S/98.3	-4.08	574

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	S/98.3	-4.08	575
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	S/98.3	-4.08	576
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	S/98.3	-4.08	576
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON	S/98.3	-4.08	577
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	S/98.3	-4.08	577
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	S/98.3	-4.08	578
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	S/98.3	-4.08	579
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	S/98.3	-4.08	579
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	S/98.3	-4.08	580
61	GEN	PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	S/98.3	-4.08	581
61	GEN	The Peelle Company Limited	195 SANDALWOOD PKWY. WEST BRAMPTON ON	S/98.3	-4.08	582
62	AUWR	HEART LAKE USED AUTO PARTS	20 FISHERMAN DR BRAMPTON ON L7A 1G2	SSE/244.3	-7.08	587
62	SCT	General Axle Products Inc.	20 Fisherman Dr Unit 1 Brampton ON L7A 1G2	SSE/244.3	-7.08	587

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
62	GEN	Hutchins & Son Automotive Limited	20 Fisherman Drive Unit #2 Brampton ON	SSE/244.3	-7.08	588
62	GEN	Hutchins & Son Automotive Limited	20 Fisherman Drive Unit #2 Brampton ON	SSE/244.3	-7.08	588
62	AUWR	HEART LAKE USED AUTO PARTS	20 FISHERMAN DR BRAMPTON ON L7A1G2	SSE/244.3	-7.08	588
62	WDS	HUTCHINS & SON AUTOMOTIVE LIMITED	20 FISHERMAN DR BRAMPTON ON L7A 1G2	SSE/244.3	-7.08	589
63	SPL	CONSTRUCTION COMPANY	200 CRESTHAVEN ROAD MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L7A 1J5	WNW/198.5	7.92	589
63	PES	BRAMPTON PEST CONTROL	200 CRESTHAVEN RD, UNIT 78 BRAMPTON ON L7A 1J5	WNW/198.5	7.92	590
64	PES	ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A 1L1	SSE/182.2	-7.08	591
64	PES	ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A 1L1	SSE/182.2	-7.08	591
64	PES	ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A 1L1	SSE/182.2	-7.08	591
64	NPRI	BENTALL REAL ESTATE SERVICES	440 Railside Drive Brampton ON L7A1L1	SSE/182.2	-7.08	592
64	EHS		440 Railside Drive Brampton ON	SSE/182.2	-7.08	593
64	ECA	The Regional Municipality of Peel	440 Railside Drive Brampton ON L7A1L1	SSE/182.2	-7.08	593
64	EHS		440 Railside Dr Brampton ON L7A1L1	SSE/182.2	-7.08	593

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	PES	ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A1L1	SSE/182.2	-7.08	594
64	ECA	The Regional Municipality of Peel	Railside Dr (lot at south end of Railside Drive, adjacent to 440 Railside Drive) Brampton ON L6T 4B9	SSE/182.2	-7.08	594
64	PES	ITWAL LIMITED	440 Railside DR Brampton ON L7A 1L1	SSE/182.2	-7.08	594
64	PES	ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A1L1	SSE/182.2	-7.08	595
64	SPL	ALECTRA UTILITIES CORPORATION	440 Railside Drive Brampton ON	SSE/182.2	-7.08	595
65	EHS		495619 - 153 Van Kirk Drive Brampton ON L7A 1A4	SSE/95.9	-4.08	596
66	WWIS		lot 13 con 1 ON ***Well ID:*** 4908749	SSE/14.9	-6.08	596
67	GEN	Armacell Canada	153 VAN KIRK DRIVE BRAMPTON ON	S/125.6	-3.93	597
68	SCT	INDUSTRIAL THERMO POLYMERS	153 VAN KIRK DR BRAMPTON ON L7A 1A4	S/125.6	-3.93	601
68	CA	INDUSTRIAL THERMO POLYMERS LIMITED	153 VAN KIRK DRIVE BRAMPTON CITY ON L7A 1A4	S/125.6	-3.93	602
68	SCT	Industrial Thermo Polymers Ltd	153 Van Kirk Dr Brampton ON L7A 1A4	S/125.6	-3.93	602
68	SCT	Industrial Thermo Polymers Ltd.	153 Van Kirk Dr Brampton ON L7A 1A4	S/125.6	-3.93	602
68	EBR	Industrial Thermo Polymers Limited	153 Van Kirk Drive CITY OF BRAMPTON ON	S/125.6	-3.93	603

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
68	GEN	INDUSTRIAL THERMO POLYMERS LTD	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	603
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	604
68	EHS		153 Vankirk Dr. Brampton ON L7A 1A4	S/125.6	-3.93	604
68	EBR	Industrial Thermo Polymers Limited	153 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	S/125.6	-3.93	604
68	CA	Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	S/125.6	-3.93	605
68	CA	Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	S/125.6	-3.93	605
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	605
68	EBR	Industrial Thermo Polymers Limited	153 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	S/125.6	-3.93	606
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	606
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	607
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	607
68	EASR	1932675 ONTARIO LIMITED	153 VAN KIRK DR BRAMPTON ON L7A 1A4	S/125.6	-3.93	608
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON	S/125.6	-3.93	608

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
68	ECA	Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	S/125.6	-3.93	609
68	EASR	ARMACELL CANADA INC.	153 VAN KIRK DR BRAMPTON ON L7A 1A4	S/125.6	-3.93	609
68	EHS		153 Van Kirk Dr Brampton ON L7A1A4	S/125.6	-3.93	610
68	ECA	Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	S/125.6	-3.93	610
68	ECA	Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	S/125.6	-3.93	610
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	610
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	611
68	GEN	INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	612
68	GEN	Armacell Canada	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	612
68	GEN	Armacell Canada	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	613
68	SPL		153 Vankirk Drive Brampton ON	S/125.6	-3.93	614
68	SPL	Armacell Canada Inc.	153 Van Kirk Dr Brampton ON L7A 1A4	S/125.6	-3.93	614
68	SPL	Armacell Canada Inc.	153 Van Kirk Dr. Brampton ON	S/125.6	-3.93	615

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
68	GEN	Armacell Canada	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	616
68	NPR2	ARMACELL CANADA INC.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	S/125.6	-3.93	617
68	EHS		153 Van Kirk Drive Brampton ON L7A 1A4	S/125.6	-3.93	664
69	ECA	Armbro Inc.	Brampton ON	SSE/5.2	-6.08	664
69	ECA	The Corporation of the City of Brampton	Brampton ON L6Y 4R2	SSE/5.2	-6.08	664
69	ECA	Terraco Inc.	Brampton ON M5M 2L4	SSE/5.2	-6.08	664
69	ECA	Terraco Inc.	Brampton ON M5M 2L4	SSE/5.2	-6.08	665
70	SCT	FAWCETT METAL FABRICATING (DIV	27 FISHERMAN DR UNIT 9-10 BRAMPTON ON L7A 1E2	SE/243.6	-7.46	665
70	SCT	ACCU-CUT MACHINING SERVICES	27 FISHERMAN DR BRAMPTON ON L7A 1E2	SE/243.6	-7.46	665
70	SCT	FAWCETT METAL FABRICATING	27 FISHERMAN DR BRAMPTON ON L7A 1E2	SE/243.6	-7.46	666
70	SCT	TSL Aerospace Technologies	27 Fisherman Dr Unit 12 Brampton ON L7A 1E2	SE/243.6	-7.46	666
70	SCT	TSL Aerospace Technologies Ltd.	27 Fisherman Dr Unit 12 Brampton ON L7A 1E2	SE/243.6	-7.46	666
70	SCT	Louri Products Ltd.	27 Fisherman Dr Unit 9-10 Brampton ON L7A 1E2	SE/243.6	-7.46	666

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
70	SCT	Fantasy Aluminium Installation Ltd.	27 Fisherman Dr Unit 11 Brampton ON L7A 1E2	SE/243.6	-7.46	667
70	SCT	Fantasy Aluminium Ltd.	27 Fisherman Dr Unit 11 Brampton ON L7A 1E2	SE/243.6	-7.46	667
70	EHS		27 FISHERMAN DRIVE Brampton ON L7A 1E2	SE/243.6	-7.46	667
71	SCT	Sota Glazing Inc	443 Railside Dr Brampton ON L7A 1E1	SE/242.8	-7.25	668
71	SCT	SOTA Glazing Inc.	443 Railside Dr Brampton ON L7A 1E1	SE/242.8	-7.25	668
71	GEN	MEDIRO WROUGHT IRON LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	SE/242.8	-7.25	668
71	GEN	MEDIRO WROUGHT IRON LTD. 26-392	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	SE/242.8	-7.25	669
71	GEN	SOTAWALL INC.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	SE/242.8	-7.25	669
71	GEN	SOTAWALL INC.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	SE/242.8	-7.25	669
71	GEN	SOTAWALL LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	SE/242.8	-7.25	670
71	EASR	SOTAWALL LIMITED	443 Railside DR Brampton ON L7A 1E1	SE/242.8	-7.25	671
71	EHS		443 Railside Drive Brampton ON	SE/242.8	-7.25	671
71	EHS		443 Railside Drive Brampton ON	SE/242.8	-7.25	672

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
71	GEN	SOTAWALL LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	SE/242.8	-7.25	672
71	GEN	SOTAWALL LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	SE/242.8	-7.25	673
71	GEN	SOTAWALL LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	SE/242.8	-7.25	673
72	HINC		37 BANINGTON CRESCENT BRAMPTON ON L7A 1G4	WNW/115.8	8.87	677
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	677
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	678
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	678
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	678
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	679
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON	SSE/143.0	-4.08	679
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	679
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	680
73	GEN	Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	680

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	Dymin Steel	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	680
73	GEN	Dymin Steel	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	681
73	GEN	Dymin Steel	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	681
73	GEN	Dymin Steel	133 Vankirk Dr. Brampton ON L7A 1A4	SSE/143.0	-4.08	682
74	EBR	2270334 Ontario Inc.	150 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	SSE/175.9	-3.49	684
74	CA	2270334 Ontario Inc.	150 Van Kirk Dr Brampton ON	SSE/175.9	-3.49	685
74	ECA	2270334 Ontario Inc.	150 Van Kirk Dr Brampton ON L7A 2Y4	SSE/175.9	-3.49	685
75	GEN	DAY & ROSS INC.	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	685
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	686
75	EHS		170 Van Kirk Drive n/a ON L7A 1K9	S/241.0	-2.29	687
75	SPL	Day & Ross Inc.	170 VANKIRK DR.<UNOFFICIAL> Brampton ON L7A 1K9	S/241.0	-2.29	688
75	SPL	Day & Ross Inc.	170 Van Kirk Drive Brampton ON L7A 1K9	S/241.0	-2.29	689

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
75	SPL	Day & Ross Transport<UNOFFICIAL>	170 Van Kirk Drive Brampton ON L7A 1K9	S/241.0	-2.29	689
75	DTNK	DAY & ROSS INC	170 VAN KIRK DR BRAMPTON ON	S/241.0	-2.29	690
75	DTNK	DAY & ROSS INC	170 VAN KIRK DR BRAMPTON ON	S/241.0	-2.29	691
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	691
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	693
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	695
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	697
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON	S/241.0	-2.29	699
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	701
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	703
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	705
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	708
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	712

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
75	SPL	Day and Ross Inc.	170 Van Kirk Dr Brampton ON	S/241.0	-2.29	716
75	GEN	DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	S/241.0	-2.29	717
75	GEN	Day & Ross Inc.	170 VAN KIRK DRIVE BRAMPTON ON	S/241.0	-2.29	721
75	SPL		170 Van Kirk Drive, Brampton, ON BRAMPTON ON	S/241.0	-2.29	737
75	GEN	Sterling Specialty Chemicals	170 Van Kirk Drive Brampton ON	S/241.0	-2.29	738
76	SPL	Aztec Hydraulics Inc.	Regan Road & Vankirk Drive, Brampton ON	SSE/166.7	-4.08	738
77	SPL	ALECTRA UTILITIES CORPORATION	82 Banington Crescent, Brampton ON	WNW/174.0	9.87	739
78	SPL	GIVE AND GO PREPARED FOODS CORP.	BRAMPTON ON	SE/248.4	-6.30	740
79	GEN	THE STEVENS COMPANY LTD	425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	SE/240.0	-6.63	741
79	GEN	THE STEVENS COMPANY LTD	425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	SE/240.0	-6.63	741
79	GEN	THE STEVENS COMPANY LTD	425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	SE/240.0	-6.63	741
79	GEN	Hamilton Health Sciences Juravinski Hospital	425 Railside Drive Brampton ON L7A0N8	SE/240.0	-6.63	742
79	GEN	THE STEVENS COMPANY LTD	425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	SE/240.0	-6.63	742

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
79	GEN	Hamilton Health Sciences Corporation	Stevens Warehouse, 425 Railside Drive Brampton ON	SE/240.0	-6.63	744
80	WWIS		S/E CORNER OF MAYFIELD & MCLAUCHLIN lot 17 con 1 ON ***Well ID:*** 7043898	W/141.5	7.92	745
81	SCT	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	747
81	CA	SHERWIN-WILLIAMS CANADA, BRAMPTON FACILI	130 VAN KIRK DRIVE BRAMPTON CITY ON L7A 1B1	SSE/212.1	-3.08	747
81	SCT	The Sherwin-Williams Company - Eastern Division	130 Van Kirk Dr Brampton ON L7A 1B1	SSE/212.1	-3.08	748
81	EBR	Sherwin-Williams Canada Inc.	130 Van Kirk Drive CITY OF BRAMPTON ON	SSE/212.1	-3.08	748
81	SCT	Sherwin-Williams Canada Inc. - Eastern Division	130 Van Kirk Dr Brampton ON L7A 1B1	SSE/212.1	-3.08	748
81	GEN	SHERWIN WILLIAMS AUTO FINISHES INC	130 VAL KIRK DR. BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	749
81	GEN	SHERWIN WILLIAMS AUTO FINISHES INC11-314	130 VAL KIRK DR. BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	749
81	GEN	SHERWIN WILLIAMS AUTO FINISHES INC	130 VAL KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	749
81	GEN	SHERWIN WILLIAMS AUTO FINISHES INC.	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	750
81	GEN	SHERWIN WILLIAMS	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	750
81	GEN	CUSTOM COLOUR PAINTS LTD.	130 VAN KIRK DR. BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	751

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
81	GEN	CUSTOM COLOUR PAINTS LTD.	130 VAN KIRK DR. BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	752
81	GEN	CUSTOM (SEE & USE ON0004205)	130 VAN KIRK DR. BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	752
81	GEN	CUSTOM (SEE & USE ON0004205) 11-314	130 VAN KIRK DR. BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	752
81	GEN	CUSTOM COLOUR PAINTS (SEE&USE ON000420)	130 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	753
81	SCT	Sherwin-Williams Canada Inc. - Chemical Coatings Div.	130 Van Kirk Dr Brampton ON L7A 1B1	SSE/212.1	-3.08	753
81	SCT	Sherwin-Williams Canada Inc.	130 Van Kirk Dr Brampton ON L7A 1B1	SSE/212.1	-3.08	753
81	EBR	Sherwin-Williams Canada Inc.	130 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1B1 CITY OF BRAMPTON ON	SSE/212.1	-3.08	753
81	CA	Sherwin-Williams Canada Inc.	130 Van Kirk Dr Brampton ON L7A 1B1	SSE/212.1	-3.08	754
81	GEN	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	754
81	GEN	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	755
81	GEN	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	756
81	GEN	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	757
81	GEN	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON	SSE/212.1	-3.08	758

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
81	ECA	Sherwin-Williams Canada Inc.	130 Van Kirk Dr Brampton ON L7A 1B1	SSE/212.1	-3.08	759
81	GEN	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	760
81	GEN	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	761
81	GEN	THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	762
81	GEN	THE SHERWIN-WILLIAMS COMPANY performance coatings	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	763
81	GEN	THE SHERWIN-WILLIAMS COMPANY performance coatings	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	764
81	GEN	THE SHERWIN-WILLIAMS COMPANY performance coatings	130 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	766
81	GEN	Sherwin Williams Canada Product Finishes	130 VAN KIRK DR BRAMPTON ON	SSE/212.1	-3.08	768
81	NPR2	BRAMPTON	130 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	777
81	PFHA	BRAMPTON	130 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/212.1	-3.08	826
82	WWIS		SOUTH END RAIL SIDE DRIVE Brampton ON ***Well ID:*** 7205572	SE/168.0	-6.08	877
83	ECA	Great-L Developments Inc.	Brampton ON M2K 2S5	WNW/26.7	9.90	880
83	ECA	Partacc West Developments Inc.	Brampton ON L3R 9R9	WNW/26.7	9.90	880

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
83	ECA	Partacc West Developments Inc.	Brampton ON M3R 9R9	WNW/26.7	9.90	880
84	GEN	Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	SSE/111.8	-5.73	881
84	GEN	Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	SSE/111.8	-5.73	882
84	GEN	Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	SSE/111.8	-5.73	884
84	GEN	Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	SSE/111.8	-5.73	886
84	GEN	Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	SSE/111.8	-5.73	887
84	GEN	Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	SSE/111.8	-5.73	889
84	GEN	Regional Municipality of Peel	420 Railside Drive Brampton ON	SSE/111.8	-5.73	891
85	EASR	GIVE AND GO PREPARED FOODS CORP.	415 Railside DR Brampton ON L7L 1E1	SE/243.2	-5.08	909
86	EHS		120A Van Kirk Drive Brampton ON L7A 1B1	SSE/244.6	-3.08	909
87	EHS		120 Van Kirk Dr Brampton ON L7A 1B1	SSE/246.4	-3.08	909
88	EHS		495618 111 Van Kirk Drive Brampton Brampton ON L7A 1A4	SSE/62.1	-3.56	910
89	SCT	Exacta Fabtool Limited	120 Van Kirk Dr Brampton ON L7A 1B1	SSE/208.5	-3.08	910

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
89	SCT	Exacta Fabtool Limited - Div. of Exacta Precision Products Limited	120 Van Kirk Dr Brampton ON L7A 1B1	SSE/208.5	-3.08	910
89	GEN	EXACTA FABTOOL LIMITED	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/208.5	-3.08	910
89	SCT	Body Care Innovations	120A Van Kirk Dr Brampton ON L7A 1B1	SSE/208.5	-3.08	911
89	CA	Body Care Manufacturing Inc.	120A Van Kirk Dr Brampton ON L7A 1B1	SSE/208.5	-3.08	911
89	ECA	Body Care Manufacturing Inc.	120A Van Kirk Dr Brampton ON L7A 1B1	SSE/208.5	-3.08	911
89	GEN	Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	SSE/208.5	-3.08	912
89	GEN	WILSON TOOL CANADA	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/208.5	-3.08	912
89	GEN	Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	SSE/208.5	-3.08	913
89	GEN	WILSON TOOL CANADA	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/208.5	-3.08	913
89	GEN	Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	SSE/208.5	-3.08	913
89	GEN	Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	SSE/208.5	-3.08	914
89	GEN	WILSON TOOL CANADA	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/208.5	-3.08	914
89	GEN	Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	SSE/208.5	-3.08	915

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
89	GEN	WILSON TOOL CANADA	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/208.5	-3.08	915
89	GEN	Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	SSE/208.5	-3.08	916
89	GEN	WILSON TOOL CANADA-PRESS BRAKE DIVISION	120 Van Kirk Drive Brampton ON	SSE/208.5	-3.08	919
89	EHS		120 Van Kirk Drive Brampton ON L7A 1B1	SSE/208.5	-3.08	922
89	GEN	Total Body Care Inc.	120A Van Kirk Drive Brampton ON	SSE/208.5	-3.08	922
89	GEN	1000456356 Ontario Inc.	120 Van Kirk Drive Brampton ON	SSE/208.5	-3.08	923
90	EHS		Wanless Dr & Mclaughlin Rd N Brampton ON	W/193.0	9.85	923
91	EHS		111 Van Kirk Drive Brampton ON	SSE/74.6	-3.08	923
91	EHS		111 Van Kirk Drive Brampton ON L7A 1A4	SSE/74.6	-3.08	923
92	EHS		398 Railside Drive Brampton ON L7A 1E1	SE/110.4	-4.81	924
93	SCT	Kal-Trading Inc.	100 Van Kirk Dr Brampton ON L7A 1B1	SSE/219.2	-2.08	924
93	EASR	315594 ONTARIO INC.	100 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/219.2	-2.08	924
93	EHS		100 Van Kirk Drive Brampton ON	SSE/219.2	-2.08	924

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
94	PES	1569692 ONTARIO LTD. O/A CANADIAN GREEN	7 DELPHINIUM WAY BRAMPTON ON L7A 0N4	W/248.7	9.92	925
95	SPL	Ontario Clean Water Agency	2819 Mayfield Rd Brampton ON	WNW/197.7	13.95	925
96	WWIS		80 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7277923	SSE/208.3	-2.08	926
97	PRT	BUTCHER ENGINEERING	105 VAN KIRK DR BRAMPTON ON L7A 1A4	SSE/76.1	-3.08	929
97	EBR	The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton Ontario Brampton ON	SSE/76.1	-3.08	929
97	GEN	BUTCH ENGINEERING ENTERPRISES LTD.	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/76.1	-3.08	930
97	GEN	BUTCHER ENGINEERING ENTERPRISES LTD.	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/76.1	-3.08	930
97	GEN	BUTCH ENGINEERING ENTERPRISES LTD.06-157	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/76.1	-3.08	932
97	SPL	The Butcher Engineering Enterprises Limited	105 Van Kirk Dr Brampton ON L7A 1A4	SSE/76.1	-3.08	933
97	EHS		105 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.1	-3.08	933
97	CA	The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.1	-3.08	934
97	CA	The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.1	-3.08	934
97	NPRI	THE BUTCHER ENGINEERING ENTERPRISES LTD.	105 Van Kirk Dr. Brampton ON L7A1A4	SSE/76.1	-3.08	934

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
97	DTNK	BUTCHER ENGINEERING	105 VAN KIRK DR BRAMPTON ON	SSE/76.1	-3.08	935
97	DTNK	BUTCHER ENGINEERING	105 VAN KIRK DR BRAMPTON ON	SSE/76.1	-3.08	935
97	GEN	BUTCHER ENGINEERING ENTERPRISES LTD.	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/76.1	-3.08	936
97	GEN	BUTCHER ENGINEERING ENTERPRISES LTD.	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/76.1	-3.08	938
97	NPRI	BUTCHER ENTERPRISES	105 VanKirk Brampton ON L7A1A4	SSE/76.1	-3.08	940
97	INC		105 VAN KIRK DR, BRAMPTON ON	SSE/76.1	-3.08	940
97	SPL		105 Van Kirk Dr. Brampton ON	SSE/76.1	-3.08	941
97	ECA	The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton ON L6W 1W2	SSE/76.1	-3.08	942
97	ECA	The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton ON L6W 1W2	SSE/76.1	-3.08	942
97	EHS		105 Van Kirk Dr Brampton ON L7A1A4	SSE/76.1	-3.08	943
97	NPR2	VAN KIRK PLANT	105 VAN KIRK DR. BRAMPTON ON L7A1A4	SSE/76.1	-3.08	943
97	NPR2	VANKIRK	105 VANKIRK BRAMPTON ON L7A1A4	SSE/76.1	-3.08	980
98	RSC	SABRINA HOMES (MAYFIELD ACQUISITIONS) INC.	2719 MAYFIELD ROAD ON Brampton ON	WNW/62.6	12.15	982

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
99	WWIS		95 VAN KIRK DR Brampton ON ***Well ID:*** 7172053	SSE/163.7	-2.08	983
99	WWIS		95 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7172054	SSE/163.7	-2.08	987
99	WWIS		95 VAN KIRK DR Brampton ON ***Well ID:*** 7172055	SSE/163.7	-2.08	991
99	WWIS		95 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7172057	SSE/163.7	-2.08	994
99	WWIS		95 VAN KIRK DR Brampton ON ***Well ID:*** 7172058	SSE/163.7	-2.08	999
99	WWIS		95 VAN KIRK DR Brampton ON ***Well ID:*** 7172060	SSE/163.7	-2.08	1002
99	WWIS		95 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7172056	SSE/163.7	-2.08	1006
99	WWIS		95 VAN KIRK DR Brampton ON ***Well ID:*** 7172051	SSE/163.7	-2.08	1010
99	WWIS		95 VAN KIRK DR Brampton ON ***Well ID:*** 7172059	SSE/163.7	-2.08	1014
99	WWIS		95 VANKIRK DR Brampton ON ***Well ID:*** 7172052	SSE/163.7	-2.08	1017
100	CA	GREAT-L DEV. LTD. - LOT 17, CONC. 1 WHS	CRESTHAVEN RD./MAYFIELD RD. BRAMPTON CITY ON	WNW/247.2	14.00	1021
100	CA	GREAT-L DEV. LTD. - LOT 17, CONC. 1 WHS	CRESTHAVEN RD./MAYFIELD RD. BRAMPTON CITY ON	WNW/247.2	14.00	1021
100	CA	VAUGHANWOOD DEV. LTD. AND DENCO PROP. CA	ROBERTSON DAVIES DR/MAYFIELD BRAMPTON CITY ON	WNW/247.2	14.00	1022

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
101	WWIS		ON ***Well ID:*** 7283936	SE/130.1	-3.08	1022
102	WWIS		ON ***Well ID:*** 7294565	SSE/147.7	-2.08	1023
103	WWIS		ON ***Well ID:*** 7306218	SSE/28.0	-4.08	1024
104	ECA	The Corporation of the City of Brampton	McLaughlin Road (from Lowry Drive to Wanless Drive) Brampton ON L6Y 4R2	SSE/6.5	-3.68	1025
104	ECA	Hurontario Street GP Inc.	Brampton ON M9C 5L5	SSE/6.5	-3.68	1025
104	ECA	Hurontario Street GP Inc.	Brampton ON M9C 5L5	SSE/6.5	-3.68	1025
105	WWIS		2719 MAYFIELD ROAD lot 17 con 1 Brampton ON ***Well ID:*** 7248959	WNW/85.1	12.90	1025
106	WWIS		2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378696	WNW/9.2	12.84	1028
107	EHS		80 Van Kirk Drive Brampton ON L7A 1B1	SSE/246.1	-2.08	1030
107	GEN	Archway Marketing Service	80 Van Kirk Drive Brampton ON L7A 1B1	SSE/246.1	-2.08	1030
107	SCT	Archway Marketing Services Inc	80 Van Kirk Dr Unit 8 Brampton ON L7A 1B1	SSE/246.1	-2.08	1031
107	EHS		80 Van Kirk Drive Brampton ON	SSE/246.1	-2.08	1031
107	PINC	PIPELINE HIT - 1 ¼"	80 VAN KIRK DRIVE,UNIT 2,BRAMPTON, ON,L7A 1B1,CA	SSE/246.1	-2.08	1032

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			ON			
107	PINC	PIPELINE HIT 1 1/4"	80 VAN KIRK, UNIT 1,,BRAMPTON,ON, L7A 1B1,CA ON	SSE/246.1	-2.08	1032
107	GEN	SOTAWALL INC.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/246.1	-2.08	1033
107	GEN	SOTAWALL INC.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/246.1	-2.08	1033
107	GEN	SOTAWALL LTD.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/246.1	-2.08	1033
107	EHS		70 & 80 Van Kirk Drive Brampton ON	SSE/246.1	-2.08	1035
107	GEN	SOTAWALL LTD.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/246.1	-2.08	1035
107	GEN	SOTAWALL LTD.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/246.1	-2.08	1036
107	GEN	Harmon Facades ULC (aka Sotawall)	80 VAN KIRK DRIVE BRAMPTON ON	SSE/246.1	-2.08	1037
108	EHS		10254 Hurontario St Brampton ON	SE/157.5	-2.08	1044
108	EHS		10254 Hurontario St Brampton ON L7A0E4	SE/157.5	-2.08	1044
108	EHS		10254 Hurontario St Brampton ON L7A0E4	SE/157.5	-2.08	1044
108	RSC	10254 HURONTARIO PROPERTY INC.	10254 HURONTARIO STREET ON Brampton ON	SE/157.5	-2.08	1044

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
108	RSC	10254 HURONTARIO PROPERTY INC.	10254 HURONTARIO STREET ON Brampton ON	SE/157.5	-2.08	1045
108	EHS		10254 Hurontario St Brampton ON L7A0E4	SE/157.5	-2.08	1045
108	ECA	10254 Hurontario Property Inc.	10254 Hurontario Street Brampton ON M9C 1B8	SE/157.5	-2.08	1046
108	ECA	10254 Hurontario Property Inc.	10254 Hurontario Street Brampton ON M9C 1B8	SE/157.5	-2.08	1046
108	ECA	10254 Hurontario Property Inc.	10254 Hurontario Street Brampton ON M9C 1B8	SE/157.5	-2.08	1046
108	GEN	CT REIT (Hurontario) Limited Partnership, by its g	10254 Hurontario Street Brampton ON L7A 0E4	SE/157.5	-2.08	1047
109	EASR	GB (MAYFIELD 2) INC.	2650 Mayfield Road Caledon ON L7C 3K7	WNW/192.1	13.94	1047
110	CA	COPPERWELD CANADA, SONCO STEEL TUBE DIV.	95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1048
110	SPL	SONCO STEEL TUBE LTD.	SONCO, 95 VAN KIRK DRIVE, BRAMPTON, L6X 2M3 95 VAN KIRK DR. (HEAD OFFICE) BRAMPTON ON L6X 2M3 BRAMPTON CITY ON L7A 1A4	SSE/62.1	-3.08	1048
110	SPL	SONCO STEEL TUBE LTD.	VAN KIRK DRIVE BRAMPTON PLANT 95 VANKIRK DRIVE BRAMPTON CITY ON	SSE/62.1	-3.08	1049
110	SPL	SONCO STEEL TUBE LTD.	BRAMPTON PLANT 95 VANKIRK DRIVE BRAMPTON CITY ON	SSE/62.1	-3.08	1050
110	EBR	Copperweld Canada	95 Van Kirk Drive CITY OF BRAMPTON ON	SSE/62.1	-3.08	1051
110	EHS		95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1051

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
110	EHS		95 Van Kirk Dr. Brampton ON L7A 1A4	SSE/62.1	-3.08	1051
110	GEN	SONCO STEEL TUBE LTD	95 VANKIRK DR. BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1051
110	GEN	SONCO STEEL TUBE LTD 35-058	95 VANKIRK DR. BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1052
110	GEN	SONCO STEEL TUBE LTD.	95 VANKIRK DRIVE BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1053
110	GEN	SONCO (SEE & USE ON0164204)	95 VANKIRK DRIVE BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1053
110	GEN	LTV COPPERWELD	95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1054
110	GEN	COPPERWELD CANADA INC.	95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1054
110	EHS		95 VAN KIRK DR BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1055
110	EHS		95 Van Kirk Brampton ON L7A 1A4	SSE/62.1	-3.08	1055
110	EBR	6832458 Canada Inc.	95 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON	SSE/62.1	-3.08	1055
110	GEN	Brampton-Canada Associates Ltd.	95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1056
110	CA	6832458 Canada Inc.	95 Van Kirk Dr Brampton ON L7A 1A4	SSE/62.1	-3.08	1056
110	GEN	Brampton-Canada Associates Ltd.	95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1056

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
110	GEN	Metelix Products inc	95 Van Kirk Drive Brampton ON	SSE/62.1	-3.08	1057
110	GEN	Metelix Products inc	95 Van Kirk Drive Brampton ON	SSE/62.1	-3.08	1057
110	EHS		95 Van Kirk Drive Brampton ON	SSE/62.1	-3.08	1058
110	ECA	6832458 Canada Inc.	95 Van Kirk Dr Brampton ON J4H 3V6	SSE/62.1	-3.08	1058
110	GEN	Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1058
110	GEN	Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1059
110	GEN	Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1059
110	GEN	Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1060
110	GEN	Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1060
110	GEN	Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1061
110	GEN	METELIX PRODUCTS INC.	95 Van Kirk Drive Brampton ON	SSE/62.1	-3.08	1061
110	GEN	1955379 ONTARIO INC	95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/62.1	-3.08	1065
110	NPR2	COPPERWELD CANADA INC. - VAN KIRK DRIVE	95 VAN KIRK DRIVE BRAMPTON ON L7A1A4	SSE/62.1	-3.08	1065

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
110	SPL		behind 95 Van Kirk Drive, Brampton BRAMPTON ON	SSE/62.1	-3.08	1083
110	EHS		95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1084
110	EHS		95 Van Kirk Drive Brampton ON L7A 1A4	SSE/62.1	-3.08	1084
110	GEN	Elgner Group Investments Ltd.	95 Van Kirk Drive Brampton ON	SSE/62.1	-3.08	1084
111	WWIS		80 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7277924	SSE/191.2	-2.08	1085
112	WWIS		2650 mayfield rd con 1 Caledon ON ***Well ID:*** 7353563	WNW/30.0	13.88	1088
113	WWIS		2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378695	WNW/165.5	15.92	1090
114	WWIS		2650 MAYFIELD RD BRAMPTON ON ***Well ID:*** 7262154	WNW/174.7	15.89	1092
115	WWIS		Robertson Davies Drive & Mayfield Road lot 18 con 1 ON ***Well ID:*** 7408615	WNW/36.6	15.70	1095
116	WWIS		2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378685	WNW/26.0	15.32	1098
117	WWIS		2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378694	WNW/154.4	16.93	1100
118	EBR	GO Transit	85 Van Kirk Dr., Brampton ON CITY OF BRAMPTON ON	SSE/76.5	-3.08	1103

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
118	CA	GO a division of Metrolinx	85 Van Kirk Dr Brampton ON L7A 1A4	SSE/76.5	-3.08	1103
118	GEN	Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1103
118	GEN	Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1104
118	GEN	Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1105
118	GEN	Metrolinx	85 Van Kirk Drive Brampton ON	SSE/76.5	-3.08	1105
118	CFOT	METROLINX O/A GO TRANSIT	85 VAN KIRK DR BRAMPTON ON	SSE/76.5	-3.08	1106
118	ECA	GO a division of Metrolinx	85 Van Kirk Dr Brampton ON M5J 2W3	SSE/76.5	-3.08	1106
118	GEN	Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1106
118	GEN	Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1107
118	GEN	Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1108
118	GEN	Metrolinx GO Transit	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1109
118	GEN	Metrolinx GO Transit	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1109
118	GEN	Metrolinx GO Transit	85 Van Kirk Drive Brampton ON L7A 1A4	SSE/76.5	-3.08	1110

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
118	GEN	Metrolinx - Bus	85 Van Kirk Drive Brampton ON	SSE/76.5	-3.08	1111
118	ECA	Metrolinx	85 Van Kirk Dr Brampton ON M5J 3A5	SSE/76.5	-3.08	1115
119	WWIS		70 VAN KIRK DR Brampton ON ***Well ID:*** 7347856	SSE/207.0	-2.08	1116
120	SCT	N.H.D. GROUP LTD.	70 VAN KIRK DR BRAMPTON ON L7A 1B1	SSE/233.5	-2.08	1119
120	SCT	NHD GROUP LTD.	70 Van Kirk Dr Brampton ON L7A 1B1	SSE/233.5	-2.08	1119
120	GEN	NHD GROUP LTD.	70 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/233.5	-2.08	1120
120	GEN	NHD GROUP LTD. 28-640	70 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/233.5	-2.08	1120
120	GEN	N.H.D. GROUP LTD.	70 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	SSE/233.5	-2.08	1121
120	EASR	SOTAWALL LIMITED	70 Van Kirk DR Brampton ON L7A 1B1	SSE/233.5	-2.08	1121
121	PINC	PIPELINE HIT 1/2"	21 ROBERTSON DAVIES DR,, BRAMPTON,ON,L7A 1K4,CA ON	WNW/235.2	14.92	1121
122	EHS		75 Van Kirk Drive Brampton ON L7A 1A4	SSE/49.2	-2.08	1122
122	RSC	Brampton-Canada Associates Ltd.	75 VAN KIRK DR ON BRAMPTON ON	SSE/49.2	-2.08	1122
122	EHS		75 Van Kirk Dr Brampton ON	SSE/49.2	-2.08	1122

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
123	SCT	Master Link Marketing Inc.	26 Robertson Davies Dr Brampton ON L7A 1J9	WNW/175.6	15.92	1123
123	SPL		26 Robertson Davies Drive Brampton, ON BRAMPTON ON	WNW/175.6	15.92	1123
124	WWIS		ON ***Well ID:*** 7164666	SSE/91.6	-2.08	1124
124	WWIS		ON ***Well ID:*** 7169172	SSE/91.6	-2.08	1125
125	GEN	Exel Canada Ltd. c/o Keurig Canada	100 Ironside Dr. Unit 1 Brampton ON L4A0X4	SE/180.2	-3.15	1126
125	GEN	DHL Supply Chain	100 Ironside Dr. Unit 1 Brampton ON L4A0X4	SE/180.2	-3.15	1126
126	WWIS		2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378698	WNW/17.7	17.92	1127
127	RSC	LORMEL JOINT VENTURE INC.	No Municipal Address Caledon ON	WNW/140.8	16.86	1129
128	EHS		2650 Mayfield Rd Brampton ON L7C 3K7	WNW/140.1	16.84	1129
129	PES	2582011 ONTARIO INC. O/A TRULY NOLEN	32 BAYBROOK RD BRAMPTON ON L7A1M1	WNW/248.1	14.95	1130
129	PES	2582011 ONTARIO INC.	32 BAYBROOK RD BRAMPTON ON L7A 1M1	WNW/248.1	14.95	1130
129	PES	2582011 ONTARIO INC.	32 BAYBROOK RD BRAMPTON ON L7A 1M1	WNW/248.1	14.95	1130
130	WWIS		6152 PENETANGUISHENE RD Springwater ON ***Well ID:*** 7220338	WNW/86.2	17.79	1131

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
131	NPCB	ARMBRO CONSTRUCTION	45 VAN KIRK RD BRAMPTON ON L7A 1A6	SSE/172.8	-2.08	1134
131	NPCB	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD VAN KIRK RD BRAMPTON ON L7A 1A6	SSE/172.8	-2.08	1134
131	OPCB	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1135
131	OPCB	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1135
131	OPCB	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1135
131	OPCB	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1136
131	OPCB	ARMBRO CONSTRUCTION	45 VAN KIRK RD BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1136
131	GEN	ARMBRO CONSTRUCTION 02-735	45 VAN KIRK DRIVE C/O 25 VAN KIRK DRIVE, UNIT #8 BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1137
131	GEN	ARMBRO CONSTRUCTION	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1137
131	GEN	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1138
131	GEN	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1138
131	GEN	AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON	SSE/172.8	-2.08	1139
131	OPCB	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1139

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
131	EBR	Aecon Construction and Materials Limited	45 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1A6 CITY OF BRAMPTON ON	SSE/172.8	-2.08	1140
131	EBR	Strada Crush Limited	45 Van Kirk Road Brampton Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	SSE/172.8	-2.08	1140
131	SPL	Petro-Canada	45 Vankirk Dr. Brampton ON L7A 1A4	SSE/172.8	-2.08	1141
131	NPCB	ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1141
131	EBR	Strada Aggregates Inc.	45 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON	SSE/172.8	-2.08	1142
131	CA	Strada Aggregates Inc.	45 Van Kirk Rd Brampton ON L7A 1A4	SSE/172.8	-2.08	1142
131	CA	Aecon Construction and Materials Limited	45 Van Kirk Dr Brampton ON L7A 1A4	SSE/172.8	-2.08	1143
131	GEN	AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1143
131	EBR	Aecon Construction and Materials Limited	45 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A6 CITY OF BRAMPTON ON	SSE/172.8	-2.08	1144
131	EBR	Aecon Construction and Materials Limited/Construction et Materiaux Aecon Limitee	45 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON	SSE/172.8	-2.08	1144
131	GEN	AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1144
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1145

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
131	GEN	AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1145
131	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	45 Van Kirk Dr Brampton ON	SSE/172.8	-2.08	1146
131	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	45 Van Kirk Dr Brampton ON	SSE/172.8	-2.08	1146
131	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	45 Van Kirk Dr Brampton ON	SSE/172.8	-2.08	1147
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1147
131	GEN	AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	SSE/172.8	-2.08	1147
131	NPRI	STRADA AGGREGATES	45 VANKIRK Avenue BRAMPTON ON L1L6G6	SSE/172.8	-2.08	1148
131	NPRI	STRADA AGGREGATES	45 VANKIRK Avenue BRAMPTON ON L1L6G6	SSE/172.8	-2.08	1149
131	NPRI	STRADA AGGREGATES	45 VANKIRK Avenue BRAMPTON ON L1L6G6	SSE/172.8	-2.08	1150
131	GEN	AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON	SSE/172.8	-2.08	1151
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON	SSE/172.8	-2.08	1152
131	ECA	Aecon Construction and Materials Limited/Construction et Materiaux Aecon Limitee	45 Van Kirk Dr Brampton ON L7A 1A9	SSE/172.8	-2.08	1152
131	ECA	Strada Aggregates Inc.	45 Van Kirk Rd Brampton ON L4K 1L3	SSE/172.8	-2.08	1152

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
131	ECA	Aecon Construction and Materials Limited	45 Van Kirk Dr Brampton ON M9W 7K6	SSE/172.8	-2.08	1153
131	GEN	AECON CONSTRUCTION AND MATERIALS LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	SSE/172.8	-2.08	1153
131	GEN	AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	SSE/172.8	-2.08	1154
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1154
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1155
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1155
131	GEN	AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	SSE/172.8	-2.08	1155
131	GEN	AECON CONSTRUCTION AND MATERIALS LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	SSE/172.8	-2.08	1156
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1157
131	NCPL	Aecon Construction and Materials Limited	45 Van Kirk Dr Brampton ON	SSE/172.8	-2.08	1157
131	GEN	AECON CONSTRUCTION AND MATERIALS LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	SSE/172.8	-2.08	1157
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1158
131	GEN	AECON CONSTRUCTION AND MATERIALS LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	SSE/172.8	-2.08	1159

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1159
131	GEN	GIP Constructions and Materials Limited	45 VAN KIRK DRIVE BRAMPTON ON	SSE/172.8	-2.08	1160
131	GEN	SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1163
131	EBR	GIP Construction and Materials Limited	45 Van Kirk Drive Brampton, ON L7A 1A6 Canada ON	SSE/172.8	-2.08	1166
131	NPR2	BRAMPTON ASPHALT PLANT	45 VAN KIRK DRIVE BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1166
131	NPR2	PORTABLE PLANT #3	45 VAN KIRK DRIVE BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1181
131	NPR2	PORTABLE PLANT #2	45 VAN KIRK DRIVE BRAMPTON ON L7A1A6	SSE/172.8	-2.08	1191
131	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	45 Van Kirk Dr Brampton ON	SSE/172.8	-2.08	1203
132	EHS		Brampton Asphalt Plant Brampton ON L7A 1C7	SSE/153.8	-2.08	1204
133	EHS		55 Van Kirk Dr, 45 Van kirk Dr, 12 Canam Crescent Brampton ON L7A 1A9	SSE/151.8	-2.08	1204
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447535	SE/59.7	-4.12	1204
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447522	SE/59.7	-4.12	1207
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON	SE/59.7	-4.12	1211

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7447520			
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447534	SE/59.7	-4.12	1214
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447538	SE/59.7	-4.12	1217
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447544	SE/59.7	-4.12	1220
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447540	SE/59.7	-4.12	1224
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447539	SE/59.7	-4.12	1227
134	WWIS		55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447523	SE/59.7	-4.12	1230
135	PES	VERDE PROPERTY MAINTENANCE LTD	25 VIRGINIA DR BRAMPTON ON L7A 2E6	WNW/61.6	17.92	1234
135	PES	VERDE PROPERTY MAINTENANCE LTD	25 VIRGINIA DR BRAMPTON ON L7A2E6	WNW/61.6	17.92	1234
135	PES	VERDE PROPERTY MAINTENANCE LTD	25 VIRGINIA DR BRAMPTON ON L7A2E6	WNW/61.6	17.92	1234
135	PES	VERDE PROPERTY MAINTENANCE LTD	25 VIRGINIA DR BRAMPTON ON L7A2E6	WNW/61.6	17.92	1235
136	ECA	2066650 Ontario Inc.	Brampton ON M5C 1T4	SE/5.8	-5.88	1235
136	ECA	2066650 Ontario Inc.	Brampton ON M5C 1T4	SE/5.8	-5.88	1235
136	ECA	The Regional Municipality of Peel	Brampton ON L6T 4B9	SE/5.8	-5.88	1236

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
136	ECA	2066650 Ontario Inc.	Brampton ON M5C 1T4	SE/5.8	-5.88	1236
136	ECA	City of Toronto	Brampton ON M5V 3C6	SE/5.8	-5.88	1236
137	WWIS		ON ***Well ID:*** 7396621	SSE/212.2	-3.09	1237
138	WWIS		lot 11 con 1 ON ***Well ID:*** 4901582	SSE/160.6	-3.30	1238
139	WWIS		2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378693	WNW/248.4	16.93	1240
140	SCT	HAULTEC TRAILERS LTD	12 CANAM CRES BRAMPTON ON L7A 1A9	SE/141.4	-3.99	1243
140	GEN	AMBRO DIESEL SALES AND SERVICE	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	SE/141.4	-3.99	1243
140	GEN	AMBRO DIESEL SALES AND SERVICE	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	SE/141.4	-3.99	1243
140	GEN	AMBRO DIESEL SALES AND SERVICE 03-260	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	SE/141.4	-3.99	1244
140	GEN	ROTO-MILL SERVICES LTD.	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	SE/141.4	-3.99	1244
140	GEN	ROTO-MILL SERVICES LIMITED	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	SE/141.4	-3.99	1245
140	SPL	Roto Mill Services Ltd.	12 Canam Crescent, Brampton Brampton ON L7A 1A9	SE/141.4	-3.99	1245
140	GEN	Aecon Group Inc	12 Canam Cres Brampton ON L7A 1A9	SE/141.4	-3.99	1246

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
140	WWIS		12 CANAM CRES lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447531	SE/141.4	-3.99	1246
140	WWIS		12 CANAM CRES lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447521	SE/141.4	-3.99	1249
140	WWIS		12 CANAM CRES lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447532	SE/141.4	-3.99	1253
140	WWIS		12 CANAM CRES lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447524	SE/141.4	-3.99	1256
141	SCT	C.M.X. CORPORATION	35 VAN KIRK DR UNIT 12 BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1259
141	SCT	W.A. Whitney of Canada Ltd.	35 Van Kirk Dr Unit 14 Brampton ON L7A 1A5	SSE/245.9	-3.76	1259
141	SPL	PETRO-CANADA	35 VANKIRK DR SERVICE STATION BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1260
141	SCT	C.M.X. Corporation - Valcom Paging	35 Van Kirk Dr Unit 12 Brampton ON L7A 1A5	SSE/245.9	-3.76	1261
141	SCT	Adhesifs Adhpro Inc.	35 Van Kirk Dr Unit 19B Brampton ON L7A 1A5	SSE/245.9	-3.76	1261
141	GEN	CANADIAN MINE DEVELOPMENT	BEHIND 35 VAN KIRK DR. BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1261
141	GEN	CANADIAN MINE DEVELOPMENT	BEHIND 35 VAN KIRK DR. BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1261
141	GEN	CANADIAN MINE DEVELOPMENT 08-349	BEHIND 35 VAN KIRK DR. BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1262
141	GEN	BRAMPTON GUARD(OUT OF BUSINESS) 05-804	35 VAN KIRK DRIVE, UNIT 17 BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1262

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VANKIRK DRIVE, UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1262
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1263
141	SCT	CMX Corporation - Valcom	35 Van Kirk Dr Unit 12 Brampton ON L7A 1A5	SSE/245.9	-3.76	1263
141	SCT	Classifier Milling Systems	35 Van Kirk Dr Unit 17 Brampton ON L7A 1A5	SSE/245.9	-3.76	1264
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1264
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1265
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1265
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1265
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON	SSE/245.9	-3.76	1266
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1266
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1267
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1267
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1268

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
141	GEN	ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	SSE/245.9	-3.76	1268
141	GEN	Mantella Corporation	35 Van Kirk Drive Brampton ON	SSE/245.9	-3.76	1270
142	EHS		20 & 30 Ironside Drive (formerly 190 Bovaird Drive) Brampton ON L7A 1A2	SE/164.0	-9.08	1270
143	EHS		190 BOVAIRD DR W Brampton ON L7A 1A2	SE/172.1	-9.08	1270
144	EHS		190 Bovaird Drive W, Brampton Brampton ON L7A 1A2	SE/167.1	-9.08	1270
145	WWIS		lot 11 con 1 ON ***Well ID:*** 4901581	SE/180.2	-5.15	1271
146	SCT	TORODE PRECISION COMPONENTS	190 HIGHWAY 7 W SUITE 52 BRAMPTON ON L7A 1A2	SE/147.3	-9.89	1273
146	RST	NORTHWOOD PARK SERVICE CENTRE INC	190 HIGHWAY 7 W BRAMPTON ON L7A1A2	SE/147.3	-9.89	1274
146	SCT	Torode Precision Components Inc.	190 Highway 7 W Unit 52 Brampton ON L7A 1A2	SE/147.3	-9.89	1274
146	SCT	Gaio Fabricating Inc.	190 Bovaird Dr W Unit 22 Brampton ON L7A 1A2	SE/147.3	-9.89	1274
146	SCT	Marklyn Group	190 Bovaird Dr W Unit 28 Brampton ON L7A 1A2	SE/147.3	-9.89	1274
146	SCT	Torode Precision Components	190 Bovaird Dr W Unit 52 Brampton ON L7A 1A2	SE/147.3	-9.89	1275
146	GEN	PACEMARATHON MOTOR LINES	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1275

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	SE/147.3	-9.89	1276
146	EBR	1480411 Ontario Inc.	190 Bovaird Drive West Brampton Regional Municipality of Peel L7A 1A2 CITY OF BRAMPTON ON	SE/147.3	-9.89	1276
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1276
146	CA	1480411 Ontario Inc.	190 Bovaird Dr W Brampton ON L7A 1A2	SE/147.3	-9.89	1277
146	SCT	Dor-Control Craftsmen Limited	190 Bovaird Dr W Unit 17 Brampton ON L7A 1A2	SE/147.3	-9.89	1277
146	SCT	Estate Lighting Supply Ltd.	190 Bovaird Dr W Unit 54 Brampton ON L7A 1A2	SE/147.3	-9.89	1278
146	ECA	Call Disposal Services Ltd.	190 Bovaird Dr W Unit #25-26R Brampton ON L9T 7T5	SE/147.3	-9.89	1278
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1278
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	SE/147.3	-9.89	1279
146	GEN	SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A 1A2	SE/147.3	-9.89	1279
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1279
146	GEN	SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A 1A2	SE/147.3	-9.89	1280

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	SE/147.3	-9.89	1280
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1281
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	SE/147.3	-9.89	1281
146	GEN	SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A 1A2	SE/147.3	-9.89	1282
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1282
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON	SE/147.3	-9.89	1282
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON	SE/147.3	-9.89	1283
146	GEN	KENCO MECHANICAL MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON	SE/147.3	-9.89	1283
146	ECA	1480411 Ontario Inc.	190 Bovaird Dr W Brampton ON L7A 2Y4	SE/147.3	-9.89	1284
146	GEN	SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A1A2	SE/147.3	-9.89	1284
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1285
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	SE/147.3	-9.89	1285
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1285

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
146	GEN	KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	SE/147.3	-9.89	1286
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	SE/147.3	-9.89	1286
146	GEN	SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A1A2	SE/147.3	-9.89	1287
146	GEN	KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	SE/147.3	-9.89	1287
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1288
146	GEN	SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A1A2	SE/147.3	-9.89	1288
146	GEN	KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	SE/147.3	-9.89	1289
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	SE/147.3	-9.89	1289
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1289
146	GEN	Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	SE/147.3	-9.89	1290
146	GEN	KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	SE/147.3	-9.89	1292
146	GEN	SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A1A2	SE/147.3	-9.89	1292
146	GEN	Kris Kay Truck Lines	190 Bovaird Dr. W #32 Brampton ON L7A 1A2	SE/147.3	-9.89	1293

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
146	EHS		190 Bovaird Dr W Brampton ON L7A1A2	SE/147.3	-9.89	1294
146	PES	SDH INC. O/A CLINTAR OUTDOOR SERVICES	15 - 190 BOVAIRD DR W BRAMPTON ON L7A1A2	SE/147.3	-9.89	1294
146	PES	SDH INC.	190 Bovaird DR W Brampton ON L7A 1A2	SE/147.3	-9.89	1294
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1295
146	GEN	SDH Inc	190 Bovaird Drive West Unit 15 Brampton ON L7A 1A2	SE/147.3	-9.89	1295
146	GEN	KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	SE/147.3	-9.89	1296
146	PES	SDH INC.	190 Bovaird DR W Brampton ON L7A 1A2	SE/147.3	-9.89	1296
146	GEN	JSS Solvents Inc.	190 Bovaird Dr. West Unit #38 Brampton ON L7A1A2	SE/147.3	-9.89	1297
146	GEN	KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	SE/147.3	-9.89	1297
146	GEN	SDH Inc	190 Bovaird Drive West Unit 15 Brampton ON L7A 1A2	SE/147.3	-9.89	1300
146	GEN	1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	SE/147.3	-9.89	1300
146	GEN	SDH Inc	190 Bovaird Drive West Unit 15 Brampton ON L7A 1A2	SE/147.3	-9.89	1305

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
146	GEN	Maple Reinders Constructors	190 Bovaird Rd W Brampton ON L7A 1A2	SE/147.3	-9.89	1308
147	SPL	Attrell Toyota	110 Canam Crescent (Bovaird and VanKirk) Brampton ON	SE/49.6	-8.08	1308
147	GEN	Attrell Toyota	110 Canam Drive Brampton ON L7A 2A9	SE/49.6	-8.08	1309
147	SPL	Accuworx	110 Canam Crescent, Brampton, ON L7A 1A9 BRAMPTON ON	SE/49.6	-8.08	1310
147	GEN	Brenntag Canada Inc	110 Canam Crescent Brampton ON	SE/49.6	-8.08	1311
148	GEN	Kia of Brampton	9 Canam cres. Brampton ON L7A 1G1	SSE/246.6	-5.35	1311
149	WWIS		190 bovaird dr w. brampton lot 11 con 1 Brampton ON ***Well ID:*** 7329307	SE/104.3	-10.08	1311
150	WWIS		223 BOVAIRD DR W Brampton ON ***Well ID:*** 7284163	SE/129.9	-11.08	1315
151	WWIS		HUTCHINSON FARM LN lot 19 con 1 CALEDON ON ***Well ID:*** 7321774	WNW/11.6	17.84	1318
152	EHS		Bovaird Brampton ON	SE/71.9	-10.93	1321
153	GEN	Chrysler Group LLC	190 Canam Crescent Brampton ON	SE/230.9	-8.95	1321
153	EHS		190 Canam Cres Brampton ON L7A1A9	SE/230.9	-8.95	1322
153	EASR	1035312 ONTARIO LIMITED	190 CANAM BRAMPTON ON	SE/230.9	-8.95	1322

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
153	EASR	1035312 ONTARIO LIMITED	190 CANAM CRES BRAMPTON ON L7A 1A9	SE/230.9	-8.95	1322
154	WWIS		ON ***Well ID:*** 7179434	SE/126.5	-11.08	1322
155	WWIS		MANETT CRESENT Brampton ON ***Well ID:*** 7191506	SE/130.0	-11.08	1323
156	WWIS		MANNETT CRESENT Brampton ON ***Well ID:*** 7191505	SE/78.3	-11.87	1325
157	WWIS		PART OF LOT 20, CONCESSION 1 WHS CALEDON ON ***Well ID:*** 7265666	WNW/113.7	16.92	1327
158	WWIS		MANETT CRESENT Brampton ON ***Well ID:*** 7191504	SE/27.5	-11.92	1330
159	EASR	MANETT RESIDENCES INC.	100 Manett Crescent Brampton ON L6X 4X4	SE/95.0	-12.08	1332
159	GEN	1737126 Ont Inc.	100 Manett Cres. Brampton ON L6X 4X4	SE/95.0	-12.08	1332
159	SPL	ENBRIDGE INC	100 Manett Crescent, Brampton BRAMPTON ON	SE/95.0	-12.08	1333
159	EHS		100 Manett Crescent Brampton ON L6X 4P7	SE/95.0	-12.08	1334
160	WWIS		MANETT CRESCENT Brampton ON ***Well ID:*** 7191501	SE/122.4	-11.90	1334
161	WWIS		MANETT CRESCENT Brampton ON ***Well ID:*** 7191502	SE/67.9	-12.08	1336
162	EHS		0 Manett Crescent Brampton ON	SE/87.1	-12.08	1338

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
163	WWIS		MANETT CRESCENT Brampton ON ***Well ID:*** 7191503	SE/28.2	-12.08	1338
164	CA	LDASK MBC CORP., KORETZ ESTATES LTD.	MANETT CRES./TESSLER CRES. BRAMPTON CITY ON	SE/153.5	-11.08	1340
164	CA	LDASK MBC CORP., KORETZ ESTATES LTD.	MANETT CRES./TESSLER CRES. BRAMPTON CITY ON	SE/153.5	-11.08	1341
165	BORE		ON	SE/85.7	-12.08	1341
166	PINC		70 Tessler Crescent, Brampton ON	SE/199.4	-11.01	1342
167	SPL	UNKNOWN	STORM SEWER AT 194 ECCLESTONE DR. BRAMPTON CITY ON L6X 3P5	SE/103.1	-12.08	1342
168	PES	SPECIALIST PEST CONTROL SERVICES	106 RICHWOOD CRES. BRAMPTON ON L6X 4K7	SE/163.6	-13.09	1343
168	PES	SPECIALIST PEST CONTROL SERVICES	106 RICHWOOD CRES. BRAMPTON ON L6X 4K7	SE/163.6	-13.09	1344
168	PES	8016917 CANADA INC.	106 RICHWOOD CRES BRAMPTON ON L6X4K7	SE/163.6	-13.09	1344
168	PES	8016917 CANADA INC. O/A PEST CONTROL COMPANY GTA	106 RICHWOOD CRES BRAMPTON ON L6X4K7	SE/163.6	-13.09	1344
168	PES	8016917 CANADA INC.	106 Richwood Cres Brampton ON L6X 4K7	SE/163.6	-13.09	1345
168	PES	SPECIALIST PEST CONTROL SERVICES	106 RICHWOOD CRES. BRAMPTON ON L6X4K7	SE/163.6	-13.09	1345

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
168	PES	8016917 CANADA INC.	106 RICHWOOD CRES BRAMPTON ON L6X4K7	SE/163.6	-13.09	1346
168	PES	SPECIALIST PEST CONTROL SERVICES	106 RICHWOOD CRES. BRAMPTON ON L6X4K7	SE/163.6	-13.09	1346
168	PES	8016917 CANADA INC.	106 Richwood Cres Brampton ON L6X 4K7	SE/163.6	-13.09	1346
169	ECA	The Regional Municipality of Peel	Bovaird Road (95m east of Sunforest Drive to 200m west of McLaughlin Road) Brampton ON	SE/8.8	-12.08	1347
169	ECA	The Regional Municipality of Peel	Bovaird Drive Brampton ON L6T 4B9	SE/8.8	-12.08	1347
170	BORE		ON	SE/236.8	-13.12	1347
171	PES	GREENLAND VIEW LANDSCAPING	48 HORSHAM STREET BRAMPTON ON L6X 3R2	SE/169.4	-11.08	1349
171	PES	GREENLAND VIEW LANDSCAPING	48 HORSHAM ST BRAMPTON ON L6X 3R2	SE/169.4	-11.08	1349
171	PES	GREENLAND VIEW LANDSCAPING	48 HORSHAM ST BRAMPTON ON L6X3R2	SE/169.4	-11.08	1349
171	PES	GREENLAND VIEW LANDSCAPING	48 HORSHAM ST BRAMPTON ON L6X3R2	SE/169.4	-11.08	1350
172	WWIS		lot 19 con 1 ON ***Well ID:*** 4904556	WNW/165.9	15.92	1350
173	PES	Supreme Pest Control Corporation	12 RICHWOOD CRES BRAMPTON ON L6X 4K9	SE/183.4	-14.33	1354
173	PES	Supreme Pest Control Corporation	12 RICHWOOD CRES BRAMPTON ON L6X 4K9	SE/183.4	-14.33	1355

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
173	PES	Supreme Pest Control Corporation	12 RICHWOOD CRES BRAMPTON ON L6X 4K9	SE/183.4	-14.33	1355
173	PES	Supreme Pest Control Corporation	12 RICHWOOD CRES BRAMPTON ON L6X 4K9	SE/183.4	-14.33	1355
174	SCT	PAKISTANI ELECTR & PRINT MEDIA	17 BURNHOPE DR BRAMPTON ON L6X 3R9	SE/189.0	-12.03	1356
175	EHS		12461 Mclaughlin Rd Caledon ON L7C2A8	WNW/18.9	16.92	1356
176	EHS		12461 McLaughlin Road Kleinburg ON L7C 2A8	WNW/11.6	16.92	1356
177	BORE		ON	SE/59.9	-16.06	1356
178	GEN	The Everlast Group	12461 Mclaughlin Road Caledon ON	WNW/238.5	16.94	1358
179	WWIS		ON ***Well ID:*** 7308412	WNW/158.8	14.50	1358
180	WWIS		lot 20 con 1 ON ***Well ID:*** 4904291	WNW/181.0	18.67	1359
181	WWIS		lot 21 con 1 ON ***Well ID:*** 4901624	WNW/194.2	19.29	1363
182	WWIS		Moore Street & Burton Road lot 9 con 1 Brampton ON ***Well ID:*** 7378803	SE/66.4	-20.12	1366
183	SPL	ALECTRA UTILITIES CORPORATION	107 Saddletree trail ON	SE/190.2	-21.08	1369
184	EHS		Williams Parkway Brampton ON	SE/15.5	-21.11	1370

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
185	WWIS		ON **Well ID:** 7312145	SE/27.2	-21.08	1370
186	WWIS		WILLIAMS PARKWAY BRAMPTON ON **Well ID:** 7312128	SE/41.3	-21.08	1371
187	WWIS		lot 21 con 2 ON **Well ID:** 4901721	WNW/184.2	17.06	1373
188	WWIS		lot 21 con 1 ON **Well ID:** 4901621	WNW/195.4	17.24	1376
189	WWIS		Moore Street & Burton Road lot 8 con 1 Brampton ON **Well ID:** 7380773	SE/73.7	-20.54	1378
190	EHS		Old School Rd And Mclaughlin Rd Caledon ON	WNW/200.4	18.93	1382
191	WWIS		Moore Street & Burton Road lot 8 con 1 Brampton ON **Well ID:** 7378802	SE/183.2	-19.43	1382
192	SCT	Mirage Digital Printing	144 Martindale Cres Brampton ON L6X 2V2	SE/29.4	-22.10	1385
193	WWIS		OLD SCHOOL ROAD lot 21 con 1 BRAMPTON ON **Well ID:** 7300314	WNW/5.5	16.86	1385
194	SPL	The Regional Municipality of Peel	69 Moore Street Brampton ON	SE/43.5	-21.08	1388
195	WWIS		Moore Street & Burton Road lot 8 con 1 Brampton ON **Well ID:** 7378801	SE/150.6	-20.08	1389
196	WWIS		lot 21 con 2 ON **Well ID:** 4901723	WNW/212.0	17.92	1392
197	WWIS		lot 21 con 1 ON **Well ID:** 4901623	WNW/204.7	17.92	1394

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
198	WWIS		Moore Street & Burton Road lot 8 con 1 Brampton ON ***Well ID:*** 7380774	SE/68.7	-21.25	1398
199	SPL		45 Moore St, Brampton BRAMPTON ON	SE/37.0	-22.08	1402
200	WWIS		lot 21 con 1 ON ***Well ID:*** 4901622	WNW/200.8	18.92	1403
201	WWIS		lot 21 con 2 ON ***Well ID:*** 4901722	WNW/209.2	18.92	1405
202	PRT	GAS ALY LTD	370 MAIN ST N BRAMPTON ON L6V4A4	ESE/242.8	-26.32	1408
202	PES	TOWERS DEPARTMENT STORE STORE #46	370 MAIN STREET NORTH BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1408
202	SCT	REPROTECH PRINTING SERVICE	370 MAIN ST N BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1408
202	SCT	DIRECTORIES INTERNATIONAL LTD	370 MAIN ST N BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1409
202	RST	SUNOCO GAS BAR	370 MAIN ST N BRAMPTON ON L6V4A4	ESE/242.8	-26.32	1409
202	GEN	SUNOCO INC.	370 MAIN STREET BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1409
202	GEN	BRIDLEWOOD CLEANERS	604575 ONTARIO LTD. 370 MAIN STREET NORTH BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1410
202	GEN	BRIDLEWOOD CLEANERS, 604575 ONTARIO LTD.	370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	ESE/242.8	-26.32	1410
202	GEN	BRIDLEWOOD CLEANERS 06-096	604575 ONTARIO LTD. 370 MAIN STREET NORTH BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1410

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
202	GEN	BRIDLEWOOD CLEANERS	370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	ESE/242.8	-26.32	1411
202	GEN	GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.	SUPER FRESH #098 370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	ESE/242.8	-26.32	1411
202	GEN	434173 ONTARIO LTD.	O/A BRIDLEWOOD DRY CLEANERS 370 MAIN ST. SOUTH BRAMPTON ON L6V 1P8	ESE/242.8	-26.32	1411
202	GEN	BRIDLEWOOD DRY CLEANERS	370 MAIN STREET BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1412
202	GEN	FIRST QUALITY 1 HOUR PHOTO 15-680	370 MAIN STREET BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1412
202	GEN	434173 ONTARIO LTD. 43-172	O/A BRIDLEWOOD DRY CLEANERS 370 MAIN ST. SOUTH BRAMPTON ON L6V 1P8	ESE/242.8	-26.32	1412
202	GEN	BRIDLEWOOD DRY CLEANERS	370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	ESE/242.8	-26.32	1413
202	GEN	KINGSPOINT PROPERTY	370 MAIN ST. BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1413
202	RST	SUNOCO INC	370 MAIN ST N BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1414
202	GEN	Suncor Energy Products	370 MAIN STREET BRAMPTON ON	ESE/242.8	-26.32	1414
202	PES	GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED	370 MAIN ST N BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1414
202	GEN	The Cannington Group Inc	370 Main Street Brampton ON L6V 4A4	ESE/242.8	-26.32	1415

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
202	FSTH	1451134 ONTARIO LTD	370 MAIN ST N BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1415
202	EHS		370 Main Street North Brampton ON L6V 4A4	ESE/242.8	-26.32	1416
202	PES	GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED	370 MAIN ST N BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1416
202	EHS		370 Main Street North Brampton ON L6V 4A4	ESE/242.8	-26.32	1416
202	DTNK	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1416
202	DTNK	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1417
202	GEN	Suncor Energy Products	370 MAIN STREET BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1418
202	PES	GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED	370 MAIN ST N BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1418
202	NPRI	THE GREAT ATLANTIC & PACIFIC COMPANY OF CANAD	370 MAIN Street North BRAMPTON ON L6V1P8	ESE/242.8	-26.32	1419
202	GEN	9495088 Canada Inc	370 Main St N Brampton ON L6V 4A4	ESE/242.8	-26.32	1421
202	PES	GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED	370 MAIN ST N BRAMPTON ON L6V4A4	ESE/242.8	-26.32	1422
202	DTNK		370 MAIN ST N BRAMPTON ON L6V 4A4	ESE/242.8	-26.32	1422
202	EXP	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1423

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
202	EXP	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1423
202	EXP	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1423
202	EXP	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1424
202	EXP	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1424
202	EXP	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1424
202	EXP	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1424
202	EXP	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	ESE/242.8	-26.32	1425
203	GEN	Alectra Utilities Corporation	8 Martindale Crescent Brampton ON	SE/222.3	-23.08	1425
204	PES	JOHN PALUMBO PHARMACY LTD. O/A SHOPPERS DRUG MART #1353	366 MAIN STREET N BRAMPTON ON L6V1P8	SE/248.5	-24.00	1425
204	GEN	Counsel Kingspoint Ltd.	366 Main St. Brampton ON	SE/248.5	-24.00	1426
204	PES	JOHN PALUMBO PHARMACY LTD. O/A SHOPPERS DRUG MART #1353	366 MAIN STREET N BRAMPTON ON L6V1P8	SE/248.5	-24.00	1426
204	GEN	John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	SE/248.5	-24.00	1426

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
204	GEN	WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	SE/248.5	-24.00	1427
204	GEN	WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	SE/248.5	-24.00	1427
204	GEN	John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	SE/248.5	-24.00	1428
204	GEN	WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	SE/248.5	-24.00	1428
204	GEN	John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	SE/248.5	-24.00	1428
204	GEN	WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	SE/248.5	-24.00	1429
204	GEN	Queen Square Family Health Team	366 Main Street North Suite 203 Brampton ON L6V 1P8	SE/248.5	-24.00	1429
204	GEN	John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	SE/248.5	-24.00	1430
204	GEN	Queen Square Family Health Team	366 Main Street North Suite 203 Brampton ON L6V 1P8	SE/248.5	-24.00	1430
204	GEN	WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	SE/248.5	-24.00	1430
204	PES	JOHN PALUMBO PHARMACY LTD.	366 Main ST N Brampton ON L6V 1P8	SE/248.5	-24.00	1431
204	GEN	John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	SE/248.5	-24.00	1431
204	GEN	Queen Square Family Health Team	366 Main Street North Suite 203 Brampton ON L6V 1P8	SE/248.5	-24.00	1432

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
204	GEN	WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	SE/248.5	-24.00	1432
204	GEN	Samara Al Windawi	366 Main Street North, Suite 203 Brampton ON	SE/248.5	-24.00	1434
204	GEN	Shoppers Drug Mart 1353	366 MAIN STREET NORTH BRAMPTON ON	SE/248.5	-24.00	1438
204	GEN	Shoppers Drug Mart #1353	366 Main Street North Brampton ON	SE/248.5	-24.00	1442
205	SPL	ALECTRA UTILITIES CORPORATION	BRAMPTON ON	SE/221.4	-23.08	1442
206	SCT	MICHAEL SCOTT INC.	22 WIMBLEDON CRT BRAMPTON ON L6V 2S4	ESE/226.3	-21.06	1443
207	SPL	BRAMPTON TRANSIT MOTOR VEHICLE	ETOBICOKE CREEK HWY 10 AND ENGLISH ST OPERATING FLUIDS BRAMPTON CITY ON	SE/247.8	-23.62	1444
208	GEN	SIR JOHN A. MACDONALD SR. PUB.SCHL.	PEEL BOARD OF EDUCATION 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4	ESE/229.9	-15.02	1444
208	GEN	SIR JOHN A. MACDONALD SR. PUB.SCHL.30-247	PEEL BOARD OF EDUCATION 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4	ESE/229.9	-15.02	1445
208	GEN	PEEL DISTRICT SCHOOL BOARD	SIR JOHN A. MACDONALD SR. PUBLIC SCHOOL 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4	ESE/229.9	-15.02	1446
208	SPL	Peel District School Board	250 Centre St N Brampton ON L6V 2R4	ESE/229.9	-15.02	1446
209	SPL	Enbridge Gas Distribution	16 English Street Brampton ON	SE/248.6	-22.08	1447

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
209	PINC	PIPELINE HIT - 1"	16 ENGLISH STREET,,BRAMPTON,ON, L6X 1L4,CA ON	SE/248.6	-22.08	1448
210	SCT	GolfCity Motor Caddies Inc.	44 English St Brampton ON L6X 1L6	SE/178.6	-22.08	1449
210	PINC	PIPELINE HIT 0.5"	44 ENGLISH STREET,,BRAMPTON,ON, L6X 1L6,CA ON	SE/178.6	-22.08	1449
211	EHS		367 Main St. N. Brampton ON L6X 1N6	SE/223.1	-23.05	1449
212	EHS		7 English Street Brampton ON L6X 1L3	SE/214.0	-22.08	1449
213	SPL	Enbridge Gas Distribution Inc.	34 Tolton Dr Brampton ON	ESE/185.9	-21.44	1450
213	PINC	PIPELINE HIT - 1/2"	34 TOLTON DR,,BRAMPTON,ON,L6V 2R1,CA ON	ESE/185.9	-21.44	1451
214	SPL	Enbridge Gas Distribution Inc.	36 Tolton Drive Brampton ON	ESE/185.5	-21.91	1451
214	PINC	PIPELINE HIT 0.5"	36 TOLTON DR.,,BRAMPTON,ON,L6V 2R1,CA ON	ESE/185.5	-21.91	1452
214	PINC	PIPELINE HIT - 1/2"	36 TOLTON DRIVE,,BRAMPTON,ON,L6V 2R1,CA ON	ESE/185.5	-21.91	1452
215	WWIS		ON ***Well ID:*** 7266922	SE/208.9	-23.08	1453
216	EHS		365 Main St N Brampton ON L6X 1N6	SE/206.1	-23.09	1454
217	PES	ENVIRO MASTERS (ETOBICOKE)	84 KINGSWOOD DRIVE BRAMPTON ON L6V 2W3	ESE/223.5	-12.08	1454

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
218	WWIS		Moore Street & English Street lot 8 con 1 Brampton ON ***Well ID:*** 7380753	SE/13.3	-22.08	1454
219	WWIS		lot 22 con 1 ON ***Well ID:*** 4901628	WNW/206.8	18.97	1457
220	SPL	ENBRIDGE CONSUMERS GAS	54 Kingswood Drive, Brampton ON	ESE/224.4	-12.08	1460
221	HINC		27 TOLTON DRIVE BRAMPTON ON L6V 2P9	ESE/133.6	-20.88	1460
222	EHS		12891 McLaughlin Road Caledon ON	WNW/187.2	18.92	1461
223	ANDR	Dales Dump (suspected)	Brampton ON L6V	ESE/125.9	-27.22	1461
224	SPL	Enbridge Gas Distribution Inc.	19 Vodden Crt Brampton ON	ESE/149.1	-12.08	1462
224	PINC	PIPELINE HIT - 1 ¼"	19 VODDEN COURT,,BRAMPTON,ON, L6V 2V7,CA ON	ESE/149.1	-12.08	1463
225	HINC		71 Greene Drive BRAMPTON ON L6V 2P2	ESE/211.9	-12.08	1463
226	SPL	Enbridge Gas Distribution Inc.	40 Greene Drive Brampton ON L6V 2R7	ESE/245.8	-11.64	1463
226	PINC		40 Greene Drive, Brampton ON	ESE/245.8	-11.64	1464
227	EHS		344 Main Street North Brampton ON L6V 1P8	SE/104.3	-24.03	1465
228	PINC	ENBRIDGE GAS INC	21 CHERYL CRT,,BRAMPTON,ON,L6V 3C2,CA	ESE/89.5	-14.94	1465

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			ON			
228	SPL	ENBRIDGE CONSUMERS GAS	21 Cheryl Court, Brampton BRAMPTON ON	ESE/89.5	-14.94	1465
229	EHS		12891 Mclaughlin Road Caledon ON	WNW/121.4	18.92	1466
230	GEN	DUFFERIN-PEEL R.C.S.S. BOARD	ST. ANNE 124 VODDEN ST BRAMPTON ON	ESE/79.8	-13.24	1467
231	PES	PETER'S NO FRILLS	345 MAIN STREET BRAMPTON ON L6X1N6	SE/89.5	-23.16	1467
231	PES	1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS	345 MAIN ST N BRAMPTON ON L6X 1N6	SE/89.5	-23.16	1467
231	PES	1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS	345 MAIN ST N BRAMPTON ON L6X 1N6	SE/89.5	-23.16	1468
231	PES	1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS	345 MAIN ST N BRAMPTON ON L6X1N6	SE/89.5	-23.16	1468
231	SPL	Vari-Therm Limited	345 Main St N Brampton ON	SE/89.5	-23.16	1468
231	PES	FORTINO'S (VODDEN) LTD.	345 MAIN STREET NORTH BRAMPTON ON L6X1N6	SE/89.5	-23.16	1469
231	SPL		345 Main Street N BRAMPTON ON	SE/89.5	-23.16	1470
232	GEN	HY & ZEL'S INC.	12 VODDEN STREET BRAMPTON ON L6Y 1A2	SE/73.9	-25.94	1470
232	PES	HY & ZELS - BRAMPTON	12 VODDEN STREET BRAMPTON ON L6Y1A2	SE/73.9	-25.94	1471

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
232	GEN	Big Lots Canada Inc.	12 Vodden Street East Brampton ON	SE/73.9	-25.94	1471
232	GEN	Big Lots Canada Inc.	12 Vodden Street East Brampton ON	SE/73.9	-25.94	1472
232	PES	HY & ZELS - BRAMPTON	12 VODDEN STREET BRAMPTON ON L6Y1A2	SE/73.9	-25.94	1472
233	HINC		222 CENTRE STREET NORTH BRAMPTON ON L6V 2R4	ESE/59.7	-17.82	1472
234	SPL		36 Newby Court BRAMPTON ON	ESE/47.9	-22.08	1473
235	GEN	VODDEN XRAY	36 VODDEN STREET EAST BRAMPTON ON L6V 1M4	ESE/53.3	-27.74	1474
235	GEN	VODDEN MEDICAL ARTS PHARMACY	36 VODDEN STREET EAST BRAMPTON ON L6V 1M4	ESE/53.3	-27.74	1474
235	GEN	VODDEN MEDICAL ARTS PHARMACY	36 vodden st e brampton ON L6V 4H4	ESE/53.3	-27.74	1474
235	EHS		36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1475
235	GEN	CMLHealthCare	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1475
235	GEN	1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1475
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1476
235	GEN	CMLHealthCare	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1476

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1476
235	GEN	North Brampton Physiotherapy	36 Vodden Street E. Suite 306 Brampton ON L6V 4H4	ESE/53.3	-27.74	1477
235	GEN	CMLHealthCare	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1477
235	GEN	1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1477
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1478
235	GEN	1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1478
235	GEN	North Brampton Physiotherapy	36 Vodden Street E. Suite 306 Brampton ON L6V 4H4	ESE/53.3	-27.74	1478
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1479
235	EHS		36 Vodden Street East Brampton ON	ESE/53.3	-27.74	1479
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON	ESE/53.3	-27.74	1479
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 304 Brampton ON	ESE/53.3	-27.74	1480
235	GEN	Wise Elephant FHT	36 Vodden Street E Suite 203 ON	ESE/53.3	-27.74	1480
235	GEN	1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON	ESE/53.3	-27.74	1480

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
235	EHS		36 Vodden Street East Brampton ON	ESE/53.3	-27.74	1481
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	ESE/53.3	-27.74	1481
235	GEN	Wise Elephant FHT	36 Vodden Street E Suite 203 ON L6V4H4	ESE/53.3	-27.74	1481
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	ESE/53.3	-27.74	1482
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1482
235	GEN	1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1482
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1483
235	GEN	Wise Elephant FHT	36 Vodden Street E Suite 203 ON L6V4H4	ESE/53.3	-27.74	1483
235	GEN	1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1483
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	ESE/53.3	-27.74	1484
235	GEN	Wise Elephant FHT	36 Vodden Street E Suite 203 ON L6V4H4	ESE/53.3	-27.74	1484
235	GEN	1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	ESE/53.3	-27.74	1484
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON L5C1V8	ESE/53.3	-27.74	1485

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1485
235	GEN	SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION	36 Vodden St E Suite 105 Brampton ON L6V 4H4	ESE/53.3	-27.74	1486
235	GEN	Wise Elephant FHT	36 Vodden Street E Suite 203 ON L6V4H4	ESE/53.3	-27.74	1486
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	ESE/53.3	-27.74	1487
235	EHS		36 Vodden St E Brampton ON L6V4H4	ESE/53.3	-27.74	1487
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1487
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	ESE/53.3	-27.74	1488
235	GEN	SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION	36 Vodden St E Suite 105 Brampton ON L6V 4H4	ESE/53.3	-27.74	1488
235	GEN	COMPLETE IMMIGRATION MEDICAL CENTRE	36 VODDEN STREET EAST,SUITE 203 BRAMPTON ON L6V4H4	ESE/53.3	-27.74	1488
235	GEN	SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION	36 Vodden St E Suite 105 Brampton ON L6V 4H4	ESE/53.3	-27.74	1489
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	ESE/53.3	-27.74	1489
235	GEN	COMPLETE IMMIGRATION MEDICAL CENTRE	36 VODDEN STREET EAST,SUITE 203 BRAMPTON ON L6V4H4	ESE/53.3	-27.74	1490
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1490

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
235	GEN	Complete Immigration Medical Centre	36 VODDEN STREET EAST,SUITE 203 BRAMPTON ON	ESE/53.3	-27.74	1490
235	GEN	Saint Elizabeth Health Care	36 Vodden St. E, Suite 202 Brampton ON	ESE/53.3	-27.74	1492
235	GEN	LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1496
235	GEN	Smilemakers Dental	36 Vodden St E Suite 105 Brampton ON	ESE/53.3	-27.74	1499
235	EHS		36 Vodden Street East Brampton ON L6V 4H4	ESE/53.3	-27.74	1502
235	GEN	Coverdale Infusion Clinic Inc	36 Vodden Street East Brampton ON	ESE/53.3	-27.74	1502
236	SPL	The Regional Municipality of Peel	220 Centre St. North Brampton ON	ESE/48.1	-17.88	1502
237	WWIS		36 VODDEN ST E Brampton ON ***Well ID:*** 7217101	ESE/44.8	-28.08	1503
238	SCT	Microbase 2000 Systems Inc.	332 Main St N Unit 1 Brampton ON L6V 1P8	SE/48.5	-24.69	1507
239	WWIS		ON ***Well ID:*** 4901072	ESE/36.6	-15.27	1507
240	WWIS		36 VODDEN ST E Brampton ON ***Well ID:*** 7217099	ESE/30.6	-28.15	1510
241	CA	R.M. OF PEEL	VODDEN ST.W/PLEASANTVIEW AVE. BRAMPTON CITY ON	SE/160.5	-22.08	1513
242	EHS		23-0353 Brampton ON L6V	ESE/5.6	-26.74	1514

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
243	SPL	The Regional Municipality of Peel	Vodden Street East and Centre St. North Brampton ON	ESE/2.6	-18.92	1514
244	GEN	1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	SE/24.1	-22.08	1515
245	WWIS		ON ***Well ID:*** 4900510	ESE/9.2	-18.68	1516
246	GEN	Kennedy Road Tabernacle	141 Kennedy Road N Brampton ON L6V 1X9	ESE/70.4	-12.08	1519
247	CA	R.M. OF PEEL	POST RD/VODDEN ST. BRAMPTON CITY ON	ESE/2.6	-14.29	1519
247	SPL	CONSUMERS' GAS CO. LTD., THE	VODDEN & POST ROAD NATURAL GAS PIPELINE BRAMPTON CITY ON	ESE/2.6	-14.29	1520
248	INC		Main Street & Vodden Street, Brampton ON	SE/3.5	-23.53	1520
249	WWIS		lot 22 con 1 ON ***Well ID:*** 4908096	WNW/187.5	19.46	1521
250	EHS		Downtown Brampton Brampton ON	SE/12.1	-23.55	1526
251	CA	The Corporation of the City of Brampton	75 Vodden Street East Brampton ON L6V 4H7	ESE/39.0	-22.82	1526
251	GEN	The Corporation of The City of Brampton	75 Vodden St. East Brampton ON	ESE/39.0	-22.82	1527
251	ECA	The Corporation of the City of Brampton	75 Vodden St E Brampton ON L6Y 4R2	ESE/39.0	-22.82	1527
251	GEN	The Corporation of The City of Brampton	75 Vodden St. East Brampton ON L6V2R2	ESE/39.0	-22.82	1527

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
251	GEN	The Corporation of The City of Brampton	75 Vodden St. East Brampton ON L6V2R2	ESE/39.0	-22.82	1528
251	GEN	The Corporation of The City of Brampton	75 Vodden St. East Brampton ON L6V2R2	ESE/39.0	-22.82	1528
251	GEN	The Corporation of The City of Brampton Buildings and Property Management	75 Vodden St. East Brampton ON L6V2R2	ESE/39.0	-22.82	1529
251	GEN	The Corporation of The City of Brampton Buildings and Property Management	75 Vodden St. East Brampton ON L6V2R2	ESE/39.0	-22.82	1529
251	GEN	The Corporation of The City of Brampton Buildings and Property Management	75 Vodden St. East Brampton ON L6V2R2	ESE/39.0	-22.82	1529
251	GEN	City of Brampton	Fire Station 207, 75 Vodden St. East Brampton ON	ESE/39.0	-22.82	1530
252	WWIS		320 MAIN STREET W. BRAMPTON ON ***Well ID:*** 7147718	SE/19.0	-24.84	1533
253	SPL	Terra HX Inc.	39 Greene Drive, Brampton BRAMPTON ON	ESE/127.4	-12.08	1536
254	EHS		131 Kennedy Road North Brampton ON L6V 1X9	ESE/41.5	-12.08	1537
255	EHS		215 Centre Street North Brampton ON L6V 1T4	ESE/44.9	-21.06	1537
256	EHS		129-131 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X9	ESE/30.4	-12.08	1537
256	EHS		131 Kennedy Road North Brampton ON L6V 1X9	ESE/30.4	-12.08	1537

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
257	PRT	MANJITS ESSO	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/102.6	-12.08	1538
257	SPL	PROVMAR FUELS INC.	140 KENNEDY ROAD TANK TRUCK (CARGO) BRAMPTON CITY ON	ESE/102.6	-12.08	1538
257	RST	BASHAR ENTERPRISES INC	140 KENNEDY RD N BRAMPTON ON L6V2N4	ESE/102.6	-12.08	1539
257	RST	ESSO MAXIMUM	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/102.6	-12.08	1539
257	RST	MANN MANJIT	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/102.6	-12.08	1539
257	FSTH	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/102.6	-12.08	1539
257	FSTH	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/102.6	-12.08	1540
257	CA	Imperial Oil Limited	140 Kennedy Rd N Brampton ON L6V 2N4	ESE/102.6	-12.08	1541
257	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1541
257	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1542
257	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1543
257	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1543
257	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1544

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
257	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1544
257	FST	MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1545
257	FST	MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1545
257	FST	MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1545
257	RST	MANN MANJIT	140 KENNEDY RD N BRAMPTON ON L6V2N4	ESE/102.6	-12.08	1546
257	EHS		140 Kennedy Rd N Brampton ON L6V2N4	ESE/102.6	-12.08	1546
257	ECA	Imperial Oil Limited	140 Kennedy Rd N Brampton ON M3C 1K5	ESE/102.6	-12.08	1546
257	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1546
257	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1547
257	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1547
257	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1547
257	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1547
257	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1548

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
257	FST	MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	ESE/102.6	-12.08	1548
258	WWIS		KENNEDY RD N BRAMPTON ON ***Well ID:*** 7312109	ESE/49.5	-12.08	1548
259	SPL	SERVICE MASTER	115 NANCY MCCREDIE DRIVE BRAMPTON ON L6X 2N4	SE/149.8	-22.08	1551
260	WWIS		VODDEN ST E & KENNEDY RD N BRAMPTON ON ***Well ID:*** 7312124	ESE/20.5	-12.08	1552
261	WWIS		ON ***Well ID:*** 4903777	SE/42.7	-25.20	1555
262	WWIS		Kennedy Rd N Brampton ON ***Well ID:*** 7359808	ESE/50.1	-12.90	1557
263	SPL	Alectra Utilities Corporation	47 Vodden St Brampton ON	SE/33.8	-22.08	1558
264	EASR	THE REGIONAL MUNICIPALITY OF PEEL	ON	ESE/33.0	-12.56	1559
265	EHS		320 Main Street North Brampton ON	SE/56.2	-25.40	1559
266	GEN	Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	SE/63.1	-25.90	1560
266	GEN	Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	SE/63.1	-25.90	1560
266	GEN	Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	SE/63.1	-25.90	1561
266	GEN	Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	SE/63.1	-25.90	1561

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
266	GEN	Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	SE/63.1	-25.90	1562
266	GEN	Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	SE/63.1	-25.90	1563
266	GEN	Main Street Dental Office	320 Main Street North Brampton ON	SE/63.1	-25.90	1566
267	PINC		35 Pleasantview Avenue, Brampton ON	SE/232.4	-22.08	1567
268	RST	PETRO-CANADA	KENNEDY N & VODDEN BRAMPTON ON L6V 1X7	ESE/22.0	-13.02	1567
269	WWIS		121 KENNEDY ROAD NORTH Brampton ON ***Well ID:*** 7298062	ESE/16.7	-13.08	1567
270	WWIS		ON ***Well ID:*** 7233319	ESE/16.0	-13.08	1570
271	WWIS		227 VODDEN ST EAST Brampton ON ***Well ID:*** 7219364	ESE/59.3	-13.08	1571
272	SCT	Plastech Machinery Solutions	58 Nancy McCredie Dr Brampton ON L6X 2N6	SE/166.9	-22.08	1574
273	SPL	BRAMPTON HYDRO-ELECTRIC COMMIS	30 CUMBERLAND BRAMPTON CITY ON L6V 1W6	ESE/77.8	-12.28	1575
274	BORE		ON	ESE/121.9	-12.86	1576
275	BORE		ON	ESE/75.3	-13.08	1577
276	WWIS		227 VODDOEN STREET EAST Brampton ON ***Well ID:*** 7219365	ESE/53.2	-13.08	1578

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
277	PRT	PETRO CAN ROCCO & RALPH SERVICE CENTRE LTD	121 KENNEDY RD N BRAMPTON ON L6V 1X7	ESE/41.0	-13.08	1581
277	RST	KENNEDY & VODDEN PETRO CANADA	121 KENNEDY RD N BRAMPTON ON L6V 1X7	ESE/41.0	-13.08	1581
277	RST	PERFECT LUBE	121 KENNEDY RD N BRAMPTON ON L6V 1X7	ESE/41.0	-13.08	1582
277	CA	Petro-Canada	121 Kennedy Road North Brampton ON L6V 1X7	ESE/41.0	-13.08	1582
277	DTNK	SIMCOE ENERGY & TECHNICAL SERVICES INC *	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1582
277	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1583
277	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1583
277	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1583
277	RST	KENNEDY & VODDEN PETRO CANADA	121 KENNEDY RD N BRAMPTON ON L6V1X7	ESE/41.0	-13.08	1583
277	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1584
277	ECA	Petro-Canada	121 Kennedy Road North Brampton ON L6L 6N5	ESE/41.0	-13.08	1584
277	GEN	Suncor Energy Products	121 Kennedy Road N Brampton ON L6V1X	ESE/41.0	-13.08	1584
277	GEN	Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	ESE/41.0	-13.08	1585

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
277	GEN	Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	ESE/41.0	-13.08	1585
277	GEN	Suncor Energy Products Partnership	121 Kennedy Road North Brampton ON	ESE/41.0	-13.08	1586
277	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1589
277	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1589
277	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1590
277	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1590
277	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/41.0	-13.08	1590
278	BORE		ON	ESE/41.5	-13.08	1590
279	WWIS		121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON ***Well ID:*** 7401799	ESE/43.6	-13.08	1592
280	PINC	BACKYARD GETAWAYS	16 LOCUSTWOOD CRT,,BRAMPTON,ON, L6V 3C1,CA ON	ESE/112.8	-18.45	1595
280	SPL		16 Locustwood Crt Brampton ON	ESE/112.8	-18.45	1596
281	BORE		ON	ESE/242.0	-12.08	1596
282	WWIS		227 VODDEN STREET EAST Brampton ON ***Well ID:*** 7219358	ESE/57.2	-13.08	1598

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
283	WWIS		121 KENNEDY RD. N BRAMPTON ON ***Well ID:*** 7308835	ESE/46.3	-13.08	1601
284	GEN	BRAMPTON HYDRO-ELECTRIC COMMISSION	HANSEN ROAD-SOUTH OF VODDEN 129 GLIDDEN ROAD BRAMPTON ON L6W 3L9	ESE/240.6	-12.08	1603
284	GEN	BRAMPTON HYDRO-ELECTRIC COMMISSION06-328	HANSEN ROAD-SOUTH OF VODDEN 129 GLIDDEN ROAD BRAMPTON ON L6W 3L9	ESE/240.6	-12.08	1604
284	GEN	BRAMPTON HYDRO-ELECTRIC COMMISSION	HANSEN ROAD-SOUTH OF VODDEN BRAMPTON ON	ESE/240.6	-12.08	1604
285	WWIS		121 KENNEDY RD. N. BRAMPTON ON ***Well ID:*** 7308837	ESE/53.3	-13.08	1605
286	WWIS		121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON ***Well ID:*** 7401794	ESE/61.5	-13.08	1607
287	BORE		ON	ESE/99.8	-13.08	1611
288	WWIS		121 KENNEDY ROAD NORTH Brampton ON ***Well ID:*** 7298064	ESE/60.2	-13.08	1612
289	SPL		BRAMPTON ON	SE/113.5	-23.11	1615
290	WWIS		121 KENNEDY RD. N BRAMPTON ON ***Well ID:*** 7308836	ESE/59.1	-13.08	1616
291	WWIS		99 KENNEDY STREET N Brampton ON ***Well ID:*** 7369738	ESE/68.5	-13.20	1619
292	WWIS		99 KENNEDY STREET N Brampton ON ***Well ID:*** 7369739	ESE/66.7	-13.08	1623
293	WWIS		121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON	ESE/69.8	-13.20	1627

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7401796			
294	BORE		ON	ESE/127.4	-13.08	1631
295	WWIS		121 KENNEDY ROAD NORTH Brampton ON ***Well ID:*** 7298063	ESE/69.0	-13.08	1632
296	WWIS		99 KENNEDY STREET N Brampton ON ***Well ID:*** 7369740	ESE/70.7	-13.08	1635
297	BORE		ON	ESE/87.1	-13.08	1639
298	PES	THE XTERMINATOR	52 CUMBERLAND DR BRAMPTON ON L6V 1W6	ESE/134.4	-14.10	1641
299	WWIS		121 KENNEDY ROAD NORTH Brampton ON ***Well ID:*** 7298061	ESE/77.1	-13.08	1641
300	WWIS		OLD SCHOOL ROAD BRAMPTON ON ***Well ID:*** 7300315	WNW/153.1	17.40	1644
301	CA	WALLSTAR PROPERTIES LTD.	99 KENNEDY RD.N. BRAMPTON ON L6V 1X8	ESE/91.8	-13.93	1647
301	EHS		99 Kennedy Rd N Brampton ON L6V 1X7	ESE/91.8	-13.93	1647
302	SPL	The Corporation of the City of Brampton	225 Vodden St E Brampton ON L6V 4M1	ESE/120.6	-13.08	1648
303	BORE		ON	ESE/110.6	-13.08	1648
304	GEN	LEO ARCHDEKIN FUNERAL HOME	289 MAIN STREET N. BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1650
304	GEN	LEO ARCHDEKIN FUNERAL HOME	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1650

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
304	GEN	TRILLIUM FUNERAL SERVICES CORP.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1650
304	GEN	LEO ARCHDEKIN FUNERAL HOME 44-011	289 MAIN STREET N. BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1651
304	GEN	SCOTT FUNERAL HOME, DIV. OF 44-543	TRILLIUM FUNERAL SERVICES CORP. 289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1651
304	GEN	TRILLIUM FUNERAL SERVICES CORPORATION	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1651
304	GEN	TRILLIUM FUNERAL SERVICES CORPORATION	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1652
304	GEN	TRILLIUM FUNERAL SERVICES CORPORATION	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1652
304	GEN	TRILLIUM FUNERAL SERVICES CORPORATION	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1653
304	GEN	ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1653
304	GEN	ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON	SE/138.4	-23.15	1653
304	GEN	ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1654
304	GEN	ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1654
304	GEN	ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1654
304	GEN	ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1655

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
304	GEN	ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1655
304	GEN	ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	SE/138.4	-23.15	1655
304	GEN	Scott Funeral Home - Brampton Chapel	289 MAIN STREET NORTH BRAMPTON ON	SE/138.4	-23.15	1656
305	BORE		ON	ESE/87.8	-13.17	1659
306	EHS		300 Main Street North Brampton ON L6V 4H6	SE/148.0	-25.08	1660
306	GEN	Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON L6V 4H6	SE/148.0	-25.08	1660
306	GEN	Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON L6V 4H6	SE/148.0	-25.08	1661
306	GEN	Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON L6V 4H6	SE/148.0	-25.08	1661
306	GEN	Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON L6V 4H6	SE/148.0	-25.08	1662
306	GEN	Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON L6V 4H6	SE/148.0	-25.08	1662
306	GEN	Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON L6V 4H6	SE/148.0	-25.08	1662
306	GEN	Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON	SE/148.0	-25.08	1663
306	GEN	Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON	SE/148.0	-25.08	1663

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
306	GEN	Central Brampton Family Health Team	300 Main St. N, #200 Brampton ON L6V 4H6	SE/148.0	-25.08	1664
306	GEN	Central Brampton Family Health Team	300 Main St. N,2and Floor Brampton ON L6V 4H6	SE/148.0	-25.08	1664
306	GEN	Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON L6V4H6	SE/148.0	-25.08	1664
306	GEN	Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON L6V 4H6	SE/148.0	-25.08	1665
306	GEN	Dr Essam Michael Medicine Professional Corporation	300 Main St N Brampton ON L6V 1P6	SE/148.0	-25.08	1665
306	GEN	Dr Essam Michael Medicine Professional Corporation	300 Main St N Brampton ON L6V 1P6	SE/148.0	-25.08	1666
306	GEN	Dr Essam Michael Medicine Professional Corporation	300 Main St N Brampton ON L6V 1P6	SE/148.0	-25.08	1666
306	GEN	Astra Fertility Group	Astra Fertility, 300 Main St N Brampton ON	SE/148.0	-25.08	1667
307	SPL		178 Beech St. Brampton ON	ESE/169.2	-20.40	1670
308	PES	ZELLERS LIMITED 146	227 VODDEN STREET CENTENNIAL MALL BRAMPTON ON	ESE/186.1	-13.08	1671
308	EHS		227 Vodden St E Brampton ON L6V 1N2	ESE/186.1	-13.08	1671
308	PES	ZELLERS LIMITED 146	227 VODDEN STREET CENTENNIAL MALL BRAMPTON ON L6V 1N2	ESE/186.1	-13.08	1671

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
308	GEN	PHARMA PLUS DRUGS LTD	227 VODDEN STREET BRAMPTON ON L6V 1N2	ESE/186.1	-13.08	1672
308	GEN	PHARMA PLUS DRUGS LTD. 31-751	227 VODDEN ST., BRAMPTON C/O 5935 AIRPORT ROAD #500 MISSISSAUGA ON L4V 1W5	ESE/186.1	-13.08	1672
308	GEN	PHARMA PLUS DRUGMARTS LTD.	227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	ESE/186.1	-13.08	1673
308	GEN	GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.	FOOD BASICS #983 227 VODDEN STREET BRAMPTON ON L6V 1N2	ESE/186.1	-13.08	1673
308	GEN	PHARMA PLUS DRUGS LTD.	227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	ESE/186.1	-13.08	1674
308	PES	ZELLERS STORE #146-CENTENNIAL MALL	227 VODDEN ST BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1674
308	PES	ZELLERS LIMITED 146	227 VODDEN ST; CENTENNIAL MALL BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1674
308	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 904	227 VODDEN STREET BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1675
308	PES	ZELLERS INC	227 VODDEN STREET N BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1675
308	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/186.1	-13.08	1675
308	GEN	1723525 Ontario Inc.	227 Vodden Street East Unit 30B Brampton ON	ESE/186.1	-13.08	1676
308	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/186.1	-13.08	1676
308	PES	ZELLERS INC	227 VODDEN STREET N BRAMPTON ON L6V 1N2	ESE/186.1	-13.08	1676

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
308	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 904	227 Vodden Street Brampton ON L6V 1N2	ESE/186.1	-13.08	1677
308	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/186.1	-13.08	1677
308	NPRI	ZELLERS	227 VODDEN Street BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1678
308	EHS		227 Vodden St E Brampton On Brampton ON L6V1N1	ESE/186.1	-13.08	1680
308	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON	ESE/186.1	-13.08	1680
308	INC		227 VODDEN STREET EAST, BRAMPTON ON	ESE/186.1	-13.08	1681
308	EHS		227 Vodden St E Brampton ON L6V1N1	ESE/186.1	-13.08	1681
308	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/186.1	-13.08	1682
308	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/186.1	-13.08	1682
308	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/186.1	-13.08	1682
308	GEN	Pharma Plus Drugmarts Ltd	227 Vodden Street East Brampton ON L6V 1N2	ESE/186.1	-13.08	1683
308	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/186.1	-13.08	1683
308	GEN	Pharma Plus Drugmarts Ltd	227 Vodden Street East Brampton ON L6V 1N2	ESE/186.1	-13.08	1683

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
308	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/186.1	-13.08	1684
308	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 904	227 VODDEN STREET BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1684
308	PES	ZELLERS LIMITED 146	227 VODDEN ST; CENTENNIAL MALL BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1685
308	PES	ZELLERS INC	227 VODDEN STREET N BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1685
308	PES	ZELLERS STORE #146-CENTENNIAL MALL	227 VODDEN ST BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1685
308	PES	ZELLERS LIMITED 146	227 VODDEN ST; CENTENNIAL MALL BRAMPTON ON L6V1N2	ESE/186.1	-13.08	1686
308	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/186.1	-13.08	1686
308	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/186.1	-13.08	1687
308	GEN	Rexall Pharmacy Group Ltd	227 Vodden Street East Brampton ON	ESE/186.1	-13.08	1687
308	EHS		227 Vodden Street East Brampton ON L6V 4J4	ESE/186.1	-13.08	1690
309	SCT	The Blind Service Co.	13 Harmsworth Ave Brampton ON L6X 2N2	SE/184.3	-22.08	1690
310	EHS		99 Kennedy Road North Brampton ON L6V 1X7	ESE/108.3	-14.08	1691
311	WWIS		OLD SCHOOL RD BRAMPTON ON	WNW/141.7	17.99	1691

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7300300			
312	SPL		61 Mara Cres, Brampton BRAMPTON ON	ESE/177.3	-28.06	1694
313	PINC		124 Mill Street North, Brampton ON	SE/134.8	-23.08	1694
314	SPL	Enbridge Gas Distribution Inc.	67 Nancy McCredie Drive Brampton ON	SE/119.5	-22.08	1695
314	PINC	CEDAR HILLS CONTRACTING	67 NANCY MCCREDIE DR,,BRAMPTON, ON,L6X 2N4,CA ON	SE/119.5	-22.08	1696
315	BORE		ON	SE/240.1	-22.08	1696
316	SCT	APC Products Ltd.	38 Lorne Ave Brampton ON L6X 1L1	SE/155.3	-23.08	1697
317	BORE		ON	ESE/113.9	-14.08	1698
318	BORE		ON	ESE/122.0	-13.82	1699
319	BORE		ON	ESE/151.8	-13.08	1700
320	WWIS		lot 22 con 1 ON ***Well ID:*** 4904066	WNW/218.8	19.92	1701
321	SPL	Enbridge Energy Distribution Inc.	32 Nancy McCreedie Drive Brampton ON	SE/155.2	-22.08	1707
321	PINC	ENBRIDGE GAS INC	32 NANCY MCCREDIE DR,,BRAMPTON, ON,L6X 2N5,CA ON	SE/155.2	-22.08	1707

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
322	GEN	PHOTOGRAPHIC IMAGERY	21 HARMSWORTH AVENUE BRAMPTON ON L6X 2N2	SE/205.3	-22.08	1708
323	WWIS		Old School Road & Hurontario Street lot 22 con 1 Caledon ON ***Well ID:*** 7380784	NW/193.9	22.93	1708
324	GEN	COLOUR CRAFT LABS	116 MILL STREET NORTH BRAMPTON ON L6X 2P2	SE/168.1	-23.08	1711
325	EHS		95 Kennedy Road North Brampton ON L6V 1X7	ESE/181.8	-14.08	1712
326	EHS		225 Vodden St E Brampton ON L6V 4M1	ESE/199.0	-13.55	1712
327	EHS		Services and Housing in the Province Brampton ON L6X 1N4	SE/232.2	-25.08	1712
328	SPL	The Regional Municipality of Peel	135 Sailsbury Circle Brampton ON	ESE/248.7	-16.81	1712
329	PINC	PIPELINE HIT 1/2"	33 HARMSWORTH AVE,,BRAMPTON,ON, L6X 2N2,CA ON	SE/245.0	-22.08	1713
330	SPL	PRIVATE RESIDENCE	INFRONT OF 110 MILL ST. (N.O.S.) BRAMPTON CITY ON	SE/229.0	-23.75	1714
331	BORE		ON	ESE/212.0	-14.08	1714
332	WWIS		lot 22 con 1 ON ***Well ID:*** 4907265	NW/41.6	22.06	1716
333	WWIS		2939 OLD SCHOOL RD. lot 22 con 1 BRAMPTON ON ***Well ID:*** 7199058	NW/44.5	23.98	1720
335	WWIS		2939 OLD SCHOOL RD. lot 22 con 1 BRAMPTON ON	NW/32.8	24.24	1727

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7199059			
336	WWIS		lot 22 con 1 ON ***Well ID:*** 4901626	WNW/13.6	18.92	1730
337	WWIS		lot 22 con 1 ON ***Well ID:*** 4901629	WNW/38.8	20.46	1733
338	SPL	Makkar Transport<UNOFFICIAL>	Hwy 10 @ Old School Road Caledon ON	NW/6.2	25.74	1736
338	PINC	ENBRIDGE GAS INC	EAST OF VALLEYSCAPE TRAIL (WEST OF LOT#36),OLD SCHOOL RD & HWY 10, CALEDON,ON,L7C 2B7,CA ON	NW/6.2	25.74	1737
338	SPL		hwy 10 southbound and Old School Road intersection in Brampton CALEDON ON	NW/6.2	25.74	1738
338	SPL		Hwy 10 and Old School Road Caledon CALEDON ON	NW/6.2	25.74	1739
339	WWIS		lot 23 con 1 ON ***Well ID:*** 4902901	WNW/43.0	18.13	1739
340	WWIS		lot 22 con 1 ON ***Well ID:*** 4901627	NW/12.1	25.64	1743
341	WWIS		2676 OLD SCHOOL RD. lot 23 con 1 BRAMPTON ON ***Well ID:*** 7145558	WNW/63.4	18.21	1745
342	WWIS		lot 23 con 1 ON ***Well ID:*** 4901630	WNW/66.7	16.90	1748
343	WWIS		lot 23 con 1 ON ***Well ID:*** 4904378	WNW/81.5	19.19	1750
344	WWIS		lot 23 con 1 ON ***Well ID:*** 4901631	WNW/76.7	16.56	1755

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
345	WWIS		lot 23 con 1 ON ***Well ID:*** 4902900	WNW/132.0	21.41	1758
346	WWIS		lot 23 con 1 ON ***Well ID:*** 4906471	WNW/123.7	21.67	1761
347	WWIS		n/a Old School Rd X Hurontario Street lot 23 con 1 Caledon ON ***Well ID:*** 7406244	NW/244.0	28.93	1764
348	WWIS		n/a Old School Rd X Hurontario Street lot 23 con 1 Caledon ON ***Well ID:*** 7406221	NW/209.9	28.93	1767
349	WWIS		lot 23 con 1 ON ***Well ID:*** 4902899	WNW/165.3	17.64	1771

Executive Summary: Summary By Data Source

ANDR - Anderson's Waste Disposal Sites

A search of the ANDR database, dated 1860s-Present has found that there are 1 ANDR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Dales Dump (suspected)	Brampton ON L6V	125.9	223

AUWR - Automobile Wrecking & Supplies

A search of the AUWR database, dated 1999-Apr 30, 2025 has found that there are 2 AUWR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HEART LAKE USED AUTO PARTS	20 FISHERMAN DR BRAMPTON ON L7A1G2	244.3	62
HEART LAKE USED AUTO PARTS	20 FISHERMAN DR BRAMPTON ON L7A 1G2	244.3	62

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 19 BORE site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	36.5	36
	ON	26.8	44
	ON	85.7	165

Site	Address	Distance (m)	Map Key
	ON	236.8	170
	ON	59.9	177
	ON	121.9	274
	ON	75.3	275
	ON	41.5	278
	ON	242.0	281
	ON	99.8	287
	ON	127.4	294
	ON	87.1	297
	ON	110.6	303
	ON	87.8	305

Site	Address	Distance (m)	Map Key
	ON	240.1	315
	ON	113.9	317
	ON	122.0	318
	ON	151.8	319
	ON	212.0	331

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 36 CA site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BRAMPTON BRICK LIMITED	225 WANLESS DR. BRAMPTON CITY ON L7A 1E9	196.0	16
RICHVALE YORK BLOCK INC.	225 WANLESS DRIVE BRAMPTON CITY ON L7A 1E9	196.0	16
	225 Wanless Drive Brampton ON L7A 1E9	196.0	16
Brampton Brick Limited - Brique Brampton Limitee	225 Wanless Drive Brampton ON L7A 1E9	196.0	16
Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	196.0	16

Site	Address	Distance (m)	Map Key
Brampton Brick Limited / Brique Brampton Limitee	225 Wanless Dr Brampton ON L7A 1E9	196.0	16
Medical Waste Management Inc.	225 Wanless Drive Brampton ON L7A 1E9	196.0	16
PEEL BLOCK (1987) LIMITED DIV. BRAM. BRI	225 WANLESS DRIVE BRAMPTON CITY ON L7A 1E9	196.0	16
The Corporation of the City of Brampton	120 Sandalwood Pky Brampton ON	246.1	22
Hydro One Brampton Networks Inc.	175 Sandalwood Parkway West Brampton ON L7A 1E8	119.8	56
INDUSTRIAL THERMO POLYMERS LIMITED	153 VAN KIRK DRIVE BRAMPTON CITY ON L7A 1A4	125.6	68
Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	125.6	68
Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	125.6	68
2270334 Ontario Inc.	150 Van Kirk Dr Brampton ON	175.9	74
SHERWIN-WILLIAMS CANADA, BRAMPTON FACILI	130 VAN KIRK DRIVE BRAMPTON CITY ON L7A 1B1	212.1	81
Sherwin-Williams Canada Inc.	130 Van Kirk Dr Brampton ON L7A 1B1	212.1	81

Site	Address	Distance (m)	Map Key
Body Care Manufacturing Inc.	120A Van Kirk Dr Brampton ON L7A 1B1	208.5	89
The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton ON L7A 1A4	76.1	97
The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton ON L7A 1A4	76.1	97
GREAT-L DEV. LTD. - LOT 17, CONC. 1 WHS	CRESTHAVEN RD./MAYFIELD RD. BRAMPTON CITY ON	247.2	100
GREAT-L DEV. LTD. - LOT 17, CONC. 1 WHS	CRESTHAVEN RD./MAYFIELD RD. BRAMPTON CITY ON	247.2	100
VAUGHANWOOD DEV. LTD. AND DENCO PROP. CA	ROBERTSON DAVIES DR/MAYFIELD BRAMPTON CITY ON	247.2	100
COPPERWELD CANADA, SONCO STEEL TUBE DIV.	95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	62.1	110
6832458 Canada Inc.	95 Van Kirk Dr Brampton ON L7A 1A4	62.1	110
GO a division of Metrolinx	85 Van Kirk Dr Brampton ON L7A 1A4	76.5	118
Strada Aggregates Inc.	45 Van Kirk Rd Brampton ON L7A 1A4	172.8	131
Aecon Construction and Materials Limited	45 Van Kirk Dr Brampton ON L7A 1A4	172.8	131
1480411 Ontario Inc.	190 Bovaird Dr W Brampton ON L7A 1A2	147.3	146

Site	Address	Distance (m)	Map Key
LDASK MBC CORP., KORETZ ESTATES LTD.	MANETT CRES./TESSLER CRES. BRAMPTON CITY ON	153.5	164
LDASK MBC CORP., KORETZ ESTATES LTD.	MANETT CRES./TESSLER CRES. BRAMPTON CITY ON	153.5	164
R.M. OF PEEL	VODDEN ST.W/PLEASANTVIEW AVE. BRAMPTON CITY ON	160.5	241
R.M. OF PEEL	POST RD/VODDEN ST. BRAMPTON CITY ON	2.6	247
The Corporation of the City of Brampton	75 Vodden Street East Brampton ON L6V 4H7	39.0	251
Imperial Oil Limited	140 Kennedy Rd N Brampton ON L6V 2N4	102.6	257
Petro-Canada	121 Kennedy Road North Brampton ON L6V 1X7	41.0	277
WALLSTAR PROPERTIES LTD.	99 KENNEDY RD.N. BRAMPTON ON L6V 1X8	91.8	301

CFOT - Commercial Fuel Oil Tanks

A search of the CFOT database, dated Oct 2023 has found that there are 1 CFOT site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
METROLINX O/A GO TRANSIT	85 VAN KIRK DR BRAMPTON ON	76.5	118

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 17 DTNK site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKETING)	225 WANLESS DR BRAMPTON ON	196.0	16
BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKETING)	225 WANLESS DR BRAMPTON ON	196.0	16
CITY OF BRAMPTON	120 SANDALWOOD PKWY W BRAMPTON ON	246.1	22
DAY & ROSS INC	170 VAN KIRK DR BRAMPTON ON	241.0	75
DAY & ROSS INC	170 VAN KIRK DR BRAMPTON ON	241.0	75
BUTCHER ENGINEERING	105 VAN KIRK DR BRAMPTON ON	76.1	97
BUTCHER ENGINEERING	105 VAN KIRK DR BRAMPTON ON	76.1	97
	370 MAIN ST N BRAMPTON ON L6V 4A4	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257

Site	Address	Distance (m)	Map Key
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
SIMCOE ENERGY & TECHNICAL SERVICES INC *	121 KENNEDY RD N BRAMPTON ON	41.0	277

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011 - May 31, 2025 has found that there are 17 EASR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BRAMPTON BRICK LIMITED/BRIQUE BRAMPTON LIMITEE	225a Wanless Drive Brampton ON L7A 1E9	196.0	16
THE CORPORATION OF THE CITY OF BRAMPTON	120 SANDALWOOD PKWY WEST BRAMPTON ON L7A 1L2	246.1	22
THE CORPORATION OF THE CITY OF BRAMPTON	130 Sandalwood PKY W Brampton ON L7A 1L2	102.1	42

Site	Address	Distance (m)	Map Key
THE CORPORATION OF THE CITY OF BRAMPTON	130 Sandalwood PKY W Brampton ON L7A 1L2	102.1	42
THE CORPORATION OF THE CITY OF BRAMPTON	130 Sandalwood PKY W Brampton ON L7A 1L2	102.1	42
BRAMPTON HYDRO INC.	175 Sandalwood PKY W Brampton ON L7A 1E8	119.8	56
ARMACELL CANADA INC.	153 VAN KIRK DR BRAMPTON ON L7A 1A4	125.6	68
1932675 ONTARIO LIMITED	153 VAN KIRK DR BRAMPTON ON L7A 1A4	125.6	68
SOTAWALL LIMITED	443 Railside DR Brampton ON L7A 1E1	242.8	71
GIVE AND GO PREPARED FOODS CORP.	415 Railside DR Brampton ON L7L 1E1	243.2	85
315594 ONTARIO INC.	100 VAN KIRK DR BRAMPTON ON L7A 1B1	219.2	93
GB (MAYFIELD 2) INC.	2650 Mayfield Road Caledon ON L7C 3K7	192.1	109
SOTAWALL LIMITED	70 Van Kirk DR Brampton ON L7A 1B1	233.5	120
1035312 ONTARIO LIMITED	190 CANAM CRES BRAMPTON ON L7A 1A9	230.9	153
1035312 ONTARIO LIMITED	190 CANAM BRAMPTON ON	230.9	153

Site	Address	Distance (m)	Map Key
MANETT RESIDENCES INC.	100 Manett Crescent Brampton ON L6X 4X4	95.0	159
THE REGIONAL MUNICIPALITY OF PEEL	ON	33.0	264

EBR - Environmental Registry

A search of the EBR database, dated 1994 - May 31, 2025 has found that there are 26 EBR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Brampton Brick Limited	225 Wanless Drive Brampton Ontario Brampton ON	196.0	16
Brampton Brick Limited	225 Wanless Drive Brampton Ontario Brampton ON	196.0	16
Brampton Brick Limited	225 Wanless Drive Brampton Ontario Brampton ON	196.0	16
Brampton Brick Limited	225 Wanless Drive Brampton Ontario Brampton ON	196.0	16
Roxy Construction Co. Limited	225 Wanless Drive Brampton Ontario Brampton ON	196.0	16
Brampton Brick Limited	225 Wanless Drive CITY OF BRAMPTON ON	196.0	16
Giffels Associates for Brampton Transit	120 Sandalwood Pkwy Brampton Ontario L7W 1L2 Brampton ON	246.1	22

Site	Address	Distance (m)	Map Key
City of Brampton	130 Sandalwood Pkwy W, Brampton CITY OF BRAMPTON ON	102.1	42
Hydro One Brampton Networks Inc.	175 Sandalwood Parkway West Brampton Ontario L7A 1E8 Brampton ON	119.8	56
Industrial Thermo Polymers Limited	153 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	125.6	68
Industrial Thermo Polymers Limited	153 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	125.6	68
Industrial Thermo Polymers Limited	153 Van Kirk Drive CITY OF BRAMPTON ON	125.6	68
2270334 Ontario Inc.	150 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	175.9	74
Sherwin-Williams Canada Inc.	130 Van Kirk Drive CITY OF BRAMPTON ON	212.1	81
Sherwin-Williams Canada Inc.	130 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1B1 CITY OF BRAMPTON ON	212.1	81
The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton Ontario Brampton ON	76.1	97
Copperweld Canada	95 Van Kirk Drive CITY OF BRAMPTON ON	62.1	110
6832458 Canada Inc.	95 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON	62.1	110

Site	Address	Distance (m)	Map Key
GO Transit	85 Van Kirk Dr., Brampton ON CITY OF BRAMPTON ON	76.5	118
GIP Construction and Materials Limited	45 Van Kirk Drive Brampton, ON L7A 1A6 Canada ON	172.8	131
Aecon Construction and Materials Limited/Construction et Materiaux Aecon Limitee	45 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON	172.8	131
Aecon Construction and Materials Limited	45 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A6 CITY OF BRAMPTON ON	172.8	131
Strada Aggregates Inc.	45 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON	172.8	131
Strada Crush Limited	45 Van Kirk Road Brampton Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	172.8	131
Aecon Construction and Materials Limited	45 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1A6 CITY OF BRAMPTON ON	172.8	131
1480411 Ontario Inc.	190 Bovaird Drive West Brampton Regional Municipality of Peel L7A 1A2 CITY OF BRAMPTON ON	147.3	146

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011 - May 31, 2025 has found that there are 68 ECA site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	196.0	16

Site	Address	Distance (m)	Map Key
Brampton Brick Limited / Brique Brampton Limitee	225 Wanless Dr Brampton ON L7A 1E9	196.0	16
Medical Waste Management Inc.	225 Wanless Drive Brampton ON L6T 5R7	196.0	16
Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	196.0	16
Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	196.0	16
The Corporation of the City of Brampton	120 Sandalwood Pky W Brampton ON L7A 1L2	246.1	22
The Corporation of the City of Brampton	120 Sandalwood Pky Brampton ON L6Y 4R2	246.1	22
The Corporation of the City of Brampton	120 Sandalwood Pky W Brampton ON L6Y 4R2	246.1	22
The Corporation of the City of Brampton	120 Sandalwood Pky W Brampton ON L6Y 4R2	246.1	22
The Corporation of the City of Brampton	120 Sandalwood Pky W Brampton ON L6Y 4R2	246.1	22
Mia Properties Limited	CON 1 WEST OF CENTRE ROAD Brampton ON M2P 2B7	10.8	25
Mia Properties Limited	CON 1 WEST OF CENTRE ROAD Brampton ON M2P 2B7	10.8	25
Petro-Canada Limited	West of Hurontario Street Brampton ON L6L 6N5	10.8	25

Site	Address	Distance (m)	Map Key
149259 Canada Limited	Lot 14, Concession 1 WHS Brampton ON M5P 3M2	11.9	29
Mia Properties Limited	Brampton ON M2P 6O2	11.9	29
Ciro Excavating & Grading Ltd.	Brampton ON L4L 3P6	11.9	29
Ciro Excavating & Grading Ltd.	Brampton ON L4L 3P6	11.9	29
149259 Canada Limited	Lot 14, Concession 1 WHS Brampton ON M5P 3M2	11.9	29
Mia Properties Limited	Brampton ON M3B 2T5	11.9	29
Mia Properties Limited	Brampton ON M2P 6O2	11.9	29
Mia Properties Limited	Brampton ON M3B 2T5	11.9	29
The Corporation of the City of Brampton	130 Sandalwood Pky W Brampton ON L6Y 4R2	102.1	42
Brampton West 6-2 Limited	Brampton ON M3B 2T5	19.8	52
Brampton West 6-2 Limited	Brampton ON M3B 2T5	19.8	52

Site	Address	Distance (m)	Map Key
Brampton West 6-2 Limited	Brampton ON M3B 2T5	19.8	52
Brampton West 6-2 Limited	McLaughlin Road (from Wanless Drive to approximately 240m south of Wanless Drive) Brampton ON M3B 2T5	19.8	52
Hydro One Brampton Networks Inc.	175 Sandalwood Parkway West Brampton ON L7A 1E8	119.8	56
The Regional Municipality of Peel	440 Railside Drive Brampton ON L7A1L1	182.2	64
The Regional Municipality of Peel	Railside Dr (lot at south end of Railside Drive, adjacent to 440 Railside Drive) Brampton ON L6T 4B9	182.2	64
Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	125.6	68
Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	125.6	68
Industrial Thermo Polymers Limited	153 Van Kirk Dr Brampton ON L7A 1A4	125.6	68
Armbro Inc.	Brampton ON	5.2	69
The Corporation of the City of Brampton	Brampton ON L6Y 4R2	5.2	69
Terraco Inc.	Brampton ON M5M 2L4	5.2	69
Terraco Inc.	Brampton ON M5M 2L4	5.2	69

Site	Address	Distance (m)	Map Key
2270334 Ontario Inc.	150 Van Kirk Dr Brampton ON L7A 2Y4	175.9	74
Sherwin-Williams Canada Inc.	130 Van Kirk Dr Brampton ON L7A 1B1	212.1	81
Great-L Developments Inc.	Brampton ON M2K 2S5	26.7	83
Partacc West Developments Inc.	Brampton ON L3R 9R9	26.7	83
Partacc West Developments Inc.	Brampton ON M3R 9R9	26.7	83
Body Care Manufacturing Inc.	120A Van Kirk Dr Brampton ON L7A 1B1	208.5	89
The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton ON L6W 1W2	76.1	97
The Butcher Engineering Enterprises Limited	105 Van Kirk Drive Brampton ON L6W 1W2	76.1	97
The Corporation of the City of Brampton	McLaughlin Road (from Lowry Drive to Wanless Drive) Brampton ON L6Y 4R2	6.5	104
Hurontario Street GP Inc.	Brampton ON M9C 5L5	6.5	104
Hurontario Street GP Inc.	Brampton ON M9C 5L5	6.5	104

Site	Address	Distance (m)	Map Key
10254 Hurontario Property Inc.	10254 Hurontario Street Brampton ON M9C 1B8	157.5	108
10254 Hurontario Property Inc.	10254 Hurontario Street Brampton ON M9C 1B8	157.5	108
10254 Hurontario Property Inc.	10254 Hurontario Street Brampton ON M9C 1B8	157.5	108
6832458 Canada Inc.	95 Van Kirk Dr Brampton ON J4H 3V6	62.1	110
GO a division of Metrolinx	85 Van Kirk Dr Brampton ON M5J 2W3	76.5	118
Metrolinx	85 Van Kirk Dr Brampton ON M5J 3A5	76.5	118
Aecon Construction and Materials Limited/Construction et Materiaux Aecon Limitee	45 Van Kirk Dr Brampton ON L7A 1A9	172.8	131
Strada Aggregates Inc.	45 Van Kirk Rd Brampton ON L4K 1L3	172.8	131
Aecon Construction and Materials Limited	45 Van Kirk Dr Brampton ON M9W 7K6	172.8	131
2066650 Ontario Inc.	Brampton ON M5C 1T4	5.8	136
2066650 Ontario Inc.	Brampton ON M5C 1T4	5.8	136
The Regional Municipality of Peel	Brampton ON L6T 4B9	5.8	136

Site	Address	Distance (m)	Map Key
2066650 Ontario Inc.	Brampton ON M5C 1T4	5.8	136
City of Toronto	Brampton ON M5V 3C6	5.8	136
Call Disposal Services Ltd.	190 Bovaird Dr W Unit #25-26R Brampton ON L9T 7T5	147.3	146
1480411 Ontario Inc.	190 Bovaird Dr W Brampton ON L7A 2Y4	147.3	146
The Regional Municipality of Peel	Bovaird Road (95m east of Sunforest Drive to 200m west of McLaughlin Road) Brampton ON	8.8	169
The Regional Municipality of Peel	Bovaird Drive Brampton ON L6T 4B9	8.8	169
The Corporation of the City of Brampton	75 Vodden St E Brampton ON L6Y 4R2	39.0	251
Imperial Oil Limited	140 Kennedy Rd N Brampton ON M3C 1K5	102.6	257
Petro-Canada	121 Kennedy Road North Brampton ON L6L 6N5	41.0	277

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Aug 31, 2024 has found that there are 91 EHS site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	225 Wanless Dr Brampton ON L7A 1E9	196.0	16
	225 Wanless Drive Brampton ON	196.0	16
	225 Wanless Drive Brampton ON L7A 1E9	196.0	16
	175 Sandalwood Parkway West Brampton ON L7A 1E8	121.0	55
	175 Sandalwood Parkway West Brampton ON L7A 1E8	121.0	55
	175 Sandalwood Parkway West Brampton ON	119.8	56
	175 Sandalwood Pkwy Brampton ON	119.8	56
	20 Fisherman Drive Brampton ON	238.5	60
	440 Railside Drive Brampton ON	182.2	64
	440 Railside Dr Brampton ON L7A1L1	182.2	64
	495619 - 153 Van Kirk Drive Brampton ON L7A 1A4	95.9	65
	153 Vankirk Dr. Brampton ON L7A 1A4	125.6	68

Site	Address	Distance (m)	Map Key
	153 Van Kirk Dr Brampton ON L7A1A4	125.6	68
	153 Van Kirk Drive Brampton ON L7A 1A4	125.6	68
	27 FISHERMAN DRIVE Brampton ON L7A 1E2	243.6	70
	443 Railside Drive Brampton ON	242.8	71
	443 Railside Drive Brampton ON	242.8	71
	170 Van Kirk Drive n/a ON L7A 1K9	241.0	75
	120A Van Kirk Drive Brampton ON L7A 1B1	244.6	86
	120 Van Kirk Dr Brampton ON L7A 1B1	246.4	87
	495618 111 Van Kirk Drive Brampton Brampton ON L7A 1A4	62.1	88
	120 Van Kirk Drive Brampton ON L7A 1B1	208.5	89
	Wanless Dr & Mclaughlin Rd N Brampton ON	193.0	90

Site	Address	Distance (m)	Map Key
	111 Van Kirk Drive Brampton ON	74.6	91
	111 Van Kirk Drive Brampton ON L7A 1A4	74.6	91
	398 Railside Drive Brampton ON L7A 1E1	110.4	92
	100 Van Kirk Drive Brampton ON	219.2	93
	105 Van Kirk Drive Brampton ON L7A 1A4	76.1	97
	105 Van Kirk Dr Brampton ON L7A1A4	76.1	97
	80 Van Kirk Drive Brampton ON L7A 1B1	246.1	107
	80 Van Kirk Drive Brampton ON	246.1	107
	70 & 80 Van Kirk Drive Brampton ON	246.1	107
	10254 Hurontario St Brampton ON	157.5	108
	10254 Hurontario St Brampton ON L7A0E4	157.5	108
	10254 Hurontario St Brampton ON L7A0E4	157.5	108

Site	Address	Distance (m)	Map Key
	10254 Hurontario St Brampton ON L7A0E4	157.5	108
	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
	95 Van Kirk Dr. Brampton ON L7A 1A4	62.1	110
	95 VAN KIRK DR BRAMPTON ON L7A 1A4	62.1	110
	95 Van Kirk Brampton ON L7A 1A4	62.1	110
	95 Van Kirk Drive Brampton ON	62.1	110
	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
	75 Van Kirk Drive Brampton ON L7A 1A4	49.2	122
	75 Van Kirk Dr Brampton ON	49.2	122
	2650 Mayfield Rd Brampton ON L7C 3K7	140.1	128

Site	Address	Distance (m)	Map Key
	Brampton Asphalt Plant Brampton ON L7A 1C7	153.8	132
	55 Van Kirk Dr, 45 Van kirk Dr, 12 Canam Crescent Brampton ON L7A 1A9	151.8	133
	20 & 30 Ironside Drive (formerly 190 Bovaird Drive) Brampton ON L7A 1A2	164.0	142
	190 BOVAIRD DR W Brampton ON L7A 1A2	172.1	143
	190 Bovaird Drive W, Brampton Brampton ON L7A 1A2	167.1	144
	190 Bovaird Dr W Brampton ON L7A1A2	147.3	146
	Bovaird Brampton ON	71.9	152
	190 Canam Cres Brampton ON L7A1A9	230.9	153
	100 Manett Crescent Brampton ON L6X 4P7	95.0	159
	0 Manett Crescent Brampton ON	87.1	162
	12461 Mclaughlin Rd Caledon ON L7C2A8	18.9	175
	12461 McLaughlin Road Kleinburg ON L7C 2A8	11.6	176

Site	Address	Distance (m)	Map Key
	Williams Parkway Brampton ON	15.5	184
	Old School Rd And Mclaughlin Rd Caledon ON	200.4	190
	370 Main Street North Brampton ON L6V 4A4	242.8	202
	370 Main Street North Brampton ON L6V 4A4	242.8	202
	367 Main St. N. Brampton ON L6X 1N6	223.1	211
	7 English Street Brampton ON L6X 1L3	214.0	212
	365 Main St N Brampton ON L6X 1N6	206.1	216
	12891 McLaughlin Road Caledon ON	187.2	222
	344 Main Street North Brampton ON L6V 1P8	104.3	227
	12891 Mclaughlin Road Caledon ON	121.4	229
	36 Vodden Street East Brampton ON L6V 4H4	53.3	235

Site	Address	Distance (m)	Map Key
	36 Vodden Street East Brampton ON	53.3	235
	36 Vodden Street East Brampton ON	53.3	235
	36 Vodden St E Brampton ON L6V4H4	53.3	235
	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
	23-0353 Brampton ON L6V	5.6	242
	Downtown Brampton Brampton ON	12.1	250
	131 Kennedy Road North Brampton ON L6V 1X9	41.5	254
	215 Centre Street North Brampton ON L6V 1T4	44.9	255
	129-131 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X9	30.4	256
	131 Kennedy Road North Brampton ON L6V 1X9	30.4	256
	140 Kennedy Rd N Brampton ON L6V2N4	102.6	257
	320 Main Street North Brampton ON	56.2	265

Site	Address	Distance (m)	Map Key
	99 Kennedy Rd N Brampton ON L6V 1X7	91.8	301
	300 Main Street North Brampton ON L6V 4H6	148.0	306
	227 Vodden St E Brampton ON L6V 1N2	186.1	308
	227 Vodden St E Brampton On Brampton ON L6V1N1	186.1	308
	227 Vodden St E Brampton ON L6V1N1	186.1	308
	227 Vodden Street East Brampton ON L6V 4J4	186.1	308
	99 Kennedy Road North Brampton ON L6V 1X7	108.3	310
	95 Kennedy Road North Brampton ON L6V 1X7	181.8	325
	225 Vodden St E Brampton ON L6V 4M1	199.0	326
	Services and Housing in the Province Brampton ON L6X 1N4	232.2	327

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Oct 2023 has found that there are 18 EXP site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC	370 MAIN ST N BRAMPTON ON	242.8	202
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257

Site	Address	Distance (m)	Map Key
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	102.6	257
2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	41.0	277
2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	41.0	277
2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	41.0	277
2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	41.0	277

FST - Fuel Storage Tank

A search of the FST database, dated Oct 2023 has found that there are 18 FST site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ROXY CONSTRUCTION CO LTD	225 WANLESS DR BRAMPTON ON	196.0	16
CITY OF BRAMPTON	120 SANDALWOOD PKWY W BRAMPTON ON	246.1	22
CITY OF BRAMPTON	120 SANDALWOOD PKWY W BRAMPTON ON	246.1	22

Site	Address	Distance (m)	Map Key
HYDRO ONE BRAMPTON	175 SANDALWOOD PKY W BRAMPTON ON	119.8	56
HYDRO ONE BRAMPTON	175 SANDALWOOD PKY W BRAMPTON ON	119.8	56
SUNCOR ENERGY PRODUCTS PARTNERSHIP	45 Van Kirk Dr Brampton ON	172.8	131
SUNCOR ENERGY PRODUCTS PARTNERSHIP	45 Van Kirk Dr Brampton ON	172.8	131
SUNCOR ENERGY PRODUCTS PARTNERSHIP	45 Van Kirk Dr Brampton ON	172.8	131
SUNCOR ENERGY PRODUCTS PARTNERSHIP	45 Van Kirk Dr Brampton ON	172.8	131
MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	102.6	257
MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	102.6	257
MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	102.6	257
MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	102.6	257
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	41.0	277

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	41.0	277
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	41.0	277
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	41.0	277
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	41.0	277

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 7 FSTH site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ROXY CONSTRUCTION CO LTD	225 WANLESS DR BRAMPTON ON L7A 1E9	196.0	16
ROXY CONSTRUCTION CO LTD	225 WANLESS DR BRAMPTON ON L7A 1E9	196.0	16
HYDRO ONE BRAMPTON NETWORKS INC	175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	119.8	56
HYDRO ONE BRAMPTON NETWORKS INC	175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	119.8	56
1451134 ONTARIO LTD	370 MAIN ST N BRAMPTON ON L6V 4A4	242.8	202
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON L6V 2N4	102.6	257

Site	Address	Distance (m)	Map Key
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON L6V 2N4	102.6	257

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Dec 31, 2024 has found that there are 506 GEN site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
RICHVALE YORK BLOCK INC.	O/A PEEL BLOCK 225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
ROXY CONSTRUCTION CO. LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
PEEL BLOCK CO. (1987) LTD.	DIV. OF BRAMPTON BRICK LTD. 225A WANLESS DR. BRAMPTON ON L7A 1E9	196.0	16
PEEL BLOCK CO. (1987) LIMITED	225A WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
PEEL BLOCK CO. (1987) LTD. 30-678	DIV. OF BRAMPTON BRICK LTD. 225A WANLESS DR. BRAMPTON ON L7A 1E9	196.0	16
PEEL BLOCK COMPANY (1987) LIMITED	225A WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
RICHVALE YORK BLOCK INC.	225A WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16

Site	Address	Distance (m)	Map Key
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON BRICK LIMITED	225 WANLESS DRIVE BRAMPTON ON	196.0	16

Site	Address	Distance (m)	Map Key
City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway W Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway West Brampton ON	246.1	22
City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	246.1	22
City of Brampton	120 Sandalwood Parkway West Brampton ON L7A 1L2	246.1	22

Site	Address	Distance (m)	Map Key
City of Brampton Public Works	120 Sandalwood Parkway West Brampton ON L7A 1L2	246.1	22
City of Brampton Public Works	120 Sandalwood Parkway West Brampton ON L7A 1L2	246.1	22
City of Brampton Public Works	120 Sandalwood Parkway West Brampton ON L7A 1L2	246.1	22
City of Brampton	Roads - Fleet, 120 Sandalwood Parkway West Brampton ON	246.1	22
HOME ALONE PROPERTY MANAGEMENT LTD	8 MILKWEED CRESCENT BRAMPTON ON	140.3	30
ROXY CONSTRUCTION LTD.	180 VAN SCOTT DRIVE, UNIT B BRAMPTON ON L7A 1E4	183.4	41
ROXY CONSTRUCTION LTD.(OUT OF BUSINESS)	180 VAN SCOTT DRIVE, UNIT B BRAMPTON ON L7A 1E4	183.4	41
ROXY CONSTRUCTION LTD.(OUT OF BUSINESS)	180 VAN SCOTT DRIVE UNIT B BRAMPTON ON L7A 1E4	183.4	41
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	102.1	42
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	102.1	42
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	102.1	42
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	102.1	42

Site	Address	Distance (m)	Map Key
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A 0L1	102.1	42
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON	102.1	42
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A0L1	102.1	42
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A0L1	102.1	42
Corporation Of The City Of Brampton	130 Sandalwood Pkwy West Brampton ON L7A0L1	102.1	42
Corporation Of The City Of Brampton Works & Transportation	130 Sandalwood Pkwy West Brampton ON L7A0L1	102.1	42
Corporation Of The City Of Brampton Works & Transportation	130 Sandalwood Pkwy West Brampton ON L7A0L1	102.1	42
Corporation Of The City Of Brampton Works & Transportation	130 Sandalwood Pkwy West Brampton ON L7A0L1	102.1	42
Belfor Property Restoration	130 Sandalwood Parkway West Brampton ON L7A 1A8	102.1	42
City of Brampton	Brampton Transit - Sandalwood, 130 Sandalwood Pkwy West Brampton ON	102.1	42
Brampton Transit	130 Sandalwood Parkway West Brampton ON	102.1	42

Site	Address	Distance (m)	Map Key
The Corporation of The City og Brampton	95 Sandelwood Pkwy. Brampton ON	167.2	46
PEELLE COMPANY LIMITED, THE	105 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	98.0	48
BRAMPTON HYDRO 05-867	175 SANDALWOOD PARKWAY WEST BRAMPTON ON L7A 1E8	119.8	56
BRAMPTON HYDRO	175 SANDALWOOD PARKWAY WEST BRAMPTON ON L7A 1E8	119.8	56
BRAMPTON HYDRO-ELECTRIC COMMISSION	175 SANDALWOOD PARKWAY WEST BRAMPTON ON L7A 1E8	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56

Site	Address	Distance (m)	Map Key
Alectra Utilities Corp.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Alectra Utilities Corp.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Alectra Utilities Corporation	175 Sandalwood Pkwy. West Brampton ON	119.8	56
City of Brampton	175 Sandalwood Parkway West Brampton ON	119.8	56
City of Brampton	175 Sandalwood Parkway West Brampton ON	119.8	56
City of Brampton	175 Sandalwood Parkway West Brampton ON	119.8	56
Alectra Utilities Corp.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
Alectra Utilities Corp.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
PEELLE COMPANY LIMITED, THE	195 SANDAL WOOD PKWY WEST BRAMPTON ON L7A 1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	98.3	61

Site	Address	Distance (m)	Map Key
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	98.3	61
PEELLE COMPANY LIMITED, THE	195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	98.3	61
The Peelle Company Limited	195 SANDALWOOD PKWY. WEST BRAMPTON ON	98.3	61

Site	Address	Distance (m)	Map Key
Hutchins & Son Automotive Limited	20 Fisherman Drive Unit #2 Brampton ON	244.3	62
Hutchins & Son Automotive Limited	20 Fisherman Drive Unit #2 Brampton ON	244.3	62
Armacell Canada	153 VAN KIRK DRIVE BRAMPTON ON	125.6	67
INDUSTRIAL THERMO POLYMERS LTD	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON	125.6	68
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68

Site	Address	Distance (m)	Map Key
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
INDUSTRIAL THERMO POLYMERS LTD.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
Armacell Canada	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
Armacell Canada	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
Armacell Canada	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
MEDIRO WROUGHT IRON LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	242.8	71
MEDIRO WROUGHT IRON LTD. 26-392	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	242.8	71
SOTAWALL INC.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	242.8	71
SOTAWALL INC.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	242.8	71
SOTAWALL LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	242.8	71
SOTAWALL LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	242.8	71
SOTAWALL LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	242.8	71

Site	Address	Distance (m)	Map Key
SOTAWALL LTD.	443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	242.8	71
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON	143.0	73
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel Inc.	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73

Site	Address	Distance (m)	Map Key
Dymin Steel	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
Dymin Steel	133 Vankirk Dr. Brampton ON L7A 1A4	143.0	73
DAY & ROSS INC.	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75

Site	Address	Distance (m)	Map Key
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
DAY AND ROSS INCORPORATED	170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	241.0	75
Day & Ross Inc.	170 VAN KIRK DRIVE BRAMPTON ON	241.0	75
Sterling Specialty Chemicals	170 Van Kirk Drive Brampton ON	241.0	75
THE STEVENS COMPANY LTD	425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	240.0	79
THE STEVENS COMPANY LTD	425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	240.0	79
THE STEVENS COMPANY LTD	425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	240.0	79
Hamilton Health Sciences Juravinski Hospital	425 Railside Drive Brampton ON L7A0N8	240.0	79
THE STEVENS COMPANY LTD	425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	240.0	79

Site	Address	Distance (m)	Map Key
Hamilton Health Sciences Corporation	Stevens Warehouse, 425 Railside Drive Brampton ON	240.0	79
SHERWIN WILLIAMS AUTO FINISHES INC	130 VAL KIRK DR. BRAMPTON ON L7A 1B1	212.1	81
SHERWIN WILLIAMS AUTO FINISHES INC11-314	130 VAL KIRK DR. BRAMPTON ON L7A 1B1	212.1	81
SHERWIN WILLIAMS AUTO FINISHES INC	130 VAL KIRK DR BRAMPTON ON L7A 1B1	212.1	81
SHERWIN WILLIAMS AUTO FINISHES INC.	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
SHERWIN WILLIAMS	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
CUSTOM COLOUR PAINTS LTD.	130 VAN KIRK DR. BRAMPTON ON L7A 1B1	212.1	81
CUSTOM COLOUR PAINTS LTD.	130 VAN KIRK DR. BRAMPTON ON L7A 1B1	212.1	81
CUSTOM (SEE & USE ON0004205)	130 VAN KIRK DR. BRAMPTON ON L7A 1B1	212.1	81
CUSTOM (SEE & USE ON0004205) 11-314	130 VAN KIRK DR. BRAMPTON ON L7A 1B1	212.1	81
CUSTOM COLOUR PAINTS (SEE&USE ON000420)	130 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81

Site	Address	Distance (m)	Map Key
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON	212.1	81
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY performance coatings	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY performance coatings	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
THE SHERWIN-WILLIAMS COMPANY performance coatings	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
Sherwin Williams Canada Product Finishes	130 VAN KIRK DR BRAMPTON ON	212.1	81

Site	Address	Distance (m)	Map Key
Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	111.8	84
Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	111.8	84
Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	111.8	84
Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	111.8	84
Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	111.8	84
Region Of Peel	420 Railside Drive Brampton ON L7A 1L1	111.8	84
Regional Municipality of Peel	420 Railside Drive Brampton ON	111.8	84
EXACTA FABTOOL LIMITED	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	208.5	89
Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	208.5	89
WILSON TOOL CANADA	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	208.5	89
Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	208.5	89
WILSON TOOL CANADA	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	208.5	89

Site	Address	Distance (m)	Map Key
Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	208.5	89
Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	208.5	89
WILSON TOOL CANADA	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	208.5	89
Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	208.5	89
WILSON TOOL CANADA	120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	208.5	89
Total Body Care Inc.	120A Van Kirk Drive Brampton ON L7A 1B1	208.5	89
WILSON TOOL CANADA-PRESS BRAKE DIVISION	120 Van Kirk Drive Brampton ON	208.5	89
Total Body Care Inc.	120A Van Kirk Drive Brampton ON	208.5	89
1000456356 Ontario Inc.	120 Van Kirk Drive Brampton ON	208.5	89
BUTCH ENGINEERING ENTERPRISES LTD.	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	76.1	97
BUTCHER ENGINEERING ENTERPRISES LTD.	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	76.1	97

Site	Address	Distance (m)	Map Key
BUTCH ENGINEERING ENTERPRISES LTD.06-157	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	76.1	97
BUTCHER ENGINEERING ENTERPRISES LTD.	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	76.1	97
BUTCHER ENGINEERING ENTERPRISES LTD.	105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	76.1	97
Archway Marketing Service	80 Van Kirk Drive Brampton ON L7A 1B1	246.1	107
SOTAWALL INC.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	246.1	107
SOTAWALL INC.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	246.1	107
SOTAWALL LTD.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	246.1	107
SOTAWALL LTD.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	246.1	107
SOTAWALL LTD.	80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	246.1	107
Harmon Facades ULC (aka Sotawall)	80 VAN KIRK DRIVE BRAMPTON ON	246.1	107
CT REIT (Hurontario) Limited Partnership, by its g	10254 Hurontario Street Brampton ON L7A 0E4	157.5	108
SONCO STEEL TUBE LTD	95 VANKIRK DR. BRAMPTON ON L7A 1A4	62.1	110

Site	Address	Distance (m)	Map Key
SONCO STEEL TUBE LTD 35-058	95 VANKIRK DR. BRAMPTON ON L7A 1A4	62.1	110
SONCO STEEL TUBE LTD.	95 VANKIRK DRIVE BRAMPTON ON L7A 1A4	62.1	110
SONCO (SEE & USE ON0164204)	95 VANKIRK DRIVE BRAMPTON ON L7A 1A4	62.1	110
LTV COPPERWELD	95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	62.1	110
COPPERWELD CANADA INC.	95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	62.1	110
Brampton-Canada Associates Ltd.	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
Brampton-Canada Associates Ltd.	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
Metelix Products inc	95 Van Kirk Drive Brampton ON	62.1	110
Metelix Products inc	95 Van Kirk Drive Brampton ON	62.1	110
Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110

Site	Address	Distance (m)	Map Key
Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
Metelix Products inc	95 Van Kirk Drive Brampton ON L7A 1A4	62.1	110
METELIX PRODUCTS INC.	95 Van Kirk Drive Brampton ON	62.1	110
1955379 ONTARIO INC	95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	62.1	110
Elgner Group Investments Ltd.	95 Van Kirk Drive Brampton ON	62.1	110
Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118
Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118
Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118
Metrolinx	85 Van Kirk Drive Brampton ON	76.5	118
Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118

Site	Address	Distance (m)	Map Key
Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118
Metrolinx	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118
Metrolinx GO Transit	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118
Metrolinx GO Transit	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118
Metrolinx GO Transit	85 Van Kirk Drive Brampton ON L7A 1A4	76.5	118
Metrolinx - Bus	85 Van Kirk Drive Brampton ON	76.5	118
NHD GROUP LTD.	70 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	233.5	120
NHD GROUP LTD. 28-640	70 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	233.5	120
N.H.D. GROUP LTD.	70 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	233.5	120
Exel Canada Ltd. c/o Keurig Canada	100 Ironside Dr. Unit 1 Brampton ON L4A0X4	180.2	125
DHL Supply Chain	100 Ironside Dr. Unit 1 Brampton ON L4A0X4	180.2	125

Site	Address	Distance (m)	Map Key
ARMBRO CONSTRUCTION 02-735	45 VAN KIRK DRIVE C/O 25 VAN KIRK DRIVE, UNIT #8 BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	172.8	131
AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON	172.8	131
AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	172.8	131
AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131
AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131
AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	172.8	131
AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON	172.8	131

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON	172.8	131
AECON CONSTRUCTION AND MATERIALS LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	172.8	131
AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131
AECON GROUP INCORPORATED	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	172.8	131
AECON CONSTRUCTION AND MATERIALS LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131
AECON CONSTRUCTION AND MATERIALS LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131

Site	Address	Distance (m)	Map Key
AECON CONSTRUCTION AND MATERIALS LTD.	45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131
GIP Constructions and Materials Limited	45 VAN KIRK DRIVE BRAMPTON ON	172.8	131
SUNCOR ENERGY	45 VANKIRK BRAMPTON ON L7A1A6	172.8	131
AMBRO DIESEL SALES AND SERVICE	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	141.4	140
AMBRO DIESEL SALES AND SERVICE	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	141.4	140
AMBRO DIESEL SALES AND SERVICE 03-260	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	141.4	140
ROTO-MILL SERVICES LTD.	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	141.4	140
ROTO-MILL SERVICES LIMITED	12 CANAM CRESCENT BRAMPTON ON L7A 1A9	141.4	140
Aecon Group Inc	12 Canam Cres Brampton ON L7A 1A9	141.4	140
CANADIAN MINE DEVELOPMENT	BEHIND 35 VAN KIRK DR. BRAMPTON ON L7A 1A5	245.9	141
CANADIAN MINE DEVELOPMENT	BEHIND 35 VAN KIRK DR. BRAMPTON ON L7A 1A5	245.9	141

Site	Address	Distance (m)	Map Key
CANADIAN MINE DEVELOPMENT 08-349	BEHIND 35 VAN KIRK DR. BRAMPTON ON L7A 1A5	245.9	141
BRAMPTON GUARD(OUT OF BUSINESS) 05-804	35 VAN KIRK DRIVE, UNIT 17 BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VANKIRK DRIVE, UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141

Site	Address	Distance (m)	Map Key
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
ACCURATE AIR COMPRESSORS INC.	35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	245.9	141
Mantella Corporation	35 Van Kirk Drive Brampton ON	245.9	141
PACEMARATHON MOTOR LINES	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	147.3	146
SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A 1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A 1A2	147.3	146

Site	Address	Distance (m)	Map Key
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	147.3	146
SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A 1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON	147.3	146
KENCO MECHANICAL MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON	147.3	146
SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	147.3	146

Site	Address	Distance (m)	Map Key
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	147.3	146
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	147.3	146
SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A1A2	147.3	146
KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A1A2	147.3	146
KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	147.3	146
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
Rice Development	190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	147.3	146
KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	147.3	146

Site	Address	Distance (m)	Map Key
SDH Inc	190 Bovaird Dr West Unit 15 Brampton ON L7A1A2	147.3	146
Kris Kay Truck Lines	190 Bovaird Dr. W #32 Brampton ON L7A 1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
SDH Inc	190 Bovaird Drive West Unit 15 Brampton ON L7A 1A2	147.3	146
KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	147.3	146
JSS Solvents Inc.	190 Bovaird Dr. West Unit #38 Brampton ON L7A1A2	147.3	146
KENCO MACHINERY MOVERS&MILLRIGHTS	190 BOVAIRD DRIVE WEST UNITS 25&26 R BRAMPTON ON L7A1A2	147.3	146
SDH Inc	190 Bovaird Drive West Unit 15 Brampton ON L7A 1A2	147.3	146
1012582 ONTARIO LTD.	190 Bovaird Dr W #35A Brampton ON L7A 1A2	147.3	146
SDH Inc	190 Bovaird Drive West Unit 15 Brampton ON L7A 1A2	147.3	146
Maple Reinders Constructors	190 Bovaird Rd W Brampton ON L7A 1A2	147.3	146

Site	Address	Distance (m)	Map Key
Attrell Toyota	110 Canam Drive Brampton ON L7A 2A9	49.6	147
Brenntag Canada Inc	110 Canam Crescent Brampton ON	49.6	147
Kia of Brampton	9 Canam cres. Brampton ON L7A 1G1	246.6	148
Chrysler Group LLC	190 Canam Crescent Brampton ON	230.9	153
1737126 Ont Inc.	100 Manett Cres. Brampton ON L6X 4X4	95.0	159
The Everlast Group	12461 Mclaughlin Road Caledon ON	238.5	178
SUNOCO INC.	370 MAIN STREET BRAMPTON ON L6V 4A4	242.8	202
BRIDLEWOOD CLEANERS	604575 ONTARIO LTD. 370 MAIN STREET NORTH BRAMPTON ON L6V 4A4	242.8	202
BRIDLEWOOD CLEANERS, 604575 ONTARIO LTD.	370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	242.8	202
BRIDLEWOOD CLEANERS 06-096	604575 ONTARIO LTD. 370 MAIN STREET NORTH BRAMPTON ON L6V 4A4	242.8	202
BRIDLEWOOD CLEANERS	370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	242.8	202
GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.	SUPER FRESH #098 370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	242.8	202

Site	Address	Distance (m)	Map Key
434173 ONTARIO LTD.	O/A BRIDLEWOOD DRY CLEANERS 370 MAIN ST. SOUTH BRAMPTON ON L6V 1P8	242.8	202
BRIDLEWOOD DRY CLEANERS	370 MAIN STREET BRAMPTON ON L6V 4A4	242.8	202
FIRST QUALITY 1 HOUR PHOTO 15-680	370 MAIN STREET BRAMPTON ON L6V 4A4	242.8	202
434173 ONTARIO LTD. 43-172	O/A BRIDLEWOOD DRY CLEANERS 370 MAIN ST. SOUTH BRAMPTON ON L6V 1P8	242.8	202
BRIDLEWOOD DRY CLEANERS	370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	242.8	202
KINGSPOINT PROPERTY	370 MAIN ST. BRAMPTON ON L6V 4A4	242.8	202
Suncor Energy Products	370 MAIN STREET BRAMPTON ON	242.8	202
The Cannington Group Inc	370 Main Street Brampton ON L6V 4A4	242.8	202
Suncor Energy Products	370 MAIN STREET BRAMPTON ON L6V 4A4	242.8	202
9495088 Canada Inc	370 Main St N Brampton ON L6V 4A4	242.8	202
Alectra Utilities Corporation	8 Martindale Crescent Brampton ON	222.3	203

Site	Address	Distance (m)	Map Key
Counsel Kingspoint Ltd.	366 Main St. Brampton ON	248.5	204
John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	248.5	204
WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	248.5	204
WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	248.5	204
John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	248.5	204
WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	248.5	204
John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	248.5	204
WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	248.5	204
Queen Square Family Health Team	366 Main Street North Suite 203 Brampton ON L6V 1P8	248.5	204
John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	248.5	204
Queen Square Family Health Team	366 Main Street North Suite 203 Brampton ON L6V 1P8	248.5	204
WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	248.5	204

Site	Address	Distance (m)	Map Key
John Palumbo Pharmacy Ltd.	366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	248.5	204
Queen Square Family Health Team	366 Main Street North Suite 203 Brampton ON L6V 1P8	248.5	204
WILTADEN LIMITED	366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	248.5	204
Samara Al Windawi	366 Main Street North, Suite 203 Brampton ON	248.5	204
Shoppers Drug Mart 1353	366 MAIN STREET NORTH BRAMPTON ON	248.5	204
Shoppers Drug Mart #1353	366 Main Street North Brampton ON	248.5	204
SIR JOHN A. MACDONALD SR.PUB. SCHL.	PEEL BOARD OF EDUCATION 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4	229.9	208
SIR JOHN A. MACDONALD SR.PUB. SCHL.30-247	PEEL BOARD OF EDUCATION 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4	229.9	208
PEEL DISTRICT SCHOOL BOARD	SIR JOHN A. MACDONALD SR. PUBLIC SCHOOL 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4	229.9	208
DUFFERIN-PEEL R.C.S.S. BOARD	ST. ANNE 124 VODDEN ST BRAMPTON ON	79.8	230
HY & ZEL'S INC.	12 VODDEN STREET BRAMPTON ON L6Y 1A2	73.9	232

Site	Address	Distance (m)	Map Key
Big Lots Canada Inc.	12 Vodden Street East Brampton ON	73.9	232
Big Lots Canada Inc.	12 Vodden Street East Brampton ON	73.9	232
VODDEN XRAY	36 VODDEN STREET EAST BRAMPTON ON L6V 1M4	53.3	235
VODDEN MEDICAL ARTS PHARMACY	36 VODDEN STREET EAST BRAMPTON ON L6V 1M4	53.3	235
VODDEN MEDICAL ARTS PHARMACY	36 vodden st e brampton ON L6V 4H4	53.3	235
CMLHealthCare	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 304 Brampton ON L6V 4H4	53.3	235
CMLHealthCare	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 304 Brampton ON L6V 4H4	53.3	235
North Brampton Physiotherapy	36 Vodden Street E. Suite 306 Brampton ON L6V 4H4	53.3	235
CMLHealthCare	36 Vodden Street East Brampton ON L6V 4H4	53.3	235

Site	Address	Distance (m)	Map Key
1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 304 Brampton ON L6V 4H4	53.3	235
1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	53.3	235
North Brampton Physiotherapy	36 Vodden Street E. Suite 306 Brampton ON L6V 4H4	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 304 Brampton ON	53.3	235
Wise Elephant FHT	36 Vodden Street E Suite 203 ON	53.3	235
1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	53.3	235
Wise Elephant FHT	36 Vodden Street E Suite 203 ON L6V4H4	53.3	235

Site	Address	Distance (m)	Map Key
Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
Wise Elephant FHT	36 Vodden Street E Suite 203 ON L6V4H4	53.3	235
1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	53.3	235
Wise Elephant FHT	36 Vodden Street E Suite 203 ON L6V4H4	53.3	235
1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON L5C1V8	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION	36 Vodden St E Suite 105 Brampton ON L6V 4H4	53.3	235

Site	Address	Distance (m)	Map Key
Wise Elephant FHT	36 Vodden Street E Suite 203 ON L6V4H4	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	53.3	235
SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION	36 Vodden St E Suite 105 Brampton ON L6V 4H4	53.3	235
COMPLETE IMMIGRATION MEDICAL CENTRE	36 VODDEN STREET EAST,SUITE 203 BRAMPTON ON L6V4H4	53.3	235
SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION	36 Vodden St E Suite 105 Brampton ON L6V 4H4	53.3	235
Saint Elizabeth Health Care	36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	53.3	235
COMPLETE IMMIGRATION MEDICAL CENTRE	36 VODDEN STREET EAST,SUITE 203 BRAMPTON ON L6V4H4	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
Complete Immigration Medical Centre	36 VODDEN STREET EAST,SUITE 203 BRAMPTON ON	53.3	235

Site	Address	Distance (m)	Map Key
Saint Elizabeth Health Care	36 Vodden St. E, Suite 202 Brampton ON	53.3	235
LifeLabs LP	36 Vodden Street East Brampton ON L6V 4H4	53.3	235
Smilemakers Dental	36 Vodden St E Suite 105 Brampton ON	53.3	235
Coverdale Infusion Clinic Inc	36 Vodden Street East Brampton ON	53.3	235
1798836 Ontario Inc.	36 Vodden Street, Suite 304 Brampton ON L6V 4H4	24.1	244
Kennedy Road Tabernacle	141 Kennedy Road N Brampton ON L6V 1X9	70.4	246
The Corporation of The City of Brampton	75 Vodden St. East Brampton ON	39.0	251
The Corporation of The City of Brampton	75 Vodden St. East Brampton ON L6V2R2	39.0	251
The Corporation of The City of Brampton	75 Vodden St. East Brampton ON L6V2R2	39.0	251
The Corporation of The City of Brampton	75 Vodden St. East Brampton ON L6V2R2	39.0	251
The Corporation of The City of Brampton Buildings and Property Management	75 Vodden St. East Brampton ON L6V2R2	39.0	251
The Corporation of The City of Brampton Buildings and Property Management	75 Vodden St. East Brampton ON L6V2R2	39.0	251

Site	Address	Distance (m)	Map Key
The Corporation of The City of Brampton Buildings and Property Management	75 Vodden St. East Brampton ON L6V2R2	39.0	251
City of Brampton	Fire Station 207, 75 Vodden St. East Brampton ON	39.0	251
Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	63.1	266
Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	63.1	266
Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	63.1	266
Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	63.1	266
Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	63.1	266
Main Street Dental Office	320 Main Street N unit #9 Brampton ON L6V4A3	63.1	266
Main Street Dental Office	320 Main Street North Brampton ON	63.1	266
Suncor Energy Products	121 Kennedy Road N Brampton ON L6V1X	41.0	277
Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	41.0	277

Site	Address	Distance (m)	Map Key
Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	41.0	277
Suncor Energy Products Partnership	121 Kennedy Road North Brampton ON	41.0	277
BRAMPTON HYDRO-ELECTRIC COMMISSION	HANSEN ROAD-SOUTH OF VODDEN 129 GLIDDEN ROAD BRAMPTON ON L6W 3L9	240.6	284
BRAMPTON HYDRO-ELECTRIC COMMISSION06-328	HANSEN ROAD-SOUTH OF VODDEN 129 GLIDDEN ROAD BRAMPTON ON L6W 3L9	240.6	284
BRAMPTON HYDRO-ELECTRIC COMMISSION	HANSEN ROAD-SOUTH OF VODDEN BRAMPTON ON	240.6	284
LEO ARCHDEKIN FUNERAL HOME	289 MAIN STREET N. BRAMPTON ON L6X 1N5	138.4	304
LEO ARCHDEKIN FUNERAL HOME	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
TRILLIUM FUNERAL SERVICES CORP.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
LEO ARCHDEKIN FUNERAL HOME 44-011	289 MAIN STREET N. BRAMPTON ON L6X 1N5	138.4	304
SCOTT FUNERAL HOME, DIV. OF 44-543	TRILLIUM FUNERAL SERVICES CORP. 289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
TRILLIUM FUNERAL SERVICES CORPORATION	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304

Site	Address	Distance (m)	Map Key
TRILLIUM FUNERAL SERVICES CORPORATION	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
TRILLIUM FUNERAL SERVICES CORPORATION	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
TRILLIUM FUNERAL SERVICES CORPORATION	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON	138.4	304
ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
ARBOR MEMORIAL INC.	289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	138.4	304
Scott Funeral Home - Brampton Chapel	289 MAIN STREET NORTH BRAMPTON ON	138.4	304

Site	Address	Distance (m)	Map Key
Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON L6V 4H6	148.0	306
Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON L6V 4H6	148.0	306
Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON L6V 4H6	148.0	306
Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON L6V 4H6	148.0	306
Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON L6V 4H6	148.0	306
Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON L6V 4H6	148.0	306
Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON	148.0	306
Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON	148.0	306
Central Brampton Family Health Team	300 Main St. N, #200 Brampton ON L6V 4H6	148.0	306
Central Brampton Family Health Team	300 Main St. N,2and Floor Brampton ON L6V 4H6	148.0	306
Queen West Medical Associates	300 Main Street North, Suite 100 Brampton ON L6V4H6	148.0	306

Site	Address	Distance (m)	Map Key
Brampton East Medical Group	300 Main St. N,2and Floor Brampton ON L6V 4H6	148.0	306
Dr Essam Michael Medicine Professional Corporation	300 Main St N Brampton ON L6V 1P6	148.0	306
Dr Essam Michael Medicine Professional Corporation	300 Main St N Brampton ON L6V 1P6	148.0	306
Dr Essam Michael Medicine Professional Corporation	300 Main St N Brampton ON L6V 1P6	148.0	306
Astra Fertility Group	Astra Fertility, 300 Main St N Brampton ON	148.0	306
PHARMA PLUS DRUGS LTD	227 VODDEN STREET BRAMPTON ON L6V 1N2	186.1	308
PHARMA PLUS DRUGS LTD. 31-751	227 VODDEN ST., BRAMPTON C/O 5935 AIRPORT ROAD #500 MISSISSAUGA ON L4V 1W5	186.1	308
PHARMA PLUS DRUGMARTS LTD.	227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	186.1	308
GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.	FOOD BASICS #983 227 VODDEN STREET BRAMPTON ON L6V 1N2	186.1	308
PHARMA PLUS DRUGS LTD.	227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	186.1	308
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	186.1	308
1723525 Ontario Inc.	227 Vodden Street East Unit 30B Brampton ON	186.1	308

Site	Address	Distance (m)	Map Key
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	186.1	308
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	186.1	308
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON	186.1	308
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	186.1	308
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	186.1	308
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	186.1	308
Pharma Plus Drugmarts Ltd	227 Vodden Street East Brampton ON L6V 1N2	186.1	308
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	186.1	308
Pharma Plus Drugmarts Ltd	227 Vodden Street East Brampton ON L6V 1N2	186.1	308
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	186.1	308
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	186.1	308

Site	Address	Distance (m)	Map Key
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	186.1	308
Rexall Pharmacy Group Ltd	227 Vodden Street East Brampton ON	186.1	308
PHOTOGRAPHIC IMAGERY	21 HARMSWORTH AVENUE BRAMPTON ON L6X 2N2	205.3	322
COLOUR CRAFT LABS	116 MILL STREET NORTH BRAMPTON ON L6X 2P2	168.1	324

GHG - Greenhouse Gas Emissions from Large Facilities

A search of the GHG database, dated 2013-Apr 2024 has found that there are 1 GHG site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Brampton Brick Limited	225 Wanless Drive Brampton ON L7A 1E9	196.0	16

HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 4 HINC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	37 BANINGTON CRESCENT BRAMPTON ON L7A 1G4	115.8	72
	27 TOLTON DRIVE BRAMPTON ON L6V 2P9	133.6	221
	71 Greene Drive BRAMPTON ON L6V 2P2	211.9	225

Site	Address	Distance (m)	Map Key
	222 CENTRE STREET NORTH BRAMPTON ON L6V 2R4	59.7	233

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated 31 Oct, 2023 has found that there are 4 INC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	225a Wanless Drive, Brampton ON	196.0	16
	105 VAN KIRK DR, BRAMPTON ON	76.1	97
	Main Street & Vodden Street, Brampton ON	3.5	248
	227 VODDEN STREET EAST, BRAMPTON ON	186.1	308

NCPL - Non-Compliance Reports

A search of the NCPL database, dated Dec 31, 2023 has found that there are 1 NCPL site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Aecon Construction and Materials Limited	45 Van Kirk Dr Brampton ON	172.8	131

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 8 NPCB site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BRAMPTON HYDRO	175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	119.8	56
BRAMPTON HYDRO NETWORKS INC.	175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	119.8	56
BRAMPTON HYDRO NETWORKS INC.	175 Sandalwood Pkwy. West Brampton ON L7A 1E8	119.8	56
BRAMPTON HYDRO	175 SANDALWOOD PKWY SANDALWOOD PKWY BRAMPTON ON L7A 1E8	119.8	56
BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON	119.8	56
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION	45 VAN KIRK RD BRAMPTON ON L7A 1A6	172.8	131
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD VAN KIRK RD BRAMPTON ON L7A 1A6	172.8	131

NPR2 - National Pollutant Release Inventory

A search of the NPR2 database, dated Feb 2024 has found that there are 10 NPR2 site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BRAMPTON BRICK	225 WANLESS DRIVE BRAMPTON ON L7A1E9	196.0	16
HYDRO ONE BRAMPTON	175 SANDALWOOD PKWY., WEST BRAMPTON ON L7A1E8	119.8	56

Site	Address	Distance (m)	Map Key
ARMACELL CANADA INC.	153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	125.6	68
BRAMPTON	130 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	212.1	81
VAN KIRK PLANT	105 VAN KIRK DR. BRAMPTON ON L7A1A4	76.1	97
VANKIRK	105 VANKIRK BRAMPTON ON L7A1A4	76.1	97
COPPERWELD CANADA INC. - VAN KIRK DRIVE	95 VAN KIRK DRIVE BRAMPTON ON L7A1A4	62.1	110
PORTABLE PLANT #2	45 VAN KIRK DRIVE BRAMPTON ON L7A1A6	172.8	131
PORTABLE PLANT #3	45 VAN KIRK DRIVE BRAMPTON ON L7A1A6	172.8	131
BRAMPTON ASPHALT PLANT	45 VAN KIRK DRIVE BRAMPTON ON L7A1A6	172.8	131

NPRI - National Pollutant Release Inventory - Historic

A search of the NPRI database, dated 1993-May 2017 has found that there are 9 NPRI site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
LAFARGE CANADA INC.	225 WANLESS Drive BRAMPTON ON L7A1E9	196.0	16

Site	Address	Distance (m)	Map Key
BENTALL REAL ESTATE SERVICES	440 Railside Drive Brampton ON L7A1L1	182.2	64
THE BUTCHER ENGINEERING ENTERPRISES LTD.	105 Van Kirk Dr. Brampton ON L7A1A4	76.1	97
BUTCHER ENTERPRISES	105 VanKirk Brampton ON L7A1A4	76.1	97
STRADA AGGREGATES	45 VANKIRK Avenue BRAMPTON ON L1L6G6	172.8	131
STRADA AGGREGATES	45 VANKIRK Avenue BRAMPTON ON L1L6G6	172.8	131
STRADA AGGREGATES	45 VANKIRK Avenue BRAMPTON ON L1L6G6	172.8	131
THE GREAT ATLANTIC & PACIFIC COMPANY OF CANAD	370 MAIN Street North BRAMPTON ON L6V1P8	242.8	202
ZELLERS	227 VODDEN Street BRAMPTON ON L6V1N2	186.1	308

OPCB - Inventory of PCB Storage Sites

A search of the OPCB database, dated 1987-Oct 2004; 2012-Dec 2013 has found that there are 13 OPCB site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Brampton Hydro	175 Sandalwood Pkwy Brampton ON L7A 1E8	119.8	56
BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	119.8	56

Site	Address	Distance (m)	Map Key
BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	119.8	56
BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	119.8	56
BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	119.8	56
Brampton Hydro	175 Sandalwood Pkwy Brampton ON L7A 1E8	119.8	56
BRAMPTON HYDRO	175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	119.8	56
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION	45 VAN KIRK RD BRAMPTON ON L7A 1A4	172.8	131
ARMBRO CONSTRUCTION LTD.	45 VAN KIRK RD BRAMPTON ON L7A 1A4	172.8	131

PES - Pesticide Register

A search of the PES database, dated Oct 2011 - May 31, 2025 has found that there are 103 PES site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	143.7	31
NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	143.7	31
	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	143.7	31
	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	143.7	31
NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	143.7	31
NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	143.7	31
NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	143.7	31
NH PEST CONTROL INC.	4 NARCISSUS GATE BRAMPTON ON L7A 1V9	143.7	31
NH PEST CONTROL INC.	2 NARCISSUS GATE BRAMPTON ON L7A1V9	153.8	34
RATRO PEST CONTROL INC.	194 VAN SCOTT DR BRAMPTON ON L7A 1V8	182.7	40
RATRO PEST CONTROL INC.	194 VAN SCOTT DR BRAMPTON ON L7A 1V8	182.7	40

Site	Address	Distance (m)	Map Key
PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A 3J8	167.3	45
PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A 3J8	167.3	45
PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A3J8	167.3	45
PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A3J8	167.3	45
PREMIER TURF INC	39 PAPPAIN CRES BRAMPTON ON L7A3J8	167.3	45
Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	16.7	50
Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	16.7	50
Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	16.7	50
	154 Twin Pines Crescent Brampton ON L7A 1N2	16.7	50
Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	16.7	50
Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	16.7	50

Site	Address	Distance (m)	Map Key
Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	16.7	50
Zeta Pest Control Inc.	154 Twin Pines Crescent Brampton ON L7A 1N2	16.7	50
CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A 1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST BRAMPTON ON L7A1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	130.3	53

Site	Address	Distance (m)	Map Key
CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	130.3	53
	11 TINSMITH ST brampton ON L7A 1N3	130.3	53
CANADA PEST CONTROL INC.	11 TINSMITH ST brampton ON L7A 1N3	130.3	53
BRAMPTON PEST CONTROL	200 CRESTHAVEN RD, UNIT 78 BRAMPTON ON L7A 1J5	198.5	63
ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A 1L1	182.2	64
ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A 1L1	182.2	64
ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A 1L1	182.2	64
ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A1L1	182.2	64
ITWAL LIMITED	440 Railside DR Brampton ON L7A 1L1	182.2	64
ITWAL LIMITED	440 RAILSIDE DR BRAMPTON ON L7A1L1	182.2	64

Site	Address	Distance (m)	Map Key
1569692 ONTARIO LTD. O/A CANADIAN GREEN	7 DELPHINIUM WAY BRAMPTON ON L7A 0N4	248.7	94
2582011 ONTARIO INC. O/A TRULY NOLEN	32 BAYBROOK RD BRAMPTON ON L7A1M1	248.1	129
2582011 ONTARIO INC.	32 BAYBROOK RD BRAMPTON ON L7A 1M1	248.1	129
2582011 ONTARIO INC.	32 BAYBROOK RD BRAMPTON ON L7A 1M1	248.1	129
VERDE PROPERTY MAINTENANCE LTD	25 VIRGINIA DR BRAMPTON ON L7A 2E6	61.6	135
VERDE PROPERTY MAINTENANCE LTD	25 VIRGINIA DR BRAMPTON ON L7A2E6	61.6	135
VERDE PROPERTY MAINTENANCE LTD	25 VIRGINIA DR BRAMPTON ON L7A2E6	61.6	135
VERDE PROPERTY MAINTENANCE LTD	25 VIRGINIA DR BRAMPTON ON L7A2E6	61.6	135
SDH INC. O/A CLINTAR OUTDOOR SERVICES	15 - 190 BOVAIRD DR W BRAMPTON ON L7A1A2	147.3	146
SDH INC.	190 Bovaird DR W Brampton ON L7A 1A2	147.3	146
SDH INC.	190 Bovaird DR W Brampton ON L7A 1A2	147.3	146
SPECIALIST PEST CONTROL SERVICES	106 RICHWOOD CRES. BRAMPTON ON L6X 4K7	163.6	168

Site	Address	Distance (m)	Map Key
SPECIALIST PEST CONTROL SERVICES	106 RICHWOOD CRES. BRAMPTON ON L6X 4K7	163.6	168
8016917 CANADA INC.	106 RICHWOOD CRES BRAMPTON ON L6X4K7	163.6	168
8016917 CANADA INC. O/A PEST CONTROL COMPANY GTA	106 RICHWOOD CRES BRAMPTON ON L6X4K7	163.6	168
8016917 CANADA INC.	106 Richwood Cres Brampton ON L6X 4K7	163.6	168
SPECIALIST PEST CONTROL SERVICES	106 RICHWOOD CRES. BRAMPTON ON L6X4K7	163.6	168
8016917 CANADA INC.	106 RICHWOOD CRES BRAMPTON ON L6X4K7	163.6	168
SPECIALIST PEST CONTROL SERVICES	106 RICHWOOD CRES. BRAMPTON ON L6X4K7	163.6	168
8016917 CANADA INC.	106 Richwood Cres Brampton ON L6X 4K7	163.6	168
GREENLAND VIEW LANDSCAPING	48 HORSHAM STREET BRAMPTON ON L6X 3R2	169.4	171
GREENLAND VIEW LANDSCAPING	48 HORSHAM ST BRAMPTON ON L6X 3R2	169.4	171
GREENLAND VIEW LANDSCAPING	48 HORSHAM ST BRAMPTON ON L6X3R2	169.4	171

Site	Address	Distance (m)	Map Key
GREENLAND VIEW LANDSCAPING	48 HORSHAM ST BRAMPTON ON L6X3R2	169.4	171
Supreme Pest Control Corporation	12 RICHWOOD CRES BRAMPTON ON L6X 4K9	183.4	173
Supreme Pest Control Corporation	12 RICHWOOD CRES BRAMPTON ON L6X 4K9	183.4	173
Supreme Pest Control Corporation	12 RICHWOOD CRES BRAMPTON ON L6X 4K9	183.4	173
Supreme Pest Control Corporation	12 RICHWOOD CRES BRAMPTON ON L6X 4K9	183.4	173
TOWERS DEPARTMENT STORE STORE #46	370 MAIN STREET NORTH BRAMPTON ON L6V 4A4	242.8	202
GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED	370 MAIN ST N BRAMPTON ON L6V 4A4	242.8	202
GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED	370 MAIN ST N BRAMPTON ON L6V 4A4	242.8	202
GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED	370 MAIN ST N BRAMPTON ON L6V 4A4	242.8	202
GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED	370 MAIN ST N BRAMPTON ON L6V4A4	242.8	202
JOHN PALUMBO PHARMACY LTD. O/A SHOPPERS DRUG MART #1353	366 MAIN STREET N BRAMPTON ON L6V1P8	248.5	204
JOHN PALUMBO PHARMACY LTD.	366 Main ST N Brampton ON L6V 1P8	248.5	204

Site	Address	Distance (m)	Map Key
JOHN PALUMBO PHARMACY LTD. O/A SHOPPERS DRUG MART #1353	366 MAIN STREET N BRAMPTON ON L6V1P8	248.5	204
ENVIRO MASTERS (ETOBICOKE)	84 KINGSWOOD DRIVE BRAMPTON ON L6V 2W3	223.5	217
PETER'S NO FRILLS	345 MAIN STREET BRAMPTON ON L6X1N6	89.5	231
1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS	345 MAIN ST N BRAMPTON ON L6X 1N6	89.5	231
1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS	345 MAIN ST N BRAMPTON ON L6X 1N6	89.5	231
1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS	345 MAIN ST N BRAMPTON ON L6X1N6	89.5	231
FORTINO'S (VODDEN) LTD.	345 MAIN STREET NORTH BRAMPTON ON L6X1N6	89.5	231
HY & ZELS - BRAMPTON	12 VODDEN STREET BRAMPTON ON L6Y1A2	73.9	232
HY & ZELS - BRAMPTON	12 VODDEN STREET BRAMPTON ON L6Y1A2	73.9	232
THE XTERMINATOR	52 CUMBERLAND DR BRAMPTON ON L6V 1W6	134.4	298
ZELLERS LIMITED 146	227 VODDEN STREET CENTENNIAL MALL BRAMPTON ON	186.1	308

Site	Address	Distance (m)	Map Key
ZELLERS LIMITED 146	227 VODDEN STREET CENTENNIAL MALL BRAMPTON ON L6V 1N2	186.1	308
ZELLERS STORE #146- CENTENNIAL MALL	227 VODDEN ST BRAMPTON ON L6V1N2	186.1	308
ZELLERS LIMITED 146	227 VODDEN ST; CENTENNIAL MALL BRAMPTON ON L6V1N2	186.1	308
METRO ONTARIO INC O/A METRO/FOOD BASICS # 904	227 VODDEN STREET BRAMPTON ON L6V1N2	186.1	308
ZELLERS INC	227 VODDEN STREET N BRAMPTON ON L6V1N2	186.1	308
ZELLERS INC	227 VODDEN STREET N BRAMPTON ON L6V 1N2	186.1	308
METRO ONTARIO INC O/A METRO/FOOD BASICS # 904	227 Vodden Street Brampton ON L6V 1N2	186.1	308
METRO ONTARIO INC O/A METRO/FOOD BASICS # 904	227 VODDEN STREET BRAMPTON ON L6V1N2	186.1	308
ZELLERS LIMITED 146	227 VODDEN ST; CENTENNIAL MALL BRAMPTON ON L6V1N2	186.1	308
ZELLERS INC	227 VODDEN STREET N BRAMPTON ON L6V1N2	186.1	308
ZELLERS STORE #146- CENTENNIAL MALL	227 VODDEN ST BRAMPTON ON L6V1N2	186.1	308
ZELLERS LIMITED 146	227 VODDEN ST; CENTENNIAL MALL BRAMPTON ON L6V1N2	186.1	308

Site	Address	Distance (m)	Map Key

PFHA - Potential PFAS Handlers from NPRI

A search of the PFHA database, dated Feb 2024 has found that there are 1 PFHA site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BRAMPTON	130 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	212.1	81

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 19 PINC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PIPELINE HIT 1 1/4"	80 VAN KIRK, UNIT 1,,BRAMPTON,ON,L7A 1B1,CA ON	246.1	107
PIPELINE HIT - 1 ¼"	80 VAN KIRK DRIVE,UNIT 2,BRAMPTON, ON,L7A 1B1,CA ON	246.1	107
PIPELINE HIT 1/2"	21 ROBERTSON DAVIES DR,,BRAMPTON, ON,L7A 1K4,CA ON	235.2	121
	70 Tessler Crescent, Brampton ON	199.4	166
PIPELINE HIT - 1"	16 ENGLISH STREET,,BRAMPTON,ON,L6X 1L4,CA ON	248.6	209
PIPELINE HIT 0.5"	44 ENGLISH STREET,,BRAMPTON,ON,L6X 1L6,CA ON	178.6	210
PIPELINE HIT - 1/2"	34 TOLTON DR,,BRAMPTON,ON,L6V 2R1, CA ON	185.9	213

Site	Address	Distance (m)	Map Key
PIPELINE HIT 0.5"	36 TOLTON DR.,,BRAMPTON,ON,L6V 2R1, CA ON	185.5	214
PIPELINE HIT - 1/2"	36 TOLTON DRIVE,,BRAMPTON,ON,L6V 2R1,CA ON	185.5	214
PIPELINE HIT - 1 ¼"	19 VODDEN COURT,,BRAMPTON,ON,L6V 2V7,CA ON	149.1	224
	40 Greene Drive, Brampton ON	245.8	226
ENBRIDGE GAS INC	21 CHERYL CRT,,BRAMPTON,ON,L6V 3C2, CA ON	89.5	228
	35 Pleasantview Avenue, Brampton ON	232.4	267
BACKYARD GETAWAYS	16 LOCUSTWOOD CRT,,BRAMPTON,ON, L6V 3C1,CA ON	112.8	280
	124 Mill Street North, Brampton ON	134.8	313
CEDAR HILLS CONTRACTING	67 NANCY MCCREDIE DR,,BRAMPTON,ON, L6X 2N4,CA ON	119.5	314
ENBRIDGE GAS INC	32 NANCY MCCREDIE DR,,BRAMPTON,ON, L6X 2N5,CA ON	155.2	321
PIPELINE HIT 1/2"	33 HARMSWORTH AVE,,BRAMPTON,ON, L6X 2N2,CA ON	245.0	329

Site	Address	Distance (m)	Map Key
ENBRIDGE GAS INC	EAST OF VALLEYSCAPE TRAIL (WEST OF LOT#36),OLD SCHOOL RD & HWY 10, CALEDON,ON,L7C 2B7,CA ON	6.2	338

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 7 PRT site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKET	225 WANLESS DR BRAMPTON ON L7A1E9	196.0	16
ROXY CONSTRUCTION CO LTD	225 WANLESS DR BRAMPTON ON L7A 1E9	196.0	16
BRAMPTON HYDRO ELECTRIC COMMISSION	175 SANDALWOOD PKWY W BRAMPTON ON L7A 1E8	119.8	56
BUTCHER ENGINEERING	105 VAN KIRK DR BRAMPTON ON L7A 1A4	76.1	97
GAS ALY LTD	370 MAIN ST N BRAMPTON ON L6V4A4	242.8	202
MANJITS ESSO	140 KENNEDY RD N BRAMPTON ON L6V 2N4	102.6	257
PETRO CAN ROCCO & RALPH SERVICE CENTRE LTD	121 KENNEDY RD N BRAMPTON ON L6V 1X7	41.0	277

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-May 2025 has found that there are 5 RSC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SABRINA HOMES (MAYFIELD ACQUISITIONS) INC.	2719 MAYFIELD ROAD ON Brampton ON	62.6	98
10254 HURONTARIO PROPERTY INC.	10254 HURONTARIO STREET ON Brampton ON	157.5	108
10254 HURONTARIO PROPERTY INC.	10254 HURONTARIO STREET ON Brampton ON	157.5	108
Brampton-Canada Associates Ltd.	75 VAN KIRK DR ON BRAMPTON ON	49.2	122
LORMEL JOINT VENTURE INC.	No Municipal Address Caledon ON	140.8	127

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Apr 30, 2025 has found that there are 11 RST site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
NORTHWOOD PARK SERVICE CENTRE INC	190 HIGHWAY 7 W BRAMPTON ON L7A1A2	147.3	146
SUNOCO GAS BAR	370 MAIN ST N BRAMPTON ON L6V4A4	242.8	202
SUNOCO INC	370 MAIN ST N BRAMPTON ON L6V 4A4	242.8	202
MANN MANJIT	140 KENNEDY RD N BRAMPTON ON L6V2N4	102.6	257
ESSO MAXIMUM	140 KENNEDY RD N BRAMPTON ON L6V 2N4	102.6	257

Site	Address	Distance (m)	Map Key
BASHAR ENTERPRISES INC	140 KENNEDY RD N BRAMPTON ON L6V2N4	102.6	257
MANN MANJIT	140 KENNEDY RD N BRAMPTON ON L6V 2N4	102.6	257
PETRO-CANADA	KENNEDY N & VODDEN BRAMPTON ON L6V 1X7	22.0	268
KENNEDY & VODDEN PETRO CANADA	121 KENNEDY RD N BRAMPTON ON L6V 1X7	41.0	277
PERFECT LUBE	121 KENNEDY RD N BRAMPTON ON L6V 1X7	41.0	277
KENNEDY & VODDEN PETRO CANADA	121 KENNEDY RD N BRAMPTON ON L6V1X7	41.0	277

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 56 SCT site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Brampton Brick Limited	225 Wanless Dr Brampton ON L7A 1E9	196.0	16
LAFARGE CANADA INC. - CONSTRUC	225 Wanless Rd Brampton ON L7A 1E9	196.0	16
Lafarge Canada Inc. - Construction Materials Group	225 Wanless Dr Brampton ON L7A 1E9	196.0	16

Site	Address	Distance (m)	Map Key
THE PEELLE COMPANY LIMITED	195 SANDALWOOD PKY W MISSISSAUGA ON L7A 1J6	98.3	61
The Peelle Company Limited	195 Sandalwood Pky W Brampton ON L7A 1J6	98.3	61
General Axle Products Inc.	20 Fisherman Dr Unit 1 Brampton ON L7A 1G2	244.3	62
INDUSTRIAL THERMO POLYMERS	153 VAN KIRK DR BRAMPTON ON L7A 1A4	125.6	68
Industrial Thermo Polymers Ltd	153 Van Kirk Dr Brampton ON L7A 1A4	125.6	68
Industrial Thermo Polymers Ltd.	153 Van Kirk Dr Brampton ON L7A 1A4	125.6	68
FAWCETT METAL FABRICATING	27 FISHERMAN DR BRAMPTON ON L7A 1E2	243.6	70
TSL Aerospace Technologies	27 Fisherman Dr Unit 12 Brampton ON L7A 1E2	243.6	70
TSL Aerospace Technologies Ltd.	27 Fisherman Dr Unit 12 Brampton ON L7A 1E2	243.6	70
Louri Products Ltd.	27 Fisherman Dr Unit 9-10 Brampton ON L7A 1E2	243.6	70
Fantasy Aluminium Installation Ltd.	27 Fisherman Dr Unit 11 Brampton ON L7A 1E2	243.6	70
Fantasy Aluminium Ltd.	27 Fisherman Dr Unit 11 Brampton ON L7A 1E2	243.6	70

Site	Address	Distance (m)	Map Key
FAWCETT METAL FABRICATING (DIV	27 FISHERMAN DR UNIT 9-10 BRAMPTON ON L7A 1E2	243.6	70
ACCU-CUT MACHINING SERVICES	27 FISHERMAN DR BRAMPTON ON L7A 1E2	243.6	70
Sota Glazing Inc	443 Railside Dr Brampton ON L7A 1E1	242.8	71
SOTA Glazing Inc.	443 Railside Dr Brampton ON L7A 1E1	242.8	71
THE SHERWIN-WILLIAMS COMPANY	130 VAN KIRK DR BRAMPTON ON L7A 1B1	212.1	81
The Sherwin-Williams Company - Eastern Division	130 Van Kirk Dr Brampton ON L7A 1B1	212.1	81
Sherwin-Williams Canada Inc. - Eastern Division	130 Van Kirk Dr Brampton ON L7A 1B1	212.1	81
Sherwin-Williams Canada Inc. - Chemical Coatings Div.	130 Van Kirk Dr Brampton ON L7A 1B1	212.1	81
Sherwin-Williams Canada Inc.	130 Van Kirk Dr Brampton ON L7A 1B1	212.1	81
Body Care Innovations	120A Van Kirk Dr Brampton ON L7A 1B1	208.5	89
Exacta Fabtool Limited	120 Van Kirk Dr Brampton ON L7A 1B1	208.5	89

Site	Address	Distance (m)	Map Key
Exacta Fabtool Limited - Div. of Exacta Precision Products Limited	120 Van Kirk Dr Brampton ON L7A 1B1	208.5	89
Kal-Trading Inc.	100 Van Kirk Dr Brampton ON L7A 1B1	219.2	93
Archway Marketing Services Inc	80 Van Kirk Dr Unit 8 Brampton ON L7A 1B1	246.1	107
N.H.D. GROUP LTD.	70 VAN KIRK DR BRAMPTON ON L7A 1B1	233.5	120
NHD GROUP LTD.	70 Van Kirk Dr Brampton ON L7A 1B1	233.5	120
Master Link Marketing Inc.	26 Robertson Davies Dr Brampton ON L7A 1J9	175.6	123
HAULTEC TRAILERS LTD	12 CANAM CRES BRAMPTON ON L7A 1A9	141.4	140
C.M.X. CORPORATION	35 VAN KIRK DR UNIT 12 BRAMPTON ON L7A 1A5	245.9	141
W.A. Whitney of Canada Ltd.	35 Van Kirk Dr Unit 14 Brampton ON L7A 1A5	245.9	141
C.M.X. Corporation - Valcom Paging	35 Van Kirk Dr Unit 12 Brampton ON L7A 1A5	245.9	141
Adhesifs Adhpro Inc.	35 Van Kirk Dr Unit 19B Brampton ON L7A 1A5	245.9	141
CMX Corporation - Valcom	35 Van Kirk Dr Unit 12 Brampton ON L7A 1A5	245.9	141

Site	Address	Distance (m)	Map Key
Classifier Milling Systems	35 Van Kirk Dr Unit 17 Brampton ON L7A 1A5	245.9	141
TORODE PRECISION COMPONENTS	190 HIGHWAY 7 W SUITE 52 BRAMPTON ON L7A 1A2	147.3	146
Torode Precision Components Inc.	190 Highway 7 W Unit 52 Brampton ON L7A 1A2	147.3	146
Gaio Fabricating Inc.	190 Bovaird Dr W Unit 22 Brampton ON L7A 1A2	147.3	146
Marklyn Group	190 Bovaird Dr W Unit 28 Brampton ON L7A 1A2	147.3	146
Torode Precision Components	190 Bovaird Dr W Unit 52 Brampton ON L7A 1A2	147.3	146
Dor-Control Craftsmen Limited	190 Bovaird Dr W Unit 17 Brampton ON L7A 1A2	147.3	146
Estate Lighting Supply Ltd.	190 Bovaird Dr W Unit 54 Brampton ON L7A 1A2	147.3	146
PAKISTANI ELECTR & PRINT MEDIA	17 BURNHOPE DR BRAMPTON ON L6X 3R9	189.0	174
Mirage Digital Printing	144 Martindale Cres Brampton ON L6X 2V2	29.4	192
REPROTECH PRINTING SERVICE	370 MAIN ST N BRAMPTON ON L6V 4A4	242.8	202

Site	Address	Distance (m)	Map Key
DIRECTORIES INTERNATIONAL LTD	370 MAIN ST N BRAMPTON ON L6V 4A4	242.8	202
MICHAEL SCOTT INC.	22 WIMBLEDON CRT BRAMPTON ON L6V 2S4	226.3	206
GolfCity Motor Caddies Inc.	44 English St Brampton ON L6X 1L6	178.6	210
Microbase 2000 Systems Inc.	332 Main St N Unit 1 Brampton ON L6V 1P8	48.5	238
Plastech Machinery Solutions	58 Nancy McCredie Dr Brampton ON L6X 2N6	166.9	272
The Blind Service Co.	13 Harmsworth Ave Brampton ON L6X 2N2	184.3	309
APC Products Ltd.	38 Lorne Ave Brampton ON L6X 1L1	155.3	316

SPL - Ontario Spills

A search of the SPL database, dated 1988-Jun 2024; Aug-Mar 2025 has found that there are 79 SPL site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Brampton Brick Limited/Brique Brampton Limitee	225 Wanless Dr Brampton ON L7A 1E9	196.0	16
Brampton Brick Limited	225 Wanless Dr Brampton ON L7A 1E9	196.0	16
Canada Cartage Systems Limited	225 Wanless Dr Brampton ON	196.0	16

Site	Address	Distance (m)	Map Key
Canada Cartage Limited	225 Wanless Drive Brampton ON	196.0	16
Brampton Brick Limited	225 Wanless Dr Brampton ON L7A 1E9	196.0	16
The Corporation of the City of Brampton	Steeles Ave and Kenndy Rd; 120 Sandalwood Pky W Brampton; Brampton ON L7A 1L2	246.1	22
	120 Sandalwood Parkway West, Brampton ON BRAMPTON ON	246.1	22
	34 Burnt Elm Dr, Brampton BRAMPTON ON	198.0	43
	156 Twin Pine Cres. Brampton ON	11.6	49
BRAMPTON HYDRO-ELECTRIC COMMIS	175 SANDALWOOD PKWY WEST MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L7A 1E8	119.8	56
BRAMPTON HYDRO-ELECTRIC COMMIS	175 SANDALWOOD PARKWAY WEST MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L7A 1E8	119.8	56
BRAMPTON HYDRO-ELECTRIC COMMIS	175 SANDALWOOD PARKWAY BRAMPTON CITY ON	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pky W Brampton ON L7A 1E8	119.8	56
Hydro One Brampton Networks Inc.	175 Sandalwood Pky W Brampton ON L7A 1E8	119.8	56

Site	Address	Distance (m)	Map Key
	22 Coppermill Drive Brampton ON L7A 1N4	249.3	58
CONSTRUCTION COMPANY	200 CRESTHAVEN ROAD MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L7A 1J5	198.5	63
ALECTRA UTILITIES CORPORATION	440 Railside Drive Brampton ON	182.2	64
	153 Vankirk Drive Brampton ON	125.6	68
Armacell Canada Inc.	153 Van Kirk Dr Brampton ON L7A 1A4	125.6	68
Armacell Canada Inc.	153 Van Kirk Dr. Brampton ON	125.6	68
Day & Ross Inc.	170 VANKIRK DR.<UNOFFICIAL> Brampton ON L7A 1K9	241.0	75
Day & Ross Inc.	170 Van Kirk Drive Brampton ON L7A 1K9	241.0	75
Day & Ross Transport<UNOFFICIAL>	170 Van Kirk Drive Brampton ON L7A 1K9	241.0	75
Day and Ross Inc.	170 Van Kirk Dr Brampton ON	241.0	75
	170 Van Kirk Drive, Brampton, ON BRAMPTON ON	241.0	75
Aztec Hydraulics Inc.	Regan Road & Vankirk Drive, Brampton ON	166.7	76

Site	Address	Distance (m)	Map Key
ALECTRA UTILITIES CORPORATION	82 Banington Crescent, Brampton ON	174.0	77
GIVE AND GO PREPARED FOODS CORP.	BRAMPTON ON	248.4	78
Ontario Clean Water Agency	2819 Mayfield Rd Brampton ON	197.7	95
The Butcher Engineering Enterprises Limited	105 Van Kirk Dr Brampton ON L7A 1A4	76.1	97
	105 Van Kirk Dr. Brampton ON	76.1	97
SONCO STEEL TUBE LTD.	SONCO, 95 VAN KIRK DRIVE, BRAMPTON, L6X 2M3 95 VAN KIRK DR. (HEAD OFFICE) BRAMPTON ON L6X 2M3 BRAMPTON CITY ON L7A 1A4	62.1	110
SONCO STEEL TUBE LTD.	VAN KIRK DRIVE BRAMPTON PLANT 95 VANKIRK DRIVE BRAMPTON CITY ON	62.1	110
SONCO STEEL TUBE LTD.	BRAMPTON PLANT 95 VANKIRK DRIVE BRAMPTON CITY ON	62.1	110
	behind 95 Van Kirk Drive, Brampton BRAMPTON ON	62.1	110
	26 Robertson Davies Drive Brampton, ON BRAMPTON ON	175.6	123
Petro-Canada	45 Vankirk Dr. Brampton ON L7A 1A4	172.8	131

Site	Address	Distance (m)	Map Key
Roto Mill Services Ltd.	12 Canam Crescent, Brampton Brampton ON L7A 1A9	141.4	140
PETRO-CANADA	35 VANKIRK DR SERVICE STATION BRAMPTON ON L7A 1A5	245.9	141
Attrell Toyota	110 Canam Crescent (Bovaird and VanKirk) Brampton ON	49.6	147
Accuworx	110 Canam Crescent, Brampton, ON L7A 1A9 BRAMPTON ON	49.6	147
ENBRIDGE INC	100 Manett Crescent, Brampton BRAMPTON ON	95.0	159
UNKNOWN	STORM SEWER AT 194 ECCLESTONE DR. BRAMPTON CITY ON L6X 3P5	103.1	167
ALECTRA UTILITIES CORPORATION	107 Saddletree trail ON	190.2	183
The Regional Municipality of Peel	69 Moore Street Brampton ON	43.5	194
	45 Moore St, Brampton BRAMPTON ON	37.0	199
ALECTRA UTILITIES CORPORATION	BRAMPTON ON	221.4	205
BRAMPTON TRANSIT MOTOR VEHICLE	ETOBICOKE CREEK HWY 10 AND ENGLISH ST OPERATING FLUIDS BRAMPTON CITY ON	247.8	207
Peel District School Board	250 Centre St N Brampton ON L6V 2R4	229.9	208

Site	Address	Distance (m)	Map Key
Enbridge Gas Distribution	16 English Street Brampton ON	248.6	209
Enbridge Gas Distribution Inc.	34 Tolton Dr Brampton ON	185.9	213
Enbridge Gas Distribution Inc.	36 Tolton Drive Brampton ON	185.5	214
ENBRIDGE CONSUMERS GAS	54 Kingswood Drive, Brampton ON	224.4	220
Enbridge Gas Distribution Inc.	19 Vodden Crt Brampton ON	149.1	224
Enbridge Gas Distribution Inc.	40 Greene Drive Brampton ON L6V 2R7	245.8	226
ENBRIDGE CONSUMERS GAS	21 Cheryl Court, Brampton BRAMPTON ON	89.5	228
Vari-Therm Limited	345 Main St N Brampton ON	89.5	231
	345 Main Street N BRAMPTON ON	89.5	231
	36 Newby Court BRAMPTON ON	47.9	234
The Regional Municipality of Peel	220 Centre St. North Brampton ON	48.1	236

Site	Address	Distance (m)	Map Key
The Regional Municipality of Peel	Vodden Street East and Centre St. North Brampton ON	2.6	243
CONSUMERS' GAS CO. LTD., THE	VODDEN & POST ROAD NATURAL GAS PIPELINE BRAMPTON CITY ON	2.6	247
Terra HX Inc.	39 Greene Drive, Brampton BRAMPTON ON	127.4	253
PROVMAR FUELS INC.	140 KENNEDY ROAD TANK TRUCK (CARGO) BRAMPTON CITY ON	102.6	257
SERVICE MASTER	115 NANCY MCCREDIE DRIVE BRAMPTON ON L6X 2N4	149.8	259
Alectra Utilities Corporation	47 Vodden St Brampton ON	33.8	263
BRAMPTON HYDRO-ELECTRIC COMMIS	30 CUMBERLAND BRAMPTON CITY ON L6V 1W6	77.8	273
	16 Locustwood Crt Brampton ON	112.8	280
	BRAMPTON ON	113.5	289
The Corporation of the City of Brampton	225 Vodden St E Brampton ON L6V 4M1	120.6	302
	178 Beech St. Brampton ON	169.2	307
	61 Mara Cres, Brampton BRAMPTON ON	177.3	312

Site	Address	Distance (m)	Map Key
Enbridge Gas Distribution Inc.	67 Nancy McCredie Drive Brampton ON	119.5	314
Enbridge Energy Distribution Inc.	32 Nancy McCreedie Drive Brampton ON	155.2	321
The Regional Municipality of Peel	135 Sailsbury Circle Brampton ON	248.7	328
PRIVATE RESIDENCE	INFRONT OF 110 MILL ST. (N.O.S.) BRAMPTON CITY ON	229.0	330
Makkar Transport<UNOFFICIAL>	Hwy 10 @ Old School Road Caledon ON	6.2	338
	hwy 10 southbound and Old School Road intersection in Brampton CALEDON ON	6.2	338
	Hwy 10 and Old School Road Caledon CALEDON ON	6.2	338

WDS - Waste Disposal Sites - MOE CA Inventory

A search of the WDS database, dated Oct 2011 - May 31, 2025 has found that there are 2 WDS site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Safety-Kleen (On-Site) Inc.	175 Sandalwood Parkway West Brampton ON N1G 4P5	119.8	56
HUTCHINS & SON AUTOMOTIVE LIMITED	20 FISHERMAN DR BRAMPTON ON L7A 1G2	244.3	62

WWIS - Water Well Information System

A search of the WWIS database, dated Dec 31 2023 has found that there are 165 WWIS site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	225 WANLESS DR Brampton ON ***Well ID:*** 7359021	243.4	1
	225 Wanless Dr Brampton ON ***Well ID:*** 7354806	245.9	2
	225 WANLESS DR lot 15 con 1 Brampton ON ***Well ID:*** 7390047	231.3	3
	225 WANLESS DR Brampton ON ***Well ID:*** 7390050	238.9	4
	225 WANLESS DR Brampton ON ***Well ID:*** 7359020	229.4	5
	225 WANLESS DR Brampton ON ***Well ID:*** 7390048	224.6	6
	225 WANLESS DR Brampton ON ***Well ID:*** 7390078	224.8	7
	225 Wanless Drive lot 15 con 1 Brampton ON ***Well ID:*** 7405164	214.1	8
	225 Wanless Drive lot 15 con 1 Brampton ON ***Well ID:*** 7405167	216.5	9
	225 Wanless Dr Brampton ON ***Well ID:*** 7354807	220.5	10
	225 Wanless Drive lot 15 con 1 Brampton ON	202.3	11

Site	Address	Distance (m)	Map Key
	Well ID: 7405166		
	lot 15 con 1 ON ***Well ID:*** 7407100	200.1	12
	120 SANDLEWOOD Brampton ON ***Well ID:*** 7122450	207.6	13
	120 SANDLEWOOD Brampton ON ***Well ID:*** 7122451	194.5	14
	120 SANDALWOOD PARKWAY Brampton ON ***Well ID:*** 7114845	198.7	15
	120 SANDALWOOD PARKWAY Brampton ON ***Well ID:*** 7123806	116.9	17
	225 WANLESS DR Brampton ON ***Well ID:*** 7390044	133.9	18
	225 WANLESS DR Brampton ON ***Well ID:*** 7359022	129.7	19
	120 SANDLEWOOD PARKWAY BRAMPTON ON ***Well ID:*** 7117441	86.3	20
	120 SANDLEWOOD Brampton ON ***Well ID:*** 7122452	92.6	21
	120 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7114851	246.1	22
	130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7246995	154.9	23

Site	Address	Distance (m)	Map Key
	130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7247001	225.3	24
	ON ***Well ID:*** 7167767	66.6	26
	ON ***Well ID:*** 7170238	61.7	27
	130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7246996	52.5	28
	130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7246999	119.2	32
	lot 16 con 1 ON ***Well ID:*** 4908671	24.1	33
	130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7247000	193.0	35
	130 SANDALWOOD PKWY W BRAMPTON BUS DEPOT Brampton ON ***Well ID:*** 7277183	168.3	37
	130 SANDALWOOD PKWY WEST Brampton ON ***Well ID:*** 7246997	30.7	38
	lot 16 con 1 ON ***Well ID:*** 4908672	76.1	39
	lot 16 con 1 ON ***Well ID:*** 4901595	57.3	47
	175 SANDALWOOD PARKWAY W lot 13 con 1 BRAMPTON ON	150.7	51

Site	Address	Distance (m)	Map Key
	Well ID: 7219199		
	lot 13 con 1 ON ***Well ID:*** 7335999	154.8	54
	ON ***Well ID:*** 7217049	215.1	57
	10534 HURONTARIO ST Mississauga ON ***Well ID:*** 7342881	248.5	59
	lot 13 con 1 ON ***Well ID:*** 4908749	14.9	66
	S/E CORNER OF MAYFIELD & MCLAUCHLIN lot 17 con 1 ON ***Well ID:*** 7043898	141.5	80
	SOUTH END RAIL SIDE DRIVE Brampton ON ***Well ID:*** 7205572	168.0	82
	80 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7277923	208.3	96
	95 VAN KIRK DR Brampton ON ***Well ID:*** 7172053	163.7	99
	95 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7172054	163.7	99
	95 VAN KIRK DR Brampton ON ***Well ID:*** 7172055	163.7	99
	95 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7172057	163.7	99

Site	Address	Distance (m)	Map Key
	95 VAN KIRK DR Brampton ON ***Well ID:*** 7172058	163.7	99
	95 VAN KIRK DR Brampton ON ***Well ID:*** 7172060	163.7	99
	95 VAN KIRK DRIVE Brampton ON ***Well ID:*** 7172056	163.7	99
	95 VAN KIRK DR Brampton ON ***Well ID:*** 7172051	163.7	99
	95 VAN KIRK DR Brampton ON ***Well ID:*** 7172059	163.7	99
	95 VANKIRK DR Brampton ON ***Well ID:*** 7172052	163.7	99
	ON ***Well ID:*** 7283936	130.1	101
	ON ***Well ID:*** 7294565	147.7	102
	ON ***Well ID:*** 7306218	28.0	103
	2719 MAYFIELD ROAD lot 17 con 1 Brampton ON ***Well ID:*** 7248959	85.1	105
	2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378696	9.2	106
	80 VAN KIRK DRIVE Brampton ON	191.2	111

Site	Address	Distance (m)	Map Key
	Well ID: 7277924		
	2650 mayfield rd con 1 Caledon ON ***Well ID:*** 7353563	30.0	112
	2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378695	165.5	113
	2650 MAYFIELD RD BRAMPTON ON ***Well ID:*** 7262154	174.7	114
	Robertson Davies Drive & Mayfield Road lot 18 con 1 ON ***Well ID:*** 7408615	36.6	115
	2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378685	26.0	116
	2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378694	154.4	117
	70 VAN KIRK DR Brampton ON ***Well ID:*** 7347856	207.0	119
	ON ***Well ID:*** 7164666	91.6	124
	ON ***Well ID:*** 7169172	91.6	124
	2650 Mayfield Road lot 18 con 1 Brampton ON ***Well ID:*** 7378698	17.7	126
	6152 PENETANGUISHENE RD Springwater ON ***Well ID:*** 7220338	86.2	130

Site	Address	Distance (m)	Map Key
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447535	59.7	134
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447522	59.7	134
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447520	59.7	134
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447534	59.7	134
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447538	59.7	134
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447544	59.7	134
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447540	59.7	134
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447539	59.7	134
	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447523	59.7	134
	ON ***Well ID:*** 7396621	212.2	137
	lot 11 con 1 ON ***Well ID:*** 4901582	160.6	138
	2650 Mayfield Road lot 18 con 1 Brampton ON	248.4	139

Site	Address	Distance (m)	Map Key
	Well ID: 7378693		
	12 CANAM CRES lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447531	141.4	140
	12 CANAM CRES lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447521	141.4	140
	12 CANAM CRES lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447532	141.4	140
	12 CANAM CRES lot 11 con 1 BRAMPTON ON ***Well ID:*** 7447524	141.4	140
	lot 11 con 1 ON ***Well ID:*** 4901581	180.2	145
	190 bovaird dr w. brampton lot 11 con 1 Brampton ON ***Well ID:*** 7329307	104.3	149
	223 BOVAIRD DR W Brampton ON ***Well ID:*** 7284163	129.9	150
	HUTCHINSON FARM LN lot 19 con 1 CALEDON ON ***Well ID:*** 7321774	11.6	151
	ON ***Well ID:*** 7179434	126.5	154
	MANETT CRESENT Brampton ON ***Well ID:*** 7191506	130.0	155
	MANNETT CRESENT Brampton ON ***Well ID:*** 7191505	78.3	156

Site	Address	Distance (m)	Map Key
	PART OF LOT 20, CONCESSION 1 WHS CALEDON ON ***Well ID:*** 7265666	113.7	157
	MANETT CRESENT Brampton ON ***Well ID:*** 7191504	27.5	158
	MANETT CRESCENT Brampton ON ***Well ID:*** 7191501	122.4	160
	MANETT CRESCENT Brampton ON ***Well ID:*** 7191502	67.9	161
	MANETT CRESCENT Brampton ON ***Well ID:*** 7191503	28.2	163
	lot 19 con 1 ON ***Well ID:*** 4904556	165.9	172
	ON ***Well ID:*** 7308412	158.8	179
	lot 20 con 1 ON ***Well ID:*** 4904291	181.0	180
	lot 21 con 1 ON ***Well ID:*** 4901624	194.2	181
	Moore Street & Burton Road lot 9 con 1 Brampton ON ***Well ID:*** 7378803	66.4	182
	ON ***Well ID:*** 7312145	27.2	185
	WILLIAMS PARKWAY BRAMPTON ON	41.3	186

Site	Address	Distance (m)	Map Key
	Well ID: 7312128		
	lot 21 con 2 ON ***Well ID:*** 4901721	184.2	187
	lot 21 con 1 ON ***Well ID:*** 4901621	195.4	188
	Moore Street & Burton Road lot 8 con 1 Brampton ON ***Well ID:*** 7380773	73.7	189
	Moore Street & Burton Road lot 8 con 1 Brampton ON ***Well ID:*** 7378802	183.2	191
	OLD SCHOOL ROAD lot 21 con 1 BRAMPTON ON ***Well ID:*** 7300314	5.5	193
	Moore Street & Burton Road lot 8 con 1 Brampton ON ***Well ID:*** 7378801	150.6	195
	lot 21 con 2 ON ***Well ID:*** 4901723	212.0	196
	lot 21 con 1 ON ***Well ID:*** 4901623	204.7	197
	Moore Street & Burton Road lot 8 con 1 Brampton ON ***Well ID:*** 7380774	68.7	198
	lot 21 con 1 ON ***Well ID:*** 4901622	200.8	200
	lot 21 con 2 ON ***Well ID:*** 4901722	209.2	201


Site	Address	Distance (m)	Map Key
	ON ***Well ID:*** 7266922	208.9	215
	Moore Street & English Street lot 8 con 1 Brampton ON ***Well ID:*** 7380753	13.3	218
	lot 22 con 1 ON ***Well ID:*** 4901628	206.8	219
	36 VODDEN ST E Brampton ON ***Well ID:*** 7217101	44.8	237
	ON ***Well ID:*** 4901072	36.6	239
	36 VODDEN ST E Brampton ON ***Well ID:*** 7217099	30.6	240
	ON ***Well ID:*** 4900510	9.2	245
	lot 22 con 1 ON ***Well ID:*** 4908096	187.5	249
	320 MAIN STREET W. BRAMPTON ON ***Well ID:*** 7147718	19.0	252
	KENNEDY RD N BRAMPTON ON ***Well ID:*** 7312109	49.5	258
	VODDEN ST E & KENNEDY RD N BRAMPTON ON ***Well ID:*** 7312124	20.5	260
	ON	42.7	261

Site	Address	Distance (m)	Map Key
	Well ID: 4903777		
	Kennedy Rd N Brampton ON ***Well ID:*** 7359808	50.1	262
	121 KENNEDY ROAD NORTH Brampton ON ***Well ID:*** 7298062	16.7	269
	ON ***Well ID:*** 7233319	16.0	270
	227 VODDEN ST EAST Brampton ON ***Well ID:*** 7219364	59.3	271
	227 VODDOEN STREET EAST Brampton ON ***Well ID:*** 7219365	53.2	276
	121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON ***Well ID:*** 7401799	43.6	279
	227 VODDEN STREET EAST Brampton ON ***Well ID:*** 7219358	57.2	282
	121 KENNEDY RD. N BRAMPTON ON ***Well ID:*** 7308835	46.3	283
	121 KENNEDY RD. N. BRAMPTON ON ***Well ID:*** 7308837	53.3	285
	121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON ***Well ID:*** 7401794	61.5	286
	121 KENNEDY ROAD NORTH Brampton ON ***Well ID:*** 7298064	60.2	288

Site	Address	Distance (m)	Map Key
	121 KENNEDY RD. N BRAMPTON ON ***Well ID:*** 7308836	59.1	290
	99 KENNEDY STREET N Brampton ON ***Well ID:*** 7369738	68.5	291
	99 KENNEDY STREET N Brampton ON ***Well ID:*** 7369739	66.7	292
	121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON ***Well ID:*** 7401796	69.8	293
	121 KENNEDY ROAD NORTH Brampton ON ***Well ID:*** 7298063	69.0	295
	99 KENNEDY STREET N Brampton ON ***Well ID:*** 7369740	70.7	296
	121 KENNEDY ROAD NORTH Brampton ON ***Well ID:*** 7298061	77.1	299
	OLD SCHOOL ROAD BRAMPTON ON ***Well ID:*** 7300315	153.1	300
	OLD SCHOOL RD BRAMPTON ON ***Well ID:*** 7300300	141.7	311
	lot 22 con 1 ON ***Well ID:*** 4904066	218.8	320
	Old School Road & Hurontario Street lot 22 con 1 Caledon ON ***Well ID:*** 7380784	193.9	323
	lot 22 con 1 ON	41.6	332

Site	Address	Distance (m)	Map Key
	Well ID: 4907265		
	2939 OLD SCHOOL RD. lot 22 con 1 BRAMPTON ON ***Well ID:*** 7199058	44.5	333
	ON ***Well ID:*** 7355069	0.3	334
	2939 OLD SCHOOL RD. lot 22 con 1 BRAMPTON ON ***Well ID:*** 7199059	32.8	335
	lot 22 con 1 ON ***Well ID:*** 4901626	13.6	336
	lot 22 con 1 ON ***Well ID:*** 4901629	38.8	337
	lot 23 con 1 ON ***Well ID:*** 4902901	43.0	339
	lot 22 con 1 ON ***Well ID:*** 4901627	12.1	340
	2676 OLD SCHOOL RD. lot 23 con 1 BRAMPTON ON ***Well ID:*** 7145558	63.4	341
	lot 23 con 1 ON ***Well ID:*** 4901630	66.7	342
	lot 23 con 1 ON ***Well ID:*** 4904378	81.5	343
	lot 23 con 1 ON ***Well ID:*** 4901631	76.7	344

Site	Address	Distance (m)	Map Key
	lot 23 con 1 ON ***Well ID:*** 4902900	132.0	345
	lot 23 con 1 ON ***Well ID:*** 4906471	123.7	346
	n/a Old School Rd X Hurontario Street lot 23 con 1 Caledon ON ***Well ID:*** 7406244	244.0	347
	n/a Old School Rd X Hurontario Street lot 23 con 1 Caledon ON ***Well ID:*** 7406221	209.9	348
	lot 23 con 1 ON ***Well ID:*** 4902899	165.3	349



Map: 0.25 Kilometer Radius

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 1

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 2

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 3


Order Number: 25071000582

Address: Kennedy STS, Caledon, ON

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 4

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 5


Order Number: 25071000582

Address: Kennedy STS, Caledon, ON

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 6

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 7

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 8

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 9


Order Number: 25071000582

Address: Kennedy STS, Caledon, ON

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 10

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 11

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 12

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 13

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 14

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 15

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 16

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 17

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 18

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 19

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 20

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 21

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 22

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 23

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 24

Order Number: 25071000582

Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation


- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail

- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital

- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 25

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 26

Order Number: 25071000582

Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation


- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail

- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital

- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 27

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 28

Order Number: 25071000582


Address: Kennedy STS, Caledon, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Aerial


Year: 2023

Order Number: 25071000582

Address: Kennedy STS, Caledon, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Address: Kennedy STS, ON

Source: ESRI World Topographic Map

Order Number: 25071000582

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
334	1 of 1	WNW/0.3	260.4 / 18.41	ON	WWIS

Well ID:	7355069	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	07/19/2018
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C39205	**Contractor:**	6946
Tag:	A233614	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1008207898	**Tag No:**	A233614
Depth M:		**Contractor:**	6946
Year Completed:		**Latitude:**	43.7483962644677
Well Completed Dt:		**Longitude:**	-79.8571447390051
Audit No:	C39205	**Y:**	43.74839626230118
Path:		**X:**	-79.8571445889561

Bore Hole Information

Bore Hole ID:	1008207898	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592014.00
Code OB Desc:		**North83:**	4844563.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:		**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	WSW/243.4	244.8 / 2.86	225 WANLESS DR	WWIS

Brampton ON

Well ID:	7359021	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	05/20/2020
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z332492	***Contractor:***	7241
Tag:	A286360	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	

Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7359021.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/13/2020
Year Completed:	2020
Depth (m):	
Latitude:	43.7193259637493
Longitude:	-79.8132789244643
X:	-79.81327877425844
Y:	43.71932596193044
Path:	735\7359021.pdf

Bore Hole Information

Bore Hole ID:	1008281664	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595592.00
Code OB Desc:		***North83:***	4841384.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/13/2020	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1009636070
Layer:	4
Color:	2
General Color:	GREY
Material 1:	06

Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	10.0
Formation End Depth:	18.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009636069
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	3.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009636068
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.5
Formation End Depth:	3.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009636067
Layer:	1
Color:	2
General Color:	GREY
Material 1:	27
Material 1 Desc:	OTHER
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009638587
Layer: 2
Plug From: 0.5
Plug To: 7.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009638588
Layer: 3
Plug From: 7.0
Plug To: 18.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009638586
Layer: 1
Plug From: 0.0
Plug To: 0.5
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009640874
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1009633075
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009641770
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 8.0
Casing Diameter: 2.0
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1009642659
Layer: 1
Slot: 10
Screen Top Depth: 8.0
Screen End Depth: 18.0
Screen Material: 5
Screen Depth UOM: ft

Screen Diameter UOM:	Inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009643588
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009639987
Diameter:	6.0
Depth From:	0.0
Depth To:	18.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

---

2 | **1 of 1** | **WSW/245.9** | **245.9 / 3.92** | **225 Wanless Dr Brampton ON** | **WWIS**

Well ID:	7354806	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	03/02/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z333596	**Contractor:**	7644
Tag:	A282846	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7354806.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/10/2020
Year Completed:	2020

Depth (m):	6.096
Latitude:	43.7198096419738
Longitude:	-79.8139025139675
X:	-79.81390236382562
Y:	43.71980964009071
Path:	735\7354806.pdf

Bore Hole Information

Bore Hole ID:	1008190590	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595541.00
Code OB Desc:		**North83:**	4841437.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/10/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008360878
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008361590
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008361591
Layer:	2
Plug From:	1.0
Plug To:	8.0
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1008361592
Layer:	3
Plug From:	8.0
Plug To:	17.0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1008360281
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008362837
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008363131
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	17.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.375

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008363575
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008362247

Diameter:	8.0
Depth From:	0.0
Depth To:	17.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

3 **1 of 1** **SW/231.3** **244.9 / 2.92** **225 WANLESS DR lot 15 con 1 Brampton ON** **WWIS**

Well ID:	7390047	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	06/21/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z354780	**Contractor:**	7644
Tag:	A286360	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	015
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7390047.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/07/2021
Year Completed:	2021
Depth (m):	
Latitude:	43.7192185839018
Longitude:	-79.8133431157808
X:	-79.8133429660612
Y:	43.7192185822631
Path:	739\7390047.pdf

Bore Hole Information

Bore Hole ID:	1008687156	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595587.00
Code OB Desc:		**North83:**	4841372.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/07/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Pipe Information

Pipe ID:	1009764867
Casing No:	0
Comment:	
Alt Name:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009855960
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

4	***1 of 1***	***WSW/238.9***	***245.9 / 3.92***	***225 WANLESS DR Brampton ON***	***WWIS***

Well ID:	7390050	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	06/21/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z354775	***Contractor:***	7644
Tag:	A282783	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7390050.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/07/2021
Year Completed:	2021
Depth (m):	
Latitude:	43.7197652759221
Longitude:	-79.8139654615335
X:	-79.81396531145646
Y:	43.71976527442496
Path:	739\7390050.pdf

Bore Hole Information

Bore Hole ID:	1008687165	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595536.00
Code OB Desc:		***North83:***	4841432.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	05/07/2021	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Pipe Information

Pipe ID:	1009764870
Casing No:	0
Comment:	
Alt Name:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009855963
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

---

5 ***1 of 1*** ***WSW/229.4*** ***245.9 / 3.92*** ***225 WANLESS DR Brampton ON*** ***WWIS***

Well ID:	7359020	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Monitoring and Test Hole	***Date Received:***	05/20/2020
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z332493	***Contractor:***	7241
Tag:	A286359	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	

Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1008281661
Depth M:
Year Completed: 2020
Well Completed Dt: 01/13/2020
Audit No: Z332493
Path:
Tag No: A286359
Contractor: 7241
Latitude: 43.7195934646708
Longitude: -79.8138943646418
Y: 43.719593463052306
X: -79.81389421522964

Bore Hole Information

Bore Hole ID: 1008281661
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/13/2020
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 595542.00
North83: 4841413.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1009636064
Layer: 2
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.5
Formation End Depth: 3.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009636065
Layer: 3
Color: 6
General Color: BROWN
Material 1: 06

Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	3.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009636063
Layer:	1
Color:	2
General Color:	GREY
Material 1:	27
Material 1 Desc:	OTHER
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009636066
Layer:	4
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	10.0
Formation End Depth:	18.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009638583
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009638584
Layer:	2
Plug From:	0.5
Plug To:	7.0
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1009638585
Layer:	3
Plug From:	7.0
Plug To:	18.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1009640873
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1009633074
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1009641769
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	8.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1009642658
Layer:	1
Slot:	10
Screen Top Depth:	8.0
Screen End Depth:	18.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	Inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009643587
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	

Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009639986
Diameter:	6.0
Depth From:	0.0
Depth To:	18.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

---

6 **1 of 1** **WSW/224.6** **245.8 / 3.89** **225 WANLESS DR Brampton ON** **WWIS**

Well ID:	7390048	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	06/21/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z354778	**Contractor:**	7644
Tag:	A286359	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7390048.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/07/2021
Year Completed:	2021
Depth (m):	
Latitude:	43.7196400204451
Longitude:	-79.814042419173
X:	-79.81404226921526
Y:	43.71964001809068
Path:	739\7390048.pdf

Bore Hole Information

Bore Hole ID:	1008687159	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595530.00
Code OB Desc:		**North83:**	4841418.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/07/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Pipe Information

Pipe ID: 1009764868
Casing No: 0
Comment:
Alt Name:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009855961
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

---

7 ***1 of 1*** ***WSW/224.8*** ***245.8 / 3.84*** ***225 WANLESS DR Brampton ON*** ***WWIS***

Well ID: 7390078
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z360423
Tag: A171489
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 06/21/2021
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7644
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7390078.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/07/2021
Year Completed:	2021
Depth (m):	
Latitude:	43.7196948053352
Longitude:	-79.8141158250161
X:	-79.8141156750204
Y:	43.71969480349093
Path:	739\7390078.pdf

Bore Hole Information

Bore Hole ID:	1008687842	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595524.00
Code OB Desc:		**North83:**	4841424.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/07/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Pipe Information

Pipe ID:	1009764898
Casing No:	0
Comment:	
Alt Name:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009855991
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

8	***1 of 1***	***WSW/214.1***	***245.9 / 4.01***	***225 Wanless Drive lot 15 con 1 Brampton ON***	***WWIS***

Well ID:	7405164	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	

Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12/03/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	2FBCRV3R	**Contractor:**	7732
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	015
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1008875226	**Tag No:**	_NO_TAG
Depth M:		**Contractor:**	7732
Year Completed:	2021	**Latitude:**	43.7193131138331
Well Completed Dt:	11/15/2021	**Longitude:**	-79.8137757522885
Audit No:	2FBCRV3R	**Y:**	43.71931311213791
Path:		**X:**	-79.81377560174238

Bore Hole Information

Bore Hole ID:	1008875226	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595552.00
Code OB Desc:		**North83:**	4841382.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/15/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008875362
Layer:	1
Color:	
General Color:	
Material 1:	
Material 1 Desc:	
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008875464
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008875484
Layer:	1
Plug From:	0.0
Plug To:	4.599999904632568
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1008875286
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008875409
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.049999952316284
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008875429
Layer:	1
Slot:	
Screen Top Depth:	3.049999952316284
Screen End Depth:	4.599999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008875287
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m

Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008875356
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.5
Water Found Depth UOM: m

---

9 | **1 of 1** | **WSW/216.5** | **245.9 / 3.92** | **225 Wanless Drive lot 15 con 1 Brampton ON** | **WWIS**

Well ID: 7405167
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: IXIICZR6
Tag: _NO_TAG
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 12/03/2021
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7732
Form Version: 9
Owner:
County: PEEL
Lot: 015
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1008875235
Depth M:
Year Completed: 2021
Well Completed Dt: 11/15/2021
Audit No: IXIICZR6
Path:

Tag No: _NO_TAG
Contractor: 7732
Latitude: 43.7194588207946
Longitude: -79.8139342642653
Y: 43.71945881897622
X: -79.81393411390233

Bore Hole Information

Bore Hole ID: 1008875235
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/15/2021
Remarks:
Location Method Desc: on Water Well Record

Elevation:
Elevrc:
Zone: 17
East83: 595539.00
North83: 4841398.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008875365
Layer: 1
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008875467
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008875487
Layer: 1
Plug From: 0.0
Plug To: 6.099999904632568
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008875292
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008875412
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.049999952316284
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1008875432
Layer:	1
Slot:	
Screen Top Depth:	3.049999952316284
Screen End Depth:	6.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008875293
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008875359
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	1.5
Water Found Depth UOM:	m

---

10 | ***1 of 1*** | ***WSW/220.5*** | ***245.8 / 3.84*** | ***225 Wanless Dr Brampton ON*** | ***WWIS***

Well ID:	7354807	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	03/02/2020
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z333597	***Contractor:***	7644
Tag:	A282785	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		

Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7354807.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/10/2020
Year Completed: 2020
Depth (m): 6.096
Latitude: 43.7196499240187
Longitude: -79.8141291247704
X: -79.814128974578
Y: 43.71964992224175
Path: 735\7354807.pdf

Bore Hole Information

Bore Hole ID: 1008190593
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/10/2020
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595523.00
North83: 4841419.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008360879
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 06
Material 2 Desc: SILT
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008361593
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008361594
Layer: 2
Plug From: 1.0
Plug To: 8.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008361595
Layer: 3
Plug From: 8.0
Plug To: 17.0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1008360282
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008362838
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008363132
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 17.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.375

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008363576
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:

Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008362248
Diameter:	8.0
Depth From:	0.0
Depth To:	17.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

11 | ***1 of 1*** | ***WSW/202.3*** | ***246.5 / 4.57*** | ***225 Wanless Drive lot 15 con 1 Brampton ON*** | ***WWIS***

Well ID:	7405166	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	12/03/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	VIGO43IT	**Contractor:**	7732
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	015
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1008875232	**Tag No:**	_NO_TAG
Depth M:		**Contractor:**	7732
Year Completed:	2021	**Latitude:**	43.719644141288
Well Completed Dt:	11/15/2021	**Longitude:**	-79.8144395994094
Audit No:	VIGO43IT	**Y:**	43.71964413948129
Path:		**X:**	-79.81443944930987

Bore Hole Information

Bore Hole ID:	1008875232	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595498.00
Code OB Desc:		**North83:**	4841418.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/15/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008875364
Layer: 1
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008875466
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008875486
Layer: 1
Plug From: 0.0
Plug To: 6.099999904632568
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008875290
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008875411
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.049999952316284
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008875431

Layer:	1
Slot:	
Screen Top Depth:	3.049999952316284
Screen End Depth:	6.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008875291
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008875358
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	1.5
Water Found Depth UOM:	m

---

12 | ***1 of 1*** | ***WSW/200.1*** | ***246.5 / 4.57*** | ***lot 15 con 1 ON*** | ***WWIS***

Well ID:	7407100	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	12/29/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C47179	**Contractor:**	7247
Tag:	A306834	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	015
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Additional Detail(s) (Map)

Bore Hole ID:	1008902380	***Tag No:***	A306834
Depth M:		***Contractor:***	7247
Year Completed:	2021	***Latitude:***	43.7195897428846
Well Completed Dt:	07/16/2021	***Longitude:***	-79.8144034289441
Audit No:	C47179	***Y:***	43.71958974098349
Path:		***X:***	-79.81440327866133

Bore Hole Information

Bore Hole ID:	1008902380	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595501.00
Code OB Desc:		***North83:***	4841412.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	07/16/2021	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

13 ***1 of 1*** ***SSW/207.6*** ***242.9 / 0.92*** ***120 SANDLEWOOD Brampton ON*** ***WWIS***

Well ID:	7122450	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Other	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	04/29/2009
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z096609	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7122450.pdf

Additional Detail(s) (Map)

Well Completed Date:	03/24/2009
Year Completed:	2009
Depth (m):	
Latitude:	43.7176609258258
Longitude:	-79.811611070694
X:	-79.81161092056112
Y:	43.717660924254155

Path: 712\7122450.pdf

Bore Hole Information

Bore Hole ID:	1002420365	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595729.00
Code OB Desc:		**North83:**	4841201.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03/24/2009	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002532914
Layer: 1
Plug From: 0.0
Plug To: 2.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002532919
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1002532912
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002532916
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.0
Casing Diameter: 2.609999895095825
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002532917
Layer: 1

Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 3.3399999141693115

Water Details

Water ID: 1002532915
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1002532913
Diameter: 10.899999618530273
Depth From: 0.0
Depth To: 2.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

14 | **1 of 1** | **SSW/194.5** | **242.9 / 0.92** | **120 SANDLEWOOD Brampton ON** | **WWIS**

Well ID: 7122451
Construction Date:
Use 1st: Other
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z096611
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/29/2009
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7122451.pdf

Additional Detail(s) (Map)

Well Completed Date: 03/24/2009
Year Completed: 2009
Depth (m):
Latitude: 43.7177455570568
Longitude: -79.8119569906851
X: -79.81195684099812
Y: 43.7177455553685
Path: 712\7122451.pdf

Bore Hole Information

Bore Hole ID:	1002420368	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595701.00
Code OB Desc:		***North83:***	4841210.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	03/24/2009	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002532958
Layer:	1
Plug From:	0.0
Plug To:	0.20000000298023224
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1002532963
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1002532955
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002532960
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	2.0
Casing Diameter:	2.609999895095825
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002532961
Layer:	1
Slot:	10

Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 3.3399999141693115

Water Details

Water ID: 1002532959
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1002532957
Diameter: 10.899999618530273
Depth From: 0.0
Depth To: 2.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

15 | **1 of 1** | **S/198.7** | **240.9 / -1.08** | **120 SANDALWOOD PARKWAY Brampton ON** | **WWIS**

Well ID:	7114845	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	0	**Date Received:**	11/12/2008
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	M03765	**Contractor:**	7241
Tag:	A080526	**Form Version:**	5
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BRAMPTON CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114845.pdf

Additional Detail(s) (Map)

Well Completed Date: 08/15/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7171077634152
Longitude: -79.8103682008051
X: -79.81036805060674
Y: 43.71710776109784
Path: 711\7114845.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114845.pdf

Additional Detail(s) (Map)

Well Completed Date: 08/15/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7168221533531
Longitude: -79.8106097149641
X: -79.8106095653145
Y: 43.716822151170064
Path: 711\7114845.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114845.pdf

Additional Detail(s) (Map)

Well Completed Date: 08/15/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7174706431369
Longitude: -79.8097651498723
X: -79.80976500003786
Y: 43.71747064107875
Path: 711\7114845.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114845.pdf

Additional Detail(s) (Map)

Well Completed Date: 08/15/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7169470190143
Longitude: -79.8104955200291
X: -79.81049536970411
Y: 43.7169470173395
Path: 711\7114845.pdf

Bore Hole Information

Bore Hole ID: 1001880813
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/15/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 999999.00
North83: 9999999.00
Org CS: UTM83
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002708887

Layer: 1
Plug From: 0.0
Plug To: 2.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002708888
Method Construction Code:
Method Construction:
Other Method Construction:

Bore Hole Information

Bore Hole ID: 1002708859
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 08/15/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595878.00
North83: 4841182.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002708863
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Annular Space/Abandonment Sealing Record

Plug ID: 1002708864
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002708862
Method Construction Code:
Method Construction:
Other Method Construction: HOLLOW STEM

Pipe Information

Pipe ID: 1002708865

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002708867
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM:

Construction Record - Screen

Screen ID: 1002708866
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002708868
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002708861
Diameter: 21.31999969482422
Depth From:
Depth To: 2.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002708869 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17

Code OB:		**East83:**	595830.00
Code OB Desc:		**North83:**	4841141.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	08/15/2008	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002708873
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Annular Space/Abandonment Sealing Record

Plug ID:	1002708874
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002708872
Method Construction Code:	
Method Construction:	
Other Method Construction:	

Hole Diameter

Hole ID:	1002708871
Diameter:	
Depth From:	
Depth To:	2.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002708875	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595820.00
Code OB Desc:		**North83:**	4841123.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	08/15/2008	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002708880
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Annular Space/Abandonment Sealing Record

Plug ID: 1002708879
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002708878
Method Construction Code:
Method Construction:
Other Method Construction:

Hole Diameter

Hole ID: 1002708877
Diameter:
Depth From:
Depth To: 2.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002708881
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 08/15/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595811.00
North83: 4841109.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Sealing Record

Plug ID: 1002708885
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Annular Space/Abandonment Sealing Record

Plug ID: 1002708886
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002708884
Method Construction Code:
Method Construction:
Other Method Construction:

Hole Diameter

Hole ID: 1002708883
Diameter:
Depth From:
Depth To: 2.0
Hole Depth UOM: m
Hole Diameter UOM: cm

16	*1 of 62*	*W/196.0*	*248.8 / 6.87*	***BRAMPTON BRICK LIMITED*** ***225 WANLESS DR.*** ***BRAMPTON CITY ON L7A 1E9***	*CA*

Certificate #: 8-3064-88-
Application Year: 88
Issue Date: 9/1/1988
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: DUST CONTROL SYSTEM
Contaminants: Suspended Particulate Matter
Emission Control:

16	*2 of 62*	*W/196.0*	*248.8 / 6.87*	***PEEL BLOCK (1987) LIMITED DIV. BRAM. BRI*** ***225 WANLESS DRIVE*** ***BRAMPTON CITY ON L7A 1E9***	*CA*

Certificate #: 8-3130-88-
Application Year: 88
Issue Date: 11/18/1988
Approval Type: Industrial air
Status: Approved

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: CONCRETE BLOCK PLANT
Contaminants: Nitrogen Oxides, Suspended Particulate Matter
Emission Control: No Controls

16	3 of 62	W/196.0	248.8 / 6.87	***RICHVALE YORK BLOCK INC.*** ***225 WANLESS DRIVE*** ***BRAMPTON CITY ON L7A 1E9***	CA

Certificate #: 8-3487-93-
Application Year: 93
Issue Date: 11/26/1993
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: BIN VENT DUST COLL., WATER/UNIT HEATERS
Contaminants: Suspended Particulate Matter, Nitrogen Oxides
Emission Control: Baghouse (Incl Vent Fil.)

16	4 of 62	W/196.0	248.8 / 6.87	***ROXY CONSTRUCTION CO LTD*** ***225 WANLESS DR*** ***BRAMPTON ON L7A 1E9***	PRT

Location ID: 2015
Type: private
Expiry Date:
Capacity (L): 22730.00
Licence #: 0001060062

16	5 of 62	W/196.0	248.8 / 6.87	***BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKET*** ***225 WANLESS DR*** ***BRAMPTON ON L7A1E9***	PRT

Location ID: 2015
Type: retail
Expiry Date: 1993-01-31
Capacity (L): 1000
Licence #: 0076355098

16	6 of 62	W/196.0	248.8 / 6.87	***Brampton Brick Limited*** ***225 Wanless Dr*** ***Brampton ON L7A 1E9***	SCT

Established: 01-AUG-50
Plant Size (ft²):
Employment:

--Details--
Description: Clay Building Material and Refractory Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
SIC/NAICS Code:		327120			

16	7 of 62	W/196.0	248.8 / 6.87	**LAFARGE CANADA INC. - CONSTRUC** **225 Wanless Rd** **Brampton ON L7A 1E9**	SCT

Established: 0000
Plant Size (ft²): 0
Employment: 0

--Details--
Description: Ready-Mix Concrete Manufacturing
SIC/NAICS Code: 327320

16	8 of 62	W/196.0	248.8 / 6.87	**Lafarge Canada Inc. - Construction Materials Group** **225 Wanless Dr** **Brampton ON L7A 1E9**	SCT

Established:
Plant Size (ft²):
Employment:

16	9 of 62	W/196.0	248.8 / 6.87	**225 Wanless Drive** **Brampton ON L7A 1E9**	CA

Certificate #: 6668-4F3MGM
Application Year: 02
Issue Date: 7/21/02
Approval Type: Industrial air
Status: Revoked and/or Replaced
Application Type: Amended CofA
Client Name: Brampton Brick Limited
Client Address: 225 Wanless Drive
Client City: Brampton
Client Postal Code: L7A 1E9
Project Description: This application is for an amendment to an existing certificate of approval (air) for the expansion of an existing brick manufacturing plant and for the addition of one new tunnel kiln and associated lime scrubber to control discharges of hydrogen fluoride.
Contaminants:
Emission Control:

16	10 of 62	W/196.0	248.8 / 6.87	**Brampton Brick Limited - Brique Brampton Limitee** **225 Wanless Drive** **Brampton ON L7A 1E9**	CA

Certificate #: 4573-5A6RC3
Application Year: 02
Issue Date: 7/21/02
Approval Type: Industrial air
Status: Approved
Application Type: Amended CofA
Client Name: Brampton Brick Limited - Brique Brampton Limitee
Client Address: 225 Wanless Drive
Client City: Brampton
Client Postal Code: L7A 1E9
Project Description: Brampton Brick Limited - Brique Brampton Limitee, the manufacturer of clay brick, have submitted an application to

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

amend their current Certificate of Approval as follows; to replace the main stack and scrubbers of Kiln 1 and Kiln 2 with a larger scrubber of the same type, and a new insulated stack.

Contaminants:
Emission Control: Other - Air

---

16 | ***11 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***Brampton Brick Limited***
225 Wanless Drive CITY OF BRAMPTON
ON | ***EBR***

EBR Registry No: IA9E1225
Ministry Ref No: 8308787886RE1
Notice Type: Instrument Decision
Notice Stage:
Notice Date: September 15, 2005
Proposal Date: October 06, 1999
Year: 1999
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Brampton Brick Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 225 Wanless Drive, Brampton Ontario, Canada L7A 1E9
Comment Period:
URL:
Summary:

Site Location Details:

225 Wanless Drive CITY OF BRAMPTON

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

---

16 | ***12 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***Brampton Brick Limited***
225 Wanless Drive Brampton Ontario Brampton
ON | ***EBR***

EBR Registry No: IA9E1327
Ministry Ref No: 8000-4E5QZ8
Notice Type: Instrument Decision
Notice Stage:
Notice Date: September 15, 2005
Proposal Date: November 30, 1999
Year: 1999
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Brampton Brick Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 225 Wanless Drive, Brampton Ontario, L7A 1E9
Comment Period:
URL:
Summary:

Site Location Details:

225 Wanless Drive Brampton Ontario Brampton

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	13 of 62	W/196.0	248.8 / 6.87	**Brampton Brick Limited** **225 Wanless Drive Brampton Ontario Brampton ON**	EBR

EBR Registry No: IA02E0194
Ministry Ref No: 9859-57DJSR
Notice Type: Instrument Decision
Notice Stage:
Notice Date: July 26, 2002
Proposal Date: February 15, 2002
Year: 2002
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Brampton Brick Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 225 Wanless Drive, Brampton Ontario, L7A 1E9
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

225 Wanless Drive Brampton Ontario Brampton

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	14 of 62	W/196.0	248.8 / 6.87	**Brampton Brick Limited** **225 Wanless Drive Brampton Ontario Brampton ON**	EBR

EBR Registry No: IA02E1383
Ministry Ref No: 3534-5FLVVE
Notice Type: Instrument Decision
Notice Stage:
Notice Date: November 02, 2006
Proposal Date: November 06, 2002
Year: 2002
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Brampton Brick Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 225 Wanless Drive, Brampton Ontario, L7A 1E9
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

225 Wanless Drive Brampton Ontario Brampton

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	15 of 62	W/196.0	248.8 / 6.87	**RICHVALE YORK BLOCK INC.** **O/A PEEL BLOCK 225 WANLESS DRIVE** **BRAMPTON ON L7A 1E9**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON0213934	***Choice of Contact:***	
Approval Years:	93,94,95,96,97,98	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	3542
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	STRUCTURAL CONCRETE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

16	***16 of 62***	***W/196.0***	***248.8 / 6.87***	***ROXY CONSTRUCTION CO. LIMITED*** ***225 WANLESS DRIVE*** ***BRAMPTON ON L7A 1E9***	***GEN***

Generator Info

Generator No:	ON0385902	***Choice of Contact:***	
Approval Years:	98,99,00,01,02,03,04,05	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6351
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	GARAGES(GEN. REPAIR)		

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	17 of 62	W/196.0	248.8 / 6.87	PEEL BLOCK CO. (1987) LTD. DIV. OF BRAMPTON BRICK LTD. 225A WANLESS DR. BRAMPTON ON L7A 1E9	GEN

Generator Info

Generator No:	ON0627101	***Choice of Contact:***	
Approval Years:	90	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	3542
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	STRUCTURAL CONCRETE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	18 of 62	W/196.0	248.8 / 6.87	PEEL BLOCK CO. (1987) LIMITED 225A WANLESS DRIVE BRAMPTON ON L7A 1E9	GEN

Generator Info

Generator No:	ON0627101	***Choice of Contact:***	
Approval Years:	92,93,97,98	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	3542
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	STRUCTURAL CONCRETE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	19 of 62	W/196.0	248.8 / 6.87	PEEL BLOCK CO. (1987) LTD. 30-678 DIV. OF BRAMPTON BRICK LTD. 225A WANLESS DR. BRAMPTON ON L7A 1E9	GEN

Generator Info

Generator No:	ON0627101	***Choice of Contact:***	
Approval Years:	94,95,96	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	3542
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	STRUCTURAL CONCRETE		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

16 | ***20 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***PEEL BLOCK COMPANY (1987) LIMITED***
225A WANLESS DRIVE
BRAMPTON ON L7A 1E9 | ***GEN***

Generator Info

Generator No: ON0627101
Approval Years: 99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: STRUCTURAL CONCRETE

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3542

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

16 | ***21 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***BRAMPTON BRICK LIMITED***
225 WANLESS DRIVE
BRAMPTON ON L7A 1E9 | ***GEN***

Generator Info

Generator No: ON1294801
Approval Years: 94,95,96,97,98,99,00,01,02,03,04,05,06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: DOMESTIC CLAY PROD.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3511

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

16	***22 of 62***	***W/196.0***	***248.8 / 6.87***	***RICHVALE YORK BLOCK INC.*** ***225A WANLESS DRIVE*** ***BRAMPTON ON L7A 1E9***	***GEN***

Generator Info

Generator No: ON0627101
Approval Years: 04,05,06
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Concrete Pipe Brick and Block Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 327330

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

16	***23 of 62***	***W/196.0***	***248.8 / 6.87***	***ROXY CONSTRUCTION CO LTD*** ***225 WANLESS DR*** ***BRAMPTON ON L7A 1E9***	***FSTH***

License Issue Date: 12/23/1991
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Year of Installation: 1990
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

---

16 | ***24 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***Brampton Brick Limited***
225 Wanless Drive Brampton Ontario Brampton ON | ***EBR***

EBR Registry No: IA03E1565
Ministry Ref No: 7907-5SDQBF
Notice Type: Instrument Decision
Notice Stage:
Notice Date: June 23, 2005
Proposal Date: November 05, 2003
Year: 2003
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Brampton Brick Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 225 Wanless Drive, Brampton Ontario, L7A 1E9
Comment Period:
URL:
Summary:

Site Location Details:

225 Wanless Drive Brampton Ontario Brampton

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

---

16 | ***25 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***Roxy Construction Co. Limited***
225 Wanless Drive Brampton Ontario Brampton ON | ***EBR***

EBR Registry No: IA06E1330
Ministry Ref No: 3661-6TURZV
Notice Type: Instrument Decision
Notice Stage:
Notice Date: December 09, 2008
Proposal Date: October 25, 2006
Year: 2006
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Roxy Construction Co. Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 225 Wanless Drive, Brampton Ontario, Canada L7A 1E9
Comment Period:
URL:
Summary:

Site Location Details:

225 Wanless Drive Brampton Ontario Brampton

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	26 of 62	W/196.0	248.8 / 6.87	ROXY CONSTRUCTION CO LTD 225 WANLESS DR BRAMPTON ON L7A 1E9	FSTH

License Issue Date: 12/23/1991
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1990
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	27 of 62	W/196.0	248.8 / 6.87	Brampton Brick Limited/Brique Brampton Limitee 225 Wanless Dr Brampton ON L7A 1E9	SPL

Ref No: 8567-83DQV3
Year:
Incident Dt:
Dt MOE Arvl on Scn: 3/11/2010
MOE Reported Dt: 3/9/2010
Dt Document Closed: 5/31/2010
Site No:
MOE Response: Planned Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 225 Wanless Drive
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Entity Operating Name:
Client Name: Brampton Brick Limited/Brique Brampton Limitee
Client Type:
Source Type:
Incident Cause: Other Discharges
Incident Preceding Spill:
Incident Reason: Equipment Failure
Incident Summary: Brampton Brick: 2300L diesel fuel to pea gravel, contained
Environment Impact: Possible
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 2300 L
Contaminant Qty 1: 2300
Contaminant Unit: L
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Contaminant UN No 1:					
Receiving Medium:					
Activity Preceding Spill:					
Property 2nd Watershed:					
Property Tertiary Watershed:					
Sector Type:		Other			
SAC Action Class:		Land Spills			
Call Report Locatn Geodata:					
Time Reported:					
System Facility Address:					

16	***28 of 62***	***W/196.0***	***248.8 / 6.87***	***Brampton Brick Limited*** ***225 Wanless Drive*** ***Brampton ON L7A 1E9***	***CA***

Certificate #:	0092-5KUR22
Application Year:	2003
Issue Date:	4/5/2003
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

16	***29 of 62***	***W/196.0***	***248.8 / 6.87***	***Brampton Brick Limited / Brique Brampton Limitee*** ***225 Wanless Dr*** ***Brampton ON L7A 1E9***	***CA***

Certificate #:	1735-7KUJ8A
Application Year:	2008
Issue Date:	11/17/2008
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

16	***30 of 62***	***W/196.0***	***248.8 / 6.87***	***Medical Waste Management Inc.*** ***225 Wanless Drive*** ***Brampton ON L7A 1E9***	***CA***

Certificate #:	A841667
Application Year:	2000
Issue Date:	8/8/2000
Approval Type:	Waste Management Systems
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

16 | ***31 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKETING)***
225 WANLESS DR
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9910971
Status: EXPIRED
Instance ID: 398062
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Refill Cntr - Cylr Fill
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

16 | ***32 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***BRAMPTON BRICK SALES (DIV OF BRAMPTON BRICK MARKETING)***
225 WANLESS DR
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10602738
Status: EXPIRED
Instance ID: 30174
Instance Type: FS Propane Tank
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

16	33 of 62	W/196.0	248.8 / 6.87	**BRAMPTON BRICK LIMITED** **225 WANLESS DRIVE** **BRAMPTON ON L7A 1E9**	GEN

Generator Info

Generator No: ON1294801
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Miscellaneous Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 339990

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

---

16 | **34 of 62** | **W/196.0** | **248.8 / 6.87** | **225 Wanless Dr**
Brampton ON L7A 1E9 | **EHS**

Order No: 20120911022
Status: C
Report Type: Site Report
Report Date: 12-SEP-12
Date Received: 11-SEP-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: NY
Search Radius (km): .25
X: -79.817948
Y: 43.722036

---

16 | **35 of 62** | **W/196.0** | **248.8 / 6.87** | **BRAMPTON BRICK LIMITED**
225 WANLESS DRIVE
BRAMPTON ON L7A 1E9 | **GEN**

Generator Info

Generator No: ON1294801
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Miscellaneous Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 339990

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

16 | ***36 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***BRAMPTON BRICK LIMITED***
225 WANLESS DRIVE
BRAMPTON ON L7A 1E9 | ***GEN***

Generator Info

Generator No: ON1294801
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Miscellaneous Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 339990

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

16 | **37 of 62** | **W/196.0** | **248.8 / 6.87** | **ROXY CONSTRUCTION CO LTD**
225 WANLESS DR
BRAMPTON ON | **FST**

Inventory No: 10602684
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

16 | **38 of 62** | **W/196.0** | **248.8 / 6.87** | **BRAMPTON BRICK LIMITED**
225 WANLESS DRIVE
BRAMPTON ON L7A 1E9 | **GEN**

Generator Info

Generator No: ON1294801
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Miscellaneous Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 339990

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

16 | ***39 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***LAFARGE CANADA INC.***
225 WANLESS Drive
BRAMPTON ON L7A1E9 | ***NPRI***

NPRI ID:	8800000802	***Org ID:***	
Other ID:		***Submit Date:***	
No Other ID:		***Last Modified:***	
Track ID:		***Contact ID:***	
Report ID:		***Cont Type:***	MED
Report Type:		***Contact Title:***	Mr.
Rpt Type ID:		***Cont First Name:***	TOM
Report Year:	2004	***Cont Last Name:***	BAUMGARTEN
Not-Current Rpt?:		***Contact Position:***	Environmental Compliance Manager
Yr of Last Filed Rpt:		***Contact Fax:***	
Fac ID:		***Contact Ph.:***	
Fac Name:	LCI RMC POP6 PLANT	***Cont Area Code:***	905
Fac Address1:		***Contact Tel.:***	7387070
Fac Address2:		***Contact Ext.:***	
Fac Postal Zip:		***Cont Fax Area Cde:***	905
Facility Lat:		***Contact Fax:***	7387080
Facility Long:		***Contact Email:***	tom.baumgarten@lafarge-na.com
DLS (Last Filed Rpt):		***Latitude:***	
Facility DLS:		***Longitude:***	
Datum:		***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	7	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	31-33		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3273		
NAICS 4 Description:	Cement and Concrete Product Manufacturing		
NAICS Code (6 digit):	327320		
NAICS 6 Description:	Ready-Mix Concrete Manufacturing		

Substance Release Report

CAS No: 74-82-8
Report ID:
Rpt Period: 2004
Subst Released: Methane
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 11104-93-1
Report ID:
Rpt Period: 2004
Subst Released: Nitrogen oxides (expressed as NO2)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004
Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 10024-97-2
Report ID:
Rpt Period: 2004
Subst Released: Nitrous oxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 630-08-0
Report ID:
Rpt Period: 2004
Subst Released: Carbon monoxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 7446-09-5
Report ID:
Rpt Period: 2004
Subst Released: Sulphur dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 124-38-9
Report ID:

Rpt Period: 2004
Subst Released: Carbon dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M08
Report ID:
Rpt Period: 2004
Subst Released: PM - Total Particulate Matter
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M09
Report ID:
Rpt Period: 2004
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air: .629
Water:
Land:
Total Releases: .629
Units: tonnes

CAS No: NA - M10
Report ID:
Rpt Period: 2004
Subst Released: PM2.5 - Particulate Matter <= 2.5 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

---

16 | **40 of 62** | **W/196.0** | **248.8 / 6.87** | **225 Wanless Drive Brampton ON** | **EHS**

Order No: 20140102017
Status: C
Report Type: Custom Report
Report Date: 13-JAN-14
Date Received: 02-JAN-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.815229
Y: 43.720726

---

16 | **41 of 62** | **W/196.0** | **248.8 / 6.87** | **BRAMPTON BRICK LIMITED 225 WANLESS DRIVE BRAMPTON ON** | **GEN**

Generator Info

Generator No:	ON1294801	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	327120
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	CLAY BUILDING MATERIAL AND REFRACTORY MANUFACTURING		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

16	***42 of 62***	***W/196.0***	***248.8 / 6.87***	***225a Wanless Drive, Brampton ON***	***INC***

Incident No:	821252	***Any Health Impact:***	No
Incident ID:		***Any Enviro Impact:***	No
Instance No:		***Service Intrp:***	No
Status Code:		***Was Prop Damaged:***	No
Incident Status:		***Reside App. Type:***	
Incident Severity:		***Commer App. Type:***	
Task No:	3856556	***Indus App. Type:***	

Attribute Category:	FS-Perform L1 Incident Insp	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	
Date of Occurrence:	2012/06/04 00:00:00	**Operation Pressure:**	
Time of Occurrence:	15:30:00	**Equipment Type:**	
Occr Insp Start Dt:	2012/06/05 00:00:00	**Equipment Model:**	
Incident Creat On:		**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Vapour Release	**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Natural Gas	**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:	NULL	**Tank Storage Type:**	
Prc Escalation Req:	NULL	**Tank Location Type:**	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	225a Wanless Drive, Brampton - Vapour Release		
Invent Postal Code:			
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:	Power failure at Brampton Brick caused regulators to slam after burners turned off, caused reliefs to let go for a minute.		
Operation Type Involved:	Industrial / Manufacturing Facility		

16	***43 of 62***	***W/196.0***	***248.8 / 6.87***	***Brampton Brick Limited*** ***225 Wanless Drive*** ***Brampton ON L7A 1E9***	***GHG***

GHG ID No:	G10664	**Facility Nm (Map):**	Brampton Brick Limited
DUNS No:	0	**Company Nm (Map):**	Brampton Brick Limited
Facility ID:	10664	**Address (Map):**	225 Wanless Drive
City (Map):	Brampton	**Mass Balance:**	Not applicable / Sans Objet
Postal Code (Map):	L7A 1E9	**Emission Factors:**	Not applicable / Sans Objet
Province (Map):	Ontario	**Engineer Estimates:**	Not applicable / Sans Objet
Latitude (Map):	43.7211	**Longitude (Map):**	-79.8164
Latitude:	43.7211	**Y (Map):**	
Longitude:	-79.8164	**X (Map):**	
Year:	2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022		
Facility Detail:	http://indicators-map.canada.ca/App/Detail?id=0110664&GoCTemplateCulture=en-CA		
GHG Rp Quantification Req:	Applicable		
Rprt Comp Legal Nm:	Brampton Brick Limited		
Rprt Comp Trade Nm:			
Rprt Comp Bus No:	100621424		
Public Contact:	Kyle Halfyard		
Public Contact Position:	Environmental Analyst		
Pub Cont Phone:	4163050180		
Pub Cont Ext:			

Pub Cont Email:	khalfyard@bramptonbrick.com
Pub Cont Mail Addr:	225 Wanless Drive
Pub Cont City:	Brampton
Pub Cont Prov:	Ontario
Pub Cont Postal Cd:	L7A 1E9
Industry Classification:	Clay Building Material and Refractory Manufacturing
GHG Emissions (kt):	
Monitoring or Direct Measure:	Not applicable / Sans Objet
NAICS Code:	327120
NAICS Code Desc (English):	Clay Building Material and Refractory Manufacturing
NAICS Code Desc (French):	Fabrication de matériaux de construction en argile et de produits réfractaires
NAICS Data Link:	https://www23.statcan.gc.ca/imdb/p3VD.pl?Function=getVD&TVD=1369825&CVD=1370970&CPV=327120&CST=27012022&CLV=5&MLV=5
Data Source(s):	Greenhouse Gas Reporting Program (GHGRP); Facility Greenhouse Gas Data Greenhouse Gas Emissions (Map)
Total Emissions:	70.96
Units:	kilotonnes of carbon dioxide equivalents (kt CO2 eq)
Facility GHG Data Link:	https://climate-change.canada.ca/facility-emissions/GHGRP-G10664-2021.html
Total Emissions:	53.09
Units:	kilotonnes of carbon dioxide equivalents (kt CO2 eq)
Facility GHG Data Link:	https://climate-change.canada.ca/facility-emissions/GHGRP-G10664-2022.html

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2015
CO2 Tonnes:	60754.75	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.67	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	18.76	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.66	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	174.9	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	60948.41		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2017
CO2 Tonnes:	72949	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.8	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	22.4	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.78	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	206.7	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0

HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	73178.1		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2014
CO2 Tonnes:	50099.44	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.55	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	15.4	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.56	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	148.4	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	50263.24		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2021
CO2 Tonnes:	70715.85	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.79	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	22.12	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.74	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	196.1	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0

HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	70934.07		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2018
CO2 Tonnes:	61290	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.73	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	20.44	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.61	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	161.65	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	61472.09		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2011
CO2 Tonnes:	53247.03977	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.553	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	15.484	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.49419	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	130.96035	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0

HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	53393.48412		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2013
CO2 Tonnes:	56481.57001	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.55	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	15.4	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.66	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	174.9	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	56671.87001		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2022
CO2 Tonnes:	52931.77	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.57	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	15.96	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.54	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	143.1	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0

HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	53090.83		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2012
CO2 Tonnes:	72529.29999	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.74	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	20.72	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.72	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	190.8	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	72740.81999		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2020
CO2 Tonnes:	47085.15	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.53	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	14.84	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.5	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	132.5	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0

HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	47232.49		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2016
CO2 Tonnes:	69433.76001	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.77	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	21.56	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.74	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	196.1	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	69651.42001		

GHG Emission Details

Facility NPRI ID:	7302	***Year:***	2019
CO2 Tonnes:	35446.11	***HFC-143 Tonne CO2e:***	0
CO2 Tonnes CO2e:		***HFC-227ea Tonnes:***	0
CH4 Tonnes:	0.391	***HFC-227ea Ton CO2e:***	0
CH4 Tonnes CO2e:	10.948	***HFC-236fa Tonnes:***	0
N2O Tonnes:	0.375	***HFC-236fa Ton CO2e:***	0
N2O Tonnes CO2e:	99.375	***HFC-245ca Tonnes:***	0
HFC-23 Tonnes:	0	***HFC-245ca Ton CO2e:***	0
HFC-23 Tonnes CO2e:	0	***HFC Total Ton Co2e:***	0
HFC-32 Tonnes:	0	***CF4 Tonnes:***	0
HFC-32 Tonnes CO2e:	0	***CF4 Tonnes CO2e:***	0
HFC-125 Tonnes:	0	***C2F6 Tonnes:***	0
HFC-125 tonne CO2e:	0	***C2F6 Tonnes CO2e:***	0
HFC-134a Tonnes:	0	***C3F8 Tonnes:***	0
HFC-134a Tonn CO2e:	0	***C3F8 Tonnes CO2e:***	0
HFC-143a Tonnes:	0	***C4F10 Tonnes:***	0
HFC-143a ton CO2e:	0	***C4F10 Tonnes CO2e:***	0
HFC-152a Tonnes:	0	***C4F8 Tonnes:***	0
HFC-152a ton CO2e:	0	***C4F8 Tonnes CO2e:***	0
HFC-41 Tonnes:	0	***C5F12 Tonnes:***	0
HFC-41 Tonnes CO2e:	0	***C5F12 Tonnes CO2e:***	0
HFC-43 10mee t:	0	***C6F14 Tonnes:***	0
HFC-43 10mee T CO2:	0	***C6F14 Tonnes CO2e:***	0
HFC-134 Tonnes:	0	***PFC Total Ton CO2e:***	0
HFC-134 Tonne CO2e:	0	***SF6 Tonnes:***	0
HFC-143 Tonnes:	0	***SF6 Tonnes CO2e:***	0
Total Emissions (tonnes CO2e):	35556.433		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

GHG Emissions from Large Facilities

Report Year:	2022
CO2 EQ:	53.09
Symbol:	3
E Units:	kilotonnes of carbon dioxide equivalents (kt CO2 eq)
E Detail Page URL:	https://indicators-map.canada.ca/App/Detail?id=0110664&GoCTemplateCulture=en-CA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	44 of 62	W/196.0	248.8 / 6.87	***Brampton Brick Limited*** ***225 Wanless Dr*** ***Brampton ON L7A 1E9***	SPL

Ref No:	1751-A7HLWB	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2016/02/26	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2016/02/26	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:	3162-4E5QZD
MOE Response:	No
Site County/District:	
Site Geo Ref Meth:	NA
Site District Office:	
Nearest Watercourse:	
Site Name:	225 Wanless Drive
Site Address:	225 Wanless Dr
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	NA
Site Map Datum:	NA
Northing:	NA
Easting:	NA
Entity Operating Name:	
Client Name:	Brampton Brick Limited
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	Bypass
Incident Reason:	Equipment Failure
Incident Summary:	Brampton Brick Ltd- Fluoride gas released to atmos
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
Contaminant Qty 1:	0
Contaminant Unit:	other - see incident description
Contaminant Code:	51
Contaminant Name:	FLUORIDE 1.5
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Air Spills - Gases and Vapours
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	45 of 62	W/196.0	248.8 / 6.87	**Brampton Brick Limited** **225 Wanless Drive** **Brampton ON L7A 1E9**	ECA

Approval No:	6668-4F3MGM	**MOE District:**	Halton-Peel
Approval Date:	2002-07-21	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.81376
Record Type:	ECA	**Latitude:**	43.72144
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Brampton Brick Limited
Address: 225 Wanless Drive
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8000-4E5QZ8-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	46 of 62	W/196.0	248.8 / 6.87	**Brampton Brick Limited / Brique Brampton Limitee** **225 Wanless Dr** **Brampton ON L7A 1E9**	ECA

Approval No:	1735-7KUJ8A	**MOE District:**	Halton-Peel
Approval Date:	2008-11-17	**City:**	
Status:	Approved	**Longitude:**	-79.81376
Record Type:	ECA	**Latitude:**	43.72144
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Brampton Brick Limited / Brique Brampton Limitee
Address: 225 Wanless Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3661-6TURZV-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	47 of 62	W/196.0	248.8 / 6.87	**Medical Waste Management Inc.** **225 Wanless Drive** **Brampton ON L6T 5R7**	ECA

Approval No:	A841667	**MOE District:**	Halton-Peel
Approval Date:	2000-08-08	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.81376
Record Type:	ECA	**Latitude:**	43.72144
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	

Approval Type: ECA-WASTE MANAGEMENT SYSTEMS
Project Type: WASTE MANAGEMENT SYSTEMS
Business Name: Medical Waste Management Inc.
Address: 225 Wanless Drive
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6333-4MFPLD-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	48 of 62	W/196.0	248.8 / 6.87	**Brampton Brick Limited** **225 Wanless Drive** **Brampton ON L7A 1E9**	ECA

Approval No:	4573-5A6RC3	**MOE District:**	Halton-Peel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Date: 2002-07-21
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Brampton Brick Limited
Address: 225 Wanless Drive
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9859-57DJSR-14.pdf
PDF Site Location:
City:
Longitude: -79.81376
Latitude: 43.72144
Geometry X:
Geometry Y:

---

16 | **49 of 62** | **W/196.0** | **248.8 / 6.87** | **Brampton Brick Limited**
225 Wanless Drive
Brampton ON L7A 1E9 | **ECA**

Approval No: 0092-5KUR22
Approval Date: 2003-04-05
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Brampton Brick Limited
Address: 225 Wanless Drive
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3534-5FLVVE-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81376
Latitude: 43.72144
Geometry X:
Geometry Y:

---

16 | **50 of 62** | **W/196.0** | **248.8 / 6.87** | **BRAMPTON BRICK LIMITED**
225 WANLESS DRIVE
BRAMPTON ON L7A 1E9 | **GEN**

Generator Info

Generator No: ON1294801
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Lauren Mulkerns
Phone No Admin: (905) 840-1011 Ext.3303
SIC Description: CLAY BUILDING MATERIAL AND REFRACTORY MANUFACTURING
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 327120

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

16	51 of 62	W/196.0	248.8 / 6.87	**BRAMPTON BRICK LIMITED** **225 WANLESS DRIVE** **BRAMPTON ON L7A 1E9**	GEN

Generator Info

Generator No: ON1294801
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Lauren Mulkerns
Phone No Admin: (905) 840-1011 Ext.3303
SIC Description: CLAY BUILDING MATERIAL AND REFRACTORY MANUFACTURING
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 327120

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145

Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 143
Waste Class Name: STEEL MAKING RESIDUES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

---

16 | ***52 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***BRAMPTON BRICK LIMITED***
225 WANLESS DRIVE
BRAMPTON ON L7A 1E9 | ***GEN***

Generator Info

Generator No: ON1294801
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Lauren Mulkerns
Phone No Admin: (905) 840-1011 Ext.3303
SIC Description: CLAY BUILDING MATERIAL AND REFRACTORY MANUFACTURING

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 327120

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

16 | ***53 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***BRAMPTON BRICK LIMITED***
225 WANLESS DRIVE
BRAMPTON ON L7A 1E9 | ***GEN***

Generator Info

Generator No: ON1294801
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 143 L
Waste Class Name: Residues from steel making

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

16	***54 of 62***	***W/196.0***	***248.8 / 6.87***	***225 Wanless Drive***	***EHS***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON L7A 1E9	

Order No:	20181022134	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	NY
Report Date:	23-OCT-18	**Search Radius (km):**	.25
Date Received:	22-OCT-18	**X:**	-79.816465
Previous Site Name:		**Y:**	43.722179
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	55 of 62	W/196.0	248.8 / 6.87	**Canada Cartage Systems Limited** **225 Wanless Dr** **Brampton ON**	SPL

Ref No:	1320-B87GKH	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2019/01/07	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2019/01/07	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2019/01/11	**Agency Involved:**	

Site No:	NA
MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Brampton Brick<UNOFFICIAL>
Site Address:	225 Wanless Dr
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4841364.69
Easting:	595635.87
Entity Operating Name:	
Client Name:	Canada Cartage Systems Limited
Client Type:	Corporation
Source Type:	Truck - Transport/Hauling
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Maintenance
Incident Summary:	Canada Cartage 15 L of oil to grnd/cb
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	15 L
Contaminant Qty 1:	15
Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	MOTOR OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	1993
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Time Reported:					
System Facility Address:					
16	56 of 62	W/196.0	248.8 / 6.87	BRAMPTON BRICK LIMITED 225 WANLESS DRIVE BRAMPTON ON L7A 1E9	GEN

Generator Info

Generator No:	ON1294801	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	148 C
Waste Class Name:	Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class:	221 I
Waste Class Name:	Light fuels

Waste Detail(s)

Waste Class:	143 L
Waste Class Name:	Residues from steel making

Waste Detail(s)

Waste Class:	146 L
Waste Class Name:	Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

16 | **57 of 62** | **W/196.0** | **248.8 / 6.87** | ***Canada Cartage Limited***
225 Wanless Drive
Brampton ON | ***SPL***

Ref No: 8215-BFUJYU
Year:
Incident Dt: 9/9/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/9/2019
Dt Document Closed: 11/16/2019
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Nearest Watercourse:	
Site Name:	Brick Parking Lot<UNOFFICIAL>
Site Address:	225 Wanless Drive
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4841579
Easting:	595343
Entity Operating Name:	
Client Name:	Canada Cartage Limited
Client Type:	Corporation
Source Type:	Truck - Transport/Hauling
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Unknown / N/A
Incident Summary:	Canada Cartage: 15L hydraulic oil to ground
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	15 L
Contaminant Qty 1:	15
Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	HYDRAULIC OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	n/a
Contaminant UN No 1:	n/a
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	58 of 62	W/196.0	248.8 / 6.87	***BRAMPTON BRICK LIMITED*** ***225 WANLESS DRIVE*** ***BRAMPTON ON L7A 1E9***	GEN

Generator Info

Generator No:	ON1294801	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 263 C
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 143 L
Waste Class Name: Residues from steel making

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	59 of 62	W/196.0	248.8 / 6.87	BRAMPTON BRICK LIMITED 225 WANLESS DRIVE BRAMPTON ON	GEN

Generator Info

Generator No: ON1294801
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 113 C
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 143 L
Waste Class Name: STEEL MAKING RESIDUES

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 263 C

Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Generator Info as of Dec 2024

Generator No: ON1294801
Generator Company Name: BRAMPTON BRICK LIMITED
Street: 225 WANLESS DRIVE
City: BRAMPTON
Province State: Ontario
Country: Canada
Postal Code: L7A1E9
Waste Class: 212 L,221 I,251 L,251 L,252 L,112 C,146 L,221 L,145 L,143 L,113 C,331 I,148 C,263 C,122 C,145 I,263 L,146 T, 263 I,213 L,148 C,331 B,331 B

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 221 - LIGHT FUELS; 251 - OIL SKIMMINGS & SLUDGES; 251 - OIL SKIMMINGS & SLUDGES; 252 - WASTE OILS & LUBRICANTS; 112 - ACID WASTE - HEAVY METALS; 146 - OTHER SPECIFIED INORGANICS; 221 - LIGHT FUELS; 145 - PAINT/PIGMENT/COATING RESIDUES; 143 - STEEL MAKING RESIDUES; 113 - ACID WASTE - OTHER METALS; 331 - WASTE COMPRESSED GASES; 148 - INORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 122 - ALKALINE WASTES - OTHER METALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 263 - ORGANIC LABORATORY CHEMICALS; 146 - OTHER SPECIFIED INORGANICS; 263 - ORGANIC LABORATORY CHEMICALS; 213 - PETROLEUM DISTILLATES; 148 - INORGANIC LABORATORY CHEMICALS; 331 - WASTE COMPRESSED GASES; 331 - WASTE COMPRESSED GASES

2017 Generator Info

Gen No: ON1294801
ID: 6571
Choice of Contact: CO_ADMIN
Phone No Official: (905) 840-1011 Ext.

Contaminated Fac:	N	***Phone No Admin:***	(905) 840-1011 Ext.3303
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	327120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	BRAMPTON BRICK LIMITED		
Gen Div:			
Gen Op Name:	BRAMPTON BRICK LIMITED		
Gen Op Div:			
Site Adrs1:	225 WANLESS DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1E9		
Site Country:	Canada		
Co Official:	Brad Cobbledick		
Co Admin:	Lauren Mulkerns		

2017 Generator Manifest

ID:	23023	***Sum Received Qty:***	20.0
Generator No:	ON1294801	***Waste Class Name:***	WASTE COMPRESSED GASES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	I	***District:***	202
Waste Code:	331		

2017 Generator Manifest

ID:	23028	***Sum Received Qty:***	22020.0
Generator No:	ON1294801	***Waste Class Name:***	OTHER SPECIFIED INORGANICS
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	L	***District:***	306
Waste Code:	146		

2017 Generator Manifest

ID:	23021	***Sum Received Qty:***	100.0
Generator No:	ON1294801	***Waste Class Name:***	ACID WASTE - HEAVY METALS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	C	***District:***	202
Waste Code:	112		

2017 Generator Manifest

ID:	23022	***Sum Received Qty:***	133.0
Generator No:	ON1294801	***Waste Class Name:***	ACID WASTE - OTHER METALS
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	C	***District:***	202
Waste Code:	113		

2017 Generator Manifest

ID:	23025	***Sum Received Qty:***	150.0
Generator No:	ON1294801	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	251		

2017 Generator Manifest

ID:	23020	***Sum Received Qty:***	95815.0
Generator No:	ON1294801	***Waste Class Name:***	OTHER SPECIFIED INORGANICS
Receiver Type:	030	***Count Manifests:***	5
Waste Char:	L	***District:***	201
Waste Code:	146		

2017 Generator Manifest

ID:	23026	***Sum Received Qty:***	18.0
Generator No:	ON1294801	***Waste Class Name:***	ACID WASTE - HEAVY METALS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	C	***District:***	306
Waste Code:	112		

2017 Generator Manifest

ID:	23030	***Sum Received Qty:***	30.0
Generator No:	ON1294801	***Waste Class Name:***	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	C	***District:***	306
Waste Code:	263		

2017 Generator Manifest

ID:	23024	***Sum Received Qty:***	10906.0
Generator No:	ON1294801	***Waste Class Name:***	OTHER SPECIFIED INORGANICS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	203
Waste Code:	146		

2017 Generator Manifest

ID:	23027	***Sum Received Qty:***	3.0
Generator No:	ON1294801	***Waste Class Name:***	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	C	***District:***	306
Waste Code:	122		

2017 Generator Manifest

ID:	23029	***Sum Received Qty:***	4477.0
Generator No:	ON1294801	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	5
Waste Char:	L	***District:***	306
Waste Code:	252		

2018 Generator Info

Gen No:	ON1294801	***Choice of Contact:***	CO_ADMIN
ID:	6409	***Phone No Official:***	(905) 840-1011 Ext.
Contaminated Fac:	N	***Phone No Admin:***	(905) 840-1011 Ext.3303
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	327120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	BRAMPTON BRICK LIMITED		
Gen Div:			
Gen Op Name:	BRAMPTON BRICK LIMITED		
Gen Op Div:			

Site Adrs1:	225 WANLESS DRIVE
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 1E9
Site Country:	Canada
Co Official:	Brad Cobbledick
Co Admin:	Lauren Mulkerns

2018 Generator Manifest

ID:	22650	**Sum Received Qty:**	152.0
Generator No:	ON1294801	**Waste Class Name:**	ACID WASTE - OTHER METALS
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	C	**District:**	306
Waste Code:	113		

2018 Generator Manifest

ID:	22651	**Sum Received Qty:**	230890.0
Generator No:	ON1294801	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	53
Waste Char:	L	**District:**	306
Waste Code:	146		

2018 Generator Manifest

ID:	22649	**Sum Received Qty:**	493140.0
Generator No:	ON1294801	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	105
Waste Char:	L	**District:**	301
Waste Code:	146		

2018 Generator Manifest

ID:	22652	**Sum Received Qty:**	4885.0
Generator No:	ON1294801	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	5
Waste Char:	L	**District:**	306
Waste Code:	252		

2019 Generator Info

Gen No:	ON1294801	**Choice of Contact:**	CO_ADMIN
ID:	6235	**Phone No Official:**	(905) 840-1011 Ext.
Contaminated Fac:	N	**Phone No Admin:**	(905) 840-1011 Ext.3303
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	327120	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	BRAMPTON BRICK LIMITED		
Gen Div:			
Gen Op Name:	BRAMPTON BRICK LIMITED		
Gen Op Div:			
Site Adrs1:	225 WANLESS DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			

Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 1E9
Site Country:	Canada
Co Official:	Brad Cobbledick
Co Admin:	Lauren Mulkerns

2019 Generator Manifest

ID:	22349	**Sum Received Qty:**	305.0
Generator No:	ON1294801	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	I	**District:**	306
Waste Code:	145		

2019 Generator Manifest

ID:	22346	**Sum Received Qty:**	74398.0
Generator No:	ON1294801	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	19
Waste Char:	L	**District:**	301
Waste Code:	146		

2019 Generator Manifest

ID:	22350	**Sum Received Qty:**	139.0
Generator No:	ON1294801	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	C	**District:**	306
Waste Code:	148		

2019 Generator Manifest

ID:	22352	**Sum Received Qty:**	8904.0
Generator No:	ON1294801	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	6
Waste Char:	L	**District:**	306
Waste Code:	252		

2019 Generator Manifest

ID:	22353	**Sum Received Qty:**	5.0
Generator No:	ON1294801	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	306
Waste Code:	263		

2019 Generator Manifest

ID:	22347	**Sum Received Qty:**	277300.0
Generator No:	ON1294801	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	64
Waste Char:	L	**District:**	305
Waste Code:	146		

2019 Generator Manifest

ID:	22345	**Sum Received Qty:**	48000.0
Generator No:	ON1294801	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	4

Waste Char: L
Waste Code: 146
District: 202

2019 Generator Manifest

ID: 22348
Generator No: ON1294801
Receiver Type: 035
Waste Char: C
Waste Code: 112
Sum Received Qty: 70.0
Waste Class Name: ACID WASTE - HEAVY METALS
Count Manifests: 2
District: 306

2019 Generator Manifest

ID: 22354
Generator No: ON1294801
Receiver Type: 035
Waste Char: I
Waste Code: 331
Sum Received Qty: 100.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 1
District: 306

2019 Generator Manifest

ID: 22351
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 3035.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 2
District: 306

2020 Generator Info

Gen No: ON1294801
ID: 6033
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 327120
NAICS Code2:
NAICS Code3:
Gen Name: BRAMPTON BRICK LIMITED
Gen Div:
Gen Op Name: BRAMPTON BRICK LIMITED
Gen Op Div:
Site Adrs1: 225 WANLESS DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1E9
Site Country: Canada
Co Official: Lauren Mulkerns
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Official: (905) 840-1011 Ext.3303
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305

2020 Generator Manifest

ID: 19910
Generator No: ON1294801
Receiver Type: 035
Waste Char: C
Waste Code: 148
Sum Received Qty: 50.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 1
District: 306

2020 Generator Manifest

ID: 19906
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 146

Sum Received Qty: 4530.0
Waste Class Name: OTHER SPECIFIED INORGANICS
Count Manifests: 1
District: 301

2020 Generator Manifest

ID: 19908
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 252

Sum Received Qty: 3400.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 2
District: 305

2020 Generator Manifest

ID: 19904
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 146

Sum Received Qty: 39000.0
Waste Class Name: OTHER SPECIFIED INORGANICS
Count Manifests: 3
District: 202

2020 Generator Manifest

ID: 19905
Generator No: ON1294801
Receiver Type: 035
Waste Char: T
Waste Code: 146

Sum Received Qty: 13000.0
Waste Class Name: OTHER SPECIFIED INORGANICS
Count Manifests: 1
District: 202

2020 Generator Manifest

ID: 19912
Generator No: ON1294801
Receiver Type: 035
Waste Char: C
Waste Code: 263

Sum Received Qty: 10.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 2
District: 306

2020 Generator Manifest

ID: 19914
Generator No: ON1294801
Receiver Type: 035
Waste Char: I
Waste Code: 331

Sum Received Qty: 300.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 1
District: 306

2020 Generator Manifest

ID: 19907
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 146

Sum Received Qty: 419150.0
Waste Class Name: OTHER SPECIFIED INORGANICS
Count Manifests: 98
District: 305

2020 Generator Manifest

ID: 19911
Generator No: ON1294801
Receiver Type: 035

Sum Received Qty: 1200.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1

Waste Char: L
Waste Code: 252
District: 306

2020 Generator Manifest

ID: 19909
Generator No: ON1294801
Receiver Type: 035
Waste Char: C
Waste Code: 112
Sum Received Qty: 200.0
Waste Class Name: ACID WASTE - HEAVY METALS
Count Manifests: 1
District: 306

2020 Generator Manifest

ID: 19913
Generator No: ON1294801
Receiver Type: 035
Waste Char: I
Waste Code: 263
Sum Received Qty: 5.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 1
District: 306

2021 Generator Info

Gen No: ON1294801
ID: 5896
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 327120
NAICS Code2:
NAICS Code3:
Gen Name: BRAMPTON BRICK LIMITED
Gen Div:
Gen Op Name: BRAMPTON BRICK LIMITED
Gen Op Div:
Site Adrs1: 225 WANLESS DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1E9
Site Country: Canada
Co Official: Lauren Mulkerns
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Official: (905) 840-1011 Ext.3303
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305

2021 Generator Manifest

ID: 20281
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 145
Sum Received Qty: 72064.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 6
District: 301

2021 Generator Manifest

ID: 20283
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 145
Sum Received Qty: 53747.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 2
District: 305

2021 Generator Manifest

ID: 20280
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 146

Sum Received Qty: 29986.0
Waste Class Name: OTHER SPECIFIED INORGANICS
Count Manifests: 2
District: 203

2021 Generator Manifest

ID: 20282
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 146

Sum Received Qty: 31900.0
Waste Class Name: OTHER SPECIFIED INORGANICS
Count Manifests: 4
District: 301

2021 Generator Manifest

ID: 20285
Generator No: ON1294801
Receiver Type: 035
Waste Char: C
Waste Code: 148

Sum Received Qty: 140.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 3
District: 306

2021 Generator Manifest

ID: 20290
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 252

Sum Received Qty: 2200.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 2
District: 306

2021 Generator Manifest

ID: 20278
Generator No: ON1294801
Receiver Type: 030
Waste Char: L
Waste Code: 145

Sum Received Qty: 11470.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 201

2021 Generator Manifest

ID: 20279
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 251

Sum Received Qty: 1000.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 202

2021 Generator Manifest

ID: 20289
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 251

Sum Received Qty: 3140.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 3
District: 306

2021 Generator Manifest

ID: 20284
Generator No: ON1294801
Receiver Type: 035

Sum Received Qty: 212400.0
Waste Class Name: OTHER SPECIFIED INORGANICS
Count Manifests: 51

Waste Char: L
Waste Code: 146
District: 305

2021 Generator Manifest

ID: 20286
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 20.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 306

2021 Generator Manifest

ID: 20287
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 213
Sum Received Qty: 40.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 1
District: 306

2021 Generator Manifest

ID: 20288
Generator No: ON1294801
Receiver Type: 035
Waste Char: L
Waste Code: 221
Sum Received Qty: 615.0
Waste Class Name: LIGHT FUELS
Count Manifests: 1
District: 306

2021 Generator Manifest

ID: 20291
Generator No: ON1294801
Receiver Type: 035
Waste Char: I
Waste Code: 331
Sum Received Qty: 200.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 2
District: 306

---

16 | ***60 of 62*** | ***W/196.0*** | ***248.8 / 6.87*** | ***Brampton Brick Limited*** ***225 Wanless Dr*** ***Brampton ON L7A 1E9*** | ***SPL***

Ref No: 1587-BU5QXQ
Year:
Incident Dt: 10/6/2020
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/6/2020
Dt Document Closed:
Site No: 3162-4E5QZD
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: 225 Wanless Drive
Site Address: 225 Wanless Dr
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Entity Operating Name:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Client Name:	Brampton Brick Limited
Client Type:	Corporation
Source Type:	Discharge Point (Stack/Pipe) - Manufacturing
Incident Cause:	
Incident Preceding Spill:	Process Upset/Malfunction
Incident Reason:	Unknown / N/A
Incident Summary:	Brampton Brick; limstone particulates to atm
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	7 ton (Imperial)
Contaminant Qty 1:	7
Contaminant Unit:	ton (Imperial)
Contaminant Code:	99
Contaminant Name:	LIMESTONE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Air
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

16	61 of 62	W/196.0	248.8 / 6.87	BRAMPTON BRICK 225 WANLESS DRIVE BRAMPTON ON L7A1E9	NPR2

NPRI ID:	7302	**Latitude:**	43.7211
Facility ID:	245880;280312;344284;373388;402354;436691;449072;453668	**Longitude:**	-79.8164
Facility Name:	BRAMPTON BRICK		
Note:	Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0. For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report: https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=7302		

NPRI ID Substances Summary

CAS No:	NA - M09	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	PM10 - Particulate Matter <= 10 Micrometers		
Name French:	PM10 - Matière particulaire <= 10 micromètres		
Sort English:	PM10 - Particulate Matter <= 10 Micrometers		
Sort French:	PM10 - Matière particulaire <= 10 micromètres		

CAS No:	7664-39-3	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Hydrogen fluoride		
Name French:	Fluorure d'hydrogène		
Sort English:	Hydrogen fluoride		

Sort French: Fluorure d'hydrogène

CAS No: NA - M10 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: PM2.5 - Particulate Matter <= 2.5 Micrometers
Name French: PM2,5 - Matière particulaire <= 2,5 micromètres
Sort English: PM2.5 - Particulate Matter <= 2.5 Micrometers
Sort French: PM2,5 - Matière particulaire <= 2,5 micromètres

CAS No: NA - M08 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Total particulate matter
Name French: Matière particulaire totale
Sort English: PM - Total Particulate Matter
Sort French: PM - Particules totales

CAS No: 7446-09-5 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Sulphur dioxide
Name French: Dioxyde de soufre
Sort English: Sulphur dioxide
Sort French: Dioxyde de soufre

CAS No: NA - M16 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: Volatile Organic Compounds (VOCs)
Name French: Composés organiques volatils (COV)
Sort English: Volatile Organic Compounds (VOCs)
Sort French: Composés organiques volatils (COV)

CAS No: 630-08-0 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Carbon monoxide
Name French: Monoxyde de carbone
Sort English: Carbon monoxide
Sort French: Oxyde de carbone (monoxyde de carbone)

CAS No: 11104-93-1 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Nitrogen oxides (expressed as nitrogen dioxide)
Name French: Oxydes d'azote (exprimés en dioxyde d'azote)
Sort English: Nitrogen oxides (expressed as nitrogen dioxide)
Sort French: Oxydes d'azote (exprimés en dioxyde d'azote)

CAS No: 7647-01-0 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Hydrochloric acid
Name French: Acide chlorhydrique
Sort English: Hydrochloric acid
Sort French: Acide chlorhydrique

Geographic Location

Report Year: -1 **Forward Sort Area:** L7A
Census Subdiv ID: 3521010 **DLS Description:**
Ecozone ID: 8 **NTS Description:** D-066-K/030-M-12
Water Survey ID: 2 **Province Code:** ON
SOMA: TRUE **Datum:** 1983.0

ON PEMA:	TRUE	**Latitude:**	43.7211
QC PEMA:	FALSE	**Longitude:**	-79.8164
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	7302
Facility ID:	449072

Facility

Facility ID:	449072	**IDM ID:**	9988
Portable:	FALSE	**AB Approval ID:**	
NAICS Primary:	327120	**GHGRP ID:**	
NAICS Secondary:		**ON GHGRP ID:**	
NAICS Tertiary:			
Facility Name:	Brampton Brick Limited		
Website:			

Address

Address1:	225 Wanless Drive
Address2:	
City:	Brampton
Postal Zip:	L7A 1E9
Prov:	

Address Geographic

Latitude:	43.721100	**Datum:**	
Longitude:	-79.816400	**Land Survey:**	
UTM Easting:	0.000000	**Topograph:**	
UTM Northing:	0.000000	**Additional Info:**	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	327120	**Start Date:**	2007
Record Year:	2007	**End Date:**	2011
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	**Start Date:**	2017
Record Year:	2017	**End Date:**	2021
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		

NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code: 327120 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay Building Material and Refractory Manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code: 327120 ***Start Date:*** 2022
Record Year: 2022 ***End Date:*** 2026
Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay building material and refractory manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code: 327120 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay building material and refractory manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NPRI ID Facility ID

NPRI ID:	7302
Facility ID:	245880

Facility

Facility ID:	245880	***IDM ID:***	9988
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	327330	***GHGRP ID:***	G10664
NAICS Secondary:	0	***ON GHGRP ID:***	1011
NAICS Tertiary:	0		
Facility Name:	Brampton Brick		
Website:	www.bramptonbrick.com		

Address

Address1:	225 Wanless Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1E9
Prov:	

Address Geographic

Latitude:	43.7211	***Datum:***	1983
Longitude:	-79.8164	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	327330	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete pipe, brick and block manufacturing		

NAICS Title Fr: Fabrication de tuyaux, briques et blocs en béton

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete pipe, brick and block manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete pipe, brick and block manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NPRI Report

Report ID:	48213	***No of Employees:***	44
Report Year:	2012	***Is Compressor:***	
Company ID:	111480	***Is NPRI Part 4:***	
SWR Report ID:	69784	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2016-05-26 00:00:00.0000000

Company

Company Name:	Brampton Brick Ltd.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.bramptonbrick.com

NPRI Report Comment

Description En:	NPRI report update comment
Description Fr:	Commentaire sur la mise à jour du rapport de l'INRP

Comment: Hydrogen Chloride created was incorrectly entered (corresponding amount of Hydrogen Chloride created in the previous year was incorrectly entered as well). Both are fixed here.

Note:

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental / Quality Analyst		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:	Stantec Consulting Limited		
Description En:			
Description Fr:			
Position:	Project Manager		
Language:	1		
Email:	boris.chen@stantec.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Technical Director		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report

Report ID:	53572	***No of Employees:***	45
Report Year:	2011	***Is Compressor:***	
Company ID:	111482	***Is NPRI Part 4:***	
SWR Report ID:	2838	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2012-06-25 00:00:00.0000000

Company

Company Name: Brampton Brick Ltd.
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website: www.bramptonbrick.com

NPRI Report Contact

Contact Type:
First Name: Boris
Last Name: Chen
Company Name: Stantec Consulting Limited
Description En:
Description Fr:
Position: Air Quality Scientist
Language: 1
Email: boris.chen@stantec.com
Phone: 9054156351
Extension:
Fax: 9054749889

NPRI Report Contact

Contact Type:
First Name: Brad
Last Name: Cobbledick
Company Name:
Description En:
Description Fr:
Position: Vice President Technical Services
Language: 1
Email: bcobbledick@bramptonbrick.com
Phone: 9058401011
Extension:
Fax: 9058406126

NPRI Report Contact

Contact Type:
First Name: Brad
Last Name: Cobbledick
Company Name:
Description En:
Description Fr:
Position: Technical Director
Language: 1
Email: bcobbledick@bramptonbrick.com
Phone: 9058401011
Extension:
Fax: 9058406126

NPRI Report Contact

Contact Type:
First Name: Brad
Last Name: Cobbledick
Company Name:
Description En:
Description Fr:
Position: Technical Director
Language: 1
Email: bcobbledick@bramptonbrick.com
Phone: 9058401011
Extension:
Fax: 9058406126

NPRI Report

Report ID: 114428
Report Year: 2010
Company ID: 111480
SWR Report ID: 20100000007302
No of Employees: 59
Is Compressor:
Is NPRI Part 4:
Is Battery:

Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	TRUE	***Submit Date:***	2011-06-09 00:00:00.0000000

Company

Company Name:	Brampton Brick Ltd.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.bramptonbrick.com

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:			
Language:	0		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:			
Language:	0		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:			
Description En:			
Description Fr:			
Position:	Air Quality Scientist		
Language:	0		
Email:	boris.chen@stantec.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:			
Language:	0		
Email:	bcobbledick@bramptonbrick.com		

NPRI ID Facility ID

NPRI ID: 7302
Facility ID: 436691

Facility

Facility ID:	436691	***IDM ID:***	9988
Portable:	FALSE	***AB Approval ID:***	
NAICS Primary:	327120	***GHGRP ID:***	
NAICS Secondary:	0	***ON GHGRP ID:***	
NAICS Tertiary:	0		

Facility Name: Brampton Brick Limited
Website:

Address

Address1:
Address2:
City: Brampton
Postal Zip: L7A 1E9
Prov:

Address Geographic

Latitude:	43.721100	***Datum:***	
Longitude:	-79.816400	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	327120	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021

Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay building material and refractory manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code:	327120	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006

Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay Building Material and Refractory Manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code:	327120	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		

Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En:	Clay Building Material and Refractory Manufacturing
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NPRI Report

Report ID:	331414	***No of Employees:***	50
Report Year:	2021	***Is Compressor:***	
Company ID:	175672	***Is NPRI Part 4:***	
SWR Report ID:	22468	***Is Battery:***	
Repor Type ID:	8	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2022-06-01 10:35:14.0539805

Company

Company Name:	Brampton Brick Limited
DUNS No:	
Trade Name En:	
Trade Name Fr:	
Website:	www.bramptonbrick.com

NPRI Report Contact

Contact Type:		***Phone:***	905-840-1011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Manager		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-840-1011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Manager		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-840-1011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	

Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: EHS Manager
Language: 1
Email: lmulkerns@bramptonbrick.com

NPRI Report Contact

Contact Type:
First Name: Lauren
Last Name: Mulkerns
Company Name:
Description En:
Description Fr:
Position: EHS Manager
Language: 1
Email: lmulkerns@bramptonbrick.com
Phone: 905-840-1011
Extension:
Fax:

NPRI ID Facility ID

NPRI ID: 7302
Facility ID: 344284

Facility

Facility ID: 344284
Portable: FALSE
NAICS Primary: 327330
NAICS Secondary: 0
NAICS Tertiary: 0
Facility Name: BRAMPTON BRICK
Website:
IDM ID: 0
AB Approval ID: 0
GHGRP ID: 0
ON GHGRP ID: 0

Address

Address1: 225 Wanless Drive
Address2:
City: BRAMPTON
Postal Zip: L7A1E9
Prov:

Address Geographic

Latitude: 43.7211
Longitude: -79.8164
UTM Easting: 0.000000
UTM Northing: 0.000000
UTM Zone: 0
Datum: 1983
Land Survey:
Topograph:
Additional Info:

Primary NAICS Details

NAICS Code: 327330
Record Year: 2022
Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Concrete pipe, brick and block manufacturing
NAICS Title Fr: Fabrication de tuyaux, briques et blocs en béton
Start Date: 2022
End Date: 2026

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete pipe, brick and block manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete pipe, brick and block manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	**Start Date:**	2002
Record Year:	2002	**End Date:**	2006
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NPRI Report

Report ID:	110160	**No of Employees:**	59
Report Year:	2009	**Is Compressor:**	
Company ID:	129957	**Is NPRI Part 4:**	
SWR Report ID:	20090000007302	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2010-05-19 00:00:00.0000000

Company

Company Name:	BRAMPTON BRICK
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9058401011
First Name:	Brad	**Extension:**	
Last Name:	Cobbledick	**Fax:**	9058406126
Company Name:			
Description En:			
Description Fr:			

Position: Technical Director
Language: 0
Email: bcobbledick@bramptonbrick.com

NPRI Report Contact

Contact Type: | ***Phone:*** 9054156351
First Name: Boris | ***Extension:***
Last Name: Chen | ***Fax:*** 9054749889
Company Name:
Description En:
Description Fr:
Position: Air Quality Scientist
Language: 0
Email: boris.chen@stantec.com

NPRI Report Contact

Contact Type: NPRI | ***Phone:*** 9058401011
First Name: Brad | ***Extension:***
Last Name: Cobbledick | ***Fax:*** 9058406126
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Technical Director
Language: 0
Email: bcobbledick@bramptonbrick.com

NPRI Report Contact

Contact Type: | ***Phone:*** 9058401011
First Name: Brad | ***Extension:***
Last Name: Cobbledick | ***Fax:*** 9058406126
Company Name:
Description En:
Description Fr:
Position: Technical Director
Language: 0
Email: bcobbledick@bramptonbrick.com

NPRI Report

Report ID: 114734 | ***No of Employees:*** 59
Report Year: 2008 | ***Is Compressor:***
Company ID: 129957 | ***Is NPRI Part 4:***
SWR Report ID: 20080000007302 | ***Is Battery:***
Repor Type ID: 1 | ***Corres Lang ID:*** 0
New Reporter: FALSE | ***Submit Date:*** 2009-05-25 00:00:00.0000000

Company

Company Name: BRAMPTON BRICK
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type: | ***Phone:*** 9058401011
First Name: Brad | ***Extension:***

Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Technical Director		
Language:	0		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Technical Director		
Language:	0		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Technical Director		
Language:	0		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054747700
First Name:	Gregory	***Extension:***	251
Last Name:	Crooks	***Fax:***	9054799326
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Air Quality Engineer, Jacques Whitford Limited		
Language:	0		
Email:	gcrooks@jacqueswhitford.com		

NPRI Report

Report ID:	153686	***No of Employees:***	50
Report Year:	2007	***Is Compressor:***	
Company ID:	129957	***Is NPRI Part 4:***	
SWR Report ID:	20070000007302	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2008-08-05 00:00:00.0000000

Company

Company Name:	BRAMPTON BRICK
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	Report Submission and Electronic Certification Comment
Description Fr:	Soumission de déclaration et attestation électronique
Comment:	David Brown, corporate engineer of Brampton Brick Limited reviewed the NPRI report for 2007 and approved Jacques Whitford in an email dated August 05, 2008 to proceed with submission of the report via OWNERS.
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	David	***Extension:***	
Last Name:	Brown	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Property Manager		
Language:	0		
Email:	DBrown@BramptonBrick.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058401011
First Name:	David	***Extension:***	
Last Name:	Brown	***Fax:***	9058406126
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Property Manager		
Language:	0		
Email:	DBrown@BramptonBrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	David	***Extension:***	
Last Name:	Brown	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Property Manager		
Language:	0		
Email:	DBrown@BramptonBrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054747700
First Name:	Gregory	***Extension:***	251
Last Name:	Crooks	***Fax:***	9054799326
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Air Quality Engineer, Jacques Whitford Limited		
Language:	0		
Email:	gcrooks@jacqueswhitford.com		

NPRI Report

Report ID:	154827	***No of Employees:***	50
Report Year:	2006	***Is Compressor:***	
Company ID:	129957	***Is NPRI Part 4:***	
SWR Report ID:	20060000007302	***Is Battery:***	

Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2007-06-13 00:00:00.0000000

Company

Company Name:	BRAMPTON BRICK
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	Report Submission and Electronic Certification Comment
Description Fr:	Soumission de déclaration et attestation électronique
Comment:	I, David Brown, have read and agree with the report as atached, using my consultant's logon password.
Note:	

NPRI Report Contact

Contact Type:		**Phone:**	9058401011
First Name:	David	**Extension:**	
Last Name:	Brown	**Fax:**	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Property Manager		
Language:	0		
Email:	DBrown@BramptonBrick.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058401011
First Name:	David	**Extension:**	
Last Name:	Brown	**Fax:**	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Property Manager		
Language:	0		
Email:	DBrown@BramptonBrick.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058401011
First Name:	David	**Extension:**	
Last Name:	Brown	**Fax:**	9058406126
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Property Manager		
Language:	0		
Email:	DBrown@BramptonBrick.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054747700
First Name:	Gregory	**Extension:**	251
Last Name:	Crooks	**Fax:**	9054799326
Company Name:			
Description En:			

Description Fr:
Position: Senior Air Quality Engineer, Jacques Whitford Limited
Language: 0
Email: gcrooks@jacqueswhitford.com

NPRI Report

Report ID: 255483
Report Year: 2005
Company ID: 129957
SWR Report ID: 20050000007302
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 50
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 2006-05-30 00:00:00.0000000

Company

Company Name: BRAMPTON BRICK
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Yvonne
Last Name: Chiu
Company Name:
Description En:
Description Fr:
Position: Environmental Scientist, Jacques Whitford Limited
Language: 0
Email: yvonne.chiu@jacqueswhitford.com
Phone: 9054747700
Extension: 286
Fax: 9054799326

NPRI Report Contact

Contact Type:
First Name: David
Last Name: Brown
Company Name:
Description En:
Description Fr:
Position: Property Manager
Language: 0
Email: DBrown@BramptonBrick.com
Phone: 9058401011
Extension: 0
Fax: 9058406126

NPRI Report Contact

Contact Type: NPRI
First Name: David
Last Name: Brown
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Property Manager
Language: 0
Email: DBrown@BramptonBrick.com
Phone: 9058401011
Extension: 0
Fax: 9058406126

NPRI Report Contact

Contact Type:
Phone: 9054747700

First Name:	Gregory	**Extension:**	251
Last Name:	Crooks	**Fax:**	9054799326
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Air Quality Engineer, Jacques Whitford Limited		
Language:	0		
Email:	gcrooks@jacqueswhitford.com		

NPRI Report

Report ID:	263756	**No of Employees:**	50
Report Year:	2004	**Is Compressor:**	
Company ID:	129957	**Is NPRI Part 4:**	
SWR Report ID:	20040000007302	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2005-06-28 00:00:00.0000000

Company

Company Name:	BRAMPTON BRICK
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9058401011
First Name:	David	**Extension:**	0
Last Name:	Brown	**Fax:**	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Property Manager		
Language:	0		
Email:	DBrown@BramptonBrick.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054747700
First Name:	Gregory	**Extension:**	251
Last Name:	Crooks	**Fax:**	9054799326
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Air Quality Engineer, Jacques Whitford Limited		
Language:	0		
Email:	gcrooks@jacqueswhitford.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054747700
First Name:	Yvonne	**Extension:**	286
Last Name:	Chiu	**Fax:**	9054799326
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Scientist, Jacques Whitford Limited		
Language:	0		
Email:	yvonne.chiu@jacqueswhitford.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058401011
First Name:	David	***Extension:***	0
Last Name:	Brown	***Fax:***	9058406126
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Property Manager		
Language:	0		
Email:	DBrown@BramptonBrick.com		

NPRI Report

Report ID:	172638	***No of Employees:***	50
Report Year:	2003	***Is Compressor:***	
Company ID:	138805	***Is NPRI Part 4:***	
SWR Report ID:	20030000007302	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2004-06-01 00:00:00.0000000

Company

Company Name:	BRAMPTON BRICK LTD.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9055682929
First Name:	Steve	***Extension:***	4357
Last Name:	Mercer	***Fax:***	9055681686
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Engineer, EIT		
Language:	0		
Email:	steve.mercer@amec.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	David	***Extension:***	0
Last Name:	Brown	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Property Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058401011
First Name:	David	***Extension:***	0
Last Name:	Brown	***Fax:***	9058406126
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		

Position: Property Manager
Language: 0
Email:

NPRI Report Contact

Contact Type:		***Phone:***	9055682929
First Name:	Steve	***Extension:***	4357
Last Name:	Mercer	***Fax:***	9055681686
Company Name:			
Description En:			
Description Fr:			

Position: Environmental Engineer, EIT
Language: 0
Email: steve.mercer@amec.com

NPRI ID Facility ID

NPRI ID: 7302
Facility ID: 402354

Facility

Facility ID:	402354	***IDM ID:***	9988
Portable:	FALSE	***AB Approval ID:***	
NAICS Primary:	327120	***GHGRP ID:***	
NAICS Secondary:	0	***ON GHGRP ID:***	
NAICS Tertiary:	0		

Facility Name: Brampton Brick Limited
Website:

Address

Address1: 225 Wanless Drive
Address2:
City: BRAMPTON
Postal Zip: L7A 1E9
Prov:

Address Geographic

Latitude:	43.7211	***Datum:***	
Longitude:	-79.8164	***Land Survey:***	
UTM Easting:	595432.000000	***Topograph:***	
UTM Northing:	4841484.000000	***Additional Info:***	
UTM Zone:	17		

Primary NAICS Details

NAICS Code:	327120	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001

Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay Building Material and Refractory Manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code:	327120	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026

Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En:	Clay building material and refractory manufacturing
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code:	327120	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NPRI Report

Report ID:	322871	***No of Employees:***	50
Report Year:	2020	***Is Compressor:***	
Company ID:	161484	***Is NPRI Part 4:***	
SWR Report ID:	170173	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	
New Reporter:	FALSE	***Submit Date:***	2022-02-21 13:55:45.3766667

Company

Company Name:	Brampton Brick Limited
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	NPRI report update comment
Description Fr:	Commentaire sur la mise à jour du rapport de l'INRP
Comment:	Requested to provide additional explanation for total particulate material.
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	9058401011

First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Manager		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Manager		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Manager		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Manager		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Manager		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	

Company Name:
Description En:
Description Fr:
Position: EHS Manager
Language: 0
Email: lmulkerns@bramptonbrick.com

NPRI Report

Report ID:	308031	***No of Employees:***	50
Report Year:	2019	***Is Compressor:***	
Company ID:	161484	***Is NPRI Part 4:***	
SWR Report ID:	157093	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2020-07-16 10:26:20.7500000

Company

Company Name: Brampton Brick Limited
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Kaarthika	***Extension:***	3309
Last Name:	Sriskantha	***Fax:***	

Company Name:
Description En:
Description Fr:
Position: EHS Supervisor
Language: 1
Email: ksriskantha@bramptonbrick.com

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126

Company Name:
Description En:
Description Fr:
Position: Vice President of Technical Services
Language: 1
Email: bcobbledick@bramptonbrick.com

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Kaarthika	***Extension:***	3309
Last Name:	Sriskantha	***Fax:***	

Company Name:
Description En:
Description Fr:
Position: EHS Supervisor
Language: 1
Email: ksriskantha@bramptonbrick.com

NPRI Report Contact

Contact Type:		**Phone:**	9058401011
First Name:	Brad	**Extension:**	
Last Name:	Cobbledick	**Fax:**	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President of Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058401011
First Name:	Kaarthika	**Extension:**	3309
Last Name:	Sriskantha	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Supervisor		
Language:	1		
Email:	ksriskantha@bramptonbrick.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058401011
First Name:	Kaarthika	**Extension:**	3309
Last Name:	Sriskantha	**Fax:**	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	EHS Supervisor		
Language:	1		
Email:	ksriskantha@bramptonbrick.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058401011
First Name:	Kaarthika	**Extension:**	3309
Last Name:	Sriskantha	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	EHS Supervisor		
Language:	1		
Email:	ksriskantha@bramptonbrick.com		

NPRI ID Facility ID

NPRI ID:	7302
Facility ID:	280312

Facility

Facility ID:	280312	**IDM ID:**	9988
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	327120	**GHGRP ID:**	G10664
NAICS Secondary:	0	**ON GHGRP ID:**	1011
NAICS Tertiary:	0		
Facility Name:	Brampton Brick		
Website:	www.bramptonbrick.com		

Address

Address1: 225 Wanless Drive
Address2:
City: BRAMPTON
Postal Zip: L7A1E9
Prov:

Address Geographic

Latitude: 43.7211
Longitude: -79.8164
UTM Easting: 0.000000
UTM Northing: 0.000000
UTM Zone: 0
Datum: 1983
Land Survey:
Topograph:
Additional Info:

Primary NAICS Details

NAICS Code: 327120
Record Year: 2012
Start Date: 2012
End Date: 2016
Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay building material and refractory manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code: 327120
Record Year: 1997
Start Date: 1993
End Date: 2001
Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay Building Material and Refractory Manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code: 327120
Record Year: 2007
Start Date: 2007
End Date: 2011
Key Indus Sector En: Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr: Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En: Clay Building Material and Refractory Manufacturing
NAICS Title Fr: Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code:	327120	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NPRI Report

Report ID:	89861	***No of Employees:***	48
Report Year:	2018	***Is Compressor:***	
Company ID:	111482	***Is NPRI Part 4:***	
SWR Report ID:	147232	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2019-05-17 09:33:57.8400000

Company

Company Name:	Brampton Brick Ltd.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.bramptonbrick.com

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Manager		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:	Stantec Consulting Ltd.		
Description En:			
Description Fr:			
Position:	Project Manager		
Language:	1		
Email:	boris.chen@stantec.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:	Stantec Consulting Ltd.		

Description En:
Description Fr:
Position: Project Manager
Language: 1
Email: boris.chen@stantec.com

NPRI Report Contact

Contact Type: ***Phone:*** 9058401011
First Name: Lauren ***Extension:***
Last Name: Mulkerns ***Fax:*** 9058406126
Company Name:
Description En:
Description Fr:
Position: Environmental / Quality Analyst
Language: 1
Email: lmulkerns@bramptonbrick.com

NPRI Report Contact

Contact Type: ***Phone:*** 9054156351
First Name: Boris ***Extension:***
Last Name: Chen ***Fax:*** 9054749889
Company Name: Stantec Consulting Ltd.
Description En:
Description Fr:
Position: Project Manager
Language: 1
Email: boris.chen@stantec.com

NPRI Report Contact

Contact Type: ***Phone:*** 9058401011
First Name: Brad ***Extension:***
Last Name: Cobbledick ***Fax:*** 9058406126
Company Name:
Description En:
Description Fr:
Position: Vice President of Technical Services
Language: 1
Email: bcobbledick@bramptonbrick.com

NPRI Report Contact

Contact Type: NPRI ***Phone:*** 9058401011
First Name: Lauren ***Extension:***
Last Name: Mulkerns ***Fax:***
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Environmental Manager
Language: 1
Email: lmulkerns@bramptonbrick.com

NPRI Report

Report ID: 89859 ***No of Employees:*** 48
Report Year: 2017 ***Is Compressor:***
Company ID: 111482 ***Is NPRI Part 4:***
SWR Report ID: 96677 ***Is Battery:***
Repor Type ID: 1 ***Corres Lang ID:*** 1
New Reporter: FALSE ***Submit Date:*** 2018-05-30 15:19:35.5700000

Company

Company Name: Brampton Brick Ltd.
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website: www.bramptonbrick.com

NPRI Report Contact

Contact Type:
First Name: Boris
Last Name: Chen
Company Name: Stantec Consulting Ltd.
Description En:
Description Fr:
Position: Project Manager
Language: 1
Email: boris.chen@stantec.com
Phone: 9054156351
Extension:
Fax: 9054749889

NPRI Report Contact

Contact Type:
First Name: Boris
Last Name: Chen
Company Name: Stantec Consulting Ltd.
Description En:
Description Fr:
Position: Project Manager
Language: 1
Email: boris.chen@stantec.com
Phone: 9054156351
Extension:
Fax: 9054749889

NPRI Report Contact

Contact Type:
First Name: Boris
Last Name: Chen
Company Name: Stantec Consulting Ltd.
Description En:
Description Fr:
Position: Project Manager
Language: 1
Email: boris.chen@stantec.com
Phone: 9054156351
Extension:
Fax: 9054749889

NPRI Report Contact

Contact Type:
First Name: Brad
Last Name: Cobbledick
Company Name:
Description En:
Description Fr:
Position: Vice President Technical Services
Language: 1
Email: bcobbledick@bramptonbrick.com
Phone: 9058401011
Extension:
Fax: 9058406126

NPRI Report Contact

Contact Type:
First Name: Brad
Phone: 9058401011
Extension:

Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President of Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Kaarthika	***Extension:***	
Last Name:	Sriskantha	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental/Quality Analyst		
Language:	1		
Email:	ksriskantha@bramptonbrick.com		

NPRI Report

Report ID:	89860	***No of Employees:***	48
Report Year:	2016	***Is Compressor:***	
Company ID:	111482	***Is NPRI Part 4:***	
SWR Report ID:	82718	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2017-05-30 08:53:07.2533333

Company

Company Name:	Brampton Brick Ltd.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.bramptonbrick.com

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:	Stantec Consulting Ltd.		
Description En:			
Description Fr:			
Position:	Project Manager		
Language:	1		
Email:	boris.chen@stantec.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President of Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:	Stantec Consulting Ltd.		
Description En:			
Description Fr:			
Position:	Project Manager		
Language:	1		
Email:	boris.chen@stantec.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Kaarthika	***Extension:***	
Last Name:	Sriskantha	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental/Quality Analyst		
Language:	1		
Email:	ksriskantha@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:	Stantec Consulting Ltd.		
Description En:			
Description Fr:			
Position:	Project Manager		
Language:	1		
Email:	boris.chen@stantec.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report

Report ID:	16392	***No of Employees:***	48
Report Year:	2015	***Is Compressor:***	
Company ID:	111481	***Is NPRI Part 4:***	
SWR Report ID:	69412	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2016-05-25 00:00:00.0000000

Company

Company Name:	Brampton Brick Limited
DUNS No:	0
Trade Name En:	

Trade Name Fr:
Website: www.bramptonbrick.com

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Kaarthika	***Extension:***	
Last Name:	Sriskantha	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental/Quality Analyst		
Language:	1		
Email:	ksriskantha@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President of Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:	Stantec Consulting Limited		
Description En:			
Description Fr:			
Position:	Project Manager		
Language:	1		
Email:	boris.chen@stantec.com		

NPRI Report

Report ID:	29596	***No of Employees:***	45
Report Year:	2014	***Is Compressor:***	
Company ID:	111481	***Is NPRI Part 4:***	
SWR Report ID:	69791	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2016-05-26 00:00:00.0000000

Company

Company Name: Brampton Brick Limited
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website: www.bramptonbrick.com

NPRI Report Comment

Description En: NPRI report update comment
Description Fr: Commentaire sur la mise à jour du rapport de l'INRP
Comment: Hydrogen Chloride created was incorrectly entered (corresponding amount of Hydrogen Chloride created in the previous year was incorrectly entered as well). Both are fixed here.
Note:

NPRI Report Contact

Contact Type:
First Name: Boris
Last Name: Chen
Company Name: Stantec Consulting Limited
Description En:
Description Fr:
Position: Project Manager
Language: 1
Email: boris.chen@stantec.com
Phone: 9054156351
Extension:
Fax: 9054749889

NPRI Report Contact

Contact Type:
First Name: Brad
Last Name: Cobbledick
Company Name:
Description En:
Description Fr:
Position: Vice President Technical Services
Language: 1
Email: bcobbledick@bramptonbrick.com
Phone: 9058401011
Extension:
Fax: 9058406126

NPRI Report Contact

Contact Type:
First Name: Lauren
Last Name: Mulkerns
Company Name:
Description En:
Description Fr:
Position: Environmental / Quality Supervisor
Language: 1
Email: lmulkerns@bramptonbrick.com
Phone: 9058401011
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Brad
Last Name: Cobbledick
Company Name:
Description En:
Description Fr:
Position: Vice President Technical Services
Language: 1
Email: bcobbledick@bramptonbrick.com
Phone: 9058401011
Extension:
Fax: 9058406126

NPRI Report

Report ID:	39225	***No of Employees:***	45
Report Year:	2013	***Is Compressor:***	
Company ID:	111481	***Is NPRI Part 4:***	
SWR Report ID:	69788	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2016-05-26 00:00:00.0000000

Company

Company Name:	Brampton Brick Limited
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.bramptonbrick.com

NPRI Report Comment

Description En:	NPRI report update comment
Description Fr:	Commentaire sur la mise à jour du rapport de l'INRP
Comment:	Hydrogen Chloride created was incorrectly entered (corresponding amount of Hydrogen Chloride created in the previous year was incorrectly entered as well). Both are fixed here.
Note:	

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	Also report under O. Reg 455 (GHG Reporting)
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	Lauren	***Extension:***	
Last Name:	Mulkerns	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental / Quality Analyst		
Language:	1		
Email:	lmulkerns@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058401011

First Name:	Brad	***Extension:***	
Last Name:	Cobbledick	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President Technical Services		
Language:	1		
Email:	bcobbledick@bramptonbrick.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054156351
First Name:	Boris	***Extension:***	
Last Name:	Chen	***Fax:***	9054749889
Company Name:	Stantec Consulting Limited		
Description En:			
Description Fr:			
Position:	Project Manager		
Language:	1		
Email:	boris.chen@stantec.com		

NPRI ID Facility ID

NPRI ID:	7302
Facility ID:	373388

Facility

Facility ID:	373388	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	327330	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	BRAMPTON BRICK		
Website:			

Address

Address1:	225 Wanless Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1E9
Prov:	

Primary NAICS Details

NAICS Code:	327330	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete pipe, brick and block manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange

de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete pipe, brick and block manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete pipe, brick and block manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipes, bricks and blocks from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NAICS Code:	327330	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Concrete Pipe, Brick and Block Manufacturing		
NAICS Title Fr:	Fabrication de tuyaux, briques et blocs en béton		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing concrete pipe, brick and block from a mixture of cement, water and aggregate.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à fabriquer tuyaux, briques et blocs en béton avec un mélange de ciment, d'eau et d'agrégats.

NPRI Report

Report ID:	277681	***No of Employees:***	50
Report Year:	2002	***Is Compressor:***	
Company ID:	136400	***Is NPRI Part 4:***	
SWR Report ID:	20020000007302	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2003-06-02 00:00:00.0000000

Company

Company Name:	BRAMPTON BRICK LTD.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058401011
First Name:	David	***Extension:***	0
Last Name:	Brown	***Fax:***	9058406126
Company Name:			
Description En:			
Description Fr:			
Position:	Property Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9055682929
First Name:	Steve	***Extension:***	4357
Last Name:	Mercer	***Fax:***	9055681686
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Engineer, EIT		
Language:	0		
Email:	steve.mercer@amec.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058401011
First Name:	David	***Extension:***	0
Last Name:	Brown	***Fax:***	9058406126
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Property Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9055682929
First Name:	Steve	***Extension:***	4357
Last Name:	Mercer	***Fax:***	9055681686
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Engineer, EIT		
Language:	0		
Email:	steve.mercer@amec.com		

NPRI ID Facility ID

NPRI ID:	7302
Facility ID:	453668

Facility

Facility ID:	453668	***IDM ID:***	9988
Portable:	FALSE	***AB Approval ID:***	
NAICS Primary:	327120	***GHGRP ID:***	
NAICS Secondary:		***ON GHGRP ID:***	
NAICS Tertiary:			
Facility Name:	Brampton Brick Limited		
Website:			

Address

Address1:	225 Wanless Drive
Address2:	
City:	Brampton
Postal Zip:	L7A 1E9
Prov:	

Address Geographic

Latitude:	43.721100	***Datum:***	
Longitude:	-79.816400	***Land Survey:***	

UTM Easting:	0.000000	**Topograph:**	
UTM Northing:	0.000000	**Additional Info:**	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	327120	**Start Date:**	2017
Record Year:	2017	**End Date:**	2021
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code:	327120	**Start Date:**	2002
Record Year:	2002	**End Date:**	2006
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	**Start Date:**	2022
Record Year:	2022	**End Date:**	2026
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay building material and refractory manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires.

NAICS Code:	327120	**Start Date:**	2012
Record Year:	2012	**End Date:**	2016

Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques
NAICS Title En:	Clay building material and refractory manufacturing
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NAICS Code:	327120	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Cement, Lime and Other Non-Metallic Minerals		
Key Indus Sector Fr:	Ciment, chaux et autres produits minéraux non métalliques		
NAICS Title En:	Clay Building Material and Refractory Manufacturing		
NAICS Title Fr:	Fabrication de matériaux de construction en argile et de produits réfractaires		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in shaping, moulding, baking, burning and hardening building materials and refractories. These products may be made of clay or other materials with similar properties.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à façonner, mouler, cuire et durcir des matériaux de construction et des produits réfractaires. Ces produits peuvent avoir été fabriqués à partir d'argile ou de produits possédant des propriétés semblables.

NPRI Report

Report ID:	353649	***No of Employees:***	293
Report Year:	2022	***Is Compressor:***	
Company ID:	181376	***Is NPRI Part 4:***	
SWR Report ID:	36645	***Is Battery:***	
Repor Type ID:	8	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2023-08-11 10:43:32.5720224

Company

Company Name: Brampton Brick Limited
DUNS No:
Trade Name En:
Trade Name Fr:
Website: www.bramptonbrick.com

NPRI Report Comment

Description En: NPRI report update comment
Description Fr: Commentaire sur la mise à jour du rapport de l'INRP
Comment: Hydrogen fluoride emissions recently reported in kilograms. Changed to tonnes.
Note:

NPRI Report Contact

Contact Type: NPRI
First Name: Kyle
Last Name: Halfyard
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Environmental Analyst
Language: 1
Email: khalfyard@bramptonbrick.com
Phone: 416-305-0180
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Kyle
Last Name: Halfyard
Company Name:
Description En:
Description Fr:
Position: Environmental Analyst
Language: 1
Email: khalfyard@bramptonbrick.com
Phone: 416-305-0180
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Kyle
Last Name: Halfyard
Company Name:
Description En:
Description Fr:
Position: Environmental Analyst
Language: 1
Email: khalfyard@bramptonbrick.com
Phone: 416-305-0180
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Kyle
Last Name: Halfyard
Company Name:
Description En:
Description Fr:
Position: Environmental Analyst
Language: 1
Email: khalfyard@bramptonbrick.com
Phone: 416-305-0180
Extension:
Fax:

Alternative Location Info

Facility ID: 344284
Facility Name: BRAMPTON BRICK LIMITED
Address1:
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 373388
Facility Name: BRAMPTON BRICK
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 280312
Facility Name: BRAMPTON BRICK LIMITED
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 402354
Facility Name: BRAMPTON BRICK LIMITED
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 402354
Facility Name: BRAMPTON BRICK LIMITED
Address1:
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 402354
Facility Name: BRAMPTON BRICK
Address1: 225 WANLESS DRIVE
City: BRAMPTON

Postal ZIP: L7A1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 453668
Facility Name: BRAMPTON BRICK
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 436691
Facility Name: BRAMPTON BRICK LIMITED
Address1:
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 245880
Facility Name: BRAMPTON BRICK
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 453668
Facility Name: BRAMPTON BRICK LIMITED
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 373388
Facility Name: BRAMPTON BRICK LIMITED
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 436691
Facility Name: BRAMPTON BRICK LIMITED
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 453668
Facility Name: BRAMPTON BRICK LIMITED
Address1:
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 245880
Facility Name: BRAMPTON BRICK LIMITED
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 280312
Facility Name: BRAMPTON BRICK
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 373388
Facility Name: BRAMPTON BRICK LIMITED
Address1:
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON
Latitude: 43.7211
Longitude: -79.8164

Alternative Location Info

Facility ID: 344284
Facility Name: BRAMPTON BRICK LIMITED
Address1: 225 WANLESS DRIVE
City: BRAMPTON
Postal ZIP: L7A 1E9
Province EN: ON

Latitude:	43.7211
Longitude:	-79.8164

Alternative Location Info

Facility ID:	245880
Facility Name:	BRAMPTON BRICK LIMITED
Address1:	
City:	BRAMPTON
Postal ZIP:	L7A 1E9
Province EN:	ON
Latitude:	43.7211
Longitude:	-79.8164

Alternative Location Info

Facility ID:	436691
Facility Name:	BRAMPTON BRICK
Address1:	225 WANLESS DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1E9
Province EN:	ON
Latitude:	43.7211
Longitude:	-79.8164

Alternative Location Info

Facility ID:	344284
Facility Name:	BRAMPTON BRICK
Address1:	225 WANLESS DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1E9
Province EN:	ON
Latitude:	43.7211
Longitude:	-79.8164

Alternative Location Info

Facility ID:	280312
Facility Name:	BRAMPTON BRICK LIMITED
Address1:	
City:	BRAMPTON
Postal ZIP:	L7A 1E9
Province EN:	ON
Latitude:	43.7211
Longitude:	-79.8164

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
16	62 of 62	W/196.0	248.8 / 6.87	***BRAMPTON BRICK LIMITED/BRIQUE BRAMPTON LIMITEE*** ***225a Wanless Drive*** ***Brampton ON L7A 1E9***	EASR

Approval No:	R-010-5115324224	***MOE District:***	Halton-Peel
Status:	REGISTERED	***Municipality:***	Brampton
Date:	August 11, 2023	***Latitude:***	43.72138889
Record Type:	EASR	***Longitude:***	-79.81638889
Link Source:	MOFA	***Geometry X:***	-8885119.7681000009
Project Type:	Air Emissions	***Geometry Y:***	5422427.219499995
Full Address:			
Approval Type:	EASR-Air Emissions		
SWP Area Name:	Toronto		
PDF NAICS Code:	327390		

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3057692
PDF Site Location: 225a Wanless Drive Brampton ON L7A 1E9

---

17 **1 of 1** **SSW/116.9** **243.7 / 1.78** **120 SANDALWOOD PARKWAY Brampton ON** **WWIS**

Well ID: 7123806
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z098099
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info: WKQ-001326

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 06/08/2009
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7123806.pdf

Additional Detail(s) (Map)

Well Completed Date: 05/25/2009
Year Completed: 2009
Depth (m):
Latitude: 43.7170291365553
Longitude: -79.8123311499259
X: -79.81233100003878
Y: 43.717029134918384
Path: 712\7123806.pdf

Bore Hole Information

Bore Hole ID: 1002449194
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 05/25/2009
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595672.00
North83: 4841130.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002600434
Layer: 1
Plug From: 0.0
Plug To: 20.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1002600440
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1002600431
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002600436
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1002600437
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1002600435
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1002600433
Diameter: 20.31999969482422
Depth From: 0.0
Depth To: 6.0

Hole Depth UOM: ft
Hole Diameter UOM: inch

---

18 | **1 of 1** | **WSW/133.9** | **248.9 / 6.92** | **225 WANLESS DR Brampton ON** | **WWIS**

Well ID:	7390044	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	06/21/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z354776	**Contractor:**	7644
Tag:	A286361	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/739\7390044.pdf

Additional Detail(s) (Map)

Well Completed Date: 05/07/2021
Year Completed: 2021
Depth (m):
Latitude: 43.7202139770679
Longitude: -79.81642710278
X: -79.81642695322601
Y: 43.72021397494137
Path: 739\7390044.pdf

Bore Hole Information

Bore Hole ID:	1008687147	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595337.00
Code OB Desc:		**North83:**	4841479.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/07/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Pipe Information

Pipe ID: 1009764864

Casing No:	0
Comment:	
Alt Name:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009855957
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

---

19 | ***1 of 1*** | ***WSW/129.7*** | ***248.9 / 6.92*** | ***225 WANLESS DR Brampton ON*** | ***WWIS***

Well ID:	7359022	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	05/20/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z332496	**Contractor:**	7241
Tag:	A286361	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1008281667	**Tag No:**	A286361
Depth M:		**Contractor:**	7241
Year Completed:	2020	**Latitude:**	43.7201782260341
Well Completed Dt:	01/14/2020	**Longitude:**	-79.8164526357114
Audit No:	Z332496	**Y:**	43.72017822425479
Path:		**X:**	-79.8164524860364

Bore Hole Information

Bore Hole ID:	1008281667	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17

Code OB:		**East83:**	595335.00
Code OB Desc:		**North83:**	4841475.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/14/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009636073
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	3.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009636072
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.5
Formation End Depth:	3.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009636074
Layer:	4
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	10.0
Formation End Depth:	16.0

Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009636071
Layer: 1
Color: 2
General Color: GREY
Material 1: 27
Material 1 Desc: OTHER
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009638590
Layer: 2
Plug From: 0.5
Plug To: 5.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009638591
Layer: 3
Plug From: 5.0
Plug To: 16.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009638589
Layer: 1
Plug From: 0.0
Plug To: 0.5
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009640875
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1009633076
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1009641771
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	6.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1009642660
Layer:	1
Slot:	10
Screen Top Depth:	6.0
Screen End Depth:	16.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	Inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009643589
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009639988
Diameter:	6.0
Depth From:	0.0
Depth To:	16.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	1 of 1	SW/86.3	243.9 / 1.92	120 SANDLEWOOD PARKWAY BRAMPTON ON	WWIS

Well ID:	7117441	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	0	***Date Received:***	01/09/2009
Water Type:		***Selected Flag:***	TRUE

Casing Material:		**Abandonment Rec:**	
Audit No:	Z93755	**Contractor:**	7241
Tag:	A078932	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7117441.pdf

Additional Detail(s) (Map)

Well Completed Date:	12/11/2008
Year Completed:	2008
Depth (m):	6.096
Latitude:	43.7170256793267
Longitude:	-79.8128650151285
X:	-79.81286486504926
Y:	43.71702567694343
Path:	711\7117441.pdf

Bore Hole Information

Bore Hole ID:	1001945086	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595629.00
Code OB Desc:		**North83:**	4841129.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12/11/2008	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1002443733
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	3.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1002443734
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	34
Material 1 Desc:	TILL
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	3.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1002443737
Layer:	2
Plug From:	9.0
Plug To:	20.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1002443736
Layer:	1
Plug From:	0.0
Plug To:	9.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1002443741
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1002443732
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002443739
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	1.5
Casing Diameter UOM:	inch

Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1002443740
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.5

Water Details

Water ID: 1002443738
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1002443735
Diameter: 3.5
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

21 | **1 of 1** | **SSW/92.6** | **243.6 / 1.71** | **120 SANDLEWOOD Brampton ON** | **WWIS**

Well ID: 7122452
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z096608
Tag: A078932
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/29/2009
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7122452.pdf

Additional Detail(s) (Map)

Well Completed Date: 03/24/2009
Year Completed: 2009

Depth (m):
Latitude: 43.7167595918585
Longitude: -79.8123861297559
X: -79.81238597963576
Y: 43.7167595901625
Path: 712\7122452.pdf

Bore Hole Information

Bore Hole ID: 1002420371
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 03/24/2009
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595668.00
North83: 4841100.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002532969
Layer: 1
Plug From: 0.0
Plug To: 2.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002532974
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1002532966
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002532971
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.0
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1002532972
Layer:	1
Slot:	10
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03000020980835

Water Details

Water ID:	1002532970
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1002532968
Diameter:	10.899999618530273
Depth From:	0.0
Depth To:	2.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

22	***1 of 29***	***S/246.1***	***239.9 / -2.08***	***City of Brampton*** ***120 Sandalwood Parkway W*** ***Brampton ON L7A 1L2***	***GEN***

Generator Info

Generator No:	ON6695350	***Choice of Contact:***	
Approval Years:	05,06,07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	913910
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Other Local Municipal and Regional Public Administration		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

22	***2 of 29***	***S/246.1***	***239.9 / -2.08***	***Giffels Associates for Brampton Transit*** ***120 Sandalwood Pkwy Brampton Ontario L7W 1L2 Brampton ON***	***EBR***

EBR Registry No:	IT07E0003	***Decision Posted:***	
Ministry Ref No:	2006-000336	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:		***Act 1:***	

Notice Date:	April 12, 2007	**Act 2:**	
Proposal Date:	January 11, 2007	**Site Location Map:**	
Year:	2007		
Instrument Type:			
Off Instrument Name:			
Posted By:			
Company Name:	Giffels Associates for Brampton Transit		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	30 International Blvd, Toronto Ontario, M9W 5P3		
Comment Period:			
URL:			
Summary:			

Site Location Details:

120 Sandalwood Pkwy Brampton Ontario L7W 1L2 Brampton

---

22 | 3 of 29 | S/246.1 | 239.9 / -2.08 | **120 SANDALWOOD PKWY WEST Brampton ON** | WWIS

Well ID:	7114851	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/12/2008
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	M03757	**Contractor:**	7241
Tag:	A079086	**Form Version:**	5
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/03/2008
Year Completed:	2008
Depth (m):	
Latitude:	43.7160865821907
Longitude:	-79.820431079773
X:	-79.82043092949385
Y:	43.71608658006292
Path:	711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/02/2008

Year Completed: 2008
Depth (m):
Latitude: 43.717076105633
Longitude: -79.8099219271109
X: -79.80992177670161
Y: 43.71707610411346
Path: 711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/02/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7173736889584
Longitude: -79.8099656925066
X: -79.80996554258168
Y: 43.71737368722154
Path: 711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/01/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7183679544305
Longitude: -79.8111998420072
X: -79.81119969165458
Y: 43.71836795219394
Path: 711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/02/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7207613166087
Longitude: -79.8084461192831
X: -79.80844596879707
Y: 43.72076131528279
Path: 711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/03/2008
Year Completed: 2008
Depth (m): 5.5
Latitude: 43.7165468257942
Longitude: -79.8083806807967
X: -79.8083805305201
Y: 43.71654682424931
Path: 711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/02/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7171069430212
Longitude: -79.8094247608036
X: -79.8094246105513
Y: 43.717106941029314
Path: 711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/01/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7198642724763
Longitude: -79.8096308592193
X: -79.8096307089178
Y: 43.71986426996347
Path: 711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/01/2008
Year Completed: 2008
Depth (m):
Latitude: 43.719764217634
Longitude: -79.8190802350144
X: -79.81908008529096
Y: 43.719764216407825
Path: 711\7114851.pdf

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7114851.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/01/2008
Year Completed: 2008
Depth (m):
Latitude: 43.7184892403097
Longitude: -79.8116071117946
X: -79.81160696161275
Y: 43.71848923843792
Path: 711\7114851.pdf

Bore Hole Information

Bore Hole ID: 1001881164
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/03/2008
Remarks:
Location Method Desc: on Water Well Record

Elevation:
Elevrc:
Zone: 17
East83: 595991.00
North83: 4841081.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1002709381
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 28
Material 3 Desc: SAND
Formation Top Depth: 0.6000000238418579
Formation End Depth: 2.700000047683716
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002709382
Layer: 3
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 28
Material 3 Desc: SAND
Formation Top Depth: 2.700000047683716
Formation End Depth: 5.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002709380
Layer: 1
Color: 6
General Color: BROWN
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 28
Material 2 Desc: SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.6000000238418579
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002709385

Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.0999999046325684
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002709386
Layer: 3
Plug From: 2.0999999046325684
Plug To: 5.5
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002709384
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002709390
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1002709379
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002709387
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.4000000953674316
Casing Diameter: 5.199999809265137
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002709388
Layer: 1
Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03000020980835

Hole Diameter

Hole ID:	1002709383
Diameter:	11.5
Depth From:	0.0
Depth To:	5.5
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002709307	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595124.00
Code OB Desc:		***North83:***	4841426.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	10/01/2008	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002709311
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002709310
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002709312
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002709314
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	2.4000000953674316

Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002709313
Layer:
Slot:
Screen Top Depth: 2.4000000953674316
Screen End Depth: 5.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002709315
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002709309
Diameter: 11.5
Depth From:
Depth To: 5.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002709352
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 10/02/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595906.00
North83: 4841142.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002709356
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002709355
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002709357
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002709359
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.4000000953674316
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002709358
Layer:
Slot:
Screen Top Depth: 2.4000000953674316
Screen End Depth: 5.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002709360
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:

Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002709354
Diameter: 11.5
Depth From:
Depth To: 5.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002709298
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 10/01/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595728.00
North83: 4841293.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002709302
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002709301
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002709303
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1002709305
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	2.4000000953674316
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002709304
Layer:	
Slot:	
Screen Top Depth:	2.4000000953674316
Screen End Depth:	5.5
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002709306
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002709300
Diameter:	11.5
Depth From:	
Depth To:	5.5
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002709325	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595979.00
Code OB Desc:		***North83:***	4841549.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3

Date Completed: 10/02/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002709329
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002709328
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002709330
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002709332
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.4000000953674316
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002709331
Layer:
Slot:
Screen Top Depth: 2.4000000953674316
Screen End Depth: 5.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:

Pump Test ID: 1002709333
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002709327
Diameter: 11.5
Depth From:
Depth To:
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002709343
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 10/02/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595866.00
North83: 4841138.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002709347
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002709346
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID:	1002709348
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002709350
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	2.4000000953674316
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002709349
Layer:	
Slot:	
Screen Top Depth:	2.4000000953674316
Screen End Depth:	5.5
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002709351
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002709345
Diameter:	11.5
Depth From:	
Depth To:	5.5
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002709334	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595862.00
Code OB Desc:		**North83:**	4841171.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	10/02/2008	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002709338
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002709337
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002709339
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002709341
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	2.4000000953674316
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002709340
Layer:	
Slot:	
Screen Top Depth:	2.4000000953674316
Screen End Depth:	5.5
Screen Material:	
Screen Depth UOM:	m

Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002709342
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002709336
Diameter: 11.5
Depth From:
Depth To: 5.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002709370
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 10/01/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595761.00
North83: 4841280.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002709374
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002709373
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002709375
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002709377
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.4000000953674316
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002709376
Layer:
Slot:
Screen Top Depth: 2.4000000953674316
Screen End Depth: 5.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002709378
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002709372
Diameter: 11.5
Depth From:

Depth To: 5.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002709316
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 10/01/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595885.00
North83: 4841448.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002709320
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002709319
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002709321
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002709323
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.4000000953674316
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002709322
Layer:
Slot:
Screen Top Depth: 2.4000000953674316
Screen End Depth: 5.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002709324
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002709318
Diameter: 11.5
Depth From:
Depth To: 5.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002709361
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 10/03/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 595021.00
North83: 4841016.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002709365

Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002709364
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002709366
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002709368
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 2.4000000953674316
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002709367
Layer:
Slot:
Screen Top Depth: 2.4000000953674316
Screen End Depth: 5.5
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002709369
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:

Flowing:

Hole Diameter

Hole ID: 1002709363
Diameter: 11.5
Depth From:
Depth To:
Hole Depth UOM: m
Hole Diameter UOM: cm

---

22 | ***4 of 29*** | ***S/246.1*** | ***239.9 / -2.08*** | ***The Corporation of the City of Brampton***
120 Sandalwood Pky
Brampton ON | ***CA***

Certificate #: 0158-6YKQA7
Application Year: 2007
Issue Date: 2/20/2007
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

22 | ***5 of 29*** | ***S/246.1*** | ***239.9 / -2.08*** | ***The Corporation of the City of Brampton***
Steeles Ave and Kenndy Rd; 120 Sandalwood Pky W
Brampton; Brampton ON L7A 1L2 | ***SPL***

Ref No: 5737-8ACPMG
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/18/2010
Dt Document Closed:
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Brampton Transit Bus<UNOFFICIAL>; 120 Sandalwood Parkway West
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Incident Reason:	
Incident Summary:	Brampton Transit Bus: motor oil to rd and CB
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Surface Water Pollution
Contaminant Qty:	0 other - see incident description
Contaminant Qty 1:	0
Contaminant Unit:	other - see incident description
Contaminant Code:	15
Contaminant Name:	MOTOR OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Motor Vehicle
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	6 of 29	S/246.1	239.9 / -2.08	THE CORPORATION OF THE CITY OF BRAMPTON 120 SANDALWOOD PKWY WEST BRAMPTON ON L7A 1L2	EASR

Approval No:	R-003-1000000338	**MOE District:**	
Status:	REGISTERED	**Municipality:**	BRAMPTON
Date:	2012-01-13	**Latitude:**	
Record Type:	EASR	**Longitude:**	
Link Source:	MOFA	**Geometry X:**	
Project Type:	Heating System	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Heating System		
SWP Area Name:			
PDF NAICS Code:			
PDF URL:			
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	7 of 29	S/246.1	239.9 / -2.08	The Corporation of the City of Brampton 120 Sandalwood Pky W Brampton ON L7A 1L2	ECA

Approval No:	8178-8QFSHW	**MOE District:**	
Approval Date:	2/8/2012	**City:**	Brampton
Status:	Approved	**Longitude:**	
Record Type:		**Latitude:**	
Link Source:		**Geometry X:**	
SWP Area Name:		**Geometry Y:**	
Approval Type:			
Project Type:	Air/Noise		
Business Name:			
Address:			
Full Address:			
Full PDF Link:			
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	8 of 29	S/246.1	239.9 / -2.08	CITY OF BRAMPTON 120 SANDALWOOD PKWY W BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	64502571	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	64502571	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Gasoline Station - Card/Keylock		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	9 of 29	S/246.1	239.9 / -2.08	City of Brampton 120 Sandalwood Parkway W Brampton ON L7A 1L2	GEN

Generator Info

Generator No:	ON6695350	**Choice of Contact:**	
Approval Years:	2009	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	913910
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Other Local Municipal and Regional Public Administration		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	10 of 29	S/246.1	239.9 / -2.08	City of Brampton 120 Sandalwood Parkway W Brampton ON L7A 1L2	GEN

Generator Info

Generator No:	ON6695350	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	913910
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Other Local Municipal and Regional Public Administration		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

---

22 ***11 of 29*** ***S/246.1*** ***239.9 / -2.08*** ***City of Brampton*** ***GEN***
120 Sandalwood Parkway W
Brampton ON L7A 1L2

Generator Info

Generator No:	ON6695350	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	913910
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Other Local Municipal and Regional Public Administration		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

---

22 ***12 of 29*** ***S/246.1*** ***239.9 / -2.08*** ***City of Brampton*** ***GEN***
120 Sandalwood Parkway West
Brampton ON L7A 1L2

Generator Info

Generator No:	ON3601966	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:
MHSW Facility:
SIC Code: 811199

---

22 | ***13 of 29*** | ***S/246.1*** | ***239.9 / -2.08*** | ***CITY OF BRAMPTON***
120 SANDALWOOD PKWY W
BRAMPTON ON | ***FST***

Inventory No: 64502572
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: Clear diesel
Tank Material: Steel
Corrosion Protect: Painted
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

22 | ***14 of 29*** | ***S/246.1*** | ***239.9 / -2.08*** | ***CITY OF BRAMPTON***
120 SANDALWOOD PKWY W
BRAMPTON ON | ***FST***

Inventory No: 64502573
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: Dyed diesel
Tank Material: Steel
Corrosion Protect: Painted
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

22 | ***15 of 29*** | ***S/246.1*** | ***239.9 / -2.08*** | ***City of Brampton***
120 Sandalwood Parkway W
Brampton ON L7A 1L2 | ***GEN***

Generator Info

Generator No: ON6695350
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Other Local Municipal and Regional Public Administration
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 913910

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		LIGHT FUELS			

22	16 of 29	S/246.1	239.9 / -2.08	**City of Brampton** **120 Sandalwood Parkway West** **Brampton ON L7A 1L2**	GEN

Generator Info

Generator No:	ON3601966	**Choice of Contact:**	
Approval Years:	2012	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	811199
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Automotive Repair and Maintenance		

22	17 of 29	S/246.1	239.9 / -2.08	**City of Brampton** **120 Sandalwood Parkway West** **Brampton ON**	GEN

Generator Info

Generator No:	ON3601966	**Choice of Contact:**	
Approval Years:	2013	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	811199
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

22	18 of 29	S/246.1	239.9 / -2.08	**The Corporation of the City of Brampton** **120 Sandalwood Pky** **Brampton ON L6Y 4R2**	ECA

Approval No:	3084-76LNKS	**MOE District:**	
Approval Date:	2015-12-07	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	
SWP Area Name:		**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	The Corporation of the City of Brampton		
Address:	120 Sandalwood Pky		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/9677-85YLNQ-14.pdf		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
PDF Site Location:					

22	19 of 29	S/246.1	239.9 / -2.08	**The Corporation of the City of Brampton** **120 Sandalwood Pky W** **Brampton ON L6Y 4R2**	ECA

Approval No: 8178-8QFSHW
Approval Date: 2012-02-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: The Corporation of the City of Brampton
Address: 120 Sandalwood Pky W
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5310-889QN2-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

22	20 of 29	S/246.1	239.9 / -2.08	**The Corporation of the City of Brampton** **120 Sandalwood Pky W** **Brampton ON L6Y 4R2**	ECA

Approval No: 3084-76LNKS
Approval Date: 2007-10-27
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: The Corporation of the City of Brampton
Address: 120 Sandalwood Pky W
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8305-73URNC-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

22	21 of 29	S/246.1	239.9 / -2.08	**The Corporation of the City of Brampton** **120 Sandalwood Pky W** **Brampton ON L6Y 4R2**	ECA

Approval No: 0158-6YKQA7
Approval Date: 2007-02-20
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Corporation of the City of Brampton
Address: 120 Sandalwood Pky W
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2761-6UVS84-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

22	22 of 29	S/246.1	239.9 / -2.08	**City of Brampton** **120 Sandalwood Parkway West** **Brampton ON L7A 1L2**	GEN

Generator Info

Generator No:	ON3601966	***Choice of Contact:***	CO_ADMIN
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	811199
Country:	Canada		
Co Admin:	Annaliza San Juan		
Phone No Admin:	905.458.4888 Ext.63116		
SIC Description:	ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE		

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

22	***23 of 29***	***S/246.1***	***239.9 / -2.08***	***City of Brampton*** ***120 Sandalwood Parkway West*** ***Brampton ON L7A 1L2***	***GEN***

Generator Info

Generator No:	ON3601966	***Choice of Contact:***	CO_ADMIN
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	811199
Country:	Canada		
Co Admin:	Annaliza San Juan		
Phone No Admin:	905.458.4888 Ext.63116		
SIC Description:	ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

22	***24 of 29***	***S/246.1***	***239.9 / -2.08***	***City of Brampton*** ***120 Sandalwood Parkway West*** ***Brampton ON L7A 1L2***	***GEN***

Generator Info

Generator No:	ON3601966	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: **MHSW Facility:** No
PO Box No: **SIC Code:** 811199
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

22	25 of 29	S/246.1	239.9 / -2.08	**City of Brampton Public Works** **120 Sandalwood Parkway West** **Brampton ON L7A 1L2**	GEN

Generator Info

Generator No: ON3601966
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

22	26 of 29	S/246.1	239.9 / -2.08	**City of Brampton Public Works** **120 Sandalwood Parkway West** **Brampton ON L7A 1L2**	GEN

Generator Info

Generator No: ON3601966
Approval Years: As of Jul 2020
Status: Registered
Choice of Contact:
Contaminated Fac:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No: ***SIC Code:***
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

22	***27 of 29***	***S/246.1***	***239.9 / -2.08***	***City of Brampton Public Works*** ***120 Sandalwood Parkway West*** ***Brampton ON L7A 1L2***	***GEN***

Generator Info

Generator No: ON3601966 ***Choice of Contact:***
Approval Years: As of Nov 2021 ***Contaminated Fac:***
Status: Registered ***MHSW Facility:***
PO Box No: ***SIC Code:***
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

22	***28 of 29***	***S/246.1***	***239.9 / -2.08***	***City of Brampton*** ***Roads - Fleet, 120 Sandalwood Parkway West*** ***Brampton ON***	***GEN***

Generator Info

Generator No:	ON3601966	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	212 L
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Generator Info as of Dec 2024

Generator No:	ON3601966
Generator Company Name:	City of Brampton
Street:	Roads - Fleet, 120 Sandalwood Parkway West
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A1L2
Waste Class:	252 L,212 L,251 L

Waste Class Decoded:

252 - WASTE OILS & LUBRICANTS; 212 - ALIPHATIC SOLVENTS; 251 - OIL SKIMMINGS & SLUDGES

2017 Generator Info

Gen No:	ON3601966	***Choice of Contact:***	CO_ADMIN
ID:	14465	***Phone No Official:***	905.458.4888 Ext.63102
Contaminated Fac:	N	***Phone No Admin:***	905.458.4888 Ext.63116
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	811199	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	City of Brampton		
Gen Div:	Public Works		
Gen Op Name:	City of Brampton		
Gen Op Div:	Public Works		
Site Adrs1:	120 Sandalwood Parkway West		
Site Bldg:	Roads - Fleet		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			

Site Postal Code:	L7A 1L2
Site Country:	Canada
Co Official:	Mike Lewis
Co Admin:	Annaliza San Juan

2017 Generator Manifest

ID:	37060	***Sum Received Qty:***	3639.0
Generator No:	ON3601966	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	3
Waste Char:	L	***District:***	305
Waste Code:	252		

2017 Generator Manifest

ID:	37057	***Sum Received Qty:***	5000.0
Generator No:	ON3601966	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	301
Waste Code:	251		

2017 Generator Manifest

ID:	37059	***Sum Received Qty:***	41325.0
Generator No:	ON3601966	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	L	***District:***	305
Waste Code:	251		

2017 Generator Manifest

ID:	37058	***Sum Received Qty:***	11290.0
Generator No:	ON3601966	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	301
Waste Code:	252		

2018 Generator Info

Gen No:	ON3601966	***Choice of Contact:***	CO_ADMIN
ID:	14356	***Phone No Official:***	905.458.4888 Ext.63102
Contaminated Fac:	N	***Phone No Admin:***	905.458.4888 Ext.63116
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	811199	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	City of Brampton
Gen Div:	Public Works
Gen Op Name:	City of Brampton
Gen Op Div:	Public Works
Site Adrs1:	120 Sandalwood Parkway West
Site Bldg:	Roads - Fleet
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1L2
Site Country:	Canada
Co Official:	Mike Lewis
Co Admin:	Annaliza San Juan

2018 Generator Manifest

ID:	36964	***Sum Received Qty:***	4465.0
Generator No:	ON3601966	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	L	***District:***	305
Waste Code:	252		

2018 Generator Manifest

ID:	36963	***Sum Received Qty:***	4000.0
Generator No:	ON3601966	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	301
Waste Code:	251		

2019 Generator Info

Gen No:	ON3601966	***Choice of Contact:***	CO_ADMIN
ID:	14174	***Phone No Official:***	905.458.4888 Ext.63102
Contaminated Fac:	N	***Phone No Admin:***	905.458.4888 Ext.63116
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	811199	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	City of Brampton		
Gen Div:	Public Works		
Gen Op Name:	City of Brampton		
Gen Op Div:	Public Works		
Site Adrs1:	120 Sandalwood Parkway West		
Site Bldg:	Roads - Fleet		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1L2		
Site Country:	Canada		
Co Official:	Mike Lewis		
Co Admin:	Annaliza San Juan		

2019 Generator Manifest

ID:	36162	***Sum Received Qty:***	3431.0
Generator No:	ON3601966	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	L	***District:***	305
Waste Code:	252		

2020 Generator Info

Gen No:	ON3601966	***Choice of Contact:***	CO_ADMIN
ID:	13822	***Phone No Official:***	905.458.4888 Ext.63102
Contaminated Fac:	N	***Phone No Admin:***	905.458.4888 Ext.63116
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	811199	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	City of Brampton		
Gen Div:	Public Works		
Gen Op Name:	City of Brampton		
Gen Op Div:	Public Works		

Site Adrs1:	120 Sandalwood Parkway West
Site Bldg:	Roads - Fleet
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1L2
Site Country:	Canada
Co Official:	Mike Lewis
Co Admin:	Annaliza San Juan

2020 Generator Manifest

ID:	33284	***Sum Received Qty:***	935.0
Generator No:	ON3601966	***Waste Class Name:***	ALIPHATIC SOLVENTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	212		

2020 Generator Manifest

ID:	33285	***Sum Received Qty:***	2501.0
Generator No:	ON3601966	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	L	***District:***	305
Waste Code:	252		

2021 Generator Info

Gen No:	ON3601966	***Choice of Contact:***	CO_ADMIN
ID:	13706	***Phone No Official:***	905.458.4888 Ext.63102
Contaminated Fac:	N	***Phone No Admin:***	905.458.4888 Ext.63116
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	811199	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	City of Brampton		
Gen Div:	Public Works		
Gen Op Name:	City of Brampton		
Gen Op Div:	Public Works		
Site Adrs1:	120 Sandalwood Parkway West		
Site Bldg:	Roads - Fleet		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1L2		
Site Country:	Canada		
Co Official:	Mike Lewis		
Co Admin:	Annaliza San Juan		

2021 Generator Manifest

ID:	33823	***Sum Received Qty:***	2200.0
Generator No:	ON3601966	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	252		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	29 of 29	S/246.1	239.9 / -2.08	120 Sandalwood Parkway West, Brampton ON BRAMPTON ON	SPL

Ref No:	1-2H7VJG	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	Jan 31,2023 06:18:16 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2023/01/31	**Impact to Health:**	
Dt Document Closed:	Jan 31,2023 02:13:59 PM	**Agency Involved:**	

Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 120 Sandalwood Parkway West, Brampton ON
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type: Fuel Pump
Incident Cause:
Incident Preceding Spill:
Incident Reason:
Incident Summary: City of Brampton diesel spill 100 L
Environment Impact:
Health Env Consequence: Low
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1: 99
Contaminant Unit: litre (L)
Contaminant Code:
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed: 02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed: 02HC | Humber River - Don River
Sector Type: CONSTRUCTION, TRANSPORTATION, MINING, AND FORESTRY MACHINERY AND EQUIPMENT RENTAL AND LEASING
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00002393232"],"wkts":["POINT (-79.8125694000 43.7170456000)"],"creation_date":"2023-01-31"}
Time Reported: 9:18:16
System Facility Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	1 of 1	S/154.9	240.7 / -1.21	130 SANDALWOOD PKWY WEST Brampton ON	WWIS

Well ID:	7246995	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Abandoned Monitoring and Test Hole	**Date Received:**	08/24/2015

Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z216309	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/724\7246995.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/15/2015
Year Completed:	2015
Depth (m):	
Latitude:	43.7159533092807
Longitude:	-79.8101800106535
X:	-79.8101798609045
Y:	43.71595330734021
Path:	724\7246995.pdf

Bore Hole Information

Bore Hole ID:	1005635241	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595847.00
Code OB Desc:		**North83:**	4841013.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/15/2015	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005718903
Layer:	1
Plug From:	0.0
Plug To:	30.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005718902
Method Construction Code:	D

Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1005718894
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005718898
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 20.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005718899
Layer: 1
Slot: 10
Screen Top Depth: 20.0
Screen End Depth: 30.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1005718897
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005718896
Diameter: 2.0
Depth From: 0.0
Depth To: 30.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

24 | **1 of 1** | **S/225.3** | **239.9 / -2.08** | **130 SANDALWOOD PKWY WEST Brampton ON** | **WWIS**

Well ID: 7247001
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Abandoned Monitoring and Test Hole
Water Type:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 08/24/2015
Selected Flag: TRUE

Casing Material:		**Abandonment Rec:**	
Audit No:	Z216313	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/724\7247001.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/15/2015
Year Completed:	2015
Depth (m):	
Latitude:	43.7159585150378
Longitude:	-79.8089509552414
X:	-79.80895080518812
Y:	43.71595851320429
Path:	724\7247001.pdf

Bore Hole Information

Bore Hole ID:	1005635305	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595946.00
Code OB Desc:		**North83:**	4841015.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/15/2015	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005718961
Layer:	1
Plug From:	0.0
Plug To:	15.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005718960
Method Construction Code:	D
Method Construction:	Direct Push

Other Method Construction:

Pipe Information

Pipe ID: 1005718952
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005718956
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 5.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005718957
Layer: 1
Slot: 10
Screen Top Depth: 5.0
Screen End Depth: 15.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1005718955
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005718954
Diameter: 2.0
Depth From: 0.0
Depth To: 15.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

25 | ***1 of 3*** | ***WSW/10.8*** | ***247.9 / 5.92*** | ***Mia Properties Limited*** ***CON 1 WEST OF CENTRE ROAD*** ***Brampton ON M2P 2B7*** | ***ECA***

Approval No: 6260-4XTNNK
Approval Date: 2001-06-20
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
MOE District: Halton-Peel
City:
Longitude: -79.8165
Latitude: 43.7187
Geometry X:
Geometry Y:

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Mia Properties Limited
Address: CON 1 WEST OF CENTRE ROAD
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9711-4XPK9F-14.pdf
PDF Site Location:

---

25 **2 of 3** **WSW/10.8** **247.9 / 5.92** **Mia Properties Limited**
CON 1 WEST OF CENTRE ROAD
Brampton ON M2P 2B7 **ECA**

Approval No: 8705-4XTNYF
Approval Date: 2001-06-20
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
MOE District: Halton-Peel
City:
Longitude: -79.8165
Latitude: 43.718700000000005
Geometry X:
Geometry Y:
Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Business Name: Mia Properties Limited
Address: CON 1 WEST OF CENTRE ROAD
Full Address:
Full PDF Link:
PDF Site Location:

---

25 **3 of 3** **WSW/10.8** **247.9 / 5.92** **Petro-Canada Limited**
West of Hurontario Street
Brampton ON L6L 6N5 **ECA**

Approval No: 2377-4UTQX4
Approval Date: 2001-03-16
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
MOE District: Halton-Peel
City:
Longitude: -79.8165
Latitude: 43.7187
Geometry X:
Geometry Y:
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Petro-Canada Limited
Address: West of Hurontario Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0406-4UJNFN-14.pdf
PDF Site Location:

---

26 **1 of 1** **W/66.6** **249.9 / 7.92**
ON **WWIS**

Well ID: 7167767
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: M06550
Tag: A094779
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 08/24/2011
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 5
Owner:
County: PEEL
Lot:
Concession:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Well Depth: ***Concession Name:***
Overburden/Bedrock: ***Easting NAD83:***
Pump Rate: ***Northing NAD83:***
Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Additional Detail(s) (Map)

Bore Hole ID:	1003555123	***Tag No:***	A094779
Depth M:		***Contractor:***	6607
Year Completed:	2010	***Latitude:***	43.7203542651888
Well Completed Dt:	04/01/2010	***Longitude:***	-79.8178023580613
Audit No:	M06550	***Y:***	43.72035426310635
Path:		***X:***	-79.81780220789867

Bore Hole Information

Bore Hole ID:	1003555123	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595226.00
Code OB Desc:		***North83:***	4841493.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	04/01/2010	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
27	1 of 1	W/61.7	249.9 / 7.92	ON	WWIS

Well ID:	7170238	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	10/20/2011
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	M06572	***Contractor:***	6607
Tag:	A094779	***Form Version:***	5
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7170238.pdf

Additional Detail(s) (Map)

Well Completed Date:	04/01/2010
Year Completed:	2010
Depth (m):	
Latitude:	43.7203460334799
Longitude:	-79.8178770073503
X:	-79.81787685697743
Y:	43.720346031500455
Path:	717\7170238.pdf

Bore Hole Information

Bore Hole ID:	1003586330	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595220.00
Code OB Desc:		***North83:***	4841492.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	04/01/2010	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

28 ***1 of 1*** ***SSW/52.5*** ***241.1 / -0.86*** ***130 SANDALWOOD PKWY WEST Brampton ON*** ***WWIS***

Well ID:	7246996	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	08/24/2015
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z216308	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/724\7246996.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/15/2015
Year Completed:	2015
Depth (m):	
Latitude:	43.715369379385
Longitude:	-79.8111722354289

X:	-79.81117208490656
Y:	43.715369377062565
Path:	724\7246996.pdf

Bore Hole Information

Bore Hole ID:	1005635244	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595768.00
Code OB Desc:		***North83:***	4840947.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	07/15/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005718911
Layer:	1
Plug From:	0.0
Plug To:	26.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005718910
Method Construction Code:	
Method Construction:	
Other Method Construction:	

Pipe Information

Pipe ID:	1005718904
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005718908
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	16.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005718909
Layer:	1
Slot:	10
Screen Top Depth:	16.0
Screen End Depth:	26.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1005718907
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005718906
Diameter:	2.0
Depth From:	0.0
Depth To:	26.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

29 ***1 of 8*** ***SSW/11.9*** ***240.9 / -1.08*** ***Mia Properties Limited*** ***ECA***

Brampton ON M2P 6O2

Approval No:	8346-4NNQHG	**MOE District:**	Halton-Peel
Approval Date:	2000-09-01	**City:**	
Status:	Approved	**Longitude:**	-79.8111
Record Type:	ECA	**Latitude:**	43.7148
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Mia Properties Limited		
Address:			
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/5063-4NJLH8-14.pdf		
PDF Site Location:			

---

29 ***2 of 8*** ***SSW/11.9*** ***240.9 / -1.08*** ***Mia Properties Limited*** ***ECA***

Brampton ON M3B 2T5

Approval No:	9053-5NSLMW	**MOE District:**	Halton-Peel
Approval Date:	2003-06-23	**City:**	
Status:	Approved	**Longitude:**	-79.8111
Record Type:	ECA	**Latitude:**	43.7148
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Mia Properties Limited		
Address:			
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2458-5NMMRW-14.pdf		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PDF Site Location:

---

29 **3 of 8** **SSW/11.9** **240.9 / -1.08** **149259 Canada Limited** **ECA**
Lot 14, Concession 1 WHS
Brampton ON M5P 3M2

Approval No:	1283-4Q8SGB	**MOE District:**	Halton-Peel
Approval Date:	2000-10-23	**City:**	
Status:	Approved	**Longitude:**	-79.81110000000001
Record Type:	ECA	**Latitude:**	43.714800000000004
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	
Approval Type:	ECA-Municipal and Private Water Works		
Project Type:	Municipal and Private Water Works		
Business Name:	149259 Canada Limited		
Address:	Lot 14, Concession 1 WHS		
Full Address:			
Full PDF Link:			
PDF Site Location:			

---

29 **4 of 8** **SSW/11.9** **240.9 / -1.08** **Mia Properties Limited** **ECA**

Brampton ON M2P 6O2

Approval No:	7383-4NNRNL	**MOE District:**	Halton-Peel
Approval Date:	2000-09-01	**City:**	
Status:	Approved	**Longitude:**	-79.81110000000001
Record Type:	ECA	**Latitude:**	43.714800000000004
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	
Approval Type:	ECA-Municipal and Private Water Works		
Project Type:	Municipal and Private Water Works		
Business Name:	Mia Properties Limited		
Address:			
Full Address:			
Full PDF Link:			
PDF Site Location:			

---

29 **5 of 8** **SSW/11.9** **240.9 / -1.08** **Ciro Excavating & Grading Ltd.** **ECA**

Brampton ON L4L 3P6

Approval No:	0575-5AYKBQ	**MOE District:**	Halton-Peel
Approval Date:	2002-06-10	**City:**	
Status:	Approved	**Longitude:**	-79.81110000000001
Record Type:	ECA	**Latitude:**	43.714800000000004
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	
Approval Type:	ECA-Municipal and Private Water Works		
Project Type:	Municipal and Private Water Works		
Business Name:	Ciro Excavating & Grading Ltd.		
Address:			
Full Address:			
Full PDF Link:			
PDF Site Location:			

---

29 **6 of 8** **SSW/11.9** **240.9 / -1.08** **Ciro Excavating & Grading Ltd.** **ECA**

Brampton ON L4L 3P6

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No: 0480-5AYKPY
Approval Date: 2002-06-10
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Ciro Excavating & Grading Ltd.
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6263-5ATHAX-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.8111
Latitude: 43.7148
Geometry X:
Geometry Y:

---

29 | **7 of 8** | **SSW/11.9** | **240.9 / -1.08** | **149259 Canada Limited**
Lot 14, Concession 1 WHS
Brampton ON M5P 3M2 | **ECA**

Approval No: 1470-4Q8SPL
Approval Date: 2000-10-23
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: 149259 Canada Limited
Address: Lot 14, Concession 1 WHS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8668-4PSKS8-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.8111
Latitude: 43.7148
Geometry X:
Geometry Y:

---

29 | **8 of 8** | **SSW/11.9** | **240.9 / -1.08** | **Mia Properties Limited**

Brampton ON M3B 2T5 | **ECA**

Approval No: 7427-5NSLEQ
Approval Date: 2003-06-24
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: Mia Properties Limited
Address:
Full Address:
Full PDF Link:
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.81110000000001
Latitude: 43.714800000000004
Geometry X:
Geometry Y:

---

30 | **1 of 1** | **WSW/140.3** | **245.9 / 3.92** | **HOME ALONE PROPERTY MANAGEMENT LTD**
8 MILKWEED CRESCENT
BRAMPTON ON | **GEN**

Generator Info

Generator No: ON3399446
Approval Years: 2012
Choice of Contact:
Contaminated Fac:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:		**MHSW Facility:**		
PO Box No:		**SIC Code:**	531310	
Country:				
Co Admin:				
Phone No Admin:				
SIC Description:	Real Estate Property Managers			

31 **1 of 8** **WSW/143.7** **245.9 / 3.92** **NH PEST CONTROL INC.** **PES**
4 NARCISSUS GATE
BRAMPTON ON L7A 1V9

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1038314003	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-11-18	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71722222	**Operator Region:**	
Longitude:	-79.81722222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2193603		

31 **2 of 8** **WSW/143.7** **245.9 / 3.92** **NH PEST CONTROL INC.** **PES**
4 NARCISSUS GATE
BRAMPTON ON L7A 1V9

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1038314003	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2020-12-08	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71722222	**Operator Region:**	
Longitude:	-79.81722222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2313942		

31 **3 of 8** **WSW/143.7** **245.9 / 3.92** **4 NARCISSUS GATE** **PES**
BRAMPTON ON L7A 1V9

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1038314003	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2021-03-29	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	

Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71722222	**Operator Region:**	
Longitude:	-79.81722222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2372846

---

31 | ***4 of 8*** | ***WSW/143.7*** | ***245.9 / 3.92*** | ***4 NARCISSUS GATE BRAMPTON ON L7A 1V9*** | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1038314003	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	December, 5 2021	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71722222	**Operator Region:**	
Longitude:	-79.81722222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2535564

---

31 | ***5 of 8*** | ***WSW/143.7*** | ***245.9 / 3.92*** | ***NH PEST CONTROL INC. 4 NARCISSUS GATE BRAMPTON ON L7A 1V9*** | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1038314003	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	November 16, 2022	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71722222	**Operator Region:**	
Longitude:	-79.81722222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2785306

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	6 of 8	WSW/143.7	245.9 / 3.92	NH PEST CONTROL INC. 4 NARCISSUS GATE BRAMPTON ON L7A 1V9	PES

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1038314003	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	December 12, 2023	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71722222	**Operator Region:**	
Longitude:	-79.81722222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3225933		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	7 of 8	WSW/143.7	245.9 / 3.92	NH PEST CONTROL INC. 4 NARCISSUS GATE BRAMPTON ON L7A 1V9	PES

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1038314003	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	December 19, 2024	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71722222	**Operator Region:**	
Longitude:	-79.81722222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3815538		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	8 of 8	WSW/143.7	245.9 / 3.92	NH PEST CONTROL INC. 4 NARCISSUS GATE BRAMPTON ON L7A 1V9	PES

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1038314003	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	March 27, 2025	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71722222	**Operator Region:**	
Longitude:	-79.81722222	**Operator District:**	
Lot:		**Operator County:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3950195		

---

32 | **1 of 1** | **S/119.2** | **239.9 / -2.08** | **130 SANDALWOOD PKWY WEST Brampton ON** | **WWIS**

Well ID:	7246999	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Abandoned Monitoring and Test Hole	**Date Received:**	08/24/2015
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z216312	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/724\7246999.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/15/2015
Year Completed:	2015
Depth (m):	
Latitude:	43.7146262173733
Longitude:	-79.8089773463498
X:	-79.80897719600542
Y:	43.71462621549235
Path:	724\7246999.pdf

Bore Hole Information

Bore Hole ID:	1005635283	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595946.00
Code OB Desc:		**North83:**	4840867.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/15/2015	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005718941
Layer:	1
Plug From:	0.0
Plug To:	21.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005718940
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005718932
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005718936
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	11.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005718937
Layer:	1
Slot:	10
Screen Top Depth:	11.0
Screen End Depth:	2.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1005718935
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005718934
Diameter:	2.0
Depth From:	0.0
Depth To:	21.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

33 | **1 of 1** | **W/24.1** | **249.9 / 7.92** | **lot 16 con 1 ON** | **WWIS**

Well ID:	4908671	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	1
Final Well Status:	Abandoned-Other	**Date Received:**	01/24/2001
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	214835	**Contractor:**	1413
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	016
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4908671.pdf

Additional Detail(s) (Map)

Well Completed Date:	12/01/2000
Year Completed:	2000
Depth (m):	
Latitude:	43.7203161631249
Longitude:	-79.8193425130946
X:	-79.81934236267826
Y:	43.720316161056125
Path:	490\4908671.pdf

Bore Hole Information

Bore Hole ID:	10323206	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	595102.00
Code OB Desc:		**North83:**	4841487.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	3
Date Completed:	12/01/2000	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	gps
Location Method Desc:	from gps		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	933171269
Layer:	2
Plug From:	4.0
Plug To:	60.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933171268
Layer:	1
Plug From:	0.0
Plug To:	4.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964908671
Method Construction Code:	0
Method Construction:	Not Known
Other Method Construction:	

Pipe Information

Pipe ID:	10871776
Casing No:	1
Comment:	
Alt Name:	

---

34 | ***1 of 1*** | ***WSW/153.8*** | ***245.9 / 3.92*** | ***NH PEST CONTROL INC.***
2 NARCISSUS GATE
BRAMPTON ON L7A1V9 | ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:	10202	***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:	Legacy Licenses (Excluding TS)	***Oper Area Code:***	647
Licence Type:	Operator	***Oper Phone No:***	6098202
Licence Type Code:	02	***Operator Ext:***	
Licence Class:	01	***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

---

35 | ***1 of 1*** | ***SSE/193.0*** | ***239.1 / -2.88*** | ***130 SANDALWOOD PKWY WEST***
Brampton ON | ***WWIS***

Well ID:	7247000	***Flowing (Y/N):***	

Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	08/24/2015
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z216314	**Contractor:**	7241
Tag:	A165275	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/724\7247000.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/15/2015
Year Completed:	2015
Depth (m):	
Latitude:	43.7146125001698
Longitude:	-79.8076617995342
X:	-79.80766164962442
Y:	43.71461249844848
Path:	724\7247000.pdf

Bore Hole Information

Bore Hole ID:	1005635302	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596052.00
Code OB Desc:		**North83:**	4840867.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	5
Date Completed:	07/15/2015	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID:	1005718951
Layer:	1
Plug From:	0.0
Plug To:	30.0
Plug Depth UOM:	ft

Method of Construction & Well

Use

Method Construction ID:	1005718950
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005718942
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005718946
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	20.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005718947
Layer:	1
Slot:	10
Screen Top Depth:	20.0
Screen End Depth:	30.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1005718945
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005718944
Diameter:	2.0
Depth From:	0.0
Depth To:	30.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

36	***1 of 1***	***W/36.5***	***248.9 / 6.92***	***ON***	***BORE***

Borehole ID:	637335	***Inclin FLG:***	No
OGF ID:	215537732	***SP Status:***	Initial Entry

Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	APR-1966	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.721364
Total Depth m:	4.7	**Longitude DD:**	-79.819725
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	595070
Drill Method:	Power auger	**Northing:**	4841603
Orig Ground Elev m:	247	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	245		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218480517	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL.		

Geology Stratum ID:	218480520	**Mat Consistency:**	Hard
Top Depth:	3.8	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL. GREY,GLACIAL,HARD,AGE GLACIAL.		

Geology Stratum ID:	218480519	**Mat Consistency:**	Stiff
Top Depth:	1.8	**Material Moisture:**	
Bottom Depth:	3.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.GREY,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218480521	**Mat Consistency:**	Hard
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL. RED,GLACIAL,HARD,AGE GLACIAL. 000100120006005000125050001400 50 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218480518	**Mat Consistency:**	Stiff
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	1.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SAND. BROWN,GLACIAL,STIFF, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 052980 NTS_Sheet: 30M12F		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

37 | ***1 of 1*** | ***SSE/168.3*** | ***239.9 / -2.07*** | ***130 SANDALWOOD PKWY W BRAMPTON BUS DEPOT Brampton ON*** | ***WWIS***

Well ID:	7277183	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	12/15/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z244646	**Contractor:**	7472
Tag:	A214638	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1006306662	**Tag No:**	A214638
Depth M:	7.62	**Contractor:**	7472
Year Completed:	2016	**Latitude:**	43.7144891908052

Well Completed Dt:	11/03/2016	***Longitude:***	-79.8079249252319
Audit No:	Z244646	***Y:***	43.71448918897655
Path:		***X:***	-79.80792477508156

Bore Hole Information

Bore Hole ID:	1006306662	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596031.00
Code OB Desc:		***North83:***	4840853.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	11/03/2016	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006498149
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	34
Material 1 Desc:	TILL
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	06
Material 3 Desc:	SILT
Formation Top Depth:	13.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006498147
Layer:	1
Color:	
General Color:	
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006498148
Layer:	2

Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	01
Material 2 Desc:	FILL
Material 3:	06
Material 3 Desc:	SILT
Formation Top Depth:	1.0
Formation End Depth:	13.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006498157
Layer:	2
Plug From:	14.0
Plug To:	25.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006498156
Layer:	1
Plug From:	0.0
Plug To:	14.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006498155
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1006498146
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006498152
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	15.0
Casing Diameter:	0.699999988079071
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006498153
Layer:	1

Slot: 10
Screen Top Depth: 15.0
Screen End Depth: 25.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 0.800000011920929

Water Details

Water ID: 1006498151
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006498150
Diameter: 6.0
Depth From: 0.0
Depth To: 25.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

38 | **1 of 1** | **S/30.7** | **239.9 / -2.08** | **130 SANDALWOOD PKWY WEST Brampton ON** | **WWIS**

Well ID: 7246997
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Abandoned Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z216310
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 08/24/2015
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/724\7246997.pdf

Additional Detail(s) (Map)

Well Completed Date: 02/15/2015
Year Completed: 2015
Depth (m):
Latitude: 43.7143411732723
Longitude: -79.8101374318411
X: -79.81013728181622
Y: 43.714341171004904
Path: 724\7246997.pdf

Bore Hole Information

Bore Hole ID:	1005635263	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595853.00
Code OB Desc:		***North83:***	4840834.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	02/15/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005718921
Layer:	1
Plug From:	0.0
Plug To:	30.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005718920
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005718912
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005718916
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	20.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005718917
Layer:	1
Slot:	10

Screen Top Depth:	20.0
Screen End Depth:	30.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1005718915
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005718914
Diameter:	2.0
Depth From:	0.0
Depth To:	30.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

39 | ***1 of 1*** | ***W/76.1*** | ***249.1 / 7.14*** | ***lot 16 con 1 ON*** | ***WWIS***

Well ID:	4908672	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	1
Final Well Status:	Abandoned-Other	**Date Received:**	01/24/2001
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	214836	**Contractor:**	1413
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	016
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4908672.pdf

Additional Detail(s) (Map)

Well Completed Date:	12/01/2000
Year Completed:	2000
Depth (m):	
Latitude:	43.7197959681198
Longitude:	-79.8195389461655
X:	-79.81953879546889
Y:	43.71979596611209
Path:	490\4908672.pdf

Bore Hole Information

Bore Hole ID:	10323207	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	595087.00
Code OB Desc:		***North83:***	4841429.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	3
Date Completed:	12/01/2000	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	gps
Location Method Desc:	from gps		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	933171270
Layer:	1
Plug From:	0.0
Plug To:	3.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933171271
Layer:	2
Plug From:	3.0
Plug To:	26.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964908672
Method Construction Code:	0
Method Construction:	Not Known
Other Method Construction:	

Pipe Information

Pipe ID:	10871777
Casing No:	1
Comment:	
Alt Name:	

---

40 ***1 of 2*** ***SW/182.7*** ***245.9 / 3.92*** ***RATRO PEST CONTROL INC.***
194 VAN SCOTT DR
BRAMPTON ON L7A 1V8 ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:	L-240-8177870401	***Operator Class:***	
Status:	Active	***Operator No:***	
Approval Date:	December 13, 2022	***Operator Type:***	
Report Source:	PEST-Operator	***Oper Area Code:***	
Licence Type:	Operator	***Oper Phone No:***	

Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71583333	**Operator Region:**	
Longitude:	-79.81583333	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2809556

---

40 | ***2 of 2*** | ***SW/182.7*** | ***245.9 / 3.92*** | ***RATRO PEST CONTROL INC.***
194 VAN SCOTT DR
BRAMPTON ON L7A 1V8 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-8177870401	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	October 15, 2023	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71583333	**Operator Region:**	
Longitude:	-79.81583333	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3136419

---

41 | ***1 of 3*** | ***SW/183.4*** | ***245.5 / 3.59*** | ***ROXY CONSTRUCTION LTD.***
180 VAN SCOTT DRIVE, UNIT B
BRAMPTON ON L7A 1E4 | ***GEN***

Generator Info

Generator No:	ON0385901	**Choice of Contact:**	
Approval Years:	94,95,96,97	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6351
Country:			
Co Admin:			
Phone No Admin:			

SIC Description: GARAGES(GEN. REPAIR)

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252

Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

41 **2 of 3** **SW/183.4** **245.5 / 3.59** **ROXY CONSTRUCTION LTD.(OUT OF BUSINESS)**
180 VAN SCOTT DRIVE, UNIT B
BRAMPTON ON L7A 1E4 **GEN**

Generator Info

Generator No: ON0385901
Approval Years: 98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: GARAGES(GEN. REPAIR)

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6351

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

41 **3 of 3** **SW/183.4** **245.5 / 3.59** **ROXY CONSTRUCTION LTD.(OUT OF BUSINESS)**
180 VAN SCOTT DRIVE UNIT B
BRAMPTON ON L7A 1E4 **GEN**

Generator Info

Generator No: ON0385901
Approval Years: 99
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: OTHER IND. CONSTR.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4119

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

42 | **1 of 20** | **S/102.1** | **238.9 / -3.08** | **Corporation Of The City Of Brampton**
130 Sandalwood Pkwy West
Brampton ON L7A 0L1 | **GEN**

Generator Info

Generator No: ON6992416
Approval Years: 07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Urban Transit Systems

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 485110

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

42 | **2 of 20** | **S/102.1** | **238.9 / -3.08** | **Corporation Of The City Of Brampton**
130 Sandalwood Pkwy West
Brampton ON L7A 0L1 | **GEN**

Generator Info

Generator No: ON6992416
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 485110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: Urban Transit Systems

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

42 | ***3 of 20*** | ***S/102.1*** | ***238.9 / -3.08*** | ***Corporation Of The City Of Brampton***
130 Sandalwood Pkwy West
Brampton ON L7A 0L1 | ***GEN***

Generator Info

Generator No: ON6992416
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Urban Transit Systems

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 485110

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

42 | ***4 of 20*** | ***S/102.1*** | ***238.9 / -3.08*** | ***Corporation Of The City Of Brampton***
130 Sandalwood Pkwy West
Brampton ON L7A 0L1 | ***GEN***

Generator Info

Generator No:	ON6992416	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	485110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Urban Transit Systems		

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

---

42 ***5 of 20*** ***S/102.1*** ***238.9 / -3.08*** ***Corporation Of The City Of Brampton*** ***GEN***
130 Sandalwood Pkwy West
Brampton ON L7A 0L1

Generator Info

Generator No:	ON6992416	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	485110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Urban Transit Systems		

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

42 | ***6 of 20*** | ***S/102.1*** | ***238.9 / -3.08*** | ***Corporation Of The City Of Brampton*** | ***GEN***
130 Sandalwood Pkwy West
Brampton ON

Generator Info

Generator No:	ON6992416	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	485110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

42 | ***7 of 20*** | ***S/102.1*** | ***238.9 / -3.08*** | ***THE CORPORATION OF THE CITY OF BRAMPTON*** | ***EASR***
130 Sandalwood PKY W
Brampton ON L7A 1L2

Approval No:	R-002-1480312432	***MOE District:***	Halton-Peel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: REGISTERED
Date: 2015-01-29
Record Type: EASR
Link Source: MOFA
Project Type: Standby Power System
Full Address:
Approval Type: EASR-Standby Power System
SWP Area Name: Toronto
PDF NAICS Code:
PDF URL:
PDF Site Location:

Municipality: Brampton
Latitude: 43.71361111
Longitude: -79.80777778
Geometry X:
Geometry Y:

---

42 | 8 of 20 | S/102.1 | 238.9 / -3.08 | **THE CORPORATION OF THE CITY OF BRAMPTON**
130 Sandalwood PKY W
Brampton ON L7A 1L2 | EASR

Approval No: R-003-8480492100
Status: REGISTERED
Date: 2015-01-29
Record Type: EASR
Link Source: MOFA
Project Type: Heating System
Full Address:
Approval Type: EASR-Heating System
SWP Area Name: Toronto
PDF NAICS Code:
PDF URL:
PDF Site Location:

MOE District: Halton-Peel
Municipality: Brampton
Latitude: 43.71361111
Longitude: -79.80777778
Geometry X:
Geometry Y:

---

42 | 9 of 20 | S/102.1 | 238.9 / -3.08 | **City of Brampton**
130 Sandalwood Pkwy W, Brampton CITY OF BRAMPTON
ON | EBR

EBR Registry No: 012-8297
Ministry Ref No: SR 1899870
Notice Type: Instrument Decision
Notice Stage:
Notice Date: August 31, 2016
Proposal Date: July 29, 2016
Year: 2016
Instrument Type: (Liquid Fuels Handling Code) - Liquid Fuels Handling Code Section
Off Instrument Name:
Posted By:
Company Name: City of Brampton
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2 Wellington Street West, Brampton Ontario, Canada L6Y 4R2
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

130 Sandalwood Pkwy W, Brampton CITY OF BRAMPTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	10 of 20	S/102.1	238.9 / -3.08	Corporation Of The City Of Brampton 130 Sandalwood Pkwy West Brampton ON L7A0L1	GEN

Generator Info

Generator No:	ON6992416	***Choice of Contact:***	CO_ADMIN
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	485110
Country:	Canada		
Co Admin:	Dale A Morin		
Phone No Admin:	905-874-2750 Ext.62314		
SIC Description:	485110		

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	11 of 20	S/102.1	238.9 / -3.08	Corporation Of The City Of Brampton 130 Sandalwood Pkwy West Brampton ON L7A0L1	GEN

Generator Info

Generator No:	ON6992416	***Choice of Contact:***	CO_ADMIN
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	485110
Country:	Canada		

Co Admin: Dale A Morin
Phone No Admin: 905-874-2750 Ext.2648
SIC Description: 485110

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

42 | ***12 of 20*** | ***S/102.1*** | ***238.9 / -3.08*** | ***Corporation Of The City Of Brampton***
130 Sandalwood Pkwy West
Brampton ON L7A0L1 | ***GEN***

Generator Info

Generator No: ON6992416
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Dale A Morin
Phone No Admin: 905-874-2750 Ext.2648
SIC Description: 485110

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 485110

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

42 | **13 of 20** | **S/102.1** | **238.9 / -3.08** | **Corporation Of The City Of Brampton Works & Transportation**
130 Sandalwood Pkwy West
Brampton ON L7A0L1 | **GEN**

Generator Info

Generator No: ON6992416
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

42 | **14 of 20** | **S/102.1** | **238.9 / -3.08** | **The Corporation of the City of Brampton**
130 Sandalwood Pky W
Brampton ON L6Y 4R2 | **ECA**

Approval No: 2870-AAJR5X
Approval Date: 2017-09-01
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: The Corporation of the City of Brampton
Address: 130 Sandalwood Pky W
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4860-A7DRSR-14.pdf
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

---

42 | **15 of 20** | **S/102.1** | **238.9 / -3.08** | **Corporation Of The City Of Brampton Works & Transportation**
130 Sandalwood Pkwy West
Brampton ON L7A0L1 | **GEN**

Generator Info

Generator No: ON6992416
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	16 of 20	S/102.1	238.9 / -3.08	***Corporation Of The City Of Brampton Works & Transportation*** ***130 Sandalwood Pkwy West*** ***Brampton ON L7A0L1***	GEN

Generator Info

Generator No: ON6992416
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

---

42 | ***17 of 20*** | ***S/102.1*** | ***238.9 / -3.08*** | ***THE CORPORATION OF THE CITY OF BRAMPTON*** ***130 Sandalwood PKY W*** ***Brampton ON L7A 1L2*** | ***EASR***

Approval No:	R-010-4113463657	***MOE District:***	Halton-Peel
Status:	REGISTERED	***Municipality:***	Brampton
Date:	2021-09-29	***Latitude:***	43.71611111
Record Type:	EASR	***Longitude:***	-79.81
Link Source:	MOFA	***Geometry X:***	-8884408.5602000002
Project Type:	Air Emissions	***Geometry Y:***	5421614.3149000024
Full Address:			
Approval Type:	EASR-Air Emissions		
SWP Area Name:	Toronto		
PDF NAICS Code:	488490		
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2490289		
PDF Site Location:	130 Sandalwood Parkway West Brampton ON L7A 1L2		

---

42 | ***18 of 20*** | ***S/102.1*** | ***238.9 / -3.08*** | ***Belfor Property Restoration*** ***130 Sandalwood Parkway West*** ***Brampton ON L7A 1A8*** | ***GEN***

Generator Info

Generator No:	ON7476229	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

2021 Generator Info

Gen No:	ON7476229	***Choice of Contact:***	CO_OFFICIAL
ID:	30425	***Phone No Official:***	9055645777 Ext.217
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	236110	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	Belfor Property Restoration
Gen Div:	
Gen Op Name:	Belfor Property Restoration
Gen Op Div:	
Site Adrs1:	130 Sandalwood Parkway West
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1A8
Site Country:	Canada
Co Official:	Cheryl Belfor Property Restorati Stern
Co Admin:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	19 of 20	S/102.1	238.9 / -3.08	***City of Brampton*** ***Brampton Transit - Sandalwood, 130 Sandalwood Pkwy West*** ***Brampton ON***	GEN

Generator Info

Generator No:	ON6992416	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	221 I
Waste Class Name:	LIGHT FUELS

Waste Detail(s)

Waste Class:	331 I
Waste Class Name:	WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class:	122 C

Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No: ON6992416
Generator Company Name: City of Brampton
Street: Brampton Transit - Sandalwood, 130 Sandalwood Pkwy West
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A0L1
Waste Class: 212 I,148 I,148 C,252 L,251 L,212 L,122 C,331 I,221 I,145 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 252 - WASTE OILS & LUBRICANTS; 251 - OIL SKIMMINGS & SLUDGES; 212 - ALIPHATIC SOLVENTS; 122 - ALKALINE WASTES - OTHER METALS; 331 - WASTE COMPRESSED GASES; 221 - LIGHT FUELS; 145 - PAINT/PIGMENT/COATING RESIDUES

2017 Generator Info

Gen No: ON6992416
ID: 27460
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 485110
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_ADMIN
Phone No Official: 905-874-2333 Ext.
Phone No Admin: 6473890679 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

Gen Name: Corporation Of The City Of Brampton
Gen Div: Works & Transportation
Gen Op Name: Brampton Transit
Gen Op Div: Sandalwood
Site Adrs1: 130 Sandalwood Pkwy West
Site Bldg: Brampton Transit - Sandalwood
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A0L1
Site Country: Canada
Co Official: JIM JOUKEMA
Co Admin: William M

2017 Generator Manifest

ID: 53645
Generator No: ON6992416
Receiver Type: 035
Waste Char: L
Waste Code: 251

Sum Received Qty: 77520.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 8
District: 305

2017 Generator Manifest

ID: 53640
Generator No: ON6992416
Receiver Type: 030
Waste Char: L
Waste Code: 252

Sum Received Qty: 368.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 201

2017 Generator Manifest

ID: 53641
Generator No: ON6992416
Receiver Type: 035
Waste Char: I
Waste Code: 145

Sum Received Qty: 200.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 201

2017 Generator Manifest

ID: 53643
Generator No: ON6992416
Receiver Type: 035
Waste Char: L
Waste Code: 251

Sum Received Qty: 10626.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 2
District: 301

2017 Generator Manifest

ID: 53644
Generator No: ON6992416
Receiver Type: 035
Waste Char: L
Waste Code: 212

Sum Received Qty: 2915.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 3
District: 305

2017 Generator Manifest

ID: 53646
Generator No: ON6992416
Receiver Type: 035
Waste Char: L
Waste Code: 252

Sum Received Qty: 31789.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 8
District: 305

2017 Generator Manifest

ID: 53639
Generator No: ON6992416
Receiver Type: 030
Waste Char: L
Waste Code: 221

Sum Received Qty: 192.0
Waste Class Name: LIGHT FUELS
Count Manifests: 1
District: 201

2017 Generator Manifest

ID: 53642
Generator No: ON6992416
Receiver Type: 035

Sum Received Qty: 1000.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1

Waste Char:	L	**District:**	202
Waste Code:	251		

2018 Generator Info

Gen No:	ON6992416	**Choice of Contact:**	CO_ADMIN
ID:	27881	**Phone No Official:**	905-874-2333 Ext.
Contaminated Fac:	N	**Phone No Admin:**	6473890679 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	485110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Corporation Of The City Of Brampton		
Gen Div:	Works & Transportation		
Gen Op Name:	Brampton Transit		
Gen Op Div:	Sandalwood		
Site Adrs1:	130 Sandalwood Pkwy West		
Site Bldg:	Brampton Transit - Sandalwood		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A0L1		
Site Country:	Canada		
Co Official:	JIM JOUKEMA		
Co Admin:	William M		

2018 Generator Manifest

ID:	53634	**Sum Received Qty:**	9400.0
Generator No:	ON6992416	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	251		

2018 Generator Manifest

ID:	53632	**Sum Received Qty:**	78170.0
Generator No:	ON6992416	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	13
Waste Char:	L	**District:**	301
Waste Code:	251		

2018 Generator Manifest

ID:	53633	**Sum Received Qty:**	5000.0
Generator No:	ON6992416	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	5
Waste Char:	L	**District:**	305
Waste Code:	212		

2018 Generator Manifest

ID:	53635	**Sum Received Qty:**	34191.0
Generator No:	ON6992416	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	10
Waste Char:	L	**District:**	305
Waste Code:	252		

2019 Generator Info

Gen No:	ON6992416	**Choice of Contact:**	CO_ADMIN
ID:	28151	**Phone No Official:**	905-874-2333 Ext.
Contaminated Fac:	N	**Phone No Admin:**	6473890679 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	485110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Corporation Of The City Of Brampton		
Gen Div:	Works & Transportation		
Gen Op Name:	Brampton Transit		
Gen Op Div:	Sandalwood		
Site Adrs1:	130 Sandalwood Pkwy West		
Site Bldg:	Brampton Transit - Sandalwood		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A0L1		
Site Country:	Canada		
Co Official:	JIM JOUKEMA		
Co Admin:	William M		

2019 Generator Manifest

ID:	53569	**Sum Received Qty:**	205.0
Generator No:	ON6992416	**Waste Class Name:**	LIGHT FUELS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	I	**District:**	305
Waste Code:	221		

2019 Generator Manifest

ID:	53566	**Sum Received Qty:**	5170.0
Generator No:	ON6992416	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	301
Waste Code:	146		

2019 Generator Manifest

ID:	53568	**Sum Received Qty:**	5000.0
Generator No:	ON6992416	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	5
Waste Char:	L	**District:**	305
Waste Code:	212		

2019 Generator Manifest

ID:	53570	**Sum Received Qty:**	98043.0
Generator No:	ON6992416	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	11
Waste Char:	L	**District:**	305
Waste Code:	251		

2019 Generator Manifest

ID:	53571	**Sum Received Qty:**	35408.0
Generator No:	ON6992416	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	11
Waste Char:	L	**District:**	305

Waste Code: 252

2019 Generator Manifest

ID: 53565
Generator No: ON6992416
Receiver Type: 035
Waste Char: I
Waste Code: 145
Sum Received Qty: 320.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 202

2019 Generator Manifest

ID: 53567
Generator No: ON6992416
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 35090.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 5
District: 301

2020 Generator Info

Gen No: ON6992416
ID: 27855
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 485110
NAICS Code2:
NAICS Code3:
Gen Name: Corporation Of The City Of Brampton
Gen Div: Works & Transportation
Gen Op Name: Brampton Transit
Gen Op Div: Sandalwood
Site Adrs1: 130 Sandalwood Pkwy West
Site Bldg: Brampton Transit - Sandalwood
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A0L1
Site Country: Canada
Co Official: JIM JOUKEMA
Co Admin: William M
Choice of Contact: CO_ADMIN
Phone No Official: 905-874-2333 Ext.
Phone No Admin: 6473890679 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2020 Generator Manifest

ID: 50020
Generator No: ON6992416
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 27230.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 4
District: 301

2020 Generator Manifest

ID: 50018
Generator No: ON6992416
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 250.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 202

2020 Generator Manifest

ID:	50021	**Sum Received Qty:**	4000.0
Generator No:	ON6992416	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	302
Waste Code:	146		

2020 Generator Manifest

ID:	50017	**Sum Received Qty:**	480.0
Generator No:	ON6992416	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	I	**District:**	202
Waste Code:	145		

2020 Generator Manifest

ID:	50023	**Sum Received Qty:**	93275.0
Generator No:	ON6992416	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	8
Waste Char:	L	**District:**	305
Waste Code:	251		

2020 Generator Manifest

ID:	50024	**Sum Received Qty:**	37908.0
Generator No:	ON6992416	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	10
Waste Char:	L	**District:**	305
Waste Code:	252		

2020 Generator Manifest

ID:	50022	**Sum Received Qty:**	4824.0
Generator No:	ON6992416	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	5
Waste Char:	L	**District:**	305
Waste Code:	212		

2020 Generator Manifest

ID:	50019	**Sum Received Qty:**	21480.0
Generator No:	ON6992416	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	301
Waste Code:	146		

2020 Generator Manifest

ID:	50025	**Sum Received Qty:**	24000.0
Generator No:	ON6992416	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	L	**District:**	306
Waste Code:	251		

2021 Generator Info

Gen No:	ON6992416	**Choice of Contact:**	CO_ADMIN
ID:	28366	**Phone No Official:**	905-874-2333 Ext.
Contaminated Fac:	N	**Phone No Admin:**	6473890679 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)

NAICS Code1:	485110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Corporation Of The City Of Brampton		
Gen Div:	Works & Transportation		
Gen Op Name:	Brampton Transit		
Gen Op Div:	Sandalwood		
Site Adrs1:	130 Sandalwood Pkwy West		
Site Bldg:	Brampton Transit - Sandalwood		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A0L1		
Site Country:	Canada		
Co Official:	JIM JOUKEMA		
Co Admin:	William M		

2021 Generator Manifest

ID:	51983	**Sum Received Qty:**	820.0
Generator No:	ON6992416	**Waste Class Name:**	LIGHT FUELS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	I	**District:**	305
Waste Code:	221		

2021 Generator Manifest

ID:	51985	**Sum Received Qty:**	39894.0
Generator No:	ON6992416	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	12
Waste Char:	L	**District:**	305
Waste Code:	252		

2021 Generator Manifest

ID:	51982	**Sum Received Qty:**	8789.0
Generator No:	ON6992416	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	5
Waste Char:	L	**District:**	305
Waste Code:	212		

2021 Generator Manifest

ID:	51984	**Sum Received Qty:**	183705.0
Generator No:	ON6992416	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	16
Waste Char:	L	**District:**	305
Waste Code:	251		

42	***20 of 20***	***S/102.1***	***238.9 / -3.08***	***Brampton Transit*** ***130 Sandalwood Parkway West*** ***Brampton ON***	***GEN***

Generator Info as of Dec 2024

Generator No:	ONS0305-1-5QTFUA-1
Generator Company Name:	Brampton Transit
Street:	130 Sandalwood Parkway West

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A 0L1
Waste Class: 221 L

Waste Class Decoded:

221 - LIGHT FUELS

---

43 | ***1 of 1*** | ***WSW/198.0*** | ***244.9 / 2.91*** | ***34 Burnt Elm Dr, Brampton BRAMPTON ON*** | ***SPL***

Ref No: 1-4TN36P
Year:
Incident Dt: Mar 06,2024 09:20:00 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: Mar 06,2024 10:32:32 PM
Dt Document Closed: Mar 12,2024 12:49:21 PM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 34 Burnt Elm Dr, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type: Unknown / N/A
Incident Cause:
Incident Preceding Spill:
Incident Reason:
Incident Summary: RoP: oil in catch basin in Brampton, cleaning
Environment Impact:
Health Env Consequence: Low
Nature of Impact:
Contaminant Qty: 1 other - see notes
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: % OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Surface Water
Activity Preceding Spill:
Property 2nd Watershed: 02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed: 02HB | Sixteen Mile Creek - Credit River
Sector Type:
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001932546"],"wkts":["POINT (-79.8188405000 43.7177103000)"],"creation_date":"2024-03-06"}
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

44 | 1 of 1 | W/26.8 | 247.9 / 5.92 | ON | BORE

Borehole ID: 637336
OGF ID: 215537733
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: APR-1966
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 4.6
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 248
Elev Reliabil Note:
DEM Ground Elev m: 246
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.721731
Longitude DD: -79.820401
UTM Zone: 17
Easting: 595015
Northing: 4841643
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218480522
Top Depth: 0
Bottom Depth: .3
Material Color:
Material 1: Soil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218480523
Top Depth: .3
Bottom Depth: 3.1
Material Color: Brown
Material 1: Till
Material 2: Silt
Material 3: Sand
Material 4: Clay
Gsc Material Description:
Stratum Description: TILL,SILT,SAND,CLAY.BROWN,GLACIAL,HARD, AGE GLACIAL.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218480524
Top Depth: 3.1
Bottom Depth: 4.6
Material Color: Brown
Material 1: Till
Material 2: Silt
Material 3: Sand
Material 4: Clay
Gsc Material Description:
Stratum Description: TILL,SILT,SAND,CLAY.BROWN,GLACIAL,HARD, AGE GLACIAL. 0001004000103050AGE GLACIAL **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Source

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: H
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1B.txt RecordID: 052990 NTS_Sheet: 30M12F
Confiden 1: Logged by professional. Exact and complete description of material and properties.
Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

45 **1 of 5** **W/167.3** **248.9 / 6.92** **PES**

PREMIER TURF INC
39 PAPPAIN CRES
BRAMPTON ON L7A 3J8

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

45 **2 of 5** **W/167.3** **248.9 / 6.92** **PES**

PREMIER TURF INC
39 PAPPAIN CRES
BRAMPTON ON L7A 3J8

Detail Licence No: 02-01-07199-0
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: OPERATOR
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Trade Name:
PDF URL:

---

45 **3 of 5** **W/167.3** **248.9 / 6.92** **PES**

PREMIER TURF INC
39 PAPPAIN CRES
BRAMPTON ON L7A3J8

Detail Licence No:	02-01-04324-0	**Operator Box:**	
Licence No:	04324	**Operator Class:**	
Status:		**Operator No:**	4324
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	4203906
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	
Lot:		**Operator County:**	49
Concession:		**Op Municipality:**	
Region:	3	**Post Office Box:**	
District:		**MOE District:**	
County:	49	**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

45 **4 of 5** **W/167.3** **248.9 / 6.92** **PES**

PREMIER TURF INC
39 PAPPAIN CRES
BRAMPTON ON L7A3J8

Detail Licence No:		**Operator Box:**	
Licence No:	07199	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	4203906
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

45 **5 of 5** **W/167.3** **248.9 / 6.92** **PES**

PREMIER TURF INC
39 PAPPAIN CRES
BRAMPTON ON L7A3J8

Detail Licence No:		**Operator Box:**	
Licence No:	04324	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	4203906
Licence Type Code:	01	**Operator Ext:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Class:	06		**Operator Lot:**	
Licence Control:			**Oper Concession:**	
Latitude:			**Operator Region:**	
Longitude:			**Operator District:**	
Lot:			**Operator County:**	
Concession:			**Op Municipality:**	
Region:			**Post Office Box:**	
District:			**MOE District:**	
County:			**SWP Area Name:**	
Trade Name:				
PDF URL:				

46 | **1 of 1** | **SSE/167.2** | **239.1 / -2.80** | **The Corporation of The City og Brampton**
95 Sandelwood Pkwy.
Brampton ON | **GEN**

Generator Info

Generator No:	ON9795760	**Choice of Contact:**	
Approval Years:	2013	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	913910
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

47 | **1 of 1** | **W/57.3** | **247.9 / 5.92** | **lot 16 con 1**
ON | **WWIS**

Well ID:	4901595	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Commerical	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	07/05/1966
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1307
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	016
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901595.pdf

Additional Detail(s) (Map)

Well Completed Date:	06/11/1966
Year Completed:	1966
Depth (m):	7.62
Latitude:	43.7225298949875
Longitude:	-79.8209688541865
X:	-79.82096870429199
Y:	43.7225298933566
Path:	490\4901595.pdf

Bore Hole Information

Bore Hole ID:	10316440	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	594967.50
Code OB Desc:		**North83:**	4841731.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	06/11/1966	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	932034911
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	14.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932034910
Layer:	2
Color:	7
General Color:	RED
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	10.0
Formation End Depth:	14.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932034909
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901595
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10865010
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523065
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	25.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901595
Pump Set At:	
Static Level:	6.0
Final Level After Pumping:	
Recommended Pump Depth:	24.0
Pumping Rate:	5.0
Flowing Rate:	
Recommended Pump Rate:	5.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	
Pumping Duration MIN:	

Flowing: No

Water Details

Water ID: 933789545
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 25.0
Water Found Depth UOM: ft

---

48 | ***1 of 1*** | ***SSE/98.0*** | ***237.9 / -4.08*** | ***PEELLE COMPANY LIMITED, THE 105 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6*** | ***GEN***

Generator Info

Generator No: ON0138401
Approval Years: 02,03,04,05
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Metal Window & Door Mfg.
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 332321

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

49 | ***1 of 1*** | ***S/11.6*** | ***237.9 / -4.08*** | ***156 Twin Pine Cres. Brampton ON*** | ***SPL***

Ref No: 3586-9YAQDM
Year:
Incident Dt: 7/10/2015
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/10/2015
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: spill<UNOFFICIAL>
Site Address: 156 Twin Pine Cres.
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4835213
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Easting:	567249
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	Maintenance
Incident Summary:	Hydraulic oil 20 L spill, CB impacted cleaning
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	20 L
Contaminant Qty 1:	20
Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	HYDRAULIC OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

50 | ***1 of 8*** | ***S/16.7*** | ***237.9 / -4.08*** | ***Zeta Pest Control Inc.***
154 Twin Pines Crescent
Brampton ON L7A 1N2 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-6051229095	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-04-05	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71305556	**Operator Region:**	
Longitude:	-79.80916667	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2142562		

50 | ***2 of 8*** | ***S/16.7*** | ***237.9 / -4.08*** | ***Zeta Pest Control Inc.***
154 Twin Pines Crescent
Brampton ON L7A 1N2 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-6051229095	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-12-02	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Type:	Operator		**Oper Phone No:**	
Licence Type Code:			**Operator Ext:**	
Licence Class:			**Operator Lot:**	
Licence Control:			**Oper Concession:**	
Latitude:	43.71305556		**Operator Region:**	
Longitude:	-79.80916667		**Operator District:**	
Lot:			**Operator County:**	
Concession:			**Op Municipality:**	
Region:			**Post Office Box:**	
District:			**MOE District:**	Halton-Peel
County:			**SWP Area Name:**	Credit Valley
Trade Name:				
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2196737			

50	3 of 8	S/16.7	237.9 / -4.08	**Zeta Pest Control Inc.** **154 Twin Pines Crescent** **Brampton ON L7A 1N2**	PES

Detail Licence No:			**Operator Box:**	
Licence No:	L-240-6051229095		**Operator Class:**	
Status:	Active		**Operator No:**	
Approval Date:	2020-11-02		**Operator Type:**	
Report Source:	PEST-Operator		**Oper Area Code:**	
Licence Type:	Operator		**Oper Phone No:**	
Licence Type Code:			**Operator Ext:**	
Licence Class:			**Operator Lot:**	
Licence Control:			**Oper Concession:**	
Latitude:	43.71305556		**Operator Region:**	
Longitude:	-79.80916667		**Operator District:**	
Lot:			**Operator County:**	
Concession:			**Op Municipality:**	
Region:			**Post Office Box:**	
District:			**MOE District:**	Halton-Peel
County:			**SWP Area Name:**	Credit Valley
Trade Name:				
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2299985			

50	4 of 8	S/16.7	237.9 / -4.08	**154 Twin Pines Crescent** **Brampton ON L7A 1N2**	PES

Detail Licence No:			**Operator Box:**	
Licence No:	L-240-6051229095		**Operator Class:**	
Status:	Active		**Operator No:**	
Approval Date:	December, 19 2021		**Operator Type:**	
Report Source:	PEST-Operator		**Oper Area Code:**	
Licence Type:	Operator		**Oper Phone No:**	
Licence Type Code:			**Operator Ext:**	
Licence Class:			**Operator Lot:**	
Licence Control:			**Oper Concession:**	
Latitude:	43.71305556		**Operator Region:**	
Longitude:	-79.80916667		**Operator District:**	
Lot:			**Operator County:**	
Concession:			**Op Municipality:**	
Region:			**Post Office Box:**	
District:			**MOE District:**	Halton-Peel
County:			**SWP Area Name:**	Credit Valley
Trade Name:				
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2546786			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	5 of 8	S/16.7	237.9 / -4.08	Zeta Pest Control Inc. 154 Twin Pines Crescent Brampton ON L7A 1N2	PES

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-6051229095	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	November 24, 2022	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71305556	**Operator Region:**	
Longitude:	-79.80916667	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2792307

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	6 of 8	S/16.7	237.9 / -4.08	Zeta Pest Control Inc. 154 Twin Pines Crescent Brampton ON L7A 1N2	PES

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-6051229095	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	November 12, 2023	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71305556	**Operator Region:**	
Longitude:	-79.80916667	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3181077

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	7 of 8	S/16.7	237.9 / -4.08	Zeta Pest Control Inc. 154 Twin Pines Crescent Brampton ON L7A 1N2	PES

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-6051229095	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	December 31, 2024	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71305556	**Operator Region:**	
Longitude:	-79.80916667	**Operator District:**	
Lot:		**Operator County:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3825809		

---

50 | **8 of 8** | **S/16.7** | **237.9 / -4.08** | **Zeta Pest Control Inc.**
154 Twin Pines Crescent
Brampton ON L7A 1N2 | **PES**

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-6051229095	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	April 27, 2025	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71305556	**Operator Region:**	
Longitude:	-79.80916667	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=4030538		

---

51 | **1 of 1** | **SSE/150.7** | **238.3 / -3.67** | **175 SANDALWOOD PARKWAY W lot 13 con 1**
BRAMPTON ON | **WWIS**

Well ID:	7219199	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	04/16/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z181996	**Contractor:**	7201
Tag:	A150896	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	013
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7219199.pdf

Additional Detail(s) (Map)

Well Completed Date:	02/24/2014
Year Completed:	2014
Depth (m):	5.334

Latitude:	43.7131678378826
Longitude:	-79.8064118983658
X:	-79.80641174773999
Y:	43.7131678364029
Path:	721\7219199.pdf

Bore Hole Information

Bore Hole ID:	1004731521	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596155.00
Code OB Desc:		**North83:**	4840708.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/24/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	gis
Location Method Desc:	from gis		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005136634
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	15.0
Formation End Depth:	17.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005136633
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	0.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005136643
Layer: 3
Plug From: 11.5
Plug To: 17.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005136642
Layer: 2
Plug From: 1.0
Plug To: 11.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005136641
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1005136640
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005136632
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005136637
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 12.5
Casing Diameter: 0.75
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005136638
Layer: 1
Slot:
Screen Top Depth: 12.5
Screen End Depth: 17.5
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch

Screen Diameter: 0.75

Water Details

Water ID: 1005136636
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005136635
Diameter: 8.25
Depth From: 0.0
Depth To: 17.5
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

52 ***1 of 4*** ***W/19.8*** ***247.9 / 5.92*** ***Brampton West 6-2 Limited*** ***ECA***

Brampton ON M3B 2T5

Approval No: 2360-6A2LYC
Approval Date: 2005-03-02
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Brampton West 6-2 Limited
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9645-69VR3M-14.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.822
Latitude: 43.7228
Geometry X:
Geometry Y:

---

52 ***2 of 4*** ***W/19.8*** ***247.9 / 5.92*** ***Brampton West 6-2 Limited*** ***ECA***

Brampton ON M3B 2T5

Approval No: 2497-6A2M5M
Approval Date: 2005-03-02
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: Brampton West 6-2 Limited
Address:
Full Address:
Full PDF Link:
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.822
Latitude: 43.7228
Geometry X:
Geometry Y:

---

52 ***3 of 4*** ***W/19.8*** ***247.9 / 5.92*** ***Brampton West 6-2 Limited*** ***ECA***

Brampton ON M3B 2T5

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No:	7197-6AKME4	**MOE District:**	Halton-Peel
Approval Date:	2005-04-04	**City:**	
Status:	Approved	**Longitude:**	-79.822
Record Type:	ECA	**Latitude:**	43.7228
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Brampton West 6-2 Limited		
Address:			
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/5574-69DK5M-14.pdf		
PDF Site Location:			

---

52 | ***4 of 4*** | ***W/19.8*** | ***247.9 / 5.92*** | ***Brampton West 6-2 Limited***
McLaughlin Road (from Wanless Drive to approximately 240m south of Wanless Drive)
Brampton ON M3B 2T5 | ***ECA***

Approval No:	1179-6E3NZ9	**MOE District:**	Halton-Peel
Approval Date:	2005-07-08	**City:**	
Status:	Approved	**Longitude:**	-79.822
Record Type:	ECA	**Latitude:**	43.7228
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Brampton West 6-2 Limited		
Address:	McLaughlin Road (from Wanless Drive to approximately 240m south of Wanless Drive)		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4337-6DYL47-14.pdf		
PDF Site Location:			

---

53 | ***1 of 14*** | ***S/130.3*** | ***238.3 / -3.62*** | ***CANADA PEST CONTROL INC.***
11 TINSMITH ST
BRAMPTON ON L7A 1N3 | ***PES***

Detail Licence No:	02-01-07034-0	**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	OPERATOR	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

53 | ***2 of 14*** | ***S/130.3*** | ***238.3 / -3.62*** | ***CANADA PEST CONTROL INC.***
11 TINSMITH ST
BRAMPTON ON L7A1N3 | ***PES***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail Licence No:		**Operator Box:**	
Licence No:	08748	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	5650505
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
53	3 of 14	S/130.3	238.3 / -3.62	CANADA PEST CONTROL INC. 11 TINSMITH ST BRAMPTON ON L7A1N3	PES

Detail Licence No:		**Operator Box:**	
Licence No:	09190	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	5650505
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
53	4 of 14	S/130.3	238.3 / -3.62	CANADA PEST CONTROL INC. 11 TINSMITH ST BRAMPTON ON L7A1N3	PES

Detail Licence No:		**Operator Box:**	
Licence No:	10053	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	5650505
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	

Trade Name:
PDF URL:

---

53 ***5 of 14*** ***S/130.3*** ***238.3 / -3.62*** ***CANADA PEST CONTROL INC.*** ***PES***
11 TINSMITH ST
BRAMPTON ON L7A1N3

Detail Licence No:		***Operator Box:***	
Licence No:	08359	***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:	Legacy Licenses (Excluding TS)	***Oper Area Code:***	416
Licence Type:	Operator	***Oper Phone No:***	5650505
Licence Type Code:	02	***Operator Ext:***	
Licence Class:	01	***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

---

53 ***6 of 14*** ***S/130.3*** ***238.3 / -3.62*** ***CANADA PEST CONTROL INC.*** ***PES***
11 TINSMITH ST
BRAMPTON ON L7A1N3

Detail Licence No:		***Operator Box:***	
Licence No:	07034	***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:	Legacy Licenses (Excluding TS)	***Oper Area Code:***	416
Licence Type:	Operator	***Oper Phone No:***	5650505
Licence Type Code:	02	***Operator Ext:***	
Licence Class:	01	***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

---

53 ***7 of 14*** ***S/130.3*** ***238.3 / -3.62*** ***CANADA PEST CONTROL INC.*** ***PES***
11 TINSMITH ST
BRAMPTON ON L7A1N3

Detail Licence No:		***Operator Box:***	
Licence No:	07858	***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:	Legacy Licenses (Excluding TS)	***Oper Area Code:***	416
Licence Type:	Operator	***Oper Phone No:***	5650505
Licence Type Code:	02	***Operator Ext:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Class:	01		**Operator Lot:**	
Licence Control:			**Oper Concession:**	
Latitude:			**Operator Region:**	
Longitude:			**Operator District:**	
Lot:			**Operator County:**	
Concession:			**Op Municipality:**	
Region:			**Post Office Box:**	
District:			**MOE District:**	
County:			**SWP Area Name:**	
Trade Name:				
PDF URL:				

---

53 | ***8 of 14*** | ***S/130.3*** | ***238.3 / -3.62*** | ***CANADA PEST CONTROL INC.***
11 TINSMITH ST
brampton ON L7A 1N3 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-4043186894	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-02-06	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71277778	**Operator Region:**	
Longitude:	-79.81083333	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2123611		

---

53 | ***9 of 14*** | ***S/130.3*** | ***238.3 / -3.62*** | ***CANADA PEST CONTROL INC.***
11 TINSMITH ST
brampton ON L7A 1N3 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-4043186894	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-12-29	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.71277778	**Operator Region:**	
Longitude:	-79.81083333	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2204420		

---

53 | ***10 of 14*** | ***S/130.3*** | ***238.3 / -3.62*** | ***CANADA PEST CONTROL INC.***
11 TINSMITH ST | ***PES***

brampton ON L7A 1N3

Detail Licence No:		***Operator Box:***	
Licence No:	L-240-4043186894	***Operator Class:***	
Status:	Active	***Operator No:***	
Approval Date:	2020-12-31	***Operator Type:***	
Report Source:	PEST-Operator	***Oper Area Code:***	
Licence Type:	Operator	***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:	43.71277778	***Operator Region:***	
Longitude:	-79.81083333	***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	Halton-Peel
County:		***SWP Area Name:***	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2322307

---

53 | ***11 of 14*** | ***S/130.3*** | ***238.3 / -3.62*** | ***11 TINSMITH ST brampton ON L7A 1N3*** | ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:	L-240-4043186894	***Operator Class:***	
Status:	Active	***Operator No:***	
Approval Date:	January 5, 2022	***Operator Type:***	
Report Source:	PEST-Operator	***Oper Area Code:***	
Licence Type:	Operator	***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:	43.71277778	***Operator Region:***	
Longitude:	-79.81083333	***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	Halton-Peel
County:		***SWP Area Name:***	Credit Valley
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2551858

---

53 | ***12 of 14*** | ***S/130.3*** | ***238.3 / -3.62*** | ***CANADA PEST CONTROL INC. 11 TINSMITH ST brampton ON L7A 1N3*** | ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:	L-240-4043186894	***Operator Class:***	
Status:	Active	***Operator No:***	
Approval Date:	December 24, 2022	***Operator Type:***	
Report Source:	PEST-Operator	***Oper Area Code:***	
Licence Type:	Operator	***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:	43.71277778	***Operator Region:***	
Longitude:	-79.81083333	***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	Halton-Peel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

County: **SWP Area Name:** Credit Valley
Trade Name:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2822032

---

53 | **13 of 14** | **S/130.3** | **238.3 / -3.62** | **CANADA PEST CONTROL INC.**
11 TINSMITH ST
brampton ON L7A 1N3 | **PES**

Detail Licence No:
Licence No: L-240-4043186894
Status: Active
Approval Date: December 28, 2023
Report Source: PEST-Operator
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude: 43.71277778
Longitude: -79.81083333
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3247952

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District: Halton-Peel
SWP Area Name: Credit Valley

---

53 | **14 of 14** | **S/130.3** | **238.3 / -3.62** | **CANADA PEST CONTROL INC.**
11 TINSMITH ST
brampton ON L7A 1N3 | **PES**

Detail Licence No:
Licence No: L-240-4043186894
Status: Active
Approval Date: December 29, 2024
Report Source: PEST-Operator
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude: 43.71277778
Longitude: -79.81083333
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3824194

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District: Halton-Peel
SWP Area Name: Credit Valley

---

54 | **1 of 1** | **SSE/154.8** | **237.7 / -4.22** | **lot 13 con 1**
ON | **WWIS**

Well ID: 7335999
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 06/26/2019
Selected Flag: TRUE
Abandonment Rec:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Audit No:	C45860	**Contractor:**	7215
Tag:	A269235	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	013
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1007499259	**Tag No:**	A269235
Depth M:		**Contractor:**	7215
Year Completed:	2019	**Latitude:**	43.7128290595058
Well Completed Dt:	05/28/2019	**Longitude:**	-79.8058724503583
Audit No:	C45860	**Y:**	43.712829058147136
Path:		**X:**	-79.80587229973243

Bore Hole Information

Bore Hole ID:	1007499259	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596199.00
Code OB Desc:		**North83:**	4840671.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/28/2019	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

55 | ***1 of 2*** | ***SSE/121.0*** | ***237.4 / -4.53*** | ***175 Sandalwood Parkway West Brampton ON L7A 1E8*** | ***EHS***

Order No:	23100400896	**Nearest Intersection:**	
Status:	C	**Municipality:**	The Corporation of the City of Brampton
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	10-OCT-23	**Search Radius (km):**	.25
Date Received:	04-OCT-23	**X:**	-79.80633
Previous Site Name:		**Y:**	43.71273
Lot/Building Size:			
Additional Info Ordered:			

---

55 | ***2 of 2*** | ***SSE/121.0*** | ***237.4 / -4.53*** | ***175 Sandalwood Parkway West Brampton ON L7A 1E8*** | ***EHS***

Order No:	23092600061	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	29-SEP-23	**Search Radius (km):**	.25
Date Received:	26-SEP-23	**X:**	-79.80633

Previous Site Name:				**Y:**	43.71273
Lot/Building Size:					
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos				

56	1 of 49	SSE/119.8	237.0 / -4.90	**BRAMPTON HYDRO-ELECTRIC COMMIS** **175 SANDALWOOD PKWY WEST MOTOR VEHICLE (OPERATING FLUID)** **BRAMPTON CITY ON L7A 1E8**	SPL

Ref No:	80256	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	9/28/1992	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/23/1992	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER CONTAINER LEAK		
Incident Preceding Spill:			
Incident Reason:	NEGLIGENCE (APPARENT)		
Incident Summary:	BACKENTRY,BRAMPTON HYDRO: 40-50L DIESEL FUEL TO GRAVEL YARD.		
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Soil contamination		
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

56	2 of 49	SSE/119.8	237.0 / -4.90	**BRAMPTON HYDRO-ELECTRIC COMMIS** **175 SANDALWOOD PARKWAY WEST MOTOR**	SPL

VEHICLE (OPERATING FLUID)
BRAMPTON CITY ON L7A 1E8

Ref No:	80333	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	9/28/1992	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	11/23/1992	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: OTHER CONTAINER LEAK
Incident Preceding Spill:
Incident Reason: MATERIAL FAILURE
Incident Summary: BACKENTRY- BRAMPTON HYDRO50 L GASOLINE TO GROUND FROM MOTOR VEHICLE
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

56 ***3 of 49*** ***SSE/119.8*** ***237.0 / -4.90*** ***BRAMPTON HYDRO ELECTRIC COMMISSION***
175 SANDALWOOD PKWY W
BRAMPTON ON L7A 1E8 ***PRT***

Location ID: 27743
Type: private
Expiry Date:
Capacity (L): 69174.00
Licence #: 0076440023

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	4 of 49	SSE/119.8	237.0 / -4.90	BRAMPTON HYDRO-ELECTRIC COMMIS 175 SANDALWOOD PARKWAY BRAMPTON CITY ON	SPL

Ref No:	156613	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	5/31/1998	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	6/9/1998	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: COOLING SYSTEM LEAK
Incident Preceding Spill:
Incident Reason: STORM/FLOOD/WIND
Incident Summary: BRAMPTON HYDRO-900 L 30% GLYCOL/WATER MIX TO STORMSEWER FROM SOLAR UNIT.
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Water course or lake
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: WATER
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	5 of 49	SSE/119.8	237.0 / -4.90	BRAMPTON HYDRO 175 SANDALWOOD PKWY SANDALWOOD PKWY BRAMPTON ON L7A 1E8	NPCB

Company Code: F1012
Industry:

Site Status:
Transaction Date:
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code:
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Storage
Contents:

---

56 | ***6 of 49*** | ***SSE/119.8*** | ***237.0 / -4.90*** | ***Safety-Kleen (On-Site) Inc.***
175 Sandalwood Parkway West
Brampton ON N1G 4P5 | ***WDS***

Approval No:	4144-4VPPMP	***Total Area (ha):***	
Mob Unit Cert No:		***Landfill Cap (m³):***	
EBR Registry No:		***Transfer Area (ha):***	
Status:	Approved	***Transfer Cap (m³):***	
Facility Type:		***Transfer Cert No:***	
Record Type:	ECA	***Inciner. Area (ha):***	
Link Source:	IDS	***Inciner. Cap (t):***	
Project Type:	WASTE DISPOSAL SITES	***Process Area (m³):***	
Application Status:		***Process Cap (m³/d):***	
Issue Date:	2001-05-04	***Process Vol (m³):***	
Input Date:		***Process Feed (m³):***	
Date Received:		***Site Concession:***	
Est Closure Date:		***Site Region/County:***	
Mobile Capacity:		***SWP Area Name:***	Toronto
Mobile Units:		***MOE District:***	Halton-Peel
Mobile Description:		***District Office:***	
Prop City:		***Latitude:***	43.712723
Prop Postal:		***Longitude:***	-79.80605
Prop Phone:		***Geometry X:***	
Serial Link:		***Geometry Y:***	

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 175 Sandalwood Parkway West
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/1046-4USKWQ-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	7 of 49	SSE/119.8	237.0 / -4.90	BRAMPTON HYDRO 175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	OPCB

Year: 1998
Site Number: 30292A016
Name Owner:
Additional Site Information:

--Details--
Quantity: 850.00
Address Site:
Description: Weight of Bulk Liquid with High Level PCBs (>1000 ppm) kg

Quantity: 876.00
Address Site:
Description: Weight of Capacitors with High Level PCBs (>1000 ppm) kg

Quantity: 8320.00
Address Site:
Description: Weight of Bulk Liquid with Low Level PCBs (< 1000 ppm) kg

Quantity: 198.00
Address Site:
Description: Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 3.00
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Soil with Low Level PCBs (< 1000 ppm) kg

Quantity: 400.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Soil with Low Level PCBs (< 1000 ppm) kg

Quantity: 900.00
Address Site:
Description: Weight of Soil Not in Drums with Low Level PCBs (< 1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg

Quantity: 150.00
Address Site:
Description: Calculated Weight of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg

Quantity: 688.00
Address Site:
Description: Weight of Other Material Not in Drums with Low Level PCBs (< 1000 ppm) kg

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	8 of 49	SSE/119.8	237.0 / -4.90	BRAMPTON HYDRO 175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	OPCB

Year: 1999
Site Number: 30292A016
Name Owner:
Additional Site Information:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Quantity: 850.00
Address Site:
Description: Weight of Bulk Liquid with High Level PCBs (>1000 ppm) kg

Quantity: 876.00
Address Site:
Description: Weight of Capacitors with High Level PCBs (>1000 ppm) kg

Quantity: 8320.00
Address Site:
Description: Weight of Bulk Liquid with Low Level PCBs (< 1000 ppm) kg

Quantity: 198.00
Address Site:
Description: Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 3.00
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Soil with Low Level PCBs (< 1000 ppm) kg

Quantity: 400.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Soil with Low Level PCBs (< 1000 ppm) kg

Quantity: 900.00
Address Site:
Description: Weight of Soil Not in Drums with Low Level PCBs (< 1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg

Quantity: 150.00
Address Site:
Description: Calculated Weight of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg

Quantity: 688.00
Address Site:
Description: Weight of Other Material Not in Drums with Low Level PCBs (< 1000 ppm) kg

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	9 of 49	SSE/119.8	237.0 / -4.90	BRAMPTON HYDRO 175 SANDALWOOD PKWY BRAMPTON ON L7A 1E8	OPCB

Year: 2000
Site Number: 30292A016
Name Owner:
Additional Site Information:

--Details--
Quantity: 850.00
Address Site:
Description: Weight of Bulk Liquid with High Level PCBs (>1000 ppm) kg

Quantity: 8320.00
Address Site:
Description: Weight of Bulk Liquid with Low Level PCBs (< 1000 ppm) kg

Quantity: 198.00
Address Site:
Description: Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 3.00
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Soil with Low Level PCBs (< 1000 ppm) kg

Quantity: 876.00
Address Site:
Description: Weight of Capacitors with High Level PCBs (>1000 ppm) kg

Quantity: 400.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Soil with Low Level PCBs (< 1000 ppm) kg

Quantity: 900.00
Address Site:
Description: Weight of Soil Not in Drums with Low Level PCBs (< 1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg

Quantity: 150.00
Address Site:
Description: Calculated Weight of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg

Quantity: 688.00
Address Site:
Description: Weight of Other Material Not in Drums with Low Level PCBs (< 1000 ppm) kg

---

56 | ***10 of 49*** | ***SSE/119.8*** | ***237.0 / -4.90*** | ***BRAMPTON HYDRO***
175 SANDALWOOD PKWY
BRAMPTON ON L7A 1E8 | ***OPCB***

Year: 2003
Site Number: 30292A016
Name Owner:
Additional Site Information:

--Details--
Quantity: 1.00
Address Site:
Description: Number of Drums of Soil with Low Level PCBs (< 1000 ppm) kg

Quantity: 400.00
Address Site:
Description: Weight of Drums of Soil with Low Level PCBs (< 1000 ppm) kg

Quantity: 285.00
Address Site:
Description: Weight of Bulk Liquid with High Level PCBs (>1000 ppm) kg

---

56 | ***11 of 49*** | ***SSE/119.8*** | ***237.0 / -4.90*** | ***BRAMPTON HYDRO 05-867***
175 SANDALWOOD PARKWAY WEST | ***GEN***

BRAMPTON ON L7A 1E8

Generator Info

Generator No:	ON0291408	***Choice of Contact:***	
Approval Years:	92,93,94,95,96	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	4911
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELECT. POWER SYS.		

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 243

Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

56 | **12 of 49** | **SSE/119.8** | **237.0 / -4.90** | **BRAMPTON HYDRO**
175 SANDALWOOD PARKWAY WEST
BRAMPTON ON L7A 1E8 | **GEN**

Generator Info

Generator No: ON0291408
Approval Years: 97
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ELECT. POWER SYS.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4911

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

56 | ***13 of 49*** | ***SSE/119.8*** | ***237.0 / -4.90*** | ***BRAMPTON HYDRO-ELECTRIC COMMISSION***
175 SANDALWOOD PARKWAY WEST
BRAMPTON ON L7A 1E8 | ***GEN***

Generator Info

Generator No: ON0291408
Approval Years: 98,99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ELECT. POWER SYS.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4911

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

56	*14 of 49*	*SSE/119.8*	*237.0 / -4.90*	***Hydro One Brampton Networks Inc.*** ***175 Sandalwood Pkwy. West*** ***Brampton ON L7A 1E8***	*GEN*

Generator Info

Generator No: ON0291408
Approval Years: 02,03,04,05,06,07,08
Status:
PO Box No:
Country:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

---

56 | **15 of 49** | **SSE/119.8** | **237.0 / -4.90** | **BRAMPTON HYDRO**
175 SANDALWOOD PKWY
BRAMPTON ON | **NPCB**

Company Code: F1033
Industry: Undefined
Site Status: Stored for Disposal
Transaction Date: 12/30/1995
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code: Askarel/Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for disposal
Contents:

---

56 | **16 of 49** | **SSE/119.8** | **237.0 / -4.90** | **BRAMPTON HYDRO NETWORKS INC.**
175 Sandalwood Pkwy. West
Brampton ON L7A 1E8 | **NPCB**

Company Code: O0004
Industry: Utility
Site Status: Stored for Disposal
Transaction Date: 2/29/2000
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code: Other Waste/Unknown
Location: CONTAINER # 227
Item/State:
No. of Items:
Manufacturer:
Status: Stored for disposal
Contents:

---

56 | **17 of 49** | **SSE/119.8** | **237.0 / -4.90** | **BRAMPTON HYDRO**
175 SANDALWOOD PKWY
BRAMPTON ON L7A 1E8 | **OPCB**

Year: 2004
Site Number: 30292A016
Name Owner:
Additional Site Information:

--Details--
Quantity: 3
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 1
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 122
Address Site:
Description: Weight of Drums of Ballasts with High Level PCBs (>1000 ppm) kg

---

56 | **18 of 49** | **SSE/119.8** | **237.0 / -4.90** | **HYDRO ONE BRAMPTON NETWORKS INC**
175 SANDALWOOD PKY W
BRAMPTON ON L7A 1E8 | **FSTH**

License Issue Date: 2/22/2002
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1991
Corrosion Protection:
Capacity: 22755
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1991
Corrosion Protection:
Capacity: 46419
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

---

56 | **19 of 49** | **SSE/119.8** | **237.0 / -4.90** | **Hydro One Brampton Networks Inc.**
175 Sandalwood Parkway West Brampton
Ontario L7A 1E8 Brampton
ON | **EBR**

EBR Registry No: IA06E0028
Ministry Ref No: 6842-6JSKAY
Notice Type: Instrument Decision
Notice Stage:
Notice Date: May 09, 2006
Proposal Date: January 06, 2006
Year: 2006
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Hydro One Brampton Networks Inc.
Site Address:
Location Other:
Proponent Name:

Proponent Address: 175 Sandalwood Parkway West, Brampton Ontario, L7A 1E8
Comment Period:
URL:
Summary:

Site Location Details:

175 Sandalwood Parkway West Brampton Ontario L7A 1E8 Brampton

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	20 of 49	SSE/119.8	237.0 / -4.90	Hydro One Brampton Networks Inc. 175 Sandalwood Pky W Brampton ON L7A 1E8	SPL

Ref No: 7686-7G725Y
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/2/2008
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: 175 Sandalwood Parkway West
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Entity Operating Name:
Client Name: Hydro One Brampton Networks Inc.
Client Type:
Source Type:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Incident Reason: Spill
Incident Summary: Hydro One Brampton Transformer spill
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty: 160 L
Contaminant Qty 1: 160
Contaminant Unit: L
Contaminant Code: 15
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	21 of 49	SSE/119.8	237.0 / -4.90	HYDRO ONE BRAMPTON NETWORKS INC 175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	FSTH

License Issue Date: 2/22/2002
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1991
Corrosion Protection:
Capacity: 22755
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1991
Corrosion Protection:
Capacity: 46419
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	22 of 49	SSE/119.8	237.0 / -4.90	BRAMPTON HYDRO 175 SANDALWOOD PKY W BRAMPTON ON L7A 1E8	NPCB

Company Code: F1033
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

--Details--
Label: F103303
Serial No.:
PCB Type/Code: OTHER WASTE/LOW
Location:
Item/State: CTNR SOIL / GRAVEL/FULL
No. of Items: 1
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 900 KG

Label: F103304
Serial No.:
PCB Type/Code: OTHER WASTE/LOW
Location:
Item/State: CTNR DEBRIS, ETC/FULL
No. of Items: 1
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 688 KG

Label: F103302
Serial No.:
PCB Type/Code: MINERAL OIL/UNKNOWN
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 3

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 198 KG

Label: F103301
Serial No.:
PCB Type/Code: MINERAL OIL/UNKNOWN
Location:
Item/State: BARREL MINERAL OIL/FULL
No. of Items: 47
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 8320 KG

Label: F103300
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: BARREL PCB ASKAREL/FULL
No. of Items: 3
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 850 KG

56	23 of 49	SSE/119.8	237.0 / -4.90	**BRAMPTON HYDRO NETWORKS INC.** **175 SANDALWOOD PKY W** **BRAMPTON ON L7A 1E8**	NPCB

Company Code: O0004
Industry: UTILITY
Site Status: STORAGE ONLY (NON FEDERAL)
Transaction Date: 5/18/2000
Inspection Date:

--Details--
Label: DO00002
Serial No.:
PCB Type/Code: OTHER WASTE/UNKNOWN
Location:
Item/State: BARREL OTHER LIQUID/FULL
No. of Items: 1
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 150 L

Label: DO00004
Serial No.:
PCB Type/Code: OTHER WASTE/UNKNOWN
Location:
Item/State: BARREL OTHER LIQUID/FULL
No. of Items: 1
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 200 L

Label: DO00003
Serial No.:
PCB Type/Code: OTHER WASTE/UNKNOWN
Location:
Item/State: BARREL OTHER LIQUID/FULL
No. of Items: 1
Manufacturer:
Status: STORED FOR DISPOSAL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Contents:		200 L			

56	24 of 49	SSE/119.8	237.0 / -4.90	**Hydro One Brampton Networks Inc.** **175 Sandalwood Parkway West** **Brampton ON L7A 1E8**	CA

Certificate #: 7798-6NAQ4W
Application Year: 2006
Issue Date: 4/29/2006
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

56	25 of 49	SSE/119.8	237.0 / -4.90	**Hydro One Brampton Networks Inc.** **175 Sandalwood Pkwy. West** **Brampton ON L7A 1E8**	GEN

Generator Info

Generator No: ON0291408
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Electric Power Distribution

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 221122

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	26 of 49	SSE/119.8	237.0 / -4.90	**Hydro One Brampton Networks Inc.** **175 Sandalwood Pkwy. West** **Brampton ON L7A 1E8**	GEN

Generator Info

Generator No: ON0291408
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 221122

Phone No Admin:
SIC Description: Electric Power Distribution

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 212

Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

56 | **27 of 49** | **SSE/119.8** | **237.0 / -4.90** | **Hydro One Brampton Networks Inc.**
175 Sandalwood Pkwy. West
Brampton ON L7A 1E8 | **GEN**

Generator Info

Generator No: ON0291408
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Electric Power Distribution

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 221122

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

56 ***28 of 49*** ***SSE/119.8*** ***237.0 / -4.90*** ***HYDRO ONE BRAMPTON***
175 SANDALWOOD PKY W
BRAMPTON ON ***FST***

Inventory No: 11317600
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

56 ***29 of 49*** ***SSE/119.8*** ***237.0 / -4.90*** ***HYDRO ONE BRAMPTON***
175 SANDALWOOD PKY W
BRAMPTON ON ***FST***

Inventory No: 11317576
Inventory Status: Active
Installation Year:

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:

Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:

Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

56 | ***30 of 49*** | ***SSE/119.8*** | ***237.0 / -4.90*** | ***Hydro One Brampton Networks Inc.***
175 Sandalwood Pkwy. West
Brampton ON L7A 1E8 | ***GEN***

Generator Info

Generator No: ON0291408
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Electric Power Distribution

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 221122

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

56 ***31 of 49*** ***SSE/119.8*** ***237.0 / -4.90*** ***175 Sandalwood Parkway West Brampton ON*** ***EHS***

Order No: 20140813102
Status: C
Report Type: Custom Report
Report Date: 21-AUG-14
Date Received: 13-AUG-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.806129
Y: 43.712713

---

56 ***32 of 49*** ***SSE/119.8*** ***237.0 / -4.90*** ***175 Sandalwood Pkwy Brampton ON*** ***EHS***

Order No: 20140908049
Status: C
Report Type: Custom Report
Report Date: 09-SEP-14
Date Received: 08-SEP-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0
X: -79.804424
Y: 43.709818

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	33 of 49	SSE/119.8	237.0 / -4.90	Hydro One Brampton Networks Inc. 175 Sandalwood Pkwy. West Brampton ON	GEN

Generator Info

Generator No:	ON0291408	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	221122
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELECTRIC POWER DISTRIBUTION		

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

56	*34 of 49*	*SSE/119.8*	*237.0 / -4.90*	***Brampton Hydro*** ***175 Sandalwood Pkwy*** ***Brampton ON L7A 1E8***	***OPCB***

Year: 2012
Site Number: 30292A016
Name Owner: Brampton Hydro
Additional Site Information:

56	*35 of 49*	*SSE/119.8*	*237.0 / -4.90*	***Brampton Hydro*** ***175 Sandalwood Pkwy*** ***Brampton ON L7A 1E8***	***OPCB***

Year: 2013
Site Number: 30292A016
Name Owner: Brampton Hydro
Additional Site Information:

56	*36 of 49*	*SSE/119.8*	*237.0 / -4.90*	***BRAMPTON HYDRO INC.*** ***175 Sandalwood PKY W*** ***Brampton ON L7A 1E8***	***EASR***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No:	R-002-8562662756	**MOE District:**	Halton-Peel
Status:	REGISTERED	**Municipality:**	Brampton
Date:	2016-01-20	**Latitude:**	43.71277778
Record Type:	EASR	**Longitude:**	-79.80611111
Link Source:	MOFA	**Geometry X:**	
Project Type:	Standby Power System	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Standby Power System		
SWP Area Name:	Toronto		
PDF NAICS Code:			
PDF URL:			
PDF Site Location:			

56	37 of 49	SSE/119.8	237.0 / -4.90	**Hydro One Brampton Networks Inc.** **175 Sandalwood Pky W** **Brampton ON L7A 1E8**	SPL

Ref No:	8570-A7436U	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2016/02/12	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2016/02/12	**Impact to Health:**	
Dt Document Closed:	2016/03/16	**Agency Involved:**	
Site No:	4464-4USKWZ		
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:	1-10 metres eg. Good Quality GPS		
Site District Office:			
Nearest Watercourse:			
Site Name:	175 Sandalwood Parkway West		
Site Address:	175 Sandalwood Pky W		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:	GPS		
Site Map Datum:	NAD83		
Northing:	4840762		
Easting:	596141		
Entity Operating Name:			
Client Name:	Hydro One Brampton Networks Inc.		
Client Type:			
Source Type:			
Incident Cause:			
Incident Preceding Spill:	Collision/Accident		
Incident Reason:	Operator/Human Error		
Incident Summary:	Diesel spill to CB - Contained and cleaned		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	0 other - see incident description		
Contaminant Qty 1:	0		
Contaminant Unit:	other - see incident description		
Contaminant Code:	13		
Contaminant Name:	DIESEL FUEL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Electric Power Generation		
SAC Action Class:	Watercourse Spills		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

56 ***38 of 49*** ***SSE/119.8*** ***237.0 / -4.90*** ***Hydro One Brampton Networks Inc.*** ***ECA***
175 Sandalwood Parkway West
Brampton ON L7A 1E8

Approval No:	7798-6NAQ4W	***MOE District:***	Halton-Peel
Approval Date:	2006-04-29	***City:***	
Status:	Approved	***Longitude:***	-79.80605
Record Type:	ECA	***Latitude:***	43.712723
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Toronto	***Geometry Y:***	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Hydro One Brampton Networks Inc.
Address: 175 Sandalwood Parkway West
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6842-6JSKAY-14.pdf
PDF Site Location:

---

56 ***39 of 49*** ***SSE/119.8*** ***237.0 / -4.90*** ***Hydro One Brampton Networks Inc.*** ***GEN***
175 Sandalwood Pkwy. West
Brampton ON L7A 1E8

Generator Info

Generator No:	ON0291408	***Choice of Contact:***	CO_ADMIN
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	221122
Country:	Canada		

Co Admin: Elizabeth Pimentel
Phone No Admin: 905-840-6300 Ext.5695
SIC Description: ELECTRIC POWER DISTRIBUTION

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	40 of 49	SSE/119.8	237.0 / -4.90	Alectra Utilities Corp. 175 Sandalwood Pkwy. West Brampton ON L7A 1E8	GEN

Generator Info

Generator No:	ON0291408	***Choice of Contact:***	CO_ADMIN
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	221122
Country:	Canada		
Co Admin:	Elizabeth Pimentel		
Phone No Admin:	905-840-6300 Ext.5695		
SIC Description:	ELECTRIC POWER DISTRIBUTION		

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

---

56 | **41 of 49** | **SSE/119.8** | **237.0 / -4.90** | **Hydro One Brampton Networks Inc.**
175 Sandalwood Pkwy. West
Brampton ON L7A 1E8 | **GEN**

Generator Info

Generator No: ON0291408
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Elizabeth Pimentel
Phone No Admin: 905-840-6300 Ext.5695
SIC Description: ELECTRIC POWER DISTRIBUTION

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 221122

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221

Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

56 | **42 of 49** | **SSE/119.8** | **237.0 / -4.90** | **Alectra Utilities Corp.**
175 Sandalwood Pkwy. West
Brampton ON L7A 1E8 | **GEN**

Generator Info

Generator No: ON0291408
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 243 D
Waste Class Name: PCB

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

---

56 | ***43 of 49*** | ***SSE/119.8*** | ***237.0 / -4.90*** | ***Alectra Utilities Corp.***
175 Sandalwood Pkwy. West
Brampton ON L7A 1E8 | ***GEN***

Generator Info

Generator No: ON0291408
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 243 D
Waste Class Name: PCB

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	44 of 49	SSE/119.8	237.0 / -4.90	Alectra Utilities Corp. 175 Sandalwood Pkwy. West Brampton ON L7A 1E8	GEN

Generator Info

Generator No: ON0291408
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 243 D
Waste Class Name: PCB

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

---

56 | ***45 of 49*** | ***SSE/119.8*** | ***237.0 / -4.90*** | ***Alectra Utilities Corporation 175 Sandalwood Pkwy. West Brampton ON*** | ***GEN***

Generator Info

Generator No: ON0291408
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 243 D
Waste Class Name: PCBS

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No: ON0291408
Generator Company Name: Alectra Utilities Corporation
Street: 175 Sandalwood Pkwy. West
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A1E8
Waste Class: 212 I,243 D,252 L,148 L,213 T,221 L,212 L,213 I,251 L,252 T,331 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 243 - PCBS; 252 - WASTE OILS & LUBRICANTS; 148 - INORGANIC LABORATORY CHEMICALS; 213 - PETROLEUM DISTILLATES; 221 - LIGHT FUELS; 212 - ALIPHATIC SOLVENTS; 213 - PETROLEUM DISTILLATES; 251 - OIL SKIMMINGS & SLUDGES; 252 - WASTE OILS & LUBRICANTS; 331 - WASTE COMPRESSED GASES

2017 Generator Info

Gen No: ON0291408
ID: 2800
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 221122
NAICS Code2:
NAICS Code3:
Gen Name: Alectra Utilities Corp.
Gen Div:
Gen Op Name: Alectra Utilities Corp.
Gen Op Div:
Site Adrs1: 175 Sandalwood Pkwy. West

Choice of Contact: CO_ADMIN
Phone No Official: 905-840-6300 Ext.5509
Phone No Admin: 905-840-6300 Ext.5695
County Ont: PEEL (R. M.)
County Out:
District: 305

Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1E8
Site Country: Canada
Co Official: George Lovell
Co Admin: Elizabeth Pimentel

2017 Generator Manifest

ID: 12966
Generator No: ON0291408
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 520.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 305

2017 Generator Manifest

ID: 12970
Generator No: ON0291408
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 688.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 2
District: 305

2017 Generator Manifest

ID: 12965
Generator No: ON0291408
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 8200.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 202

2017 Generator Manifest

ID: 12969
Generator No: ON0291408
Receiver Type: 035
Waste Char: T
Waste Code: 251
Sum Received Qty: 552.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 305

2017 Generator Manifest

ID: 12964
Generator No: ON0291408
Receiver Type: 035
Waste Char: D
Waste Code: 243
Sum Received Qty: 7618.0
Waste Class Name: PCBS
Count Manifests: 2
District: 202

2017 Generator Manifest

ID: 12968
Generator No: ON0291408
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 77459.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 23
District: 305

2017 Generator Manifest

ID:	12967	**Sum Received Qty:**	200.0
Generator No:	ON0291408	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	4
Waste Char:	T	**District:**	305
Waste Code:	213		

2018 Generator Info

Gen No:	ON0291408	**Choice of Contact:**	CO_ADMIN
ID:	2734	**Phone No Official:**	9053174767 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905-840-6300 Ext.5695
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	221122	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Alectra Utilities Corp.		
Gen Div:			
Gen Op Name:	Alectra Utilities Corp.		
Gen Op Div:			
Site Adrs1:	175 Sandalwood Pkwy. West		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1E8		
Site Country:	Canada		
Co Official:	Adrian Phillips		
Co Admin:	Elizabeth Pimentel		

2018 Generator Manifest

ID:	12799	**Sum Received Qty:**	1630.0
Generator No:	ON0291408	**Waste Class Name:**	PCBS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	D	**District:**	202
Waste Code:	243		

2018 Generator Manifest

ID:	12803	**Sum Received Qty:**	683.0
Generator No:	ON0291408	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	252		

2018 Generator Manifest

ID:	12802	**Sum Received Qty:**	63476.0
Generator No:	ON0291408	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	22
Waste Char:	L	**District:**	305
Waste Code:	251		

2018 Generator Manifest

ID:	12800	**Sum Received Qty:**	8293.0
Generator No:	ON0291408	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	202

Waste Code: 251

2018 Generator Manifest

ID: 12801
Generator No: ON0291408
Receiver Type: 035
Waste Char: T
Waste Code: 213
Sum Received Qty: 200.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 4
District: 305

2019 Generator Info

Gen No: ON0291408
ID: 2663
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 221122
NAICS Code2:
NAICS Code3:
Gen Name: Alectra Utilities Corp.
Gen Div:
Gen Op Name: Alectra Utilities Corp.
Gen Op Div:
Site Adrs1: 175 Sandalwood Pkwy. West
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1E8
Site Country: Canada
Co Official: Adrian Phillips
Co Admin: Elizabeth Pimentel
Choice of Contact: CO_ADMIN
Phone No Official: 9053174767 Ext.
Phone No Admin: 647-526-1479 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2019 Generator Manifest

ID: 12445
Generator No: ON0291408
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 70239.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 19
District: 305

2019 Generator Manifest

ID: 12442
Generator No: ON0291408
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 6820.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 301

2019 Generator Manifest

ID: 12443
Generator No: ON0291408
Receiver Type: 035
Waste Char: L
Waste Code: 221
Sum Received Qty: 200.0
Waste Class Name: LIGHT FUELS
Count Manifests: 1
District: 302

2019 Generator Manifest

ID:	12446	**Sum Received Qty:**	6775.0
Generator No:	ON0291408	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	305
Waste Code:	252		

2019 Generator Manifest

ID:	12441	**Sum Received Qty:**	1700.0
Generator No:	ON0291408	**Waste Class Name:**	PCBS
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	D	**District:**	202
Waste Code:	243		

2019 Generator Manifest

ID:	12444	**Sum Received Qty:**	180.0
Generator No:	ON0291408	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	4
Waste Char:	T	**District:**	305
Waste Code:	213		

2020 Generator Info

Gen No:	ON0291408	**Choice of Contact:**	CO_ADMIN
ID:	2574	**Phone No Official:**	9053174767 Ext.
Contaminated Fac:	N	**Phone No Admin:**	647-526-1479 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	221122	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Alectra Utilities Corp.		
Gen Div:			
Gen Op Name:	Alectra Utilities Corp.		
Gen Op Div:			
Site Adrs1:	175 Sandalwood Pkwy. West		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1E8		
Site Country:	Canada		
Co Official:	Adrian Phillips		
Co Admin:	Elizabeth Pimentel		

2020 Generator Manifest

ID:	11290	**Sum Received Qty:**	95418.0
Generator No:	ON0291408	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	24
Waste Char:	L	**District:**	305
Waste Code:	251		

2020 Generator Manifest

ID:	11291	**Sum Received Qty:**	2370.0
Generator No:	ON0291408	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	305
Waste Code:	252		

2020 Generator Manifest

ID:	11289	***Sum Received Qty:***	200.0
Generator No:	ON0291408	***Waste Class Name:***	PETROLEUM DISTILLATES
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	T	***District:***	305
Waste Code:	213		

2021 Generator Info

Gen No:	ON0291408	***Choice of Contact:***	CO_ADMIN
ID:	2526	***Phone No Official:***	9053174767 Ext.
Contaminated Fac:	N	***Phone No Admin:***	647-526-1479 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	221122	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Alectra Utilities Corp.		
Gen Div:			
Gen Op Name:	Alectra Utilities Corp.		
Gen Op Div:			
Site Adrs1:	175 Sandalwood Pkwy. West		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1E8		
Site Country:	Canada		
Co Official:	Adrian Phillips		
Co Admin:	Elizabeth Pimentel		

2021 Generator Manifest

ID:	11356	***Sum Received Qty:***	60.0
Generator No:	ON0291408	***Waste Class Name:***	WASTE COMPRESSED GASES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	I	***District:***	306
Waste Code:	331		

2021 Generator Manifest

ID:	11352	***Sum Received Qty:***	3260.0
Generator No:	ON0291408	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	T	***District:***	202
Waste Code:	252		

2021 Generator Manifest

ID:	11351	***Sum Received Qty:***	4010.0
Generator No:	ON0291408	***Waste Class Name:***	PCBS
Receiver Type:	035	***Count Manifests:***	3
Waste Char:	D	***District:***	202
Waste Code:	243		

2021 Generator Manifest

ID:	11354	***Sum Received Qty:***	83770.0

Generator No:	ON0291408	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	24
Waste Char:	L	**District:**	305
Waste Code:	251		

2021 Generator Manifest

ID:	11353	**Sum Received Qty:**	200.0
Generator No:	ON0291408	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	4
Waste Char:	T	**District:**	305
Waste Code:	213		

2021 Generator Manifest

ID:	11355	**Sum Received Qty:**	1130.0
Generator No:	ON0291408	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	4
Waste Char:	T	**District:**	305
Waste Code:	252		

---

56 | ***46 of 49*** | ***SSE/119.8*** | ***237.0 / -4.90*** | ***HYDRO ONE BRAMPTON***
175 SANDALWOOD PKWY., WEST
BRAMPTON ON L7A1E8 | ***NPR2***

NPRI ID:	4473	**Latitude:**	43.7143
Facility ID:	224846;366761;369950;370554;372237; 372238;379038	**Longitude:**	-79.8081
Facility Name:	HYDRO ONE BRAMPTON		

Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=4473

NPRI ID Substances Summary

CAS No:	107-21-1	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Ethylene glycol		
Name French:	Éthylène glycol		
Sort English:	Ethylene glycol		
Sort French:	Éthylèneglycol		

Geographic Location

Report Year:	-1	**Forward Sort Area:**	L7A
Census Subdiv ID:	3521010	**DLS Description:**	
Ecozone ID:	8	**NTS Description:**	C-055-K/030-M-12
Water Survey ID:	2	**Province Code:**	ON
SOMA:	TRUE	**Datum:**	1983.0
ON PEMA:	TRUE	**Latitude:**	43.7143
QC PEMA:	FALSE	**Longitude:**	-79.8081
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID: 4473
Facility ID: 224846

Facility

Facility ID: 224846
Portable: FALSE
NAICS Primary: 221122
NAICS Secondary: 0
NAICS Tertiary: 0
Facility Name: Brampton Hydro
Website:
IDM ID: 0
AB Approval ID: 0
GHGRP ID: 0
ON GHGRP ID: 0

Address

Address1: 175 Sandalwood Parkway, West
Address2:
City: BRAMPTON
Postal Zip: L7A1E8
Prov:

Primary NAICS Details

NAICS Code: 221122
Record Year: 1997
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric Power Distribution
NAICS Title Fr: Distribution d'électricité
Start Date: 1993
End Date: 2001

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122
Record Year: 2002
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric Power Distribution
NAICS Title Fr: Distribution d'électricité
Start Date: 2002
End Date: 2006

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2007
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric Power Distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les agents et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NAICS Code:	221122	**Start Date:**	2022
Record Year:	2022	**End Date:**	2026
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NPRI Report

Report ID:	1429	**No of Employees:**	202
Report Year:	1996	**Is Compressor:**	
Company ID:	99794	**Is NPRI Part 4:**	
SWR Report ID:	19960000004473	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1997-06-02 00:00:00.0000000

Company

Company Name:	Brampton Hydro Electric Commission
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report

Report ID:	2246	**No of Employees:**	212
Report Year:	1995	**Is Compressor:**	
Company ID:	99794	**Is NPRI Part 4:**	
SWR Report ID:	19950000004473	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1996-06-03 00:00:00.0000000

Company

Company Name:	Brampton Hydro Electric Commission
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report

Report ID:	5249	**No of Employees:**	212
Report Year:	1994	**Is Compressor:**	
Company ID:	99794	**Is NPRI Part 4:**	
SWR Report ID:	19940000004473	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1995-06-01 00:00:00.0000000

Company

Company Name:	Brampton Hydro Electric Commission
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI ID Facility ID

NPRI ID:	4473
Facility ID:	379038

Facility

Facility ID:	379038	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	221122	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	Brampton Hydro		
Website:	bramptonhydro.on.ca		

Address

Address1:	175 Sandalwood Parkway, West
Address2:	
City:	BRAMTON
Postal Zip:	L7A1E8
Prov:	

Primary NAICS Details

NAICS Code:	221122	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NAICS Code:	221122	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric

power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les agents et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NPRI Report

Report ID:	285989	***No of Employees:***	199
Report Year:	1998	***Is Compressor:***	
Company ID:	136446	***Is NPRI Part 4:***	
SWR Report ID:	19980000004473	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	1999-06-01 00:00:00.0000000

Company

Company Name:	Brampton Hydro Electric Commission
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	bramptonhydro.on.ca

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	Ethylene glycol is used as a heat transfer fluid in a closed loop HVAC ì system at approximately 35% solution in the following systems: System 1 Storage - Removed by Phillips (1997) System 2 HRU1 - 900Gallons Imperial System 3 HRU2 **Note: data in the [Comment] field for some records is truncated from the source.
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	LORAINE	***Extension:***	0
Last Name:	MYLER	***Fax:***	0

Company Name:
Description En:
Description Fr:
Position: ADMINISTRATIVE SERVICES MGR.
Language: 0
Email:

NPRI Report Contact

Contact Type:
First Name: Dan
Last Name: Warren
Company Name:
Description En:
Description Fr:
Position: Bldg. Maintenance Supervisor
Language: 0
Email: DWarren@bramptonhydro.on.ca
Phone: 9058406300
Extension: 402
Fax: 9058401305

NPRI Report Contact

Contact Type: NPRI
First Name: Loraine
Last Name: Myler
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Administrative Services Mgr.
Language: 0
Email:
Phone: 9058406300
Extension: 225
Fax: 9058401305

NPRI Report Contact

Contact Type:
First Name: Loraine
Last Name: Myler
Company Name:
Description En:
Description Fr:
Position: Administrative Services Mgr.
Language: 0
Email: LMyler@bramptonhydro.on.ca
Phone: 9058406300
Extension: 225
Fax: 9058401305

NPRI ID Facility ID

NPRI ID: 4473
Facility ID: 372237

Facility

Facility ID: 372237
Portable: FALSE
NAICS Primary: 221122
NAICS Secondary: 0
NAICS Tertiary: 0
Facility Name: Brampton Hydro
Website: www.bramptonhydro.on.ca
IDM ID: 0
AB Approval ID: 0
GHGRP ID: 0
ON GHGRP ID: 0

Address

Address1: 175 Sandalwood Parkway West

Address2:
City: BRAMPTON
Postal Zip: L7A1E8
Prov:

Primary NAICS Details

NAICS Code:	221122	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122
Record Year: 2012
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité
Start Date: 2012
End Date: 2016

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les agents et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122
Record Year: 2017
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité
Start Date: 2017
End Date: 2021

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NAICS Code: 221122
Record Year: 2022
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité
Start Date: 2022
End Date: 2026

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NPRI Report

Report ID:	210792	**No of Employees:**	190
Report Year:	1999	**Is Compressor:**	
Company ID:	138807	**Is NPRI Part 4:**	
SWR Report ID:	19990000004473	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2000-06-01 00:00:00.0000000

Company

Company Name:	Brampton Hydro Electric Commission
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.bramptonhydro.on.ca

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	Ethylene glycol is used as a heat transfer fluid in a closed loop HVAC system at approximately 35% solution in the following systems: System 1 Storage Removed by Phillips (1997) System 2 HRU1
Note:	

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058406300
First Name:	Loraine	**Extension:**	225
Last Name:	Myler	**Fax:**	9058401305
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager Administrative Service		
Language:	0		
Email:	lmyler@bramptonhydro.on.ca		

NPRI Report Contact

Contact Type:		**Phone:**	9058406300
First Name:	Loraine	**Extension:**	225
Last Name:	Myler	**Fax:**	9058406300
Company Name:			
Description En:			
Description Fr:			
Position:	Manager Administrative Service		
Language:	0		
Email:	lmyler@bramptonhydro.on.ca		

NPRI Report Contact

Contact Type:		**Phone:**	9058406300
First Name:	Loraine	**Extension:**	225
Last Name:	Myler	**Fax:**	9058406300
Company Name:			
Description En:			
Description Fr:			
Position:	Manager Administrative Service		
Language:	0		
Email:	lmyler@bramptonhydro.on.ca		

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	Loraine	***Extension:***	0
Last Name:	Myler	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Manager Administrative Service		
Language:	0		
Email:			

NPRI ID Facility ID

NPRI ID:	4473
Facility ID:	370554

Facility

Facility ID:	370554	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	221122	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	BRAMPTON HYDRO		
Website:			

Address

Address1:	175 Sandalwood Parkway West
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1E8
Prov:	

Primary NAICS Details

NAICS Code:	221122	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Electricity		

Key Indus Sector Fr: Électricité
NAICS Title En: Electric Power Distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2007
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric Power Distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les agents et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Electricity

Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NAICS Code: 221122
Record Year: 2022
Start Date: 2022
End Date: 2026
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NPRI Report

Report ID: 288120
Report Year: 1997
Company ID: 99794
SWR Report ID: 19970000004473
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 202
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 1998-06-01 00:00:00.0000000

Company

Company Name: Brampton Hydro Electric Commission
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Comment

Description En: General comments about the facility
Description Fr: Commentaires généraux à propos de l'installation
Comment: ETHYLENE GLYCOL IS USED AS A HEAT TRANSFER FLUID IN A CLOSED LOOP HVAC ì
SYSTEM. AT APPROX. 35% SOLUTION IN THE FOLLOWING SYSTEMS:
SYSTEM 1 STORAGE - REMOVED BY PHILLIPS
SYSTEM 2 HRU1 - 900 GALLONS IMPERIAL
SYSTEM 3 HRU2 **Note: data in the [Comment] field for some records is truncated from the source.
Note:

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058406300
First Name:	Loraine	**Extension:**	225
Last Name:	Myler	**Fax:**	9058401305
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Administrative Services Mgr.		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	0
First Name:	LORAINE	**Extension:**	0
Last Name:	MYLER	**Fax:**	0
Company Name:			
Description En:			
Description Fr:			
Position:	ADMINISTRATIVE SERVICES MGR.		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058406300
First Name:	LORAINE	**Extension:**	225
Last Name:	MYLER	**Fax:**	9058041305
Company Name:			
Description En:			
Description Fr:			
Position:	ADMINISTRATIVE SERVICES MGR.		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058406300
First Name:	DAN	**Extension:**	402
Last Name:	WARREN	**Fax:**	9058401305
Company Name:			
Description En:			
Description Fr:			
Position:	BLDG. MAINTENANCE SUPERVISOR		
Language:	0		
Email:			

NPRI ID Facility ID

NPRI ID:	4473
Facility ID:	366761

Facility

Facility ID:	366761	**IDM ID:**	0
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	221122	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:	HYDRO ONE BRAMPTON		
Website:			

Address

Address1: 175 Sandalwood Pkwy., West
Address2:
City: BRAMPTON
Postal Zip: L7A1E8
Prov:

Primary NAICS Details

NAICS Code: 221122 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric Power Distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric Power Distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NAICS Code:	221122	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les agents et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs

individuels.

NPRI Report

Report ID:	277578	***No of Employees:***	178
Report Year:	2002	***Is Compressor:***	
Company ID:	139855	***Is NPRI Part 4:***	
SWR Report ID:	20020000004473	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2003-06-02 00:00:00.0000000

Company

Company Name:	HYDRO ONE
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	Ethylene glycol is used as a heat transfer fluid in a closed loop HVAC system at approx. 35% solution in the following systems: System 1 Storage Removed by Phillips (1997) System 2 HRU1 900 Gallons Imperial S **Note: data in the [Comment] field for some records is truncated from the source.
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	9058406300
First Name:	Ann	***Extension:***	395
Last Name:	Pynn	***Fax:***	9058401305
Company Name:			
Description En:			
Description Fr:			
Position:	Administrative Services Supervisor		
Language:	0		
Email:	apynn@hydroonebrampton.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058406300
First Name:	Ann	***Extension:***	395
Last Name:	Pynn	***Fax:***	9058401305
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Administrative Services Supervisor		
Language:	0		
Email:	apynn@hydroonebrampton.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058406300
First Name:	Ann	***Extension:***	395
Last Name:	Pynn	***Fax:***	9058401305

Company Name:
Description En:
Description Fr:
Position: Administrative Services Supervisor
Language: 0
Email: apynn@hydroonebrampton.com

NPRI Report Contact

Contact Type:
First Name: Ann
Last Name: Pynn
Company Name:
Description En:
Description Fr:
Position: Administrative Services Supervisor
Language: 0
Email: apynn@hydroonebrampton.com
Phone: 9058406300
Extension: 395
Fax: 9058401305

NPRI ID Facility ID

NPRI ID: 4473
Facility ID: 369950

Facility

Facility ID: 369950
Portable: FALSE
NAICS Primary: 221122
NAICS Secondary: 0
NAICS Tertiary: 0
Facility Name: Brampton Hydro
Website: bramptonhydro.on.ca
IDM ID: 0
AB Approval ID: 0
GHGRP ID: 0
ON GHGRP ID: 0

Address

Address1: 175 Sandalwood Pkwy. W
Address2:
City: BRAMPTON
Postal Zip: L7A1E8
Prov:

Primary NAICS Details

NAICS Code: 221122
Record Year: 2002
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric Power Distribution
NAICS Title Fr: Distribution d'électricité
Start Date: 2002
End Date: 2006

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des

centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les agents et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution

d'énergie exploités par d'autres.

NAICS Code:	221122	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NAICS Code:	221122	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric power distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NPRI Report

Report ID:	281764	***No of Employees:***	188
Report Year:	2000	***Is Compressor:***	
Company ID:	136447	***Is NPRI Part 4:***	
SWR Report ID:	20000000004473	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2001-06-01 00:00:00.0000000

Company

Company Name:	Brampton Hydro Networks Inc.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	bramptonhydro.on.ca

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	Ethylene glycol is used as a heat transfer fluid in a closed loop HVAC system at approx. 35% solution in the following systems: System 1 Storage Removed by Phillips (1997)

System 2 HRU1 900 Gallons Imperial
System 3 HRU2

Note:

NPRI Report Contact

Contact Type:		***Phone:***	9058406300
First Name:	Loraine	***Extension:***	225
Last Name:	Myler	***Fax:***	9058401305
Company Name:			
Description En:			
Description Fr:			
Position:	Administrative Services Manage		
Language:	0		
Email:	lmyler@bramptonhydro.on.ca		

NPRI Report Contact

Contact Type:		***Phone:***	9058406300
First Name:	Loraine	***Extension:***	225
Last Name:	Myler	***Fax:***	9058401305
Company Name:			
Description En:			
Description Fr:			
Position:	Administrative Services Manage		
Language:	0		
Email:	lmyler@bramptonhydro.on.ca		

NPRI Report Contact

Contact Type:		***Phone:***	9058406300
First Name:	Loraine	***Extension:***	225
Last Name:	Myler	***Fax:***	9058401305
Company Name:			
Description En:			
Description Fr:			
Position:	Administrative Services Manage		
Language:	0		
Email:	lmyler@bramptonhydro.on.ca		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058406300
First Name:	Loraine	***Extension:***	225
Last Name:	Myler	***Fax:***	9058401305
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Administrative Services Manage		
Language:	0		
Email:	lmyler@bramptonhydro.on.ca		

NPRI ID Facility ID

NPRI ID:	4473
Facility ID:	372238

Facility

Facility ID:	372238	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0

NAICS Primary:	221122	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:	Hydro One Brampton		
Website:	HydroOneBrampton.com		

Address

Address1:	175 Sandalwood Pkwy. W
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1E8
Prov:	

Primary NAICS Details

NAICS Code:	221122	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	**Start Date:**	2002
Record Year:	2002	**End Date:**	2006
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		
NAICS Title Fr:	Distribution d'électricité		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code:	221122	**Start Date:**	2007
Record Year:	2007	**End Date:**	2011
Key Indus Sector En:	Electricity		
Key Indus Sector Fr:	Électricité		
NAICS Title En:	Electric Power Distribution		

NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les négociants et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer. The electric power distribution system includes distribution lines and transformer stations integral to power distribution, as well as any dedicated generating stations. Electric power brokers and agents, that arrange the sale of electricity over power distribution systems operated by others, are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels. La distribution s'effectue par des lignes et par des transformateurs qui font partie intégrante du système, ainsi que, éventuellement, par des centrales spécialisées. Sont inclus les agents et les courtiers en électricité qui négocient la vente d'électricité par l'entremise de réseaux de distribution d'énergie exploités par d'autres.

NAICS Code: 221122 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NAICS Code: 221122 ***Start Date:*** 2022
Record Year: 2022 ***End Date:*** 2026
Key Indus Sector En: Electricity
Key Indus Sector Fr: Électricité
NAICS Title En: Electric power distribution
NAICS Title Fr: Distribution d'électricité

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the distribution of electric power to the individual user or consumer.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à distribuer de l'électricité aux usagers ou consommateurs individuels.

NPRI Report

Report ID:	280449	***No of Employees:***	192
Report Year:	2001	***Is Compressor:***	
Company ID:	139856	***Is NPRI Part 4:***	
SWR Report ID:	20010000004473	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2002-06-03 00:00:00.0000000

Company

Company Name:	Hydro One Brampton Networks Inc
DUNS No:	209657584
Trade Name En:	
Trade Name Fr:	
Website:	HydroOneBrampton.com

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	Ethylene glycol is used as a heat transfer fluid in a closed loop HVAC system at approximately 35% solution in the following systems: System 1 - Removed in 1997 System 2 - HRU 1 - 900 Imperial gallons System 3 - HRU 2 - 400 Imperial gallons System 4 **Note: data in the [Comment] field for some records is truncated from the source.
Note:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058406300
First Name:	Loraine	***Extension:***	225
Last Name:	Myler	***Fax:***	9058401305
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Administrative Services Manage		
Language:	0		
Email:	lmyler@HydroOneBrampton.Com		

NPRI Report Contact

Contact Type:		***Phone:***	9058406300
First Name:	Loraine	***Extension:***	225
Last Name:	Myler	***Fax:***	9058401305
Company Name:			
Description En:			
Description Fr:			
Position:	Administrative Services Manage		
Language:	0		
Email:	lmyler@HydroOneBrampton.Com		

NPRI Report Contact

Contact Type:		***Phone:***	9058406300
First Name:	Loraine	***Extension:***	225
Last Name:	Myler	***Fax:***	9058401305
Company Name:			
Description En:			
Description Fr:			
Position:	Administrative Services Manage		
Language:	0		
Email:	lmyler@HydroOneBrampton.Com		

NPRI Report Contact

Contact Type:		***Phone:***	9058406300
First Name:	Loraine	***Extension:***	225
Last Name:	Myler	***Fax:***	9058401305
Company Name:			
Description En:			
Description Fr:			
Position:	Administrative Services Manage		
Language:	0		
Email:	lmyler@HydroOneBrampton.Com		

Alternative Location Info

Facility ID:	372238
Facility Name:	BRAMPTON HYDRO
Address1:	175 SANDALWOOD PKWY. W
City:	BRAMPTON
Postal ZIP:	L7A1E8
Province EN:	ON
Latitude:	43.7143
Longitude:	-79.8081

Alternative Location Info

Facility ID:	366761
Facility Name:	BRAMPTON HYDRO
Address1:	175 SANDALWOOD PARKWAY, WEST
City:	BRAMPTON
Postal ZIP:	L7A1E8
Province EN:	ON
Latitude:	43.7143
Longitude:	-79.8081

Alternative Location Info

Facility ID:	372237
Facility Name:	BRAMPTON HYDRO
Address1:	175 SANDALWOOD PARKWAY, WEST
City:	BRAMPTON
Postal ZIP:	L7A1E8
Province EN:	ON
Latitude:	43.7143
Longitude:	-79.8081

Alternative Location Info

Facility ID:	372237
Facility Name:	BRAMPTON HYDRO

Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 224846
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY., WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372237
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 379038
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 369950
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 379038
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 379038
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 370554
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 379038
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY., WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372238
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 369950
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 370554
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON

Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 370554
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372237
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY., WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372238
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 224846
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 366761
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 370554
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY., WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 369950
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY., WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 224846
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 379038
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372238
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY., WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 369950
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMTON
Postal ZIP: L7A1E8
Province EN: ON

Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 370554
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 224846
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 224846
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 366761
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 369950
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 370554

Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372238
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 369950
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372237
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 224846
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 379038
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 366761
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372237
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY. W
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 372238
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 366761
Facility Name: BRAMPTON HYDRO
Address1: 175 SANDALWOOD PARKWAY, WEST
City: BRAMTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

Alternative Location Info

Facility ID: 366761
Facility Name: HYDRO ONE BRAMPTON
Address1: 175 SANDALWOOD PKWY., WEST
City: BRAMPTON
Postal ZIP: L7A1E8
Province EN: ON
Latitude: 43.7143
Longitude: -79.8081

56	***47 of 49***	***SSE/119.8***	***237.0 / -4.90***	***City of Brampton*** ***175 Sandalwood Parkway West*** ***Brampton ON***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info as of Dec 2024

Generator No:	ON001064949
Generator Company Name:	City of Brampton
Street:	175 Sandalwood Parkway West
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A 1E8
Waste Class:	212 L, 331 I, 251 L, 252 T, 150 L, 331 I, 221 I, 252 T, 252 L, 213 T, 212 L, 222 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 331 - WASTE COMPRESSED GASES; 251 - OIL SKIMMINGS & SLUDGES; 252 - WASTE OILS & LUBRICANTS; 150 - INERT INORGANIC WASTES; 331 - WASTE COMPRESSED GASES; 221 - LIGHT FUELS; 252 - WASTE OILS & LUBRICANTS; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES; 212 - ALIPHATIC SOLVENTS; 222 - HEAVY FUELS

Generator Info as of Dec 2024

Generator No:	ON001064949
Generator Company Name:	City of Brampton
Street:	175 Sandalwood Parkway West
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A 1E8
Waste Class:	212 L,252 L,331 I,251 L,252 T,150 L,331 I,221 I,252 T,252 L,213 T,212 L,222 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 252 - WASTE OILS & LUBRICANTS; 331 - WASTE COMPRESSED GASES; 251 - OIL SKIMMINGS & SLUDGES; 252 - WASTE OILS & LUBRICANTS; 150 - INERT INORGANIC WASTES; 331 - WASTE COMPRESSED GASES; 221 - LIGHT FUELS; 252 - WASTE OILS & LUBRICANTS; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES; 212 - ALIPHATIC SOLVENTS; 222 - HEAVY FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	48 of 49	SSE/119.8	237.0 / -4.90	***City of Brampton*** ***175 Sandalwood Parkway West*** ***Brampton ON***	GEN

Generator Info as of Dec 2024

Generator No:	ON001064967
Generator Company Name:	City of Brampton
Street:	175 Sandalwood Parkway West
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A 1E8
Waste Class:	212 L, 331 I, 251 L, 252 T, 150 L, 331 I, 221 I, 252 T, 252 L, 213 T, 212 L, 222 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 331 - WASTE COMPRESSED GASES; 251 - OIL SKIMMINGS & SLUDGES; 252 - WASTE OILS & LUBRICANTS; 150 - INERT INORGANIC WASTES; 331 - WASTE COMPRESSED GASES; 221 - LIGHT FUELS; 252 - WASTE OILS & LUBRICANTS; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES; 212 - ALIPHATIC SOLVENTS; 222 - HEAVY FUELS

Generator Info as of Dec 2024

Generator No:	ON001064967

Generator Company Name: City of Brampton
Street: 175 Sandalwood Parkway West
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A 1E8
Waste Class: 212 L,252 L,331 I,251 L,252 T,150 L,331 I,221 I,252 T,252 L,213 T,212 L,222 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 252 - WASTE OILS & LUBRICANTS; 331 - WASTE COMPRESSED GASES; 251 - OIL SKIMMINGS & SLUDGES; 252 - WASTE OILS & LUBRICANTS; 150 - INERT INORGANIC WASTES; 331 - WASTE COMPRESSED GASES; 221 - LIGHT FUELS; 252 - WASTE OILS & LUBRICANTS; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES; 212 - ALIPHATIC SOLVENTS; 222 - HEAVY FUELS

56	49 of 49	SSE/119.8	237.0 / -4.90	**City of Brampton** **175 Sandalwood Parkway West** **Brampton ON**	GEN

Generator Info as of Dec 2024

Generator No: ON001065537
Generator Company Name: City of Brampton
Street: 175 Sandalwood Parkway West
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A 1E8
Waste Class: 212 L, 331 I, 251 L, 252 T, 150 L, 331 I, 221 I, 252 T, 252 L, 213 T, 212 L, 222 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 331 - WASTE COMPRESSED GASES; 251 - OIL SKIMMINGS & SLUDGES; 252 - WASTE OILS & LUBRICANTS; 150 - INERT INORGANIC WASTES; 331 - WASTE COMPRESSED GASES; 221 - LIGHT FUELS; 252 - WASTE OILS & LUBRICANTS; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES; 212 - ALIPHATIC SOLVENTS; 222 - HEAVY FUELS

Generator Info as of Dec 2024

Generator No: ON001065537
Generator Company Name: City of Brampton
Street: 175 Sandalwood Parkway West
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A 1E8
Waste Class: 212 L,252 L,331 I,251 L,252 T,150 L,331 I,221 I,252 T,252 L,213 T,212 L,222 I

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 252 - WASTE OILS & LUBRICANTS; 331 - WASTE COMPRESSED GASES; 251 - OIL SKIMMINGS & SLUDGES; 252 - WASTE OILS & LUBRICANTS; 150 - INERT INORGANIC WASTES; 331 - WASTE COMPRESSED GASES; 221 - LIGHT FUELS; 252 - WASTE OILS & LUBRICANTS; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES; 212 - ALIPHATIC SOLVENTS; 222 - HEAVY FUELS

57	1 of 1	SSE/215.1	236.5 / -5.46	ON	WWIS

Well ID: 7217049
Construction Date:
Use 1st:
Use 2nd:
Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:

Final Well Status:		**Date Received:**	02/28/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C23581	**Contractor:**	7215
Tag:	A155149	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1004716242	**Tag No:**	A155149
Depth M:		**Contractor:**	7215
Year Completed:	2013	**Latitude:**	43.71266253262
Well Completed Dt:	12/06/2013	**Longitude:**	-79.8045848074915
Audit No:	C23581	**Y:**	43.712662531083275
Path:		**X:**	-79.80458465682558

Bore Hole Information

Bore Hole ID:	1004716242	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596303.00
Code OB Desc:		**North83:**	4840654.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12/06/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

58 | ***1 of 1*** | ***SSW/249.3*** | ***238.9 / -3.08*** | ***22 Coppermill Drive Brampton ON L7A 1N4*** | ***SPL***

Ref No:	0251-66QP54	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11/14/2004	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	Oil
MOE Reported Dt:	11/14/2004	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	PRIVATE RESIDENCE OF S.21<UNOFFICIAL>		
Site Address:			
Site Region:	Central		

Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	Other Discharges
Incident Preceding Spill:	
Incident Reason:	Unknown - Reason not determined
Incident Summary:	Brampton: Gasoline from vehicle to catchbasin.
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	Surface Water Pollution
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	12
Contaminant Name:	GASOLINE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Water
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	Spill to Inland Watercourses; Spill to Land
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

59 **1 of 1** **SSE/248.5** **235.9 / -6.08** **10534 HURONTARIO ST**
Mississauga ON **WWIS**

Well ID:	7342881	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	09/16/2019
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z312151	**Contractor:**	7320
Tag:	A270115	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/734\7342881.pdf

Additional Detail(s) (Map)

Well Completed Date: 06/08/2019
Year Completed: 2019
Depth (m): 6.1
Latitude: 43.7126471683874
Longitude: -79.8039768771224
X: -79.8039767266435
Y: 43.71264716631055
Path: 734\7342881.pdf

Bore Hole Information

Bore Hole ID: 1007669760
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/08/2019
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596352.00
North83: 4840653.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007872474
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 17
Material 3 Desc: SHALE
Formation Top Depth: 2.0999999046325684
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007872473
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 2.0999999046325684
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1007873631
Layer:	2
Plug From:	0.30000001192092896
Plug To:	2.700000047683716
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007873632
Layer:	3
Plug From:	2.700000047683716
Plug To:	6.099999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007873630
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1007875209
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Method of Construction & Well Use

Method Construction ID:	1007875210
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	HSA

Pipe Information

Pipe ID:	1007871517
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007875821
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	-0.699999988079071
Depth To:	3.049999952316284
Casing Diameter:	6.099999904632568
Casing Diameter UOM:	cm

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007876290
Layer: 1
Slot: .01
Screen Top Depth: 3.049999952316284
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007876905
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007876745
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth:
Water Found Depth UOM:

Hole Diameter

Hole ID: 1007874653
Diameter: 21.0
Depth From: 0.0
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

---

60 | ***1 of 1*** | ***SSE/238.5*** | ***235.5 / -6.47*** | ***20 Fisherman Drive Brampton ON*** | ***EHS***

Order No: 20160520077
Status: C
Report Type: Standard Report
Report Date: 27-MAY-16
Date Received: 20-MAY-16
Previous Site Name:
Lot/Building Size:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.803896
Y: 43.712461

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Additional Info Ordered:					
61	1 of 16	S/98.3	237.9 / -4.08	THE PEELLE COMPANY LIMITED 195 SANDALWOOD PKY W MISSISSAUGA ON L7A 1J6	SCT

Established: 1926
Plant Size (ft²): 80000
Employment: 100

--Details--
Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	2 of 16	S/98.3	237.9 / -4.08	The Peelle Company Limited 195 Sandalwood Pky W Brampton ON L7A 1J6	SCT

Established: 01-SEP-05
Plant Size (ft²): 80000
Employment:

--Details--
Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	3 of 16	S/98.3	237.9 / -4.08	PEELLE COMPANY LIMITED, THE 195 SANDAL WOOD PKWY WEST BRAMPTON ON L7A 1J6	GEN

Generator Info

Generator No: ON0138401
Approval Years: 99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: METAL DOOR & WINDOW

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3031

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 253

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		EMULSIFIED OILS			
61	4 of 16	S/98.3	237.9 / -4.08	PEELLE COMPANY LIMITED, THE 195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	GEN

Generator Info

Generator No:	ON0138401	**Choice of Contact:**	
Approval Years:	06,07,08	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	332321
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Metal Window and Door Manufacturing		

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

61	5 of 16	S/98.3	237.9 / -4.08	PEELLE COMPANY LIMITED, THE 195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	GEN

Generator Info

Generator No:	ON0138401	**Choice of Contact:**	
Approval Years:	2009	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	332321
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Metal Window and Door Manufacturing		

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

61 | ***6 of 16*** | ***S/98.3*** | ***237.9 / -4.08*** | ***PEELLE COMPANY LIMITED, THE 195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6*** | ***GEN***

Generator Info

Generator No: ON0138401
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Metal Window and Door Manufacturing
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 332321

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	7 of 16	S/98.3	237.9 / -4.08	PEELLE COMPANY LIMITED, THE 195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	GEN

Generator Info

Generator No:	ON0138401	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	332321
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Metal Window and Door Manufacturing		

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	8 of 16	S/98.3	237.9 / -4.08	PEELLE COMPANY LIMITED, THE 195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A 1J6	GEN

Generator Info

Generator No:	ON0138401	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	332321
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Metal Window and Door Manufacturing		

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

61	9 of 16	S/98.3	237.9 / -4.08	**PEELLE COMPANY LIMITED, THE** **195 SANDALWOOD PKWY. WEST** **BRAMPTON ON**	GEN

Generator Info

Generator No: ON0138401
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: METAL WINDOW AND DOOR MANUFACTURING
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 332321

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

61	10 of 16	S/98.3	237.9 / -4.08	**PEELLE COMPANY LIMITED, THE** **195 SANDALWOOD PKWY. WEST** **BRAMPTON ON L7A1J6**	GEN

Generator Info

Generator No: ON0138401
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: ALEX STOBO
Phone No Admin: 905-846-4545 Ext.225
SIC Description: METAL WINDOW AND DOOR MANUFACTURING
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 332321

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

61	11 of 16	S/98.3	237.9 / -4.08	**PEELLE COMPANY LIMITED, THE** **195 SANDALWOOD PKWY. WEST** **BRAMPTON ON L7A1J6**	GEN

Generator Info

Generator No: ON0138401
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: ALEX STOBO
Phone No Admin: 905-846-4545 Ext.225
SIC Description: METAL WINDOW AND DOOR MANUFACTURING
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 332321

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	12 of 16	S/98.3	237.9 / -4.08	PEELLE COMPANY LIMITED, THE 195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	GEN

Generator Info

Generator No: ON0138401
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: ALEX STOBO
Phone No Admin: 905-846-4545 Ext.225
SIC Description: METAL WINDOW AND DOOR MANUFACTURING
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 332321

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
61	13 of 16	S/98.3	237.9 / -4.08	PEELLE COMPANY LIMITED, THE 195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6	GEN

Generator Info

Generator No:	ON0138401	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class:	241 B
Waste Class Name:	Halogenated solvents and residues

Waste Detail(s)

Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	145 T
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	213 T
Waste Class Name:	Petroleum distillates

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class:	253 L
Waste Class Name:	Emulsified oils

Waste Detail(s)

Waste Class:	253 T
Waste Class Name:	Emulsified oils

61	***14 of 16***	***S/98.3***	***237.9 / -4.08***	***PEELLE COMPANY LIMITED, THE 195 SANDALWOOD PKWY. WEST BRAMPTON ON L7A1J6***	***GEN***

Generator Info

Generator No:	ON0138401	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	145 T
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	253 T
Waste Class Name:	Emulsified oils

Waste Detail(s)

Waste Class:	253 L
Waste Class Name:	Emulsified oils

Waste Detail(s)

Waste Class:	213 T
Waste Class Name:	Petroleum distillates

Waste Detail(s)

Waste Class:	241 B
Waste Class Name:	Halogenated solvents and residues

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints

61	***15 of 16***	***S/98.3***	***237.9 / -4.08***	***PEELLE COMPANY LIMITED, THE*** ***195 SANDALWOOD PKWY. WEST*** ***BRAMPTON ON L7A1J6***	***GEN***

Generator Info

Generator No:	ON0138401	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	

Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 253 T
Waste Class Name: Emulsified oils

Waste Detail(s)

Waste Class: 145 T
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 241 B
Waste Class Name: Halogenated solvents and residues

---

61 | ***16 of 16*** | ***S/98.3*** | ***237.9 / -4.08*** | ***The Peelle Company Limited***
195 SANDALWOOD PKWY. WEST
BRAMPTON ON | ***GEN***

Generator Info

Generator No: ON0138401
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 241 B
Waste Class Name: HALOGENATED SOLVENTS

Waste Detail(s)

Waste Class: 253 L
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 145 T
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 253 T
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Generator Info as of Dec 2024

Generator No: ON0138401
Generator Company Name: The Peelle Company Limited
Street: 195 SANDALWOOD PKWY. WEST
City: BRAMPTON
Province State: Ontario
Country: Canada
Postal Code: L7A1J6
Waste Class: 252 L,145 L,253 L,213 T,241 B,253 T,145 T,122 C,251 L

Waste Class Decoded:

252 - WASTE OILS & LUBRICANTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 253 - EMULSIFIED OILS; 213 - PETROLEUM DISTILLATES; 241

- HALOGENATED SOLVENTS; 253 - EMULSIFIED OILS; 145 - PAINT/PIGMENT/COATING RESIDUES; 122 - ALKALINE WASTES - OTHER METALS; 251 - OIL SKIMMINGS & SLUDGES

2017 Generator Info

Gen No:	ON0138401	***Choice of Contact:***	CO_ADMIN
ID:	1615	***Phone No Official:***	905-846-4545 Ext.225
Contaminated Fac:	N	***Phone No Admin:***	905-846-4545 Ext.206
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	332321	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	PEELLE COMPANY LIMITED, THE
Gen Div:	
Gen Op Name:	PEELLE COMPANY LIMITED, THE
Gen Op Div:	
Site Adrs1:	195 SANDALWOOD PKWY. WEST
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A1J6
Site Country:	Canada
Co Official:	DONELDA CROFT
Co Admin:	VESNA JOVICIC

2018 Generator Info

Gen No:	ON0138401	***Choice of Contact:***	CO_ADMIN
ID:	1576	***Phone No Official:***	905-846-4545 Ext.225
Contaminated Fac:	N	***Phone No Admin:***	905-846-4545 Ext.206
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	332321	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	PEELLE COMPANY LIMITED, THE
Gen Div:	
Gen Op Name:	PEELLE COMPANY LIMITED, THE
Gen Op Div:	
Site Adrs1:	195 SANDALWOOD PKWY. WEST
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A1J6
Site Country:	Canada
Co Official:	DONELDA CROFT
Co Admin:	VESNA JOVICIC

2018 Generator Manifest

ID:	7267	***Sum Received Qty:***	171.0
Generator No:	ON0138401	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	145		

2018 Generator Manifest

ID:	7265	***Sum Received Qty:***	38.0
Generator No:	ON0138401	***Waste Class Name:***	OTHER INORGANIC ACID WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	C	***District:***	305
Waste Code:	114		

2018 Generator Manifest

ID:	7269	***Sum Received Qty:***	205.0
Generator No:	ON0138401	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	252		

2018 Generator Manifest

ID:	7268	***Sum Received Qty:***	3690.0
Generator No:	ON0138401	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	***Count Manifests:***	5
Waste Char:	T	***District:***	305
Waste Code:	145		

2018 Generator Manifest

ID:	7266	***Sum Received Qty:***	57.0
Generator No:	ON0138401	***Waste Class Name:***	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	C	***District:***	305
Waste Code:	122		

2018 Generator Manifest

ID:	7270	***Sum Received Qty:***	410.0
Generator No:	ON0138401	***Waste Class Name:***	EMULSIFIED OILS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	T	***District:***	305
Waste Code:	253		

2019 Generator Info

Gen No:	ON0138401	***Choice of Contact:***	CO_ADMIN
ID:	1533	***Phone No Official:***	905-846-4545 Ext.206
Contaminated Fac:	N	***Phone No Admin:***	905-846-4545 Ext.206
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	332321	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	PEELLE COMPANY LIMITED, THE		
Gen Div:			
Gen Op Name:	PEELLE COMPANY LIMITED, THE		
Gen Op Div:			
Site Adrs1:	195 SANDALWOOD PKWY. WEST		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A1J6		
Site Country:	Canada		

Co Official: VESNA JOVICIC
Co Admin: VESNA JOVICIC

2019 Generator Manifest

ID: 7166
Generator No: ON0138401
Receiver Type: 035
Waste Char: B
Waste Code: 241
Sum Received Qty: 19.0
Waste Class Name: HALOGENATED SOLVENTS
Count Manifests: 1
District: 305

2019 Generator Manifest

ID: 7167
Generator No: ON0138401
Receiver Type: 035
Waste Char: T
Waste Code: 253
Sum Received Qty: 615.0
Waste Class Name: EMULSIFIED OILS
Count Manifests: 2
District: 305

2019 Generator Manifest

ID: 7165
Generator No: ON0138401
Receiver Type: 035
Waste Char: T
Waste Code: 145
Sum Received Qty: 5125.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 5
District: 305

2020 Generator Info

Gen No: ON0138401
ID: 1465
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 332321
NAICS Code2:
NAICS Code3:
Gen Name: PEELLE COMPANY LIMITED, THE
Gen Div:
Gen Op Name: PEELLE COMPANY LIMITED, THE
Gen Op Div:
Site Adrs1: 195 SANDALWOOD PKWY. WEST
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A1J6
Site Country: Canada
Co Official: VESNA JOVICIC
Co Admin: VESNA JOVICIC
Choice of Contact: CO_ADMIN
Phone No Official: 905-846-4545 Ext.206
Phone No Admin: 905-846-4545 Ext.206
County Ont: PEEL (R. M.)
County Out:
District: 305

2020 Generator Manifest

ID: 6465
Generator No: ON0138401
Receiver Type: 035
Waste Char: T
Waste Code: 145
Sum Received Qty: 6560.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 5
District: 305

2021 Generator Info

Gen No:	ON0138401	**Choice of Contact:**	CO_ADMIN
ID:	1447	**Phone No Official:**	905-846-4545 Ext.206
Contaminated Fac:	N	**Phone No Admin:**	905-846-4545 Ext.206
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	332321	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	PEELLE COMPANY LIMITED, THE		
Gen Div:			
Gen Op Name:	PEELLE COMPANY LIMITED, THE		
Gen Op Div:			
Site Adrs1:	195 SANDALWOOD PKWY. WEST		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A1J6		
Site Country:	Canada		
Co Official:	VESNA JOVICIC		
Co Admin:	VESNA JOVICIC		

2021 Generator Manifest

ID:	6423	**Sum Received Qty:**	410.0
Generator No:	ON0138401	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	252		

2021 Generator Manifest

ID:	6421	**Sum Received Qty:**	246469.0
Generator No:	ON0138401	**Waste Class Name:**	LANDFILL LEACHATES
Receiver Type:	020	**Count Manifests:**	6
Waste Char:	L	**District:**	102
Waste Code:	149		

2021 Generator Manifest

ID:	6422	**Sum Received Qty:**	6560.0
Generator No:	ON0138401	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	7
Waste Char:	T	**District:**	305
Waste Code:	145		

---

62 **1 of 6** **SSE/244.3** **234.9 / -7.08** ***HEART LAKE USED AUTO PARTS***
20 FISHERMAN DR
BRAMPTON ON L7A 1G2 **AUWR**

Headcode:	00096400
Headcode Desc:	AUTOMOBILE PARTS & SUPPLIES-USED & REBUILT
Phone:	
List Name:	
Description:	

---

62 **2 of 6** **SSE/244.3** **234.9 / -7.08** ***General Axle Products Inc.***
20 Fisherman Dr Unit 1
Brampton ON L7A 1G2 **SCT**

Established: 1991
Plant Size (ft²): 9000
Employment:

--Details--
Description: Motor Vehicle Transmission and Power Train Parts Manufacturing
SIC/NAICS Code: 336350

---

62 | ***3 of 6*** | ***SSE/244.3*** | ***234.9 / -7.08*** | ***Hutchins & Son Automotive Limited***
20 Fisherman Drive Unit #2
Brampton ON | ***GEN***

Generator Info

Generator No: ON8694583
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Used Motor Vehicle Parts and Accessories Wholesaler-Distributors, Automotive Parts and Accessories Stores, Used Car Dealers

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 415310, 441310, 441120

---

62 | ***4 of 6*** | ***SSE/244.3*** | ***234.9 / -7.08*** | ***Hutchins & Son Automotive Limited***
20 Fisherman Drive Unit #2
Brampton ON | ***GEN***

Generator Info

Generator No: ON8694583
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Used Motor Vehicle Parts and Accessories Wholesaler-Distributors, Automotive Parts and Accessories Stores, Used Car Dealers

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 415310, 441310, 441120

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

62 | ***5 of 6*** | ***SSE/244.3*** | ***234.9 / -7.08*** | ***HEART LAKE USED AUTO PARTS***
20 FISHERMAN DR
BRAMPTON ON L7A1G2 | ***AUWR***

Headcode: 01169400
Headcode Desc: SCRAP METALS

Phone: 9058402144
List Name:
Description:

---

62 **6 of 6** **SSE/244.3** **234.9 / -7.08** **HUTCHINS & SON AUTOMOTIVE LIMITED** **WDS**
20 FISHERMAN DR
BRAMPTON ON L7A 1G2

Approval No: R-007-2649777732
Mob Unit Cert No:
EBR Registry No:
Status: REGISTERED
Facility Type:
Record Type: EASR
Link Source: MOFA
Project Type: End-of-Life Vehicle Waste Disposal Sites
Application Status:
Issue Date: 2016-09-22
Input Date:
Date Received:
Est Closure Date:
Mobile Capacity:
Mobile Units:
Mobile Description:
Prop City:
Prop Postal:
Prop Phone:
Serial Link:
Approval Type: EASR-End-of-Life Vehicle Waste Disposal Sites
Proponent:
Prop Address:
Proponent County/District:
Full Address: 20 FISHERMAN DR
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2025277
PDF Site Location:

Total Area (ha):
Landfill Cap (m³):
Transfer Area (ha):
Transfer Cap (m³):
Transfer Cert No:
Inciner. Area (ha):
Inciner. Cap (t):
Process Area (m³):
Process Cap (m³/d):
Process Vol (m³):
Process Feed (m³):
Site Concession:
Site Region/County:
SWP Area Name: Toronto
MOE District: Halton-Peel
District Office:
Latitude: 43.71305556
Longitude: -79.8025
Geometry X:
Geometry Y:

---

63 **1 of 2** **WNW/198.5** **249.9 / 7.92** **CONSTRUCTION COMPANY** **SPL**
200 CRESTHAVEN ROAD MOTOR VEHICLE
(OPERATING FLUID)
BRAMPTON CITY ON L7A 1J5

Ref No: 173587
Year:
Incident Dt: 10/8/1999
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/8/1999
Dt Document Closed:
Site No:
MOE Response:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: PEEL REGION

Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	BRAMPTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	OTHER CAUSE (N.O.S.)
Incident Preceding Spill:	
Incident Reason:	OTHER
Incident Summary:	DARCELL DEVELOPMENTS- SPILL OF GASOLINE INTO CATCH BASIN- FIRE STARTED
Environment Impact:	CONFIRMED
Health Env Consequence:	
Nature of Impact:	Water course or lake
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND / WATER
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

63 | ***2 of 2*** | ***WNW/198.5*** | ***249.9 / 7.92*** | ***BRAMPTON PEST CONTROL***
200 CRESTHAVEN RD, UNIT 78
BRAMPTON ON L7A 1J5 | ***PES***

Detail Licence No:	02-01-06853-0	**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	OPERATOR	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PDF URL:

---

64 **1 of 12** **SSE/182.2** **234.9 / -7.08** **ITWAL LIMITED** **PES**
440 RAILSIDE DR
BRAMPTON ON L7A 1L1

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

64 **2 of 12** **SSE/182.2** **234.9 / -7.08** **ITWAL LIMITED** **PES**
440 RAILSIDE DR
BRAMPTON ON L7A 1L1

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

64 **3 of 12** **SSE/182.2** **234.9 / -7.08** **ITWAL LIMITED** **PES**
440 RAILSIDE DR
BRAMPTON ON L7A 1L1

Detail Licence No: 23-01-12756-0
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: LIMITED
Licence Type Code:
Licence Class:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	4 of 12	SSE/182.2	234.9 / -7.08	**BENTALL REAL ESTATE SERVICES** **440 Railside Drive** **Brampton ON L7A1L1**	NPRI

NPRI ID:	8800001265	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	
Rpt Type ID:		**Cont First Name:**	
Report Year:	2004	**Cont Last Name:**	
Not-Current Rpt?:		**Contact Position:**	
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	440 RAILSIDE DRIVE	**Cont Area Code:**	
Fac Address1:		**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:		**Cont Fax Area Cde:**	
Facility Lat:		**Contact Fax:**	
Facility Long:		**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	1	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	53		
NAICS 2 Description:	Real Estate and Rental and Leasing		
NAICS Code (4 digit):	5311		
NAICS 4 Description:	Lessors of Real Estate		
NAICS Code (6 digit):	531120		
NAICS 6 Description:	Lessors of Non-Residential Buildings (except Mini-Warehouses)		

Substance Release Report

CAS No:	11104-93-1
Report ID:	
Rpt Period:	2004
Subst Released:	Nitrogen oxides (expressed as NO2)
Air:	
Water:	
Land:	

Total Releases:
Units: tonnes

CAS No: 7446-09-5
Report ID:
Rpt Period: 2004
Subst Released: Sulphur dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004
Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:
Total Releases:
Units: tonnes

---

64 ***5 of 12*** ***SSE/182.2*** ***234.9 / -7.08*** ***440 Railside Drive Brampton ON*** ***EHS***

Order No: 20140918019
Status: C
Report Type: Custom Report
Report Date: 23-SEP-14
Date Received: 18-SEP-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.804442
Y: 43.710799

---

64 ***6 of 12*** ***SSE/182.2*** ***234.9 / -7.08*** ***The Regional Municipality of Peel 440 Railside Drive Brampton ON L7A1L1*** ***ECA***

Approval No: 4244-9LFK2J
Approval Date: 10/21/14
Status: Approved
Record Type:
Link Source:
SWP Area Name:
Approval Type:
Project Type: Air/Noise
Business Name: The Regional Municipality of Peel
Address:
Full Address: Heart Lake Community Recycling Centre Railside Drive (lot at south end of Railside Drive, adjacent to 440 Railside Drive) Brampton City, Regional Municipality of Peel L7A1L1
Full PDF Link:
PDF Site Location:

MOE District:
City: Brampton
Longitude:
Latitude:
Geometry X:
Geometry Y:

---

64 ***7 of 12*** ***SSE/182.2*** ***234.9 / -7.08*** ***440 Railside Dr Brampton ON L7A1L1*** ***EHS***

Order No: 20141121090
Status: C
Report Type: Site Report
Report Date: 24-NOV-14

Nearest Intersection:
Municipality: Peel
Client Prov/State: ON
Search Radius (km): .001

Date Received:	21-NOV-14	**X:**	-79.803562
Previous Site Name:		**Y:**	43.710675
Lot/Building Size:			
Additional Info Ordered:			

---

64 **8 of 12** **SSE/182.2** **234.9 / -7.08** **ITWAL LIMITED** **PES**
440 RAILSIDE DR
BRAMPTON ON L7A1L1

Detail Licence No:		**Operator Box:**	
Licence No:	16729	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	8409400
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

64 **9 of 12** **SSE/182.2** **234.9 / -7.08** **The Regional Municipality of Peel** **ECA**
Railside Dr (lot at south end of Railside Drive, adjacent to 440 Railside Drive)
Brampton ON L6T 4B9

Approval No:	4244-9LFK2J	**MOE District:**	
Approval Date:	2014-10-21	**City:**	
Status:	Approved	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	
SWP Area Name:		**Geometry Y:**	

Approval Type:	ECA-AIR
Project Type:	AIR
Business Name:	The Regional Municipality of Peel
Address:	Railside Dr (lot at south end of Railside Drive, adjacent to 440 Railside Drive)
Full Address:	
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/1723-8N3MA8-14.pdf
PDF Site Location:	

---

64 **10 of 12** **SSE/182.2** **234.9 / -7.08** **ITWAL LIMITED** **PES**
440 Railside Dr
Brampton ON L7A 1L1

Detail Licence No:		**Operator Box:**	
Licence No:	L-232-4032960540	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2018-11-13	**Operator Type:**	
Report Source:	PEST-Limited Vendor	**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Latitude:	43.71138889	**Operator Region:**	
Longitude:	-79.80472222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Toronto
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2103637		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	11 of 12	SSE/182.2	234.9 / -7.08	ITWAL LIMITED 440 RAILSIDE DR BRAMPTON ON L7A1L1	PES

Detail Licence No:		**Operator Box:**	
Licence No:	12756	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	8409400
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	12 of 12	SSE/182.2	234.9 / -7.08	ALECTRA UTILITIES CORPORATION 440 Railside Drive Brampton ON	SPL

Ref No:	1-1FVAUQ	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/27/2021 5:21:17 PM	**Impact to Health:**	1 Minor Health Impact
Dt Document Closed:	5/11/2022 10:04:59 AM	**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	440 Railside Drive Brampton		
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	ALECTRA UTILITIES CORPORATION		
Client Type:	Private Business		

Source Type:	
Incident Cause:	
Incident Preceding Spill:	Unknown / N/A
Incident Reason:	Unknown
Incident Summary:	Alectra Utilities transformer spill Brampton
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	150 litre (L)
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	Unknown
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HB;02ED - Nottawasaga;Credit - 16 Mile
Sector Type:	HYDRO-ELECTRIC POWER GENERATION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001474146"],"wkts":["POINT (-79.8034082000 43.7106364000)"],"creation_date":"2021-11-27"}
Time Reported:	
System Facility Address:	

65 | ***1 of 1*** | ***SSE/95.9*** | ***237.9 / -4.08*** | ***495619 - 153 Van Kirk Drive Brampton ON L7A 1A4*** | ***EHS***

Order No:	24062700392	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	CA
Report Date:	03-JUL-24	**Search Radius (km):**	.25
Date Received:	27-JUN-24	**X:**	-79.8074584
Previous Site Name:		**Y:**	43.7107876
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos		

66 | ***1 of 1*** | ***SSE/14.9*** | ***235.9 / -6.08*** | ***lot 13 con 1 ON*** | ***WWIS***

Well ID:	4908749	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	1
Final Well Status:	Abandoned-Other	**Date Received:**	06/14/2001
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	205388	**Contractor:**	6443
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	013
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4908749.pdf

Additional Detail(s) (Map)

Well Completed Date: 12/05/2000
Year Completed: 2000
Depth (m):
Latitude: 43.7109092331535
Longitude: -79.8056809398014
X: -79.80568078992643
Y: 43.71090923147361
Path: 490\4908749.pdf

Bore Hole Information

Bore Hole ID: 10323283
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/05/2000
Remarks:
Location Method Desc: Lot centroid
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596217.50
North83: 4840458.00
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: lot

Method of Construction & Well Use

Method Construction ID: 964908749
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871853
Casing No: 1
Comment:
Alt Name:

---

67 | ***1 of 1*** | ***S/125.6*** | ***238.0 / -3.93*** | ***Armacell Canada***
153 VAN KIRK DRIVE
BRAMPTON ON | ***GEN***

Generator Info

Generator No: ON1688801
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Generator Info as of Dec 2024

Generator No: ON1688801
Generator Company Name: Armacell Canada
Street: 153 VAN KIRK DRIVE
City: BRAMPTON
Province State: Ontario
Country: Canada
Postal Code: L7A1A4
Waste Class: 211 H,213 I,252 L,148 L,213 T,145 I,331 I

Waste Class Decoded:

211 - AROMATIC SOLVENTS; 213 - PETROLEUM DISTILLATES; 252 - WASTE OILS & LUBRICANTS; 148 - INORGANIC LABORATORY CHEMICALS; 213 - PETROLEUM DISTILLATES; 145 - PAINT/PIGMENT/COATING RESIDUES; 331 - WASTE COMPRESSED GASES

2017 Generator Info

Gen No: ON1688801
ID: 7577
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 333220
NAICS Code2:
NAICS Code3:
Gen Name: Armacell Canada
Gen Div:
Gen Op Name: Armacell Canada
Gen Op Div:
Site Adrs1: 153 VAN KIRK DRIVE
Site Bldg:

Choice of Contact: CO_ADMIN
Phone No Official: 905 846 3666 Ext.16160
Phone No Admin: 9058463666 Ext.239
County Ont: PEEL (R. M.)
County Out:
District: 305

Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Gerry GH Howe
Co Admin: Gerry GH Howe

2017 Generator Manifest

ID: 25172
Generator No: ON1688801
Receiver Type: 035
Waste Char: T
Waste Code: 213
Sum Received Qty: 120.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 4
District: 305

2018 Generator Info

Gen No: ON1688801
ID: 7388
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 333220
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_ADMIN
Phone No Official: 905 846 3666 Ext.16160
Phone No Admin: 9058463666 Ext.239
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: Armacell Canada
Gen Div:
Gen Op Name: Armacell Canada
Gen Op Div:
Site Adrs1: 153 VAN KIRK DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Gerry GH Howe
Co Admin: Gerry GH Howe

2018 Generator Manifest

ID: 24871
Generator No: ON1688801
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 600.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 305

2018 Generator Manifest

ID: 24870
Generator No: ON1688801
Receiver Type: 035
Waste Char: T
Waste Code: 213
Sum Received Qty: 120.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 4
District: 305

2019 Generator Info

Gen No: ON1688801
Choice of Contact: CO_ADMIN

ID:	7175	**Phone No Official:**	905 846 3666 Ext.16160
Contaminated Fac:	N	**Phone No Admin:**	9058463666 Ext.239
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	333220	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Armacell Canada		
Gen Div:			
Gen Op Name:	Armacell Canada		
Gen Op Div:			
Site Adrs1:	153 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1A4		
Site Country:	Canada		
Co Official:	Gerry GH Howe		
Co Admin:	Gerry GH Howe		

2019 Generator Manifest

ID:	24432	**Sum Received Qty:**	120.0
Generator No:	ON1688801	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	4
Waste Char:	T	**District:**	305
Waste Code:	213		

2020 Generator Info

Gen No:	ON1688801	**Choice of Contact:**	CO_ADMIN
ID:	6937	**Phone No Official:**	905 846 3666 Ext.16160
Contaminated Fac:	N	**Phone No Admin:**	9058463666 Ext.239
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	333220	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Armacell Canada		
Gen Div:			
Gen Op Name:	Armacell Canada		
Gen Op Div:			
Site Adrs1:	153 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1A4		
Site Country:	Canada		
Co Official:	Gerry GH Howe		
Co Admin:	Gerry GH Howe		

2020 Generator Manifest

ID:	21880	**Sum Received Qty:**	90.0
Generator No:	ON1688801	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	T	**District:**	305
Waste Code:	213		

2021 Generator Info

Gen No:	ON1688801	***Choice of Contact:***	CO_ADMIN
ID:	6767	***Phone No Official:***	905 846 3666 Ext.16160
Contaminated Fac:	N	***Phone No Admin:***	9058463666 Ext.239
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	333220	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	Armacell Canada
Gen Div:	
Gen Op Name:	Armacell Canada
Gen Op Div:	
Site Adrs1:	153 VAN KIRK DRIVE
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 1A4
Site Country:	Canada
Co Official:	Gerry GH Howe
Co Admin:	Gerry GH Howe

2021 Generator Manifest

ID:	22252	***Sum Received Qty:***	800.0
Generator No:	ON1688801	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	202
Waste Code:	252		

2021 Generator Manifest

ID:	22253	***Sum Received Qty:***	30.0
Generator No:	ON1688801	***Waste Class Name:***	PETROLEUM DISTILLATES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	T	***District:***	305
Waste Code:	213		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	1 of 34	S/125.6	238.0 / -3.93	***INDUSTRIAL THERMO POLYMERS*** ***153 VAN KIRK DR*** ***BRAMPTON ON L7A 1A4***	SCT

Established:	1980
Plant Size (ft²):	85000
Employment:	50

--Details--

Description:	UNSUPPORTED PLASTICS FILM AND SHEET
SIC/NAICS Code:	3081
Description:	UNSUPPORTED PLASTICS PROFILE SHAPES
SIC/NAICS Code:	3082
Description:	PLASTICS PIPE
SIC/NAICS Code:	3084
Description:	PLASTICS FOAM PRODUCTS
SIC/NAICS Code:	3086

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: PLASTICS PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3089

Description: FABRICATED PIPE AND PIPE FITTINGS
SIC/NAICS Code: 3498

Description: SHIP BUILDING AND REPAIRING
SIC/NAICS Code: 3731

68	*2 of 34*	*S/125.6*	*238.0 / -3.93*	***INDUSTRIAL THERMO POLYMERS LIMITED*** ***153 VAN KIRK DRIVE*** ***BRAMPTON CITY ON L7A 1A4***	*CA*

Certificate #: 8-3480-96-
Application Year: 96
Issue Date: 10/10/1996
Approval Type: Industrial air
Status:
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: USE OF HCFC 142-B, APPROVAL REQUIRED
Contaminants:
Emission Control:

68	*3 of 34*	*S/125.6*	*238.0 / -3.93*	***Industrial Thermo Polymers Ltd*** ***153 Van Kirk Dr*** ***Brampton ON L7A 1A4***	*SCT*

Established: 01-JAN-80
Plant Size (ft²): 400000
Employment:

--Details--
Description: Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: Polystyrene Foam Product Manufacturing
SIC/NAICS Code: 326140

Description: Doll, Toy and Game Manufacturing
SIC/NAICS Code: 339930

Description: Urethane and Other Foam Product (except Polystyrene) Manufacturing
SIC/NAICS Code: 326150

68	*4 of 34*	*S/125.6*	*238.0 / -3.93*	***Industrial Thermo Polymers Ltd.*** ***153 Van Kirk Dr*** ***Brampton ON L7A 1A4***	*SCT*

Established: 1980
Plant Size (ft²): 85000

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Employment: 50

---

68 | ***5 of 34*** | ***S/125.6*** | ***238.0 / -3.93*** | ***Industrial Thermo Polymers Limited***
153 Van Kirk Drive CITY OF BRAMPTON
ON | ***EBR***

EBR Registry No: IA6E0548
Ministry Ref No: 8344493RE1
Notice Type: Instrument Decision
Notice Stage:
Notice Date: August 19, 1996
Proposal Date: April 18, 1996
Year: 1996
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Industrial Thermo Polymers Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 153 Van Kirk Drive, Brampton Ontario, L7A 1A4
Comment Period:
URL:
Summary:

Site Location Details:

153 Van Kirk Drive CITY OF BRAMPTON

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

---

68 | ***6 of 34*** | ***S/125.6*** | ***238.0 / -3.93*** | ***INDUSTRIAL THERMO POLYMERS LTD***
153 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON1688801
Approval Years: 96,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: FOAMED & EXP. PLAS.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 1611

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 213

Waste Class Name: PETROLEUM DISTILLATES

---

68 | **7 of 34** | **S/125.6** | **238.0 / -3.93** | **INDUSTRIAL THERMO POLYMERS LTD.**
153 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | **GEN**

Generator Info

Generator No: ON1688801
Approval Years: 99,00,01,02,03,04,05,06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: FOAMED & EXP. PLAS.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 1611

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | **8 of 34** | **S/125.6** | **238.0 / -3.93** | **153 Vankirk Dr.**
Brampton ON L7A 1A4 | **EHS**

Order No: 20050816013
Status: C
Report Type: Custom Report
Report Date: 8/25/2005
Date Received: 8/16/2005
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: V ankirk & Sandlewood
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.807527
Y: 43.710123

---

68 | **9 of 34** | **S/125.6** | **238.0 / -3.93** | **Industrial Thermo Polymers Limited**
153 Van Kirk Drive Brampton Regional
Municipality of Peel L7A 1A4 CITY OF
BRAMPTON
ON | **EBR**

EBR Registry No: 010-1149
Ministry Ref No: 7363-6YPQJP
Notice Type: Instrument Decision
Notice Stage:
Notice Date: July 16, 2009
Proposal Date: July 23, 2007
Year: 2007
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Off Instrument Name:
Posted By:
Company Name: Industrial Thermo Polymers Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 153 Van Kirk Drive, Brampton Ontario, Canada L7A 1A4
Comment Period:
URL:
Summary:

Site Location Details:

153 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON

68	*10 of 34*	*S/125.6*	*238.0 / -3.93*	***Industrial Thermo Polymers Limited*** ***153 Van Kirk Dr*** ***Brampton ON L7A 1A4***	***CA***

Certificate #: 0887-7BQPHM
Application Year: 2008
Issue Date: 3/31/2008
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

68	*11 of 34*	*S/125.6*	*238.0 / -3.93*	***Industrial Thermo Polymers Limited*** ***153 Van Kirk Dr*** ***Brampton ON L7A 1A4***	***CA***

Certificate #: 4129-7QBSDN
Application Year: 2009
Issue Date: 7/10/2009
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

68	*12 of 34*	*S/125.6*	*238.0 / -3.93*	***INDUSTRIAL THERMO POLYMERS LTD.*** ***153 VAN KIRK DRIVE*** ***BRAMPTON ON L7A 1A4***	***GEN***

Generator Info

Generator No: ON1688801 ***Choice of Contact:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Rubber and Plastics Industry Machinery Manufacturing
Contaminated Fac:
MHSW Facility:
SIC Code: 333220

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

68	***13 of 34***	***S/125.6***	***238.0 / -3.93***	***Industrial Thermo Polymers Limited 153 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON***	***EBR***

EBR Registry No: 011-7092
Ministry Ref No: 5638-8XLQVF
Notice Type: Instrument Decision
Notice Stage:
Notice Date: August 04, 2015
Proposal Date: August 31, 2012
Year: 2012
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Industrial Thermo Polymers Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 153 Van Kirk Drive, Brampton Ontario, Canada L7A 1A4
Comment Period:
URL:
Summary:
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

153 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON

68	***14 of 34***	***S/125.6***	***238.0 / -3.93***	***INDUSTRIAL THERMO POLYMERS LTD. 153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4***	***GEN***

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON1688801
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Rubber and Plastics Industry Machinery Manufacturing
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 333220

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

68	15 of 34	S/125.6	238.0 / -3.93	INDUSTRIAL THERMO POLYMERS LTD. 153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No: ON1688801
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Rubber and Plastics Industry Machinery Manufacturing
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 333220

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

68	16 of 34	S/125.6	238.0 / -3.93	INDUSTRIAL THERMO POLYMERS LTD. 153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No:	ON1688801	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	333220
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Rubber and Plastics Industry Machinery Manufacturing		

Waste Detail(s)

Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

---

68 | ***17 of 34*** | ***S/125.6*** | ***238.0 / -3.93*** | ***1932675 ONTARIO LIMITED***
153 VAN KIRK DR
BRAMPTON ON L7A 1A4 | ***EASR***

Approval No:	R-003-1397208460	***MOE District:***	Halton-Peel
Status:	REGISTERED	***Municipality:***	BRAMPTON
Date:	2014-02-10	***Latitude:***	43.71055556
Record Type:	EASR	***Longitude:***	-79.80722222
Link Source:	MOFA	***Geometry X:***	
Project Type:	Heating System	***Geometry Y:***	
Full Address:			
Approval Type:	EASR-Heating System		
SWP Area Name:	Credit Valley		
PDF NAICS Code:			
PDF URL:			
PDF Site Location:			

---

68 | ***18 of 34*** | ***S/125.6*** | ***238.0 / -3.93*** | ***INDUSTRIAL THERMO POLYMERS LTD.***
153 VAN KIRK DRIVE
BRAMPTON ON | ***GEN***

Generator Info

Generator No:	ON1688801	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	333220
Country:			
Co Admin:			
Phone No Admin:			

SIC Description: RUBBER AND PLASTICS INDUSTRY MACHINERY MANUFACTURING

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | **19 of 34** | **S/125.6** | **238.0 / -3.93** | **Industrial Thermo Polymers Limited**
153 Van Kirk Dr
Brampton ON L7A 1A4 | **ECA**

Approval No: 8383-9Y2PVV
Approval Date: 2015-07-30
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Industrial Thermo Polymers Limited
Address: 153 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5638-8XLQVF-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.80716
Latitude: 43.710674
Geometry X:
Geometry Y:

---

68 | **20 of 34** | **S/125.6** | **238.0 / -3.93** | **ARMACELL CANADA INC.**
153 VAN KIRK DR
BRAMPTON ON L7A 1A4 | **EASR**

Approval No: R-003-3571116459
Status: REGISTERED
Date: 2016-02-18
Record Type: EASR
Link Source: MOFA
Project Type: Heating System
Full Address:
Approval Type: EASR-Heating System
SWP Area Name: Credit Valley
PDF NAICS Code:
PDF URL:
PDF Site Location:

MOE District: Halton-Peel
Municipality: BRAMPTON
Latitude: 43.71055556
Longitude: -79.8075
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	21 of 34	S/125.6	238.0 / -3.93	153 Van Kirk Dr Brampton ON L7A1A4	EHS

Order No:	20150211048	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	12-FEB-15	**Search Radius (km):**	.25
Date Received:	11-FEB-15	**X:**	-79.80728
Previous Site Name:		**Y:**	43.710817
Lot/Building Size:			

Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	22 of 34	S/125.6	238.0 / -3.93	Industrial Thermo Polymers Limited 153 Van Kirk Dr Brampton ON L7A 1A4	ECA

Approval No:	4129-7QBSDN	**MOE District:**	Halton-Peel
Approval Date:	2009-07-10	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.80716
Record Type:	ECA	**Latitude:**	43.710674
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Industrial Thermo Polymers Limited
Address: 153 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7363-6YPQJP-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	23 of 34	S/125.6	238.0 / -3.93	Industrial Thermo Polymers Limited 153 Van Kirk Dr Brampton ON L7A 1A4	ECA

Approval No:	0887-7BQPHM	**MOE District:**	Halton-Peel
Approval Date:	2008-03-31	**City:**	
Status:	Approved	**Longitude:**	-79.80716
Record Type:	ECA	**Latitude:**	43.710674
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	

Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Industrial Thermo Polymers Limited
Address: 153 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1998-77FMAJ-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	24 of 34	S/125.6	238.0 / -3.93	INDUSTRIAL THERMO POLYMERS LTD. 153 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No:	ON1688801	**Choice of Contact:**	CO_ADMIN
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	333220
Country:	Canada		

Co Admin: Gerry GH Howe
Phone No Admin: 9058463666 Ext.239
SIC Description: RUBBER AND PLASTICS INDUSTRY MACHINERY MANUFACTURING

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

68 | ***25 of 34*** | ***S/125.6*** | ***238.0 / -3.93*** | ***INDUSTRIAL THERMO POLYMERS LTD.***
153 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON1688801
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 333220
Co Admin: Gerry GH Howe
Phone No Admin: 9058463666 Ext.239
SIC Description: RUBBER AND PLASTICS INDUSTRY MACHINERY MANUFACTURING

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

68 | **26 of 34** | **S/125.6** | **238.0 / -3.93** | **INDUSTRIAL THERMO POLYMERS LTD.**
153 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | **GEN**

Generator Info

Generator No: ON1688801
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Gerry GH Howe
Phone No Admin: 9058463666 Ext.239
SIC Description: RUBBER AND PLASTICS INDUSTRY MACHINERY MANUFACTURING
Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 333220

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

68 | **27 of 34** | **S/125.6** | **238.0 / -3.93** | **Armacell Canada**
153 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | **GEN**

Generator Info

Generator No: ON1688801
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 T

Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	28 of 34	S/125.6	238.0 / -3.93	**Armacell Canada** **153 VAN KIRK DRIVE** **BRAMPTON ON L7A 1A4**	GEN

Generator Info

Generator No: ON1688801
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

---

68 | ***29 of 34*** | ***S/125.6*** | ***238.0 / -3.93*** | ***153 Vankirk Drive Brampton ON*** | ***SPL***

Ref No: 0030-BAWS35
Year:
Incident Dt: 4/4/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/4/2019
Dt Document Closed: 4/6/2019
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Parking Lot<UNOFFICIAL>
Site Address: 153 Vankirk Drive
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4840419.19
Easting: 596082.47
Entity Operating Name:
Client Name:
Client Type:
Source Type: Container/Drum/Tote
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Unknown / N/A
Incident Summary: Manitoulin Transport - < 0.5L Lube Oil, To Asphalt Parking Lot
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0.5 L
Contaminant Qty 1: 0.5
Contaminant Unit: L
Contaminant Code: 15
Contaminant Name: SEAL OIL (TURBINE LUBE OIL)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

---

68 | ***30 of 34*** | ***S/125.6*** | ***238.0 / -3.93*** | ***Armacell Canada Inc. 153 Van Kirk Dr*** | ***SPL***

Brampton ON L7A 1A4

Ref No:	8775-BGRREH	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	10/8/2019	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/8/2019	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	

Site No:	3130-65YR7P
MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	NA
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	153 Van Kirk Drive
Site Address:	153 Van Kirk Dr
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	NA
Site Geo Ref Accu:	NA
Site Map Datum:	NA
Northing:	NA
Easting:	NA
Entity Operating Name:	
Client Name:	Armacell Canada Inc.
Client Type:	Corporation
Source Type:	Discharge Point (Stack/Pipe) - Manufacturing
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Equipment Failure
Incident Summary:	Armacell dust release to property
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	1 hr
Contaminant Qty 1:	1
Contaminant Unit:	hr
Contaminant Code:	32
Contaminant Name:	DUST
Contaminant Limit 1:	
Contam Limit Freq 1:	n/a
Contaminant UN No 1:	n/a
Receiving Medium:	Air
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Air Spills - Gases and Vapours
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

68 | **31 of 34** | **S/125.6** | **238.0 / -3.93** | **Armacell Canada Inc.**
153 Van Kirk Dr.
Brampton ON | **SPL**

Ref No:	3431-BQVMBV	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2020/06/24	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2020/06/24	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	

Site No:	NA
MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Armacell Canada<UNOFFICIAL>
Site Address:	153 Van Kirk Dr.
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	Armacell Canada Inc.
Client Type:	Corporation
Source Type:	Storage Facility
Incident Cause:	
Incident Preceding Spill:	Process Upset/Malfunction
Incident Reason:	Equipment Failure
Incident Summary:	Armacell: ~400yd² PET Dust to Ground, Contained & Cleaning
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	400
Contaminant Qty 1:	400
Contaminant Unit:	
Contaminant Code:	27
Contaminant Name:	POLYETHYLENE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Air; Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

68	***32 of 34***	***S/125.6***	***238.0 / -3.93***	***Armacell Canada*** ***153 VAN KIRK DRIVE*** ***BRAMPTON ON L7A 1A4***	***GEN***

Generator Info

Generator No:	ON1688801	**Choice of Contact:**	
Approval Years:	As of Nov 2021	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

---

68 | **33 of 34** | **S/125.6** | **238.0 / -3.93** | **ARMACELL CANADA INC.**
153 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | **NPR2**

NPRI ID: 7190
Facility ID: 245078;279943;376909;402991;436620;448993
Facility Name: ARMACELL CANADA INC.
Latitude: 43.7107
Longitude: -79.8075
Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=7190

NPRI ID Substances Summary

CAS No: NA - M09
Is VOC?: FALSE
Is DF?: FALSE
Is PAH?: FALSE
NPRI: TRUE
Name English: PM10 - Particulate Matter <= 10 Micrometers
Name French: PM10 - Matière particulaire <= 10 micromètres
Sort English: PM10 - Particulate Matter <= 10 Micrometers
Sort French: PM10 - Matière particulaire <= 10 micromètres

CAS No: N/A (Speciated VOCs)
Is VOC?: FALSE
Is DF?: FALSE
Is PAH?: FALSE
NPRI: TRUE
Name English: Speciated VOCs (62 substances)
Name French: COVs différenciés (62 substances)
Sort English: Speciated VOCs (62 substances)
Sort French: COVs différenciés (62 substances)

CAS No:	NA - M16	***Is PAH?:***	FALSE
Is VOC?:	TRUE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Volatile Organic Compounds (VOCs)		
Name French:	Composés organiques volatils (COV)		
Sort English:	Volatile Organic Compounds (VOCs)		
Sort French:	Composés organiques volatils (COV)		

CAS No:	NA - M16	***Is PAH?:***	FALSE
Is VOC?:	TRUE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Volatile Organic Compounds (Total)		
Name French:	Composés organiques volatils (total)		
Sort English:	Volatile Organic Compounds (Total)		
Sort French:	Composés organiques volatils (total)		

CAS No:	NA - M10	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Name French:	PM2,5 - Matière particulaire <= 2,5 micromètres		
Sort English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Sort French:	PM2,5 - Matière particulaire <= 2,5 micromètres		

CAS No:	N/A (Speciated VOCs)	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Speciated VOCs (62 substances)		
Name French:	COVs différenciés (62 substances)		
Sort English:			
Sort French:			

Geographic Location

Report Year:	-1	***Forward Sort Area:***	L6Z
Census Subdiv ID:	3521010	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-055-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.7107
QC PEMA:	FALSE	***Longitude:***	-79.8075
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	7190
Facility ID:	448993

Facility

Facility ID:	448993	***IDM ID:***	9653
Portable:	FALSE	***AB Approval ID:***	
NAICS Primary:	326150	***GHGRP ID:***	
NAICS Secondary:		***ON GHGRP ID:***	
NAICS Tertiary:			
Facility Name:	Armacell Canada Inc.		
Website:			

Address

Address1:	153 Van Kirk Drive

Address2:
City: Brampton
Postal Zip: L7A 1A4
Prov:

Address Geographic

Latitude:	43.710700	***Datum:***	
Longitude:	-79.807500	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	326150	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques, sauf de polystyrène		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NPRI Report

Report ID:	348030	***No of Employees:***	146
Report Year:	2022	***Is Compressor:***	
Company ID:	181908	***Is NPRI Part 4:***	
SWR Report ID:	30194	***Is Battery:***	

Repor Type ID:	8	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2023-06-01 14:25:28.6161585

Company

Company Name:	Armacell Canada Inc.
DUNS No:	
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	905-920-3060
First Name:	Ben	***Extension:***	
Last Name:	Sprang	***Fax:***	
Company Name:	SONAIR Environmental Inc.		
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	1		
Email:	bsprang@sonairenviro.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-846-3666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-846-3666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-846-3666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		**Phone:**	905-846-3666
First Name:	Paul	**Extension:**	162105
Last Name:	Blair	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI ID Facility ID

NPRI ID:	7190
Facility ID:	245078

Facility

Facility ID:	245078	**IDM ID:**	9653
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	326150	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:	Armacell Canada Inc.		
Website:			

Address

Address1:	153 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4
Prov:	

Address Geographic

Latitude:	43.7107	**Datum:**	1983
Longitude:	-79.8075	**Land Survey:**	
UTM Easting:	0.000000	**Topograph:**	
UTM Northing:	0.000000	**Additional Info:**	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	326150	**Start Date:**	2007
Record Year:	2007	**End Date:**	2011
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	**Start Date:**	2022

Record Year: 2022 ***End Date:*** 2026
Key Indus Sector En: Plastics and Rubber
Key Indus Sector Fr: Plastiques et caoutchouc
NAICS Title En: Urethane and other foam product (except polystyrene) manufacturing
NAICS Title Fr: Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code: 326150 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Plastics and Rubber
Key Indus Sector Fr: Plastiques et caoutchouc
NAICS Title En: Urethane and other foam product (except polystyrene) manufacturing
NAICS Title Fr: Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code: 326150 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Plastics and Rubber
Key Indus Sector Fr: Plastiques et caoutchouc
NAICS Title En: Urethane and other foam product (except polystyrene) manufacturing
NAICS Title Fr: Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code: 326150 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Plastics and Rubber
Key Indus Sector Fr: Plastiques et caoutchouc
NAICS Title En: Urethane and Other Foam Product (except Polystyrene) Manufacturing
NAICS Title Fr: Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques, sauf de polystyrène

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NPRI Report

Report ID:	15913	***No of Employees:***	95
Report Year:	2015	***Is Compressor:***	
Company ID:	109867	***Is NPRI Part 4:***	
SWR Report ID:	68529	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2016-05-25 00:00:00.0000000

Company

Company Name:	Armacell Canada Inc.
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058463666
First Name:	Linda	***Extension:***	273
Last Name:	Bailey	***Fax:***	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Emmanuel	***Extension:***	
Last Name:	Piec	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	emmanuel.n.piec@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Emmanuel	***Extension:***	
Last Name:	Piec	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	emmanuel.n.piec@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Linda	***Extension:***	273
Last Name:	Bailey	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9056354063
First Name:	Robin	***Extension:***	3701
Last Name:	Brown	***Fax:***	9056354874
Company Name:	Rubidium Environmental		
Description En:			
Description Fr:			
Position:	President		
Language:	1		
Email:	rbrown@rb-enviro.com		

NPRI ID Facility ID

NPRI ID:	7190
Facility ID:	402991

Facility

Facility ID:	402991	***IDM ID:***	9653
Portable:	FALSE	***AB Approval ID:***	
NAICS Primary:	326150	***GHGRP ID:***	
NAICS Secondary:	0	***ON GHGRP ID:***	
NAICS Tertiary:	0		
Facility Name:	Armacell Canada Inc.		
Website:			

Address

Address1:	153 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A 1A4
Prov:	

Address Geographic

Latitude:	43.7107	***Datum:***	
Longitude:	-79.8075	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	326150	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques, sauf de polystyrène		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2022

Record Year:	2022	**End Date:**	2026
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	**Start Date:**	2007
Record Year:	2007	**End Date:**	2011
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	**Start Date:**	2017
Record Year:	2017	**End Date:**	2021
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NPRI Report

Report ID:	309211	**No of Employees:**	150
Report Year:	2020	**Is Compressor:**	
Company ID:	162997	**Is NPRI Part 4:**	
SWR Report ID:	166151	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	1
New Reporter:	FALSE	**Submit Date:**	2021-07-14 08:54:45.3433333

Company

Company Name: Armacell Canada Inc.
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Zannatul
Last Name: Hasib
Company Name:
Description En:
Description Fr:
Position: Engineering Manager
Language: 1
Email: zannatul.m.hasib@armacell.com
Phone: 9058463666
Extension: 161403
Fax:

NPRI Report Contact

Contact Type:
First Name: Paul
Last Name: Blair
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 1
Email: paul.blair@armacell.com
Phone: 9058463666
Extension: 162105
Fax:

NPRI Report Contact

Contact Type:
First Name: Zannatul
Last Name: Hasib
Company Name:
Description En:
Description Fr:
Position: Engineering Manager
Language: 1
Email: zannatul.m.hasib@armacell.com
Phone: 9058463666
Extension: 161403
Fax:

NPRI Report Contact

Contact Type:
First Name: Thomas
Last Name: Li
Company Name: SONAIR Environmental Inc.
Description En:
Description Fr:
Position: Principal
Language: 1
Email: tli@sonairenviro.com
Phone: 9059203060
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Thomas
Last Name: Li
Company Name:
Description En:
Description Fr:
Phone: 9059203060
Extension:
Fax:

Position: Principal
Language: 1
Email: tli@sonairenviro.com

NPRI Report Contact

Contact Type:
First Name: Zannatul
Last Name: Hasib
Company Name:
Description En:
Description Fr:
Position: Engineering Manager
Language: 1
Email: zannatul.m.hasib@armacell.com
Phone: 9058463666
Extension: 161403
Fax:

NPRI Report Contact

Contact Type: NPRI
First Name: Zannatul
Last Name: Hasib
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Engineering Manager
Language: 1
Email: zannatul.m.hasib@armacell.com
Phone: 9058463666
Extension: 161403
Fax:

NPRI Report Contact

Contact Type:
First Name: Paul
Last Name: Blair
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 1
Email: paul.blair@armacell.com
Phone: 9058463666
Extension: 162105
Fax:

NPRI Report

Report ID: 305127
Report Year: 2019
Company ID: 162997
SWR Report ID: 158331
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 150
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 1
Submit Date: 2020-07-31 17:31:09.2066667

Company

Company Name: Armacell Canada Inc.
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Paul
Phone: 9058463666
Extension: 162105

Last Name:	Blair	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Engineering Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Jason	***Extension:***	161005
Last Name:	Collins	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	jason.collins@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9059203060
First Name:	Thomas	***Extension:***	
Last Name:	Li	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Principal		
Language:	1		
Email:	tli@sonairenviro.com		

NPRI Report Contact

Contact Type:		***Phone:***	9059203060
First Name:	Thomas	***Extension:***	
Last Name:	Li	***Fax:***	
Company Name:	SONAIR Environmental		
Description En:			
Description Fr:			
Position:	Principal		
Language:	1		
Email:	tli@sonairenviro.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058463666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Engineering Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			

Description En:
Description Fr:
Position: Engineering Manager
Language: 1
Email: paul.blair@armacell.com

NPRI Report Contact

Contact Type:
First Name: Paul
Last Name: Blair
Company Name:
Description En:
Description Fr:
Position: Engineering Manager
Language: 1
Email: paul.blair@armacell.com
Phone: 9058463666
Extension: 162105
Fax:

NPRI Report Contact

Contact Type:
First Name: Jason
Last Name: Collins
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 1
Email: jason.collins@armacell.com
Phone: 9058463666
Extension: 161005
Fax:

NPRI ID Facility ID

NPRI ID: 7190
Facility ID: 436620

Facility

Facility ID: 436620
Portable: FALSE
NAICS Primary: 326150
NAICS Secondary: 0
NAICS Tertiary: 0
Facility Name: Armacell Canada Inc.
Website:
IDM ID: 9653
AB Approval ID:
GHGRP ID:
ON GHGRP ID:

Address

Address1:
Address2:
City: Brampton
Postal Zip: L7A 1A4
Prov:

Address Geographic

Latitude: 43.710700
Longitude: -79.807500
UTM Easting: 0.000000
UTM Northing: 0.000000
UTM Zone: 0
Datum:
Land Survey:
Topograph:
Additional Info:

Primary NAICS Details

NAICS Code:	326150	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques, sauf de polystyrène		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NPRI Report

Report ID:	329123	***No of Employees:***	146
Report Year:	2021	***Is Compressor:***	
Company ID:	175868	***Is NPRI Part 4:***	
SWR Report ID:	19567	***Is Battery:***	
Repor Type ID:	8	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2022-05-31 10:30:30.8250594

Company

Company Name:	Armacell Canada Inc.
DUNS No:	
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	905-846-3666
First Name:	Paul	***Extension:***	161603
Last Name:	Gill	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Engineering Manager		
Language:	1		
Email:	paul.gill@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-920-3060
First Name:	Natalie	***Extension:***	
Last Name:	Mayer	***Fax:***	
Company Name:	SONAIR Environmental Inc.		
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	1		
Email:	nmayer@sonairenviro.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-846-3666
First Name:	Paul	***Extension:***	161603
Last Name:	Gill	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Engineering Manager		
Language:	1		
Email:	paul.gill@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-846-3666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-846-3666
First Name:	Paul	***Extension:***	161603
Last Name:	Gill	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Engineering Manager		
Language:	1		
Email:	paul.gill@armacell.com		

NPRI ID Facility ID

NPRI ID:	7190
Facility ID:	279943

Facility

Facility ID:	279943	***IDM ID:***	9653
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	326150	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	INDUSTRIAL THERMO POLYMERS		
Website:			

Address

Address1:	153 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4
Prov:	

Address Geographic

Latitude:	43.7107	***Datum:***	1983
Longitude:	-79.8075	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	326150	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques, sauf de polystyrène		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and Other Foam Product (except Polystyrene) Manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NPRI Report

Report ID:	89233	***No of Employees:***	150
Report Year:	2018	***Is Compressor:***	
Company ID:	109866	***Is NPRI Part 4:***	
SWR Report ID:	147112	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2019-05-30 14:34:32.0433333

Company

Company Name:	Industrial Thermo Polymers
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9056354063
First Name:	Scott	***Extension:***	3700
Last Name:	Ackerl	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	1		
Email:	sackerl@rb-enviro.com		

NPRI Report Contact

Contact Type:		***Phone:***	9056354063
First Name:	Thomas	***Extension:***	3704
Last Name:	Li	***Fax:***	9056354874
Company Name:	Rubidium Environmental		
Description En:			
Description Fr:			
Position:	Technical Manager, Environmental Compliance Services		
Language:	1		
Email:	tli@rb-enviro.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Engineering Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Jason	***Extension:***	161005
Last Name:	Collins	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	jason.collins@armacell.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058463666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Engineering Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Engineering Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Jason	***Extension:***	161005
Last Name:	Collins	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	jason.collins@armacell.com		

NPRI Report

Report ID:	89236	***No of Employees:***	148
Report Year:	2017	***Is Compressor:***	
Company ID:	109866	***Is NPRI Part 4:***	
SWR Report ID:	152430	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2019-05-27 10:55:43.8500000

Company

Company Name:	Industrial Thermo Polymers
DUNS No:	340399982
Trade Name En:	

Trade Name Fr:
Website:

NPRI Report Comment

Description En: NPRI report update comment
Description Fr: Commentaire sur la mise à jour du rapport de l'INRP
Comment: No changes are made. Comparing 2017 and 2018 new SWIM implementations.
Note:

NPRI Report Contact

Contact Type:
First Name: Robin
Last Name: Brown
Company Name: Rubidium Environmental
Description En:
Description Fr:
Position: President
Language: 1
Email: rbrown@rb-enviro.com
Phone: 9056354063
Extension: 3701
Fax: 9056354874

NPRI Report Contact

Contact Type:
First Name: Jason
Last Name: Collins
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 1
Email: jason.collins@armacell.com
Phone: 9058463666
Extension: 161005
Fax:

NPRI Report Contact

Contact Type:
First Name: Andrew
Last Name: Beck
Company Name:
Description En:
Description Fr:
Position: Project Engineering Specialist
Language: 1
Email: abeck@rb-enviro.com
Phone: 9056354063
Extension: 3702
Fax:

NPRI Report Contact

Contact Type:
First Name: Paul
Last Name: Blair
Company Name:
Description En:
Description Fr:
Position: Engineering Manager
Language: 1
Email: paul.blair@armacell.com
Phone: 9058463666
Extension: 162105
Fax:

NPRI Report Contact

Contact Type:
Phone: 9058463666

First Name:	Jason	***Extension:***	161005
Last Name:	Collins	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	jason.collins@armacell.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058463666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Engineering Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Paul	***Extension:***	162105
Last Name:	Blair	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Engineering Manager		
Language:	1		
Email:	paul.blair@armacell.com		

NPRI Report

Report ID:	89232	***No of Employees:***	120
Report Year:	2016	***Is Compressor:***	
Company ID:	109866	***Is NPRI Part 4:***	
SWR Report ID:	82219	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2017-05-29 09:16:03.0033333

Company

Company Name:	Industrial Thermo Polymers
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9056354063
First Name:	Shelby	***Extension:***	3709
Last Name:	Hawkins	***Fax:***	9056354874
Company Name:			
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	1		
Email:	shawkins@rb-enviro.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Mohammad	***Extension:***	162104
Last Name:	Hasan	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Process Technologist		
Language:	1		
Email:	mohammad.m.hasan@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Mohammad	***Extension:***	162104
Last Name:	Hasan	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Process Technologist		
Language:	1		
Email:	mohammad.m.hasan@armacell.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Emmanuel	***Extension:***	
Last Name:	Piec	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	emmanuel.n.piec@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Emmanuel	***Extension:***	
Last Name:	Piec	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	1		
Email:	emmanuel.n.piec@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9056354063
First Name:	Robin	***Extension:***	3701
Last Name:	Brown	***Fax:***	9056354874
Company Name:	Rubidium Environmental		
Description En:			
Description Fr:			
Position:	President		
Language:	1		
Email:	rbrown@rb-enviro.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058463666
First Name:	Mohammad	**Extension:**	162104
Last Name:	Hasan	**Fax:**	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Senior Process Technologist		
Language:	1		
Email:	mohammad.m.hasan@armacell.com		

NPRI Report

Report ID:	24540	**No of Employees:**	99
Report Year:	2014	**Is Compressor:**	
Company ID:	109866	**Is NPRI Part 4:**	
SWR Report ID:	43609	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	1
New Reporter:	FALSE	**Submit Date:**	2015-03-12 00:00:00.0000000

Company

Company Name:	Industrial Thermo Polymers
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9058463666
First Name:	Linda	**Extension:**	273
Last Name:	Bailey	**Fax:**	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058463666
First Name:	Linda	**Extension:**	273
Last Name:	Bailey	**Fax:**	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:		**Phone:**	9056354063
First Name:	Robin	**Extension:**	3701
Last Name:	Brown	**Fax:**	9056354874
Company Name:	Rubidium Environmental		
Description En:			
Description Fr:			
Position:	President		
Language:	1		

Email: rbrown@rb-enviro.com

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Chairman/CEO		
Language:	1		
Email:	itps@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Chairman/CEO		
Language:	1		
Email:	itps@tundrafoam.com		

NPRI Report

Report ID:	34361	***No of Employees:***	95
Report Year:	2013	***Is Compressor:***	
Company ID:	109866	***Is NPRI Part 4:***	
SWR Report ID:	28136	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2014-04-16 00:00:00.0000000

Company

Company Name:	Industrial Thermo Polymers
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058463666
First Name:	Linda	***Extension:***	273
Last Name:	Bailey	***Fax:***	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			

Description En:
Description Fr:
Position: Chairman/CEO
Language: 1
Email: itps@tundrafoam.com

NPRI Report Contact

Contact Type:
First Name: Steve
Last Name: Hartman
Company Name:
Description En:
Description Fr:
Position: Chairman/CEO
Language: 1
Email: itps@tundrafoam.com
Phone: 9058463666
Extension: 229
Fax: 9058460363

NPRI Report Contact

Contact Type:
First Name: Connie
Last Name: Lum
Company Name: Pinchin Environmental Ltd.
Description En:
Description Fr:
Position: Senior Project Manager
Language: 1
Email: clum@Pinchin.com
Phone: 5197464210
Extension: 3758
Fax: 5197467108

NPRI Report Contact

Contact Type:
First Name: Linda
Last Name: Bailey
Company Name:
Description En:
Description Fr:
Position: Manager, Research & Development
Language: 1
Email: linda@tundrafoam.com
Phone: 9058463666
Extension: 273
Fax: 9058460363

NPRI Report

Report ID: 43875
Report Year: 2012
Company ID: 109866
SWR Report ID: 14717
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 107
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 1
Submit Date: 2013-05-27 00:00:00.0000000

Company

Company Name: Industrial Thermo Polymers
DUNS No: 340399982
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:		**Phone:**	9058463666
First Name:	Linda	**Extension:**	273
Last Name:	Bailey	**Fax:**	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058463666
First Name:	Steve	**Extension:**	229
Last Name:	Hartman	**Fax:**	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Chairman/CEO		
Language:	1		
Email:	itps@tundrafoam.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058463666
First Name:	Steve	**Extension:**	229
Last Name:	Hartman	**Fax:**	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Chairman/CEO		
Language:	1		
Email:	itps@tundrafoam.com		

NPRI Report Contact

Contact Type:		**Phone:**	9053631367
First Name:	Connie	**Extension:**	
Last Name:	Lum	**Fax:**	9053630681
Company Name:	Pinchin Environmental Ltd.		
Description En:			
Description Fr:			
Position:	Senior Project Manager		
Language:	1		
Email:	clum@pinchin.com		

NPRI Report

Report ID:	55725	**No of Employees:**	95
Report Year:	2011	**Is Compressor:**	
Company ID:	109866	**Is NPRI Part 4:**	
SWR Report ID:	6425	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	1
New Reporter:	FALSE	**Submit Date:**	2012-06-27 00:00:00.0000000

Company

Company Name:	Industrial Thermo Polymers
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	President		
Language:	1		
Email:	itps@thundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Linda	***Extension:***	273
Last Name:	Bailey	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9053631325
First Name:	Ian	***Extension:***	
Last Name:	Hutcheson	***Fax:***	
Company Name:	Pinchin Environmental Ltd.		
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	1		
Email:	ihutcheson@pinchin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	President		
Language:	1		
Email:	itps@thundrafoam.com		

NPRI Report

Report ID:	130417	***No of Employees:***	130
Report Year:	2010	***Is Compressor:***	
Company ID:	109866	***Is NPRI Part 4:***	
SWR Report ID:	20100000007190	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2011-06-07 00:00:00.0000000

Company

Company Name:	Industrial Thermo Polymers

DUNS No: 340399982
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type: NPRI
First Name: Steve
Last Name: Hartman
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: President
Language: 0
Email: itps@thundrafoam.com
Phone: 9058463666
Extension: 229
Fax: 9058460363

NPRI Report Contact

Contact Type:
First Name: Linda
Last Name: Bailey
Company Name:
Description En:
Description Fr:
Position: Manager, Research & Development
Language: 0
Email: linda@tundrafoam.com
Phone: 9058463666
Extension: 273
Fax: 9058460363

NPRI Report Contact

Contact Type:
First Name: Steve
Last Name: Hartman
Company Name:
Description En:
Description Fr:
Position: President
Language: 0
Email: itps@thundrafoam.com
Phone: 9058463666
Extension: 229
Fax: 9058460363

NPRI Report

Report ID: 134111
Report Year: 2009
Company ID: 131139
SWR Report ID: 20090000007190
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 108
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 2010-05-14 00:00:00.0000000

Company

Company Name: INDUSTRIAL THERMO POLYMERS
DUNS No: 340399982
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
Phone: 9058463666

First Name:	Steve	**Extension:**	229
Last Name:	Hartman	**Fax:**	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	President		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058463666
First Name:	Linda	**Extension:**	273
Last Name:	Bailey	**Fax:**	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058463666
First Name:	Steve	**Extension:**	229
Last Name:	Hartman	**Fax:**	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	President		
Language:	1		
Email:	itps@thundrafoam.com		

NPRI Report Contact

Contact Type:		**Phone:**	9053631356
First Name:	Shawn	**Extension:**	
Last Name:	McDonald	**Fax:**	9053630681
Company Name:			
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	0		
Email:	smcdonald@pinchin.com		

NPRI Report

Report ID:	138416	**No of Employees:**	100
Report Year:	2008	**Is Compressor:**	
Company ID:	131139	**Is NPRI Part 4:**	
SWR Report ID:	20080000007190	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2009-05-11 00:00:00.0000000

Company

Company Name:	INDUSTRIAL THERMO POLYMERS
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	President		
Language:	1		
Email:	itps@thundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	President		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Linda	***Extension:***	273
Last Name:	Bailey	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9053631361
First Name:	Roslyn	***Extension:***	
Last Name:	Miller	***Fax:***	9053630681
Company Name:			
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	0		
Email:	rmiller@pinchin.com		

NPRI Report

Report ID:	141373	***No of Employees:***	100
Report Year:	2007	***Is Compressor:***	
Company ID:	131139	***Is NPRI Part 4:***	
SWR Report ID:	20070000007190	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2008-05-26 00:00:00.0000000

Company

Company Name:	INDUSTRIAL THERMO POLYMERS
DUNS No:	340399982

Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	President		
Language:	1		
Email:	itps@thundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9053631361
First Name:	Roslyn	***Extension:***	
Last Name:	Miller	***Fax:***	9053630681
Company Name:			
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	0		
Email:	rmiller@pinchin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Linda	***Extension:***	273
Last Name:	Bailey	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Research & Development		
Language:	1		
Email:	linda@tundrafoam.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	President		
Language:	0		
Email:			

NPRI Report

Report ID:	154666	***No of Employees:***	100
Report Year:	2006	***Is Compressor:***	
Company ID:	131139	***Is NPRI Part 4:***	
SWR Report ID:	20060000007190	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2007-05-28 00:00:00.0000000

Company

Company Name: INDUSTRIAL THERMO POLYMERS
DUNS No: 340399982
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Linda
Last Name: Bailey
Company Name:
Description En:
Description Fr:
Position: Manager, Research & Development
Language: 0
Email: linda@tundrafoam.com
Phone: 9058464209
Extension:
Fax: 9058460363

NPRI Report Contact

Contact Type: NPRI
First Name: Steve
Last Name: Hartman
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: President
Language: 1
Email: itps@thundrafoam.com
Phone: 9058463666
Extension: 229
Fax: 9058460363

NPRI Report Contact

Contact Type:
First Name: Roslyn
Last Name: Miller
Company Name:
Description En:
Description Fr:
Position: Project Technologist
Language: 0
Email: rmiller@pinchin.com
Phone: 9053631361
Extension:
Fax: 9053630681

NPRI Report Contact

Contact Type:
First Name: Steve
Last Name: Hartman
Company Name:
Description En:
Description Fr:
Position: President
Language: 0
Email:
Phone: 9058463666
Extension: 229
Fax: 9058460363

NPRI Report

Report ID: 254530
Report Year: 2005
Company ID: 131139
SWR Report ID: 20050000007190
No of Employees: 100
Is Compressor:
Is NPRI Part 4:
Is Battery:

Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2006-05-04 00:00:00.0000000

Company

Company Name:	INDUSTRIAL THERMO POLYMERS
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	President		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9057126405
First Name:	Roslyn	***Extension:***	0
Last Name:	Miller	***Fax:***	9055079151
Company Name:			
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	0		
Email:	rmiller@pinchin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9057126405
First Name:	Roslyn	***Extension:***	0
Last Name:	Miller	***Fax:***	9055079151
Company Name:			
Description En:			
Description Fr:			
Position:	Project Technologist		
Language:	0		
Email:	rmiller@pinchin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058463666
First Name:	Steve	***Extension:***	229
Last Name:	Hartman	***Fax:***	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	President		
Language:	1		
Email:	itps@thundrafoam.com		

NPRI Report

Report ID:	264374	**No of Employees:**	100
Report Year:	2004	**Is Compressor:**	
Company ID:	131139	**Is NPRI Part 4:**	
SWR Report ID:	20040000007190	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2006-01-27 00:00:00.0000000

Company

Company Name:	INDUSTRIAL THERMO POLYMERS
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	NPRI report update comment
Description Fr:	Commentaire sur la mise à jour du rapport de l'INRP
Comment:	Need to report to Part 5 for speciated VOC.
Note:	

NPRI Report Comment

Description En:	Report Submission and Electronic Certification Comment
Description Fr:	Soumission de déclaration et attestation électronique
Comment:	Updated 2004 Report
Note:	

NPRI Report Contact

Contact Type:		**Phone:**	9058463666
First Name:	Steve	**Extension:**	229
Last Name:	Hartman	**Fax:**	9058460363
Company Name:			
Description En:			
Description Fr:			
Position:	President		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9057126485
First Name:	Jennifer	**Extension:**	0
Last Name:	Ahluwalia	**Fax:**	9055079151
Company Name:			
Description En:			
Description Fr:			
Position:	Project Engineer		
Language:	0		
Email:	jahluwalia@pinchin.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058463666
First Name:	Steve	**Extension:**	229
Last Name:	Hartman	**Fax:**	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		

Position: President
Language: 1
Email: itps@thundrafoam.com

NPRI Report Contact

Contact Type:
First Name: Jennifer
Last Name: Ahluwalia
Company Name:
Description En:
Description Fr:
Position: Project Engineer
Language: 0
Email: jahluwalia@pinchin.com
Phone: 9057126485
Extension: 0
Fax: 9055079151

NPRI Report

Report ID: 169165
Report Year: 2003
Company ID: 131139
SWR Report ID: 20030000007190
Repor Type ID: 1
New Reporter: TRUE
No of Employees: 100
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 2006-01-27 00:00:00.0000000

Company

Company Name: INDUSTRIAL THERMO POLYMERS
DUNS No: 340399982
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Comment

Description En: Report Submission and Electronic Certification Comment
Description Fr: Soumission de déclaration et attestation électronique
Comment: Updated 2003 Report
Note:

NPRI Report Comment

Description En: NPRI report update comment
Description Fr: Commentaire sur la mise à jour du rapport de l'INRP
Comment: Need to report to Part 5 for speciated VOCs.
Note:

NPRI Report Contact

Contact Type:
First Name: Steve
Last Name: Hartman
Company Name:
Description En:
Description Fr:
Position: President
Language: 0
Email:
Phone: 9058463666
Extension: 229
Fax: 9058460363

NPRI Report Contact

Contact Type:		**Phone:**	9057126452
First Name:	Brian	**Extension:**	0
Last Name:	Kwong	**Fax:**	9055079151
Company Name:			
Description En:			
Description Fr:			
Position:	Project Engineer, E.I.T.		
Language:	0		
Email:	bkwong@pinchin.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058463666
First Name:	Steve	**Extension:**	229
Last Name:	Hartman	**Fax:**	9058460363
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	President		
Language:	1		
Email:	itps@thundrafoam.com		

NPRI Report Contact

Contact Type:		**Phone:**	9057126452
First Name:	Brian	**Extension:**	0
Last Name:	Kwong	**Fax:**	9055079151
Company Name:			
Description En:			
Description Fr:			
Position:	Project Engineer, E.I.T.		
Language:	0		
Email:	bkwong@pinchin.com		

NPRI ID Facility ID

NPRI ID:	7190
Facility ID:	376909

Facility

Facility ID:	376909	**IDM ID:**	0
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	326150	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:			
Website:			

Address

Address1:	153 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4
Prov:	

Primary NAICS Details

NAICS Code:	326150	**Start Date:**	2012

Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Plastics and Rubber
Key Indus Sector Fr: Plastiques et caoutchouc
NAICS Title En: Urethane and other foam product (except polystyrene) manufacturing
NAICS Title Fr: Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code: 326150 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Plastics and Rubber
Key Indus Sector Fr: Plastiques et caoutchouc
NAICS Title En: Urethane and Other Foam Product (except Polystyrene) Manufacturing
NAICS Title Fr: Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques, sauf de polystyrène

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code: 326150 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Plastics and Rubber
Key Indus Sector Fr: Plastiques et caoutchouc
NAICS Title En: Urethane and Other Foam Product (except Polystyrene) Manufacturing
NAICS Title Fr: Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code: 326150 ***Start Date:*** 2007
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Plastics and Rubber
Key Indus Sector Fr: Plastiques et caoutchouc
NAICS Title En: Urethane and Other Foam Product (except Polystyrene) Manufacturing
NAICS Title Fr: Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique autre que le polystyrène en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NAICS Code:	326150	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Plastics and Rubber		
Key Indus Sector Fr:	Plastiques et caoutchouc		
NAICS Title En:	Urethane and other foam product (except polystyrene) manufacturing		
NAICS Title Fr:	Fabrication de produits en mousse d'uréthane et en d'autres mousses plastiques (sauf de polystyrène)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in converting plastics resins, other than polystyrene, into foam products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la transformation de résines de matière plastique, autre que le polystyrène, en produits à base de mousse.

NPRI Report

Report ID:	194386	***No of Employees:***	122
Report Year:	2002	***Is Compressor:***	
Company ID:	137867	***Is NPRI Part 4:***	
SWR Report ID:	20020000007190	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2003-06-02 00:00:00.0000000

Company

Company Name:	INDUSTRIAL THERMO POLYMERS
DUNS No:	340399982
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9057126486
First Name:	Cindy	***Extension:***	0
Last Name:	MacCormack	***Fax:***	9055079151
Company Name:			

Description En:
Description Fr:
Position: Project Engineer, E.I.T.
Language: 0
Email: cmaccormack@pinchin.com

NPRI Report Contact

Contact Type:
First Name: Steve
Last Name: Hartman
Company Name:
Description En:
Description Fr:
Position: President
Language: 0
Email:
Phone: 9058463666
Extension: 229
Fax: 9058460363

NPRI Report Contact

Contact Type:
First Name: Cindy
Last Name: MacCormack
Company Name:
Description En:
Description Fr:
Position: Project Engineer, E.I.T.
Language: 0
Email: cmaccormack@pinchin.com
Phone: 9057126486
Extension: 0
Fax: 9055079151

NPRI Report Contact

Contact Type: NPRI
First Name: Steve
Last Name: Hartman
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: President
Language: 0
Email:
Phone: 9058463666
Extension: 229
Fax: 9058460363

Alternative Location Info

Facility ID: 279943
Facility Name: ARMACELL CANADA INC.
Address1:
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 279943
Facility Name:
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107

Longitude: -79.8075

Alternative Location Info

Facility ID: 245078
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 436620
Facility Name:
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 376909
Facility Name: INDUSTRIAL THERMO POLYMERS
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 436620
Facility Name: ARMACELL CANADA INC.
Address1:
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 279943
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 376909
Facility Name:

Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 402991
Facility Name: INDUSTRIAL THERMO POLYMERS
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 376909
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 245078
Facility Name: ARMACELL CANADA INC.
Address1:
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 279943
Facility Name: INDUSTRIAL THERMO POLYMERS
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 376909
Facility Name: ARMACELL CANADA INC.
Address1:
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 245078
Facility Name:
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 448993
Facility Name: ARMACELL CANADA INC.
Address1:
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 436620
Facility Name: INDUSTRIAL THERMO POLYMERS
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 402991
Facility Name: ARMACELL CANADA INC.
Address1:
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 448993
Facility Name:
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 448993
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON

Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 448993
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 436620
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 376909
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 402991
Facility Name:
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 402991
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 448993
Facility Name: INDUSTRIAL THERMO POLYMERS
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 245078
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 402991
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 436620
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 279943
Facility Name: ARMACELL CANADA INC.
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7107
Longitude: -79.8075

Alternative Location Info

Facility ID: 245078
Facility Name: INDUSTRIAL THERMO POLYMERS
Address1: 153 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Latitude: 43.7107
Longitude: -79.8075

---

68 | **34 of 34** | **S/125.6** | **238.0 / -3.93** | **153 Van Kirk Drive**
Brampton ON L7A 1A4 | **EHS**

Order No: 22032800121
Status: C
Report Type: Standard Report
Report Date: 31-MAR-22
Date Received: 28-MAR-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8074362
Y: 43.71085

---

69 | **1 of 4** | **SSE/5.2** | **235.9 / -6.08** | **Armbro Inc.**

Brampton ON | **ECA**

Approval No: 9994-8ZRS72
Approval Date: 2012-11-06
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Armbro Inc.
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9166-8Z4JFV-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.8057
Latitude: 43.7108
Geometry X:
Geometry Y:

---

69 | **2 of 4** | **SSE/5.2** | **235.9 / -6.08** | **The Corporation of the City of Brampton**

Brampton ON L6Y 4R2 | **ECA**

Approval No: 2959-6UHH76
Approval Date: 2006-10-14
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Corporation of the City of Brampton
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0624-6UFLFR-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.8057
Latitude: 43.7108
Geometry X:
Geometry Y:

---

69 | **3 of 4** | **SSE/5.2** | **235.9 / -6.08** | **Terraco Inc.**

Brampton ON M5M 2L4 | **ECA**

Approval No: 6276-4L8PNU
Approval Date: 2000-06-15
Status: Approved
Record Type: ECA
Link Source: IDS

MOE District: Halton-Peel
City:
Longitude: -79.8057
Latitude: 43.7108
Geometry X:

SWP Area Name: Credit Valley **Geometry Y:**
Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Business Name: Terraco Inc.
Address:
Full Address:
Full PDF Link:
PDF Site Location:

---

69 **4 of 4** **SSE/5.2** **235.9 / -6.08** **Terraco Inc.** **ECA**

Brampton ON M5M 2L4

Approval No: 5105-4L8P7L **MOE District:** Halton-Peel
Approval Date: 2000-06-15 **City:**
Status: Approved **Longitude:** -79.8057
Record Type: ECA **Latitude:** 43.7108
Link Source: IDS **Geometry X:**
SWP Area Name: Credit Valley **Geometry Y:**
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Terraco Inc.
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5883-4L5MPW-14.pdf
PDF Site Location:

---

70 **1 of 9** **SE/243.6** **234.5 / -7.46** **FAWCETT METAL FABRICATING (DIV** **SCT**
27 FISHERMAN DR UNIT 9-10
BRAMPTON ON L7A 1E2

Established: 1992
Plant Size (ft²): 7000
Employment: 5

--Details--
Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Motor Home, Travel Trailer and Camper Manufacturing
SIC/NAICS Code: 336215

---

70 **2 of 9** **SE/243.6** **234.5 / -7.46** **ACCU-CUT MACHINING SERVICES** **SCT**
27 FISHERMAN DR
BRAMPTON ON L7A 1E2

Established: 1990
Plant Size (ft²): 0
Employment: 2

--Details--
Description: MACHINE TOOLS, METAL FORMING TYPES
SIC/NAICS Code: 3542

Description: GENERAL INDUSTRIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3569

Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

---

70 **3 of 9** **SE/243.6** **234.5 / -7.46** **FAWCETT METAL FABRICATING** **SCT**
27 FISHERMAN DR
BRAMPTON ON L7A 1E2

Established: 1992
Plant Size (ft²): 7000
Employment: 5

--Details--
Description: FABRICATED METAL PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3499

Description: TRANSPORTATION EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3799

---

70 **4 of 9** **SE/243.6** **234.5 / -7.46** **TSL Aerospace Technologies** **SCT**
27 Fisherman Dr Unit 12
Brampton ON L7A 1E2

Established: 1986
Plant Size (ft²): 20000
Employment: 10

--Details--
Description: Textile Bag and Canvas Mills
SIC/NAICS Code: 314910

Description: Aerospace Product and Parts Manufacturing
SIC/NAICS Code: 336410

Description: Ship Building and Repairing
SIC/NAICS Code: 336611

Description: All Other Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417990

---

70 **5 of 9** **SE/243.6** **234.5 / -7.46** **TSL Aerospace Technologies Ltd.** **SCT**
27 Fisherman Dr Unit 12
Brampton ON L7A 1E2

Established: 1986
Plant Size (ft²): 20000
Employment: 10

--Details--
Description: All Other Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417990

---

70 **6 of 9** **SE/243.6** **234.5 / -7.46** **Louri Products Ltd.** **SCT**
27 Fisherman Dr Unit 9-10
Brampton ON L7A 1E2

Established: 1997
Plant Size (ft²): 3900
Employment: 11

--Details--
Description: Fruit and Vegetable Canning, Pickling and Drying
SIC/NAICS Code: 311420

---

70 ***7 of 9*** ***SE/243.6*** ***234.5 / -7.46*** ***Fantasy Aluminium Installation Ltd.*** ***SCT***
27 Fisherman Dr Unit 11
Brampton ON L7A 1E2

Established: 1984
Plant Size (ft²):
Employment: 2

--Details--
Description: Glass and Glazing Work
SIC/NAICS Code: 232320

Description: Metallic and Other Siding Work
SIC/NAICS Code: 232340

Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

---

70 ***8 of 9*** ***SE/243.6*** ***234.5 / -7.46*** ***Fantasy Aluminium Ltd.*** ***SCT***
27 Fisherman Dr Unit 11
Brampton ON L7A 1E2

Established: 1984
Plant Size (ft²):
Employment: 2

--Details--
Description: Glass and Glazing Contractors
SIC/NAICS Code: 238150

Description: Finish Carpentry Contractors
SIC/NAICS Code: 238350

Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

---

70 ***9 of 9*** ***SE/243.6*** ***234.5 / -7.46*** ***27 FISHERMAN DRIVE*** ***EHS***
Brampton ON L7A 1E2

Order No:	24082702371	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	AB
Report Date:	28-AUG-24	***Search Radius (km):***	.25
Date Received:	27-AUG-24	***X:***	-79.8021393

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Previous Site Name: ***Y:*** 43.7112531
Lot/Building Size:
Additional Info Ordered:

---

71 ***1 of 13*** ***SE/242.8*** ***234.7 / -7.25*** ***Sota Glazing Inc*** ***SCT***
443 Railside Dr
Brampton ON L7A 1E1

Established: 01-JUN-89
Plant Size (ft²): 100000
Employment:

--Details--
Description: Glass and Glazing Contractors
SIC/NAICS Code: 238150

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

---

71 ***2 of 13*** ***SE/242.8*** ***234.7 / -7.25*** ***SOTA Glazing Inc.*** ***SCT***
443 Railside Dr
Brampton ON L7A 1E1

Established: 1989
Plant Size (ft²): 70000
Employment: 80

--Details--
Description: Glass and Glazing Work
SIC/NAICS Code: 232320

Description: Other Building Exterior Finishing Work
SIC/NAICS Code: 232390

Description: Glass Product Manufacturing from Purchased Glass
SIC/NAICS Code: 327215

Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

---

71 ***3 of 13*** ***SE/242.8*** ***234.7 / -7.25*** ***MEDIRO WROUGHT IRON LTD.*** ***GEN***
443 RAILSIDE DRIVE
BRAMPTON ON L7A 1E1

Generator Info

Generator No: ON0911301
Approval Years: 89,90
Status:
PO Box No:
Country:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3039

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Phone No Admin:
SIC Description: OTHER ARCH. METAL

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

71 | ***4 of 13*** | ***SE/242.8*** | ***234.7 / -7.25*** | ***MEDIRO WROUGHT IRON LTD. 26-392***
443 RAILSIDE DRIVE
BRAMPTON ON L7A 1E1 | ***GEN***

Generator Info

Generator No: ON0911301
Approval Years: 92,93,94,95,96,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: OTHER ARCH. METAL

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3039

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

71 | ***5 of 13*** | ***SE/242.8*** | ***234.7 / -7.25*** | ***SOTAWALL INC.***
443 RAILSIDE DRIVE
BRAMPTON ON L7A 1E1 | ***GEN***

Generator Info

Generator No: ON8049393
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: ALL OTHER PROFESSIONAL, SCIENTIFIC AND TECHNICAL SERVICES

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 541990

Waste Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

---

71 | ***6 of 13*** | ***SE/242.8*** | ***234.7 / -7.25*** | ***SOTAWALL INC.***
443 RAILSIDE DRIVE
BRAMPTON ON L7A 1E1 | ***GEN***

Generator Info

Generator No:	ON8049393	**Choice of Contact:**	
Approval Years:	As of Dec 2017	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	150 L
Waste Class Name:	Inert organic wastes

2017 Generator Info

Gen No:	ON8049393	**Choice of Contact:**	CO_OFFICIAL
ID:	31472	**Phone No Official:**	905-846-3177 Ext.2249
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	METROPOLITAN TORONTO
NAICS Code1:	541990	**County Out:**	
NAICS Code2:		**District:**	301
NAICS Code3:			
Gen Name:	SOTAWALL INC.		
Gen Div:			
Gen Op Name:	SOTAWALL INC.		
Gen Op Div:			
Site Adrs1:	443 RAILSIDE DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1E1		
Site Country:	Canada		
Co Official:	FRANK DIMARIA		
Co Admin:			

2017 Generator Manifest

ID:	58868	**Sum Received Qty:**	60.0
Generator No:	ON8049393	**Waste Class Name:**	INERT INORGANIC WASTES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	201
Waste Code:	150		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
71	7 of 13	SE/242.8	234.7 / -7.25	**SOTAWALL LTD.** **443 RAILSIDE DRIVE** **BRAMPTON ON L7A 1E1**	GEN

Generator Info

Generator No:	ON6803501	**Choice of Contact:**	
Approval Years:	As of Dec 2018	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 211 I
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

71 | ***8 of 13*** | ***SE/242.8*** | ***234.7 / -7.25*** | ***SOTAWALL LIMITED***
443 Railside DR
Brampton ON L7A 1E1 | ***EASR***

Approval No: R-010-4110400743
Status: REGISTERED
Date: 2018-04-03
Record Type: EASR
Link Source: MOFA
Project Type: Air Emissions
Full Address:
Approval Type: EASR-Air Emissions
SWP Area Name: Toronto
PDF NAICS Code: 332329
PDF URL:
PDF Site Location:

MOE District: Halton-Peel
Municipality: Brampton
Latitude: 43.71166667
Longitude: -79.80083333
Geometry X:
Geometry Y:

---

71 | ***9 of 13*** | ***SE/242.8*** | ***234.7 / -7.25*** | ***443 Railside Drive***
Brampton ON | ***EHS***

Order No: 20161019115
Status: C
Report Type: Custom Report
Report Date: 21-OCT-16
Date Received: 19-OCT-16
Previous Site Name:
Lot/Building Size:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.801255
Y: 43.711267

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Additional Info Ordered:

---

71 ***10 of 13*** ***SE/242.8*** ***234.7 / -7.25*** ***443 Railside Drive Brampton ON*** ***EHS***

Order No:	20160928008	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	03-OCT-16	***Search Radius (km):***	.25
Date Received:	28-SEP-16	***X:***	-79.80097
Previous Site Name:		***Y:***	43.711839
Lot/Building Size:			
Additional Info Ordered:			

---

71 ***11 of 13*** ***SE/242.8*** ***234.7 / -7.25*** ***SOTAWALL LTD.***
443 RAILSIDE DRIVE
BRAMPTON ON L7A 1E1 ***GEN***

Generator Info

Generator No:	ON6803501	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 211 I
Waste Class Name: Aromatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
71	12 of 13	SE/242.8	234.7 / -7.25	SOTAWALL LTD. 443 RAILSIDE DRIVE BRAMPTON ON L7A 1E1	GEN

Generator Info

Generator No:	ON6803501	**Choice of Contact:**	
Approval Years:	As of Nov 2021	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 211 I
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
71	13 of 13	SE/242.8	234.7 / -7.25	SOTAWALL LTD. 443 RAILSIDE DRIVE	GEN

BRAMPTON ON L7A 1E1

Generator Info

Generator No:	ON6803501	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	112 C
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class:	211 I
Waste Class Name:	AROMATIC SOLVENTS

Waste Detail(s)

Waste Class:	146 T
Waste Class Name:	OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class:	122 C
Waste Class Name:	ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class:	232 I
Waste Class Name:	POLYMERIC RESINS

Waste Detail(s)

Waste Class:	145 I
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	WASTE OILS & LUBRICANTS

2017 Generator Info

Gen No:	ON6803501	***Choice of Contact:***	CO_OFFICIAL
ID:	26759	***Phone No Official:***	9058463177 Ext.2255
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	333120	***County Out:***	
NAICS Code2:		***District:***	305

NAICS Code3:
Gen Name: SOTAWALL LTD.
Gen Div:
Gen Op Name: SOTAWALL LTD.
Gen Op Div:
Site Adrs1: 443 RAILSIDE DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1E1
Site Country: Canada
Co Official: DARCY BRADBURN
Co Admin:

2018 Generator Info

Gen No: ON6803501
ID: 27128
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 333120
NAICS Code2:
NAICS Code3:
Gen Name: SOTAWALL LTD.
Gen Div:
Gen Op Name: SOTAWALL LTD.
Gen Op Div:
Site Adrs1: 443 RAILSIDE DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1E1
Site Country: Canada
Co Official: DARCY BRADBURN
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9058463177 Ext.2255
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305

2018 Generator Manifest

ID: 52672
Generator No: ON6803501
Receiver Type: 035
Waste Char: I
Waste Code: 232
Sum Received Qty: 171.0
Waste Class Name: POLYMERIC RESINS
Count Manifests: 1
District: 305

2018 Generator Manifest

ID: 52671
Generator No: ON6803501
Receiver Type: 035
Waste Char: I
Waste Code: 211
Sum Received Qty: 76.0
Waste Class Name: AROMATIC SOLVENTS
Count Manifests: 2
District: 305

2019 Generator Info

Gen No: ON6803501
ID: 27365
Choice of Contact: CO_OFFICIAL
Phone No Official: 9058463177 Ext.2255

Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	333120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SOTAWALL LTD.		
Gen Div:			
Gen Op Name:	SOTAWALL LTD.		
Gen Op Div:			
Site Adrs1:	443 RAILSIDE DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1E1		
Site Country:	Canada		
Co Official:	DARCY BRADBURN		
Co Admin:			

2020 Generator Info

Gen No:	ON6803501	***Choice of Contact:***	CO_OFFICIAL
ID:	27086	***Phone No Official:***	9058463177 Ext.2255
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	333120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SOTAWALL LTD.		
Gen Div:			
Gen Op Name:	SOTAWALL LTD.		
Gen Op Div:			
Site Adrs1:	443 RAILSIDE DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1E1		
Site Country:	Canada		
Co Official:	DARCY BRADBURN		
Co Admin:			

2020 Generator Manifest

ID:	49099	***Sum Received Qty:***	410.0
Generator No:	ON6803501	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	I	***District:***	305
Waste Code:	145		

2021 Generator Info

Gen No:	ON6803501	***Choice of Contact:***	CO_OFFICIAL
ID:	27562	***Phone No Official:***	9058463177 Ext.2255
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	333120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Gen Name: SOTAWALL LTD.
Gen Div:
Gen Op Name: SOTAWALL LTD.
Gen Op Div:
Site Adrs1: 443 RAILSIDE DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1E1
Site Country: Canada
Co Official: DARCY BRADBURN
Co Admin:

72	1 of 1	WNW/115.8	250.8 / 8.87	37 BANINGTON CRESCENT BRAMPTON ON L7A 1G4	HINC

External File Num: FS INC 0805-02049
Fuel Occurrence Type:
Date of Occurrence:
Fuel Type Involved:
Status Desc: Completed - No Action Required
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved:
Service Interruptions:
Property Damage:
Fuel Life Cycle Stage:
Root Cause:
Reported Details: Non-mandated. FS Inspector has declined an investigation since the fire is electrical in nature.
Fuel Category: Unknown
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Peel
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

73	1 of 13	SSE/143.0	237.9 / -4.08	Dymin Steel Inc. 133 Vankirk Dr. Brampton ON L7A 1A4	GEN

Generator Info

Generator No: ON3053241
Approval Years: 07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Metal Service Centres

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 416210

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	2 of 13	SSE/143.0	237.9 / -4.08	Dymin Steel Inc. 133 Vankirk Dr. Brampton ON L7A 1A4	GEN

Generator Info

Generator No:	ON3053241	***Choice of Contact:***	
Approval Years:	2009	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	416210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Metal Service Centres		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	3 of 13	SSE/143.0	237.9 / -4.08	Dymin Steel Inc. 133 Vankirk Dr. Brampton ON L7A 1A4	GEN

Generator Info

Generator No:	ON3053241	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	416210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Metal Service Centres		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	4 of 13	SSE/143.0	237.9 / -4.08	Dymin Steel Inc. 133 Vankirk Dr. Brampton ON L7A 1A4	GEN

Generator Info

Generator No:	ON3053241	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	416210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Metal Service Centres		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

73 | ***5 of 13*** | ***SSE/143.0*** | ***237.9 / -4.08*** | ***Dymin Steel Inc.***
133 Vankirk Dr.
Brampton ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON3053241
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Metal Service Centres

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 416210

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

73 | ***6 of 13*** | ***SSE/143.0*** | ***237.9 / -4.08*** | ***Dymin Steel Inc.***
133 Vankirk Dr.
Brampton ON | ***GEN***

Generator Info

Generator No: ON3053241
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: METAL SERVICE CENTRES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 416210

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

73 | ***7 of 13*** | ***SSE/143.0*** | ***237.9 / -4.08*** | ***Dymin Steel Inc.***
133 Vankirk Dr.
Brampton ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON3053241
Approval Years: 2016
Status:
PO Box No:
Country: Canada

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 416210

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin: Stella Marin
Phone No Admin: 905-840-0808 Ext.
SIC Description: METAL SERVICE CENTRES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

73 | ***8 of 13*** | ***SSE/143.0*** | ***237.9 / -4.08*** | ***Dymin Steel Inc.*** ***133 Vankirk Dr.*** ***Brampton ON L7A 1A4*** | ***GEN***

Generator Info

Generator No: ON3053241
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Peter Edwards
Phone No Admin: 905-840-0808 Ext.
SIC Description: METAL SERVICE CENTRES
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 416210

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

73 | ***9 of 13*** | ***SSE/143.0*** | ***237.9 / -4.08*** | ***Dymin Steel Inc.*** ***133 Vankirk Dr.*** ***Brampton ON L7A 1A4*** | ***GEN***

Generator Info

Generator No: ON3053241
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Peter Edwards
Phone No Admin: 905-840-0808 Ext.
SIC Description: METAL SERVICE CENTRES
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 416210

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

73 | ***10 of 13*** | ***SSE/143.0*** | ***237.9 / -4.08*** | ***Dymin Steel*** ***133 Vankirk Dr.*** ***Brampton ON L7A 1A4*** | ***GEN***

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON3053241
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

---

73 | ***11 of 13*** | ***SSE/143.0*** | ***237.9 / -4.08*** | ***Dymin Steel***
133 Vankirk Dr.
Brampton ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON3053241
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

---

73 | ***12 of 13*** | ***SSE/143.0*** | ***237.9 / -4.08*** | ***Dymin Steel***
133 Vankirk Dr.
Brampton ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON3053241
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	13 of 13	SSE/143.0	237.9 / -4.08	Dymin Steel 133 Vankirk Dr. Brampton ON L7A 1A4	GEN

Generator Info

Generator No: ON3053241
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

2017 Generator Info

Gen No: ON3053241
ID: 12378
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 416210
NAICS Code2:
NAICS Code3:
Gen Name: Dymin Steel
Gen Div:
Gen Op Name: Dymin Steel
Gen Op Div:
Site Adrs1: 133 Vankirk Dr.
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada

Choice of Contact: CO_ADMIN
Phone No Official: 905-840-0808 Ext.
Phone No Admin: 905-840-0808 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

Co Official: Dave Stadnik
Co Admin: Stella Marin

2018 Generator Info

Gen No: ON3053241
ID: 12184
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 416210
NAICS Code2:
NAICS Code3:
Gen Name: Dymin Steel
Gen Div:
Gen Op Name: Dymin Steel
Gen Op Div:
Site Adrs1: 133 Vankirk Dr.
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Joseph Lamarche
Co Admin: Jay Joshi
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-840-0808 Ext.
Phone No Admin: 905-840-0808 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2019 Generator Info

Gen No: ON3053241
ID: 11906
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 416210
NAICS Code2:
NAICS Code3:
Gen Name: Dymin Steel
Gen Div:
Gen Op Name: Dymin Steel
Gen Op Div:
Site Adrs1: 133 Vankirk Dr.
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Joseph Lamarche
Co Admin: Jay Joshi
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-840-0808 Ext.
Phone No Admin: 905-840-0808 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2020 Generator Info

Gen No: ON3053241
ID: 11564
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 416210
NAICS Code2:
NAICS Code3:
Gen Name: Dymin Steel
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-840-0808 Ext.301
Phone No Admin: 905-840-0808 Ext.304
County Ont: PEEL (R. M.)
County Out:
District: 305

Gen Div:
Gen Op Name: Dymin Steel
Gen Op Div:
Site Adrs1: 133 Vankirk Dr.
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Joseph Lamarche
Co Admin: Manali Desai

2021 Generator Info

Gen No: ON3053241
ID: 11388
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 416210
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-840-0808 Ext.301
Phone No Admin: 905-840-0808 Ext.304
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: Dymin Steel
Gen Div:
Gen Op Name: Dymin Steel
Gen Op Div:
Site Adrs1: 133 Vankirk Dr.
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Joseph Lamarche
Co Admin: Manali Desai

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	1 of 3	SSE/175.9	238.5 / -3.49	2270334 Ontario Inc. 150 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON	EBR

EBR Registry No: 011-4254
Ministry Ref No: 9425-8JBRJ2
Notice Type: Instrument Decision
Notice Stage:
Notice Date: November 02, 2011
Proposal Date: July 25, 2011
Year: 2011
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: 2270334 Ontario Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 30 Van Kirk Drive, Brampton Ontario, Canada L7A 2Y4
Comment Period:
URL:
Summary:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Location Details:

150 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON

---

74 ***2 of 3*** ***SSE/175.9*** ***238.5 / -3.49*** ***2270334 Ontario Inc.***
150 Van Kirk Dr
Brampton ON ***CA***

Certificate #:	4172-8MSRQG
Application Year:	2011
Issue Date:	10/26/2011
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

---

74 ***3 of 3*** ***SSE/175.9*** ***238.5 / -3.49*** ***2270334 Ontario Inc.***
150 Van Kirk Dr
Brampton ON L7A 2Y4 ***ECA***

Approval No:	4172-8MSRQG	***MOE District:***	Halton-Peel
Approval Date:	2011-10-26	***City:***	
Status:	Approved	***Longitude:***	-79.81188
Record Type:	ECA	***Latitude:***	43.71881
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Toronto	***Geometry Y:***	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	2270334 Ontario Inc.		
Address:	150 Van Kirk Dr		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/9425-8JBRJ2-13.pdf		
PDF Site Location:			

---

75 ***1 of 23*** ***S/241.0*** ***239.6 / -2.29*** ***DAY & ROSS INC.***
170 VAN KIRK DRIVE
BRAMPTON ON L7A 1K9 ***GEN***

Generator Info

Generator No:	ON0900103	***Choice of Contact:***	
Approval Years:	98	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	4561
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	GEN. FREIGHT TRUCK.		

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

75 | **2 of 23** | **S/241.0** | **239.6 / -2.29** | **DAY AND ROSS INCORPORATED**
170 VAN KIRK DRIVE
BRAMPTON ON L7A 1K9 | **GEN**

Generator Info

Generator No: ON0900103
Approval Years: 99,00,01,02,03,04,05,06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: GEN. FREIGHT TRUCK.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4561

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

75	***3 of 23***	***S/241.0***	***239.6 / -2.29***	***170 Van Kirk Drive n/a ON L7A 1K9***	***EHS***

Order No: 20070105007w **Nearest Intersection:**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	C	**Municipality:**	
Report Type:	CAN - Online Mapless	**Client Prov/State:**	
Report Date:	1/5/2007	**Search Radius (km):**	0.25
Date Received:	1/5/2007	**X:**	
Previous Site Name:		**Y:**	
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	4 of 23	S/241.0	239.6 / -2.29	**Day & Ross Inc.** **170 VANKIRK DR.<UNOFFICIAL>** **Brampton ON L7A 1K9**	SPL

Ref No:	1807-629K6R	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	6/24/2004	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	Oil
MOE Reported Dt:	6/24/2004	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	170 VANKIRK DR.<UNOFFICIAL>		
Site Address:			
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Day & Ross Inc.		
Client Type:			
Source Type:			
Incident Cause:	Other Discharges		
Incident Preceding Spill:			
Incident Reason:	Equipment Failure		
Incident Summary:	Ross & Day,300 L diesel to rd,clned up		
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:	Soil Contamination		
Contaminant Qty:	300 L		
Contaminant Qty 1:			
Contaminant Unit:	L		
Contaminant Code:	13		
Contaminant Name:	DIESEL FUEL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Transport Truck		
SAC Action Class:	Spill to Land		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	5 of 23	S/241.0	239.6 / -2.29	Day & Ross Inc. 170 Van Kirk Drive Brampton ON L7A 1K9	SPL

Ref No:	6178-7TDGZV	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	6/26/2009	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:	Referral to others		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Day & Ross Parking Lot<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Day & Ross Inc.		
Client Type:			
Source Type:			
Incident Cause:	Discharge or Emission to Air		
Incident Preceding Spill:			
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	Day & Ross: Propane Leak from truck		
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Air Pollution; Human Health/Safety		
Contaminant Qty:	0 other - see incident description		
Contaminant Qty 1:	0		
Contaminant Unit:	other - see incident description		
Contaminant Code:			
Contaminant Name:	PROPANE		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Motor Vehicle		
SAC Action Class:	Air Spills - Gases and Vapours		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	6 of 23	S/241.0	239.6 / -2.29	Day & Ross Transport<UNOFFICIAL> 170 Van Kirk Drive Brampton ON L7A 1K9	SPL

Ref No:	0346-8LB3X7	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/1/2011	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	

MOE Reported Dt:	9/1/2011		**Impact to Health:**
Dt Document Closed:	9/8/2011		**Agency Involved:**
Site No:			
MOE Response:		No Field Response	
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:		Day & Ross Transport<UNOFFICIAL>	
Site Address:		170 Van Kirk Drive	
Site Region:			
Site Municipality:		Brampton	
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:		Day & Ross Transport<UNOFFICIAL>	
Client Type:			
Source Type:			
Incident Cause:		Other Discharges	
Incident Preceding Spill:			
Incident Reason:		Other - Reason not otherwise defined	
Incident Summary:		Day & Ross: <1L phosphoric acid to grd.	
Environment Impact:		Not Anticipated	
Health Env Consequence:			
Nature of Impact:		Other Impact(s)	
Contaminant Qty:		1 L	
Contaminant Qty 1:		1	
Contaminant Unit:		L	
Contaminant Code:		n/a	
Contaminant Name:		Phosphoric acid	
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:		Transport Truck	
SAC Action Class:		Land Spills	
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

75	***7 of 23***	***S/241.0***	***239.6 / -2.29***	***DAY & ROSS INC 170 VAN KIRK DR BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10249391		**Expired Date:**
Status:	EXPIRED		**Max Hazard Rank:**
Instance ID:	14749		**Facility Location:**
Instance Type:	FS Facility		**Facility Type:**
Instance Creation Dt:			**Fuel Type 2:**
Instance Install Dt:			**Fuel Type 3:**
Item Description:			**Panam Related:**
Manufacturer:			**Panam Venue Nm:**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Refill Cntr - Cylr Fill
Original Source: EXP
Record Date: Up to Mar 2012

75	*8 of 23*	*S/241.0*	*239.6 / -2.29*	***DAY & ROSS INC*** ***170 VAN KIRK DR*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11573997 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 91112 ***Facility Location:***
Instance Type: FS Propane Tank ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

75	*9 of 23*	*S/241.0*	*239.6 / -2.29*	***DAY AND ROSS INCORPORATED*** ***170 VAN KIRK DRIVE*** ***BRAMPTON ON L7A 1K9***	***GEN***

Generator Info

Generator No:	ON0900103	***Choice of Contact:***	
Approval Years:	2009	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	484122
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	General Freight Trucking Long Distance Less Than Truck-Load		

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

75	***10 of 23***	***S/241.0***	***239.6 / -2.29***	***DAY AND ROSS INCORPORATED*** ***170 VAN KIRK DRIVE*** ***BRAMPTON ON L7A 1K9***	***GEN***

Generator Info

Generator No: ON0900103
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: General Freight Trucking Long Distance Less Than Truck-Load

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 484122

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

75 | ***11 of 23*** | ***S/241.0*** | ***239.6 / -2.29*** | ***DAY AND ROSS INCORPORATED***
170 VAN KIRK DRIVE
BRAMPTON ON L7A 1K9 | ***GEN***

Generator Info

Generator No: ON0900103
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: General Freight Trucking Long Distance Less Than Truck-Load

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 484122

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112

Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

75 | **12 of 23** | **S/241.0** | **239.6 / -2.29** | **DAY AND ROSS INCORPORATED**
170 VAN KIRK DRIVE
BRAMPTON ON L7A 1K9 | **GEN**

Generator Info

Generator No: ON0900103
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: General Freight Trucking Long Distance Less Than Truck-Load

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 484122

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

---

75 | ***13 of 23*** | ***S/241.0*** | ***239.6 / -2.29*** | ***DAY AND ROSS INCORPORATED***
170 VAN KIRK DRIVE
BRAMPTON ON | ***GEN***

Generator Info

Generator No: ON0900103
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 484122

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

75 | ***14 of 23*** | ***S/241.0*** | ***239.6 / -2.29*** | ***DAY AND ROSS INCORPORATED***
170 VAN KIRK DRIVE
BRAMPTON ON L7A 1K9 | ***GEN***

Generator Info

Generator No: ON0900103
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Ellen Saunders
Phone No Admin: 9058466311 Ext.
SIC Description: 484122

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 484122

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 122

Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 268
Waste Class Name: AMINES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

75	***15 of 23***	***S/241.0***	***239.6 / -2.29***	***DAY AND ROSS INCORPORATED*** ***170 VAN KIRK DRIVE*** ***BRAMPTON ON L7A 1K9***	***GEN***

Generator Info

Generator No: ON0900103
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Ellen Saunders
Phone No Admin: 9058466311 Ext.
SIC Description: 484122

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 484122

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Detail(s)

Waste Class: 268
Waste Class Name: AMINES

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

75	16 of 23	S/241.0	239.6 / -2.29	DAY AND ROSS INCORPORATED 170 VAN KIRK DRIVE	GEN

BRAMPTON ON L7A 1K9

Generator Info

Generator No:	ON0900103	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	484122
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	484122		

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148

Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
75	17 of 23	S/241.0	239.6 / -2.29	DAY AND ROSS INCORPORATED 170 VAN KIRK DRIVE BRAMPTON ON L7A 1K9	GEN

Generator Info

Generator No:	ON0900103	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 232 L
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 269 A
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Detail(s)

Waste Class: 268 C
Waste Class Name: Amines

Waste Detail(s)

Waste Class: 269 L
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 331 B
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 135 I
Waste Class Name: Wastes containing other reactive anions

Waste Detail(s)

Waste Class: 113 I
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 232 H
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 146 C
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 146 I
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 147 L
Waste Class Name: Chemical fertilizer wastes

Waste Detail(s)

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 212 C
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 212 B
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 221 C

Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

75 **18 of 23** **S/241.0** **239.6 / -2.29** **DAY AND ROSS INCORPORATED**
170 VAN KIRK DRIVE
BRAMPTON ON L7A 1K9
GEN

Generator Info

Generator No: ON0900103
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 268 C
Waste Class Name: Amines

Waste Detail(s)

Waste Class: 232 H
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 212 B
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 269 A
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 232 L
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 221 C
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 269 L
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 147 L
Waste Class Name: Chemical fertilizer wastes

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 331 B
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 146 I
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 113 I
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 135 I
Waste Class Name: Wastes containing other reactive anions

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 212 C
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 146 C
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

---

75 | **19 of 23** | **S/241.0** | **239.6 / -2.29** | **Day and Ross Inc.**
170 Van Kirk Dr
Brampton ON | **SPL**

Ref No: 4325-BBC34U
Year:
Incident Dt: 4/17/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/17/2019
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Day & Ross Freight<UNOFFICIAL>
Site Address: 170 Van Kirk Dr
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4840092.56
Easting: 595948.16
Entity Operating Name:
Client Name: Day and Ross Inc.
Client Type: Corporation
Source Type: Container/Drum/Tote
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Unknown / N/A
Incident Summary: Day&Ross: ~200L UN3265 to ground. Contained & Cleaning.
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 200 L
Contaminant Qty 1: 200
Contaminant Unit: L
Contaminant Code: 99
Contaminant Name: CORROSIVE LIQUIDS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1760
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

75 | **20 of 23** | **S/241.0** | **239.6 / -2.29** | **DAY AND ROSS INCORPORATED**
170 VAN KIRK DRIVE
BRAMPTON ON L7A 1K9 | **GEN**

Generator Info

Generator No: ON0900103
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 233 L
Waste Class Name: Other polymeric wastes

Waste Detail(s)

Waste Class: 265 L
Waste Class Name: Graphic arts wastes

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 146 I
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 113 I
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 122 L
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Detail(s)

Waste Class: 269 A
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 221 C
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 232 H
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 268 C
Waste Class Name: Amines

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 212 C
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 331 B
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 146 C
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 135 I
Waste Class Name: Wastes containing other reactive anions

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 145 C
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 113 C
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 263 C

Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 212 B
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 232 L
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 269 L
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Detail(s)

Waste Class: 147 L
Waste Class Name: Chemical fertilizer wastes

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

75	21 of 23	S/241.0	239.6 / -2.29	**Day & Ross Inc.** **170 VAN KIRK DRIVE** **BRAMPTON ON**	GEN

Generator Info

Generator No: ON0900103
Approval Years: As of Oct 2022
Status: Registered
Choice of Contact:
Contaminated Fac:
MHSW Facility:

PO Box No: ***SIC Code:***
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 264 L
Waste Class Name: PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class: 269 A
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 221 C
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 233 L
Waste Class Name: OTHER POLYMERIC WASTES

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 135 I
Waste Class Name: REACTIVE ANION WASTES

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 265 L
Waste Class Name: GRAPHIC ART WASTES

Waste Detail(s)

Waste Class: 268 C
Waste Class Name: AMINES

Waste Detail(s)

Waste Class: 145 H
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 146 L
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 232 H
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 212 C
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 148 L
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 146 C
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 269 L
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 232 L
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 145 C
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 113 C
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 148 A
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263 B
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 146 I
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 232 I
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 331 B
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 147 L
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 122 L
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213 T

Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 263 C
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 113 I
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 212 B
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Generator Info as of Dec 2024

Generator No: ON0900103
Generator Company Name: Day & Ross Inc.
Street: 170 VAN KIRK DRIVE
City: BRAMPTON
Province State: Ontario
Country: Canada
Postal Code: L7A1K9
Waste Class: 213 I,252 L,213 T,212 I,122 C,145 H,212 L,212 C,251 L,221 C,263 A,148 A,269 A,232 L,232 H,211 H,265 L,331 B,212 B,262 L,264 L,112 C,221 I,145 L,113 C,113 I,232 I,147 L,148 C,269 L,263 L,146 L,146 I,331 I,145 I,145 B, 263 I,135 I,213 L,146 C,268 C,122 L,312 P,263 C,263 B,148 L,145 C,148 I,233 L,331 L

Waste Class Decoded:

213 - PETROLEUM DISTILLATES; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES; 212 - ALIPHATIC SOLVENTS; 122 - ALKALINE WASTES - OTHER METALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 212 - ALIPHATIC SOLVENTS; 212 - ALIPHATIC SOLVENTS; 251 - OIL SKIMMINGS & SLUDGES; 221 - LIGHT FUELS; 263 - ORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 269 - NON-HALOGENATED PESTICIDES; 232 - POLYMERIC RESINS; 232 - POLYMERIC RESINS; 211 - AROMATIC SOLVENTS; 265 - GRAPHIC ART WASTES; 331 - WASTE COMPRESSED GASES; 212 - ALIPHATIC SOLVENTS; 262 - DETERGENTS/SOAPS; 264 - PHOTOPROCESSING WASTES; 112 - ACID WASTE - HEAVY METALS; 221 - LIGHT FUELS; 145 - PAINT/PIGMENT/COATING RESIDUES; 113 - ACID WASTE - OTHER METALS; 113 - ACID WASTE - OTHER METALS; 232 - POLYMERIC RESINS; 147 - CHEMICAL FERTILIZER WASTES; 148 - INORGANIC LABORATORY CHEMICALS; 269 - NON-HALOGENATED PESTICIDES; 263 - ORGANIC LABORATORY CHEMICALS; 146 - OTHER SPECIFIED INORGANICS; 146 - OTHER SPECIFIED INORGANICS; 331 - WASTE COMPRESSED GASES; 145 - PAINT/PIGMENT/COATING RESIDUES; 145 - PAINT/PIGMENT/COATING RESIDUES; 263 - ORGANIC LABORATORY CHEMICALS; 135 - REACTIVE ANION WASTES; 213 - PETROLEUM DISTILLATES; 146 - OTHER SPECIFIED INORGANICS; 268 - AMINES; 122 - ALKALINE WASTES - OTHER METALS; 312 - PATHOLOGICAL WASTES; 263 - ORGANIC LABORATORY CHEMICALS; 263 - ORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 148 - INORGANIC LABORATORY CHEMICALS; 233 - OTHER

POLYMERIC WASTES; 331 - WASTE COMPRESSED GASES

2017 Generator Info

Gen No:	ON0900103	***Choice of Contact:***	CO_OFFICIAL
ID:	5432	***Phone No Official:***	506-375-4401 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9058466311 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	484122	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	DAY AND ROSS INCORPORATED		
Gen Div:			
Gen Op Name:	DAY AND ROSS INCORPORATED		
Gen Op Div:			
Site Adrs1:	170 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1K9		
Site Country:	Canada		
Co Official:	BRENT STAIRS		
Co Admin:	Ellen Saunders		

2017 Generator Manifest

ID:	20448	***Sum Received Qty:***	650.0
Generator No:	ON0900103	***Waste Class Name:***	PETROLEUM DISTILLATES
Receiver Type:	035	***Count Manifests:***	13
Waste Char:	T	***District:***	305
Waste Code:	213		

2017 Generator Manifest

ID:	20449	***Sum Received Qty:***	6600.0
Generator No:	ON0900103	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	251		

2017 Generator Manifest

ID:	20450	***Sum Received Qty:***	2047.0
Generator No:	ON0900103	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	L	***District:***	305
Waste Code:	252		

2017 Generator Manifest

ID:	20447	***Sum Received Qty:***	2000.0
Generator No:	ON0900103	***Waste Class Name:***	POLYMERIC RESINS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	201
Waste Code:	232		

2017 Generator Manifest

ID:	20446	**Sum Received Qty:**	170.0
Generator No:	ON0900103	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	I	**District:**	201
Waste Code:	145		

2018 Generator Info

Gen No:	ON0900103	**Choice of Contact:**	CO_OFFICIAL
ID:	5301	**Phone No Official:**	506-375-4401 Ext.
Contaminated Fac:	N	**Phone No Admin:**	9058466311 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	484122	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	DAY AND ROSS INCORPORATED		
Gen Div:			
Gen Op Name:	DAY AND ROSS INCORPORATED		
Gen Op Div:			
Site Adrs1:	170 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1K9		
Site Country:	Canada		
Co Official:	BRENT STAIRS		
Co Admin:	Ellen Saunders		

2018 Generator Manifest

ID:	20148	**Sum Received Qty:**	13.0
Generator No:	ON0900103	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	B	**District:**	305
Waste Code:	145		

2018 Generator Manifest

ID:	20147	**Sum Received Qty:**	602.0
Generator No:	ON0900103	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	201
Waste Code:	251		

2018 Generator Manifest

ID:	20153	**Sum Received Qty:**	16.0
Generator No:	ON0900103	**Waste Class Name:**	DETERGENTS/SOAPS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	262		

2018 Generator Manifest

ID:	20154	**Sum Received Qty:**	31.0
Generator No:	ON0900103	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	A	**District:**	305

Waste Code: 263

2018 Generator Manifest

ID: 20149
Generator No: ON0900103
Receiver Type: 035
Waste Char: C
Waste Code: 148
Sum Received Qty: 84.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 1
District: 305

2018 Generator Manifest

ID: 20150
Generator No: ON0900103
Receiver Type: 035
Waste Char: I
Waste Code: 212
Sum Received Qty: 44.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 305

2018 Generator Manifest

ID: 20151
Generator No: ON0900103
Receiver Type: 035
Waste Char: T
Waste Code: 213
Sum Received Qty: 650.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 13
District: 305

2018 Generator Manifest

ID: 20152
Generator No: ON0900103
Receiver Type: 035
Waste Char: L
Waste Code: 232
Sum Received Qty: 248.0
Waste Class Name: POLYMERIC RESINS
Count Manifests: 1
District: 305

2019 Generator Info

Gen No: ON0900103
ID: 5165
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 484122
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 506-375-4401 Ext.
Phone No Admin: 9058466311 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

Gen Name: DAY AND ROSS INCORPORATED
Gen Div:
Gen Op Name: DAY AND ROSS INCORPORATED
Gen Op Div:
Site Adrs1: 170 VAN KIRK DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1K9
Site Country: Canada
Co Official: BRENT STAIRS
Co Admin: Ellen Saunders

2019 Generator Manifest

ID:	19862	**Sum Received Qty:**	550.0
Generator No:	ON0900103	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	11
Waste Char:	T	**District:**	305
Waste Code:	213		

2019 Generator Manifest

ID:	19864	**Sum Received Qty:**	1937.0
Generator No:	ON0900103	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	6
Waste Char:	L	**District:**	305
Waste Code:	263		

2019 Generator Manifest

ID:	19863	**Sum Received Qty:**	1204.0
Generator No:	ON0900103	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	252		

2019 Generator Manifest

ID:	19861	**Sum Received Qty:**	233.0
Generator No:	ON0900103	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	I	**District:**	305
Waste Code:	212		

2019 Generator Manifest

ID:	19859	**Sum Received Qty:**	318.0
Generator No:	ON0900103	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	I	**District:**	305
Waste Code:	145		

2019 Generator Manifest

ID:	19858	**Sum Received Qty:**	12000.0
Generator No:	ON0900103	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	C	**District:**	203
Waste Code:	148		

2019 Generator Manifest

ID:	19860	**Sum Received Qty:**	308.0
Generator No:	ON0900103	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	C	**District:**	305
Waste Code:	148		

2020 Generator Info

Gen No:	ON0900103	**Choice of Contact:**	CO_OFFICIAL
ID:	5001	**Phone No Official:**	506-375-4401 Ext.
Contaminated Fac:	N	**Phone No Admin:**	9058724013 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)

NAICS Code1:	484122	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	DAY AND ROSS INCORPORATED		
Gen Div:			
Gen Op Name:	DAY AND ROSS INCORPORATED		
Gen Op Div:			
Site Adrs1:	170 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1K9		
Site Country:	Canada		
Co Official:	BRENT STAIRS		
Co Admin:	Charmaine Munn		

2020 Generator Manifest

ID:	17687	**Sum Received Qty:**	26.0
Generator No:	ON0900103	**Waste Class Name:**	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	C	**District:**	305
Waste Code:	122		

2020 Generator Manifest

ID:	17692	**Sum Received Qty:**	60.0
Generator No:	ON0900103	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	I	**District:**	305
Waste Code:	212		

2020 Generator Manifest

ID:	17693	**Sum Received Qty:**	1115.0
Generator No:	ON0900103	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	212		

2020 Generator Manifest

ID:	17690	**Sum Received Qty:**	17.0
Generator No:	ON0900103	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	A	**District:**	305
Waste Code:	148		

2020 Generator Manifest

ID:	17694	**Sum Received Qty:**	500.0
Generator No:	ON0900103	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	9
Waste Char:	T	**District:**	305
Waste Code:	213		

2020 Generator Manifest

ID:	17698	**Sum Received Qty:**	14.0
Generator No:	ON0900103	**Waste Class Name:**	DETERGENTS/SOAPS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	262		

2020 Generator Manifest

ID:	17699	**Sum Received Qty:**	94.0
Generator No:	ON0900103	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	A	**District:**	305
Waste Code:	263		

2020 Generator Manifest

ID:	17688	**Sum Received Qty:**	10.0
Generator No:	ON0900103	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	B	**District:**	305
Waste Code:	145		

2020 Generator Manifest

ID:	17695	**Sum Received Qty:**	301.0
Generator No:	ON0900103	**Waste Class Name:**	POLYMERIC RESINS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	I	**District:**	305
Waste Code:	232		

2020 Generator Manifest

ID:	17691	**Sum Received Qty:**	592.0
Generator No:	ON0900103	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	9
Waste Char:	C	**District:**	305
Waste Code:	148		

2020 Generator Manifest

ID:	17702	**Sum Received Qty:**	33.0
Generator No:	ON0900103	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	035	**Count Manifests:**	4
Waste Char:	I	**District:**	305
Waste Code:	331		

2020 Generator Manifest

ID:	17700	**Sum Received Qty:**	630.0
Generator No:	ON0900103	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	L	**District:**	305
Waste Code:	263		

2020 Generator Manifest

ID:	17689	**Sum Received Qty:**	103.0
Generator No:	ON0900103	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	I	**District:**	305

Waste Code: 145

2020 Generator Manifest

ID: 17696
Generator No: ON0900103
Receiver Type: 035
Waste Char: L
Waste Code: 232
Sum Received Qty: 1558.0
Waste Class Name: POLYMERIC RESINS
Count Manifests: 2
District: 305

2020 Generator Manifest

ID: 17697
Generator No: ON0900103
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 1148.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 2
District: 305

2020 Generator Manifest

ID: 17701
Generator No: ON0900103
Receiver Type: 035
Waste Char: L
Waste Code: 269
Sum Received Qty: 29.0
Waste Class Name: NON-HALOGENATED PESTICIDES
Count Manifests: 1
District: 305

2021 Generator Info

Gen No: ON0900103
ID: 4898
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 484122
NAICS Code2:
NAICS Code3:
Gen Name: DAY AND ROSS INCORPORATED
Gen Div:
Gen Op Name: DAY AND ROSS INCORPORATED
Gen Op Div:
Site Adrs1: 170 VAN KIRK DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1K9
Site Country: Canada
Co Official: BRENT STAIRS
Co Admin: Charmaine Munn
Choice of Contact: CO_OFFICIAL
Phone No Official: 506-375-4401 Ext.
Phone No Admin: 9058724013 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2021 Generator Manifest

ID: 18030
Generator No: ON0900103
Receiver Type: 035
Waste Char: C
Waste Code: 145
Sum Received Qty: 13.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 305

2021 Generator Manifest

ID:	18032	**Sum Received Qty:**	431.0
Generator No:	ON0900103	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	305
Waste Code:	145		

2021 Generator Manifest

ID:	18039	**Sum Received Qty:**	650.0
Generator No:	ON0900103	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	13
Waste Char:	T	**District:**	305
Waste Code:	213		

2021 Generator Manifest

ID:	18046	**Sum Received Qty:**	39.0
Generator No:	ON0900103	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	A	**District:**	305
Waste Code:	263		

2021 Generator Manifest

ID:	18050	**Sum Received Qty:**	2219.0
Generator No:	ON0900103	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	6
Waste Char:	L	**District:**	305
Waste Code:	263		

2021 Generator Manifest

ID:	18038	**Sum Received Qty:**	137.0
Generator No:	ON0900103	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	I	**District:**	305
Waste Code:	213		

2021 Generator Manifest

ID:	18040	**Sum Received Qty:**	1376.0
Generator No:	ON0900103	**Waste Class Name:**	POLYMERIC RESINS
Receiver Type:	035	**Count Manifests:**	4
Waste Char:	I	**District:**	305
Waste Code:	232		

2021 Generator Manifest

ID:	18041	**Sum Received Qty:**	411.0
Generator No:	ON0900103	**Waste Class Name:**	POLYMERIC RESINS
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	L	**District:**	305
Waste Code:	232		

2021 Generator Manifest

ID:	18031	**Sum Received Qty:**	1517.0
Generator No:	ON0900103	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	10
Waste Char:	I	**District:**	305

Waste Code: 145

2021 Generator Manifest

ID: 18034
Generator No: ON0900103
Receiver Type: 035
Waste Char: C
Waste Code: 148
Sum Received Qty: 638.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 10
District: 305

2021 Generator Manifest

ID: 18036
Generator No: ON0900103
Receiver Type: 035
Waste Char: L
Waste Code: 148
Sum Received Qty: 1320.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 1
District: 305

2021 Generator Manifest

ID: 18043
Generator No: ON0900103
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 6800.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 305

2021 Generator Manifest

ID: 18051
Generator No: ON0900103
Receiver Type: 035
Waste Char: I
Waste Code: 331
Sum Received Qty: 53.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 4
District: 305

2021 Generator Manifest

ID: 18028
Generator No: ON0900103
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 4800.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 2
District: 202

2021 Generator Manifest

ID: 18042
Generator No: ON0900103
Receiver Type: 035
Waste Char: L
Waste Code: 233
Sum Received Qty: 203.0
Waste Class Name: OTHER POLYMERIC WASTES
Count Manifests: 1
District: 305

2021 Generator Manifest

ID: 18049
Generator No: ON0900103
Receiver Type: 035
Waste Char: I
Waste Code: 263
Sum Received Qty: 67.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 2
District: 305

2021 Generator Manifest

ID:	18047	**Sum Received Qty:**	266.0
Generator No:	ON0900103	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	B	**District:**	305
Waste Code:	263		

2021 Generator Manifest

ID:	18048	**Sum Received Qty:**	64.0
Generator No:	ON0900103	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	C	**District:**	305
Waste Code:	263		

2021 Generator Manifest

ID:	18052	**Sum Received Qty:**	15.0
Generator No:	ON0900103	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	331		

2021 Generator Manifest

ID:	18029	**Sum Received Qty:**	233.0
Generator No:	ON0900103	**Waste Class Name:**	ACID WASTE - HEAVY METALS
Receiver Type:	035	**Count Manifests:**	4
Waste Char:	C	**District:**	305
Waste Code:	112		

2021 Generator Manifest

ID:	18044	**Sum Received Qty:**	1150.0
Generator No:	ON0900103	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	L	**District:**	305
Waste Code:	252		

2021 Generator Manifest

ID:	18045	**Sum Received Qty:**	309.0
Generator No:	ON0900103	**Waste Class Name:**	DETERGENTS/SOAPS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	305
Waste Code:	262		

2021 Generator Manifest

ID:	18033	**Sum Received Qty:**	97.0
Generator No:	ON0900103	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	146		

2021 Generator Manifest

ID:	18035	**Sum Received Qty:**	59.0
Generator No:	ON0900103	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	2

Waste Char:	I	**District:**	305
Waste Code:	148		

2021 Generator Manifest

ID:	18037	**Sum Received Qty:**	185.0
Generator No:	ON0900103	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	212		

---

75 | ***22 of 23*** | ***S/241.0*** | ***239.6 / -2.29*** | ***170 Van Kirk Drive, Brampton, ON BRAMPTON ON*** | ***SPL***

Ref No:	1-2HO5UT	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	Feb 07,2023 10:30:21 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2023/02/7	**Impact to Health:**	
Dt Document Closed:	Jun 02,2023 02:50:24 PM	**Agency Involved:**	

Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 170 Van Kirk Drive, Brampton, ON
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type: Truck - Only Saddle Tanks
Incident Cause:
Incident Preceding Spill: Accident/Collision
Incident Reason:
Incident Summary: Day and Ross Trucking Yard: 10 L diesel to asphalt
Environment Impact:
Health Env Consequence: Low
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1: 10
Contaminant Unit: litre (L)
Contaminant Code:
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill: Normal operations
Property 2nd Watershed: 02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed: 02HB | Sixteen Mile Creek - Credit River
Sector Type: GENERAL FREIGHT TRUCKING, LOCAL
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001877734"],"wkts":["POINT (-79.8089264000 43.7076781000)"],"creation_date":"2023-02-07"}
Time Reported: 23:38:21

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
System Facility Address:					
75	23 of 23	S/241.0	239.6 / -2.29	**Sterling Specialty Chemicals** **170 Van Kirk Drive** **Brampton ON**	GEN

Generator Info as of Dec 2024

Generator No:	ON001071645
Generator Company Name:	Sterling Specialty Chemicals
Street:	170 Van Kirk Drive
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A 1K9
Waste Class:	213 L

Waste Class Decoded:

213 - PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
76	1 of 1	SSE/166.7	237.9 / -4.08	**Aztec Hydraulics Inc.** **Regan Road & Vankirk Drive,** **Brampton ON**	SPL

Ref No:	4313-ADYK4M	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/20/2016	**Discharger Report:**	
Dt MOE Arvl on Scn:	9/21/2016	**Material Group:**	
MOE Reported Dt:	9/20/2016	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:	NA		
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Accident site<UNOFFICIAL>		
Site Address:	Regan Road & Vankirk Drive,		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Aztec Hydraulics Inc.		
Client Type:			
Source Type:			
Incident Cause:			
Incident Preceding Spill:	Collision/Accident		
Incident Reason:	Operator/Human Error		
Incident Summary:	Aztec Hydraulics: MVA, 150 L diesel to road, cntd & clng		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	150 L		
Contaminant Qty 1:	150		

Contaminant Unit: L
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Highway Spills (usually highway accidents)
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

77 | **1 of 1** | **WNW/174.0** | **251.8 / 9.87** | **ALECTRA UTILITIES CORPORATION**
82 Banington Crescent, Brampton
ON | **SPL**

Ref No: 1-1TM6QQ
Year:
Incident Dt: 5/26/2022 7:10:35 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/26/2022 7:10:37 PM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 82 Banington Crescent, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: ALECTRA UTILITIES CORPORATION
Client Type: Private Business
Source Type:
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason:
Incident Summary: Alectra: Historical spill, 140-150L - Non PCB
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see notes
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill: Unknown
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Property Tertiary Watershed:
Sector Type: ELECTRIC POWER DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001823772"],"wkts":["POINT (-79.8259318000 43.7276463000)"],"creation_date":"2022-05-26"}
Time Reported:
System Facility Address:

---

78 | ***1 of 1*** | ***SE/248.4*** | ***235.6 / -6.30*** | ***GIVE AND GO PREPARED FOODS CORP.*** | ***SPL***

BRAMPTON ON

Ref No: 1-CRWUSZ
Year:
Incident Dt: Oct 31,2024 06:59:59 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: Nov 01,2024 02:22:42 PM
Dt Document Closed: Nov 18,2024 11:06:05 AM
Site No:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name: GIVE AND GO PREPARED FOODS CORP.
Site Address:
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: GIVE AND GO PREPARED FOODS CORP.
Client Type: Private Business
Source Type: Truck - Transport/Hauling
Incident Cause:
Incident Preceding Spill: Unknown / N/A
Incident Reason: Unknown
Incident Summary: Give N Go Prepared Foods: diesel spill to asphalt, cb, cntd & clng
Environment Impact:
Health Env Consequence: Not Anticipated
Nature of Impact:
Contaminant Qty: 2.5 litre (L)
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill: Other (specify)
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HB;02ED - Nottawasaga;Credit - 16 Mile
Sector Type:
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00002128630"],"wkts":["POINT (-79.8005403000 43.7101536000)"],"creation_date":"2024-11-01"}
Time Reported:
System Facility Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	1 of 6	SE/240.0	235.3 / -6.63	THE STEVENS COMPANY LTD 425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	GEN

Generator Info

Generator No:	ON7929968	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 L
Waste Class Name:	Pharmaceuticals

Waste Detail(s)

Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	2 of 6	SE/240.0	235.3 / -6.63	THE STEVENS COMPANY LTD 425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	GEN

Generator Info

Generator No:	ON7929968	***Choice of Contact:***	
Approval Years:	As of Jan 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 L
Waste Class Name:	Pharmaceuticals

Waste Detail(s)

Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	3 of 6	SE/240.0	235.3 / -6.63	THE STEVENS COMPANY LTD 425 RAILSIDE DRIVE BRAMPTON ON L7A 0N8	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON7929968	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders

Waste Detail(s)

Waste Class:	261 L
Waste Class Name:	Pharmaceuticals

79	***4 of 6***	***SE/240.0***	***235.3 / -6.63***	***Hamilton Health Sciences Juravinski Hospital*** ***425 Railside Drive*** ***Brampton ON L7A0N8***	***GEN***

Generator Info

Generator No:	ON8671958	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	262 L
Waste Class Name:	DETERGENTS/SOAPS

Waste Detail(s)

Waste Class:	212 I
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	262 C
Waste Class Name:	DETERGENTS/SOAPS

79	***5 of 6***	***SE/240.0***	***235.3 / -6.63***	***THE STEVENS COMPANY LTD*** ***425 RAILSIDE DRIVE*** ***BRAMPTON ON L7A 0N8***	***GEN***

Generator Info

Generator No:	ON7929968	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	331 I
Waste Class Name:	WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class:	261 L
Waste Class Name:	PHARMACEUTICALS

2018 Generator Info

Gen No:	ON7929968	**Choice of Contact:**	CO_OFFICIAL
ID:	31565	**Phone No Official:**	9057918600 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	339112	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	THE STEVENS COMPANY LTD		
Gen Div:			
Gen Op Name:	THE STEVENS COMPANY LTD		
Gen Op Div:			
Site Adrs1:	425 RAILSIDE DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 0N8		
Site Country:	Canada		
Co Official:	TOM RAK		
Co Admin:			

2020 Generator Info

Gen No:	ON7929968	**Choice of Contact:**	CO_OFFICIAL
ID:	31654	**Phone No Official:**	9057918600 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	339112	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	THE STEVENS COMPANY LTD		
Gen Div:			
Gen Op Name:	THE STEVENS COMPANY LTD		
Gen Op Div:			
Site Adrs1:	425 RAILSIDE DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		

Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 0N8
Site Country:	Canada
Co Official:	TOM RAK
Co Admin:	

2021 Generator Info

Gen No:	ON7929968	**Choice of Contact:**	CO_OFFICIAL
ID:	32354	**Phone No Official:**	9057918600 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	339112	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	THE STEVENS COMPANY LTD		
Gen Div:			
Gen Op Name:	THE STEVENS COMPANY LTD		
Gen Op Div:			
Site Adrs1:	425 RAILSIDE DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 0N8		
Site Country:	Canada		
Co Official:	TOM RAK		
Co Admin:			

2021 Generator Manifest

ID:	57007	**Sum Received Qty:**	400.0
Generator No:	ON7929968	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	L	**District:**	201
Waste Code:	263		

2021 Generator Manifest

ID:	57006	**Sum Received Qty:**	200.0
Generator No:	ON7929968	**Waste Class Name:**	PHARMACEUTICALS
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	L	**District:**	201
Waste Code:	261		

2021 Generator Manifest

ID:	57008	**Sum Received Qty:**	753.5
Generator No:	ON7929968	**Waste Class Name:**	PHARMACEUTICALS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	A	**District:**	305
Waste Code:	261		

79	***6 of 6***	***SE/240.0***	***235.3 / -6.63***	***Hamilton Health Sciences Corporation Stevens Warehouse, 425 Railside Drive Brampton ON***	***GEN***

Generator Info as of Dec 2024

Generator No:	ON8671958
Generator Company Name:	Hamilton Health Sciences Corporation
Street:	Stevens Warehouse, 425 Railside Drive
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A0N8
Waste Class:	212 I,262 C,262 L

Waste Class Decoded:

212 - ALIPHATIC SOLVENTS; 262 - DETERGENTS/SOAPS; 262 - DETERGENTS/SOAPS

---

80 | ***1 of 1*** | ***W/141.5*** | ***249.9 / 7.92*** | ***S/E CORNER OF MAYFIELD & MCLAUCHLIN lot 17 con 1 ON*** | ***WWIS***

Well ID:	7043898	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Not Used	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	05/28/2007
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z73229	***Contractor:***	7219
Tag:	A053253	***Form Version:***	3
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	017
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7043898.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/05/2007
Year Completed:	2007
Depth (m):	
Latitude:	43.7250689120609
Longitude:	-79.8279648728216
X:	-79.82796472287986
Y:	43.72506891042873
Path:	704\7043898.pdf

Bore Hole Information

Bore Hole ID:	11766332	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	594400.00
Code OB Desc:		***North83:***	4842005.00
Open Hole:		***Org CS:***	UTM83

Cluster Kind:
Date Completed: 05/05/2007
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 933319287
Layer: 2
Plug From: 1.7599999904632568
Plug To: 2.4000000953674316
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933319288
Layer: 3
Plug From: 2.4000000953674316
Plug To: 2.740000009536743
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933319286
Layer: 1
Plug From: 0.0
Plug To: 1.7599999904632568
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 967043898
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 11774022
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930899568
Layer: 1
Material: 3
Open Hole or Material: CONCRETE
Depth From:
Depth To:

Casing Diameter: 76.19999694824219
Casing Diameter UOM: cm
Casing Depth UOM: m

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 11778649
Pump Set At:
Static Level: 2.619999885559082
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 11852793
Diameter: 76.19999694824219
Depth From: 0.0
Depth To: 2.740000009536743
Hole Depth UOM: m
Hole Diameter UOM: cm

---

81 | ***1 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***THE SHERWIN-WILLIAMS COMPANY***
130 VAN KIRK DR
BRAMPTON ON L7A 1B1 | ***SCT***

Established: 1971
Plant Size (ft²): 25000
Employment: 25

--Details--
Description: PLASTIC MATERIALS, SYNTHETIC RESINS, AND NONVULCANIZABLE ELASTOMERS
SIC/NAICS Code: 2821

Description: PAINTS, VARNISHES, LACQUERS, ENAMELS, AND ALLIED PRODUCTS
SIC/NAICS Code: 2851

Description: Resin and Synthetic Rubber Manufacturing
SIC/NAICS Code: 325210

Description: Paint and Coating Manufacturing
SIC/NAICS Code: 325510

---

81 | ***2 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***SHERWIN-WILLIAMS CANADA, BRAMPTON FACILI***
130 VAN KIRK DRIVE
BRAMPTON CITY ON L7A 1B1 | ***CA***

Certificate #: 8-3211-99-
Application Year: 99

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Issue Date: 12/23/1999
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: PAINT SPRAY BOOTH, PROCESS VENT. SYSTEM
Contaminants:
Emission Control:

---

81 ***3 of 34*** ***SSE/212.1*** ***238.9 / -3.08*** ***The Sherwin-Williams Company - Eastern Division***
130 Van Kirk Dr
Brampton ON L7A 1B1 ***SCT***

Established: 1992
Plant Size (ft²): 25000
Employment: 25

---

81 ***4 of 34*** ***SSE/212.1*** ***238.9 / -3.08*** ***Sherwin-Williams Canada Inc.***
130 Van Kirk Drive CITY OF BRAMPTON ON ***EBR***

EBR Registry No: IA9E0833
Ministry Ref No: 8321199
Notice Type: Instrument Decision
Notice Stage:
Notice Date: September 13, 2001
Proposal Date: July 13, 1999
Year: 1999
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Sherwin-Williams Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 224 Catherine Street, Fort Erie Ontario, L2A 5M9
Comment Period:
URL:
Summary:

Site Location Details:

130 Van Kirk Drive CITY OF BRAMPTON

---

81 ***5 of 34*** ***SSE/212.1*** ***238.9 / -3.08*** ***Sherwin-Williams Canada Inc. - Eastern Division***
130 Van Kirk Dr
Brampton ON L7A 1B1 ***SCT***

Established: 1992
Plant Size (ft²): 25000
Employment: 25

--Details--
Description: Resin and Synthetic Rubber Manufacturing
SIC/NAICS Code: 325210

Description: Paint and Coating Manufacturing
SIC/NAICS Code: 325510

---

81 | **6 of 34** | **SSE/212.1** | **238.9 / -3.08** | **SHERWIN WILLIAMS AUTO FINISHES INC**
130 VAL KIRK DR.
BRAMPTON ON L7A 1B1 | **GEN**

Generator Info

Generator No: ON0004205
Approval Years: 90
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT & VARNISH IND.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3751

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

81 | **7 of 34** | **SSE/212.1** | **238.9 / -3.08** | **SHERWIN WILLIAMS AUTO FINISHES INC11-314**
130 VAL KIRK DR.
BRAMPTON ON L7A 1B1 | **GEN**

Generator Info

Generator No: ON0004205
Approval Years: 92,93,94,95,96
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT & VARNISH IND.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3751

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

81 | **8 of 34** | **SSE/212.1** | **238.9 / -3.08** | **SHERWIN WILLIAMS AUTO FINISHES INC**
130 VAL KIRK DR
BRAMPTON ON L7A 1B1 | **GEN**

Generator Info

Generator No: ON0004205
Approval Years: 97
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT & VARNISH IND.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3751

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

81 | ***9 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***SHERWIN WILLIAMS AUTO FINISHES INC.***
130 VAN KIRK DR
BRAMPTON ON L7A 1B1 | ***GEN***

Generator Info

Generator No: ON0004205
Approval Years: 98,99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT & VARNISH IND.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3751

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

81 | ***10 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***SHERWIN WILLIAMS***
130 VAN KIRK DR
BRAMPTON ON L7A 1B1 | ***GEN***

Generator Info

Generator No: ON0004205
Approval Years: 02,03,04,05,06,07,08
Status:
PO Box No:
Country:
Co Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 325510

Phone No Admin:
SIC Description: Paint & Coating Mfg.

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

81	***11 of 34***	***SSE/212.1***	***238.9 / -3.08***	***CUSTOM COLOUR PAINTS LTD.*** ***130 VAN KIRK DR.*** ***BRAMPTON ON L7A 1B1***	***GEN***

Generator Info

Generator No: ON0239401
Approval Years: 86,87
Choice of Contact:
Contaminated Fac:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 0000
Country:
Co Admin:
Phone No Admin:
SIC Description: *** NOT DEFINED ***

---

81 ***12 of 34*** ***SSE/212.1*** ***238.9 / -3.08*** ***CUSTOM COLOUR PAINTS LTD.*** ***GEN***
130 VAN KIRK DR.
BRAMPTON ON L7A 1B1

Generator Info

Generator No: ON0239401 ***Choice of Contact:***
Approval Years: 88,89 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 3751
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT & VARNISH IND.

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

81 ***13 of 34*** ***SSE/212.1*** ***238.9 / -3.08*** ***CUSTOM (SEE & USE ON0004205)*** ***GEN***
130 VAN KIRK DR.
BRAMPTON ON L7A 1B1

Generator Info

Generator No: ON0239401 ***Choice of Contact:***
Approval Years: 90 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 3751
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT & VARNISH IND.

---

81 ***14 of 34*** ***SSE/212.1*** ***238.9 / -3.08*** ***CUSTOM (SEE & USE ON0004205) 11-314*** ***GEN***
130 VAN KIRK DR.
BRAMPTON ON L7A 1B1

Generator Info

Generator No: ON0239401 ***Choice of Contact:***
Approval Years: 92,93,94,95,96,97 ***Contaminated Fac:***
Status: ***MHSW Facility:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT & VARNISH IND.

SIC Code: 3751

---

81 | **15 of 34** | **SSE/212.1** | **238.9 / -3.08**

CUSTOM COLOUR PAINTS (SEE&USE ON000420)
130 VAN KIRK DRIVE
BRAMPTON ON L7A 1B1

GEN

Generator Info

Generator No: ON0239401
Approval Years: 98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT & VARNISH IND.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3751

---

81 | **16 of 34** | **SSE/212.1** | **238.9 / -3.08**

Sherwin-Williams Canada Inc. - Chemical Coatings Div.
130 Van Kirk Dr
Brampton ON L7A 1B1

SCT

Established: 1991
Plant Size (ft²): 25000
Employment: 25

--Details--
Description: Resin and Synthetic Rubber Manufacturing
SIC/NAICS Code: 325210

Description: Paint and Coating Manufacturing
SIC/NAICS Code: 325510

---

81 | **17 of 34** | **SSE/212.1** | **238.9 / -3.08**

Sherwin-Williams Canada Inc.
130 Van Kirk Dr
Brampton ON L7A 1B1

SCT

Established: 01-JUL-91
Plant Size (ft²): 25000
Employment:

--Details--
Description: Paint and Coating Manufacturing
SIC/NAICS Code: 325510

Description: Paint and Coating Manufacturing
SIC/NAICS Code: 325510

---

81 | **18 of 34** | **SSE/212.1** | **238.9 / -3.08**

Sherwin-Williams Canada Inc.
130 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1B1 CITY OF BRAMPTON

EBR

EBR Registry No: 010-2401
Ministry Ref No: 8601-79LKMK
Notice Type: Instrument Decision
Notice Stage:
Notice Date: August 05, 2009
Proposal Date: December 21, 2007
Year: 2007
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Sherwin-Williams Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 130 Van Kirk Drive, Brampton Ontario, Canada L7A 1B1
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

130 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1B1 CITY OF BRAMPTON

81	19 of 34	SSE/212.1	238.9 / -3.08	**Sherwin-Williams Canada Inc.** **130 Van Kirk Dr** **Brampton ON L7A 1B1**	CA

Certificate #: 2913-7R4RX4
Application Year: 2009
Issue Date: 7/31/2009
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

81	20 of 34	SSE/212.1	238.9 / -3.08	**THE SHERWIN-WILLIAMS COMPANY** **130 VAN KIRK DR** **BRAMPTON ON L7A 1B1**	GEN

Generator Info

Generator No: ON0004205
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Paint and Coating Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 325510

Waste Detail(s)

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

81 | ***21 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***THE SHERWIN-WILLIAMS COMPANY***
130 VAN KIRK DR
BRAMPTON ON L7A 1B1 | ***GEN***

Generator Info

Generator No: ON0004205
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Paint and Coating Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 325510

Waste Detail(s)

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

81	22 of 34	SSE/212.1	238.9 / -3.08	**THE SHERWIN-WILLIAMS COMPANY** **130 VAN KIRK DR** **BRAMPTON ON L7A 1B1**	GEN

Generator Info

Generator No: ON0004205
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Paint and Coating Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 325510

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

81 | ***23 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***THE SHERWIN-WILLIAMS COMPANY***
130 VAN KIRK DR
BRAMPTON ON L7A 1B1 | ***GEN***

Generator Info

Generator No: ON0004205
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Paint and Coating Manufacturing

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 325510

Waste Detail(s)

Waste Class: 231

Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

---

81 | ***24 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***THE SHERWIN-WILLIAMS COMPANY***
130 VAN KIRK DR
BRAMPTON ON | ***GEN***

Generator Info

Generator No: ON0004205
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT AND COATING MANUFACTURING

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 325510

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

81 ***25 of 34*** ***SSE/212.1*** ***238.9 / -3.08*** ***Sherwin-Williams Canada Inc.***
130 Van Kirk Dr
Brampton ON L7A 1B1 ***ECA***

Approval No: 2913-7R4RX4
Approval Date: 2009-07-31
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Sherwin-Williams Canada Inc.
Address: 130 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8601-79LKMK-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.80614
Latitude: 43.707962
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	26 of 34	SSE/212.1	238.9 / -3.08	THE SHERWIN-WILLIAMS COMPANY 130 VAN KIRK DR BRAMPTON ON L7A 1B1	GEN

Generator Info

Generator No:	ON0004205	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	325510
Country:	Canada		
Co Admin:	Michael Allen		
Phone No Admin:	9058460740 Ext.120		
SIC Description:	PAINT AND COATING MANUFACTURING		

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

81 | ***27 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***THE SHERWIN-WILLIAMS COMPANY***
130 VAN KIRK DR
BRAMPTON ON L7A 1B1 | ***GEN***

Generator Info

Generator No:	ON0004205	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	325510
Country:	Canada		
Co Admin:	Michael Allen		
Phone No Admin:	9058460740 Ext.120		
SIC Description:	PAINT AND COATING MANUFACTURING		

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Detail(s)

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

81 | ***28 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***THE SHERWIN-WILLIAMS COMPANY***
130 VAN KIRK DR
BRAMPTON ON L7A 1B1 | ***GEN***

Generator Info

Generator No:	ON0004205	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	325510
Country:	Canada		
Co Admin:			
Phone No Admin:			

SIC Description: PAINT AND COATING MANUFACTURING

Waste Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

81 | **29 of 34** | **SSE/212.1** | **238.9 / -3.08** | **THE SHERWIN-WILLIAMS COMPANY**
performance coatings
130 VAN KIRK DR
BRAMPTON ON L7A 1B1 | **GEN**

Generator Info

Generator No: ON0004205
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 212 B
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 232 B
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 232 L
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

81	30 of 34	SSE/212.1	238.9 / -3.08	THE SHERWIN-WILLIAMS COMPANY performance coatings	GEN

130 VAN KIRK DR
BRAMPTON ON L7A 1B1

Generator Info

Generator No:	ON0004205	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 212 B
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 232 B
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 232 L
Waste Class Name: Polymeric resins

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	31 of 34	SSE/212.1	238.9 / -3.08	THE SHERWIN-WILLIAMS COMPANY performance coatings 130 VAN KIRK DR BRAMPTON ON L7A 1B1	GEN

Generator Info

Generator No: ON0004205
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 212 B
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: Aromatic solvents and residues

Waste Detail(s)

Waste Class: 232 L
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 145 L

Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 232 B
Waste Class Name: Polymeric resins

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

81 | **32 of 34** | **SSE/212.1** | **238.9 / -3.08** | **Sherwin Williams Canada Product Finishes**
130 VAN KIRK DR
BRAMPTON ON | **GEN**

Generator Info

Generator No: ON0004205
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 232 B
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 232 L
Waste Class Name: POLYMERIC RESINS

Waste Detail(s)

Waste Class: 212 B
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 211 H
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 145 H
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: INERT INORGANIC WASTES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Generator Info as of Dec 2024

Generator No: ON0004205
Generator Company Name: Sherwin Williams Canada Product Finishes
Street: 130 VAN KIRK DR
City: BRAMPTON
Province State: Ontario
Country: Canada
Postal Code: L7A1B1
Waste Class: 145 B,211 H,145 H,145 I,252 L,263 I,145 L,150 L,212 B,146 T,232 B,212 L,232 L,331 I,251 L,113 C

Waste Class Decoded:

145 - PAINT/PIGMENT/COATING RESIDUES; 211 - AROMATIC SOLVENTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 145 - PAINT/PIGMENT/COATING RESIDUES; 252 - WASTE OILS & LUBRICANTS; 263 - ORGANIC LABORATORY CHEMICALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 150 - INERT INORGANIC WASTES; 212 - ALIPHATIC SOLVENTS; 146 - OTHER SPECIFIED INORGANICS; 232 - POLYMERIC RESINS; 212 - ALIPHATIC SOLVENTS; 232 - POLYMERIC RESINS; 331 - WASTE COMPRESSED GASES; 251 - OIL SKIMMINGS & SLUDGES; 113 - ACID WASTE - OTHER METALS

2017 Generator Info

Gen No:	ON0004205	***Choice of Contact:***	CO_OFFICIAL
ID:	624	***Phone No Official:***	9058460740 Ext.121
Contaminated Fac:	N	***Phone No Admin:***	9058460740 Ext.120
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	325510	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	THE SHERWIN-WILLIAMS COMPANY		
Gen Div:	product finishes		
Gen Op Name:	THE SHERWIN-WILLIAMS COMPANY		
Gen Op Div:			
Site Adrs1:	130 VAN KIRK DR		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1B1		
Site Country:	Canada		
Co Official:	Nicole Viau		
Co Admin:	Michael Allen		

2017 Generator Manifest

ID:	2001	***Sum Received Qty:***	11410.0
Generator No:	ON0004205	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	***Count Manifests:***	12
Waste Char:	L	***District:***	305
Waste Code:	145		

2017 Generator Manifest

ID:	1999	***Sum Received Qty:***	6206.0
Generator No:	ON0004205	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	***Count Manifests:***	10
Waste Char:	H	***District:***	305
Waste Code:	145		

2017 Generator Manifest

ID:	2002	***Sum Received Qty:***	4726.0
Generator No:	ON0004205	***Waste Class Name:***	AROMATIC SOLVENTS
Receiver Type:	035	***Count Manifests:***	11
Waste Char:	H	***District:***	305
Waste Code:	211		

2017 Generator Manifest

ID:	1998	***Sum Received Qty:***	1217.0
Generator No:	ON0004205	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES

Receiver Type:	035	**Count Manifests:**	2
Waste Char:	B	**District:**	305
Waste Code:	145		

2017 Generator Manifest

ID:	2000	**Sum Received Qty:**	12180.0
Generator No:	ON0004205	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	12
Waste Char:	I	**District:**	305
Waste Code:	145		

2017 Generator Manifest

ID:	2003	**Sum Received Qty:**	15.0
Generator No:	ON0004205	**Waste Class Name:**	POLYMERIC RESINS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	232		

2018 Generator Info

Gen No:	ON0004205	**Choice of Contact:**	CO_OFFICIAL
ID:	611	**Phone No Official:**	9058460740 Ext.121
Contaminated Fac:	N	**Phone No Admin:**	9058460740 Ext.120
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	325510	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	THE SHERWIN-WILLIAMS COMPANY
Gen Div:	performance coatings
Gen Op Name:	THE SHERWIN-WILLIAMS COMPANY
Gen Op Div:	
Site Adrs1:	130 VAN KIRK DR
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 1B1
Site Country:	Canada
Co Official:	Nicole Viau
Co Admin:	Michael Allen

2018 Generator Manifest

ID:	1910	**Sum Received Qty:**	7084.0
Generator No:	ON0004205	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	7
Waste Char:	B	**District:**	305
Waste Code:	145		

2018 Generator Manifest

ID:	1913	**Sum Received Qty:**	9813.9
Generator No:	ON0004205	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	17
Waste Char:	L	**District:**	305
Waste Code:	145		

2018 Generator Manifest

ID: 1914
Generator No: ON0004205
Receiver Type: 035
Waste Char: H
Waste Code: 211
Sum Received Qty: 7981.0
Waste Class Name: AROMATIC SOLVENTS
Count Manifests: 13
District: 305

2018 Generator Manifest

ID: 1912
Generator No: ON0004205
Receiver Type: 035
Waste Char: I
Waste Code: 145
Sum Received Qty: 13816.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 14
District: 305

2018 Generator Manifest

ID: 1911
Generator No: ON0004205
Receiver Type: 035
Waste Char: H
Waste Code: 145
Sum Received Qty: 7912.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 13
District: 305

2018 Generator Manifest

ID: 1915
Generator No: ON0004205
Receiver Type: 035
Waste Char: L
Waste Code: 232
Sum Received Qty: 20.0
Waste Class Name: POLYMERIC RESINS
Count Manifests: 1
District: 305

2019 Generator Info

Gen No: ON0004205
ID: 592
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 325510
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9058460740 Ext.121
Phone No Admin: 9058460740 Ext.120
County Ont: PEEL (R. M.)
County Out:
District: 305

Gen Name: THE SHERWIN-WILLIAMS COMPANY
Gen Div: performance coatings
Gen Op Name: THE SHERWIN-WILLIAMS COMPANY
Gen Op Div:
Site Adrs1: 130 VAN KIRK DR
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: Nicole Viau
Co Admin: Michael Allen

2019 Generator Manifest

ID: 1794
Generator No: ON0004205
Receiver Type: 035
Sum Received Qty: 687.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 3

Waste Char: I
Waste Code: 331
District: 305

2019 Generator Manifest

ID: 1789
Generator No: ON0004205
Receiver Type: 035
Waste Char: B
Waste Code: 145
Sum Received Qty: 2228.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 6
District: 305

2019 Generator Manifest

ID: 1792
Generator No: ON0004205
Receiver Type: 035
Waste Char: L
Waste Code: 145
Sum Received Qty: 10211.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 18
District: 305

2019 Generator Manifest

ID: 1793
Generator No: ON0004205
Receiver Type: 035
Waste Char: H
Waste Code: 211
Sum Received Qty: 5040.0
Waste Class Name: AROMATIC SOLVENTS
Count Manifests: 14
District: 305

2019 Generator Manifest

ID: 1791
Generator No: ON0004205
Receiver Type: 035
Waste Char: I
Waste Code: 145
Sum Received Qty: 13078.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 15
District: 305

2019 Generator Manifest

ID: 1790
Generator No: ON0004205
Receiver Type: 035
Waste Char: H
Waste Code: 145
Sum Received Qty: 8347.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 15
District: 305

2020 Generator Info

Gen No: ON0004205
ID: 554
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 325510
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9058460740 Ext.121
Phone No Admin: 9058460740 Ext.120
County Ont: PEEL (R. M.)
County Out:
District: 305

Gen Name: THE SHERWIN-WILLIAMS COMPANY
Gen Div: performance coatings
Gen Op Name: THE SHERWIN-WILLIAMS COMPANY
Gen Op Div:
Site Adrs1: 130 VAN KIRK DR
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:

Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 1B1
Site Country:	Canada
Co Official:	Nicole Viau
Co Admin:	Michael Allen

2020 Generator Manifest

ID:	1542	**Sum Received Qty:**	200.0
Generator No:	ON0004205	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	301
Waste Code:	251		

2020 Generator Manifest

ID:	1544	**Sum Received Qty:**	5862.0
Generator No:	ON0004205	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	9
Waste Char:	H	**District:**	305
Waste Code:	145		

2020 Generator Manifest

ID:	1545	**Sum Received Qty:**	12020.0
Generator No:	ON0004205	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	10
Waste Char:	I	**District:**	305
Waste Code:	145		

2020 Generator Manifest

ID:	1547	**Sum Received Qty:**	3557.0
Generator No:	ON0004205	**Waste Class Name:**	AROMATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	9
Waste Char:	H	**District:**	305
Waste Code:	211		

2020 Generator Manifest

ID:	1550	**Sum Received Qty:**	547.0
Generator No:	ON0004205	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	I	**District:**	402
Waste Code:	145		

2020 Generator Manifest

ID:	1551	**Sum Received Qty:**	364.0
Generator No:	ON0004205	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	030	**Count Manifests:**	1
Waste Char:	L	**District:**	402
Waste Code:	145		

2020 Generator Manifest

ID:	1548	**Sum Received Qty:**	110.0
Generator No:	ON0004205	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	035	**Count Manifests:**	1

Waste Char: I
Waste Code: 331
District: 305

2020 Generator Manifest

ID: 1552
Generator No: ON0004205
Receiver Type: 030
Waste Char: H
Waste Code: 211
Sum Received Qty: 727.0
Waste Class Name: AROMATIC SOLVENTS
Count Manifests: 1
District: 402

2020 Generator Manifest

ID: 1543
Generator No: ON0004205
Receiver Type: 035
Waste Char: B
Waste Code: 145
Sum Received Qty: 18788.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 305

2020 Generator Manifest

ID: 1546
Generator No: ON0004205
Receiver Type: 035
Waste Char: L
Waste Code: 145
Sum Received Qty: 11912.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 12
District: 305

2020 Generator Manifest

ID: 1549
Generator No: ON0004205
Receiver Type: 030
Waste Char: H
Waste Code: 145
Sum Received Qty: 544.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 402

2021 Generator Info

Gen No: ON0004205
ID: 557
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 325510
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9058460740 Ext.121
Phone No Admin: 9058460740 Ext.120
County Ont: PEEL (R. M.)
County Out:
District: 305

Gen Name: THE SHERWIN-WILLIAMS COMPANY
Gen Div: performance coatings
Gen Op Name: THE SHERWIN-WILLIAMS COMPANY
Gen Op Div:
Site Adrs1: 130 VAN KIRK DR
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: Nicole Viau
Co Admin: Michael Allen

2021 Generator Manifest

ID: 1557
Generator No: ON0004205
Receiver Type: 035
Waste Char: L
Waste Code: 145

Sum Received Qty: 10697.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 12
District: 305

2021 Generator Manifest

ID: 1559
Generator No: ON0004205
Receiver Type: 035
Waste Char: B
Waste Code: 212

Sum Received Qty: 6.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 305

2021 Generator Manifest

ID: 1556
Generator No: ON0004205
Receiver Type: 035
Waste Char: I
Waste Code: 145

Sum Received Qty: 13743.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 12
District: 305

2021 Generator Manifest

ID: 1560
Generator No: ON0004205
Receiver Type: 035
Waste Char: L
Waste Code: 232

Sum Received Qty: 3.0
Waste Class Name: POLYMERIC RESINS
Count Manifests: 1
District: 305

2021 Generator Manifest

ID: 1558
Generator No: ON0004205
Receiver Type: 035
Waste Char: H
Waste Code: 211

Sum Received Qty: 8120.0
Waste Class Name: AROMATIC SOLVENTS
Count Manifests: 11
District: 305

2021 Generator Manifest

ID: 1554
Generator No: ON0004205
Receiver Type: 035
Waste Char: B
Waste Code: 145

Sum Received Qty: 730.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 3
District: 305

2021 Generator Manifest

ID: 1555
Generator No: ON0004205
Receiver Type: 035
Waste Char: H
Waste Code: 145

Sum Received Qty: 12090.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 11
District: 305

2021 Generator Manifest

ID: 1561
Generator No: ON0004205
Receiver Type: 035

Sum Received Qty: 72.0
Waste Class Name: WASTE COMPRESSED GASES
Count Manifests: 1

Waste Char: I **District:** 305
Waste Code: 331

---

81 **33 of 34** **SSE/212.1** **238.9 / -3.08** **BRAMPTON**
130 VAN KIRK DRIVE
BRAMPTON ON L7A 1B1
NPR2

NPRI ID: 2703 **Latitude:** 43.7082
Facility ID: 223920;284152;341502;368431;417952;432250;444369 **Longitude:** -79.806
Facility Name: BRAMPTON
Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=2703

NPRI ID Substances Summary

CAS No: NA - 03 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Cadmium (and its compounds)
Name French: Cadmium (et ses composés)
Sort English: Cadmium (and its compounds)
Sort French: Cadmium (et ses composés)

CAS No: 100-41-4 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: Ethylbenzene
Name French: Éthylbenzène
Sort English: Ethylbenzene
Sort French: Éthylbenzène

CAS No: NA - 08 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Lead (and its compounds)
Name French: Plomb (et ses composés)
Sort English: Lead (and its compounds)
Sort French: Plomb (et ses composés)

CAS No: NA - 05 **Is PAH?:** FALSE
Is VOC?: FALSE **NPRI:** TRUE
Is DF?: FALSE
Name English: Cobalt (and its compounds)
Name French: Cobalt (et ses composés)
Sort English: Cobalt (and its compounds)
Sort French: Cobalt (et ses composés)

CAS No: 95-63-6 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: 1,2,4-Trimethylbenzene
Name French: 1,2,4-Triméthylbenzène
Sort English: Trimethylbenzene:1,2,4-
Sort French: Triméthylbenzène:1,2,4-

CAS No:	NA - 19	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Hexavalent chromium (and its compounds)		
Name French:	Chrome hexavalent (et ses composés)		
Sort English:	Hexavalent chromium (and its compounds)		
Sort French:	Chrome hexavalent (et ses composés)		

CAS No:	111-76-2	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	2-Butoxyethanol		
Name French:	2-Butoxyéthanol		
Sort English:	Butoxyethanol:2-		
Sort French:	Butoxyéthanol:2-		

CAS No:	1330-20-7	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Xylene (all isomers)		
Name French:	Xylène (tous les isomères)		
Sort English:	Xylene (all isomers)		
Sort French:	Xylène (tous les isomères)		

CAS No:	1330-20-7	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Xylene (mixed isomers)		
Name French:	Xylène (mélanges d'isomères)		
Sort English:	Xylene (mixed isomers)		
Sort French:	Xylène (mélanges d'isomères)		

CAS No:	108-88-3	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Toluene		
Name French:	Toluène		
Sort English:	Toluene		
Sort French:	Toluène		

CAS No:	78-93-3	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Methyl ethyl ketone		
Name French:	Méthyléthylcétone		
Sort English:	Methyl ethyl ketone		
Sort French:	Méthyléthylcétone		

Geographic Location

Report Year:	-1	**Forward Sort Area:**	L6Z
Census Subdiv ID:	3521010	**DLS Description:**	
Ecozone ID:	8	**NTS Description:**	D-045-K/030-M-12
Water Survey ID:	2	**Province Code:**	ON
SOMA:	TRUE	**Datum:**	1983.0
ON PEMA:	TRUE	**Latitude:**	43.7082
QC PEMA:	FALSE	**Longitude:**	-79.806
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	417952

Facility

Facility ID:	417952	***IDM ID:***	10695
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	418410	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	
NAICS Tertiary:	0		
Facility Name:	Brampton		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A 1B1
Prov:	

Address Geographic

Latitude:	43.70820	***Datum:***	1983
Longitude:	-79.80600	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	418410	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues, sauf les produits chimiques agricoles		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code:	418410	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2007
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2022
Record Year: 2022 ***End Date:*** 2026
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers

NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NPRI Report

Report ID:	313030	***No of Employees:***	18
Report Year:	2020	***Is Compressor:***	
Company ID:	171358	***Is NPRI Part 4:***	
SWR Report ID:	1243	***Is Battery:***	
Repor Type ID:	8	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2021-09-03 10:59:04.5469055

Company

Company Name:	Sherwin-Williams Canada Inc
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:			
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	216-566-1130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:			
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		

Description Fr: Responsable des renseignements au public
Position:
Language: 1
Email: Michael.S.Allen@sherwin.com

NPRI ID Facility ID

NPRI ID: 2703
Facility ID: 444369

Facility

Facility ID: 444369
Portable: FALSE
NAICS Primary: 418410
NAICS Secondary:
NAICS Tertiary:
Facility Name: Brampton
Website:
IDM ID: 10695
AB Approval ID: 0
GHGRP ID: 0
ON GHGRP ID:

Address

Address1: 130 Van Kirk Drive
Address2:
City: Brampton
Postal Zip: L7A 1B1
Prov:

Address Geographic

Latitude: 43.708200
Longitude: -79.806000
UTM Easting: 0.000000
UTM Northing: 0.000000
UTM Zone: 0
Datum: 1983
Land Survey:
Topograph:
Additional Info:

Primary NAICS Details

NAICS Code: 418410
Record Year: 1997
Start Date: 1993
End Date: 2001
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues, sauf les produits chimiques agricoles

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410
Record Year: 2002
Start Date: 2002
End Date: 2006
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors

NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2007
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code:	418410	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NPRI Report

Report ID:	338323	***No of Employees:***	24
Report Year:	2022	***Is Compressor:***	
Company ID:	178494	***Is NPRI Part 4:***	
SWR Report ID:	26635	***Is Battery:***	
Repor Type ID:	8	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2023-05-19 08:13:31.9547407

Company

Company Name:	Sherwin-Williams Canada Inc
DUNS No:	
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Regional Facilities Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	216-566-1130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Mgr		
Language:	1		

Email: mjsoltes@sherwin.com

NPRI Report Contact

Contact Type:		***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Regional Facilities Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	284152

Facility

Facility ID:	284152	***IDM ID:***	10695
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	418410	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	Brampton		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1B1
Prov:	

Address Geographic

Latitude:	43.7082	***Datum:***	1983
Longitude:	-79.806	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	418410	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code:	418410	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code:	418410	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues, sauf les produits chimiques agricoles		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code:	418410	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code:	418410	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		

NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410
Record Year: 2012
Start Date: 2012
End Date: 2016
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NPRI Report

Report ID: 67669
Report Year: 2019
Company ID: 112753
SWR Report ID: 161178
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 16
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 1
Submit Date: 2020-05-21 11:23:15.5570000

Company

Company Name: Sherwin-Williams Canada
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Allen
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: Michael.S.Allen@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report

Report ID:	95917	***No of Employees:***	18
Report Year:	2018	***Is Compressor:***	
Company ID:	110705	***Is NPRI Part 4:***	
SWR Report ID:	145060	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2019-05-24 09:02:03.1900000

Company

Company Name:	Sherwin-Williams Canada
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		

Language: 1
Email: Michael.S.Allen@sherwin.com

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Allen
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: Michael.S.Allen@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report

Report ID: 95916
Report Year: 2017
Company ID: 110705
SWR Report ID: 95096
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 15
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 1
Submit Date: 2018-05-16 09:52:30.7333333

Company

Company Name: Sherwin-Williams Canada
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Allen
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: Michael.S.Allen@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report Contact

Contact Type: NPRI
First Name: Michael
Last Name: Allen
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Facility Manager
Language: 1
Email: Michael.S.Allen@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Soltes
Phone: 2165661130
Extension:
Fax: 2162638624

Company Name:
Description En:
Description Fr:
Position: Environmental Project Manager
Language: 1
Email: mjsoltes@sherwin.com

NPRI Report

Report ID: 95915
Report Year: 2016
Company ID: 110705
SWR Report ID: 83782
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 15
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 1
Submit Date: 2017-05-25 11:56:33.1100000

Company

Company Name: Sherwin-Williams Canada
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type: NPRI
First Name: Michael
Last Name: Allen
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Facility Manager
Language: 1
Email: Michael.S.Allen@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Soltes
Company Name:
Description En:
Description Fr:
Position: Environmental Project Manager
Language: 1
Email: mjsoltes@sherwin.com
Phone: 2165661130
Extension:
Fax: 2162638624

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Allen
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: Michael.S.Allen@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report

Report ID:	24377	**No of Employees:**	15
Report Year:	2015	**Is Compressor:**	
Company ID:	110705	**Is NPRI Part 4:**	
SWR Report ID:	71207	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	1
New Reporter:	FALSE	**Submit Date:**	2016-05-20 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Canada
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058460740
First Name:	Michael	**Extension:**	
Last Name:	Allen	**Fax:**	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		**Phone:**	2165661130
First Name:	Michael	**Extension:**	
Last Name:	Soltes	**Fax:**	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Michael	**Extension:**	
Last Name:	Allen	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Michael	**Extension:**	
Last Name:	Allen	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		

Email: Michael.S.Allen@sherwin.com

NPRI Report

Report ID:	33930	***No of Employees:***	15
Report Year:	2014	***Is Compressor:***	
Company ID:	110705	***Is NPRI Part 4:***	
SWR Report ID:	49456	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2015-05-27 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Canada
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			

Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Facility Manager
Language: 1
Email: melba.hibbard@sherwin.com

NPRI Report

Report ID:	42705	***No of Employees:***	15
Report Year:	2013	***Is Compressor:***	
Company ID:	110705	***Is NPRI Part 4:***	
SWR Report ID:	29508	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2014-05-28 00:00:00.0000000

Company

Company Name: Sherwin-Williams Canada
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Melba	**Extension:**	
Last Name:	Hibbard	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report

Report ID:	51972	**No of Employees:**	14
Report Year:	2012	**Is Compressor:**	
Company ID:	112753	**Is NPRI Part 4:**	
SWR Report ID:	14511	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	1
New Reporter:	FALSE	**Submit Date:**	2013-05-22 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Canada
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	2165661130
First Name:	Michael	**Extension:**	
Last Name:	Soltes	**Fax:**	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Melba	**Extension:**	
Last Name:	Hibbard	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058460740
First Name:	Melba	**Extension:**	
Last Name:	Hibbard	**Fax:**	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report

Report ID:	61347	***No of Employees:***	14
Report Year:	2011	***Is Compressor:***	
Company ID:	112753	***Is NPRI Part 4:***	
SWR Report ID:	2172	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2012-06-27 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Canada
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			

Description Fr:	
Position:	Facility Manager
Language:	1
Email:	melba.hibbard@sherwin.com

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report

Report ID:	153681	***No of Employees:***	12
Report Year:	2010	***Is Compressor:***	
Company ID:	112753	***Is NPRI Part 4:***	
SWR Report ID:	20100000002703	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2011-06-14 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Canada
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	Report Submission and Electronic Certification Comment
Description Fr:	Soumission de déclaration et attestation électronique
Comment:	Thanks!
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			

Position:
Language: 0
Email: deboom@sherwin.com

NPRI Report Contact

Contact Type: ***Phone:*** 4106258051
First Name: Derrick ***Extension:***
Last Name: Boom ***Fax:*** 2162638609
Company Name:
Description En:
Description Fr:
Position:
Language: 0
Email: deboom@sherwin.com

NPRI Report Contact

Contact Type: ***Phone:*** 9058460740
First Name: Melba ***Extension:***
Last Name: Hibbard ***Fax:***
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 0
Email: melba.hibbard@sherwin.com

NPRI Report Contact

Contact Type: NPRI ***Phone:*** 9058460740
First Name: Melba ***Extension:***
Last Name: Hibbard ***Fax:***
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Facility Manager
Language: 0
Email: melba.hibbard@sherwin.com

NPRI Report

Report ID: 151715 ***No of Employees:*** 15
Report Year: 2009 ***Is Compressor:***
Company ID: 132437 ***Is NPRI Part 4:***
SWR Report ID: 20090000002703 ***Is Battery:***
Repor Type ID: 1 ***Corres Lang ID:*** 0
New Reporter: FALSE ***Submit Date:*** 2010-05-27 00:00:00.0000000

Company

Company Name: SHERWIN-WILLIAMS CANADA
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Comment

Description En: Report Submission and Electronic Certification Comment
Description Fr: Soumission de déclaration et attestation électronique

Comment: Thanks!
Note:

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Darren	***Extension:***	
Last Name:	Armstrong	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:	darren.armstrong@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Darren	***Extension:***	
Last Name:	Armstrong	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:	darren.armstrong@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report

Report ID:	153632	***No of Employees:***	13
Report Year:	2008	***Is Compressor:***	
Company ID:	132437	***Is NPRI Part 4:***	
SWR Report ID:	20080000002703	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2009-05-27 00:00:00.0000000

Company

Company Name: SHERWIN-WILLIAMS CANADA
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type: NPRI
First Name: Darren
Last Name: Armstrong
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension:
Fax: 9058403010

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Company Name:
Description En:
Description Fr:
Position: Environmental Specialist
Language: 0
Email: deboom@sherwin.com
Phone: 4106258051
Extension:
Fax: 2162638609

NPRI Report Contact

Contact Type:
First Name: Darren
Last Name: Armstrong
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension:
Fax: 9058402301

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Company Name:
Description En:
Description Fr:
Position: Senior Environmental Specialist
Language: 0
Email: deboom@sherwin.com
Phone: 4106258051
Extension:
Fax: 2162638609

NPRI Report

Report ID: 153789
Report Year: 2007
Company ID: 132437
SWR Report ID: 20070000002703
Repor Type ID: 1
No of Employees: 21
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0

New Reporter:	TRUE	***Submit Date:***	2008-05-29 00:00:00.0000000

Company

Company Name:	SHERWIN-WILLIAMS CANADA
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Darren	***Extension:***	
Last Name:	Armstrong	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Darren	***Extension:***	
Last Name:	Armstrong	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI ID Facility ID

NPRI ID:	2703

Facility ID: 341502

Facility

Facility ID:	341502	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	325510	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	BRAMPTON		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1B1
Prov:	

Address Geographic

Latitude:	43.7082	***Datum:***	1983
Longitude:	-79.806	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	325510	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		

NAICS Title En: Paint and Coating Manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NPRI Report

Report ID:	152278	***No of Employees:***	21
Report Year:	2006	***Is Compressor:***	
Company ID:	132437	***Is NPRI Part 4:***	
SWR Report ID:	20060000002703	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2007-05-23 00:00:00.0000000

Company

Company Name: SHERWIN-WILLIAMS CANADA
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Darren	***Extension:***	
Last Name:	Armstrong	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			

Description En:
Description Fr:
Position: Environmental Specialist
Language: 0
Email: deboom@sherwin.com

NPRI Report Contact

Contact Type: NPRI
First Name: Darren
Last Name: Armstrong
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension:
Fax: 9058403010

NPRI Report

Report ID: 254719
Report Year: 2005
Company ID: 142649
SWR Report ID: 20050000002703
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 21
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 2006-05-23 00:00:00.0000000

Company

Company Name: THE SHERWIN-WILLIAMS
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Darren
Last Name: Armstrong
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension: 0
Fax: 9058402301

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Company Name:
Description En:
Description Fr:
Position: Environmental Specialist
Language: 0
Email: deboom@sherwin.com
Phone: 4106258051
Extension: 0
Fax: 2162638609

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058460740
First Name:	Darren	**Extension:**	0
Last Name:	Armstrong	**Fax:**	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Darren	**Extension:**	0
Last Name:	Armstrong	**Fax:**	0
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	166700	**No of Employees:**	21
Report Year:	2004	**Is Compressor:**	
Company ID:	132437	**Is NPRI Part 4:**	
SWR Report ID:	20040000002703	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2005-05-20 00:00:00.0000000

Company

Company Name:	SHERWIN-WILLIAMS CANADA
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	Report Submission and Electronic Certification Comment
Description Fr:	Soumission de déclaration et attestation électronique
Comment:	Thank You!
Note:	

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058460740
First Name:	Mike	**Extension:**	0
Last Name:	Vanduyse	**Fax:**	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058460740

First Name:	Mike	**Extension:**	0
Last Name:	Vanduyse	**Fax:**	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Mike	**Extension:**	0
Last Name:	Vanduyse	**Fax:**	0
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	4106258051
First Name:	Derrick	**Extension:**	0
Last Name:	Boom	**Fax:**	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report

Report ID:	271150	**No of Employees:**	21
Report Year:	2003	**Is Compressor:**	
Company ID:	140244	**Is NPRI Part 4:**	
SWR Report ID:	20030000002703	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2004-06-01 00:00:00.0000000

Company

Company Name:	THE SHERWIN-WILLIAMS COMPANY, BRAMPTON
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Andrew	**Extension:**	0
Last Name:	Hoskins	**Fax:**	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	0
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Andrew	***Extension:***	0
Last Name:	Hoskins	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Andrew	***Extension:***	0
Last Name:	Hoskins	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	368431

Facility

Facility ID:	368431	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	325510	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	BRAMPTON		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1B1
Prov:	

Primary NAICS Details

NAICS Code:	325510	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NPRI Report

Report ID:	276393	***No of Employees:***	21
Report Year:	2002	***Is Compressor:***	
Company ID:	145968	***Is NPRI Part 4:***	
SWR Report ID:	20020000002703	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2003-06-02 00:00:00.0000000

Company

Company Name:	THE SHERWIN-WILLIAMS COMPANY, BRAMPTON
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	0
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	432250

Facility

Facility ID:	432250	***IDM ID:***	10695
Portable:	FALSE	***AB Approval ID:***	
NAICS Primary:	418410	***GHGRP ID:***	
NAICS Secondary:	0	***ON GHGRP ID:***	
NAICS Tertiary:	0		

Facility Name: Brampton
Website:

Address

Address1:
Address2:
City: Brampton
Postal Zip: L7A 1B1
Prov:

Address Geographic

Latitude:	43.708200	***Datum:***	1983
Longitude:	-79.806000	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	418410	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code:	418410	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues, sauf les produits chimiques agricoles		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code:	418410	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		

NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2007
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NAICS Code: 418410 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NPRI Report

Report ID:	326187	***No of Employees:***	18
Report Year:	2021	***Is Compressor:***	
Company ID:	174954	***Is NPRI Part 4:***	
SWR Report ID:	11685	***Is Battery:***	
Repor Type ID:	8	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2022-05-24 15:20:15.9879236

Company

Company Name:	Sherwin-Williams Canada Inc
DUNS No:	
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Regional Facilities Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	216-566-1130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Mgr		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Regional Facilities Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI ID Facility ID

NPRI ID:	2703

Facility ID: 223920

Facility

Facility ID:	223920	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	325510	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:			
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1B1
Prov:	

Primary NAICS Details

NAICS Code:	325510	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code:	325510	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		

NAICS Title En: Paint and coating manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code: 325510 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and Coating Manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code: 325510 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and Coating Manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NAICS Code: 325510 ***Start Date:*** 2007
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and Coating Manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NPRI Report

Report ID:	279941	***No of Employees:***	21
Report Year:	2001	***Is Compressor:***	
Company ID:	99991	***Is NPRI Part 4:***	
SWR Report ID:	20010000002703	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2002-06-03 00:00:00.0000000

Company

Company Name:	The Sherwin-Williams Company
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	4106288051
First Name:	Derrick	***Extension:***	0
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	senior environmental specialis		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	2165662182
First Name:	Scott	**Extension:**	0
Last Name:	Thomas	**Fax:**	2165662730
Company Name:			
Description En:			
Description Fr:			
Position:	Director, Environmental Affair		
Language:	0		
Email:			

NPRI Report

Report ID:	194539	**No of Employees:**	21
Report Year:	2000	**Is Compressor:**	
Company ID:	139367	**Is NPRI Part 4:**	
SWR Report ID:	20000000002703	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2001-06-01 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Company
DUNS No:	004206397
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	2165662182
First Name:	Scott	**Extension:**	0
Last Name:	Thomas	**Fax:**	2162638602
Company Name:			
Description En:			
Description Fr:			
Position:	Director, Environmental Affair		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Wally	**Extension:**	0
Last Name:	Debling	**Fax:**	9058403010
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058460740
First Name:	Wally	**Extension:**	0
Last Name:	Debling	**Fax:**	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	283700	***No of Employees:***	21
Report Year:	1999	***Is Compressor:***	
Company ID:	145794	***Is NPRI Part 4:***	
SWR Report ID:	19990000002703	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2000-06-01 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Company
DUNS No:	420636397
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	Faye	***Extension:***	0
Last Name:	Menhart	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Director, Human Resources		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	176297	***No of Employees:***	21
Report Year:	1998	***Is Compressor:***	
Company ID:	102411	***Is NPRI Part 4:***	
SWR Report ID:	19980000002703	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0

New Reporter:	FALSE	**Submit Date:**	1999-06-01 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Company
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	0
First Name:	Steve	**Extension:**	0
Last Name:	Shawver	**Fax:**	0
Company Name:			
Description En:			
Description Fr:			
Position:	Director Store Operations		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Wally	**Extension:**	0
Last Name:	Debling	**Fax:**	9058403010
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058460740
First Name:	Wally	**Extension:**	0
Last Name:	Debling	**Fax:**	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	182308	**No of Employees:**	21
Report Year:	1997	**Is Compressor:**	
Company ID:	102411	**Is NPRI Part 4:**	
SWR Report ID:	19970000002703	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1998-06-01 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Company
DUNS No:	0
Trade Name En:	
Trade Name Fr:	

Website:

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	Steve	***Extension:***	0
Last Name:	Shawver	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Director Store Operations		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	851	***No of Employees:***	22
Report Year:	1996	***Is Compressor:***	
Company ID:	102411	***Is NPRI Part 4:***	
SWR Report ID:	19960000002703	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	1997-06-02 00:00:00.0000000

Company

Company Name:	Sherwin-Williams Company
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report

Report ID:	3408	***No of Employees:***	22
Report Year:	1995	***Is Compressor:***	
Company ID:	99991	***Is NPRI Part 4:***	
SWR Report ID:	19950000002703	***Is Battery:***	

Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1996-06-03 00:00:00.0000000

Company

Company Name:	The Sherwin-Williams Company
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report

Report ID:	4523	**No of Employees:**	22
Report Year:	1994	**Is Compressor:**	
Company ID:	100308	**Is NPRI Part 4:**	
SWR Report ID:	19940000002703	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1995-06-01 00:00:00.0000000

Company

Company Name:	THE SHERWIN WILLIAMS CO
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report

Report ID:	6131	**No of Employees:**	0
Report Year:	1993	**Is Compressor:**	
Company ID:	99991	**Is NPRI Part 4:**	
SWR Report ID:	19930000002703	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1994-06-01 00:00:00.0000000

Company

Company Name:	The Sherwin-Williams Company
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

Alternative Location Info

Facility ID:	432250
Facility Name:	BRAMPTON
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A 1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	341502
Facility Name:	BRAMPTON

Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 417952
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 223920
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 417952
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 368431
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 223920
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 284152
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 444369
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 432250
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 444369
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 284152
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 284152
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON

Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 444369
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 223920
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 341502
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 341502
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 432250
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 417952
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 368431
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 368431
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 417952
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 432250
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 223920
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON

Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	444369
Facility Name:	
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	341502
Facility Name:	BRAMPTON
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A 1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	284152
Facility Name:	BRAMPTON
Address1:	
City:	BRAMPTON
Postal ZIP:	L7A 1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	368431
Facility Name:	BRAMPTON
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A 1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

---

81 | ***34 of 34*** | ***SSE/212.1*** | ***238.9 / -3.08*** | ***BRAMPTON
130 VAN KIRK DRIVE
BRAMPTON ON L7A 1B1*** | ***PFHA***

NPRI ID:	2703
Facility ID:	223920;284152;341502;368431;417952;432250;444369
Latitude:	43.7082
Longitude:	-79.806
Note:	Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0. For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the

facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=2703

Alternative Location Info

Facility ID: 432250
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 417952
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 444369
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 341502
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 368431
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID:	432250
Facility Name:	
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	223920
Facility Name:	BRAMPTON
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A 1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	444369
Facility Name:	
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	341502
Facility Name:	BRAMPTON
Address1:	
City:	BRAMPTON
Postal ZIP:	L7A 1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	223920
Facility Name:	BRAMPTON
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

Alternative Location Info

Facility ID:	284152
Facility Name:	BRAMPTON
Address1:	130 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1B1
Province EN:	ON
Latitude:	43.7082

Longitude: -79.806

Alternative Location Info

Facility ID: 417952
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 223920
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 417952
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 432250
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 417952
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 284152
Facility Name:

Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 444369
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 368431
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 432250
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 341502
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 341502
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 444369
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 223920
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 284152
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 284152
Facility Name: BRAMPTON
Address1:
City: BRAMPTON
Postal ZIP: L7A 1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 368431
Facility Name:
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1B1
Province EN: ON
Latitude: 43.7082
Longitude: -79.806

Alternative Location Info

Facility ID: 368431
Facility Name: BRAMPTON
Address1: 130 VAN KIRK DRIVE
City: BRAMPTON

Postal ZIP:	L7A1B1
Province EN:	ON
Latitude:	43.7082
Longitude:	-79.806

NPRI ID Substances Summary

CAS No:	NA - 03	**Is VOC?:**	FALSE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Cadmium (and its compounds)		
Name French:	Cadmium (et ses composés)		
Sort English:	Cadmium (and its compounds)		
Sort French:	Cadmium (et ses composés)		

CAS No:	NA - 19	**Is VOC?:**	FALSE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Hexavalent chromium (and its compounds)		
Name French:	Chrome hexavalent (et ses composés)		
Sort English:	Hexavalent chromium (and its compounds)		
Sort French:	Chrome hexavalent (et ses composés)		

CAS No:	1330-20-7	**Is VOC?:**	TRUE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Xylene (all isomers)		
Name French:	Xylène (tous les isomères)		
Sort English:	Xylene (all isomers)		
Sort French:	Xylène (tous les isomères)		

CAS No:	78-93-3	**Is VOC?:**	TRUE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Methyl ethyl ketone		
Name French:	Méthyléthylcétone		
Sort English:	Methyl ethyl ketone		
Sort French:	Méthyléthylcétone		

CAS No:	NA - 08	**Is VOC?:**	FALSE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Lead (and its compounds)		
Name French:	Plomb (et ses composés)		
Sort English:	Lead (and its compounds)		
Sort French:	Plomb (et ses composés)		

CAS No:	95-63-6	**Is VOC?:**	TRUE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	1,2,4-Trimethylbenzene		
Name French:	1,2,4-Triméthylbenzène		
Sort English:	Trimethylbenzene:1,2,4-		
Sort French:	Triméthylbenzène:1,2,4-		

CAS No:	NA - 05	**Is VOC?:**	FALSE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Cobalt (and its compounds)		
Name French:	Cobalt (et ses composés)		
Sort English:	Cobalt (and its compounds)		
Sort French:	Cobalt (et ses composés)		

CAS No:	111-76-2	**Is VOC?:**	TRUE
Digits:		**Is DF?:**	FALSE

Decimal Points:		**Is PAH?:**	FALSE
Name English:	2-Butoxyethanol		
Name French:	2-Butoxyéthanol		
Sort English:	Butoxyethanol:2-		
Sort French:	Butoxyéthanol:2-		

CAS No:	100-41-4	**Is VOC?:**	TRUE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Ethylbenzene		
Name French:	Éthylbenzène		
Sort English:	Ethylbenzene		
Sort French:	Éthylbenzène		

CAS No:	1330-20-7	**Is VOC?:**	TRUE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Xylene (mixed isomers)		
Name French:	Xylène (mélanges d'isomères)		
Sort English:	Xylene (mixed isomers)		
Sort French:	Xylène (mélanges d'isomères)		

CAS No:	108-88-3	**Is VOC?:**	TRUE
Digits:		**Is DF?:**	FALSE
Decimal Points:		**Is PAH?:**	FALSE
Name English:	Toluene		
Name French:	Toluène		
Sort English:	Toluene		
Sort French:	Toluène		

Geographic Location

Report Year:	-1	**Forward Sort Area:**	L6Z
Census Subdiv ID:	3521010	**DLS Description:**	
Ecozone ID:	8	**NTS Description:**	D-045-K/030-M-12
Water Survey ID:	2	**Province Code:**	ON
SOMA:	TRUE	**Datum:**	1983.0
ON PEMA:	TRUE	**Latitude:**	43.7082
QC PEMA:	FALSE	**Longitude:**	-79.806
QC Windsor Corridr:	TRUE		

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	223920

Facility

IDM ID:	0	**Portable:**	FALSE
AB Approval ID:	0	**NAICS Primary:**	325510
GHGRP ID:	0	**NAICS Secondary:**	0
ON GHGRP ID:	0	**NAICS Tertiary:**	0
Facility Name:			
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1B1
Prov:	

Primary NAICS Details

Key Indus Sectr ID:	3	***Start Date:***	1993
NAICS Code:	325510	***End Date:***	2001
Record Year:	1997		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID:	3	***Start Date:***	2002
NAICS Code:	325510	***End Date:***	2006
Record Year:	2002		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID:	3	***Start Date:***	2012
NAICS Code:	325510	***End Date:***	2016
Record Year:	2012		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID:	3	***Start Date:***	2017
NAICS Code:	325510	***End Date:***	2021

Record Year: 2017
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and coating manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID: 3
NAICS Code: 325510
Record Year: 2022
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and coating manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements
Start Date: 2022
End Date: 2026

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID: 3
NAICS Code: 325510
Record Year: 2007
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and Coating Manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements
Start Date: 2007
End Date: 2011

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NPRI Report

Report ID: 279941
Report Year: 2001
Company ID: 99991
SWR Report ID: 20010000002703
Repor Type ID: 1
No of Employees: 21
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corresp Lang ID: 0

New Reporter:	FALSE	***Submit Date:***	2002-06-03 00:00:00.0000000

Company

DUNS No:	0
Company Name:	The Sherwin-Williams Company
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	4106288051
First Name:	Derrick	***Extension:***	0
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	senior environmental specialis		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	2165662182
First Name:	Scott	***Extension:***	0
Last Name:	Thomas	***Fax:***	2165662730
Company Name:			
Description En:			
Description Fr:			
Position:	Director, Environmental Affair		
Language:	0		
Email:			

NPRI Report

Report ID:	194539	***No of Employees:***	21

Report Year:	2000	**Is Compressor:**	
Company ID:	139367	**Is NPRI Part 4:**	
SWR Report ID:	20000000002703	**Is Battery:**	
Repor Type ID:	1	**Corresp Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2001-06-01 00:00:00.0000000

Company

DUNS No:	004206397
Company Name:	Sherwin-Williams Company
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Wally	**Extension:**	0
Last Name:	Debling	**Fax:**	9058403010
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	2165662182
First Name:	Scott	**Extension:**	0
Last Name:	Thomas	**Fax:**	2162638602
Company Name:			
Description En:			
Description Fr:			
Position:	Director, Environmental Affair		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058460740
First Name:	Wally	**Extension:**	0
Last Name:	Debling	**Fax:**	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	283700	**No of Employees:**	21
Report Year:	1999	**Is Compressor:**	
Company ID:	145794	**Is NPRI Part 4:**	
SWR Report ID:	19990000002703	**Is Battery:**	
Repor Type ID:	1	**Corresp Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2000-06-01 00:00:00.0000000

Company

DUNS No: 420636397
Company Name: Sherwin-Williams Company
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Faye
Last Name: Menhart
Company Name:
Description En:
Description Fr:
Position: Director, Human Resources
Language: 0
Email:
Phone: 0
Extension: 0
Fax: 0

NPRI Report Contact

Contact Type:
First Name: Wally
Last Name: Debling
Company Name:
Description En:
Description Fr:
Position: Store Manager
Language: 0
Email:
Phone: 9058460740
Extension: 0
Fax: 9058403010

NPRI Report Contact

Contact Type: NPRI
First Name: Wally
Last Name: Debling
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Store Manager
Language: 0
Email:
Phone: 9058460740
Extension: 0
Fax: 9058403010

NPRI Report

Report ID: 176297
Report Year: 1998
Company ID: 102411
SWR Report ID: 19980000002703
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 21
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corresp Lang ID: 0
Submit Date: 1999-06-01 00:00:00.0000000

Company

DUNS No: 0
Company Name: Sherwin-Williams Company
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	Steve	***Extension:***	0
Last Name:	Shawver	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Director Store Operations		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	182308	***No of Employees:***	21
Report Year:	1997	***Is Compressor:***	
Company ID:	102411	***Is NPRI Part 4:***	
SWR Report ID:	19970000002703	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	1998-06-01 00:00:00.0000000

Company

DUNS No:	0
Company Name:	Sherwin-Williams Company
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	Steve	***Extension:***	0
Last Name:	Shawver	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Director Store Operations		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	851	***No of Employees:***	22
Report Year:	1996	***Is Compressor:***	
Company ID:	102411	***Is NPRI Part 4:***	
SWR Report ID:	19960000002703	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	1997-06-02 00:00:00.0000000

Company

DUNS No:	0
Company Name:	Sherwin-Williams Company
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report

Report ID:	3408	***No of Employees:***	22
Report Year:	1995	***Is Compressor:***	
Company ID:	99991	***Is NPRI Part 4:***	
SWR Report ID:	19950000002703	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	1996-06-03 00:00:00.0000000

Company

DUNS No:	0
Company Name:	The Sherwin-Williams Company
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report

Report ID:	4523	**No of Employees:**	22
Report Year:	1994	**Is Compressor:**	
Company ID:	100308	**Is NPRI Part 4:**	
SWR Report ID:	19940000002703	**Is Battery:**	
Repor Type ID:	1	**Corresp Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1995-06-01 00:00:00.0000000

Company

DUNS No:	0
Company Name:	THE SHERWIN WILLIAMS CO
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report

Report ID:	6131	**No of Employees:**	0
Report Year:	1993	**Is Compressor:**	
Company ID:	99991	**Is NPRI Part 4:**	
SWR Report ID:	19930000002703	**Is Battery:**	
Repor Type ID:	1	**Corresp Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1994-06-01 00:00:00.0000000

Company

DUNS No:	0
Company Name:	The Sherwin-Williams Company
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	284152

Facility

IDM ID:	10695	**Portable:**	FALSE
AB Approval ID:	0	**NAICS Primary:**	418410
GHGRP ID:	0	**NAICS Secondary:**	0
ON GHGRP ID:	0	**NAICS Tertiary:**	0
Facility Name:	Brampton		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1B1
Prov:	

Address Geographic

Datum:	1983	**UTM Zone:**	0
Latitude:	43.7082	**UTM Easting:**	0.000000
Longitude:	-79.806	**UTM Northing:**	0.000000

Land Survey:
Topograph:
Additional Info:

Primary NAICS Details

Key Indus Sectr ID:	19	***Start Date:***	1993
NAICS Code:	418410	***End Date:***	2001
Record Year:	1997		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues, sauf les produits chimiques agricoles		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	***Start Date:***	2002
NAICS Code:	418410	***End Date:***	2006
Record Year:	2002		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	***Start Date:***	2007
NAICS Code:	418410	***End Date:***	2011
Record Year:	2007		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	***Start Date:***	2012
NAICS Code:	418410	***End Date:***	2016
Record Year:	2012		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	***Start Date:***	2017
NAICS Code:	418410	***End Date:***	2021
Record Year:	2017		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	***Start Date:***	2022
NAICS Code:	418410	***End Date:***	2026
Record Year:	2022		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NPRI Report

Report ID:	67669	***No of Employees:***	16
Report Year:	2019	***Is Compressor:***	

Company ID:	112753	***Is NPRI Part 4:***	
SWR Report ID:	161178	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2020-05-21 11:23:15.5570000

Company

DUNS No:	0
Company Name:	Sherwin-Williams Canada
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report

Report ID:	95917	***No of Employees:***	18
Report Year:	2018	***Is Compressor:***	
Company ID:	110705	***Is NPRI Part 4:***	
SWR Report ID:	145060	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2019-05-24 09:02:03.1900000

Company

DUNS No:	0

Company Name: Sherwin-Williams Canada
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report

Report ID:	95916	***No of Employees:***	15
Report Year:	2017	***Is Compressor:***	
Company ID:	110705	***Is NPRI Part 4:***	
SWR Report ID:	95096	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2018-05-16 09:52:30.7333333

Company

DUNS No: 0
Company Name: Sherwin-Williams Canada
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:		***Phone:***	2165661130

First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report

Report ID:	95915	***No of Employees:***	15
Report Year:	2016	***Is Compressor:***	
Company ID:	110705	***Is NPRI Part 4:***	
SWR Report ID:	83782	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2017-05-25 11:56:33.1100000

Company

DUNS No:	0
Company Name:	Sherwin-Williams Canada
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report

Report ID:	24377	***No of Employees:***	15
Report Year:	2015	***Is Compressor:***	
Company ID:	110705	***Is NPRI Part 4:***	
SWR Report ID:	71207	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2016-05-20 00:00:00.0000000

Company

DUNS No:	0
Company Name:	Sherwin-Williams Canada
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		

Position: Facility Manager
Language: 1
Email: Michael.S.Allen@sherwin.com

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Allen
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: Michael.S.Allen@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Soltes
Company Name:
Description En:
Description Fr:
Position: Environmental Project Manager
Language: 1
Email: mjsoltes@sherwin.com
Phone: 2165661130
Extension:
Fax: 2162638624

NPRI Report

Report ID: 33930
Report Year: 2014
Company ID: 110705
SWR Report ID: 49456
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 15
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corresp Lang ID: 1
Submit Date: 2015-05-27 00:00:00.0000000

Company

DUNS No: 0
Company Name: Sherwin-Williams Canada
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Melba
Last Name: Hibbard
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: melba.hibbard@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report Contact

Contact Type: NPRI
First Name: Melba
Phone: 9058460740
Extension:

Last Name:	Hibbard	**Fax:**	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Melba	**Extension:**	
Last Name:	Hibbard	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:		**Phone:**	2165661130
First Name:	Michael	**Extension:**	
Last Name:	Soltes	**Fax:**	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report

Report ID:	42705	**No of Employees:**	15
Report Year:	2013	**Is Compressor:**	
Company ID:	110705	**Is NPRI Part 4:**	
SWR Report ID:	29508	**Is Battery:**	
Repor Type ID:	1	**Corresp Lang ID:**	1
New Reporter:	FALSE	**Submit Date:**	2014-05-28 00:00:00.0000000

Company

DUNS No:	0
Company Name:	Sherwin-Williams Canada
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Melba	**Extension:**	
Last Name:	Hibbard	**Fax:**	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	2165661130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Manager		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Facility Manager		
Language:	1		
Email:	melba.hibbard@sherwin.com		

NPRI Report

Report ID:	51972	***No of Employees:***	14
Report Year:	2012	***Is Compressor:***	
Company ID:	112753	***Is NPRI Part 4:***	
SWR Report ID:	14511	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2013-05-22 00:00:00.0000000

Company

DUNS No:	0
Company Name:	Sherwin-Williams Canada
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		

Language: 1
Email: melba.hibbard@sherwin.com

NPRI Report Contact

Contact Type: | ***Phone:*** 9058460740
First Name: Melba | ***Extension:***
Last Name: Hibbard | ***Fax:***
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: melba.hibbard@sherwin.com

NPRI Report Contact

Contact Type: | ***Phone:*** 2165661130
First Name: Michael | ***Extension:***
Last Name: Soltes | ***Fax:*** 2162638624
Company Name:
Description En:
Description Fr:
Position: Environmental Project Manager
Language: 1
Email: mjsoltes@sherwin.com

NPRI Report Contact

Contact Type: NPRI | ***Phone:*** 9058460740
First Name: Melba | ***Extension:***
Last Name: Hibbard | ***Fax:***
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Facility Manager
Language: 1
Email: melba.hibbard@sherwin.com

NPRI Report

Report ID: 61347 | ***No of Employees:*** 14
Report Year: 2011 | ***Is Compressor:***
Company ID: 112753 | ***Is NPRI Part 4:***
SWR Report ID: 2172 | ***Is Battery:***
Repor Type ID: 1 | ***Corresp Lang ID:*** 1
New Reporter: FALSE | ***Submit Date:*** 2012-06-27 00:00:00.0000000

Company

DUNS No: 0
Company Name: Sherwin-Williams Canada
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type: | ***Phone:*** 9058460740
First Name: Melba | ***Extension:***
Last Name: Hibbard | ***Fax:***

Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: melba.hibbard@sherwin.com

NPRI Report Contact

Contact Type: NPRI
First Name: Melba
Last Name: Hibbard
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Facility Manager
Language: 1
Email: melba.hibbard@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Melba
Last Name: Hibbard
Company Name:
Description En:
Description Fr:
Position: Facility Manager
Language: 1
Email: melba.hibbard@sherwin.com
Phone: 9058460740
Extension:
Fax:

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Soltes
Company Name:
Description En:
Description Fr:
Position: Environmental Project Manager
Language: 1
Email: mjsoltes@sherwin.com
Phone: 2165661130
Extension:
Fax: 2162638624

NPRI Report Contact

Contact Type:
First Name: Michael
Last Name: Soltes
Company Name:
Description En:
Description Fr:
Position: Environmental Project Manager
Language: 1
Email: mjsoltes@sherwin.com
Phone: 2165661130
Extension:
Fax: 2162638624

NPRI Report

Report ID: 153681
Report Year: 2010
Company ID: 112753
SWR Report ID: 20100000002703
Repor Type ID: 1
No of Employees: 12
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corresp Lang ID: 0

New Reporter:	FALSE	***Submit Date:***	2011-06-14 00:00:00.0000000

Company

DUNS No:	0
Company Name:	Sherwin-Williams Canada
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	Report Submission and Electronic Certification Comment
Description Fr:	Soumission de déclaration et attestation électronique
Comment:	Thanks!
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:			
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:			
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Facility Manager		
Language:	0		
Email:	melba.hibbard@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Melba	***Extension:***	
Last Name:	Hibbard	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		

Position: Facility Manager
Language: 0
Email: melba.hibbard@sherwin.com

NPRI Report

Report ID: 151715
Report Year: 2009
Company ID: 132437
SWR Report ID: 20090000002703
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 15
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corresp Lang ID: 0
Submit Date: 2010-05-27 00:00:00.0000000

Company

DUNS No: 0
Company Name: SHERWIN-WILLIAMS CANADA
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Comment

Description En: Report Submission and Electronic Certification Comment
Description Fr: Soumission de déclaration et attestation électronique
Comment: Thanks!
Note:

NPRI Report Contact

Contact Type: NPRI
First Name: Darren
Last Name: Armstrong
Company Name:
Phone: 9058460740
Extension:
Fax: 9058403010
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Plant Manager
Language: 0
Email: darren.armstrong@sherwin.com

NPRI Report Contact

Contact Type:
First Name: Darren
Last Name: Armstrong
Company Name:
Description En:
Description Fr:
Phone: 9058460740
Extension:
Fax: 9058402301
Position: Plant Manager
Language: 0
Email: darren.armstrong@sherwin.com

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Company Name:
Description En:
Description Fr:
Phone: 4106258051
Extension:
Fax: 2162638609
Position: Senior Environmental Specialist

Language: 0
Email: deboom@sherwin.com

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Company Name:
Description En:
Description Fr:
Position: Environmental Specialist
Language: 0
Email: deboom@sherwin.com
Phone: 4106258051
Extension:
Fax: 2162638609

NPRI Report

Report ID: 153632
Report Year: 2008
Company ID: 132437
SWR Report ID: 20080000002703
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 13
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corresp Lang ID: 0
Submit Date: 2009-05-27 00:00:00.0000000

Company

DUNS No: 0
Company Name: SHERWIN-WILLIAMS CANADA
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type: NPRI
First Name: Darren
Last Name: Armstrong
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension:
Fax: 9058403010

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Company Name:
Description En:
Description Fr:
Position: Senior Environmental Specialist
Language: 0
Email: deboom@sherwin.com
Phone: 4106258051
Extension:
Fax: 2162638609

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Phone: 4106258051
Extension:
Fax: 2162638609

Company Name:
Description En:
Description Fr:
Position: Environmental Specialist
Language: 0
Email: deboom@sherwin.com

NPRI Report Contact

Contact Type:
First Name: Darren
Last Name: Armstrong
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension:
Fax: 9058402301

NPRI Report

Report ID: 153789
Report Year: 2007
Company ID: 132437
SWR Report ID: 20070000002703
Repor Type ID: 1
New Reporter: TRUE
No of Employees: 21
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corresp Lang ID: 0
Submit Date: 2008-05-29 00:00:00.0000000

Company

DUNS No: 0
Company Name: SHERWIN-WILLIAMS CANADA
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Darren
Last Name: Armstrong
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension:
Fax: 9058402301

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Company Name:
Description En:
Description Fr:
Position: Environmental Specialist
Language: 0
Email: deboom@sherwin.com
Phone: 4106258051
Extension:
Fax: 2162638609

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Darren	***Extension:***	
Last Name:	Armstrong	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:			

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	341502

Facility

IDM ID:	0	***Portable:***	FALSE
AB Approval ID:	0	***NAICS Primary:***	325510
GHGRP ID:	0	***NAICS Secondary:***	0
ON GHGRP ID:	0	***NAICS Tertiary:***	0
Facility Name:	BRAMPTON		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1B1
Prov:	

Address Geographic

Datum:	1983	***UTM Zone:***	0
Latitude:	43.7082	***UTM Easting:***	0.000000
Longitude:	-79.806	***UTM Northing:***	0.000000
Land Survey:			
Topograph:			
Additional Info:			

Primary NAICS Details

Key Indus Sectr ID:	3	***Start Date:***	1993
NAICS Code:	325510	***End Date:***	2001
Record Year:	1997		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		

NAICS Title En: Paint and Coating Manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID: 3 ***Start Date:*** 2012
NAICS Code: 325510 ***End Date:*** 2016
Record Year: 2012
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and coating manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID: 3 ***Start Date:*** 2017
NAICS Code: 325510 ***End Date:*** 2021
Record Year: 2017
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and coating manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID: 3 ***Start Date:*** 2022
NAICS Code: 325510 ***End Date:*** 2026
Record Year: 2022
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and coating manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and

manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID:	3	***Start Date:***	2002
NAICS Code:	325510	***End Date:***	2006
Record Year:	2002		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID:	3	***Start Date:***	2007
NAICS Code:	325510	***End Date:***	2011
Record Year:	2007		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NPRI Report

Report ID:	152278	***No of Employees:***	21
Report Year:	2006	***Is Compressor:***	
Company ID:	132437	***Is NPRI Part 4:***	
SWR Report ID:	20060000002703	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2007-05-23 00:00:00.0000000

Company

DUNS No:	0
Company Name:	SHERWIN-WILLIAMS CANADA
Trade Name En:	
Trade Name Fr:	

Website:

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Darren	***Extension:***	
Last Name:	Armstrong	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Senior Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Darren	***Extension:***	
Last Name:	Armstrong	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	254719	***No of Employees:***	21
Report Year:	2005	***Is Compressor:***	
Company ID:	142649	***Is NPRI Part 4:***	
SWR Report ID:	20050000002703	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2006-05-23 00:00:00.0000000

Company

DUNS No: 0
Company Name: THE SHERWIN-WILLIAMS
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Darren
Last Name: Armstrong
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension: 0
Fax: 9058402301

NPRI Report Contact

Contact Type: NPRI
First Name: Darren
Last Name: Armstrong
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension: 0
Fax: 9058403010

NPRI Report Contact

Contact Type:
First Name: Darren
Last Name: Armstrong
Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 0
Email:
Phone: 9058460740
Extension: 0
Fax: 0

NPRI Report Contact

Contact Type:
First Name: Derrick
Last Name: Boom
Company Name:
Description En:
Description Fr:
Position: Environmental Specialist
Language: 0
Email: deboom@sherwin.com
Phone: 4106258051
Extension: 0
Fax: 2162638609

NPRI Report

Report ID: 166700
Report Year: 2004
Company ID: 132437
SWR Report ID: 20040000002703
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 21
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corresp Lang ID: 0
Submit Date: 2005-05-20 00:00:00.0000000

Company

DUNS No:	0
Company Name:	SHERWIN-WILLIAMS CANADA
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	Report Submission and Electronic Certification Comment
Description Fr:	Soumission de déclaration et attestation électronique
Comment:	Thank You!
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	0
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Mike	***Extension:***	0
Last Name:	Vanduyse	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Mike	***Extension:***	0
Last Name:	Vanduyse	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Mike	***Extension:***	0
Last Name:	Vanduyse	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		

Language: 0
Email:

NPRI Report

Report ID:	271150	***No of Employees:***	21
Report Year:	2003	***Is Compressor:***	
Company ID:	140244	***Is NPRI Part 4:***	
SWR Report ID:	20030000002703	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2004-06-01 00:00:00.0000000

Company

DUNS No: 0
Company Name: THE SHERWIN-WILLIAMS COMPANY, BRAMPTON
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Andrew	***Extension:***	0
Last Name:	Hoskins	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	0
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Andrew	***Extension:***	0
Last Name:	Hoskins	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Plant Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Andrew	***Extension:***	0
Last Name:	Hoskins	***Fax:***	0

Company Name:
Description En:
Description Fr:
Position: Plant Manager
Language: 0
Email:

NPRI ID Facility ID

NPRI ID: 2703
Facility ID: 432250

Facility

IDM ID: 10695
AB Approval ID:
GHGRP ID:
ON GHGRP ID:
Facility Name: Brampton
Website:
Portable: FALSE
NAICS Primary: 418410
NAICS Secondary: 0
NAICS Tertiary: 0

Address

Address1:
Address2:
City: Brampton
Postal Zip: L7A 1B1
Prov:

Address Geographic

Datum: 1983
Latitude: 43.708200
Longitude: -79.806000
Land Survey:
Topograph:
Additional Info:
UTM Zone: 0
UTM Easting: 0.000000
UTM Northing: 0.000000

Primary NAICS Details

Key Indus Sectr ID: 19
NAICS Code: 418410
Record Year: 1997
Start Date: 1993
End Date: 2001
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues, sauf les produits chimiques agricoles

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19
NAICS Code: 418410
Start Date: 2002
End Date: 2006

Record Year: 2002
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2007
NAICS Code: 418410 ***End Date:*** 2011
Record Year: 2007
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2012
NAICS Code: 418410 ***End Date:*** 2016
Record Year: 2012
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2017
NAICS Code: 418410 ***End Date:*** 2021
Record Year: 2017
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	***Start Date:***	2022
NAICS Code:	418410	***End Date:***	2026
Record Year:	2022		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NPRI Report

Report ID:	326187	***No of Employees:***	18
Report Year:	2021	***Is Compressor:***	
Company ID:	174954	***Is NPRI Part 4:***	
SWR Report ID:	11685	***Is Battery:***	
Repor Type ID:	8	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2022-05-24 15:20:15.9879236

Company

DUNS No:	
Company Name:	Sherwin-Williams Canada Inc
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	216-566-1130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Mgr		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Regional Facilities Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Regional Facilities Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	444369

Facility

IDM ID:	10695	***Portable:***	FALSE
AB Approval ID:	0	***NAICS Primary:***	418410
GHGRP ID:	0	***NAICS Secondary:***	
ON GHGRP ID:		***NAICS Tertiary:***	
Facility Name:	Brampton		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	Brampton
Postal Zip:	L7A 1B1
Prov:	

Address Geographic

Datum:	1983	***UTM Zone:***	0
Latitude:	43.708200	***UTM Easting:***	0.000000
Longitude:	-79.806000	***UTM Northing:***	0.000000
Land Survey:			
Topograph:			
Additional Info:			

Primary NAICS Details

Key Indus Sectr ID:	19	***Start Date:***	1993
NAICS Code:	418410	***End Date:***	2001
Record Year:	1997		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		

NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues, sauf les produits chimiques agricoles

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2002
NAICS Code: 418410 ***End Date:*** 2006
Record Year: 2002
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2007
NAICS Code: 418410 ***End Date:*** 2011
Record Year: 2007
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
NAICS Title Fr: Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2012
NAICS Code: 418410 ***End Date:*** 2016
Record Year: 2012
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	***Start Date:***	2017
NAICS Code:	418410	***End Date:***	2021
Record Year:	2017		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	***Start Date:***	2022
NAICS Code:	418410	***End Date:***	2026
Record Year:	2022		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except agricultural) and allied product merchant wholesalers		
NAICS Title Fr:	Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NPRI Report

Report ID:	338323	***No of Employees:***	24
Report Year:	2022	***Is Compressor:***	
Company ID:	178494	***Is NPRI Part 4:***	
SWR Report ID:	26635	***Is Battery:***	
Repor Type ID:	8	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2023-05-19 08:13:31.9547407

Company

DUNS No:	
Company Name:	Sherwin-Williams Canada Inc
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	216-566-1130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	2162638624
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Project Mgr		
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:	Regional Facilities Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Regional Facilities Manager		
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	417952

Facility

IDM ID:	10695	***Portable:***	FALSE
AB Approval ID:	0	***NAICS Primary:***	418410
GHGRP ID:	0	***NAICS Secondary:***	0
ON GHGRP ID:		***NAICS Tertiary:***	0
Facility Name:	Brampton		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A 1B1
Prov:	

Address Geographic

Datum:	1983	**UTM Zone:**	0
Latitude:	43.70820	**UTM Easting:**	0.000000
Longitude:	-79.80600	**UTM Northing:**	0.000000
Land Survey:			
Topograph:			
Additional Info:			

Primary NAICS Details

Key Indus Sectr ID:	19	**Start Date:**	1993
NAICS Code:	418410	**End Date:**	2001
Record Year:	1997		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues, sauf les produits chimiques agricoles		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	**Start Date:**	2002
NAICS Code:	418410	**End Date:**	2006
Record Year:	2002		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID:	19	**Start Date:**	2007
NAICS Code:	418410	**End Date:**	2011
Record Year:	2007		
Key Indus Sector En:	Other (Except Manufacturing)		
Key Indus Sector Fr:	Autres (sauf fabrication)		
NAICS Title En:	Chemical (except Agricultural) and Allied Product Wholesaler-Distributors		
NAICS Title Fr:	Grossistes-distributeurs de produits chimiques et de produits analogues (sauf agricoles)		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2012
NAICS Code: 418410 ***End Date:*** 2016
Record Year: 2012
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2017
NAICS Code: 418410 ***End Date:*** 2021
Record Year: 2017
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

Key Indus Sectr ID: 19 ***Start Date:*** 2022
NAICS Code: 418410 ***End Date:*** 2026
Record Year: 2022
Key Indus Sector En: Other (Except Manufacturing)
Key Indus Sector Fr: Autres (sauf fabrication)
NAICS Title En: Chemical (except agricultural) and allied product merchant wholesalers
NAICS Title Fr: Grossistes-marchands de produits chimiques et de produits analogues (sauf agricoles)

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in wholesaling industrial and household chemicals, cleaning compounds and preparations, plastics resins, plastic basic forms and shapes, and industrial gases.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à vendre en gros des produits chimiques, des produits et préparations de nettoyage, des résines plastiques, des formes primaires en plastique à usage industriel ou domestique, et des gaz industriels.

NPRI Report

Report ID:	313030	***No of Employees:***	18
Report Year:	2020	***Is Compressor:***	
Company ID:	171358	***Is NPRI Part 4:***	
SWR Report ID:	1243	***Is Battery:***	
Repor Type ID:	8	***Corresp Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2021-09-03 10:59:04.5469055

Company

DUNS No:	0
Company Name:	Sherwin-Williams Canada Inc
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:			
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	216-566-1130
First Name:	Michael	***Extension:***	
Last Name:	Soltes	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:			
Language:	1		
Email:	mjsoltes@sherwin.com		

NPRI Report Contact

Contact Type:		***Phone:***	905-846-0740
First Name:	Michael	***Extension:***	
Last Name:	Allen	***Fax:***	
Company Name:			
Description En:			
Description Fr:			
Position:			
Language:	1		
Email:	Michael.S.Allen@sherwin.com		

NPRI ID Facility ID

NPRI ID:	2703
Facility ID:	368431

Facility

IDM ID:	0	***Portable:***	FALSE

AB Approval ID:	0	***NAICS Primary:***	325510
GHGRP ID:	0	***NAICS Secondary:***	0
ON GHGRP ID:	0	***NAICS Tertiary:***	0
Facility Name:	BRAMPTON		
Website:			

Address

Address1:	130 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1B1
Prov:	

Primary NAICS Details

Key Indus Sectr ID:	3	***Start Date:***	1993
NAICS Code:	325510	***End Date:***	2001
Record Year:	1997		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and Coating Manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID:	3	***Start Date:***	2012
NAICS Code:	325510	***End Date:***	2016
Record Year:	2012		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID:	3	***Start Date:***	2017
NAICS Code:	325510	***End Date:***	2021
Record Year:	2017		
Key Indus Sector En:	Chemicals		
Key Indus Sector Fr:	Produits chimiques		
NAICS Title En:	Paint and coating manufacturing		
NAICS Title Fr:	Fabrication de peintures et de revêtements		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID: 3 ***Start Date:*** 2022
NAICS Code: 325510 ***End Date:*** 2026
Record Year: 2022
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and coating manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID: 3 ***Start Date:*** 2002
NAICS Code: 325510 ***End Date:*** 2006
Record Year: 2002
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and Coating Manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

Key Indus Sectr ID: 3 ***Start Date:*** 2007
NAICS Code: 325510 ***End Date:*** 2011
Record Year: 2007
Key Indus Sector En: Chemicals
Key Indus Sector Fr: Produits chimiques
NAICS Title En: Paint and Coating Manufacturing
NAICS Title Fr: Fabrication de peintures et de revêtements

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in mixing pigments, solvents and binders into paints, stains and other coatings; and manufacturing related products.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est le mélange de pigments, de solvants et de liants pour produire des peintures, des teintures, d'autres revêtements; de même que la fabrication de produits connexes.

NPRI Report

Report ID:	276393	***No of Employees:***	21
Report Year:	2002	***Is Compressor:***	
Company ID:	145968	***Is NPRI Part 4:***	
SWR Report ID:	20020000002703	***Is Battery:***	
Repor Type ID:	1	***Corresp Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2003-06-02 00:00:00.0000000

Company

DUNS No:	0
Company Name:	THE SHERWIN-WILLIAMS COMPANY, BRAMPTON
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058402301
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	4106258051
First Name:	Derrick	***Extension:***	0
Last Name:	Boom	***Fax:***	2162638609
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Specialist		
Language:	0		
Email:	deboom@sherwin.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058460740
First Name:	Wally	***Extension:***	0
Last Name:	Debling	***Fax:***	9058403010
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Store Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9058460740
First Name:	Wally	**Extension:**	0
Last Name:	Debling	**Fax:**	0
Company Name:			
Description En:			
Description Fr:			
Position:	Store Manager		
Language:	0		
Email:			

82 **1 of 1** **SE/168.0** **235.9 / -6.08** **SOUTH END RAIL SIDE DRIVE**
Brampton ON **WWIS**

Well ID:	7205572	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	07/31/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z175392	**Contractor:**	9999
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1004473532	**Tag No:**	
Depth M:	7.6	**Contractor:**	9999
Year Completed:	2013	**Latitude:**	43.7094372150535
Well Completed Dt:	06/25/2013	**Longitude:**	-79.8009624637991
Audit No:	Z175392	**Y:**	43.709437213143104
Path:		**X:**	-79.80096231417339

Bore Hole Information

Bore Hole ID:	1004473532	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596600.00
Code OB Desc:		**North83:**	4840300.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	06/25/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004889239
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.30000001192092896
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004889241
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	34
Material 3 Desc:	TILL
Formation Top Depth:	0.699999988079071
Formation End Depth:	1.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004889240
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	02
Material 2 Desc:	TOPSOIL
Material 3:	05
Material 3 Desc:	CLAY
Formation Top Depth:	0.30000001192092896
Formation End Depth:	0.699999988079071
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004889242
Layer:	4
Color:	6
General Color:	BROWN
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	15
Material 2 Desc:	LIMESTONE
Material 3:	26

Material 3 Desc: ROCK
Formation Top Depth: 1.5
Formation End Depth: 7.599999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004889249
Layer: 1
Plug From: 0.0
Plug To: 7.599999904632568
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004889248
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1004889238
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004889245
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 7.599999904632568
Casing Diameter: 2.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004889246
Layer: 1
Slot:
Screen Top Depth: 4.599999904632568
Screen End Depth: 7.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 2.0

Water Details

Water ID: 1004889244
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID:	1004889243
Diameter:	5.0
Depth From:	0.0
Depth To:	7.599999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

83 ***1 of 3*** ***WNW/26.7*** ***251.8 / 9.90*** ***Great-L Developments Inc.*** ***ECA***

Brampton ON M2K 2S5

Approval No:	8636-4QVTLF	***MOE District:***	Halton-Peel
Approval Date:	2000-12-08	***City:***	
Status:	Approved	***Longitude:***	-79.8274
Record Type:	ECA	***Latitude:***	43.726800000000004
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Credit Valley	***Geometry Y:***	
Approval Type:	ECA-Municipal and Private Water Works		
Project Type:	Municipal and Private Water Works		
Business Name:	Great-L Developments Inc.		
Address:			
Full Address:			
Full PDF Link:			
PDF Site Location:			

---

83 ***2 of 3*** ***WNW/26.7*** ***251.8 / 9.90*** ***Partacc West Developments Inc.*** ***ECA***

Brampton ON L3R 9R9

Approval No:	9203-6ZNJSB	***MOE District:***	Halton-Peel
Approval Date:	2007-04-10	***City:***	
Status:	Approved	***Longitude:***	-79.8274
Record Type:	ECA	***Latitude:***	43.726800000000004
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Credit Valley	***Geometry Y:***	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Business Name:	Partacc West Developments Inc.		
Address:			
Full Address:			
Full PDF Link:			
PDF Site Location:			

---

83 ***3 of 3*** ***WNW/26.7*** ***251.8 / 9.90*** ***Partacc West Developments Inc.*** ***ECA***

Brampton ON M3R 9R9

Approval No:	1598-6ZNHZL	***MOE District:***	Halton-Peel
Approval Date:	2007-04-10	***City:***	
Status:	Approved	***Longitude:***	-79.8274
Record Type:	ECA	***Latitude:***	43.7268
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Credit Valley	***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Partacc West Developments Inc.		
Address:			
Full Address:			

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3399-6ZJR72-14.pdf
PDF Site Location:

84	1 of 7	SSE/111.8	236.2 / -5.73	***Region Of Peel*** ***420 Railside Drive*** ***Brampton ON L7A 1L1***	GEN

Generator Info

Generator No:	ON4748407	***Choice of Contact:***	CO_ADMIN
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	Yes
PO Box No:		***SIC Code:***	562112
Country:	Canada		
Co Admin:	Matthew Stevens		
Phone No Admin:	416-807-4125 Ext.		
SIC Description:	562112		

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
84	2 of 7	SSE/111.8	236.2 / -5.73	**Region Of Peel** **420 Railside Drive** **Brampton ON L7A 1L1**	GEN

Generator Info

Generator No: ON4748407
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Matthew Stevens
Phone No Admin: 416-807-4125 Ext.

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: Yes
SIC Code: 562112

SIC Description: 562112

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

84 | ***3 of 7*** | ***SSE/111.8*** | ***236.2 / -5.73*** | ***Region Of Peel***
420 Railside Drive
Brampton ON L7A 1L1 | ***GEN***

Generator Info

Generator No: ON4748407
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Matthew Stevens
Phone No Admin: 416-807-4125 Ext.
SIC Description: 562112

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: Yes
SIC Code: 562112

Waste Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

---

84 | **4 of 7** | **SSE/111.8** | **236.2 / -5.73** | **Region Of Peel**
420 Railside Drive
Brampton ON L7A 1L1 | **GEN**

Generator Info

Generator No:	ON4748407	**Choice of Contact:**	
Approval Years:	As of Dec 2018	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 147 T
Waste Class Name: Chemical fertilizer wastes

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

84	5 of 7	SSE/111.8	236.2 / -5.73	**Region Of Peel** **420 Railside Drive** **Brampton ON L7A 1L1**	GEN

Generator Info

Generator No:	ON4748407	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	148 T
Waste Class Name:	Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders

Waste Detail(s)

Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class:	147 T
Waste Class Name:	Chemical fertilizer wastes

Waste Detail(s)

Waste Class:	150 L
Waste Class Name:	Inert organic wastes

Waste Detail(s)

Waste Class:	263 A
Waste Class Name:	Misc. waste organic chemicals

Waste Detail(s)

Waste Class:	242 A
Waste Class Name:	Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class:	148 C
Waste Class Name:	Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

84	***6 of 7***	***SSE/111.8***	***236.2 / -5.73***	***Region Of Peel*** ***420 Railside Drive*** ***Brampton ON L7A 1L1***	***GEN***

Generator Info

Generator No:	ON4748407	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		

Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 147 T
Waste Class Name: Chemical fertilizer wastes

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

---

84 | ***7 of 7*** | ***SSE/111.8*** | ***236.2 / -5.73*** | ***Regional Municipality of Peel***
420 Railside Drive
Brampton ON | ***GEN***

Generator Info

Generator No: ON4748407
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 148 T

Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 147 T
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 263 A
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 242 A
Waste Class Name: HALOGENATED PESTICIDES

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: INERT INORGANIC WASTES

Waste Detail(s)

Waste Class: 121 C
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 145 B
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Generator Info as of Dec 2024

Generator No: ON4748407
Generator Company Name: Regional Municipality of Peel
Street: 420 Railside Drive
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A1L1
Waste Class: 252 L, 263 I, 145 B, 243 D, 121 C, 122 C, 145 I, 147 I, 112 C, 148 I, 221 I, 145 L, 251 L, 312 P, 212 L, 331 I, 147 T, 213 I, 261 A, 242 A, 263 A, 148 T, 148 C, 150 L

Waste Class Decoded:

252 - WASTE OILS & LUBRICANTS; 263 - ORGANIC LABORATORY CHEMICALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 243 - PCBS; 121 - ALKALINE WASTES - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 147 - CHEMICAL FERTILIZER WASTES; 112 - ACID WASTE - HEAVY METALS; 148 - INORGANIC LABORATORY CHEMICALS; 221 - LIGHT FUELS; 145 - PAINT/PIGMENT/COATING RESIDUES; 251 - OIL SKIMMINGS & SLUDGES; 312 - PATHOLOGICAL WASTES; 212 - ALIPHATIC SOLVENTS; 331 - WASTE COMPRESSED GASES; 147 - CHEMICAL FERTILIZER WASTES; 213 - PETROLEUM DISTILLATES; 261 - PHARMACEUTICALS; 242 - HALOGENATED PESTICIDES; 263 - ORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 150 - INERT INORGANIC WASTES

Generator Info as of Dec 2024

Generator No: ON4748407
Generator Company Name: Regional Municipality of Peel
Street: 420 Railside Drive

City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A1L1
Waste Class:	263 I,252 L,145 I,145 B,147 I,121 C,122 C,148 I,145 L,112 C,243 D,221 I,251 L,312 P,212 L,331 I,147 T,213 I,261 A,242 A,263 A,148 T,148 C,150 L

Waste Class Decoded:

263 - ORGANIC LABORATORY CHEMICALS; 252 - WASTE OILS & LUBRICANTS; 145 - PAINT/PIGMENT/COATING RESIDUES; 145 - PAINT/PIGMENT/COATING RESIDUES; 147 - CHEMICAL FERTILIZER WASTES; 121 - ALKALINE WASTES - HEAVY METALS; 122 - ALKALINE WASTES - OTHER METALS; 148 - INORGANIC LABORATORY CHEMICALS; 145 - PAINT/PIGMENT/COATING RESIDUES; 112 - ACID WASTE - HEAVY METALS; 243 - PCBS; 221 - LIGHT FUELS; 251 - OIL SKIMMINGS & SLUDGES; 312 - PATHOLOGICAL WASTES; 212 - ALIPHATIC SOLVENTS; 331 - WASTE COMPRESSED GASES; 147 - CHEMICAL FERTILIZER WASTES; 213 - PETROLEUM DISTILLATES; 261 - PHARMACEUTICALS; 242 - HALOGENATED PESTICIDES; 263 - ORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 148 - INORGANIC LABORATORY CHEMICALS; 150 - INERT INORGANIC WASTES

2017 Generator Info

Gen No:	ON4748407	***Choice of Contact:***	CO_OFFICIAL
ID:	18877	***Phone No Official:***	905-791-7800 Ext.3976
Contaminated Fac:	N	***Phone No Admin:***	905-791-7800 Ext.3441
MHSW Facility:	Y	***County Ont:***	PEEL (R. M.)
NAICS Code1:	562112	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Region Of Peel		
Gen Div:			
Gen Op Name:	Region Of Peel		
Gen Op Div:			
Site Adrs1:	420 Railside Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1L1		
Site Country:	Canada		
Co Official:	Matthew Stevens		
Co Admin:	David Bruno		

2017 Generator Manifest

ID:	42664	***Sum Received Qty:***	1000.0
Generator No:	ON4748407	***Waste Class Name:***	ACID WASTE - HEAVY METALS
Receiver Type:	035	***Count Manifests:***	10
Waste Char:	C	***District:***	201
Waste Code:	112		

2017 Generator Manifest

ID:	42673	***Sum Received Qty:***	1040.0
Generator No:	ON4748407	***Waste Class Name:***	PHARMACEUTICALS
Receiver Type:	035	***Count Manifests:***	11
Waste Char:	A	***District:***	201
Waste Code:	261		

2017 Generator Manifest

ID:	42674	***Sum Received Qty:***	30225.0
Generator No:	ON4748407	***Waste Class Name:***	ORGANIC LABORATORY CHEMICALS

Receiver Type: 035
Waste Char: A
Waste Code: 263
Count Manifests: 42
District: 201

2017 Generator Manifest

ID: 42669
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 2800.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 14
District: 201

2017 Generator Manifest

ID: 42672
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 1300.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 13
District: 201

2017 Generator Manifest

ID: 42666
Generator No: ON4748407
Receiver Type: 035
Waste Char: B
Waste Code: 145
Sum Received Qty: 100760.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 63
District: 201

2017 Generator Manifest

ID: 42671
Generator No: ON4748407
Receiver Type: 035
Waste Char: A
Waste Code: 242
Sum Received Qty: 3200.0
Waste Class Name: HALOGENATED PESTICIDES
Count Manifests: 20
District: 201

2017 Generator Manifest

ID: 42665
Generator No: ON4748407
Receiver Type: 035
Waste Char: C
Waste Code: 121
Sum Received Qty: 16100.0
Waste Class Name: ALKALINE WASTES - HEAVY METALS
Count Manifests: 67
District: 201

2017 Generator Manifest

ID: 42667
Generator No: ON4748407
Receiver Type: 035
Waste Char: T
Waste Code: 147
Sum Received Qty: 2300.0
Waste Class Name: CHEMICAL FERTILIZER WASTES
Count Manifests: 13
District: 201

2017 Generator Manifest

ID: 42670
Generator No: ON4748407
Receiver Type: 035
Waste Char: I
Waste Code: 221
Sum Received Qty: 3800.0
Waste Class Name: LIGHT FUELS
Count Manifests: 15
District: 201

2017 Generator Manifest

ID:	42675	***Sum Received Qty:***	26154.0
Generator No:	ON4748407	***Waste Class Name:***	WASTE COMPRESSED GASES
Receiver Type:	035	***Count Manifests:***	117
Waste Char:	I	***District:***	201
Waste Code:	331		

2017 Generator Manifest

ID:	42668	***Sum Received Qty:***	1300.0
Generator No:	ON4748407	***Waste Class Name:***	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	***Count Manifests:***	11
Waste Char:	T	***District:***	201
Waste Code:	148		

2017 Generator Manifest

ID:	42676	***Sum Received Qty:***	48650.0
Generator No:	ON4748407	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	10
Waste Char:	L	***District:***	305
Waste Code:	252		

2017 Generator Manifest

ID:	42677	***Sum Received Qty:***	540.5
Generator No:	ON4748407	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	6
Waste Char:	P	***District:***	305
Waste Code:	312		

2018 Generator Info

Gen No:	ON4748407	***Choice of Contact:***	CO_OFFICIAL
ID:	18951	***Phone No Official:***	905-791-7800 Ext.3976
Contaminated Fac:	N	***Phone No Admin:***	905-791-7800 Ext.3441
MHSW Facility:	Y	***County Ont:***	PEEL (R. M.)
NAICS Code1:	562112	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Region Of Peel		
Gen Div:			
Gen Op Name:	Region Of Peel		
Gen Op Div:			
Site Adrs1:	420 Railside Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1L1		
Site Country:	Canada		
Co Official:	Matthew Stevens		
Co Admin:	David Bruno		

2018 Generator Manifest

ID:	42577	***Sum Received Qty:***	3400.0
Generator No:	ON4748407	***Waste Class Name:***	LIGHT FUELS

Receiver Type: 035
Waste Char: I
Waste Code: 221
Count Manifests: 13
District: 201

2018 Generator Manifest

ID: 42580
Generator No: ON4748407
Receiver Type: 035
Waste Char: A
Waste Code: 261
Sum Received Qty: 3790.0
Waste Class Name: PHARMACEUTICALS
Count Manifests: 20
District: 201

2018 Generator Manifest

ID: 42583
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 14849.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 202

2018 Generator Manifest

ID: 42576
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 3000.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 14
District: 201

2018 Generator Manifest

ID: 42585
Generator No: ON4748407
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 687.5
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 8
District: 305

2018 Generator Manifest

ID: 42571
Generator No: ON4748407
Receiver Type: 035
Waste Char: C
Waste Code: 121
Sum Received Qty: 15662.0
Waste Class Name: ALKALINE WASTES - HEAVY METALS
Count Manifests: 74
District: 201

2018 Generator Manifest

ID: 42578
Generator No: ON4748407
Receiver Type: 035
Waste Char: A
Waste Code: 242
Sum Received Qty: 2435.0
Waste Class Name: HALOGENATED PESTICIDES
Count Manifests: 22
District: 201

2018 Generator Manifest

ID: 42587
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 31300.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 5
District: 306

2018 Generator Manifest

ID: 42570
Generator No: ON4748407
Receiver Type: 035
Waste Char: C
Waste Code: 112

Sum Received Qty: 690.0
Waste Class Name: ACID WASTE - HEAVY METALS
Count Manifests: 9
District: 201

2018 Generator Manifest

ID: 42586
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 150

Sum Received Qty: 4500.0
Waste Class Name: INERT INORGANIC WASTES
Count Manifests: 1
District: 306

2018 Generator Manifest

ID: 42573
Generator No: ON4748407
Receiver Type: 035
Waste Char: B
Waste Code: 145

Sum Received Qty: 97680.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 71
District: 201

2018 Generator Manifest

ID: 42579
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 252

Sum Received Qty: 1570.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 15
District: 201

2018 Generator Manifest

ID: 42572
Generator No: ON4748407
Receiver Type: 035
Waste Char: C
Waste Code: 122

Sum Received Qty: 375.0
Waste Class Name: ALKALINE WASTES - OTHER METALS
Count Manifests: 3
District: 201

2018 Generator Manifest

ID: 42575
Generator No: ON4748407
Receiver Type: 035
Waste Char: T
Waste Code: 148

Sum Received Qty: 1260.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 13
District: 201

2018 Generator Manifest

ID: 42581
Generator No: ON4748407
Receiver Type: 035
Waste Char: A
Waste Code: 263

Sum Received Qty: 32755.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 45
District: 201

2018 Generator Manifest

ID: 42574

Sum Received Qty: 1175.0

Generator No:	ON4748407	**Waste Class Name:**	CHEMICAL FERTILIZER WASTES
Receiver Type:	035	**Count Manifests:**	13
Waste Char:	T	**District:**	201
Waste Code:	147		

2018 Generator Manifest

ID:	42582	**Sum Received Qty:**	27921.3
Generator No:	ON4748407	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	035	**Count Manifests:**	135
Waste Char:	I	**District:**	201
Waste Code:	331		

2018 Generator Manifest

ID:	42584	**Sum Received Qty:**	55005.0
Generator No:	ON4748407	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	11
Waste Char:	L	**District:**	305
Waste Code:	252		

2019 Generator Info

Gen No:	ON4748407	**Choice of Contact:**	CO_OFFICIAL
ID:	18923	**Phone No Official:**	905-791-7800 Ext.3976
Contaminated Fac:	N	**Phone No Admin:**	905-791-7800 Ext.4641
MHSW Facility:	Y	**County Ont:**	PEEL (R. M.)
NAICS Code1:	562112	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	Region Of Peel
Gen Div:	
Gen Op Name:	Region Of Peel
Gen Op Div:	
Site Adrs1:	420 Railside Drive
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1L1
Site Country:	Canada
Co Official:	Matthew Stevens
Co Admin:	David Bruno

2019 Generator Manifest

ID:	42044	**Sum Received Qty:**	3000.0
Generator No:	ON4748407	**Waste Class Name:**	LIGHT FUELS
Receiver Type:	035	**Count Manifests:**	11
Waste Char:	I	**District:**	201
Waste Code:	221		

2019 Generator Manifest

ID:	42052	**Sum Received Qty:**	14950.0
Generator No:	ON4748407	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	7
Waste Char:	L	**District:**	301
Waste Code:	252		

2019 Generator Manifest

ID: 42055
Generator No: ON4748407
Receiver Type: 035
Waste Char: P
Waste Code: 312

Sum Received Qty: 506.0
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 6
District: 305

2019 Generator Manifest

ID: 42048
Generator No: ON4748407
Receiver Type: 035
Waste Char: A
Waste Code: 261

Sum Received Qty: 1470.0
Waste Class Name: PHARMACEUTICALS
Count Manifests: 15
District: 201

2019 Generator Manifest

ID: 42053
Generator No: ON4748407
Receiver Type: 035
Waste Char: P
Waste Code: 312

Sum Received Qty: 652.0
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 6
District: 302

2019 Generator Manifest

ID: 42040
Generator No: ON4748407
Receiver Type: 035
Waste Char: T
Waste Code: 147

Sum Received Qty: 980.0
Waste Class Name: CHEMICAL FERTILIZER WASTES
Count Manifests: 12
District: 201

2019 Generator Manifest

ID: 42049
Generator No: ON4748407
Receiver Type: 035
Waste Char: A
Waste Code: 263

Sum Received Qty: 39358.0
Waste Class Name: ORGANIC LABORATORY CHEMICALS
Count Manifests: 53
District: 201

2019 Generator Manifest

ID: 42035
Generator No: ON4748407
Receiver Type: 035
Waste Char: C
Waste Code: 112

Sum Received Qty: 715.0
Waste Class Name: ACID WASTE - HEAVY METALS
Count Manifests: 9
District: 201

2019 Generator Manifest

ID: 42041
Generator No: ON4748407
Receiver Type: 035
Waste Char: I
Waste Code: 148

Sum Received Qty: 70.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 1
District: 201

2019 Generator Manifest

ID: 42043

Sum Received Qty: 3000.0

Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 212
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 10
District: 201

2019 Generator Manifest

ID: 42050
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 312
Sum Received Qty: 400.0
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 1
District: 201

2019 Generator Manifest

ID: 42054
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 48181.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 12
District: 305

2019 Generator Manifest

ID: 42057
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 1510.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 306

2019 Generator Manifest

ID: 42039
Generator No: ON4748407
Receiver Type: 035
Waste Char: I
Waste Code: 147
Sum Received Qty: 70.0
Waste Class Name: CHEMICAL FERTILIZER WASTES
Count Manifests: 1
District: 201

2019 Generator Manifest

ID: 42042
Generator No: ON4748407
Receiver Type: 035
Waste Char: T
Waste Code: 148
Sum Received Qty: 1050.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 14
District: 201

2019 Generator Manifest

ID: 42036
Generator No: ON4748407
Receiver Type: 035
Waste Char: C
Waste Code: 121
Sum Received Qty: 14244.0
Waste Class Name: ALKALINE WASTES - HEAVY METALS
Count Manifests: 72
District: 201

2019 Generator Manifest

ID: 42038
Generator No: ON4748407
Receiver Type: 035
Waste Char: B
Waste Code: 145
Sum Received Qty: 90080.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 82
District: 201

2019 Generator Manifest

ID:	42045	***Sum Received Qty:***	2340.0
Generator No:	ON4748407	***Waste Class Name:***	HALOGENATED PESTICIDES
Receiver Type:	035	***Count Manifests:***	21
Waste Char:	A	***District:***	201
Waste Code:	242		

2019 Generator Manifest

ID:	42047	***Sum Received Qty:***	1670.0
Generator No:	ON4748407	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	15
Waste Char:	L	***District:***	201
Waste Code:	252		

2019 Generator Manifest

ID:	42051	***Sum Received Qty:***	21886.0
Generator No:	ON4748407	***Waste Class Name:***	WASTE COMPRESSED GASES
Receiver Type:	035	***Count Manifests:***	124
Waste Char:	I	***District:***	201
Waste Code:	331		

2019 Generator Manifest

ID:	42037	***Sum Received Qty:***	75.0
Generator No:	ON4748407	***Waste Class Name:***	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	C	***District:***	201
Waste Code:	122		

2019 Generator Manifest

ID:	42046	***Sum Received Qty:***	100.0
Generator No:	ON4748407	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	201
Waste Code:	251		

2019 Generator Manifest

ID:	42056	***Sum Received Qty:***	5640.0
Generator No:	ON4748407	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	306
Waste Code:	251		

2020 Generator Info

Gen No:	ON4748407	***Choice of Contact:***	CO_OFFICIAL
ID:	18621	***Phone No Official:***	905-791-7800 Ext.3976
Contaminated Fac:	N	***Phone No Admin:***	905-791-7800 Ext.4641
MHSW Facility:	Y	***County Ont:***	PEEL (R. M.)
NAICS Code1:	562112	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Region Of Peel		
Gen Div:			

Gen Op Name:	Region Of Peel
Gen Op Div:	
Site Adrs1:	420 Railside Drive
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1L1
Site Country:	Canada
Co Official:	Matthew Stevens
Co Admin:	David Bruno

2020 Generator Manifest

ID:	38879	**Sum Received Qty:**	94908.0
Generator No:	ON4748407	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	80
Waste Char:	B	**District:**	201
Waste Code:	145		

2020 Generator Manifest

ID:	38883	**Sum Received Qty:**	1260.0
Generator No:	ON4748407	**Waste Class Name:**	INORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	14
Waste Char:	T	**District:**	201
Waste Code:	148		

2020 Generator Manifest

ID:	38885	**Sum Received Qty:**	150.0
Generator No:	ON4748407	**Waste Class Name:**	LIGHT FUELS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	C	**District:**	201
Waste Code:	221		

2020 Generator Manifest

ID:	38884	**Sum Received Qty:**	1800.0
Generator No:	ON4748407	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	9
Waste Char:	L	**District:**	201
Waste Code:	212		

2020 Generator Manifest

ID:	38878	**Sum Received Qty:**	286.0
Generator No:	ON4748407	**Waste Class Name:**	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	C	**District:**	201
Waste Code:	122		

2020 Generator Manifest

ID:	38881	**Sum Received Qty:**	280.0
Generator No:	ON4748407	**Waste Class Name:**	CHEMICAL FERTILIZER WASTES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	I	**District:**	201
Waste Code:	147		

2020 Generator Manifest

ID: 38895
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 251

Sum Received Qty: 10500.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 306

2020 Generator Manifest

ID: 38876
Generator No: ON4748407
Receiver Type: 035
Waste Char: C
Waste Code: 112

Sum Received Qty: 780.0
Waste Class Name: ACID WASTE - HEAVY METALS
Count Manifests: 12
District: 201

2020 Generator Manifest

ID: 38890
Generator No: ON4748407
Receiver Type: 035
Waste Char: A
Waste Code: 261

Sum Received Qty: 1890.0
Waste Class Name: PHARMACEUTICALS
Count Manifests: 12
District: 201

2020 Generator Manifest

ID: 38887
Generator No: ON4748407
Receiver Type: 035
Waste Char: A
Waste Code: 242

Sum Received Qty: 2080.0
Waste Class Name: HALOGENATED PESTICIDES
Count Manifests: 20
District: 201

2020 Generator Manifest

ID: 38894
Generator No: ON4748407
Receiver Type: 035
Waste Char: P
Waste Code: 312

Sum Received Qty: 1502.0
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 15
District: 302

2020 Generator Manifest

ID: 38880
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 145

Sum Received Qty: 1920.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 201

2020 Generator Manifest

ID: 38886
Generator No: ON4748407
Receiver Type: 035
Waste Char: I
Waste Code: 221

Sum Received Qty: 2600.0
Waste Class Name: LIGHT FUELS
Count Manifests: 10
District: 201

2020 Generator Manifest

ID:	38888	**Sum Received Qty:**	100.0
Generator No:	ON4748407	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	I	**District:**	201
Waste Code:	252		

2020 Generator Manifest

ID:	38892	**Sum Received Qty:**	17284.1
Generator No:	ON4748407	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	035	**Count Manifests:**	94
Waste Char:	I	**District:**	201
Waste Code:	331		

2020 Generator Manifest

ID:	38893	**Sum Received Qty:**	71100.0
Generator No:	ON4748407	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	24
Waste Char:	L	**District:**	301
Waste Code:	252		

2020 Generator Manifest

ID:	38877	**Sum Received Qty:**	10529.0
Generator No:	ON4748407	**Waste Class Name:**	ALKALINE WASTES - HEAVY METALS
Receiver Type:	035	**Count Manifests:**	61
Waste Char:	C	**District:**	201
Waste Code:	121		

2020 Generator Manifest

ID:	38882	**Sum Received Qty:**	840.0
Generator No:	ON4748407	**Waste Class Name:**	CHEMICAL FERTILIZER WASTES
Receiver Type:	035	**Count Manifests:**	11
Waste Char:	T	**District:**	201
Waste Code:	147		

2020 Generator Manifest

ID:	38889	**Sum Received Qty:**	1500.0
Generator No:	ON4748407	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	14
Waste Char:	L	**District:**	201
Waste Code:	252		

2020 Generator Manifest

ID:	38891	**Sum Received Qty:**	40725.0
Generator No:	ON4748407	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	54
Waste Char:	A	**District:**	201
Waste Code:	263		

2021 Generator Info

Gen No:	ON4748407	**Choice of Contact:**	CO_OFFICIAL
ID:	18736	**Phone No Official:**	905-791-7800 Ext.3976
Contaminated Fac:	N	**Phone No Admin:**	905-791-7800 Ext.4641
MHSW Facility:	Y	**County Ont:**	PEEL (R. M.)

NAICS Code1:	562112	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Region Of Peel		
Gen Div:			
Gen Op Name:	Region Of Peel		
Gen Op Div:			
Site Adrs1:	420 Railside Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1L1		
Site Country:	Canada		
Co Official:	Matthew Stevens		
Co Admin:	David Bruno		

2021 Generator Manifest

ID:	40091	**Sum Received Qty:**	6800.0
Generator No:	ON4748407	**Waste Class Name:**	ALKALINE WASTES - HEAVY METALS
Receiver Type:	035	**Count Manifests:**	53
Waste Char:	C	**District:**	201
Waste Code:	121		

2021 Generator Manifest

ID:	40095	**Sum Received Qty:**	5160.0
Generator No:	ON4748407	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	H	**District:**	201
Waste Code:	145		

2021 Generator Manifest

ID:	40107	**Sum Received Qty:**	57855.0
Generator No:	ON4748407	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	56
Waste Char:	A	**District:**	201
Waste Code:	263		

2021 Generator Manifest

ID:	40096	**Sum Received Qty:**	2400.0
Generator No:	ON4748407	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	201
Waste Code:	145		

2021 Generator Manifest

ID:	40103	**Sum Received Qty:**	2865.0
Generator No:	ON4748407	**Waste Class Name:**	HALOGENATED PESTICIDES
Receiver Type:	035	**Count Manifests:**	25
Waste Char:	A	**District:**	201
Waste Code:	242		

2021 Generator Manifest

ID:	40112	**Sum Received Qty:**	6600.0
Generator No:	ON4748407	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	306
Waste Code:	251		

2021 Generator Manifest

ID:	40090	**Sum Received Qty:**	650.0
Generator No:	ON4748407	**Waste Class Name:**	ACID WASTE - HEAVY METALS
Receiver Type:	035	**Count Manifests:**	10
Waste Char:	C	**District:**	201
Waste Code:	112		

2021 Generator Manifest

ID:	40105	**Sum Received Qty:**	1700.0
Generator No:	ON4748407	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	15
Waste Char:	L	**District:**	201
Waste Code:	252		

2021 Generator Manifest

ID:	40111	**Sum Received Qty:**	1497.5
Generator No:	ON4748407	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	12
Waste Char:	P	**District:**	302
Waste Code:	312		

2021 Generator Manifest

ID:	40093	**Sum Received Qty:**	90840.0
Generator No:	ON4748407	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	76
Waste Char:	B	**District:**	201
Waste Code:	145		

2021 Generator Manifest

ID:	40098	**Sum Received Qty:**	980.0
Generator No:	ON4748407	**Waste Class Name:**	CHEMICAL FERTILIZER WASTES
Receiver Type:	035	**Count Manifests:**	13
Waste Char:	T	**District:**	201
Waste Code:	147		

2021 Generator Manifest

ID:	40101	**Sum Received Qty:**	200.0
Generator No:	ON4748407	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	201
Waste Code:	212		

2021 Generator Manifest

ID:	40106	**Sum Received Qty:**	3530.0
Generator No:	ON4748407	**Waste Class Name:**	PHARMACEUTICALS
Receiver Type:	035	**Count Manifests:**	16
Waste Char:	A	**District:**	201

Waste Code: 261

2021 Generator Manifest

ID: 40109
Generator No: ON4748407
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 17413.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 2
District: 301

2021 Generator Manifest

ID: 40097
Generator No: ON4748407
Receiver Type: 035
Waste Char: I
Waste Code: 147
Sum Received Qty: 420.0
Waste Class Name: CHEMICAL FERTILIZER WASTES
Count Manifests: 4
District: 201

2021 Generator Manifest

ID: 40099
Generator No: ON4748407
Receiver Type: 035
Waste Char: I
Waste Code: 148
Sum Received Qty: 70.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 1
District: 201

2021 Generator Manifest

ID: 40104
Generator No: ON4748407
Receiver Type: 035
Waste Char: I
Waste Code: 252
Sum Received Qty: 200.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 2
District: 201

2021 Generator Manifest

ID: 40092
Generator No: ON4748407
Receiver Type: 035
Waste Char: C
Waste Code: 122
Sum Received Qty: 65.0
Waste Class Name: ALKALINE WASTES - OTHER METALS
Count Manifests: 1
District: 201

2021 Generator Manifest

ID: 40100
Generator No: ON4748407
Receiver Type: 035
Waste Char: T
Waste Code: 148
Sum Received Qty: 1680.0
Waste Class Name: INORGANIC LABORATORY CHEMICALS
Count Manifests: 16
District: 201

2021 Generator Manifest

ID: 40102
Generator No: ON4748407
Receiver Type: 035
Waste Char: I
Waste Code: 221
Sum Received Qty: 600.0
Waste Class Name: LIGHT FUELS
Count Manifests: 3
District: 201

2021 Generator Manifest

ID:	40094	**Sum Received Qty:**	1500.0
Generator No:	ON4748407	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	D	**District:**	201
Waste Code:	145		

2021 Generator Manifest

ID:	40108	**Sum Received Qty:**	19262.4
Generator No:	ON4748407	**Waste Class Name:**	WASTE COMPRESSED GASES
Receiver Type:	035	**Count Manifests:**	105
Waste Char:	I	**District:**	201
Waste Code:	331		

2021 Generator Manifest

ID:	40110	**Sum Received Qty:**	65800.0
Generator No:	ON4748407	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	25
Waste Char:	L	**District:**	301
Waste Code:	252		

---

85 | ***1 of 1*** | ***SE/243.2*** | ***236.9 / -5.08*** | ***GIVE AND GO PREPARED FOODS CORP.*** | ***EASR***

415 Railside DR
Brampton ON L7L 1E1

Approval No:	R-010-2113238807	**MOE District:**	Halton-Peel
Status:	REGISTERED	**Municipality:**	Brampton
Date:	2021-06-04	**Latitude:**	43.71194444
Record Type:	EASR	**Longitude:**	-79.80361111
Link Source:	MOFA	**Geometry X:**	-8883697.3524
Project Type:	Air Emissions	**Geometry Y:**	5420972.5986
Full Address:			
Approval Type:	EASR-Air Emissions		
SWP Area Name:	Toronto		
PDF NAICS Code:	493120		
PDF URL:			
PDF Site Location:			

---

86 | ***1 of 1*** | ***SSE/244.6*** | ***238.9 / -3.08*** | ***120A Van Kirk Drive*** | ***EHS***

Brampton ON L7A 1B1

Order No:	23111500120	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Express Report	**Client Prov/State:**	ON
Report Date:	15-NOV-23	**Search Radius (km):**	.25
Date Received:	15-NOV-23	**X:**	-79.80552
Previous Site Name:		**Y:**	43.70749
Lot/Building Size:			
Additional Info Ordered:			

---

87 | ***1 of 1*** | ***SSE/246.4*** | ***238.9 / -3.08*** | ***120 Van Kirk Dr*** | ***EHS***

Brampton ON L7A 1B1

Order No:	22050300635	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	06-MAY-22	**Search Radius (km):**	.25
Date Received:	03-MAY-22	**X:**	-79.8054379

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Previous Site Name: **Y:** 43.7074069
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

---

88 | **1 of 1** | **SSE/62.1** | **238.4 / -3.56** | **495618 111 Van Kirk Drive Brampton Brampton ON L7A 1A4** | **EHS**

Order No: 24062700397
Status: C
Report Type: Standard Report
Report Date: 03-JUL-24
Date Received: 27-JUN-24
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: CA
Search Radius (km): .25
X: -79.8029066
Y: 43.7079171

---

89 | **1 of 20** | **SSE/208.5** | **238.9 / -3.08** | **Exacta Fabtool Limited 120 Van Kirk Dr Brampton ON L7A 1B1** | **SCT**

Established: 01-JUL-83
Plant Size (ft²): 32000
Employment:

--Details--
Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Description: Cutlery and Hand Tool Manufacturing
SIC/NAICS Code: 332210

Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

---

89 | **2 of 20** | **SSE/208.5** | **238.9 / -3.08** | **Exacta Fabtool Limited - Div. of Exacta Precision Products Limited 120 Van Kirk Dr Brampton ON L7A 1B1** | **SCT**

Established: 1983
Plant Size (ft²): 15000
Employment: 20

--Details--
Description: Other Personal and Household Goods Repair and Maintenance
SIC/NAICS Code: 811490

---

89 | **3 of 20** | **SSE/208.5** | **238.9 / -3.08** | **EXACTA FABTOOL LIMITED 120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1** | **GEN**

Generator Info

Generator No: ON2439901
Approval Years: 99,00,01,02,03,04,05,06,07,08

Choice of Contact:
Contaminated Fac:

Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: METAL DIES, ETC. IND.

MHSW Facility:
SIC Code: 3062

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

89 | ***4 of 20*** | ***SSE/208.5*** | ***238.9 / -3.08*** | ***Body Care Innovations*** ***120A Van Kirk Dr*** ***Brampton ON L7A 1B1*** | ***SCT***

Established: 01-JUL-91
Plant Size (ft²):
Employment:

--Details--
Description: Toilet Preparation Manufacturing
SIC/NAICS Code: 325620

Description: Toilet Preparation Manufacturing
SIC/NAICS Code: 325620

Description: Soap and Cleaning Compound Manufacturing
SIC/NAICS Code: 325610

---

89 | ***5 of 20*** | ***SSE/208.5*** | ***238.9 / -3.08*** | ***Body Care Manufacturing Inc.*** ***120A Van Kirk Dr*** ***Brampton ON L7A 1B1*** | ***CA***

Certificate #: 0181-7DRNZ6
Application Year: 2008
Issue Date: 4/22/2008
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

89 | ***6 of 20*** | ***SSE/208.5*** | ***238.9 / -3.08*** | ***Body Care Manufacturing Inc.*** ***120A Van Kirk Dr*** ***Brampton ON L7A 1B1*** | ***ECA***

Approval No: 0181-7DRNZ6
Approval Date: 2008-04-22
MOE District: Halton-Peel
City:

Status:	Approved	**Longitude:**	-79.80543
Record Type:	ECA	**Latitude:**	43.707294
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Body Care Manufacturing Inc.		
Address:	120A Van Kirk Dr		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6548-7ABHFF-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	7 of 20	SSE/208.5	238.9 / -3.08	**Total Body Care Inc.** **120A Van Kirk Drive** **Brampton ON L7A 1B1**	GEN

Generator Info

Generator No:	ON4406953	**Choice of Contact:**	CO_ADMIN
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	325610
Country:	Canada		
Co Admin:	Shelley Hubbard		
Phone No Admin:	905-495-6204 Ext.22		
SIC Description:	SOAP AND CLEANING COMPOUND MANUFACTURING		

Waste Detail(s)

Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	8 of 20	SSE/208.5	238.9 / -3.08	**WILSON TOOL CANADA** **120 VAN KIRK DRIVE** **BRAMPTON ON L7A 1B1**	GEN

Generator Info

Generator No:	ON2439901	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	332710
Country:	Canada		
Co Admin:	Amandeep Singh		
Phone No Admin:	905-840-2240 Ext.232		
SIC Description:	MACHINE SHOPS		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	9 of 20	SSE/208.5	238.9 / -3.08	Total Body Care Inc. 120A Van Kirk Drive Brampton ON L7A 1B1	GEN

Generator Info

Generator No:	ON4406953	***Choice of Contact:***	CO_ADMIN
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	325610
Country:	Canada		
Co Admin:	Shelley Hubbard		
Phone No Admin:	905-495-6204 Ext.22		
SIC Description:	SOAP AND CLEANING COMPOUND MANUFACTURING		

Waste Detail(s)

Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	10 of 20	SSE/208.5	238.9 / -3.08	WILSON TOOL CANADA 120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	GEN

Generator Info

Generator No:	ON2439901	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class:	253 L
Waste Class Name:	Emulsified oils

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	11 of 20	SSE/208.5	238.9 / -3.08	Total Body Care Inc. 120A Van Kirk Drive Brampton ON L7A 1B1	GEN

Generator Info

Generator No:	ON4406953	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	

Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

---

89 | ***12 of 20*** | ***SSE/208.5*** | ***238.9 / -3.08*** | ***Total Body Care Inc.***
120A Van Kirk Drive
Brampton ON L7A 1B1 | ***GEN***

Generator Info

Generator No: ON4406953
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

---

89 | ***13 of 20*** | ***SSE/208.5*** | ***238.9 / -3.08*** | ***WILSON TOOL CANADA***
120 VAN KIRK DRIVE
BRAMPTON ON L7A 1B1 | ***GEN***

Generator Info

Generator No: ON2439901
Approval Years: As of Oct 2019
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 253 L
Waste Class Name: Emulsified oils

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	14 of 20	SSE/208.5	238.9 / -3.08	Total Body Care Inc. 120A Van Kirk Drive Brampton ON L7A 1B1	GEN

Generator Info

Generator No: ON4406953
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	15 of 20	SSE/208.5	238.9 / -3.08	WILSON TOOL CANADA 120 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	GEN

Generator Info

Generator No: ON2439901
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		253 L			
Waste Class Name:		Emulsified oils			

89	16 of 20	SSE/208.5	238.9 / -3.08	**Total Body Care Inc.** **120A Van Kirk Drive** **Brampton ON L7A 1B1**	GEN

Generator Info

Generator No:	ON4406953	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	212 L
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	262 L
Waste Class Name:	DETERGENTS/SOAPS

2017 Generator Info

Gen No:	ON4406953	**Choice of Contact:**	CO_ADMIN
ID:	17532	**Phone No Official:**	905-495-6204 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905-495-6204 Ext.22
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	325610	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Total Body Care Inc.		
Gen Div:			
Gen Op Name:	Total Body Care Inc.		
Gen Op Div:			
Site Adrs1:	120A Van Kirk Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1B1		
Site Country:	Canada		
Co Official:	Craig Hubbard		
Co Admin:	Shelley Hubbard		

2017 Generator Manifest

ID:	41019	**Sum Received Qty:**	10000.0
Generator No:	ON4406953	**Waste Class Name:**	DETERGENTS/SOAPS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	301
Waste Code:	262		

2018 Generator Info

Gen No:	ON4406953	**Choice of Contact:**	CO_ADMIN
ID:	17561	**Phone No Official:**	905-495-6204 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905-495-6204 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	325610	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Total Body Care Inc.		
Gen Div:			
Gen Op Name:	Total Body Care Inc.		
Gen Op Div:			
Site Adrs1:	120A Van Kirk Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1B1		
Site Country:	Canada		
Co Official:	Patrick Amiel		
Co Admin:	Shabniz Nazarali		

2018 Generator Manifest

ID:	40908	**Sum Received Qty:**	24000.0
Generator No:	ON4406953	**Waste Class Name:**	DETERGENTS/SOAPS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	201
Waste Code:	262		

2019 Generator Info

Gen No:	ON4406953	**Choice of Contact:**	CO_ADMIN
ID:	17458	**Phone No Official:**	905-495-6204 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905-495-6204 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	325610	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Total Body Care Inc.		
Gen Div:			
Gen Op Name:	Total Body Care Inc.		
Gen Op Div:			
Site Adrs1:	120A Van Kirk Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1B1		
Site Country:	Canada		
Co Official:	Patrick Amiel		

Co Admin: Shabniz Nazarali

2019 Generator Manifest

ID: 40221
Generator No: ON4406953
Receiver Type: 035
Waste Char: L
Waste Code: 262
Sum Received Qty: 13600.0
Waste Class Name: DETERGENTS/SOAPS
Count Manifests: 2
District: 201

2019 Generator Manifest

ID: 40220
Generator No: ON4406953
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 60.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 201

2020 Generator Info

Gen No: ON4406953
ID: 17164
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 325610
NAICS Code2:
NAICS Code3:
Gen Name: Total Body Care Inc.
Gen Div:
Gen Op Name: Total Body Care Inc.
Gen Op Div:
Site Adrs1: 120A Van Kirk Drive
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: Patrick Amiel
Co Admin: Shabniz Nazarali
Choice of Contact: CO_ADMIN
Phone No Official: 905-495-6204 Ext.
Phone No Admin: 905-495-6204 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2020 Generator Manifest

ID: 37120
Generator No: ON4406953
Receiver Type: 035
Waste Char: L
Waste Code: 262
Sum Received Qty: 22000.0
Waste Class Name: DETERGENTS/SOAPS
Count Manifests: 2
District: 201

2021 Generator Info

Gen No: ON4406953
ID: 17230
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 325610
NAICS Code2:
NAICS Code3:
Gen Name: Total Body Care Inc.
Gen Div:
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-495-6204 Ext.
Phone No Admin: 905-495-6204 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

Gen Op Name:	Total Body Care Inc.
Gen Op Div:	
Site Adrs1:	120A Van Kirk Drive
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1B1
Site Country:	Canada
Co Official:	Patrick Amiel
Co Admin:	Shabniz Nazarali

2021 Generator Manifest

ID:	38236	***Sum Received Qty:***	5000.0
Generator No:	ON4406953	***Waste Class Name:***	ALIPHATIC SOLVENTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	201
Waste Code:	212		

2021 Generator Manifest

ID:	38237	***Sum Received Qty:***	12000.0
Generator No:	ON4406953	***Waste Class Name:***	DETERGENTS/SOAPS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	201
Waste Code:	262		

---

89 ***17 of 20*** ***SSE/208.5*** ***238.9 / -3.08*** ***WILSON TOOL CANADA-PRESS BRAKE DIVISION***
120 Van Kirk Drive
Brampton ON ***GEN***

Generator Info

Generator No:	ON2439901	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	253 L
Waste Class Name:	EMULSIFIED OILS

Waste Detail(s)

Waste Class:	251 L

Waste Class Name: OIL SKIMMINGS & SLUDGES

Generator Info as of Dec 2024

Generator No: ON2439901
Generator Company Name: WILSON TOOL CANADA-PRESS BRAKE DIVISION
Street: 120 Van Kirk Drive
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A 1B1
Waste Class: 253 L,252 L

Waste Class Decoded:

253 - EMULSIFIED OILS; 252 - WASTE OILS & LUBRICANTS

2017 Generator Info

Gen No: ON2439901
ID: 9730
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 332710
NAICS Code2:
NAICS Code3:
Gen Name: WILSON TOOL CANADA
Gen Div:
Gen Op Name: WILSON TOOL CANADA
Gen Op Div:
Site Adrs1: 120 VAN KIRK DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: MARCO ROMASCO
Co Admin: Amandeep Singh

Choice of Contact: CO_OFFICIAL
Phone No Official: 905 840-2240 Ext.223
Phone No Admin: 905-840-2240 Ext.232
County Ont: PEEL (R. M.)
County Out:
District: 305

2017 Generator Manifest

ID: 30565
Generator No: ON2439901
Receiver Type: 035
Waste Char: L
Waste Code: 252

Sum Received Qty: 5600.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 2
District: 304

2018 Generator Info

Gen No: ON2439901
ID: 9493
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 332710
NAICS Code2:
NAICS Code3:
Gen Name: WILSON TOOL CANADA
Gen Div:

Choice of Contact: CO_OFFICIAL
Phone No Official: 905 840-2240 Ext.223
Phone No Admin: 905-840-2240 Ext.222
County Ont: PEEL (R. M.)
County Out:
District: 305

Gen Op Name: WILSON TOOL CANADA
Gen Op Div:
Site Adrs1: 120 VAN KIRK DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: MARCO ROMASCO
Co Admin: Michael Rajk

2018 Generator Manifest

ID: 30247
Generator No: ON2439901
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 5700.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 3
District: 304

2019 Generator Info

Gen No: ON2439901
ID: 9201
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 332710
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 905 840-2240 Ext.223
Phone No Admin: 905-840-2240 Ext.222
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: WILSON TOOL CANADA
Gen Div:
Gen Op Name: WILSON TOOL CANADA
Gen Op Div:
Site Adrs1: 120 VAN KIRK DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: MARCO ROMASCO
Co Admin: Michael Rajk

2019 Generator Manifest

ID: 29647
Generator No: ON2439901
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 4300.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 304

2021 Generator Info

Gen No: ON2439901
ID: 8628
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 332710
Choice of Contact: CO_OFFICIAL
Phone No Official: 905 840-2240 Ext.223
Phone No Admin: 905-840-2240 Ext.222
County Ont: PEEL (R. M.)
County Out:

NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	WILSON TOOL CANADA		
Gen Div:			
Gen Op Name:	WILSON TOOL CANADA		
Gen Op Div:			
Site Adrs1:	120 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1B1		
Site Country:	Canada		
Co Official:	MARCO ROMASCO		
Co Admin:	Michael Rajk		

2021 Generator Manifest

ID:	27136	***Sum Received Qty:***	9800.0
Generator No:	ON2439901	***Waste Class Name:***	EMULSIFIED OILS
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	L	***District:***	305
Waste Code:	253		

2021 Generator Manifest

ID:	27135	***Sum Received Qty:***	3000.0
Generator No:	ON2439901	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	304
Waste Code:	252		

---

89 ***18 of 20*** ***SSE/208.5*** ***238.9 / -3.08*** ***120 Van Kirk Drive Brampton ON L7A 1B1*** ***EHS***

Order No:	22101700266	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	20-OCT-22	***Search Radius (km):***	.25
Date Received:	17-OCT-22	***X:***	-79.8048183
Previous Site Name:		***Y:***	43.7074398
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

89 ***19 of 20*** ***SSE/208.5*** ***238.9 / -3.08*** ***Total Body Care Inc. 120A Van Kirk Drive Brampton ON*** ***GEN***

Generator Info as of Dec 2024

Generator No:	ON001060379
Generator Company Name:	Total Body Care Inc.
Street:	120A Van Kirk Drive
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A 1B1
Waste Class:	262 L

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Decoded:

262 - DETERGENTS/SOAPS

---

89 | ***20 of 20*** | ***SSE/208.5*** | ***238.9 / -3.08*** | ***1000456356 Ontario Inc.*** ***120 Van Kirk Drive*** ***Brampton ON*** | ***GEN***

Generator Info as of Dec 2024

Generator No:	ON001071762
Generator Company Name:	1000456356 Ontario Inc.
Street:	120 Van Kirk Drive
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L7A 1B1
Waste Class:	251 L

Waste Class Decoded:

251 - OIL SKIMMINGS & SLUDGES

---

90 | ***1 of 1*** | ***W/193.0*** | ***251.8 / 9.85*** | ***Wanless Dr & Mclaughlin Rd N*** ***Brampton ON*** | ***EHS***

Order No:	20120403014	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	4/13/2012	***Search Radius (km):***	0.25
Date Received:	4/3/2012 12:43:48 PM	***X:***	-79.829682
Previous Site Name:		***Y:***	43.725658
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans;		

---

91 | ***1 of 2*** | ***SSE/74.6*** | ***238.9 / -3.08*** | ***111 Van Kirk Drive*** ***Brampton ON*** | ***EHS***

Order No:	20140616017	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	19-JUN-14	***Search Radius (km):***	.35
Date Received:	16-JUN-14	***X:***	-79.802905
Previous Site Name:		***Y:***	43.70783
Lot/Building Size:			
Additional Info Ordered:			

---

91 | ***2 of 2*** | ***SSE/74.6*** | ***238.9 / -3.08*** | ***111 Van Kirk Drive*** ***Brampton ON L7A 1A4*** | ***EHS***

Order No:	22032800123	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	31-MAR-22	***Search Radius (km):***	.25
Date Received:	28-MAR-22	***X:***	-79.8028828
Previous Site Name:		***Y:***	43.7080691

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Lot/Building Size:
Additional Info Ordered:

---

92 **1 of 1** **SE/110.4** **237.1 / -4.81** **398 Railside Drive**
Brampton ON L7A 1E1 **EHS**

Order No:	23032100470	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	29-MAR-23	**Search Radius (km):**	.25
Date Received:	21-MAR-23	**X:**	-79.80022093
Previous Site Name:		**Y:**	43.70828479
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

---

93 **1 of 3** **SSE/219.2** **239.9 / -2.08** **Kal-Trading Inc.**
100 Van Kirk Dr
Brampton ON L7A 1B1 **SCT**

Established: 1992
Plant Size (ft²): 40000
Employment: 25

--Details--
Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

---

93 **2 of 3** **SSE/219.2** **239.9 / -2.08** **315594 ONTARIO INC.**
100 VAN KIRK DR
BRAMPTON ON L7A 1B1 **EASR**

Approval No:	R-001-6677825112	**MOE District:**	Halton-Peel
Status:	REGISTERED	**Municipality:**	BRAMPTON
Date:	2016-11-11	**Latitude:**	43.70666667
Record Type:	EASR	**Longitude:**	-79.80416667
Link Source:	MOFA	**Geometry X:**	
Project Type:	Automotive Refinishing Facility	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Automotive Refinishing Facility		
SWP Area Name:	Credit Valley		
PDF NAICS Code:			
PDF URL:			
PDF Site Location:			

---

93 **3 of 3** **SSE/219.2** **239.9 / -2.08** **100 Van Kirk Drive**
Brampton ON **EHS**

Order No:	20160922030	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	05-OCT-16	**Search Radius (km):**	.25
Date Received:	22-SEP-16	**X:**	-79.804074
Previous Site Name:		**Y:**	43.706767
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
94	1 of 1	W/248.7	251.9 / 9.92	1569692 ONTARIO LTD. O/A CANADIAN GREEN 7 DELPHINIUM WAY BRAMPTON ON L7A 0N4	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	1 of 1	WNW/197.7	255.9 / 13.95	Ontario Clean Water Agency 2819 Mayfield Rd Brampton ON	SPL

Ref No: 8185-8M6RB9
Year:
Incident Dt: 9/29/2011
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/29/2011
Dt Document Closed:
Site No:
MOE Response: Referral to others
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Snelgrove Elevated Tank<UNOFFICIAL>
Site Address: 2819 Mayfield Rd
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Ontario Clean Water Agency
Client Type:
Source Type:
Incident Cause: Other Discharges
Incident Preceding Spill:
Incident Reason: Unknown - Reason not determined
Incident Summary: Snelgrove Elevated Tank:overflow, chl water to storm
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Contaminant Qty 1:	0
Contaminant Unit:	
Contaminant Code:	99
Contaminant Name:	WATER (HIGH CHLORINE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Water Supply
SAC Action Class:	Primary Assessment of Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

96 | ***1 of 1*** | ***SSE/208.3*** | ***239.9 / -2.08*** | ***80 VAN KIRK DRIVE Brampton ON*** | ***WWIS***

Well ID:	7277923	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	0	**Date Received:**	12/23/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z247468	**Contractor:**	7241
Tag:	A211476	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/727\7277923.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/22/2016
Year Completed:	2016
Depth (m):	58.2168
Latitude:	43.7064012461173
Longitude:	-79.8033812096965
X:	-79.80338105991699
Y:	43.706401243963526
Path:	727\7277923.pdf

Bore Hole Information

Bore Hole ID:	1006320527	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596410.00
Code OB Desc:		**North83:**	4839960.00
Open Hole:		**Org CS:**	UTM83

Cluster Kind:
Date Completed: 11/22/2016
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006520772
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3: 60
Material 3 Desc: CEMENTED
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006520774
Layer: 3
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 92
Material 3 Desc: WEATHERED
Formation Top Depth: 6.0
Formation End Depth: 191.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006520773
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 28
Material 2 Desc: SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.5
Formation End Depth: 6.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006520783
Layer:	2
Plug From:	0.5
Plug To:	8.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006520784
Layer:	3
Plug From:	8.0
Plug To:	19.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006520782
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006520781
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1006520771
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006520777
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	9.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006520778
Layer:	1
Slot:	10
Screen Top Depth:	9.0
Screen End Depth:	19.0

Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1006520776
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006520775
Diameter: 6.0
Depth From: 0.0
Depth To: 19.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

97	1 of 22	SSE/76.1	238.9 / -3.08	**BUTCHER ENGINEERING** **105 VAN KIRK DR** **BRAMPTON ON L7A 1A4**	PRT

Location ID: 18871
Type: retail
Expiry Date: 1993-01-31
Capacity (L): 1000
Licence #: 0076350875

97	2 of 22	SSE/76.1	238.9 / -3.08	**The Butcher Engineering Enterprises Limited** **105 Van Kirk Drive Brampton Ontario Brampton ON**	EBR

EBR Registry No: IA03E0788
Ministry Ref No: 6441-5MWR44
Notice Type: Instrument Decision
Notice Stage:
Notice Date: November 07, 2003
Proposal Date: June 03, 2003
Year: 2003
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: The Butcher Engineering Enterprises Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 120 Orenda Road, Brampton Ontario, L6W 1W2
Comment Period:
URL:
Summary:

Site Location Details:

105 Van Kirk Drive Brampton Ontario Brampton

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	3 of 22	SSE/76.1	238.9 / -3.08	BUTCH ENGINEERING ENTERPRISES LTD. 105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No:	ON0041001	***Choice of Contact:***	
Approval Years:	86,87,88,89,90	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6352
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PAINT/BODY REPAIR		

Waste Detail(s)

Waste Class:	123
Waste Class Name:	ALKALINE PHOSPHATES

Waste Detail(s)

Waste Class:	131
Waste Class Name:	NEUTRALIZED WASTES - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	4 of 22	SSE/76.1	238.9 / -3.08	BUTCHER ENGINEERING ENTERPRISES LTD. 105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No:	ON0041001	***Choice of Contact:***	
Approval Years:	92,93,95,96,97,98,99,00,01,02,03,04,05,06,07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6352
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PAINT/BODY REPAIR		

Waste Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Detail(s)

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	5 of 22	SSE/76.1	238.9 / -3.08	BUTCH ENGINEERING ENTERPRISES LTD.06-157 105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No: ON0041001
Approval Years: 94
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PAINT/BODY REPAIR

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6352

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Detail(s)

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	6 of 22	SSE/76.1	238.9 / -3.08	The Butcher Engineering Enterprises Limited 105 Van Kirk Dr Brampton ON L7A 1A4	SPL

Ref No:	5042-7GF2L7	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	7/10/2008	**Impact to Health:**	
Dt Document Closed:	9/17/2008	**Agency Involved:**	

Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: The Butcher Engineering (Van Kirk location)
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Entity Operating Name:
Client Name: The Butcher Engineering Enterprises Limited
Client Type:
Source Type:
Incident Cause: Overflow (Tanks Lagoons)
Incident Preceding Spill:
Incident Reason: Fire/Explosion - Resulting from fires/explosions (Not occurrences which cause a fire or explosion)
Incident Summary: Butcher Engineering, Fire run off
Environment Impact: Possible
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 50 L
Contaminant Qty 1: 50
Contaminant Unit: L
Contaminant Code: 27
Contaminant Name: PAINT OR PAINT RELATED N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	7 of 22	SSE/76.1	238.9 / -3.08	105 Van Kirk Drive Brampton ON L7A 1A4	EHS

Order No:	20100602039	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	6/11/2010	**Search Radius (km):**	0.25
Date Received:	6/2/2010	**X:**	-79.801835
Previous Site Name:		**Y:**	43.706708

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Lot/Building Size:	6 acres				
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans				

97	8 of 22	SSE/76.1	238.9 / -3.08	**The Butcher Engineering Enterprises Limited** **105 Van Kirk Drive** **Brampton ON L7A 1A4**	CA

Certificate #:	6733-6LFSMG
Application Year:	2006
Issue Date:	2/20/2006
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

97	9 of 22	SSE/76.1	238.9 / -3.08	**The Butcher Engineering Enterprises Limited** **105 Van Kirk Drive** **Brampton ON L7A 1A4**	CA

Certificate #:	9113-5RWNXB
Application Year:	2003
Issue Date:	10/29/2003
Approval Type:	Air
Status:	Revoked and/or Replaced
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

97	10 of 22	SSE/76.1	238.9 / -3.08	**THE BUTCHER ENGINEERING ENTERPRISES LTD.** **105 Van Kirk Dr.** **Brampton ON L7A1A4**	NPRI

NPRI ID:	7100004774	**Org ID:**	
Other ID:	*	**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	
Rpt Type ID:		**Cont First Name:**	
Report Year:	2009	**Cont Last Name:**	
Not-Current Rpt?:		**Contact Position:**	
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	VAN KIRK PLANT	**Cont Area Code:**	
Fac Address1:		**Contact Tel.:**	
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:		**Cont Fax Area Cde:**	
Facility Lat:		**Contact Fax:**	

Facility Long:				**Contact Email:**	
DLS (Last Filed Rpt):				**Latitude:**	
Facility DLS:				**Longitude:**	
Datum:				**UTM Zone:**	
Facility Cmnts:	No			**UTM Northing:**	
URL:				**UTM Easting:**	
No of Empl.:	0			**Waste Streams:**	No
Parent Co.:	*			**No Streams:**	
No Parent Co.:				**Waste Off Sites:**	No
Pollut Prev Cmnts:	No			**No Off Sites:**	
Stacks:	No			**Shutdown:**	No
No of Stacks:				**No of Shutdown:**	
Canadian SIC Code (2 digit):					
Canadian SIC Code:					
SIC Code Description:					
American SIC Code:					
NAICS Code (2 digit):					
NAICS 2 Description:					
NAICS Code (4 digit):					
NAICS 4 Description:					
NAICS Code (6 digit):					
NAICS 6 Description:					

97	***11 of 22***	***SSE/76.1***	***238.9 / -3.08***	***BUTCHER ENGINEERING*** ***105 VAN KIRK DR*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	9902292	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	393693	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Refill Cntr - Cylr Fill		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

97	***12 of 22***	***SSE/76.1***	***238.9 / -3.08***	***BUTCHER ENGINEERING*** ***105 VAN KIRK DR***	***DTNK***

BRAMPTON ON

Delisted Expired Fuel Safety Facilities

Instance No:	11094406	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	68052	**Facility Location:**	
Instance Type:	FS Propane Tank	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Tank		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	13 of 22	SSE/76.1	238.9 / -3.08	BUTCHER ENGINEERING ENTERPRISES LTD. 105 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No:	ON0041001	**Choice of Contact:**	
Approval Years:	2009	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	332810
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Coating Engraving Heat Treating and Allied Activities		

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class:	113
Waste Class Name:	ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

---

97 | ***14 of 22*** | ***SSE/76.1*** | ***238.9 / -3.08*** | ***BUTCHER ENGINEERING ENTERPRISES LTD.***
105 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON0041001
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Coating Engraving Heat Treating and Allied Activities

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 332810

Waste Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Detail(s)

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 268
Waste Class Name: AMINES

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

97 **15 of 22** **SSE/76.1** **238.9 / -3.08** **BUTCHER ENTERPRISES**
105 VanKirk
Brampton ON L7A1A4 **NPRI**

NPRI ID: 7100000052
Other ID:
No Other ID:
Track ID:
Report ID:
Report Type:
Rpt Type ID:
Report Year: 2009
Not-Current Rpt?:
Yr of Last Filed Rpt:
Fac ID:
Fac Name: VANKIRK
Fac Address1:
Fac Address2:
Fac Postal Zip:
Facility Lat:
Facility Long:
DLS (Last Filed Rpt):
Facility DLS:
Datum:
Facility Cmnts:
URL: www.butcherent.com
No of Empl.: 0
Parent Co.:
No Parent Co.:
Pollut Prev Cmnts:
Stacks:
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit):
NAICS 2 Description:
NAICS Code (4 digit):
NAICS 4 Description:
NAICS Code (6 digit):
NAICS 6 Description:

Org ID:
Submit Date:
Last Modified:
Contact ID:
Cont Type: MED
Contact Title:
Cont First Name:
Cont Last Name:
Contact Position:
Contact Fax:
Contact Ph.:
Cont Area Code:
Contact Tel.:
Contact Ext.:
Cont Fax Area Cde:
Contact Fax:
Contact Email:
Latitude:
Longitude:
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams:
No Streams:
Waste Off Sites:
No Off Sites:
Shutdown:
No of Shutdown:

---

97 **16 of 22** **SSE/76.1** **238.9 / -3.08** **105 VAN KIRK DR, BRAMPTON ON** **INC**

Incident No: 1679356
Incident ID:
Instance No:
Status Code:
Incident Status:
Incident Severity:
Task No: 5658486
Attribute Category: FS-Perform L1 Incident Insp
Context:

Any Health Impact: No
Any Enviro Impact: No
Service Intrp: Yes
Was Prop Damaged: Yes
Reside App. Type:
Commer App. Type:
Indus App. Type:
Institut App. Type:
Depth Ground Cover:

Date of Occurrence:	2014/07/10 00:00:00	**Operation Pressure:**	
Time of Occurrence:	NULL	**Equipment Type:**	
Occr Insp Start Dt:	2014/07/10 00:00:00	**Equipment Model:**	
Incident Creat On:		**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Vapour Release	**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Natural Gas	**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:	NULL	**Tank Storage Type:**	
Prc Escalation Req:	NULL	**Tank Location Type:**	

Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 105 VAN KIRK DR, BRAMPTON - VAPOUR RELEASE
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: NULL
Operation Type Involved: Commercial (e.g. restaurant, business unit, etc)

97	17 of 22	SSE/76.1	238.9 / -3.08	105 Van Kirk Dr. Brampton ON	SPL

Ref No:	1361-9YAGWE	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	7/10/2015	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	7/10/2015	**Impact to Health:**	
Dt Document Closed:	10/3/2015	**Agency Involved:**	

Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: commercial<UNOFFICIAL>
Site Address: 105 Van Kirk Dr.
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:

Client Name:	
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	Operator/Human Error
Incident Summary:	TSSA - Brampton, ceiling line struck by roofers, made safe
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 L
Contaminant Qty 1:	0
Contaminant Unit:	L
Contaminant Code:	35
Contaminant Name:	NATURAL GAS (METHANE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Unknown / N/A
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

97 | ***18 of 22*** | ***SSE/76.1*** | ***238.9 / -3.08*** | ***The Butcher Engineering Enterprises Limited***
105 Van Kirk Drive
Brampton ON L6W 1W2 | ***ECA***

Approval No:	9113-5RWNXB	**MOE District:**	Halton-Peel
Approval Date:	2003-10-29	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.80181
Record Type:	ECA	**Latitude:**	43.70694
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	The Butcher Engineering Enterprises Limited		
Address:	105 Van Kirk Drive		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6441-5MWR44-14.pdf		
PDF Site Location:			

---

97 | ***19 of 22*** | ***SSE/76.1*** | ***238.9 / -3.08*** | ***The Butcher Engineering Enterprises Limited***
105 Van Kirk Drive
Brampton ON L6W 1W2 | ***ECA***

Approval No:	6733-6LFSMG	**MOE District:**	Halton-Peel
Approval Date:	2006-02-20	**City:**	
Status:	Revoked and/or Replaced	**Longitude:**	-79.80181
Record Type:	ECA	**Latitude:**	43.70694
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	The Butcher Engineering Enterprises Limited		
Address:	105 Van Kirk Drive		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2560-69ML7Q-14.pdf		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PDF Site Location:

---

97 **20 of 22** **SSE/76.1** **238.9 / -3.08** **105 Van Kirk Dr**
Brampton ON L7A1A4 **EHS**

Order No:	20170307142	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	14-MAR-17	**Search Radius (km):**	.25
Date Received:	07-MAR-17	**X:**	-79.801698
Previous Site Name:		**Y:**	43.706783
Lot/Building Size:			
Additional Info Ordered:			

---

97 **21 of 22** **SSE/76.1** **238.9 / -3.08** **VAN KIRK PLANT**
105 VAN KIRK DR.
BRAMPTON ON L7A1A4 **NPR2**

NPRI ID:	4774	**Latitude:**	43.7068
Facility ID:	225211;343105;356154;366867;366868; 366869;372353	**Longitude:**	-79.8042
Facility Name:	VAN KIRK PLANT		

Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=4774

NPRI ID Substances Summary

CAS No:		**Is PAH?:**	
Is VOC?:		**NPRI:**	
Is DF?:			
Name English:			
Name French:			
Sort English:			
Sort French:			

CAS No:	111-76-2	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	2-Butoxyethanol		
Name French:	2-Butoxyéthanol		
Sort English:	Butoxyethanol:2-		
Sort French:	Butoxyéthanol:2-		

CAS No:	NA - M16	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Volatile Organic Compounds (VOCs)		
Name French:	Composés organiques volatils (COV)		
Sort English:	Volatile Organic Compounds (VOCs)		
Sort French:	Composés organiques volatils (COV)		

CAS No:	NA - M10	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		

Name English:	PM2.5 - Particulate Matter <= 2.5 Micrometers
Name French:	PM2,5 - Matière particulaire <= 2,5 micromètres
Sort English:	PM2.5 - Particulate Matter <= 2.5 Micrometers
Sort French:	PM2,5 - Matière particulaire <= 2,5 micromètres

CAS No:	NA - 19	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Hexavalent chromium (and its compounds)		
Name French:	Chrome hexavalent (et ses composés)		
Sort English:	Hexavalent chromium (and its compounds)		
Sort French:	Chrome hexavalent (et ses composés)		

CAS No:	7632-00-0	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Sodium nitrite		
Name French:	Nitrite de sodium		
Sort English:	Sodium nitrite		
Sort French:	Nitrite de sodium		

CAS No:	7664-93-9	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Sulphuric acid		
Name French:	Acide sulfurique		
Sort English:	Sulphuric acid		
Sort French:	Acide sulfurique		

CAS No:	NA - M09	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	PM10 - Particulate Matter <= 10 Micrometers		
Name French:	PM10 - Matière particulaire <= 10 micromètres		
Sort English:	PM10 - Particulate Matter <= 10 Micrometers		
Sort French:	PM10 - Matière particulaire <= 10 micromètres		

CAS No:	7647-01-0	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Hydrochloric acid		
Name French:	Acide chlorhydrique		
Sort English:	Hydrochloric acid		
Sort French:	Acide chlorhydrique		

CAS No:	78-92-2	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	sec-Butyl alcohol		
Name French:	Butan-2-ol		
Sort English:	Butyl alcohol:sec-		
Sort French:	Butan-2-ol		

CAS No:	78-83-1	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	i-Butyl alcohol		
Name French:	2-Méthylpropan-1-ol		
Sort English:	Butyl alcohol:i-		
Sort French:	Méthylpropan-1-ol:2-		

Geographic Location

Report Year:	-1	**Forward Sort Area:**	L6Z
Census Subdiv ID:	3521010	**DLS Description:**	

Ecozone ID:	8	***NTS Description:***	D-045-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.7068
QC PEMA:	FALSE	***Longitude:***	-79.8042
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	4774
Facility ID:	366867

Facility

Facility ID:	366867	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	332810	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	Van Kirk Plant		
Website:			

Address

Address1:	105 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4
Prov:	

Primary NAICS Details

NAICS Code:	332810	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe canadienne, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et des produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		

NAICS Title En: Coating, engraving, cold and heat treating and allied activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et par le froid, et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code: 332810 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, engraving, cold and heat treating and allied activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et par le froid, et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code: 332810 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, Engraving, Heat Treating and Allied Activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code: 332810 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, Engraving, Heat Treating and Allied Activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NPRI Report

Report ID:	278012	***No of Employees:***	97
Report Year:	2001	***Is Compressor:***	
Company ID:	101822	***Is NPRI Part 4:***	
SWR Report ID:	20010000004774	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2002-06-03 00:00:00.0000000

Company

Company Name:	The Butcher Engineering Enterprises Limited
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9058466838
First Name:	Humberto	***Extension:***	0
Last Name:	Eusebio	***Fax:***	9058466774

Company Name:
Description En:
Description Fr:
Position: General Manager
Language: 0
Email:

NPRI Report Contact

Contact Type: NPRI
First Name: Scott
Last Name: McPherson
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: Manager
Language: 0
Email:
Phone: 9058466838
Extension: 0
Fax: 9058466774

NPRI Report Contact

Contact Type:
First Name: Angelo
Last Name: Venerus
Company Name:
Description En:
Description Fr:
Position: Consultant
Language: 0
Email: vipinc@on.aibn.com
Phone: 5198231252
Extension: 0
Fax: 5198232046

NPRI ID Facility ID

NPRI ID: 4774
Facility ID: 366869

Facility

Facility ID: 366869
Portable: FALSE
NAICS Primary: 336390
NAICS Secondary: 0
NAICS Tertiary: 0
Facility Name: VAN KIRK
Website:
IDM ID: 0
AB Approval ID: 0
GHGRP ID: 0
ON GHGRP ID: 0

Address

Address1: 105 Van Kirk Drive
Address2:
City: BRAMPTON
Postal Zip: L7A1A4
Prov:

Primary NAICS Details

NAICS Code: 336390
Record Year: 2002
Key Indus Sector En: Transportation Equipment Mfg.
Key Indus Sector Fr: Fabrication de matériel de transport
NAICS Title En: Other Motor Vehicle Parts Manufacturing
Start Date: 2002
End Date: 2006

NAICS Title Fr: Fabrication d'autres pièces pour véhicules automobiles

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other industry, primarily engaged in manufacturing motor vehicle parts and accessories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe et dont l'activité principale est la fabrication de pièces et d'accessoires pour véhicules automobiles.

NAICS Code: 336390 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Transportation Equipment Mfg.
Key Indus Sector Fr: Fabrication de matériel de transport
NAICS Title En: Other motor vehicle parts manufacturing
NAICS Title Fr: Fabrication d'autres pièces pour véhicules automobiles

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing motor vehicle parts and accessories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de pièces et d'accessoires pour véhicules automobiles.

NAICS Code: 336390 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Transportation Equipment Mfg.
Key Indus Sector Fr: Fabrication de matériel de transport
NAICS Title En: Other Motor Vehicle Parts Manufacturing
NAICS Title Fr: Fabrication d'autres pièces pour véhicules automobiles

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other industry, primarily engaged in manufacturing motor vehicle parts and accessories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe et dont l'activité principale est la fabrication de pièces et d'accessoires pour véhicules automobiles.

NAICS Code: 336390 ***Start Date:*** 2012
Record Year: 2012 ***End Date:*** 2016
Key Indus Sector En: Transportation Equipment Mfg.
Key Indus Sector Fr: Fabrication de matériel de transport
NAICS Title En: Other motor vehicle parts manufacturing
NAICS Title Fr: Fabrication d'autres pièces pour véhicules automobiles

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing motor vehicle parts and accessories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de pièces et d'accessoires pour véhicules automobiles.

NAICS Code:	336390	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Transportation Equipment Mfg.		
Key Indus Sector Fr:	Fabrication de matériel de transport		
NAICS Title En:	Other motor vehicle parts manufacturing		
NAICS Title Fr:	Fabrication d'autres pièces pour véhicules automobiles		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing motor vehicle parts and accessories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale est la fabrication de pièces et d'accessoires pour véhicules automobiles.

NAICS Code:	336390	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Transportation Equipment Mfg.		
Key Indus Sector Fr:	Fabrication de matériel de transport		
NAICS Title En:	Other Motor Vehicle Parts Manufacturing		
NAICS Title Fr:	Fabrication d'autres pièces pour véhicules automobiles		

NAICS Description En:

This Canadian industry comprises establishments, not classified to any other industry, primarily engaged in manufacturing motor vehicle parts and accessories.

NAICS Description Fr:

Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe et dont l'activité principale est la fabrication de pièces et d'accessoires pour véhicules automobiles.

NPRI Report

Report ID:	276276	***No of Employees:***	93
Report Year:	2002	***Is Compressor:***	
Company ID:	141499	***Is NPRI Part 4:***	
SWR Report ID:	20020000004774	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2003-06-02 00:00:00.0000000

Company

Company Name:	THE BUTCHER ENGINEERING ENTERPRISES LIMITED
DUNS No:	118822152
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9054593030
First Name:	Bob	***Extension:***	127

Last Name:	Luffman	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	QS and Environmental Coordinator		
Language:	0		
Email:	bluffman@butcher-eng.com		

NPRI Report Contact

Contact Type:		***Phone:***	5196629168
First Name:	Rob	***Extension:***	0
Last Name:	Toth	***Fax:***	5196629434
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Consultant		
Language:	0		
Email:	toth@sympatico.ca		

NPRI Report Contact

Contact Type:		***Phone:***	9054593030
First Name:	Chris	***Extension:***	111
Last Name:	Butcher	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	Executive Vice President		
Language:	0		
Email:	cbutcher@butcher-eng.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054593030
First Name:	Bob	***Extension:***	127
Last Name:	Luffman	***Fax:***	9054590689
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	QS and Environmental Coordinator		
Language:	0		
Email:	bluffman@butcher-eng.com		

NPRI ID Facility ID

NPRI ID:	4774
Facility ID:	356154

Facility

Facility ID:	356154	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	332810	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	VAN KIRK PLANT		
Website:			

Address

Address1: 105 Van Kirk Dr.
Address2:
City: BRAMPTON
Postal Zip: L7A1A4
Prov:

Address Geographic

Latitude:	43.7068	***Datum:***	0
Longitude:	-79.8042	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	332810	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe canadienne, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et des produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code:	332810	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		

NAICS Title En: Coating, engraving, cold and heat treating and allied activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et par le froid, et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code: 332810 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, Engraving, Heat Treating and Allied Activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code: 332810 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, Engraving, Heat Treating and Allied Activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code: 332810 ***Start Date:*** 2007
Record Year: 2007 ***End Date:*** 2011
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication

NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NPRI Report

Report ID:	142762	***No of Employees:***	59
Report Year:	2009	***Is Compressor:***	
Company ID:	132739	***Is NPRI Part 4:***	
SWR Report ID:	20090000004774	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2010-04-22 00:00:00.0000000

Company

Company Name:	THE BUTCHER ENGINEERING ENTERPRISES LTD.
DUNS No:	200364693
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	Sodium nitrite (CAS # 7632-00-0), Sulfuric acid (CAS # 7664-93-9), and Volatile Organic Compounds (NA-M16) are not reported in 2009 due to reduced customer demand and Facility Closure on August 31, 2009.
Note:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054593030
First Name:	Sue	***Extension:***	139
Last Name:	Watson	***Fax:***	9054590689
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Human Resources Manager		
Language:	0		
Email:	swatson@butcherent.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054593030

First Name:	Sue	***Extension:***	139
Last Name:	Watson	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	Human Resources Manager		
Language:	0		
Email:	swatson@butcherent.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054593030
First Name:	Colin	***Extension:***	110
Last Name:	McKillop	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	CEO		
Language:	0		
Email:	cmckillop@butcherent.com		

NPRI Report Contact

Contact Type:		***Phone:***	9057611783
First Name:	MIHAELA	***Extension:***	
Last Name:	DRAGHICI	***Fax:***	9057616524
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Consultant		
Language:	0		
Email:	mdraghici@envirovision-inc.com		

NPRI Report

Report ID:	106685	***No of Employees:***	59
Report Year:	2008	***Is Compressor:***	
Company ID:	132739	***Is NPRI Part 4:***	
SWR Report ID:	20080000004774	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2009-05-14 00:00:00.0000000

Company

Company Name:	THE BUTCHER ENGINEERING ENTERPRISES LTD.
DUNS No:	200364693
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	2-BUTOXYETHANOL (CAS # 111-76-2) is not reportable due to chemicals formulation and decreased in usage of materials containing it. PM10 is not reportable due to decreased usage of paints. SODIUM NITRITE (CAS # 7632-00-0) is reportable due chemicals form **Note: data in the [Comment] field for some records is truncated from the source.
Note:	

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9054593030
First Name:	Sue	**Extension:**	139
Last Name:	Watson	**Fax:**	9054590689
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	QMR		
Language:	0		
Email:	swatson@butcherent.com		

NPRI Report Contact

Contact Type:		**Phone:**	9057611783
First Name:	MIHAELA	**Extension:**	
Last Name:	DRAGHICI	**Fax:**	9057616524
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Consultant		
Language:	0		
Email:	mdraghici@envirovision-inc.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054593030
First Name:	Sue	**Extension:**	139
Last Name:	Watson	**Fax:**	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	QMR		
Language:	0		
Email:	swatson@butcherent.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054593030
First Name:	L. Christopher	**Extension:**	111
Last Name:	Butcher	**Fax:**	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	Executive Vice President		
Language:	0		
Email:	cbutcher@butcherent.com		

NPRI Report

Report ID:	124512	**No of Employees:**	118
Report Year:	2007	**Is Compressor:**	
Company ID:	132739	**Is NPRI Part 4:**	
SWR Report ID:	20070000004774	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2008-05-28 00:00:00.0000000

Company

Company Name:	THE BUTCHER ENGINEERING ENTERPRISES LTD.
DUNS No:	200364693
Trade Name En:	
Trade Name Fr:	

Website:

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	Hexavalent chromium compounds (NA-19) is not reported in 2007 (use only Cr VI free paints).
Note:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	4168913267
First Name:	Ted	***Extension:***	
Last Name:	Howard	***Fax:***	9054590689
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Maintenance Manager		
Language:	0		
Email:	thoward@butcherent.com		

NPRI Report Contact

Contact Type:		***Phone:***	9057611783
First Name:	MIHAELA	***Extension:***	
Last Name:	DRAGHICI	***Fax:***	9057616524
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Consultant		
Language:	0		
Email:	mdraghici@envirovision-inc.com		

NPRI Report Contact

Contact Type:		***Phone:***	4168913267
First Name:	Ted	***Extension:***	
Last Name:	Howard	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	Maintenance Manager		
Language:	0		
Email:	thoward@butcherent.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054593030
First Name:	Yong	***Extension:***	110
Last Name:	Lee	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	General Manager		
Language:	0		
Email:	ylee@butcherent.com		

NPRI Report

Report ID:	120014	***No of Employees:***	87
Report Year:	2006	***Is Compressor:***	

Company ID:	132739	**Is NPRI Part 4:**	
SWR Report ID:	20060000004774	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2007-06-01 00:00:00.0000000

Company

Company Name:	THE BUTCHER ENGINEERING ENTERPRISES LTD.
DUNS No:	200364693
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9054593030
First Name:	Bob	**Extension:**	127
Last Name:	Luffman	**Fax:**	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	QS and Environmental Coordinator		
Language:	0		
Email:	bluffman@butcher-eng.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054593030
First Name:	Chris	**Extension:**	111
Last Name:	Butcher	**Fax:**	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	Executive Vice President		
Language:	0		
Email:	cbutcher@butcher-eng.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9054593030
First Name:	Bob	**Extension:**	127
Last Name:	Luffman	**Fax:**	9054590689
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	QS and Environmental Coordinator		
Language:	0		
Email:	bluffman@butcher-eng.com		

NPRI Report Contact

Contact Type:		**Phone:**	4164675555
First Name:	Bijal	**Extension:**	233
Last Name:	Shah	**Fax:**	4164679824
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Engineer		
Language:	0		
Email:	bshah@altech-group.com		

NPRI Report

Report ID:	248027	***No of Employees:***	87
Report Year:	2005	***Is Compressor:***	
Company ID:	148870	***Is NPRI Part 4:***	
SWR Report ID:	20050000004774	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2006-05-30 00:00:00.0000000

Company

Company Name:	THE BUTCHER ENGINEERING ENTERPRISES
DUNS No:	200364693
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	4164675555
First Name:	Bijal	***Extension:***	233
Last Name:	Shah	***Fax:***	4164679824
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Engineer		
Language:	0		
Email:	bshah@altech-group.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054593030
First Name:	Chris	***Extension:***	111
Last Name:	Butcher	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	Executive Vice President		
Language:	0		
Email:	cbutcher@butcher-eng.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054593030
First Name:	Bob	***Extension:***	127
Last Name:	Luffman	***Fax:***	9054590689
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	QS and Environmental Coordinator		
Language:	0		
Email:	bluffman@butcher-eng.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054593030
First Name:	Bob	***Extension:***	127
Last Name:	Luffman	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	QS and Environmental Coordinator		

Language: 0
Email: bluffman@butcher-eng.com

NPRI Report

Report ID: 178216
Report Year: 2004
Company ID: 132739
SWR Report ID: 20040000004774
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 87
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 2005-05-13 00:00:00.0000000

Company

Company Name: THE BUTCHER ENGINEERING ENTERPRISES LTD.
DUNS No: 200364693
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Bob
Last Name: Luffman
Company Name:
Description En:
Description Fr:
Position: QS and Environmental Coordinator
Language: 0
Email: bluffman@butcher-eng.com
Phone: 9054593030
Extension: 127
Fax: 9054590689

NPRI Report Contact

Contact Type: NPRI
First Name: Bob
Last Name: Luffman
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: QS and Environmental Coordinator
Language: 0
Email: bluffman@butcher-eng.com
Phone: 9054593030
Extension: 127
Fax: 9054590689

NPRI Report Contact

Contact Type:
First Name: Chris
Last Name: Butcher
Company Name:
Description En:
Description Fr:
Position: Executive Vice President
Language: 0
Email: cbutcher@butcher-eng.com
Phone: 9054593030
Extension: 111
Fax: 9054590689

NPRI Report Contact

Contact Type:
First Name: Bijal
Last Name: Shah
Phone: 4164675555
Extension: 233
Fax: 4164679824

Company Name:
Description En:
Description Fr:
Position: Environmental Engineer
Language: 0
Email: bshah@altech-group.com

NPRI Report

Report ID: 271489
Report Year: 2003
Company ID: 132739
SWR Report ID: 20030000004774
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 87
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 2005-09-23 00:00:00.0000000

Company

Company Name: THE BUTCHER ENGINEERING ENTERPRISES LTD.
DUNS No: 200364693
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Comment

Description En: Report Submission and Electronic Certification Comment
Description Fr: Soumission de déclaration et attestation électronique
Comment: Change in Carbon Black from 1.700T to 0.017T (due to typographical error).
Note:

NPRI Report Comment

Description En: NPRI report update comment
Description Fr: Commentaire sur la mise à jour du rapport de l'INRP
Comment: Correction in numbers.
Note:

NPRI Report Contact

Contact Type: NPRI
First Name: Bob
Last Name: Luffman
Company Name:
Description En: Public Contact
Description Fr: Responsable des renseignements au public
Position: QS and Environmental Coordinator
Language: 0
Email: bluffman@butcher-eng.com
Phone: 9054593030
Extension: 127
Fax: 9054590689

NPRI Report Contact

Contact Type:
First Name: Chris
Last Name: Butcher
Company Name:
Description En:
Description Fr:
Position: Executive Vice President
Language: 0
Email: cbutcher@butcher-eng.com
Phone: 9054593030
Extension: 111
Fax: 9054590689

NPRI Report Contact

Contact Type:		***Phone:***	9054593030
First Name:	Bob	***Extension:***	127
Last Name:	Luffman	***Fax:***	9054590689
Company Name:			
Description En:			
Description Fr:			
Position:	QS and Environmental Coordinator		
Language:	0		
Email:	bluffman@butcher-eng.com		

NPRI Report Contact

Contact Type:		***Phone:***	5196629168
First Name:	Rob	***Extension:***	0
Last Name:	Toth	***Fax:***	5196629434
Company Name:			
Description En:			
Description Fr:			
Position:	President		
Language:	0		
Email:	rtoth@rtltd.ca		

NPRI ID Facility ID

NPRI ID:	4774
Facility ID:	366868

Facility

Facility ID:	366868	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	332810	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	Vank Kirk Plant		
Website:			

Address

Address1:	105 Van Kirk Dr.
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4
Prov:	

Primary NAICS Details

NAICS Code:	332810	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry

include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe canadienne, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et des produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code:	332810	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code:	332810	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NPRI Report

Report ID:	185181	***No of Employees:***	100
Report Year:	2000	***Is Compressor:***	
Company ID:	148374	***Is NPRI Part 4:***	

SWR Report ID:	20000000004774	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2001-06-01 00:00:00.0000000

Company

Company Name:	The Butcher Engineering Enterprises Limited
DUNS No:	200364693
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	0
First Name:	Chris	**Extension:**	0
Last Name:	Butcher	**Fax:**	0
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	5198231252
First Name:	Angelo	**Extension:**	0
Last Name:	Venerus	**Fax:**	5198232046
Company Name:			
Description En:			
Description Fr:			
Position:	Consultant		
Language:	0		
Email:	vipinc@on.aibn.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9058466838
First Name:	Humberto	**Extension:**	0
Last Name:	Eusebio	**Fax:**	9058466774
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager		
Language:	0		
Email:			

NPRI Report

Report ID:	284431	**No of Employees:**	105
Report Year:	1999	**Is Compressor:**	
Company ID:	148374	**Is NPRI Part 4:**	
SWR Report ID:	19990000004774	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2000-06-01 00:00:00.0000000

Company

Company Name:	The Butcher Engineering Enterprises Limited
DUNS No:	200364693

Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058466838
First Name:	Humberto	***Extension:***	0
Last Name:	Eusebio	***Fax:***	9058466774
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	5198231252
First Name:	Angelo	***Extension:***	0
Last Name:	Venerus	***Fax:***	5198232046
Company Name:			
Description En:			
Description Fr:			
Position:	Consultant		
Language:	0		
Email:	vipinc@on.aibn.com		

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	Chris	***Extension:***	0
Last Name:	Butcher	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President		
Language:	0		
Email:			

NPRI ID Facility ID

NPRI ID:	4774
Facility ID:	343105

Facility

Facility ID:	343105	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	0	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	VAN KIRK PLANT		
Website:			

Address

Address1:	105 Van Kirk Dr.
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4

Prov:

NPRI Report

Report ID:	151447	***No of Employees:***	0
Report Year:	2009	***Is Compressor:***	
Company ID:	134709	***Is NPRI Part 4:***	
SWR Report ID:	20097100004774	***Is Battery:***	
Repor Type ID:	4	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2010-04-22 00:00:00.0000000

Company

Company Name:	THE BUTCHER ENGINEERING ENTERPRISES LTD.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI ID Facility ID

NPRI ID:	4774
Facility ID:	225211

Facility

Facility ID:	225211	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	332810	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	Van Kirk		
Website:			

Address

Address1:	105 Van Kirk Dr.
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4
Prov:	

Primary NAICS Details

NAICS Code:	332810	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe canadienne, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et des produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code: 332810 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, engraving, cold and heat treating and allied activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et par le froid, et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code: 332810 ***Start Date:*** 2022
Record Year: 2022 ***End Date:*** 2026
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, engraving, cold and heat treating and allied activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et par le froid, et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code: 332810 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, Engraving, Heat Treating and Allied Activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le

polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NPRI Report

Report ID:	1643	***No of Employees:***	56
Report Year:	1996	***Is Compressor:***	
Company ID:	101822	***Is NPRI Part 4:***	
SWR Report ID:	19960000004774	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	1997-06-02 00:00:00.0000000

Company

Company Name: The Butcher Engineering Enterprises Limited
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report

Report ID:	2482	**No of Employees:**	45
Report Year:	1995	**Is Compressor:**	
Company ID:	101822	**Is NPRI Part 4:**	
SWR Report ID:	19950000004774	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1996-06-03 00:00:00.0000000

Company

Company Name: The Butcher Engineering Enterprises Limited
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI ID Facility ID

NPRI ID: 4774
Facility ID: 372353

Facility

Facility ID:	372353	**IDM ID:**	0
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	332810	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		

Facility Name: Van Kirk Plant
Website:

Address

Address1: 105 Van Kirk Dr.
Address2:
City: BRAMPTON
Postal Zip: L7A1A4
Prov:

Primary NAICS Details

NAICS Code:	332810	**Start Date:**	2012
Record Year:	2012	**End Date:**	2016

Key Indus Sector En: Other Manufacturing
Key Indus Sector Fr: Autres fabrication
NAICS Title En: Coating, engraving, cold and heat treating and allied activities
NAICS Title Fr: Revêtement, gravure, traitement thermique et par le froid, et activités analogues

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in

plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe canadienne, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et des produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code:	332810	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, engraving, cold and heat treating and allied activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et par le froid, et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter le métal d'autres façons semblables. Ces activités consistent souvent à chauffer le métal, en général pour le durcir.

NAICS Code:	332810	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le flambage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements dont l'activité consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NAICS Code:	332810	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Other Manufacturing		
Key Indus Sector Fr:	Autres fabrication		
NAICS Title En:	Coating, Engraving, Heat Treating and Allied Activities		
NAICS Title Fr:	Revêtement, gravure, traitement thermique et activités analogues		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in coating, engraving, heat treating and similarly processing metal. These activities often involve heating the metal, and the purpose is often to harden it. In general, the hardening of metal is included. Other activities of this industry include tempering, brazing, plating (including electroplating and re-chroming), polishing, sand-blasting and colouring metal and metal products. Establishments that perform these processes on other materials, such as plastics, in addition to metals, as well as establishments primarily engaged in plating with precious metal for the trade are included.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à recouvrir, graver, travailler à chaud ou traiter d'autres façons semblables du métal. Ces activités consistent souvent à chauffer le métal, en général pour le durcir. Habituellement, le durcissement du métal est compris. Parmi les autres activités de cette classe, notons le trempage, le brasage, le placage (y compris la galvanoplastie et le chromage), le polissage, le sablage et la coloration du métal et de produits métalliques. Sont inclus les établissements qui effectuent ces opérations sur d'autres matières, telles que le plastique, en plus des métaux, ainsi que les établissements dont l'activité principale consiste à appliquer des placages en métaux précieux sur des produits destinés à être vendus.

NPRI Report

Report ID:	286271	***No of Employees:***	85
Report Year:	1998	***Is Compressor:***	
Company ID:	101822	***Is NPRI Part 4:***	
SWR Report ID:	19980000004774	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0

New Reporter:	FALSE	***Submit Date:***	1999-06-01 00:00:00.0000000

Company

Company Name:	The Butcher Engineering Enterprises Limited
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	5198231252
First Name:	Angelo	***Extension:***	0
Last Name:	Venerus	***Fax:***	5198232046
Company Name:			
Description En:			
Description Fr:			
Position:	Consultant		
Language:	0		
Email:	vipinc@on.aibn.com		

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	Chris	***Extension:***	0
Last Name:	Butcher	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Vice President		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9058466838
First Name:	Scott	***Extension:***	0
Last Name:	McPherson	***Fax:***	9058466774
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Maintenance Manager		
Language:	0		
Email:			

Alternative Location Info

Facility ID:	356154
Facility Name:	VAN KIRK
Address1:	105 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A4
Province EN:	ON
Latitude:	43.7068
Longitude:	-79.8042

Alternative Location Info

Facility ID:	366867
Facility Name:	VAN KIRK

Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 225211
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 372353
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 225211
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 356154
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 356154
Facility Name: VANK KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366867
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 356154
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366869
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366868
Facility Name: VANK KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366868
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 356154
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DR.
City: BRAMPTON

Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366869
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366867
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366869
Facility Name: VANK KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366868
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 372353
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 343105
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 343105
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 372353
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 343105
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 372353
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 225211
Facility Name: VANK KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON

Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366869
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366869
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 343105
Facility Name: VANK KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 225211
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366868
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366868

Facility Name: VAN KIRK
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366867
Facility Name: VAN KIRK PLANT
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 225211
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 343105
Facility Name: VAN KIRK
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 372353
Facility Name: VANK KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

Alternative Location Info

Facility ID: 366867
Facility Name: VANK KIRK PLANT
Address1: 105 VAN KIRK DR.
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.7068
Longitude: -79.8042

97	22 of 22	SSE/76.1	238.9 / -3.08	VANKIRK 105 VANKIRK BRAMPTON ON L7A1A4	NPR2

NPRI ID: 52 **Latitude:** 45.7406
Facility ID: 315509 **Longitude:** -73.6942
Facility Name: VANKIRK
Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=52

NPRI ID Substances Summary

CAS No: 107-21-1 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: Ethylene glycol
Name French: Éthylène glycol
Sort English: Ethylene glycol
Sort French: Éthylèneglycol

CAS No: 872-50-4 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: N-Methyl-2-pyrrolidone
Name French: N-Méthyl-2-pyrrolidone
Sort English: Methyl-2-pyrrolidone:N-
Sort French: Méthyl-2-pyrrolidone:N-

CAS No: NA - M16 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: Volatile Organic Compounds (VOCs)
Name French: Composés organiques volatils (COV)
Sort English: Volatile Organic Compounds (VOCs)
Sort French: Composés organiques volatils (COV)

CAS No: 1330-20-7 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: Xylene (all isomers)
Name French: Xylène (tous les isomères)
Sort English: Xylene (all isomers)
Sort French: Xylène (tous les isomères)

CAS No: 100-41-4 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE
Name English: Ethylbenzene
Name French: Éthylbenzène
Sort English: Ethylbenzene
Sort French: Éthylbenzène

CAS No: 78-93-3 **Is PAH?:** FALSE
Is VOC?: TRUE **NPRI:** TRUE
Is DF?: FALSE

Name English:	Methyl ethyl ketone		
Name French:	Méthyléthylcétone		
Sort English:	Methyl ethyl ketone		
Sort French:	Méthyléthylcétone		

CAS No:	1330-20-7	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Xylene (mixed isomers)		
Name French:	Xylène (mélanges d'isomères)		
Sort English:	Xylene (mixed isomers)		
Sort French:	Xylène (mélanges d'isomères)		

CAS No:	108-88-3	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Toluene		
Name French:	Toluène		
Sort English:	Toluene		
Sort French:	Toluène		

CAS No:	95-63-6	**Is PAH?:**	FALSE
Is VOC?:	TRUE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	1,2,4-Trimethylbenzene		
Name French:	1,2,4-Triméthylbenzène		
Sort English:	Trimethylbenzene:1,2,4-		
Sort French:	Triméthylbenzène:1,2,4-		

Geographic Location

Report Year:	-1	**Forward Sort Area:**	J6X
Census Subdiv ID:	2464008	**DLS Description:**	
Ecozone ID:	8	**NTS Description:**	C-086-J/031-H-12
Water Survey ID:	2	**Province Code:**	QC
SOMA:	TRUE	**Datum:**	1983.0
ON PEMA:	FALSE	**Latitude:**	45.7406
QC PEMA:	TRUE	**Longitude:**	-73.6942
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	52
Facility ID:	315509

Facility

Facility ID:	315509	**IDM ID:**	0
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	0	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:	VANKIRK		
Website:	www.butcherent.com		

Address

Address1:	105 VanKirk
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4

Prov:

Alternative Location Info

Facility ID: 222549
Facility Name: VANKIRK
Address1: 105 VANKIRK
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 45.7406
Longitude: -73.6942

Alternative Location Info

Facility ID: 365165
Facility Name: VANKIRK
Address1: 105 VANKIRK
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 45.7406
Longitude: -73.6942

Alternative Location Info

Facility ID: 341752
Facility Name: VANKIRK
Address1: 105 VANKIRK
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 45.7406
Longitude: -73.6942

Alternative Location Info

Facility ID: 365235
Facility Name: VANKIRK
Address1: 105 VANKIRK
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 45.7406
Longitude: -73.6942

---

98 | ***1 of 1*** | ***WNW/62.6*** | ***254.1 / 12.15*** | ***SABRINA HOMES (MAYFIELD ACQUISITIONS) INC.***
2719 MAYFIELD ROAD ON
Brampton ON | ***RSC***

RSC No: 223607
RA No:
Status: FILED
Filing Date:
Date Ack:
Date Returned:
Approval Date: August 10, 2017
Cert Date:
Cert Prop Use No:
Curr Property Use:
Intended Prop Use:

X: -79.83048165485297
Y: 43.72780485419365
Latitude: 43.72780486
Longitude: -79.83048166
UTM Coordinates:
Latitude Longitude:
Accuracy Estimate:
Measurement Method:
Mailing Address:
Telephone:
Fax:

Restoration Type:		**Email:**	
Soil Type:		**Postal Code:**	L7A 0C1
Criteria:		**Ministry District:**	
Stratified (Y/N):		**MOE District:**	Halton-Peel
Audit (Y/N):		**SWP Area Name:**	Credit Valley
Entire Leg Prop. (Y/N):		**Qual Person Name:**	IAN SHAW
CPU Issu Sect 1686:		**Consultant:**	
Business Name:	SABRINA HOMES (MAYFIELD ACQUISITIONS) INC.		
Address:	2719 MAYFIELD ROAD ON		
Legal Desc:			
Site Pin:	14251-3642 (LT)		
Asmt Roll No:			
Project Type:	POST2011		
Approval Type:	RSC based on Phase One and Two ESAs		
Applicable Standards:			
PDF Link:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=223607		

99 | ***1 of 10*** | ***SSE/163.7*** | ***239.9 / -2.08*** | ***95 VAN KIRK DR Brampton ON*** | ***WWIS***

Well ID:	7172053	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/22/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z130962	**Contractor:**	7241
Tag:	A123865	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172053.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/24/2011
Year Completed:	2011
Depth (m):	7.01
Latitude:	43.7063564001228
Longitude:	-79.8025381079176
X:	-79.80253795805754
Y:	43.706356398174194
Path:	717\7172053.pdf

Bore Hole Information

Bore Hole ID:	1003610277	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596478.00
Code OB Desc:		**North83:**	4839956.00
Open Hole:		**Org CS:**	UTM83

Cluster Kind:
Date Completed: 10/24/2011
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004088286
Layer: 1
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088289
Layer: 4
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 4.570000171661377
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088288
Layer: 3
Color: 2
General Color: GREY
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 1.5199999809265137
Formation End Depth: 4.570000171661377
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	1004088290
Layer:	5
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	6.099999904632568
Formation End Depth:	7.010000228881836
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088287
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	12
Material 3 Desc:	STONES
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.5199999809265137
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088301
Layer:	3
Plug From:	3.6600000858306885
Plug To:	7.010000228881836
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088300
Layer:	2
Plug From:	0.3100000023841858
Plug To:	3.6600000858306885
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088299
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Method of Construction & Well

Use

Method Construction ID: 1004088298
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004088285
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004088294
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.9600000381469727
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004088295
Layer: 1
Slot: 10
Screen Top Depth: 3.9600000381469727
Screen End Depth: 7.010000228881836
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004088293
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004088291
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 2.130000114440918
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004088292
Diameter: 7.619999885559082
Depth From: 2.130000114440918

Depth To: 7.010000228881836
Hole Depth UOM: m
Hole Diameter UOM: cm

99 **2 of 10** **SSE/163.7** **239.9 / -2.08** **95 VAN KIRK DRIVE Brampton ON** **WWIS**

Well ID: 7172054
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z130963
Tag: A123864
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/22/2011
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172054.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/25/2011
Year Completed: 2011
Depth (m): 6.1
Latitude: 43.7063564001228
Longitude: -79.8025381079176
X: -79.80253795805754
Y: 43.706356398174194
Path: 717\7172054.pdf

Bore Hole Information

Bore Hole ID: 1003610279
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/25/2011
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596478.00
North83: 4839956.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004088305
Layer: 3
Color: 2
General Color: GREY
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 1.5199999809265137
Formation End Depth: 2.740000009536743
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088304
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 28
Material 2 Desc: SAND
Material 3: 12
Material 3 Desc: STONES
Formation Top Depth: 0.3100000023841858
Formation End Depth: 1.5199999809265137
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088307
Layer: 5
Color: 2
General Color: GREY
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 3.9600000381469727
Formation End Depth: 5.179999828338623
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088306
Layer: 4
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 2.740000009536743

Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088308
Layer:	6
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	5.179999828338623
Formation End Depth:	6.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088303
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088318
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.740000009536743
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088317
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088319
Layer:	3
Plug From:	2.740000009536743
Plug To:	6.099999904632568

Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004088316
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004088302
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004088312
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004088313
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004088311
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004088309
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 1.5199999809265137
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID:	1004088310
Diameter:	7.619999885559082
Depth From:	1.5199999809265137
Depth To:	6.099999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

99 | **3 of 10** | **SSE/163.7** | **239.9 / -2.08** | **95 VAN KIRK DR Brampton ON** | **WWIS**

Well ID:	7172055	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/22/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z138894	**Contractor:**	7241
Tag:	A123871	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172055.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/25/2011
Year Completed:	2011
Depth (m):	6.1
Latitude:	43.7063564001228
Longitude:	-79.8025381079176
X:	-79.80253795805754
Y:	43.706356398174194
Path:	717\7172055.pdf

Bore Hole Information

Bore Hole ID:	1003610281	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596478.00
Code OB Desc:		**North83:**	4839956.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/25/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004088322
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088325
Layer:	5
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	3.9600000381469727
Formation End Depth:	6.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088323
Layer:	3
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	1.2200000286102295
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088324
Layer:	4
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85

Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	2.440000057220459
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088321
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088334
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088335
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.740000009536743
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088336
Layer:	3
Plug From:	2.740000009536743
Plug To:	6.099999904632568
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004088333
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID: 1004088320
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004088329
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004088330
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004088328
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004088327
Diameter: 7.619999885559082
Depth From: 2.130000114440918
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004088326
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 2.130000114440918
Hole Depth UOM: m
Hole Diameter UOM: cm

---

99 | ***4 of 10*** | ***SSE/163.7*** | ***239.9 / -2.08*** | ***95 VAN KIRK DRIVE Brampton ON*** | ***WWIS***

Well ID: 7172057
Construction Date:
Flowing (Y/N):
Flow Rate:

Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/22/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z138901	**Contractor:**	7241
Tag:	A123870	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172057.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/25/2011
Year Completed: 2011
Depth (m): 5.49
Latitude: 43.7063564001228
Longitude: -79.8025381079176
X: -79.80253795805754
Y: 43.706356398174194
Path: 717\7172057.pdf

Bore Hole Information

Bore Hole ID:	1003610285	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596478.00
Code OB Desc:		**North83:**	4839956.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/25/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004088357
Layer: 3
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 05
Material 2 Desc: CLAY
Material 3: 12

Material 3 Desc:	STONES
Formation Top Depth:	1.5399999618530273
Formation End Depth:	2.130000114440918
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088356
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.5399999618530273
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088358
Layer:	4
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	2.130000114440918
Formation End Depth:	3.6600000858306885
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088360
Layer:	6
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	4.269999980926514
Formation End Depth:	5.489999771118164
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088355
Layer:	1
Color:	2

General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088359
Layer: 5
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 3.6600000858306885
Formation End Depth: 4.269999980926514
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088369
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088370
Layer: 2
Plug From: 0.3100000023841858
Plug To: 3.0999999046325684
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088371
Layer: 3
Plug From: 3.0999999046325684
Plug To: 5.489999771118164
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004088368
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID:	1004088354
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004088364
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.3499999046325684
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004088365
Layer:	1
Slot:	10
Screen Top Depth:	3.3499999046325684
Screen End Depth:	5.489999771118164
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004088363
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004088361
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	3.0999999046325684
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1004088362
Diameter:	7.619999885559082
Depth From:	3.0999999046325684
Depth To:	5.489999771118164
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
99	5 of 10	SSE/163.7	239.9 / -2.08	95 VAN KIRK DR Brampton ON	WWIS

Well ID: 7172058
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z138902
Tag: A123863
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/22/2011
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172058.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/25/2011
Year Completed: 2011
Depth (m): 5.49
Latitude: 43.7063564001228
Longitude: -79.8025381079176
X: -79.80253795805754
Y: 43.706356398174194
Path: 717\7172058.pdf

Bore Hole Information

Bore Hole ID: 1003610287
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/25/2011
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596478.00
North83: 4839956.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004088375
Layer: 3
Color: 2
General Color: GREY

Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 1.5199999809265137
Formation End Depth: 4.880000114440918
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088373
Layer: 1
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088376
Layer: 4
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 4.880000114440918
Formation End Depth: 5.489999771118164
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088374
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 28
Material 2 Desc: SAND
Material 3: 12
Material 3 Desc: STONES
Formation Top Depth: 0.3100000023841858
Formation End Depth: 1.5199999809265137
Formation End Depth UOM: m

Annular Space/Abandonment

Sealing Record

Plug ID:	1004088387
Layer:	3
Plug From:	2.130000114440918
Plug To:	5.489999771118164
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088385
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088386
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.130000114440918
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004088384
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004088372
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004088380
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	2.440000057220459
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004088381
Layer:	1
Slot:	10
Screen Top Depth:	2.440000057220459
Screen End Depth:	5.489999771118164
Screen Material:	5

Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004088379
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004088378
Diameter:	7.619999885559082
Depth From:	2.130000114440918
Depth To:	5.489999771118164
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1004088377
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	2.130000114440918
Hole Depth UOM:	m
Hole Diameter UOM:	cm

99 | ***6 of 10*** | ***SSE/163.7*** | ***239.9 / -2.08*** | ***95 VAN KIRK DR Brampton ON*** | ***WWIS***

Well ID:	7172060	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/22/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z138885	**Contractor:**	7241
Tag:	A123874	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172060.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/25/2011
Year Completed:	2011
Depth (m):	5.49

Latitude:	43.7063564001228
Longitude:	-79.8025381079176
X:	-79.80253795805754
Y:	43.706356398174194
Path:	717\7172060.pdf

Bore Hole Information

Bore Hole ID:	1003610291	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596478.00
Code OB Desc:		**North83:**	4839956.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/25/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004088409
Layer:	4
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	2.440000057220459
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088408
Layer:	3
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	1.8300000429153442
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088406
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088407
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	12
Material 3 Desc:	STONES
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.8300000429153442
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088410
Layer:	5
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	3.9600000381469727
Formation End Depth:	5.489999771118164
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088419
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088422
Layer:	4

Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088420
Layer: 2
Plug From: 0.3100000023841858
Plug To: 2.440000057220459
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088421
Layer: 3
Plug From: 2.440000057220459
Plug To: 5.489999771118164
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004088418
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004088405
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004088414
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.440000057220459
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004088415
Layer: 1
Slot: 10
Screen Top Depth: 2.440000057220459
Screen End Depth: 5.489999771118164
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID:	1004088413
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004088412
Diameter:	7.619999885559082
Depth From:	2.130000114440918
Depth To:	5.489999771118164
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1004088411
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	2.130000114440918
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

99 ***7 of 10*** ***SSE/163.7*** ***239.9 / -2.08*** ***95 VAN KIRK DRIVE Brampton ON*** ***WWIS***

Well ID:	7172056	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Test Hole	***Date Received:***	11/22/2011
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z138900	***Contractor:***	7241
Tag:	A123868	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172056.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/25/2011
Year Completed:	2011
Depth (m):	4.88
Latitude:	43.7063564001228
Longitude:	-79.8025381079176
X:	-79.80253795805754
Y:	43.706356398174194

Path: 717\7172056.pdf

Bore Hole Information

Bore Hole ID:	1003610283	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596478.00
Code OB Desc:		***North83:***	4839956.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	10/25/2011	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004088338
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088339
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	12
Material 3 Desc:	STONES
Formation Top Depth:	0.3100000023841858
Formation End Depth:	0.6100000143051147
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088340
Layer:	3
Color:	7
General Color:	RED

Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 0.6100000143051147
Formation End Depth: 2.440000057220459
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088342
Layer: 5
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 3.9600000381469727
Formation End Depth: 4.880000114440918
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088341
Layer: 4
Color: 2
General Color: GREY
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 2.440000057220459
Formation End Depth: 3.9600000381469727
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088351
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088353
Layer: 3
Plug From: 1.8300000429153442
Plug To: 4.880000114440918
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088352
Layer:	2
Plug From:	0.3100000023841858
Plug To:	1.8300000429153442
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004088350
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004088337
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004088346
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	2.130000114440918
Casing Diameter:	4.03000020980835
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004088347
Layer:	1
Slot:	10
Screen Top Depth:	2.130000114440918
Screen End Depth:	4.880000114440918
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004088345
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004088344
Diameter:	7.619999885559082

Depth From:	1.2200000286102295
Depth To:	4.880000114440918
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1004088343
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	1.2200000286102295
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

99 | ***8 of 10*** | ***SSE/163.7*** | ***239.9 / -2.08*** | ***95 VAN KIRK DR Brampton ON*** | ***WWIS***

Well ID:	7172051	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/22/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z138884	**Contractor:**	7241
Tag:	A123867	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172051.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/24/2011
Year Completed:	2011
Depth (m):	6.1
Latitude:	43.7063564001228
Longitude:	-79.8025381079176
X:	-79.80253795805754
Y:	43.706356398174194
Path:	717\7172051.pdf

Bore Hole Information

Bore Hole ID:	1003610273	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596478.00
Code OB Desc:		**North83:**	4839956.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/24/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004088109
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 28
Material 2 Desc: SAND
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.3100000023841858
Formation End Depth: 1.5399999618530273
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088108
Layer: 1
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.3100000023841858
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004088110
Layer: 3
Color: 2
General Color: GREY
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 1.5399999618530273
Formation End Depth: 2.430000066757202
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID:	1004088112
Layer:	5
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	3.6600000858306885
Formation End Depth:	6.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088111
Layer:	4
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	2.430000066757202
Formation End Depth:	3.6600000858306885
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088122
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.740000009536743
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088123
Layer:	3
Plug From:	2.740000009536743
Plug To:	6.099999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088121
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004088120

Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1004088107
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004088116
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004088117
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004088115
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004088114
Diameter: 7.619999885559082
Depth From: 1.5199999809265137
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004088113
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 1.5199999809265137
Hole Depth UOM: m
Hole Diameter UOM: cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
99	9 of 10	SSE/163.7	239.9 / -2.08	95 VAN KIRK DR Brampton ON	WWIS

Well ID: 7172059
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z138903
Tag: A123872
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/22/2011
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172059.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/25/2011
Year Completed: 2011
Depth (m): 4.88
Latitude: 43.7063564001228
Longitude: -79.8025381079176
X: -79.80253795805754
Y: 43.706356398174194
Path: 717\7172059.pdf

Bore Hole Information

Bore Hole ID: 1003610289
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/25/2011
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596478.00
North83: 4839956.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004088393
Layer: 5

Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	3.9600000381469727
Formation End Depth:	4.880000114440918
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088390
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	12
Material 3 Desc:	STONES
Formation Top Depth:	0.3100000023841858
Formation End Depth:	1.2200000286102295
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088392
Layer:	4
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	2.440000057220459
Formation End Depth:	3.9600000381469727
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088391
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	1.2200000286102295
Formation End Depth:	2.440000057220459
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088389
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	77
Material 2 Desc:	LOOSE
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088404
Layer:	3
Plug From:	1.8799999952316284
Plug To:	4.880000114440918
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088403
Layer:	2
Plug From:	0.3100000023841858
Plug To:	1.8799999952316284
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004088402
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1004088401
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004088388
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID: 1004088397
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.8799999952316284
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004088398
Layer: 1
Slot: 10
Screen Top Depth: 1.8799999952316284
Screen End Depth: 4.880000114440918
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.820000171661377

Water Details

Water ID: 1004088396
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004088394
Diameter: 11.430000305175781
Depth From: 0.0
Depth To: 1.5199999809265137
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004088395
Diameter: 7.619999885559082
Depth From: 1.5199999809265137
Depth To: 4.880000114440918
Hole Depth UOM: m
Hole Diameter UOM: cm

99 ***10 of 10*** ***SSE/163.7*** ***239.9 / -2.08*** ***95 VANKIRK DR Brampton ON*** ***WWIS***

Well ID: 7172052
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z140333
Tag: A123866
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/22/2011
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7

Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7172052.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/24/2011
Year Completed:	2011
Depth (m):	5.18
Latitude:	43.7063564001228
Longitude:	-79.8025381079176
X:	-79.80253795805754
Y:	43.706356398174194
Path:	717\7172052.pdf

Bore Hole Information

Bore Hole ID:	1003610275	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596478.00
Code OB Desc:		**North83:**	4839956.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/24/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004088230
Layer:	4
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	3.6600000858306885
Formation End Depth:	4.269999980926514
Formation End Depth UOM:	m

Overburden and Bedrock

Materials Interval

Formation ID:	1004088227
Layer:	1
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088231
Layer:	5
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	4.269999980926514
Formation End Depth:	5.179999828338623
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088229
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	1.5399999618530273
Formation End Depth:	3.6600000858306885
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004088228
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	85
Material 3 Desc:	SOFT

Formation Top Depth: 0.3100000023841858
Formation End Depth: 1.5399999618530273
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088241
Layer: 2
Plug From: 0.3100000023841858
Plug To: 2.130000114440918
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088242
Layer: 3
Plug From: 2.130000114440918
Plug To: 5.179999828338623
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004088240
Layer: 1
Plug From: 0.0
Plug To: 0.3100000023841858
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004088239
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004088226
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004088235
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 2.130000114440918
Casing Diameter: 4.03000020980835
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1004088236
Layer:	1
Slot:	10
Screen Top Depth:	2.130000114440918
Screen End Depth:	5.179999828338623
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	4.820000171661377

Water Details

Water ID:	1004088234
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004088233
Diameter:	7.619999885559082
Depth From:	2.130000114440918
Depth To:	5.179999828338623
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1004088232
Diameter:	11.430000305175781
Depth From:	0.0
Depth To:	2.130000114440918
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

100 | ***1 of 3*** | ***WNW/247.2*** | ***255.9 / 14.00*** | ***GREAT-L DEV. LTD. - LOT 17, CONC. 1 WHS CRESTHAVEN RD./MAYFIELD RD. BRAMPTON CITY ON*** | ***CA***

Certificate #:	3-0968-92-
Application Year:	92
Issue Date:	8/7/1992
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

---

100 | ***2 of 3*** | ***WNW/247.2*** | ***255.9 / 14.00*** | ***GREAT-L DEV. LTD. - LOT 17, CONC. 1 WHS CRESTHAVEN RD./MAYFIELD RD. BRAMPTON CITY ON*** | ***CA***

Certificate #:	7-0781-92-
Application Year:	92

Issue Date:	8/7/1992
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

---

100 | **3 of 3** | **WNW/247.2** | **255.9 / 14.00** | **VAUGHANWOOD DEV. LTD. AND DENCO PROP. CA**
ROBERTSON DAVIES DR/MAYFIELD
BRAMPTON CITY ON | **CA**

Certificate #:	3-0461-96-
Application Year:	96
Issue Date:	5/27/1996
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

---

101 | **1 of 1** | **SE/130.1** | **238.9 / -3.08** | **ON** | **WWIS**

Well ID:	7283936	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	03/30/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C35162	**Contractor:**	7215
Tag:	A217082	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1006372724	**Tag No:**	A217082
Depth M:		**Contractor:**	7215
Year Completed:	2016	**Latitude:**	43.7074526289916
Well Completed Dt:	12/09/2016	**Longitude:**	-79.7988920065593

Audit No:	C35162	**Y:**	43.70745262698781
Path:		**X:**	-79.79889185728189

Bore Hole Information

Bore Hole ID:	1006372724	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596770.00
Code OB Desc:		**North83:**	4840082.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12/09/2016	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

102	1 of 1	SSE/147.7	239.9 / -2.08	ON	WWIS

Well ID:	7294565	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	09/12/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C37490	**Contractor:**	7215
Tag:	A230130	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1006721601	**Tag No:**	A230130
Depth M:		**Contractor:**	7215
Year Completed:	2017	**Latitude:**	43.7063625414508
Well Completed Dt:	08/04/2017	**Longitude:**	-79.8022649287377
Audit No:	C37490	**Y:**	43.706362539379555
Path:		**X:**	-79.80226477866941

Bore Hole Information

Bore Hole ID:	1006721601	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596500.00
Code OB Desc:		**North83:**	4839957.00

Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/04/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

103 **1 of 1** **SSE/28.0** **237.9 / -4.08** **ON** **WWIS**

Well ID:	7306218	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	02/15/2018
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C39733	**Contractor:**	7215
Tag:	A238234	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1006989810	**Tag No:**	A238234
Depth M:		**Contractor:**	7215
Year Completed:	2018	**Latitude:**	43.7069966479713
Well Completed Dt:	01/19/2018	**Longitude:**	-79.8000554108978
Audit No:	C39733	**Y:**	43.70699664638292
Path:		**X:**	-79.80005526058525

Bore Hole Information

Bore Hole ID:	1006989810	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596677.00
Code OB Desc:		**North83:**	4840030.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/19/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	1 of 3	SSE/6.5	238.3 / -3.68	The Corporation of the City of Brampton McLaughlin Road (from Lowry Drive to Wanless Drive) Brampton ON L6Y 4R2	ECA

Approval No:	5356-6BENE5	**MOE District:**	Halton-Peel
Approval Date:	2005-04-15	**City:**	
Status:	Approved	**Longitude:**	-79.8003
Record Type:	ECA	**Latitude:**	43.7069
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	The Corporation of the City of Brampton		
Address:	McLaughlin Road (from Lowry Drive to Wanless Drive)		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/1147-6B6VUQ-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	2 of 3	SSE/6.5	238.3 / -3.68	Hurontario Street GP Inc. Brampton ON M9C 5L5	ECA

Approval No:	7657-6WXQ89	**MOE District:**	Halton-Peel
Approval Date:	2007-01-10	**City:**	
Status:	Approved	**Longitude:**	-79.80030000000001
Record Type:	ECA	**Latitude:**	43.706900000000005
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Business Name:	Hurontario Street GP Inc.		
Address:			
Full Address:			
Full PDF Link:			
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	3 of 3	SSE/6.5	238.3 / -3.68	Hurontario Street GP Inc. Brampton ON M9C 5L5	ECA

Approval No:	3403-6WXQ2F	**MOE District:**	Halton-Peel
Approval Date:	2007-01-10	**City:**	
Status:	Approved	**Longitude:**	-79.8003
Record Type:	ECA	**Latitude:**	43.7069
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Hurontario Street GP Inc.		
Address:			
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3607-6WNMAL-14.pdf		
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
105	1 of 1	WNW/85.1	254.8 / 12.90	2719 MAYFIELD ROAD lot 17 con 1 Brampton ON	WWIS

Well ID:	7248959	**Flowing (Y/N):**	

Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	09/29/2015
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z218402	***Contractor:***	7147
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	017
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1005707705	***Tag No:***	
Depth M:		***Contractor:***	7147
Year Completed:	2015	***Latitude:***	43.7278167785301
Well Completed Dt:	09/11/2015	***Longitude:***	-79.8307669938597
Audit No:	Z218402	***Y:***	43.727816777168684
Path:		***X:***	-79.83076684379388

Bore Hole Information

Bore Hole ID:	1005707705	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	594170.00
Code OB Desc:		***North83:***	4842307.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	09/11/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005738923
Layer:	1
Plug From:	0.0
Plug To:	2.200000047683716
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1005738924
Layer:	2

Plug From: 2.200000047683716
Plug To: 17.399999618530273
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005738925
Layer: 3
Plug From:
Plug To: 17.399999618530273
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005738922
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1005738916
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005738920
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 17.399999618530273
Casing Diameter: 15.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005738921
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 1005738919
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 3.700000047683716
Water Found Depth UOM: m

Hole Diameter

Hole ID:	1005738918
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

106 | ***1 of 1*** | ***WNW/9.2*** | ***254.8 / 12.84*** | ***2650 Mayfield Road lot 18 con 1 Brampton ON*** | ***WWIS***

Well ID:	7378696	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	01/19/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	E8WCIBBP	***Contractor:***	7732
Tag:	_NO_TAG	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	018
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378696.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/13/2021
Year Completed:	2021
Depth (m):	
Latitude:	43.7286888353939
Longitude:	-79.8306382813563
X:	-79.83063813134612
Y:	43.7286888335637
Path:	737\7378696.pdf

Bore Hole Information

Bore Hole ID:	1008554344	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	594179.00
Code OB Desc:		***North83:***	4842404.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/13/2021	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			

Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008554441
Layer: 1
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008554494
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008554510
Layer: 1
Plug From: 0.0
Plug To: 6.099999904632568
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008554377
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008554456
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008554471
Layer: 1

Slot:
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008554378
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008554408
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 0.03999999910593033
Water Found Depth UOM: m

---

107 ***1 of 13*** ***SSE/246.1*** ***239.9 / -2.08*** ***80 Van Kirk Drive Brampton ON L7A 1B1*** ***EHS***

Order No: 20081002004
Status: C
Report Type: Standard Report
Report Date: 10/14/2008
Date Received: 10/2/2008
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: Van Kirk Drive and Regan Road
Municipality:
Client Prov/State: IL
Search Radius (km): 0.25
X: -79.802877
Y: 43.705292

---

107 ***2 of 13*** ***SSE/246.1*** ***239.9 / -2.08*** ***Archway Marketing Service 80 Van Kirk Drive Brampton ON L7A 1B1*** ***GEN***

Generator Info

Generator No: ON2699042
Approval Years: 07,08
Status:
PO Box No:
Country:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 314990

Co Admin:
Phone No Admin:
SIC Description: All Other Textile Product Mills

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

107 | ***3 of 13*** | ***SSE/246.1*** | ***239.9 / -2.08*** | ***Archway Marketing Services Inc***
80 Van Kirk Dr Unit 8
Brampton ON L7A 1B1 | ***SCT***

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Quick Printing
SIC/NAICS Code: 323114

Description: Other Printing
SIC/NAICS Code: 323119

Description: All Other Support Services
SIC/NAICS Code: 561990

Description: Business Service Centres
SIC/NAICS Code: 561430

Description: Investment Advice
SIC/NAICS Code: 523930

Description: Direct Mail Advertising
SIC/NAICS Code: 541860

Description: Digital Printing
SIC/NAICS Code: 323115

---

107 | ***4 of 13*** | ***SSE/246.1*** | ***239.9 / -2.08*** | ***80 Van Kirk Drive***
Brampton ON | ***EHS***

Order No: 20120704033
Status: C
Report Type: Standard Report
Report Date: 13-JUL-12
Date Received: 04-JUL-12
Previous Site Name:
Lot/Building Size: 9.41 AC
Additional Info Ordered:

Nearest Intersection:
Municipality: Brampton
Client Prov/State: ON
Search Radius (km): .25
X: -79.802746
Y: 43.705342

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
107	5 of 13	SSE/246.1	239.9 / -2.08	PIPELINE HIT - 1 ¼" 80 VAN KIRK DRIVE,UNIT 2,BRAMPTON,ON,L7A 1B1,CA ON	PINC

Incident Id:		Pipe Material:	
Incident No:	1290746	Fuel Category:	
Incident Reported Dt:	11/26/2013	Health Impact:	
Type:	FS-Pipeline Incident	Environment Impact:	
Status Code:		Property Damage:	
Tank Status:	Pipeline Damage Reason Est	Service Interrupt:	
Task No:		Enforce Policy:	
Spills Action Centre:		Public Relation:	
Fuel Type:		Pipeline System:	
Fuel Occurrence Tp:		PSIG:	
Date of Occurrence:		Attribute Category:	
Occurrence Start Dt:		Regulator Location:	
Depth:		Method Details:	
Customer Acct Name:	PIPELINE HIT - 1 ¼"		
Incident Address:	80 VAN KIRK DRIVE,UNIT 2,BRAMPTON,ON,L7A 1B1,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
107	6 of 13	SSE/246.1	239.9 / -2.08	PIPELINE HIT 1 1/4" 80 VAN KIRK, UNIT 1,,BRAMPTON,ON,L7A 1B1, CA ON	PINC

Incident Id:		Pipe Material:	
Incident No:	1267950	Fuel Category:	
Incident Reported Dt:	10/24/2013	Health Impact:	
Type:	FS-Pipeline Incident	Environment Impact:	
Status Code:		Property Damage:	
Tank Status:	Pipeline Damage Reason Est	Service Interrupt:	
Task No:		Enforce Policy:	
Spills Action Centre:		Public Relation:	
Fuel Type:		Pipeline System:	
Fuel Occurrence Tp:		PSIG:	
Date of Occurrence:		Attribute Category:	
Occurrence Start Dt:		Regulator Location:	
Depth:		Method Details:	
Customer Acct Name:	PIPELINE HIT 1 1/4"		
Incident Address:	80 VAN KIRK, UNIT 1,,BRAMPTON,ON,L7A 1B1,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
107	7 of 13	SSE/246.1	239.9 / -2.08	SOTAWALL INC. 80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	GEN

Generator Info

Generator No:	ON2736783	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	333120
Country:	Canada		
Co Admin:	FERNANADO PINTO		
Phone No Admin:	9058463177 Ext.		
SIC Description:	CONSTRUCTION MACHINERY MANUFACTURING		

Waste Detail(s)

Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
107	8 of 13	SSE/246.1	239.9 / -2.08	SOTAWALL INC. 80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	GEN

Generator Info

Generator No:	ON2736783	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	333120
Country:	Canada		
Co Admin:	FERNANADO PINTO		
Phone No Admin:	9058463177 Ext.		
SIC Description:	CONSTRUCTION MACHINERY MANUFACTURING		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
107	9 of 13	SSE/246.1	239.9 / -2.08	SOTAWALL LTD. 80 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	GEN

Generator Info

Generator No:	ON2736783	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	262 L
Waste Class Name:	Detergents and soaps

Waste Detail(s)

Waste Class:	253 T
Waste Class Name:	Emulsified oils

Waste Detail(s)

Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class:	146 T
Waste Class Name:	Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class:	252 T
Waste Class Name:	Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 253 L
Waste Class Name: Emulsified oils

---

107 **10 of 13** **SSE/246.1** **239.9 / -2.08** **70 & 80 Van Kirk Drive Brampton ON** **EHS**

Order No: 20160928006
Status: C
Report Type: Custom Report
Report Date: 03-OCT-16
Date Received: 28-SEP-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.802165
Y: 43.704922

---

107 **11 of 13** **SSE/246.1** **239.9 / -2.08** **SOTAWALL LTD.**
80 VAN KIRK DRIVE
BRAMPTON ON L7A 1B1 **GEN**

Generator Info

Generator No: ON2736783
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 253 T
Waste Class Name: Emulsified oils

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

107 | ***12 of 13*** | ***SSE/246.1*** | ***239.9 / -2.08*** | ***SOTAWALL LTD.***
80 VAN KIRK DRIVE
BRAMPTON ON L7A 1B1 | ***GEN***

Generator Info

Generator No: ON2736783
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Detail(s)

Waste Class: 253 T
Waste Class Name: Emulsified oils

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

107	13 of 13	SSE/246.1	239.9 / -2.08	**Harmon Facades ULC (aka Sotawall)** **80 VAN KIRK DRIVE** **BRAMPTON ON**	GEN

Generator Info

Generator No: ON2736783
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 253 T
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 253 L
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 252 T
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Detail(s)

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 262 L
Waste Class Name: DETERGENTS/SOAPS

Generator Info as of Dec 2024

Generator No: ON2736783

Generator Company Name:	Harmon Facades ULC (aka Sotawall)
Street:	80 VAN KIRK DRIVE
City:	BRAMPTON
Province State:	Ontario
Country:	Canada
Postal Code:	L7A1B1
Waste Class:	252 L,122 C,112 C,252 T,253 L,145 L,146 T,262 L,253 T,145 I,212 L,232 L,232 I

Waste Class Decoded:

252 - WASTE OILS & LUBRICANTS; 122 - ALKALINE WASTES - OTHER METALS; 112 - ACID WASTE - HEAVY METALS; 252 - WASTE OILS & LUBRICANTS; 253 - EMULSIFIED OILS; 145 - PAINT/PIGMENT/COATING RESIDUES; 146 - OTHER SPECIFIED INORGANICS; 262 - DETERGENTS/SOAPS; 253 - EMULSIFIED OILS; 145 - PAINT/PIGMENT/COATING RESIDUES; 212 - ALIPHATIC SOLVENTS; 232 - POLYMERIC RESINS; 232 - POLYMERIC RESINS

2017 Generator Info

Gen No:	ON2736783	***Choice of Contact:***	CO_OFFICIAL
ID:	11151	***Phone No Official:***	9058463177 Ext.2255
Contaminated Fac:	N	***Phone No Admin:***	9058463177 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	333120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SOTAWALL LTD.		
Gen Div:			
Gen Op Name:	SOTAWALL LTD.		
Gen Op Div:			
Site Adrs1:	80 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1B1		
Site Country:	Canada		
Co Official:	DARCY BADBURN		
Co Admin:	FERNANADO PINTO		

2017 Generator Manifest

ID:	32810	***Sum Received Qty:***	80.0
Generator No:	ON2736783	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	L	***District:***	305
Waste Code:	145		

2017 Generator Manifest

ID:	32812	***Sum Received Qty:***	38.0
Generator No:	ON2736783	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	252		

2017 Generator Manifest

ID:	32809	***Sum Received Qty:***	171.0
Generator No:	ON2736783	***Waste Class Name:***	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	***Count Manifests:***	4

Waste Char: C
Waste Code: 122
District: 305

2017 Generator Manifest

ID: 32811
Generator No: ON2736783
Receiver Type: 035
Waste Char: T
Waste Code: 146
Sum Received Qty: 170.0
Waste Class Name: OTHER SPECIFIED INORGANICS
Count Manifests: 2
District: 305

2017 Generator Manifest

ID: 32813
Generator No: ON2736783
Receiver Type: 035
Waste Char: L
Waste Code: 253
Sum Received Qty: 57.0
Waste Class Name: EMULSIFIED OILS
Count Manifests: 1
District: 305

2017 Generator Manifest

ID: 32808
Generator No: ON2736783
Receiver Type: 035
Waste Char: C
Waste Code: 112
Sum Received Qty: 57.0
Waste Class Name: ACID WASTE - HEAVY METALS
Count Manifests: 1
District: 305

2018 Generator Info

Gen No: ON2736783
ID: 10901
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 333120
NAICS Code2:
NAICS Code3:
Gen Name: SOTAWALL LTD.
Gen Div:
Gen Op Name: SOTAWALL LTD.
Gen Op Div:
Site Adrs1: 80 VAN KIRK DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: DARCY BADBURN
Co Admin: FERNANADO PINTO
Choice of Contact: CO_OFFICIAL
Phone No Official: 9058463177 Ext.2255
Phone No Admin: 9058463177 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2018 Generator Manifest

ID: 32541
Generator No: ON2736783
Receiver Type: 035
Waste Char: T
Waste Code: 253
Sum Received Qty: 57.0
Waste Class Name: EMULSIFIED OILS
Count Manifests: 1
District: 305

2018 Generator Manifest

ID:	32542	**Sum Received Qty:**	19.0
Generator No:	ON2736783	**Waste Class Name:**	DETERGENTS/SOAPS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	262		

2018 Generator Manifest

ID:	32539	**Sum Received Qty:**	615.0
Generator No:	ON2736783	**Waste Class Name:**	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	I	**District:**	305
Waste Code:	145		

2018 Generator Manifest

ID:	32538	**Sum Received Qty:**	19.0
Generator No:	ON2736783	**Waste Class Name:**	ALKALINE WASTES - OTHER METALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	C	**District:**	305
Waste Code:	122		

2018 Generator Manifest

ID:	32540	**Sum Received Qty:**	152.0
Generator No:	ON2736783	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	305
Waste Code:	252		

2019 Generator Info

Gen No:	ON2736783	**Choice of Contact:**	CO_OFFICIAL
ID:	10602	**Phone No Official:**	9058463177 Ext.2255
Contaminated Fac:	N	**Phone No Admin:**	9058463177 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	333120	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	SOTAWALL LTD.		
Gen Div:			
Gen Op Name:	SOTAWALL LTD.		
Gen Op Div:			
Site Adrs1:	80 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1B1		
Site Country:	Canada		
Co Official:	DARCY BADBURN		
Co Admin:	FERNANADO PINTO		

2019 Generator Manifest

ID:	31806	**Sum Received Qty:**	19.0
Generator No:	ON2736783	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305

Waste Code: 252

2019 Generator Manifest

ID: 31807
Generator No: ON2736783
Receiver Type: 035
Waste Char: T
Waste Code: 252
Sum Received Qty: 19.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 305

2019 Generator Manifest

ID: 31808
Generator No: ON2736783
Receiver Type: 035
Waste Char: L
Waste Code: 253
Sum Received Qty: 600.0
Waste Class Name: EMULSIFIED OILS
Count Manifests: 1
District: 305

2019 Generator Manifest

ID: 31809
Generator No: ON2736783
Receiver Type: 035
Waste Char: T
Waste Code: 253
Sum Received Qty: 114.0
Waste Class Name: EMULSIFIED OILS
Count Manifests: 1
District: 305

2019 Generator Manifest

ID: 31804
Generator No: ON2736783
Receiver Type: 035
Waste Char: C
Waste Code: 112
Sum Received Qty: 133.0
Waste Class Name: ACID WASTE - HEAVY METALS
Count Manifests: 2
District: 305

2019 Generator Manifest

ID: 31805
Generator No: ON2736783
Receiver Type: 035
Waste Char: C
Waste Code: 122
Sum Received Qty: 19.0
Waste Class Name: ALKALINE WASTES - OTHER METALS
Count Manifests: 1
District: 305

2020 Generator Info

Gen No: ON2736783
ID: 10241
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 333120
NAICS Code2:
NAICS Code3:
Gen Name: SOTAWALL LTD.
Gen Div:
Gen Op Name: SOTAWALL LTD.
Gen Op Div:
Site Adrs1: 80 VAN KIRK DRIVE
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Choice of Contact: CO_OFFICIAL
Phone No Official: 9058463177 Ext.2255
Phone No Admin: 9058463177 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: DARCY BADBURN
Co Admin: FERNANADO PINTO

2020 Generator Manifest

ID: 29051
Generator No: ON2736783
Receiver Type: 035
Waste Char: L
Waste Code: 145
Sum Received Qty: 19.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 305

2020 Generator Manifest

ID: 29053
Generator No: ON2736783
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 19.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 305

2020 Generator Manifest

ID: 29054
Generator No: ON2736783
Receiver Type: 035
Waste Char: T
Waste Code: 253
Sum Received Qty: 205.0
Waste Class Name: EMULSIFIED OILS
Count Manifests: 1
District: 305

2020 Generator Manifest

ID: 29050
Generator No: ON2736783
Receiver Type: 035
Waste Char: I
Waste Code: 145
Sum Received Qty: 205.0
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES
Count Manifests: 1
District: 305

2020 Generator Manifest

ID: 29052
Generator No: ON2736783
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 19.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 305

2021 Generator Info

Gen No: ON2736783
ID: 10024
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 333120
NAICS Code2:
NAICS Code3:
Gen Name: SOTAWALL LTD.
Gen Div:
Gen Op Name: SOTAWALL LTD.
Gen Op Div:
Site Adrs1: 80 VAN KIRK DRIVE
Site Bldg:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9058463177 Ext.2255
Phone No Admin: 9058463177 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A 1B1
Site Country: Canada
Co Official: DARCY BADBURN
Co Admin: FERNANADO PINTO

2021 Generator Manifest

ID: 29252
Generator No: ON2736783
Receiver Type: 035
Waste Char: L
Waste Code: 253
Sum Received Qty: 205.0
Waste Class Name: EMULSIFIED OILS
Count Manifests: 1
District: 306

---

108 | ***1 of 10*** | ***SE/157.5*** | ***239.9 / -2.08*** | ***10254 Hurontario St Brampton ON*** | ***EHS***

Order No: 20150312070
Status: C
Report Type: Custom Report
Report Date: 19-MAR-15
Date Received: 12-MAR-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.79697
Y: 43.70887

---

108 | ***2 of 10*** | ***SE/157.5*** | ***239.9 / -2.08*** | ***10254 Hurontario St Brampton ON L7A0E4*** | ***EHS***

Order No: 20141104031
Status: C
Report Type: Custom Report
Report Date: 10-NOV-14
Date Received: 04-NOV-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.796967
Y: 43.70885

---

108 | ***3 of 10*** | ***SE/157.5*** | ***239.9 / -2.08*** | ***10254 Hurontario St Brampton ON L7A0E4*** | ***EHS***

Order No: 20160226110
Status: C
Report Type: Custom Report
Report Date: 04-MAR-16
Date Received: 26-FEB-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.79696
Y: 43.708859

---

108 | ***4 of 10*** | ***SE/157.5*** | ***239.9 / -2.08*** | ***10254 HURONTARIO PROPERTY INC. 10254 HURONTARIO STREET ON Brampton ON*** | ***RSC***

RSC No: 225037
X: -79.79858987135036

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

RA No:		**Y:**	43.70952934816374
Status:	FILED	**Latitude:**	43.70952935
Filing Date:		**Longitude:**	-79.79858987
Date Ack:		**UTM Coordinates:**	
Date Returned:		**Latitude Longitude:**	
Approval Date:	October 5, 2018	**Accuracy Estimate:**	
Cert Date:		**Measurement Method:**	
Cert Prop Use No:		**Mailing Address:**	
Curr Property Use:		**Telephone:**	
Intended Prop Use:		**Fax:**	
Restoration Type:		**Email:**	
Soil Type:		**Postal Code:**	L7A 0E4
Criteria:		**Ministry District:**	
Stratified (Y/N):		**MOE District:**	Halton-Peel
Audit (Y/N):		**SWP Area Name:**	Toronto
Entire Leg Prop. (Y/N):		**Qual Person Name:**	FREDERICK TAYLOR
CPU Issu Sect 1686:		**Consultant:**	

Business Name: 10254 HURONTARIO PROPERTY INC.
Address: 10254 HURONTARIO STREET ON
Legal Desc:
Site Pin: 14249-0275 (LT)
Asmt Roll No:
Project Type: POST2011
Approval Type: RSC based on Phase One and Two ESAs
Applicable Standards:
PDF Link: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=225037

---

108 | ***5 of 10*** | ***SE/157.5*** | ***239.9 / -2.08*** | ***10254 HURONTARIO PROPERTY INC.***
10254 HURONTARIO STREET ON
Brampton ON | ***RSC***

RSC No:	225036	**X:**	-79.7968366734278
RA No:		**Y:**	43.70817463976197
Status:	FILED	**Latitude:**	43.70817464
Filing Date:		**Longitude:**	-79.79683667
Date Ack:		**UTM Coordinates:**	
Date Returned:		**Latitude Longitude:**	
Approval Date:	September 27, 2018	**Accuracy Estimate:**	
Cert Date:		**Measurement Method:**	
Cert Prop Use No:		**Mailing Address:**	
Curr Property Use:		**Telephone:**	
Intended Prop Use:		**Fax:**	
Restoration Type:		**Email:**	
Soil Type:		**Postal Code:**	L7A 0E4
Criteria:		**Ministry District:**	
Stratified (Y/N):		**MOE District:**	Halton-Peel
Audit (Y/N):		**SWP Area Name:**	Credit Valley
Entire Leg Prop. (Y/N):		**Qual Person Name:**	FREDERICK TAYLOR
CPU Issu Sect 1686:		**Consultant:**	

Business Name: 10254 HURONTARIO PROPERTY INC.
Address: 10254 HURONTARIO STREET ON
Legal Desc:
Site Pin: 14249-0276 (LT)
Asmt Roll No:
Project Type: POST2011
Approval Type: RSC based on Phase One and Two ESAs
Applicable Standards:
PDF Link: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=225036

---

108 | ***6 of 10*** | ***SE/157.5*** | ***239.9 / -2.08*** | ***10254 Hurontario St***
Brampton ON L7A0E4 | ***EHS***

Order No:	20171208079	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	15-DEC-17	**Search Radius (km):**	.3
Date Received:	08-DEC-17	**X:**	-79.796988
Previous Site Name:		**Y:**	43.708876
Lot/Building Size:			
Additional Info Ordered:			

108 **7 of 10** **SE/157.5** **239.9 / -2.08** **10254 Hurontario Property Inc.** **ECA**
10254 Hurontario Street
Brampton ON M9C 1B8

Approval No:	2016-B88JPF	**MOE District:**	
Approval Date:	2019-01-10	**City:**	
Status:	Approved	**Longitude:**	
Record Type:	ECA	**Latitude:**	
Link Source:	IDS	**Geometry X:**	
SWP Area Name:		**Geometry Y:**	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: 10254 Hurontario Property Inc.
Address: 10254 Hurontario Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4636-B7JK8U-13.pdf
PDF Site Location:

108 **8 of 10** **SE/157.5** **239.9 / -2.08** **10254 Hurontario Property Inc.** **ECA**
10254 Hurontario Street
Brampton ON M9C 1B8

Approval No:	7454-B8MSFM	**MOE District:**	Halton-Peel
Approval Date:	2019-02-02	**City:**	
Status:	Approved	**Longitude:**	-79.79699
Record Type:	ECA	**Latitude:**	43.708887
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: 10254 Hurontario Property Inc.
Address: 10254 Hurontario Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7572-B8BLW2-14.pdf
PDF Site Location:

108 **9 of 10** **SE/157.5** **239.9 / -2.08** **10254 Hurontario Property Inc.** **ECA**
10254 Hurontario Street
Brampton ON M9C 1B8

Approval No:	0911-BD8KNM	**MOE District:**	Halton-Peel
Approval Date:	2019-06-27	**City:**	
Status:	Approved	**Longitude:**	-79.79699
Record Type:	ECA	**Latitude:**	43.708887
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: 10254 Hurontario Property Inc.
Address: 10254 Hurontario Street
Full Address:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3558-BCWP68-14.pdf
PDF Site Location:

---

108 | ***10 of 10*** | ***SE/157.5*** | ***239.9 / -2.08*** | ***CT REIT (Hurontario) Limited Partnership, by its g***
10254 Hurontario Street
Brampton ON L7A 0E4 | ***GEN***

Generator Info

Generator No: ON8868731
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

109 | ***1 of 1*** | ***WNW/192.1*** | ***255.9 / 13.94*** | ***GB (MAYFIELD 2) INC.***
2650 Mayfield Road
Caledon ON L7C 3K7 | ***EASR***

Approval No: R-009-7173722431
Status: REGISTERED
Date: April 7, 2022
Record Type: EASR
Link Source: MOFA
Project Type: Water Taking - Construction Dewatering
Full Address:
Approval Type: EASR-Water Taking - Construction Dewatering
SWP Area Name: Credit Valley
MOE District: Halton-Peel
Municipality: Caledon
Latitude: 43.72916667
Longitude: -79.83305556
Geometry X: -8886975.0929000005
Geometry Y: 5423625.3147999998

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PDF NAICS Code:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2618171
PDF Site Location: 2650 Mayfield Road
Caledon ON L7C 3K7

---

110 | **1 of 36** | **SSE/62.1** | **238.9 / -3.08** | **COPPERWELD CANADA, SONCO STEEL TUBE DIV.**
95 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | **CA**

Certificate #: 8-3097-98-
Application Year: 98
Issue Date: //
Approval Type: Industrial air
Status: In progress
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: VENT/HOODS FOR WELDING OPERATIONS
Contaminants:
Emission Control:

---

110 | **2 of 36** | **SSE/62.1** | **238.9 / -3.08** | **SONCO STEEL TUBE LTD.**
SONCO, 95 VAN KIRK DRIVE, BRAMPTON, L6X 2M3 95 VAN KIRK DR. (HEAD OFFICE)
BRAMPTON ON L6X 2M3
BRAMPTON CITY ON L7A 1A4 | **SPL**

Ref No: 113222
Year:
Incident Dt: 5/16/1995
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/16/1995
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: CONTAINER OVERFLOW
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: SONCO STEEL-50L VARSOL TO GRAVEL YARD.NO WATER- WAYS.SONCO CLEANING.
Environment Impact: POSSIBLE
Health Env Consequence:
Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Nature of Impact:	Soil contamination
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

110 | ***3 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***SONCO STEEL TUBE LTD.***
VAN KIRK DRIVE BRAMPTON PLANT 95
VANKIRK DRIVE
BRAMPTON CITY ON | ***SPL***

Ref No:	80562	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	1/4/1993	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	1/4/1993	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	PEEL R.M.
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER CAUSE (N.O.S.)		
Incident Preceding Spill:			
Incident Reason:	INTENTIONAL/PLANNED		
Incident Summary:	SONCO STEEL TUBE: METAL SCALE DUST DUMPED ON GROUND NEXT TO WASTE BIN.		
Environment Impact:	CONFIRMED		
Health Env Consequence:			
Nature of Impact:	Water course or lake		
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			

Contaminant UN No 1:	
Receiving Medium:	LAND
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

110	***4 of 36***	***SSE/62.1***	***238.9 / -3.08***	***SONCO STEEL TUBE LTD. BRAMPTON PLANT 95 VANKIRK DRIVE BRAMPTON CITY ON***	***SPL***

Ref No:	127305	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	6/3/1996	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	6/3/1996	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	UNKNOWN		
Incident Preceding Spill:			
Incident Reason:	CARELESS APPLICATION		
Incident Summary:	SONCO STEEL TUBE-205 L TAR/WATER MIX TO DITCH. NONE TO SEWER.CLEANING.		
Environment Impact:	CONFIRMED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND / WATER		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

System Facility Address:

---

110 | ***5 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***Copperweld Canada***
95 Van Kirk Drive CITY OF BRAMPTON
ON | ***EBR***

EBR Registry No:	IA8E0337	***Decision Posted:***	
Ministry Ref No:	8309798 19980304	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:		***Act 1:***	
Notice Date:	February 09, 1999	***Act 2:***	
Proposal Date:	March 13, 1998	***Site Location Map:***	
Year:	1998		

Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Copperweld Canada
Site Address:
Location Other:
Proponent Name:
Proponent Address: Sonco Steel Tube Div., 14 Holtby Avenue, Brampton Ontario, L3X 2M3
Comment Period:
URL:
Summary:

Site Location Details:

95 Van Kirk Drive CITY OF BRAMPTON

---

110 | ***6 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***95 Van Kirk Drive***
Brampton ON L7A 1A4 | ***EHS***

Order No:	20020321008	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Complete Report	***Client Prov/State:***	VA
Report Date:	4/2/02	***Search Radius (km):***	0.45
Date Received:	3/21/02	***X:***	-79.799379
Previous Site Name:		***Y:***	43.705307
Lot/Building Size:			

Additional Info Ordered: Fire Insur. Maps and/or Site Plans and/or Inspection Reports

---

110 | ***7 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***95 Van Kirk Dr.***
Brampton ON L7A 1A4 | ***EHS***

Order No:	20020625004	***Nearest Intersection:***	Bovarid
Status:	C	***Municipality:***	
Report Type:	Complete Report	***Client Prov/State:***	ON
Report Date:	7/3/02	***Search Radius (km):***	0.30
Date Received:	6/25/02	***X:***	-79.800467
Previous Site Name:		***Y:***	43.704935
Lot/Building Size:			
Additional Info Ordered:			

---

110 | ***8 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***SONCO STEEL TUBE LTD***
95 VANKIRK DR.
BRAMPTON ON L7A 1A4 | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON0161001	***Choice of Contact:***	
Approval Years:	86,87,88,89,90,97	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	2921
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	STEEL PIPE & TUBE		

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

110	***9 of 36***	***SSE/62.1***	***238.9 / -3.08***	***SONCO STEEL TUBE LTD 35-058*** ***95 VANKIRK DR.*** ***BRAMPTON ON L7A 1A4***	***GEN***

Generator Info

Generator No:	ON0161001	***Choice of Contact:***	
Approval Years:	92,93,94,95,96	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	2921
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	STEEL PIPE & TUBE		

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	10 of 36	SSE/62.1	238.9 / -3.08	SONCO STEEL TUBE LTD. 95 VANKIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No:	ON0161001	***Choice of Contact:***	
Approval Years:	98,99	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	2921
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	STEEL PIPE & TUBE		

Waste Detail(s)

Waste Class:	253
Waste Class Name:	EMULSIFIED OILS

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	11 of 36	SSE/62.1	238.9 / -3.08	SONCO (SEE & USE ON0164204) 95 VANKIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No:	ON0161001	***Choice of Contact:***	
Approval Years:	00	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	2921
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	STEEL PIPE & TUBE		

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

110 | ***12 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***LTV COPPERWELD***
95 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON0164204
Approval Years: 00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: STEEL PIPE & TUBE

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 2921

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

110 | ***13 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***COPPERWELD CANADA INC.***
95 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON0164204
Approval Years: 02,03,04,05
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

---

110 | **14 of 36** | **SSE/62.1** | **238.9 / -3.08** | **95 VAN KIRK DR BRAMPTON ON L7A 1A4** | **EHS**

Order No: 20060501009
Status: C
Report Type: Site Report
Report Date: 5/2/2006
Date Received: 5/1/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: REGAN RD AND VAN KIRK DR
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.799554
Y: 43.705441

---

110 | **15 of 36** | **SSE/62.1** | **238.9 / -3.08** | **95 Van Kirk Brampton ON L7A 1A4** | **EHS**

Order No: 20060821002
Status: C
Report Type: Complete Report
Report Date: 8/22/2006
Date Received: 8/21/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps And /or Site Plans; Title Search; Aerials Photos; Topographical Maps; City Directory

Nearest Intersection:
Municipality:
Client Prov/State: OH
Search Radius (km): 0.5
X: -79.799292
Y: 43.705496

---

110 | **16 of 36** | **SSE/62.1** | **238.9 / -3.08** | **6832458 Canada Inc. 95 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON** | **EBR**

EBR Registry No: 010-3395
Ministry Ref No: 0442-7DQNJE
Notice Type: Instrument Decision
Notice Stage:
Notice Date: July 14, 2008
Proposal Date: April 21, 2008

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Year: 2008
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: 6832458 Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 550 rue du Parc Industriel Park, Longueuil Quebec, Canada J4H 3V6
Comment Period:
URL:
Summary:

Site Location Details:

95 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON

110	17 of 36	SSE/62.1	238.9 / -3.08	**Brampton-Canada Associates Ltd.** **95 Van Kirk Drive** **Brampton ON L7A 1A4**	GEN

Generator Info

Generator No: ON2922344
Approval Years: 06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Real Estate Property Managers
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 531310

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

110	18 of 36	SSE/62.1	238.9 / -3.08	**6832458 Canada Inc.** **95 Van Kirk Dr** **Brampton ON L7A 1A4**	CA

Certificate #: 2674-7EUQXQ
Application Year: 2008
Issue Date: 7/6/2008
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

110	19 of 36	SSE/62.1	238.9 / -3.08	**Brampton-Canada Associates Ltd.** **95 Van Kirk Drive** **Brampton ON L7A 1A4**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON2922344	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	531310
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Real Estate Property Managers		

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	20 of 36	SSE/62.1	238.9 / -3.08	Metelix Products inc 95 Van Kirk Drive Brampton ON	GEN

Generator Info

Generator No:	ON4998636	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	326193
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Motor Vehicle Plastic Parts Manufacturing		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	21 of 36	SSE/62.1	238.9 / -3.08	Metelix Products inc 95 Van Kirk Drive Brampton ON	GEN

Generator Info

Generator No:	ON4998636	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	326193
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	MOTOR VEHICLE PLASTIC PARTS MANUFACTURING		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	22 of 36	SSE/62.1	238.9 / -3.08	95 Van Kirk Drive Brampton ON	EHS

Order No: 20150603027
Status: C
Report Type: Custom Report
Report Date: 08-JUN-15
Date Received: 03-JUN-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.800178
Y: 43.705902

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	23 of 36	SSE/62.1	238.9 / -3.08	6832458 Canada Inc. 95 Van Kirk Dr Brampton ON J4H 3V6	ECA

Approval No: 2674-7EUQXQ
Approval Date: 2008-07-06
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: 6832458 Canada Inc.
Address: 95 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0442-7DQNJE-13.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.799324
Latitude: 43.702106
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	24 of 36	SSE/62.1	238.9 / -3.08	Metelix Products inc 95 Van Kirk Drive Brampton ON L7A 1A4	GEN

Generator Info

Generator No: ON4998636
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: MOTOR VEHICLE PLASTIC PARTS MANUFACTURING
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 326193

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

110 **25 of 36** **SSE/62.1** **238.9 / -3.08** **Metelix Products inc** **GEN**
95 Van Kirk Drive
Brampton ON L7A 1A4

Generator Info

Generator No:	ON4998636	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	326193
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	MOTOR VEHICLE PLASTIC PARTS MANUFACTURING		

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

110 **26 of 36** **SSE/62.1** **238.9 / -3.08** **Metelix Products inc** **GEN**
95 Van Kirk Drive
Brampton ON L7A 1A4

Generator Info

Generator No:	ON4998636	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2014	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	326193
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	MOTOR VEHICLE PLASTIC PARTS MANUFACTURING		

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

110 | ***27 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***Metelix Products inc*** ***95 Van Kirk Drive*** ***Brampton ON L7A 1A4*** | ***GEN***

Generator Info

Generator No: ON4998636
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

110 | ***28 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***Metelix Products inc*** ***95 Van Kirk Drive*** ***Brampton ON L7A 1A4*** | ***GEN***

Generator Info

Generator No: ON4998636
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 T

Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

110 | ***29 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***Metelix Products inc***
95 Van Kirk Drive
Brampton ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON4998636
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

110 | ***30 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***METELIX PRODUCTS INC.***
95 Van Kirk Drive
Brampton ON | ***GEN***

Generator Info

Generator No: ON4998636
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: PETROLEUM DISTILLATES

Generator Info as of Dec 2024

Generator No: ON4998636
Generator Company Name: METELIX PRODUCTS INC.
Street: 95 Van Kirk Drive
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A1A4
Waste Class: 232 L,252 L,251 L,213 T

Waste Class Decoded:

232 - POLYMERIC RESINS; 252 - WASTE OILS & LUBRICANTS; 251 - OIL SKIMMINGS & SLUDGES; 213 - PETROLEUM DISTILLATES

2017 Generator Info

Gen No: ON4998636
ID: 19834
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 326193
NAICS Code2:
NAICS Code3:
Gen Name: Metelix Products inc
Gen Div:
Gen Op Name: Metelix Products inc
Gen Op Div:
Site Adrs1: 95 Van Kirk Drive
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Joseph Remedios
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9054952374 Ext.223
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305

2017 Generator Manifest

ID: 43841
Generator No: ON4998636
Sum Received Qty: 100.0
Waste Class Name: PETROLEUM DISTILLATES

Receiver Type:	035	**Count Manifests:**	2
Waste Char:	T	**District:**	305
Waste Code:	213		

2017 Generator Manifest

ID:	43842	**Sum Received Qty:**	2818.0
Generator No:	ON4998636	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	305
Waste Code:	252		

2017 Generator Manifest

ID:	43840	**Sum Received Qty:**	100.0
Generator No:	ON4998636	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	I	**District:**	305
Waste Code:	213		

2018 Generator Info

Gen No:	ON4998636	**Choice of Contact:**	CO_OFFICIAL
ID:	19933	**Phone No Official:**	905-495-2374 Ext.202
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	326193	**County Out:**	
NAICS Code2:	326198	**District:**	305
NAICS Code3:			
Gen Name:	Metelix Products inc		
Gen Div:			
Gen Op Name:	Metelix Products inc		
Gen Op Div:			
Site Adrs1:	95 Van Kirk Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A4		
Site Country:	Canada		
Co Official:	John Burns		
Co Admin:			

2018 Generator Manifest

ID:	43746	**Sum Received Qty:**	1000.0
Generator No:	ON4998636	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	252		

2018 Generator Manifest

ID:	43745	**Sum Received Qty:**	150.0
Generator No:	ON4998636	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	T	**District:**	305
Waste Code:	213		

2019 Generator Info

Gen No:	ON4998636	***Choice of Contact:***	CO_OFFICIAL
ID:	19953	***Phone No Official:***	905-495-2374 Ext.202
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	326193	***County Out:***	
NAICS Code2:	326198	***District:***	305
NAICS Code3:			
Gen Name:	Metelix Products inc		
Gen Div:			
Gen Op Name:	Metelix Products inc		
Gen Op Div:			
Site Adrs1:	95 Van Kirk Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A4		
Site Country:	Canada		
Co Official:	John Burns		
Co Admin:			

2019 Generator Manifest

ID:	43276	***Sum Received Qty:***	50.0
Generator No:	ON4998636	***Waste Class Name:***	PETROLEUM DISTILLATES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	T	***District:***	305
Waste Code:	213		

2020 Generator Info

Gen No:	ON4998636	***Choice of Contact:***	CO_OFFICIAL
ID:	19676	***Phone No Official:***	905-495-2374 Ext.202
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	326193	***County Out:***	
NAICS Code2:	326198	***District:***	305
NAICS Code3:			
Gen Name:	Metelix Products inc		
Gen Div:			
Gen Op Name:	Metelix Products inc		
Gen Op Div:			
Site Adrs1:	95 Van Kirk Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A4		
Site Country:	Canada		
Co Official:	John Burns		
Co Admin:			

2020 Generator Manifest

ID:	40018	***Sum Received Qty:***	100.0
Generator No:	ON4998636	***Waste Class Name:***	PETROLEUM DISTILLATES
Receiver Type:	035	***Count Manifests:***	2

Waste Char: T
Waste Code: 213
District: 305

2021 Generator Info

Gen No: ON4998636
ID: 19823
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 326193
NAICS Code2: 326198
NAICS Code3:
Gen Name: Metelix Products inc
Gen Div:
Gen Op Name: Metelix Products inc
Gen Op Div:
Site Adrs1: 95 Van Kirk Drive
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Ian Godwin
Co Admin: Eugene Kaczmarek
Choice of Contact: CO_OFFICIAL
Phone No Official: 416-910-3493 Ext.
Phone No Admin: 6478661604 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2021 Generator Manifest

ID: 41355
Generator No: ON4998636
Receiver Type: 035
Waste Char: T
Waste Code: 213
Sum Received Qty: 200.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 4
District: 305

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	31 of 36	SSE/62.1	238.9 / -3.08	1955379 ONTARIO INC 95 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No: ON8341386
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	32 of 36	SSE/62.1	238.9 / -3.08	COPPERWELD CANADA INC. - VAN KIRK DRIVE 95 VAN KIRK DRIVE BRAMPTON ON L7A1A4	NPR2

NPRI ID:	5693	**Latitude:**	43.708
Facility ID:	371906;372617;372683;379667	**Longitude:**	-79.8045
Facility Name:	COPPERWELD CANADA INC. - VAN KIRK DRIVE		
Note:	Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0. For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report: https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=5693		

NPRI ID Substances Summary

CAS No:	7723-14-0	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Phosphorus (yellow or white only)		
Name French:	Phosphore (jaune ou blanc seulement)		
Sort English:	Phosphorus (yellow or white only)		
Sort French:	Phosphore (jaune ou blanc seulement)		

CAS No:	NA - 09	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Manganese (and its compounds)		
Name French:	Manganèse (et ses composés)		
Sort English:	Manganese (and its compounds)		
Sort French:	Manganèse (et ses composés)		

CAS No:	7440-62-2	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Vanadium (fume or dust)		
Name French:	Vanadium (fumée ou poussières)		
Sort English:	Vanadium (fume or dust)		
Sort French:	Vanadium (fumée ou poussières)		

Geographic Location

Report Year:	-1	**Forward Sort Area:**	L6Z
Census Subdiv ID:	3521010	**DLS Description:**	
Ecozone ID:	8	**NTS Description:**	D-045-K/030-M-12
Water Survey ID:	2	**Province Code:**	ON
SOMA:	TRUE	**Datum:**	1983.0
ON PEMA:	TRUE	**Latitude:**	43.708
QC PEMA:	FALSE	**Longitude:**	-79.8045
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	5693
Facility ID:	371906

Facility

Facility ID:	371906	**IDM ID:**	0
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	331210	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0

NAICS Tertiary: 0
Facility Name:
Website: www.ltv-copperweld.com

Address

Address1: 95 Van Kirk Drive
Address2:
City: BRAMPTON
Postal Zip: L7A1A4
Prov:

Primary NAICS Details

NAICS Code: 331210 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Iron and Steel
Key Indus Sector Fr: Fer et acier
NAICS Title En: Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel
NAICS Title Fr: Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code: 331210 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Iron and Steel
Key Indus Sector Fr: Fer et acier
NAICS Title En: Iron and steel pipes and tubes manufacturing from purchased steel
NAICS Title Fr: Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code: 331210 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Iron and Steel
Key Indus Sector Fr: Fer et acier
NAICS Title En: Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel
NAICS Title Fr: Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NPRI Report

Report ID:	275870	**No of Employees:**	70
Report Year:	2002	**Is Compressor:**	
Company ID:	146284	**Is NPRI Part 4:**	
SWR Report ID:	20020000005693	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2003-06-02 00:00:00.0000000

Company

Company Name:	COPPERWELD CANADA INC.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.ltv-copperweld.com

NPRI Report Contact

Contact Type:		**Phone:**	9054512400
First Name:	John	**Extension:**	1170
Last Name:	McKinnon	**Fax:**	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Director of Operations		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9054512400
First Name:	John	**Extension:**	1170
Last Name:	McKinnon	**Fax:**	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Director of Operations		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9054512400
First Name:	Mike	**Extension:**	1121
Last Name:	Dwyer	**Fax:**	9054512795
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Human Resources Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	4164675555
First Name:	Bijal	**Extension:**	233
Last Name:	Shah	**Fax:**	4164679824
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Engineer		
Language:	0		

Email: bshah@altech-group.com

NPRI Report Contact

Contact Type:		***Phone:***	9054512400
First Name:	Jeff	***Extension:***	2390
Last Name:	Robertson	***Fax:***	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Enginnering Manager		
Language:	0		
Email:			

NPRI ID Facility ID

NPRI ID:	5693
Facility ID:	372617

Facility

Facility ID:	372617	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	331210	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	COPPERWELD CANADA INC. - VAN KIRK DRIVE		
Website:	www.ltv-copperweld.com		

Address

Address1:	95 VAN KIRK Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4
Prov:	

Address Geographic

Latitude:	43.708	***Datum:***	1983
Longitude:	-79.8045	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	331210	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		

NAICS Title En:	Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NPRI Report

Report ID:	166435	***No of Employees:***	70
Report Year:	2004	***Is Compressor:***	
Company ID:	141750	***Is NPRI Part 4:***	
SWR Report ID:	20040000005693	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2005-04-27 00:00:00.0000000

Company

Company Name:	COPPERWELD CANADA
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.ltv-copperweld.com

NPRI Report Contact

Contact Type:		***Phone:***	9054512400
First Name:	John	***Extension:***	1170
Last Name:	McKinnon	***Fax:***	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Director of Operations		
Language:	0		
Email:	jmckinnon@copperweld.com		

NPRI Report Contact

Contact Type:		***Phone:***	4164675555
First Name:	Bijal	***Extension:***	233
Last Name:	Shah	***Fax:***	4164679824
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Engineer		
Language:	0		
Email:	bshah@altech-group.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054512400
First Name:	Mike	***Extension:***	1121
Last Name:	Dwyer	***Fax:***	9054512795
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Human Resources Manager		
Language:	0		
Email:	mdwyer@copperweld.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054512400
First Name:	John	***Extension:***	1170
Last Name:	McKinnon	***Fax:***	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Director of Operations		
Language:	0		
Email:	jmckinnon@copperweld.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054512400
First Name:	Jeff	***Extension:***	2390
Last Name:	Robertson	***Fax:***	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Enginnering Manager		
Language:	0		
Email:	jrobertson@copperweld.com		

NPRI ID Facility ID

NPRI ID:	5693
Facility ID:	372683

Facility

Facility ID:	372683	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	331210	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	Sonco Steel Tube Division		
Website:			

Address

Address1: 95 Van Kirk Drive
Address2:
City: BRAMPTON
Postal Zip: L7A1A4
Prov:

Primary NAICS Details

NAICS Code: 331210 ***Start Date:*** 1993
Record Year: 1997 ***End Date:*** 2001
Key Indus Sector En: Iron and Steel
Key Indus Sector Fr: Fer et acier
NAICS Title En: Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel
NAICS Title Fr: Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code: 331210 ***Start Date:*** 2017
Record Year: 2017 ***End Date:*** 2021
Key Indus Sector En: Iron and Steel
Key Indus Sector Fr: Fer et acier
NAICS Title En: Iron and steel pipes and tubes manufacturing from purchased steel
NAICS Title Fr: Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code: 331210 ***Start Date:*** 2002
Record Year: 2002 ***End Date:*** 2006
Key Indus Sector En: Iron and Steel
Key Indus Sector Fr: Fer et acier
NAICS Title En: Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel
NAICS Title Fr: Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés

ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NPRI Report

Report ID:	286731	***No of Employees:***	95
Report Year:	1998	***Is Compressor:***	
Company ID:	142696	***Is NPRI Part 4:***	

SWR Report ID:	19980000005693	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1999-06-01 00:00:00.0000000

Company

Company Name:	Copperweld Canada Inc.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9054512400
First Name:	Helder	**Extension:**	1280
Last Name:	Constantino	**Fax:**	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental, Health & Safety		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9054512400
First Name:	Helder	**Extension:**	1280
Last Name:	Constantino	**Fax:**	9054512795
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Environmental, Health & Safety		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	0
First Name:	John	**Extension:**	0
Last Name:	McKinnon	**Fax:**	0
Company Name:			
Description En:			
Description Fr:			
Position:	Director of Operations		
Language:	0		
Email:			

NPRI Report

Report ID:	288809	**No of Employees:**	80
Report Year:	1997	**Is Compressor:**	
Company ID:	142696	**Is NPRI Part 4:**	
SWR Report ID:	19970000005693	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	1998-06-01 00:00:00.0000000

Company

Company Name:	Copperweld Canada Inc.
DUNS No:	0

Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:		***Phone:***	9054512400
First Name:	Jeff	***Extension:***	1279
Last Name:	Robertson	***Fax:***	9058464732
Company Name:			
Description En:			
Description Fr:			
Position:	Manager of Engineering		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054512400
First Name:	Jeff	***Extension:***	1279
Last Name:	Robertson	***Fax:***	9058464732
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager of Engineering		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	0
First Name:	John	***Extension:***	0
Last Name:	McKinnon	***Fax:***	0
Company Name:			
Description En:			
Description Fr:			
Position:	Director of Operations		
Language:	0		
Email:			

NPRI ID Facility ID

NPRI ID:	5693
Facility ID:	379667

Facility

Facility ID:	379667	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	331210	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:			
Website:	www.ltv-copperweld.com		

Address

Address1:	95 VAN KIRK Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A4

Prov:

Address Geographic

Latitude:	43.708	***Datum:***	1983
Longitude:	-79.8045	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	331210	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and Steel Pipes and Tubes Manufacturing from Purchased Steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NAICS Code:	331210	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Iron and Steel		
Key Indus Sector Fr:	Fer et acier		
NAICS Title En:	Iron and steel pipes and tubes manufacturing from purchased steel		
NAICS Title Fr:	Fabrication de tubes et de tuyaux en fer et en acier à partir d'acier acheté		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in the production of welded or seamless iron and steel pipes and tubes, and heavy, rivetted steel pipes, from purchased steel.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale consiste à produire des tuyaux et des tubes en fer ou en acier, soudés ou non, et de gros tuyaux d'acier rivetés, à partir d'acier acheté.

NPRI Report

Report ID:	271605	***No of Employees:***	70

Report Year:	2003	**Is Compressor:**	
Company ID:	137118	**Is NPRI Part 4:**	
SWR Report ID:	20030000005693	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2004-06-01 00:00:00.0000000

Company

Company Name:	COPPERWELD CANADA INC.
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	www.ltv-copperweld.com

NPRI Report Contact

Contact Type:		**Phone:**	4164675555
First Name:	Bijal	**Extension:**	233
Last Name:	Shah	**Fax:**	4164679824
Company Name:			
Description En:			
Description Fr:			
Position:	Environmental Engineer		
Language:	0		
Email:	bshah@altech-group.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054512400
First Name:	Jeff	**Extension:**	2390
Last Name:	Robertson	**Fax:**	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Enginnering Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9054512400
First Name:	Mike	**Extension:**	1121
Last Name:	Dwyer	**Fax:**	9054512795
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Human Resources Manager		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		**Phone:**	9054512400
First Name:	John	**Extension:**	1170
Last Name:	McKinnon	**Fax:**	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Director of Operations		
Language:	0		
Email:			

NPRI Report Contact

Contact Type:		***Phone:***	9054512400
First Name:	John	***Extension:***	1170
Last Name:	McKinnon	***Fax:***	9054512795
Company Name:			
Description En:			
Description Fr:			
Position:	Director of Operations		
Language:	0		
Email:			

Alternative Location Info

Facility ID:	371906
Facility Name:	COPPERWELD CANADA INC. - VAN KIRK DRIVE
Address1:	95 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A4
Province EN:	ON
Latitude:	43.708
Longitude:	-79.8045

Alternative Location Info

Facility ID:	372617
Facility Name:	
Address1:	95 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A4
Province EN:	ON
Latitude:	43.708
Longitude:	-79.8045

Alternative Location Info

Facility ID:	372683
Facility Name:	COPPERWELD CANADA INC. - VAN KIRK DRIVE
Address1:	95 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A4
Province EN:	ON
Latitude:	43.708
Longitude:	-79.8045

Alternative Location Info

Facility ID:	372617
Facility Name:	SONCO STEEL TUBE DIVISION
Address1:	95 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A4
Province EN:	ON
Latitude:	43.708
Longitude:	-79.8045

Alternative Location Info

Facility ID:	371906
Facility Name:	
Address1:	95 VAN KIRK DRIVE

City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.708
Longitude: -79.8045

Alternative Location Info

Facility ID: 379667
Facility Name: COPPERWELD CANADA INC. - VAN KIRK DRIVE
Address1: 95 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.708
Longitude: -79.8045

Alternative Location Info

Facility ID: 371906
Facility Name: SONCO STEEL TUBE DIVISION
Address1: 95 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.708
Longitude: -79.8045

Alternative Location Info

Facility ID: 372683
Facility Name:
Address1: 95 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.708
Longitude: -79.8045

Alternative Location Info

Facility ID: 372617
Facility Name: COPPERWELD CANADA INC. - VAN KIRK DRIVE
Address1: 95 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.708
Longitude: -79.8045

Alternative Location Info

Facility ID: 372683
Facility Name: SONCO STEEL TUBE DIVISION
Address1: 95 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A4
Province EN: ON
Latitude: 43.708
Longitude: -79.8045

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Alternative Location Info

Facility ID:	379667
Facility Name:	SONCO STEEL TUBE DIVISION
Address1:	95 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A4
Province EN:	ON
Latitude:	43.708
Longitude:	-79.8045

Alternative Location Info

Facility ID:	379667
Facility Name:	
Address1:	95 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A4
Province EN:	ON
Latitude:	43.708
Longitude:	-79.8045

110	***33 of 36***	***SSE/62.1***	***238.9 / -3.08***	***behind 95 Van Kirk Drive, Brampton BRAMPTON ON***	***SPL***

Ref No:	1-1WQ8S7	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	7/18/2022 6:55:00 PM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	7/18/2022 8:31:07 PM	***Impact to Health:***	0 No Impact
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	behind 95 Van Kirk Drive, Brampton		
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:	Container/Drum/Tote		
Incident Cause:			
Incident Preceding Spill:			
Incident Reason:			
Incident Summary:	Metelix Products: 200L oil product to pavement, possibly cb		
Environment Impact:	1 Minor Impact		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	200 litre (L)		
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:	OIL (PETROLEUM BASED, NOT SPECIFIED)		
Contaminant Limit 1:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Surface Water
Activity Preceding Spill:
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02ED - Nottawasaga
Sector Type: MANUFACTURING AND REPRODUCING MAGNETIC AND OPTICAL MEDIA
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001478317"],"wkts":["POINT (-79.8001682000 43.7059720000)"],"creation_date":"2022-07-18"}
Time Reported:
System Facility Address:

---

110 | ***34 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***95 Van Kirk Drive***
Brampton ON L7A 1A4 | ***EHS***

Order No: 20200708122
Status: C
Report Type: Standard Report
Report Date: 13-JUL-20
Date Received: 08-JUL-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.8003446
Y: 43.7060505

---

110 | ***35 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***95 Van Kirk Drive***
Brampton ON L7A 1A4 | ***EHS***

Order No: 24081300911
Status: C
Report Type: Standard Report
Report Date: 16-AUG-24
Date Received: 13-AUG-24
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.800238
Y: 43.7059821

---

110 | ***36 of 36*** | ***SSE/62.1*** | ***238.9 / -3.08*** | ***Elgner Group Investments Ltd.***
95 Van Kirk Drive
Brampton ON | ***GEN***

Generator Info as of Dec 2024

Generator No: ON001070009
Generator Company Name: Elgner Group Investments Ltd.
Street: 95 Van Kirk Drive
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A 1A4
Waste Class: 150 L

Waste Class Decoded:

150 - INERT INORGANIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
111	1 of 1	SSE/191.2	239.9 / -2.08	80 VAN KIRK DRIVE Brampton ON	WWIS

Well ID: 7277924
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z247470
Tag: A211408
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 12/23/2016
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/727\7277924.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/21/2016
Year Completed: 2016
Depth (m): 5.7912
Latitude: 43.7053291586813
Longitude: -79.8016028763662
X: -79.80160272599808
Y: 43.70532915704339
Path: 727\7277924.pdf

Bore Hole Information

Bore Hole ID: 1006320530
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/21/2016
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596555.00
North83: 4839843.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006520798
Layer: 2
Color: 6
General Color: BROWN

Material 1:	06
Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.5
Formation End Depth:	6.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006520799
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	92
Material 3 Desc:	WEATHERED
Formation Top Depth:	6.0
Formation End Depth:	19.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006520797
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	
Material 2 Desc:	
Material 3:	60
Material 3 Desc:	CEMENTED
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006520807
Layer:	1
Plug From:	0.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006520808
Layer:	2
Plug From:	0.5
Plug To:	8.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006520809
Layer:	3
Plug From:	8.0
Plug To:	19.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006520806
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1006520796
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006520802
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	9.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006520803
Layer:	1
Slot:	10
Screen Top Depth:	9.0
Screen End Depth:	19.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1006520801
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006520800
Diameter:	6.0

Depth From:	0.0
Depth To:	19.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

112 **1 of 1** **WNW/30.0** **255.8 / 13.88** **2650 mayfield rd con 1 Caledon ON** **WWIS**

Well ID:	7353563	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	02/18/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z326463	**Contractor:**	7215
Tag:	A284380	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7353563.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/29/2020
Year Completed:	2020
Depth (m):	4.572
Latitude:	43.7290761906553
Longitude:	-79.8315371397797
X:	-79.83153698979015
Y:	43.72907618930249
Path:	735\7353563.pdf

Bore Hole Information

Bore Hole ID:	1008147978	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	594106.00
Code OB Desc:		**North83:**	4842446.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/29/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1008232082
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	11
Material 3 Desc:	GRAVEL
Formation Top Depth:	1.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008232081
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	06
Material 2 Desc:	SILT
Material 3:	27
Material 3 Desc:	OTHER
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008234292
Layer:	1
Plug From:	0.0
Plug To:	4.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1008236622
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1008229281
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008237531
Layer:	1
Material:	5

Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	5.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008238390
Layer:	1
Slot:	10
Screen Top Depth:	5.0
Screen End Depth:	15.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008239662
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

---

113 | ***1 of 1*** | ***WNW/165.5*** | ***257.9 / 15.92*** | ***2650 Mayfield Road lot 18 con 1 Brampton ON*** | ***WWIS***

Well ID:	7378695	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	01/19/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	HQTOE5FA	**Contractor:**	7732
Tag:	_NO_TAG	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	018
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378695.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/13/2021
Year Completed: 2021
Depth (m):
Latitude: 43.7280323372609
Longitude: -79.8324762302416
X: -79.83247608029802
Y: 43.72803233518825
Path: 737\7378695.pdf

Bore Hole Information

Bore Hole ID: 1008554341
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/13/2021
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 594032.00
North83: 4842329.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008554440
Layer: 1
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008554493
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008554509

Layer:	1
Plug From:	0.0
Plug To:	6.099999904632568
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1008554375
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008554455
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0999999046325684
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008554470
Layer:	1
Slot:	
Screen Top Depth:	3.0999999046325684
Screen End Depth:	6.099999904632568
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008554376
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

114	*1 of 1*	*WNW/174.7*	*257.8 / 15.89*	***2650 MAYFIELD RD BRAMPTON ON***	***WWIS***

Well ID:	7262154	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	

Use 2nd:	0	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	04/27/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z224101	**Contractor:**	7501
Tag:	A196915	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/726\7262154.pdf

Additional Detail(s) (Map)

Well Completed Date: 03/04/2016
Year Completed: 2016
Depth (m): 9.144
Latitude: 43.7279609547809
Longitude: -79.8325396976566
X: -79.83253954805569
Y: 43.72796095348071
Path: 726\7262154.pdf

Bore Hole Information

Bore Hole ID:	1005939706	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	594027.00
Code OB Desc:		**North83:**	4842321.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03/04/2016	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1006055846
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 28
Material 3 Desc: SAND

Formation Top Depth:	0.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006055847
Layer:	2
Color:	7
General Color:	RED
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	17
Material 3 Desc:	SHALE
Formation Top Depth:	25.0
Formation End Depth:	30.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006055855
Layer:	1
Plug From:	0.0
Plug To:	19.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006055854
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1006055845
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006055850
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	20.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006055851
Layer:	1

Slot:	10
Screen Top Depth:	20.0
Screen End Depth:	30.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.125

Water Details

Water ID:	1006055849
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	25.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006055848
Diameter:	6.0
Depth From:	0.0
Depth To:	30.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

115 | ***1 of 1*** | ***WNW/36.6*** | ***257.6 / 15.70*** | ***Robertson Davies Drive & Mayfield Road lot 18 con 1 ON*** | ***WWIS***

Well ID:	7408615	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	01/18/2022
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	X4V5GKPP	**Contractor:**	7472
Tag:	A334294	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	018
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/740\7408615.pdf

Additional Detail(s) (Map)

Well Completed Date:	12/02/2021
Year Completed:	2021
Depth (m):	7.62
Latitude:	43.7298403504962
Longitude:	-79.8314229499811
X:	-79.83142279951232
Y:	43.72984034807644

Path: 740\7408615.pdf

Bore Hole Information

Bore Hole ID:	1008930888	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	594114.00
Code OB Desc:		**North83:**	4842531.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12/02/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008931005
Layer:	1
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008931132
Layer:	2
Plug From:	14.0
Plug To:	25.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008931093
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008931131
Layer:	1
Plug From:	0.0

Plug To: 14.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008930952
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008930930
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008931025
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 15.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008931045
Layer: 1
Slot: 10
Screen Top Depth: 15.0
Screen End Depth: 25.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008930931
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1008931073
Diameter:	7.5
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

116 ***1 of 1*** ***WNW/26.0*** ***257.3 / 15.32*** ***2650 Mayfield Road lot 18 con 1 Brampton ON*** ***WWIS***

Well ID:	7378685	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	01/19/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	ABS48CGF	***Contractor:***	7732
Tag:	A284380	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	018
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378685.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/13/2021
Year Completed:	2021
Depth (m):	
Latitude:	43.7297966094613
Longitude:	-79.8315479657648
X:	-79.8315478162179
Y:	43.729796607163856
Path:	737\7378685.pdf

Bore Hole Information

Bore Hole ID:	1008554311	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	594104.00
Code OB Desc:		***North83:***	4842526.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/13/2021	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			

Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1008554414
Layer:	1
Color:	
General Color:	
Material 1:	
Material 1 Desc:	
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008554499
Layer:	1
Plug From:	0.0
Plug To:	4.599999904632568
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008554483
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1008554355
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008554445
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	5.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008554460
Layer:	1

Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008554356
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008554399
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.5
Water Found Depth UOM: m

---

117 | ***1 of 1*** | ***WNW/154.4*** | ***258.9 / 16.93*** | ***2650 Mayfield Road lot 18 con 1 Brampton ON*** | ***WWIS***

Well ID: 7378694
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: P9JSUSO6
Tag: _NO_TAG
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 01/19/2021
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7732
Form Version: 9
Owner:
County: PEEL
Lot: 018
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378694.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/13/2021
Year Completed:	2021
Depth (m):	
Latitude:	43.7282951725064
Longitude:	-79.8326449513012
X:	-79.83264480089909
Y:	43.72829517095455
Path:	737\7378694.pdf

Bore Hole Information

Bore Hole ID:	1008554338	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	594018.00
Code OB Desc:		***North83:***	4842358.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/13/2021	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008554439
Layer:	1
Color:	
General Color:	
Material 1:	
Material 1 Desc:	
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008554508
Layer:	1
Plug From:	0.0
Plug To:	9.100000381469727
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008554492
Layer:	1
Plug From:	

Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008554373
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008554454
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 6.099999904632568
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008554469
Layer: 1
Slot:
Screen Top Depth: 6.099999904632568
Screen End Depth: 9.100000381469727
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008554374
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008554407
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.2000000476837158
Water Found Depth UOM: m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
118	1 of 16	SSE/76.5	238.9 / -3.08	GO Transit 85 Van Kirk Dr., Brampton ON CITY OF BRAMPTON ON	EBR

EBR Registry No: 010-9868
Ministry Ref No: SR 349564
Notice Type: Instrument Decision
Notice Stage:
Notice Date: June 09, 2010
Proposal Date: April 29, 2010
Year: 2010
Instrument Type: (Liquid Fuels Handling Code) - Liquid Fuels Handling Code Section
Off Instrument Name:
Posted By:
Company Name: GO Transit
Site Address:
Location Other:
Proponent Name:
Proponent Address: 20 Bay Street, Toronto Ontario, Canada M5J 2W8
Comment Period:
URL:
Summary:

Site Location Details:

85 Van Kirk Dr., Brampton ON CITY OF BRAMPTON

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
118	2 of 16	SSE/76.5	238.9 / -3.08	GO a division of Metrolinx 85 Van Kirk Dr Brampton ON L7A 1A4	CA

Certificate #: 3243-8HDMZM
Application Year: 2011
Issue Date: 6/1/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
118	3 of 16	SSE/76.5	238.9 / -3.08	Metrolinx 85 Van Kirk Drive Brampton ON L7A 1A4	GEN

Generator Info

Generator No: ON7084609
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 485210

Phone No Admin:
SIC Description: Interurban and Rural Bus Transportation

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

118 | ***4 of 16*** | ***SSE/76.5*** | ***238.9 / -3.08*** | ***Metrolinx*** ***85 Van Kirk Drive*** ***Brampton ON L7A 1A4*** | ***GEN***

Generator Info

Generator No: ON7084609
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Interurban and Rural Bus Transportation

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 485210

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212

Waste Class Name: ALIPHATIC SOLVENTS

---

118 | ***5 of 16*** | ***SSE/76.5*** | ***238.9 / -3.08*** | ***Metrolinx*** | ***GEN***
85 Van Kirk Drive
Brampton ON L7A 1A4

Generator Info

Generator No: ON7084609
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Interurban and Rural Bus Transportation

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 485210

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

118 | ***6 of 16*** | ***SSE/76.5*** | ***238.9 / -3.08*** | ***Metrolinx*** | ***GEN***
85 Van Kirk Drive
Brampton ON

Generator Info

Generator No: ON7084609
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 485210

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

118 | ***7 of 16*** | ***SSE/76.5*** | ***238.9 / -3.08*** | ***METROLINX O/A GO TRANSIT***
85 VAN KIRK DR
BRAMPTON ON | ***CFOT***

Inventory No: 64512141
Inventory Status: Active
Installation Year: 2010
Capacity: 50000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Fuel Oil Tank
Inventory Item: FS FUEL OIL TANK

---

118 | ***8 of 16*** | ***SSE/76.5*** | ***238.9 / -3.08*** | ***GO a division of Metrolinx***
85 Van Kirk Dr
Brampton ON M5J 2W3 | ***ECA***

Approval No: 3243-8HDMZM
Approval Date: 2011-06-01
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: GO a division of Metrolinx
Address: 85 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6547-8DAQER-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.80301
Latitude: 43.706734
Geometry X:
Geometry Y:

---

118 | ***9 of 16*** | ***SSE/76.5*** | ***238.9 / -3.08*** | ***Metrolinx***
85 Van Kirk Drive
Brampton ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON7084609
Approval Years: 2016
Status:

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No

PO Box No: ***SIC Code:*** 485210
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: 485210

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 268
Waste Class Name: AMINES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

118 ***10 of 16*** ***SSE/76.5*** ***238.9 / -3.08*** ***Metrolinx*** ***GEN***
85 Van Kirk Drive
Brampton ON L7A 1A4

Generator Info

Generator No: ON7084609 ***Choice of Contact:*** CO_OFFICIAL
Approval Years: 2015 ***Contaminated Fac:*** No
Status: ***MHSW Facility:*** No
PO Box No: ***SIC Code:*** 485210
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: 485210

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 268
Waste Class Name: AMINES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

118 | ***11 of 16*** | ***SSE/76.5*** | ***238.9 / -3.08*** | ***Metrolinx***
85 Van Kirk Drive
Brampton ON L7A 1A4 | ***GEN***

Generator Info

Generator No: ON7084609
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: 485210

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 485210

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

118	12 of 16	SSE/76.5	238.9 / -3.08	**Metrolinx GO Transit** **85 Van Kirk Drive** **Brampton ON L7A 1A4**	GEN

Generator Info

Generator No: ON7084609
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

118	13 of 16	SSE/76.5	238.9 / -3.08	**Metrolinx GO Transit** **85 Van Kirk Drive**	GEN

Brampton ON L7A 1A4

Generator Info

Generator No:	ON7084609	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Waste Detail(s)

Waste Class:	212 L
Waste Class Name:	Aliphatic solvents and residues

Waste Detail(s)

Waste Class:	221 L
Waste Class Name:	Light fuels

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
118	14 of 16	SSE/76.5	238.9 / -3.08	***Metrolinx GO Transit*** ***85 Van Kirk Drive*** ***Brampton ON L7A 1A4***	GEN

Generator Info

Generator No:	ON7084609	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	251 L

Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
118	15 of 16	SSE/76.5	238.9 / -3.08	Metrolinx - Bus 85 Van Kirk Drive Brampton ON	GEN

Generator Info

Generator No: ON7084609
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Generator Info as of Dec 2024

Generator No: ON7084609
Generator Company Name: Metrolinx - Bus
Street: 85 Van Kirk Drive
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A1A4
Waste Class: 252 L,221 L,251 L,212 L,312 P

Waste Class Decoded:

252 - WASTE OILS & LUBRICANTS; 221 - LIGHT FUELS; 251 - OIL SKIMMINGS & SLUDGES; 212 - ALIPHATIC SOLVENTS; 312 - PATHOLOGICAL WASTES

2017 Generator Info

Gen No: ON7084609
ID: 27804
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 485210
NAICS Code2:
NAICS Code3:
Gen Name: Metrolinx
Gen Div: GO Transit
Gen Op Name: Metrolinx
Gen Op Div:
Site Adrs1: 85 Van Kirk Drive
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Albert Trinier
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Official: 4162027794 Ext.
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305

2017 Generator Manifest

ID: 54114
Generator No: ON7084609
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 23400.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 4
District: 305

2018 Generator Info

Gen No: ON7084609
ID: 28254
Contaminated Fac: N
MHSW Facility: N
Choice of Contact: CO_OFFICIAL
Phone No Official: 4162027794 Ext.
Phone No Admin:
County Ont: PEEL (R. M.)

NAICS Code1:	485210	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Metrolinx		
Gen Div:	GO Transit		
Gen Op Name:	Metrolinx		
Gen Op Div:			
Site Adrs1:	85 Van Kirk Drive		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A4		
Site Country:	Canada		
Co Official:	Albert Trinier		
Co Admin:			

2018 Generator Manifest

ID:	54182	**Sum Received Qty:**	1.0
Generator No:	ON7084609	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	P	**District:**	306
Waste Code:	312		

2018 Generator Manifest

ID:	54180	**Sum Received Qty:**	43900.0
Generator No:	ON7084609	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	9
Waste Char:	L	**District:**	305
Waste Code:	251		

2018 Generator Manifest

ID:	54181	**Sum Received Qty:**	500.0
Generator No:	ON7084609	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	252		

2018 Generator Manifest

ID:	54179	**Sum Received Qty:**	762.0
Generator No:	ON7084609	**Waste Class Name:**	ALIPHATIC SOLVENTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	212		

2019 Generator Info

Gen No:	ON7084609	**Choice of Contact:**	CO_OFFICIAL
ID:	28531	**Phone No Official:**	4162027794 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	485210	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Metrolinx		
Gen Div:	GO Transit		

Gen Op Name: Metrolinx
Gen Op Div:
Site Adrs1: 85 Van Kirk Drive
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Albert Trinier
Co Admin:

2019 Generator Manifest

ID: 54155
Generator No: ON7084609
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 228.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 305

2019 Generator Manifest

ID: 54156
Generator No: ON7084609
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 43500.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 7
District: 305

2020 Generator Info

Gen No: ON7084609
ID: 28221
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 485210
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 4162027794 Ext.
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: Metrolinx
Gen Div: GO Transit
Gen Op Name: Metrolinx
Gen Op Div:
Site Adrs1: 85 Van Kirk Drive
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A4
Site Country: Canada
Co Official: Albert Trinier
Co Admin:

2020 Generator Manifest

ID: 50541
Generator No: ON7084609
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 41700.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 7
District: 305

2020 Generator Manifest

ID:	50540	***Sum Received Qty:***	867.0
Generator No:	ON7084609	***Waste Class Name:***	ALIPHATIC SOLVENTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	212		

2020 Generator Manifest

ID:	50542	***Sum Received Qty:***	1100.0
Generator No:	ON7084609	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	252		

2021 Generator Info

Gen No:	ON7084609	***Choice of Contact:***	CO_ADMIN
ID:	28748	***Phone No Official:***	4162027794 Ext.
Contaminated Fac:	N	***Phone No Admin:***	4162025252 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	485210	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	Metrolinx
Gen Div:	GO Transit
Gen Op Name:	Metrolinx
Gen Op Div:	
Site Adrs1:	85 Van Kirk Drive
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1A4
Site Country:	Canada
Co Official:	Albert Trinier
Co Admin:	Kumar Kanapathipillai

2021 Generator Manifest

ID:	52572	***Sum Received Qty:***	36300.0
Generator No:	ON7084609	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	6
Waste Char:	L	***District:***	305
Waste Code:	251		

---

118 ***16 of 16*** ***SSE/76.5*** ***238.9 / -3.08*** ***Metrolinx 85 Van Kirk Dr Brampton ON M5J 3A5*** ***ECA***

Approval No:	3032-CRQQFX	***MOE District:***	Halton-Peel
Approval Date:	May 23, 2023	***City:***	
Status:	Approved	***Longitude:***	-79.80301
Record Type:	ECA	***Latitude:***	43.706734
Link Source:	IDS	***Geometry X:***	-8883630.4370000027
SWP Area Name:	Credit Valley	***Geometry Y:***	5420170.1908999989
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		

Business Name: Metrolinx
Address: 85 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2441-CHUL3Y-14.pdf
PDF Site Location: Brampton Bus Facility
85 Van Kirk Drive
City of Brampton, Regional Municipality of Peel
L7A 1A4

---

119 | **1 of 1** | **SSE/207.0** | **239.9 / -2.08** | **70 VAN KIRK DR Brampton ON** | **WWIS**

Well ID:	7347856	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	11/22/2019
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z319380	**Contractor:**	7464
Tag:	A277332	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1007721472	**Tag No:**	A277332
Depth M:	4.2672	**Contractor:**	7464
Year Completed:	2019	**Latitude:**	43.704509867273
Well Completed Dt:	08/27/2019	**Longitude:**	-79.8007504091116
Audit No:	Z319380	**Y:**	43.704509864910285
Path:		**X:**	-79.80075025927405

Bore Hole Information

Bore Hole ID:	1007721472	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596625.00
Code OB Desc:		**North83:**	4839753.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	08/27/2019	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1008125714
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	27
Material 1 Desc:	OTHER
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008125715
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	12
Material 2 Desc:	STONES
Material 3:	27
Material 3 Desc:	OTHER
Formation Top Depth:	0.5
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008125716
Layer:	3
Color:	2
General Color:	GREY
Material 1:	34
Material 1 Desc:	TILL
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	2.0
Formation End Depth:	7.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008125717
Layer:	4
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD

Formation Top Depth: 7.0
Formation End Depth: 14.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008126427
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008126429
Layer: 3
Plug From: 3.0
Plug To: 14.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008126428
Layer: 2
Plug From: 1.0
Plug To: 3.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008127386
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1008125075
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008127531
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 4.0
Casing Diameter: 2.0
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID:	1008127808
Layer:	1
Slot:	10
Screen Top Depth:	4.0
Screen End Depth:	14.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008128252
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008126798
Diameter:	6.0
Depth From:	0.0
Depth To:	14.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

---

120 **1 of 6** **SSE/233.5** **239.9 / -2.08** **N.H.D. GROUP LTD.**
70 VAN KIRK DR
BRAMPTON ON L7A 1B1 **SCT**

Established:	1975
Plant Size (ft²):	100000
Employment:	90

--Details--

Description:	MISCELLANEOUS FABRICATED WIRE PRODUCTS
SIC/NAICS Code:	3496
Description:	STEEL WORKS, BLAST FURNACES (INCLUDING COKE OVENS), AND ROLLING MILLS
SIC/NAICS Code:	3312
Description:	STEEL WIREDRAWING AND STEEL NAILS AND SPIKES
SIC/NAICS Code:	3315

---

120 **2 of 6** **SSE/233.5** **239.9 / -2.08** **NHD GROUP LTD.**
70 Van Kirk Dr
Brampton ON L7A 1B1 **SCT**

Established: 1975
Plant Size (ft²): 100000
Employment: 90

--Details--
Description: Iron and Steel Mills and Ferro-Alloy Manufacturing
SIC/NAICS Code: 331110

Description: Steel Wire Drawing
SIC/NAICS Code: 331222

Description: Cutlery and Hand Tool Manufacturing
SIC/NAICS Code: 332210

Description: Showcase, Partition, Shelving and Locker Manufacturing
SIC/NAICS Code: 337215

---

120 ***3 of 6*** ***SSE/233.5*** ***239.9 / -2.08*** ***NHD GROUP LTD.*** ***GEN***
70 VAN KIRK DRIVE
BRAMPTON ON L7A 1B1

Generator Info

Generator No: ON0429702
Approval Years: 89,90
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: WIRE & WIRE ROPE
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3052

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

120 ***4 of 6*** ***SSE/233.5*** ***239.9 / -2.08*** ***NHD GROUP LTD. 28-640*** ***GEN***
70 VAN KIRK DRIVE
BRAMPTON ON L7A 1B1

Generator Info

Generator No: ON0429702
Approval Years: 92,93,94,95,96
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: WIRE & WIRE ROPE
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3052

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
120	5 of 6	SSE/233.5	239.9 / -2.08	N.H.D. GROUP LTD. 70 VAN KIRK DRIVE BRAMPTON ON L7A 1B1	GEN

Generator Info

Generator No:	ON0429702	**Choice of Contact:**	
Approval Years:	97,98,99,00,01,02,03,04	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	3052
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	WIRE & WIRE ROPE		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
120	6 of 6	SSE/233.5	239.9 / -2.08	SOTAWALL LIMITED 70 Van Kirk DR Brampton ON L7A 1B1	EASR

Approval No:	R-010-2110249963	**MOE District:**	Halton-Peel
Status:	REGISTERED	**Municipality:**	Brampton
Date:	2017-10-04	**Latitude:**	43.70472222
Record Type:	EASR	**Longitude:**	-79.80222222
Link Source:	MOFA	**Geometry X:**	
Project Type:	Air Emissions	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Air Emissions		
SWP Area Name:	Credit Valley		
PDF NAICS Code:	332329		
PDF URL:			
PDF Site Location:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
121	1 of 1	WNW/235.2	256.9 / 14.92	PIPELINE HIT 1/2" 21 ROBERTSON DAVIES DR,,BRAMPTON,ON, L7A 1K4,CA ON	PINC

Incident Id:		**Pipe Material:**	
Incident No:	2125764	**Fuel Category:**	
Incident Reported Dt:	7/26/2017	**Health Impact:**	
Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:		**Property Damage:**	
Tank Status:	Pipeline Damage Reason Est	**Service Interrupt:**	
Task No:		**Enforce Policy:**	
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Depth: **Method Details:**
Customer Acct Name: PIPELINE HIT 1/2"
Incident Address: 21 ROBERTSON DAVIES DR,,BRAMPTON,ON,L7A 1K4,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

---

122 **1 of 3** **SSE/49.2** **239.9 / -2.08** **75 Van Kirk Drive**
Brampton ON L7A 1A4 **EHS**

Order No: 20100121020
Status: C
Report Type: Standard Report
Report Date: 1/27/2010
Date Received: 1/21/2010
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Title Search;

Nearest Intersection: Canam Crescent
Municipality: Peel
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.799155
Y: 43.704287

---

122 **2 of 3** **SSE/49.2** **239.9 / -2.08** **Brampton-Canada Associates Ltd.**
75 VAN KIRK DR ON
BRAMPTON ON **RSC**

RSC No: 114530
RA No:
Status: FILED
Filing Date:
Date Ack:
Date Returned:
Approval Date: June 30, 2011
Cert Date:
Cert Prop Use No:
Curr Property Use:
Intended Prop Use:
Restoration Type:
Soil Type:
Criteria:
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
CPU Issu Sect 1686:
Business Name: Brampton-Canada Associates Ltd.
Address: 75 VAN KIRK DR ON
Legal Desc:
Site Pin: 14249-0045(LT), 14249-0044(LT)
Asmt Roll No:
Project Type: PRE2011
Approval Type: RSC based on Phase One and Two ESAs
Applicable Standards:
PDF Link: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=114530

X: -79.79823953737271
Y: 43.704699585101615
Latitude: 43.70469959
Longitude: -79.79823954
UTM Coordinates:
Latitude Longitude:
Accuracy Estimate:
Measurement Method:
Mailing Address:
Telephone:
Fax:
Email:
Postal Code: L7A 1A4
Ministry District:
MOE District: Halton-Peel
SWP Area Name: Credit Valley
Qual Person Name: James L McCourt
Consultant:

---

122 **3 of 3** **SSE/49.2** **239.9 / -2.08** **75 Van Kirk Dr**
Brampton ON **EHS**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No:	20121102027	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Select Report	**Client Prov/State:**	ON
Report Date:	13-NOV-12	**Search Radius (km):**	.25
Date Received:	02-NOV-12	**X:**	-79.798489
Previous Site Name:		**Y:**	43.70491
Lot/Building Size:			
Additional Info Ordered:			

123	1 of 2	WNW/175.6	257.9 / 15.92	**Master Link Marketing Inc.** **26 Robertson Davies Dr** **Brampton ON L7A 1J9**	SCT

Established: 01-JUN-87
Plant Size (ft²):
Employment:

--Details--
Description: Motor Vehicle Plastic Parts Manufacturing
SIC/NAICS Code: 326193

Description: Soap and Cleaning Compound Manufacturing
SIC/NAICS Code: 325610

123	2 of 2	WNW/175.6	257.9 / 15.92	**26 Robertson Davies Drive Brampton, ON** **BRAMPTON ON**	SPL

Ref No:	1-4K6YVO	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	12/29/2023 13:52:40	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	12/29/2023 13:52:40	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			

MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 26 Robertson Davies Drive Brampton, ON
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill: Line Strike
Incident Reason:
Incident Summary: Enbridge: ½" PL IP Brampton; made safe
Environment Impact:
Health Env Consequence: Low
Nature of Impact:
Contaminant Qty: 0 other - see notes

Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	NATURAL GAS
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed:	02HC | Humber River - Don River
Sector Type:	NATURAL GAS DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001762562"],"wkts":["POINT (-79.8314907000 43.7317011000)"],"creation_date":"2023-12-29"}
Time Reported:	
System Facility Address:	

124 **1 of 2** **SSE/91.6** **239.9 / -2.08** **ON** **WWIS**

Well ID:	7164666	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	07/04/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	M10257	**Contractor:**	7472
Tag:	A111118	**Form Version:**	5
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7164666.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/12/2011
Year Completed:	2011
Depth (m):	
Latitude:	43.7046892779981
Longitude:	-79.7989720115893
X:	-79.79897186236111
Y:	43.704689275878614
Path:	716\7164666.pdf

Bore Hole Information

Bore Hole ID:	1003527002	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596768.00
Code OB Desc:		**North83:**	4839775.00

Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	05/12/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

124 **2 of 2** **SSE/91.6** **239.9 / -2.08** **ON** **WWIS**

Well ID:	7169172	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	09/28/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	M10020	**Contractor:**	7472
Tag:	A111118	**Form Version:**	5
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/716\7169172.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/12/2011
Year Completed:	2011
Depth (m):	
Latitude:	43.7046892779981
Longitude:	-79.7989720115893
X:	-79.79897186236111
Y:	43.704689275878614
Path:	716\7169172.pdf

Bore Hole Information

Bore Hole ID:	1003571220	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596768.00
Code OB Desc:		**North83:**	4839775.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	05/12/2011	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

---

125 ***1 of 2*** ***SE/180.2*** ***238.8 / -3.15*** ***Exel Canada Ltd. c/o Keurig Canada***
100 Ironside Dr. Unit 1
Brampton ON L4A0X4 ***GEN***

Generator Info

Generator No:	ON5069849	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	493110
Country:	Canada		
Co Admin:	David Robillard		
Phone No Admin:	416-523-1760 Ext.		
SIC Description:	GENERAL WAREHOUSING AND STORAGE		

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Waste Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

---

125 ***2 of 2*** ***SE/180.2*** ***238.8 / -3.15*** ***DHL Supply Chain***
100 Ironside Dr. Unit 1
Brampton ON L4A0X4 ***GEN***

Generator Info

Generator No:	ON5069849	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	493110
Country:	Canada		
Co Admin:	David Robillard		
Phone No Admin:	416-523-1760 Ext.		
SIC Description:	GENERAL WAREHOUSING AND STORAGE		

Waste Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
126	1 of 1	WNW/17.7	259.9 / 17.92	2650 Mayfield Road lot 18 con 1 Brampton ON	WWIS

Well ID: 7378698
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: IZJB75HF
Tag: _NO_TAG
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 01/19/2021
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7732
Form Version: 9
Owner:
County: PEEL
Lot: 018
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378698.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/13/2021
Year Completed: 2021
Depth (m):
Latitude: 43.7310401668262
Longitude: -79.8334111373808
X: -79.8334109869896
Y: 43.731040165259
Path: 737\7378698.pdf

Bore Hole Information

Bore Hole ID: 1008554350
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/13/2021
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593952.00
North83: 4842662.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008554443
Layer: 1
Color:
General Color:

Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008554512
Layer: 1
Plug From: 0.0
Plug To: 6.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008554496
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008554381
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008554458
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 4.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008554473
Layer: 1
Slot:
Screen Top Depth: 4.5
Screen End Depth: 7.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008554382
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008554410
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 0.10000000149011612
Water Found Depth UOM: m

---

127 | ***1 of 1*** | ***WNW/140.8*** | ***258.8 / 16.86*** | ***LORMEL JOINT VENTURE INC.***
No Municipal Address
Caledon ON | ***RSC***

RSC No:	227349	***X:***	-79.83434996036651
RA No:		***Y:***	43.7297027688435
Status:	FILED	***Latitude:***	43.72970277
Filing Date:		***Longitude:***	-79.83434996
Date Ack:		***UTM Coordinates:***	
Date Returned:		***Latitude Longitude:***	
Approval Date:	November 20, 2020	***Accuracy Estimate:***	
Cert Date:		***Measurement Method:***	
Cert Prop Use No:		***Mailing Address:***	
Curr Property Use:		***Telephone:***	
Intended Prop Use:		***Fax:***	
Restoration Type:		***Email:***	
Soil Type:		***Postal Code:***	
Criteria:		***Ministry District:***	
Stratified (Y/N):		***MOE District:***	Halton-Peel
Audit (Y/N):		***SWP Area Name:***	Credit Valley
Entire Leg Prop. (Y/N):		***Qual Person Name:***	ELENI BEYENE
CPU Issu Sect 1686:		***Consultant:***	

Business Name: LORMEL JOINT VENTURE INC.
Address: No Municipal Address
Legal Desc:
Site Pin: 14252-0978 (LT)
Asmt Roll No:
Project Type: POST2011
Approval Type: RSC based on Phase One and Two ESAs
Applicable Standards:
PDF Link: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=227349

---

128 | ***1 of 1*** | ***WNW/140.1*** | ***258.8 / 16.84*** | ***2650 Mayfield Rd***
Brampton ON L7C 3K7 | ***EHS***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No:	20191001133	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	04-OCT-19	**Search Radius (km):**	.25
Date Received:	01-OCT-19	**X:**	-79.834404
Previous Site Name:		**Y:**	43.729751
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
129	1 of 3	WNW/248.1	256.9 / 14.95	2582011 ONTARIO INC. O/A TRULY NOLEN 32 BAYBROOK RD BRAMPTON ON L7A1M1	PES

Detail Licence No:		**Operator Box:**	
Licence No:	09749	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Operator	**Oper Phone No:**	9700319
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
129	2 of 3	WNW/248.1	256.9 / 14.95	2582011 ONTARIO INC. 32 BAYBROOK RD BRAMPTON ON L7A 1M1	PES

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1039433621	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-01-11	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.73305556	**Operator Region:**	
Longitude:	-79.83222222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Toronto
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2117441		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
129	3 of 3	WNW/248.1	256.9 / 14.95	2582011 ONTARIO INC. 32 BAYBROOK RD BRAMPTON ON L7A 1M1	PES

Detail Licence No:		**Operator Box:**	

Licence No:	L-240-1039433621	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-12-03	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.73305556	**Operator Region:**	
Longitude:	-79.83222222	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Toronto
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2197410

---

130 | ***1 of 1*** | ***WNW/86.2*** | ***259.7 / 17.79*** | ***6152 PENETANGUISHENE RD Springwater ON*** | ***WWIS***

Well ID:	7220338	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Water Supply	**Date Received:**	05/15/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z155541	**Contractor:**	7075
Tag:	A135716	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/722\7220338.pdf

Additional Detail(s) (Map)

Well Completed Date:	04/10/2014
Year Completed:	2014
Depth (m):	54.864
Latitude:	43.7323519274736
Longitude:	-79.8340189413475
X:	-79.83401879129131
Y:	43.73235192524149
Path:	722\7220338.pdf

Bore Hole Information

Bore Hole ID:	1004759615	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593901.00
Code OB Desc:		**North83:**	4842807.00

Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	04/10/2014	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005149548
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	180.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005149560
Layer:	1
Plug From:	0.0
Plug To:	20.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005149559
Method Construction Code:	
Method Construction:	
Other Method Construction:	DR 12

Pipe Information

Pipe ID:	1005149546
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005149553
Layer:	2
Material:	1
Open Hole or Material:	STEEL
Depth From:	174.0
Depth To:	176.0
Casing Diameter:	5.875

Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 1005149552
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From: 2.0
Depth To: 176.0
Casing Diameter: 6.125
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005149554
Layer: 1
Slot: 10
Screen Top Depth: 176.0
Screen End Depth: 180.0
Screen Material: 1
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 6.0

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1005149547
Pump Set At: 170.0
Static Level: 136.0
Final Level After Pumping: 140.0
Recommended Pump Depth: 170.0
Pumping Rate: 8.0
Flowing Rate:
Recommended Pump Rate: 10.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 0
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing:

Draw Down & Recovery

Pump Test Detail ID: 1005149556
Test Type: Draw Down
Test Duration: 40
Test Level: 140.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 1005149555
Test Type: Draw Down
Test Duration: 10
Test Level: 140.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID:	1005149557
Test Type:	Draw Down
Test Duration:	60
Test Level:	140.0
Test Level UOM:	ft

Water Details

Water ID:	1005149551
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	180.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005149549
Diameter:	6.25
Depth From:	0.0
Depth To:	176.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Hole Diameter

Hole ID:	1005149550
Diameter:	6.0
Depth From:	176.0
Depth To:	180.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	*1 of 59*	*SSE/172.8*	*239.9 / -2.08*	***ARMBRO CONSTRUCTION*** ***45 VAN KIRK RD*** ***BRAMPTON ON L7A 1A6***	***NPCB***

Company Code:	F1143
Industry:	
Site Status:	
Transaction Date:	1/29/1996
Inspection Date:	

--Details--

Label:	
Serial No.:	
PCB Type/Code:	High > 10,000 ppm
Location:	
Item/State:	
No. of Items:	
Manufacturer:	
Status:	Stored for Disposal
Contents:	1200.00 KG

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	*2 of 59*	*SSE/172.8*	*239.9 / -2.08*	***ARMBRO CONSTRUCTION LTD.*** ***45 VAN KIRK RD VAN KIRK RD***	***NPCB***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON L7A 1A6	

Company Code: F1017
Industry:
Site Status:
Transaction Date:
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code:
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Storage
Contents:

---

131 | **3 of 59** | **SSE/172.8** | **239.9 / -2.08** | **ARMBRO CONSTRUCTION LTD.**
45 VAN KIRK RD
BRAMPTON ON L7A 1A4 | **OPCB**

Year: 2003
Site Number: 30292A083
Name Owner:
Additional Site Information:

---

131 | **4 of 59** | **SSE/172.8** | **239.9 / -2.08** | **ARMBRO CONSTRUCTION LTD.**
45 VAN KIRK RD
BRAMPTON ON L7A 1A4 | **OPCB**

Year: 1998
Site Number: 30292A083
Name Owner:
Additional Site Information:

--Details--
Quantity: 1.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 200.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 100.00
Address Site:
Description: Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 2.00
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

---

131 | **5 of 59** | **SSE/172.8** | **239.9 / -2.08** | **ARMBRO CONSTRUCTION LTD.**
45 VAN KIRK RD
BRAMPTON ON L7A 1A4 | **OPCB**

Year: 1999
Site Number: 30292A083
Name Owner:
Additional Site Information:

--Details--
Quantity: 1.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 200.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 100.00
Address Site:
Description: Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 2.00
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

---

131 ***6 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***ARMBRO CONSTRUCTION LTD.***
45 VAN KIRK RD
BRAMPTON ON L7A 1A4 ***OPCB***

Year: 2000
Site Number: 30292A083
Name Owner:
Additional Site Information:

--Details--
Quantity: 100.00
Address Site:
Description: Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 2.00
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 200.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Ballasts with High Level PCBs (>1000 ppm)

---

131 ***7 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***ARMBRO CONSTRUCTION***
45 VAN KIRK RD
BRAMPTON ON L7A 1A4 ***OPCB***

Year: 1995
Site Number: 30292A083
Name Owner:
Additional Site Information:

--Details--
Quantity: 1.00
Address Site:

Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 200.00
Address Site:
Description: Weight of Drums of Ballasts with High Level PCBs (>1000 ppm) kg

Quantity: 90.00
Address Site:
Description: Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg

Quantity: 2.00
Address Site:
Description: Number of Transformers with Low Level PCBs (< 1000 ppm) kg

---

131 | **8 of 59** | **SSE/172.8** | **239.9 / -2.08** | **ARMBRO CONSTRUCTION 02-735**
45 VAN KIRK DRIVE C/O 25 VAN KIRK DRIVE, UNIT #8
BRAMPTON ON L7A 1A4 | **GEN**

Generator Info

Generator No: ON0510603
Approval Years: 94,95
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: OTHER IND. CONSTR.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4119

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

131 | **9 of 59** | **SSE/172.8** | **239.9 / -2.08** | **ARMBRO CONSTRUCTION**
45 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 | **GEN**

Generator Info

Generator No: ON0510603
Approval Years: 99
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: OTHER IND. CONSTR.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4119

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

---

131 ***10 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***ARMBRO CONSTRUCTION LTD.***
45 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 ***GEN***

Generator Info

Generator No: ON0510603
Approval Years: 00
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: OTHER IND. CONSTR.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4119

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

131 ***11 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***ARMBRO CONSTRUCTION LTD.***
45 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4 ***GEN***

Generator Info

Generator No: ON0510606
Approval Years: 01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4119

SIC Description: OTHER IND. CONSTR.

Waste Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

131 | ***12 of 59*** | ***SSE/172.8*** | ***239.9 / -2.08*** | ***AECON GROUP INCORPORATED***
45 VAN KIRK DRIVE
BRAMPTON ON | ***GEN***

Generator Info

Generator No: ON3364572
Approval Years: 03,04,06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

---

131 | ***13 of 59*** | ***SSE/172.8*** | ***239.9 / -2.08*** | ***ARMBRO CONSTRUCTION LTD.***
45 VAN KIRK RD
BRAMPTON ON L7A 1A4 | ***OPCB***

Year: 2004
Site Number: 30292A083
Name Owner:
Additional Site Information:

---

131 ***14 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***Aecon Construction and Materials Limited 45 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1A6 CITY OF BRAMPTON ON*** ***EBR***

EBR Registry No: 010-1506
Ministry Ref No: 0088-72VJLH
Notice Type: Instrument Decision
Notice Stage:
Notice Date: May 25, 2009
Proposal Date: August 28, 2007
Year: 2007
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Aecon Construction and Materials Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 45 Van Kirk Drive, Brampton Ontario, Canada L7A 1A6
Comment Period:
URL:
Summary:

Site Location Details:

45 Van Kirk Drive Brampton Regional Municipality of Peel L7A 1A6 CITY OF BRAMPTON

---

131 ***15 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***Strada Crush Limited 45 Van Kirk Road Brampton Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON ON*** ***EBR***

EBR Registry No: 010-1577
Ministry Ref No: 9718-76CLHD
Notice Type: Instrument Decision
Notice Stage:
Notice Date: September 14, 2009
Proposal Date: September 04, 2007
Year: 2007
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Strada Crush Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 69 Connie Crescent, Concord Ontario, Canada L4K 1L3
Comment Period:
URL:
Summary:

Site Location Details:

45 Van Kirk Road Brampton Regional Municipality of Peel L7A 1A4 CITY OF BRAMPTON

---

131 **16 of 59** **SSE/172.8** **239.9 / -2.08** **Petro-Canada**
45 Vankirk Dr.
Brampton ON L7A 1A4 **SPL**

Ref No:	1185-6FZKYB	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/6/2005	**Discharger Report:**	0
Dt MOE Arvl on Scn:		**Material Group:**	Oil
MOE Reported Dt:	9/7/2005	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Petro Canada Service Station<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Petro-Canada		
Client Type:			
Source Type:			
Incident Cause:	Overflow (Tanks Lagoons)		
Incident Preceding Spill:			
Incident Reason:	Unknown - Reason not determined		
Incident Summary:	Petro Canada: Spill of DSL at gas station		
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:	Other Impact(s)		
Contaminant Qty:	150 L		
Contaminant Qty 1:	150		
Contaminant Unit:	L		
Contaminant Code:			
Contaminant Name:	DIESEL FUEL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Service Station		
SAC Action Class:	TSSA - Fuel Safety Branch		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

---

131 **17 of 59** **SSE/172.8** **239.9 / -2.08** **ARMBRO CONSTRUCTION LTD.**
45 VAN KIRK RD
BRAMPTON ON L7A 1A4 **NPCB**

Company Code: F1038
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

--Details--
Label: F103800
Serial No.:
PCB Type/Code: MINERAL OIL/UNKNOWN
Location:
Item/State: TRANSFORMER/FULL
No. of Items: 2
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 100 KG

---

131 | **18 of 59** | **SSE/172.8** | **239.9 / -2.08** | **Strada Aggregates Inc.**
45 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON | **EBR**

EBR Registry No: 010-9990
Ministry Ref No: 2364-84VKVK
Notice Type: Instrument Decision
Notice Stage:
Notice Date: February 10, 2015
Proposal Date: May 12, 2010
Year: 2010
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Strada Aggregates Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 30 Floral Parkway, Vaughan Ontario, Canada L4K 4R1
Comment Period:
URL:
Summary:

Site Location Details:

45 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON

---

131 | **19 of 59** | **SSE/172.8** | **239.9 / -2.08** | **Strada Aggregates Inc.**
45 Van Kirk Rd
Brampton ON L7A 1A4 | **CA**

Certificate #: 1787-7V5KS3
Application Year: 2009
Issue Date: 9/7/2009
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminants:
Emission Control:

---

131 | ***20 of 59*** | ***SSE/172.8*** | ***239.9 / -2.08*** | ***Aecon Construction and Materials Limited*** | ***CA***

45 Van Kirk Dr
Brampton ON L7A 1A4

Certificate #: 8335-763HYS
Application Year: 2007
Issue Date: 11/5/2007
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

131 | ***21 of 59*** | ***SSE/172.8*** | ***239.9 / -2.08*** | ***AECON GROUP INCORPORATED*** | ***GEN***

45 VAN KIRK DRIVE
BRAMPTON ON L7A 1A4

Generator Info

Generator No: ON3364572
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Non-Metallic Mineral Mining and Quarrying

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 212398

Waste Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	22 of 59	SSE/172.8	239.9 / -2.08	Aecon Construction and Materials Limited 45 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A6 CITY OF BRAMPTON ON	EBR

EBR Registry No: 011-6305
Ministry Ref No: 7327-8TYPCG
Notice Type: Instrument Decision
Notice Stage:
Notice Date: February 27, 2015
Proposal Date: May 09, 2012
Year: 2012
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Aecon Construction and Materials Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 45 Van Kirk Drive, Brampton Ontario, Canada L7A 1A6
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

45 Van Kirk Drive Brampton, Regional Municipality of Peel L7A 1A6 CITY OF BRAMPTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	23 of 59	SSE/172.8	239.9 / -2.08	Aecon Construction and Materials Limited/Construction et Materiaux Aecon Limitee 45 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON	EBR

EBR Registry No: 011-8797
Ministry Ref No: 5467-962RZT
Notice Type: Instrument Decision
Notice Stage:
Notice Date: April 06, 2016
Proposal Date: April 12, 2013
Year: 2013
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Aecon Construction and Materials Limited/Construction et Materiaux Aecon Limitee
Site Address:
Location Other:
Proponent Name:
Proponent Address: 12 Canam Crescent, Brampton Ontario, Canada L7A 1A9
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

45 Van Kirk Drive Brampton, Regional Municipality of Peel CITY OF BRAMPTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	24 of 59	SSE/172.8	239.9 / -2.08	AECON GROUP INCORPORATED 45 VAN KIRK DRIVE	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON L7A 1A4	

Generator Info

Generator No:	ON3364572	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	212398
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Non-Metallic Mineral Mining and Quarrying		

Waste Detail(s)

Waste Class:	222
Waste Class Name:	HEAVY FUELS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

131	***25 of 59***	***SSE/172.8***	***239.9 / -2.08***	***SUNCOR ENERGY*** ***45 VANKIRK*** ***BRAMPTON ON L7A1A6***	***GEN***

Generator Info

Generator No:	ON9566259	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	412110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

131	***26 of 59***	***SSE/172.8***	***239.9 / -2.08***	***AECON GROUP INCORPORATED*** ***45 VAN KIRK DRIVE*** ***BRAMPTON ON L7A 1A4***	***GEN***

Generator Info

Generator No:	ON3364572	***Choice of Contact:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Non-Metallic Mineral Mining and Quarrying
Contaminated Fac:
MHSW Facility:
SIC Code: 212398

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

131 | ***27 of 59*** | ***SSE/172.8*** | ***239.9 / -2.08*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** | ***FST***
45 Van Kirk Dr
Brampton ON

Inventory No: 11635081
Inventory Status: active
Installation Year: 2001
Capacity: 25000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS
Dyed Diesel
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

131 | ***28 of 59*** | ***SSE/172.8*** | ***239.9 / -2.08*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** | ***FST***
45 Van Kirk Dr
Brampton ON

Inventory No: 11072721
Inventory Status: active
Installation Year: 1983
Capacity: 46419
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBSClear Diesel; Formerly Dyed DieselOriginally Clear Diesel when first installed
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	29 of 59	SSE/172.8	239.9 / -2.08	SUNCOR ENERGY PRODUCTS PARTNERSHIP 45 Van Kirk Dr Brampton ON	FST

Inventory No: 11072712
Inventory Status: active
Installation Year: 1983
Capacity: 46419
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBSClear Diesel

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	30 of 59	SSE/172.8	239.9 / -2.08	SUNCOR ENERGY 45 VANKIRK BRAMPTON ON L7A1A6	GEN

Generator Info

Generator No: ON9566259
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Petroleum Product Wholesaler-Distributors

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 412110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	31 of 59	SSE/172.8	239.9 / -2.08	AECON GROUP INCORPORATED 45 VAN KIRK DRIVE BRAMPTON ON L7A 1A4	GEN

Generator Info

Generator No: ON3364572
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Non-Metallic Mineral Mining and Quarrying

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 212398

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Detail(s)

Waste Class: 252

Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

131 | **32 of 59** | **SSE/172.8** | **239.9 / -2.08** | **STRADA AGGREGATES**
45 VANKIRK Avenue
BRAMPTON ON L1L6G6 | **NPRI**

NPRI ID:	8800000739	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mr.
Rpt Type ID:		**Cont First Name:**	TONY
Report Year:	2004	**Cont Last Name:**	CUPANI
Not-Current Rpt?:		**Contact Position:**	Health and Safety and Operations Manager
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	STRADA 047	**Cont Area Code:**	905
Fac Address1:		**Contact Tel.:**	6606000
Fac Address2:		**Contact Ext.:**	304
Fac Postal Zip:		**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	6605242
Facility Long:		**Contact Email:**	TONYC@CONSTRADA.COM
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	2	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	21		
NAICS 2 Description:	Mining, Quarrying, and Oil and Gas Extraction		
NAICS Code (4 digit):	2123		
NAICS 4 Description:	Non-Metallic Mineral Mining and Quarrying		
NAICS Code (6 digit):	212323		
NAICS 6 Description:	Sand and Gravel Mining and Quarrying		

Substance Release Report

CAS No: NA - M09
Report ID:
Rpt Period: 2004
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air: .596
Water:
Land:
Total Releases: .596
Units: tonnes

CAS No: NA - M10

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report ID:	
Rpt Period:	2004
Subst Released:	PM2.5 - Particulate Matter <= 2.5 Microns
Air:	.454
Water:	
Land:	
Total Releases:	.454
Units:	tonnes

---

131 | **33 of 59** | **SSE/172.8** | **239.9 / -2.08** | **STRADA AGGREGATES**
45 VANKIRK Avenue
BRAMPTON ON L1L6G6 | **NPRI**

NPRI ID:	8800000120	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mr.
Rpt Type ID:		**Cont First Name:**	TONY
Report Year:	2006	**Cont Last Name:**	CUPANI
Not-Current Rpt?:		**Contact Position:**	Health and Safety and Security
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	STRADA 047	**Cont Area Code:**	905
Fac Address1:		**Contact Tel.:**	6606000
Fac Address2:		**Contact Ext.:**	304
Fac Postal Zip:		**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	6605242
Facility Long:		**Contact Email:**	TONYC@CONSTRADA.COM
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	2	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	21		
NAICS 2 Description:	Mining, Quarrying, and Oil and Gas Extraction		
NAICS Code (4 digit):	2123		
NAICS 4 Description:	Non-Metallic Mineral Mining and Quarrying		
NAICS Code (6 digit):	212323		
NAICS 6 Description:	Sand and Gravel Mining and Quarrying		

Substance Release Report

CAS No:	NA - M09
Report ID:	
Rpt Period:	2006
Subst Released:	PM10 - Particulate Matter <= 10 Microns
Air:	
Water:	
Land:	
Total Releases:	0
Units:	tonnes

CAS No:	NA - M10
Report ID:	
Rpt Period:	2006
Subst Released:	PM2.5 - Particulate Matter <= 2.5 Microns
Air:	
Water:	
Land:	
Total Releases:	0
Units:	tonnes

CAS No:	NA - M08
Report ID:	
Rpt Period:	2006
Subst Released:	PM - Total Particulate Matter
Air:	
Water:	
Land:	
Total Releases:	0
Units:	tonnes

131 | **34 of 59** | **SSE/172.8** | **239.9 / -2.08** | **STRADA AGGREGATES**
45 VANKIRK Avenue
BRAMPTON ON L1L6G6 | **NPRI**

NPRI ID:	8800000146	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mr.
Rpt Type ID:		**Cont First Name:**	TONY
Report Year:	2005	**Cont Last Name:**	CUPANI
Not-Current Rpt?:		**Contact Position:**	Health and Safety and Operations Manager
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	STRADA 047	**Cont Area Code:**	905
Fac Address1:		**Contact Tel.:**	6606000
Fac Address2:		**Contact Ext.:**	304
Fac Postal Zip:		**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	6605242
Facility Long:		**Contact Email:**	TONYC@CONSTRADA.COM
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	2	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	21		
NAICS 2 Description:	Mining, Quarrying, and Oil and Gas Extraction		
NAICS Code (4 digit):	2123		
NAICS 4 Description:	Non-Metallic Mineral Mining and Quarrying		
NAICS Code (6 digit):	212323		
NAICS 6 Description:	Sand and Gravel Mining and Quarrying		

Substance Release Report

CAS No: NA - M09
Report ID:
Rpt Period: 2005
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air:
Water:
Land:
Total Releases: 0
Units: tonnes

CAS No: NA - M10
Report ID:
Rpt Period: 2005
Subst Released: PM2.5 - Particulate Matter <= 2.5 Microns
Air:
Water:
Land:
Total Releases: 0
Units: tonnes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	35 of 59	SSE/172.8	239.9 / -2.08	AECON GROUP INCORPORATED 45 VAN KIRK DRIVE BRAMPTON ON	GEN

Generator Info

Generator No: ON3364572
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ALL OTHER NON-METALLIC MINERAL MINING AND QUARRYING

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 212398

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Detail(s)

Waste Class: 252

Waste Class Name: WASTE OILS & LUBRICANTS

---

131 **36 of 59** **SSE/172.8** **239.9 / -2.08** **SUNCOR ENERGY** **GEN**
45 VANKIRK
BRAMPTON ON

Generator Info

Generator No:	ON9566259	**Choice of Contact:**	
Approval Years:	2013	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	412110
Country:			
Co Admin:			
Phone No Admin:			

SIC Description: PETROLEUM PRODUCT WHOLESALER-DISTRIBUTORS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

131 **37 of 59** **SSE/172.8** **239.9 / -2.08** **Aecon Construction and Materials Limited/Construction et Materiaux Aecon Limitee** **ECA**
45 Van Kirk Dr
Brampton ON L7A 1A9

Approval No:	4306-A3FPKT	**MOE District:**	Halton-Peel
Approval Date:	2016-04-01	**City:**	
Status:	Approved	**Longitude:**	-79.80368
Record Type:	ECA	**Latitude:**	43.707226
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Aecon Construction and Materials Limited/Construction et Materiaux Aecon Limitee
Address: 45 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5467-962RZT-14.pdf
PDF Site Location:

---

131 **38 of 59** **SSE/172.8** **239.9 / -2.08** **Strada Aggregates Inc.** **ECA**
45 Van Kirk Rd
Brampton ON L4K 1L3

Approval No:	1787-7V5KS3	**MOE District:**	Halton-Peel
Approval Date:	2009-09-07	**City:**	
Status:	Approved	**Longitude:**	-79.799515
Record Type:	ECA	**Latitude:**	43.70263
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Strada Aggregates Inc.
Address: 45 Van Kirk Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9718-76CLHD-14.pdf
PDF Site Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	39 of 59	SSE/172.8	239.9 / -2.08	Aecon Construction and Materials Limited 45 Van Kirk Dr Brampton ON M9W 7K6	ECA

Approval No: 8335-763HYS
Approval Date: 2007-11-05
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Aecon Construction and Materials Limited
Address: 45 Van Kirk Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8186-75DNXT-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.80368
Latitude: 43.707226
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	40 of 59	SSE/172.8	239.9 / -2.08	AECON CONSTRUCTION AND MATERIALS LTD. 45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	GEN

Generator Info

Generator No: ON3364572
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Sean Roberge
Phone No Admin: 905-876-2434 Ext.233
SIC Description: ALL OTHER NON-METALLIC MINERAL MINING AND QUARRYING

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 212398

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	41 of 59	SSE/172.8	239.9 / -2.08	AECON GROUP INCORPORATED 45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	GEN

Generator Info

Generator No:	ON3364572	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	212398
Country:	Canada		
Co Admin:	Sean Roberge		
Phone No Admin:	905-876-2434 Ext.233		
SIC Description:	ALL OTHER NON-METALLIC MINERAL MINING AND QUARRYING		

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Waste Detail(s)

Waste Class:	222
Waste Class Name:	HEAVY FUELS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	42 of 59	SSE/172.8	239.9 / -2.08	SUNCOR ENERGY 45 VANKIRK BRAMPTON ON L7A1A6	GEN

Generator Info

Generator No:	ON9566259	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	412110
Country:	Canada		
Co Admin:	JOHN AUTERBERRY		
Phone No Admin:	905-469-3769 Ext.		
SIC Description:	PETROLEUM PRODUCT WHOLESALER-DISTRIBUTORS		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

131 ***43 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***SUNCOR ENERGY*** ***GEN***
45 VANKIRK
BRAMPTON ON L7A1A6

Generator Info

Generator No: ON9566259
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: JOHN AUTERBERRY
Phone No Admin: 905-469-3769 Ext.
SIC Description: PETROLEUM PRODUCT WHOLESALER-DISTRIBUTORS
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 412110

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

131 ***44 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***SUNCOR ENERGY*** ***GEN***
45 VANKIRK
BRAMPTON ON L7A1A6

Generator Info

Generator No: ON9566259
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: JOHN AUTERBERRY
Phone No Admin: 905-469-3769 Ext.
SIC Description: PETROLEUM PRODUCT WHOLESALER-DISTRIBUTORS
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 412110

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

131 ***45 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***AECON GROUP INCORPORATED*** ***GEN***
45 VAN KIRK DRIVE
BRAMPTON ON L7A 1A6

Generator Info

Generator No: ON3364572
Approval Years: 2014
Status:
PO Box No:
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 212398

Country: Canada
Co Admin: Sean Roberge
Phone No Admin: 905-876-2434 Ext.233
SIC Description: ALL OTHER NON-METALLIC MINERAL MINING AND QUARRYING

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 222
Waste Class Name: HEAVY FUELS

---

131 | **46 of 59** | **SSE/172.8** | **239.9 / -2.08** | **AECON CONSTRUCTION AND MATERIALS LTD.**
45 VAN KIRK DRIVE
BRAMPTON ON L7A 1A6 | **GEN**

Generator Info

Generator No: ON3364572
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 222 I
Waste Class Name: Heavy fuels

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

131	47 of 59	SSE/172.8	239.9 / -2.08	**SUNCOR ENERGY** **45 VANKIRK** **BRAMPTON ON L7A1A6**	GEN

Generator Info

Generator No: ON9566259
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

131	48 of 59	SSE/172.8	239.9 / -2.08	**Aecon Construction and Materials Limited** **45 Van Kirk Dr** **Brampton ON**	NCPL

Year: 2016
Type of Concern: Legislation Non-Compliance
Contaminant: BENZO[A]PYRENE
Discharge Type: Air Emissions
Status Report:
Sector: Miscellaneous Industrial
Site Address: 45 Van Kirk Dr
District Area: Halton Peel
Facility Owner: Aecon Construction and Materials Limited
Site Name:

Details

Incident Date:
Exceedance Start Date: 7/1/2016
Exceedance End Date: 12/31/2016
Limit/Unit/Freq: 0.00001µg/m³ / annual avg
Quantity Min/Max: 0.0000198/0.0000198
Facility Action: Other
Ministry Action: Assessment underway

131	49 of 59	SSE/172.8	239.9 / -2.08	**AECON CONSTRUCTION AND MATERIALS LTD.** **45 VAN KIRK DRIVE** **BRAMPTON ON L7A 1A6**	GEN

Generator Info

Generator No: ON3364572
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 222 I
Waste Class Name: Heavy fuels

131	*50 of 59*	*SSE/172.8*	*239.9 / -2.08*	***SUNCOR ENERGY*** ***45 VANKIRK*** ***BRAMPTON ON L7A1A6***	***GEN***

Generator Info

Generator No: ON9566259
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	51 of 59	SSE/172.8	239.9 / -2.08	AECON CONSTRUCTION AND MATERIALS LTD. 45 VAN KIRK DRIVE BRAMPTON ON L7A 1A6	GEN

Generator Info

Generator No:	ON3364572	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	222 I
Waste Class Name:	Heavy fuels

Waste Detail(s)

Waste Class:	221 I
Waste Class Name:	Light fuels

Waste Detail(s)

Waste Class:	213 L
Waste Class Name:	Petroleum distillates

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	52 of 59	SSE/172.8	239.9 / -2.08	SUNCOR ENERGY 45 VANKIRK BRAMPTON ON L7A1A6	GEN

Generator Info

Generator No:	ON9566259	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	221 L
Waste Class Name:	Light fuels

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 221 I
Waste Class Name: Light fuels

---

131 | **53 of 59** | **SSE/172.8** | **239.9 / -2.08** | **GIP Constructions and Materials Limited**
45 VAN KIRK DRIVE
BRAMPTON ON | **GEN**

Generator Info

Generator No: ON3364572
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 213 L
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 222 I
Waste Class Name: HEAVY FUELS

Generator Info as of Dec 2024

Generator No: ON3364572
Generator Company Name: GIP Constructions and Materials Limited
Street: 45 VAN KIRK DRIVE
City: BRAMPTON
Province State: Ontario
Country: Canada
Postal Code: L7A1A6
Waste Class: 221 I, 222 I, 252 L, 213 L

Waste Class Decoded:

221 - LIGHT FUELS; 222 - HEAVY FUELS; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES

Generator Info as of Dec 2024

Generator No: ON3364572

Generator Company Name:	GIP Constructions and Materials Limited
Street:	45 VAN KIRK DRIVE
City:	BRAMPTON
Province State:	Ontario
Country:	Canada
Postal Code:	L7A1A6
Waste Class:	221 I,222 I,252 L,213 L,251 L

Waste Class Decoded:

221 - LIGHT FUELS; 222 - HEAVY FUELS; 252 - WASTE OILS & LUBRICANTS; 213 - PETROLEUM DISTILLATES; 251 - OIL SKIMMINGS & SLUDGES

2017 Generator Info

Gen No:	ON3364572	***Choice of Contact:***	CO_OFFICIAL
ID:	13557	***Phone No Official:***	905-876-2434 Ext.2234
Contaminated Fac:	N	***Phone No Admin:***	905-876-2434 Ext.233
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	212398	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	AECON CONSTRUCTION AND MATERIALS LTD.
Gen Div:	
Gen Op Name:	AECON CONSTRUCTION AND MATERIALS LTD.
Gen Op Div:	
Site Adrs1:	45 VAN KIRK DRIVE
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 1A6
Site Country:	Canada
Co Official:	Blair Dukeshire
Co Admin:	Sean Roberge

2018 Generator Info

Gen No:	ON3364572	***Choice of Contact:***	CO_OFFICIAL
ID:	13408	***Phone No Official:***	905-876-2434 Ext.2234
Contaminated Fac:	N	***Phone No Admin:***	905-876-2434 Ext.233
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	212398	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	AECON CONSTRUCTION AND MATERIALS LTD.
Gen Div:	
Gen Op Name:	AECON CONSTRUCTION AND MATERIALS LTD.
Gen Op Div:	
Site Adrs1:	45 VAN KIRK DRIVE
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 1A6
Site Country:	Canada
Co Official:	Blair Dukeshire
Co Admin:	Sean Roberge

2019 Generator Info

Gen No:	ON3364572	***Choice of Contact:***	CO_OFFICIAL
ID:	13180	***Phone No Official:***	905-876-2434 Ext.2234
Contaminated Fac:	N	***Phone No Admin:***	905-876-2434 Ext.233
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	212398	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	AECON CONSTRUCTION AND MATERIALS LTD.		
Gen Div:			
Gen Op Name:	AECON CONSTRUCTION AND MATERIALS LTD.		
Gen Op Div:			
Site Adrs1:	45 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1A6		
Site Country:	Canada		
Co Official:	Blair Dukeshire		
Co Admin:	Sean Roberge		

2020 Generator Info

Gen No:	ON3364572	***Choice of Contact:***	CO_OFFICIAL
ID:	12857	***Phone No Official:***	905-876-2434 Ext.2234
Contaminated Fac:	N	***Phone No Admin:***	905-876-2434 Ext.233
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	212398	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	AECON CONSTRUCTION AND MATERIALS LTD.		
Gen Div:			
Gen Op Name:	AECON CONSTRUCTION AND MATERIALS LTD.		
Gen Op Div:			
Site Adrs1:	45 VAN KIRK DRIVE		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1A6		
Site Country:	Canada		
Co Official:	Blair Dukeshire		
Co Admin:	Sean Roberge		

2021 Generator Info

Gen No:	ON3364572	***Choice of Contact:***	CO_OFFICIAL
ID:	12708	***Phone No Official:***	905-876-2434 Ext.2234
Contaminated Fac:	N	***Phone No Admin:***	905-876-2434 Ext.233
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	212398	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	AECON CONSTRUCTION AND MATERIALS LTD.		
Gen Div:			
Gen Op Name:	AECON CONSTRUCTION AND MATERIALS LTD.		
Gen Op Div:			

Site Adrs1:	45 VAN KIRK DRIVE
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A 1A6
Site Country:	Canada
Co Official:	Blair Dukeshire
Co Admin:	Sean Roberge

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
131	54 of 59	SSE/172.8	239.9 / -2.08	SUNCOR ENERGY 45 VANKIRK BRAMPTON ON L7A1A6	GEN

Generator Info

Generator No:	ON9566259	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	221 L
Waste Class Name:	LIGHT FUELS

Waste Detail(s)

Waste Class:	221 I
Waste Class Name:	LIGHT FUELS

2017 Generator Info

Gen No:	ON9566259	**Choice of Contact:**	CO_OFFICIAL
ID:	37355	**Phone No Official:**	905-469-3794 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905-469-3769 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	412110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	SUNCOR ENERGY		
Gen Div:			
Gen Op Name:	SUNCOR ENERGY		
Gen Op Div:			
Site Adrs1:	45 VANKIRK		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A1A6		
Site Country:	Canada		
Co Official:	CRAIG BUJARSKY		
Co Admin:	JOHN AUTERBERRY		

2017 Generator Manifest

ID:	66094	***Sum Received Qty:***	8600.0
Generator No:	ON9566259	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	251		

2018 Generator Info

Gen No:	ON9566259	***Choice of Contact:***	CO_OFFICIAL
ID:	38088	***Phone No Official:***	905-469-3794 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905-469-3769 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	412110	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SUNCOR ENERGY		
Gen Div:			
Gen Op Name:	SUNCOR ENERGY		
Gen Op Div:			
Site Adrs1:	45 VANKIRK		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A1A6		
Site Country:	Canada		
Co Official:	CRAIG BUJARSKY		
Co Admin:	JOHN AUTERBERRY		

2018 Generator Manifest

ID:	66631	***Sum Received Qty:***	1300.0
Generator No:	ON9566259	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	251		

2019 Generator Info

Gen No:	ON9566259	***Choice of Contact:***	CO_OFFICIAL
ID:	38651	***Phone No Official:***	905-804-3856 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905-469-3769 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	412110	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SUNCOR ENERGY		
Gen Div:			
Gen Op Name:	SUNCOR ENERGY		
Gen Op Div:			
Site Adrs1:	45 VANKIRK		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			

Site Postal Code: L7A1A6
Site Country: Canada
Co Official: Michelle Chandler
Co Admin: JOHN AUTERBERRY

2019 Generator Manifest

ID: 66692
Generator No: ON9566259
Receiver Type: 035
Waste Char: I
Waste Code: 221
Sum Received Qty: 9515.0
Waste Class Name: LIGHT FUELS
Count Manifests: 2
District: 306

2020 Generator Info

Gen No: ON9566259
ID: 38405
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 412110
NAICS Code2:
NAICS Code3:
Gen Name: SUNCOR ENERGY
Gen Div:
Gen Op Name: SUNCOR ENERGY
Gen Op Div:
Site Adrs1: 45 VANKIRK
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A1A6
Site Country: Canada
Co Official: Michelle Chandler
Co Admin: JOHN AUTERBERRY
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-804-3856 Ext.
Phone No Admin: 905-469-3769 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2021 Generator Info

Gen No: ON9566259
ID: 39441
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 412110
NAICS Code2:
NAICS Code3:
Gen Name: SUNCOR ENERGY
Gen Div:
Gen Op Name: SUNCOR ENERGY
Gen Op Div:
Site Adrs1: 45 VANKIRK
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L7A1A6
Site Country: Canada
Co Official: Michelle Chandler
Co Admin: JOHN AUTERBERRY
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-804-3856 Ext.
Phone No Admin: 905-469-3769 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2021 Generator Manifest

ID:	65633	***Sum Received Qty:***	5600.0
Generator No:	ON9566259	***Waste Class Name:***	LIGHT FUELS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	221		

---

131 ***55 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***GIP Construction and Materials Limited*** ***EBR***
45 Van Kirk Drive Brampton, ON L7A 1A6
Canada
ON

EBR Registry No:	019-6083	***Decision Posted:***	August 20, 2024
Ministry Ref No:	6407-C3TE7N	***Exception Posted:***	
Notice Type:	Instrument	***Section:***	Ontario Regulation 419/05, section 39 (3)
Notice Stage:	Decision	***Act 1:***	Environmental Protection Act, R.S.O. 1990
Notice Date:		***Act 2:***	Environmental Protection Act
Proposal Date:	March 23, 2023	***Site Location Map:***	43.702579,-79.799572
Year:	0023		

Instrument Type: Approval to register for a technical standard for air pollution (industry standard)

Off Instrument Name: Approval for registration in the "Technical Standards Registry – Air Pollution" (Industry Standard) (EPA reg. 419 s. 39(3))

Posted By: Ministry of the Environment, Conservation and Parks

Company Name:

Site Address:
45 Van Kirk Drive
Brampton,
ON
L7A 1A6
Canada

Location Other:

Proponent Name: GIP Construction and Materials Limited

Proponent Address:
GIP Construction and Materials Limited
20 Carlson Court
Toronto,
ON
M9W 7K6
Canada

Comment Period: March 23, 2023 - May 7, 2023 (45 days) Closed

URL: https://ero.ontario.ca/notice/019-6083

Summary: We have granted approval to GIP Construction and Materials Limited (formerly AECON Construction and Materials Limited), located in Brampton, Ontario, to be registered under the Technical Standards Registry – Air Pollution. This facility will adhere to all technical and operational requirements in the Asphalt Mix – Industry Standard.

Site Location Details:

---

131 ***56 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***BRAMPTON ASPHALT PLANT*** ***NPR2***
45 VAN KIRK DRIVE
BRAMPTON ON L7A1A6

NPRI ID:	10560	***Latitude:***	43.7019
Facility ID:	243507;381118	***Longitude:***	-79.7993

Facility Name: BRAMPTON ASPHALT PLANT

Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=10560

NPRI ID Substances Summary

CAS No:		***Is PAH?:***	
Is VOC?:		***NPRI:***	
Is DF?:			
Name English:			
Name French:			
Sort English:			
Sort French:			

CAS No:	NA - M10	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Name French:	PM2,5 - Matière particulaire <= 2,5 micromètres		
Sort English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Sort French:	PM2,5 - Matière particulaire <= 2,5 micromètres		

CAS No:	NA - M09	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	PM10 - Particulate Matter <= 10 Micrometers		
Name French:	PM10 - Matière particulaire <= 10 micromètres		
Sort English:	PM10 - Particulate Matter <= 10 Micrometers		
Sort French:	PM10 - Matière particulaire <= 10 micromètres		

CAS No:	NA - M08	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Total particulate matter		
Name French:	Matière particulaire totale		
Sort English:	PM - Total Particulate Matter		
Sort French:	PM - Particules totales		

CAS No:	630-08-0	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	Carbon monoxide		
Name French:	Monoxyde de carbone		
Sort English:	Carbon monoxide		
Sort French:	Oxyde de carbone (monoxyde de carbone)		

Geographic Location

Report Year:	-1	***Forward Sort Area:***	L6Z
Census Subdiv ID:	3521010	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-044-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.7019
QC PEMA:	FALSE	***Longitude:***	-79.7993
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	10560
Facility ID:	381118

Facility

Facility ID:	381118	**IDM ID:**	0
Portable:	FALSE	**AB Approval ID:**	0
NAICS Primary:	324121	**GHGRP ID:**	0
NAICS Secondary:	0	**ON GHGRP ID:**	0
NAICS Tertiary:	0		
Facility Name:	BRAMPTON ASPHALT PLANT		
Website:			

Address

Address1:	45 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A6
Prov:	

Primary NAICS Details

NAICS Code:	324121	**Start Date:**	2002
Record Year:	2002	**End Date:**	2006
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	**Start Date:**	1993
Record Year:	1997	**End Date:**	2001
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	**Start Date:**	2007
Record Year:	2007	**End Date:**	2011
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron achetés.

NAICS Code:	324121	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir

d'asphalte, de goudron ou de matériaux bitumineux.

NPRI Report

Report ID:	276152	***No of Employees:***	7
Report Year:	2002	***Is Compressor:***	
Company ID:	135687	***Is NPRI Part 4:***	
SWR Report ID:	20020000010560	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2003-06-02 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS LIMITED
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054541078
First Name:	Dan	***Extension:***	41
Last Name:	Capobianco	***Fax:***	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Asphalt Services		
Language:	0		
Email:	dcapobianco@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Phil	***Extension:***	40
Last Name:	Gignac	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Plant Manager		
Language:	0		
Email:	pgignac@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Project Coordinator		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9064541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827

Company Name:
Description En:
Description Fr:
Position: Project Coordinator
Language: 0
Email: cburpee@aecon.com

NPRI ID Facility ID

NPRI ID: 10560
Facility ID: 243507

Facility

Facility ID: 243507
Portable: FALSE
NAICS Primary: 324121
NAICS Secondary: 0
NAICS Tertiary: 0
Facility Name: Brampton Asphalt Plant
Website:
IDM ID: 11147
AB Approval ID: 0
GHGRP ID: 0
ON GHGRP ID: 0

Address

Address1: 45 Van Kirk Drive
Address2:
City: BRAMPTON
Postal Zip: L7A1A6
Prov:

Address Geographic

Latitude: 43.7019
Longitude: -79.7993
UTM Easting: 0.000000
UTM Northing: 0.000000
UTM Zone: 0
Datum: 1983
Land Survey:
Topograph:
Additional Info:

Primary NAICS Details

NAICS Code: 324121
Record Year: 1997
Key Indus Sector En: Petroleum and Coal Product Refining and Mfg.
Key Indus Sector Fr: Fabrication et raffinage des produits du pétrole et du charbon
NAICS Title En: Asphalt Paving Mixture and Block Manufacturing
NAICS Title Fr: Fabrication de mélanges d'asphaltage et de pavés d'asphalte
Start Date: 1993
End Date: 2001

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code: 324121
Record Year: 2002
Key Indus Sector En: Petroleum and Coal Product Refining and Mfg.
Start Date: 2002
End Date: 2006

Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron achetés.

NAICS Code:	324121	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NPRI Report

Report ID:	61189	***No of Employees:***	0
Report Year:	2011	***Is Compressor:***	
Company ID:	111553	***Is NPRI Part 4:***	
SWR Report ID:	12443	***Is Battery:***	
Repor Type ID:	3	***Corres Lang ID:***	1
New Reporter:	FALSE	***Submit Date:***	2015-04-08 00:00:00.0000000

Company

Company Name:	Aecon Construction & Materials Ltd.
DUNS No:	208904482
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	Reason the facility does not meet the criteria for NPRI
Description Fr:	La raison pour laquelle cette installation ne rencontre pas les critères de déclaration de l'INRP
Comment:	Facility did not meet the employee screening criteria nor did it meet the reporting thresholds for Part 4 contaminants from stationary combustion equipment.
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Donn	***Extension:***	
Last Name:	Bernal	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	General Manager, Materials		
Language:	1		
Email:	dbernal@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9052354218
First Name:	Christina	***Extension:***	112
Last Name:	Wright	***Fax:***	9052354219
Company Name:	BCX Environmental Consulting		
Description En:			
Description Fr:			
Position:	Environmental Compliance Specialist		
Language:	1		
Email:	cwright@bcxenvironmental.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Donn	***Extension:***	
Last Name:	Bernal	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	General Manager, Materials		
Language:	1		
Email:	dbernal@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9052354218
First Name:	Christina	***Extension:***	112
Last Name:	Wright	***Fax:***	9052354219
Company Name:	BCX Environmental Consulting		
Description En:			
Description Fr:			
Position:	Environmental Compliance Specialist		
Language:	1		
Email:	cwright@bcxenvironmental.com		

NPRI Report

Report ID:	138208	***No of Employees:***	5
Report Year:	2010	***Is Compressor:***	
Company ID:	111553	***Is NPRI Part 4:***	
SWR Report ID:	20100000010560	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2011-06-17 00:00:00.0000000

Company

Company Name:	Aecon Construction & Materials Ltd.
DUNS No:	208904482
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	5242
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			

Position: Manager Asphalt Operations
Language: 0
Email: cburpee@aecon.com

NPRI Report Contact

Contact Type:
First Name: Colin
Last Name: Burpee
Company Name:
Description En:
Description Fr:
Position: Manager Asphalt Operations
Language: 0
Email: cburpee@aecon.com
Phone: 9054541078
Extension: 5242
Fax: 9054519827

NPRI Report Contact

Contact Type:
First Name: Colin
Last Name: Burpee
Company Name:
Description En:
Description Fr:
Position: Manager Asphalt Operations
Language: 0
Email: cburpee@aecon.com
Phone: 9054541078
Extension: 5242
Fax: 9054519827

NPRI Report

Report ID: 131827
Report Year: 2009
Company ID: 129445
SWR Report ID: 20090000010560
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 8
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 2010-05-25 00:00:00.0000000

Company

Company Name: AECON CONSTRUCTION & MATERIALS
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type:
First Name: Colin
Last Name: Burpee
Company Name:
Description En:
Description Fr:
Position: Manager Asphalt Operations
Language: 0
Email: cburpee@aecon.com
Phone: 9054541078
Extension: 5242
Fax: 9054519827

NPRI Report Contact

Contact Type:
First Name: Colin
Phone: 9054541078
Extension: 5242

Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	5242
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	123092	**No of Employees:**	8
Report Year:	2008	**Is Compressor:**	
Company ID:	129445	**Is NPRI Part 4:**	
SWR Report ID:	20080000010560	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2009-05-26 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	5242
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	5242
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	5242
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	153226	***No of Employees:***	8
Report Year:	2007	***Is Compressor:***	
Company ID:	129445	***Is NPRI Part 4:***	
SWR Report ID:	20070000010560	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2008-05-26 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	This asphalt plant operates under OHMPA's Best Practices
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	152843	**No of Employees:**	8
Report Year:	2006	**Is Compressor:**	
Company ID:	129445	**Is NPRI Part 4:**	
SWR Report ID:	20060000010560	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2007-05-31 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	42
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	42
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	255303	**No of Employees:**	8
Report Year:	2005	**Is Compressor:**	
Company ID:	129445	**Is NPRI Part 4:**	
SWR Report ID:	20050000010560	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2006-05-29 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	42

Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	42
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	169902	**No of Employees:**	8
Report Year:	2004	**Is Compressor:**	
Company ID:	129445	**Is NPRI Part 4:**	
SWR Report ID:	20040000010560	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2005-07-06 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9054541078
First Name:	Dan	**Extension:**	41
Last Name:	Capobianco	**Fax:**	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Asphalt Services		
Language:	0		
Email:	dcapobianco@aecon.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	42
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manager		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manager		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	174761	***No of Employees:***	8
Report Year:	2003	***Is Compressor:***	
Company ID:	135405	***Is NPRI Part 4:***	
SWR Report ID:	20030000010560	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	TRUE	***Submit Date:***	2004-06-01 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS LIMITED
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054541078
First Name:	Dan	***Extension:***	41
Last Name:	Capobianco	***Fax:***	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Asphalt Services		
Language:	0		
Email:	dcapobianco@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manager		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manager		

Language: 0
Email: cburpee@aecon.com

Alternative Location Info

Facility ID: 243507
Facility Name: BRAMPTON ASPHALT PLANT
Address1: 45 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A6
Province EN: ON
Latitude: 43.7019
Longitude: -79.7993

Alternative Location Info

Facility ID: 381118
Facility Name: BRAMPTON ASPHALT PLANT
Address1: 45 VAN KIRK DRIVE
City: BRAMPTON
Postal ZIP: L7A1A6
Province EN: ON
Latitude: 43.7019
Longitude: -79.7993

---

131 | **57 of 59** | **SSE/172.8** | **239.9 / -2.08** | **PORTABLE PLANT #3**
45 VAN KIRK DRIVE
BRAMPTON ON L7A1A6 | **NPR2**

NPRI ID: 10736
Facility ID: 357666
Facility Name: PORTABLE PLANT #3
Latitude: 43.702599
Longitude: -79.797997
Note: Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0.

For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report:

https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=10736

NPRI ID Substances Summary

CAS No: NA - M10
Is VOC?: FALSE
Is DF?: FALSE
Is PAH?: FALSE
NPRI: TRUE
Name English: PM2.5 - Particulate Matter <= 2.5 Micrometers
Name French: PM2,5 - Matière particulaire <= 2,5 micromètres
Sort English: PM2.5 - Particulate Matter <= 2.5 Micrometers
Sort French: PM2,5 - Matière particulaire <= 2,5 micromètres

CAS No: NA - M08
Is VOC?: FALSE
Is DF?: FALSE
Is PAH?: FALSE
NPRI: TRUE
Name English: Total particulate matter
Name French: Matière particulaire totale
Sort English: PM - Total Particulate Matter
Sort French: PM - Particules totales

CAS No: NA - M09
Is VOC?: FALSE
Is PAH?: FALSE
NPRI: TRUE

Is DF?:	FALSE
Name English:	PM10 - Particulate Matter <= 10 Micrometers
Name French:	PM10 - Matière particulaire <= 10 micromètres
Sort English:	PM10 - Particulate Matter <= 10 Micrometers
Sort French:	PM10 - Matière particulaire <= 10 micromètres

Geographic Location

Report Year:	2008	***Forward Sort Area:***	L6Z
Census Subdiv ID:	3521010	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-044-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.702599
QC PEMA:	FALSE	***Longitude:***	-79.797997
Quebec Windsor Corr:	TRUE		

Geographic Location

Report Year:	2003	***Forward Sort Area:***	L6Z
Census Subdiv ID:	3521010	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-044-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.702599
QC PEMA:	FALSE	***Longitude:***	-79.797997
Quebec Windsor Corr:	TRUE		

Geographic Location

Report Year:	2004	***Forward Sort Area:***	L6Z
Census Subdiv ID:	3521010	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-044-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.702599
QC PEMA:	FALSE	***Longitude:***	-79.797997
Quebec Windsor Corr:	TRUE		

Geographic Location

Report Year:	2005	***Forward Sort Area:***	L6Z
Census Subdiv ID:	3521010	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-044-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.702599
QC PEMA:	FALSE	***Longitude:***	-79.797997
Quebec Windsor Corr:	TRUE		

Geographic Location

Report Year:	2006	***Forward Sort Area:***	L6Z
Census Subdiv ID:	3521010	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-044-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.702599

QC PEMA:	FALSE	***Longitude:***	-79.797997
Quebec Windsor Corr:	TRUE		

Geographic Location

Report Year:	2007	***Forward Sort Area:***	L6Z
Census Subdiv ID:	3521010	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-044-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	43.702599
QC PEMA:	FALSE	***Longitude:***	-79.797997
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	10736
Facility ID:	357666

Facility

Facility ID:	357666	***IDM ID:***	0
Portable:	TRUE	***AB Approval ID:***	0
NAICS Primary:	324121	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	PORTABLE PLANT #3		
Website:			

Address

Address1:	45 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A6
Prov:	

Address Geographic

Latitude:	43.7026	***Datum:***	0
Longitude:	-79.798	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	324121	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron achetés.

NAICS Code:	324121	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016

Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon
NAICS Title En:	Asphalt paving mixture and block manufacturing
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NPRI Report

Report ID:	116165	***No of Employees:***	4
Report Year:	2008	***Is Compressor:***	
Company ID:	129445	***Is NPRI Part 4:***	
SWR Report ID:	20080000010736	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2009-05-26 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	5242
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	5242
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	5242
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	151837	***No of Employees:***	4
Report Year:	2007	***Is Compressor:***	
Company ID:	129445	***Is NPRI Part 4:***	
SWR Report ID:	20070000010736	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2008-05-26 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	This asphalt plant is currently holding OHMPA Trillium status and operates under OHMPA's Best Practices.
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	4162972600
First Name:	Kevin	***Extension:***	3721
Last Name:	Martin	***Fax:***	4169402283
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Estimator/Coordinator		
Language:	0		
Email:	kmartin@aecon.com		

NPRI Report

Report ID:	154042	***No of Employees:***	4
Report Year:	2006	***Is Compressor:***	
Company ID:	129445	***Is NPRI Part 4:***	
SWR Report ID:	20060000010736	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2007-05-31 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	4162972600
First Name:	Kevin	***Extension:***	3721
Last Name:	Martin	***Fax:***	4169402283
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Estimator/Coordinator		
Language:	0		
Email:	kmartin@aecon.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		

Position: Manager, Asphalt Operations
Language: 0
Email: cburpee@aecon.com

NPRI Report Contact

Contact Type: | ***Phone:*** 9054541078
First Name: Colin | ***Extension:*** 42
Last Name: Burpee | ***Fax:*** 9054519827
Company Name:
Description En:
Description Fr:
Position: Manager, Asphalt Operations
Language: 0
Email: cburpee@aecon.com

NPRI Report Contact

Contact Type: | ***Phone:*** 9054541078
First Name: Colin | ***Extension:*** 42
Last Name: Burpee | ***Fax:*** 9054519827
Company Name:
Description En:
Description Fr:
Position: Manager, Asphalt Operations
Language: 0
Email: cburpee@aecon.com

NPRI Report

Report ID: 176887 | ***No of Employees:*** 4
Report Year: 2005 | ***Is Compressor:***
Company ID: 129445 | ***Is NPRI Part 4:***
SWR Report ID: 20050000010736 | ***Is Battery:***
Repor Type ID: 1 | ***Corres Lang ID:*** 0
New Reporter: FALSE | ***Submit Date:*** 2006-05-29 00:00:00.0000000

Company

Company Name: AECON CONSTRUCTION & MATERIALS
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Contact

Contact Type: | ***Phone:*** 9054541078
First Name: Colin | ***Extension:*** 42
Last Name: Burpee | ***Fax:*** 9054519827
Company Name:
Description En:
Description Fr:
Position: Manager, Asphalt Operations
Language: 0
Email: cburpee@aecon.com

NPRI Report Contact

Contact Type: | ***Phone:*** 4162972600
First Name: Kevin | ***Extension:*** 3721

Last Name:	Martin	**Fax:**	4169402283
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Estimator/Coordinator		
Language:	0		
Email:	kmartin@aecon.com		

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	42
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9054541078
First Name:	Colin	**Extension:**	42
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	264224	**No of Employees:**	4
Report Year:	2004	**Is Compressor:**	
Company ID:	129445	**Is NPRI Part 4:**	
SWR Report ID:	20040000010736	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2005-07-06 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		**Phone:**	9054541078
First Name:	Colin	**Extension:**	42
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manger		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manager		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Asphalt Operations Manager		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report

Report ID:	191098	***No of Employees:***	4
Report Year:	2003	***Is Compressor:***	
Company ID:	135405	***Is NPRI Part 4:***	
SWR Report ID:	20030000010736	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2004-06-01 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS LIMITED
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manger		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manager		

Language:	0
Email:	cburpee@aecon.com

NPRI Report Contact

Contact Type:	NPRI	**Phone:**	9054541078
First Name:	Colin	**Extension:**	42
Last Name:	Burpee	**Fax:**	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Asphalt Operations Manager		
Language:	0		
Email:	cburpee@aecon.com		

Alternative Location Info

Facility ID:	357666
Facility Name:	PORTABLE PLANT #3
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	43.702599
Longitude:	-79.797997

---

131 | ***58 of 59*** | ***SSE/172.8*** | ***239.9 / -2.08*** | ***PORTABLE PLANT #2
45 VAN KIRK DRIVE
BRAMPTON ON L7A1A6*** | ***NPR2***

NPRI ID:	10735	**Latitude:**	44.4515
Facility ID:	357665;374546	**Longitude:**	-79.574699
Facility Name:	PORTABLE PLANT #2		
Note:	Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0. For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report: https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2023&name=10735		

NPRI ID Substances Summary

CAS No:	NA - M08	**Is PAH?:**	FALSE
Is VOC?:	FALSE	**NPRI:**	TRUE
Is DF?:	FALSE		
Name English:	Total particulate matter		
Name French:	Matière particulaire totale		
Sort English:	PM - Total Particulate Matter		
Sort French:	PM - Particules totales		

CAS No:		**Is PAH?:**	
Is VOC?:		**NPRI:**	
Is DF?:			
Name English:			
Name French:			
Sort English:			
Sort French:			

CAS No:	NA - M10	**Is PAH?:**	FALSE

Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Name French:	PM2,5 - Matière particulaire <= 2,5 micromètres		
Sort English:	PM2.5 - Particulate Matter <= 2.5 Micrometers		
Sort French:	PM2,5 - Matière particulaire <= 2,5 micromètres		

CAS No:	NA - M09	***Is PAH?:***	FALSE
Is VOC?:	FALSE	***NPRI:***	TRUE
Is DF?:	FALSE		
Name English:	PM10 - Particulate Matter <= 10 Micrometers		
Name French:	PM10 - Matière particulaire <= 10 micromètres		
Sort English:	PM10 - Particulate Matter <= 10 Micrometers		
Sort French:	PM10 - Matière particulaire <= 10 micromètres		

Geographic Location

Report Year:	-1	***Forward Sort Area:***	L0L
Census Subdiv ID:	3543023	***DLS Description:***	
Ecozone ID:	8	***NTS Description:***	B-044-K/030-M-12
Water Survey ID:	2	***Province Code:***	ON
SOMA:	TRUE	***Datum:***	1983.0
ON PEMA:	TRUE	***Latitude:***	44.4515
QC PEMA:	FALSE	***Longitude:***	-79.574699
Quebec Windsor Corr:	TRUE		

NPRI ID Facility ID

NPRI ID:	10735
Facility ID:	374546

Facility

Facility ID:	374546	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	324121	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	PORTABLE PLANT #2		
Website:			

Address

Address1:	45 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A6
Prov:	

Address Geographic

Latitude:	43.702	***Datum:***	0
Longitude:	-79.7994	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	324121	***Start Date:***	2002

Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron achetés.

NAICS Code:	324121	***Start Date:***	2017
Record Year:	2017	***End Date:***	2021
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt,

bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	***Start Date:***	2012
Record Year:	2012	***End Date:***	2016
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	***Start Date:***	2022
Record Year:	2022	***End Date:***	2026
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NPRI Report

Report ID:	272882	***No of Employees:***	4
Report Year:	2003	***Is Compressor:***	
Company ID:	135502	***Is NPRI Part 4:***	
SWR Report ID:	20030000010735	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2004-06-01 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS LIMTED
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manger		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Asphalt Operations Manager		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Operations Manager		
Language:	0		
Email:	cburpee@aecon.com		

NPRI ID Facility ID

NPRI ID:	10735
Facility ID:	357665

Facility

Facility ID:	357665	***IDM ID:***	0
Portable:	FALSE	***AB Approval ID:***	0
NAICS Primary:	324121	***GHGRP ID:***	0
NAICS Secondary:	0	***ON GHGRP ID:***	0
NAICS Tertiary:	0		
Facility Name:	GENCOR #1 PORTABLE ASPHALT PLANT NO. 2		
Website:			

Address

Address1:	45 Van Kirk Drive
Address2:	
City:	BRAMPTON
Postal Zip:	L7A1A6
Prov:	

Address Geographic

Latitude:	43.702	***Datum:***	0
Longitude:	-79.7994	***Land Survey:***	
UTM Easting:	0.000000	***Topograph:***	
UTM Northing:	0.000000	***Additional Info:***	
UTM Zone:	0		

Primary NAICS Details

NAICS Code:	324121	***Start Date:***	1993
Record Year:	1997	***End Date:***	2001
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	***Start Date:***	2002
Record Year:	2002	***End Date:***	2006
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron.

NAICS Code:	324121	***Start Date:***	2007
Record Year:	2007	***End Date:***	2011
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt Paving Mixture and Block Manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir de produits asphaltiques, bitumineux ou de goudron achetés.

NAICS Code:	324121	**Start Date:**	2017
Record Year:	2017	**End Date:**	2021
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	**Start Date:**	2012
Record Year:	2012	**End Date:**	2016
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NAICS Code:	324121	**Start Date:**	2022
Record Year:	2022	**End Date:**	2026
Key Indus Sector En:	Petroleum and Coal Product Refining and Mfg.		
Key Indus Sector Fr:	Fabrication et raffinage des produits du pétrole et du charbon		
NAICS Title En:	Asphalt paving mixture and block manufacturing		
NAICS Title Fr:	Fabrication de mélanges d'asphaltage et de pavés d'asphalte		

NAICS Description En:

This Canadian industry comprises establishments primarily engaged in manufacturing asphalt paving mixtures and blocks, from purchased asphalt, bituminous materials or coal tar.

NAICS Description Fr:

Cette classe canadienne comprend les établissements dont l'activité principale est la fabrication de mélanges d'asphalte et blocs pour pavage, à partir d'asphalte, de goudron ou de matériaux bitumineux.

NPRI Report

Report ID:	151899	**No of Employees:**	4
Report Year:	2007	**Is Compressor:**	
Company ID:	129445	**Is NPRI Part 4:**	
SWR Report ID:	20070000010735	**Is Battery:**	
Repor Type ID:	1	**Corres Lang ID:**	0
New Reporter:	FALSE	**Submit Date:**	2008-05-26 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	This asphalt plant operates under OHMPA's Best Practices
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	4162972600
First Name:	Kevin	***Extension:***	3721
Last Name:	Martin	***Fax:***	4169402283
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Estimator/Coordinator		
Language:	0		
Email:	kmatrin@aecon.com		

NPRI Report

Report ID:	152205	***No of Employees:***	4
Report Year:	2006	***Is Compressor:***	
Company ID:	129444	***Is NPRI Part 4:***	
SWR Report ID:	20060000010735	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2007-05-31 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Comment

Description En:	General comments about the facility
Description Fr:	Commentaires généraux à propos de l'installation
Comment:	This plant is among the winners of OHMPA's 2006 Trillium award.
Note:	

NPRI Report Contact

Contact Type:		***Phone:***	4162972600
First Name:	Kevin	***Extension:***	3721
Last Name:	Martin	***Fax:***	4169402283
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Coordinator/Estimator		
Language:	0		
Email:	kmartin@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager, Asphalt Operations		
Language:	0		

Email: cburpee@aecon.com

NPRI Report

Report ID:	255218	***No of Employees:***	4
Report Year:	2005	***Is Compressor:***	
Company ID:	129444	***Is NPRI Part 4:***	
SWR Report ID:	20050000010735	***Is Battery:***	
Repor Type ID:	1	***Corres Lang ID:***	0
New Reporter:	FALSE	***Submit Date:***	2006-05-29 00:00:00.0000000

Company

Company Name:	AECON CONSTRUCTION & MATERIALS
DUNS No:	0
Trade Name En:	
Trade Name Fr:	
Website:	

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	4162972600
First Name:	Kevin	***Extension:***	3721
Last Name:	Martin	***Fax:***	4169402283
Company Name:			
Description En:			
Description Fr:			
Position:	Asphalt Coordinator/Estimator		
Language:	0		
Email:	kmartin@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			

Description En:
Description Fr:
Position: Manager, Asphalt Operations
Language: 0
Email: cburpee@aecon.com

NPRI Report

Report ID: 264325
Report Year: 2004
Company ID: 129444
SWR Report ID: 20040000010735
Repor Type ID: 1
New Reporter: FALSE
No of Employees: 4
Is Compressor:
Is NPRI Part 4:
Is Battery:
Corres Lang ID: 0
Submit Date: 2005-12-09 00:00:00.0000000

Company

Company Name: AECON CONSTRUCTION & MATERIALS
DUNS No: 0
Trade Name En:
Trade Name Fr:
Website:

NPRI Report Comment

Description En: NPRI report update comment
Description Fr: Commentaire sur la mise à jour du rapport de l'INRP
Comment: Only filed MOE 2004 Report
Note:

NPRI Report Comment

Description En: Report Submission and Electronic Certification Comment
Description Fr: Soumission de déclaration et attestation électronique
Comment: Original report submitted to MOE but NPRI did not get attached for this facility. All other facilities had no problems and were submitted at the same time.
Note:

NPRI Report Contact

Contact Type:
First Name: Colin
Last Name: Burpee
Company Name:
Description En:
Description Fr:
Position: Manager, Asphalt Operations
Language: 0
Email: cburpee@aecon.com
Phone: 9054541078
Extension: 42
Fax: 9054519827

NPRI Report Contact

Contact Type:
First Name: Kevin
Last Name: Martin
Company Name:
Description En:
Description Fr:
Position: Asphalt Coordinator/Estimator
Language: 0
Email: kmartin@aecon.com
Phone: 9054541078
Extension: 25
Fax: 9054519827

NPRI Report Contact

Contact Type:	NPRI	***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:	Public Contact		
Description Fr:	Responsable des renseignements au public		
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

NPRI Report Contact

Contact Type:		***Phone:***	9054541078
First Name:	Colin	***Extension:***	42
Last Name:	Burpee	***Fax:***	9054519827
Company Name:			
Description En:			
Description Fr:			
Position:	Manager, Asphalt Operations		
Language:	0		
Email:	cburpee@aecon.com		

Alternative Location Info

Facility ID:	357665
Facility Name:	GENCOR #1 PORTABLE ASPHALT PLANT NO. 2
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	44.4515
Longitude:	-79.574699

Alternative Location Info

Facility ID:	357665
Facility Name:	PORTABLE PLANT #2
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	44.4515
Longitude:	-79.574699

Alternative Location Info

Facility ID:	355395
Facility Name:	GENCOR #1 PORTABLE ASPHALT PLANT NO. 2
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	44.4515
Longitude:	-79.574699

Alternative Location Info

Facility ID:	243598

Facility Name:	GENCOR #1 PORTABLE ASPHALT PLANT NO. 2
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	44.4515
Longitude:	-79.574699

Alternative Location Info

Facility ID:	374546
Facility Name:	PORTABLE PLANT #2
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	44.4515
Longitude:	-79.574699

Alternative Location Info

Facility ID:	243598
Facility Name:	PORTABLE PLANT #2
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	44.4515
Longitude:	-79.574699

Alternative Location Info

Facility ID:	355395
Facility Name:	PORTABLE PLANT #2
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	44.4515
Longitude:	-79.574699

Alternative Location Info

Facility ID:	374546
Facility Name:	GENCOR #1 PORTABLE ASPHALT PLANT NO. 2
Address1:	45 VAN KIRK DRIVE
City:	BRAMPTON
Postal ZIP:	L7A1A6
Province EN:	ON
Latitude:	44.4515
Longitude:	-79.574699

---

131 ***59 of 59*** ***SSE/172.8*** ***239.9 / -2.08*** ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** ***FST***
45 Van Kirk Dr
Brampton ON

Inventory No:	10326584	**Tank Material:**	
Inventory Status:	Active	**Corrosion Protect:**	
Installation Year:		**Overfill Protection:**	
Capacity:	117838	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Card/Keylock
Tank Type:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Manufacturer:
Model:
Description:

---

132 | **1 of 1** | **SSE/153.8** | **239.9 / -2.08** | **Brampton Asphalt Plant**
Brampton ON L7A 1C7 | **EHS**

Order No:	23011900504	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	24-JAN-23	**Search Radius (km):**	.25
Date Received:	19-JAN-23	**X:**	-79.79754409
Previous Site Name:		**Y:**	43.70286083
Lot/Building Size:			
Additional Info Ordered:			

---

133 | **1 of 1** | **SSE/151.8** | **239.9 / -2.08** | **55 Van Kirk Dr, 45 Van kirk Dr, 12 Canam Crescent**
Brampton ON L7A 1A9 | **EHS**

Order No:	22120501166	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	08-DEC-22	**Search Radius (km):**	.25
Date Received:	05-DEC-22	**X:**	-79.79750669
Previous Site Name:		**Y:**	43.70285929
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

134 | **1 of 9** | **SE/59.7** | **237.8 / -4.12** | **55 VAN KIRK DRIVE lot 11 con 1**
BRAMPTON ON | **WWIS**

Well ID:	7447535	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05/24/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	M8OMEZYF	**Contractor:**	6607
Tag:	A372561	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	011
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418222	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596882.00
Code OB Desc:		**North83:**	4839721.00

Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/23/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009418441
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	9.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009418439
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	4.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009418440
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	34
Material 1 Desc:	TILL
Material 2:	06
Material 2 Desc:	SILT
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	4.0
Formation End Depth:	9.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009418635
Layer:	2
Plug From:	1.0
Plug To:	9.600000381469727
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009418634
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009418587
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1009418334
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1009418293
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1009418490
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1009418519
Layer:	1
Slot:	10
Screen Top Depth:	10.0

Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009418294
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009418555
Diameter:	8.0
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

134 | ***2 of 9*** | ***SE/59.7*** | ***237.8 / -4.12*** | ***55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON*** | ***WWIS***

Well ID:	7447522	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	05/24/2023
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	5G2H9DB3	***Contractor:***	6607
Tag:	A375456	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	011
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418183	***Elevation:***	

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597031.00
Code OB Desc:		**North83:**	4839472.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/22/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009418409
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	7.0
Formation End Depth:	18.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418407
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	5.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418408
Layer:	2
Color:	2
General Color:	GREY
Material 1:	34
Material 1 Desc:	TILL
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD

Formation Top Depth: 5.0
Formation End Depth: 7.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418612
Layer: 3
Plug From: 5.0
Plug To: 7.5
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418574
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418611
Layer: 2
Plug From: 1.0
Plug To: 5.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418610
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1009418321
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1009418267
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009418477
Layer: 1
Material: 5

Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 8.0
Casing Diameter: 2.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1009418506
Layer: 1
Slot: 10
Screen Top Depth: 8.0
Screen End Depth: 18.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009418268
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1009418378
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 8.0
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1009418540
Diameter: 8.0
Depth From: 5.0
Depth To: 18.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1009418539
Diameter: 14.0
Depth From: 0.0

Depth To:	5.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

134 **3 of 9** **SE/59.7** **237.8 / -4.12** **55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON** **WWIS**

Well ID:	7447520	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05/24/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	2EY4JZQO	**Contractor:**	6607
Tag:	A372483	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	011
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418177	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597012.00
Code OB Desc:		**North83:**	4839574.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/16/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009418402
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	34
Material 2 Desc:	TILL
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	2.200000047683716
Formation End Depth:	3.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418401
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	2.200000047683716
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418403
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	3.0
Formation End Depth:	6.800000190734863
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418607
Layer:	2
Plug From:	0.30000001192092896
Plug To:	3.5999999046325684
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418572
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418606
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1009418319
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1009418263
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1009418475
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.10000000149011612
Depth To:	3.799999952316284
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1009418504
Layer:	1
Slot:	10
Screen Top Depth:	3.799999952316284
Screen End Depth:	6.800000190734863
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009418264
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID: 1009418376
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 4.5
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1009418536
Diameter: 21.0
Depth From: 3.0
Depth To: 6.800000190734863
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1009418535
Diameter: 36.0
Depth From: 0.0
Depth To: 3.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

134 | **4 of 9** | **SE/59.7** | **237.8 / -4.12** | **55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON** | **WWIS**

Well ID:	7447534	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05/24/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	L3MLEB2X	**Contractor:**	6607
Tag:	A367152	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	011
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418219	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596755.00
Code OB Desc:		**North83:**	4839629.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/18/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1009418437
Layer: 2
Color: 6
General Color: BROWN
Material 1: 34
Material 1 Desc: TILL
Material 2: 06
Material 2 Desc: SILT
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 4.0
Formation End Depth: 8.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009418436
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009418438
Layer: 3
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 8.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418632
Layer: 1

Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418586
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418633
Layer: 2
Plug From: 1.0
Plug To: 9.600000381469727
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009418333
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1009418291
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009418489
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1009418518
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009418292
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1009418385
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	8.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1009418554
Diameter:	8.0
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

134 ***5 of 9*** ***SE/59.7*** ***237.8 / -4.12*** ***55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON*** ***WWIS***

Well ID:	7447538	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	05/24/2023
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	OSKR52J8	***Contractor:***	6607
Tag:	A372565	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	011
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418231	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	596963.00
Code OB Desc:		***North83:***	4839568.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	02/15/2023	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009418448
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	34
Material 2 Desc:	TILL
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	1.7999999523162842
Formation End Depth:	3.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418447
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	1.7999999523162842
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418449
Layer:	3
Color:	7
General Color:	RED
Material 1:	28
Material 1 Desc:	SAND
Material 2:	

Material 2 Desc:
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 3.0
Formation End Depth: 6.800000190734863
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418590
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418641
Layer: 2
Plug From: 0.30000001192092896
Plug To: 3.5999999046325684
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418640
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1009418337
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1009418299
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009418493
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.10000000149011612
Depth To: 3.799999952316284
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1009418522
Layer:	1
Slot:	10
Screen Top Depth:	3.799999952316284
Screen End Depth:	6.800000190734863
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009418300
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1009418387
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	3.5999999046325684
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1009418558
Diameter:	36.0
Depth From:	0.0
Depth To:	3.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1009418559
Diameter:	21.0
Depth From:	3.0
Depth To:	6.800000190734863
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
134	6 of 9	SE/59.7	237.8 / -4.12	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON	WWIS

Well ID:	7447544	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05/24/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	WO26LMIY	**Contractor:**	6607
Tag:	A327880	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	011
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418249	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597030.00
Code OB Desc:		**North83:**	4839638.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/23/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009418466
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	34
Material 1 Desc:	TILL
Material 2:	06
Material 2 Desc:	SILT
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	4.0
Formation End Depth:	8.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009418467
Layer:	3

Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	8.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009418465
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	4.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009418654
Layer:	2
Plug From:	1.0
Plug To:	9.600000381469727
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009418596
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009418653
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1009418343
Method Construction Code:	6
Method Construction:	Boring

Other Method Construction:

Pipe Information

Pipe ID: 1009418311
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009418499
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1009418528
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009418312
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1009418566
Diameter: 8.0
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
134	7 of 9	SE/59.7	237.8 / -4.12	55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON	WWIS

Well ID: 7447540
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: PWQDSSLF
Tag: A365047
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/24/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 9
Owner:
County: PEEL
Lot: 011
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1009418237
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/19/2023
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596870.00
North83: 4839496.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1009418453
Layer: 1
Color:
General Color:
Material 1: 01
Material 1 Desc: FILL
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 3.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009418454
Layer: 2
Color:
General Color:
Material 1: 34
Material 1 Desc: TILL
Material 2: 06
Material 2 Desc: SILT
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 3.0
Formation End Depth: 8.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009418455
Layer: 3
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 8.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418592
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418646
Layer: 2
Plug From: 1.0
Plug To: 9.600000381469727
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418645
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009418339
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1009418303
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009418495
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1009418524
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0999999046325684

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009418304
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1009418389
Layer: 1
Kind Code:
Kind:

Water Found Depth: 8.0
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1009418562
Diameter: 8.0
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

134 | **8 of 9** | **SE/59.7** | **237.8 / -4.12** | **55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON** | **WWIS**

Well ID: 7447539
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: OUYQTJSO
Tag: A375463
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/24/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 9
Owner:
County: PEEL
Lot: 011
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1009418234
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/21/2023
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 596961.00
North83: 4839497.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1009418452
Layer: 3
Color: 7
General Color: RED

Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 7.5
Formation End Depth: 20.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1009418450
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 28
Material 2 Desc: SAND
Material 3: 11
Material 3 Desc: GRAVEL
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1009418451
Layer: 2
Color: 6
General Color: BROWN
Material 1: 34
Material 1 Desc: TILL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 7.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418642
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418591
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418643
Layer:	2
Plug From:	1.0
Plug To:	10.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418644
Layer:	3
Plug From:	10.0
Plug To:	11.0
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1009418338
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1009418301
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1009418494
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	12.0
Casing Diameter:	2.0
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1009418523
Layer:	1
Slot:	10
Screen Top Depth:	12.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009418302

Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1009418388
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 7.0
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1009418561
Diameter: 8.0
Depth From: 10.0
Depth To: 20.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1009418560
Diameter: 14.0
Depth From: 0.0
Depth To: 10.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

134 | ***9 of 9*** | ***SE/59.7*** | ***237.8 / -4.12*** | ***55 VAN KIRK DRIVE lot 11 con 1 BRAMPTON ON*** | ***WWIS***

Well ID: 7447523
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 6RM5ELQD
Tag: A367129
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/24/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 9
Owner:
County: PEEL
Lot: 011
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:

Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Bore Hole Information

Bore Hole ID: 1009418186 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17
Code OB: ***East83:*** 596799.00
Code OB Desc: ***North83:*** 4839447.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 01/20/2023 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1009418410
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009418411
Layer: 2
Color: 6
General Color: BROWN
Material 1: 34
Material 1 Desc: TILL
Material 2: 06
Material 2 Desc: SILT
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 4.0
Formation End Depth: 8.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009418412

Layer: 3
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 8.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418615
Layer: 3
Plug From: 10.0
Plug To: 11.600000381469727
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418575
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418613
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009418614
Layer: 2
Plug From: 1.0
Plug To: 10.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009418322
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1009418269
Casing No: 0

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1009418478
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	12.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1009418507
Layer:	1
Slot:	10
Screen Top Depth:	12.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009418270
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009418542
Diameter:	8.0
Depth From:	10.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Hole Diameter

Hole ID:	1009418541
Diameter:	14.0
Depth From:	0.0
Depth To:	10.0

Hole Depth UOM:	ft
Hole Diameter UOM:	inch

135 *1 of 4* *WNW/61.6* *259.9 / 17.92* ***VERDE PROPERTY MAINTENANCE LTD*** ***25 VIRGINIA DR*** ***BRAMPTON ON L7A 2E6*** ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

135 *2 of 4* *WNW/61.6* *259.9 / 17.92* ***VERDE PROPERTY MAINTENANCE LTD*** ***25 VIRGINIA DR*** ***BRAMPTON ON L7A2E6*** ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	07376	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	4325503
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

135 *3 of 4* *WNW/61.6* *259.9 / 17.92* ***VERDE PROPERTY MAINTENANCE LTD*** ***25 VIRGINIA DR*** ***BRAMPTON ON L7A2E6*** ***PES***

Detail Licence No:	02-01-03815-0	**Operator Box:**	
Licence No:	03815	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	4325503
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Control:	0			**Oper Concession:**	
Latitude:				**Operator Region:**	3
Longitude:				**Operator District:**	
Lot:				**Operator County:**	49
Concession:				**Op Municipality:**	
Region:	3			**Post Office Box:**	
District:				**MOE District:**	
County:	49			**SWP Area Name:**	
Trade Name:					
PDF URL:					

---

135 *4 of 4* *WNW/61.6* *259.9 / 17.92*

VERDE PROPERTY MAINTENANCE LTD
25 VIRGINIA DR
BRAMPTON ON L7A2E6

PES

Detail Licence No:		**Operator Box:**	
Licence No:	03815	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	416
Licence Type:	Operator	**Oper Phone No:**	4325503
Licence Type Code:	01	**Operator Ext:**	
Licence Class:	06	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

136 *1 of 5* *SE/5.8* *236.1 / -5.88*

2066650 Ontario Inc.

Brampton ON M5C 1T4

ECA

Approval No:	2563-7M9J7S	**MOE District:**	Halton-Peel
Approval Date:	2008-12-12	**City:**	
Status:	Approved	**Longitude:**	-79.795
Record Type:	ECA	**Latitude:**	43.7029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Business Name:	2066650 Ontario Inc.		
Address:			
Full Address:			
Full PDF Link:			
PDF Site Location:			

---

136 *2 of 5* *SE/5.8* *236.1 / -5.88*

2066650 Ontario Inc.

Brampton ON M5C 1T4

ECA

Approval No:	4355-7M8SY6	**MOE District:**	Halton-Peel
Approval Date:	2008-12-12	**City:**	
Status:	Approved	**Longitude:**	-79.795
Record Type:	ECA	**Latitude:**	43.7029

Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	2066650 Ontario Inc.		
Address:			
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/9891-7M5R9A-14.pdf		
PDF Site Location:			

---

136 | ***3 of 5*** | ***SE/5.8*** | ***236.1 / -5.88*** | ***The Regional Municipality of Peel*** | ***ECA***

Brampton ON L6T 4B9

Approval No:	5066-6MNHFK	**MOE District:**	Halton-Peel
Approval Date:	2006-03-09	**City:**	
Status:	Approved	**Longitude:**	-79.795
Record Type:	ECA	**Latitude:**	43.7029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	The Regional Municipality of Peel		
Address:			
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/0699-6MGPZR-14.pdf		
PDF Site Location:			

---

136 | ***4 of 5*** | ***SE/5.8*** | ***236.1 / -5.88*** | ***2066650 Ontario Inc.*** | ***ECA***

Brampton ON M5C 1T4

Approval No:	0458-7NFMF9	**MOE District:**	Halton-Peel
Approval Date:	2009-03-02	**City:**	
Status:	Approved	**Longitude:**	-79.795
Record Type:	ECA	**Latitude:**	43.7029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	2066650 Ontario Inc.		
Address:			
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/8479-7M7PHC-14.pdf		
PDF Site Location:			

---

136 | ***5 of 5*** | ***SE/5.8*** | ***236.1 / -5.88*** | ***City of Toronto*** | ***ECA***

Brampton ON M5V 3C6

Approval No:	3303-5XSLKH	**MOE District:**	Halton-Peel
Approval Date:	2004-04-16	**City:**	
Status:	Approved	**Longitude:**	-79.795
Record Type:	ECA	**Latitude:**	43.7029
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Business Name:	City of Toronto		
Address:			

Full Address:
Full PDF Link:
PDF Site Location:

137 **1 of 1** **SSE/212.2** **238.8 / -3.09** **ON** **WWIS**

Well ID:	7396621	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	09/07/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z366732	**Contractor:**	7241
Tag:	A311792	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1008779699	**Tag No:**	A311792
Depth M:		**Contractor:**	7241
Year Completed:	2021	**Latitude:**	43.7018978731577
Well Completed Dt:	07/27/2021	**Longitude:**	-79.7972405962568
Audit No:	Z366732	**Y:**	43.701897871091965
Path:		**X:**	-79.79724044579166

Bore Hole Information

Bore Hole ID:	1008779699	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596912.00
Code OB Desc:		**North83:**	4839467.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/27/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Pipe Information

Pipe ID:	1009771546
Casing No:	0
Comment:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Alt Name:					
138	1 of 1	SSE/160.6	238.6 / -3.30	lot 11 con 1 ON	WWIS

Well ID: 4901582
Construction Date:
Use 1st: Industrial
Use 2nd: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 05/24/1967
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1325
Form Version: 1
Owner:
County: PEEL
Lot: 011
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901582.pdf

Additional Detail(s) (Map)

Well Completed Date: 04/17/1967
Year Completed: 1967
Depth (m): 13.1064
Latitude: 43.7020343813519
Longitude: -79.7965230057403
X: -79.79652285558923
Y: 43.702034378842626
Path: 490\4901582.pdf

Bore Hole Information

Bore Hole ID: 10316427
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/17/1967
Remarks:
Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 596969.60
North83: 4839483.00
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 932034879

Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	10.0
Formation End Depth:	43.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932034877
Layer:	1
Color:	
General Color:	
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932034878
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	1.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901582
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10864997
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523043
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	43.0
Casing Diameter:	42.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901582
Pump Set At:	
Static Level:	10.0
Final Level After Pumping:	27.0
Recommended Pump Depth:	40.0
Pumping Rate:	1.0
Flowing Rate:	
Recommended Pump Rate:	1.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	3
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933789530
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	26.0
Water Found Depth UOM:	ft

---

139 ***1 of 1*** ***WNW/248.4*** ***258.9 / 16.93*** ***2650 Mayfield Road lot 18 con 1 Brampton ON*** ***WWIS***

Well ID:	7378693	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	01/19/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	2WNFJTXQ	***Contractor:***	7732
Tag:	_NO_TAG	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	018
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		

Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378693.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/13/2021
Year Completed: 2021
Depth (m):
Latitude: 43.7305040102725
Longitude: -79.8373452135351
X: -79.8373450641475
Y: 43.730504008235094
Path: 737\7378693.pdf

Bore Hole Information

Bore Hole ID: 1008554335
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 01/13/2021
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593636.00
North83: 4842598.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008554438
Layer: 1
Color:
General Color:
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008554507
Layer: 1
Plug From: 0.0
Plug To: 7.599999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008554491
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008554371
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008554453
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 4.5
Casing Diameter: 5.0
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008554468
Layer: 1
Slot:
Screen Top Depth: 4.5
Screen End Depth: 7.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.300000190734863

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008554372
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008554406
Layer: 1

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Kind Code: 8
Kind: Untested
Water Found Depth: 0.5
Water Found Depth UOM: m

---

140 **1 of 12** **SE/141.4** **238.0 / -3.99** **HAULTEC TRAILERS LTD**
12 CANAM CRES
BRAMPTON ON L7A 1A9 **SCT**

Established: 1993
Plant Size (ft²):
Employment: 20

--Details--
Description: TRUCK TRAILERS
SIC/NAICS Code: 3715

---

140 **2 of 12** **SE/141.4** **238.0 / -3.99** **AMBRO DIESEL SALES AND SERVICE**
12 CANAM CRESCENT
BRAMPTON ON L7A 1A9 **GEN**

Generator Info

Generator No: ON0510602
Approval Years: 86,87
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: IND. MACHINERY, WH.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 5731

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

140 **3 of 12** **SE/141.4** **238.0 / -3.99** **AMBRO DIESEL SALES AND SERVICE**
12 CANAM CRESCENT
BRAMPTON ON L7A 1A9 **GEN**

Generator Info

Generator No: ON0510602
Approval Years: 88,89
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: IND. MACHINERY, WH.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 5731

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

140 ***4 of 12*** ***SE/141.4*** ***238.0 / -3.99*** ***AMBRO DIESEL SALES AND SERVICE 03-260***
12 CANAM CRESCENT
BRAMPTON ON L7A 1A9 ***GEN***

Generator Info

Generator No: ON0510602
Approval Years: 92,93,94,95,96,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: IND. MACHINERY, WH.
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 5731

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

140 ***5 of 12*** ***SE/141.4*** ***238.0 / -3.99*** ***ROTO-MILL SERVICES LTD.***
12 CANAM CRESCENT
BRAMPTON ON L7A 1A9 ***GEN***

Generator Info

Generator No: ON1144701
Approval Years: 97,98
Status:
Choice of Contact:
Contaminated Fac:
MHSW Facility:

PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: CONSTRTUCTION EQUIP.

SIC Code: 3192

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

140 | ***6 of 12*** | ***SE/141.4*** | ***238.0 / -3.99*** | ***ROTO-MILL SERVICES LIMITED*** | ***GEN***
12 CANAM CRESCENT
BRAMPTON ON L7A 1A9

Generator Info

Generator No: ON1144701
Approval Years: 99,00,01,02,03,04,05,06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: CONSTRTUCTION EQUIP.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 3192

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

140 | ***7 of 12*** | ***SE/141.4*** | ***238.0 / -3.99*** | ***Roto Mill Services Ltd.*** | ***SPL***
12 Canam Crescent, Brampton
Brampton ON L7A 1A9

Ref No: 5443-6J3F9S
Year:
Incident Dt: 11/12/2005
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/12/2005
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Roto Mill Services Ltd.<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Roto Mill Services Ltd.
Client Type:
Source Type:

Municipality No:
Nature of Damage:
Discharger Report: 0
Material Group: Oil
Impact to Health:
Agency Involved:

Incident Cause:	Other Discharges
Incident Preceding Spill:	
Incident Reason:	Fire/Explosion - Resulting from fires/explosions (Not occurrences which cause a fire or explosion)
Incident Summary:	Roto Mill: 30 L diesel to ground, cleaned up
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Soil Contamination; Surface Water Pollution
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	L
Contaminant Code:	
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land & Water
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other Plant
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

140 | ***8 of 12*** | ***SE/141.4*** | ***238.0 / -3.99*** | ***Aecon Group Inc*** ***12 Canam Cres*** ***Brampton ON L7A 1A9*** | ***GEN***

Generator Info

Generator No:	ON6787396	***Choice of Contact:***	
Approval Years:	07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	237310
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Highway Street and Bridge Construction		

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

140 | ***9 of 12*** | ***SE/141.4*** | ***238.0 / -3.99*** | ***12 CANAM CRES lot 11 con 1*** ***BRAMPTON ON*** | ***WWIS***

Well ID:	7447531	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	05/24/2023
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	GIAS25HS	***Contractor:***	6607
Tag:	A367121	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	011
Depth to Bedrock:		***Concession:***	01

Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418210	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597024.00
Code OB Desc:		**North83:**	4839491.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/14/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009418428
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	34
Material 2 Desc:	TILL
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	0.6000000238418579
Formation End Depth:	2.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418427
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	0.6000000238418579
Formation End Depth UOM:	m

Annular Space/Abandonment

Sealing Record

Plug ID:	1009418627
Layer:	2
Plug From:	0.30000001192092896
Plug To:	0.800000011920929
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418583
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418626
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1009418330
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1009418285
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1009418486
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.10000000149011612
Depth To:	0.8999999761581421
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1009418515
Layer:	1
Slot:	10
Screen Top Depth:	0.8999999761581421
Screen End Depth:	2.0999999046325684
Screen Material:	5

Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009418286
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1009418382
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.899999976158142
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1009418550
Diameter: 21.0
Depth From: 0.0
Depth To: 2.0999999046325684
Hole Depth UOM: m
Hole Diameter UOM: cm

---

140 | ***10 of 12*** | ***SE/141.4*** | ***238.0 / -3.99*** | ***12 CANAM CRES lot 11 con 1 BRAMPTON ON*** | ***WWIS***

Well ID: 7447521
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 2N724EDP
Tag: A372507
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/24/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 9
Owner:
County: PEEL
Lot: 011
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:

Clear/Cloudy: ***UTM Reliability:***
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Bore Hole Information

Bore Hole ID: 1009418180 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17
Code OB: ***East83:*** 596987.00
Code OB Desc: ***North83:*** 4839407.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 02/10/2023 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1009418405
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 1.0
Formation End Depth: 2.4000000953674316
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1009418406
Layer: 3
Color: 6
General Color: BROWN
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 2.4000000953674316
Formation End Depth: 6.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1009418404
Layer: 1

Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	01
Material 3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418608
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418609
Layer:	2
Plug From:	0.30000001192092896
Plug To:	3.299999952316284
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418573
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1009418320
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1009418265
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1009418476
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.10000000149011612

Depth To:	3.5999999046325684
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1009418505
Layer:	1
Slot:	10
Screen Top Depth:	3.5999999046325684
Screen End Depth:	6.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009418266
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1009418377
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	2.0999999046325684
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1009418538
Diameter:	21.0
Depth From:	3.0
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1009418537
Diameter:	36.0
Depth From:	0.0
Depth To:	3.0
Hole Depth UOM:	m

Hole Diameter UOM: cm

---

140 | **11 of 12** | **SE/141.4** | **238.0 / -3.99** | **12 CANAM CRES lot 11 con 1 BRAMPTON ON** | **WWIS**

Well ID:	7447532	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05/24/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	J3YWNAFK	**Contractor:**	6607
Tag:	A372566	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	011
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418213	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596934.00
Code OB Desc:		**North83:**	4839508.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/13/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009418429
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418431
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	2.4000000953674316
Formation End Depth:	6.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418430
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	34
Material 2 Desc:	TILL
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	1.0
Formation End Depth:	2.4000000953674316
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418628
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418629
Layer:	2
Plug From:	0.30000001192092896
Plug To:	2.700000047683716
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418584
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Method of Construction & Well

Use

Method Construction ID:	1009418331
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1009418287
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1009418487
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.10000000149011612
Depth To:	3.0
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1009418516
Layer:	1
Slot:	10
Screen Top Depth:	3.0
Screen End Depth:	6.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009418288
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1009418383
Layer:	1

Kind Code:	8
Kind:	Untested
Water Found Depth:	2.0999999046325684
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1009418551
Diameter:	36.0
Depth From:	0.0
Depth To:	3.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1009418552
Diameter:	21.0
Depth From:	3.0
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

140 | ***12 of 12*** | ***SE/141.4*** | ***238.0 / -3.99*** | ***12 CANAM CRES lot 11 con 1 BRAMPTON ON*** | ***WWIS***

Well ID:	7447524	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	05/24/2023
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	BKHFBCEF	**Contractor:**	6607
Tag:	A372474	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	011
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009418189	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	596896.00
Code OB Desc:		**North83:**	4839498.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/14/2023	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1009418414
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	0.6000000238418579
Formation End Depth:	3.299999952316284
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418415
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	3.299999952316284
Formation End Depth:	6.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1009418413
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	0.6000000238418579
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1009418576
Layer:	1
Plug From:	
Plug To:	

Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418617
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.700000047683716
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1009418616
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1009418323
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1009418271
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009418479
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.10000000149011612
Depth To: 3.0
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1009418508
Layer: 1
Slot: 10
Screen Top Depth: 3.0
Screen End Depth: 6.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009418272
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1009418379
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 3.299999952316284
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1009418543
Diameter: 21.0
Depth From: 0.0
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

141 | ***1 of 24*** | ***SSE/245.9*** | ***238.2 / -3.76*** | ***C.M.X. CORPORATION***
35 VAN KIRK DR UNIT 12
BRAMPTON ON L7A 1A5 | ***SCT***

Established: 1985
Plant Size (ft²): 3000
Employment: 2

--Details--
Description: COMMUNICATIONS EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3669

Description: RADIOTELEPHONE COMMUNICATIONS
SIC/NAICS Code: 4812

Description: Other Communications Equipment Manufacturing
SIC/NAICS Code: 334290

---

141 | ***2 of 24*** | ***SSE/245.9*** | ***238.2 / -3.76*** | ***W.A. Whitney of Canada Ltd.***
35 Van Kirk Dr Unit 14
Brampton ON L7A 1A5 | ***SCT***

Established: 1964
Plant Size (ft²): 2800

Employment: 2

--Details--
Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

---

141 | ***3 of 24*** | ***SSE/245.9*** | ***238.2 / -3.76*** | ***PETRO-CANADA***
35 VANKIRK DR SERVICE STATION
BRAMPTON ON L7A 1A5 | ***SPL***

Ref No: 182360
Year:
Incident Dt: 6/17/2000
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/17/2000
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: UNKNOWN
Incident Preceding Spill:
Incident Reason: UNKNOWN
Incident Summary: PETRO-CANADA STATION -UNKNOWN AMOUNT OF DIESELFUEL TO PAVEMENT.
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact: Other
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
141	4 of 24	SSE/245.9	238.2 / -3.76	C.M.X. Corporation - Valcom Paging 35 Van Kirk Dr Unit 12 Brampton ON L7A 1A5	SCT

Established: 1985
Plant Size (ft²): 3000
Employment: 2

--Details--
Description: Wireless Telecommunications Carriers (except Satellite)
SIC/NAICS Code: 513320

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
141	5 of 24	SSE/245.9	238.2 / -3.76	Adhesifs Adhpro Inc. 35 Van Kirk Dr Unit 19B Brampton ON L7A 1A5	SCT

Established: 1990
Plant Size (ft²):
Employment: 2

--Details--
Description: Adhesive Manufacturing
SIC/NAICS Code: 325520

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
141	6 of 24	SSE/245.9	238.2 / -3.76	CANADIAN MINE DEVELOPMENT BEHIND 35 VAN KIRK DR. BRAMPTON ON L7A 1A5	GEN

Generator Info

Generator No: ON0894501
Approval Years: 86,87,88,89
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: GARAGES(GEN. REPAIR)

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6351

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
141	7 of 24	SSE/245.9	238.2 / -3.76	CANADIAN MINE DEVELOPMENT BEHIND 35 VAN KIRK DR. BRAMPTON ON L7A 1A5	GEN

Generator Info

Generator No: ON0894501
Approval Years: 90

Choice of Contact:
Contaminated Fac:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 6351
Country:
Co Admin:
Phone No Admin:
SIC Description: GARAGES(GEN. REPAIR)

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

141 ***8 of 24*** ***SSE/245.9*** ***238.2 / -3.76*** ***CANADIAN MINE DEVELOPMENT 08-349***
BEHIND 35 VAN KIRK DR.
BRAMPTON ON L7A 1A5 ***GEN***

Generator Info

Generator No: ON0894501 ***Choice of Contact:***
Approval Years: 92,93,94,95,96,97,98 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 6351
Country:
Co Admin:
Phone No Admin:
SIC Description: GARAGES(GEN. REPAIR)

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

141 ***9 of 24*** ***SSE/245.9*** ***238.2 / -3.76*** ***BRAMPTON GUARD(OUT OF BUSINESS) 05-804***
35 VAN KIRK DRIVE, UNIT 17
BRAMPTON ON L7A 1A5 ***GEN***

Generator Info

Generator No: ON1556200 ***Choice of Contact:***
Approval Years: 92,93,94,95,96,97,98 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 2841
Country:
Co Admin:
Phone No Admin:
SIC Description: NEWSPAPER, ETC. IND.

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

141 ***10 of 24*** ***SSE/245.9*** ***238.2 / -3.76*** ***ACCURATE AIR COMPRESSORS INC.***
35 VANKIRK DRIVE, UNIT 13A
BRAMPTON ON L7A 1A5 ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON2453500	***Choice of Contact:***	
Approval Years:	99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	3199
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	OTHER MACHINERY		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

---

141 ***11 of 24*** ***SSE/245.9*** ***238.2 / -3.76*** ***ACCURATE AIR COMPRESSORS INC.*** ***GEN***
35 VAN KIRK DR. UNIT 13A
BRAMPTON ON L7A 1A5

Generator Info

Generator No:	ON2453500	***Choice of Contact:***	
Approval Years:	02,03,04,05,06,07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

---

141 ***12 of 24*** ***SSE/245.9*** ***238.2 / -3.76*** ***CMX Corporation - Valcom*** ***SCT***
35 Van Kirk Dr Unit 12
Brampton ON L7A 1A5

Established:	1985
Plant Size (ft²):	3000
Employment:	2

--Details--

Description:	Other Communications Equipment Manufacturing
SIC/NAICS Code:	334290

Description: Wireless Telecommunications Carriers (except Satellite)
SIC/NAICS Code: 517210

---

141 **13 of 24** **SSE/245.9** **238.2 / -3.76** **Classifier Milling Systems** **SCT**
35 Van Kirk Dr Unit 17
Brampton ON L7A 1A5

Established: 01-JUN-93
Plant Size (ft²): 4000
Employment:

--Details--
Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

Description: All Other Industrial Machinery Manufacturing
SIC/NAICS Code: 333299

Description: Commercial and Service Industry Machinery Manufacturing
SIC/NAICS Code: 333310

Description: All Other General-Purpose Machinery Manufacturing
SIC/NAICS Code: 333990

---

141 **14 of 24** **SSE/245.9** **238.2 / -3.76** **ACCURATE AIR COMPRESSORS INC.** **GEN**
35 VAN KIRK DR. UNIT 13A
BRAMPTON ON L7A 1A5

Generator Info

Generator No: ON2453500
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Plumbing Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 416120

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
141	15 of 24	SSE/245.9	238.2 / -3.76	ACCURATE AIR COMPRESSORS INC. 35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	GEN

Generator Info

Generator No:	ON2453500	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	416120
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Plumbing Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
141	16 of 24	SSE/245.9	238.2 / -3.76	ACCURATE AIR COMPRESSORS INC. 35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	GEN

Generator Info

Generator No:	ON2453500	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	416120
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Plumbing Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
141	17 of 24	SSE/245.9	238.2 / -3.76	ACCURATE AIR COMPRESSORS INC. 35 VAN KIRK DR. UNIT 13A BRAMPTON ON L7A 1A5	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON2453500	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	416120
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Plumbing Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

141	***18 of 24***	***SSE/245.9***	***238.2 / -3.76***	***ACCURATE AIR COMPRESSORS INC.*** ***35 VAN KIRK DR. UNIT 13A*** ***BRAMPTON ON***	***GEN***

Generator Info

Generator No:	ON2453500	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	416120
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PLUMBING, HEATING AND AIR-CONDITIONING EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

141	***19 of 24***	***SSE/245.9***	***238.2 / -3.76***	***ACCURATE AIR COMPRESSORS INC.*** ***35 VAN KIRK DR. UNIT 13A*** ***BRAMPTON ON L7A 1A5***	***GEN***

Generator Info

Generator No:	ON2453500	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	416120

Country: Canada
Co Admin:
Phone No Admin:
SIC Description: PLUMBING, HEATING AND AIR-CONDITIONING EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

141 | ***20 of 24*** | ***SSE/245.9*** | ***238.2 / -3.76*** | ***ACCURATE AIR COMPRESSORS INC.***
35 VAN KIRK DR. UNIT 13A
BRAMPTON ON L7A 1A5 | ***GEN***

Generator Info

Generator No: ON2453500
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: PLUMBING, HEATING AND AIR-CONDITIONING EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 416120

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

141 | ***21 of 24*** | ***SSE/245.9*** | ***238.2 / -3.76*** | ***ACCURATE AIR COMPRESSORS INC.***
35 VAN KIRK DR. UNIT 13A
BRAMPTON ON L7A 1A5 | ***GEN***

Generator Info

Generator No: ON2453500
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: PLUMBING, HEATING AND AIR-CONDITIONING EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 416120

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

141 | ***22 of 24*** | ***SSE/245.9*** | ***238.2 / -3.76*** | ***ACCURATE AIR COMPRESSORS INC.***
35 VAN KIRK DR. UNIT 13A
BRAMPTON ON L7A 1A5 | ***GEN***

Generator Info

Generator No: ON2453500
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

141 | ***23 of 24*** | ***SSE/245.9*** | ***238.2 / -3.76*** | ***ACCURATE AIR COMPRESSORS INC.***
35 VAN KIRK DR. UNIT 13A
BRAMPTON ON L7A 1A5 | ***GEN***

Generator Info

Generator No: ON2453500
Approval Years: As of Oct 2019
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

2017 Generator Info

Gen No: ON2453500
ID: 9774
Contaminated Fac: N

Choice of Contact: CO_OFFICIAL
Phone No Official: (905)846-5992 Ext.
Phone No Admin:

MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	416120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	ACCURATE AIR COMPRESSORS INC.		
Gen Div:			
Gen Op Name:	ACCURATE AIR COMPRESSORS INC.		
Gen Op Div:			
Site Adrs1:	35 VAN KIRK DR. UNIT 13A		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1A5		
Site Country:	Canada		
Co Official:	MIKE A ROGERS		
Co Admin:			

2018 Generator Info

Gen No:	ON2453500	***Choice of Contact:***	CO_OFFICIAL
ID:	9536	***Phone No Official:***	(905)846-5992 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	416120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	ACCURATE AIR COMPRESSORS INC.		
Gen Div:			
Gen Op Name:	ACCURATE AIR COMPRESSORS INC.		
Gen Op Div:			
Site Adrs1:	35 VAN KIRK DR. UNIT 13A		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A 1A5		
Site Country:	Canada		
Co Official:	MIKE A ROGERS		
Co Admin:			

2019 Generator Info

Gen No:	ON2453500	***Choice of Contact:***	CO_OFFICIAL
ID:	9240	***Phone No Official:***	(905)846-5992 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	416120	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	ACCURATE AIR COMPRESSORS INC.		
Gen Div:			
Gen Op Name:	ACCURATE AIR COMPRESSORS INC.		
Gen Op Div:			
Site Adrs1:	35 VAN KIRK DR. UNIT 13A		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Province Out:
Site Postal Code: L7A 1A5
Site Country: Canada
Co Official: MIKE A ROGERS
Co Admin:

---

141 | ***24 of 24*** | ***SSE/245.9*** | ***238.2 / -3.76*** | ***Mantella Corporation***
35 Van Kirk Drive
Brampton ON | ***GEN***

Generator Info as of Dec 2024

Generator No: ON001072347
Generator Company Name: Mantella Corporation
Street: 35 Van Kirk Drive
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A 1A5
Waste Class: 146 L

Waste Class Decoded:

146 - OTHER SPECIFIED INORGANICS

---

142 | ***1 of 1*** | ***SE/164.0*** | ***232.9 / -9.08*** | ***20 & 30 Ironside Drive (formerly 190 Bovaird Drive)***
Brampton ON L7A 1A2 | ***EHS***

Order No: 24031500300
Status: C
Report Type: Standard Express Report
Report Date: 18-MAR-24
Date Received: 15-MAR-24
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.7924759
Y: 43.7032311

---

143 | ***1 of 1*** | ***SE/172.1*** | ***232.9 / -9.08*** | ***190 BOVAIRD DR W***
Brampton ON L7A 1A2 | ***EHS***

Order No: 20301600144
Status: C
Report Type: Custom Report
Report Date: 11-NOV-20
Date Received: 16-OCT-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.79233834
Y: 43.70323466

---

144 | ***1 of 1*** | ***SE/167.1*** | ***232.9 / -9.08*** | ***190 Bovaird Drive W, Brampton***
Brampton ON L7A 1A2 | ***EHS***

Order No: 24031900837
Status: C
Report Type: Custom Report
Report Date: 22-MAR-24
Date Received: 19-MAR-24

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.79236552

Previous Site Name: | **Y:** 43.70319008
Lot/Building Size:
Additional Info Ordered:

---

145 | 1 of 1 | SE/180.2 | 236.8 / -5.15 | lot 11 con 1 ON | WWIS

Well ID:	4901581	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Commerical	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	05/26/1965
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1325
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	011
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901581.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/21/1965
Year Completed:	1965
Depth (m):	9.7536
Latitude:	43.7013802263528
Longitude:	-79.7959652029896
X:	-79.7959650532378
Y:	43.701380224345755
Path:	490\4901581.pdf

Bore Hole Information

Bore Hole ID:	10316426	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597015.60
Code OB Desc:		**North83:**	4839411.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	01/21/1965	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock

Materials Interval

Formation ID:	932034876
Layer:	3
Color:	2
General Color:	GREY
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	16.0
Formation End Depth:	32.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932034874
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	12.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932034875
Layer:	2
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	12.0
Formation End Depth:	16.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901581
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10864996
Casing No:	1

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	930523042
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	32.0
Casing Diameter:	24.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930523041
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	18.0
Casing Diameter:	24.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901581
Pump Set At:	
Static Level:	11.0
Final Level After Pumping:	22.0
Recommended Pump Depth:	25.0
Pumping Rate:	2.0
Flowing Rate:	
Recommended Pump Rate:	2.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

Water Details

Water ID:	933789529
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	28.0
Water Found Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	1 of 58	SE/147.3	232.1 / -9.89	***TORODE PRECISION COMPONENTS*** ***190 HIGHWAY 7 W SUITE 52*** ***BRAMPTON ON L7A 1A2***	SCT

Established: 1981
Plant Size (ft²): 1200

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Employment: 1

--Details--
Description: INDUSTRIAL TRUCKS, TRACTORS, TRAILERS, AND STACKERS
SIC/NAICS Code: 3537

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

---

146 | **2 of 58** | **SE/147.3** | **232.1 / -9.89** | **NORTHWOOD PARK SERVICE CENTRE INC**
190 HIGHWAY 7 W
BRAMPTON ON L7A1A2 | **RST**

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054512431
List Name:
Description:

---

146 | **3 of 58** | **SE/147.3** | **232.1 / -9.89** | **Torode Precision Components Inc.**
190 Highway 7 W Unit 52
Brampton ON L7A 1A2 | **SCT**

Established: 1981
Plant Size (ft²): 1200
Employment: 1

---

146 | **4 of 58** | **SE/147.3** | **232.1 / -9.89** | **Gaio Fabricating Inc.**
190 Bovaird Dr W Unit 22
Brampton ON L7A 1A2 | **SCT**

Established: 01-JUL-84
Plant Size (ft²): 3000
Employment:

--Details--
Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

---

146 | **5 of 58** | **SE/147.3** | **232.1 / -9.89** | **Marklyn Group**
190 Bovaird Dr W Unit 28
Brampton ON L7A 1A2 | **SCT**

Established: 01-JAN-78
Plant Size (ft²): 15000
Employment:

--Details--
Description: Motor Vehicle Seating and Interior Trim Manufacturing
SIC/NAICS Code: 336360

Description: Automobile and Light-Duty Motor Vehicle Manufacturing
SIC/NAICS Code: 336110

Description: Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

Description: Other Rubber Product Manufacturing
SIC/NAICS Code: 326290

---

146 **6 of 58** **SE/147.3** **232.1 / -9.89** **Torode Precision Components** **SCT**
190 Bovaird Dr W Unit 52
Brampton ON L7A 1A2

Established: 01-JAN-81
Plant Size (ft²): 1200
Employment:

--Details--
Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

Description: Material Handling Equipment Manufacturing
SIC/NAICS Code: 333920

---

146 **7 of 58** **SE/147.3** **232.1 / -9.89** **PACEMARATHON MOTOR LINES** **GEN**
190 Bovaird Dr W #35A
Brampton ON L7A 1A2

Generator Info

Generator No: ON2669500
Approval Years: 05,06
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: General Freight Trucking Long Distance Less Than Truck-Load
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 484122

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	8 of 58	SE/147.3	232.1 / -9.89	Rice Development 190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON7066709	**Choice of Contact:**	
Approval Years:	05	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	551113
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Holding Companies		

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	9 of 58	SE/147.3	232.1 / -9.89	1480411 Ontario Inc. 190 Bovaird Drive West Brampton Regional Municipality of Peel L7A 1A2 CITY OF BRAMPTON ON	EBR

EBR Registry No:	010-3575	**Decision Posted:**	
Ministry Ref No:	5364-7EEJZG	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:		**Act 1:**	
Notice Date:	August 25, 2008	**Act 2:**	
Proposal Date:	May 14, 2008	**Site Location Map:**	
Year:	2008		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	1480411 Ontario Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	30 Van Kirk Drive, Brampton Ontario, Canada L7A 2Y4		
Comment Period:			
URL:			
Summary:			

Site Location Details:

190 Bovaird Drive West Brampton Regional Municipality of Peel L7A 1A2 CITY OF BRAMPTON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	10 of 58	SE/147.3	232.1 / -9.89	1012582 ONTARIO LTD. 190 Bovaird Dr W #35A Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON2669500	**Choice of Contact:**	
Approval Years:	07,08	**Contaminated Fac:**	
Status:		**MHSW Facility:**	

PO Box No:
SIC Code: 484122
Country:
Co Admin:
Phone No Admin:
SIC Description: General Freight Trucking Long Distance Less Than Truck-Load

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

146 | ***11 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***1480411 Ontario Inc.***
190 Bovaird Dr W
Brampton ON L7A 1A2 | ***CA***

Certificate #: 6021-7HPNUK
Application Year: 2008
Issue Date: 8/20/2008
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

146 | ***12 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***Dor-Control Craftsmen Limited***
190 Bovaird Dr W Unit 17
Brampton ON L7A 1A2 | ***SCT***

Established: 01-SEP-73
Plant Size (ft²): 2000
Employment:

--Details--
Description: Finish Carpentry Contractors
SIC/NAICS Code: 238350

Description: All Other Building Equipment Contractors
SIC/NAICS Code: 238299

Description: Other Building Finishing Contractors
SIC/NAICS Code: 238390

Description: General-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416310

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Electrical Contractors and Other Wiring Installation Contractors
SIC/NAICS Code: 238210

---

146 | **13 of 58** | **SE/147.3** | **232.1 / -9.89** | **Estate Lighting Supply Ltd.**
190 Bovaird Dr W Unit 54
Brampton ON L7A 1A2 | **SCT**

Established: 01-SEP-93
Plant Size (ft²): 6000
Employment:

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

---

146 | **14 of 58** | **SE/147.3** | **232.1 / -9.89** | **Call Disposal Services Ltd.**
190 Bovaird Dr W Unit #25-26R
Brampton ON L9T 7T5 | **ECA**

Approval No: 1647-8Q8LUG
Approval Date: 2012-01-19
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
MOE District: Halton-Peel
City:
Longitude: -79.79228
Latitude: 43.70072
Geometry X:
Geometry Y:
Approval Type: ECA-WASTE MANAGEMENT SYSTEMS
Project Type: WASTE MANAGEMENT SYSTEMS
Business Name: Call Disposal Services Ltd.
Address: 190 Bovaird Dr W Unit #25-26R
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4213-8PCMSG-14.pdf
PDF Site Location:

---

146 | **15 of 58** | **SE/147.3** | **232.1 / -9.89** | **1012582 ONTARIO LTD.**
190 Bovaird Dr W #35A
Brampton ON L7A 1A2 | **GEN**

Generator Info

Generator No: ON2669500
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 484122
SIC Description: General Freight Trucking Long Distance Less Than Truck-Load

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

146 | ***16 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***Rice Development***
190 Bovaird Drive West Unit 7
Brampton ON L7A 1A2 | ***GEN***

Generator Info

Generator No: ON7066709
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Holding Companies

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 551113

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

146 | ***17 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***SDH Inc***
190 Bovaird Dr West Unit 15
Brampton ON L7A 1A2 | ***GEN***

Generator Info

Generator No: ON4097634
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Landscaping Services

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 561730

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

146 | ***18 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***1012582 ONTARIO LTD.***
190 Bovaird Dr W #35A
Brampton ON L7A 1A2 | ***GEN***

Generator Info

Generator No: ON2669500
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: General Freight Trucking Long Distance Less Than Truck-Load

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 484122

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

146 | ***19 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***SDH Inc*** | ***GEN***
190 Bovaird Dr West Unit 15
Brampton ON L7A 1A2

Generator Info

Generator No: ON4097634
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Landscaping Services

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 561730

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

146 | ***20 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***Rice Development*** | ***GEN***
190 Bovaird Drive West Unit 7
Brampton ON L7A 1A2

Generator Info

Generator No: ON7066709
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 551113

Phone No Admin:
SIC Description: Holding Companies

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

146 | ***21 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***1012582 ONTARIO LTD.***
190 Bovaird Dr W #35A
Brampton ON L7A 1A2 | ***GEN***

Generator Info

Generator No: ON2669500
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: General Freight Trucking Long Distance Less Than Truck-Load

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 484122

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

146 | ***22 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***Rice Development***
190 Bovaird Drive West Unit 7
Brampton ON L7A 1A2 | ***GEN***

Generator Info

Generator No: ON7066709
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Holding Companies

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 551113

Waste Detail(s)

Waste Class: 251

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		OIL SKIMMINGS & SLUDGES			

146	23 of 58	SE/147.3	232.1 / -9.89	**SDH Inc** **190 Bovaird Dr West Unit 15** **Brampton ON L7A 1A2**	GEN

Generator Info

Generator No:	ON4097634	**Choice of Contact:**	
Approval Years:	2012	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	561730
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Landscaping Services		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

146	24 of 58	SE/147.3	232.1 / -9.89	**1012582 ONTARIO LTD.** **190 Bovaird Dr W #35A** **Brampton ON L7A 1A2**	GEN

Generator Info

Generator No:	ON2669500	**Choice of Contact:**	
Approval Years:	2012	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	484122
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	General Freight Trucking Long Distance Less Than Truck-Load		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

146	25 of 58	SE/147.3	232.1 / -9.89	**Rice Development** **190 Bovaird Drive West Unit 7** **Brampton ON**	GEN

Generator Info

Generator No:	ON7066709	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	551113
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	HOLDING COMPANIES		

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

---

146 ***26 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***1012582 ONTARIO LTD.*** ***GEN***
190 Bovaird Dr W #35A
Brampton ON

Generator Info

Generator No:	ON2669500	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	484122
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

---

146 ***27 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***KENCO MECHANICAL MOVERS&MILLRIGHTS*** ***GEN***
190 BOVAIRD DRIVE WEST UNITS 25&26 R
BRAMPTON ON

Generator Info

Generator No:	ON8482603	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	

PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Code: 811310
SIC Description: COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND ELECTRONIC) REPAIR AND MAINTENANCE

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

146 | ***28 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***1480411 Ontario Inc.***
190 Bovaird Dr W
Brampton ON L7A 2Y4 | ***ECA***

Approval No: 6021-7HPNUK
Approval Date: 2008-08-20
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
Approval Type: ECA-AIR
Project Type: AIR
Business Name: 1480411 Ontario Inc.
Address: 190 Bovaird Dr W
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5364-7EEJZG-13.pdf
PDF Site Location:
MOE District: Halton-Peel
City:
Longitude: -79.79228
Latitude: 43.700756
Geometry X:
Geometry Y:

---

146 | ***29 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***SDH Inc***
190 Bovaird Dr West Unit 15
Brampton ON L7A1A2 | ***GEN***

Generator Info

Generator No: ON4097634
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: sean hayes
Phone No Admin: 905 796 5849 Ext.
SIC Description: LANDSCAPING SERVICES
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 561730

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		OIL SKIMMINGS & SLUDGES			

146	30 of 58	SE/147.3	232.1 / -9.89	1012582 ONTARIO LTD. 190 Bovaird Dr W #35A Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON2669500	**Choice of Contact:**	CO_ADMIN
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	484122
Country:	Canada		
Co Admin:	Rita Mallouk		
Phone No Admin:	905-796-8200 Ext.36		
SIC Description:	484122		

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

146	31 of 58	SE/147.3	232.1 / -9.89	Rice Development 190 Bovaird Drive West Unit 7 Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON7066709	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	551113
Country:	Canada		
Co Admin:	Donna Pinheiro		
Phone No Admin:	905-796-3630 Ext.227		
SIC Description:	HOLDING COMPANIES		

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

146	32 of 58	SE/147.3	232.1 / -9.89	1012582 ONTARIO LTD. 190 Bovaird Dr W #35A Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON2669500	***Choice of Contact:***	CO_ADMIN
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	484122
Country:	Canada		
Co Admin:	Rita Mallouk		
Phone No Admin:	905-796-8200 Ext.36		
SIC Description:	484122		

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

---

146 ***33 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***KENCO MACHINERY MOVERS&MILLRIGHTS***
190 BOVAIRD DRIVE WEST UNITS 25&26 R
BRAMPTON ON L7A1A2 ***GEN***

Generator Info

Generator No:	ON8482603	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	811310
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND ELECTRONIC) REPAIR AND MAINTENANCE		

Waste Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

---

146 ***34 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***Rice Development***
190 Bovaird Drive West Unit 7
Brampton ON L7A 1A2 ***GEN***

Generator Info

Generator No:	ON7066709	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: **MHSW Facility:** No
PO Box No: **SIC Code:** 551113
Country: Canada
Co Admin: Donna Pinheiro
Phone No Admin: 905-796-3630 Ext.227
SIC Description: HOLDING COMPANIES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

146 | ***35 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***SDH Inc*** | ***GEN***
190 Bovaird Dr West Unit 15
Brampton ON L7A1A2

Generator Info

Generator No: ON4097634 **Choice of Contact:** CO_OFFICIAL
Approval Years: 2015 **Contaminated Fac:** No
Status: **MHSW Facility:** No
PO Box No: **SIC Code:** 561730
Country: Canada
Co Admin: Corrie G Porreco
Phone No Admin: 905 796 5849 Ext.
SIC Description: LANDSCAPING SERVICES

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

146 | ***36 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***KENCO MACHINERY MOVERS&MILLRIGHTS*** | ***GEN***
190 BOVAIRD DRIVE WEST UNITS 25&26 R
BRAMPTON ON L7A1A2

Generator Info

Generator No: ON8482603 **Choice of Contact:** CO_OFFICIAL
Approval Years: 2015 **Contaminated Fac:** No
Status: **MHSW Facility:** No
PO Box No: **SIC Code:** 811310
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND ELECTRONIC) REPAIR AND MAINTENANCE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

146 ***37 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***1012582 ONTARIO LTD.*** ***GEN***
190 Bovaird Dr W #35A
Brampton ON L7A 1A2

Generator Info

Generator No: ON2669500
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Rita Mallouk
Phone No Admin: 905-796-8200 Ext.36
SIC Description: 484122

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 484122

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

146 ***38 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***SDH Inc*** ***GEN***
190 Bovaird Dr West Unit 15
Brampton ON L7A1A2

Generator Info

Generator No: ON4097634
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Corrie G Porreco
Phone No Admin: 905 796 5849 Ext.
SIC Description: LANDSCAPING SERVICES

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 561730

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

146 | ***39 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***KENCO MACHINERY MOVERS&MILLRIGHTS***
190 BOVAIRD DRIVE WEST UNITS 25&26 R
BRAMPTON ON L7A1A2 | ***GEN***

Generator Info

Generator No: ON8482603
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND ELECTRONIC) REPAIR AND MAINTENANCE

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 811310

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

146 | ***40 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***Rice Development***
190 Bovaird Drive West Unit 7
Brampton ON L7A 1A2 | ***GEN***

Generator Info

Generator No: ON7066709
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin: Donna Pinheiro
Phone No Admin: 905-796-3630 Ext.227
SIC Description: HOLDING COMPANIES

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 551113

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

146 | ***41 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***1012582 ONTARIO LTD.***
190 Bovaird Dr W #35A
Brampton ON L7A 1A2 | ***GEN***

Generator Info

Generator No: ON2669500
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 I
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

---

146 | ***42 of 58*** | ***SE/147.3*** | ***232.1 / -9.89*** | ***Rice Development***
190 Bovaird Drive West Unit 7
Brampton ON L7A 1A2 | ***GEN***

Generator Info

Generator No: ON7066709
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

2017 Generator Info

Gen No:	ON7066709	***Choice of Contact:***	CO_OFFICIAL
ID:	27742	***Phone No Official:***	905-796-3630 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905-796-3630 Ext.227
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	551113	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	Rice Development
Gen Div:	Rice Business Centre
Gen Op Name:	Rice Development
Gen Op Div:	Rice Business Centre
Site Adrs1:	190 Bovaird Drive West
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	Unit 7
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1A2
Site Country:	Canada
Co Official:	Gary Rogers
Co Admin:	Donna Pinheiro

2018 Generator Info

Gen No:	ON7066709	***Choice of Contact:***	CO_OFFICIAL
ID:	28187	***Phone No Official:***	905-796-3630 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905-796-3630 Ext.227
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	551113	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	Rice Development
Gen Div:	Rice Business Centre
Gen Op Name:	Rice Development
Gen Op Div:	Rice Business Centre
Site Adrs1:	190 Bovaird Drive West
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	Unit 7
Site City:	Brampton
Province Out:	
Site Postal Code:	L7A 1A2
Site Country:	Canada
Co Official:	Gary Rogers
Co Admin:	Donna Pinheiro

2019 Generator Info

Gen No:	ON7066709	***Choice of Contact:***	CO_OFFICIAL
ID:	28466	***Phone No Official:***	905-796-3630 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905-796-3630 Ext.227
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	551113	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	Rice Development
Gen Div:	Rice Business Centre
Gen Op Name:	Rice Development
Gen Op Div:	Rice Business Centre
Site Adrs1:	190 Bovaird Drive West
Site Bldg:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Pobox:
Province In: ONTARIO
Site Adrs2: Unit 7
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A2
Site Country: Canada
Co Official: Gary Rogers
Co Admin: Donna Pinheiro

---

146 | **43 of 58** | **SE/147.3** | **232.1 / -9.89** | **KENCO MACHINERY MOVERS&MILLRIGHTS**
190 BOVAIRD DRIVE WEST UNITS 25&26 R
BRAMPTON ON L7A1A2 | **GEN**

Generator Info

Generator No: ON8482603
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

146 | **44 of 58** | **SE/147.3** | **232.1 / -9.89** | **SDH Inc**
190 Bovaird Dr West Unit 15
Brampton ON L7A1A2 | **GEN**

Generator Info

Generator No: ON4097634
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	45 of 58	SE/147.3	232.1 / -9.89	Kris Kay Truck Lines 190 Bovaird Dr. W #32 Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON4217766	**Choice of Contact:**	
Approval Years:	As of Dec 2017	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Detail(s)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

2017 Generator Info

Gen No:	ON4217766	**Choice of Contact:**	CO_OFFICIAL
ID:	16828	**Phone No Official:**	905-456-8902 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	484122	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Kris Kay Truck Lines		
Gen Div:			
Gen Op Name:	Kris Kay Truck Lines		
Gen Op Div:			
Site Adrs1:	190 Bovaird Dr. W #32		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A2		
Site Country:	Canada		
Co Official:	Paul Borsellino		
Co Admin:			

2017 Generator Manifest

ID:	40126	**Sum Received Qty:**	4600.0
Generator No:	ON4217766	**Waste Class Name:**	ORGANIC LABORATORY CHEMICALS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	306
Waste Code:	263		

2017 Generator Manifest

ID:	40125	***Sum Received Qty:***	40.0
Generator No:	ON4217766	***Waste Class Name:***	PAINT/PIGMENT/COATING RESIDUES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	I	***District:***	306
Waste Code:	145		

---

146 ***46 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***190 Bovaird Dr W Brampton ON L7A1A2*** ***EHS***

Order No:	20161214130	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	21-DEC-16	***Search Radius (km):***	.25
Date Received:	14-DEC-16	***X:***	-79.792276
Previous Site Name:		***Y:***	43.703159
Lot/Building Size:			
Additional Info Ordered:			

---

146 ***47 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***SDH INC. O/A CLINTAR OUTDOOR SERVICES 15 - 190 BOVAIRD DR W BRAMPTON ON L7A1A2*** ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:	10225	***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:	Legacy Licenses (Excluding TS)	***Oper Area Code:***	905
Licence Type:	Operator	***Oper Phone No:***	7965849
Licence Type Code:	02	***Operator Ext:***	
Licence Class:	01	***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

---

146 ***48 of 58*** ***SE/147.3*** ***232.1 / -9.89*** ***SDH INC. 190 Bovaird DR W Brampton ON L7A 1A2*** ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:	L-240-3048411618	***Operator Class:***	
Status:	Active	***Operator No:***	
Approval Date:	2019-03-14	***Operator Type:***	
Report Source:	PEST-Operator	***Oper Area Code:***	
Licence Type:	Operator	***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:	43.70111111	***Operator Region:***	
Longitude:	-79.79222222	***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Region: **Post Office Box:**
District: **MOE District:** Halton-Peel
County: **SWP Area Name:** Credit Valley
Trade Name:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2136395

---

146 **49 of 58** **SE/147.3** **232.1 / -9.89** **1012582 ONTARIO LTD.**
190 Bovaird Dr W #35A
Brampton ON L7A 1A2
GEN

Generator Info

Generator No: ON2669500
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 252 I
Waste Class Name: Waste crankcase oils and lubricants

---

146 **50 of 58** **SE/147.3** **232.1 / -9.89** **SDH Inc**
190 Bovaird Drive West Unit 15
Brampton ON L7A 1A2
GEN

Generator Info

Generator No: ON4097634
Approval Years: As of Jul 2020
Status: Registered

Choice of Contact:
Contaminated Fac:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No: **SIC Code:**
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

146 **51 of 58** **SE/147.3** **232.1 / -9.89** **KENCO MACHINERY MOVERS&MILLRIGHTS**
190 BOVAIRD DRIVE WEST UNITS 25&26 R
BRAMPTON ON L7A1A2 **GEN**

Generator Info

Generator No: ON8482603 **Choice of Contact:**
Approval Years: As of Jul 2020 **Contaminated Fac:**
Status: Registered **MHSW Facility:**
PO Box No: **SIC Code:**
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

146 **52 of 58** **SE/147.3** **232.1 / -9.89** **SDH INC.**
190 Bovaird DR W
Brampton ON L7A 1A2 **PES**

Detail Licence No: **Operator Box:**
Licence No: L-240-3048411618 **Operator Class:**
Status: Active **Operator No:**
Approval Date: 2019-10-09 **Operator Type:**
Report Source: PEST-Operator **Oper Area Code:**
Licence Type: Operator **Oper Phone No:**
Licence Type Code: **Operator Ext:**
Licence Class: **Operator Lot:**
Licence Control: **Oper Concession:**
Latitude: 43.70111111 **Operator Region:**
Longitude: -79.79222222 **Operator District:**
Lot: **Operator County:**
Concession: **Op Municipality:**
Region: **Post Office Box:**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2185914		

146	53 of 58	SE/147.3	232.1 / -9.89	**JSS Solvents Inc.** **190 Bovaird Dr. West Unit #38** **Brampton ON L7A1A2**	GEN

Generator Info

Generator No:	ON9501375	**Choice of Contact:**	
Approval Years:	As of Oct 2019	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	241 H
Waste Class Name:	Halogenated solvents and residues

Waste Detail(s)

Waste Class:	241 L
Waste Class Name:	Halogenated solvents and residues

2019 Generator Info

Gen No:	ON9501375	**Choice of Contact:**	CO_OFFICIAL
ID:	38398	**Phone No Official:**	6476400922 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	418990	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	JSS Solvents Inc.		
Gen Div:			
Gen Op Name:	JSS Solvents Inc.		
Gen Op Div:			
Site Adrs1:	190 Bovaird Dr. West		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit #38		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A1A2		
Site Country:	Canada		
Co Official:	Deepnarain Panday		
Co Admin:			

146	54 of 58	SE/147.3	232.1 / -9.89	**KENCO MACHINERY MOVERS&MILLRIGHTS** **190 BOVAIRD DRIVE WEST UNITS 25&26 R** **BRAMPTON ON L7A1A2**	GEN

Generator Info

Generator No:	ON8482603	***Choice of Contact:***	
Approval Years:	As of Jan 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

2017 Generator Info

Gen No:	ON8482603	***Choice of Contact:***	CO_OFFICIAL
ID:	33216	***Phone No Official:***	905-454-9415 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	811310	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	KENCO MACHINERY MOVERS&MILLRIGHTS		
Gen Div:			
Gen Op Name:	SAME		
Gen Op Div:			
Site Adrs1:	190 BOVAIRD DRIVE WEST UNITS 25&26 R		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L7A1A2		
Site Country:	Canada		
Co Official:	LYNN BOWMAN		
Co Admin:			

2018 Generator Info

Gen No:	ON8482603	***Choice of Contact:***	CO_OFFICIAL
ID:	33840	***Phone No Official:***	905-454-9415 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	811310	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	KENCO MACHINERY MOVERS&MILLRIGHTS		
Gen Div:			
Gen Op Name:	SAME		
Gen Op Div:			
Site Adrs1:	190 BOVAIRD DRIVE WEST UNITS 25&26 R		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			

Site Postal Code:	L7A1A2
Site Country:	Canada
Co Official:	LYNN BOWMAN
Co Admin:	

2018 Generator Manifest

ID:	61242	**Sum Received Qty:**	683.0
Generator No:	ON8482603	**Waste Class Name:**	WASTE OILS & LUBRICANTS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	305
Waste Code:	252		

2019 Generator Info

Gen No:	ON8482603	**Choice of Contact:**	CO_OFFICIAL
ID:	34240	**Phone No Official:**	905-454-9415 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	811310	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	KENCO MACHINERY MOVERS&MILLRIGHTS
Gen Div:	
Gen Op Name:	SAME
Gen Op Div:	
Site Adrs1:	190 BOVAIRD DRIVE WEST UNITS 25&26 R
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A1A2
Site Country:	Canada
Co Official:	LYNN BOWMAN
Co Admin:	

2020 Generator Info

Gen No:	ON8482603	**Choice of Contact:**	CO_OFFICIAL
ID:	33969	**Phone No Official:**	905-454-9415 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	811310	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	KENCO MACHINERY MOVERS&MILLRIGHTS
Gen Div:	
Gen Op Name:	SAME
Gen Op Div:	
Site Adrs1:	190 BOVAIRD DRIVE WEST UNITS 25&26 R
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	BRAMPTON
Province Out:	
Site Postal Code:	L7A1A2
Site Country:	Canada
Co Official:	LYNN BOWMAN
Co Admin:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	55 of 58	SE/147.3	232.1 / -9.89	SDH Inc 190 Bovaird Drive West Unit 15 Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON4097634	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	221 I
Waste Class Name:	Light fuels

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	56 of 58	SE/147.3	232.1 / -9.89	1012582 ONTARIO LTD. 190 Bovaird Dr W #35A Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON2669500	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	213 T
Waste Class Name:	Petroleum distillates

Waste Detail(s)

Waste Class:	213 I
Waste Class Name:	Petroleum distillates

Waste Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Detail(s)

Waste Class: 252 I
Waste Class Name: Waste crankcase oils and lubricants

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

2017 Generator Info

Gen No: ON2669500
ID: 10828
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 484122
NAICS Code2:
NAICS Code3:
Gen Name: 1012582 ONTARIO LTD.
Gen Div:
Gen Op Name: PACE MARATHON
Gen Op Div:
Site Adrs1: 190 Bovaird Dr W #35A
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A2
Site Country: Canada
Co Official: George Mallouk
Co Admin: Rita Mallouk
Choice of Contact: CO_ADMIN
Phone No Official: 905-796-8200 Ext.32
Phone No Admin: 905-796-8200 Ext.36
County Ont: PEEL (R. M.)
County Out:
District: 305

2017 Generator Manifest

ID: 32396
Generator No: ON2669500
Receiver Type: 035
Waste Char: T
Waste Code: 213
Sum Received Qty: 390.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 13
District: 305

2017 Generator Manifest

ID: 32397
Generator No: ON2669500
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 2275.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 305

2018 Generator Info

Gen No: ON2669500
ID: 10580
Contaminated Fac: N
Choice of Contact: CO_ADMIN
Phone No Official: 905-796-8200 Ext.32
Phone No Admin: 905-796-8200 Ext.36

MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	484122	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	1012582 ONTARIO LTD.		
Gen Div:			
Gen Op Name:	PACE MARATHON		
Gen Op Div:			
Site Adrs1:	190 Bovaird Dr W #35A		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A2		
Site Country:	Canada		
Co Official:	George Mallouk		
Co Admin:	Rita Mallouk		

2018 Generator Manifest

ID:	32082	***Sum Received Qty:***	909.0
Generator No:	ON2669500	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	252		

2018 Generator Manifest

ID:	32080	***Sum Received Qty:***	500.0
Generator No:	ON2669500	***Waste Class Name:***	ALIPHATIC SOLVENTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	212		

2018 Generator Manifest

ID:	32081	***Sum Received Qty:***	390.0
Generator No:	ON2669500	***Waste Class Name:***	PETROLEUM DISTILLATES
Receiver Type:	035	***Count Manifests:***	13
Waste Char:	T	***District:***	305
Waste Code:	213		

2019 Generator Info

Gen No:	ON2669500	***Choice of Contact:***	CO_ADMIN
ID:	10284	***Phone No Official:***	905-796-8200 Ext.32
Contaminated Fac:	N	***Phone No Admin:***	905-796-8200 Ext.36
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	484122	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	1012582 ONTARIO LTD.		
Gen Div:			
Gen Op Name:	PACE MARATHON		
Gen Op Div:			
Site Adrs1:	190 Bovaird Dr W #35A		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			

Site City: Brampton
Province Out:
Site Postal Code: L7A 1A2
Site Country: Canada
Co Official: George Mallouk
Co Admin: Rita Mallouk

2019 Generator Manifest

ID: 31385
Generator No: ON2669500
Receiver Type: 035
Waste Char: T
Waste Code: 212
Sum Received Qty: 30.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 305

2019 Generator Manifest

ID: 31386
Generator No: ON2669500
Receiver Type: 035
Waste Char: T
Waste Code: 213
Sum Received Qty: 330.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 11
District: 305

2019 Generator Manifest

ID: 31387
Generator No: ON2669500
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 3568.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 2
District: 305

2020 Generator Info

Gen No: ON2669500
ID: 9928
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 484122
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_ADMIN
Phone No Official: 905-796-8200 Ext.32
Phone No Admin: 905-796-8200 Ext.36
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: 1012582 ONTARIO LTD.
Gen Div:
Gen Op Name: PACE MARATHON
Gen Op Div:
Site Adrs1: 190 Bovaird Dr W #35A
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A2
Site Country: Canada
Co Official: George Mallouk
Co Admin: Rita Mallouk

2020 Generator Manifest

ID: 28637
Generator No: ON2669500
Receiver Type: 035
Waste Char: T
Sum Received Qty: 300.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 10
District: 305

Waste Code: 213

2020 Generator Manifest

ID: 28638
Generator No: ON2669500
Receiver Type: 035
Waste Char: L
Waste Code: 252
Sum Received Qty: 1833.0
Waste Class Name: WASTE OILS & LUBRICANTS
Count Manifests: 1
District: 305

2020 Generator Manifest

ID: 28636
Generator No: ON2669500
Receiver Type: 035
Waste Char: I
Waste Code: 213
Sum Received Qty: 30.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 1
District: 305

2021 Generator Info

Gen No: ON2669500
ID: 9690
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 484122
NAICS Code2:
NAICS Code3:
Gen Name: 1012582 ONTARIO LTD.
Gen Div:
Gen Op Name: PACE MARATHON
Gen Op Div:
Site Adrs1: 190 Bovaird Dr W #35A
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 1A2
Site Country: Canada
Co Official: George Mallouk
Co Admin: Rita Mallouk
Choice of Contact: CO_ADMIN
Phone No Official: 905-796-8200 Ext.32
Phone No Admin: 905-796-8200 Ext.36
County Ont: PEEL (R. M.)
County Out:
District: 305

2021 Generator Manifest

ID: 28792
Generator No: ON2669500
Receiver Type: 035
Waste Char: I
Waste Code: 213
Sum Received Qty: 30.0
Waste Class Name: PETROLEUM DISTILLATES
Count Manifests: 1
District: 305

2021 Generator Manifest

ID: 28791
Generator No: ON2669500
Receiver Type: 035
Waste Char: L
Waste Code: 212
Sum Received Qty: 650.0
Waste Class Name: ALIPHATIC SOLVENTS
Count Manifests: 1
District: 305

2021 Generator Manifest

ID:	28793	**Sum Received Qty:**	358.0
Generator No:	ON2669500	**Waste Class Name:**	PETROLEUM DISTILLATES
Receiver Type:	035	**Count Manifests:**	12
Waste Char:	T	**District:**	305
Waste Code:	213		

146 **57 of 58** **SE/147.3** **232.1 / -9.89**

SDH Inc
190 Bovaird Drive West Unit 15
Brampton ON L7A 1A2

GEN

Generator Info

Generator No:	ON4097634	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	221 I
Waste Class Name:	LIGHT FUELS

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	OIL SKIMMINGS & SLUDGES

2017 Generator Info

Gen No:	ON4097634	**Choice of Contact:**	CO_OFFICIAL
ID:	16353	**Phone No Official:**	9057965849 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905 796 5849 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	561730	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	SDH Inc		
Gen Div:			
Gen Op Name:	Clintar Landscape Management		
Gen Op Div:			
Site Adrs1:	190 Bovaird Dr West		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 15		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A1A2		
Site Country:	Canada		
Co Official:	Sean D Hayes		
Co Admin:	Sean Hayes		

2017 Generator Manifest

ID:	39519	***Sum Received Qty:***	683.0
Generator No:	ON4097634	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	252		

2018 Generator Info

Gen No:	ON4097634	***Choice of Contact:***	CO_OFFICIAL
ID:	16338	***Phone No Official:***	9057965849 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905 796 5849 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	561730	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SDH Inc		
Gen Div:			
Gen Op Name:	Clintar Landscape Management		
Gen Op Div:			
Site Adrs1:	190 Bovaird Dr West		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 15		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A1A2		
Site Country:	Canada		
Co Official:	Sean D Hayes		
Co Admin:	Sean Hayes		

2019 Generator Info

Gen No:	ON4097634	***Choice of Contact:***	CO_OFFICIAL
ID:	16201	***Phone No Official:***	9057965849 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905 796 5849 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	561730	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SDH Inc		
Gen Div:			
Gen Op Name:	Clintar Commercial Outdoor Services		
Gen Op Div:			
Site Adrs1:	190 Bovaird Drive West		
Site Bldg:	Clintar Commercial Outdoor Services		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 15		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A2		
Site Country:	Canada		
Co Official:	Sean D Hayes		
Co Admin:	Sean Hayes		

2019 Generator Manifest

ID:	38681	***Sum Received Qty:***	500.0

Generator No:	ON4097634	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	252		

2020 Generator Info

Gen No:	ON4097634	***Choice of Contact:***	CO_OFFICIAL
ID:	15897	***Phone No Official:***	9057965849 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905 796 5849 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	561730	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SDH Inc		
Gen Div:			
Gen Op Name:	Clintar Commercial Outdoor Services		
Gen Op Div:			
Site Adrs1:	190 Bovaird Drive West		
Site Bldg:	Clintar Commercial Outdoor Services		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 15		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A2		
Site Country:	Canada		
Co Official:	Sean D Hayes		
Co Admin:	Sean Hayes		

2021 Generator Info

Gen No:	ON4097634	***Choice of Contact:***	CO_OFFICIAL
ID:	15905	***Phone No Official:***	9057965849 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905 796 5849 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	561730	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	SDH Inc		
Gen Div:			
Gen Op Name:	Clintar Commercial Outdoor Services		
Gen Op Div:			
Site Adrs1:	190 Bovaird Drive West		
Site Bldg:	Clintar Commercial Outdoor Services		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Unit 15		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L7A 1A2		
Site Country:	Canada		
Co Official:	Sean D Hayes		
Co Admin:	Sean Hayes		

2021 Generator Manifest

ID:	36634	***Sum Received Qty:***	500.0
Generator No:	ON4097634	***Waste Class Name:***	WASTE OILS & LUBRICANTS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	252		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	58 of 58	SE/147.3	232.1 / -9.89	Maple Reinders Constructors 190 Bovaird Rd W Brampton ON L7A 1A2	GEN

Generator Info

Generator No:	ON2965644	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	145 I
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Waste Detail(s)

Waste Class:	252 L
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Detail(s)

Waste Class:	145 L
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
147	1 of 4	SE/49.6	233.9 / -8.08	Attrell Toyota 110 Canam Crescent (Bovaird and VanKirk) Brampton ON	SPL

Ref No:	5425-7SQSFE	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:		***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	6/5/2009	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:	Deferred Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Attrell Toyota at Brampton Auto Mall<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Attrell Toyota		
Client Type:			
Source Type:			

Incident Cause:	Other Discharges
Incident Preceding Spill:	
Incident Reason:	Unknown - Reason not determined
Incident Summary:	Attrell Toyota, waste engine oil to drain, June 1
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	Other Impact(s)
Contaminant Qty:	50 other - see incident description
Contaminant Qty 1:	50
Contaminant Unit:	other - see incident description
Contaminant Code:	
Contaminant Name:	ENGINE OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

147 | ***2 of 4*** | ***SE/49.6*** | ***233.9 / -8.08*** | ***Attrell Toyota***
110 Canam Drive
Brampton ON L7A 2A9 | ***GEN***

Generator Info

Generator No:	ON4473811	***Choice of Contact:***	
Approval Years:	As of Oct 2019	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	150 L
Waste Class Name:	Inert organic wastes

2019 Generator Info

Gen No:	ON4473811	***Choice of Contact:***	CO_OFFICIAL
ID:	17757	***Phone No Official:***	905-450-4867 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	441110	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Attrell Toyota		
Gen Div:			
Gen Op Name:	Attrell Toyota		
Gen Op Div:			
Site Adrs1:	110 Canam Drive		
Site Bldg:			

Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 2A9
Site Country: Canada
Co Official: Joe Borello
Co Admin:

2019 Generator Manifest

ID:	40564	**Sum Received Qty:**	15000.0
Generator No:	ON4473811	**Waste Class Name:**	INERT INORGANIC WASTES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	L	**District:**	305
Waste Code:	150		

---

147 | ***3 of 4*** | ***SE/49.6*** | ***233.9 / -8.08*** | ***Accuworx*** | ***SPL***

110 Canam Crescent, Brampton, ON L7A 1A9
BRAMPTON ON

Ref No:	1-4OP1LK	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	Feb 27,2024 10:30:26 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	Feb 27,2024 04:11:26 PM	**Impact to Health:**	
Dt Document Closed:	Mar 05,2024 04:07:39 PM	**Agency Involved:**	

Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name: Accuworx
Site Address: 110 Canam Crescent, Brampton, ON L7A 1A9
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: BRENNTAG CANADA INC.
Client Type: Private Business
Source Type: Motor Vehicle
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Equipment failure/malfunction
Incident Summary: Brenntag: 50L engine oil to asphalt. Clean up complete_110 Canam Crescent, Brampton
Environment Impact:
Health Env Consequence: Low
Nature of Impact:
Contaminant Qty: 50 litre (L)
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: ENGINE OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land

Activity Preceding Spill: Normal operations
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02ED - Nottawasaga
Sector Type: GENERAL FREIGHT TRUCKING, LONG DISTANCE, TRUCK-LOAD
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001475894"],"wkts":["POINT (-79.7938630000 43.7016987000)"],"creation_date":"2024-02-27"}
Time Reported:
System Facility Address: 220 SUPERIOR BLVD, MISSISSAUGA, ON L5T 2L2

147	4 of 4	SE/49.6	233.9 / -8.08	**Brenntag Canada Inc** **110 Canam Crescent** **Brampton ON**	GEN

Generator Info as of Dec 2024

Generator No: ONS0305-1-4OP1LK-1
Generator Company Name: Brenntag Canada Inc
Street: 110 Canam Crescent
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L7A 1A9
Waste Class: 251 L

Waste Class Decoded:

251 - OIL SKIMMINGS & SLUDGES

148	1 of 1	SSE/246.6	236.6 / -5.35	**Kia of Brampton** **9 Canam cres.** **Brampton ON L7A 1G1**	GEN

Generator Info

Generator No: ON5434629
Approval Years: 05
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: New Car Dealers

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 441110

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

149	1 of 1	SE/104.3	231.9 / -10.08	**190 bovaird dr w. brampton lot 11 con 1** **Brampton ON**	WWIS

Well ID: 7329307
Construction Date:
Use 1st: Test Hole
Use 2nd: Monitoring
Final Well Status: Test Hole

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 03/04/2019

Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z305710	**Contractor:**	7247
Tag:	A263862	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	011
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/732\7329307.pdf

Additional Detail(s) (Map)

Well Completed Date:	12/19/2018
Year Completed:	2018
Depth (m):	10.668
Latitude:	43.7019206493035
Longitude:	-79.7917173530111
X:	-79.79171720273563
Y:	43.7019206470459
Path:	732\7329307.pdf

Bore Hole Information

Bore Hole ID:	1007456960	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597357.00
Code OB Desc:		**North83:**	4839476.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12/19/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007823311
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	81
Material 2 Desc:	SANDY
Material 3:	05
Material 3 Desc:	CLAY
Formation Top Depth:	0.0
Formation End Depth:	5.0

Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007823315
Layer: 5
Color: 6
General Color: BROWN
Material 1: 17
Material 1 Desc: SHALE
Material 2: 92
Material 2 Desc: WEATHERED
Material 3: 06
Material 3 Desc: SILT
Formation Top Depth: 25.0
Formation End Depth: 35.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007823314
Layer: 4
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 81
Material 2 Desc: SANDY
Material 3: 61
Material 3 Desc: CLAYEY
Formation Top Depth: 15.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007823312
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 61
Material 2 Desc: CLAYEY
Material 3: 81
Material 3 Desc: SANDY
Formation Top Depth: 5.0
Formation End Depth: 8.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007823313
Layer: 3
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT

Material 2: 81
Material 2 Desc: SANDY
Material 3: 11
Material 3 Desc: GRAVEL
Formation Top Depth: 8.5
Formation End Depth: 15.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007825234
Layer: 1
Plug From: 0.0
Plug To: 28.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007827575
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1007821872
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007828240
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 30.0
Casing Diameter: 2.0
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007828957
Layer: 1
Slot: 10
Screen Top Depth: 30.0
Screen End Depth: 35.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.125

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1007829774
Pump Set At:

Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1007829511
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	15.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007826768
Diameter:	6.0
Depth From:	0.0
Depth To:	35.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

---

150 | ***1 of 1*** | ***SE/129.9*** | ***230.9 / -11.08*** | ***223 BOVAIRD DR W Brampton ON*** | ***WWIS***

Well ID:	7284163	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Monitoring and Test Hole	**Date Received:**	04/03/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z229952	**Contractor:**	7215
Tag:	A212514	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/728\7284163.pdf

Additional Detail(s) (Map)

Well Completed Date: 02/03/2017

Year Completed:	2017
Depth (m):	4.572
Latitude:	43.7015412009994
Longitude:	-79.7907445308833
X:	-79.79074438062707
Y:	43.70154119925306
Path:	728\7284163.pdf

Bore Hole Information

Bore Hole ID:	1006376673	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597436.00
Code OB Desc:		**North83:**	4839435.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/03/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006620495
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	9.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006620493
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Overburden and Bedrock

Materials Interval

Formation ID:	1006620494
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	2.0
Formation End Depth:	9.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006620504
Layer:	2
Plug From:	4.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006620505
Layer:	3
Plug From:	1.0
Plug To:	0.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006620503
Layer:	1
Plug From:	15.0
Plug To:	4.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1006620502
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1006620492
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006620498

Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	5.0
Depth To:	-2.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006620499
Layer:	1
Slot:	10
Screen Top Depth:	15.0
Screen End Depth:	5.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1006620497
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1006620496
Diameter:	9.0
Depth From:	15.0
Depth To:	0.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

151 **1 of 1** **WNW/11.6** **259.8 / 17.84** **HUTCHINSON FARM LN lot 19 con 1 CALEDON ON** **WWIS**

Well ID:	7321774	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	11/07/2018
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z278293	**Contractor:**	6607
Tag:	A242072	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	019
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/732\7321774.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/24/2018
Year Completed: 2018
Depth (m): 4.5
Latitude: 43.7336651700805
Longitude: -79.8391963180007
X: -79.8391961676818
Y: 43.733665168433056
Path: 732\7321774.pdf

Bore Hole Information

Bore Hole ID: 1007307020
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/24/2018
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593482.00
North83: 4842947.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007603008
Layer: 1
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 61
Material 2 Desc: CLAYEY
Material 3: 11
Material 3 Desc: GRAVEL
Formation Top Depth: 0.0
Formation End Depth: 3.9000000953674316
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007603009
Layer: 2
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 61
Material 2 Desc: CLAYEY
Material 3: 11

Material 3 Desc: GRAVEL
Formation Top Depth: 3.9000000953674316
Formation End Depth: 4.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007603017
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007603018
Layer: 2
Plug From: 0.30000001192092896
Plug To: 1.2000000476837158
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007603016
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007603007
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007603013
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007603014
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 4.5
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Water Details

Water ID:	1007603011
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	3.9000000953674316
Water Found Depth UOM:	m

Water Details

Water ID:	1007603012
Layer:	2
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1007603010
Diameter:	21.0
Depth From:	0.0
Depth To:	4.5
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

152 ***1 of 1*** ***SE/71.9*** ***231.0 / -10.93*** ***Bovaird Brampton ON*** ***EHS***

Order No:	24062700012	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	23-JUL-24	***Search Radius (km):***	.1
Date Received:	27-JUN-24	***X:***	-79.79279728
Previous Site Name:		***Y:***	43.70046045
Lot/Building Size:			
Additional Info Ordered:			

---

153 ***1 of 4*** ***SE/230.9*** ***233.0 / -8.95*** ***Chrysler Group LLC 190 Canam Crescent Brampton ON*** ***GEN***

Generator Info

Generator No:	ON7916066	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	441110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	NEW CAR DEALERS		

Waste Detail(s)

Waste Class:	150

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: INERT INORGANIC WASTES

---

153 *2 of 4* **SE/230.9** **233.0 / -8.95** **190 Canam Cres**
Brampton ON L7A1A9 **EHS**

Order No:	20130507069	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	16-MAY-13	**Search Radius (km):**	.25
Date Received:	07-MAY-13	**X:**	-79.795047
Previous Site Name:		**Y:**	43.699187
Lot/Building Size:			
Additional Info Ordered:	Title Searches		

---

153 *3 of 4* **SE/230.9** **233.0 / -8.95** **1035312 ONTARIO LIMITED**
190 CANAM BRAMPTON
ON **EASR**

Approval No:	R-001-7533622169	**MOE District:**	
Status:	Registered	**Municipality:**	BRAMPTON
Date:	10/26/15	**Latitude:**	
Record Type:		**Longitude:**	
Link Source:		**Geometry X:**	
Project Type:	Automotive Refinishing Facility	**Geometry Y:**	
Full Address:			
Approval Type:			
SWP Area Name:			
PDF NAICS Code:			
PDF URL:			
PDF Site Location:			

---

153 *4 of 4* **SE/230.9** **233.0 / -8.95** **1035312 ONTARIO LIMITED**
190 CANAM CRES
BRAMPTON ON L7A 1A9 **EASR**

Approval No:	R-001-7533622169	**MOE District:**	Halton-Peel
Status:	REGISTERED	**Municipality:**	BRAMPTON
Date:	2015-10-26	**Latitude:**	43.69916667
Record Type:	EASR	**Longitude:**	-79.795
Link Source:	MOFA	**Geometry X:**	
Project Type:	Automotive Refinishing Facility	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Automotive Refinishing Facility		
SWP Area Name:	Credit Valley		
PDF NAICS Code:			
PDF URL:			
PDF Site Location:			

---

154 *1 of 1* **SE/126.5** **230.9 / -11.08** **ON** **WWIS**

Well ID:	7179434	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	03/28/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C17746	**Contractor:**	7230
Tag:	A128917	**Form Version:**	8

Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7179434.pdf

Additional Detail(s) (Map)

Well Completed Date:	03/01/2012
Year Completed:	2012
Depth (m):	
Latitude:	43.701258594687
Longitude:	-79.7904151250444
X:	-79.79041497483071
Y:	43.70125859345083
Path:	717\7179434.pdf

Bore Hole Information

Bore Hole ID:	1003753378	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597463.00
Code OB Desc:		**North83:**	4839404.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03/01/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

155 | ***1 of 1*** | ***SE/130.0*** | ***230.9 / -11.08*** | ***MANETT CRESENT Brampton ON*** | ***WWIS***

Well ID:	7191506	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	11/14/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z160607	**Contractor:**	7241
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	

Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:	WKQ-005420		

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191506.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/30/2012
Year Completed:	2012
Depth (m):	
Latitude:	43.7012579380709
Longitude:	-79.7903530851394
X:	-79.79035293450205
Y:	43.70125793621605
Path:	719\7191506.pdf

Bore Hole Information

Bore Hole ID:	1004203980	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597468.00
Code OB Desc:		**North83:**	4839404.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/30/2012	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004525205
Layer:	1
Plug From:	0.0
Plug To:	25.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004525204
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004525196
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID: 1004525200
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004525201
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1004525199
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004525198
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

156 ***1 of 1*** ***SE/78.3*** ***230.1 / -11.87*** ***MANNETT CRESENT Brampton ON*** ***WWIS***

Well ID:	7191505	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	11/14/2012
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z160608	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	

Clear/Cloudy: ***UTM Reliability:***
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info: WKQ-005420

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191505.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/30/2012
Year Completed: 2012
Depth (m):
Latitude: 43.7009204586733
Longitude: -79.7907942405843
X: -79.79079409073962
Y: 43.70092045711392
Path: 719\7191505.pdf

Bore Hole Information

Bore Hole ID: 1004203977
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/30/2012
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 597433.00
North83: 4839366.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004525195
Layer: 1
Plug From: 0.0
Plug To: 20.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1004525194
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004525186
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004525190
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004525191
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1004525189
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004525188
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

157 | ***1 of 1*** | ***WNW/113.7*** | ***258.9 / 16.92*** | ***PART OF LOT 20, CONCESSION 1 WHS CALEDON ON*** | ***WWIS***

Well ID: 7265666
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z235422
Tag: A206199
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 06/24/2016
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7472
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/726\7265666.pdf

Additional Detail(s) (Map)

Well Completed Date: 02/26/2016
Year Completed: 2016
Depth (m): 4.572
Latitude: 43.7346275097913
Longitude: -79.8390908041886
X: -79.83909065421072
Y: 43.7346275081437
Path: 726\7265666.pdf

Bore Hole Information

Bore Hole ID: 1006078617
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/26/2016
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 593489.00
North83: 4843054.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006110123
Layer: 2
Color: 6
General Color: BROWN
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006110122
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2:

Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006110131
Layer: 2
Plug From: 9.0
Plug To: 15.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006110130
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1006110129
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1006110121
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006110126
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006110127
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 15.0
Screen Material: 5
Screen Depth UOM: ft

Screen Diameter UOM: inch
Screen Diameter: 2.5

Water Details

Water ID: 1006110125
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006110124
Diameter: 6.0
Depth From: 0.0
Depth To: 15.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

158 | **1 of 1** | **SE/27.5** | **230.0 / -11.92** | **MANETT CRESENT Brampton ON** | **WWIS**

Well ID: 7191504
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z160609
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info: WKQ005420

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/14/2012
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191504.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/30/2012
Year Completed: 2012
Depth (m):
Latitude: 43.7006193790819
Longitude: -79.7912718911162
X: -79.79127174102075
Y: 43.70061937689693
Path: 719\7191504.pdf

Bore Hole Information

Bore Hole ID: 1004203974
DP2BR:
Elevation:
Elevrc:

Spatial Status:		***Zone:***	17
Code OB:		***East83:***	597395.00
Code OB Desc:		***North83:***	4839332.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/30/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004525185
Layer:	1
Plug From:	0.0
Plug To:	21.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004525184
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004525176
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004525180
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004525181
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Water Details

Water ID:	1004525179
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004525178
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

159 ***1 of 4*** ***SE/95.0*** ***229.9 / -12.08*** ***MANETT RESIDENCES INC.***
100 Manett Crescent
Brampton ON L6X 4X4 ***EASR***

Approval No:	R-009-6111450385	***MOE District:***	Halton-Peel
Status:	REGISTERED	***Municipality:***	Brampton
Date:	2019-07-15	***Latitude:***	43.70194444
Record Type:	EASR	***Longitude:***	-79.78972222
Link Source:	MOFA	***Geometry X:***	
Project Type:	Water Taking - Construction Dewatering	***Geometry Y:***	
Full Address:			
Approval Type:	EASR-Water Taking - Construction Dewatering		
SWP Area Name:	Credit Valley		
PDF NAICS Code:			
PDF URL:			
PDF Site Location:			

---

159 ***2 of 4*** ***SE/95.0*** ***229.9 / -12.08*** ***1737126 Ont Inc.***
100 Manett Cres.
Brampton ON L6X 4X4 ***GEN***

Generator Info

Generator No:	ON7769490	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	146 L
Waste Class Name:	Other specified inorganic sludges, slurries or solids

2021 Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Gen No:	ON7769490	**Choice of Contact:**	CO_OFFICIAL
ID:	31630	**Phone No Official:**	7052386893 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	238910	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	1737126 Ont Inc.		
Gen Div:			
Gen Op Name:	CC Underground		
Gen Op Div:			
Site Adrs1:	100 Manett Cres.		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6X 4X4		
Site Country:	Canada		
Co Official:	Michael Stanton		
Co Admin:			

2021 Generator Manifest

ID:	56195	**Sum Received Qty:**	1630.0
Generator No:	ON7769490	**Waste Class Name:**	OTHER SPECIFIED INORGANICS
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	301
Waste Code:	146		

---

159 | ***3 of 4*** | ***SE/95.0*** | ***229.9 / -12.08*** | ***ENBRIDGE INC***
100 Manett Crescent, Brampton
BRAMPTON ON | ***SPL***

Ref No:	1-3Y1PXL	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	10/19/2023 8:51:01 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/19/2023 11:48:01 AM	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	100 Manett Crescent, Brampton		
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	ENBRIDGE INC		
Client Type:	Private Business		
Source Type:	Pipeline/Components		
Incident Cause:			
Incident Preceding Spill:	Line Strike		
Incident Reason:	Unknown		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Summary:	TSSA FSB - 2inch Plastic IP Line Strike - MS
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	1 other - see notes
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	NATURAL GAS
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Activity Preceding Spill:	Construction or repair
Property 2nd Watershed:	02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed:	02HB | Sixteen Mile Creek - Credit River
Sector Type:	NATURAL GAS DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001714770"],"wkts":["POINT (-79.7904912000 43.7009135000)"],"creation_date":"2023-10-19"}
Time Reported:	
System Facility Address:	

159 | ***4 of 4*** | ***SE/95.0*** | ***229.9 / -12.08*** | ***100 Manett Crescent Brampton ON L6X 4P7*** | ***EHS***

Order No:	23101300877	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	16-OCT-23	**Search Radius (km):**	.25
Date Received:	13-OCT-23	**X:**	-79.7904912
Previous Site Name:		**Y:**	43.7009135
Lot/Building Size:			
Additional Info Ordered:	City Directory		

160 | ***1 of 1*** | ***SE/122.4*** | ***230.0 / -11.90*** | ***MANETT CRESCENT Brampton ON*** | ***WWIS***

Well ID:	7191501	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Abandoned-Other	**Date Received:**	11/14/2012
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z160612	**Contractor:**	7241
Tag:	A128917	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:	WKQ-005420		

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191501.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/30/2012
Year Completed:	2012
Depth (m):	
Latitude:	43.7009852521262
Longitude:	-79.7901103570853
X:	-79.79011020711899
Y:	43.70098524995269
Path:	719\7191501.pdf

Bore Hole Information

Bore Hole ID:	1004203965	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	597488.00
Code OB Desc:		***North83:***	4839374.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/30/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004525155
Layer:	1
Plug From:	0.0
Plug To:	17.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004525154
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004525146
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004525150
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	

Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004525151
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1004525149
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004525148
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

161 | ***1 of 1*** | ***SE/67.9*** | ***229.9 / -12.08*** | ***MANETT CRESCENT Brampton ON*** | ***WWIS***

Well ID:	7191502	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring and Test Hole	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	11/14/2012
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z160610	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:	WKQ-005420		

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191502.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/30/2012
Year Completed:	2012
Depth (m):	
Latitude:	43.7006391655734
Longitude:	-79.7905889163821
X:	-79.79058876560059
Y:	43.7006391641677
Path:	719\7191502.pdf

Bore Hole Information

Bore Hole ID:	1004203968	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597450.00
Code OB Desc:		**North83:**	4839335.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/30/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004525165
Layer:	1
Plug From:	0.0
Plug To:	21.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004525164
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004525156
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004525160
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch

Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004525161
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1004525159
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1004525158
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

162 | ***1 of 1*** | ***SE/87.1*** | ***229.9 / -12.08*** | ***0 Manett Crescent Brampton ON*** | ***EHS***

Order No: 20171129156
Status: C
Report Type: Standard Report
Report Date: 06-DEC-17
Date Received: 29-NOV-17
Previous Site Name:
Lot/Building Size: 1.787 acres
Additional Info Ordered:

Nearest Intersection:
Municipality: Brampton
Client Prov/State: ON
Search Radius (km): .25
X: -79.790323
Y: 43.700691

---

163 | ***1 of 1*** | ***SE/28.2*** | ***229.9 / -12.08*** | ***MANETT CRESCENT Brampton ON*** | ***WWIS***

Well ID: 7191503
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z160611
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 11/14/2012
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:

Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:	WKQ-005420		

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7191503.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/30/2012
Year Completed:	2012
Depth (m):	
Latitude:	43.7003542531728
Longitude:	-79.790892494687
X:	-79.79089234489149
Y:	43.70035425119934
Path:	719\7191503.pdf

Bore Hole Information

Bore Hole ID:	1004203971	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	597426.00
Code OB Desc:		**North83:**	4839303.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/30/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004525175
Layer:	1
Plug From:	0.0
Plug To:	16.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1004525174
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004525166
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004525170
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004525171
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Water Details

Water ID:	1004525169
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1004525168
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
164	1 of 2	SE/153.5	230.9 / -11.08	LDASK MBC CORP., KORETZ ESTATES LTD. MANETT CRES./TESSLER CRES. BRAMPTON CITY ON	CA

Certificate #:	3-0498-99-
Application Year:	99
Issue Date:	5/26/1999
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
164	2 of 2	SE/153.5	230.9 / -11.08	LDASK MBC CORP., KORETZ ESTATES LTD. MANETT CRES./TESSLER CRES. BRAMPTON CITY ON	CA

Certificate #: 7-0342-99-
Application Year: 99
Issue Date: 5/26/1999
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
165	1 of 1	SE/85.7	229.9 / -12.08	ON	BORE

Borehole ID: 637357
OGF ID: 215537754
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: SEP-1968
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 4.8
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 230
Elev Reliabil Note:
DEM Ground Elev m: 231
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.699736
Longitude DD: -79.79204
UTM Zone: 17
Easting: 597335
Northing: 4839233
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218480591
Top Depth: 0
Bottom Depth: 0
Material Color:
Material 1: Soil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SOIL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218480592
Top Depth: 0
Bottom Depth: 4.8
Material Color:
Material 1: Till
Material 2: Silt
Material 3: Shale

Mat Consistency:
Material Moisture: Moist
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:

Material 4: Sand
Depositional Gen: glacial
Gsc Material Description:
Stratum Description: TILL,SILT,SHALE,SANDGLACIAL,MOIST,AGE GLACIAL. 00001100000 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type: Data Survey
Source Appl: Spatial/Tabular
Source Orig: Geological Survey of Canada
Source Iden: 1
Source Date: 1956-1972
Scale or Res: Varies
Confidence: H
Horizontal: NAD27
Observatio:
Verticalda: Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1B.txt RecordID: 053200 NTS_Sheet: 30M12F
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier: 1
Horizontal Datum: NAD27
Source Type: Data Survey
Vertical Datum: Mean Average Sea Level
Source Date: 1956-1972
Projection Name: Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

166 | **1 of 1** | **SE/199.4** | **230.9 / -11.01** | **70 Tessler Crescent, Brampton ON** | **PINC**

Incident Id: 2810436
Pipe Material:
Incident No: 653674
Fuel Category: Natural Gas
Incident Reported Dt:
Health Impact: No
Type: FS-Pipeline Incident
Environment Impact: No
Status Code: Pipeline Damage Reason Est
Property Damage: No
Tank Status: RC Established
Service Interrupt: Yes
Task No: 3466428
Enforce Policy: No
Spills Action Centre:
Public Relation: No
Fuel Type: Natural Gas
Pipeline System:
Fuel Occurrence Tp: Pipeline Strike
PSIG:
Date of Occurrence: 9/1/2011 0:00
Attribute Category: FS-Perform P-line Inc Invest
Occurrence Start Dt: 2011/10/07
Regulator Location:
Depth:
Method Details: E-mail
Customer Acct Name:
Incident Address:
Operation Type: Private Dwelling
Pipeline Type:
Regulator Type:
Summary: 70 Tessler Crescent, Brampton - 1/2" Pipeline Hit
Reported By: Blackburn, Chris - enbridge
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
Occurrence Desc: Damaged 1/2" pe ip GAS SERVICE
Damage Reason: Excavation practices not sufficient
Notes:

---

167 | **1 of 1** | **SE/103.1** | **229.9 / -12.08** | **UNKNOWN STORM SEWER AT 194 ECCLESTONE DR. BRAMPTON CITY ON L6X 3P5** | **SPL**

Ref No: 113754
Municipality No: 21101
Year:
Nature of Damage:
Incident Dt: 5/28/1995
Discharger Report:
Dt MOE Arvl on Scn:
Material Group:
MOE Reported Dt: 5/28/1995
Impact to Health:

Dt Document Closed:		**Agency Involved:**	F.D., WORKS
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER CAUSE (N.O.S.)		
Incident Preceding Spill:			
Incident Reason:	INTENTIONAL/PLANNED		
Incident Summary:	SOURCE UNKNOWN: 2 L OF AMMONIA & GASOLINE MIXT. TO STORM SEWER,F.D.,WORKS		
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Water course or lake		
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	WATER		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

168	1 of 9	SE/163.6	228.8 / -13.09	**SPECIALIST PEST CONTROL SERVICES** **106 RICHWOOD CRES.** **BRAMPTON ON L6X 4K7**	PES

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

168 | **2 of 9** | **SE/163.6** | **228.8 / -13.09** | **SPECIALIST PEST CONTROL SERVICES** | **PES**
106 RICHWOOD CRES.
BRAMPTON ON L6X 4K7

Detail Licence No:	02-01-07035-0	**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	OPERATOR	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

168 | **3 of 9** | **SE/163.6** | **228.8 / -13.09** | **8016917 CANADA INC.** | **PES**
106 RICHWOOD CRES
BRAMPTON ON L6X4K7

Detail Licence No:		**Operator Box:**	
Licence No:	09219	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	647
Licence Type:	Operator	**Oper Phone No:**	5677378
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

168 | **4 of 9** | **SE/163.6** | **228.8 / -13.09** | **8016917 CANADA INC. O/A PEST CONTROL COMPANY GTA** | **PES**
106 RICHWOOD CRES
BRAMPTON ON L6X4K7

Detail Licence No:		**Operator Box:**	
Licence No:	10071	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	647
Licence Type:	Operator	**Oper Phone No:**	5677378
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

168 | ***5 of 9*** | ***SE/163.6*** | ***228.8 / -13.09*** | ***8016917 CANADA INC.***
106 Richwood Cres
Brampton ON L6X 4K7 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-240-1036242730	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-11-10	**Operator Type:**	
Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.69805556	**Operator Region:**	
Longitude:	-79.79111111	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2191913		

---

168 | ***6 of 9*** | ***SE/163.6*** | ***228.8 / -13.09*** | ***SPECIALIST PEST CONTROL SERVICES***
106 RICHWOOD CRES.
BRAMPTON ON L6X4K7 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	06642	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	289
Licence Type:	Operator	**Oper Phone No:**	2334435
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
168	7 of 9	SE/163.6	228.8 / -13.09	8016917 CANADA INC. 106 RICHWOOD CRES BRAMPTON ON L6X4K7	PES

Detail Licence No:		Operator Box:	
Licence No:	08840	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:	Legacy Licenses (Excluding TS)	Oper Area Code:	647
Licence Type:	Operator	Oper Phone No:	5677378
Licence Type Code:	02	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
168	8 of 9	SE/163.6	228.8 / -13.09	SPECIALIST PEST CONTROL SERVICES 106 RICHWOOD CRES. BRAMPTON ON L6X4K7	PES

Detail Licence No:		Operator Box:	
Licence No:	07035	Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:	Legacy Licenses (Excluding TS)	Oper Area Code:	289
Licence Type:	Operator	Oper Phone No:	2334435
Licence Type Code:	02	Operator Ext:	
Licence Class:	01	Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
168	9 of 9	SE/163.6	228.8 / -13.09	8016917 CANADA INC. 106 Richwood Cres Brampton ON L6X 4K7	PES

Detail Licence No:		Operator Box:	
Licence No:	L-240-1036242730	Operator Class:	
Status:	Active	Operator No:	
Approval Date:	2020-12-17	Operator Type:	
Report Source:	PEST-Operator	Oper Area Code:	
Licence Type:	Operator	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:	43.69805556	Operator Region:	
Longitude:	-79.79111111	Operator District:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Lot: **Operator County:**
Concession: **Op Municipality:**
Region: **Post Office Box:**
District: **MOE District:** Halton-Peel
County: **SWP Area Name:** Credit Valley
Trade Name:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2318480

---

169 **1 of 2** **SE/8.8** **229.9 / -12.08** **The Regional Municipality of Peel**
Bovaird Road (95m east of Sunforest Drive to 200m west of McLaughlin Road)
Brampton ON **ECA**

Approval No: 5124-6BCMR9 **MOE District:** Halton-Peel
Approval Date: 2005-04-12 **City:**
Status: Approved **Longitude:** -79.7894
Record Type: ECA **Latitude:** 43.6988
Link Source: IDS **Geometry X:**
SWP Area Name: Credit Valley **Geometry Y:**
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Peel
Address: Bovaird Road (95m east of Sunforest Drive to 200m west of McLaughlin Road)
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7622-6B6VJE-14.pdf
PDF Site Location:

---

169 **2 of 2** **SE/8.8** **229.9 / -12.08** **The Regional Municipality of Peel**
Bovaird Drive
Brampton ON L6T 4B9 **ECA**

Approval No: 3975-6HSJVU **MOE District:** Halton-Peel
Approval Date: 2005-11-07 **City:**
Status: Approved **Longitude:** -79.7894
Record Type: ECA **Latitude:** 43.6988
Link Source: IDS **Geometry X:**
SWP Area Name: Credit Valley **Geometry Y:**
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Peel
Address: Bovaird Drive
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3441-6GTRZJ-14.pdf
PDF Site Location:

---

170 **1 of 1** **SE/236.8** **228.8 / -13.12**
ON **BORE**

Borehole ID: 637359 **Inclin FLG:** No
OGF ID: 215537756 **SP Status:** Initial Entry
Status: **Surv Elev:** No
Type: Borehole **Piezometer:** No
Use: Geotechnical/Geological Investigation **Primary Name:**
Completion Date: APR-1968 **Municipality:**
Static Water Level: **Lot:**
Primary Water Use: Not Used **Township:**
Sec. Water Use: **Latitude DD:** 43.697662
Total Depth m: 6.4 **Longitude DD:** -79.791833
Depth Ref: Ground Surface **UTM Zone:** 17
Depth Elev: **Easting:** 597355

Drill Method:	Power auger	**Northing:**	4839003
Orig Ground Elev m:	230	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	228		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218480596	**Mat Consistency:**	
Top Depth:	3	**Material Moisture:**	Wet
Bottom Depth:	4.9	**Material Texture:**	Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM,SILT. BROWN,GREY,FLUVIO-GLACIAL,WET,AGE GLACIAL.		

Geology Stratum ID:	218480597	**Mat Consistency:**	
Top Depth:	4.9	**Material Moisture:**	Moist
Bottom Depth:	6.4	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Shale	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SHALE. RED,GLACIAL,MOIST,AGE GLACIAL.00000040001000580016009 2 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218480595	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	Moist
Bottom Depth:	3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.BROWN,GLACIAL,MOIST, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 053220 NTS_Sheet: 30M12F		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Source Originators:		Geological Survey of Canada			

171 1 of 4 SE/169.4 230.9 / -11.08 GREENLAND VIEW LANDSCAPING 48 HORSHAM STREET BRAMPTON ON L6X 3R2 PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type:
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

171 2 of 4 SE/169.4 230.9 / -11.08 GREENLAND VIEW LANDSCAPING 48 HORSHAM ST BRAMPTON ON L6X 3R2 PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code: 02
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

171 3 of 4 SE/169.4 230.9 / -11.08 GREENLAND VIEW LANDSCAPING 48 HORSHAM ST BRAMPTON ON L6X3R2 PES

Detail Licence No:
Licence No: 04284
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Operator
Licence Type Code: 01
Licence Class: 06
Licence Control:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 905
Oper Phone No: 4529720
Operator Ext:
Operator Lot:
Oper Concession:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

171 | ***4 of 4*** | ***SE/169.4*** | ***230.9 / -11.08*** | ***GREENLAND VIEW LANDSCAPING***
48 HORSHAM ST
BRAMPTON ON L6X3R2 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	04284	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Operator	**Oper Phone No:**	4529720
Licence Type Code:	02	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

172 | ***1 of 1*** | ***WNW/165.9*** | ***257.9 / 15.92*** | ***lot 19 con 1***
ON | ***WWIS***

Well ID:	4904556	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	01/24/1975
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	3513
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	019
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4904556.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/15/1974
Year Completed:	1974
Depth (m):	36.576
Latitude:	43.7335675499967
Longitude:	-79.8446680269308
X:	-79.8446678771081
Y:	43.73356754845458
Path:	490\4904556.pdf

Bore Hole Information

Bore Hole ID:	10319338	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	593041.50
Code OB Desc:		**North83:**	4842930.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	4
Date Completed:	05/15/1974	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	p4

Location Method Desc:	Original Pre1985 UTM Rel Code 4: margin of error : 30 m - 100 m
Elevrc Desc:	
Location Source Date:	
Improvement Location Source:	
Improvement Location Method:	
Source Revision Comment:	
Supplier Comment:	

Overburden and Bedrock Materials Interval

Formation ID:	932046211
Layer:	6
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	88.0
Formation End Depth:	120.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932046210
Layer:	5
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	63.0
Formation End Depth:	88.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932046207
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932046208
Layer:	3
Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	20.0
Formation End Depth:	42.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932046209
Layer:	4
Color:	7
General Color:	RED
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	42.0
Formation End Depth:	63.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932046206
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	

Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964904556
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10867908
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930527187
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 90.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930527188
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 120.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: BAILER
Pump Test ID: 994904556
Pump Set At:
Static Level: 5.0
Final Level After Pumping: 40.0
Recommended Pump Depth: 100.0
Pumping Rate: 7.0
Flowing Rate:
Recommended Pump Rate: 6.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 2
Pumping Duration HR: 2
Pumping Duration MIN: 0

Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934259169
Test Type: Recovery
Test Duration: 15
Test Level: 20.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934533701
Test Type: Recovery
Test Duration: 30
Test Level: 10.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934787827
Test Type: Recovery
Test Duration: 45
Test Level: 5.0
Test Level UOM: ft

Water Details

Water ID: 933792589
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 63.0
Water Found Depth UOM: ft

Water Details

Water ID: 933792590
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 110.0
Water Found Depth UOM: ft

---

173 ***1 of 4*** ***SE/183.4*** ***227.6 / -14.33*** ***Supreme Pest Control Corporation***
12 RICHWOOD CRES
BRAMPTON ON L6X 4K9 ***PES***

Detail Licence No:
Licence No: L-240-8239970261
Status: Active
Approval Date: August 24, 2023
Report Source: PEST-Operator
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude: 43.69722222
Longitude: -79.79027778
Lot:
Concession:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Region: **Post Office Box:**
District: **MOE District:** Halton-Peel
County: **SWP Area Name:** Credit Valley
Trade Name:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3076143

---

173 **2 of 4** **SE/183.4** **227.6 / -14.33** **Supreme Pest Control Corporation** **PES**
12 RICHWOOD CRES
BRAMPTON ON L6X 4K9

Detail Licence No:
Licence No: L-240-4261822158
Status: Active
Approval Date: January 4, 2024
Report Source: PEST-Operator
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude: 43.69722222
Longitude: -79.79027778
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3252711

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District: Halton-Peel
SWP Area Name: Credit Valley

---

173 **3 of 4** **SE/183.4** **227.6 / -14.33** **Supreme Pest Control Corporation** **PES**
12 RICHWOOD CRES
BRAMPTON ON L6X 4K9

Detail Licence No:
Licence No: L-240-4261822158
Status: Active
Approval Date: September 5, 2024
Report Source: PEST-Operator
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude: 43.69722222
Longitude: -79.79027778
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3653031

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District: Halton-Peel
SWP Area Name: Credit Valley

---

173 **4 of 4** **SE/183.4** **227.6 / -14.33** **Supreme Pest Control Corporation** **PES**
12 RICHWOOD CRES
BRAMPTON ON L6X 4K9

Detail Licence No:
Licence No: L-240-4261822158
Status: Active
Approval Date: December 30, 2024

Operator Box:
Operator Class:
Operator No:
Operator Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Source:	PEST-Operator	**Oper Area Code:**	
Licence Type:	Operator	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.69722222	**Operator Region:**	
Longitude:	-79.79027778	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Credit Valley
Trade Name:			
PDF URL:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3825472		

---

174 | ***1 of 1*** | ***SE/189.0*** | ***229.9 / -12.03*** | ***PAKISTANI ELECTR & PRINT MEDIA***
17 BURNHOPE DR
BRAMPTON ON L6X 3R9 | ***SCT***

Established:	1982
Plant Size (ft²):	900
Employment:	3

--Details--

Description:	NEWSPAPERS: PUBLISHING, OR PUBLISHING AND PRINTING
SIC/NAICS Code:	2711

---

175 | ***1 of 1*** | ***WNW/18.9*** | ***258.9 / 16.92*** | ***12461 Mclaughlin Rd***
Caledon ON L7C2A8 | ***EHS***

Order No:	20161213120	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	15-DEC-16	**Search Radius (km):**	.25
Date Received:	13-DEC-16	**X:**	-79.84472
Previous Site Name:		**Y:**	43.735381
Lot/Building Size:			
Additional Info Ordered:			

---

176 | ***1 of 1*** | ***WNW/11.6*** | ***258.9 / 16.92*** | ***12461 McLaughlin Road***
Kleinburg ON L7C 2A8 | ***EHS***

Order No:	20180809112	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	16-AUG-18	**Search Radius (km):**	.25
Date Received:	09-AUG-18	**X:**	-79.844802
Previous Site Name:		**Y:**	43.735335
Lot/Building Size:			
Additional Info Ordered:			

---

177 | ***1 of 1*** | ***SE/59.9*** | ***225.9 / -16.06*** | ***ON*** | ***BORE***

Borehole ID:	637361	**Inclin FLG:**	No
OGF ID:	215537758	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No

Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	APR-1968	***Municipality:***	
Static Water Level:	0.2	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.697264
Total Depth m:	4.7	***Longitude DD:***	-79.78818
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	597650
Drill Method:	Power auger	***Northing:***	4838963
Orig Ground Elev m:	227	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	227		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218480600	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Soil	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SOIL.		

Geology Stratum ID:	218480602	***Mat Consistency:***	Dense
Top Depth:	1.5	***Material Moisture:***	
Bottom Depth:	4.7	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Clay	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.BROWN,GLACIAL,VERY DENSE, AGE GLACIAL. 000090080005005600001 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218480601	***Mat Consistency:***	
Top Depth:	.3	***Material Moisture:***	Wet
Bottom Depth:	1.5	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY. BROWN,GLACIAL,WET,AGE GLACIAL,WATER STABLE AT 745.3 FEET.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 053240 NTS_Sheet: 30M12F		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
178	1 of 1	WNW/238.5	258.9 / 16.94	***The Everlast Group*** ***12461 Mclaughlin Road*** ***Caledon ON***	GEN

Generator Info

Generator No:	ON8868707	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	532310
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	General Rental Centres		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
179	1 of 1	WNW/158.8	256.4 / 14.50	***ON***	WWIS

Well ID:	7308412	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	03/22/2018
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	C41560	***Contractor:***	7230
Tag:	A229363	***Form Version:***	8
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1007009197	***Tag No:***	A229363
Depth M:		***Contractor:***	7230
Year Completed:	2017	***Latitude:***	43.7373194120286
Well Completed Dt:	07/14/2017	***Longitude:***	-79.8461791880969
Audit No:	C41560	***Y:***	43.73731941055591
Path:		***X:***	-79.84617903753268

Bore Hole Information

Bore Hole ID:	1007009197	***Elevation:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592914.00
Code OB Desc:		**North83:**	4843345.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	07/14/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

180 **1 of 1** **WNW/181.0** **260.6 / 18.67** **lot 20 con 1 ON** **WWIS**

Well ID:	4904291	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	02/08/1974
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	3513
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	020
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4904291.pdf

Additional Detail(s) (Map)

Well Completed Date:	12/15/1973
Year Completed:	1973
Depth (m):	37.4904
Latitude:	43.7354264432661
Longitude:	-79.8495372720439
X:	-79.84953712152382
Y:	43.73542644118363
Path:	490\4904291.pdf

Bore Hole Information

Bore Hole ID:	10319079	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592646.50
Code OB Desc:		**North83:**	4843131.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	6
Date Completed:	12/15/1973	**UTMRC Desc:**	margin of error : 300 m - 1 km

Remarks: ***Location Method:*** p6
Location Method Desc: Original Pre1985 UTM Rel Code 6: margin of error : 300 m - 1 km
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932045154
Layer: 5
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 78.0
Formation End Depth: 123.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932045151
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 2.0
Formation End Depth: 28.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932045150
Layer: 1
Color: 6
General Color: BROWN
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932045152
Layer: 3
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 28.0
Formation End Depth: 55.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932045153
Layer: 4
Color: 3
General Color: BLUE
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 55.0
Formation End Depth: 78.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964904291
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10867649
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930526845
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 82.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930526846

Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	123.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	BAILER
Pump Test ID:	994904291
Pump Set At:	
Static Level:	20.0
Final Level After Pumping:	120.0
Recommended Pump Depth:	120.0
Pumping Rate:	1.0
Flowing Rate:	
Recommended Pump Rate:	1.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	2
Pumping Duration HR:	4
Pumping Duration MIN:	0
Flowing:	No

Draw Down & Recovery

Pump Test Detail ID:	934258560
Test Type:	Recovery
Test Duration:	15
Test Level:	85.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934787223
Test Type:	Recovery
Test Duration:	45
Test Level:	45.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934533092
Test Type:	Recovery
Test Duration:	30
Test Level:	60.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	935043393
Test Type:	Recovery
Test Duration:	60
Test Level:	30.0
Test Level UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water Details

Water ID:	933792317
Layer:	1
Kind Code:	5
Kind:	Not stated
Water Found Depth:	65.0
Water Found Depth UOM:	ft

Water Details

Water ID:	933792318
Layer:	2
Kind Code:	1
Kind:	FRESH
Water Found Depth:	120.0
Water Found Depth UOM:	ft

---

181 | ***1 of 1*** | ***WNW/194.2*** | ***261.2 / 19.29*** | ***lot 21 con 1 ON*** | ***WWIS***

Well ID:	4901624	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	12/22/1964
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	1325
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	021
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901624.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/15/1964
Year Completed:	1964
Depth (m):	16.4592
Latitude:	43.7366340780329
Longitude:	-79.8514389293184
X:	-79.85143877880816
Y:	43.736634076610805
Path:	490\4901624.pdf

Bore Hole Information

Bore Hole ID:	10316469	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592491.50
Code OB Desc:		***North83:***	4843263.00

Open Hole: ***Org CS:***
Cluster Kind: ***UTMRC:*** 5
Date Completed: 10/15/1964 ***UTMRC Desc:*** margin of error : 100 m - 300 m
Remarks: ***Location Method:*** p5
Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932035027
Layer: 3
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 29.0
Formation End Depth: 53.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035026
Layer: 2
Color: 6
General Color: BROWN
Material 1: 14
Material 1 Desc: HARDPAN
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 1.0
Formation End Depth: 29.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035028
Layer: 4
Color:
General Color:
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 53.0
Formation End Depth: 54.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	932035025
Layer:	1
Color:	
General Color:	
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901624
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10865039
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523109
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	54.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901624
Pump Set At:	
Static Level:	30.0
Final Level After Pumping:	50.0
Recommended Pump Depth:	52.0
Pumping Rate:	2.0
Flowing Rate:	
Recommended Pump Rate:	1.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	0
Pumping Duration MIN:	30

Flowing: No

Water Details

Water ID: 933789575
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 53.0
Water Found Depth UOM: ft

---

182 | **1 of 1** | **SE/66.4** | **221.8 / -20.12** | **Moore Street & Burton Road lot 9 con 1 Brampton ON** | **WWIS**

Well ID: 7378803
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: PNE9SXEL
Tag: A308491
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 01/25/2021
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7472
Form Version: 9
Owner:
County: PEEL
Lot: 009
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378803.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/24/2020
Year Completed: 2020
Depth (m): 7.62
Latitude: 43.6940969013261
Longitude: -79.7815997002165
X: -79.78159954988216
Y: 43.694096898801995
Path: 737\7378803.pdf

Bore Hole Information

Bore Hole ID: 1008556264
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/24/2020
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:

Elevation:
Elevrc:
Zone: 17
East83: 598185.00
North83: 4838619.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008556354
Layer: 2
Color:
General Color:
Material 1: 26
Material 1 Desc: ROCK
Material 2:
Material 2 Desc:
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 20.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008556353
Layer: 1
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008556444
Layer: 1
Plug From: 0.0
Plug To: 14.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008556445
Layer: 2
Plug From: 14.0
Plug To: 25.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008556416
Layer: 1

Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008556311
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008556295
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008556369
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 15.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008556384
Layer: 1
Slot: 10
Screen Top Depth: 15.0
Screen End Depth: 25.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008556296
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1008556401
Diameter:	7.5
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

183 ***1 of 1*** ***SE/190.2*** ***220.9 / -21.08*** ***ALECTRA UTILITIES CORPORATION***
107 Saddletree trail
ON ***SPL***

Ref No:	1-1V54OE	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	6/27/2022 3:00:00 PM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	6/27/2022 5:40:16 PM	***Impact to Health:***	0 No Impact
Dt Document Closed:	7/15/2022 9:05:05 AM	***Agency Involved:***	

Site No:	
MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	
Site Address:	107 Saddletree trail
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	ALECTRA UTILITIES CORPORATION
Client Type:	Private Business
Source Type:	
Incident Cause:	
Incident Preceding Spill:	Explosion
Incident Reason:	
Incident Summary:	Alectra Utilities; Transformer Explosion 20L: non PCB; Complete
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	20 litre (L)
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	COMPRESSOR OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	Normal operations
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	
Sector Type:	ELECTRIC POWER DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001951587"],"wkts":["POINT (-79.7840430000 43.6925765000)"],"creation_date":"2022-06-27"}
Time Reported:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
System Facility Address:					

184 1 of 1 SE/15.5 220.8 / -21.11 Williams Parkway Brampton ON EHS

Order No:	20150401097	Nearest Intersection:	
Status:	C	Municipality:	
Report Type:	Custom Report	Client Prov/State:	ON
Report Date:	17-JUL-15	Search Radius (km):	.25
Date Received:	01-APR-15	X:	-79.7817
Previous Site Name:		Y:	43.693448
Lot/Building Size:			
Additional Info Ordered:			

185 1 of 1 SE/27.2 220.9 / -21.08 ON WWIS

Well ID:	7312145	Flowing (Y/N):	
Construction Date:		Flow Rate:	
Use 1st:		Data Entry Status:	Yes
Use 2nd:		Data Src:	
Final Well Status:		Date Received:	06/07/2018
Water Type:		Selected Flag:	TRUE
Casing Material:		Abandonment Rec:	
Audit No:	C36871	Contractor:	7464
Tag:	A238334	Form Version:	8
Constructn Method:		Owner:	
Elevation (m):		County:	PEEL
Elevatn Reliabilty:		Lot:	
Depth to Bedrock:		Concession:	
Well Depth:		Concession Name:	
Overburden/Bedrock:		Easting NAD83:	
Pump Rate:		Northing NAD83:	
Static Water Level:		Zone:	
Clear/Cloudy:		UTM Reliability:	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1007086634	Tag No:	A238334
Depth M:		Contractor:	7464
Year Completed:	2018	Latitude:	43.6934465120293
Well Completed Dt:	02/27/2018	Longitude:	-79.7814019165374
Audit No:	C36871	Y:	43.69344651004344
Path:		X:	-79.7814017670288

Bore Hole Information

Bore Hole ID:	1007086634	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	598202.00
Code OB Desc:		North83:	4838547.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	02/27/2018	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

---

186 | ***1 of 1*** | ***SE/41.3*** | ***220.9 / -21.08*** | ***WILLIAMS PARKWAY BRAMPTON ON*** | ***WWIS***

Well ID:	7312128	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	06/07/2018
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z277208	***Contractor:***	7472
Tag:	A242002	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/731\7312128.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/26/2018
Year Completed:	2018
Depth (m):	7.62
Latitude:	43.693525809867
Longitude:	-79.7812389933
X:	-79.78123884322373
Y:	43.69352580832395
Path:	731\7312128.pdf

Bore Hole Information

Bore Hole ID:	1007086537	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	598215.00
Code OB Desc:		***North83:***	4838556.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/26/2018	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1007174406
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007174407
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	28
Material 3 Desc:	SAND
Formation Top Depth:	1.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007174415
Layer:	2
Plug From:	14.0
Plug To:	25.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007174414
Layer:	1
Plug From:	0.0
Plug To:	14.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1007174413
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007174405

Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007174410
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	15.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1007174411
Layer:	1
Slot:	10
Screen Top Depth:	15.0
Screen End Depth:	25.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Water Details

Water ID:	1007174409
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007174408
Diameter:	6.0
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

187 | ***1 of 1*** | ***WNW/184.2*** | ***259.0 / 17.06*** | ***lot 21 con 2 ON*** | ***WWIS***

Well ID:	4901721	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	08/24/1964
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	4813
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	021
Depth to Bedrock:		**Concession:**	02

Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901721.pdf

Additional Detail(s) (Map)

Well Completed Date:	06/03/1964
Year Completed:	1964
Depth (m):	22.86
Latitude:	43.7376092767755
Longitude:	-79.8526124282947
X:	-79.85261227814546
Y:	43.7376092755757
Path:	490\4901721.pdf

Bore Hole Information

Bore Hole ID:	10316566	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592395.50
Code OB Desc:		**North83:**	4843370.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	06/03/1964	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932035376
Layer:	3
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	30.0
Formation End Depth:	75.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035374
Layer:	1

Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	09
Material 2 Desc:	MEDIUM SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035375
Layer:	2
Color:	
General Color:	
Material 1:	09
Material 1 Desc:	MEDIUM SAND
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	10.0
Formation End Depth:	30.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901721
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10865136
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523262
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	55.0
Casing Diameter:	7.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930523263
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE

Depth From:	
Depth To:	75.0
Casing Diameter:	7.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901721
Pump Set At:	
Static Level:	12.0
Final Level After Pumping:	70.0
Recommended Pump Depth:	70.0
Pumping Rate:	2.0
Flowing Rate:	
Recommended Pump Rate:	2.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	4
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933789672
Layer:	1
Kind Code:	2
Kind:	SALTY
Water Found Depth:	55.0
Water Found Depth UOM:	ft

---

188 | ***1 of 1*** | ***WNW/195.4*** | ***259.2 / 17.24*** | ***lot 21 con 1 ON*** | ***WWIS***

Well ID:	4901621	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Livestock	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	11/18/1959
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	1325
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	021
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901621.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/10/1959
Year Completed: 1959
Depth (m): 6.096
Latitude: 43.7375838907632
Longitude: -79.852774348898
X: -79.85277419852784
Y: 43.73758388949238
Path: 490\4901621.pdf

Bore Hole Information

Bore Hole ID: 10316466
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/10/1959
Remarks:
Elevation:
Elevrc:
Zone: 17
East83: 592382.50
North83: 4843367.00
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5
Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932035015
Layer: 2
Color: 6
General Color: BROWN
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 2.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035014
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 09
Material 2 Desc: MEDIUM SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964901621
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10865036
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930523105
Layer: 1
Material: 3
Open Hole or Material: CONCRETE
Depth From:
Depth To: 20.0
Casing Diameter: 30.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 994901621
Pump Set At:
Static Level: 12.0
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Water Details

Water ID: 933789571
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 12.0
Water Found Depth UOM: ft

189	1 of 1	SE/73.7	221.4 / -20.54	Moore Street & Burton Road lot 8 con 1 Brampton ON	WWIS

Well ID: 7380773
Construction Date:
Flowing (Y/N):
Flow Rate:

Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	02/22/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	UVT5BYIU	**Contractor:**	7472
Tag:	A315082	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	008
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/738\7380773.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/27/2021
Year Completed: 2021
Depth (m): 9.144
Latitude: 43.6936000785135
Longitude: -79.7806046280101
X: -79.7806044783182
Y: 43.69360007723228
Path: 738\7380773.pdf

Bore Hole Information

Bore Hole ID:	1008573800	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	598266.00
Code OB Desc:		**North83:**	4838565.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/27/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008573889
Layer: 2
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:
Material 3: 77

Material 3 Desc:	LOOSE
Formation Top Depth:	2.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008573891
Layer:	4
Color:	
General Color:	
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	25.0
Formation End Depth:	30.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008573890
Layer:	3
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	10.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008573888
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	
Material 1 Desc:	
Material 2:	
Material 2 Desc:	
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008573982
Layer:	2
Plug From:	19.0

Plug To: 30.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008573981
Layer: 1
Plug From: 0.0
Plug To: 19.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008573953
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008573849
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008573832
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008573908
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 20.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008573923
Layer: 1
Slot: 10
Screen Top Depth: 20.0
Screen End Depth: 30.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008573833
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008573938
Diameter:	7.5
Depth From:	0.0
Depth To:	30.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

190 | ***1 of 1*** | ***WNW/200.4*** | ***260.9 / 18.93*** | ***Old School Rd And Mclaughlin Rd Caledon ON*** | ***EHS***

Order No:	20140808014	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	14-AUG-14	***Search Radius (km):***	.25
Date Received:	08-AUG-14	***X:***	-79.850367
Previous Site Name:		***Y:***	43.740875
Lot/Building Size:			
Additional Info Ordered:			

---

191 | ***1 of 1*** | ***SE/183.2*** | ***222.5 / -19.43*** | ***Moore Street & Burton Road lot 8 con 1 Brampton ON*** | ***WWIS***

Well ID:	7378802	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	01/25/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	347WJVZA	***Contractor:***	7472
Tag:	A308427	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	008
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	

Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378802.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/24/2020
Year Completed: 2020
Depth (m): 4.572
Latitude: 43.6941984375071
Longitude: -79.7793019490964
X: -79.77930179934654
Y: 43.69419843617175
Path: 737\7378802.pdf

Bore Hole Information

Bore Hole ID: 1008556261
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/24/2020
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 598370.00
North83: 4838633.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008556352
Layer: 1
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008556442
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1008556415
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008556443
Layer:	2
Plug From:	9.0
Plug To:	15.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1008556310
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1008556293
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008556368
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008556383
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	15.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008556294
Pump Set At:	

Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1008556400
Diameter: 7.5
Depth From: 0.0
Depth To: 15.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

192 | ***1 of 1*** | ***SE/29.4*** | ***219.8 / -22.10*** | ***Mirage Digital Printing 144 Martindale Cres Brampton ON L6X 2V2*** | ***SCT***

Established: 2006
Plant Size (ft²):
Employment:

--Details--
Description: Sporting and Athletic Goods Manufacturing
SIC/NAICS Code: 339920

---

193 | ***1 of 1*** | ***WNW/5.5*** | ***258.8 / 16.86*** | ***OLD SCHOOL ROAD lot 21 con 1 BRAMPTON ON*** | ***WWIS***

Well ID:	7300314	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	12/04/2017
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z239549	***Contractor:***	7360
Tag:	A231665	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	021
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/730\7300314.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/14/2017
Year Completed:	2017
Depth (m):	7.62
Latitude:	43.7398945048056
Longitude:	-79.8524383880675
X:	-79.85243823749423
Y:	43.73989450343876
Path:	730\7300314.pdf

Bore Hole Information

Bore Hole ID:	1006842719	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592406.00
Code OB Desc:		***North83:***	4843624.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	11/14/2017	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007028306
Layer:	3
Color:	7
General Color:	RED
Material 1:	34
Material 1 Desc:	TILL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	20.0
Formation End Depth:	25.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007028305
Layer:	2
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	5.0
Formation End Depth:	20.0

Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007028304
Layer: 1
Color: 6
General Color: BROWN
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007028313
Layer: 1
Plug From: 10.0
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007028312
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1007028303
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007028309
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 12.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007028310
Layer: 1
Slot: .10
Screen Top Depth: 12.0

Screen End Depth:	17.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1007028308
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	12.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007028307
Diameter:	6.0
Depth From:	0.0
Depth To:	25.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

194 | ***1 of 1*** | ***SE/43.5*** | ***220.9 / -21.08*** | ***The Regional Municipality of Peel***
69 Moore Street
Brampton ON | ***SPL***

Ref No:	6747-BLCR3N	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2020/01/31	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2020/01/31	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2020/04/15	**Agency Involved:**	

Site No:	NA
MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	Fletchers Creek
Site Name:	Fletcher's Creek outfall<UNOFFICIAL>
Site Address:	69 Moore Street
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4838489
Easting:	598333
Entity Operating Name:	
Client Name:	The Regional Municipality of Peel
Client Type:	Municipal Government
Source Type:	Water Supply
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Equipment Failure
Incident Summary:	RofPeel: 6" WMB, sediment to Fletcher's Creek
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
Contaminant Qty 1:	0

Contaminant Unit:	other - see incident description
Contaminant Code:	41
Contaminant Name:	WATER/SEDIMENT
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

195 **1 of 1** **SE/150.6** **221.9 / -20.08** **Moore Street & Burton Road lot 8 con 1 Brampton ON** **WWIS**

Well ID:	7378801	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	01/25/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	OVPY29XW	**Contractor:**	7472
Tag:	A308333	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	008
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7378801.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/24/2020
Year Completed:	2020
Depth (m):	5.1816
Latitude:	43.6934956110665
Longitude:	-79.7784103489324
X:	-79.77841019931574
Y:	43.69349560929097
Path:	737\7378801.pdf

Bore Hole Information

Bore Hole ID:	1008556258	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	598443.00
Code OB Desc:		**North83:**	4838556.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4

Date Completed: 11/24/2020
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1008556351
Layer: 1
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 17.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008556414
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008556441
Layer: 2
Plug From: 11.0
Plug To: 17.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008556440
Layer: 1
Plug From: 0.0
Plug To: 11.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008556309
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID:	1008556291
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008556367
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	12.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008556382
Layer:	1
Slot:	10
Screen Top Depth:	12.0
Screen End Depth:	17.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008556292
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008556399
Diameter:	7.5
Depth From:	0.0
Depth To:	17.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
196	1 of 1	WNW/212.0	259.9 / 17.92	lot 21 con 2 ON	WWIS

Well ID: 4901723
Construction Date:
Use 1st: Domestic
Use 2nd: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 08/16/1966
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1325
Form Version: 1
Owner:
County: PEEL
Lot: 021
Concession: 02
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901723.pdf

Additional Detail(s) (Map)

Well Completed Date: 06/07/1966
Year Completed: 1966
Depth (m): 9.144
Latitude: 43.7385181734777
Longitude: -79.8543584732613
X: -79.8543583230444
Y: 43.73851817149435
Path: 490\4901723.pdf

Bore Hole Information

Bore Hole ID: 10316568
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/07/1966
Remarks:
Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 592253.50
North83: 4843469.00
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 932035384
Layer: 4
Color:
General Color:

Material 1: 06
Material 1 Desc: SILT
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 29.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035383
Layer: 3
Color:
General Color:
Material 1: 14
Material 1 Desc: HARDPAN
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 25.0
Formation End Depth: 29.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035381
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035382
Layer: 2
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Method of Construction & Well

Use

Method Construction ID: 964901723
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10865138
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930523265
Layer: 1
Material: 3
Open Hole or Material: CONCRETE
Depth From:
Depth To: 30.0
Casing Diameter: 30.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 994901723
Pump Set At:
Static Level: 8.0
Final Level After Pumping: 20.0
Recommended Pump Depth: 20.0
Pumping Rate: 2.0
Flowing Rate:
Recommended Pump Rate: 1.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933789674
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 30.0
Water Found Depth UOM: ft

197	1 of 1	WNW/204.7	259.9 / 17.92	lot 21 con 1 ON	WWIS

Well ID: 4901623
Construction Date:
Use 1st: Domestic
Use 2nd: 0
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1

Final Well Status:	Water Supply	**Date Received:**	09/29/1964
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1309
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	021
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901623.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/08/1964
Year Completed: 1964
Depth (m): 21.0312
Latitude: 43.7386538275784
Longitude: -79.8544179782543
X: -79.85441782831602
Y: 43.73865382611827
Path: 490\4901623.pdf

Bore Hole Information

Bore Hole ID:	10316468	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592248.50
Code OB Desc:		**North83:**	4843484.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	09/08/1964	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932035019
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 1.0

Formation End Depth: 16.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035022
Layer: 5
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 11
Material 3 Desc: GRAVEL
Formation Top Depth: 37.0
Formation End Depth: 49.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035023
Layer: 6
Color:
General Color:
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 17
Material 2 Desc: SHALE
Material 3:
Material 3 Desc:
Formation Top Depth: 49.0
Formation End Depth: 52.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035021
Layer: 4
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 26.0
Formation End Depth: 37.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035018
Layer: 1
Color: 8
General Color: BLACK
Material 1: 02

Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 1.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035020
Layer: 3
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3:
Material 3 Desc:
Formation Top Depth: 16.0
Formation End Depth: 26.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035024
Layer: 7
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 52.0
Formation End Depth: 69.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964901623
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10865038
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930523108
Layer: 2

Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	69.0
Casing Diameter:	7.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930523107
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	55.0
Casing Diameter:	7.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901623
Pump Set At:	
Static Level:	19.0
Final Level After Pumping:	55.0
Recommended Pump Depth:	65.0
Pumping Rate:	1.0
Flowing Rate:	
Recommended Pump Rate:	1.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	26
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933789573
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	22.0
Water Found Depth UOM:	ft

Water Details

Water ID:	933789574
Layer:	2
Kind Code:	2
Kind:	SALTY
Water Found Depth:	65.0
Water Found Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
198	1 of 1	SE/68.7	220.7 / -21.25	Moore Street & Burton Road lot 8 con 1 Brampton ON	WWIS

Well ID: 7380774 **Flowing (Y/N):**

Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	02/22/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	MG6IR3JX	**Contractor:**	7472
Tag:	A315026	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	008
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/738\7380774.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/27/2021
Year Completed: 2021
Depth (m): 4.572
Latitude: 43.6925198202938
Longitude: -79.7780951204225
X: -79.77809496989025
Y: 43.69251981821586
Path: 738\7380774.pdf

Bore Hole Information

Bore Hole ID:	1008573803	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	598470.00
Code OB Desc:		**North83:**	4838448.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/27/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008573892
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:

Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 0.0
Formation End Depth: 2.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008573894
Layer: 3
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2: 06
Material 2 Desc: SILT
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 10.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008573893
Layer: 2
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 2.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008573983
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008573954
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008573984

Layer: 2
Plug From: 9.0
Plug To: 15.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008573850
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008573834
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008573909
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008573924
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 15.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008573835
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:

Flowing:

Hole Diameter

Hole ID: 1008573939
Diameter: 7.5
Depth From: 0.0
Depth To: 15.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

199 | ***1 of 1*** | ***SE/37.0*** | ***219.9 / -22.08*** | ***45 Moore St, Brampton BRAMPTON ON*** | ***SPL***

Ref No: 1-1NU6Q5
Year:
Incident Dt: 3/8/2022 10:09:00 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/8/2022 6:11:50 PM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 45 Moore St, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type: Pipeline/Components
Incident Cause:
Incident Preceding Spill:
Incident Reason:
Incident Summary: TSSA FSB: Enbridge line strike - 1/2in plastic intermediate service
Environment Impact: 0 No Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill: Construction or repair
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HC-Humber - Don
Sector Type:
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001743857"],"wkts":["POINT (-79.7781198000 43.6922192000)"],"creation_date":"2022-03-08"}
Time Reported:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
System Facility Address:					

200 1 of 1 WNW/200.8 260.9 / 18.92 lot 21 con 1 ON WWIS

Well ID:	4901622	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	11/18/1959
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1325
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	021
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901622.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/26/1959
Year Completed:	1959
Depth (m):	7.9248
Latitude:	43.7397122532016
Longitude:	-79.855813513429
X:	-79.85581336326563
Y:	43.73971225138387
Path:	490\4901622.pdf

Bore Hole Information

Bore Hole ID:	10316467	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592134.50
Code OB Desc:		**North83:**	4843600.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	09/26/1959	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	932035017
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	09
Material 1 Desc:	MEDIUM SAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	3.0
Formation End Depth:	26.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035016
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	09
Material 2 Desc:	MEDIUM SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	3.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901622
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10865037
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523106
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	26.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	994901622

Pump Set At:	
Static Level:	15.0
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

Water Details

Water ID:	933789572
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	15.0
Water Found Depth UOM:	ft

---

201 ***1 of 1*** ***WNW/209.2*** ***260.9 / 18.92*** ***lot 21 con 2 ON*** ***WWIS***

Well ID:	4901722	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	12/02/1964
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1307
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	021
Depth to Bedrock:		**Concession:**	02
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901722.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/19/1964
Year Completed:	1964
Depth (m):	11.8872
Latitude:	43.7396954919589
Longitude:	-79.8559380184094
X:	-79.85593786792927
Y:	43.7396954903966
Path:	490\4901722.pdf

Bore Hole Information

Bore Hole ID:	10316567	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592124.50
Code OB Desc:		***North83:***	4843598.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	11/19/1964	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932035379
Layer: 3
Color: 7
General Color: RED
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 27.0
Formation End Depth: 38.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035377
Layer: 1
Color: 6
General Color: BROWN
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2: 05
Material 2 Desc: CLAY
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035380
Layer: 4
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:

Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 38.0
Formation End Depth: 39.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035378
Layer: 2
Color: 6
General Color: BROWN
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 15.0
Formation End Depth: 27.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964901722
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10865137
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930523264
Layer: 1
Material: 3
Open Hole or Material: CONCRETE
Depth From:
Depth To: 38.0
Casing Diameter: 30.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 994901722
Pump Set At:
Static Level: 15.0
Final Level After Pumping:
Recommended Pump Depth: 36.0
Pumping Rate: 2.0
Flowing Rate:
Recommended Pump Rate: 2.0

Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

Water Details

Water ID:	933789673
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	15.0
Water Found Depth UOM:	ft

---

202 **1 of 41** **ESE/242.8** **215.6 / -26.32** **GAS ALY LTD** **PRT**
370 MAIN ST N
BRAMPTON ON L6V4A4

Location ID:	1961
Type:	retail
Expiry Date:	1994-07-31
Capacity (L):	145472
Licence #:	0054442001

---

202 **2 of 41** **ESE/242.8** **215.6 / -26.32** **TOWERS DEPARTMENT STORE STORE #46** **PES**
370 MAIN STREET NORTH
BRAMPTON ON L6V 4A4

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

202 **3 of 41** **ESE/242.8** **215.6 / -26.32** **REPROTECH PRINTING SERVICE** **SCT**
370 MAIN ST N
BRAMPTON ON L6V 4A4

Established:	1989
Plant Size (ft²):	1700
Employment:	6

--Details--

Description: COMMERCIAL PRINTING, LITHOGRAPHIC
SIC/NAICS Code: 2752

Description: TYPESETTING
SIC/NAICS Code: 2791

---

202 **4 of 41** **ESE/242.8** **215.6 / -26.32** **DIRECTORIES INTERNATIONAL LTD** **SCT**
370 MAIN ST N
BRAMPTON ON L6V 4A4

Established: 1982
Plant Size (ft²): 0
Employment: 5

--Details--
Description: BOOKS: PUBLISHING, OR PUBLISHING AND PRINTING
SIC/NAICS Code: 2731

Description: MISCELLANEOUS PUBLISHING
SIC/NAICS Code: 2741

---

202 **5 of 41** **ESE/242.8** **215.6 / -26.32** **SUNOCO GAS BAR** **RST**
370 MAIN ST N
BRAMPTON ON L6V4A4

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054598874
List Name:
Description:

---

202 **6 of 41** **ESE/242.8** **215.6 / -26.32** **SUNOCO INC.** **GEN**
370 MAIN STREET
BRAMPTON ON L6V 4A4

Generator Info

Generator No: ON0004948
Approval Years: 01,02
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PETROLEUM PROD., WH.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 5111

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	7 of 41	ESE/242.8	215.6 / -26.32	BRIDLEWOOD CLEANERS 604575 ONTARIO LTD. 370 MAIN STREET NORTH BRAMPTON ON L6V 4A4	GEN

Generator Info

Generator No:	ON0474300	**Choice of Contact:**	
Approval Years:	86,87,88,89,90	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	9721
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	POWER LAUND./CLEANERS		

Waste Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	8 of 41	ESE/242.8	215.6 / -26.32	BRIDLEWOOD CLEANERS, 604575 ONTARIO LTD. 370 MAIN STREET NORTH BRAMPTON ON L6V 1P8	GEN

Generator Info

Generator No:	ON0474300	**Choice of Contact:**	
Approval Years:	92,93,97,98	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	9721
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	POWER LAUND./CLEANER		

Waste Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	9 of 41	ESE/242.8	215.6 / -26.32	BRIDLEWOOD CLEANERS 06-096 604575 ONTARIO LTD. 370 MAIN STREET NORTH BRAMPTON ON L6V 4A4	GEN

Generator Info

Generator No:	ON0474300	**Choice of Contact:**	
Approval Years:	94,95,96	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	9721
Country:			
Co Admin:			
Phone No Admin:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: POWER LAUND./CLEANER

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

202 **10 of 41** **ESE/242.8** **215.6 / -26.32** **BRIDLEWOOD CLEANERS**
370 MAIN STREET NORTH
BRAMPTON ON L6V 1P8 **GEN**

Generator Info

Generator No: ON0474300
Approval Years: 99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: POWER LAUND./CLEANERS

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 9721

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

202 **11 of 41** **ESE/242.8** **215.6 / -26.32** **GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.**
SUPER FRESH #098 370 MAIN STREET NORTH
BRAMPTON ON L6V 1P8 **GEN**

Generator Info

Generator No: ON0928794
Approval Years: 98,99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: CAMERA/PHOTO. SUPPLY

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6571

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

202 **12 of 41** **ESE/242.8** **215.6 / -26.32** **434173 ONTARIO LTD.**
O/A BRIDLEWOOD DRY CLEANERS 370 MAIN ST. SOUTH
BRAMPTON ON L6V 1P8 **GEN**

Generator Info

Generator No: ON1233200

Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 89
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: POWER LAUND./CLEANER
Contaminated Fac:
MHSW Facility:
SIC Code: 9721

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

202 | ***13 of 41*** | ***ESE/242.8*** | ***215.6 / -26.32*** | ***BRIDLEWOOD DRY CLEANERS 370 MAIN STREET BRAMPTON ON L6V 4A4*** | ***GEN***

Generator Info

Generator No: ON1233200
Approval Years: 92,93,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: POWER LAUND./CLEANER
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 9721

Waste Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

202 | ***14 of 41*** | ***ESE/242.8*** | ***215.6 / -26.32*** | ***FIRST QUALITY 1 HOUR PHOTO 15-680 370 MAIN STREET BRAMPTON ON L6V 4A4*** | ***GEN***

Generator Info

Generator No: ON1619200
Approval Years: 92,93,94,95,96,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: CAMERA/PHOTO. SUPPLY
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6571

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

202 | ***15 of 41*** | ***ESE/242.8*** | ***215.6 / -26.32*** | ***434173 ONTARIO LTD. 43-172 O/A BRIDLEWOOD DRY CLEANERS 370 MAIN ST. SOUTH BRAMPTON ON L6V 1P8*** | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON1233200	***Choice of Contact:***	
Approval Years:	94,95,96	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	9721
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	POWER LAUND./CLEANER		

Waste Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

202	***16 of 41***	***ESE/242.8***	***215.6 / -26.32***	***BRIDLEWOOD DRY CLEANERS*** ***370 MAIN STREET NORTH*** ***BRAMPTON ON L6V 1P8***	***GEN***

Generator Info

Generator No:	ON1233200	***Choice of Contact:***	
Approval Years:	99,00,01,02,03,04	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	9721
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	POWER LAUND./CLEANERS		

Waste Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

202	***17 of 41***	***ESE/242.8***	***215.6 / -26.32***	***KINGSPOINT PROPERTY*** ***370 MAIN ST.*** ***BRAMPTON ON L6V 4A4***	***GEN***

Generator Info

Generator No:	ON2873109	***Choice of Contact:***	
Approval Years:	02,03,04	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	18 of 41	ESE/242.8	215.6 / -26.32	SUNOCO INC 370 MAIN ST N BRAMPTON ON L6V 4A4	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054598874
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	19 of 41	ESE/242.8	215.6 / -26.32	Suncor Energy Products 370 MAIN STREET BRAMPTON ON	GEN

Generator Info

Generator No: ON0004948
Approval Years: 03,04,05,06,07,08
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Other Gasoline Stations

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 447190

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	20 of 41	ESE/242.8	215.6 / -26.32	GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED 370 MAIN ST N BRAMPTON ON L6V 4A4	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	21 of 41	ESE/242.8	215.6 / -26.32	The Cannington Group Inc 370 Main Street Brampton ON L6V 4A4	GEN

Generator Info

Generator No:	ON6403318	***Choice of Contact:***	
Approval Years:	05,06	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	453999
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Miscellaneous Store Retailers (except Beer and Wine-Making Supplies Stores)		

Waste Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

Waste Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class:	221
Waste Class Name:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	22 of 41	ESE/242.8	215.6 / -26.32	1451134 ONTARIO LTD 370 MAIN ST N BRAMPTON ON L6V 4A4	FSTH

License Issue Date:	4/14/2004
Tank Status:	Licensed
Tank Status As Of:	August 2007
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	2001
Corrosion Protection:	
Capacity:	27300
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline
Status:	Active
Year of Installation:	2001
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline
Status:	Active
Year of Installation:	2001
Corrosion Protection:	
Capacity:	36300

Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2001
Corrosion Protection:
Capacity: 36300
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

---

202 | **23 of 41** | **ESE/242.8** | **215.6 / -26.32** | **370 Main Street North Brampton ON L6V 4A4** | **EHS**

Order No: 20090813002
Status: C
Report Type: Standard Report
Report Date: 8/14/2009
Date Received: 8/13/2009
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Title Searches; City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.770363
Y: 43.69539

---

202 | **24 of 41** | **ESE/242.8** | **215.6 / -26.32** | **GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED 370 MAIN ST N BRAMPTON ON L6V 4A4** | **PES**

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

202 | **25 of 41** | **ESE/242.8** | **215.6 / -26.32** | **370 Main Street North Brampton ON L6V 4A4** | **EHS**

Order No: 20100825009
Status: C
Report Type: Custom Report
Report Date: 8/31/2010
Date Received: 8/25/2010
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.770606
Y: 43.695486

---

202 | **26 of 41** | **ESE/242.8** | **215.6 / -26.32** | **THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC 370 MAIN ST N** | **DTNK**

BRAMPTON ON

Delisted Expired Fuel Safety Facilities

Instance No:	10598202	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29769	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

202	27 of 41	ESE/242.8	215.6 / -26.32	THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC 370 MAIN ST N BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10598156	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29979	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			

TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

202 ***28 of 41*** ***ESE/242.8*** ***215.6 / -26.32*** ***Suncor Energy Products*** ***GEN***
370 MAIN STREET
BRAMPTON ON L6V 4A4

Generator Info

Generator No: ON0004948
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Other Gasoline Stations
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 447190

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

202 ***29 of 41*** ***ESE/242.8*** ***215.6 / -26.32*** ***GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED*** ***PES***
370 MAIN ST N
BRAMPTON ON L6V 4A4

Detail Licence No: 23-01-13893-0
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: LIMITED
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	30 of 41	ESE/242.8	215.6 / -26.32	THE GREAT ATLANTIC & PACIFIC COMPANY OF CANAD 370 MAIN Street North BRAMPTON ON L6V1P8	NPRI

NPRI ID:	8800001915	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mr.
Rpt Type ID:		**Cont First Name:**	KIRK
Report Year:	2004	**Cont Last Name:**	SHIPLO
Not-Current Rpt?:		**Contact Position:**	Director of maintenance
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	A&P - 370 MAIN ST. N.	**Cont Area Code:**	416
Fac Address1:		**Contact Tel.:**	2346979
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:		**Cont Fax Area Cde:**	
Facility Lat:		**Contact Fax:**	
Facility Long:		**Contact Email:**	kshiplo@aptea.com
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	20	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	53		
NAICS 2 Description:	Real Estate and Rental and Leasing		
NAICS Code (4 digit):	5311		
NAICS 4 Description:	Lessors of Real Estate		
NAICS Code (6 digit):	531120		
NAICS 6 Description:	Lessors of Non-Residential Buildings (except Mini-Warehouses)		

Substance Release Report

CAS No:	124-38-9
Report ID:	
Rpt Period:	2004
Subst Released:	Carbon dioxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes

CAS No:	7446-09-5
Report ID:	
Rpt Period:	2004
Subst Released:	Sulphur dioxide
Air:	
Water:	
Land:	

Total Releases:
Units: tonnes

CAS No: 10024-97-2
Report ID:
Rpt Period: 2004
Subst Released: Nitrous oxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 74-82-8
Report ID:
Rpt Period: 2004
Subst Released: Methane
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M09
Report ID:
Rpt Period: 2004
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 630-08-0
Report ID:
Rpt Period: 2004
Subst Released: Carbon monoxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004
Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 11104-93-1
Report ID:
Rpt Period: 2004

Subst Released:	Nitrogen oxides (expressed as NO2)
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M08
Report ID:	
Rpt Period:	2004
Subst Released:	PM - Total Particulate Matter
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M10
Report ID:	
Rpt Period:	2004
Subst Released:	PM2.5 - Particulate Matter <= 2.5 Microns
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	31 of 41	ESE/242.8	215.6 / -26.32	**9495088 Canada Inc** **370 Main St N** **Brampton ON L6V 4A4**	GEN

Generator Info

Generator No:	ON2657232	**Choice of Contact:**	
Approval Years:	As of Dec 2017	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

2017 Generator Info

Gen No:	ON2657232	**Choice of Contact:**	CO_OFFICIAL
ID:	10751	**Phone No Official:**	905-453-6220 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	METROPOLITAN TORONTO
NAICS Code1:	441320	**County Out:**	
NAICS Code2:		**District:**	301
NAICS Code3:			
Gen Name:	9495088 Canada Inc		
Gen Div:			
Gen Op Name:	Toiro Car Care		
Gen Op Div:			
Site Adrs1:	370 Main St N		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L6V 4A4
Site Country: Canada
Co Official: Fernando H Francisco
Co Admin:

2017 Generator Manifest

ID:	32296	**Sum Received Qty:**	3530.0
Generator No:	ON2657232	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	301
Waste Code:	251		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	32 of 41	ESE/242.8	215.6 / -26.32	GIANT TIGER STORE #151 - TORA BRAMPTON LIMITED 370 MAIN ST N BRAMPTON ON L6V4A4	PES

Detail Licence No:
Licence No: 13893
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 905
Oper Phone No: 4579721
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
202	33 of 41	ESE/242.8	215.6 / -26.32	370 MAIN ST N BRAMPTON ON L6V 4A4	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9793580	**Expired Date:**	
Status:	Expired-No Env Recd	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:		**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	FS GASOLINE STATION - SELF SERVE
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	

Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: 28-FEB-2022
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

202 ***34 of 41*** ***ESE/242.8*** ***215.6 / -26.32*** ***THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC***
370 MAIN ST N
BRAMPTON ON ***EXP***

Inventory No: 10598128
Inventory Status: Expired-No Env Recd
Installation Year: 2001
Capacity: 27300
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

202 ***35 of 41*** ***ESE/242.8*** ***215.6 / -26.32*** ***THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC***
370 MAIN ST N
BRAMPTON ON ***EXP***

Inventory No: 64147761
Inventory Status: EXPIRED
Installation Year: 1989
Capacity: 27280
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

202 ***36 of 41*** ***ESE/242.8*** ***215.6 / -26.32*** ***THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC***
370 MAIN ST N
BRAMPTON ON ***EXP***

Inventory No: 64147759
Inventory Status: EXPIRED
Installation Year: 1989
Capacity: 22730
Capacity Unit:
Tank Type:
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

---

202 | ***37 of 41*** | ***ESE/242.8*** | ***215.6 / -26.32*** | ***THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC***
370 MAIN ST N
BRAMPTON ON | ***EXP***

Inventory No: 10598182
Inventory Status: Expired-No Env Recd
Installation Year: 2001
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

202 | ***38 of 41*** | ***ESE/242.8*** | ***215.6 / -26.32*** | ***THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC***
370 MAIN ST N
BRAMPTON ON | ***EXP***

Inventory No: 10598225
Inventory Status: Expired-No Env Recd
Installation Year: 2001
Capacity: 36300
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

202 | ***39 of 41*** | ***ESE/242.8*** | ***215.6 / -26.32*** | ***THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC***
370 MAIN ST N
BRAMPTON ON | ***EXP***

Inventory No: 10598268
Inventory Status: Expired-No Env Recd
Installation Year: 2001
Capacity: 36300
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

202 | ***40 of 41*** | ***ESE/242.8*** | ***215.6 / -26.32*** | ***THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC***
370 MAIN ST N
BRAMPTON ON | ***EXP***

Inventory No: 64147757

Tank Material: Fiberglass (FRP)

Inventory Status:	EXPIRED	***Corrosion Protect:***	Fiberglass
Installation Year:	1989	***Overfill Protection:***	
Capacity:	36370	***Inventory Context:***	FS Liquid Fuel Tank
Capacity Unit:		***Inventory Item:***	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	2009VBS		
Previous Fuel Type:	Gasoline		

---

202 | ***41 of 41*** | ***ESE/242.8*** | ***215.6 / -26.32*** | ***THARMALINGAM SUBRAMANIAM O/A 2117076 ONTARIO INC***
370 MAIN ST N
BRAMPTON ON | ***EXP***

Inventory No:	64147760	***Tank Material:***	Fiberglass (FRP)
Inventory Status:	EXPIRED	***Corrosion Protect:***	Fiberglass
Installation Year:	1989	***Overfill Protection:***	
Capacity:	36370	***Inventory Context:***	FS Liquid Fuel Tank
Capacity Unit:		***Inventory Item:***	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	2009VBS		
Previous Fuel Type:	Gasoline		

---

203 | ***1 of 1*** | ***SE/222.3*** | ***218.9 / -23.08*** | ***Alectra Utilities Corporation***
8 Martindale Crescent
Brampton ON | ***GEN***

Generator Info as of Dec 2024

Generator No:	ONS0305-1-34PLVQ-1
Generator Company Name:	Alectra Utilities Corporation
Street:	8 Martindale Crescent
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6X 2T9
Waste Class:	251 L

Waste Class Decoded:

251 - OIL SKIMMINGS & SLUDGES

---

204 | ***1 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***JOHN PALUMBO PHARMACY LTD. O/A SHOPPERS DRUG MART #1353***
366 MAIN STREET N
BRAMPTON ON L6V1P8 | ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:		***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:		***Oper Area Code:***	
Licence Type:	Vendor	***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

204 | **2 of 21** | **SE/248.5** | **217.9 / -24.00** | **Counsel Kingspoint Ltd.**
366 Main St.
Brampton ON | **GEN**

Generator Info

Generator No: ON7463263
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Financial Investment Activities

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 523990

Waste Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

204 | **3 of 21** | **SE/248.5** | **217.9 / -24.00** | **JOHN PALUMBO PHARMACY LTD. O/A**
SHOPPERS DRUG MART #1353
366 MAIN STREET N
BRAMPTON ON L6V1P8 | **PES**

Detail Licence No:
Licence No: 15013
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 647
Oper Phone No: 8886375
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

204 | **4 of 21** | **SE/248.5** | **217.9 / -24.00** | **John Palumbo Pharmacy Ltd.**
366 MAIN STREET NORTH
BRAMPTON ON L6V 1P8 | **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON8458912	***Choice of Contact:***	CO_ADMIN
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	446110
Country:	Canada		
Co Admin:	NASTRAN NAJAFI-FARD		
Phone No Admin:	4164931120 Ext.3218		
SIC Description:	446110		

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

204	***5 of 21***	***SE/248.5***	***217.9 / -24.00***	***WILTADEN LIMITED*** ***366 MAIN STREET NORTH UNIT 201*** ***BRAMPTON ON L6V1P8***	***GEN***

Generator Info

Generator No:	ON9119549	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621110
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	OFFICES OF PHYSICIANS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

204	***6 of 21***	***SE/248.5***	***217.9 / -24.00***	***WILTADEN LIMITED*** ***366 MAIN STREET NORTH UNIT 201*** ***BRAMPTON ON L6V1P8***	***GEN***

Generator Info

Generator No:	ON9119549	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621110
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	OFFICES OF PHYSICIANS		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

204 | ***7 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***John Palumbo Pharmacy Ltd.***
366 MAIN STREET NORTH
BRAMPTON ON L6V 1P8 | ***GEN***

Generator Info

Generator No: ON8458912
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: NASTRAN NAJAFI-FARD
Phone No Admin: 4164931120 Ext.3218
SIC Description: 446110

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 446110

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

204 | ***8 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***WILTADEN LIMITED***
366 MAIN STREET NORTH UNIT 201
BRAMPTON ON L6V1P8 | ***GEN***

Generator Info

Generator No: ON9119549
Approval Years: 2014
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: OFFICES OF PHYSICIANS

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

204 | ***9 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***John Palumbo Pharmacy Ltd.***
366 MAIN STREET NORTH
BRAMPTON ON L6V 1P8 | ***GEN***

Generator Info

Generator No: ON8458912
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

204 | ***10 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***WILTADEN LIMITED***
366 MAIN STREET NORTH UNIT 201
BRAMPTON ON L6V1P8 | ***GEN***

Generator Info

Generator No: ON9119549
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

204 | ***11 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***Queen Square Family Health Team***
366 Main Street North Suite 203
Brampton ON L6V 1P8 | ***GEN***

Generator Info

Generator No: ON9575416
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			

204	12 of 21	SE/248.5	217.9 / -24.00	John Palumbo Pharmacy Ltd. 366 MAIN STREET NORTH BRAMPTON ON L6V 1P8	GEN

Generator Info

Generator No:	ON8458912	**Choice of Contact:**	
Approval Years:	As of Jul 2020	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	Pharmaceuticals

204	13 of 21	SE/248.5	217.9 / -24.00	Queen Square Family Health Team 366 Main Street North Suite 203 Brampton ON L6V 1P8	GEN

Generator Info

Generator No:	ON9575416	**Choice of Contact:**	
Approval Years:	As of Jul 2020	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

204	14 of 21	SE/248.5	217.9 / -24.00	WILTADEN LIMITED 366 MAIN STREET NORTH UNIT 201 BRAMPTON ON L6V1P8	GEN

Generator Info

Generator No:	ON9119549	**Choice of Contact:**	

Approval Years:	As of Jul 2020	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

---

204 | ***15 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***JOHN PALUMBO PHARMACY LTD.***
366 Main ST N
Brampton ON L6V 1P8 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	L-232-9069847845	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-11-21	**Operator Type:**	
Report Source:	PEST-Limited Vendor	**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	43.69472222	**Operator Region:**	
Longitude:	-79.77166667	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Halton-Peel
County:		**SWP Area Name:**	Toronto
Trade Name:			

PDF URL: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2194572

---

204 | ***16 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***John Palumbo Pharmacy Ltd.***
366 MAIN STREET NORTH
BRAMPTON ON L6V 1P8 | ***GEN***

Generator Info

Generator No:	ON8458912	**Choice of Contact:**	
Approval Years:	As of Nov 2021	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	Pharmaceuticals

Waste Detail(s)

Waste Class:	312 P

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		Pathological wastes			

204	17 of 21	SE/248.5	217.9 / -24.00	**Queen Square Family Health Team** **366 Main Street North Suite 203** **Brampton ON L6V 1P8**	GEN

Generator Info

Generator No:	ON9575416	**Choice of Contact:**	
Approval Years:	As of Nov 2021	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

204	18 of 21	SE/248.5	217.9 / -24.00	**WILTADEN LIMITED** **366 MAIN STREET NORTH UNIT 201** **BRAMPTON ON L6V1P8**	GEN

Generator Info

Generator No:	ON9119549	**Choice of Contact:**	
Approval Years:	As of Jan 2021	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

2017 Generator Info

Gen No:	ON9119549	**Choice of Contact:**	CO_OFFICIAL
ID:	35626	**Phone No Official:**	9054555477 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	WILTADEN LIMITED		
Gen Div:			
Gen Op Name:	QUEEN SQUARE DOCTORS		
Gen Op Div:			
Site Adrs1:	366 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			

Province In: ONTARIO
Site Adrs2: UNIT 201
Site City: BRAMPTON
Province Out:
Site Postal Code: L6V1P8
Site Country: Canada
Co Official: Frances C Roesch
Co Admin:

2017 Generator Manifest

ID: 63866
Generator No: ON9119549
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 163.2
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 5
District: 305

2018 Generator Info

Gen No: ON9119549
ID: 36314
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621110
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9054555477 Ext.
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: WILTADEN LIMITED
Gen Div:
Gen Op Name: QUEEN SQUARE DOCTORS
Gen Op Div:
Site Adrs1: 366 MAIN STREET NORTH
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2: UNIT 201
Site City: BRAMPTON
Province Out:
Site Postal Code: L6V1P8
Site Country: Canada
Co Official: Betty Olkowicz
Co Admin:

2018 Generator Manifest

ID: 64352
Generator No: ON9119549
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 135.4
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 5
District: 305

2019 Generator Info

Gen No: ON9119549
ID: 36820
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621110
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9054555477 Ext.
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: WILTADEN LIMITED
Gen Div:
Gen Op Name: QUEEN SQUARE DOCTORS

Gen Op Div:
Site Adrs1: 366 MAIN STREET NORTH
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2: UNIT 201
Site City: BRAMPTON
Province Out:
Site Postal Code: L6V1P8
Site Country: Canada
Co Official: Betty Olkowicz
Co Admin:

2019 Generator Manifest

ID: 64374
Generator No: ON9119549
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 173.0
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 4
District: 305

2020 Generator Info

Gen No: ON9119549
ID: 36558
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621110
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9054555477 Ext.
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: WILTADEN LIMITED
Gen Div:
Gen Op Name: QUEEN SQUARE DOCTORS
Gen Op Div:
Site Adrs1: 366 MAIN STREET NORTH
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2: UNIT 201
Site City: BRAMPTON
Province Out:
Site Postal Code: L6V1P8
Site Country: Canada
Co Official: Betty Olkowicz
Co Admin:

2020 Generator Manifest

ID: 60479
Generator No: ON9119549
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 121.57
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 4
District: 305

---

204 | ***19 of 21*** | ***SE/248.5*** | ***217.9 / -24.00*** | ***Samara Al Windawi***
366 Main Street North, Suite 203
Brampton ON | ***GEN***

Generator Info

Generator No: ON9575416
Choice of Contact:

Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

Generator Info as of Dec 2024

Generator No:	ON9575416
Generator Company Name:	Samara Al Windawi
Street:	366 Main Street North, Suite 203
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6V1P8
Waste Class:	312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

2017 Generator Info

Gen No:	ON9575416	**Choice of Contact:**	CO_OFFICIAL
ID:	37399	**Phone No Official:**	905-453-1453 Ext.302
Contaminated Fac:	N	**Phone No Admin:**	905-453-1453 Ext.304
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621390	**County Out:**	
NAICS Code2:	621330	**District:**	305
NAICS Code3:			
Gen Name:	Queen Square Family Health Team		
Gen Div:			
Gen Op Name:	Queen Square Family Health Team		
Gen Op Div:			
Site Adrs1:	366 Main Street North		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Suite 203		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	Sandra S.K. Kalicharan		
Co Admin:	Rekha J J.L. Latchman		

2017 Generator Manifest

ID:	66177	**Sum Received Qty:**	7.0
Generator No:	ON9575416	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	P	**District:**	306
Waste Code:	312		

2018 Generator Info

Gen No:	ON9575416	***Choice of Contact:***	CO_OFFICIAL
ID:	38135	***Phone No Official:***	905-453-1453 Ext.302
Contaminated Fac:	N	***Phone No Admin:***	905-453-1453 Ext.304
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621390	***County Out:***	
NAICS Code2:	621330	***District:***	305
NAICS Code3:			
Gen Name:	Queen Square Family Health Team		
Gen Div:			
Gen Op Name:	Queen Square Family Health Team		
Gen Op Div:			
Site Adrs1:	366 Main Street North		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Suite 203		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	Sandra S.K. Kalicharan		
Co Admin:	Rekha J J.L. Latchman		

2019 Generator Info

Gen No:	ON9575416	***Choice of Contact:***	CO_OFFICIAL
ID:	38695	***Phone No Official:***	905-453-1453 Ext.302
Contaminated Fac:	N	***Phone No Admin:***	905-453-1453 Ext.304
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621390	***County Out:***	
NAICS Code2:	621330	***District:***	305
NAICS Code3:			
Gen Name:	Queen Square Family Health Team		
Gen Div:			
Gen Op Name:	Queen Square Family Health Team		
Gen Op Div:			
Site Adrs1:	366 Main Street North		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Suite 203		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	Sandra S.K. Kalicharan		
Co Admin:	Rekha J J.L. Latchman		

2019 Generator Manifest

ID:	66777	***Sum Received Qty:***	7.0
Generator No:	ON9575416	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	P	***District:***	306
Waste Code:	312		

2020 Generator Info

Gen No:	ON9575416	***Choice of Contact:***	CO_OFFICIAL
ID:	38450	***Phone No Official:***	905-453-1453 Ext.302
Contaminated Fac:	N	***Phone No Admin:***	905-453-1453 Ext.304

MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621390	***County Out:***	
NAICS Code2:	621330	***District:***	305
NAICS Code3:			
Gen Name:	Queen Square Family Health Team		
Gen Div:			
Gen Op Name:	Queen Square Family Health Team		
Gen Op Div:			
Site Adrs1:	366 Main Street North		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Suite 203		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	Sandra S.K. Kalicharan		
Co Admin:	Rekha J J.L. Latchman		

2021 Generator Info

Gen No:	ON9575416	***Choice of Contact:***	CO_OFFICIAL
ID:	39495	***Phone No Official:***	905-453-1453 Ext.302
Contaminated Fac:	N	***Phone No Admin:***	905-453-1453 Ext.304
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621390	***County Out:***	
NAICS Code2:	621330	***District:***	305
NAICS Code3:			
Gen Name:	Queen Square Family Health Team		
Gen Div:			
Gen Op Name:	Queen Square Family Health Team		
Gen Op Div:			
Site Adrs1:	366 Main Street North		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	Suite 203		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	Sandra S.K. Kalicharan		
Co Admin:	Rekha J J.L. Latchman		

2021 Generator Manifest

ID:	65716	***Sum Received Qty:***	36.31
Generator No:	ON9575416	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

2021 Generator Manifest

ID:	65717	***Sum Received Qty:***	15.0
Generator No:	ON9575416	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	306
Waste Code:	312		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
204	20 of 21	SE/248.5	217.9 / -24.00	Shoppers Drug Mart 1353 366 MAIN STREET NORTH BRAMPTON ON	GEN

Generator Info

Generator No:	ON8458912	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

Generator Info as of Dec 2024

Generator No:	ON8458912
Generator Company Name:	Shoppers Drug Mart 1353
Street:	366 MAIN STREET NORTH
City:	BRAMPTON
Province State:	Ontario
Country:	Canada
Postal Code:	L6V1P8
Waste Class:	312 P, 261 A, 312 P, 261 A

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

Generator Info as of Dec 2024

Generator No:	ON8458912
Generator Company Name:	Shoppers Drug Mart 1353
Street:	366 MAIN STREET NORTH
City:	BRAMPTON
Province State:	Ontario
Country:	Canada
Postal Code:	L6V1P8
Waste Class:	312 P,261 A

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

2017 Generator Info

Gen No:	ON8458912	***Choice of Contact:***	CO_ADMIN

ID:	33131	**Phone No Official:**	905-456-0167 Ext.
Contaminated Fac:	N	**Phone No Admin:**	4164931120 Ext.3218
MHSW Facility:	N	**County Ont:**	METROPOLITAN TORONTO
NAICS Code1:	446110	**County Out:**	
NAICS Code2:		**District:**	301
NAICS Code3:			
Gen Name:	John Palumbo Pharmacy Ltd.		
Gen Div:			
Gen Op Name:	Shoppers Drug Mart 1353		
Gen Op Div:			
Site Adrs1:	366 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	JOHN PALUMBO		
Co Admin:	NASTRAN NAJAFI-FARD		

2017 Generator Manifest

ID:	60780	**Sum Received Qty:**	71.8
Generator No:	ON8458912	**Waste Class Name:**	PHARMACEUTICALS
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	A	**District:**	305
Waste Code:	261		

2017 Generator Manifest

ID:	60781	**Sum Received Qty:**	6.64
Generator No:	ON8458912	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	P	**District:**	305
Waste Code:	312		

2018 Generator Info

Gen No:	ON8458912	**Choice of Contact:**	CO_ADMIN
ID:	33746	**Phone No Official:**	905-456-0167 Ext.
Contaminated Fac:	N	**Phone No Admin:**	4164931120 Ext.
MHSW Facility:	N	**County Ont:**	METROPOLITAN TORONTO
NAICS Code1:	446110	**County Out:**	
NAICS Code2:		**District:**	301
NAICS Code3:			
Gen Name:	John Palumbo Pharmacy Ltd.		
Gen Div:			
Gen Op Name:	Shoppers Drug Mart 1353		
Gen Op Div:			
Site Adrs1:	366 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	JOHN PALUMBO		
Co Admin:	Pharmacy Operations Development		

2018 Generator Manifest

ID:	61104	***Sum Received Qty:***	36.3
Generator No:	ON8458912	***Waste Class Name:***	PHARMACEUTICALS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	A	***District:***	305
Waste Code:	261		

2018 Generator Manifest

ID:	61105	***Sum Received Qty:***	46.9
Generator No:	ON8458912	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

2019 Generator Info

Gen No:	ON8458912	***Choice of Contact:***	CO_ADMIN
ID:	34143	***Phone No Official:***	905-456-0167 Ext.
Contaminated Fac:	N	***Phone No Admin:***	4164931120 Ext.
MHSW Facility:	N	***County Ont:***	METROPOLITAN TORONTO
NAICS Code1:	446110	***County Out:***	
NAICS Code2:		***District:***	301
NAICS Code3:			
Gen Name:	John Palumbo Pharmacy Ltd.		
Gen Div:			
Gen Op Name:	Shoppers Drug Mart 1353		
Gen Op Div:			
Site Adrs1:	366 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	JOHN PALUMBO		
Co Admin:	Pharmacy Operations Development		

2019 Generator Manifest

ID:	60972	***Sum Received Qty:***	57.0
Generator No:	ON8458912	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

2019 Generator Manifest

ID:	60971	***Sum Received Qty:***	180.0
Generator No:	ON8458912	***Waste Class Name:***	PHARMACEUTICALS
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	A	***District:***	305
Waste Code:	261		

2020 Generator Info

Gen No:	ON8458912	***Choice of Contact:***	CO_ADMIN
ID:	33869	***Phone No Official:***	905-456-0167 Ext.

Contaminated Fac:	N	***Phone No Admin:***	4164931120 Ext.
MHSW Facility:	N	***County Ont:***	METROPOLITAN TORONTO
NAICS Code1:	446110	***County Out:***	
NAICS Code2:		***District:***	301
NAICS Code3:			
Gen Name:	John Palumbo Pharmacy Ltd.		
Gen Div:			
Gen Op Name:	Shoppers Drug Mart 1353		
Gen Op Div:			
Site Adrs1:	366 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	JOHN PALUMBO		
Co Admin:	Pharmacy Operations Development		

2020 Generator Manifest

ID:	57253	***Sum Received Qty:***	92.0
Generator No:	ON8458912	***Waste Class Name:***	PHARMACEUTICALS
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	A	***District:***	305
Waste Code:	261		

2020 Generator Manifest

ID:	57254	***Sum Received Qty:***	26.18
Generator No:	ON8458912	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	P	***District:***	305
Waste Code:	312		

2021 Generator Info

Gen No:	ON8458912	***Choice of Contact:***	CO_ADMIN
ID:	34672	***Phone No Official:***	905-456-0167 Ext.
Contaminated Fac:	N	***Phone No Admin:***	4164931120 Ext.
MHSW Facility:	N	***County Ont:***	METROPOLITAN TORONTO
NAICS Code1:	446110	***County Out:***	
NAICS Code2:		***District:***	301
NAICS Code3:			
Gen Name:	Hitesh Khaira Pharmacy Ltd.		
Gen Div:			
Gen Op Name:	Shoppers Drug Mart 1353		
Gen Op Div:			
Site Adrs1:	366 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6V 1P8		
Site Country:	Canada		
Co Official:	Hitesh Khaira		
Co Admin:	Pharmacy Operations Development		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2021 Generator Manifest

ID:	59716	***Sum Received Qty:***	52.0
Generator No:	ON8458912	***Waste Class Name:***	PHARMACEUTICALS
Receiver Type:	035	***Count Manifests:***	4
Waste Char:	A	***District:***	305
Waste Code:	261		

2021 Generator Manifest

ID:	59717	***Sum Received Qty:***	22.66
Generator No:	ON8458912	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

---

204 ***21 of 21*** ***SE/248.5*** ***217.9 / -24.00*** ***Shoppers Drug Mart #1353*** ***GEN***
366 Main Street North
Brampton ON

Generator Info as of Dec 2024

Generator No:	ON001067718
Generator Company Name:	Shoppers Drug Mart #1353
Street:	366 Main Street North
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6V 1P8
Waste Class:	312 P, 261 A, 312 P, 261 A

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

Generator Info as of Dec 2024

Generator No:	ON001067718
Generator Company Name:	Shoppers Drug Mart #1353
Street:	366 Main Street North
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6V 1P8
Waste Class:	312 P,261 A

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

---

205 ***1 of 1*** ***SE/221.4*** ***218.9 / -23.08*** ***ALECTRA UTILITIES CORPORATION*** ***SPL***

BRAMPTON ON

Ref No:	1-34PLVQ	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	4/6/2023 8:00:58 AM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	4/6/2023 8:59:22 AM	***Impact to Health:***	0 No Impact

Dt Document Closed:	4/6/2023 11:05:28 AM	**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	ALECTRA UTILITIES CORPORATION		
Client Type:	Private Business		
Source Type:	Transformer		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Incident Reason:	Equipment failure/malfunction		
Incident Summary:	Alectra Utilities: transformer leaking non-PCB oil in foundation and grass		
Environment Impact:	1 Minor Impact		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	90 litre (L)		
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:	TRANSFORMER OIL (N.O.S.)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Activity Preceding Spill:	Normal operations		
Property 2nd Watershed:	02H | Northern Lake Ontario and Niagara River		
Property Tertiary Watershed:	02HC | Humber River - Don River		
Sector Type:	ELECTRIC POWER DISTRIBUTION		
SAC Action Class:			
Call Report Locatn Geodata:	{"integration_ids":["PR00001786960"],"wkts":["POINT (-79.7791901000 43.6899683000)"],"creation_date":"2023-04-06"}		
Time Reported:			
System Facility Address:			

206	***1 of 1***	***ESE/226.3***	***220.9 / -21.06***	***MICHAEL SCOTT INC.*** ***22 WIMBLEDON CRT*** ***BRAMPTON ON L6V 2S4***	***SCT***

Established:	1984
Plant Size (ft²):	1000
Employment:	2

--Details--

Description:	COMMERCIAL PRINTING, LITHOGRAPHIC
SIC/NAICS Code:	2752
Description:	COMMERCIAL PRINTING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code:	2759

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
207	1 of 1	SE/247.8	218.3 / -23.62	BRAMPTON TRANSIT MOTOR VEHICLE ETOBICOKE CREEK HWY 10 AND ENGLISH ST OPERATING FLUIDS BRAMPTON CITY ON	SPL

Ref No:	197458	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	4/2/2001	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/2/2001	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	PEEL REGION, FIRE DEPT.
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER TRANSPORTATION ACCIDENT		
Incident Preceding Spill:			
Incident Reason:	ERROR		
Incident Summary:	BRAMPTON TRANSIT: 75 L DIESEL TO ROAD AND CREEK.REGION, FIRE DEPT.		
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Water course or lake		
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land, Water		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
208	1 of 4	ESE/229.9	226.9 / -15.02	SIR JOHN A. MACDONALD SR.PUB.SCHL. PEEL BOARD OF EDUCATION 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON0359849	***Choice of Contact:***	
Approval Years:	86,87,88,89,90	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	8511
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELEMT./SECON. EDUC.		

Waste Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

208	***2 of 4***	***ESE/229.9***	***226.9 / -15.02***	***SIR JOHN A. MACDONALD SR.PUB.SCHL.30-247 PEEL BOARD OF EDUCATION 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4***	***GEN***

Generator Info

Generator No:	ON0359849	***Choice of Contact:***	
Approval Years:	92,93,94,95,96	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	8511
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELEMT./SECON. EDUC.		

Waste Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

208 ***3 of 4*** ***ESE/229.9*** ***226.9 / -15.02*** ***PEEL DISTRICT SCHOOL BOARD SIR JOHN A. MACDONALD SR. PUBLIC SCHOOL 250 CENTRE STREET, NORTH BRAMPTON ON L6V 2R4*** ***GEN***

Generator Info

Generator No: ON0359849
Approval Years: 97,98,99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ELEMT./SECON. EDUC.
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 8511

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

208 ***4 of 4*** ***ESE/229.9*** ***226.9 / -15.02*** ***Peel District School Board 250 Centre St N Brampton ON L6V 2R4*** ***SPL***

Ref No: 2346-BLFGM4
Year:
Incident Dt: 2020/02/03
Dt MOE Arvl on Scn:
MOE Reported Dt: 2020/02/03
Dt Document Closed: 2020/04/09
Site No: 8119-BLFRKQ
MOE Response: No
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	NA
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Sir John A MacDonald Sr. Middle School
Site Address:	250 Centre St N
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	NA
Site Geo Ref Accu:	NA
Site Map Datum:	NA
Northing:	NA
Easting:	NA
Entity Operating Name:	
Client Name:	Peel District School Board
Client Type:	Other (Describe)
Source Type:	Other
Incident Cause:	
Incident Preceding Spill:	Vandalism
Incident Reason:	Deliberate Act
Incident Summary:	Peel District School Board: smashed car battery, cleaned
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	1 kg
Contaminant Qty 1:	1
Contaminant Unit:	kg
Contaminant Code:	21
Contaminant Name:	SULPHURIC ACID
Contaminant Limit 1:	
Contam Limit Freq 1:	n/a
Contaminant UN No 1:	1830
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

209	1 of 2	SE/248.6	219.9 / -22.08	Enbridge Gas Distribution 16 English Street Brampton ON	SPL

Ref No:	8632-97CLGN	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	03-MAY-13	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	03-MAY-13	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:	Not MOE mandate		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	16 English Street<UNOFFICIAL>		
Site Address:	16 English Street		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			

Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	Enbridge Gas Distribution
Client Type:	
Source Type:	
Incident Cause:	Leak/Break
Incident Preceding Spill:	
Incident Reason:	Operator/Human Error
Incident Summary:	Enbridge: 1" Service, Line strike, not safe.
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	0 other - see incident description
Contaminant Qty 1:	0
Contaminant Unit:	other - see incident description
Contaminant Code:	35
Contaminant Name:	NATURAL GAS (METHANE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Pipeline/Components
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

209	***2 of 2***	***SE/248.6***	***219.9 / -22.08***	***PIPELINE HIT - 1"*** ***16 ENGLISH STREET,,BRAMPTON,ON,L6X 1L4, CA*** ***ON***	***PINC***

Incident Id:		***Pipe Material:***	
Incident No:	1093342	***Fuel Category:***	
Incident Reported Dt:	5/3/2013	***Health Impact:***	
Type:	FS-Pipeline Incident	***Environment Impact:***	
Status Code:		***Property Damage:***	
Tank Status:	Pipeline Damage Reason Est	***Service Interrupt:***	
Task No:		***Enforce Policy:***	
Spills Action Centre:		***Public Relation:***	
Fuel Type:		***Pipeline System:***	
Fuel Occurrence Tp:		***PSIG:***	
Date of Occurrence:		***Attribute Category:***	
Occurrence Start Dt:		***Regulator Location:***	
Depth:		***Method Details:***	
Customer Acct Name:	PIPELINE HIT - 1"		
Incident Address:	16 ENGLISH STREET,,BRAMPTON,ON,L6X 1L4,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
210	1 of 2	SE/178.6	219.9 / -22.08	GolfCity Motor Caddies Inc. 44 English St Brampton ON L6X 1L6	SCT

Established:
Plant Size (ft²):
Employment: 5

--Details--
Description: Recreational and Other Motor Vehicles Wholesaler-Distributors
SIC/NAICS Code: 415190

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
210	2 of 2	SE/178.6	219.9 / -22.08	PIPELINE HIT 0.5" 44 ENGLISH STREET,,BRAMPTON,ON,L6X 1L6, CA ON	PINC

Incident Id:
Incident No: 1090968
Incident Reported Dt: 4/30/2013
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: PIPELINE HIT 0.5"
Incident Address: 44 ENGLISH STREET,,BRAMPTON,ON,L6X 1L6,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
211	1 of 1	SE/223.1	218.9 / -23.05	367 Main St. N. Brampton ON L6X 1N6	EHS

Order No: 20030620008
Status: C
Report Type: Site Report
Report Date: 6/23/03
Date Received: 6/20/03
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.77161
Y: 43.694418

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
212	1 of 1	SE/214.0	219.9 / -22.08	7 English Street Brampton ON L6X 1L3	EHS

Order No: 24031500603

Nearest Intersection:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	C	**Municipality:**	BRAMPTON
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	20-MAR-24	**Search Radius (km):**	.2
Date Received:	15-MAR-24	**X:**	-79.7719554
Previous Site Name:		**Y:**	43.6938342
Lot/Building Size:	1859 m3		
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

213 **1 of 2** **ESE/185.9** **220.5 / -21.44** **Enbridge Gas Distribution Inc.**
34 Tolton Dr
Brampton ON
SPL

Ref No:	5024-ASEGCN	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2017/10/20	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2017/10/23	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2017/12/16	**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Site of line strike<UNOFFICIAL>		
Site Address:	34 Tolton Dr		
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839018.38		
Easting:	599325.36		
Entity Operating Name:			
Client Name:	Enbridge Gas Distribution Inc.		
Client Type:	Corporation		
Source Type:	Valve/Fitting/Piping		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Incident Reason:	Operator/Human Error		
Incident Summary:	TSSA FSB; ½ pl IP, service line dmgd; made safe		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	0 other - see incident description		
Contaminant Qty 1:	0		
Contaminant Unit:	other - see incident description		
Contaminant Code:	35		
Contaminant Name:	NATURAL GAS (METHANE)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	1075		
Receiving Medium:	Air		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Miscellaneous Industrial		
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
213	2 of 2	ESE/185.9	220.5 / -21.44	PIPELINE HIT - 1/2" 34 TOLTON DR,,BRAMPTON,ON,L6V 2R1,CA ON	PINC

Incident Id:
Incident No: 2178296
Incident Reported Dt: 10/23/2017
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: PIPELINE HIT - 1/2"
Incident Address: 34 TOLTON DR,,BRAMPTON,ON,L6V 2R1,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
214	1 of 3	ESE/185.5	220.0 / -21.91	Enbridge Gas Distribution Inc. 36 Tolton Drive Brampton ON	SPL

Ref No: 3441-AA92WQ
Year:
Incident Dt: 2016/05/23
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/05/23
Dt Document Closed: 2016/08/10
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Residential<UNOFFICIAL>
Site Address: 36 Tolton Drive
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Enbridge Gas Distribution Inc.
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Operator/Human Error
Incident Summary: TSSA FSB: 1/2" plastic line strike to atm.

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Communal
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

214 ***2 of 3*** ***ESE/185.5*** ***220.0 / -21.91*** ***PIPELINE HIT 0.5"*** ***PINC***
36 TOLTON DR.,,BRAMPTON,ON,L6V 2R1,CA
ON

Incident Id:
Incident No: 2199422
Incident Reported Dt: 11/29/2017
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: PIPELINE HIT 0.5"
Incident Address: 36 TOLTON DR.,,BRAMPTON,ON,L6V 2R1,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

---

214 ***3 of 3*** ***ESE/185.5*** ***220.0 / -21.91*** ***PIPELINE HIT - 1/2"*** ***PINC***
36 TOLTON DRIVE,,BRAMPTON,ON,L6V 2R1,CA
ON

Incident Id:
Incident No: 1870058
Incident Reported Dt: 5/24/2016
Type: FS-Pipeline Incident
Status Code:
Tank Status: Home Owner Pipeline Strike
Task No:
Spills Action Centre:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	
Depth:		**Method Details:**	
Customer Acct Name:	PIPELINE HIT - 1/2"		
Incident Address:	36 TOLTON DRIVE,,BRAMPTON,ON,L6V 2R1,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

---

215 | ***1 of 1*** | ***SE/208.9*** | ***218.9 / -23.08*** | ***ON*** | ***WWIS***

Well ID:	7266922	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	07/15/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C26205	**Contractor:**	7215
Tag:	A173163	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1006146479	**Tag No:**	A173163
Depth M:		**Contractor:**	7215
Year Completed:	2014	**Latitude:**	43.6940882171723
Well Completed Dt:	10/24/2014	**Longitude:**	-79.7715360641606
Audit No:	C26205	**Y:**	43.694088214946454
Path:		**X:**	-79.77153591380782

Bore Hole Information

Bore Hole ID:	1006146479	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	598996.00
Code OB Desc:		**North83:**	4838630.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/24/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

---

216 | ***1 of 1*** | ***SE/206.1*** | ***218.8 / -23.09*** | ***365 Main St N Brampton ON L6X 1N6*** | ***EHS***

Order No:	20130220011	***Nearest Intersection:***	
Status:	C	***Municipality:***	Brampton
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	28-FEB-13	***Search Radius (km):***	.25
Date Received:	20-FEB-13	***X:***	-79.771352
Previous Site Name:		***Y:***	43.694193
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

217 | ***1 of 1*** | ***ESE/223.5*** | ***229.9 / -12.08*** | ***ENVIRO MASTERS (ETOBICOKE) 84 KINGSWOOD DRIVE BRAMPTON ON L6V 2W3*** | ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:		***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:		***Oper Area Code:***	
Licence Type:	Operator	***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

---

218 | ***1 of 1*** | ***SE/13.3*** | ***219.9 / -22.08*** | ***Moore Street & English Street lot 8 con 1 Brampton ON*** | ***WWIS***

Well ID:	7380753	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	02/22/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	YTQ5SMOP	***Contractor:***	7472
Tag:	A308432	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	008
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	

Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/738\7380753.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/07/2021
Year Completed:	2021
Depth (m):	4.572
Latitude:	43.6910282093439
Longitude:	-79.7758546510061
X:	-79.77585450055277
Y:	43.691028206857915
Path:	738\7380753.pdf

Bore Hole Information

Bore Hole ID:	1008573521	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	598653.00
Code OB Desc:		***North83:***	4838285.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	01/07/2021	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008573618
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008573619
Layer:	2
Color:	2
General Color:	GREY
Material 1:	05

Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	5.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008573679
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008573702
Layer:	1
Plug From:	0.0
Plug To:	9.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008573703
Layer:	2
Plug From:	9.0
Plug To:	15.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1008573580
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1008573558
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008573634
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch

Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008573649
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 15.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008573559
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1008573664
Diameter: 7.5
Depth From: 0.0
Depth To: 15.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

219 | ***1 of 1*** | ***WNW/206.8*** | ***260.9 / 18.97*** | ***lot 22 con 1 ON*** | ***WWIS***

Well ID: 4901628
Construction Date:
Use 1st: Domestic
Use 2nd: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 01/14/1963
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1325
Form Version: 1
Owner:
County: PEEL
Lot: 022
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:

Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901628.pdf

Additional Detail(s) (Map)

Well Completed Date:	08/13/1962
Year Completed:	1962
Depth (m):	10.9728
Latitude:	43.7406902637679
Longitude:	-79.8572727210764
X:	-79.85727257078953
Y:	43.7406902623695
Path:	490\4901628.pdf

Bore Hole Information

Bore Hole ID:	10316473	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592015.50
Code OB Desc:		**North83:**	4843707.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	08/13/1962	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932035041
Layer:	2
Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	09
Material 2 Desc:	MEDIUM SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	15.0
Formation End Depth:	36.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035040
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	05

Material 1 Desc:	CLAY
Material 2:	09
Material 2 Desc:	MEDIUM SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901628
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10865043
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523113
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	36.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901628
Pump Set At:	
Static Level:	21.0
Final Level After Pumping:	
Recommended Pump Depth:	34.0
Pumping Rate:	0.0
Flowing Rate:	
Recommended Pump Rate:	0.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933789579
Layer:	1
Kind Code:	1
Kind:	FRESH

Water Found Depth: 32.0
Water Found Depth UOM: ft

---

220 | **1 of 1** | **ESE/224.4** | **229.9 / -12.08** | **ENBRIDGE CONSUMERS GAS**
54 Kingswood Drive, Brampton
ON | **SPL**

Ref No: 1-1TK361
Year:
Incident Dt: 5/25/2022 7:45:54 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/25/2022 7:45:56 PM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 54 Kingswood Drive, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: ENBRIDGE CONSUMERS GAS
Client Type: Private Business
Source Type:
Incident Cause:
Incident Preceding Spill: Line Strike
Incident Reason:
Incident Summary: TSSA FSB: 1/2" pl IP service damage, made safe
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see notes
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: NATURAL GAS
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill: Construction or repair
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:
Sector Type: NATURAL GAS DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001774563"],"wkts":["POINT (-79.7616989000 43.7032640000)"],"creation_date":"2022-05-25"}
Time Reported:
System Facility Address:

---

221 | **1 of 1** | **ESE/133.6** | **221.1 / -20.88** | **27 TOLTON DRIVE**
BRAMPTON ON L6V 2P9 | **HINC**

External File Num: FS INC 0902-00661

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Fuel Occurrence Type:	Explosion
Date of Occurrence:	2/2/2009
Fuel Type Involved:	Propane
Status Desc:	Completed - Causal Analysis(End)
Job Type Desc:	Incident/Near-Miss Occurrence (FS)
Oper. Type Involved:	Private Dwelling
Service Interruptions:	No
Property Damage:	Yes
Fuel Life Cycle Stage:	Utilization
Root Cause:	Root Cause: Equipment/Material/Component:No Procedures:Yes Maintenance:No Design:No Training:No Management:Yes Human Factors:Yes
Reported Details:	
Fuel Category:	Unknown
Occurrence Type:	Incident
Affiliation:	Emergency Services (Fire, Police,etc)
County Name:	Peel
Approx. Quant. Rel:	
Nearby body of water:	
Enter Drainage Syst.:	
Approx. Quant. Unit:	
Environmental Impact:	

---

222 | ***1 of 1*** | ***WNW/187.2*** | ***260.9 / 18.92*** | ***12891 McLaughlin Road Caledon ON*** | ***EHS***

Order No:	20091112013	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	11/13/2009	**Search Radius (km):**	0.25
Date Received:	11/12/2009	**X:**	-79.85743
Previous Site Name:		**Y:**	43.741053
Lot/Building Size:			
Additional Info Ordered:			

---

223 | ***1 of 1*** | ***ESE/125.9*** | ***214.7 / -27.22*** | ***Dales Dump (suspected)*** | ***ANDR***

Brampton ON L6V

Legal Description:	Chinguacousy
Location Description:	Dales Estate, Vodden St
Municipality:	Brampton Town
Current Municipality:	Brampton City
RM:	Peel Region
Facility:	Dump
Date Active:	1963
Date Begun:	1963
Date Complete:	
Area (Ha):	
Landfill Type:	
Group Name:	
Operated By:	
Serial:	PEEL26
NTS:	30M12
Diameter (m):	206

Historical Summary:

Dales Dump, Vodden St In February 1963 there was a fire at Dales Dump on Vodden St (RPA: RG5 79.0001 Feb 16 1963 Dump). In June 1963 there was another fire involving garbage in the dump on the Dales Estate on Vodden St (RPA: RG5 79.0001 Jun 28 1963 Dump). 1964 NTS Map 30M12W Vodden St runs east-west from Hurontario St to Highway 7. There are no obvios cluse ast to dump location. 1971 Air Photos Vodden St appears incomplete between a portion extending east from Hurontario St to Etobicoke Creek. East of the creek, Vodden is partially laid out and built. A large active ground disturbance is visible @UTM NAD27 599200--4838550 with 13mm diameter @ 1:15820 or 206m. This area, though would be southwest

of modern Sproule Dr and Willams Dr, but access to the site appears to have been via Vodden St (YUML: 1971 Air Photos FL 4329 Roll 52 #42). Working conclusion It appears very likely that there was a dump on the Dales Estate property on Vodden St Brampton, which was active in 1963, although its exact location has yet to be determined. The 1971 ground disturbance with centroid @ UTM NAD27 599200--4838550 has to be regarded as a strong possibility.

Waste Type: garbage, ashes & rubbish
UTM X Nad 27: 599200
UTM Y Nad 27: 4838550
UTM Zone: 17

---

224 | ***1 of 2*** | ***ESE/149.1*** | ***229.9 / -12.08*** | ***Enbridge Gas Distribution Inc.*** ***19 Vodden Crt*** ***Brampton ON*** | ***SPL***

Ref No: 4206-9PWQR2
Year:
Incident Dt: 2014/10/15
Dt MOE Arvl on Scn:
MOE Reported Dt: 2014/10/15
Dt Document Closed: 2014/12/20
Site No: NA
MOE Response: Referral to others
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Residential<UNOFFICIAL>
Site Address: 19 Vodden Crt
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Enbridge Gas Distribution Inc.
Client Type:
Source Type:
Incident Cause: Leak/Break
Incident Preceding Spill:
Incident Reason: Operator/Human Error
Incident Summary: TSSA: Enbridge, 1 1/4 inch damage, safe
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Valve/Fitting/Piping
SAC Action Class: TSSA - Boilers & Pressure Vessels Safety Program
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
224	2 of 2	ESE/149.1	229.9 / -12.08	PIPELINE HIT - 1 ¼" 19 VODDEN COURT,,BRAMPTON,ON,L6V 2V7, CA ON	PINC

Incident Id:
Incident No: 1499470
Incident Reported Dt: 10/15/2014
Type: FS-Pipeline Incident
Status Code:
Tank Status: Not Investigated
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:
Customer Acct Name: PIPELINE HIT - 1 ¼"
Incident Address: 19 VODDEN COURT,,BRAMPTON,ON,L6V 2V7,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
225	1 of 1	ESE/211.9	229.9 / -12.08	71 Greene Drive BRAMPTON ON L6V 2P2	HINC

External File Num: FS INC 0611-03669
Fuel Occurrence Type:
Date of Occurrence:
Fuel Type Involved:
Status Desc: Pending Level 1 Occurrence Investigation
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved:
Service Interruptions:
Property Damage:
Fuel Life Cycle Stage:
Root Cause:
Reported Details:
Fuel Category: Gaseous Fuel
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Peel
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
226	1 of 2	ESE/245.8	230.3 / -11.64	Enbridge Gas Distribution Inc. 40 Greene Drive Brampton ON L6V 2R7	SPL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	0422-8LVK7K	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/20/2011	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/20/2011	**Impact to Health:**	
Dt Document Closed:	10/6/2011	**Agency Involved:**	
Site No:			
MOE Response:	Not MOE mandate		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Pipeline<UNOFFICIAL>		
Site Address:	40 Greene Drive		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Enbridge Gas Distribution Inc.		
Client Type:			
Source Type:			
Incident Cause:	Pipe Or Hose Leak		
Incident Preceding Spill:			
Incident Reason:	Other - Reason not otherwise defined		
Incident Summary:	TSSAfsb- 1 1/4" Plastic Main Strike		
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Air Pollution; Human Health/Safety		
Contaminant Qty:	0 other - see incident description		
Contaminant Qty 1:	0		
Contaminant Unit:	other - see incident description		
Contaminant Code:	35		
Contaminant Name:	NATURAL GAS (METHANE)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Pipeline		
SAC Action Class:	TSSA - Fuel Safety Branch		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
226	2 of 2	ESE/245.8	230.3 / -11.64	40 Greene Drive, Brampton ON	PINC

Incident Id:		**Pipe Material:**	
Incident No:	659524	**Fuel Category:**	Natural Gas
Incident Reported Dt:		**Health Impact:**	
Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:	Pipeline Damage Reason Est	**Property Damage:**	No
Tank Status:	RC Established	**Service Interrupt:**	
Task No:	3482790	**Enforce Policy:**	Yes
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Date of Occurrence:		**Attribute Category:**	FS-Perform P-line Inc Invest
Occurrence Start Dt:	2011/09/20	**Regulator Location:**	
Depth:		**Method Details:**	E-mail
Customer Acct Name:			
Incident Address:			
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:	40 Greene Drive, Brampton - 1 ¼" Pipeline Hit		
Reported By:	Bill Reid - Enbridge		
Affiliation:			
Occurrence Desc:			
Damage Reason:	Excavation practices not sufficient		
Notes:			

---

227 | **1 of 1** | **SE/104.3** | **217.9 / -24.03** | **344 Main Street North Brampton ON L6V 1P8** | **EHS**

Order No:	20191120305	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Express Report	**Client Prov/State:**	ON
Report Date:	20-NOV-19	**Search Radius (km):**	.25
Date Received:	20-NOV-19	**X:**	-79.7702285
Previous Site Name:		**Y:**	43.6937294
Lot/Building Size:			
Additional Info Ordered:	Topographic Maps		

---

228 | **1 of 2** | **ESE/89.5** | **227.0 / -14.94** | **ENBRIDGE GAS INC 21 CHERYL CRT,,BRAMPTON,ON,L6V 3C2,CA ON** | **PINC**

Incident Id:		**Pipe Material:**	
Incident No:	3116534	**Fuel Category:**	
Incident Reported Dt:	10/4/2021	**Health Impact:**	
Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:		**Property Damage:**	
Tank Status:	Pipeline Damage Reason Est	**Service Interrupt:**	
Task No:		**Enforce Policy:**	
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	
Depth:		**Method Details:**	
Customer Acct Name:	ENBRIDGE GAS INC		
Incident Address:	21 CHERYL CRT,,BRAMPTON,ON,L6V 3C2,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

---

228 | **2 of 2** | **ESE/89.5** | **227.0 / -14.94** | **ENBRIDGE CONSUMERS GAS 21 Cheryl Court, Brampton BRAMPTON ON** | **SPL**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	1-1ARBAE	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	10/2/2021 8:15:00 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/2/2021 11:02:18 AM	**Impact to Health:**	0 No Impact
Dt Document Closed:	11/11/2021 9:35:01 AM	**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	21 Cheryl Court, Brampton		
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	ENBRIDGE CONSUMERS GAS		
Client Type:	Private Business		
Source Type:	Pipeline/Components		
Incident Cause:			
Incident Preceding Spill:	Line Strike		
Incident Reason:	Human error (Specify)		
Incident Summary:	TSSA: 1/2" plastic IP service line strike by homeowner		
Environment Impact:	1 Minor Impact		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	0 other - see notes		
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:	NATURAL GAS		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Air		
Activity Preceding Spill:	Construction or repair		
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula		
Property Tertiary Watershed:	02HC-Humber - Don		
Sector Type:	NATURAL GAS DISTRIBUTION		
SAC Action Class:			
Call Report Locatn Geodata:	{"integration_ids":["PR00001795625"],"wkts":["POINT (-79.7640931000 43.6991380000)"],"creation_date":"2021-10-02"}		
Time Reported:			
System Facility Address:			

229	1 of 1	WNW/121.4	260.9 / 18.92	12891 Mclaughlin Road Caledon ON	EHS

Order No:	20130813007	**Nearest Intersection:**	
Status:	C	**Municipality:**	Town of Caledon
Report Type:	Custom Report	**Client Prov/State:**	NS
Report Date:	16-AUG-13	**Search Radius (km):**	.25
Date Received:	13-AUG-13	**X:**	-79.857437
Previous Site Name:	Residential and agricultural	**Y:**	43.741894
Lot/Building Size:	~19 acres		
Additional Info Ordered:	Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
230	1 of 1	ESE/79.8	228.7 / -13.24	DUFFERIN-PEEL R.C.S.S. BOARD ST. ANNE 124 VODDEN ST BRAMPTON ON	GEN

Generator Info

Generator No:	ON0829854	**Choice of Contact:**	
Approval Years:	93,94	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	0000
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	*** NOT DEFINED ***		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
231	1 of 7	SE/89.5	218.8 / -23.16	PETER'S NO FRILLS 345 MAIN STREET BRAMPTON ON L6X1N6	PES

Detail Licence No:	23-01-11732-0	**Operator Box:**	
Licence No:	11732	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	4529122
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	1
Lot:		**Operator County:**	49
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
231	2 of 7	SE/89.5	218.8 / -23.16	1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS 345 MAIN ST N BRAMPTON ON L6X 1N6	PES

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			

PDF URL:

---

231 | ***3 of 7*** | ***SE/89.5*** | ***218.8 / -23.16*** | ***1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS***
345 MAIN ST N
BRAMPTON ON L6X 1N6 | ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:		***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:		***Oper Area Code:***	
Licence Type:	Vendor	***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

---

231 | ***4 of 7*** | ***SE/89.5*** | ***218.8 / -23.16*** | ***1408939 ONTARIO LIMITED O/A SAM'S NO FRILLS***
345 MAIN ST N
BRAMPTON ON L6X1N6 | ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:	12526	***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:	Legacy Licenses (Excluding TS)	***Oper Area Code:***	905
Licence Type:	Limited Vendor	***Oper Phone No:***	4529122
Licence Type Code:	23	***Operator Ext:***	
Licence Class:	01	***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

---

231 | ***5 of 7*** | ***SE/89.5*** | ***218.8 / -23.16*** | ***Vari-Therm Limited***
345 Main St N
Brampton ON | ***SPL***

Ref No:	4858-AXNRS2	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2018/04/09	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2018/04/09	***Impact to Health:***	2 - Minor Environment
Dt Document Closed:		***Agency Involved:***	

Site No:	NA
MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Sam's No Frills<UNOFFICIAL>
Site Address:	345 Main St N
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	Vari-Therm Limited
Client Type:	Corporation
Source Type:	Other
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Equipment Failure
Incident Summary:	No Frills: ~ 125 kg of R 507 to atm
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	125 kg
Contaminant Qty 1:	125
Contaminant Unit:	kg
Contaminant Code:	38
Contaminant Name:	REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	1078
Receiving Medium:	Air
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Air Spills - Gases and Vapours
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

231 | ***6 of 7*** | ***SE/89.5*** | ***218.8 / -23.16*** | ***FORTINO'S (VODDEN) LTD.***
345 MAIN STREET NORTH
BRAMPTON ON L6X1N6 | ***PES***

Detail Licence No:		**Operator Box:**	
Licence No:	10625	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Retail Vendor Class 03	**Oper Phone No:**	4536734
Licence Type Code:	21	**Operator Ext:**	
Licence Class:	03	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

County: **SWP Area Name:**
Trade Name:
PDF URL:

---

231 **7 of 7** **SE/89.5** **218.8 / -23.16** **345 Main Street N**
BRAMPTON ON
SPL

Ref No: 1-1IHABO **Municipality No:**
Year: **Nature of Damage:**
Incident Dt: 12/30/2021 9:00:00 AM **Discharger Report:**
Dt MOE Arvl on Scn: **Material Group:**
MOE Reported Dt: 12/30/2021 5:33:46 PM **Impact to Health:** 0 No Impact
Dt Document Closed: **Agency Involved:**
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 345 Main Street N
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type: Valve/Fitting/Piping
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason:
Incident Summary: R507 Refrigerant Leak - 240 kg, Farzin's No Frills, Brampton
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 240 kilogram (kg)
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: FREON
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Activity Preceding Spill: Normal operations
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HB - Credit - 16 Mile
Sector Type: SUPERMARKETS AND OTHER GROCERY (EXCEPT CONVENIENCE) STORES
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001723070"],"wkts":["POINT (-79.7707399000 43.6932411000)"],"creation_date":"2021-12-30"}
Time Reported:
System Facility Address:

---

232 **1 of 5** **SE/73.9** **216.0 / -25.94** **HY & ZEL'S INC.**
12 VODDEN STREET
BRAMPTON ON L6Y 1A2
GEN

Generator Info

Generator No:	ON2370416	***Choice of Contact:***	
Approval Years:	00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6031
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHARMACIES		

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

232 ***2 of 5*** ***SE/73.9*** ***216.0 / -25.94*** ***HY & ZELS - BRAMPTON***
12 VODDEN STREET
BRAMPTON ON L6Y1A2 ***PES***

Detail Licence No:		***Operator Box:***	
Licence No:		***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:		***Oper Area Code:***	
Licence Type:	Limited Vendor	***Oper Phone No:***	
Licence Type Code:	23	***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

---

232 ***3 of 5*** ***SE/73.9*** ***216.0 / -25.94*** ***Big Lots Canada Inc.***
12 Vodden Street East
Brampton ON ***GEN***

Generator Info

Generator No:	ON7084002	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	453999
Country:			
Co Admin:			
Phone No Admin:			

SIC Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)

Waste Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

232 | **4 of 5** | **SE/73.9** | **216.0 / -25.94** | **Big Lots Canada Inc.**
12 Vodden Street East
Brampton ON | **GEN**

Generator Info

Generator No:	ON7084002	**Choice of Contact:**	
Approval Years:	2012	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	453999
Country:			
Co Admin:			
Phone No Admin:			

SIC Description: All Other Miscellaneous Store Retailers (except Beer and Wine-Making Supplies Stores)

---

232 | **5 of 5** | **SE/73.9** | **216.0 / -25.94** | **HY & ZELS - BRAMPTON**
12 VODDEN STREET
BRAMPTON ON L6Y1A2 | **PES**

Detail Licence No:		**Operator Box:**	
Licence No:	12981	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	4540073
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

233 | **1 of 1** | **ESE/59.7** | **224.1 / -17.82** | **222 CENTRE STREET NORTH**
BRAMPTON ON L6V 2R4 | **HINC**

External File Num:	FS INC 0906-03486
Fuel Occurrence Type:	
Date of Occurrence:	
Fuel Type Involved:	
Status Desc:	Pending Level 1 Occurrence Investigation
Job Type Desc:	Incident/Near-Miss Occurrence (FS)
Oper. Type Involved:	
Service Interruptions:	
Property Damage:	
Fuel Life Cycle Stage:	
Root Cause:	
Reported Details:	

Fuel Category: Gaseous Fuel
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Peel
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

---

234 | ***1 of 1*** | ***ESE/47.9*** | ***219.9 / -22.08*** | ***36 Newby Court BRAMPTON ON*** | ***SPL***

Ref No: 1-12I2B4
Year:
Incident Dt: 8/5/2021 11:00:46 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/6/2021 12:55:52 AM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 36 Newby Court
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type: Transformer
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Vandalism/deliberate act
Incident Summary: Alectra - 50 L mineral oil to ground
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 50 litre (L)
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: MINERAL OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill: Unknown
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HC-Humber - Don
Sector Type: ELECTRIC POWER DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001868447"],"wkts":["POINT (-79.7658145000 43.6970215000)"],"creation_date":"2021-08-06"}
Time Reported:
System Facility Address:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
235	1 of 53	ESE/53.3	214.2 / -27.74	VODDEN XRAY 36 VODDEN STREET EAST BRAMPTON ON L6V 1M4	GEN

Generator Info

Generator No:	ON2185000	**Choice of Contact:**	
Approval Years:	96,97,98,99,00,01	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	8682
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	RADIOLOGICAL LAB.		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
235	2 of 53	ESE/53.3	214.2 / -27.74	VODDEN MEDICAL ARTS PHARMACY 36 VODDEN STREET EAST BRAMPTON ON L6V 1M4	GEN

Generator Info

Generator No:	ON2564800	**Choice of Contact:**	
Approval Years:	00,01	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6031
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHARMACIES		

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
235	3 of 53	ESE/53.3	214.2 / -27.74	VODDEN MEDICAL ARTS PHARMACY 36 vodden st e brampton ON L6V 4H4	GEN

Generator Info

Generator No:	ON2564800	**Choice of Contact:**	
Approval Years:	02,03,04	**Contaminated Fac:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: ***MHSW Facility:***
PO Box No: ***SIC Code:***
Country:
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***4 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***36 Vodden Street East Brampton ON L6V 4H4*** ***EHS***

Order No: 20050225006
Status: C
Report Type:
Report Date: 3/1/2005
Date Received: 2/25/2005
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Additional AND Report

Nearest Intersection: Main Street North
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.767816
Y: 43.694564

---

235 ***5 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***CMLHealthCare 36 Vodden Street East Brampton ON L6V 4H4*** ***GEN***

Generator Info

Generator No: ON5048494
Approval Years: 2009
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Medical and Diagnostic Laboratories

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621510

---

235 ***6 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***1798836 Ontario Inc. 36 Vodden Street, Suite 304 Brampton ON L6V 4H4*** ***GEN***

Generator Info

Generator No: ON2595063
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 623110

SIC Description: Nursing Care Facilities

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***7 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***Saint Elizabeth Health Care*** ***36 Vodden St. E, Suite 304*** ***Brampton ON L6V 4H4*** | ***GEN***

Generator Info

Generator No: ON6716255
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Ambulatory Health Care Services

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621990

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***8 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***CMLHealthCare*** ***36 Vodden Street East*** ***Brampton ON L6V 4H4*** | ***GEN***

Generator Info

Generator No: ON5048494
Approval Years: 2010
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Medical and Diagnostic Laboratories

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621510

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***9 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***Saint Elizabeth Health Care*** ***36 Vodden St. E, Suite 304*** ***Brampton ON L6V 4H4*** | ***GEN***

Generator Info

Generator No: ON6716255
Approval Years: 2011

Choice of Contact:
Contaminated Fac:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 621990
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Ambulatory Health Care Services

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***10 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***North Brampton Physiotherapy*** ***GEN***
36 Vodden Street E. Suite 306
Brampton ON L6V 4H4

Generator Info

Generator No: ON4647424 ***Choice of Contact:***
Approval Years: 2011 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 621340
Country:
Co Admin:
Phone No Admin:
SIC Description:

---

235 ***11 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***CMLHealthCare*** ***GEN***
36 Vodden Street East
Brampton ON L6V 4H4

Generator Info

Generator No: ON5048494 ***Choice of Contact:***
Approval Years: 2011 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 621510
Country:
Co Admin:
Phone No Admin:
SIC Description: Medical and Diagnostic Laboratories

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***12 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***1798836 Ontario Inc.*** ***GEN***
36 Vodden Street, Suite 304
Brampton ON L6V 4H4

Generator Info

Generator No: ON2595063 ***Choice of Contact:***
Approval Years: 2011 ***Contaminated Fac:***
Status: ***MHSW Facility:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Nursing Care Facilities

SIC Code: 623110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***13 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***Saint Elizabeth Health Care*** | ***GEN***
36 Vodden St. E, Suite 304
Brampton ON L6V 4H4

Generator Info

Generator No: ON6716255
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: All Other Ambulatory Health Care Services

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621990

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***14 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***1798836 Ontario Inc.*** | ***GEN***
36 Vodden Street, Suite 304
Brampton ON L6V 4H4

Generator Info

Generator No: ON2595063
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Nursing Care Facilities

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 623110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***15 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***North Brampton Physiotherapy*** | ***GEN***
36 Vodden Street E. Suite 306
Brampton ON L6V 4H4

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON4647424	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621340
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Offices of Physical Occupational and Speech Therapists and Audiologists		

---

235 ***16 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***LifeLabs LP*** ***GEN***
36 Vodden Street East
Brampton ON L6V 4H4

Generator Info

Generator No:	ON5048494	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621510
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Medical and Diagnostic Laboratories		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

235 ***17 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***36 Vodden Street East*** ***EHS***
Brampton ON

Order No:	20131108007	***Nearest Intersection:***	
Status:	C	***Municipality:***	Peel
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	18-NOV-13	***Search Radius (km):***	.25
Date Received:	08-NOV-13	***X:***	-79.768046
Previous Site Name:		***Y:***	43.694757
Lot/Building Size:	8 sq. meters		
Additional Info Ordered:			

---

235 ***18 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***LifeLabs LP*** ***GEN***
36 Vodden Street East
Brampton ON

Generator Info

Generator No:	ON5048494	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621510
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	MEDICAL AND DIAGNOSTIC LABORATORIES		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***19 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***Saint Elizabeth Health Care*** ***GEN***
36 Vodden St. E, Suite 304
Brampton ON

Generator Info

Generator No: ON6716255
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ALL OTHER AMBULATORY HEALTH CARE SERVICES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621990

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***20 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***Wise Elephant FHT*** ***GEN***
36 Vodden Street E
Suite 203 ON

Generator Info

Generator No: ON9090044
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: OFFICES OF PHYSICIANS

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***21 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***1798836 Ontario Inc.*** ***GEN***
36 Vodden Street, Suite 304
Brampton ON

Generator Info

Generator No: ON2595063
Approval Years: 2013
Status:
PO Box No:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 623110

Country:
Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***22 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***36 Vodden Street East Brampton ON*** ***EHS***

Order No: 20150612060
Status: C
Report Type: Standard Report
Report Date: 16-JUN-15
Date Received: 12-JUN-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: MA
Search Radius (km): .25
X: -79.767875
Y: 43.694587

---

235 ***23 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***Saint Elizabeth Health Care 36 Vodden St. E, Suite 305 Brampton ON L6V 4H4*** ***GEN***

Generator Info

Generator No: ON6716255
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Sam Gray
Phone No Admin: 800-263-1857 Ext.203
SIC Description: ALL OTHER AMBULATORY HEALTH CARE SERVICES

Choice of Contact: CO_ADMIN
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621990

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***24 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***Wise Elephant FHT 36 Vodden Street E Suite 203 ON L6V4H4*** ***GEN***

Generator Info

Generator No: ON9090044
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: OFFICES OF PHYSICIANS

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***25 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***Saint Elizabeth Health Care*** ***GEN***
36 Vodden St. E, Suite 305
Brampton ON L6V 4H4

Generator Info

Generator No: ON6716255
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Liliana Candaic
Phone No Admin: 905-826-0854 Ext.5203
SIC Description: ALL OTHER AMBULATORY HEALTH CARE SERVICES
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621990

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***26 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***LifeLabs LP*** ***GEN***
36 Vodden Street East
Brampton ON L6V 4H4

Generator Info

Generator No: ON5048494
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: MEDICAL AND DIAGNOSTIC LABORATORIES
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621510

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 ***27 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***1798836 Ontario Inc.*** ***GEN***
36 Vodden Street, Suite 304
Brampton ON L6V 4H4

Generator Info

Generator No: ON2595063
Approval Years: 2016
Status:
PO Box No:
Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 623110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Co Admin:
Phone No Admin:
SIC Description: 623110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***28 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***LifeLabs LP*** ***36 Vodden Street East*** ***Brampton ON L6V 4H4*** | ***GEN***

Generator Info

Generator No: ON5048494
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: MEDICAL AND DIAGNOSTIC LABORATORIES

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621510

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***29 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***Wise Elephant FHT*** ***36 Vodden Street E*** ***Suite 203 ON L6V4H4*** | ***GEN***

Generator Info

Generator No: ON9090044
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description: OFFICES OF PHYSICIANS

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

235 | ***30 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***1798836 Ontario Inc.*** ***36 Vodden Street, Suite 304*** ***Brampton ON L6V 4H4*** | ***GEN***

Generator Info

Generator No:	ON2595063	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	623110
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	623110		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

235 | ***31 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***Saint Elizabeth Health Care*** ***36 Vodden St. E, Suite 305*** ***Brampton ON L6V 4H4*** | ***GEN***

Generator Info

Generator No:	ON6716255	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2014	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	621990
Country:	Canada		
Co Admin:	Liliana Candaic		
Phone No Admin:	905-826-0854 Ext.5203		
SIC Description:	ALL OTHER AMBULATORY HEALTH CARE SERVICES		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

235 | ***32 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***Wise Elephant FHT*** ***36 Vodden Street E*** ***Suite 203 ON L6V4H4*** | ***GEN***

Generator Info

Generator No:	ON9090044	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2014	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	621110
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	OFFICES OF PHYSICIANS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

235 | ***33 of 53*** | ***ESE/53.3*** | ***214.2 / -27.74*** | ***1798836 Ontario Inc.*** ***36 Vodden Street, Suite 304*** | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON L6V 4H4	

Generator Info

Generator No:	ON2595063	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	623110
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	623110		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

235	***34 of 53***	***ESE/53.3***	***214.2 / -27.74***	***LifeLabs LP*** ***36 Vodden Street East*** ***Brampton ON L5C1V8***	***GEN***

Generator Info

Generator No:	ON5048494	***Choice of Contact:***	CO_ADMIN
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621510
Country:	Canada		
Co Admin:	Jacquie Maertz		
Phone No Admin:	905 565 0433 Ext.2202		
SIC Description:	MEDICAL AND DIAGNOSTIC LABORATORIES		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

235	***35 of 53***	***ESE/53.3***	***214.2 / -27.74***	***LifeLabs LP*** ***36 Vodden Street East*** ***Brampton ON L6V 4H4***	***GEN***

Generator Info

Generator No:	ON5048494	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			

235	36 of 53	ESE/53.3	214.2 / -27.74	**SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION** **36 Vodden St E Suite 105** **Brampton ON L6V 4H4**	GEN

Generator Info

Generator No:	ON4280337	**Choice of Contact:**	
Approval Years:	As of Dec 2018	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

235	37 of 53	ESE/53.3	214.2 / -27.74	**Wise Elephant FHT** **36 Vodden Street E** **Suite 203 ON L6V4H4**	GEN

Generator Info

Generator No:	ON9090044	**Choice of Contact:**	
Approval Years:	As of Dec 2017	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

2017 Generator Info

Gen No:	ON9090044	**Choice of Contact:**	CO_OFFICIAL
ID:	35520	**Phone No Official:**	9054594385 Ext.201
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Wise Elephant FHT		
Gen Div:			
Gen Op Name:	Wise Elephant FHT		
Gen Op Div:			
Site Adrs1:	36 Vodden Street E		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Suite 203
Province Out:
Site Postal Code: L6V4H4
Site Country: Canada
Co Official: Natalie Young
Co Admin:

2017 Generator Manifest

ID: 63733
Generator No: ON9090044
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 133.0
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 4
District: 305

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
235	38 of 53	ESE/53.3	214.2 / -27.74	Saint Elizabeth Health Care 36 Vodden St. E, Suite 305 Brampton ON L6V 4H4	GEN

Generator Info

Generator No: ON6716255
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
235	39 of 53	ESE/53.3	214.2 / -27.74	36 Vodden St E Brampton ON L6V4H4	EHS

Order No: 20170328163
Status: C
Report Type: Standard Report
Report Date: 04-APR-17
Date Received: 28-MAR-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.768217
Y: 43.694871

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
235	40 of 53	ESE/53.3	214.2 / -27.74	LifeLabs LP 36 Vodden Street East Brampton ON L6V 4H4	GEN

Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON5048494
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

235	41 of 53	ESE/53.3	214.2 / -27.74	**Saint Elizabeth Health Care** **36 Vodden St. E, Suite 305** **Brampton ON L6V 4H4**	GEN

Generator Info

Generator No: ON6716255
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

235	42 of 53	ESE/53.3	214.2 / -27.74	**SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION** **36 Vodden St E Suite 105** **Brampton ON L6V 4H4**	GEN

Generator Info

Generator No: ON4280337
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

235	43 of 53	ESE/53.3	214.2 / -27.74	**COMPLETE IMMIGRATION MEDICAL CENTRE** **36 VODDEN STREET EAST,SUITE 203**	GEN

BRAMPTON ON L6V4H4

Generator Info

Generator No:	ON3671124	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

235	***44 of 53***	***ESE/53.3***	***214.2 / -27.74***	***SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION*** ***36 Vodden St E Suite 105*** ***Brampton ON L6V 4H4***	***GEN***

Generator Info

Generator No:	ON4280337	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Waste Detail(s)

Waste Class:	148 C
Waste Class Name:	Misc. wastes and inorganic chemicals

235	***45 of 53***	***ESE/53.3***	***214.2 / -27.74***	***Saint Elizabeth Health Care*** ***36 Vodden St. E, Suite 305*** ***Brampton ON L6V 4H4***	***GEN***

Generator Info

Generator No:	ON6716255	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Phone No Admin:
SIC Description:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

235	***46 of 53***	***ESE/53.3***	***214.2 / -27.74***	***COMPLETE IMMIGRATION MEDICAL CENTRE 36 VODDEN STREET EAST,SUITE 203 BRAMPTON ON L6V4H4***	***GEN***

Generator Info

Generator No: ON3671124
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

235	***47 of 53***	***ESE/53.3***	***214.2 / -27.74***	***LifeLabs LP 36 Vodden Street East Brampton ON L6V 4H4***	***GEN***

Generator Info

Generator No: ON5048494
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

235	***48 of 53***	***ESE/53.3***	***214.2 / -27.74***	***Complete Immigration Medical Centre 36 VODDEN STREET EAST,SUITE 203 BRAMPTON ON***	***GEN***

Generator Info

Generator No:	ON3671124	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

Generator Info as of Dec 2024

Generator No:	ON3671124
Generator Company Name:	Complete Immigration Medical Centre
Street:	36 VODDEN STREET EAST,SUITE 203
City:	BRAMPTON
Province State:	Ontario
Country:	Canada
Postal Code:	L6V4H4
Waste Class:	312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

2019 Generator Info

Gen No:	ON3671124	***Choice of Contact:***	CO_OFFICIAL
ID:	14466	***Phone No Official:***	905 459 2700 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	METROPOLITAN TORONTO
NAICS Code1:	621110	***County Out:***	
NAICS Code2:		***District:***	301
NAICS Code3:			
Gen Name:	COMPLETE IMMIGRATION MEDICAL CENTRE		
Gen Div:			
Gen Op Name:	COMPLETE IMMIGRATION MEDICAL CENTRE		
Gen Op Div:			
Site Adrs1:	36 VODDEN STREET EAST,SUITE 203		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6V4H4		
Site Country:	Canada		
Co Official:	JASMEEN KAUR BRAR		
Co Admin:			

2020 Generator Info

Gen No:	ON3671124	***Choice of Contact:***	CO_OFFICIAL
ID:	14123	***Phone No Official:***	905 459 2700 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	METROPOLITAN TORONTO
NAICS Code1:	621110	***County Out:***	

NAICS Code2:		***District:***	301
NAICS Code3:			
Gen Name:	COMPLETE IMMIGRATION MEDICAL CENTRE		
Gen Div:			
Gen Op Name:	COMPLETE IMMIGRATION MEDICAL CENTRE		
Gen Op Div:			
Site Adrs1:	36 VODDEN STREET EAST,SUITE 203		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6V4H4		
Site Country:	Canada		
Co Official:	JASMEEN KAUR BRAR		
Co Admin:			

2020 Generator Manifest

ID:	33608	***Sum Received Qty:***	38.4
Generator No:	ON3671124	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	3
Waste Char:	P	***District:***	305
Waste Code:	312		

2021 Generator Info

Gen No:	ON3671124	***Choice of Contact:***	CO_OFFICIAL
ID:	14019	***Phone No Official:***	905 459 2700 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	METROPOLITAN TORONTO
NAICS Code1:	621110	***County Out:***	
NAICS Code2:		***District:***	301
NAICS Code3:			
Gen Name:	COMPLETE IMMIGRATION MEDICAL CENTRE		
Gen Div:			
Gen Op Name:	COMPLETE IMMIGRATION MEDICAL CENTRE		
Gen Op Div:			
Site Adrs1:	36 VODDEN STREET EAST,SUITE 203		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6V4H4		
Site Country:	Canada		
Co Official:	JASMEEN KAUR BRAR		
Co Admin:			

2021 Generator Manifest

ID:	34182	***Sum Received Qty:***	104.28
Generator No:	ON3671124	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	6
Waste Char:	P	***District:***	305
Waste Code:	312		

235	***49 of 53***	***ESE/53.3***	***214.2 / -27.74***	***Saint Elizabeth Health Care*** ***36 Vodden St. E, Suite 202*** ***Brampton ON***	***GEN***

Generator Info

Generator No:	ON6716255	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

Generator Info as of Dec 2024

Generator No:	ON6716255
Generator Company Name:	Saint Elizabeth Health Care
Street:	36 Vodden St. E, Suite 202
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6V4H4
Waste Class:	312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

2017 Generator Info

Gen No:	ON6716255	***Choice of Contact:***	CO_ADMIN
ID:	26420	***Phone No Official:***	9059686472 Ext.
Contaminated Fac:	N	***Phone No Admin:***	800-263-1857 Ext.203
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621990	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Saint Elizabeth Health Care		
Gen Div:			
Gen Op Name:	Saint Elizabeth Health Care		
Gen Op Div:			
Site Adrs1:	36 Vodden St. E, Suite 305		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Heather Hickey		
Co Admin:	Sam Gray		

2018 Generator Info

Gen No:	ON6716255	***Choice of Contact:***	CO_ADMIN

ID:	26782	**Phone No Official:**	9059686472 Ext.
Contaminated Fac:	N	**Phone No Admin:**	800-263-1857 Ext.203
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621990	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Saint Elizabeth Health Care		
Gen Div:			
Gen Op Name:	Saint Elizabeth Health Care		
Gen Op Div:			
Site Adrs1:	36 Vodden St. E, Suite 305		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Heather Hickey		
Co Admin:	Sam Gray		

2018 Generator Manifest

ID:	52229	**Sum Received Qty:**	106.0
Generator No:	ON6716255	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	6
Waste Char:	P	**District:**	302
Waste Code:	312		

2019 Generator Info

Gen No:	ON6716255	**Choice of Contact:**	CO_ADMIN
ID:	27003	**Phone No Official:**	9059686472 Ext.
Contaminated Fac:	N	**Phone No Admin:**	800-263-1857 Ext.203
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621990	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Saint Elizabeth Health Care		
Gen Div:			
Gen Op Name:	Saint Elizabeth Health Care		
Gen Op Div:			
Site Adrs1:	36 Vodden St. E, Suite 305		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Heather Hickey		
Co Admin:	Sam Gray		

2019 Generator Manifest

ID:	52164	**Sum Received Qty:**	580.0
Generator No:	ON6716255	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	34
Waste Char:	P	**District:**	302
Waste Code:	312		

2020 Generator Info

Gen No:	ON6716255	***Choice of Contact:***	CO_ADMIN
ID:	26730	***Phone No Official:***	9059686472 Ext.
Contaminated Fac:	N	***Phone No Admin:***	800-263-1857 Ext.203
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621990	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Saint Elizabeth Health Care		
Gen Div:			
Gen Op Name:	Saint Elizabeth Health Care		
Gen Op Div:			
Site Adrs1:	36 Vodden St. E, Suite 305		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Heather Hickey		
Co Admin:	Sam Gray		

2020 Generator Manifest

ID:	48692	***Sum Received Qty:***	2895.0
Generator No:	ON6716255	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	95
Waste Char:	P	***District:***	302
Waste Code:	312		

2021 Generator Info

Gen No:	ON6716255	***Choice of Contact:***	CO_ADMIN
ID:	27201	***Phone No Official:***	9059686472 Ext.
Contaminated Fac:	N	***Phone No Admin:***	800-263-1857 Ext.203
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621990	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Saint Elizabeth Health Care		
Gen Div:			
Gen Op Name:	Saint Elizabeth Health Care		
Gen Op Div:			
Site Adrs1:	36 Vodden St. E, Suite 305		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Heather Hickey		
Co Admin:	Michael M		

2021 Generator Manifest

ID:	50556	***Sum Received Qty:***	1129.0
Generator No:	ON6716255	***Waste Class Name:***	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Receiver Type:	035	**Count Manifests:**	99
Waste Char:	P	**District:**	302
Waste Code:	312		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
235	50 of 53	ESE/53.3	214.2 / -27.74	LifeLabs LP 36 Vodden Street East Brampton ON L6V 4H4	GEN

Generator Info

Generator No:	ON5048494	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

2017 Generator Info

Gen No:	ON5048494	**Choice of Contact:**	CO_OFFICIAL
ID:	20031	**Phone No Official:**	905 565 0043 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621510	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	LifeLabs LP		
Gen Div:			
Gen Op Name:	LifeLabs LP		
Gen Op Div:			
Site Adrs1:	36 Vodden Street East		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Amber Daniels		
Co Admin:			

2017 Generator Manifest

ID:	44147	**Sum Received Qty:**	958.2
Generator No:	ON5048494	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	44
Waste Char:	P	**District:**	305
Waste Code:	312		

2018 Generator Info

Gen No:	ON5048494	**Choice of Contact:**	CO_OFFICIAL

ID:	20137	**Phone No Official:**	905 565 0043 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621510	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	LifeLabs LP		
Gen Div:			
Gen Op Name:	LifeLabs LP		
Gen Op Div:			
Site Adrs1:	36 Vodden Street East		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Amber Daniels		
Co Admin:			

2018 Generator Manifest

ID:	44073	**Sum Received Qty:**	1089.2
Generator No:	ON5048494	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	51
Waste Char:	P	**District:**	305
Waste Code:	312		

2019 Generator Info

Gen No:	ON5048494	**Choice of Contact:**	CO_OFFICIAL
ID:	20166	**Phone No Official:**	905 565 0043 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621510	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	LifeLabs LP		
Gen Div:			
Gen Op Name:	LifeLabs LP		
Gen Op Div:			
Site Adrs1:	36 Vodden Street East		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Amber Daniels		
Co Admin:			

2019 Generator Manifest

ID:	43622	**Sum Received Qty:**	1596.0
Generator No:	ON5048494	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	52
Waste Char:	P	**District:**	305
Waste Code:	312		

2020 Generator Info

Gen No:	ON5048494	***Choice of Contact:***	CO_OFFICIAL
ID:	19895	***Phone No Official:***	905 565 0043 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621510	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	LifeLabs LP		
Gen Div:			
Gen Op Name:	LifeLabs LP		
Gen Op Div:			
Site Adrs1:	36 Vodden Street East		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Amber Daniels		
Co Admin:			

2020 Generator Manifest

ID:	40325	***Sum Received Qty:***	1123.02
Generator No:	ON5048494	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	52
Waste Char:	P	***District:***	305
Waste Code:	312		

2021 Generator Info

Gen No:	ON5048494	***Choice of Contact:***	CO_OFFICIAL
ID:	20050	***Phone No Official:***	4162093990 Ext.
Contaminated Fac:	N	***Phone No Admin:***	
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621510	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	LifeLabs LP		
Gen Div:			
Gen Op Name:	LifeLabs LP		
Gen Op Div:			
Site Adrs1:	36 Vodden Street East		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	Stephen Vanderhorst		
Co Admin:			

2021 Generator Manifest

ID:	41690	***Sum Received Qty:***	1306.97
Generator No:	ON5048494	***Waste Class Name:***	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Receiver Type:	035	**Count Manifests:**	51
Waste Char:	P	**District:**	305
Waste Code:	312		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
235	51 of 53	ESE/53.3	214.2 / -27.74	Smilemakers Dental 36 Vodden St E Suite 105 Brampton ON	GEN

Generator Info

Generator No:	ON4280337	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	148 C
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Generator Info as of Dec 2024

Generator No:	ON4280337
Generator Company Name:	Smilemakers Dental
Street:	36 Vodden St E Suite 105
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6V4H4
Waste Class:	312 P,148 C

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 148 - INORGANIC LABORATORY CHEMICALS

2017 Generator Info

Gen No:	ON4280337	**Choice of Contact:**	CO_OFFICIAL
ID:	17071	**Phone No Official:**	9054570778 Ext.
Contaminated Fac:	N	**Phone No Admin:**	9054570778 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621210	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION		
Gen Div:			
Gen Op Name:	SMILEMAKERS DENTAL		
Gen Op Div:			
Site Adrs1:	36 Vodden St E Suite 105		
Site Bldg:			

Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L6V 4H4
Site Country: Canada
Co Official: SEEMA S SHETTY
Co Admin: MARIA G CORREIA

2017 Generator Manifest

ID: 40444
Generator No: ON4280337
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 3.6
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 1
District: 305

2018 Generator Info

Gen No: ON4280337
ID: 17070
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621210
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9054570778 Ext.
Phone No Admin: 9054570778 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION
Gen Div:
Gen Op Name: SMILEMAKERS DENTAL
Gen Op Div:
Site Adrs1: 36 Vodden St E Suite 105
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L6V 4H4
Site Country: Canada
Co Official: SEEMA S SHETTY
Co Admin: MARIA G CORREIA

2018 Generator Manifest

ID: 40323
Generator No: ON4280337
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 20.3
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 3
District: 305

2019 Generator Info

Gen No: ON4280337
ID: 16941
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621210
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 9054570778 Ext.
Phone No Admin: 9054570778 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION
Gen Div:

Gen Op Name:	SMILEMAKERS DENTAL
Gen Op Div:	
Site Adrs1:	36 Vodden St E Suite 105
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 4H4
Site Country:	Canada
Co Official:	SEEMA S SHETTY
Co Admin:	MARIA G CORREIA

2019 Generator Manifest

ID:	39614	**Sum Received Qty:**	10.0
Generator No:	ON4280337	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	P	**District:**	305
Waste Code:	312		

2020 Generator Info

Gen No:	ON4280337	**Choice of Contact:**	CO_OFFICIAL
ID:	16652	**Phone No Official:**	9054570778 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621210	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION
Gen Div:	
Gen Op Name:	SMILEMAKERS DENTAL
Gen Op Div:	
Site Adrs1:	36 Vodden St E Suite 105
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 4H4
Site Country:	Canada
Co Official:	SEEMA S SHETTY
Co Admin:	

2020 Generator Manifest

ID:	36565	**Sum Received Qty:**	6.4
Generator No:	ON4280337	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	P	**District:**	305
Waste Code:	312		

2021 Generator Info

Gen No:	ON4280337	**Choice of Contact:**	CO_OFFICIAL
ID:	16697	**Phone No Official:**	9054570778 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621210	**County Out:**	

NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	SEEMA S SHETTY DENTISTRY PROFESSIONAL CORPORATION		
Gen Div:			
Gen Op Name:	SMILEMAKERS DENTAL		
Gen Op Div:			
Site Adrs1:	36 Vodden St E Suite 105		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 4H4		
Site Country:	Canada		
Co Official:	SEEMA S SHETTY		
Co Admin:			

2021 Generator Manifest

ID:	37646	**Sum Received Qty:**	13.5
Generator No:	ON4280337	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	P	**District:**	305
Waste Code:	312		

---

235 ***52 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***36 Vodden Street East Brampton ON L6V 4H4*** ***EHS***

Order No:	21121200001	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	15-DEC-21	**Search Radius (km):**	.25
Date Received:	12-DEC-21	**X:**	-79.7682892
Previous Site Name:		**Y:**	43.6947634
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

---

235 ***53 of 53*** ***ESE/53.3*** ***214.2 / -27.74*** ***Coverdale Infusion Clinic Inc 36 Vodden Street East Brampton ON*** ***GEN***

Generator Info as of Dec 2024

Generator No:	ON001064145
Generator Company Name:	Coverdale Infusion Clinic Inc
Street:	36 Vodden Street East
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6V 4H4
Waste Class:	312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

---

236 ***1 of 1*** ***ESE/48.1*** ***224.1 / -17.88*** ***The Regional Municipality of Peel 220 Centre St. North*** ***SPL***

Brampton ON

Ref No:	7386-ANC9CY	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	6/15/2017	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	6/15/2017	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Watermain Break Site<UNOFFICIAL>		
Site Address:	220 Centre St. North		
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	The Regional Municipality of Peel		
Client Type:	Municipal Government		
Source Type:	Water Supply		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Incident Reason:	Unknown / N/A		
Incident Summary:	DWMD: Region of Peel: Water Main Break, Sediment to Etobicoke Creek		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	0 other - see incident description		
Contaminant Qty 1:	0		
Contaminant Unit:	other - see incident description		
Contaminant Code:	99		
Contaminant Name:	DRINKING WATER (FULLY TREATED)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	n/a		
Receiving Medium:	Surface Water; Source Water Zone		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Miscellaneous Communal		
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

237	1 of 1	ESE/44.8	213.9 / -28.08	36 VODDEN ST E Brampton ON	WWIS

Well ID:	7217101	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	02/27/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	

Audit No:	Z183319	**Contractor:**	7320
Tag:	A159432	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7217101.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/09/2014
Year Completed:	2014
Depth (m):	6.1
Latitude:	43.694967816833
Longitude:	-79.7679318124189
X:	-79.7679316619543
Y:	43.69496781507689
Path:	721\7217101.pdf

Bore Hole Information

Bore Hole ID:	1004716650	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	599285.00
Code OB Desc:		**North83:**	4838732.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/09/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005090540
Layer:	2
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.30000001192092896
Formation End Depth:	0.800000011920929
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID: 1005090542
Layer: 4
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2: 06
Material 2 Desc: SILT
Material 3:
Material 3 Desc:
Formation Top Depth: 3.4000000953674316
Formation End Depth: 3.799999952316284
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005090541
Layer: 3
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 0.800000011920929
Formation End Depth: 3.4000000953674316
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005090539
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005090543
Layer: 5
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2:
Material 2 Desc:

Material 3:
Material 3 Desc:
Formation Top Depth: 3.799999952316284
Formation End Depth: 6.099999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005090551
Layer: 2
Plug From: 2.700000047683716
Plug To: 6.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005090550
Layer: 1
Plug From: 0.0
Plug To: 2.700000047683716
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005090549
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1005090538
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005090546
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0999999046325684
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005090547
Layer: 1
Slot: 10
Screen Top Depth: 3.0999999046325684
Screen End Depth: 6.099999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm

Screen Diameter: 6.099999904632568

Water Details

Water ID: 1005090545
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005090544
Diameter: 16.0
Depth From: 0.0
Depth To: 6.099999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

---

238 | **1 of 1** | **SE/48.5** | **217.2 / -24.69** | **Microbase 2000 Systems Inc.**
332 Main St N Unit 1
Brampton ON L6V 1P8 | **SCT**

Established: 2006
Plant Size (ft²):
Employment:

--Details--
Description: Computer and Peripheral Equipment Manufacturing
SIC/NAICS Code: 334110

Description: Computer and Software Stores
SIC/NAICS Code: 443120

---

239 | **1 of 1** | **ESE/36.6** | **226.7 / -15.27** | **ON** | **WWIS**

Well ID: 4901072
Construction Date:
Use 1st: Domestic
Use 2nd: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 07/31/1951
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3514
Form Version: 1
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901072.pdf

Additional Detail(s) (Map)

Well Completed Date:	05/21/1951
Year Completed:	1951
Depth (m):	15.24
Latitude:	43.6988640730494
Longitude:	-79.7635382632048
X:	-79.76353811254481
Y:	43.69886407075697
Path:	490\4901072.pdf

Bore Hole Information

Bore Hole ID:	10315918	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	599632.60
Code OB Desc:		***North83:***	4839170.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	05/21/1951	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	p9

Location Method Desc:	Original Pre1985 UTM Rel Code 9: unknown UTM
Elevrc Desc:	
Location Source Date:	
Improvement Location Source:	
Improvement Location Method:	
Source Revision Comment:	
Supplier Comment:	

Overburden and Bedrock Materials Interval

Formation ID:	932032521
Layer:	3
Color:	
General Color:	
Material 1:	14
Material 1 Desc:	HARDPAN
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	20.0
Formation End Depth:	42.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932032519
Layer:	1
Color:	
General Color:	
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	4.0

Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932032520
Layer: 2
Color:
General Color:
Material 1: 13
Material 1 Desc: BOULDERS
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 4.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932032522
Layer: 4
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 42.0
Formation End Depth: 50.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964901072
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10864488
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930522372
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 42.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID:	930522373
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	50.0
Casing Diameter:	4.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901072
Pump Set At:	
Static Level:	5.0
Final Level After Pumping:	5.0
Recommended Pump Depth:	
Pumping Rate:	4.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

Water Details

Water ID:	933789057
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	48.0
Water Found Depth UOM:	ft

---

240 ***1 of 1*** ***ESE/30.6*** ***213.8 / -28.15*** ***36 VODDEN ST E Brampton ON*** ***WWIS***

Well ID:	7217099	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	02/27/2014
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z183326	***Contractor:***	7320
Tag:	A159431	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	

Clear/Cloudy: ***UTM Reliability:***
Municipality: BRAMPTON CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/721\7217099.pdf

Additional Detail(s) (Map)

Well Completed Date: 01/09/2014
Year Completed: 2014
Depth (m): 7.6
Latitude: 43.6946539537253
Longitude: -79.7680499225524
X: -79.76804977333659
Y: 43.69465395182158
Path: 721\7217099.pdf

Bore Hole Information

Bore Hole ID: 1004716644 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17
Code OB: ***East83:*** 599276.00
Code OB Desc: ***North83:*** 4838697.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 01/09/2014 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1005090309
Layer: 3
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3:
Material 3 Desc:
Formation Top Depth: 0.800000011920929
Formation End Depth: 3.4000000953674316
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005090308
Layer: 2
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL

Material 2: 28
Material 2 Desc: SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.30000001192092896
Formation End Depth: 0.800000011920929
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005090307
Layer: 1
Color: 8
General Color: BLACK
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005090310
Layer: 4
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 3.4000000953674316
Formation End Depth: 7.599999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005090317
Layer: 1
Plug From: 0.0
Plug To: 1.2000000476837158
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005090318
Layer: 2
Plug From: 1.2000000476837158
Plug To: 7.599999904632568
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005090316
Method Construction Code: 6
Method Construction: Boring
Other Method Construction: SSA

Pipe Information

Pipe ID: 1005090306
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005090313
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 1.5
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005090314
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 7.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.099999904632568

Water Details

Water ID: 1005090312
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005090311
Diameter: 16.0
Depth From: 0.0
Depth To: 7.599999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

241	1 of 1	SE/160.5	219.9 / -22.08	R.M. OF PEEL VODDEN ST.W/PLEASANTVIEW AVE. BRAMPTON CITY ON	CA

Certificate #: 7-1207-95-966
Application Year: 95

Issue Date: 1/8/96
Approval Type: Municipal water
Status: Received in 1995, Issued in 1996
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

242 **1 of 1** **ESE/5.6** **215.2 / -26.74** **23-0353**
Brampton ON L6V **EHS**

Order No: 23020600162
Status: C
Report Type: Custom Report
Report Date: 09-FEB-23
Date Received: 06-FEB-23
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.76684751
Y: 43.69538993

---

243 **1 of 1** **ESE/2.6** **223.0 / -18.92** **The Regional Municipality of Peel**
Vodden Street East and Centre St. North
Brampton ON **SPL**

Ref No: 8357-B8YFY7
Year:
Incident Dt: 2019/02/01
Dt MOE Arvl on Scn:
MOE Reported Dt: 2019/02/01
Dt Document Closed: 2019/02/12
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse: Etobicoke Creek
Site Name: Street and 2 CB on Vodden<UNOFFICIAL>
Site Address: Vodden Street East and Centre St. North
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839035
Easting: 599578
Entity Operating Name:
Client Name: The Regional Municipality of Peel
Client Type: Municipal Government
Source Type: Water Supply
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Weather Conditions
Incident Summary: RofPeel: 600/150mm water main break, sediment to Etobicoke Cr.
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Contaminant Qty 1:	0
Contaminant Unit:	other - see incident description
Contaminant Code:	41
Contaminant Name:	WATER/SEDIMENT
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Land; Surface Water
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

244 | **1 of 1** | **SE/24.1** | **219.9 / -22.08** | **1798836 Ontario Inc.**
36 Vodden Street, Suite 304
Brampton ON L6V 4H4 | **GEN**

Generator Info

Generator No:	ON2595063	**Choice of Contact:**	
Approval Years:	As of Dec 2017	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

2017 Generator Info

Gen No:	ON2595063	**Choice of Contact:**	CO_OFFICIAL
ID:	10343	**Phone No Official:**	905-796-0040 Ext.7709
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	623110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	1798836 Ontario Inc.
Gen Div:	
Gen Op Name:	Central West Community Care Access Centre
Gen Op Div:	Corporate Procurement & Facilities
Site Adrs1:	36 Vodden Street, Suite 304
Site Bldg:	Brampton Nursing Care Clinic
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 4H4
Site Country:	Canada
Co Official:	Yonette Richards

Co Admin:

2018 Generator Info

Gen No:	ON2595063	**Choice of Contact:**	CO_OFFICIAL
ID:	10098	**Phone No Official:**	905-796-0040 Ext.7709
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	623110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	1798836 Ontario Inc.
Gen Div:	
Gen Op Name:	Central West Community Care Access Centre
Gen Op Div:	Corporate Procurement & Facilities
Site Adrs1:	36 Vodden Street, Suite 304
Site Bldg:	Brampton Nursing Care Clinic
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 4H4
Site Country:	Canada
Co Official:	Yonette Richards
Co Admin:	

---

245 ***1 of 1*** ***ESE/9.2*** ***223.3 / -18.68*** ***ON*** ***WWIS***

Well ID:	4900510	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	12/11/1951
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	3514
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality:	BRAMPTON CITY
Site Info:	

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4900510.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/20/1951
Year Completed:	1951
Depth (m):	15.8496
Latitude:	43.6976905963656
Longitude:	-79.7640960053065
X:	-79.76409585487238
Y:	43.69769059378922
Path:	490\4900510.pdf

Bore Hole Information

Bore Hole ID:	10315358	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	599589.60
Code OB Desc:		***North83:***	4839039.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	11/20/1951	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	p9

Location Method Desc: Original Pre1985 UTM Rel Code 9: unknown UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932030431
Layer: 1
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932030432
Layer: 2
Color:
General Color:
Material 1: 13
Material 1 Desc: BOULDERS
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 20.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932030434
Layer: 4
Color: 7
General Color: RED
Material 1: 17

Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 40.0
Formation End Depth: 52.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932030433
Layer: 3
Color:
General Color:
Material 1: 14
Material 1 Desc: HARDPAN
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 25.0
Formation End Depth: 40.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964900510
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 10863928
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930521457
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 52.0
Casing Diameter: 4.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930521456
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 40.0
Casing Diameter: 4.0

Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 994900510
Pump Set At:
Static Level: 12.0
Final Level After Pumping: 12.0
Recommended Pump Depth:
Pumping Rate: 4.0
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 4
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933788460
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 48.0
Water Found Depth UOM: ft

---

246 | **1 of 1** | **ESE/70.4** | **229.9 / -12.08** | **Kennedy Road Tabernacle**
141 Kennedy Road N
Brampton ON L6V 1X9 | **GEN**

Generator Info

Generator No: ON2423454
Approval Years: 04
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Religious Organizations

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 813110

---

247 | **1 of 2** | **ESE/2.6** | **227.6 / -14.29** | **R.M. OF PEEL**
POST RD/VODDEN ST.
BRAMPTON CITY ON | **CA**

Certificate #: 3-0028-95-
Application Year: 95
Issue Date: 1/23/1995
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:

Project Description:
Contaminants:
Emission Control:

---

247 | ***2 of 2*** | ***ESE/2.6*** | ***227.6 / -14.29*** | ***CONSUMERS' GAS CO. LTD., THE VODDEN & POST ROAD NATURAL GAS PIPELINE BRAMPTON CITY ON*** | ***SPL***

Ref No:	110940	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	3/15/1995	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	3/15/1995	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: CONSUMERS'GAS-1.5 HOUR RELEASE OF NATURAL GAS, LINE STRUCK BY CONTRACTOR
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

248 | ***1 of 1*** | ***SE/3.5*** | ***218.4 / -23.53*** | ***Main Street & Vodden Street, Brampton ON*** | ***INC***

Incident No:	428694	**Any Health Impact:**	No
Incident ID:		**Any Enviro Impact:**	No
Instance No:		**Service Intrp:**	No
Status Code:		**Was Prop Damaged:**	No
Incident Status:		**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:	2995161	**Indus App. Type:**	
Attribute Category:	FS-Perform L1 Near Miss Insp	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	
Date of Occurrence:	2010/07/23 00:00:00	**Operation Pressure:**	
Time of Occurrence:	12:00:00	**Equipment Type:**	
Occr Insp Start Dt:	2010/07/30 00:00:00	**Equipment Model:**	
Incident Creat On:		**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Other	**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Propane	**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:	NULL	**Tank Storage Type:**	
Prc Escalation Req:	NULL	**Tank Location Type:**	

Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: Main Street & Vodden Street, Brampton - Near Miss
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: overfilled cylinder
Operation Type Involved: Propane Re-fill Centre

---

249 | ***1 of 1*** | ***WNW/187.5*** | ***261.4 / 19.46*** | ***lot 22 con 1 ON*** | ***WWIS***

Well ID:	4908096	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:		**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	03/20/1996
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	159734	**Contractor:**	1663
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	022
Depth to Bedrock:		**Concession:**	01

Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4908096.pdf

Additional Detail(s) (Map)

Well Completed Date:	03/16/1995
Year Completed:	1995
Depth (m):	45.72
Latitude:	43.742083717853
Longitude:	-79.8588606928937
X:	-79.85886054274793
Y:	43.742083716342336
Path:	490\4908096.pdf

Bore Hole Information

Bore Hole ID:	10322655	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	591885.50
Code OB Desc:		**North83:**	4843860.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	3
Date Completed:	03/16/1995	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	gps
Location Method Desc:	from gps		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932061853
Layer:	5
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	11
Material 3 Desc:	GRAVEL
Formation Top Depth:	26.0
Formation End Depth:	32.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932061854
Layer:	6

Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	32.0
Formation End Depth:	52.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932061849
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932061856
Layer:	8
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	55.0
Formation End Depth:	150.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932061850
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	12.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932061852
Layer:	4
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	17.0
Formation End Depth:	26.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932061851
Layer:	3
Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	12.0
Formation End Depth:	17.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932061855
Layer:	7
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	52.0
Formation End Depth:	55.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933170805
Layer:	2
Plug From:	20.0
Plug To:	68.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID: 933170804
Layer: 1
Plug From: 0.0
Plug To: 20.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908096
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871225
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930532125
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 68.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930532126
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 150.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 994908096
Pump Set At:
Static Level: 17.0
Final Level After Pumping: 140.0
Recommended Pump Depth: 145.0
Pumping Rate: 2.0
Flowing Rate:
Recommended Pump Rate: 2.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1

Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934787339
Test Type: Draw Down
Test Duration: 45
Test Level: 37.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934258746
Test Type: Draw Down
Test Duration: 15
Test Level: 26.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934533266
Test Type: Draw Down
Test Duration: 30
Test Level: 33.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935044103
Test Type: Draw Down
Test Duration: 60
Test Level: 40.0
Test Level UOM: ft

Water Details

Water ID: 933796214
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 145.0
Water Found Depth UOM: ft

---

250 | ***1 of 1*** | ***SE/12.1*** | ***218.4 / -23.55*** | ***Downtown Brampton Brampton ON*** | ***EHS***

Order No: 20200721036
Status: C
Report Type: Custom Report
Report Date: 27-JUL-20
Date Received: 21-JUL-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0
X: -79.7693214
Y: 43.6928917

---

251 | ***1 of 10*** | ***ESE/39.0*** | ***219.1 / -22.82*** | ***The Corporation of the City of Brampton 75 Vodden Street East*** | ***CA***

Brampton ON L6V 4H7

Certificate #: 5189-6F6KF9
Application Year: 2005
Issue Date: 8/11/2005
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

251 | ***2 of 10*** | ***ESE/39.0*** | ***219.1 / -22.82*** | ***The Corporation of The City of Brampton***
75 Vodden St. East
Brampton ON | ***GEN***

Generator Info

Generator No: ON6801554
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 913140

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

251 | ***3 of 10*** | ***ESE/39.0*** | ***219.1 / -22.82*** | ***The Corporation of the City of Brampton***
75 Vodden St E
Brampton ON L6Y 4R2 | ***ECA***

Approval No: 5189-6F6KF9
Approval Date: 2005-08-11
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: The Corporation of the City of Brampton
Address: 75 Vodden St E
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7360-6DJNFZ-14.pdf
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

---

251 | ***4 of 10*** | ***ESE/39.0*** | ***219.1 / -22.82*** | ***The Corporation of The City of Brampton***
75 Vodden St. East
Brampton ON L6V2R2 | ***GEN***

Generator Info

Generator No:	ON6801554	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	913140
Country:	Canada		
Co Admin:	Kevin Hamilton		
Phone No Admin:	905 458 5343 Ext.		
SIC Description:	913140		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

251 ***5 of 10*** ***ESE/39.0*** ***219.1 / -22.82*** ***The Corporation of The City of Brampton***
75 Vodden St. East
Brampton ON L6V2R2 ***GEN***

Generator Info

Generator No:	ON6801554	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	913140
Country:	Canada		
Co Admin:	Kevin Hamilton		
Phone No Admin:	905 458 5343 Ext.		
SIC Description:	913140		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

251 ***6 of 10*** ***ESE/39.0*** ***219.1 / -22.82*** ***The Corporation of The City of Brampton***
75 Vodden St. East
Brampton ON L6V2R2 ***GEN***

Generator Info

Generator No:	ON6801554	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	913140
Country:	Canada		
Co Admin:	Kevin Hamilton		
Phone No Admin:	905 458 5343 Ext.		
SIC Description:	913140		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
251	7 of 10	ESE/39.0	219.1 / -22.82	The Corporation of The City of Brampton Buildings and Property Management 75 Vodden St. East Brampton ON L6V2R2	GEN

Generator Info

Generator No:	ON6801554	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
251	8 of 10	ESE/39.0	219.1 / -22.82	The Corporation of The City of Brampton Buildings and Property Management 75 Vodden St. East Brampton ON L6V2R2	GEN

Generator Info

Generator No:	ON6801554	***Choice of Contact:***	
Approval Years:	As of Jul 2020	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
251	9 of 10	ESE/39.0	219.1 / -22.82	The Corporation of The City of Brampton Buildings and Property Management 75 Vodden St. East Brampton ON L6V2R2	GEN

Generator Info

Generator No:	ON6801554	***Choice of Contact:***	
Approval Years:	As of Nov 2021	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
251	10 of 10	ESE/39.0	219.1 / -22.82	City of Brampton Fire Station 207, 75 Vodden St. East Brampton ON	GEN

Generator Info

Generator No:	ON6801554	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	251 L
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Generator Info as of Dec 2024

Generator No:	ON6801554
Generator Company Name:	City of Brampton
Street:	Fire Station 207, 75 Vodden St. East
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6V2R2
Waste Class:	312 P,251 L

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 251 - OIL SKIMMINGS & SLUDGES

2017 Generator Info

Gen No:	ON6801554	***Choice of Contact:***	CO_OFFICIAL
ID:	26752	***Phone No Official:***	905-874-2333 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905 458 5343 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	913140	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	The Corporation of The City of Brampton
Gen Div:	Buildings and Property Management
Gen Op Name:	The Corporation of The City of Brampton
Gen Op Div:	Buildings and Property Management
Site Adrs1:	75 Vodden St. East
Site Bldg:	Fire Station 207
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V2R2
Site Country:	Canada
Co Official:	Jim Joukema
Co Admin:	Kevin Hamilton

2018 Generator Info

Gen No:	ON6801554	***Choice of Contact:***	CO_OFFICIAL
ID:	27121	***Phone No Official:***	905-874-2333 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905 458 5343 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	913140	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	The Corporation of The City of Brampton
Gen Div:	Buildings and Property Management
Gen Op Name:	The Corporation of The City of Brampton
Gen Op Div:	Buildings and Property Management
Site Adrs1:	75 Vodden St. East
Site Bldg:	Fire Station 207
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V2R2
Site Country:	Canada
Co Official:	Jim Joukema
Co Admin:	Kevin Hamilton

2019 Generator Info

Gen No:	ON6801554	***Choice of Contact:***	CO_OFFICIAL
ID:	27360	***Phone No Official:***	905-874-2333 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905 458 5343 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	913140	***County Out:***	

NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	The Corporation of The City of Brampton		
Gen Div:	Buildings and Property Management		
Gen Op Name:	The Corporation of The City of Brampton		
Gen Op Div:	Buildings and Property Management		
Site Adrs1:	75 Vodden St. East		
Site Bldg:	Fire Station 207		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V2R2		
Site Country:	Canada		
Co Official:	Jim Joukema		
Co Admin:	Scott Glew		

2020 Generator Info

Gen No:	ON6801554	***Choice of Contact:***	CO_ADMIN
ID:	27080	***Phone No Official:***	905-874-2333 Ext.
Contaminated Fac:	N	***Phone No Admin:***	437-229-1193 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	913140	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	The Corporation of The City of Brampton		
Gen Div:	Buildings and Property Management		
Gen Op Name:	The Corporation of The City of Brampton		
Gen Op Div:	Buildings and Property Management		
Site Adrs1:	75 Vodden St. East		
Site Bldg:	Fire Station 207		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V2R2		
Site Country:	Canada		
Co Official:	Jim Joukema		
Co Admin:	Nissar NA Ahamed		

2021 Generator Info

Gen No:	ON6801554	***Choice of Contact:***	CO_OFFICIAL
ID:	27556	***Phone No Official:***	905-874-2496 Ext.
Contaminated Fac:	N	***Phone No Admin:***	437-229-1193 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	913140	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	The Corporation of The City of Brampton		
Gen Div:	Buildings and Property Management		
Gen Op Name:	The Corporation of The City of Brampton		
Gen Op Div:	Buildings and Property Management		
Site Adrs1:	75 Vodden St. East		
Site Bldg:	Fire Station 207		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V2R2		

Site Country: Canada
Co Official: Dale Turpin
Co Admin: Nissar NA Ahamed

---

252 **1 of 1** **SE/19.0** **217.1 / -24.84** **320 MAIN STREET W. BRAMPTON ON** **WWIS**

Well ID: 7147718
Construction Date:
Use 1st: Test Hole
Use 2nd:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z110075
Tag: A100022
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 07/02/2010
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7215
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7147718.pdf

Additional Detail(s) (Map)

Well Completed Date: 06/14/2010
Year Completed: 2010
Depth (m): 7.62
Latitude: 43.693123851078
Longitude: -79.7689374662646
X: -79.76893731587792
Y: 43.69312384883944
Path: 714\7147718.pdf

Bore Hole Information

Bore Hole ID: 1003100516
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/14/2010
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 599207.00
North83: 4838526.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1003156167
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:
Material 3: 27
Material 3 Desc: OTHER
Formation Top Depth: 0.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003156168
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 34
Material 2 Desc: TILL
Material 3: 68
Material 3 Desc: DRY
Formation Top Depth: 4.0
Formation End Depth: 14.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003156169
Layer: 3
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 34
Material 2 Desc: TILL
Material 3: 27
Material 3 Desc: OTHER
Formation Top Depth: 14.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003156170
Layer: 4
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 27
Material 3 Desc: OTHER
Formation Top Depth: 20.0

Formation End Depth: 25.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003156173
Layer: 2
Plug From: 13.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003156172
Layer: 1
Plug From: 25.0
Plug To: 13.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003156174
Layer: 3
Plug From: 1.0
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1003156179
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1003156166
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003156176
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003156177

Layer: 1
Slot: 10
Screen Top Depth: 15.0
Screen End Depth: 25.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 1003156175
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1003156171
Diameter: 8.0
Depth From: 25.0
Depth To: 0.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

253 | **1 of 1** | **ESE/127.4** | **229.9 / -12.08** | **Terra HX Inc.**
39 Greene Drive, Brampton
BRAMPTON ON | **SPL**

Ref No: 1-2AK8MS
Year:
Incident Dt: 12/1/2022 6:45:15 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/1/2022 11:34:15 AM
Dt Document Closed: 12/28/2022 9:36:50 AM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name: Terra HX Inc.
Site Address: 39 Greene Drive, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: ALECTRA UTILITIES CORPORATION
Client Type: Private Business
Source Type: Transformer
Incident Cause:
Incident Preceding Spill: Accident/Collision
Incident Reason: Human error (Specify)
Incident Summary: Alectra: 100-150L non-PCB mineral oil to transformer foundation; clnd_39 Greene Drive, Brampton
Environment Impact: 1 Minor Impact
Health Env Consequence:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Nature of Impact:	
Contaminant Qty:	150 litre (L)
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	MINERAL OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed:	02HC | Humber River - Don River
Sector Type:	ELECTRIC POWER DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001675178"],"wkts":["POINT (-79.7587014000 43.7036216000)"],"creation_date":"2022-12-01"}
Time Reported:	
System Facility Address:	717 SAFARI RD, HAMILTON, ON L8B 1S3

254 | ***1 of 1*** | ***ESE/41.5*** | ***229.9 / -12.08*** | ***131 Kennedy Road North Brampton ON L6V 1X9*** | ***EHS***

Order No:	20120126029	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	1/30/2012 3:32:25 PM	**Search Radius (km):**	0.25
Date Received:	1/26/2012 3:31:14 PM	**X:**	-79.759285
Previous Site Name:		**Y:**	43.702796
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans;		

255 | ***1 of 1*** | ***ESE/44.9*** | ***220.9 / -21.06*** | ***215 Centre Street North Brampton ON L6V 1T4*** | ***EHS***

Order No:	20200310031	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	13-MAR-20	**Search Radius (km):**	.25
Date Received:	10-MAR-20	**X:**	-79.7644436
Previous Site Name:		**Y:**	43.6968571
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

256 | ***1 of 2*** | ***ESE/30.4*** | ***229.9 / -12.08*** | ***129-131 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X9*** | ***EHS***

Order No:	20070926002	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	CAN - Complete Report	**Client Prov/State:**	
Report Date:	10/1/2007	**Search Radius (km):**	0.25
Date Received:	9/26/2007	**X:**	-79.759258
Previous Site Name:		**Y:**	43.702734
Lot/Building Size:			
Additional Info Ordered:			

256 | ***2 of 2*** | ***ESE/30.4*** | ***229.9 / -12.08*** | ***131 Kennedy Road North Brampton ON L6V 1X9*** | ***EHS***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No:	21101300138	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	18-OCT-21	**Search Radius (km):**	.25
Date Received:	13-OCT-21	**X:**	-79.759341
Previous Site Name:		**Y:**	43.70261
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

257 | **1 of 27** | **ESE/102.6** | **229.9 / -12.08** | **MANJITS ESSO**
140 KENNEDY RD N
BRAMPTON ON L6V 2N4 | **PRT**

Location ID:	1949
Type:	retail
Expiry Date:	1995-03-31
Capacity (L):	25957
Licence #:	0076385269

---

257 | **2 of 27** | **ESE/102.6** | **229.9 / -12.08** | **PROVMAR FUELS INC.**
140 KENNEDY ROAD TANK TRUCK (CARGO)
BRAMPTON CITY ON | **SPL**

Ref No:	126181	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	5/10/1996	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	5/10/1996	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Incident Reason:	ERROR		
Incident Summary:	PROVMAR-5 L GASOLINE TO LOT,HOSE NOT TIGHTENED ,CONTAINED,CLEANED-UP.		
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

257 ***3 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***BASHAR ENTERPRISES INC*** ***RST***
140 KENNEDY RD N
BRAMPTON ON L6V2N4

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9057969898
List Name:
Description:

---

257 ***4 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***ESSO MAXIMUM*** ***RST***
140 KENNEDY RD N
BRAMPTON ON L6V 2N4

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054537140
List Name:
Description:

---

257 ***5 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***MANN MANJIT*** ***RST***
140 KENNEDY RD N
BRAMPTON ON L6V 2N4

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

---

257 ***6 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***ESSO MAXIMUM ATTN MANJIT MANN*** ***FSTH***
140 KENNEDY RD N
BRAMPTON ON L6V 2N4

License Issue Date: 12/14/2001
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 13600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 13600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

257	***7 of 27***	***ESE/102.6***	***229.9 / -12.08***	***ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON L6V 2N4***	***FSTH***

License Issue Date: 12/14/2001
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:

Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 13600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 13600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

---

257 | **8 of 27** | **ESE/102.6** | **229.9 / -12.08** | **Imperial Oil Limited**
140 Kennedy Rd N
Brampton ON L6V 2N4 | **CA**

Certificate #: 1475-7MGLG7
Application Year: 2008
Issue Date: 12/22/2008
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

257 | **9 of 27** | **ESE/102.6** | **229.9 / -12.08** | **ESSO MAXIMUM ATTN MANJIT MANN**
140 KENNEDY RD N
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No: 10596968
Status: EXPIRED
Expired Date:
Max Hazard Rank:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance ID: 28431
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

257	***10 of 27***	***ESE/102.6***	***229.9 / -12.08***	***ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10597089
Status: EXPIRED
Instance ID: 28999
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Record Date: Up to Mar 2012

---

257 | **11 of 27** | **ESE/102.6** | **229.9 / -12.08** | **ESSO MAXIMUM ATTN MANJIT MANN**
140 KENNEDY RD N
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No:	10596884	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29942	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

---

257 | **12 of 27** | **ESE/102.6** | **229.9 / -12.08** | **ESSO MAXIMUM ATTN MANJIT MANN**
140 KENNEDY RD N
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No:	10597057	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29875	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

257 ***13 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***ESSO MAXIMUM ATTN MANJIT MANN***
140 KENNEDY RD N
BRAMPTON ON ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10597015 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 30183 ***Facility Location:***
Instance Type: FS Piping ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

257 ***14 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***ESSO MAXIMUM ATTN MANJIT MANN***
140 KENNEDY RD N
BRAMPTON ON ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10596928 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance ID:	30448	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

257 ***15 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***MAC'S CONVENIENCE STORES INC.*** ***FST***
140 KENNEDY RD N
BRAMPTON ON

Inventory No:	11623928	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBSPremium		

257 ***16 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***MAC'S CONVENIENCE STORES INC.*** ***FST***
140 KENNEDY RD N
BRAMPTON ON

Inventory No:	11623937	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

257 ***17 of 27*** ***ESE/102.6*** ***229.9 / -12.08*** ***MAC'S CONVENIENCE STORES INC.*** ***FST***
140 KENNEDY RD N
BRAMPTON ON

Inventory No:	11623943	**Tank Material:**	Fiberglass (FRP)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

257 | **18 of 27** | **ESE/102.6** | **229.9 / -12.08** | **MANN MANJIT**
140 KENNEDY RD N
BRAMPTON ON L6V2N4 | **RST**

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone:	9054537140
List Name:	INFO-DIRECT(TM) BUSINESS FILE
Description:	

---

257 | **19 of 27** | **ESE/102.6** | **229.9 / -12.08** | **140 Kennedy Rd N**
Brampton ON L6V2N4 | **EHS**

Order No:	20150607014	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	12-JUN-15	**Search Radius (km):**	.25
Date Received:	07-JUN-15	**X:**	-79.758898
Previous Site Name:		**Y:**	43.703202
Lot/Building Size:			
Additional Info Ordered:	City Directory		

---

257 | **20 of 27** | **ESE/102.6** | **229.9 / -12.08** | **Imperial Oil Limited**
140 Kennedy Rd N
Brampton ON M3C 1K5 | **ECA**

Approval No:	1475-7MGLG7	**MOE District:**	Halton-Peel
Approval Date:	2008-12-22	**City:**	
Status:	Approved	**Longitude:**	-79.758835
Record Type:	ECA	**Latitude:**	43.703297
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Toronto	**Geometry Y:**	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Imperial Oil Limited		
Address:	140 Kennedy Rd N		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6508-7LGN2P-14.pdf		
PDF Site Location:			

---

257 | **21 of 27** | **ESE/102.6** | **229.9 / -12.08** | **ESSO MAXIMUM ATTN MANJIT MANN**
140 KENNEDY RD N
BRAMPTON ON | **EXP**

Inventory No:	10596993	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Fiberglass
Installation Year:	1981	**Overfill Protection:**	
Capacity:	22700	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

---

257 | ***22 of 27*** | ***ESE/102.6*** | ***229.9 / -12.08*** | ***ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON*** | ***EXP***

Inventory No: 10596951
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

257 | ***23 of 27*** | ***ESE/102.6*** | ***229.9 / -12.08*** | ***ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON*** | ***EXP***

Inventory No: 10597083
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 13600
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

257 | ***24 of 27*** | ***ESE/102.6*** | ***229.9 / -12.08*** | ***ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON*** | ***EXP***

Inventory No: 10596909
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS Premium
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

257 | ***25 of 27*** | ***ESE/102.6*** | ***229.9 / -12.08*** | ***ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON*** | ***EXP***

Inventory No: 10596862
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 22700

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Diesel
Inventory Item: FS LIQUID FUEL TANK

---

257 | **26 of 27** | **ESE/102.6** | **229.9 / -12.08**

ESSO MAXIMUM ATTN MANJIT MANN
140 KENNEDY RD N
BRAMPTON ON

EXP

Inventory No: 10597038
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 13600
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

257 | **27 of 27** | **ESE/102.6** | **229.9 / -12.08**

MAC'S CONVENIENCE STORES INC.
140 KENNEDY RD N
BRAMPTON ON

FST

Inventory No: 9510615
Inventory Status: Active
Installation Year:
Capacity: 139200
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:
Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

---

258 | **1 of 1** | **ESE/49.5** | **229.9 / -12.08**

KENNEDY RD N
BRAMPTON ON

WWIS

Well ID: 7312109
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z277308
Tag: A242005
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 06/07/2018
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7472
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/731\7312109.pdf

Additional Detail(s) (Map)

Well Completed Date: 04/26/2018
Year Completed: 2018
Depth (m): 6.096
Latitude: 43.7029305397217
Longitude: -79.7590810554585
X: -79.75908090492618
Y: 43.70293053794136
Path: 731\7312109.pdf

Bore Hole Information

Bore Hole ID: 1007086268
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/26/2018
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 599985.00
North83: 4839627.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007172445
Layer: 2
Color: 3
General Color: BLUE
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 1.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007172444
Layer: 1
Color: 2
General Color: GREY
Material 1: 27
Material 1 Desc: OTHER
Material 2:
Material 2 Desc:
Material 3: 73
Material 3 Desc: HARD

Formation Top Depth: 0.0
Formation End Depth: 1.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007172453
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007172454
Layer: 2
Plug From: 9.0
Plug To: 20.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007172452
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007172443
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007172449
Layer: 2
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 1007172448
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID:	1007172450
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Water Details

Water ID:	1007172447
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007172446
Diameter:	7.5
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

259 ***1 of 1*** ***SE/149.8*** ***219.9 / -22.08*** ***SERVICE MASTER***
115 NANCY MCCREDIE DRIVE
BRAMPTON ON L6X 2N4 ***SPL***

Ref No:	183782	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	7/17/2000	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	7/17/2000	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER CONTAINER LEAK		
Incident Preceding Spill:			

Incident Reason:	MATERIAL FAILURE
Incident Summary:	SERVICE MASTER: SPILL OF 100 L TANK MIX TO ROAD. CONTAINED/CLEANED.
Environment Impact:	POSSIBLE
Health Env Consequence:	
Nature of Impact:	Other
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

260 **1 of 1** **ESE/20.5** **229.9 / -12.08** **VODDEN ST E & KENNEDY RD N BRAMPTON ON** **WWIS**

Well ID:	7312124	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	06/07/2018
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z277231	**Contractor:**	7472
Tag:	A241128	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/731\7312124.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/26/2018
Year Completed:	2018
Depth (m):	4.572
Latitude:	43.7026341517997
Longitude:	-79.7591492242883
X:	-79.75914907358624
Y:	43.70263415014457
Path:	731\7312124.pdf

Bore Hole Information

Bore Hole ID:	1007086525	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	599980.00
Code OB Desc:		**North83:**	4839594.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/26/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007174201
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	3.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007174199
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007174200
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77

Material 3 Desc: LOOSE
Formation Top Depth: 1.0
Formation End Depth: 3.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007174209
Layer: 2
Plug From: 4.0
Plug To: 15.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007174208
Layer: 1
Plug From: 0.0
Plug To: 4.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007174207
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007174198
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007174204
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 5.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007174205
Layer: 1
Slot: 10
Screen Top Depth: 5.0
Screen End Depth: 15.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Water Details

Water ID:	1007174203
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007174202
Diameter:	7.5
Depth From:	0.0
Depth To:	15.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

261 ***1 of 1*** ***SE/42.7*** ***216.7 / -25.20*** ***ON*** ***WWIS***

Well ID:	4903777	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Not Used	***Data Entry Status:***	
Use 2nd:	0	***Data Src:***	3
Final Well Status:	Observation Wells	***Date Received:***	03/01/1952
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	0001
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4903777.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/01/1952
Year Completed:	1952
Depth (m):	9.144
Latitude:	43.6930931565978
Longitude:	-79.7685956077043
X:	-79.76859545761651
Y:	43.693093154781366
Path:	490\4903777.pdf

Bore Hole Information

Bore Hole ID:	10318610	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	599234.60

Code OB Desc:		**North83:**	4838523.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/01/1952	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	p4

Location Method Desc: Original Pre1985 UTM Rel Code 4: margin of error : 30 m - 100 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932043030
Layer: 1
Color:
General Color:
Material 1: 25
Material 1 Desc: OVERBURDEN
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964903777
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10867180
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930526221
Layer: 1
Material: 3
Open Hole or Material: CONCRETE
Depth From:
Depth To: 30.0
Casing Diameter: 48.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 994903777
Pump Set At:

Static Level:	5.0
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

262 | ***1 of 1*** | ***ESE/50.1*** | ***229.0 / -12.90*** | ***Kennedy Rd N Brampton ON*** | ***WWIS***

Well ID:	7359808	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	06/03/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	Yes
Audit No:	Z328849	**Contractor:**	7610
Tag:		**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1008302386	**Tag No:**	
Depth M:		**Contractor:**	7610
Year Completed:	2020	**Latitude:**	43.7029184388223
Well Completed Dt:	03/19/2020	**Longitude:**	-79.7587958530748
Audit No:	Z328849	**Y:**	43.702918437274825
Path:		**X:**	-79.75879570249175

Bore Hole Information

Bore Hole ID:	1008302386	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	600008.00
Code OB Desc:		**North83:**	4839626.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03/19/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1008418906
Layer: 1
Plug From: 0.0
Plug To: 3.440000057220459
Plug Depth UOM: m

Pipe Information

Pipe ID: 1008418146
Casing No: 0
Comment:
Alt Name:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008419908
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

---

263 | ***1 of 1*** | ***SE/33.8*** | ***219.9 / -22.08*** | ***Alectra Utilities Corporation***
47 Vodden St
Brampton ON | ***SPL***

Ref No: 4252-AU44JS
Year:
Incident Dt: 2017/12/15
Dt MOE Arvl on Scn:
MOE Reported Dt: 2017/12/15
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Grass near transformer box<UNOFFICIAL>
Site Address: 47 Vodden St
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4838292.95
Easting:	599019.85
Entity Operating Name:	
Client Name:	Alectra Utilities Corporation
Client Type:	Corporation
Source Type:	Transformer
Incident Cause:	
Incident Preceding Spill:	Collision/Accident
Incident Reason:	Operator/Human Error
Incident Summary:	Alectra: 2L non-pcb oil to grnd; cntnd & clning
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	2 L
Contaminant Qty 1:	2
Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	TRANSMISSION OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	1993
Receiving Medium:	Land
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

264 **1 of 1** **ESE/33.0** **229.4 / -12.56** **THE REGIONAL MUNICIPALITY OF PEEL** **EASR**

ON

Approval No:	R-009-2111200985	**MOE District:**	Halton-Peel
Status:	REGISTERED	**Municipality:**	
Date:	2019-04-12	**Latitude:**	43.70277778
Record Type:	EASR	**Longitude:**	-79.75888889
Link Source:	MOFA	**Geometry X:**	
Project Type:	Water Taking - Construction Dewatering	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Water Taking - Construction Dewatering		
SWP Area Name:	Toronto		
PDF NAICS Code:			
PDF URL:			
PDF Site Location:			

---

265 **1 of 1** **SE/56.2** **216.5 / -25.40** **320 Main Street North Brampton ON** **EHS**

Order No:	20200413010	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	16-APR-20	**Search Radius (km):**	.3
Date Received:	13-APR-20	**X:**	-79.76835156
Previous Site Name:		**Y:**	43.6931213
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
266	1 of 7	SE/63.1	216.0 / -25.90	Main Street Dental Office 320 Main Street N unit #9 Brampton ON L6V4A3	GEN

Generator Info

Generator No:	ON5088097	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621210
Country:	Canada		
Co Admin:	Ekta Tangri		
Phone No Admin:	9054569200 Ext.		
SIC Description:	OFFICES OF DENTISTS		

Waste Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
266	2 of 7	SE/63.1	216.0 / -25.90	Main Street Dental Office 320 Main Street N unit #9 Brampton ON L6V4A3	GEN

Generator Info

Generator No:	ON5088097	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621210
Country:	Canada		
Co Admin:	Ekta Tangri		
Phone No Admin:	9054569200 Ext.		
SIC Description:	OFFICES OF DENTISTS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

266 ***3 of 7*** ***SE/63.1*** ***216.0 / -25.90*** ***Main Street Dental Office*** ***GEN***
320 Main Street N unit #9
Brampton ON L6V4A3

Generator Info

Generator No: ON5088097
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Detail(s)

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

266 ***4 of 7*** ***SE/63.1*** ***216.0 / -25.90*** ***Main Street Dental Office*** ***GEN***
320 Main Street N unit #9
Brampton ON L6V4A3

Generator Info

Generator No: ON5088097
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Detail(s)

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
266	5 of 7	SE/63.1	216.0 / -25.90	Main Street Dental Office 320 Main Street N unit #9 Brampton ON L6V4A3	GEN

Generator Info

Generator No: ON5088097
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Detail(s)

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
266	6 of 7	SE/63.1	216.0 / -25.90	Main Street Dental Office 320 Main Street N unit #9 Brampton ON L6V4A3	GEN

Generator Info

Generator No:	ON5088097	***Choice of Contact:***	
Approval Years:	As of Oct 2022	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	264 L
Waste Class Name:	PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class:	264 T
Waste Class Name:	PHOTOPROCESSING WASTES

Waste Detail(s)

Waste Class:	148 C
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

2017 Generator Info

Gen No:	ON5088097	***Choice of Contact:***	CO_OFFICIAL
ID:	20167	***Phone No Official:***	9054569200 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9054569200 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Main Street Dental Office		
Gen Div:			
Gen Op Name:	Main Street Dental Office		
Gen Op Div:			
Site Adrs1:	320 Main Street N		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	unit #9		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V4A3		
Site Country:	Canada		
Co Official:	Janica Manchanda		
Co Admin:	Ekta Tangri		

2017 Generator Manifest

ID:	44377	***Sum Received Qty:***	18.9
Generator No:	ON5088097	***Waste Class Name:***	PHOTOPROCESSING WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	264		

2017 Generator Manifest

ID:	44378	***Sum Received Qty:***	22.0
Generator No:	ON5088097	***Waste Class Name:***	PHOTOPROCESSING WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	T	***District:***	305
Waste Code:	264		

2017 Generator Manifest

ID:	44379	***Sum Received Qty:***	24.0
Generator No:	ON5088097	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	3
Waste Char:	P	***District:***	305
Waste Code:	312		

2018 Generator Info

Gen No:	ON5088097	***Choice of Contact:***	CO_OFFICIAL
ID:	20288	***Phone No Official:***	9054569200 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9054569200 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Main Street Dental Office		
Gen Div:			
Gen Op Name:	Main Street Dental Office		
Gen Op Div:			
Site Adrs1:	320 Main Street N		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	unit #9		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V4A3		
Site Country:	Canada		
Co Official:	Janica Manchanda		
Co Admin:	Ekta Tangri		

2018 Generator Manifest

ID:	44292	***Sum Received Qty:***	16.85
Generator No:	ON5088097	***Waste Class Name:***	PHOTOPROCESSING WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	264		

2018 Generator Manifest

ID:	44293	***Sum Received Qty:***	15.05
Generator No:	ON5088097	***Waste Class Name:***	PATHOLOGICAL WASTES

Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

2019 Generator Info

Gen No:	ON5088097	***Choice of Contact:***	CO_OFFICIAL
ID:	20313	***Phone No Official:***	9054569200 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9054569200 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Main Street Dental Office		
Gen Div:			
Gen Op Name:	Main Street Dental Office		
Gen Op Div:			
Site Adrs1:	320 Main Street N		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	unit #9		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V4A3		
Site Country:	Canada		
Co Official:	Janica Manchanda		
Co Admin:	Ekta Tangri		

2019 Generator Manifest

ID:	43901	***Sum Received Qty:***	24.0
Generator No:	ON5088097	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

2020 Generator Info

Gen No:	ON5088097	***Choice of Contact:***	CO_OFFICIAL
ID:	20046	***Phone No Official:***	9054569200 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9054569200 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Main Street Dental Office		
Gen Div:			
Gen Op Name:	Main Street Dental Office		
Gen Op Div:			
Site Adrs1:	320 Main Street N		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	unit #9		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V4A3		
Site Country:	Canada		
Co Official:	Janica Manchanda		
Co Admin:	Ekta Tangri		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2020 Generator Manifest

ID:	40593	***Sum Received Qty:***	6.6
Generator No:	ON5088097	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	P	***District:***	305
Waste Code:	312		

2021 Generator Info

Gen No:	ON5088097	***Choice of Contact:***	CO_OFFICIAL
ID:	20194	***Phone No Official:***	9054569200 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9054569200 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	621210	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Main Street Dental Office		
Gen Div:			
Gen Op Name:	Main Street Dental Office		
Gen Op Div:			
Site Adrs1:	320 Main Street N		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:	unit #9		
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V4A3		
Site Country:	Canada		
Co Official:	Janica Manchanda		
Co Admin:	Ekta Tangri		

2021 Generator Manifest

ID:	42010	***Sum Received Qty:***	16.74
Generator No:	ON5088097	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

266	***7 of 7***	***SE/63.1***	***216.0 / -25.90***	***Main Street Dental Office*** ***320 Main Street North*** ***Brampton ON***	***GEN***

Generator Info as of Dec 2024

Generator No:	ON001071513
Generator Company Name:	Main Street Dental Office
Street:	320 Main Street North
City:	Brampton
Province State:	Ontario
Country:	Canada
Postal Code:	L6V 4A3
Waste Class:	312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
267	1 of 1	SE/232.4	219.9 / -22.08	35 Pleasantview Avenue, Brampton ON	PINC

Incident Id:	2813304	**Pipe Material:**	Plastic
Incident No:	656526	**Fuel Category:**	Natural Gas
Incident Reported Dt:		**Health Impact:**	No
Type:	FS-Pipeline Incident	**Environment Impact:**	No
Status Code:	Pipeline Damage Reason Est	**Property Damage:**	Yes
Tank Status:	RC Established	**Service Interrupt:**	Yes
Task No:	3474678	**Enforce Policy:**	Yes
Spills Action Centre:		**Public Relation:**	No
Fuel Type:	Natural Gas	**Pipeline System:**	
Fuel Occurrence Tp:	Pipeline Strike	**PSIG:**	55
Date of Occurrence:	9/2/2011 0:00	**Attribute Category:**	FS-Perform P-line Inc Invest
Occurrence Start Dt:	2011/10/21	**Regulator Location:**	Outside
Depth:		**Method Details:**	E-mail
Customer Acct Name:			
Incident Address:			
Operation Type:	Construction Site (including excavation)		
Pipeline Type:	Service / Riser Distribution Pipeline		
Regulator Type:	Service Regulator (up to 60 psi intake)		
Summary:	35 Pleasantview Avenue, Brampton - 1/2" Pipeline Hit		
Reported By:	Blackburn, Chris - Enbridge		
Affiliation:	Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)		
Occurrence Desc:			
Damage Reason:	Excavation practices not sufficient		
Notes:	z		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
268	1 of 1	ESE/22.0	228.9 / -13.02	PETRO-CANADA KENNEDY N & VODDEN BRAMPTON ON L6V 1X7	RST

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:	
List Name:	
Description:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
269	1 of 1	ESE/16.7	228.9 / -13.08	121 KENNEDY ROAD NORTH Brampton ON	WWIS

Well ID:	7298062	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	10/31/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z255527	**Contractor:**	6607
Tag:	A232575	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/729\7298062.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/08/2017
Year Completed: 2017
Depth (m): 6
Latitude: 43.7022541873171
Longitude: -79.7589833107526
X: -79.75898316112824
Y: 43.702254184765636
Path: 729\7298062.pdf

Bore Hole Information

Bore Hole ID: 1006784872
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/08/2017
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 599994.00
North83: 4839552.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006955138
Layer: 2
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 28
Material 2 Desc: SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.15000000596046448
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955139
Layer: 3
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 84
Material 2 Desc: SILTY
Material 3: 66
Material 3 Desc: DENSE

Formation Top Depth: 0.30000001192092896
Formation End Depth: 4.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955137
Layer: 1
Color: 2
General Color: GREY
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.15000000596046448
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955140
Layer: 4
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 84
Material 2 Desc: SILTY
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 4.5
Formation End Depth: 6.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006955149
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.9000000953674316
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006955148
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006955147
Method Construction Code: 6
Method Construction: Boring

Other Method Construction:

Pipe Information

Pipe ID: 1006955136
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006955143
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006955144
Layer: 1
Slot: .1
Screen Top Depth: 3.0
Screen End Depth: 6.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Water Details

Water ID: 1006955142
Layer: 1
Kind Code:
Kind:
Water Found Depth: 5.300000190734863
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006955141
Diameter: 21.0
Depth From: 0.0
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

270 ***1 of 1*** ***ESE/16.0*** ***228.9 / -13.08*** ***ON*** ***WWIS***

Well ID: 7233319
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 12/09/2014
Selected Flag: TRUE
Abandonment Rec:

Audit No:	C25780	**Contractor:**	6607
Tag:	A163428	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1005254214	**Tag No:**	A163428
Depth M:		**Contractor:**	6607
Year Completed:	2014	**Latitude:**	43.7023343956687
Well Completed Dt:	10/03/2014	**Longitude:**	-79.7589071909655
Audit No:	C25780	**Y:**	43.702334394238704
Path:		**X:**	-79.75890704060308

Bore Hole Information

Bore Hole ID:	1005254214	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	600000.00
Code OB Desc:		**North83:**	4839561.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/03/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

271 | ***1 of 1*** | ***ESE/59.3*** | ***228.9 / -13.08*** | ***227 VODDEN ST EAST Brampton ON*** | ***WWIS***

Well ID:	7219364	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	04/23/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z185806	**Contractor:**	7241
Tag:	A159357	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: BRAMPTON CITY
Site Info:

Additional Detail(s) (Map)

Bore Hole ID:	1004732769	***Tag No:***	A159357
Depth M:	5.49	***Contractor:***	7241
Year Completed:	2014	***Latitude:***	43.7028699253966
Well Completed Dt:	03/07/2014	***Longitude:***	-79.7584741694874
Audit No:	Z185806	***Y:***	43.7028699229223
Path:		***X:***	-79.75847401859018

Bore Hole Information

Bore Hole ID:	1004732769	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	600034.00
Code OB Desc:		***North83:***	4839621.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	03/07/2014	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1005130525
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.6100000143051147
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005130527
Layer: 3
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 2.440000057220459

Formation End Depth: 5.489999771118164
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005130526
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.6100000143051147
Formation End Depth: 2.440000057220459
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005130536
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.130000114440918
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005130537
Layer: 3
Plug From: 2.130000114440918
Plug To: 5.489999771118164
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005130535
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005130534
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1005130524
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1005130530
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	2.440000057220459
Casing Diameter:	5.199999809265137
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005130531
Layer:	1
Slot:	10
Screen Top Depth:	2.440000057220459
Screen End Depth:	5.489999771118164
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03000020980835

Water Details

Water ID:	1005130529
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1005130528
Diameter:	15.239999771118164
Depth From:	0.0
Depth To:	5.489999771118164
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

272 ***1 of 1*** ***SE/166.9*** ***219.9 / -22.08*** ***Plastech Machinery Solutions***
58 Nancy McCredie Dr
Brampton ON L6X 2N6 ***SCT***

Established:	1998
Plant Size (ft²):	1830
Employment:	10

--Details--

Description:	Machine Shops
SIC/NAICS Code:	332710
Description:	Rubber and Plastics Industry Machinery Manufacturing
SIC/NAICS Code:	333220
Description:	All Other Industrial Machinery Manufacturing
SIC/NAICS Code:	333299

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Industrial Mould Manufacturing
SIC/NAICS Code: 333511

Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance
SIC/NAICS Code: 811310

---

273 **1 of 1** **ESE/77.8** **229.7 / -12.28** **BRAMPTON HYDRO-ELECTRIC COMMIS**
30 CUMBERLAND
BRAMPTON CITY ON L6V 1W6 **SPL**

Ref No: 170930
Year:
Incident Dt: 7/30/1999
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/31/1999
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: COOLING SYSTEM LEAK
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: BRAMPTON HYDRO-50 L NON-PCB TRANSFORMER OIL TO GRND & 2 AUTOS.
Environment Impact: CONFIRMED
Health Env Consequence:
Nature of Impact: Multi Media Pollution
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
274	1 of 1	ESE/121.9	229.1 / -12.86	ON	BORE

Borehole ID:	654700	**Inclin FLG:**	No
OGF ID:	215555045	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1970	**Municipality:**	
Static Water Level:	0.6	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.703333
Total Depth m:	6.2	**Longitude DD:**	-79.758023
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	600070
Drill Method:	Power auger	**Northing:**	4839673
Orig Ground Elev m:	227	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	228		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218544405	**Mat Consistency:**	Dense
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. GLACIAL,VERY DENSE, AGE GLACIAL.		

Geology Stratum ID:	218544406	**Mat Consistency:**	Hard
Top Depth:	2.6	**Material Moisture:**	
Bottom Depth:	4.1	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,CLAY,SAND.GREY,GLACIAL,HARD,AGE GLACIAL,WATER STABLE AT 745.8 FEET.		

Geology Stratum ID:	218544407	**Mat Consistency:**	
Top Depth:	4.1	**Material Moisture:**	
Bottom Depth:	6.2	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	Ordovician
Material 4:	Sand	**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	SHALE,SILT,CLAY,SANDRED,MARINE,AGE ORDOVICIAN. 000000800008512000001 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1

Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 253650 NTS_Sheet: 30M12F		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

275 ***1 of 1*** ***ESE/75.3*** ***228.9 / -13.08 ON*** ***BORE***

Borehole ID:	654705	**Inclin FLG:**	No
OGF ID:	215555050	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1970	**Municipality:**	
Static Water Level:	0.5	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.70293
Total Depth m:	5	**Longitude DD:**	-79.75828
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	600050
Drill Method:	Power auger	**Northing:**	4839628
Orig Ground Elev m:	227	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	228		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218544420	**Mat Consistency:**	Dense
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	3.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:	Silt	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,GRAVEL, SILT. BROWN,GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 745.3 FEET.		

Geology Stratum ID:	218544418	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL.		

Geology Stratum ID: 218544421
Top Depth: 3.5
Bottom Depth: 5
Material Color: Grey
Material 1: Shale
Material 2: Clay
Material 3: Silt
Material 4: Sand
Gsc Material Description:
Stratum Description: SHALE,CLAY,SILT,SANDGREY,MARINE,AGE ORDOVICIAN. 000401000011510000015 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period: Ordovician
Depositional Gen: marine

Geology Stratum ID: 218544419
Top Depth: .3
Bottom Depth: 1.2
Material Color: Red
Material 1: Till
Material 2: Silt
Material 3: Sand
Material 4: Gravel
Gsc Material Description:
Stratum Description: TILL,SILT,SAND, GRAVEL. WEATHERED.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR3.txt RecordID: 253700 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

276 | **1 of 1** | **ESE/53.2** | **228.9 / -13.08** | **227 VODDOEN STREET EAST Brampton ON** | **WWIS**

Well ID: 7219365
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z185810
Tag: A159355
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/23/2014
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:

Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: BRAMPTON CITY
Site Info:

Additional Detail(s) (Map)

Bore Hole ID:	1004732772	***Tag No:***	A159355
Depth M:	4.57	***Contractor:***	7241
Year Completed:	2014	***Latitude:***	43.702725221632
Well Completed Dt:	03/07/2014	***Longitude:***	-79.7584151015328
Audit No:	Z185810	***Y:***	43.7027252200247
Path:		***X:***	-79.75841495169705

Bore Hole Information

Bore Hole ID:	1004732772	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	600039.00
Code OB Desc:		***North83:***	4839605.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	03/07/2014	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005130539
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	01
Material 1 Desc:	FILL
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.6100000143051147
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1005130541
Layer:	3
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	66

Material 3 Desc: DENSE
Formation Top Depth: 1.5
Formation End Depth: 4.570000171661377
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005130540
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.6100000143051147
Formation End Depth: 1.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005130550
Layer: 2
Plug From: 0.30000001192092896
Plug To: 1.2200000286102295
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005130549
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005130551
Layer: 3
Plug From: 1.2200000286102295
Plug To: 4.570000171661377
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005130548
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1005130538
Casing No: 0

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1005130544
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	5.199999809265137
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005130545
Layer:	1
Slot:	10
Screen Top Depth:	1.5
Screen End Depth:	4.570000171661377
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03000020980835

Water Details

Water ID:	1005130543
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1005130542
Diameter:	15.239999771118164
Depth From:	0.0
Depth To:	4.570000171661377
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
277	1 of 20	ESE/41.0	228.9 / -13.08	PETRO CAN ROCCO & RALPH SERVICE CENTRE LTD 121 KENNEDY RD N BRAMPTON ON L6V 1X7	PRT

Location ID:	1948
Type:	retail
Expiry Date:	1994-11-30
Capacity (L):	2406066
Licence #:	0055551001

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
277	2 of 20	ESE/41.0	228.9 / -13.08	KENNEDY & VODDEN PETRO CANADA 121 KENNEDY RD N BRAMPTON ON L6V 1X7	RST

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

---

277 **3 of 20** **ESE/41.0** **228.9 / -13.08** **PERFECT LUBE** **RST**
121 KENNEDY RD N
BRAMPTON ON L6V 1X7

Headcode: 921430
Headcode Desc: Oil Changes & Lubrication Service
Phone: 9058665711
List Name:
Description:

---

277 **4 of 20** **ESE/41.0** **228.9 / -13.08** **Petro-Canada** **CA**
121 Kennedy Road North
Brampton ON L6V 1X7

Certificate #: 6910-5LUPT2
Application Year: 2003
Issue Date: 5/9/2003
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

277 **5 of 20** **ESE/41.0** **228.9 / -13.08** **SIMCOE ENERGY & TECHNICAL SERVICES INC** **DTNK**
*****
121 KENNEDY RD N
BRAMPTON ON

Delisted Expired Fuel Safety Facilities

Instance No: 10110608
Status: EXPIRED
Instance ID: 12170
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Cylr Handling Facility
Original Source: EXP
Record Date: Up to Mar 2012

---

277 | ***6 of 20*** | ***ESE/41.0*** | ***228.9 / -13.08*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** | ***FST***
121 KENNEDY RD N
BRAMPTON ON

Inventory No: 14848354
Inventory Status: active
Installation Year: 2003
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

277 | ***7 of 20*** | ***ESE/41.0*** | ***228.9 / -13.08*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** | ***FST***
121 KENNEDY RD N
BRAMPTON ON

Inventory No: 14848353
Inventory Status: active
Installation Year: 2003
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

277 | ***8 of 20*** | ***ESE/41.0*** | ***228.9 / -13.08*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** | ***FST***
121 KENNEDY RD N
BRAMPTON ON

Inventory No: 14848355
Inventory Status: active
Installation Year: 2003
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS
Premium

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

277 | ***9 of 20*** | ***ESE/41.0*** | ***228.9 / -13.08*** | ***KENNEDY & VODDEN PETRO CANADA*** | ***RST***
121 KENNEDY RD N
BRAMPTON ON L6V1X7

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 9054555115
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

277 **10 of 20** **ESE/41.0** **228.9 / -13.08** **SUNCOR ENERGY PRODUCTS PARTNERSHIP** **FST**
121 KENNEDY RD N
BRAMPTON ON

Inventory No: 64661039
Inventory Status: active
Installation Year: 2014
Capacity: 35000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description:

Tank Material: Flex
Corrosion Protect: Fiberglass
Overfill Protection: Gravity
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

277 **11 of 20** **ESE/41.0** **228.9 / -13.08** **Petro-Canada** **ECA**
121 Kennedy Road North
Brampton ON L6L 6N5

Approval No: 6910-5LUPT2
Approval Date: 2003-05-09
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Petro-Canada
Address: 121 Kennedy Road North
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0582-5LLSZC-14.pdf
PDF Site Location:

MOE District: Halton-Peel
City:
Longitude: -79.758766
Latitude: 43.70207
Geometry X:
Geometry Y:

---

277 **12 of 20** **ESE/41.0** **228.9 / -13.08** **Suncor Energy Products** **GEN**
121 Kennedy Road N
Brampton ON L6V1X

Generator Info

Generator No: ON5693930
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

277 ***13 of 20*** ***ESE/41.0*** ***228.9 / -13.08*** ***Suncor Energy Products Partnership*** ***GEN***
121 Kennedy Road N
Brampton ON L6V1X

Generator Info

Generator No: ON5693930
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

277 ***14 of 20*** ***ESE/41.0*** ***228.9 / -13.08*** ***Suncor Energy Products Partnership*** ***GEN***
121 Kennedy Road N
Brampton ON L6V1X

Generator Info

Generator No: ON5693930
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
277	15 of 20	ESE/41.0	228.9 / -13.08	Suncor Energy Products Partnership 121 Kennedy Road North Brampton ON	GEN

Generator Info

Generator No: ON5693930
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 150 L
Waste Class Name: INERT INORGANIC WASTES

Generator Info as of Dec 2024

Generator No: ON5693930
Generator Company Name: Suncor Energy Products Partnership
Street: 121 Kennedy Road North
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L6V 1X7
Waste Class: 221 L,251 L,150 L,221 I

Waste Class Decoded:

221 - LIGHT FUELS; 251 - OIL SKIMMINGS & SLUDGES; 150 - INERT INORGANIC WASTES; 221 - LIGHT FUELS

2018 Generator Info

Gen No:	ON5693930	**Choice of Contact:**	CO_ADMIN
ID:	22714	**Phone No Official:**	6472175307 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905-794-0168 Ext.23
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	447110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Suncor Energy Products		
Gen Div:			
Gen Op Name:	Suncor Energy Products		
Gen Op Div:			
Site Adrs1:	121 Kennedy Road N		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V1X		
Site Country:	Canada		
Co Official:	Donna Wojtanowski		
Co Admin:	Anita Langley		

2019 Generator Info

Gen No:	ON5693930	**Choice of Contact:**	CO_ADMIN
ID:	22795	**Phone No Official:**	905-804-7634 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905-632-5939 Ext.263
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	447110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Suncor Energy Products Partnership		
Gen Div:			
Gen Op Name:	Suncor Energy Products Partnership		
Gen Op Div:			
Site Adrs1:	121 Kennedy Road N		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V1X		
Site Country:	Canada		
Co Official:	Donna Wojtanowski		
Co Admin:	Siratha Chhan		

2019 Generator Manifest

ID:	46922	**Sum Received Qty:**	88.0
Generator No:	ON5693930	**Waste Class Name:**	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	L	**District:**	306
Waste Code:	251		

2020 Generator Info

Gen No:	ON5693930	**Choice of Contact:**	CO_ADMIN
ID:	22526	**Phone No Official:**	905-804-7634 Ext.
Contaminated Fac:	N	**Phone No Admin:**	905-632-5939 Ext.263
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	447110	**County Out:**	

NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Suncor Energy Products Partnership		
Gen Div:			
Gen Op Name:	Suncor Energy Products Partnership		
Gen Op Div:			
Site Adrs1:	121 Kennedy Road N		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V1X		
Site Country:	Canada		
Co Official:	Donna Wojtanowski		
Co Admin:	Siratha Chhan		

2020 Generator Manifest

ID:	43563	***Sum Received Qty:***	65.0
Generator No:	ON5693930	***Waste Class Name:***	LIGHT FUELS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	221		

2020 Generator Manifest

ID:	43562	***Sum Received Qty:***	75.0
Generator No:	ON5693930	***Waste Class Name:***	LIGHT FUELS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	301
Waste Code:	221		

2020 Generator Manifest

ID:	43564	***Sum Received Qty:***	55.0
Generator No:	ON5693930	***Waste Class Name:***	OIL SKIMMINGS & SLUDGES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	305
Waste Code:	251		

2020 Generator Manifest

ID:	43565	***Sum Received Qty:***	70.0
Generator No:	ON5693930	***Waste Class Name:***	LIGHT FUELS
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	L	***District:***	306
Waste Code:	221		

2021 Generator Info

Gen No:	ON5693930	***Choice of Contact:***	CO_ADMIN
ID:	22800	***Phone No Official:***	905-962-5737 Ext.
Contaminated Fac:	N	***Phone No Admin:***	905-632-5939 Ext.263
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	447110	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			
Gen Name:	Suncor Energy Products Partnership		
Gen Div:			
Gen Op Name:	Suncor Energy Products Partnership		

Gen Op Div:
Site Adrs1: 121 Kennedy Road N
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L6V1X
Site Country: Canada
Co Official: Chris Lobo
Co Admin: Siratha Chhan

2021 Generator Manifest

ID: 45180
Generator No: ON5693930
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 3230.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 1
District: 301

2021 Generator Manifest

ID: 45181
Generator No: ON5693930
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 345.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 3
District: 305

---

277 | **16 of 20** | **ESE/41.0** | **228.9 / -13.08** | **2124964 ONTARIO INC O/A PETRO-CANADA**
121 KENNEDY RD N
BRAMPTON ON | **EXP**

Inventory No: 64052023
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 27277
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS - Assumed to be correct
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

277 | **17 of 20** | **ESE/41.0** | **228.9 / -13.08** | **2124964 ONTARIO INC O/A PETRO-CANADA**
121 KENNEDY RD N
BRAMPTON ON | **EXP**

Inventory No: 64052025
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 36369
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS - Assumed to be correct
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
277	18 of 20	ESE/41.0	228.9 / -13.08	2124964 ONTARIO INC O/A PETRO-CANADA 121 KENNEDY RD N BRAMPTON ON	EXP

Inventory No:	64052022	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	NULL	**Overfill Protection:**	
Capacity:	36369	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	2009VBS - Assumed to be correct		
Previous Fuel Type:	Gasoline		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
277	19 of 20	ESE/41.0	228.9 / -13.08	2124964 ONTARIO INC O/A PETRO-CANADA 121 KENNEDY RD N BRAMPTON ON	EXP

Inventory No:	64052024	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	NULL	**Overfill Protection:**	
Capacity:	36369	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	2009VBS - Assumed to be correct		
Previous Fuel Type:	Gasoline		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
277	20 of 20	ESE/41.0	228.9 / -13.08	SUNCOR ENERGY PRODUCTS PARTNERSHIP 121 KENNEDY RD N BRAMPTON ON	FST

Inventory No:	9815312	**Tank Material:**	
Inventory Status:	Active	**Corrosion Protect:**	
Installation Year:		**Overfill Protection:**	
Capacity:	185000	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			
Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
278	1 of 1	ESE/41.5	228.9 / -13.08	ON	BORE

Borehole ID:	654709	**Inclin FLG:**	No
OGF ID:	215555054	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1970	**Municipality:**	
Static Water Level:	0.6	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.702482
Total Depth m:	6.3	**Longitude DD:**	-79.758475
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	600035
Drill Method:	Power auger	**Northing:**	4839578
Orig Ground Elev m:	227	**Location Accuracy:**	

Elev Reliabil Note: ***Accuracy:*** Not Applicable
DEM Ground Elev m: 228
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218544432 ***Mat Consistency:***
Top Depth: 0 ***Material Moisture:***
Bottom Depth: .3 ***Material Texture:***
Material Color: ***Non Geo Mat Type:***
Material 1: Soil ***Geologic Formation:***
Material 2: ***Geologic Group:***
Material 3: ***Geologic Period:***
Material 4: ***Depositional Gen:***
Gsc Material Description:
Stratum Description: SOIL.

Geology Stratum ID: 218544435 ***Mat Consistency:*** Dense
Top Depth: 3.7 ***Material Moisture:***
Bottom Depth: 6.3 ***Material Texture:***
Material Color: Grey ***Non Geo Mat Type:***
Material 1: Till ***Geologic Formation:***
Material 2: Silt ***Geologic Group:***
Material 3: Sand ***Geologic Period:***
Material 4: Gravel ***Depositional Gen:*** glacial
Gsc Material Description:
Stratum Description: TILL,SILT,SAND, GRAVEL. GREY,GLACIAL,VERY DENSE, AGE GLACIAL. 0001002700045100001201000000 5
**Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218544433 ***Mat Consistency:*** Compact
Top Depth: .3 ***Material Moisture:***
Bottom Depth: 1.4 ***Material Texture:***
Material Color: Red ***Non Geo Mat Type:***
Material 1: Silt ***Geologic Formation:***
Material 2: Sand ***Geologic Group:***
Material 3: Gravel ***Geologic Period:***
Material 4: ***Depositional Gen:***
Gsc Material Description:
Stratum Description: SILT,SAND,GRAVEL. WEATHERED,COMPACT.

Geology Stratum ID: 218544434 ***Mat Consistency:*** Dense
Top Depth: 1.4 ***Material Moisture:***
Bottom Depth: 3.7 ***Material Texture:***
Material Color: Brown ***Non Geo Mat Type:***
Material 1: Till ***Geologic Formation:***
Material 2: Sand ***Geologic Group:***
Material 3: Silt ***Geologic Period:***
Material 4: Gravel ***Depositional Gen:*** glacial
Gsc Material Description:
Stratum Description: TILL,SAND,SILT, GRAVEL. BROWN,GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 744.8 FEET.

Source

Source Type: Data Survey ***Source Appl:*** Spatial/Tabular
Source Orig: Geological Survey of Canada ***Source Iden:*** 1
Source Date: 1956-1972 ***Scale or Res:*** Varies
Confidence: M ***Horizontal:*** NAD27
Observatio: ***Verticalda:*** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR3.txt RecordID: 253740 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

279 ***1 of 1*** ***ESE/43.6*** ***228.9 / -13.08*** ***121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON*** ***WWIS***

Well ID:	7401799	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	10/25/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	962ZUTHN	***Contractor:***	6607
Tag:	A327796	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	007
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS E
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/740\7401799.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/18/2021
Year Completed:	2021
Depth (m):	6
Latitude:	43.7020538556266
Longitude:	-79.7587764604911
X:	-79.75877630974477
Y:	43.70205385412501
Path:	740\7401799.pdf

Bore Hole Information

Bore Hole ID:	1008831512	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	600011.00
Code OB Desc:		***North83:***	4839530.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/18/2021	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1008831908
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	01
Material 3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	2.4000000953674316
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1008831910
Layer:	3
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	72
Material 2 Desc:	GRAVELLY
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	4.5
Formation End Depth:	6.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1008831909
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	61
Material 2 Desc:	CLAYEY
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	2.4000000953674316
Formation End Depth:	4.5
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008832231
Layer:	2
Plug From:	0.30000001192092896
Plug To:	2.700000047683716

Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008832230
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008832166
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1008831735
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008831649
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008832008
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008832062
Layer: 1
Slot: 10
Screen Top Depth: 3.0
Screen End Depth: 6.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008831650
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008831845
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 4.699999809265137
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1008832111
Diameter: 21.0
Depth From: 0.0
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

280 ***1 of 2*** ***ESE/112.8*** ***223.5 / -18.45*** ***BACKYARD GETAWAYS***
16 LOCUSTWOOD CRT,,BRAMPTON,ON,L6V 3C1,CA
ON ***PINC***

Incident Id:
Incident No: 1949206
Incident Reported Dt: 9/26/2016
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: BACKYARD GETAWAYS
Incident Address: 16 LOCUSTWOOD CRT,,BRAMPTON,ON,L6V 3C1,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

Occurrence Desc:
Damage Reason:
Notes:

---

280 *2 of 2* *ESE/112.8* *223.5 / -18.45* ***16 Locustwood Crt Brampton ON*** ***SPL***

Ref No:	8783-AE6J52	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/26/2016	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/26/2016	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	

Site No: NA
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: tssa<UNOFFICIAL>
Site Address: 16 Locustwood Crt
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Operator/Human Error
Incident Summary: TSSA: 16 Locustwood crt line strike, made safe
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 1 number (count)
Contaminant Qty 1: 1
Contaminant Unit: number (count)
Contaminant Code: 35
Contaminant Name: METHANE GAS, COMPRESSED (NATURAL GAS)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Communal
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

281 *1 of 1* *ESE/242.0* *229.9 / -12.08* ***ON*** ***BORE***

Borehole ID:	638958	**Inclin FLG:**	No

OGF ID:	215539355	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	SEP-1969	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.70427
Total Depth m:	1.2	**Longitude DD:**	-79.757259
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	600130
Drill Method:	Power auger	**Northing:**	4839778
Orig Ground Elev m:	229	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	229		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218486509	**Mat Consistency:**	
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT(36), CLAY(35),SAND. BROWN,GLACIAL,LAYERED, AGE GLACIAL. 012 Y,GLA **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218486508	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:	organic material	**Geologic Group:**	
Material 3:		**Geologic Period:**	Quaternary
Material 4:		**Depositional Gen:**	organic
Gsc Material Description:			
Stratum Description:	SOIL,ORGANIC. AGE QUATERNARY.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 069210 NTS_Sheet: 30M12F		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		

Source Originators: Geological Survey of Canada

282 **1 of 1** **ESE/57.2** **228.9 / -13.08** **227 VODDEN STREET EAST Brampton ON** **WWIS**

Well ID:	7219358	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	04/23/2014
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z185805	**Contractor:**	7241
Tag:	A159356	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1004732751	**Tag No:**	A159356
Depth M:	4.57	**Contractor:**	7241
Year Completed:	2014	**Latitude:**	43.7026521283176
Well Completed Dt:	03/07/2014	**Longitude:**	-79.7583173230001
Audit No:	Z185805	**Y:**	43.702652126150674
Path:		**X:**	-79.75831717281098

Bore Hole Information

Bore Hole ID:	1004732751	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	600047.00
Code OB Desc:		**North83:**	4839597.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	03/07/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005130445
Layer:	3
Color:	2
General Color:	GREY
Material 1:	06

Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 1.5
Formation End Depth: 4.570000171661377
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005130444
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.6000000238418579
Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005130443
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 0.6000000238418579
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005130453
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005130454
Layer: 2
Plug From: 0.30000001192092896
Plug To: 1.2200000286102295
Plug Depth UOM: m

Annular Space/Abandonment

Sealing Record

Plug ID:	1005130455
Layer:	3
Plug From:	1.2200000286102295
Plug To:	4.570000171661377
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1005130452
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005130442
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005130448
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	1.5
Casing Diameter:	5.199999809265137
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1005130449
Layer:	1
Slot:	10
Screen Top Depth:	1.5
Screen End Depth:	4.570000171661377
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03000020980835

Water Details

Water ID:	1005130447
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1005130446
Diameter:	15.239999771118164
Depth From:	0.0

Depth To: 4.570000171661377
Hole Depth UOM: m
Hole Diameter UOM: cm

---

283 **1 of 1** **ESE/46.3** **228.9 / -13.08** **121 KENNEDY RD. N BRAMPTON ON** **WWIS**

Well ID: 7308835
Construction Date:
Use 1st: Municipal
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z267014
Tag: A232654
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/05/2018
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/730\7308835.pdf

Additional Detail(s) (Map)

Well Completed Date: 02/12/2018
Year Completed: 2018
Depth (m): 6
Latitude: 43.7023832856531
Longitude: -79.7584345700768
X: -79.75843442001022
Y: 43.70238328435574
Path: 730\7308835.pdf

Bore Hole Information

Bore Hole ID: 1007013104
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/12/2018
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 600038.00
North83: 4839567.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007134092
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 0.0
Formation End Depth: 2.0999999046325684
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007134093
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 06
Material 2 Desc: SILT
Material 3: 11
Material 3 Desc: GRAVEL
Formation Top Depth: 2.0999999046325684
Formation End Depth: 6.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007134101
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.700000047683716
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007134100
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007134099
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007134091
Casing No: 0

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1007134096
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007134097
Layer:	1
Slot:	10
Screen Top Depth:	3.0
Screen End Depth:	6.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	1007134095
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1007134094
Diameter:	21.0
Depth From:	0.0
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
284	*1 of 3*	*ESE/240.6*	*229.9 / -12.08*	***BRAMPTON HYDRO-ELECTRIC COMMISSION*** ***HANSEN ROAD-SOUTH OF VODDEN 129*** ***GLIDDEN ROAD*** ***BRAMPTON ON L6W 3L9***	*GEN*

Generator Info

Generator No:	ON0291404	***Choice of Contact:***	
Approval Years:	88,89,90	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	4911
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	ELECT. POWER SYS.		

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

284 ***2 of 3*** ***ESE/240.6*** ***229.9 / -12.08*** ***BRAMPTON HYDRO-ELECTRIC COMMISSION06-328***
HANSEN ROAD-SOUTH OF VODDEN 129
GLIDDEN ROAD
BRAMPTON ON L6W 3L9 ***GEN***

Generator Info

Generator No: ON0291404
Approval Years: 92,93,94,95,96,97
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ELECT. POWER SYS.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4911

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

284 ***3 of 3*** ***ESE/240.6*** ***229.9 / -12.08*** ***BRAMPTON HYDRO-ELECTRIC COMMISSION***
HANSEN ROAD-SOUTH OF VODDEN
BRAMPTON ON ***GEN***

Generator Info

Generator No: ON0291404
Approval Years: 98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ELECT. POWER SYS.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4911

Waste Detail(s)

Waste Class: 251

Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

285 | **1 of 1** | **ESE/53.3** | **228.9 / -13.08** | **121 KENNEDY RD. N. BRAMPTON ON** | **WWIS**

Well ID: 7308837
Construction Date:
Use 1st: Municipal
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z267012
Tag: A241185
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/05/2018
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6607
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/730\7308837.pdf

Additional Detail(s) (Map)

Well Completed Date: 02/12/2018
Year Completed: 2018
Depth (m): 6
Latitude: 43.70221238505
Longitude: -79.7584505082641
X: -79.75845035793017
Y: 43.70221238300602
Path: 730\7308837.pdf

Bore Hole Information

Bore Hole ID: 1007013110
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 02/12/2018
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 600037.00
North83: 4839548.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID:	1007135284
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.0
Formation End Depth:	2.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007135285
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	11
Material 3 Desc:	GRAVEL
Formation Top Depth:	2.0999999046325684
Formation End Depth:	6.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007135293
Layer:	2
Plug From:	0.30000001192092896
Plug To:	2.700000047683716
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007135291
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1007135290
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007135283
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007135288
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007135289
Layer:	1
Slot:	10
Screen Top Depth:	3.0
Screen End Depth:	6.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	1007135287
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1007135286
Diameter:	21.0
Depth From:	0.0
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

286 ***1 of 1*** ***ESE/61.5*** ***228.9 / -13.08*** ***121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON*** ***WWIS***

Well ID:	7401794	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	10/25/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	72VARR4D	***Contractor:***	6607
Tag:	A327692	***Form Version:***	9
Constructn Method:		***Owner:***	

Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	007
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS E
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/740\7401794.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/18/2021
Year Completed:	2021
Depth (m):	6
Latitude:	43.7019173452656
Longitude:	-79.7586427589901
X:	-79.75864260904423
Y:	43.701917343131456
Path:	740\7401794.pdf

Bore Hole Information

Bore Hole ID:	1008831497	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	600022.00
Code OB Desc:		**North83:**	4839515.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/18/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008831896
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	01
Material 3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	2.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID: 1008831897
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 61
Material 2 Desc: CLAYEY
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 2.0999999046325684
Formation End Depth: 4.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1008831898
Layer: 3
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2: 72
Material 2 Desc: GRAVELLY
Material 3: 67
Material 3 Desc: DIRTY
Formation Top Depth: 4.5
Formation End Depth: 6.0
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008832220
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.700000047683716
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008832161
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1008832219
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1008831730
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008831639
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008832003
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1008832057
Layer: 1
Slot: 10
Screen Top Depth: 3.0
Screen End Depth: 6.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008831640
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008831840
Layer: 1
Kind Code: 8
Kind: Untested

Water Found Depth: 4.699999809265137
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1008832106
Diameter: 21.0
Depth From: 0.0
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

287 **1 of 1** **ESE/99.8** **228.9 / -13.08** **ON** **BORE**

Borehole ID: 654703
OGF ID: 215555048
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: NOV-1970
Static Water Level: 0.5
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 4.8
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 227
Elev Reliabil Note:
DEM Ground Elev m: 227
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.702926
Longitude DD: -79.757908
UTM Zone: 17
Easting: 600080
Northing: 4839628
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218544413
Top Depth: .9
Bottom Depth: 4.3
Material Color: Brown
Material 1: Till
Material 2: Sand
Material 3: Gravel
Material 4: Shale
Gsc Material Description:
Stratum Description: TILL,SAND,GRAVEL, SHALE. BROWN,GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 743.2 FEET.

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218544414
Top Depth: 4.3
Bottom Depth: 4.8
Material Color: Red
Material 1: Silt
Material 2: Clay
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SILT,CLAY. RED,LACUSTRINE, AGE POST-GLACIAL. 00000024 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218544412
Mat Consistency: Compact

Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND. GLACIAL,COMPACT,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 253680 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

288 ***1 of 1*** ***ESE/60.2*** ***228.9 / -13.08*** ***121 KENNEDY ROAD NORTH Brampton ON*** ***WWIS***

Well ID:	7298064	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	10/31/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z255529	**Contractor:**	6607
Tag:	A232877	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/729\7298064.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/08/2017
Year Completed:	2017
Depth (m):	5.36
Latitude:	43.7020866285449

Longitude: -79.7584779253945
X: -79.75847777451516
Y: 43.702086626936634
Path: 729\7298064.pdf

Bore Hole Information

Bore Hole ID: 1006784878
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/08/2017
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 600035.00
North83: 4839534.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006955178
Layer: 2
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 28
Material 2 Desc: SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.15000000596046448
Formation End Depth: 3.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955179
Layer: 3
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 84
Material 2 Desc: SILTY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 3.0
Formation End Depth: 4.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955177

Layer: 1
Color: 2
General Color: GREY
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.15000000596046448
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955180
Layer: 4
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 06
Material 2 Desc: SILT
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 4.5
Formation End Depth: 5.360000133514404
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006955188
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006955189
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.0999999046325684
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006955187
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1006955176
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1006955183
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	2.299999952316284
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1006955184
Layer:	1
Slot:	.1
Screen Top Depth:	2.299999952316284
Screen End Depth:	5.300000190734863
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	1006955182
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	4.5
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1006955181
Diameter:	21.0
Depth From:	0.0
Depth To:	5.300000190734863
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

289 ***1 of 1*** ***SE/113.5*** ***218.8 / -23.11*** ***BRAMPTON ON*** ***SPL***

Ref No:	1-3RHSJ3	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	8/22/2023 11:15:00 AM	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	8/22/2023 6:07:55 PM	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		

Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	Pipeline/Components
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Human error (Specify)
Incident Summary:	TSSAfsb ½ in pl IP gas srvc dmgd made safe
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Activity Preceding Spill:	Construction or repair
Property 2nd Watershed:	02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed:	02HC | Humber River - Don River
Sector Type:	NATURAL GAS DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001851173"],"wkts":["POINT (-79.7687032000 43.6920380000)"],"creation_date":"2023-08-22"}
Time Reported:	
System Facility Address:	

---

290 **1 of 1** **ESE/59.1** **228.9 / -13.08** **121 KENNEDY RD. N BRAMPTON ON** **WWIS**

Well ID:	7308836	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	04/05/2018
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z267013	**Contractor:**	6607
Tag:	A232655	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/730\7308836.pdf

Additional Detail(s) (Map)

Well Completed Date:	02/12/2018
Year Completed:	2018
Depth (m):	6
Latitude:	43.7022293103971
Longitude:	-79.7583508724104
X:	-79.75835072221899
Y:	43.7022293083984
Path:	730\7308836.pdf

Bore Hole Information

Bore Hole ID:	1007013107	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	600045.00
Code OB Desc:		**North83:**	4839550.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	02/12/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007134103
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.0
Formation End Depth:	2.0999999046325684
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007134104
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	11
Material 3 Desc:	GRAVEL
Formation Top Depth:	2.0999999046325684
Formation End Depth:	6.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007134115
Layer:	2
Plug From:	0.30000001192092896
Plug To:	2.700000047683716
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007134110
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1007134109
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007134102
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007134107
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007134108
Layer:	1
Slot:	10
Screen Top Depth:	3.0
Screen End Depth:	6.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	1007134106

Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1007134105
Diameter: 21.0
Depth From: 0.0
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

291 **1 of 1** **ESE/68.5** **228.7 / -13.20** **99 KENNEDY STREET N Brampton ON** **WWIS**

Well ID: 7369738
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z345158
Tag: A302453
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 10/06/2020
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1008485198
Depth M:
Year Completed: 2020
Well Completed Dt: 08/21/2020
Audit No: Z345158
Path:

Tag No: A302453
Contractor: 7241
Latitude: 43.7018716620768
Longitude: -79.7585816480106
Y: 43.70187166015389
X: -79.7585814975773

Bore Hole Information

Bore Hole ID: 1008485198
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 08/21/2020
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:

Elevation:
Elevrc:
Zone: 17
East83: 600027.00
North83: 4839510.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1009624414
Layer: 5
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 10.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624410
Layer: 1
Color: 2
General Color: GREY
Material 1: 27
Material 1 Desc: OTHER
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624411
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.5
Formation End Depth: 1.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624416
Layer: 7
Color:

General Color:
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 20.0
Formation End Depth:
Formation End Depth UOM:

Overburden and Bedrock Materials Interval

Formation ID: 1009624412
Layer: 3
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 1.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624413
Layer: 4
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 06
Material 3 Desc: SILT
Formation Top Depth: 5.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624415
Layer: 6
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 15.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009625551
Layer:	2
Plug From:	8.0
Plug To:	0.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009625550
Layer:	1
Plug From:	20.0
Plug To:	8.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1009625552
Layer:	3
Plug From:	0.5
Plug To:	0.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1009627171
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1009623411
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1009627606
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	10.0
Depth To:	0.0
Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1009628040
Layer:	1
Slot:	10
Screen Top Depth:	20.0
Screen End Depth:	10.0

Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	Inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009628484
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009626718
Diameter:	6.0
Depth From:	20.0
Depth To:	0.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

---

292 | ***1 of 1*** | ***ESE/66.7*** | ***228.9 / -13.08*** | ***99 KENNEDY STREET N Brampton ON*** | ***WWIS***

Well ID:	7369739	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring and Test Hole	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	10/06/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z345157	**Contractor:**	7241
Tag:	A302454	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1008485201	**Tag No:**	A302454
Depth M:		**Contractor:**	7241

Year Completed:	2020	***Latitude:***	43.7019787409705
Well Completed Dt:	08/21/2020	***Longitude:***	-79.758492562852
Audit No:	Z345157	***Y:***	43.70197873904448
Path:		***X:***	-79.75849241256769

Bore Hole Information

Bore Hole ID:	1008485201	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	600034.00
Code OB Desc:		***North83:***	4839522.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/21/2020	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009624418
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.5
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009624419
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	1.0
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009624421

Layer: 5
Color: 7
General Color: RED
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 10.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624417
Layer: 1
Color: 2
General Color: GREY
Material 1: 27
Material 1 Desc: OTHER
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624420
Layer: 4
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 06
Material 3 Desc: SILT
Formation Top Depth: 5.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624422
Layer: 6
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 15.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009625557
Layer: 1
Plug From: 20.0
Plug To: 8.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009625556
Layer: 1
Plug From:
Plug To:
Plug Depth UOM:

Annular Space/Abandonment Sealing Record

Plug ID: 1009625559
Layer: 3
Plug From: 0.5
Plug To: 0.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009625558
Layer: 2
Plug From: 8.0
Plug To: 0.5
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009627172
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1009623412
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009627607
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 10.0
Depth To: 0.0

Casing Diameter:	2.0
Casing Diameter UOM:	Inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1009628041
Layer:	1
Slot:	10
Screen Top Depth:	20.0
Screen End Depth:	10.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	Inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009628485
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009626719
Diameter:	6.0
Depth From:	20.0
Depth To:	0.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

---

293 | ***1 of 1*** | ***ESE/69.8*** | ***228.7 / -13.20*** | ***121 KENNEDY RD. N lot 7 con 1 BRAMPTON ON*** | ***WWIS***

Well ID:	7401796	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	10/25/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	7TZDDGAB	**Contractor:**	6607
Tag:	A327770	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	007
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS E

Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/740\7401796.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/18/2021
Year Completed:	2021
Depth (m):	6
Latitude:	43.7018981285504
Longitude:	-79.7585314588292
X:	-79.758531308716
Y:	43.70189812709567
Path:	740\7401796.pdf

Bore Hole Information

Bore Hole ID:	1008831503	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	600031.00
Code OB Desc:		**North83:**	4839513.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/18/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008831903
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	61
Material 2 Desc:	CLAYEY
Material 3:	73
Material 3 Desc:	HARD
Formation Top Depth:	0.6000000238418579
Formation End Depth:	4.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1008831904
Layer:	3
Color:	2

General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	72
Material 2 Desc:	GRAVELLY
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	4.5
Formation End Depth:	6.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1008831902
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	01
Material 3 Desc:	FILL
Formation Top Depth:	0.0
Formation End Depth:	0.6000000238418579
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008832223
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008832224
Layer:	2
Plug From:	0.30000001192092896
Plug To:	2.700000047683716
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1008832163
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1008831732
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1008831643
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008832005
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1008832059
Layer:	1
Slot:	10
Screen Top Depth:	3.0
Screen End Depth:	6.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008831644
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008831842
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	4.699999809265137
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1008832108
Diameter:	21.0
Depth From:	0.0
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

294 ***1 of 1*** ***ESE/127.4*** ***228.9 / -13.08*** ***ON*** ***BORE***

Borehole ID:	654701	***Inclin FLG:***	No
OGF ID:	215555046	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	NOV-1970	***Municipality:***	
Static Water Level:	0.5	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.703104
Total Depth m:	4.7	***Longitude DD:***	-79.757656
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	600100
Drill Method:	Power auger	***Northing:***	4839648
Orig Ground Elev m:	226	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	227		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218544408	***Mat Consistency:***	Hard
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.2	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND, GRAVEL. GLACIAL,HARD,AGE GLACIAL.		

Geology Stratum ID:	218544409	***Mat Consistency:***	Dense
Top Depth:	1.2	***Material Moisture:***	
Bottom Depth:	4.7	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT, GRAVEL. GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 742.6 FEET.00001LT, CLA **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies

Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 253660 NTS_Sheet: 30M12C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

295 ***1 of 1*** ***ESE/69.0*** ***228.9 / -13.08*** ***121 KENNEDY ROAD NORTH Brampton ON*** ***WWIS***

Well ID:	7298063	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	10/31/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z255528	**Contractor:**	6607
Tag:	A232568	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/729\7298063.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/08/2017
Year Completed:	2017
Depth (m):	6
Latitude:	43.7020139396789
Longitude:	-79.7584173717698
X:	-79.75841722180257
Y:	43.70201393817977
Path:	729\7298063.pdf

Bore Hole Information

Bore Hole ID:	1006784875	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	600040.00
Code OB Desc:		**North83:**	4839526.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/08/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m

Remarks: **Location Method:** wwr
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1006955166
Layer: 4
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 81
Material 2 Desc: SANDY
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 4.5
Formation End Depth: 6.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955163
Layer: 1
Color: 2
General Color: GREY
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.15000000596046448
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955164
Layer: 2
Color: 2
General Color: GREY
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 28
Material 2 Desc: SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.15000000596046448
Formation End Depth: 0.30000001192092896
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955165
Layer: 3
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 84
Material 2 Desc: SILTY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.30000001192092896
Formation End Depth: 4.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006955175
Layer: 2
Plug From: 0.30000001192092896
Plug To: 2.9000000953674316
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006955174
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006955173
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1006955162
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006955169
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 3.0
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006955170
Layer: 1
Slot: .1
Screen Top Depth: 3.0
Screen End Depth: 6.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Water Details

Water ID: 1006955168
Layer: 1
Kind Code:
Kind:
Water Found Depth: 5.300000190734863
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006955167
Diameter: 21.0
Depth From: 0.0
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

296 | **1 of 1** | **ESE/70.7** | **228.9 / -13.08** | **99 KENNEDY STREET N Brampton ON** | **WWIS**

Well ID: 7369740
Construction Date:
Use 1st: Monitoring and Test Hole
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z345156
Tag: A302455
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 10/06/2020
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1008485204
Depth M:
Year Completed: 2020
Well Completed Dt: 08/21/2020
Audit No: Z345156
Path:

Tag No: A302455
Contractor: 7241
Latitude: 43.7020581401996
Longitude: -79.7583419947899
Y: 43.702058138394015
X: -79.75834184508545

Bore Hole Information

Bore Hole ID:	1008485204	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	600046.00
Code OB Desc:		***North83:***	4839531.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/21/2020	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009624426
Layer:	4
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	5.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009624423
Layer:	1
Color:	2
General Color:	GREY
Material 1:	27
Material 1 Desc:	OTHER
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009624427
Layer:	5
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	

Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 10.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624425
Layer: 3
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 06
Material 3 Desc: SILT
Formation Top Depth: 1.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624424
Layer: 2
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.5
Formation End Depth: 1.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009624428
Layer: 6
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 91
Material 3 Desc: WATER-BEARING
Formation Top Depth: 15.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009625560

Layer: 1
Plug From:
Plug To:
Plug Depth UOM:

Annular Space/Abandonment Sealing Record

Plug ID: 1009625562
Layer: 2
Plug From: 8.0
Plug To: 0.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009625561
Layer: 1
Plug From: 20.0
Plug To: 8.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009625563
Layer: 3
Plug From: 0.5
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009627173
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1009623413
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009627608
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 10.0
Depth To: 0.0
Casing Diameter: 2.0
Casing Diameter UOM: Inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID:	1009628042
Layer:	1
Slot:	10
Screen Top Depth:	20.0
Screen End Depth:	10.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	Inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009628486
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009626720
Diameter:	6.0
Depth From:	20.0
Depth To:	0.0
Hole Depth UOM:	ft
Hole Diameter UOM:	Inch

---

297 **1 of 1** **ESE/87.1** **228.9 / -13.08** **ON** **BORE**

Borehole ID:	654706	**Inclin FLG:**	No
OGF ID:	215555051	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1970	**Municipality:**	
Static Water Level:	0.6	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.702566
Total Depth m:	6.5	**Longitude DD:**	-79.757915
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	600080
Drill Method:	Power auger	**Northing:**	4839588
Orig Ground Elev m:	226	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	227		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218544423	***Mat Consistency:***	Dense
Top Depth:	.3	***Material Moisture:***	
Bottom Depth:	1.5	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. WEATHERED,DENSE,AGE GLACIAL.		

Geology Stratum ID:	218544422	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Soil	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SOIL.		

Geology Stratum ID:	218544425	***Mat Consistency:***	Hard
Top Depth:	3.4	***Material Moisture:***	
Bottom Depth:	6.5	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:	Sand	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY,GRAVEL, SAND. RED,GLACIAL,HARD,AGE GLACIAL. 0001003200050100001101000000 5 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218544424	***Mat Consistency:***	Dense
Top Depth:	1.5	***Material Moisture:***	
Bottom Depth:	3.4	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT, GRAVEL. GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 742.4 FEET.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 253710 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level

Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

298 **1 of 1** **ESE/134.4** **227.8 / -14.10** **THE XTERMINATOR** **PES**
52 CUMBERLAND DR
BRAMPTON ON L6V 1W6

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	Operator
Report Source:		**Oper Area Code:**	
Licence Type:		**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

299 **1 of 1** **ESE/77.1** **228.9 / -13.08** **121 KENNEDY ROAD NORTH** **WWIS**
Brampton ON

Well ID:	7298061	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Test Hole	**Data Entry Status:**	
Use 2nd:	Monitoring	**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	10/31/2017
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z255543	**Contractor:**	6607
Tag:	A232864	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	BRAMPTON CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/729\7298061.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/08/2017
Year Completed:	2017
Depth (m):	6
Latitude:	43.70205706173
Longitude:	-79.7582427308148
X:	-79.75824258127824

Y: 43.70205706033565
Path: 729\7298061.pdf

Bore Hole Information

Bore Hole ID: 1006784869
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/08/2017
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 600054.00
North83: 4839531.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006955123
Layer: 1
Color: 2
General Color: GREY
Material 1:
Material 1 Desc:
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 0.15000000596046448
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955125
Layer: 3
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 84
Material 2 Desc: SILTY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.30000001192092896
Formation End Depth: 4.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006955126
Layer: 4
Color: 6

General Color:	BROWN
Material 1:	06
Material 1 Desc:	SILT
Material 2:	81
Material 2 Desc:	SANDY
Material 3:	91
Material 3 Desc:	WATER-BEARING
Formation Top Depth:	4.5
Formation End Depth:	6.0
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006955124
Layer:	2
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.15000000596046448
Formation End Depth:	0.30000001192092896
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006955135
Layer:	2
Plug From:	0.30000001192092896
Plug To:	2.9000000953674316
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006955134
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1006955133
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1006955122
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006955129
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	3.0
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1006955130
Layer:	1
Slot:	.1
Screen Top Depth:	3.0
Screen End Depth:	6.0
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	1006955128
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	5.400000095367432
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1006955127
Diameter:	21.0
Depth From:	0.0
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

300 ***1 of 1*** ***WNW/153.1*** ***259.3 / 17.40*** ***OLD SCHOOL ROAD BRAMPTON ON*** ***WWIS***

Well ID:	7300315	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	12/04/2017
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z239552	***Contractor:***	7360
Tag:	A234527	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	

Clear/Cloudy: ***UTM Reliability:***
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/730\7300315.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/15/2017
Year Completed: 2017
Depth (m): 10.668
Latitude: 43.7470718930463
Longitude: -79.8561639117712
X: -79.85616376204771
Y: 43.747071891153546
Path: 730\7300315.pdf

Bore Hole Information

Bore Hole ID: 1006842722 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17
Code OB: ***East83:*** 592095.00
Code OB Desc: ***North83:*** 4844417.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 11/15/2017 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1007028357
Layer: 3
Color: 7
General Color: RED
Material 1: 05
Material 1 Desc: CLAY
Material 2: 34
Material 2 Desc: TILL
Material 3:
Material 3 Desc:
Formation Top Depth: 25.0
Formation End Depth: 35.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007028356
Layer: 2
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND

Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 5.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1007028355
Layer: 1
Color: 6
General Color: BROWN
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007028364
Layer: 1
Plug From: 19.0
Plug To: 0.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007028363
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1007028354
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007028360
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 21.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Construction Record - Screen

Screen ID:	1007028361
Layer:	1
Slot:	.10
Screen Top Depth:	21.0
Screen End Depth:	26.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.0

Water Details

Water ID:	1007028359
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1007028358
Diameter:	6.0
Depth From:	0.0
Depth To:	35.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

301 ***1 of 2*** ***ESE/91.8*** ***228.0 / -13.93*** ***WALLSTAR PROPERTIES LTD.***
99 KENNEDY RD.N.
BRAMPTON ON L6V 1X8 ***CA***

Certificate #:	8-3010-85-006
Application Year:	85
Issue Date:	3/11/85
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	Other Organic Compounds
Emission Control:	Thermal Incineration

---

301 ***2 of 2*** ***ESE/91.8*** ***228.0 / -13.93*** ***99 Kennedy Rd N***
Brampton ON L6V 1X7 ***EHS***

Order No:	20200723199	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	28-JUL-20	***Search Radius (km):***	.2
Date Received:	23-JUL-20	***X:***	-79.7585191
Previous Site Name:		***Y:***	43.7015911
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
302	1 of 1	ESE/120.6	228.9 / -13.08	The Corporation of the City of Brampton 225 Vodden St E Brampton ON L6V 4M1	SPL

Ref No:	2700-BQH5K2	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2020/06/11	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2020/06/11	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2020/11/27	**Agency Involved:**	

Site No: 7165-BQHGB8
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: 225 Vodden Street East
Site Address: 225 Vodden St E
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Entity Operating Name:
Client Name: The Corporation of the City of Brampton
Client Type: Municipal Government
Source Type: Sewer (Private or Municipal)
Incident Cause:
Incident Preceding Spill: Overflow/Surcharge
Incident Reason: Blockage
Incident Summary: RoP: Private side surcharging manhole, cleared
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 1 other - see incident description
Contaminant Qty 1: 1
Contaminant Unit: other - see incident description
Contaminant Code: 44
Contaminant Name: SEWAGE,PRIMARY UNCHLORINATED
Contaminant Limit 1:
Contam Limit Freq 1: n/a
Contaminant UN No 1: n/a
Receiving Medium: Land; Surface Water; Source Water Zone
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Municipal Sewage
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
303	1 of 1	ESE/110.6	228.9 / -13.08	ON	BORE

Borehole ID:	654704	**Inclin FLG:**	No
OGF ID:	215555049	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1970	**Municipality:**	

Static Water Level:	0.4	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.702744
Total Depth m:	3.8	**Longitude DD:**	-79.757663
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	600100
Drill Method:	Power auger	**Northing:**	4839608
Orig Ground Elev m:	226	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	227		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218544415	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL.		

Geology Stratum ID:	218544417	**Mat Consistency:**	Dense
Top Depth:	2.1	**Material Moisture:**	
Bottom Depth:	3.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND. BROWN,GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 741.8 FEET. 000101000007010 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218544416	**Mat Consistency:**	Dense
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	2.1	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. BROWN,GLACIAL,DENSE, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 253690 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

304 *1 of 18* *SE/138.4* *218.8 / -23.15*

LEO ARCHDEKIN FUNERAL HOME
289 MAIN STREET N.
BRAMPTON ON L6X 1N5

GEN

Generator Info

Generator No: ONF001100
Approval Years: 88,89,90
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: FUNERAL HOMES
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 9731

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

304 *2 of 18* *SE/138.4* *218.8 / -23.15*

LEO ARCHDEKIN FUNERAL HOME
289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5

GEN

Generator Info

Generator No: ONF001100
Approval Years: 92,93,97,98,99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: FUNERAL HOMES
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 9731

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

304 *3 of 18* *SE/138.4* *218.8 / -23.15*

TRILLIUM FUNERAL SERVICES CORP.
289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5

GEN

Generator Info

Generator No: ONF013301
Approval Years: 92,93,97,98,99
Choice of Contact:
Contaminated Fac:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 9731
Country:
Co Admin:
Phone No Admin:
SIC Description: FUNERAL HOMES

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

304 ***4 of 18*** ***SE/138.4*** ***218.8 / -23.15*** ***LEO ARCHDEKIN FUNERAL HOME 44-011***
289 MAIN STREET N.
BRAMPTON ON L6X 1N5 ***GEN***

Generator Info

Generator No: ONF001100 ***Choice of Contact:***
Approval Years: 94,95,96 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 9731
Country:
Co Admin:
Phone No Admin:
SIC Description: FUNERAL HOMES

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

304 ***5 of 18*** ***SE/138.4*** ***218.8 / -23.15*** ***SCOTT FUNERAL HOME, DIV. OF 44-543***
TRILLIUM FUNERAL SERVICES CORP. 289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5 ***GEN***

Generator Info

Generator No: ONF013301 ***Choice of Contact:***
Approval Years: 94,95,96 ***Contaminated Fac:***
Status: ***MHSW Facility:***
PO Box No: ***SIC Code:*** 9731
Country:
Co Admin:
Phone No Admin:
SIC Description: FUNERAL HOMES

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

304 ***6 of 18*** ***SE/138.4*** ***218.8 / -23.15*** ***TRILLIUM FUNERAL SERVICES CORPORATION***
289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5 ***GEN***

Generator Info

Generator No:	ONF013301	***Choice of Contact:***	
Approval Years:	00,01,03,04,05,07,08	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	9731
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	FUNERAL HOMES		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

304 ***7 of 18*** ***SE/138.4*** ***218.8 / -23.15*** ***TRILLIUM FUNERAL SERVICES CORPORATION*** ***GEN***
289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5

Generator Info

Generator No:	ONF013301	***Choice of Contact:***	
Approval Years:	2009	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	812210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Funeral Homes		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

304 ***8 of 18*** ***SE/138.4*** ***218.8 / -23.15*** ***TRILLIUM FUNERAL SERVICES CORPORATION*** ***GEN***
289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5

Generator Info

Generator No:	ONF013301	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	812210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Funeral Homes		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
304	9 of 18	SE/138.4	218.8 / -23.15	TRILLIUM FUNERAL SERVICES CORPORATION 289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	GEN

Generator Info

Generator No:	ONF013301	**Choice of Contact:**	
Approval Years:	2011	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	812210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Funeral Homes		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
304	10 of 18	SE/138.4	218.8 / -23.15	ARBOR MEMORIAL INC. 289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	GEN

Generator Info

Generator No:	ONF013301	**Choice of Contact:**	
Approval Years:	2012	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	812210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Funeral Homes		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
304	11 of 18	SE/138.4	218.8 / -23.15	ARBOR MEMORIAL INC. 289 MAIN STREET NORTH BRAMPTON ON	GEN

Generator Info

Generator No:	ONF013301	**Choice of Contact:**	
Approval Years:	2013	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	812210
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

304 ***12 of 18*** ***SE/138.4*** ***218.8 / -23.15*** ***ARBOR MEMORIAL INC.*** ***GEN***
289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5

Generator Info

Generator No:	ONF013301	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2016	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	812210
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	812210		

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

304 ***13 of 18*** ***SE/138.4*** ***218.8 / -23.15*** ***ARBOR MEMORIAL INC.*** ***GEN***
289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5

Generator Info

Generator No:	ONF013301	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2015	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	812210
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	812210		

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

304 ***14 of 18*** ***SE/138.4*** ***218.8 / -23.15*** ***ARBOR MEMORIAL INC.*** ***GEN***
289 MAIN STREET NORTH
BRAMPTON ON L6X 1N5

Generator Info

Generator No:	ONF013301	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	812210
Country:	Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Phone No Admin:
SIC Description: 812210

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
304	15 of 18	SE/138.4	218.8 / -23.15	ARBOR MEMORIAL INC. 289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	GEN

Generator Info

Generator No: ONF013301
Approval Years: As of Dec 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
304	16 of 18	SE/138.4	218.8 / -23.15	ARBOR MEMORIAL INC. 289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	GEN

Generator Info

Generator No: ONF013301
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
304	17 of 18	SE/138.4	218.8 / -23.15	ARBOR MEMORIAL INC. 289 MAIN STREET NORTH BRAMPTON ON L6X 1N5	GEN

Generator Info

Generator No:	ONF013301	**Choice of Contact:**	
Approval Years:	As of Nov 2021	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
304	18 of 18	SE/138.4	218.8 / -23.15	Scott Funeral Home - Brampton Chapel 289 MAIN STREET NORTH BRAMPTON ON	GEN

Generator Info

Generator No:	ONF013301	**Choice of Contact:**	
Approval Years:	As of Oct 2022	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	PATHOLOGICAL WASTES

Generator Info as of Dec 2024

Generator No:	ONF013301
Generator Company Name:	Scott Funeral Home - Brampton Chapel
Street:	289 MAIN STREET NORTH
City:	BRAMPTON
Province State:	Ontario
Country:	Canada
Postal Code:	L6X1N5
Waste Class:	312 P

Waste Class Decoded:

312 - PATHOLOGICAL WASTES

2017 Generator Info

Gen No:	ONF013301	**Choice of Contact:**	CO_OFFICIAL
ID:	39092	**Phone No Official:**	905-451-1100 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	812210	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	ARBOR MEMORIAL INC.		

Gen Div:
Gen Op Name: SCOTT FUNERAL HOME
Gen Op Div:
Site Adrs1: 289 MAIN STREET NORTH
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L6X 1N5
Site Country: Canada
Co Official: Nick Larter
Co Admin:

2017 Generator Manifest

ID: 68312
Generator No: ONF013301
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 9.8
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 1
District: 305

2018 Generator Info

Gen No: ONF013301
ID: 39918
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 812210
NAICS Code2:
NAICS Code3:
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-451-1100 Ext.
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305
Gen Name: ARBOR MEMORIAL INC.
Gen Div:
Gen Op Name: SCOTT FUNERAL HOME
Gen Op Div:
Site Adrs1: 289 MAIN STREET NORTH
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: BRAMPTON
Province Out:
Site Postal Code: L6X 1N5
Site Country: Canada
Co Official: Nick Larter
Co Admin:

2018 Generator Manifest

ID: 69024
Generator No: ONF013301
Receiver Type: 035
Waste Char: P
Waste Code: 312
Sum Received Qty: 4.7
Waste Class Name: PATHOLOGICAL WASTES
Count Manifests: 1
District: 305

2019 Generator Info

Gen No: ONF013301
ID: 40489
Contaminated Fac: N
MHSW Facility: N
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-451-1100 Ext.
Phone No Admin:
County Ont: PEEL (R. M.)

NAICS Code1:	812210	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	ARBOR MEMORIAL INC.		
Gen Div:			
Gen Op Name:	SCOTT FUNERAL HOME		
Gen Op Div:			
Site Adrs1:	289 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6X 1N5		
Site Country:	Canada		
Co Official:	Nick Larter		
Co Admin:			

2019 Generator Manifest

ID:	68955	**Sum Received Qty:**	18.0
Generator No:	ONF013301	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	P	**District:**	305
Waste Code:	312		

2020 Generator Info

Gen No:	ONF013301	**Choice of Contact:**	CO_OFFICIAL
ID:	40250	**Phone No Official:**	905-451-1100 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	812210	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	ARBOR MEMORIAL INC.		
Gen Div:			
Gen Op Name:	SCOTT FUNERAL HOME		
Gen Op Div:			
Site Adrs1:	289 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6X 1N5		
Site Country:	Canada		
Co Official:	Nick Larter		
Co Admin:			

2020 Generator Manifest

ID:	64699	**Sum Received Qty:**	42.77
Generator No:	ONF013301	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	3
Waste Char:	P	**District:**	305
Waste Code:	312		

2021 Generator Info

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Gen No:	ONF013301	**Choice of Contact:**	CO_OFFICIAL
ID:	41394	**Phone No Official:**	905-451-1100 Ext.
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	812210	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	ARBOR MEMORIAL INC.		
Gen Div:			
Gen Op Name:	SCOTT FUNERAL HOME		
Gen Op Div:			
Site Adrs1:	289 MAIN STREET NORTH		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	BRAMPTON		
Province Out:			
Site Postal Code:	L6X 1N5		
Site Country:	Canada		
Co Official:	Nick Larter		
Co Admin:			

2021 Generator Manifest

ID:	67959	**Sum Received Qty:**	59.82
Generator No:	ONF013301	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	P	**District:**	305
Waste Code:	312		

---

305 ***1 of 1*** ***ESE/87.8*** ***228.8 / -13.17*** ***ON*** ***BORE***

Borehole ID:	654708	**Inclin FLG:**	No
OGF ID:	215555053	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1970	**Municipality:**	
Static Water Level:	0.5	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.702341
Total Depth m:	4.9	**Longitude DD:**	-79.75792
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	600080
Drill Method:	Power auger	**Northing:**	4839563
Orig Ground Elev m:	226	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	228		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218544429	**Mat Consistency:**	Compact
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.7	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	

Material 3: Sand
Material 4: Gravel
Gsc Material Description:
Stratum Description: TILL,SILT,SAND, GRAVEL. WEATHERED,COMPACT.

Geology Stratum ID: 218544431
Top Depth: 3.1
Bottom Depth: 4.9
Material Color: Grey
Material 1: Sand
Material 2: Silt
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SAND,SILT. GREY,VERY DENSE. 0000003200055100001031000000 2I **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218544430
Top Depth: 1.7
Bottom Depth: 3.1
Material Color: Red
Material 1: Shale
Material 2: Silt
Material 3: Clay
Material 4: Gravel
Gsc Material Description:
Stratum Description: SHALE,SILT,CLAY, GRAVEL. RED,HARD, WATER STABLE AT 741.6 FEET.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR3.txt RecordID: 253730 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

306	1 of 17	SE/148.0	216.9 / -25.08	300 Main Street North Brampton ON L6V 4H6	EHS

Order No: 20090210016
Status: C
Report Type: Custom Report
Report Date: 2/20/2009
Date Received: 2/10/2009
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.768518
Y: 43.692432

306	2 of 17	SE/148.0	216.9 / -25.08	Queen West Medical Associates	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				300 Main Street North, Suite 100 Brampton ON L6V 4H6	

Generator Info

Generator No:	ON8443705	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Offices of Physicians		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
306	3 of 17	SE/148.0	216.9 / -25.08	Brampton East Medical Group 300 Main St. N,2and Floor Brampton ON L6V 4H6	GEN

Generator Info

Generator No:	ON6780717	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Offices of Physicians		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
306	4 of 17	SE/148.0	216.9 / -25.08	Brampton East Medical Group 300 Main St. N,2and Floor Brampton ON L6V 4H6	GEN

Generator Info

Generator No:	ON6780717	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621110
Country:			
Co Admin:			

Phone No Admin:
SIC Description: Offices of Physicians

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

306 **5 of 17** **SE/148.0** **216.9 / -25.08** **Queen West Medical Associates** **GEN**
300 Main Street North, Suite 100
Brampton ON L6V 4H6

Generator Info

Generator No: ON8443705
Approval Years: 2011
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Offices of Physicians
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621110

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

306 **6 of 17** **SE/148.0** **216.9 / -25.08** **Brampton East Medical Group** **GEN**
300 Main St. N,2and Floor
Brampton ON L6V 4H6

Generator Info

Generator No: ON6780717
Approval Years: 2012
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: Offices of Physicians
Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 621110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

306 **7 of 17** **SE/148.0** **216.9 / -25.08** **Queen West Medical Associates** **GEN**
300 Main Street North, Suite 100
Brampton ON L6V 4H6

Generator Info

Generator No:	ON8443705	***Choice of Contact:***	
Approval Years:	2012	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Offices of Physicians		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

---

306 ***8 of 17*** ***SE/148.0*** ***216.9 / -25.08*** ***Brampton East Medical Group*** ***GEN***
300 Main St. N,2and Floor
Brampton ON

Generator Info

Generator No:	ON6780717	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	OFFICES OF PHYSICIANS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

306 ***9 of 17*** ***SE/148.0*** ***216.9 / -25.08*** ***Queen West Medical Associates*** ***GEN***
300 Main Street North, Suite 100
Brampton ON

Generator Info

Generator No:	ON8443705	***Choice of Contact:***	
Approval Years:	2013	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	621110
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	OFFICES OF PHYSICIANS		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

306 ***10 of 17*** ***SE/148.0*** ***216.9 / -25.08*** ***Central Brampton Family Health Team*** ***GEN***
300 Main St. N, #200
Brampton ON L6V 4H6

Generator Info

Generator No: ON6780717
Approval Years: 2016
Status:
PO Box No:
Country: Canada
Co Admin: Tracy Redden
Phone No Admin: 905-451-1710 Ext.
SIC Description: OFFICES OF PHYSICIANS

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

306 ***11 of 17*** ***SE/148.0*** ***216.9 / -25.08*** ***Central Brampton Family Health Team*** ***GEN***
300 Main St. N,2and Floor
Brampton ON L6V 4H6

Generator Info

Generator No: ON6780717
Approval Years: 2015
Status:
PO Box No:
Country: Canada
Co Admin: Tracy Redden
Phone No Admin: 905-451-1710 Ext.
SIC Description: OFFICES OF PHYSICIANS

Choice of Contact: CO_OFFICIAL
Contaminated Fac: No
MHSW Facility: No
SIC Code: 621110

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

306 ***12 of 17*** ***SE/148.0*** ***216.9 / -25.08*** ***Queen West Medical Associates*** ***GEN***
300 Main Street North, Suite 100
Brampton ON L6V4H6

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator Info

Generator No:	ON8443705	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621110
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	OFFICES OF PHYSICIANS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

306	***13 of 17***	***SE/148.0***	***216.9 / -25.08***	***Brampton East Medical Group*** ***300 Main St. N,2and Floor*** ***Brampton ON L6V 4H6***	***GEN***

Generator Info

Generator No:	ON6780717	***Choice of Contact:***	CO_OFFICIAL
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	621110
Country:	Canada		
Co Admin:	Tracy Redden		
Phone No Admin:	905-451-1710 Ext.		
SIC Description:	OFFICES OF PHYSICIANS		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

306	***14 of 17***	***SE/148.0***	***216.9 / -25.08***	***Dr Essam Michael Medicine Professional Corporation*** ***300 Main St N*** ***Brampton ON L6V 1P6***	***GEN***

Generator Info

Generator No:	ON6028285	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

306 ***15 of 17*** ***SE/148.0*** ***216.9 / -25.08*** ***Dr Essam Michael Medicine Professional Corporation*** ***GEN***
300 Main St N
Brampton ON L6V 1P6

Generator Info

Generator No: ON6028285
Approval Years: As of Jul 2020
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

---

306 ***16 of 17*** ***SE/148.0*** ***216.9 / -25.08*** ***Dr Essam Michael Medicine Professional Corporation*** ***GEN***
300 Main St N
Brampton ON L6V 1P6

Generator Info

Generator No: ON6028285
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

306 | ***17 of 17*** | ***SE/148.0*** | ***216.9 / -25.08*** | ***Astra Fertility Group***
Astra Fertility, 300 Main St N
Brampton ON | ***GEN***

Generator Info

Generator No: ON6028285
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Generator Info as of Dec 2024

Generator No: ON6028285
Generator Company Name: Astra Fertility Group
Street: Astra Fertility, 300 Main St N
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L6V1P6
Waste Class: 261 A,312 P

Waste Class Decoded:

261 - PHARMACEUTICALS; 312 - PATHOLOGICAL WASTES

2017 Generator Info

Gen No: ON6028285
ID: 23740
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 621410
NAICS Code2:
NAICS Code3:
Gen Name: Dr Essam Michael Medicine Professional Corporation
Gen Div:
Gen Op Name: Astra Fertility Clinic
Gen Op Div:

Choice of Contact: CO_OFFICIAL
Phone No Official: 905 272 3776 Ext.428
Phone No Admin:
County Ont: PEEL (R. M.)
County Out:
District: 305

Site Adrs1:	300 Main St N
Site Bldg:	Astra Fertility
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 1P6
Site Country:	Canada
Co Official:	Rosanne RG Gibson
Co Admin:	

2017 Generator Manifest

ID:	48928	**Sum Received Qty:**	469.9
Generator No:	ON6028285	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	2
Waste Char:	P	**District:**	305
Waste Code:	312		

2018 Generator Info

Gen No:	ON6028285	**Choice of Contact:**	CO_OFFICIAL
ID:	23996	**Phone No Official:**	905 272 3776 Ext.428
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621410	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	Dr Essam Michael Medicine Professional Corporation
Gen Div:	
Gen Op Name:	Astra Fertility Clinic
Gen Op Div:	
Site Adrs1:	300 Main St N
Site Bldg:	Astra Fertility
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 1P6
Site Country:	Canada
Co Official:	Claudia Barone
Co Admin:	

2018 Generator Manifest

ID:	48787	**Sum Received Qty:**	243.0
Generator No:	ON6028285	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	6
Waste Char:	P	**District:**	305
Waste Code:	312		

2019 Generator Info

Gen No:	ON6028285	**Choice of Contact:**	CO_OFFICIAL
ID:	24159	**Phone No Official:**	905 272 3776 Ext.428
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621410	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	Dr Essam Michael Medicine Professional Corporation
Gen Div:	
Gen Op Name:	Astra Fertility Clinic
Gen Op Div:	
Site Adrs1:	300 Main St N
Site Bldg:	Astra Fertility
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 1P6
Site Country:	Canada
Co Official:	Claudia Barone
Co Admin:	

2019 Generator Manifest

ID:	48609	**Sum Received Qty:**	307.0
Generator No:	ON6028285	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	7
Waste Char:	P	**District:**	305
Waste Code:	312		

2020 Generator Info

Gen No:	ON6028285	**Choice of Contact:**	CO_OFFICIAL
ID:	23869	**Phone No Official:**	905 272 3776 Ext.429
Contaminated Fac:	N	**Phone No Admin:**	
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621410	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			

Gen Name:	Dr Essam Michael Medicine Professional Corporation
Gen Div:	
Gen Op Name:	Astra Fertility Clinic
Gen Op Div:	
Site Adrs1:	300 Main St N
Site Bldg:	Astra Fertility
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 1P6
Site Country:	Canada
Co Official:	Karen Michael
Co Admin:	

2020 Generator Manifest

ID:	45163	**Sum Received Qty:**	210.5
Generator No:	ON6028285	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	6
Waste Char:	P	**District:**	305
Waste Code:	312		

2021 Generator Info

Gen No:	ON6028285	**Choice of Contact:**	CO_OFFICIAL
ID:	24232	**Phone No Official:**	905 272 3776 Ext.429
Contaminated Fac:	N	**Phone No Admin:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	621410	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Dr Essam Michael Medicine Professional Corporation		
Gen Div:			
Gen Op Name:	Astra Fertility Clinic		
Gen Op Div:			
Site Adrs1:	300 Main St N		
Site Bldg:	Astra Fertility		
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 1P6		
Site Country:	Canada		
Co Official:	Karen Michael		
Co Admin:			

2021 Generator Manifest

ID:	46939	**Sum Received Qty:**	299.1
Generator No:	ON6028285	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	6
Waste Char:	P	**District:**	305
Waste Code:	312		

---

307 | ***1 of 1*** | ***ESE/169.2*** | ***221.5 / -20.40*** | ***178 Beech St. Brampton ON*** | ***SPL***

Ref No:	4670-BC623E	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	5/13/2019	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	5/13/2019	**Impact to Health:**	0 - No Impact
Dt Document Closed:		**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Possible pesticide use - oily sheen<UNOFFICIAL>		
Site Address:	178 Beech St.		
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:			
Incident Preceding Spill:			
Incident Reason:			
Incident Summary:	MOETips: possible pesticides running off property - Beech St.		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			

Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class: Pollution Incident Reports (PIRs) and "Other" calls
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

---

308 ***1 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***ZELLERS LIMITED 146*** ***PES***
227 VODDEN STREET CENTENNIAL MALL
BRAMPTON ON

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

308 ***2 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***227 Vodden St E*** ***EHS***
Brampton ON L6V 1N2

Order No: 20031210001
Status: C
Report Type: Complete Report
Report Date: 12/15/03
Date Received: 12/10/03
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.756931
Y: 43.702789

---

308 ***3 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***ZELLERS LIMITED 146*** ***PES***
227 VODDEN STREET CENTENNIAL MALL
BRAMPTON ON L6V 1N2

Detail Licence No: 23-01-07253-0
Licence No: 07253
Status:

Operator Box:
Operator Class:
Operator No:

Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	1
Lot:		**Operator County:**	49
Concession:		**Op Municipality:**	
Region:	3	**Post Office Box:**	
District:	1	**MOE District:**	
County:	49	**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

308 | ***4 of 39*** | ***ESE/186.1*** | ***228.9 / -13.08*** | ***PHARMA PLUS DRUGS LTD***
227 VODDEN STREET
BRAMPTON ON L6V 1N2 | ***GEN***

Generator Info

Generator No:	ON1553392	**Choice of Contact:**	
Approval Years:	92,93,97	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6031
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHARMACIES		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

---

308 | ***5 of 39*** | ***ESE/186.1*** | ***228.9 / -13.08*** | ***PHARMA PLUS DRUGS LTD. 31-751***
227 VODDEN ST., BRAMPTON C/O 5935
AIRPORT ROAD #500
MISSISSAUGA ON L4V 1W5 | ***GEN***

Generator Info

Generator No:	ON1553392	**Choice of Contact:**	
Approval Years:	94,95,96	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6031
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHARMACIES		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

308 ***6 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***PHARMA PLUS DRUGMARTS LTD.***
227 VODDEN STREET EAST
BRAMPTON ON L6V 1N2 ***GEN***

Generator Info

Generator No: ON1553392
Approval Years: 98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: PHARMACIES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6031

Waste Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

308 ***7 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.***
FOOD BASICS #983 227 VODDEN STREET
BRAMPTON ON L6V 1N2 ***GEN***

Generator Info

Generator No: ON2392168
Approval Years: 98,99,00,01
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: CAMERA/PHOTO. SUPPLY

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 6571

Waste Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	8 of 39	ESE/186.1	228.9 / -13.08	PHARMA PLUS DRUGS LTD. 227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	GEN

Generator Info

Generator No:	ON1553392	***Choice of Contact:***	
Approval Years:	99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	6031
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PHARMACIES		

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	9 of 39	ESE/186.1	228.9 / -13.08	ZELLERS STORE #146- CENTENNIAL MALL 227 VODDEN ST BRAMPTON ON L6V1N2	PES

Detail Licence No:		***Operator Box:***	
Licence No:		***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:		***Oper Area Code:***	
Licence Type:	Limited Vendor	***Oper Phone No:***	
Licence Type Code:	23	***Operator Ext:***	
Licence Class:		***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	
Concession:		***Op Municipality:***	
Region:		***Post Office Box:***	
District:		***MOE District:***	
County:		***SWP Area Name:***	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	10 of 39	ESE/186.1	228.9 / -13.08	ZELLERS LIMITED 146 227 VODDEN ST; CENTENNIAL MALL BRAMPTON ON L6V1N2	PES

Detail Licence No:		***Operator Box:***	
Licence No:		***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	Vendor
Report Source:		***Oper Area Code:***	
Licence Type:		***Oper Phone No:***	
Licence Type Code:		***Operator Ext:***	
Licence Class:		***Operator Lot:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

308 | 11 of 39 | ESE/186.1 | 228.9 / -13.08 | METRO ONTARIO INC O/A METRO/FOOD BASICS # 904
227 VODDEN STREET
BRAMPTON ON L6V1N2 | PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

308 | 12 of 39 | ESE/186.1 | 228.9 / -13.08 | ZELLERS INC
227 VODDEN STREET N
BRAMPTON ON L6V1N2 | PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

308 | 13 of 39 | ESE/186.1 | 228.9 / -13.08 | Exquizeet Tattoo & Piercing Studio
227 Vodden Street, Unit 30B | GEN

Brampton ON L6V 1N2

Generator Info

Generator No:	ON6206863	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	446199, 812190
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Health and Personal Care Stores, Other Personal Care Services		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

308 ***14 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***1723525 Ontario Inc.*** ***GEN***
227 Vodden Street East Unit 30B
Brampton ON

Generator Info

Generator No:	ON6483305	***Choice of Contact:***	
Approval Years:	2010	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	812190
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	Other Personal Care Services		

---

308 ***15 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***Exquizeet Tattoo & Piercing Studio*** ***GEN***
227 Vodden Street, Unit 30B
Brampton ON L6V 1N2

Generator Info

Generator No:	ON6206863	***Choice of Contact:***	
Approval Years:	2011	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	446199, 812190
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Health and Personal Care Stores, Other Personal Care Services		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

308 ***16 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***ZELLERS INC*** ***PES***
227 VODDEN STREET N

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON L6V 1N2	

Detail Licence No:	23-01-15448-0	Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	LIMITED	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	17 of 39	ESE/186.1	228.9 / -13.08	METRO ONTARIO INC O/A METRO/FOOD BASICS # 904 227 Vodden Street Brampton ON L6V 1N2	PES

Detail Licence No:	23-01-15181-0	Operator Box:	
Licence No:		Operator Class:	
Status:		Operator No:	
Approval Date:		Operator Type:	
Report Source:		Oper Area Code:	
Licence Type:	LIMITED	Oper Phone No:	
Licence Type Code:		Operator Ext:	
Licence Class:		Operator Lot:	
Licence Control:		Oper Concession:	
Latitude:		Operator Region:	
Longitude:		Operator District:	
Lot:		Operator County:	
Concession:		Op Municipality:	
Region:		Post Office Box:	
District:		MOE District:	
County:		SWP Area Name:	
Trade Name:			
PDF URL:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	18 of 39	ESE/186.1	228.9 / -13.08	Exquizeet Tattoo & Piercing Studio 227 Vodden Street, Unit 30B Brampton ON L6V 1N2	GEN

Generator Info

Generator No:	ON6206863	Choice of Contact:	
Approval Years:	2012	Contaminated Fac:	
Status:		MHSW Facility:	
PO Box No:		SIC Code:	446199, 812190
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	All Other Health and Personal Care Stores, Other Personal Care Services		

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

308 **19 of 39** **ESE/186.1** **228.9 / -13.08** **ZELLERS**
227 VODDEN Street
BRAMPTON ON L6V1N2
NPRI

NPRI ID: 8800000616
Other ID:
No Other ID:
Track ID:
Report ID:
Report Type:
Rpt Type ID:
Report Year: 2004
Not-Current Rpt?:
Yr of Last Filed Rpt:
Fac ID:
Fac Name: ZELLERS STORE, #146 CENTENNIAL MALL
Fac Address1:
Fac Address2:
Fac Postal Zip:
Facility Lat:
Facility Long:
DLS (Last Filed Rpt):
Facility DLS:
Datum:
Facility Cmnts:
URL:
No of Empl.: 20
Parent Co.:
No Parent Co.:
Pollut Prev Cmnts:
Stacks:
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 53
NAICS 2 Description: Real Estate and Rental and Leasing
NAICS Code (4 digit): 5311
NAICS 4 Description: Lessors of Real Estate
NAICS Code (6 digit): 531120
NAICS 6 Description: Lessors of Non-Residential Buildings (except Mini-Warehouses)

Org ID:
Submit Date:
Last Modified:
Contact ID:
Cont Type: MED
Contact Title: Mr.
Cont First Name: FRED
Cont Last Name: WARE
Contact Position: SENIOR MANAGER ENERGY ENVIRONMENT SOURCING INITIATIVES
Contact Fax:
Contact Ph.:
Cont Area Code: 416
Contact Tel.: 8614938
Contact Ext.:
Cont Fax Area Cde: 416
Contact Fax: 8616619
Contact Email: fred.ware@hbc.com
Latitude:
Longitude:
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams:
No Streams:
Waste Off Sites:
No Off Sites:
Shutdown:
No of Shutdown:

Substance Release Report

CAS No: NA - M08
Report ID:
Rpt Period: 2004
Subst Released: PM - Total Particulate Matter
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 74-82-8
Report ID:

Rpt Period: 2004
Subst Released: Methane
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 11104-93-1
Report ID:
Rpt Period: 2004
Subst Released: Nitrogen oxides (expressed as NO2)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 124-38-9
Report ID:
Rpt Period: 2004
Subst Released: Carbon dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 630-08-0
Report ID:
Rpt Period: 2004
Subst Released: Carbon monoxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M10
Report ID:
Rpt Period: 2004
Subst Released: PM2.5 - Particulate Matter <= 2.5 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 10024-97-2
Report ID:
Rpt Period: 2004
Subst Released: Nitrous oxide
Air:
Water:
Land:
Total Releases:

Units: tonnes

CAS No: 7446-09-5
Report ID:
Rpt Period: 2004
Subst Released: Sulphur dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M09
Report ID:
Rpt Period: 2004
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004
Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:
Total Releases:
Units: tonnes

---

308 | **20 of 39** | **ESE/186.1** | **228.9 / -13.08** | **227 Vodden St E Brampton On**
Brampton ON L6V1N1 | **EHS**

Order No: 20140117012
Status: C
Report Type: Custom Report
Report Date: 23-JAN-14
Date Received: 17-JAN-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.756803
Y: 43.70304

---

308 | **21 of 39** | **ESE/186.1** | **228.9 / -13.08** | **Exquizeet Tattoo & Piercing Studio**
227 Vodden Street, Unit 30B
Brampton ON | **GEN**

Generator Info

Generator No: ON6206863
Approval Years: 2013
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: ALL OTHER HEALTH AND PERSONAL CARE STORES

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 446199, 812190

Waste Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

308 **22 of 39** **ESE/186.1** **228.9 / -13.08** **227 VODDEN STREET EAST, BRAMPTON ON** **INC**

Incident No:	1775464	**Any Health Impact:**	No
Incident ID:		**Any Enviro Impact:**	No
Instance No:		**Service Intrp:**	Yes
Status Code:		**Was Prop Damaged:**	No
Incident Status:		**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:	5983563	**Indus App. Type:**	
Attribute Category:	FS-Perform L1 Incident Insp	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	
Date of Occurrence:	2015/12/18 00:00:00	**Operation Pressure:**	
Time of Occurrence:	00:00:00	**Equipment Type:**	
Occr Insp Start Dt:	2015/12/22 00:00:00	**Equipment Model:**	
Incident Creat On:		**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Vapour Release	**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Natural Gas	**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:	NULL	**Tank Storage Type:**	
Prc Escalation Req:	NULL	**Tank Location Type:**	

Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 227 VODDEN STREET EAST, BRAMPTON - VAPOUR RELEASE
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: inducer motor installed wrong voltage
Operation Type Involved: Commercial (e.g. restaurant, business unit, etc)

---

308 **23 of 39** **ESE/186.1** **228.9 / -13.08** **227 Vodden St E Brampton ON L6V1N1** **EHS**

Order No:	20151223072	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	04-JAN-16	**Search Radius (km):**	.25
Date Received:	23-DEC-15	**X:**	-79.756867
Previous Site Name:		**Y:**	43.702459
Lot/Building Size:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Additional Info Ordered:					
308	24 of 39	ESE/186.1	228.9 / -13.08	**Rexall Pharmacy Group Ltd.** **227 Vodden Street East** **Brampton ON L6V 1N2**	GEN

Generator Info

Generator No:	ON9569543	**Choice of Contact:**	CO_ADMIN
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	446110
Country:	Canada		
Co Admin:	Erik Botines		
Phone No Admin:	905-502-5965 Ext.		
SIC Description:	446110		

Waste Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

308	25 of 39	ESE/186.1	228.9 / -13.08	**Exquizeet Tattoo & Piercing Studio** **227 Vodden Street, Unit 30B** **Brampton ON L6V 1N2**	GEN

Generator Info

Generator No:	ON6206863	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2016	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	446199, 812190
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	ALL OTHER HEALTH AND PERSONAL CARE STORES, 812190		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

308	26 of 39	ESE/186.1	228.9 / -13.08	**Exquizeet Tattoo & Piercing Studio** **227 Vodden Street, Unit 30B** **Brampton ON L6V 1N2**	GEN

Generator Info

Generator No:	ON6206863	**Choice of Contact:**	CO_OFFICIAL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	446199, 812190
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	ALL OTHER HEALTH AND PERSONAL CARE STORES, 812190		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

308 ***27 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***Pharma Plus Drugmarts Ltd*** ***GEN***
227 Vodden Street East
Brampton ON L6V 1N2

Generator Info

Generator No:	ON9569543	**Choice of Contact:**	CO_ADMIN
Approval Years:	2015	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	446110
Country:	Canada		
Co Admin:	Erik Botines		
Phone No Admin:	905-502-5965 Ext.		
SIC Description:	446110		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

308 ***28 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***Exquizeet Tattoo & Piercing Studio*** ***GEN***
227 Vodden Street, Unit 30B
Brampton ON L6V 1N2

Generator Info

Generator No:	ON6206863	**Choice of Contact:**	CO_OFFICIAL
Approval Years:	2014	**Contaminated Fac:**	No
Status:		**MHSW Facility:**	No
PO Box No:		**SIC Code:**	446199, 812190
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:	ALL OTHER HEALTH AND PERSONAL CARE STORES, 812190		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

308 ***29 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***Pharma Plus Drugmarts Ltd*** ***GEN***
227 Vodden Street East
Brampton ON L6V 1N2

Generator Info

Generator No:	ON9569543	***Choice of Contact:***	CO_ADMIN
Approval Years:	2014	***Contaminated Fac:***	No
Status:		***MHSW Facility:***	No
PO Box No:		***SIC Code:***	446110
Country:	Canada		
Co Admin:	Aaron Schrama		
Phone No Admin:	905-502-5965 Ext.		
SIC Description:	446110		

Waste Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

308 ***30 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***Rexall Pharmacy Group Ltd.*** ***GEN***
227 Vodden Street East
Brampton ON L6V 1N2

Generator Info

Generator No:	ON9569543	***Choice of Contact:***	
Approval Years:	As of Dec 2018	***Contaminated Fac:***	
Status:	Registered	***MHSW Facility:***	
PO Box No:		***SIC Code:***	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	Pharmaceuticals

---

308 ***31 of 39*** ***ESE/186.1*** ***228.9 / -13.08*** ***METRO ONTARIO INC O/A METRO/FOOD BASICS # 904*** ***PES***
227 VODDEN STREET
BRAMPTON ON L6V1N2

Detail Licence No:		***Operator Box:***	
Licence No:	15181	***Operator Class:***	
Status:		***Operator No:***	
Approval Date:		***Operator Type:***	
Report Source:	Legacy Licenses (Excluding TS)	***Oper Area Code:***	905
Licence Type:	Limited Vendor	***Oper Phone No:***	
Licence Type Code:	23	***Operator Ext:***	
Licence Class:	01	***Operator Lot:***	
Licence Control:		***Oper Concession:***	
Latitude:		***Operator Region:***	
Longitude:		***Operator District:***	
Lot:		***Operator County:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

308 | **32 of 39** | **ESE/186.1** | **228.9 / -13.08**

ZELLERS LIMITED 146
227 VODDEN ST; CENTENNIAL MALL
BRAMPTON ON L6V1N2

PES

Detail Licence No:
Licence No: 07253
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 905
Oper Phone No: 4575150
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

308 | **33 of 39** | **ESE/186.1** | **228.9 / -13.08**

ZELLERS INC
227 VODDEN STREET N
BRAMPTON ON L6V1N2

PES

Detail Licence No:
Licence No: 15448
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 905
Oper Phone No: 4575150
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

308 | **34 of 39** | **ESE/186.1** | **228.9 / -13.08**

ZELLERS STORE #146- CENTENNIAL MALL
227 VODDEN ST
BRAMPTON ON L6V1N2

PES

Detail Licence No:
Licence No: 12584
Status:

Operator Box:
Operator Class:
Operator No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	4575150
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

308 | ***35 of 39*** | ***ESE/186.1*** | ***228.9 / -13.08*** | ***ZELLERS LIMITED 146***
227 VODDEN ST; CENTENNIAL MALL
BRAMPTON ON L6V1N2 | ***PES***

Detail Licence No:	23-01-07253-0	**Operator Box:**	
Licence No:	07253	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	905
Licence Type:	Limited Vendor	**Oper Phone No:**	4575150
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	3
Longitude:		**Operator District:**	1
Lot:		**Operator County:**	49
Concession:		**Op Municipality:**	
Region:	3	**Post Office Box:**	
District:	1	**MOE District:**	
County:	49	**SWP Area Name:**	
Trade Name:			
PDF URL:			

---

308 | ***36 of 39*** | ***ESE/186.1*** | ***228.9 / -13.08*** | ***Rexall Pharmacy Group Ltd.***
227 Vodden Street East
Brampton ON L6V 1N2 | ***GEN***

Generator Info

Generator No:	ON9569543	**Choice of Contact:**	
Approval Years:	As of Jul 2020	**Contaminated Fac:**	
Status:	Registered	**MHSW Facility:**	
PO Box No:		**SIC Code:**	
Country:	Canada		
Co Admin:			
Phone No Admin:			
SIC Description:			

Waste Detail(s)

Waste Class:	261 A
Waste Class Name:	Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	37 of 39	ESE/186.1	228.9 / -13.08	**Rexall Pharmacy Group Ltd.** **227 Vodden Street East** **Brampton ON L6V 1N2**	GEN

Generator Info

Generator No: ON9569543
Approval Years: As of Nov 2021
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	38 of 39	ESE/186.1	228.9 / -13.08	**Rexall Pharmacy Group Ltd** **227 Vodden Street East** **Brampton ON**	GEN

Generator Info

Generator No: ON9569543
Approval Years: As of Oct 2022
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Generator Info as of Dec 2024

Generator No: ON9569543
Generator Company Name: Rexall Pharmacy Group Ltd
Street: 227 Vodden Street East
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L6V1N2
Waste Class: 312 P,261 A

Waste Class Decoded:

312 - PATHOLOGICAL WASTES; 261 - PHARMACEUTICALS

2017 Generator Info

Gen No: ON9569543
ID: 37370
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 446110
NAICS Code2:
NAICS Code3:
Gen Name: Rexall Pharmacy Group Ltd.
Gen Div:
Gen Op Name: Pharma Plus Drugmarts Ltd
Gen Op Div: Pharma Plus #1438
Site Adrs1: 227 Vodden Street East
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L6V 1N2
Site Country: Canada
Co Official: Mona Sabharwal
Co Admin: Lisa O'Keefe

Choice of Contact: CO_ADMIN
Phone No Official: 9055017800 Ext.
Phone No Admin: 9055017800 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2018 Generator Info

Gen No: ON9569543
ID: 38103
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 446110
NAICS Code2:
NAICS Code3:
Gen Name: Rexall Pharmacy Group Ltd.
Gen Div:
Gen Op Name: Pharma Plus Drugmarts Ltd
Gen Op Div: Pharma Plus #1438
Site Adrs1: 227 Vodden Street East
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L6V 1N2
Site Country: Canada
Co Official: Mona Sabharwal
Co Admin: Lisa O'Keefe

Choice of Contact: CO_ADMIN
Phone No Official: 9055017800 Ext.
Phone No Admin: 9055017800 Ext.
County Ont: PEEL (R. M.)
County Out:
District: 305

2018 Generator Manifest

ID:	66671	***Sum Received Qty:***	3.8
Generator No:	ON9569543	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	1
Waste Char:	P	***District:***	305
Waste Code:	312		

2019 Generator Info

Gen No:	ON9569543	***Choice of Contact:***	CO_ADMIN
ID:	38665	***Phone No Official:***	9055017800 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9055017800 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	446110	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	Rexall Pharmacy Group Ltd.
Gen Div:	
Gen Op Name:	Pharma Plus Drugmarts Ltd
Gen Op Div:	Pharma Plus #1438
Site Adrs1:	227 Vodden Street East
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	
Site Postal Code:	L6V 1N2
Site Country:	Canada
Co Official:	Mona Sabharwal
Co Admin:	Christy Raposo

2019 Generator Manifest

ID:	66734	***Sum Received Qty:***	13.0
Generator No:	ON9569543	***Waste Class Name:***	PATHOLOGICAL WASTES
Receiver Type:	035	***Count Manifests:***	2
Waste Char:	P	***District:***	305
Waste Code:	312		

2020 Generator Info

Gen No:	ON9569543	***Choice of Contact:***	CO_ADMIN
ID:	38420	***Phone No Official:***	9055017800 Ext.
Contaminated Fac:	N	***Phone No Admin:***	9055017800 Ext.
MHSW Facility:	N	***County Ont:***	PEEL (R. M.)
NAICS Code1:	446110	***County Out:***	
NAICS Code2:		***District:***	305
NAICS Code3:			

Gen Name:	Rexall Pharmacy Group Ltd.
Gen Div:	
Gen Op Name:	Pharma Plus Drugmarts Ltd
Gen Op Div:	Pharma Plus #1438
Site Adrs1:	227 Vodden Street East
Site Bldg:	
Site Pobox:	
Province In:	ONTARIO
Site Adrs2:	
Site City:	Brampton
Province Out:	

Site Postal Code:	L6V 1N2
Site Country:	Canada
Co Official:	Mona Sabharwal
Co Admin:	Christy Raposo

2020 Generator Manifest

ID:	62739	**Sum Received Qty:**	11.0
Generator No:	ON9569543	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	1
Waste Char:	P	**District:**	305
Waste Code:	312		

2021 Generator Info

Gen No:	ON9569543	**Choice of Contact:**	CO_ADMIN
ID:	39457	**Phone No Official:**	9055017800 Ext.
Contaminated Fac:	N	**Phone No Admin:**	9055017800 Ext.
MHSW Facility:	N	**County Ont:**	PEEL (R. M.)
NAICS Code1:	446110	**County Out:**	
NAICS Code2:		**District:**	305
NAICS Code3:			
Gen Name:	Rexall Pharmacy Group Ltd.		
Gen Div:			
Gen Op Name:	Pharma Plus Drugmarts Ltd		
Gen Op Div:	Pharma Plus #1438		
Site Adrs1:	227 Vodden Street East		
Site Bldg:			
Site Pobox:			
Province In:	ONTARIO		
Site Adrs2:			
Site City:	Brampton		
Province Out:			
Site Postal Code:	L6V 1N2		
Site Country:	Canada		
Co Official:	Mona Sabharwal		
Co Admin:	Christy Raposo		

2021 Generator Manifest

ID:	65673	**Sum Received Qty:**	84.82
Generator No:	ON9569543	**Waste Class Name:**	PATHOLOGICAL WASTES
Receiver Type:	035	**Count Manifests:**	6
Waste Char:	P	**District:**	305
Waste Code:	312		

---

308 | ***39 of 39*** | ***ESE/186.1*** | ***228.9 / -13.08*** | ***227 Vodden Street East, Brampton ON L6V 4J4*** | ***EHS***

Order No:	21052500072	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	28-MAY-21	**Search Radius (km):**	.25
Date Received:	25-MAY-21	**X:**	-79.7570735
Previous Site Name:		**Y:**	43.7034249
Lot/Building Size:			
Additional Info Ordered:			

---

309 | ***1 of 1*** | ***SE/184.3*** | ***219.9 / -22.08*** | ***The Blind Service Co., 13 Harmsworth Ave, Brampton ON L6X 2N2*** | ***SCT***

Established: 1989
Plant Size (ft²): 12000
Employment: 5

--Details--
Description: Blind and Shade Manufacturing
SIC/NAICS Code: 337920

---

310 **1 of 1** **ESE/108.3** **227.9 / -14.08** **99 Kennedy Road North Brampton ON L6V 1X7** **EHS**

Order No: 24060501599
Status: C
Report Type: Custom Report
Report Date: 10-JUN-24
Date Received: 05-JUN-24
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .15
X: -79.75851903
Y: 43.70135225

---

311 **1 of 1** **WNW/141.7** **259.9 / 17.99** **OLD SCHOOL RD BRAMPTON ON** **WWIS**

Well ID: 7300300
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z239553
Tag: A234528
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 12/04/2017
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7360
Form Version: 7
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/730\7300300.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/15/2017
Year Completed: 2017
Depth (m): 12.192
Latitude: 43.7499240686415
Longitude: -79.8532652507846
X: -79.85326510051489
Y: 43.74992406712613
Path: 730\7300300.pdf

Bore Hole Information

Bore Hole ID:	1006842501	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592324.00
Code OB Desc:		**North83:**	4844737.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/15/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007026764
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	5.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1007026765
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	5.0
Formation End Depth:	40.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1007026774
Layer:	1
Plug From:	30.0
Plug To:	0.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID: 1007026773
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1007026763
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007026768
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 32.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 1007026769
Layer: 2
Material: 5
Open Hole or Material: PLASTIC
Depth From: 32.0
Depth To: 40.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007026771
Layer: 1
Slot: .10
Screen Top Depth: 32.0
Screen End Depth: 40.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 1007026767
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1007026766

Diameter:	6.0
Depth From:	0.0
Depth To:	40.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

312 **1 of 1** **ESE/177.3** **213.9 / -28.06** **61 Mara Cres, Brampton BRAMPTON ON** **SPL**

Ref No:	1-3GPYR9	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	5/16/2023 3:24:52 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	5/16/2023 6:36:52 PM	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	

Site No:	
MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	
Site Address:	61 Mara Cres, Brampton
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	Pipeline/Components
Incident Cause:	
Incident Preceding Spill:	Line Strike
Incident Reason:	Human error (Specify)
Incident Summary:	TSSA FSB half inch IP Safe
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see notes
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	NATURAL GAS
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Activity Preceding Spill:	Normal operations
Property 2nd Watershed:	02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed:	02HC | Humber River - Don River
Sector Type:	NATURAL GAS DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001881701"],"wkts":["POINT (-79.7655934000 43.6939077000)"],"creation_date":"2023-05-16"}
Time Reported:	
System Facility Address:	

313 **1 of 1** **SE/134.8** **218.9 / -23.08** **124 Mill Street North, Brampton ON** **PINC**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Id: 2646710
Incident No: 490406
Incident Reported Dt:
Type: FS-Pipeline Incident
Status Code: Pipeline Damage Reason Est
Tank Status: RC Established
Task No: 3148575
Spills Action Centre:
Fuel Type: Natural Gas
Fuel Occurrence Tp: Pipeline Strike
Date of Occurrence: 8/31/2010 0:00
Occurrence Start Dt: 2010/11/29
Depth:
Customer Acct Name:
Incident Address:
Pipe Material: Plastic
Fuel Category: Natural Gas
Health Impact: No
Environment Impact: No
Property Damage: Yes
Service Interrupt: Yes
Enforce Policy: Yes
Public Relation: No
Pipeline System:
PSIG: 45
Attribute Category: FS-Perform P-line Inc Invest
Regulator Location: Outside
Method Details: E-mail
Operation Type: Construction Site (including excavation)
Pipeline Type: Service / Riser Distribution Pipeline
Regulator Type: Service Regulator (up to 60 psi intake)
Summary: 124 Mill Street North, Brampton - 1/2" Pipeline Hit
Reported By: Jorgensen, Eric - Enbridge
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
Occurrence Desc:
Damage Reason: Excavation practices not sufficient
Notes:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
314	1 of 2	SE/119.5	219.9 / -22.08	Enbridge Gas Distribution Inc. 67 Nancy McCredie Drive Brampton ON	SPL

Ref No: 7878-APDR48
Year:
Incident Dt: 7/18/2017
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/18/2017
Dt Document Closed: 7/22/2017
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: residential <UNOFFICIAL>
Site Address: 67 Nancy McCredie Drive
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Enbridge Gas Distribution Inc.
Client Type: Corporation
Source Type: Pipeline/Components
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Operator/Human Error
Incident Summary: TSSA FSB: 0.5 inch IP dmge, made safe
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 n/a
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Contaminant Qty 1:	0
Contaminant Unit:	n/a
Contaminant Code:	35
Contaminant Name:	NATURAL GAS (METHANE)
Contaminant Limit 1:	
Contam Limit Freq 1:	n/a
Contaminant UN No 1:	1075
Receiving Medium:	Air
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

---

314 | ***2 of 2*** | ***SE/119.5*** | ***219.9 / -22.08*** | ***CEDAR HILLS CONTRACTING***
67 NANCY MCCREDIE DR,,BRAMPTON,ON,L6X 2N4,CA
ON | ***PINC***

Incident Id:		**Pipe Material:**	
Incident No:	2120838	**Fuel Category:**	
Incident Reported Dt:	7/19/2017	**Health Impact:**	
Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:		**Property Damage:**	
Tank Status:	Pipeline Damage Reason Est	**Service Interrupt:**	
Task No:		**Enforce Policy:**	
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	
Depth:		**Method Details:**	
Customer Acct Name:	CEDAR HILLS CONTRACTING		
Incident Address:	67 NANCY MCCREDIE DR,,BRAMPTON,ON,L6X 2N4,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

---

315 | ***1 of 1*** | ***SE/240.1*** | ***219.9 / -22.08*** | ***ON*** | ***BORE***

Borehole ID:	648576	**Inclin FLG:**	No
OGF ID:	215548957	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAY-1968	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.687843
Total Depth m:	3.7	**Longitude DD:**	-79.774411
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	598775

Drill Method:	Power auger	**Northing:**	4837933
Orig Ground Elev m:	220	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	221		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218523600	**Mat Consistency:**	Hard
Top Depth:	.6	**Material Moisture:**	
Bottom Depth:	3.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT,CLAY.BROWN,GLACIAL,HARD, AGE GLACIAL. 0000001800020100D, AGE GLACIAL **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218523599	**Mat Consistency:**	Compact
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND,GRAVEL. COMPACT.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 166030 NTS_Sheet: 30M12F		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

316	*1 of 1*	*SE/155.3*	*218.9 / -23.08*	***APC Products Ltd.*** ***38 Lorne Ave*** ***Brampton ON L6X 1L1***	***SCT***

Established:	01-JAN-97
Plant Size (ft²):	
Employment:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: Narrow Fabric Mills and Schiffli Machine Embroidery
SIC/NAICS Code: 313220

---

317 ***1 of 1*** ***ESE/113.9*** ***227.9 / -14.08*** ***ON*** ***BORE***

Borehole ID:	654710	***Inclin FLG:***	No
OGF ID:	215555055	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	NOV-1970	***Municipality:***	
Static Water Level:	0.6	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.702113
Total Depth m:	-999	***Longitude DD:***	-79.757676
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	600100
Drill Method:	Power auger	***Northing:***	4839538
Orig Ground Elev m:	226	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	227		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218544437	***Mat Consistency:***	Dense
Top Depth:	2.9	***Material Moisture:***	
Bottom Depth:	4	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Gravel	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SAND,GRAVEL. FLUVIO-GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 740.1 FEET.		

Geology Stratum ID:	218544436	***Mat Consistency:***	Dense
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.9	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. WEATHERED,DENSE,AGE GLACIAL.		

Geology Stratum ID:	218544438	***Mat Consistency:***	Hard
Top Depth:	4	***Material Moisture:***	
Bottom Depth:	6.3	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:	Till	***Depositional Gen:***	glacial

Gsc Material Description:
Stratum Description: SILT,CLAY,GRAVEL, TILL. RED,FLUVIO-GLACIAL,HARD, AGE GLACIAL.

Geology Stratum ID: 218544439
Top Depth: 6.3
Bottom Depth:
Material Color:
Material 1: Shale
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SHALE. 00000080000950300013010O **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR3.txt RecordID: 253750 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

318 ***1 of 1*** ***ESE/122.0*** ***228.1 / -13.82*** ***ON*** ***BORE***

Borehole ID: 654707
OGF ID: 215555052
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: NOV-1970
Static Water Level: 0.5
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 4.8
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 226
Elev Reliabil Note:
DEM Ground Elev m: 227
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.702381
Longitude DD: -79.757484
UTM Zone: 17
Easting: 600115
Northing: 4839568
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218544427

Mat Consistency: Dense

Top Depth:	2.1	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Silt	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,CLAY,SILT.BROWN,GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 740.4 FEET.		

Geology Stratum ID:	218544428	**Mat Consistency:**	
Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:	4.8	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	SHALE,CLAY,SILT. RED,MARINE,AGE ORDOVICIAN. 000000200007010000001 000100 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218544426	**Mat Consistency:**	Compact
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.1	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	TILL,SILT,GRAVEL, SAND. WEATHERED,COMPACT.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 253720 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

319 ***1 of 1*** ***ESE/151.8*** ***228.9 / -13.08 ON*** ***BORE***

Borehole ID:	654702	**Inclin FLG:**	No
OGF ID:	215555047	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1970	**Municipality:**	
Static Water Level:	0.5	**Lot:**	

Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.702828
Total Depth m:	4.7	**Longitude DD:**	-79.757165
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	600140
Drill Method:	Power auger	**Northing:**	4839618
Orig Ground Elev m:	226	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	227		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218544410	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SILT,SAND, GRAVEL. GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218544411	**Mat Consistency:**	Dense
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. GLACIAL,VERY DENSE, AGE GLACIAL, WATER STABLE AT 742.6 FEET.000010 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 253670 NTS_Sheet: 30M12C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

320	1 of 1	WNW/218.8	261.9 / 19.92	lot 22 con 1 ON	WWIS

Well ID:	4904066	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	05/10/1973
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	3637
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	022
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4904066.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/13/1972
Year Completed:	1972
Depth (m):	16.4592
Latitude:	43.7429383842492
Longitude:	-79.860595570655
X:	-79.86059542069796
Y:	43.74293838250953
Path:	490\4904066.pdf

Bore Hole Information

Bore Hole ID:	10318855	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	591744.50
Code OB Desc:		**North83:**	4843953.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/13/1972	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	p4
Location Method Desc:	Original Pre1985 UTM Rel Code 4: margin of error : 30 m - 100 m		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932044132
Layer:	4
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	

Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 15.0
Formation End Depth: 16.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932044137
Layer: 9
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 43.0
Formation End Depth: 46.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932044135
Layer: 7
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3:
Material 3 Desc:
Formation Top Depth: 23.0
Formation End Depth: 33.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932044134
Layer: 6
Color: 7
General Color: RED
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 20.0
Formation End Depth: 23.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932044136

Layer:	8
Color:	7
General Color:	RED
Material 1:	28
Material 1 Desc:	SAND
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	12
Material 3 Desc:	STONES
Formation Top Depth:	33.0
Formation End Depth:	43.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932044138
Layer:	10
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	46.0
Formation End Depth:	54.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932044133
Layer:	5
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	16.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932044129
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932044130
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	1.0
Formation End Depth:	6.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932044131
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	6.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964904066
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10867425
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930526551
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	54.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	BAILER
Pump Test ID:	994904066
Pump Set At:	
Static Level:	26.0
Final Level After Pumping:	54.0
Recommended Pump Depth:	52.0
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	5.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	2
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Draw Down & Recovery

Pump Test Detail ID:	934257974
Test Type:	Recovery
Test Duration:	15
Test Level:	52.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	935042799
Test Type:	Recovery
Test Duration:	60
Test Level:	46.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934532086
Test Type:	Recovery
Test Duration:	30
Test Level:	50.0
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934786641
Test Type:	Recovery
Test Duration:	45
Test Level:	48.0
Test Level UOM:	ft

Water Details

Water ID:	933792100
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	48.0
Water Found Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
321	1 of 2	SE/155.2	219.9 / -22.08	Enbridge Energy Distribution Inc. 32 Nancy McCreedie Drive Brampton ON	SPL

Ref No: 3677-BANJ7S
Year:
Incident Dt: 3/27/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/27/2019
Dt Document Closed: 5/8/2019
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: spill<UNOFFICIAL>
Site Address: 32 Nancy McCreedie Drive
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Enbridge Energy Distribution Inc.
Client Type: Corporation
Source Type: Pipeline/Components
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Intentional Discharge
Incident Summary: tssa 1/2" pl IP made safe Brampton
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 1 number (count)
Contaminant Qty 1: 1
Contaminant Unit: number (count)
Contaminant Code: 35
Contaminant Name: METHANE GAS, COMPRESSED (NATURAL GAS)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1971
Receiving Medium: Air
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Communal
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
321	2 of 2	SE/155.2	219.9 / -22.08	ENBRIDGE GAS INC 32 NANCY MCCREDIE DR,,BRAMPTON,ON,L6X 2N5,CA ON	PINC

Incident Id:
Incident No: 2542668
Incident Reported Dt: 3/27/2019
Pipe Material:
Fuel Category:
Health Impact:

Type:	FS-Pipeline Incident	***Environment Impact:***	
Status Code:		***Property Damage:***	
Tank Status:	Pipeline Damage Reason Est	***Service Interrupt:***	
Task No:		***Enforce Policy:***	
Spills Action Centre:		***Public Relation:***	
Fuel Type:		***Pipeline System:***	
Fuel Occurrence Tp:		***PSIG:***	
Date of Occurrence:		***Attribute Category:***	
Occurrence Start Dt:		***Regulator Location:***	
Depth:		***Method Details:***	
Customer Acct Name:	ENBRIDGE GAS INC		
Incident Address:	32 NANCY MCCREDIE DR,,BRAMPTON,ON,L6X 2N5,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

322 | ***1 of 1*** | ***SE/205.3*** | ***219.9 / -22.08*** | ***PHOTOGRAPHIC IMAGERY 21 HARMSWORTH AVENUE BRAMPTON ON L6X 2N2*** | ***GEN***

Generator Info

Generator No:	ON1776600	***Choice of Contact:***	
Approval Years:	93,94,95,96,97,98,99,00,01	***Contaminated Fac:***	
Status:		***MHSW Facility:***	
PO Box No:		***SIC Code:***	2821
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	PLATEMAKING, ETC.		

Waste Detail(s)

Waste Class:	264
Waste Class Name:	PHOTOPROCESSING WASTES

323 | ***1 of 1*** | ***NW/193.9*** | ***264.9 / 22.93*** | ***Old School Road & Hurontario Street lot 22 con 1 Caledon ON*** | ***WWIS***

Well ID:	7380784	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	02/22/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	B75NGVQJ	***Contractor:***	7472
Tag:	A308474	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	022
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS E
Overburden/Bedrock:		***Easting NAD83:***	

Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/738\7380784.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/25/2021
Year Completed:	2021
Depth (m):	6.096
Latitude:	43.7533493021999
Longitude:	-79.8491628860063
X:	-79.84916273546061
Y:	43.75334930057056
Path:	738\7380784.pdf

Bore Hole Information

Bore Hole ID:	1008574057	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592649.00
Code OB Desc:		**North83:**	4845122.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/25/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008574149
Layer:	2
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	15.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008574148
Layer:	1
Color:	2
General Color:	GREY

Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	0.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008574212
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008574236
Layer:	1
Plug From:	0.0
Plug To:	14.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008574237
Layer:	2
Plug From:	14.0
Plug To:	20.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1008574114
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1008574093
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008574167
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	15.0
Casing Diameter:	2.0

Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008574182
Layer:	1
Slot:	10
Screen Top Depth:	15.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008574094
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1008574197
Diameter:	7.5
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

324	1 of 1	SE/168.1	218.9 / -23.08	**COLOUR CRAFT LABS** **116 MILL STREET NORTH** **BRAMPTON ON L6X 2P2**	GEN

Generator Info

Generator No:	ON1950300	**Choice of Contact:**	
Approval Years:	94,95,96,97,98	**Contaminated Fac:**	
Status:		**MHSW Facility:**	
PO Box No:		**SIC Code:**	6571
Country:			
Co Admin:			
Phone No Admin:			
SIC Description:	CAMERA/PHOTO. SUPPLY		

Waste Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

325 | **1 of 1** | **ESE/181.8** | **227.9 / -14.08** | **95 Kennedy Road North**
Brampton ON L6V 1X7 | **EHS**

Order No: 20320100008
Status: C
Report Type: Standard Report
Report Date: 04-DEC-20
Date Received: 01-DEC-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.7575294
Y: 43.701193

---

326 | **1 of 1** | **ESE/199.0** | **228.4 / -13.55** | **225 Vodden St E**
Brampton ON L6V 4M1 | **EHS**

Order No: 23010400181
Status: C
Report Type: Custom Report
Report Date: 09-JAN-23
Date Received: 04-JAN-23
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.7565213
Y: 43.7025061

---

327 | **1 of 1** | **SE/232.2** | **216.9 / -25.08** | **Services and Housing in the Province**
Brampton ON L6X 1N4 | **EHS**

Order No: 24011000233
Status: C
Report Type: Custom Report
Report Date: 15-JAN-24
Date Received: 10-JAN-24
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: AB
Search Radius (km): .3
X: -79.7676756
Y: 43.6912714

---

328 | **1 of 1** | **ESE/248.7** | **225.1 / -16.81** | **The Regional Municipality of Peel**
135 Sailsbury Circle
Brampton ON | **SPL**

Ref No: 3460-AFCCWN
Year:
Incident Dt: 2016/11/03
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/11/03
Dt Document Closed: 2016/11/07
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse: Etobicoke Creek
Site Name: water main <UNOFFICIAL>
Site Address: 135 Sailsbury Circle
Site Region:
Site Municipality: Brampton

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4839009
Easting:	599899
Entity Operating Name:	
Client Name:	The Regional Municipality of Peel
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Incident Reason:	Equipment Failure
Incident Summary:	watermain break, silt to Etobicoke Creek
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
Contaminant Qty 1:	0
Contaminant Unit:	other - see incident description
Contaminant Code:	43
Contaminant Name:	SEDIMENT(SUSPENDED SOLIDS/ SAND/ SILT)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Source Water Zone
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
329	1 of 1	SE/245.0	219.9 / -22.08	PIPELINE HIT 1/2" 33 HARMSWORTH AVE,,BRAMPTON,ON,L6X 2N2,CA ON	PINC

Incident Id:		**Pipe Material:**	
Incident No:	1108574	**Fuel Category:**	
Incident Reported Dt:	5/29/2013	**Health Impact:**	
Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:		**Property Damage:**	
Tank Status:	Pipeline Damage Reason Est	**Service Interrupt:**	
Task No:		**Enforce Policy:**	
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	
Depth:		**Method Details:**	
Customer Acct Name:	PIPELINE HIT 1/2"		
Incident Address:	33 HARMSWORTH AVE,,BRAMPTON,ON,L6X 2N2,CA		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:			
Reported By:			
Affiliation:			
Occurrence Desc:			
Damage Reason:			
Notes:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

330 *1 of 1* *SE/229.0* *218.2 / -23.75* **PRIVATE RESIDENCE** **SPL**
INFRONT OF 110 MILL ST. (N.O.S.)
BRAMPTON CITY ON

Ref No:	112900	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	5/8/1995	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	5/8/1995	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	WORKS, PEEL R.M.
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER CAUSE (N.O.S.)		
Incident Preceding Spill:			
Incident Reason:	INTENTIONAL/PLANNED		
Incident Summary:	CHEPSCOW INVESTMENT-SANI-TARY WASTEWATER TO STORM CATCH BASIN, INTENTIONAL.		
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
Contaminant Qty 1:			
Contaminant Unit:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	WATER		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

331 *1 of 1* *ESE/212.0* *227.9 / -14.08* **BORE**
ON

Borehole ID:	638960	**Inclin FLG:**	No
OGF ID:	215539357	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No

Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	SEP-1969	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.702324
Total Depth m:	1.2	***Longitude DD:***	-79.756369
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	600205
Drill Method:	Power auger	***Northing:***	4839563
Orig Ground Elev m:	221	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	227		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218486512	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	Moist
Bottom Depth:	.5	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Clay	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT(42), SAND(27),CLAY. GREY,BROWN,GLACIAL,MOIST, LENSES,AGE GLACIAL.		

Geology Stratum ID:	218486513	***Mat Consistency:***	
Top Depth:	.5	***Material Moisture:***	
Bottom Depth:	1.2	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT. BROWN,GLACIAL,AGE GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 069230 NTS_Sheet: 30M12G		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
332	1 of 1	NW/41.6	264.0 / 22.06	lot 22 con 1 ON	WWIS

Well ID:	4907265	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:		**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	03/06/1990
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	65773	**Contractor:**	3132
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	022
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4907265.pdf

Additional Detail(s) (Map)

Well Completed Date:	12/15/1989
Year Completed:	1989
Depth (m):	41.148
Latitude:	43.7512847560473
Longitude:	-79.8533758983817
X:	-79.85337574764758
Y:	43.75128475421819
Path:	490\4907265.pdf

Bore Hole Information

Bore Hole ID:	10321825	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592313.00
Code OB Desc:		**North83:**	4844888.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	2
Date Completed:	12/15/1989	**UTMRC Desc:**	margin of error : 3 - 10 m
Remarks:		**Location Method:**	gps
Location Method Desc:	from gps		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932057560
Layer:	3
Color:	2
General Color:	GREY

Material 1: 05
Material 1 Desc: CLAY
Material 2: 12
Material 2 Desc: STONES
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 45.0
Formation End Depth: 73.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932057558
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 08
Material 2 Desc: FINE SAND
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.0
Formation End Depth: 22.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932057562
Layer: 5
Color: 3
General Color: BLUE
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 10
Material 2 Desc: COARSE SAND
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 123.0
Formation End Depth: 135.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932057561
Layer: 4
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2: 66
Material 2 Desc: DENSE
Material 3:
Material 3 Desc:
Formation Top Depth: 73.0
Formation End Depth: 123.0
Formation End Depth UOM: ft

Overburden and Bedrock

Materials Interval

Formation ID:	932057559
Layer:	2
Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	12
Material 2 Desc:	STONES
Material 3:	66
Material 3 Desc:	DENSE
Formation Top Depth:	22.0
Formation End Depth:	45.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933170225
Layer:	1
Plug From:	0.0
Plug To:	16.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964907265
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10870395
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930530992
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	130.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930530993
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	135.0
Casing Diameter:	6.0
Casing Diameter UOM:	inch

Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 994907265
Pump Set At:
Static Level: 27.0
Final Level After Pumping: 45.0
Recommended Pump Depth: 60.0
Pumping Rate: 12.0
Flowing Rate:
Recommended Pump Rate: 10.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 12
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 935050646
Test Type: Draw Down
Test Duration: 60
Test Level: 45.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934256528
Test Type: Draw Down
Test Duration: 15
Test Level: 35.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934785140
Test Type: Draw Down
Test Duration: 45
Test Level: 45.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934531062
Test Type: Draw Down
Test Duration: 30
Test Level: 45.0
Test Level UOM: ft

Water Details

Water ID: 933795336
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 130.0

Water Found Depth UOM: ft

---

333 | **1 of 1** | **NW/44.5** | **265.9 / 23.98** | **2939 OLD SCHOOL RD. lot 22 con 1 BRAMPTON ON** | **WWIS**

Well ID:	7199058	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Water Supply	**Date Received:**	03/21/2013
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z158021	**Contractor:**	3349
Tag:	A121893	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	022
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7199058.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/04/2012
Year Completed: 2012
Depth (m): 42.67
Latitude: 43.7523887984054
Longitude: -79.8521375396308
X: -79.8521373897807
Y: 43.7523887965158
Path: 719\7199058.pdf

Bore Hole Information

Bore Hole ID:	1004266281	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592411.00
Code OB Desc:		**North83:**	4845012.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	09/04/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004923873

Layer:	3
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	4.880000114440918
Formation End Depth:	6.400000095367432
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004923871
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.9100000262260437
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004923874
Layer:	4
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	11
Material 3 Desc:	GRAVEL
Formation Top Depth:	6.400000095367432
Formation End Depth:	28.040000915527344
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004923877
Layer:	7
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	17
Material 2 Desc:	SHALE
Material 3:	
Material 3 Desc:	
Formation Top Depth:	35.04999923706055
Formation End Depth:	42.66999816894531
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004923875
Layer:	5
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	28.040000915527344
Formation End Depth:	30.18000030517578
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004923876
Layer:	6
Color:	7
General Color:	RED
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	11
Material 3 Desc:	GRAVEL
Formation Top Depth:	30.18000030517578
Formation End Depth:	35.04999923706055
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004923872
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.9100000262260437
Formation End Depth:	4.880000114440918
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004923910
Layer:	1
Plug From:	0.0
Plug To:	6.199999809265137
Plug Depth UOM:	m

Method of Construction & Well

Use

Method Construction ID:	1004923909
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	1004923869
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004923880
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	0.6100000143051147
Depth To:	35.04999923706055
Casing Diameter:	15.875
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004923881
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1004923870
Pump Set At:	41.0
Static Level:	6.449999809265137
Final Level After Pumping:	14.84000015258789
Recommended Pump Depth:	35.0
Pumping Rate:	15.140000343322754
Flowing Rate:	
Recommended Pump Rate:	15.140000343322754
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	0
Pumping Duration HR:	6
Pumping Duration MIN:	
Flowing:	No

Draw Down & Recovery

Pump Test Detail ID:	1004923890
Test Type:	Draw Down

Test Duration: 5
Test Level: 8.460000038146973
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923892
Test Type: Draw Down
Test Duration: 10
Test Level: 9.880000114440918
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923903
Test Type: Recovery
Test Duration: 40
Test Level: 7.21999979019165
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923885
Test Type: Recovery
Test Duration: 2
Test Level: 14.180000305175781
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923897
Test Type: Recovery
Test Duration: 20
Test Level: 9.09000015258789
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923889
Test Type: Recovery
Test Duration: 4
Test Level: 13.270000457763672
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923891
Test Type: Recovery
Test Duration: 5
Test Level: 11.949999809265137
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923895
Test Type: Recovery
Test Duration: 15
Test Level: 9.789999961853027
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923896
Test Type: Draw Down
Test Duration: 20
Test Level: 11.829999923706055
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923905
Test Type: Recovery
Test Duration: 50
Test Level: 7.0
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923882
Test Type: Draw Down
Test Duration: 1
Test Level: 7.130000114440918
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923893
Test Type: Recovery
Test Duration: 10
Test Level: 10.579999923706055
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923894
Test Type: Draw Down
Test Duration: 15
Test Level: 11.0600004196167
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923900
Test Type: Draw Down
Test Duration: 30
Test Level: 13.100000381469727
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923904
Test Type: Draw Down
Test Duration: 50
Test Level: 14.359999656677246
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923883

Test Type: Recovery
Test Duration: 1
Test Level: 14.520000457763672
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923884
Test Type: Draw Down
Test Duration: 2
Test Level: 7.5
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923899
Test Type: Recovery
Test Duration: 25
Test Level: 8.5600004196167
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923901
Test Type: Recovery
Test Duration: 30
Test Level: 7.690000057220459
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923902
Test Type: Draw Down
Test Duration: 40
Test Level: 13.789999961853027
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923886
Test Type: Draw Down
Test Duration: 3
Test Level: 7.820000171661377
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923887
Test Type: Recovery
Test Duration: 3
Test Level: 13.869999885559082
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID: 1004923888
Test Type: Draw Down
Test Duration: 4
Test Level: 8.170000076293945
Test Level UOM: m

Draw Down & Recovery

Pump Test Detail ID:	1004923898
Test Type:	Draw Down
Test Duration:	25
Test Level:	12.430000305175781
Test Level UOM:	m

Draw Down & Recovery

Pump Test Detail ID:	1004923906
Test Type:	Draw Down
Test Duration:	60
Test Level:	14.84000015258789
Test Level UOM:	m

Draw Down & Recovery

Pump Test Detail ID:	1004923907
Test Type:	Recovery
Test Duration:	60
Test Level:	6.800000190734863
Test Level UOM:	m

Water Details

Water ID:	1004923879
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	40.0
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004923878
Diameter:	15.875
Depth From:	0.0
Depth To:	42.66999816894531
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

335 ***1 of 1*** ***NW/32.8*** ***266.2 / 24.24*** ***2939 OLD SCHOOL RD. lot 22 con 1 BRAMPTON ON*** ***WWIS***

Well ID:	7199059	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Abandoned-Other	***Date Received:***	03/21/2013
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z158022	***Contractor:***	3349
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	022
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	

Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/719\7199059.pdf

Additional Detail(s) (Map)

Well Completed Date: 09/08/2012
Year Completed: 2012
Depth (m):
Latitude: 43.7525865949365
Longitude: -79.8521089161844
X: -79.85210876585383
Y: 43.75258659304862
Path: 719\7199059.pdf

Bore Hole Information

Bore Hole ID: 1004266284
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/08/2012
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 592413.00
North83: 4845034.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004924080
Layer: 2
Plug From: 15.0
Plug To: 3.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004924079
Layer: 1
Plug From: 19.809999465942383
Plug To: 15.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004924081
Layer: 3
Plug From: 3.0

Plug To: 0.0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004924078
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1004924070
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004924076
Layer: 2
Material: 3
Open Hole or Material: CONCRETE
Depth From: 1.8300000429153442
Depth To: 0.0
Casing Diameter: 91.44000244140625
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Casing

Casing ID: 1004924075
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From: 19.809999465942383
Depth To: 1.8300000429153442
Casing Diameter: 15.880000114440918
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004924077
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1004924071
Pump Set At:
Static Level:
Final Level After Pumping:

Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	LPM
Water State After Test Code:	0
Water State After Test:	
Pumping Test Method:	0
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

Water Details

Water ID:	1004924074
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004924073
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

336 | ***1 of 1*** | ***WNW/13.6*** | ***260.9 / 18.92*** | ***lot 22 con 1 ON*** | ***WWIS***

Well ID:	4901626	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	07/19/1956
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	3512
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	022
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901626.pdf

Additional Detail(s) (Map)

Well Completed Date:	06/23/1956
Year Completed:	1956
Depth (m):	15.5448

Latitude:	43.7470979012794
Longitude:	-79.8587654287503
X:	-79.85876527868686
Y:	43.74709789957327
Path:	490\4901626.pdf

Bore Hole Information

Bore Hole ID:	10316471	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	591885.50
Code OB Desc:		**North83:**	4844417.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	9
Date Completed:	06/23/1956	**UTMRC Desc:**	unknown UTM
Remarks:		**Location Method:**	p9
Location Method Desc:	Original Pre1985 UTM Rel Code 9: unknown UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932035036
Layer:	4
Color:	
General Color:	
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	42.0
Formation End Depth:	51.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035034
Layer:	2
Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	09
Material 2 Desc:	MEDIUM SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	20.0
Formation End Depth:	24.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035033
Layer:	1
Color:	5
General Color:	YELLOW
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035035
Layer:	3
Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	24.0
Formation End Depth:	42.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901626
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10865041
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523111
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	51.0
Casing Diameter:	5.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901626

Pump Set At:	
Static Level:	18.0
Final Level After Pumping:	42.0
Recommended Pump Depth:	
Pumping Rate:	10.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

Water Details

Water ID:	933789577
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	42.0
Water Found Depth UOM:	ft

---

337 | ***1 of 1*** | ***WNW/38.8*** | ***262.4 / 20.46*** | ***lot 22 con 1 ON*** | ***WWIS***

Well ID:	4901629	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	12/27/1963
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1309
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	022
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901629.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/10/1963
Year Completed:	1963
Depth (m):	17.0688
Latitude:	43.7493465758722
Longitude:	-79.8567354068399
X:	-79.85673525726877
Y:	43.74934657441313
Path:	490\4901629.pdf

Bore Hole Information

Bore Hole ID:	10316474	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592045.50
Code OB Desc:		***North83:***	4844669.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	09/10/1963	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	932035042
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035045
Layer:	4
Color:	2
General Color:	GREY
Material 1:	09
Material 1 Desc:	MEDIUM SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	29.0
Formation End Depth:	35.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035046
Layer:	5
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	

Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 35.0
Formation End Depth: 38.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035044
Layer: 3
Color: 6
General Color: BROWN
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 11.0
Formation End Depth: 29.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035043
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 2.0
Formation End Depth: 11.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932035047
Layer: 6
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 38.0
Formation End Depth: 56.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964901629

Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10865044
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523114
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	56.0
Casing Diameter:	7.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901629
Pump Set At:	
Static Level:	27.0
Final Level After Pumping:	50.0
Recommended Pump Depth:	48.0
Pumping Rate:	2.0
Flowing Rate:	
Recommended Pump Rate:	1.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	12
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933789580
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	52.0
Water Found Depth UOM:	ft

---

338 | ***1 of 4*** | ***NW/6.2*** | ***267.7 / 25.74*** | ***Makkar Transport<UNOFFICIAL>*** | ***SPL***

Hwy 10 @ Old School Road
Caledon ON

Ref No:	2806-9ZJSV3	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	8/19/2015	**Discharger Report:**	
Dt MOE Arvl on Scn:	8/20/2015	**Material Group:**	
MOE Reported Dt:	8/19/2015	**Impact to Health:**	
Dt Document Closed:	9/26/2015	**Agency Involved:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site No:	NA
MOE Response:	Yes
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	NE corner of Intersection<UNOFFICIAL>
Site Address:	Hwy 10 @ Old School Road
Site Region:	
Site Municipality:	Caledon
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	Makkar Transport<UNOFFICIAL>
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	
Incident Reason:	Operator/Human Error
Incident Summary:	Makkar Transport 300 L dsl to rd, gravel shoulder, contained
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	100 L
Contaminant Qty 1:	100
Contaminant Unit:	L
Contaminant Code:	13
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Unknown / N/A
SAC Action Class:	Primary Assessment of Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

338	*2 of 4*	*NW/6.2*	*267.7 / 25.74*	***ENBRIDGE GAS INC*** ***EAST OF VALLEYSCAPE TRAIL (WEST OF LOT#36),OLD SCHOOL RD & HWY 10,CALEDON, ON,L7C 2B7,CA*** ***ON***	***PINC***

Incident Id:		**Pipe Material:**	
Incident No:	2697198	**Fuel Category:**	
Incident Reported Dt:	10/8/2019	**Health Impact:**	
Type:	FS-Pipeline Incident	**Environment Impact:**	
Status Code:		**Property Damage:**	
Tank Status:	Pipeline Damage Reason Est	**Service Interrupt:**	
Task No:		**Enforce Policy:**	
Spills Action Centre:		**Public Relation:**	
Fuel Type:		**Pipeline System:**	
Fuel Occurrence Tp:		**PSIG:**	
Date of Occurrence:		**Attribute Category:**	
Occurrence Start Dt:		**Regulator Location:**	
Depth:		**Method Details:**	

Customer Acct Name: ENBRIDGE GAS INC
Incident Address: EAST OF VALLEYSCAPE TRAIL (WEST OF LOT#36),OLD SCHOOL RD & HWY 10,CALEDON,ON,L7C 2B7,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

338	3 of 4	NW/6.2	267.7 / 25.74	hwy 10 southbound and Old School Road intersection in Brampton CALEDON ON	SPL

Ref No: 1-14BD4I
Year:
Incident Dt: 8/26/2021 8:00:00 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/26/2021 8:21:14 AM
Dt Document Closed: 8/26/2021 2:22:46 PM
Site No:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: hwy 10 southbound and Old School Road intersection in Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: CALEDON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type: Truck - Only Saddle Tanks
Incident Cause:
Incident Preceding Spill: Accident/Collision
Incident Reason: Unknown
Incident Summary: Brampton: Diesel spill 400 L to 500 L
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 500 litre (L)
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill: Transportation
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HC-Humber - Don
Sector Type: GENERAL FREIGHT TRUCKING, LONG DISTANCE, TRUCK-LOAD
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00002456607"],"wkts":["POINT (-79.8514717356 43.7535885632)"],"creation_date":"2021-

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

08-26"}

Time Reported:
System Facility Address:

338	4 of 4	NW/6.2	267.7 / 25.74	Hwy 10 and Old School Road Caledon CALEDON ON	SPL

Ref No: 1-CFOBGJ
Year:
Incident Dt: Oct 23,2024 04:30:53 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: Oct 23,2024 06:15:53 PM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: Hwy 10 and Old School Road Caledon
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: CALEDON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type: Private Business
Source Type:
Incident Cause:
Incident Preceding Spill:
Incident Reason:
Incident Summary: BNK Transport: 30-40L Motor Oil to ditch, cntd & clng._Hwy 10 and Old School Road, Caledon
Environment Impact:
Health Env Consequence: Low
Nature of Impact:
Contaminant Qty: 0 other - see notes
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: NATURAL GAS
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HC-Humber - Don
Sector Type: GENERAL FREIGHT TRUCKING, LOCAL
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00002456607"],"wkts":["POINT (-79.8515610000 43.7535981000)"],"creation_date":"2024-10-23"}
Time Reported:
System Facility Address:

339	1 of 1	WNW/43.0	260.1 / 18.13	lot 23 con 1 ON	WWIS

Well ID:	4902901	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Livestock	**Data Entry Status:**	
Use 2nd:	Domestic	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	10/17/1968
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	4813
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	023
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4902901.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/11/1968
Year Completed: 1968
Depth (m): 16.764
Latitude: 43.750451775356
Longitude: -79.85560891568
X: -79.85560876567015
Y: 43.75045177312929
Path: 490\4902901.pdf

Bore Hole Information

Bore Hole ID:	10317742	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592134.50
Code OB Desc:		**North83:**	4844793.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	10/11/1968	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932039567
Layer: 5
Color:
General Color:
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:

Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 50.0
Formation End Depth: 55.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039565
Layer: 3
Color:
General Color:
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 40.0
Formation End Depth: 47.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039563
Layer: 1
Color:
General Color:
Material 1: 23
Material 1 Desc: PREVIOUSLY DUG
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 34.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039564
Layer: 2
Color:
General Color:
Material 1: 06
Material 1 Desc: SILT
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 34.0
Formation End Depth: 40.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039566

Layer:	4
Color:	3
General Color:	BLUE
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	47.0
Formation End Depth:	50.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964902901
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10866312
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930525019
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	55.0
Casing Diameter:	7.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994902901
Pump Set At:	
Static Level:	32.0
Final Level After Pumping:	37.0
Recommended Pump Depth:	50.0
Pumping Rate:	15.0
Flowing Rate:	
Recommended Pump Rate:	6.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	3
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933790924
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	55.0
Water Found Depth UOM:	ft

340 | **1 of 1** | **NW/12.1** | **267.6 / 25.64** | **lot 22 con 1 ON** | **WWIS**

Well ID:	4901627	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Public	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	09/09/1958
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1612
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	022
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901627.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/04/1958
Year Completed:	1958
Depth (m):	21.6408
Latitude:	43.7533774690149
Longitude:	-79.8519633728299
X:	-79.85196322258336
Y:	43.75337746702165
Path:	490\4901627.pdf

Bore Hole Information

Bore Hole ID:	10316472	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592423.50
Code OB Desc:		**North83:**	4845122.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	9
Date Completed:	09/04/1958	**UTMRC Desc:**	unknown UTM
Remarks:		**Location Method:**	p9
Location Method Desc:	Original Pre1985 UTM Rel Code 9: unknown UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932035037
Layer:	1
Color:	
General Color:	
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035038
Layer:	2
Color:	
General Color:	
Material 1:	07
Material 1 Desc:	QUICKSAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	2.0
Formation End Depth:	70.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035039
Layer:	3
Color:	
General Color:	
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	70.0
Formation End Depth:	71.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901627
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10865042

Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930523112
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 71.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 994901627
Pump Set At:
Static Level: 18.0
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Water Details

Water ID: 933789578
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 70.0
Water Found Depth UOM: ft

---

341 | **1 of 1** | **WNW/63.4** | **260.1 / 18.21** | **2676 OLD SCHOOL RD. lot 23 con 1 BRAMPTON ON** | **WWIS**

Well ID: 7145558
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z89935
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 05/28/2010
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 4011
Form Version: 7
Owner:
County: PEEL
Lot: 023
Concession: 01
Concession Name: HS W

Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7145558.pdf

Additional Detail(s) (Map)

Well Completed Date:	04/29/2010
Year Completed:	2010
Depth (m):	
Latitude:	43.7482191352623
Longitude:	-79.8583404621156
X:	-79.8583403118116
Y:	43.74821913336744
Path:	714\7145558.pdf

Bore Hole Information

Bore Hole ID:	1002986140	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	591918.00
Code OB Desc:		***North83:***	4844542.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	04/29/2010	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003031523
Layer:	4
Plug From:	5.900000095367432
Plug To:	0.949999988079071
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003031524
Layer:	5
Plug From:	0.949999988079071
Plug To:	0.8500000238418579
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003031520
Layer:	2

Plug From: 10.329999923706055
Plug To: 6.400000095367432
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003031525
Layer: 6
Plug From: 0.8500000238418579
Plug To: 0.0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003031522
Layer: 3
Plug From: 6.400000095367432
Plug To: 5.900000095367432
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003031518
Layer: 1
Plug From: 11.100000381469727
Plug To: 10.329999923706055
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1003031539
Method Construction Code:
Method Construction:
Other Method Construction: ABANDONMENT

Pipe Information

Pipe ID: 1003031509
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003031531
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1003031533
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Water Details

Water ID:	1003031530
Layer:	
Kind Code:	
Kind:	
Water Found Depth:	
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1003031517
Diameter:	60.0
Depth From:	11.100000381469727
Depth To:	7.599999904632568
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1003031516
Diameter:	75.0
Depth From:	7.599999904632568
Depth To:	0.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

342 **1 of 1** **WNW/66.7** **258.8 / 16.90** **lot 23 con 1 ON** **WWIS**

Well ID:	4901630	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	05/21/1959
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	1325
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	023
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901630.pdf

Additional Detail(s) (Map)

Well Completed Date:	04/15/1959
Year Completed:	1959
Depth (m):	12.192
Latitude:	43.7507227089583
Longitude:	-79.8556906986685
X:	-79.85569054914154
Y:	43.750722707430775
Path:	490\4901630.pdf

Bore Hole Information

Bore Hole ID:	10316475	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592127.50
Code OB Desc:		***North83:***	4844823.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	04/15/1959	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5

Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:	
Location Source Date:	
Improvement Location Source:	
Improvement Location Method:	
Source Revision Comment:	
Supplier Comment:	

Overburden and Bedrock Materials Interval

Formation ID:	932035048
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	6.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035049
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	07
Material 1 Desc:	QUICKSAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	6.0

Formation End Depth:	40.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901630
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10865045
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523115
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	40.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	994901630
Pump Set At:	
Static Level:	26.0
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	No

Water Details

Water ID:	933789581
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	40.0
Water Found Depth UOM:	ft

343	***1 of 1***	***WNW/81.5***	***261.1 / 19.19***	***lot 23 con 1 ON***	***WWIS***

Well ID:	4904378	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	07/15/1974
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	3637
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	023
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4904378.pdf

Additional Detail(s) (Map)

Well Completed Date:	01/16/1974
Year Completed:	1974
Depth (m):	13.716
Latitude:	43.7488811353263
Longitude:	-79.8579117918662
X:	-79.8579116421232
Y:	43.74888113336201
Path:	490\4904378.pdf

Bore Hole Information

Bore Hole ID:	10319163	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	591951.50
Code OB Desc:		**North83:**	4844616.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	4
Date Completed:	01/16/1974	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	p4

Location Method Desc: Original Pre1985 UTM Rel Code 4: margin of error : 30 m - 100 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	932045505
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL

Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 1.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932045506
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 1.0
Formation End Depth: 14.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932045507
Layer: 3
Color: 6
General Color: BROWN
Material 1: 08
Material 1 Desc: FINE SAND
Material 2: 05
Material 2 Desc: CLAY
Material 3:
Material 3 Desc:
Formation Top Depth: 14.0
Formation End Depth: 18.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932045509
Layer: 5
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2: 03
Material 2 Desc: MUCK
Material 3:
Material 3 Desc:
Formation Top Depth: 23.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	932045508
Layer:	4
Color:	6
General Color:	BROWN
Material 1:	09
Material 1 Desc:	MEDIUM SAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	18.0
Formation End Depth:	23.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932045510
Layer:	6
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	30.0
Formation End Depth:	40.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932045511
Layer:	7
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	12
Material 2 Desc:	STONES
Material 3:	
Material 3 Desc:	
Formation Top Depth:	40.0
Formation End Depth:	45.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964904378
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10867733
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930526969
Layer:	2
Material:	2
Open Hole or Material:	GALVANIZED
Depth From:	
Depth To:	31.0
Casing Diameter:	32.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930526968
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	25.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930526970
Layer:	3
Material:	2
Open Hole or Material:	GALVANIZED
Depth From:	
Depth To:	45.0
Casing Diameter:	21.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	BAILER
Pump Test ID:	994904378
Pump Set At:	
Static Level:	20.0
Final Level After Pumping:	29.0
Recommended Pump Depth:	40.0
Pumping Rate:	6.0
Flowing Rate:	
Recommended Pump Rate:	5.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	2
Pumping Duration HR:	1
Pumping Duration MIN:	1
Flowing:	No

Draw Down & Recovery

Pump Test Detail ID:	934787296
Test Type:	Draw Down
Test Duration:	45

Test Level: 26.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934258634
Test Type: Draw Down
Test Duration: 15
Test Level: 22.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935043468
Test Type: Draw Down
Test Duration: 60
Test Level: 29.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934533167
Test Type: Draw Down
Test Duration: 30
Test Level: 24.0
Test Level UOM: ft

Water Details

Water ID: 933792414
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 20.0
Water Found Depth UOM: ft

---

344 | **1 of 1** | **WNW/76.7** | **258.5 / 16.56** | **lot 23 con 1 ON** | **WWIS**

Well ID: 4901631
Construction Date:
Use 1st: Domestic
Use 2nd: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 08/02/1962
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1307
Form Version: 1
Owner:
County: PEEL
Lot: 023
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4901631.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/28/1962
Year Completed:	1962
Depth (m):	12.8016
Latitude:	43.7507420808851
Longitude:	-79.8558269589955
X:	-79.85582680915199
Y:	43.750742079121764
Path:	490\4901631.pdf

Bore Hole Information

Bore Hole ID:	10316476	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592116.50
Code OB Desc:		***North83:***	4844825.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	07/28/1962	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	p5
Location Method Desc:	Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932035052
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	09
Material 1 Desc:	MEDIUM SAND
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	32.0
Formation End Depth:	42.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035050
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	15.0

Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932035051
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	09
Material 1 Desc:	MEDIUM SAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	15.0
Formation End Depth:	32.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964901631
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10865046
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930523116
Layer:	1
Material:	3
Open Hole or Material:	CONCRETE
Depth From:	
Depth To:	42.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994901631
Pump Set At:	
Static Level:	32.0
Final Level After Pumping:	
Recommended Pump Depth:	40.0
Pumping Rate:	2.0
Flowing Rate:	
Recommended Pump Rate:	2.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1

Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Water Details

Water ID: 933789582
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 32.0
Water Found Depth UOM: ft

---

345 | **1 of 1** | **WNW/132.0** | **263.3 / 21.41** | **lot 23 con 1 ON** | **WWIS**

Well ID: 4902900
Construction Date:
Use 1st: Livestock
Use 2nd: Domestic
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 10/17/1968
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4813
Form Version: 1
Owner:
County: PEEL
Lot: 023
Concession: 01
Concession Name: HS W
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4902900.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/09/1968
Year Completed: 1968
Depth (m): 17.6784
Latitude: 43.7509555927145
Longitude: -79.8564687780012
X: -79.85646862824957
Y: 43.75095559100022
Path: 490\4902900.pdf

Bore Hole Information

Bore Hole ID: 10317741
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/09/1968
Remarks:
Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m

Elevation:
Elevrc:
Zone: 17
East83: 592064.50
North83: 4844848.00
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932039561
Layer: 5
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 40.0
Formation End Depth: 52.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039559
Layer: 3
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 28.0
Formation End Depth: 32.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039560
Layer: 4
Color:
General Color:
Material 1: 06
Material 1 Desc: SILT
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 32.0
Formation End Depth: 40.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039562

Layer: 6
Color:
General Color:
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 52.0
Formation End Depth: 58.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039557
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 14.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039558
Layer: 2
Color:
General Color:
Material 1: 07
Material 1 Desc: QUICKSAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 14.0
Formation End Depth: 28.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964902900
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10866311
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	930525018
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	58.0
Casing Diameter:	7.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994902900
Pump Set At:	
Static Level:	28.0
Final Level After Pumping:	40.0
Recommended Pump Depth:	53.0
Pumping Rate:	10.0
Flowing Rate:	
Recommended Pump Rate:	10.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	3
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933790923
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	58.0
Water Found Depth UOM:	ft

---

346 ***1 of 1*** ***WNW/123.7*** ***263.6 / 21.67*** ***lot 23 con 1 ON*** ***WWIS***

Well ID:	4906471	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	06/09/1986
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:		***Contractor:***	4919
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	023
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		

Site Info:

Additional Detail(s) (Map)

Bore Hole ID:	10321036	***Tag No:***	
Depth M:	21.336	***Contractor:***	4919
Year Completed:	1985	***Latitude:***	43.7520855560149
Well Completed Dt:	09/23/1985	***Longitude:***	-79.8551181986001
Audit No:		***Y:***	43.75208555400121
Path:		***X:***	-79.8551180492775

Bore Hole Information

Bore Hole ID:	10321036	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	592171.50
Code OB Desc:		***North83:***	4844975.00
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	5
Date Completed:	09/23/1985	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	topo
Location Method Desc:	from Topo. Map		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932053817
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	73
Material 2 Desc:	HARD
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	1.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932053819
Layer:	3
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	74
Material 3 Desc:	LAYERED
Formation Top Depth:	20.0
Formation End Depth:	70.0

Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932053818
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	73
Material 2 Desc:	HARD
Material 3:	
Material 3 Desc:	
Formation Top Depth:	1.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964906471
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	10869606
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930529728
Layer:	1
Material:	2
Open Hole or Material:	GALVANIZED
Depth From:	
Depth To:	70.0
Casing Diameter:	30.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	BAILER
Pump Test ID:	994906471
Pump Set At:	
Static Level:	20.0
Final Level After Pumping:	65.0
Recommended Pump Depth:	65.0
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	3.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	2

Pumping Duration HR:
Pumping Duration MIN: 30
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934528823
Test Type: Recovery
Test Duration: 30
Test Level: 63.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935048408
Test Type: Recovery
Test Duration: 60
Test Level: 61.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934782912
Test Type: Recovery
Test Duration: 45
Test Level: 62.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934254229
Test Type: Recovery
Test Duration: 15
Test Level: 64.0
Test Level UOM: ft

Water Details

Water ID: 933794447
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 20.0
Water Found Depth UOM: ft

---

347 | ***1 of 1*** | ***NW/244.0*** | ***270.9 / 28.93*** | ***n/a Old School Rd X Hurontario Street lot 23 con 1 Caledon ON*** | ***WWIS***

Well ID: 7406244
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: N2A2XJ4B
Tag: A238951
Constructn Method:
Elevation (m):
Elevatn Reliabilty:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 12/12/2021
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7282
Form Version: 9
Owner:
County: PEEL
Lot: 023

Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS E
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:	Job No. 57306, BH21-04		

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/740\7406244.pdf

Additional Detail(s) (Map)

Well Completed Date:	11/12/2021
Year Completed:	2021
Depth (m):	6.096
Latitude:	43.7555568103084
Longitude:	-79.85021369879
X:	-79.8502135491128
Y:	43.75555680799583
Path:	740\7406244.pdf

Bore Hole Information

Bore Hole ID:	1008889947	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592561.00
Code OB Desc:		**North83:**	4845366.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/12/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008890103
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	68
Material 3 Desc:	DRY
Formation Top Depth:	0.0
Formation End Depth:	17.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID: 1008890104

Layer:	2
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	84
Material 2 Desc:	SILTY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	17.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008890238
Layer:	1
Plug From:	0.0
Plug To:	8.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008890207
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008890239
Layer:	2
Plug From:	8.0
Plug To:	20.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1008890025
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1008889996
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1008890140
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC

Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008890167
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	20.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.299999952316284

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008889997
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008890069
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	17.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1008890187
Diameter:	8.25
Depth From:	0.0
Depth To:	20.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

348	***1 of 1***	***NW/209.9***	***270.9 / 28.93***	***n/a Old School Rd X Hurontario Street lot 23 con 1 Caledon ON***	***WWIS***

Well ID:	7406221	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	

Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	12/12/2021
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	UO33KVWW	**Contractor:**	7282
Tag:	A238952	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	023
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS E
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info: Job No. 57306, BH21-01

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/740\7406221.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/12/2021
Year Completed: 2021
Depth (m): 5.7912
Latitude: 43.7553352563748
Longitude: -79.8505657520738
X: -79.8505656014754
Y: 43.75533525448049
Path: 740\7406221.pdf

Bore Hole Information

Bore Hole ID:	1008889576	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592533.00
Code OB Desc:		**North83:**	4845341.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/12/2021	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008889712
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 68

Material 3 Desc:	DRY
Formation Top Depth:	0.0
Formation End Depth:	16.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1008889713
Layer:	2
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	84
Material 2 Desc:	SILTY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	16.0
Formation End Depth:	19.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008889841
Layer:	1
Plug From:	0.0
Plug To:	7.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008889781
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008889842
Layer:	2
Plug From:	7.0
Plug To:	19.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1008889660
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1008889628
Casing No:	0

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1008889733
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	9.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008889752
Layer:	1
Slot:	10
Screen Top Depth:	9.0
Screen End Depth:	19.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.299999952316284

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008889629
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008889686
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	16.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1008889772
Diameter:	8.25
Depth From:	0.0
Depth To:	19.0

Hole Depth UOM: ft
Hole Diameter UOM: inch

---

349 | **1 of 1** | **WNW/165.3** | **259.6 / 17.64** | **lot 23 con 1 ON** | **WWIS**

Well ID:	4902899	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Abandoned-Quality	**Date Received:**	10/17/1968
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	4813
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	023
Depth to Bedrock:		**Concession:**	01
Well Depth:		**Concession Name:**	HS W
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: CALEDON TOWN (CHINGUACOUSY)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4902899.pdf

Additional Detail(s) (Map)

Well Completed Date:	09/08/1968
Year Completed:	1968
Depth (m):	57.912
Latitude:	43.7514507085894
Longitude:	-79.8564593497741
X:	-79.85645919949084
Y:	43.75145070745462
Path:	490\4902899.pdf

Bore Hole Information

Bore Hole ID:	10317740	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	592064.50
Code OB Desc:		**North83:**	4844903.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	09/08/1968	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5

Location Method Desc: Original Pre1985 UTM Rel Code 5: margin of error : 100 m - 300 m
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932039548
Layer: 2
Color:
General Color:
Material 1: 07
Material 1 Desc: QUICKSAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 12.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039554
Layer: 8
Color:
General Color:
Material 1: 06
Material 1 Desc: SILT
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 143.0
Formation End Depth: 151.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039555
Layer: 9
Color: 7
General Color: RED
Material 1: 11
Material 1 Desc: GRAVEL
Material 2: 06
Material 2 Desc: SILT
Material 3:
Material 3 Desc:
Formation Top Depth: 151.0
Formation End Depth: 176.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039552
Layer: 6
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 80.0
Formation End Depth: 140.0

Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039556
Layer: 10
Color: 3
General Color: BLUE
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 176.0
Formation End Depth: 190.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039551
Layer: 5
Color:
General Color:
Material 1: 05
Material 1 Desc: CLAY
Material 2: 12
Material 2 Desc: STONES
Material 3:
Material 3 Desc:
Formation Top Depth: 70.0
Formation End Depth: 80.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039553
Layer: 7
Color: 7
General Color: RED
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 140.0
Formation End Depth: 143.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039547
Layer: 1
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY

Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 12.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039549
Layer: 3
Color: 3
General Color: BLUE
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 30.0
Formation End Depth: 53.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932039550
Layer: 4
Color:
General Color:
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 53.0
Formation End Depth: 70.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964902899
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10866310
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930525017
Layer: 1
Material:

Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	7.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994902899
Pump Set At:	
Static Level:	30.0
Final Level After Pumping:	120.0
Recommended Pump Depth:	
Pumping Rate:	9.0
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	1
Pumping Duration HR:	15
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933790922
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	176.0
Water Found Depth UOM:	ft

Unplottable Summary

Total: 236 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
AAGR		Lot 18 Con 1	Peel ON	
AAGR		Lot 20 Con 1	Peel ON	
AAGR		Lot 7 Con 2	Peel ON	
AAGR		Lot 21 Con 1	Caledon ON	
CA	The Regional Municipality of Peel	Mayfield Road	Brampton ON	
CA	Brampton West 6-2 Limited	Part of the West Half of Lot 16, Concession 1 W. H.S.	Brampton ON	
CA	Petro-Canada Inc.		Brampton ON	
CA	The Regional Municipality of Peel	Mayfield Road	Brampton ON	
CA	Mattamy (Credit River) Limited	Sandalwood Parkway	Brampton ON	
CA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	
CA	The Corporation of the City of Brampton	Kennedy Rd	Brampton ON	
CA	The Regional Municipality of Peel	Mayfield Road	Brampton ON	
CA	2066650 Ontario Inc.		Brampton ON	
CA	Sundial Homes (Sheridan) Limited	Part of West Half of Lot 15, Conc. 1WHS	Brampton ON	
CA		Lot 14, Concession 1 WHS	Brampton ON	
CA		Lot 14, Concession 1 WHS	Brampton ON	
CA		Lot 13, Conc. 1, WHS., Sandalwood Parkway	Brampton ON	

CA		Lot 13, Conc. 1, WHS., Sandalwood Parkway	Brampton ON
CA		Part of Lot 16, Concession 1, WHS	Brampton ON
CA		Part of Lot 16, Concession 1, WHS	Brampton ON
CA		Lot 17, Concession 1 WHS	Brampton ON
CA		Part of Lot 20, Concession 1	Caledon ON
CA		Lot 23, Concession 1	Caledon ON
CA		Mayfield Road	Caledon ON
CA	Caledon Village Well No. 3 and Well No. 4	Highway 10	Caledon ON
CA	Caledon Village Well No. 3 and Well No. 4	Highway 10	Caledon ON
CA	Caledon East Well Pumping Facility	Lot 23, Concession 1	Caledon ON
CA		Lot 14, Conc. 1 WHS., Westpoint Village Subd.	Brampton ON
CA		Lot 14, Conc. 1 WHS., Westpoint Village Subd.	Brampton ON
CA		Part of Lot 15, Concession 1 WHS	Brampton ON
CA		Part of Lot 15, Concession 1 WHS	Brampton ON
CA		Part of Lot 15, Concession 1 WHS	Brampton ON
CA	MCDONALD'S RESTAURANTS OF CANADA LTD.	HWY.7	BRAMTON CITY ON
CA	KINGKNOLL DEVELOPMENT LTD.	MCLAUGHLIN RD.	BRAMPTON CITY ON
CA	KINGKNOLL DEVELOPMENT LTD.	MCLAUGHLIN RD.	BRAMPTON CITY ON
CA	PEEL NON-PROFIT HOUSING CORP.	HURONTARIO ST. (PHASE 2)	BRAMPTON CITY ON
CA	REG. MUN. OF PEEL	HWY #7	BRAMPTON CITY ON
CA	THE CITY	LORNE AVE	BRAMPTON CITY ON
CA	PEEL NON-PROFIT HOUSING CORP.	HURONTARIO ST. (PHASE 2)	BRAMPTON CITY ON
CA	PEEL NON-PROFIT HOUSING CORP.	HURONTARIO ST. (PHASE 1)	BRAMPTON CITY ON

CA	PEEL NON-PROFIT HOUSING CORP.	HURONTARIO ST. (PHASE 1)	BRAMPTON CITY ON
CA	THE CITY	BEECH ST.	BRAMPTON CITY ON
CA	959823 ONTARIO LIMITED	KENDRA COURT/BRINKLEY DR.	BRAMPTON CITY ON
CA	PETRO-CANADA PRODUCTS	SANDALWOOD PKWY., S.W.M.	BRAMPTON CITY ON
CA	TEMPSON HOLDINGS LTD/GANA CONTRACTING IN	GANA TEMPSON SUBD/VAN SCOTT CR	BRAMPTON CITY ON
CA	NORTONVILLE ESTATES LTD.	VODDEN STREET	BRAMPTON CITY ON
CA	MIA PROPERTIES LIMITED	VAN KIRK DR. MIA IND. PARK	BRAMPTON CITY ON
CA	L.D.C.M. INVESTMENTS LTD.-BLOCKS 53 & 54	MURRAY STREET/BURTON ROAD	BRAMPTON CITY ON
CA	KINGSPOINT PLAZA LIMITED	MAIN STREET NORTH	BRAMPTON CITY ON
CA	717495 ONTARIO LTD. GLENROSE PARK SUBD.	WILLIAMS PARKWAY	BRAMPTON CITY ON
CA	TRICAN ESTATES LTD.	MILL ST/LOT 21, BLOCK 5	CALEDON TOWN ON
CA	STARBRAM DEVELOPMENTS INC.	HURONTARIO HWY. 10	BRAMPTON CITY ON
CA	R.M. OF PEEL	HIGHWAY NO. 10	BRAMPTON CITY ON
CA	ALAN FURBACHER BRAMPTON CITY	REGAN RD. PRIVATE PROPERTY	BRAMPTON CITY ON
CA	BRAMALEA LIMITED	A STREET HWY. 7	BRAMPTON CITY ON
CA	MATAGORDA MANAGEMENT INC.-LOT 23/CONC.IV	HURONTARIO STREET	CALEDON TOWN ON
CA	R.M. OF PEEL-ARCHIBALD ST.-FILE 90-1400	ARCHIBALD ST/MOORE ST/MURRAY S	BRAMPTON CITY ON
CA	L.D.C.M. INVESTMENTS BRAMPTON CITY	KEN WHILLANS DR.	BRAMPTON CITY ON
CA	662016 ONTARIO LTD.	HWY. #10	BRAMPTON CITY ON
CA	CITY SOUTH LIMITED	HURONTARIO STREET	BRAMPTON CITY ON
CA	MIA PROPERTIES LIMITED	MIA IND. SUBD. VAN KIRK DR.	BRAMPTON CITY ON
CA	LIOYD ALTEC	KENNEDY RD.	BRAMPTON CITY ON

CA	285240 ONTARIO LIMITED WILSON IND. SUBD.	VAN KIRK DR.	BRAMPTON CITY ON
CA	NORTHWEST PALM INVESTMENTS LTD.	VAN KIRK DRIVE	BRAMPTON CITY ON
CA	KANEFF PROPERTIES LIMITED	HURONTARIO ST.	BRAMPTON CITY ON
CA	CENTRAL PEEL HOLDINGS (1982) LIMITED	FISHERMAN DR.	BRAMPTON CITY ON
CA	BRAMPTON CITY	CENTRE STREET	BRAMPTON CITY ON
CA	R.M. OF PEEL	SANDALWOOD PARKWAY	BRAMPTON CITY ON
CA	SAM-SOR ENTERPRISES INC.	HIGHWAY 7 EASEMENT	BRAMPTON CITY ON
CA	PEEL NON-PROFIT HOUSING	MURRAY ST. PRIVATE DRIVEWAY	BRAMPTON CITY ON
CA	R.M. OF PEEL	E. HURONTARIO ST.	CALEDON TOWN ON
CA	WOLVERLEIGH CONSTRUCTION-LOTS 12 & 13	SANDALWOOD PARKWAY	BRAMPTON CITY ON
CA	L.D.C.M. INVESTMENTS LTD.-BLOCKS 53 & 54	MURRAY STREET/BURTON ROAD	BRAMPTON CITY ON
CA	R.M. OF PEEL-LOT 16, CONC. 2	KENNEDY RD.	BRAMPTON CITY ON
CA	TEMPSON HOLDINGS LTD/GANA CONTRACTING IN	GANA TEMPSON SUBD/VAN SCOTT CR	BRAMPTON CITY ON
CA	L.D.C.M. INVESTMENTS	KEN WHILLANS DR.	BRAMPTON CITY ON
CA	717495 ONTARIO LTD. GLENROSE PARK SUBD.	WILLIAMS PARKWAY	BRAMPTON CITY ON
CA	CITY SOUTH LIMITED	HURONTARIO ST.	BRAMPTON CITY ON
CA	285240 ONTARIO LTD. WILSON IND. SUBD.	VAN KIRK DR. N. OF SANDALWOOD	BRAMPTON CITY ON
CA	MIA PROPERTIES LIMITED	VAN KIRK DR. MIA IND. PARK	BRAMPTON CITY ON
CA	BRAMPTON CITY	HURONTARIO STREET	BRAMPTON CITY ON
CA	NORTHWEST PALM INVESTMENT LTD.	VAN KIRK DRIVE	BRAMPTON CITY ON
CA	KINGSPOINT PLAZA LIMITED	MAIN STREET NORTH	BRAMPTON CITY ON
CA	CENTRAL PEEL HOLDINGS (1982) LIMITED	FISHERMAN DR. BERSAMCAR SUBD.	BRAMPTON CITY ON

CA	R.M. OF PEEL	NORTH OF HIGHWAY #7	BRAMPTON CITY ON
CA	BRAMPTON CITY	CENTRE ST. WEST SIDE	BRAMPTON CITY ON
CA	SAM-SOR ENTERPRISES INC.	HWY. 7 EASEMENT	BRAMPTON CITY ON
CA	BRAMPTON CITY	KENNEDY RD. NORTH	BRAMPTON CITY ON
CA	BEACON HALL LTD.	STREET C MCLAUGHLIN RD.	BRAMPTON CITY ON
CA	BRAMPTON CITY	SANDALWOOD PARKWAY	BRAMPTON CITY ON
CA	PEEL NON-PROFIT HOUSING	MURRAY ST.PRIVATE DRIVEWAY	BRAMPTON CITY ON
CA	S.E.J.-S.H.L. HOLDINGS	WILLIAMS PKWY EAST	BRAMPTON CITY ON
CA	ORLANDO CORPORATION FLETCHER'S CREEK	E. OF MCLAUGHLIN RD.	BRAMPTON CITY ON
CA	ARMBRO MATERIALS & CONSTRUCTION LTD.	W. OF REGAN RD. ARMBRO IND.SUB	BRAMPTON CITY ON
CA	NORTONVILLE ESTATES LTD.	VODDEN STREET	BRAMPTON CITY ON
CA	BRAMALEA LIMITED	A STREET N. OF HWY. 7	BRAMPTON CITY ON
CA	WALLENSTEIN FEED AND SUPPLY LTD.	LOT 18, CONC. 1	PEEL TWP. ON
CA	REGIONAL MUNICIPALITY OF PEEL	E. HURONTARIO ST.	CALEDON TOWN ON
CA	COX CONSTRUCTION LTD. (MATHEWS)	LOT 18, CONC. 1	PEEL TWP. ON
CA	VULSAY INDUSTRIES INC.	BLOCKS E,F & N REGAN RD.	BRAMPTON CITY ON
CA	Aecon Construction and Materials Limited	Mobile Facility	Brampton ON
CA	Aecon Construction and Materials Limited	Mobile Facility	Brampton ON
CA	The Regional Municipality of Peel	Bovaird Drive	Brampton ON
CA	The Corporation of the City of Brampton	Wanless Dr Wanless Drive between Hurontario Street and McLaughlin Road	Brampton ON
CA	Petro Canada		Brampton ON
CA	Wanless Lands Inc.	Part of Lot 16, Concession 1, WHS	Brampton ON
CA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON

CA	The Regional Municipality of Peel	Bovaird Drive	Brampton ON	
CA	Sundial Homes (Sheridan) Limited	Part of West Half of Lot 15, Conc. 1WHS	Brampton ON	
CA	The Corporation of the City of Brampton	McLaughlin Road	Brampton ON	
CA	Wanless Lands Inc.	Part of Lot 16, Concession 1, WHS	Brampton ON	
CA	2066650 Ontario Inc.		Brampton ON	
CA	Fernbrook Homes (Etobicoke Creek) Limited	East of Hurontario Street	Caledon ON	
CA	Petro Canada Inc.		Brampton ON	
CONV	ARMBRO TRANSPORT INC.		ON	
CONV	SAFETY-KLEEN (ON-SITE) INC.		ON	
DTNK	GO VACATIONS CANADA INC	HWY 7	BRAMPTON ON	
DTNK	BRAMPTON BRICK SALES	HURONTARIO ST	BRAMPTON ON	
DTNK	BRAMPTON BRICK SALES	HURONTARIO ST	BRAMPTON ON	
EBR	Aecon Construction and Materials Limited	Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON	ON	
EBR	Aecon Construction and Materials Limited	Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON	ON	
EBR	Accuworx Inc.	Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON	ON	
EBR	CHRYSLER CANADA LTD.		City of Brampton ON	
ECA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L6T 4B9
ECA	1344694 Ontario Inc.	Lot 14, Conc. 1 WHS., Westpoint Village Subd.	Brampton ON	L4L 7Y7
ECA	Valleybrand Developments Ltd. /Westbrand Developments Ltd.	Part of Lot 15, Concession 1 WHS	Brampton ON	L4K 1H3
ECA	The Regional Municipality of Peel	Part of Lot 20, Concession 1	Caledon ON	L6T 4B9
ECA	Brampton North Three Limited and Wanless Lands Inc.	Part of Lot 16, Concession 1, WHS	Brampton ON	M3B 2T5
ECA	The Regional Municipality of Peel	Hurontario Street	Caledon ON	L6T 4B9

ECA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L6T 3Y3
ECA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L6T 3Y5
ECA	Hillbrand Developments Limited	Lot 15, Concession 1 West of Hurontario Street	Brampton ON	L4K 1H3
ECA	Sundial Homes (Sheridan) Limited	Part of West Half of Lot 15, Conc. 1WHS	Brampton ON	M2N 6N4
ECA	Accuworx Inc.	Mobile Facility	Brampton ON	L6T 4J4
ECA	Aecon Construction and Materials Limited	Mobile Facility	Brampton ON	L7A 1A9
ECA	The Regional Municipality of Peel	Hurontario St	Caledon ON	L6T 3Y5
ECA	The Corporation of the City of Brampton	Wanless Drive between Hurontario Street and McLaughlin Road	Brampton ON	L6Y 5T1
ECA	Sundial Homes (Sheridan) Limited	Part of West Half of Lot 15, Conc. 1WHS	Brampton ON	M2N 6N4
ECA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L6T 4B9
ECA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L6T 4B9
ECA	Wanless Lands Inc.	Part of Lot 16, Concession 1, WHS	Brampton ON	
ECA	The Regional Municipality of Peel	Lot 23, Concession 1	Caledon ON	L6T 4B9
ECA	Mayfield Road Portfolio Inc.	Mayfield Rd	Caledon ON	M3K 1N4
ECA	The Regional Municipality of Peel	Lot 23, Concession 1	Caledon ON	L6T 4B9
ECA	Aecon Construction and Materials Limited	Mobile Facility	Brampton ON	L7A 1A9
ECA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L6T 3Y3
ECA	Valleybrand Developments Ltd. /Westbrand Developments Ltd.	Part of Lot 15, Concession 1 WHS	Brampton ON	L4K 1H3
ECA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L6T 3Y3
ECA	Accuworx Inc.	Mobile Facility	Brampton ON	L6T 4J4
ECA	The Corporation of the Town of Caledon	Kennedy Rd	Caledon ON	L7C 1J6
ECA	Bluegrass South Ltd.	West of Hurontario Street	Brampton ON	L4B 3N6
ECA	Lormel Joint Venture Inc.		Caledon ON	L6J 0A8

ECA	2492090 Ontario Inc.	East of Hurontario Street	Brampton ON	L5K 0A1
ECA	Accuworx Inc.	Mobile Facility	Brampton ON	L6T 4J4
ECA	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L6T 4B9
ECA	Sabrina Homes (Mayfield Acquisitions) Inc.	Part of Lot 17, Concession 1 WHS	Brampton ON	L5N 2K7
ECA	Four X Development Inc.	West of Hurontario Street	Brampton ON	L4K 4R1
ECA	Four X Development Inc.	West of Hurontario Street	Brampton ON	L4K 4R1
ECA	Helport Developments Inc.	Part of Lot 8	Brampton ON	L4Z 1P1
ECA	Liv Developments Ltd.	West of Hurontario Street	Brampton ON	L7P 5B1
ECA	Brampton Brick Limited		Caledon ON	L7A 1E9
ECA	Wanless Lands Inc.	Part of Lot 16, Concession 1, WHS	Brampton ON	
EHS		Hurontario Street	Brampton ON	
EHS		Hurontario St Route	Brampton ON	
EHS		Hurontario Street	Brampton ON	
EHS		Williams Parkway	Brampton ON	
EHS		West of Hurontario Street	Town of Caledon ON	
EXP	MARTIN AGRI DRAINAGE LTD	LOT 20 CON 1	PEEL TWP ON	
EXP	MARTIN AGRI DRAINAGE LTD	LOT 20 CON 1	PEEL TWP ON	
FSTH	CBM	WEST SIDE HWY 10	CALEDON ON	
FSTH	CBM	WEST SIDE HWY 10	CALEDON ON	
GEN	Metrolinx	Hurontario Street	Brampton ON	
GEN	AECOM Canada Ltd.	Ken Whillans Drive	Brampton ON	
GEN	MARTIN AGRI DRAINAGE LTD.	LOT 20, CONC 1,	PEEL TWP. ON	N0B 2S0
GEN	The Regional Municipality of Peel	Mayfield Rd	Brampton ON	L7A 0C4

HINC		ICELAND POPPY TRAIL, LOT # 141	BRAMPTON ON	
PES	CALEDON COUNTRY GARDENS	HWY. #10	CALEDON ON	L0N1C0
PRT	GO VACATIONS CANADA INC	HWY 7	BRAMPTON ON	
PRT	WHITE'S GARAGE OF ALMA LTD	MAIN ST	ALMA ON	
PRT	MARTIN AGRI DRAINAGE LTD	LOT 20 CON 1	PEEL TWP ON	
PRT	CANADA BUILDING MAT'LS	WEST SIDE HWY 10	CALEDON ON	
PRT	RO NO HAULAGE	LOT 23 CON 1	CALEDON EAST ON	
PTTW	Lafarge Canada Inc.		ON	
PTTW	Wallenstein Feed and Supply	Lot 18, Concession 1 PEEL	ON	
RSC	SHRI MAHA KALI AMMAA MANDIR HINDU ASSOCIATION	0 Mayfield RD E	City of Brampton ON	
RSC	STARBRIGHT HOLDINGS INC.	0 MAYFIELD ROAD ON	Brampton ON	
RSC	UPPER MAYFIELD ESTATES INC.	0 MAYFIELD ROAD ON	Brampton ON	
RSC	CALEDON 410 DEVELOPMENTS LIMITED	0 MCLAUGHLIN ROAD ON	Caledon ON	
RST	PETRO-CANADA		BRAMPTON ON	
SCT	UNITED AGGREGATES LTD	HWY 10	CALEDON VILLAGE ON	L0N 1C0
SCT	Classifier Milling Systems Corp.		Caledon Village ON	
SCT	BLUE CIRCLE AGGREGATES	Hwy 10	Caledon Village ON	L0N 1C0
SCT	Caledon Sand & Gravel Inc.	Hwy 10	Caledon Village ON	L0N 1C0
SCT	Blue Circle Aggregates	Hwy 10	Caledon Village ON	L0N 1C0
SPL		on Highway 10	Caledon ON	
SPL	Hydro One Brampton Networks Inc.	98 Kingswood	Brampton ON	
SPL	Day & Ross Transport<UNOFFICIAL>		Brampton ON	
SPL	Hydro One Brampton Networks Inc.		Brampton ON	

SPL		Bovaird Dr	Brampton ON
SPL	Canada Cartage Systems Limited		Brampton ON
SPL		Highway 10	Caledon ON
SPL	Andrews Trucking Limited	N of Hwy 7	Brampton ON
SPL	Daniel Contracting Ltd.	Bovaird Dr	Brampton ON
SPL	Southlake Blvd and Streamline Dr. <UNOFFICIAL>	near Williams Pkwy	Brampton ON
SPL	Petro-Canada Gas Station<UNOFFICIAL>		Brampton ON
SPL	Canadian Waste Services Inc.	Orchid Drive (Hurontario & Sandelwood)	Brampton ON
SPL	Day & Ross Inc.	DAY & ROSS TRUCK - WESTBOUND LANE OF BOVAIRD ST, WEST OF KENNEDY<UNOFFICIAL>	Brampton ON
SPL	Brampton Transit<UNOFFICIAL>		Brampton ON
SPL	HARMAC TRANSPORTATION	AT VULSAY PACKAGING ON REGAN ST. TANK TRUCK (CARGO)	BRAMPTON CITY ON
SPL	UNKNOWN	MUNICIPAL PARK, KINGSWOOD DR (NEAR WILLIAMS PARKWAY)	BRAMPTON CITY ON
SRDS	CANADIAN MINE DEVELOPMENT		BRAMPTON ON
WWIS		Williams Pkwy lot 9 con 1	Brampton ON
WWIS		con 2	ON
WWIS		con 2	ON
WWIS		con 2	ON
WWIS		con 2	ON
WWIS		con 2	ON
WWIS		con 2	ON
WWIS		con 1	ON
WWIS		con 1	ON

WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 1	ON
WWIS	con 2	ON
WWIS	con 2	ON
WWIS	lot 14	ON
WWIS	lot 7	ON
WWIS	Vodden St. E. lot 7 con 1	Brampton ON
WWIS	lot 18	ON
WWIS	Vodden St. E. lot 7 con 1	Brampton ON

Unplottable Report

Site:
Lot 18 Con 1 Peel ON

Database:
AAGR

Type:
Region/County: Wellington
Township: Peel
Concession: 1
Lot: 18
Size (ha):
Landuse:
Comments: naturally rehabilitated

Site:
Lot 20 Con 1 Peel ON

Database:
AAGR

Type:
Region/County: Wellington
Township: Peel
Concession: 1
Lot: 20
Size (ha):
Landuse:
Comments: naturally rehabilitated

Site:
Lot 7 Con 2 Peel ON

Database:
AAGR

Type:
Region/County: Wellington
Township: Peel
Concession: 2
Lot: 7
Size (ha):
Landuse:
Comments: naturally rehabilitated

Site:
Lot 21 Con 1 Caledon ON

Database:
AAGR

Type: Pit
Region/County: Peel
Township: Caledon
Concession: 1
Lot: 21
Size (ha):
Landuse:
Comments: Oak Ridges Moraine, rehabilitated

Site: ***The Regional Municipality of Peel***
Mayfield Road Brampton ON

Database:
CA

Certificate #: 2749-5URJLL
Application Year: 2004

Issue Date: 4/8/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Brampton West 6-2 Limited***
Part of the West Half of Lot 16, Concession 1 W.H.S. Brampton ON

Database: ***CA***

Certificate #: 2360-6A2LYC
Application Year: 2005
Issue Date: 3/2/2005
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Petro-Canada Inc.***
Brampton ON

Database: ***CA***

Certificate #: 1681-72CKTY
Application Year: 2007
Issue Date: 4/19/2007
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Peel***
Mayfield Road Brampton ON

Database: ***CA***

Certificate #: 1649-6PLNAN
Application Year: 2006
Issue Date: 6/13/2006
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Mattamy (Credit River) Limited***
Sandalwood Parkway Brampton ON

Database: ***CA***

Certificate #: 1196-648H5K
Application Year: 2004
Issue Date: 8/26/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON

Database: ***CA***

Certificate #: 0859-7E8RF4
Application Year: 2008
Issue Date: 5/2/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the City of Brampton***
Kennedy Rd Brampton ON

Database: ***CA***

Certificate #: 0803-7DZKU4
Application Year: 2008
Issue Date: 4/28/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Peel***
Mayfield Road Brampton ON

Database: ***CA***

Certificate #: 0496-5SQMXP
Application Year: 2003
Issue Date: 10/28/2003
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:

Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***2066650 Ontario Inc.***
Brampton ON

Database: ***CA***

Certificate #: 0458-7NFMF9
Application Year: 2009
Issue Date: 3/2/2009
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Sundial Homes (Sheridan) Limited***
Part of West Half of Lot 15, Conc. 1WHS Brampton ON

Database: ***CA***

Certificate #: 0152-5SCP6F
Application Year: 2003
Issue Date: 10/20/2003
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site:
Lot 14, Concession 1 WHS Brampton ON

Database: ***CA***

Certificate #: 1283-4Q8SGB
Application Year: 00
Issue Date: 10/23/00
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: 149259 Canada Limited
Client Address: 446 Spadina Road, 3rd. Floor
Client City: Toronto
Client Postal Code: M5P 3M2
Project Description: Construction of watermains on Orchid Drive and Swansea Meadows Drive.
Contaminants:
Emission Control:

Site:
Lot 14, Concession 1 WHS Brampton ON

Database: ***CA***

Certificate #: 1470-4Q8SPL
Application Year: 00
Issue Date: 10/23/00

Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: 149259 Canada Limited
Client Address: 446 Spadina Road, 3rd. Floor
Client City: Toronto
Client Postal Code: M5P 3M2
Project Description: Construction of sanitary and storm sewers on Orchid Drive and Swansea Meadows Drive and installation of a foundation drain collector system to service a residential subdivision
Contaminants:
Emission Control:

Site:
Lot 13, Conc. 1, WHS., Sandalwood Parkway Brampton ON

Database: ***CA***

Certificate #: 6276-4L8PNU
Application Year: 00
Issue Date: 6/15/00
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Terraco Inc.
Client Address: 56 Ridley Boulevard
Client City: Toronto
Client Postal Code: M5M 2L4
Project Description: This application is for the installation of watermains on Van Kirk Drive
Contaminants:
Emission Control:

Site:
Lot 13, Conc. 1, WHS., Sandalwood Parkway Brampton ON

Database: ***CA***

Certificate #: 5105-4L8P7L
Application Year: 00
Issue Date: 6/15/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Terraco Inc.
Client Address: 56 Ridley Boulevard
Client City: Toronto
Client Postal Code: M5M 2L4
Project Description: This application is for the installation of foundation drain collectors, sanitary sewers and storm sewers on Sandalwood Parkway and McLaughlin Road.
Contaminants:
Emission Control:

Site:
Part of Lot 16, Concession 1, WHS Brampton ON

Database: ***CA***

Certificate #: 2101-5C4JJP
Application Year: 02
Issue Date: 7/19/02
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Brampton North Three Limited and Wanless Lands Inc.
Client Address: 26 Lesmill Road
Client City: Toronto
Client Postal Code: M3B 2T5
Project Description: This application is for the construction of watermains on Tournament Drive, Ryegrass Crescent, Bissell Drive, Bentgrass Lane, John Pappain Crescent, and Master Green Crescent.
Contaminants:
Emission Control:

Site:
Part of Lot 16, Concession 1, WHS Brampton ON

Database: ***CA***

Certificate #:	8313-5C4JMR
Application Year:	02
Issue Date:	7/19/02
Approval Type:	Municipal & Private sewage
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	Brampton North Three Limited and Wanless Lands Inc.
Client Address:	26 Lesmill Road
Client City:	Toronto
Client Postal Code:	M3B 2T5
Project Description:	This application is for the construction of sanitary sewers, storm sewers and appurtenances on Tournament Drive, Ryegrass Crescent, Bissell Drive, Bentgrass Lane, John Pappain Crescent, Master Green Crescent, Wanless Drive and Easement.
Contaminants:	
Emission Control:	

Site:
Lot 17, Concession 1 WHS Brampton ON

Database: ***CA***

Certificate #:	8636-4QVTLF
Application Year:	00
Issue Date:	12/8/00
Approval Type:	Municipal & Private water
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	Great-L Developments Inc.
Client Address:	1200 Sheppard Avenue East
Client City:	Toronto
Client Postal Code:	M2K 2S5
Project Description:	Watermains to be constructed in the Great-L Development Phase 2 (21T-78032) in the City of Brampton.
Contaminants:	
Emission Control:	

Site:
Part of Lot 20, Concession 1 Caledon ON

Database: ***CA***

Certificate #:	1649-53YTNP
Application Year:	01
Issue Date:	10/30/01
Approval Type:	Industrial air
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	The Corporation of the Regional Municipality of Peel
Client Address:	10 Peel Centre Drive, Fourth Floor
Client City:	Brampton
Client Postal Code:	L6T 4B9
Project Description:	Installation of a diesel Generator
Contaminants:	
Emission Control:	

Site:
Lot 23, Concession 1 Caledon ON

Database: ***CA***

Certificate #:	8631-4UMKLW
Application Year:	01
Issue Date:	5/3/01
Approval Type:	Industrial air
Status:	Approved
Application Type:	New Certificate of Approval

Client Name: Corporation of the Regional Municipality of Peel
Client Address: 10 Peel Centre Drive
Client City: Brampton
Client Postal Code: L6T 4B9
Project Description: This application is for a Certificate of Approval for a 100kW diesel generator to be used as standby and operated in the event of a power failure at the Caledon East Well Pumping facility.
Contaminants:
Emission Control: Silencer

Site: ***Database:*** ***CA***
Mayfield Road Caledon ON

Certificate #: 3357-56AJB5
Application Year: 02
Issue Date: 1/17/02
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: The Corporation of the Regional Municipality of Peel
Client Address: 10 Peel Centre Drive, Fourth Floor
Client City: Brampton
Client Postal Code: L6T 4B9
Project Description: This application is for approval to install a watermain on Mayfield Road
Contaminants:
Emission Control:

Site: ***Caledon Village Well No. 3 and Well No. 4*** ***Database:*** ***CA***
Highway 10 Caledon ON

Certificate #: 8732-5AUL84
Application Year: 02
Issue Date: 6/13/02
Approval Type: Municipal & Private water
Status: Approved
Application Type: Amended CofA
Client Name: The Corporation of the Regional Municipality of Peel
Client Address: 10 Peel Centre Drive, Fourth Floor
Client City: Brampton
Client Postal Code: L6T 4B9
Project Description: Amendment of Deadline for Hydrogeological GDUI Study Reports
Contaminants:
Emission Control:

Site: ***Caledon Village Well No. 3 and Well No. 4*** ***Database:*** ***CA***
Highway 10 Caledon ON

Certificate #: 7080-56FSCY
Application Year: 02
Issue Date: 6/13/02
Approval Type: Municipal & Private water
Status: Revoked and/or Replaced
Application Type: New Certificate of Approval
Client Name: Region of Peel
Client Address: 4th Floor, 10 Peel Centre Dr.,
Client City: Brampton
Client Postal Code: L6T 4B9
Project Description: The system comprises of two (2) well pump housees, reservoir and booster pumping station and distribution system
Contaminants:
Emission Control:

Site: ***Caledon East Well Pumping Facility*** ***Database:*** ***CA***

Lot 23, Concession 1 Caledon ON

Certificate #: 7562-4USS4E
Application Year: 01
Issue Date: 5/10/01
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the Regional Municipality of Peel
Client Address: 10 Peel Centre Drive
Client City: Brampton
Client Postal Code: L6T 4B9
Project Description: This application is for a Certificate of Approval to abandon two (2) existing waterwells and the development of a third well.
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***

Lot 14, Conc. 1 WHS., Westpoint Village Subd. Brampton ON

Certificate #: 8478-4RWU4V
Application Year: 00
Issue Date: 12/13/00
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: 1344694 Ontario Inc.
Client Address: 93 Woodstream Boulevard, #3
Client City: Woodbridge
Client Postal Code: L4L 7Y7
Project Description: This application is for the installation of watermains to serve the Westpoint Village Subdivision.
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***

Lot 14, Conc. 1 WHS., Westpoint Village Subd. Brampton ON

Certificate #: 2150-4RWTXV
Application Year: 00
Issue Date: 12/13/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: 1344694 Ontario Inc.
Client Address: 93 Woodstream Boulevard, #3
Client City: Woodbridge
Client Postal Code: L4L 7Y7
Project Description: This application is for the installation of sanitary and storm sewers to serve the Westpoint Village Subdivision.
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***

Part of Lot 15, Concession 1 WHS Brampton ON

Certificate #: 8183-4HGRV9
Application Year: 00
Issue Date: 3/17/00
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Valleybrand Developments Ltd./Westbrand Developments Ltd.
Client Address: c/o 137 Bowes Road
Client City: Concord
Client Postal Code: L4K 1H3

Project Description: Watermains to be constructed in conjunction with project No. T98025B/T-98031B.
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***
Part of Lot 15, Concession 1 WHS Brampton ON

Certificate #: 5467-4JXGTG
Application Year: 00
Issue Date: 5/15/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Valleybrand Developments Ltd./Westbrand Developments Ltd.
Client Address: c/o 137 Bowes Road
Client City: Concord
Client Postal Code: L4K 1H3
Project Description: Stormwater Management Facility
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***
Part of Lot 15, Concession 1 WHS Brampton ON

Certificate #: 1360-4HGSLM
Application Year: 00
Issue Date: 3/17/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Valleybrand Developments Ltd./Westbrand Developments Ltd.
Client Address: c/o 137 Bowes Road
Client City: Concord
Client Postal Code: L4K 1H3
Project Description: Sanitary sewers, storm sewers and foundation drain collectors to be constructed in conjunction with project No. T-98025B/T-98031B.
Contaminants:
Emission Control:

Site: ***MCDONALD'S RESTAURANTS OF CANADA LTD.*** ***Database:*** ***CA***
HWY.7 BRAMTON CITY ON

Certificate #: 3-1417-85-006
Application Year: 85
Issue Date: 12/13/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***KINGKNOLL DEVELOPMENT LTD.*** ***Database:*** ***CA***
MCLAUGHLIN RD. BRAMPTON CITY ON

Certificate #: 3-1201-85-006
Application Year: 85
Issue Date: 9/26/85

Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***KINGKNOLL DEVELOPMENT LTD.***
MCLAUGHLIN RD. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0891-85-006
Application Year: 85
Issue Date: 9/26/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***PEEL NON-PROFIT HOUSING CORP.***
HURONTARIO ST. (PHASE 2) BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0856-85-006
Application Year: 85
Issue Date: 7/25/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***REG. MUN. OF PEEL***
HWY #7 BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0760-85-006
Application Year: 85
Issue Date: 9/12/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***THE CITY***
LORNE AVE BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0751-85-006
Application Year: 85
Issue Date: 7/17/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***PEEL NON-PROFIT HOUSING CORP.***
HURONTARIO ST. (PHASE 2) BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0624-85-006
Application Year: 85
Issue Date: 7/25/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***PEEL NON-PROFIT HOUSING CORP.***
HURONTARIO ST. (PHASE 1) BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0563-85-006
Application Year: 85
Issue Date: 6/12/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***PEEL NON-PROFIT HOUSING CORP.***
HURONTARIO ST. (PHASE 1) BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0397-85-006
Application Year: 85
Issue Date: 6/12/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:

Project Description:
Contaminants:
Emission Control:

Site: ***THE CITY***
BEECH ST. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0223-85-006
Application Year: 85
Issue Date: 3/27/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***959823 ONTARIO LIMITED***
KENDRA COURT/BRINKLEY DR. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0207-99-
Application Year: 99
Issue Date: 3/22/1999
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***PETRO-CANADA PRODUCTS***
SANDALWOOD PKWY., S.W.M. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 4-0027-97-
Application Year: 97
Issue Date: 6/6/1997
Approval Type: Industrial wastewater
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: U/G DRAINAGE SYS., 3 CATCHBASINS, ETC.
Contaminants:
Emission Control:

Site: ***TEMPSON HOLDINGS LTD/GANA CONTRACTING IN***
GANA TEMPSON SUBD/VAN SCOTT CR BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0435-90-
Application Year: 90
Issue Date: 5/11/1990
Approval Type: Municipal water

Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***NORTONVILLE ESTATES LTD.***
VODDEN STREET BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0517-87-
Application Year: 87
Issue Date: 4/30/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MIA PROPERTIES LIMITED***
VAN KIRK DR. MIA IND. PARK BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1835-88-
Application Year: 88
Issue Date: 11/9/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***L.D.C.M. INVESTMENTS LTD.-BLOCKS 53 & 54***
MURRAY STREET/BURTON ROAD BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1827-90-
Application Year: 90
Issue Date: 1/9/1991
Approval Type: Municipal water
Status: Approved in 1991
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***KINGSPOINT PLAZA LIMITED***

Database: ***CA***

MAIN STREET NORTH BRAMPTON CITY ON

Certificate #: 7-0134-88-
Application Year: 88
Issue Date: 3/4/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***717495 ONTARIO LTD. GLENROSE PARK SUBD. WILLIAMS PARKWAY BRAMPTON CITY ON***

Database: ***CA***

Certificate #: 7-0934-89-
Application Year: 89
Issue Date: 6/20/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TRICAN ESTATES LTD. MILL ST/LOT 21, BLOCK 5 CALEDON TOWN ON***

Database: ***CA***

Certificate #: 3-0637-95-
Application Year: 95
Issue Date: 6/12/1995
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***STARBRAM DEVELOPMENTS INC. HURONTARIO HWY. 10 BRAMPTON CITY ON***

Database: ***CA***

Certificate #: 7-1817-87-
Application Year: 87
Issue Date: 12/17/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:

Contaminants:
Emission Control:

Site: ***R.M. OF PEEL***
HIGHWAY NO. 10 BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1776-87-
Application Year: 87
Issue Date: 11/27/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***ALAN FURBACHER BRAMPTON CITY***
REGAN RD. PRIVATE PROPERTY BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1686-87-
Application Year: 87
Issue Date: 11/17/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BRAMALEA LIMITED***
A STREET HWY. 7 BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0310-87-
Application Year: 87
Issue Date: 4/6/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MATAGORDA MANAGEMENT INC.-LOT 23/CONC.IV***
HURONTARIO STREET CALEDON TOWN ON

Database: ***CA***

Certificate #: 7-1187-91-
Application Year: 91
Issue Date: 10/9/1991
Approval Type: Municipal water
Status: Approved

Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF PEEL-ARCHIBALD ST.-FILE 90-1400***
ARCHIBALD ST/MOORE ST/MURRAY S BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1561-90-
Application Year: 90
Issue Date: 10/10/1990
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***L.D.C.M. INVESTMENTS BRAMPTON CITY***
KEN WHILLANS DR. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1495-89-
Application Year: 89
Issue Date: 9/15/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***662016 ONTARIO LTD.***
HWY. #10 BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1189-89-
Application Year: 89
Issue Date: 7/26/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CITY SOUTH LIMITED***
HURONTARIO STREET BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0916-89-
Application Year: 89
Issue Date: 6/9/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MIA PROPERTIES LIMITED***
MIA IND. SUBD. VAN KIRK DR. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0032-89-
Application Year: 89
Issue Date: 1/24/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***LIOYD ALTEC***
KENNEDY RD. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1765-88-
Application Year: 88
Issue Date: 7/4/1990
Approval Type: Municipal water
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***285240 ONTARIO LIMITED WILSON IND. SUBD.***
VAN KIRK DR. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1812-88-
Application Year: 88
Issue Date: 11/25/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:

Emission Control:

Site: ***NORTHWEST PALM INVESTMENTS LTD.***
VAN KIRK DRIVE BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1087-88-
Application Year: 88
Issue Date: 7/25/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***KANEFF PROPERTIES LIMITED***
HURONTARIO ST. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1409-86-
Application Year: 86
Issue Date: 12/1/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CENTRAL PEEL HOLDINGS (1982) LIMITED***
FISHERMAN DR. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1375-86-
Application Year: 86
Issue Date: 11/21/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BRAMPTON CITY***
CENTRE STREET BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-1120-86-
Application Year: 86
Issue Date: 9/26/1986
Approval Type: Municipal water
Status: Approved
Application Type:

Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF PEEL***
SANDALWOOD PARKWAY BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0734-86-
Application Year: 86
Issue Date: 7/17/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***SAM-SOR ENTERPRISES INC.***
HIGHWAY 7 EASEMENT BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0627-86-
Application Year: 86
Issue Date: 6/17/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***PEEL NON-PROFIT HOUSING***
MURRAY ST. PRIVATE DRIVEWAY BRAMPTON CITY ON

Database: ***CA***

Certificate #: 7-0083-86-
Application Year: 86
Issue Date: 2/21/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF PEEL***
E. HURONTARIO ST. CALEDON TOWN ON

Database: ***CA***

Certificate #: 3-1453-92-
Application Year: 92
Issue Date: 11/4/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***WOLVERLEIGH CONSTRUCTION-LOTS 12 & 13***
SANDALWOOD PARKWAY BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0258-91-
Application Year: 91
Issue Date: 4/30/1991
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***L.D.C.M. INVESTMENTS LTD.-BLOCKS 53 & 54***
MURRAY STREET/BURTON ROAD BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-2250-90-
Application Year: 90
Issue Date: 1/9/1991
Approval Type: Municipal sewage
Status: Approved in 1991
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF PEEL-LOT 16, CONC. 2***
KENNEDY RD. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0767-90-
Application Year: 90
Issue Date: 5/23/1990
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TEMPSON HOLDINGS LTD/GANA CONTRACTING IN***
GANA TEMPSON SUBD/VAN SCOTT CR BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0528-90-
Application Year: 90
Issue Date: 5/11/1990
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***L.D.C.M. INVESTMENTS***
KEN WHILLANS DR. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1796-89-
Application Year: 89
Issue Date: 9/15/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***717495 ONTARIO LTD. GLENROSE PARK SUBD.***
WILLIAMS PARKWAY BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1107-89-
Application Year: 89
Issue Date: 6/20/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CITY SOUTH LIMITED***
HURONTARIO ST. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1088-89-
Application Year: 89
Issue Date: 6/9/1989
Approval Type: Municipal sewage
Status:
Application Type:
Client Name:

Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***285240 ONTARIO LTD. WILSON IND. SUBD.***
VAN KIRK DR. N. OF SANDALWOOD BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-2145-88-
Application Year: 88
Issue Date: 11/25/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MIA PROPERTIES LIMITED***
VAN KIRK DR. MIA IND. PARK BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-2167-88-
Application Year: 88
Issue Date: 11/9/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BRAMPTON CITY***
HURONTARIO STREET BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1374-88-
Application Year: 88
Issue Date: 8/5/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***NORTHWEST PALM INVESTMENT LTD.***
VAN KIRK DRIVE BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1255-88-

Application Year: 88
Issue Date: 7/25/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***KINGSPOINT PLAZA LIMITED***
MAIN STREET NORTH BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0151-88-
Application Year: 88
Issue Date: 3/4/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CENTRAL PEEL HOLDINGS (1982) LIMITED***
FISHERMAN DR. BERSAMCAR SUBD. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1728-86-
Application Year: 86
Issue Date: 11/21/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***R.M. OF PEEL***
NORTH OF HIGHWAY #7 BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1610-86-
Application Year: 86
Issue Date: 10/23/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BRAMPTON CITY***
CENTRE ST. WEST SIDE BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1412-86-
Application Year: 86
Issue Date: 9/26/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***SAM-SOR ENTERPRISES INC.***
HWY. 7 EASEMENT BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0783-86-
Application Year: 86
Issue Date: 6/17/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BRAMPTON CITY***
KENNEDY RD. NORTH BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0747-86-
Application Year: 86
Issue Date: 6/12/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BEACON HALL LTD.***
STREET C MCLAUGHLIN RD. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0598-86-
Application Year: 86
Issue Date: 5/23/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BRAMPTON CITY***
SANDALWOOD PARKWAY BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0436-86-
Application Year: 86
Issue Date: 5/13/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***PEEL NON-PROFIT HOUSING***
MURRAY ST.PRIVATE DRIVEWAY BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0124-86-
Application Year: 86
Issue Date: 2/21/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***S.E.J.-S.H.L. HOLDINGS***
WILLIAMS PKWY EAST BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-2218-87-
Application Year: 87
Issue Date: 12/23/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***ORLANDO CORPORATION FLETCHER'S CREEK***
E. OF MCLAUGHLIN RD. BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-1662-87-
Application Year: 87

Issue Date: 9/24/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***ARMBRO MATERIALS & CONSTRUCTION LTD.***
W. OF REGAN RD. ARMBRO IND.SUB BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0608-87-
Application Year: 87
Issue Date: 5/14/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***NORTONVILLE ESTATES LTD.***
VODDEN STREET BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0610-87-
Application Year: 87
Issue Date: 4/30/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BRAMALEA LIMITED***
A STREET N. OF HWY. 7 BRAMPTON CITY ON

Database: ***CA***

Certificate #: 3-0378-87-
Application Year: 87
Issue Date: 4/6/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***WALLENSTEIN FEED AND SUPPLY LTD.***
LOT 18, CONC. 1 PEEL TWP. ON

Database: ***CA***

Certificate #:	8-2138-93-
Application Year:	93
Issue Date:	7/6/1993
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	CYC./B-HSE FILTER FOR PELLETING PROCESS
Contaminants:	Suspended Particulate Matter
Emission Control:	Baghouse (Incl Vent Fil.), Cyclone,

Site: ***REGIONAL MUNICIPALITY OF PEEL***
E. HURONTARIO ST. CALEDON TOWN ON

Database: ***CA***

Certificate #:	8-3357-92-
Application Year:	92
Issue Date:	11/24/1992
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	30 KW DIESEL GEN-SET AT SEW. PUMP STA.
Contaminants:	Nitrogen Oxides
Emission Control:	No Controls

Site: ***COX CONSTRUCTION LTD. (MATHEWS)***
LOT 18, CONC. 1 PEEL TWP. ON

Database: ***CA***

Certificate #:	8-2052-91-
Application Year:	91
Issue Date:	4/9/1992
Approval Type:	Industrial air
Status:	Approved in 1992
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	PORT. CRUSHING MACHINE/1 DIESEL ENGINE
Contaminants:	Sodium Chlorite, Suspended Particulate Matter, Sound
Emission Control:	No Controls

Site: ***VULSAY INDUSTRIES INC.***
BLOCKS E,F & N REGAN RD. BRAMPTON CITY ON

Database: ***CA***

Certificate #:	8-3071-86-
Application Year:	86
Issue Date:	11/19/1986
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	

Client Postal Code:
Project Description: ETHYLENE GLYCOL STORAGE
Contaminants: Methyl Alcohol, Polyisocyanate Activator 192S
Emission Control: No Controls

Site: ***Aecon Construction and Materials Limited***
Mobile Facility Brampton ON

Database: ***CA***

Certificate #: 1670-8H6K35
Application Year: 2011
Issue Date: 10/14/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Aecon Construction and Materials Limited***
Mobile Facility Brampton ON

Database: ***CA***

Certificate #: 4716-8FMR7G
Application Year: 2011
Issue Date: 10/14/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Peel***
Bovaird Drive Brampton ON

Database: ***CA***

Certificate #: 9801-6G2L2U
Application Year: 2005
Issue Date: 9/13/2005
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the City of Brampton***
Wanless Dr Wanless Drive between Hurontario Street and McLaughlin Road Brampton ON

Database: ***CA***

Certificate #: 8293-6TKPAP
Application Year: 2006
Issue Date: 9/13/2006

Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Petro Canada***
Brampton ON

Database: ***CA***

Certificate #: 7463-66CLP2
Application Year: 2004
Issue Date: 11/5/2004
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Wanless Lands Inc.***
Part of Lot 16, Concession 1, WHS Brampton ON

Database: ***CA***

Certificate #: 6592-5ELV44
Application Year: 2002
Issue Date: 10/22/2002
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON

Database: ***CA***

Certificate #: 5805-776MMT
Application Year: 2007
Issue Date: 9/19/2007
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Regional Municipality of Peel***
Bovaird Drive Brampton ON

Database: ***CA***

Certificate #: 5418-6B5LAN
Application Year: 2005
Issue Date: 4/15/2005
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Sundial Homes (Sheridan) Limited***
Part of West Half of Lot 15, Conc. 1WHS Brampton ON

Database: ***CA***

Certificate #: 5032-5R7Q5Z
Application Year: 2003
Issue Date: 9/15/2003
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***The Corporation of the City of Brampton***
McLaughlin Road Brampton ON

Database: ***CA***

Certificate #: 4630-6DMNQZ
Application Year: 2005
Issue Date: 6/24/2005
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Wanless Lands Inc.***
Part of Lot 16, Concession 1, WHS Brampton ON

Database: ***CA***

Certificate #: 4584-5ELV8N
Application Year: 2002
Issue Date: 10/22/2002
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:

Project Description:
Contaminants:
Emission Control:

Site: ***2066650 Ontario Inc.***
Brampton ON

Database: ***CA***

Certificate #: 4355-7M8SY6
Application Year: 2008
Issue Date: 12/12/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Fernbrook Homes (Etobicoke Creek) Limited***
East of Hurontario Street Caledon ON

Database: ***CA***

Certificate #: 3965-87HPKM
Application Year: 2010
Issue Date: 8/10/2010
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Petro Canada Inc.***
Brampton ON

Database: ***CA***

Certificate #: 3918-6WGKD6
Application Year: 2006
Issue Date: 12/20/2006
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***ARMBRO TRANSPORT INC.***
ON

Database: ***CONV***

File No:
Crown Brief No: 99-0103-0223
Court Location:
Publication City:
Location:
Region: CENTRAL REGION
Ministry District: METRO

Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: OPERATE A HEAVY DIESEL-FUELLED MOTOR VEHICLE THAT CONTRAVENES THE EMISSION STANDARDS.
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation: 361/98
Section: 12(5)
Act/Regulation/Section: EPA-361/98-12(5)
Date of Offence:
Date of Conviction:
Date Charged: 12/10/99
Charge Disposition: SUSPENDED SENTENCE
Fine: $400.00
Synopsis:

Site: ***SAFETY-KLEEN (ON-SITE) INC.***
ON

Database: ***CONV***

File No:
Crown Brief No: 02-0045-0017
Court Location:
Publication City:
Location:
Region: CENTRAL REGION
Ministry District: METRO
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: FAIL TO COMPLY WITH A C OF A OR A PROVISIONAL C OF A BY FAILING TO NOTIFY THE MINISTRY OF ITS INTENT TO TRANSPORT PCB WASTE.
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 186(3)
Act/Regulation/Section: EPA 186(3)
Date of Offence:
Date of Conviction:
Date Charged: 7/17/2003
Charge Disposition: SUSPENDED SENTENCE
Fine:
Synopsis:

Site: ***GO VACATIONS CANADA INC***
HWY 7 BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	9560095	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	390027	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Refill Cntr - Cylr Fill		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Site: ***BRAMPTON BRICK SALES***
HURONTARIO ST BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	11099172	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	68842	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			

TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

Site: ***BRAMPTON BRICK SALES***
HURONTARIO ST BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9902445
Status: EXPIRED
Instance ID: 396057
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Cylr Handling Facility
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Site: ***Aecon Construction and Materials Limited***
Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON

Database: ***EBR***

EBR Registry No: 010-8735
Ministry Ref No: 9192-7Z2N3V
Notice Type: Instrument Decision
Notice Stage:
Notice Date: October 17, 2011
Proposal Date: January 07, 2010
Year: 2010
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Aecon Construction and Materials Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 12 Canam Crescent, Brampton Ontario, Canada L7A 1A9
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON

Site: ***Aecon Construction and Materials Limited***
Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON

Database: ***EBR***

EBR Registry No: 010-8728
Ministry Ref No: 7464-7Z2LSW
Notice Type: Instrument Decision
Notice Stage:
Notice Date: October 17, 2011
Proposal Date: January 04, 2010
Year: 2010
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Aecon Construction and Materials Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 12 Canam Crescent, Brampton Ontario, Canada L7A 1A9
Comment Period:
URL:
Summary:

Site Location Details:

Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site: ***Accuworx Inc.***
Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON ON

Database: ***EBR***

EBR Registry No: 012-0850
Ministry Ref No: 7459-9E3JGP
Notice Type: Instrument Decision
Notice Stage:
Notice Date: January 13, 2017
Proposal Date: January 17, 2014
Year: 2014
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Accuworx Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 36 Advance boulevard, Brampton Ontario, Canada L6T 4J4
Comment Period:
URL:
Summary:

Site Location Details:

Mobile Facility Brampton, Regional Municipality of Peel CITY OF BRAMPTON

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site: ***CHRYSLER CANADA LTD.***
City of Brampton ON

Database: ***EBR***

EBR Registry No: IA7E0927.D
Ministry Ref No:
Notice Type: Instrument
Notice Stage:
Notice Date:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:

Proposal Date: 6/24/97
Year: 1997
Site Location Map:
Instrument Type: EPA s. 9 - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name:
Site Address:
Location Other:
Proponent Name:
Proponent Address: CHRYSLER CANADA LTD., BRAMALEA ASSEMBLY,2000 Williams Parkway,Bramalea, Ontario,L6S 6B3
Comment Period:
URL:
Summary:

Site Location Details:

City of Brampton

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L6T 4B9

Database: ***ECA***

Approval No: 2749-5URJLL
Approval Date: 2004-04-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Peel
Address: Mayfield Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6795-5SSMKA-14.pdf
PDF Site Location:

Site: ***1344694 Ontario Inc.***
Lot 14, Conc. 1 WHS., Westpoint Village Subd. Brampton ON L4L 7Y7

Database: ***ECA***

Approval No: 2150-4RWTXV
Approval Date: 2000-12-13
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: 1344694 Ontario Inc.
Address: Lot 14, Conc. 1 WHS., Westpoint Village Subd.
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3760-4RQHSK-14.pdf
PDF Site Location:

Site: ***Valleybrand Developments Ltd./Westbrand Developments Ltd.***
Part of Lot 15, Concession 1 WHS Brampton ON L4K 1H3

Database: ***ECA***

Approval No: 5467-4JXGTG
Approval Date: 2000-05-15
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS

Business Name: Valleybrand Developments Ltd./Westbrand Developments Ltd.
Address: Part of Lot 15, Concession 1 WHS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7326-4JQP6S-14.pdf
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Part of Lot 20, Concession 1 Caledon ON L6T 4B9

Database: ***ECA***

Approval No: 1649-53YTNP
Approval Date: 2001-10-30
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: The Regional Municipality of Peel
Address: Part of Lot 20, Concession 1
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5314-4ZTPJ3-14.pdf
PDF Site Location:

Site: ***Brampton North Three Limited and Wanless Lands Inc.***
Part of Lot 16, Concession 1, WHS Brampton ON M3B 2T5

Database: ***ECA***

Approval No: 8313-5C4JMR
Approval Date: 2002-07-19
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Brampton North Three Limited and Wanless Lands Inc.
Address: Part of Lot 16, Concession 1, WHS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3663-5C3MGE-14.pdf
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Hurontario Street Caledon ON L6T 4B9

Database: ***ECA***

Approval No: 9308-7HBQKN
Approval Date: 2008-08-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: The Regional Municipality of Peel
Address: Hurontario Street
Full Address:
Full PDF Link:
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L6T 3Y3

Database: ***ECA***

Approval No: 6843-75WN48
Approval Date: 2007-08-10
MOE District:
City:

Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: The Regional Municipality of Peel
Address: Mayfield Rd
Full Address:
Full PDF Link:
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L6T 3Y5

Database: ***ECA***

Approval No:	5805-776MMT	***MOE District:***	
Approval Date:	2007-09-19	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Peel
Address: Mayfield Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2880-76HKZU-14.pdf
PDF Site Location:

Site: ***Hillbrand Developments Limited***
Lot 15, Concession 1 West of Hurontario Street Brampton ON L4K 1H3

Database: ***ECA***

Approval No:	8100-4UTKYD	***MOE District:***	
Approval Date:	2001-03-14	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Hillbrand Developments Limited
Address: Lot 15, Concession 1 West of Hurontario Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7560-4UNP3Z-14.pdf
PDF Site Location:

Site: ***Sundial Homes (Sheridan) Limited***
Part of West Half of Lot 15, Conc. 1WHS Brampton ON M2N 6N4

Database: ***ECA***

Approval No:	0152-5SCP6F	***MOE District:***	
Approval Date:	2003-10-20	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Sundial Homes (Sheridan) Limited
Address: Part of West Half of Lot 15, Conc. 1WHS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6143-5PQHHY-14.pdf
PDF Site Location:

Site: ***Accuworx Inc.***
Mobile Facility Brampton ON L6T 4J4

Database: ***ECA***

Approval No:	8703-9WUSE3	***MOE District:***	
Approval Date:	2015-05-28	***City:***	
Status:	Revoked and/or Replaced	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-INDUSTRIAL SEWAGE WORKS		
Project Type:	INDUSTRIAL SEWAGE WORKS		
Business Name:	Accuworx Inc.		
Address:	Mobile Facility		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3654-9WBN7B-14.pdf		
PDF Site Location:			

Site: ***Aecon Construction and Materials Limited***
Mobile Facility Brampton ON L7A 1A9

Database: ***ECA***

Approval No:	4716-8FMR7G	***MOE District:***	
Approval Date:	2011-10-14	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	Aecon Construction and Materials Limited		
Address:	Mobile Facility		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/9192-7Z2N3V-14.pdf		
PDF Site Location:			

Site: ***The Regional Municipality of Peel***
Hurontario St Caledon ON L6T 3Y5

Database: ***ECA***

Approval No:	8194-77ZKFG	***MOE District:***	
Approval Date:	2007-10-15	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Business Name:	The Regional Municipality of Peel		
Address:	Hurontario St		
Full Address:			
Full PDF Link:			
PDF Site Location:			

Site: ***The Corporation of the City of Brampton***
Wanless Drive between Hurontario Street and McLaughlin Road Brampton ON L6Y 5T1

Database: ***ECA***

Approval No:	8293-6TKPAP	***MOE District:***	Halton-Peel
Approval Date:	2006-09-13	***City:***	
Status:	Approved	***Longitude:***	-79.822
Record Type:	ECA	***Latitude:***	43.7228
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Credit Valley	***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	The Corporation of the City of Brampton		

Address: Wanless Drive between Hurontario Street and McLaughlin Road
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4118-6TFR2Q-14.pdf
PDF Site Location:

Site: ***Sundial Homes (Sheridan) Limited***
Part of West Half of Lot 15, Conc. 1WHS Brampton ON M2N 6N4

Database: ***ECA***

Approval No: 5032-5R7Q5Z
Approval Date: 2003-09-15
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Sundial Homes (Sheridan) Limited
Address: Part of West Half of Lot 15, Conc. 1WHS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3226-5QSR7M-14.pdf
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L6T 4B9

Database: ***ECA***

Approval No: 2387-63TNAQ
Approval Date: 2004-08-16
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: The Regional Municipality of Peel
Address: Mayfield Rd
Full Address:
Full PDF Link:
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L6T 4B9

Database: ***ECA***

Approval No: 0496-5SQMXP
Approval Date: 2003-10-28
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Peel
Address: Mayfield Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9149-5RXP2L-14.pdf
PDF Site Location:

Site: ***Wanless Lands Inc.***
Part of Lot 16, Concession 1, WHS Brampton ON

Database: ***ECA***

Approval No: 4584-5ELV8N
Approval Date: 2002-10-22
Status: Approved
MOE District:
City:
Longitude:

Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Wanless Lands Inc.
Address: Part of Lot 16, Concession 1, WHS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4696-5BWMAU-14.pdf
PDF Site Location:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Regional Municipality of Peel***
Lot 23, Concession 1 Caledon ON L6T 4B9

Database: ***ECA***

Approval No: 7562-4USS4E
Approval Date: 2001-05-10
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Business Name: The Regional Municipality of Peel
Address: Lot 23, Concession 1
Full Address:
Full PDF Link:
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Mayfield Road Portfolio Inc.***
Mayfield Rd Caledon ON M3K 1N4

Database: ***ECA***

Approval No: 5859-96UQU5
Approval Date: 2013-04-30
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Mayfield Road Portfolio Inc.
Address: Mayfield Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5271-96TLGJ-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Regional Municipality of Peel***
Lot 23, Concession 1 Caledon ON L6T 4B9

Database: ***ECA***

Approval No: 8631-4UMKLW
Approval Date: 2001-05-03
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: The Regional Municipality of Peel
Address: Lot 23, Concession 1
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6302-4TQKCK-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Aecon Construction and Materials Limited***
Mobile Facility Brampton ON L7A 1A9

Database: ***ECA***

Approval No:	1670-8H6K35	***MOE District:***	
Approval Date:	2011-10-14	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-AIR
Project Type: AIR
Business Name: Aecon Construction and Materials Limited
Address: Mobile Facility
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7464-7Z2LSW-14.pdf
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L6T 3Y3

Database: ***ECA***

Approval No:	7236-6LRLZD	***MOE District:***	
Approval Date:	2006-02-07	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Business Name: The Regional Municipality of Peel
Address: Mayfield Rd
Full Address:
Full PDF Link:
PDF Site Location:

Site: ***Valleybrand Developments Ltd./Westbrand Developments Ltd.***
Part of Lot 15, Concession 1 WHS Brampton ON L4K 1H3

Database: ***ECA***

Approval No:	1360-4HGSLM	***MOE District:***	
Approval Date:	2000-03-17	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Valleybrand Developments Ltd./Westbrand Developments Ltd.
Address: Part of Lot 15, Concession 1 WHS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2307-4HGJ5V-14.pdf
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L6T 3Y3

Database: ***ECA***

Approval No:	1649-6PLNAN	***MOE District:***	
Approval Date:	2006-06-13	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Peel
Address: Mayfield Rd

Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2054-6LRVLW-14.pdf
PDF Site Location:

Site: ***Accuworx Inc.***
Mobile Facility Brampton ON L6T 4J4

Database: ***ECA***

Approval No: 8475-9FLM5G
Approval Date: 2017-01-06
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-WASTE MANAGEMENT SYSTEMS
Project Type: WASTE MANAGEMENT SYSTEMS
Business Name: Accuworx Inc.
Address: Mobile Facility
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0508-9FDKT5-14.pdf
PDF Site Location:

Site: ***The Corporation of the Town of Caledon***
Kennedy Rd Caledon ON L7C 1J6

Database: ***ECA***

Approval No: 6888-9K4KAH
Approval Date: 2014-05-20
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Corporation of the Town of Caledon
Address: Kennedy Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3940-9JQJMD-14.pdf
PDF Site Location:

Site: ***Bluegrass South Ltd.***
West of Hurontario Street Brampton ON L4B 3N6

Database: ***ECA***

Approval No: 0761-9AEHEY
Approval Date: 2013-08-16
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Bluegrass South Ltd.
Address: West of Hurontario Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8839-9A7NBN-14.pdf
PDF Site Location:

Site: ***Lormel Joint Venture Inc.***
Caledon ON L6J 0A8

Database: ***ECA***

Approval No: 6968-BVPRX6
Approval Date: 2020-12-17
Status: Approved
Record Type: ECA
MOE District:
City:
Longitude:
Latitude:

Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Lormel Joint Venture Inc.
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8617-BV2M34-14.pdf
PDF Site Location:
Geometry X:
Geometry Y:

Site: ***2492090 Ontario Inc.***
East of Hurontario Street Brampton ON L5K 0A1

Database: ***ECA***

Approval No: 5690-BW4M6J
Approval Date: 2020-12-11
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: 2492090 Ontario Inc.
Address: East of Hurontario Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9037-BVBR6V-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Accuworx Inc.***
Mobile Facility Brampton ON L6T 4J4

Database: ***ECA***

Approval No: 4267-BM5KXE
Approval Date: 2020-11-02
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR
Business Name: Accuworx Inc.
Address: Mobile Facility
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5145-BHMLCE-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L6T 4B9

Database: ***ECA***

Approval No: 6524-AZRR3X
Approval Date: 2018-07-10
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Peel
Address: Mayfield Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7493-AYMR4T-14.pdf
PDF Site Location:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Sabrina Homes (Mayfield Acquisitions) Inc.***

Database: ***ECA***

Part of Lot 17, Concession 1 WHS Brampton ON L5N 2K7

Approval No:	4638-AYVNND	***MOE District:***	
Approval Date:	2018-05-24	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Sabrina Homes (Mayfield Acquisitions) Inc.		
Address:	Part of Lot 17, Concession 1 WHS		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7679-AYLGU7-14.pdf		
PDF Site Location:			

Site: ***Four X Development Inc.***
West of Hurontario Street Brampton ON L4K 4R1

Database: ***ECA***

Approval No:	9508-AVDL3L	***MOE District:***	
Approval Date:	2018-04-04	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Four X Development Inc.		
Address:	West of Hurontario Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7109-ARVRPT-14.pdf		
PDF Site Location:			

Site: ***Four X Development Inc.***
West of Hurontario Street Brampton ON L4K 4R1

Database: ***ECA***

Approval No:	8942-AXVK4Y	***MOE District:***	
Approval Date:	2018-04-23	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Four X Development Inc.		
Address:	West of Hurontario Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/1554-AXJRJB-14.pdf		
PDF Site Location:			

Site: ***Helport Developments Inc.***
Part of Lot 8 Brampton ON L4Z 1P1

Database: ***ECA***

Approval No:	8681-AN4JZ5	***MOE District:***	
Approval Date:	2017-06-12	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	Helport Developments Inc.		
Address:	Part of Lot 8		
Full Address:			

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3555-AMURWL-14.pdf
PDF Site Location:

Site: ***Liv Developments Ltd.***
West of Hurontario Street Brampton ON L7P 5B1

Database: ***ECA***

Approval No: 0037-ARZHVB
Approval Date: 2017-10-13
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Liv Developments Ltd.
Address: West of Hurontario Street
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4821-ARTHMS-14.pdf
PDF Site Location:

Site: ***Brampton Brick Limited***
Caledon ON L7A 1E9

Database: ***ECA***

Approval No: 2799-AKAPMK
Approval Date: 2017-03-29
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Business Name: Brampton Brick Limited
Address:
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9573-A7NR8Y-14.pdf
PDF Site Location:

Site: ***Wanless Lands Inc.***
Part of Lot 16, Concession 1, WHS Brampton ON

Database: ***ECA***

Approval No: 6592-5ELV44
Approval Date: 2002-10-22
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Wanless Lands Inc.
Address: Part of Lot 16, Concession 1, WHS
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2521-5BWME4-14.pdf
PDF Site Location:

Site:
Hurontario Street Brampton ON

Database: ***EHS***

Order No: 20070809028
Status: C
Report Type: CAN - Complete Report
Report Date: 8/17/2007
Date Received: 8/9/2007
Nearest Intersection: Hurontario Street and Topflight
Municipality: Peel
Client Prov/State:
Search Radius (km): 0.25
X:

Previous Site Name:
Lot/Building Size: 6.5 acres
Additional Info Ordered: Fire Insur. Maps And /or Site Plans
Y:

Site:
Hurontario St Route Brampton ON

Database: ***EHS***

Order No: 20110509034
Status: C
Report Type: Custom Report
Report Date: 24-JAN-13
Date Received: 09-MAY-11
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.673342
Y: 43.653576

Site:
Hurontario Street Brampton ON

Database: ***EHS***

Order No: 20020415006
Status: C
Report Type: Complete Report
Report Date: 4/23/02
Date Received: 4/15/02
Previous Site Name:
Lot/Building Size: 41 acres
Additional Info Ordered: Title Search
Nearest Intersection: Rice Road
Municipality:
Client Prov/State: OH
Search Radius (km): 0.50
X: -79.794169
Y: 43.712895

Site:
Williams Parkway Brampton ON

Database: ***EHS***

Order No: 20120131012
Status: C
Report Type: Custom Report
Report Date: 06-JUL-12
Date Received: 31-JAN-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -694444.444444
Y: 43.669481

Site:
West of Hurontario Street Town of Caledon ON

Database: ***EHS***

Order No: 20031217004
Status: C
Report Type: Site Report
Report Date: 12/19/03
Date Received: 12/17/03
Previous Site Name:
Lot/Building Size: Vacant Land
Additional Info Ordered:
Nearest Intersection: West of Hurontario Street
Municipality:
Client Prov/State: ON
Search Radius (km): 0.55
X: -79.934496
Y: 43.798675

Site: ***MARTIN AGRI DRAINAGE LTD***
LOT 20 CON 1 PEEL TWP ON

Database: ***EXP***

Inventory No: 10913887
Inventory Status: Inactive
Installation Year: 1955
Capacity: 4546
Capacity Unit:
Tank Type:
Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Diesel

Site: ***MARTIN AGRI DRAINAGE LTD***
LOT 20 CON 1 PEEL TWP ON

Database: ***EXP***

Inventory No: 10913869
Inventory Status: Inactive
Installation Year: 1950
Capacity: 4546
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***CBM***
WEST SIDE HWY 10 CALEDON ON

Database: ***FSTH***

License Issue Date: 5/1/2002
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Site: ***CBM***
WEST SIDE HWY 10 CALEDON ON

Database: ***FSTH***

License Issue Date: 5/1/2002
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Site: ***Metrolinx***
Hurontario Street Brampton ON

Database: ***GEN***

Generator Info as of Dec 2024

Generator No: ON001067062
Generator Company Name: Metrolinx
Street: Hurontario Street

City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L6W 4J4
Waste Class: 251 L

Waste Class Decoded:

251 - OIL SKIMMINGS & SLUDGES

Site: ***AECOM Canada Ltd.***
Ken Whillans Drive Brampton ON

Database: ***GEN***

Generator Info as of Dec 2024

Generator No: ON001071766
Generator Company Name: AECOM Canada Ltd.
Street: Ken Whillans Drive
City: Brampton
Province State: Ontario
Country: Canada
Postal Code: L6V 4B7
Waste Class: 146 L

Waste Class Decoded:

146 - OTHER SPECIFIED INORGANICS

Site: ***MARTIN AGRI DRAINAGE LTD.***
LOT 20, CONC 1, PEEL TWP. ON N0B 2S0

Database: ***GEN***

Generator Info

Generator No: ON1432600
Approval Years: 92,93,97,98
Status:
PO Box No:
Country:
Co Admin:
Phone No Admin:
SIC Description: SEPTIC TANK INSTAL.

Choice of Contact:
Contaminated Fac:
MHSW Facility:
SIC Code: 4213

Waste Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Site: ***The Regional Municipality of Peel***
Mayfield Rd Brampton ON L7A 0C4

Database: ***GEN***

Generator Info

Generator No: ON9207702

Choice of Contact:

Approval Years: As of Jun 2018
Status: Registered
PO Box No:
Country: Canada
Co Admin:
Phone No Admin:
SIC Description:
Contaminated Fac:
MHSW Facility:
SIC Code:

Waste Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

2017 Generator Info

Gen No: ON9207702
ID: 35954
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 237310
NAICS Code2:
NAICS Code3:
Gen Name: The Regional Municipality of Peel
Gen Div: waste water
Gen Op Name: Region of Peel
Gen Op Div: waste water
Site Adrs1: Mayfield Rd
Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 0C4
Site Country: Canada
Co Official: Elaine Gilliland
Co Admin: Alyssa Accardo
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-791-7800 Ext.
Phone No Admin: 905-791-7800 Ext.3
County Ont: PEEL (R. M.)
County Out:
District: 305

2017 Generator Manifest

ID: 64264
Generator No: ON9207702
Receiver Type: 035
Waste Char: L
Waste Code: 251
Sum Received Qty: 18000.0
Waste Class Name: OIL SKIMMINGS & SLUDGES
Count Manifests: 2
District: 305

2018 Generator Info

Gen No: ON9207702
ID: 36651
Contaminated Fac: N
MHSW Facility: N
NAICS Code1: 237310
NAICS Code2:
NAICS Code3:
Gen Name: The Regional Municipality of Peel
Gen Div: waste water
Gen Op Name: Region of Peel
Gen Op Div: waste water
Site Adrs1: Mayfield Rd
Choice of Contact: CO_OFFICIAL
Phone No Official: 905-791-7800 Ext.
Phone No Admin: 905-791-7800 Ext.3
County Ont: PEEL (R. M.)
County Out:
District: 305

Site Bldg:
Site Pobox:
Province In: ONTARIO
Site Adrs2:
Site City: Brampton
Province Out:
Site Postal Code: L7A 0C4
Site Country: Canada
Co Official: Elaine Gilliland
Co Admin: Alyssa Accardo

Site:
ICELAND POPPY TRAIL, LOT # 141 BRAMPTON ON

Database: ***HINC***

External File Num: FS INC 0712-07486
Fuel Occurrence Type: Pipeline Strike
Date of Occurrence: 11/1/2007
Fuel Type Involved: Natural Gas
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Construction Site (pipeline strike)
Service Interruptions: No
Property Damage: No
Fuel Life Cycle Stage: Transmission, Distribution and Transportation
Root Cause: Root Cause: Equipment/Material/Component:No Procedures:No Maintenance:No Design:No Training:No Management:Yes Human Factors:Yes
Reported Details:
Fuel Category: Gaseous Fuel
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Peel
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

Site: ***CALEDON COUNTRY GARDENS***
HWY. #10 CALEDON ON L0N1C0

Database: ***PES***

Detail Licence No:
Licence No: 10711
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF URL:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 905
Oper Phone No: 8381026
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Site: ***GO VACATIONS CANADA INC***
HWY 7 BRAMPTON ON

Database: ***PRT***

Location ID: 1935
Type: retail
Expiry Date: 1991-01-31

Capacity (L): 1000
Licence #: 0023347001

Site: **WHITE'S GARAGE OF ALMA LTD**
MAIN ST ALMA ON

Database: PRT

Location ID: 838
Type: retail
Expiry Date: 1996-03-31
Capacity (L): 54560
Licence #: 0051634001

Site: **MARTIN AGRI DRAINAGE LTD**
LOT 20 CON 1 PEEL TWP ON

Database: PRT

Location ID: 11409
Type: private
Expiry Date:
Capacity (L): 9092.00
Licence #: 0001023784

Site: **CANADA BUILDING MAT'LS**
WEST SIDE HWY 10 CALEDON ON

Database: PRT

Location ID: 2544
Type: private
Expiry Date:
Capacity (L): 22730.00
Licence #: 0001055514

Site: **RO NO HAULAGE**
LOT 23 CON 1 CALEDON EAST ON

Database: PRT

Location ID: 2524
Type: private
Expiry Date:
Capacity (L): 13638.00
Licence #: 0001041513

Site: **Lafarge Canada Inc.**
ON

Database: PTTW

EBR Registry No: 011-5865
Ministry Ref No: 0883-8S4K4H
Notice Type: Instrument Decision
Notice Stage:
Notice Date: February 13, 2014
Proposal Date: March 05, 2012
Year: 2012
Instrument Type: (OWRA s. 34) - Permit to Take Water
Off Instrument Name:
Posted By:
Company Name: Lafarge Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: Concord Division, 7880 Keele Street, Concord Ontario, Canada L4K 4G7
Comment Period:
URL:
Summary:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

Petch Pit - Lot: 16, Concession: 2 WHS, Geographic Township of Caledon, Town of Caledon, Regional Municipality of Peel Presswood Pit - Lot: 17, Concession: 2, Geographic Township of Caledon, Town of Caledon, Regional Municipality of Peel CALEDON

Site: ***Wallenstein Feed and Supply***
Lot 18, Concession 1 PEEL ON

Database: ***PTTW***

EBR Registry No:	IA00E0028	***Decision Posted:***	
Ministry Ref No:	23008982	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:		***Act 1:***	
Notice Date:	March 05, 2001	***Act 2:***	
Proposal Date:	January 07, 2000	***Site Location Map:***	
Year:	2000		
Instrument Type:	(OWRA s. 34) - Permit to Take Water		
Off Instrument Name:			
Posted By:			
Company Name:	Wallenstein Feed and Supply		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	P.O. Box 22, Wallenstein Ontario, N0B 2S0		
Comment Period:			
URL:			
Summary:			

Site Location Details:

Lot 18, Concession 1 PEEL

Site: ***SHRI MAHA KALI AMMAA MANDIR HINDU ASSOCIATION***
0 Mayfield RD E City of Brampton ON

Database: ***RSC***

RSC No:	B-402-4255393165	***X:***	-79.75055555532991
RA No:		***Y:***	43.798055554917404
Status:	Active	***Latitude:***	43.79805556
Filing Date:		***Longitude:***	-79.75055556
Date Ack:		***UTM Coordinates:***	
Date Returned:		***Latitude Longitude:***	
Approval Date:	February 2, 2024	***Accuracy Estimate:***	
Cert Date:		***Measurement Method:***	
Cert Prop Use No:		***Mailing Address:***	
Curr Property Use:		***Telephone:***	
Intended Prop Use:		***Fax:***	
Restoration Type:		***Email:***	
Soil Type:		***Postal Code:***	L7C 0Z7
Criteria:		***Ministry District:***	
Stratified (Y/N):		***MOE District:***	Halton-Peel
Audit (Y/N):		***SWP Area Name:***	Toronto
Entire Leg Prop. (Y/N):		***Qual Person Name:***	Stephen Sears
CPU Issu Sect 1686:		***Consultant:***	
Business Name:	SHRI MAHA KALI AMMAA MANDIR HINDU ASSOCIATION		
Address:	0 Mayfield RD E		
Legal Desc:			
Site Pin:	14219-2550 (LT)		
Asmt Roll No:			
Project Type:	RSC based on Phase One ESA		
Approval Type:	RSC-RSC based on Phase One ESA		
Applicable Standards:			
PDF Link:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3299479		

Site: ***STARBRIGHT HOLDINGS INC.***
0 MAYFIELD ROAD ON Brampton ON

Database: ***RSC***

RSC No:	214669	***X:***	-79.79634554469904
RA No:		***Y:***	43.75404774355884
Status:	FILED	***Latitude:***	43.75404774
Filing Date:		***Longitude:***	-79.79634554
Date Ack:		***UTM Coordinates:***	
Date Returned:		***Latitude Longitude:***	
Approval Date:	October 15, 2014	***Accuracy Estimate:***	
Cert Date:		***Measurement Method:***	
Cert Prop Use No:		***Mailing Address:***	
Curr Property Use:		***Telephone:***	
Intended Prop Use:		***Fax:***	
Restoration Type:		***Email:***	
Soil Type:		***Postal Code:***	L6V 2K6
Criteria:		***Ministry District:***	
Stratified (Y/N):		***MOE District:***	Halton-Peel
Audit (Y/N):		***SWP Area Name:***	Toronto
Entire Leg Prop. (Y/N):		***Qual Person Name:***	SIMON LAN
CPU Issu Sect 1686:		***Consultant:***	
Business Name:	STARBRIGHT HOLDINGS INC.		
Address:	0 MAYFIELD ROAD ON		
Legal Desc:			
Site Pin:	14225-0055 (LT)		
Asmt Roll No:			
Project Type:	POST2011		
Approval Type:	RSC based on Phase One ESA		
Applicable Standards:			
PDF Link:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=214669		

Site: ***UPPER MAYFIELD ESTATES INC.***
0 MAYFIELD ROAD ON Brampton ON

Database: ***RSC***

RSC No:	237551	***X:***	-79.76204212062848
RA No:		***Y:***	43.787204437416634
Status:	FILED	***Latitude:***	43.78720444
Filing Date:		***Longitude:***	-79.76204212
Date Ack:		***UTM Coordinates:***	
Date Returned:		***Latitude Longitude:***	
Approval Date:	June 6, 2023	***Accuracy Estimate:***	
Cert Date:		***Measurement Method:***	
Cert Prop Use No:		***Mailing Address:***	
Curr Property Use:		***Telephone:***	
Intended Prop Use:		***Fax:***	
Restoration Type:		***Email:***	
Soil Type:		***Postal Code:***	L6R 0A8
Criteria:		***Ministry District:***	
Stratified (Y/N):		***MOE District:***	Halton-Peel
Audit (Y/N):		***SWP Area Name:***	Toronto
Entire Leg Prop. (Y/N):		***Qual Person Name:***	ELENI BEYENE
CPU Issu Sect 1686:		***Consultant:***	
Business Name:	UPPER MAYFIELD ESTATES INC.		
Address:	0 MAYFIELD ROAD ON		
Legal Desc:			
Site Pin:	14222-0374 (LT)		
Asmt Roll No:			
Project Type:	POST2011		
Approval Type:	RSC based on Phase One and Two ESAs		
Applicable Standards:			
PDF Link:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=237551		

Site: ***CALEDON 410 DEVELOPMENTS LIMITED***
0 MCLAUGHLIN ROAD ON Caledon ON

Database: ***RSC***

RSC No:	230128	***X:***	-79.8367137485776

RA No:		***Y:***	43.73817912403061
Status:	FILED	***Latitude:***	43.73817912
Filing Date:		***Longitude:***	-79.83671375
Date Ack:		***UTM Coordinates:***	
Date Returned:		***Latitude Longitude:***	
Approval Date:	January 11, 2022	***Accuracy Estimate:***	
Cert Date:		***Measurement Method:***	
Cert Prop Use No:		***Mailing Address:***	
Curr Property Use:		***Telephone:***	
Intended Prop Use:		***Fax:***	
Restoration Type:		***Email:***	
Soil Type:		***Postal Code:***	L7C 2C6
Criteria:		***Ministry District:***	
Stratified (Y/N):		***MOE District:***	Halton-Peel
Audit (Y/N):		***SWP Area Name:***	Toronto
Entire Leg Prop. (Y/N):		***Qual Person Name:***	DAVID MABLY
CPU Issu Sect 1686:		***Consultant:***	

Business Name: CALEDON 410 DEVELOPMENTS LIMITED
Address: 0 MCLAUGHLIN ROAD ON
Legal Desc:
Site Pin: 14252-0966 (LT), 14252-0967 (LT)
Asmt Roll No:
Project Type: POST2011
Approval Type: RSC based on Phase One and Two ESAs
Applicable Standards:
PDF Link: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=230128

Site: ***PETRO-CANADA***
BRAMPTON ON

Database: ***RST***

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 9054532849
List Name:
Description:

Site: ***UNITED AGGREGATES LTD***
HWY 10 CALEDON VILLAGE ON L0N 1C0

Database: ***SCT***

Established: 1970
Plant Size (ft²): 0
Employment: 30

--Details--
Description: MINERALS AND EARTHS, GROUND OR OTHERWISE TREATED
SIC/NAICS Code: 3295

Site: ***Classifier Milling Systems Corp.***
Caledon Village ON

Database: ***SCT***

Established: 1999
Plant Size (ft²):
Employment: 8

--Details--
Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

Site: ***BLUE CIRCLE AGGREGATES***
Hwy 10 Caledon Village ON L0N 1C0

Database: ***SCT***

Established: 1970
Plant Size (ft²): 0
Employment: 30

--Details--
Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Site: ***Caledon Sand & Gravel Inc.***
Hwy 10 Caledon Village ON L0N 1C0

Database: ***SCT***

Established: 01-JUL-55
Plant Size (ft²):
Employment:

--Details--
Description: Sand and Gravel Mining and Quarrying
SIC/NAICS Code: 212323

Description: Sand and Gravel Mining and Quarrying
SIC/NAICS Code: 212323

Site: ***Blue Circle Aggregates***
Hwy 10 Caledon Village ON L0N 1C0

Database: ***SCT***

Established: 1970
Plant Size (ft²):
Employment: 30

--Details--
Description: Sand and Gravel Mining and Quarrying
SIC/NAICS Code: 212323

Site:
on Highway 10 Caledon ON

Database: ***SPL***

Ref No: 2883-9NKMUK
Year:
Incident Dt: 2014/09/02
Dt MOE Arvl on Scn: 2014/09/02
MOE Reported Dt: 2014/09/02
Dt Document Closed:
Site No: NA
MOE Response: Priority Field Response (ERP Callout)
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: MVA<UNOFFICIAL>
Site Address: on Highway 10
Site Region:
Site Municipality: Caledon
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Client Name:
Client Type:
Source Type:
Incident Cause: Collision/Accident
Incident Preceding Spill:
Incident Reason: Unknown / N/A
Incident Summary: MVA: fatality fuel in ditch, water
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Truck - Transport/Hauling
SAC Action Class: Highway Spills (usually highway accidents)
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***Hydro One Brampton Networks Inc.***
98 Kingswood Brampton ON

Database: ***SPL***

Ref No: 7841-9MGR3G
Year:
Incident Dt: 2014/07/29
Dt MOE Arvl on Scn: 2014/08/01
MOE Reported Dt: 2014/07/29
Dt Document Closed: 2014/08/07
Site No: NA
MOE Response: Planned Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Hydro Transformer<UNOFFICIAL>
Site Address: 98 Kingswood
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Hydro One Brampton Networks Inc.
Client Type:
Source Type:
Incident Cause: Leak/Break
Incident Preceding Spill:
Incident Reason: Material Failure - Poor Design/Substandard Material
Incident Summary: Brampton Hydro oil spill.
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty: 200 L
Contaminant Qty 1: 200
Contaminant Unit: L

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Contaminant Code:	13
Contaminant Name:	MINERAL OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Transformer
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Site: ***Day & Ross Transport<UNOFFICIAL>***
Brampton ON

Database: ***SPL***

Ref No:	8081-9GPR8K	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2014/02/26	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2014/02/26	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	170 Van Kirk Drive<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Day & Ross Transport<UNOFFICIAL>		
Client Type:			
Source Type:			
Incident Cause:	Leak/Break		
Incident Preceding Spill:			
Incident Reason:	Operator/Human Error		
Incident Summary:	Day & Ross Transport: 520 L wastewater and resin to ground		
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Soil Contamination		
Contaminant Qty:	520 L		
Contaminant Qty 1:	520		
Contaminant Unit:	L		
Contaminant Code:	41		
Contaminant Name:	WASTEWATER N.O.S.		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Container/Drum/Tote		
SAC Action Class:	Land Spills		
Call Report Locatn Geodata:			
Time Reported:			

System Facility Address:

Site: ***Hydro One Brampton Networks Inc.***
Brampton ON

Database: ***SPL***

Ref No:	7214-8TYJ8Z	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	01-MAY-12	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	04-MAY-12	***Impact to Health:***	
Dt Document Closed:	31-MAY-12	***Agency Involved:***	
Site No:			

MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 11 Tobey Terrace<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Hydro One Brampton Networks Inc.
Client Type:
Source Type:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Incident Reason: Unknown - Reason not determined
Incident Summary: Hydro One-75 L X-former Oil to Grass/asphalt.
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code: 15
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transformer
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site:
Bovaird Dr Brampton ON

Database: ***SPL***

Ref No:	2305-8SNW56	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	23-MAR-12	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	23-MAR-12	***Impact to Health:***	
Dt Document Closed:	25-JUL-12	***Agency Involved:***	
Site No:			

MOE Response: Planned Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Fletchers Creek<UNOFFICIAL>
Site Address: Bovaird Dr
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: Unknown
Incident Preceding Spill:
Incident Reason:
Incident Summary: Sheen in Fletchers Creek
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code: 13
Contaminant Name: HYDROCARBON LIGHT
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Unknown
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***Canada Cartage Systems Limited***
Brampton ON

Database: ***SPL***

Ref No: 0401-8E4K3A
Year:
Incident Dt: 2/15/2011
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/15/2011
Dt Document Closed: 3/18/2011
Site No:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Airport Rd and Bovaird in intersection<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:

Northing:
Easting:
Entity Operating Name:
Client Name: Canada Cartage Systems Limited
Client Type:
Source Type:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Incident Reason: Spill
Incident Summary: TT and vehicle accident; 75 L to road
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 75 L
Contaminant Qty 1: 75
Contaminant Unit: L
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site:
Highway 10 Caledon ON

Database:
SPL

Ref No: 3563-8B95ZE
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/15/2010
Dt Document Closed: 11/19/2010
Site No:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Highway 10, 0.5km north of King<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: Other Discharges
Incident Preceding Spill:
Incident Reason: Other - Reason not otherwise defined
Incident Summary: MVA: Hwy 10, 40L of fluids to roadway
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s)

Contaminant Qty: 40 L
Contaminant Qty 1: 40
Contaminant Unit: L
Contaminant Code:
Contaminant Name: Operating Fluid
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Motor Vehicle
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***Andrews Trucking Limited***
N of Hwy 7 Brampton ON

Database: ***SPL***

Ref No: 4436-7UFKXU
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/30/2009
Dt Document Closed:
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Hwy 427<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Andrews Trucking Limited
Client Type:
Source Type:
Incident Cause: Unknown
Incident Preceding Spill:
Incident Reason: Unknown - Reason not determined
Incident Summary: Andrews Trucking Ltd: hydraulic oil to 427, N of 7
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code:
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

SAC Action Class: Primary Assessment of Incident
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***Daniel Contracting Ltd.***
Bovaird Dr Brampton ON

Database: ***SPL***

Ref No: 6635-7CLRRM
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/10/2008
Dt Document Closed: 4/14/2008
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: unknown<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Daniel Contracting Ltd.
Client Type:
Source Type:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Incident Reason: Damage By Moving Equipment - Containers damaged by moving
Incident Summary: Spill: MVA 20 - 50 L diesel, contained. Brampton
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty: 50 L
Contaminant Qty 1: 50
Contaminant Unit: L
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site: ***Southlake Blvd and Streamline Dr. <UNOFFICIAL>***
near Williams Pkwy Brampton ON

Database: ***SPL***

Ref No: 4465-6MRMHH
Year:
Incident Dt: 3/10/2006
Dt MOE Arvl on Scn:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:

MOE Reported Dt:	3/10/2006	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Southlake Blvd and Streamline Dr. <UNOFFICIAL>		
Site Address:	near Williams Pkwy		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	The Corporation of the City of Brampton		
Client Type:			
Source Type:	Other Motor Vehicle		
Incident Cause:			
Incident Preceding Spill:			
Incident Reason:			
Incident Summary:	Brampton: diesel in a stormwater pond		
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	Not Specfic Unknown		
Contaminant Qty 1:	Not Specfic		
Contaminant Unit:	Unknown		
Contaminant Code:	41		
Contaminant Name:	DIESEL FUEL AND WATER MIXTURE		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			

Site: ***Petro-Canada Gas Station<UNOFFICIAL>***
Brampton ON

Database: ***SPL***

Ref No:	5567-AEHLSE	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	10/7/2016	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	10/7/2016	***Impact to Health:***	
Dt Document Closed:	10/13/2016	***Agency Involved:***	
Site No:	NA		
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Private property - 354 Queen St. E. <UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Brampton		
Site Lot:			

Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Petro-Canada Gas Station<UNOFFICIAL>
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Unknown / N/A
Incident Summary: Region of Peel: watermain break; brown, murky water
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 41
Contaminant Name: WATER/SEDIMENT
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Municipal Sewage
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***Canadian Waste Services Inc.***
Orchid Drive (Hurontario & Sandelwood) Brampton ON

Database: ***SPL***

Ref No: 7646-5P6T6A
Year:
Incident Dt: 7/5/2003
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/5/2003
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: ORCHID DIVE CATCH BASIN<UNOFFICIAL>
Site Address:
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Canadian Waste Services Inc.
Client Type:
Source Type:
Incident Cause: Pipe Or Hose Leak
Incident Preceding Spill:
Incident Reason: Equipment Failure - Malfunction of system components
Incident Summary: Brampton: 35L Hydraulic oil spill to grnd/CatchB

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Oil
Impact to Health:
Agency Involved:

Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	Soil Contamination; Surface Water Pollution
Contaminant Qty:	35 L
Contaminant Qty 1:	
Contaminant Unit:	L
Contaminant Code:	15
Contaminant Name:	HYDRAULIC OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land & Water
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	Spill to Land
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Site: ***Day & Ross Inc.*** ***Database:*** ***SPL***
DAY & ROSS TRUCK - WESTBOUND LANE OF BOVAIRD ST, WEST OF KENNEDY<UNOFFICIAL> Brampton ON

Ref No:	8416-5YBLQE	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	4/23/2004	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	Oil
MOE Reported Dt:	4/23/2004	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	DAY & ROSS TRUCK - WESTBOUND LANE OF BOVAIRD ST, WEST OF KENNEDY<UNOFFICIAL>		
Site Address:			
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Day & Ross Inc.		
Client Type:			
Source Type:			
Incident Cause:	Other Discharges		
Incident Preceding Spill:			
Incident Reason:	Damage By Moving Equipment - Containers damaged by moving		
Incident Summary:	Day & Ross - 100 L diesel to ground		
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:	Soil Contamination		
Contaminant Qty:	100 L		
Contaminant Qty 1:			
Contaminant Unit:	L		
Contaminant Code:	13		
Contaminant Name:	DIESEL FUEL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Activity Preceding Spill:			

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Spill to Land
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***Brampton Transit<UNOFFICIAL>***
Brampton ON

Database: ***SPL***

Ref No: 8361-BG5KUC
Year:
Incident Dt: 9/18/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/18/2019
Dt Document Closed: 11/16/2019
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Northbound on Bramalea Road, just south of Sandalwood<UNOFFICIAL>
Site Address:
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: Brampton Transit<UNOFFICIAL>
Client Type:
Source Type: Motor Vehicle
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Material Failure - Poor Design/Substandard Material
Incident Summary: Brampton Transit: Unknown quantity of coolant to roadway
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 27
Contaminant Name: COOLANT (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Site: ***HARMAC TRANSPORTATION***
AT VULSAY PACKAGING ON REGAN ST. TANK TRUCK (CARGO) BRAMPTON CITY ON

Database: ***SPL***

Ref No: 136000
Municipality No: 21101

Year:		***Nature of Damage:***	
Incident Dt:	1/9/1997	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	1/9/1997	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Incident Reason: EQUIPMENT FAILURE
Incident Summary: HARMAC TRANSPORTATION - 200 L OF MOTOR OIL TO PAVEMENT DURING DELIVERY.
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:

Site: ***UNKNOWN***
MUNICIPAL PARK, KINGSWOOD DR (NEAR WILLIAMS PARKWAY) BRAMPTON CITY ON

Database: ***SPL***

Ref No:	179428	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	4/11/2000	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	4/11/2000	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	REGION OF PEEL

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:

Site Region:	
Site Municipality:	BRAMPTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	PIPE/HOSE LEAK
Incident Preceding Spill:	
Incident Reason:	OVERSTRESS/OVERPRESSURE
Incident Summary:	UKN SRCE-UKN QTY HYDR OILSPRAYED,PUDDLED,TO PARK- LANDS. REGION. CONTAINED.
Environment Impact:	CONFIRMED
Health Env Consequence:	
Nature of Impact:	Soil contamination
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	

Site: ***CANADIAN MINE DEVELOPMENT***
BRAMPTON ON

Database: ***SRDS***

Company Code:		***Sector:***	
Works ID:		***Region:***	
SIC:		***District:***	
SIC1:		***UTM Zone:***	
SIC1 Desc:		***UTM Easting:***	
SIC2:		***UTM Northing:***	
SIC2 Desc:		***UTM Precision:***	
SIC3:		***Minor Basin:***	
SIC3 Desc:		***Major Basin:***	
Body of Water:		***Report Year:***	1990-1994
Terminal Stream:			
SIC Desc:			
Mailing Address:			
Corp Address:			

Site:
Williams Pkwy lot 9 con 1 Brampton ON

Database: ***WWIS***

Well ID:	7432781	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	10/21/2022
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Y6QMNFSR	***Contractor:***	7472
Tag:	A360726	***Form Version:***	9

Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	009
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS E
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	BRAMPTON CITY (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	1009249991	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	598757.00
Code OB Desc:		***North83:***	4839422.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/05/2022	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1009250081
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	08
Material 1 Desc:	FINE SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.0
Formation End Depth:	10.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1009250082
Layer:	2
Color:	2
General Color:	GREY
Material 1:	06
Material 1 Desc:	SILT
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	10.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009250159
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009250160
Layer: 2
Plug From: 9.0
Plug To: 20.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009250143
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009250040
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1009250025
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009250101
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1009250116
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 20.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch

Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009250026
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1009250127
Diameter: 7.5
Depth From: 0.0
Depth To: 20.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Site:
con 2 ON

Database: ***WWIS***

Well ID: 4909343
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 54276
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CALEDON EAST)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 03/29/2004
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1129
Form Version: 2
Owner:
County: PEEL
Lot:
Concession: 02
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11099345
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/13/2002
Remarks:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932948639
Layer: 1
Color:
General Color:
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 1.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948640
Layer: 2
Color: 6
General Color: BROWN
Material 1: 08
Material 1 Desc: FINE SAND
Material 2: 91
Material 2 Desc: WATER-BEARING
Material 3:
Material 3 Desc:
Formation Top Depth: 1.0
Formation End Depth: 26.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948641
Layer: 3
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 91
Material 2 Desc: WATER-BEARING
Material 3:
Material 3 Desc:
Formation Top Depth: 26.0
Formation End Depth: 37.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948642
Layer: 4
Color: 6

General Color: BROWN
Material 1: 08
Material 1 Desc: FINE SAND
Material 2: 91
Material 2 Desc: WATER-BEARING
Material 3:
Material 3 Desc:
Formation Top Depth: 37.0
Formation End Depth: 60.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948643
Layer: 5
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 60.0
Formation End Depth: 81.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246766
Layer: 2
Plug From: 2.0
Plug To: 66.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246765
Layer: 1
Plug From: 0.0
Plug To: 2.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964909343
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 11103060
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930834959

Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 71.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933407295
Layer: 1
Slot: 010
Screen Top Depth: 71.0
Screen End Depth: 81.0
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 934044611
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 14.0
Water Found Depth UOM: ft

Site:
con 2 ON

Database: ***WWIS***

Well ID: 4909310
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 261890
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CALEDON TWP)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 01/19/2004
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1737
Form Version: 2
Owner:
County: PEEL
Lot:
Concession: 02
Concession Name: HS E
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11099328
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/15/2003
Remarks:
Location Method Desc: Not Applicable i.e. no UTM

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932948547
Layer: 2
Color: 6
General Color: BROWN
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 85
Material 3 Desc: SOFT
Formation Top Depth: 34.0
Formation End Depth: 55.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948550
Layer: 5
Color: 6
General Color: BROWN
Material 1: 08
Material 1 Desc: FINE SAND
Material 2: 06
Material 2 Desc: SILT
Material 3:
Material 3 Desc:
Formation Top Depth: 111.0
Formation End Depth: 135.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948549
Layer: 4
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 30
Material 2 Desc: MEDIUM GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 69.0
Formation End Depth: 111.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948546
Layer: 1
Color: 6
General Color: BROWN

Material 1: 05
Material 1 Desc: CLAY
Material 2: 08
Material 2 Desc: FINE SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 34.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948548
Layer: 3
Color: 6
General Color: BROWN
Material 1: 31
Material 1 Desc: COARSE GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 55.0
Formation End Depth: 69.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246729
Layer: 2
Plug From: 80.0
Plug To: 92.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246730
Layer: 3
Plug From: 92.0
Plug To: 135.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246728
Layer: 1
Plug From: 75.0
Plug To: 80.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964909310
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 11103043
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930834943
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 92.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933407281
Layer: 1
Slot: 010
Screen Top Depth: 92.0
Screen End Depth: 112.0
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 934044599
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 112.0
Water Found Depth UOM: ft

Site:
con 2 ON

Database: ***WWIS***

Well ID: 4909308
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 261886
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CALEDON TWP)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 01/19/2004
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1737
Form Version: 2
Owner:
County: PEEL
Lot:
Concession: 02
Concession Name: HS E
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11099326
Elevation:

DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	09/09/2003	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Method of Construction & Well Use

Method Construction ID:	964909308
Method Construction Code:	5
Method Construction:	Air Percussion
Other Method Construction:	

Pipe Information

Pipe ID:	11103041
Casing No:	1
Comment:	
Alt Name:	

Site:
con 2 ON

Database: ***WWIS***

Well ID:	4909307	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Not Used	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Observation Wells	***Date Received:***	01/19/2004
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	261887	***Contractor:***	1737
Tag:		***Form Version:***	2
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	02
Well Depth:		***Concession Name:***	HS E
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CALEDON TWP)		
Site Info:			

Bore Hole Information

Bore Hole ID:	11099325	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	09/09/2003	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na

Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932948541
Layer: 2
Color: 6
General Color: BROWN
Material 1: 31
Material 1 Desc: COARSE GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 44.0
Formation End Depth: 86.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948542
Layer: 3
Color: 2
General Color: GREY
Material 1: 34
Material 1 Desc: TILL
Material 2: 73
Material 2 Desc: HARD
Material 3:
Material 3 Desc:
Formation Top Depth: 86.0
Formation End Depth: 90.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948540
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 31
Material 2 Desc: COARSE GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 44.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246722
Layer: 1
Plug From: 0.0

Plug To: 20.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246723
Layer: 2
Plug From: 20.0
Plug To: 30.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246724
Layer: 3
Plug From: 30.0
Plug To: 38.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964909307
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 11103040
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930834941
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 46.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933407279
Layer: 1
Slot: 010
Screen Top Depth: 46.0
Screen End Depth: 56.0
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 934044597

Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	56.0
Water Found Depth UOM:	ft

Site:
con 2 ON

Database:
WWIS

Well ID:	4909306	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Not Used	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Observation Wells	***Date Received:***	01/19/2004
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	261888	***Contractor:***	1737
Tag:		***Form Version:***	2
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	02
Well Depth:		***Concession Name:***	HS E
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CALEDON TWP)		
Site Info:			

Bore Hole Information

Bore Hole ID:	11099324	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	09/11/2003	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932948535
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	85
Material 3 Desc:	SOFT
Formation Top Depth:	0.0
Formation End Depth:	65.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932948538
Layer:	4
Color:	6
General Color:	BROWN
Material 1:	31
Material 1 Desc:	COARSE GRAVEL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	96.0
Formation End Depth:	104.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932948539
Layer:	5
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	85
Material 2 Desc:	SOFT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	104.0
Formation End Depth:	107.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932948536
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	34
Material 1 Desc:	TILL
Material 2:	73
Material 2 Desc:	HARD
Material 3:	
Material 3 Desc:	
Formation Top Depth:	65.0
Formation End Depth:	77.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932948537
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	08
Material 1 Desc:	FINE SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	77.0
Formation End Depth:	96.0

Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246719
Layer: 1
Plug From: 0.0
Plug To: 20.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246721
Layer: 3
Plug From: 40.0
Plug To: 68.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246720
Layer: 2
Plug From: 20.0
Plug To: 40.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964909306
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 11103039
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930834940
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 58.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933407278
Layer: 1
Slot: 010
Screen Top Depth: 58.0
Screen End Depth: 68.0

Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Water Details

Water ID: 934044596
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 68.0
Water Found Depth UOM: ft

Site:
con 2 ON

Database: ***WWIS***

Well ID: 4909305
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 261889
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (CALEDON TWP)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 01/19/2004
Selected Flag: TRUE
Abandonment Rec:
Contractor: 1737
Form Version: 2
Owner:
County: PEEL
Lot:
Concession: 02
Concession Name: HS E
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11099323
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/12/2003
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 932948533
Layer: 3
Color: 6
General Color: BROWN
Material 1: 31
Material 1 Desc: COARSE GRAVEL

Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 97.0
Formation End Depth: 110.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948532
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 73
Material 2 Desc: HARD
Material 3:
Material 3 Desc:
Formation Top Depth: 81.0
Formation End Depth: 97.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948531
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 31
Material 2 Desc: COARSE GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 81.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932948534
Layer: 4
Color: 6
General Color: BROWN
Material 1: 34
Material 1 Desc: TILL
Material 2: 05
Material 2 Desc: CLAY
Material 3: 73
Material 3 Desc: HARD
Formation Top Depth: 110.0
Formation End Depth: 135.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246718
Layer: 3
Plug From: 50.0

Plug To: 88.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246717
Layer: 2
Plug From: 20.0
Plug To: 50.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933246716
Layer: 1
Plug From: 0.0
Plug To: 20.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964909305
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 11103038
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930834939
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 68.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933407277
Layer: 1
Slot: 010
Screen Top Depth: 68.0
Screen End Depth: 88.0
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.0

Site:
con 1 ON

Database:
WWIS

Well ID:	4909295	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Not Used	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Abandoned-Other	***Date Received:***	12/31/2003
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	262196	***Contractor:***	3108
Tag:		***Form Version:***	2
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	11099316	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	11/07/2003	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Method of Construction & Well Use

Method Construction ID:	964909295
Method Construction Code:	0
Method Construction:	Not Known
Other Method Construction:	

Pipe Information

Pipe ID:	11103031
Casing No:	1
Comment:	
Alt Name:	

Site: ***Database:*** ***WWIS***

con 1 ON

Well ID:	4908763	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Abandoned-Other	***Date Received:***	06/13/2001
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	229044	***Contractor:***	4011

Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (ALBION)
Site Info:

Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10323297
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/24/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 933171354
Layer: 3
Plug From: 3.0
Plug To: 4.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171353
Layer: 2
Plug From: 2.0
Plug To: 3.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171352
Layer: 1
Plug From: 0.0
Plug To: 2.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908763
Method Construction Code: 0
Method Construction: Not Known

Other Method Construction:

Pipe Information

Pipe ID: 10871867
Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database: ***WWIS***

Well ID: 4908762
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 229045
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (ALBION)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 06/13/2001
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4011
Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10323296
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/24/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 933171351
Layer: 3
Plug From: 4.0
Plug To: 6.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171350

Layer: 2
Plug From: 1.0
Plug To: 4.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171349
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908762
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871866
Casing No: 1
Comment:
Alt Name:

Site: ***Database:*** ***WWIS***

con 1 ON

Well ID: 4908761
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 229034
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (ALBION)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 06/13/2001
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4011
Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10323295
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/24/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 933171346
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171347
Layer: 2
Plug From: 1.0
Plug To: 6.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171348
Layer: 3
Plug From: 6.0
Plug To: 7.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908761
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871865
Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database: ***WWIS***

Well ID: 4908760
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 229066
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 06/13/2001
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4011
Form Version: 1
Owner:
County: PEEL
Lot:

Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (ALBION)
Site Info:

Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10323294
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/24/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 933171343
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171344
Layer: 2
Plug From: 1.0
Plug To: 6.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171345
Layer: 3
Plug From: 6.0
Plug To: 7.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908760
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871864
Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database:
WWIS

Well ID: 4908759
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 229067
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (ALBION)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 06/13/2001
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4011
Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10323293
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/24/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 933171342
Layer: 3
Plug From: 4.0
Plug To: 5.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171340
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID:	933171341
Layer:	2
Plug From:	1.0
Plug To:	4.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964908759
Method Construction Code:	0
Method Construction:	Not Known
Other Method Construction:	

Pipe Information

Pipe ID:	10871863
Casing No:	1
Comment:	
Alt Name:	

Site:
con 1 ON

Database: ***WWIS***

Well ID:	4908758	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Abandoned-Other	***Date Received:***	06/13/2001
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	229035	***Contractor:***	4011
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	CON
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (ALBION)		
Site Info:			

Bore Hole Information

Bore Hole ID:	10323292	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	04/24/2001	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			

Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 933171339
Layer: 3
Plug From: 4.0
Plug To: 48.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171337
Layer: 1
Plug From: 0.0
Plug To: 3.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171338
Layer: 2
Plug From: 3.0
Plug To: 4.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908758
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871862
Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database: ***WWIS***

Well ID: 4908757
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 229077
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 06/13/2001
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4011
Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:

Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (ALBION)
Site Info:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10323291
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/24/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 933171336
Layer: 3
Plug From: 102.0
Plug To: 116.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171334
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171335
Layer: 2
Plug From: 1.0
Plug To: 102.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908757
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871861
Casing No: 1
Comment:

Alt Name:

Site:
con 1 ON

Database:
WWIS

Well ID:	4908756	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Abandoned-Other	***Date Received:***	06/13/2001
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	229076	***Contractor:***	4011
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	CON
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (ALBION)		
Site Info:			

Bore Hole Information

Bore Hole ID:	10323290	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	04/24/2001	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	933171333
Layer:	3
Plug From:	4.0
Plug To:	89.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933171331
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171332
Layer: 2
Plug From: 1.0
Plug To: 4.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908756
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871860
Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database: ***WWIS***

Well ID: 4908755
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 229056
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (ALBION)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 06/13/2001
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4011
Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10323289
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/24/2001
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Annular Space/Abandonment Sealing Record

Plug ID: 933171330
Layer: 3
Plug From: 2.0
Plug To: 3.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171329
Layer: 2
Plug From: 1.0
Plug To: 2.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933171328
Layer: 1
Plug From: 0.0
Plug To: 1.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964908755
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871859
Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database: ***WWIS***

Well ID: 4908754
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 229062
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: CALEDON TOWN (ALBION)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 06/13/2001
Selected Flag: TRUE
Abandonment Rec:
Contractor: 4011
Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	10323288	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	04/24/2001	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	933171326
Layer:	2
Plug From:	0.0
Plug To:	2.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933171327
Layer:	3
Plug From:	2.0
Plug To:	3.0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933171325
Layer:	1
Plug From:	0.0
Plug To:	0.0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964908754
Method Construction Code:	0
Method Construction:	Not Known
Other Method Construction:	

Pipe Information

Pipe ID:	10871858
Casing No:	1
Comment:	
Alt Name:	

Site: ***Database:*** ***WWIS***

con 2 ON

Well ID:	4907354	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	08/10/1990
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	77155	***Contractor:***	4919
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	02
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CHINGUACOUSY)		
Site Info:			

Bore Hole Information

Bore Hole ID:	10321913	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	04/28/1990	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932058080
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	28
Material 2 Desc:	SAND
Material 3:	79
Material 3 Desc:	PACKED
Formation Top Depth:	1.0
Formation End Depth:	20.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932058081
Layer:	3
Color:	2
General Color:	GREY

Material 1: 05
Material 1 Desc: CLAY
Material 2: 73
Material 2 Desc: HARD
Material 3:
Material 3 Desc:
Formation Top Depth: 20.0
Formation End Depth: 60.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932058079
Layer: 1
Color: 6
General Color: BROWN
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2: 73
Material 2 Desc: HARD
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 1.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964907354
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10870483
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930531126
Layer: 1
Material: 2
Open Hole or Material: GALVANIZED
Depth From:
Depth To: 60.0
Casing Diameter: 30.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: BAILER
Pump Test ID: 994907354
Pump Set At:
Static Level: 20.0
Final Level After Pumping: 40.0
Recommended Pump Depth: 55.0
Pumping Rate: 10.0
Flowing Rate:
Recommended Pump Rate: 3.0

Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 2
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934257008
Test Type: Recovery
Test Duration: 15
Test Level: 38.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934531121
Test Type: Recovery
Test Duration: 30
Test Level: 36.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935050704
Test Type: Recovery
Test Duration: 60
Test Level: 32.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934785197
Test Type: Recovery
Test Duration: 45
Test Level: 34.0
Test Level UOM: ft

Water Details

Water ID: 933795450
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 20.0
Water Found Depth UOM: ft

Site:
con 2 ON

Database: ***WWIS***

Well ID: 4907112
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No: 55832
Tag:
Constructn Method:
Elevation (m):

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 06/27/1989
Selected Flag: TRUE
Abandonment Rec:
Contractor: 2576
Form Version: 1
Owner:
County: PEEL

Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	02
Well Depth:		***Concession Name:***	HS W
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	CALEDON TOWN (CALEDON TWP)		
Site Info:			

Bore Hole Information

Bore Hole ID:	10321673	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	06/05/1989	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932056838
Layer:	7
Color:	7
General Color:	RED
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	110.0
Formation End Depth:	120.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932056835
Layer:	4
Color:	2
General Color:	GREY
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	55.0
Formation End Depth:	89.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID: 932056839
Layer: 8
Color: 3
General Color: BLUE
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 120.0
Formation End Depth: 142.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932056836
Layer: 5
Color: 3
General Color: BLUE
Material 1: 15
Material 1 Desc: LIMESTONE
Material 2: 17
Material 2 Desc: SHALE
Material 3: 74
Material 3 Desc: LAYERED
Formation Top Depth: 89.0
Formation End Depth: 102.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932056837
Layer: 6
Color: 3
General Color: BLUE
Material 1: 17
Material 1 Desc: SHALE
Material 2: 85
Material 2 Desc: SOFT
Material 3:
Material 3 Desc:
Formation Top Depth: 102.0
Formation End Depth: 110.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932056832
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 05
Material 2 Desc: CLAY
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	932056833
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	12
Material 3 Desc:	STONES
Formation Top Depth:	5.0
Formation End Depth:	24.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932056840
Layer:	9
Color:	6
General Color:	BROWN
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	17
Material 2 Desc:	SHALE
Material 3:	
Material 3 Desc:	
Formation Top Depth:	142.0
Formation End Depth:	148.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932056834
Layer:	3
Color:	2
General Color:	GREY
Material 1:	11
Material 1 Desc:	GRAVEL
Material 2:	28
Material 2 Desc:	SAND
Material 3:	
Material 3 Desc:	
Formation Top Depth:	24.0
Formation End Depth:	55.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932056841
Layer:	10
Color:	2
General Color:	GREY
Material 1:	15
Material 1 Desc:	LIMESTONE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	148.0

Formation End Depth: 160.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964907112
Method Construction Code: 4
Method Construction: Rotary (Air)
Other Method Construction:

Pipe Information

Pipe ID: 10870243
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930530754
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 56.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930530755
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 160.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 994907112
Pump Set At:
Static Level: 38.0
Final Level After Pumping:
Recommended Pump Depth: 120.0
Pumping Rate: 12.0
Flowing Rate:
Recommended Pump Rate: 10.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934784608
Test Type: Recovery
Test Duration: 45
Test Level: 80.0
Test Level UOM: ft

Water Details

Water ID: 933795164
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 50.0
Water Found Depth UOM: ft

Water Details

Water ID: 933795165
Layer: 2
Kind Code: 5
Kind: Not stated
Water Found Depth: 85.0
Water Found Depth UOM: ft

Water Details

Water ID: 933795167
Layer: 4
Kind Code: 5
Kind: Not stated
Water Found Depth: 155.0
Water Found Depth UOM: ft

Water Details

Water ID: 933795166
Layer: 3
Kind Code: 5
Kind: Not stated
Water Found Depth: 130.0
Water Found Depth UOM: ft

Site:
lot 14 ON

Database: ***WWIS***

Well ID: 4904642
Construction Date:
Use 1st: Livestock
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: PEEL TOWNSHIP
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 05/21/1975
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3406
Form Version: 1
Owner:
County: WELLINGTON
Lot: 014
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	10319423	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	03/27/1975	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932046575
Layer:	2
Color:	3
General Color:	BLUE
Material 1:	17
Material 1 Desc:	SHALE
Material 2:	15
Material 2 Desc:	LIMESTONE
Material 3:	
Material 3 Desc:	
Formation Top Depth:	15.0
Formation End Depth:	56.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932046574
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964904642
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	10867993

Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930527303
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 56.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 994904642
Pump Set At:
Static Level: 28.0
Final Level After Pumping: 47.0
Recommended Pump Depth: 49.0
Pumping Rate: 6.0
Flowing Rate:
Recommended Pump Rate: 5.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 24
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934533763
Test Type:
Test Duration: 30
Test Level: 28.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935044479
Test Type:
Test Duration: 60
Test Level: 28.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934259651
Test Type:
Test Duration: 15
Test Level: 28.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934779532
Test Type:

Test Duration: 45
Test Level: 28.0
Test Level UOM: ft

Water Details

Water ID: 933792672
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 56.0
Water Found Depth UOM: ft

Site:
lot 7 ON

Database:
WWIS

Well ID: 2806796
Construction Date:
Use 1st: Domestic
Use 2nd:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No: NA
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY (TORONTO GORE)
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 11/12/1987
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3637
Form Version: 1
Owner:
County: PEEL
Lot: 007
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10153062
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/20/1985
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931444367
Layer: 3
Color: 2
General Color: GREY
Material 1: 17
Material 1 Desc: SHALE
Material 2: 73

Material 2 Desc: HARD
Material 3: 90
Material 3 Desc: VERY
Formation Top Depth: 31.0
Formation End Depth: 36.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931444366
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 1.0
Formation End Depth: 31.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931444365
Layer: 1
Color: 6
General Color: BROWN
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 1.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 962806796
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10701632
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930260306
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 36.0
Casing Diameter: 24.0

Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930260305
Layer: 1
Material: 3
Open Hole or Material: CONCRETE
Depth From:
Depth To: 32.0
Casing Diameter: 30.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: BAILER
Pump Test ID: 992806796
Pump Set At:
Static Level: 23.0
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate: 5.0
Flowing Rate:
Recommended Pump Rate: 3.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 2
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934450809
Test Type: Draw Down
Test Duration: 30
Test Level: 32.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934709966
Test Type: Draw Down
Test Duration: 45
Test Level: 33.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934970938
Test Type: Draw Down
Test Duration: 60
Test Level: 34.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934176764
Test Type: Draw Down
Test Duration: 15

Test Level: 28.0
Test Level UOM: ft

Water Details

Water ID: 933610187
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 34.0
Water Found Depth UOM: ft

Site:
Vodden St. E. lot 7 con 1 Brampton ON

Database:
WWIS

Well ID: 7443713
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: CZTHQZ4L
Tag: A375992
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/18/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7472
Form Version: 9
Owner:
County: PEEL
Lot: 007
Concession: 01
Concession Name: HS E
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1009380532
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/03/2023
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 599188.00
North83: 4838522.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1009380732
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:

Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009380733
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 5.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009380902
Layer: 2
Plug From: 9.0
Plug To: 15.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009380901
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009380859
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009380629
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1009380596
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1009380767
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.0
Depth To:	10.0
Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1009380796
Layer:	1
Slot:	10
Screen Top Depth:	10.0
Screen End Depth:	15.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.5

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1009380597
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1009380828
Diameter:	7.5
Depth From:	0.0
Depth To:	15.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Site:
lot 18 ON

Database:
WWIS

Well ID:	6714474	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Domestic	***Data Entry Status:***	
Use 2nd:		***Data Src:***	1
Final Well Status:	Water Supply	***Date Received:***	06/20/2003
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	257922	***Contractor:***	2663

Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: PEEL TOWNSHIP
Site Info:

Form Version: 1
Owner:
County: WELLINGTON
Lot: 018
Concession:
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10542319
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/10/2003
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 932922171
Layer: 6
Color:
General Color:
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 190.0
Formation End Depth: 195.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932922167
Layer: 2
Color: 6
General Color: BROWN
Material 1: 05
Material 1 Desc: CLAY
Material 2: 14
Material 2 Desc: HARDPAN
Material 3:
Material 3 Desc:
Formation Top Depth: 2.0
Formation End Depth: 68.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	932922170
Layer:	5
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	183.0
Formation End Depth:	190.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932922168
Layer:	3
Color:	6
General Color:	BROWN
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	12
Material 2 Desc:	STONES
Material 3:	14
Material 3 Desc:	HARDPAN
Formation Top Depth:	68.0
Formation End Depth:	145.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932922166
Layer:	1
Color:	8
General Color:	BLACK
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	2.0
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932922169
Layer:	4
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	05
Material 2 Desc:	CLAY
Material 3:	
Material 3 Desc:	
Formation Top Depth:	145.0

Formation End Depth: 183.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933240232
Layer: 1
Plug From: 0.0
Plug To: 20.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 966714474
Method Construction Code: 4
Method Construction: Rotary (Air)
Other Method Construction:

Pipe Information

Pipe ID: 11090889
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930779174
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 195.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 996714474
Pump Set At:
Static Level: 50.0
Final Level After Pumping: 54.0
Recommended Pump Depth: 120.0
Pumping Rate: 16.0
Flowing Rate:
Recommended Pump Rate: 16.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934350768
Test Type: Draw Down
Test Duration: 15

Test Level: 54.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934614215
Test Type: Draw Down
Test Duration: 30
Test Level: 54.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934875227
Test Type: Draw Down
Test Duration: 45
Test Level: 54.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935136286
Test Type: Draw Down
Test Duration: 60
Test Level: 54.0
Test Level UOM: ft

Water Details

Water ID: 934036121
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 195.0
Water Found Depth UOM: ft

Site:
Vodden St. E. lot 7 con 1 Brampton ON

Database: ***WWIS***

Well ID: 7443714
Construction Date:
Use 1st: Monitoring
Use 2nd:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 52AGEVGL
Tag: A375994
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: BRAMPTON CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 04/18/2023
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7472
Form Version: 9
Owner:
County: PEEL
Lot: 007
Concession: 01
Concession Name: HS E
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1009380535
DP2BR:

Elevation:
Elevrc:

Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 04/03/2023
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Zone: 17
East83: 599287.00
North83: 4838647.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1009380735
Layer: 2
Color: 2
General Color: GREY
Material 1: 05
Material 1 Desc: CLAY
Material 2: 06
Material 2 Desc: SILT
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 5.0
Formation End Depth: 15.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1009380734
Layer: 1
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 0.0
Formation End Depth: 5.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009380903
Layer: 1
Plug From: 0.0
Plug To: 9.0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009380904
Layer: 2
Plug From: 9.0
Plug To: 15.0

Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1009380860
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1009380630
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1009380598
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1009380768
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 10.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1009380797
Layer: 1
Slot: 10
Screen Top Depth: 10.0
Screen End Depth: 15.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.5

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009380599
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:

Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1009380829
Diameter:	7.5
Depth From:	0.0
Depth To:	15.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Nov 2024

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Apr 2024

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Apr 30, 2025

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2023

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Apr 30, 2025

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Apr 2025

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Apr 2025

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - May 31, 2025

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database (ODHD) is offered by the Province of Ontario's Ministry of Mines. The dataset contains information for over 164,000 percussion, overburden, sonic and diamond-drill holes. The presence of assay results with cutoff values for gold, silver, copper, zinc, lead, nickel and platinum group elements is noted. Drill hole data are compiled from assessment files that have been submitted to the ministry in accordance with the Ontario Mining Act (OMA). Source assessment file numbers are captured for cross reference with the Ontario Assessment File Database (OAFD). Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Aug 2024

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011 - May 31, 2025

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - May 31, 2025

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011 - May 31, 2025

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Aug 31, 2024

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment, Conservation and Parks (MECP). These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2024

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Jan 2025

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: Oct 31, 2021

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. As of January 1, 2023, businesses and institutions subject to the amended Reg. 347: General – Waste Management are required to report their activities and pay fees through Resource Productivity & Recovery Authority (RPRA) online Hazardous Waste Program Registry (HWPR) rather than the Hazardous Waste Information Network (HWIN) system previously operated by the Ministry of the Environment, Conservation and Parks (MECP). Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Dec 31, 2024

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Apr 2024

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: 31 Oct, 2023

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2025

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment Conservation and Parks (MECP) provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act. MECP publicly releases the Environmental Compliance Report (ECR) on the Ontario Data Catalogue. In Ontario, all facilities with regulated wastewater discharges or air emissions under the Ontario Water Resources Act and the Environmental Protection Act must monitor and report any cases where approved operating limits have been exceeded.

Government Publication Date: Dec 31, 2023

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-May 31, 2025

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Feb 2024

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Feb 28, 2025

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the Ministry of Natural Resources (MNR) handed over to the Ontario Oil, Gas and Salt Resources (OGSR) Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database includes well owner/operator, location, permit issue date, and well cap date, license number, status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provided for each well record.

Government Publication Date: 1800-Aug 2024

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - May 31, 2025

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011 - May 31, 2025

Ontario PFAS Spills: Provincial PFAS

This specific list of spills includes those incidents where one or more of the listed contaminants are identified in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA), is originally sourced from the Ministry of the Environment, Conservation and Parks spills related data. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Jun 2024; Aug 2024; Oct-Nov 2024

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Feb 2024

Potential PFAS Handlers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Feb 2024

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Potential PFAS Handlers from EASR: Provincial PPHA

The Ontario Environmental Activity and Sector Registry (EASR), described in Ontario Regulation 245/11, allows businesses with less complex operations - and hence not requiring an Environmental Compliance Approval - to register their activities with the Ontario Ministry of the Environment, Conservation and Parks (MECP). This list of potential PFAS handlers includes those EASR facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used.

Government Publication Date: Jun 30, 2024

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - May 31, 2025

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004-May 2025

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Apr 30, 2025

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Jun 2024; Aug-Mar 2025

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2021

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2024

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011 - May 31, 2025

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Dec 31 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

ERIS

DATABASE REPORT

Project Property:	*Bovaird HEIP* *Bovaird* *Brampton ON*
Project No:	*P24-6347*
Report Type:	*Quote - Custom-Build Your Own Report*
Order No:	*24062700012*
Requested by:	*EnVision Consultants Ltd.*
Date Completed:	*July 23, 2024*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....19
Map.....33
Aerial.....34
Topographic Map.....35
Detail Report.....36
Unplottable Summary.....101
Unplottable Report.....102
Appendix: Database Descriptions.....107
Definitions.....117

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*Bovaird HEIP* *Bovaird Brampton ON*
Project No:	*P24-6347*

Order Information:

Order No:	*24062700012*
Date Requested:	*June 27, 2024*
Requested by:	*EnVision Consultants Ltd.*
Report Type:	*Quote - Custom-Build Your Own Report*

Historical/Products:

ERIS Xplorer	*ERIS Xplorer*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
AAGR	Abandoned Aggregate Inventory	N	-	-	-
AGR	Aggregate Inventory	N	-	-	-
AMIS	Abandoned Mine Information System	N	-	-	-
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	N	-	-	-
CA	Certificates of Approval	N	-	-	-
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	N	-	-	-
CNG	Compressed Natural Gas Stations	N	-	-	-
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	N	-	-	-
CONV	Compliance and Convictions	N	-	-	-
CPU	Certificates of Property Use	N	-	-	-
DRL	Drill Hole Database	N	-	-	-
DTNK	Delisted Fuel Tanks	Y	0	8	8
EASR	Environmental Activity and Sector Registry	N	-	-	-
EBR	Environmental Registry	N	-	-	-
ECA	Environmental Compliance Approval	N	-	-	-
EEM	Environmental Effects Monitoring	N	-	-	-
EHS	ERIS Historical Searches	N	-	-	-
EIIS	Environmental Issues Inventory System	N	-	-	-
EMHE	Emergency Management Historical Event	N	-	-	-
EPAR	Environmental Penalty Annual Report	N	-	-	-
EXP	List of Expired Fuels Safety Facilities	Y	0	4	4
FCON	Federal Convictions	N	-	-	-
FCS	Contaminated Sites on Federal Land	N	-	-	-
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	N	-	-	-
FST	Fuel Storage Tank	Y	0	22	22
FSTH	Fuel Storage Tank - Historic	Y	0	10	10
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	78	78
GHG	Greenhouse Gas Emissions from Large Facilities	N	-	-	-
HINC	TSSA Historic Incidents	N	-	-	-

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	1	1
LIMO	Landfill Inventory Management Ontario	N	-	-	-
MINE	Canadian Mine Locations	N	-	-	-
MNR	Mineral Occurrences	N	-	-	-
NATE	National Analysis of Trends in Emergencies System (NATES)	N	-	-	-
NCPL	Non-Compliance Reports	N	-	-	-
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	N	-	-	-
NDWD	National Defence & Canadian Forces Waste Disposal Sites	N	-	-	-
NEBI	National Energy Board Pipeline Incidents	N	-	-	-
NEBP	National Energy Board Wells	N	-	-	-
NEES	National Environmental Emergencies System (NEES)	N	-	-	-
NPCB	National PCB Inventory	Y	0	0	0
NPR2	National Pollutant Release Inventory 1993-2020	N	-	-	-
NPRI	National Pollutant Release Inventory - Historic	N	-	-	-
OGWE	Oil and Gas Wells	N	-	-	-
OOGW	Ontario Oil and Gas Wells	N	-	-	-
OPCB	Inventory of PCB Storage Sites	N	-	-	-
ORD	Orders	N	-	-	-
PAP	Canadian Pulp and Paper	N	-	-	-
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	N	-	-	-
PFCH	NPRI Reporters - PFAS Substances	N	-	-	-
PFHA	Potential PFAS Handlers from NPRI	N	-	-	-
PINC	Pipeline Incidents	N	-	-	-
PRT	Private and Retail Fuel Storage Tanks	N	-	-	-
PTTW	Permit to Take Water	N	-	-	-
REC	Ontario Regulation 347 Waste Receivers Summary	N	-	-	-
RSC	Record of Site Condition	N	-	-	-
RST	Retail Fuel Storage Tanks	Y	0	9	9
SCT	Scott's Manufacturing Directory	Y	0	5	5
SPL	Ontario Spills	N	-	-	-
SRDS	Wastewater Discharger Registration Database	N	-	-	-
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	N	-	-	-
WDS	Waste Disposal Sites - MOE CA Inventory	N	-	-	-
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	N	-	-	-
WWIS	Water Well Information System	N	-	-	-

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
Total:			0	137	137

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number

No records found in the selected databases for the project property.

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	GEN	Attrell Toyota	110 Canam Drive Brampton ON L7A 2A9	N/50.6	0.82	36
2	GEN	Chrysler Group LLC	190 Canam Crescent Brampton ON	WSW/48.7	2.01	36
3	GEN	1737126 Ont Inc.	100 Manett Cres. Brampton ON L6X 4X4	ENE/98.3	-0.97	36
4	FSTH	CANADIAN TIRE CORP LTD **	10031 MCLAUGHLIN RD BRAMPTON ON L7A 2X5	SW/47.7	-1.15	37
4	FSTH	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr	10031 MCLAUGHLIN RD BRAMPTON ON L7A 2X5	SW/47.7	-1.15	37
4	GEN	Canadian Tire #675	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	38
4	GEN	K.R. Estey Holdings Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	39
4	GEN	K.R. Estey Holdings Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	39
4	GEN	K.R. Estey Holdings Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	40
4	FST	CANADIAN TIRE CORPORATION LIMITED	10031 MCLAUGHLIN RD BRAMPTON ON	SW/47.7	-1.15	41
4	FST	CANADIAN TIRE CORPORATION LIMITED	10031 MCLAUGHLIN RD BRAMPTON ON	SW/47.7	-1.15	42
4	FST	CANADIAN TIRE CORPORATION LIMITED	10031 MCLAUGHLIN RD BRAMPTON ON	SW/47.7	-1.15	42

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
4	GEN	K.R. Estey Holdings Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	42
4	GEN	Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON	SW/47.7	-1.15	43
4	GEN	Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	44
4	GEN	Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	45
4	GEN	Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	46
4	GEN	Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	47
4	GEN	Melrose Paving Co. Ltd.	10031 Mclaughlin Road North Brampton ON L7A 2X5	SW/47.7	-1.15	48
4	GEN	Kevin Shay Sales Limited	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	48
4	GEN	Canadian Tire Real Estate Limited	10031 McLaughlin Road Brampton ON L7A 2X5	SW/47.7	-1.15	49
4	GEN	Kevin Shay Sales Limited	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	49
4	GEN	7739524 CANADA LIMITED	10031 mclaughlin rd. brampton ON L7A 2X5	SW/47.7	-1.15	50
4	FST	CANADIAN TIRE CORPORATION LIMITED	10031 MCLAUGHLIN RD BRAMPTON ON	SW/47.7	-1.15	50
5	SCT	Brampton Sheet Metal Ltd.	180 Hwy 7 W Brampton ON L6V 1A1	NE/85.3	3.95	51

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
5	SCT	Lumber Land North Inc.	180 HWY 7 W Brampton ON L7A 1A1	NE/85.3	3.95	51
5	SCT	Lumber Land North Inc.	180 Highway 7 W RR 2 Brampton ON L6V 1A1	NE/85.3	3.95	51
5	GEN	PRODUCT MANAGEMENT Corporatio	180 Bovaird Drive West Rear Building, Unit B Brampton ON L6V 1A1	NE/85.3	3.95	52
5	SCT	Lumber Land North Inc.	ON	NE/85.3	3.95	52
5	SCT	Lumber Land North Inc.	180 Bovaird Dr W Brampton ON L7A 0H3	NE/85.3	3.95	52
6	GEN	Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	NE/82.0	4.31	53
6	GEN	Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	NE/82.0	4.31	53
6	GEN	Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	NE/82.0	4.31	54
6	GEN	Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	NE/82.0	4.31	55
6	GEN	Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	NE/82.0	4.31	56
6	GEN	RONA Inc.	50 Gillingham Drive Brampton ON	NE/82.0	4.31	56
6	GEN	RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	NE/82.0	4.31	57
6	GEN	RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	NE/82.0	4.31	58

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
6	GEN	RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	NE/82.0	4.31	59
6	GEN	RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	NE/82.0	4.31	59
6	GEN	RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	NE/82.0	4.31	61
6	GEN	RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	NE/82.0	4.31	62
6	GEN	RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	NE/82.0	4.31	63
7	GEN	CANADIAN TIRE CORPORATION LTD.	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	SW/51.1	-1.60	64
7	GEN	CANADIAN TIRE CORPORATION LTD.	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	SW/51.1	-1.60	65
7	GEN	CANADIAN TIRE CORPORATION LTD. PETROLEUM	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	SW/51.1	-1.60	65
7	GEN	CANADIAN TIRE CORPORATION LTD. PETROLEUM	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	SW/51.1	-1.60	65
7	GEN	CANADIAN TIRE CORPORATION LTD. PETROLEUM	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	SW/51.1	-1.60	66
7	GEN	CANADIAN TIRE CORPORATION LTD. PETROLEUM	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	SW/51.1	-1.60	66
8	GEN	Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	NE/58.4	5.65	67

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
8	GEN	Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	NE/58.4	5.65	67
8	GEN	Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	NE/58.4	5.65	67
8	GEN	Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	NE/58.4	5.65	68
8	GEN	Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	NE/58.4	5.65	68
8	GEN	Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	NE/58.4	5.65	68
9	GEN	KODAK CANADA INC.	9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	SW/5.7	-2.16	69
9	GEN	KODAK CANADA INC. 23-119	9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	SW/5.7	-2.16	69
9	GEN	KODAK CANADA INC.	9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	SW/5.7	-2.16	70
10	RST	MCLAUGHLIN ESSO	10010 MCLAUGHLIN BRAMPTON ON L6V 1A1	SW/54.6	-1.56	71
10	FSTH	MANAN NAIK	10010 MCLAUGHLIN RD NORTH BRAMPTON ON	SW/54.6	-1.56	71
10	FSTH	MANAN NAIK	10010 MCLAUGHLIN RD NORTH BRAMPTON ON	SW/54.6	-1.56	72
10	RST	RAKHI'S ESSO	10010 MCLAUGHLIN RD BRAMPTON ON L7A 2X6	SW/54.6	-1.56	72
10	FST	MAC'S CONVENIENCE STORES INC.	10010 MCLAUGHLIN RD BRAMPTON ON	SW/54.6	-1.56	72

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	FST	MAC'S CONVENIENCE STORES INC.	10010 MCLAUGHLIN RD BRAMPTON ON	SW/54.6	-1.56	73
10	FST	MAC'S CONVENIENCE STORES INC.	10010 MCLAUGHLIN RD BRAMPTON ON	SW/54.6	-1.56	73
10	RST	ESSO MCLAUGHLIN AND BOVIRD	10010 MCLAUGHLIN RD BRAMPTON ON L7A2X6	SW/54.6	-1.56	73
10	FST	MAC'S CONVENIENCE STORES INC.	10010 MCLAUGHLIN RD BRAMPTON ON	SW/54.6	-1.56	73
11	GEN	Sehdev Drugs Limited	10048 MCLAUGHLIN RD BRAMPTON ON L7A 2X6	SW/99.7	-1.15	74
11	GEN	Sehdev Drugs Limited	10048 MCLAUGHLIN RD BRAMPTON ON L7A 2X6	SW/99.7	-1.15	74
11	GEN	Sehdev Drugs Limited	10048 McLauglin Rd Brampton ON L7A 2X6	SW/99.7	-1.15	74
11	GEN	Sehdev Drugs Limited	10048 McLauglin Rd Brampton ON L7A 2X6	SW/99.7	-1.15	75
11	GEN	Sehdev Drugs Limited	10048 McLauglin Rd Brampton ON L7A 2X6	SW/99.7	-1.15	75
11	GEN	Sehdev Drugs Limited	10048 McLauglin Rd Brampton ON L7A 2X6	SW/99.7	-1.15	76
12	RST	DAVE'S GAS DEPOT	30 HWY 7 W BRAMPTON ON	NE/61.4	5.90	76
12	RST	DAVE'S GAS DEPOT	30 BOVAIRD DR W BRAMPTON ON L6V 1A1	NE/61.4	5.90	76
12	GEN	Regionional Municipality of Peel	2 - 30 Bovaird Drive West Brampton ON L7A 0H3	NE/61.4	5.90	76

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
12	GEN	Regional Municipality of Peel	2 - 30 Bovaird Drive West Brampton ON L7A 0H3	NE/61.4	5.90	77
12	GEN	Pinchin Ltd.	2-30 Bovaird Drive West Brampton ON L7A 0H3	NE/61.4	5.90	77
13	FSTH	1119838 ONTARIO INC O/A GAS STN	9950 MCLAUGHLIN RD BRAMPTON ON L6X 5C7	SW/60.9	-2.64	77
13	FSTH	1119838 ONTARIO INC O/A GAS STN	9950 MCLAUGHLIN RD BRAMPTON ON L6X 5C7	SW/60.9	-2.64	78
13	GEN	Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	SW/60.9	-2.64	78
13	GEN	Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	SW/60.9	-2.64	79
13	GEN	Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	SW/60.9	-2.64	79
13	GEN	Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	SW/60.9	-2.64	79
13	FST	PARKLAND CORPORATION	9950 MCLAUGHLIN RD BRAMPTON ON	SW/60.9	-2.64	80
13	FST	PARKLAND CORPORATION	9950 MCLAUGHLIN RD BRAMPTON ON	SW/60.9	-2.64	80
13	FST	PARKLAND CORPORATION	9950 MCLAUGHLIN RD BRAMPTON ON	SW/60.9	-2.64	80
13	GEN	Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	SW/60.9	-2.64	81
13	GEN	Husky Oil Operation Ltd.	9950 McLaughlin Rd N Brampton ON L6X 5C7	SW/60.9	-2.64	81

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
13	GEN	Parkland Corporation	9950 McLaughlin Rd N Brampton ON L6X 5C7	SW/60.9	-2.64	81
13	FST	PARKLAND CORPORATION	9950 MCLAUGHLIN RD BRAMPTON ON	SW/60.9	-2.64	82
14	RST	PIONEER PETROLEUM	675 MAIN ST N BRAMPTON ON L6V1A1	NE/54.6	4.85	82
14	RST	PIONEER PETROLEUM	675 MAIN N BRAMPTON ON	NE/54.6	4.85	82
14	RST	PIONEER PETROLEUMS	675 MAIN ST N BRAMPTON ON L6X 0G6	NE/54.6	4.85	82
14	FSTH	PIONEER PETROLEUMS MANAGEMENT INC**	675 MAIN ST N BRAMPTON ON L6X 0G6	NE/54.6	4.85	82
14	FSTH	PIONEER PETROLEUMS MANAGEMENT INC**	675 MAIN ST N BRAMPTON ON L6X 0G6	NE/54.6	4.85	83
14	DTNK	PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	NE/54.6	4.85	84
14	DTNK	PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	NE/54.6	4.85	84
14	DTNK	PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	NE/54.6	4.85	85
14	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	NE/54.6	4.85	85
14	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	NE/54.6	4.85	86
14	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	NE/54.6	4.85	86

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
14	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	NE/54.6	4.85	86
14	RST	PIONEER PETROLEUMS	675 MAIN ST N BRAMPTON ON L6X0G6	NE/54.6	4.85	86
14	GEN	Pioneer Energy LP	675 Main Street North Brampton ON L6X 0G6	NE/54.6	4.85	87
14	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	NE/54.6	4.85	87
15	GEN	A&P PHARMACY	10088 MCLAUGLIN ROAD BRAMPTON ON L7A 2X6	SW/98.0	-1.15	87
15	GEN	EM2 Corp.	10088 McLaughin Road Brampton ON L6V 1A1	SW/98.0	-1.15	88
15	GEN	2563119 Ontraio Inc	10088 McLaughlin Road Unit 14 Brampton ON L7A 2X6	SW/98.0	-1.15	88
15	GEN	2563119 Ontraio Inc	10088 McLaughlin Road Unit 14 Brampton ON L7A 2X6	SW/98.0	-1.15	88
16	DTNK	PREET PETROLEUM	HWY 7 HWY 10 BRAMPTON ON L3M 1V1	NE/0.9	4.98	89
16	INC		Bovaird Drive & Hwy #10, Brampton ON	NE/0.9	4.98	89
17	FSTH	1672237 ONTARIO LTD	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	NE/69.0	3.85	90
17	FSTH	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	NE/69.0	3.85	91
17	DTNK	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	NE/69.0	3.85	92

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	DTNK	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	NE/69.0	3.85	92
17	DTNK	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	NE/69.0	3.85	93
17	DTNK	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	NE/69.0	3.85	93
17	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	94
17	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	94
17	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	94
17	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	95
17	GEN	Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	NE/69.0	3.85	95
17	GEN	Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	NE/69.0	3.85	95
17	GEN	Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	NE/69.0	3.85	96
17	EXP	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	96
17	EXP	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	96
17	EXP	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	96

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	EXP	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	97
17	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	NE/69.0	3.85	97
18	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	NE/95.1	5.93	97
18	GEN	Pharma Plus Drugmarts Ltd	10035 Hurontario Street Brampton ON L6Z 0E6	NE/95.1	5.93	98
18	GEN	Pharma Plus Drugmarts Ltd	10035 Hurontario Street Brampton ON L6Z 0E6	NE/95.1	5.93	98
18	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	NE/95.1	5.93	98
18	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	NE/95.1	5.93	99
18	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	NE/95.1	5.93	99
18	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	NE/95.1	5.93	100

Executive Summary: Summary By Data Source

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 8 DTNK site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	54.6	14
PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	54.6	14
PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	54.6	14
PREET PETROLEUM	HWY 7 HWY 10 BRAMPTON ON L3M 1V1	0.9	16
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	69.0	17
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	69.0	17
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	69.0	17
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	69.0	17

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Oct 2023 has found that there are 4 EXP site(s) within approximately 0.10 kilometers of the

project property.

Site	Address	Distance (m)	Map Key
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	69.0	17
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	69.0	17
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	69.0	17
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	69.0	17

FST - Fuel Storage Tank

A search of the FST database, dated Oct 2023 has found that there are 22 FST site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CANADIAN TIRE CORPORATION LIMITED	10031 MCLAUGHLIN RD BRAMPTON ON	47.7	4
CANADIAN TIRE CORPORATION LIMITED	10031 MCLAUGHLIN RD BRAMPTON ON	47.7	4
CANADIAN TIRE CORPORATION LIMITED	10031 MCLAUGHLIN RD BRAMPTON ON	47.7	4
CANADIAN TIRE CORPORATION LIMITED	10031 MCLAUGHLIN RD BRAMPTON ON	47.7	4
MAC'S CONVENIENCE STORES INC.	10010 MCLAUGHLIN RD BRAMPTON ON	54.6	10
MAC'S CONVENIENCE STORES INC.	10010 MCLAUGHLIN RD BRAMPTON ON	54.6	10

Site	Address	Distance (m)	Map Key
MAC'S CONVENIENCE STORES INC.	10010 MCLAUGHLIN RD BRAMPTON ON	54.6	10
MAC'S CONVENIENCE STORES INC.	10010 MCLAUGHLIN RD BRAMPTON ON	54.6	10
PARKLAND CORPORATION	9950 MCLAUGHLIN RD BRAMPTON ON	60.9	13
PARKLAND CORPORATION	9950 MCLAUGHLIN RD BRAMPTON ON	60.9	13
PARKLAND CORPORATION	9950 MCLAUGHLIN RD BRAMPTON ON	60.9	13
PARKLAND CORPORATION	9950 MCLAUGHLIN RD BRAMPTON ON	60.9	13
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	14
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	14
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	14
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	14
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	14

Site	Address	Distance (m)	Map Key
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	69.0	17
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	69.0	17
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	69.0	17
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	69.0	17
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	69.0	17

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 10 FSTH site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CANADIAN TIRE CORP LTD **	10031 MCLAUGHLIN RD BRAMPTON ON L7A 2X5	47.7	4
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr	10031 MCLAUGHLIN RD BRAMPTON ON L7A 2X5	47.7	4
MANAN NAIK	10010 MCLAUGHLIN RD NORTH BRAMPTON ON	54.6	10
MANAN NAIK	10010 MCLAUGHLIN RD NORTH BRAMPTON ON	54.6	10
1119838 ONTARIO INC O/A GAS STN	9950 MCLAUGHLIN RD BRAMPTON ON L6X 5C7	60.9	13

Site	Address	Distance (m)	Map Key
1119838 ONTARIO INC O/A GAS STN	9950 MCLAUGHLIN RD BRAMPTON ON L6X 5C7	60.9	13
PIONEER PETROLEUMS MANAGEMENT INC**	675 MAIN ST N BRAMPTON ON L6X 0G6	54.6	14
PIONEER PETROLEUMS MANAGEMENT INC**	675 MAIN ST N BRAMPTON ON L6X 0G6	54.6	14
1672237 ONTARIO LTD	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	69.0	17
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	69.0	17

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 78 GEN site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Attrell Toyota	110 Canam Drive Brampton ON L7A 2A9	50.6	1
Chrysler Group LLC	190 Canam Crescent Brampton ON	48.7	2
1737126 Ont Inc.	100 Manett Cres. Brampton ON L6X 4X4	98.3	3
Canadian Tire #675	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4

Site	Address	Distance (m)	Map Key
K.R. Estey Holdings Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
K.R. Estey Holdings Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
K.R. Estey Holdings Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
K.R. Estey Holdings Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON	47.7	4
Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
Dirmar Reid Sales Ltd.	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
Melrose Paving Co. Ltd.	10031 Mclaughlin Road North Brampton ON L7A 2X5	47.7	4
Kevin Shay Sales Limited	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
Canadian Tire Real Estate Limited	10031 McLaughlin Road Brampton ON L7A 2X5	47.7	4

Site	Address	Distance (m)	Map Key
Kevin Shay Sales Limited	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
7739524 CANADA LIMITED	10031 mclaughlin rd. brampton ON L7A 2X5	47.7	4
PRODUCT MANAGEMENT Corporatio	180 Bovaird Drive West Rear Building, Unit B Brampton ON L6V 1A1	85.3	5
Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	82.0	6
Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	82.0	6
Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	82.0	6
Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	82.0	6
Rona Home and Garden	50 Gillingham Drive Brampton ON L6X 4X7	82.0	6
RONA Inc.	50 Gillingham Drive Brampton ON	82.0	6
RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	82.0	6
RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	82.0	6

Site	Address	Distance (m)	Map Key
RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	82.0	6
RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	82.0	6
RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	82.0	6
RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	82.0	6
RONA Inc.	50 Gillingham Drive Brampton ON L6Y 2N4	82.0	6
CANADIAN TIRE CORPORATION LTD.	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	51.1	7
CANADIAN TIRE CORPORATION LTD.	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	51.1	7
CANADIAN TIRE CORPORATION LTD. PETROLEUM	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	51.1	7
CANADIAN TIRE CORPORATION LTD. PETROLEUM	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	51.1	7
CANADIAN TIRE CORPORATION LTD. PETROLEUM	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	51.1	7
CANADIAN TIRE CORPORATION LTD. PETROLEUM	10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	51.1	7
Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	58.4	8

Site	Address	Distance (m)	Map Key
Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	58.4	8
Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	58.4	8
Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	58.4	8
Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	58.4	8
Frost Chevrolet Buick GMC Cadillac	150 Bovaird Drive West Brampton ON L7A 0H3	58.4	8
KODAK CANADA INC.	9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	5.7	9
KODAK CANADA INC. 23-119	9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	5.7	9
KODAK CANADA INC.	9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	5.7	9
Sehdev Drugs Limited	10048 MCLAUGHLIN RD BRAMPTON ON L7A 2X6	99.7	11
Sehdev Drugs Limited	10048 MCLAUGHLIN RD BRAMPTON ON L7A 2X6	99.7	11
Sehdev Drugs Limited	10048 McLauglin Rd Brampton ON L7A 2X6	99.7	11

Site	Address	Distance (m)	Map Key
Sehdev Drugs Limited	10048 McLauglin Rd Brampton ON L7A 2X6	99.7	11
Sehdev Drugs Limited	10048 McLauglin Rd Brampton ON L7A 2X6	99.7	11
Sehdev Drugs Limited	10048 McLauglin Rd Brampton ON L7A 2X6	99.7	11
Regionional Municipality of Peel	2 - 30 Bovaird Drive West Brampton ON L7A 0H3	61.4	12
Regional Municipality of Peel	2 - 30 Bovaird Drive West Brampton ON L7A 0H3	61.4	12
Pinchin Ltd.	2-30 Bovaird Drive West Brampton ON L7A 0H3	61.4	12
Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	60.9	13
Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	60.9	13
Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	60.9	13
Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	60.9	13
Suncor Energy Products Inc	9950 McLaughlin Road Brampton ON L6X 5C7	60.9	13
Husky Oil Operation Ltd.	9950 McLaughlin Rd N Brampton ON L6X 5C7	60.9	13

Site	Address	Distance (m)	Map Key
Parkland Corporation	9950 McLaughlin Rd N Brampton ON L6X 5C7	60.9	13
Pioneer Energy LP	675 Main Street North Brampton ON L6X 0G6	54.6	14
A&P PHARMACY	10088 MCLAUGLIN ROAD BRAMPTON ON L7A 2X6	98.0	15
EM2 Corp.	10088 McLaughin Road Brampton ON L6V 1A1	98.0	15
2563119 Ontraio Inc	10088 McLaughlin Road Unit 14 Brampton ON L7A 2X6	98.0	15
2563119 Ontraio Inc	10088 McLaughlin Road Unit 14 Brampton ON L7A 2X6	98.0	15
Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	69.0	17
Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	69.0	17
Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	69.0	17
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	95.1	18
Pharma Plus Drugmarts Ltd	10035 Hurontario Street Brampton ON L6Z 0E6	95.1	18

Site	Address	Distance (m)	Map Key
Pharma Plus Drugmarts Ltd	10035 Hurontario Street Brampton ON L6Z 0E6	95.1	18
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	95.1	18
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	95.1	18
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	95.1	18
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	95.1	18

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated 31 Oct, 2023 has found that there are 1 INC site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	Bovaird Drive & Hwy #10, Brampton ON	0.9	16

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Apr 30, 2024 has found that there are 9 RST site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
MCLAUGHLIN ESSO	10010 MCLAUGHLIN BRAMPTON ON L6V 1A1	54.6	10
RAKHI'S ESSO	10010 MCLAUGHLIN RD BRAMPTON ON L7A 2X6	54.6	10


Site	Address	Distance (m)	Map Key
ESSO MCLAUGHLIN AND BOVIRD	10010 MCLAUGHLIN RD BRAMPTON ON L7A2X6	54.6	10
DAVE'S GAS DEPOT	30 HWY 7 W BRAMPTON ON	61.4	12
DAVE'S GAS DEPOT	30 BOVAIRD DR W BRAMPTON ON L6V 1A1	61.4	12
PIONEER PETROLEUMS	675 MAIN ST N BRAMPTON ON L6X0G6	54.6	14
PIONEER PETROLEUM	675 MAIN ST N BRAMPTON ON L6V1A1	54.6	14
PIONEER PETROLEUM	675 MAIN N BRAMPTON ON	54.6	14
PIONEER PETROLEUMS	675 MAIN ST N BRAMPTON ON L6X 0G6	54.6	14

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 5 SCT site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Brampton Sheet Metal Ltd.	180 Hwy 7 W Brampton ON L6V 1A1	85.3	5
Lumber Land North Inc.	180 HWY 7 W Brampton ON L7A 1A1	85.3	5
Lumber Land North Inc.	180 Bovaird Dr W Brampton ON L7A 0H3	85.3	5

Site	Address	Distance (m)	Map Key
Lumber Land North Inc.	ON	85.3	5
Lumber Land North Inc.	180 Highway 7 W RR 2 Brampton ON L6V 1A1	85.3	5



Map: 0.1 Kilometer Radius

Order Number: 24062700012

Address: Bovaird, Brampton, ON

ERIS


- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership

79°48'W

43°42'N



43°42'N

Aerial


Year: 2022

Order Number: 24062700012

Address: Bovaird, Brampton, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Address: Bovaird, ON

Source: ESRI World Topographic Map

Order Number: 24062700012

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	N/50.6	231.8 / 0.82	Attrell Toyota 110 Canam Drive Brampton ON L7A 2A9	GEN

Generator No:	ON4473811
SIC Code:	
SIC Description:	
Approval Years:	As of Oct 2019
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	150 L
Waste Class Name:	Inert organic wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 1	WSW/48.7	233.0 / 2.01	Chrysler Group LLC 190 Canam Crescent Brampton ON	GEN

Generator No:	ON7916066
SIC Code:	441110
SIC Description:	NEW CAR DEALERS
Approval Years:	2013
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	150
Waste Class Name:	INERT INORGANIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	1 of 1	ENE/98.3	230.0 / -0.97	1737126 Ont Inc. 100 Manett Cres. Brampton ON L6X 4X4	GEN

Generator No:	ON7769490
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

4 | ***1 of 21*** | ***SW/47.7*** | ***229.9 / -1.15*** | ***CANADIAN TIRE CORP LTD *****
10031 MCLAUGHLIN RD
BRAMPTON ON L7A 2X5 | ***FSTH***

License Issue Date: 2/12/2007
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 2005
Corrosion Protection:
Capacity: 60000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

Status: Active
Year of Installation: 2005
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2005
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

---

4 | ***2 of 21*** | ***SW/47.7*** | ***229.9 / -1.15*** | ***CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr***
10031 MCLAUGHLIN RD
BRAMPTON ON L7A 2X5 | ***FSTH***

License Issue Date: 2/12/2007 12:08:00 PM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 2005
Corrosion Protection:
Capacity: 60000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

Status: Active

Year of Installation:	2005
Corrosion Protection:	
Capacity:	50000
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline
Status:	Active
Year of Installation:	2005
Corrosion Protection:	
Capacity:	50000
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	3 of 21	SW/47.7	229.9 / -1.15	Canadian Tire #675 10031 mclaughlin rd. brampton ON L7A 2X5	GEN

Generator No:	ON3552037
SIC Code:	452110 452991 452999
SIC Description:	Department Stores, Home and Auto Supplies Stores, All Other Miscellaneous General Merchandise Stores
Approval Years:	07,08
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	147
Waste Class Name:	CHEMICAL FERTILIZER WASTES
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	221
Waste Class Name:	LIGHT FUELS
Waste Class:	222
Waste Class Name:	HEAVY FUELS
Waste Class:	242
Waste Class Name:	HALOGENATED PESTICIDES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

4 **4 of 21** **SW/47.7** **229.9 / -1.15** **K.R. Estey Holdings Ltd.**
10031 mclaughlin rd.
brampton ON L7A 2X5
GEN

Generator No: ON3552037
SIC Code: 452110, 452991, 452999
SIC Description: Department Stores, Home and Auto Supplies Stores, All Other Miscellaneous General Merchandise Stores
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

4 **5 of 21** **SW/47.7** **229.9 / -1.15** **K.R. Estey Holdings Ltd.**
10031 mclaughlin rd.
brampton ON L7A 2X5
GEN

Generator No: ON3552037

SIC Code: 452110, 452991, 452999
SIC Description: Department Stores, Home and Auto Supplies Stores, All Other Miscellaneous General Merchandise Stores
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

4	***6 of 21***	***SW/47.7***	***229.9 / -1.15***	***K.R. Estey Holdings Ltd.*** ***10031 mclaughlin rd.*** ***brampton ON L7A 2X5***	***GEN***

Generator No: ON3552037
SIC Code: 452110, 452991, 452999
SIC Description: Department Stores, Home and Auto Supplies Stores, All Other Miscellaneous General Merchandise Stores
Approval Years: 2011

PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

4	7 of 21	SW/47.7	229.9 / -1.15	CANADIAN TIRE CORPORATION LIMITED 10031 MCLAUGHLIN RD BRAMPTON ON	FST

Inventory No: 38864045
Inventory Status: active
Installation Year: 2005
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Model:					
Description:		2009VBS			

4	8 of 21	SW/47.7	229.9 / -1.15	CANADIAN TIRE CORPORATION LIMITED 10031 MCLAUGHLIN RD BRAMPTON ON	FST

Inventory No: 38864046
Inventory Status: active
Installation Year: 2005
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

4	9 of 21	SW/47.7	229.9 / -1.15	CANADIAN TIRE CORPORATION LIMITED 10031 MCLAUGHLIN RD BRAMPTON ON	FST

Inventory No: 38864044
Inventory Status: active
Installation Year: 2005
Capacity: 60000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS
Split Tank: 40000L Diesel/ 20000L Premium

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

4	10 of 21	SW/47.7	229.9 / -1.15	K.R. Estey Holdings Ltd. 10031 mclaughlin rd. brampton ON L7A 2X5	GEN

Generator No: ON3552037
SIC Code: 452110, 452991, 452999
SIC Description: Department Stores, Home and Auto Supplies Stores, All Other Miscellaneous General Merchandise Stores
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

4	11 of 21	SW/47.7	229.9 / -1.15	**Dirmar Reid Sales Ltd.** **10031 mclaughlin rd.** **brampton ON**	GEN

Generator No: ON3552037
SIC Code: 452110, 452991, 452999
SIC Description: DEPARTMENT STORES, HOME AND AUTO SUPPLIES STORES, ALL OTHER MISCELLANEOUS GENERAL MERCHANDISE STORES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

4 | **12 of 21** | **SW/47.7** | **229.9 / -1.15** | **Dirmar Reid Sales Ltd.**
10031 mclaughlin rd.
brampton ON L7A 2X5 | **GEN**

Generator No: ON3552037
SIC Code: 452110, 452991, 452999
SIC Description: DEPARTMENT STORES, HOME AND AUTO SUPPLIES STORES, ALL OTHER MISCELLANEOUS GENERAL MERCHANDISE STORES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Matt Gunness
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-795-3330 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213

Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

---

4 | ***13 of 21*** | ***SW/47.7*** | ***229.9 / -1.15*** | ***Dirmar Reid Sales Ltd.***
10031 mclaughlin rd.
brampton ON L7A 2X5 | ***GEN***

Generator No: ON3552037
SIC Code: 452110, 452991, 452999
SIC Description: DEPARTMENT STORES, HOME AND AUTO SUPPLIES STORES, ALL OTHER MISCELLANEOUS GENERAL MERCHANDISE STORES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Matt Gunness
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-795-3330 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

4	14 of 21	SW/47.7	229.9 / -1.15	**Dirmar Reid Sales Ltd.** **10031 mclaughlin rd.** **brampton ON L7A 2X5**	GEN

Generator No: ON3552037
SIC Code: 452110, 452991, 452999
SIC Description: DEPARTMENT STORES, HOME AND AUTO SUPPLIES STORES, ALL OTHER MISCELLANEOUS GENERAL MERCHANDISE STORES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Matt Gunness
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-795-3330 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	15 of 21	SW/47.7	229.9 / -1.15	Dirmar Reid Sales Ltd. 10031 mclaughlin rd. brampton ON L7A 2X5	GEN

Generator No: ON3552037
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	16 of 21	SW/47.7	229.9 / -1.15	Melrose Paving Co. Ltd. 10031 Mclaughlin Road North Brampton ON L7A 2X5	GEN

Generator No: ON7715306
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	17 of 21	SW/47.7	229.9 / -1.15	Kevin Shay Sales Limited 10031 mclaughlin rd. brampton ON L7A 2X5	GEN

Generator No: ON3552037
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		263 I			
Waste Class Name:		Misc. waste organic chemicals			

4	18 of 21	SW/47.7	229.9 / -1.15	**Canadian Tire Real Estate Limited** **10031 McLaughlin Road** **Brampton ON L7A 2X5**	GEN

Generator No: ON9336644
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

4	19 of 21	SW/47.7	229.9 / -1.15	**Kevin Shay Sales Limited** **10031 mclaughlin rd.** **brampton ON L7A 2X5**	GEN

Generator No: ON3552037
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: Waste compressed gases including cylinders

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

---

4 | **20 of 21** | **SW/47.7** | **229.9 / -1.15** | **7739524 CANADA LIMITED**
10031 mclaughlin rd.
brampton ON L7A 2X5 | **GEN**

Generator No: ON3552037
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 242 A
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

4 | **21 of 21** | **SW/47.7** | **229.9 / -1.15** | **CANADIAN TIRE CORPORATION LIMITED**
10031 MCLAUGHLIN RD
BRAMPTON ON | **FST**

Inventory No: 38795174
Inventory Status: Active
Installation Year:
Capacity: 160000
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:
Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	1 of 6	NE/85.3	235.0 / 3.95	**Brampton Sheet Metal Ltd.** **180 Hwy 7 W** **Brampton ON L6V 1A1**	SCT

Established: 01-JUL-45
Plant Size (ft²):
Employment:

--Details--
Description: Other Ornamental and Architectural Metal Product Manufacturing
SIC/NAICS Code: 332329

Description: Plumbing, Heating and Air-Conditioning Contractors
SIC/NAICS Code: 238220

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	2 of 6	NE/85.3	235.0 / 3.95	**Lumber Land North Inc.** **180 HWY 7 W** **Brampton ON L7A 1A1**	SCT

Established: 1960
Plant Size (ft²): 30000
Employment: 20

--Details--
Description: Wood Kitchen Cabinet and Counter Top Manufacturing
SIC/NAICS Code: 337110

Description: Lumber, Plywood and Millwork Wholesaler-Distributors
SIC/NAICS Code: 416320

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: Other Building Material Dealers
SIC/NAICS Code: 444190

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	3 of 6	NE/85.3	235.0 / 3.95	**Lumber Land North Inc.** **180 Highway 7 W RR 2** **Brampton ON L6V 1A1**	SCT

Established: 1960
Plant Size (ft²): 30000
Employment: 20

--Details--
Description: Wood Kitchen Cabinet and Counter Top Manufacturing
SIC/NAICS Code: 337110

Description: Lumber, Plywood and Millwork Wholesaler-Distributors
SIC/NAICS Code: 416320

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: Other Building Material Dealers
SIC/NAICS Code: 444190

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	4 of 6	NE/85.3	235.0 / 3.95	PRODUCT MANAGEMENT Corporatio 180 Bovaird Drive West Rear Building, Unit B Brampton ON L6V 1A1	GEN

Generator No: ON4720790
SIC Code: 484239
SIC Description: Other Specialized Trucking, Long Distance
Approval Years: 03,04,05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	5 of 6	NE/85.3	235.0 / 3.95	Lumber Land North Inc. ON	SCT

Established: 1960
Plant Size (ft²): 30000
Employment: 20

--Details--
Description: Wood Kitchen Cabinet and Counter Top Manufacturing
SIC/NAICS Code: 337110

Description: Lumber, Plywood and Millwork Wholesaler-Distributors
SIC/NAICS Code: 416320

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: Other Building Material Dealers
SIC/NAICS Code: 444190

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	6 of 6	NE/85.3	235.0 / 3.95	Lumber Land North Inc. 180 Bovaird Dr W Brampton ON L7A 0H3	SCT

Established: 01-AUG-60
Plant Size (ft²): 60000
Employment:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: Wood Kitchen Cabinet and Counter Top Manufacturing
SIC/NAICS Code: 337110

Description: Other Building Material Dealers
SIC/NAICS Code: 444190

Description: Lumber, Plywood and Millwork Wholesaler-Distributors
SIC/NAICS Code: 416320

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

6	1 of 13	NE/82.0	235.3 / 4.31	**Rona Home and Garden** **50 Gillingham Drive** **Brampton ON L6X 4X7**	GEN

Generator No: ON5119629
SIC Code: 444110
SIC Description: Home Centres
Approval Years: 04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

6	2 of 13	NE/82.0	235.3 / 4.31	**Rona Home and Garden**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				50 Gillingham Drive **Brampton ON L6X 4X7**	

Generator No: ON5119629
SIC Code: 444110
SIC Description: Home Centres
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	3 of 13	NE/82.0	235.3 / 4.31	**Rona Home and Garden** **50 Gillingham Drive** **Brampton ON L6X 4X7**	GEN

Generator No: ON5119629
SIC Code: 444110
SIC Description: Home Centres
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

---

6 | **4 of 13** | **NE/82.0** | **235.3 / 4.31** | **Rona Home and Garden**
50 Gillingham Drive
Brampton ON L6X 4X7 | **GEN**

Generator No: ON5119629
SIC Code: 444110
SIC Description: Home Centres
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	5 of 13	NE/82.0	235.3 / 4.31	Rona Home and Garden 50 Gillingham Drive Brampton ON L6X 4X7	GEN

Generator No: ON5119629
SIC Code: 444110
SIC Description: Home Centres
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	6 of 13	NE/82.0	235.3 / 4.31	RONA Inc. 50 Gillingham Drive Brampton ON	GEN

Generator No: ON5119629
SIC Code: 444110
SIC Description: HOME CENTRES

Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

6	7 of 13	NE/82.0	235.3 / 4.31	RONA Inc. 50 Gillingham Drive Brampton ON L6Y 2N4	GEN

Generator No: ON5119629
SIC Code: 444110
SIC Description: HOME CENTRES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Brandy McDaniel
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-308-5322 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	8 of 13	NE/82.0	235.3 / 4.31	**RONA Inc.** **50 Gillingham Drive** **Brampton ON L6Y 2N4**	GEN

Generator No: ON5119629
SIC Code: 444110
SIC Description: HOME CENTRES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Brandy McDaniel
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-308-5322 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

6 | **9 of 13** | **NE/82.0** | **235.3 / 4.31** | **RONA Inc.**
50 Gillingham Drive
Brampton ON L6Y 2N4 | **GEN**

Generator No: ON5119629
SIC Code: 444110
SIC Description: HOME CENTRES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Brandy McDaniel
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-308-5322 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 147
Waste Class Name: CHEMICAL FERTILIZER WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

6 | **10 of 13** | **NE/82.0** | **235.3 / 4.31** | **RONA Inc.**
50 Gillingham Drive
Brampton ON L6Y 2N4 | **GEN**

Generator No: ON5119629
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 242 T
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	11 of 13	NE/82.0	235.3 / 4.31	RONA Inc. 50 Gillingham Drive Brampton ON L6Y 2N4	GEN

Generator No: ON5119629
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 242 T
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	12 of 13	NE/82.0	235.3 / 4.31	**RONA Inc.** **50 Gillingham Drive** **Brampton ON L6Y 2N4**	GEN

Generator No: ON5119629
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 263 T
Waste Class Name: Misc. waste organic chemicals

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 242 A
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 242 T
Waste Class Name: Halogenated pesticides and herbicides

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	13 of 13	NE/82.0	235.3 / 4.31	**RONA Inc.** **50 Gillingham Drive** **Brampton ON L6Y 2N4**	GEN

Generator No: ON5119629
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 T
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 262 L
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 242 A
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 269 T
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 242 T
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 331 L
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Class: 148 T
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 263 A
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148 A
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

7	1 of 6	SW/51.1	229.4 / -1.60	**CANADIAN TIRE CORPORATION LTD.** **10021 MCLAUGHLIN RD.** **BRAMPTON ON L7A 2X5**	GEN

Generator No: ON5687574
SIC Code: 447190
SIC Description: 447190
Approval Years: 2016
PO Box No:
Country: Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

7	2 of 6	SW/51.1	229.4 / -1.60	CANADIAN TIRE CORPORATION LTD. 10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	GEN

Generator No: ON5687574
SIC Code: 447190
SIC Description: 447190
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

7	3 of 6	SW/51.1	229.4 / -1.60	CANADIAN TIRE CORPORATION LTD. PETROLEUM 10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	GEN

Generator No: ON5687574
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

7	4 of 6	SW/51.1	229.4 / -1.60	CANADIAN TIRE CORPORATION LTD. PETROLEUM 10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON5687574
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

7	5 of 6	SW/51.1	229.4 / -1.60	CANADIAN TIRE CORPORATION LTD. PETROLEUM 10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	GEN

Generator No: ON5687574
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

7	6 of 6	SW/51.1	229.4 / -1.60	CANADIAN TIRE CORPORATION LTD. PETROLEUM 10021 MCLAUGHLIN RD. BRAMPTON ON L7A 2X5	GEN

Generator No: ON5687574
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		251 L			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			

8	1 of 6	NE/58.4	236.7 / 5.65	**Frost Chevrolet Buick GMC Cadillac** **150 Bovaird Drive West** **Brampton ON L7A 0H3**	GEN

Generator No:	ON2776049
SIC Code:	441110
SIC Description:	NEW CAR DEALERS
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

8	2 of 6	NE/58.4	236.7 / 5.65	**Frost Chevrolet Buick GMC Cadillac** **150 Bovaird Drive West** **Brampton ON L7A 0H3**	GEN

Generator No:	ON2776049
SIC Code:	441110
SIC Description:	NEW CAR DEALERS
Approval Years:	2015
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

8	3 of 6	NE/58.4	236.7 / 5.65	**Frost Chevrolet Buick GMC Cadillac** **150 Bovaird Drive West** **Brampton ON L7A 0H3**	GEN

Generator No:	ON2776049
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
MHSW Facility:					

Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	4 of 6	NE/58.4	236.7 / 5.65	**Frost Chevrolet Buick GMC Cadillac** **150 Bovaird Drive West** **Brampton ON L7A 0H3**	GEN

Generator No:	ON2776049
SIC Code:	
SIC Description:	
Approval Years:	As of Jul 2020
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	5 of 6	NE/58.4	236.7 / 5.65	**Frost Chevrolet Buick GMC Cadillac** **150 Bovaird Drive West** **Brampton ON L7A 0H3**	GEN

Generator No:	ON2776049
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	6 of 6	NE/58.4	236.7 / 5.65	**Frost Chevrolet Buick GMC Cadillac** **150 Bovaird Drive West** **Brampton ON L7A 0H3**	GEN

Generator No:	ON2776049
SIC Code:	
SIC Description:	
Approval Years:	As of Oct 2022
PO Box No:	
Country:	Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	1 of 3	SW/5.7	228.8 / -2.16	KODAK CANADA INC. 9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	GEN

Generator No: ON0110001
SIC Code: 3912
SIC Description: OTHER INSTRUMENTS
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 133
Waste Class Name: BRINES, CHLOR-ALKALI WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	2 of 3	SW/5.7	228.8 / -2.16	KODAK CANADA INC. 23-119	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	

Generator No: ON0110001
SIC Code: 3912
SIC Description: OTHER INSTRUMENTS
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 133
Waste Class Name: BRINES, CHLOR-ALKALI WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	3 of 3	SW/5.7	228.8 / -2.16	KODAK CANADA INC. 9977 MCLAUGHLIN ROAD BRAMPTON ON L6X 2M4	GEN

Generator No: ON0110001
SIC Code: 3912
SIC Description: OTHER INSTRUMENTS
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 133
Waste Class Name: BRINES, CHLOR-ALKALI WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	1 of 9	SW/54.6	229.4 / -1.56	MCLAUGHLIN ESSO 10010 MCLAUGHLIN BRAMPTON ON L6V 1A1	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054957473
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	2 of 9	SW/54.6	229.4 / -1.56	MANAN NAIK 10010 MCLAUGHLIN RD NORTH BRAMPTON ON	FSTH

License Issue Date: 9/18/2006
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 2003

Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2003
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2003
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

---

10 | **3 of 9** | **SW/54.6** | **229.4 / -1.56** | **MANAN NAIK**
10010 MCLAUGHLIN RD NORTH
BRAMPTON ON | **FSTH**

License Issue Date: 9/18/2006 2:32:00 PM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 2003
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2003
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2003
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

---

10 | **4 of 9** | **SW/54.6** | **229.4 / -1.56** | **RAKHI'S ESSO**
10010 MCLAUGHLIN RD
BRAMPTON ON L7A 2X6 | **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

---

10 | **5 of 9** | **SW/54.6** | **229.4 / -1.56** | **MAC'S CONVENIENCE STORES INC.**
10010 MCLAUGHLIN RD
BRAMPTON ON | **FST**

Inventory No: 16347146 **Tank Material:** Fiberglass (FRP)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2003	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

10 | ***6 of 9*** | ***SW/54.6*** | ***229.4 / -1.56*** | ***MAC'S CONVENIENCE STORES INC.***
10010 MCLAUGHLIN RD
BRAMPTON ON | ***FST***

Inventory No:	16347145	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2003	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

10 | ***7 of 9*** | ***SW/54.6*** | ***229.4 / -1.56*** | ***MAC'S CONVENIENCE STORES INC.***
10010 MCLAUGHLIN RD
BRAMPTON ON | ***FST***

Inventory No:	16347147	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2003	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

10 | ***8 of 9*** | ***SW/54.6*** | ***229.4 / -1.56*** | ***ESSO MCLAUGHLIN AND BOVIRD***
10010 MCLAUGHLIN RD
BRAMPTON ON L7A2X6 | ***RST***

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS GASOLINE OIL & NATURAL
Phone:	9054957473
List Name:	
Description:	

---

10 | ***9 of 9*** | ***SW/54.6*** | ***229.4 / -1.56*** | ***MAC'S CONVENIENCE STORES INC.***
10010 MCLAUGHLIN RD
BRAMPTON ON | ***FST***

Inventory No:	16332603	**Tank Material:**	
Inventory Status:	Active	**Corrosion Protect:**	
Installation Year:		**Overfill Protection:**	
Capacity:	139200	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:					
11	1 of 6	SW/99.7	229.9 / -1.15	Sehdev Drugs Limited 10048 MCLAUGHLIN RD BRAMPTON ON L7A 2X6	GEN

Generator No: ON8882228
SIC Code: 446110
SIC Description: 446110
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: NASTRAN NAJAFI-FARD
Choice of Contact: CO_ADMIN
Phone No Admin: 4164931220 Ext.3218
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	2 of 6	SW/99.7	229.9 / -1.15	Sehdev Drugs Limited 10048 MCLAUGHLIN RD BRAMPTON ON L7A 2X6	GEN

Generator No: ON8882228
SIC Code: 446110
SIC Description: 446110
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: NASTRAN NAJAFI-FARD
Choice of Contact: CO_ADMIN
Phone No Admin: 4164931220 Ext.3218
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	3 of 6	SW/99.7	229.9 / -1.15	Sehdev Drugs Limited 10048 McLauglin Rd Brampton ON L7A 2X6	GEN

Generator No: ON7341323
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

11 | ***4 of 6*** | ***SW/99.7*** | ***229.9 / -1.15*** | ***Sehdev Drugs Limited***
10048 McLauglin Rd
Brampton ON L7A 2X6 | ***GEN***

Generator No: ON7341323
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

11 | ***5 of 6*** | ***SW/99.7*** | ***229.9 / -1.15*** | ***Sehdev Drugs Limited***
10048 McLauglin Rd
Brampton ON L7A 2X6 | ***GEN***

Generator No: ON7341323
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
11	6 of 6	SW/99.7	229.9 / -1.15	**Sehdev Drugs Limited** **10048 McLauglin Rd** **Brampton ON L7A 2X6**	GEN
Generator No:		ON7341323			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
Waste Class:		261 A			
Waste Class Name:		PHARMACEUTICALS			
12	1 of 5	NE/61.4	236.9 / 5.90	**DAVE'S GAS DEPOT** **30 HWY 7 W** **BRAMPTON ON**	RST
Headcode:		1186800			
Headcode Desc:		Service Stations-Gasoline, Oil & Natural Gas			
Phone:		9057969131			
List Name:					
Description:					
12	2 of 5	NE/61.4	236.9 / 5.90	**DAVE'S GAS DEPOT** **30 BOVAIRD DR W** **BRAMPTON ON L6V 1A1**	RST
Headcode:		1186800			
Headcode Desc:		Service Stations-Gasoline, Oil & Natural Gas			
Phone:		9057969131			
List Name:					
Description:					
12	3 of 5	NE/61.4	236.9 / 5.90	**Regionional Municipality of Peel** **2 - 30 Bovaird Drive West** **Brampton ON L7A 0H3**	GEN
Generator No:		ON9867821			
SIC Code:		913910			
SIC Description:		Other Local Municipal and Regional Public Administration			
Approval Years:		05			
PO Box No:					
Country:					
Status:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

12 | ***4 of 5*** | ***NE/61.4*** | ***236.9 / 5.90*** | ***Regional Municipality of Peel***
2 - 30 Bovaird Drive West
Brampton ON L7A 0H3 | ***GEN***

Generator No: ON9867821
SIC Code: 913910
SIC Description: Other Local Municipal and Regional Public Administ
Approval Years: 06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

12 | ***5 of 5*** | ***NE/61.4*** | ***236.9 / 5.90*** | ***Pinchin Ltd.***
2-30 Bovaird Drive West
Brampton ON L7A 0H3 | ***GEN***

Generator No: ON5696600
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

---

13 | ***1 of 13*** | ***SW/60.9*** | ***228.4 / -2.64*** | ***1119838 ONTARIO INC O/A GAS STN***
9950 MCLAUGHLIN RD
BRAMPTON ON L6X 5C7 | ***FSTH***

License Issue Date: 2/27/2007
Tank Status: Licensed

Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 2002
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2002
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2002
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	2 of 13	SW/60.9	228.4 / -2.64	1119838 ONTARIO INC O/A GAS STN 9950 MCLAUGHLIN RD BRAMPTON ON L6X 5C7	FSTH

License Issue Date: 2/27/2007 11:46:00 AM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 2002
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2002
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2002
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	3 of 13	SW/60.9	228.4 / -2.64	Suncor Energy Products Inc 9950 McLaughlin Road Brampton ON L6X 5C7	GEN

Generator No: ON6133424
SIC Code: 447190
SIC Description: Other Gasoline Stations
Approval Years: 07,08
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	4 of 13	SW/60.9	228.4 / -2.64	Suncor Energy Products Inc 9950 McLaughlin Road Brampton ON L6X 5C7	GEN

Generator No: ON6133424
SIC Code: 447190
SIC Description: Other Gasoline Stations
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	5 of 13	SW/60.9	228.4 / -2.64	Suncor Energy Products Inc 9950 McLaughlin Road Brampton ON L6X 5C7	GEN

Generator No: ON6133424
SIC Code: 447190
SIC Description: Other Gasoline Stations
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	6 of 13	SW/60.9	228.4 / -2.64	Suncor Energy Products Inc 9950 McLaughlin Road Brampton ON L6X 5C7	GEN

Generator No: ON6133424
SIC Code: 447190
SIC Description: Other Gasoline Stations
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

13 | **7 of 13** | **SW/60.9** | **228.4 / -2.64** | **PARKLAND CORPORATION**
9950 MCLAUGHLIN RD
BRAMPTON ON | **FST**

Inventory No: 13408362
Inventory Status: active
Installation Year: 2002
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

13 | **8 of 13** | **SW/60.9** | **228.4 / -2.64** | **PARKLAND CORPORATION**
9950 MCLAUGHLIN RD
BRAMPTON ON | **FST**

Inventory No: 13408363
Inventory Status: active
Installation Year: 2002
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS
Ultra

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

13 | **9 of 13** | **SW/60.9** | **228.4 / -2.64** | **PARKLAND CORPORATION**
9950 MCLAUGHLIN RD
BRAMPTON ON | **FST**

Inventory No: 13408361
Inventory Status: active
Installation Year: 2002
Capacity: 50000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	10 of 13	SW/60.9	228.4 / -2.64	Suncor Energy Products Inc 9950 McLaughlin Road Brampton ON L6X 5C7	GEN

Generator No: ON6133424
SIC Code: 447190
SIC Description: Other Gasoline Stations
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	11 of 13	SW/60.9	228.4 / -2.64	Husky Oil Operation Ltd. 9950 McLaughlin Rd N Brampton ON L6X 5C7	GEN

Generator No: ON6904724
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	12 of 13	SW/60.9	228.4 / -2.64	Parkland Corporation 9950 McLaughlin Rd N Brampton ON L6X 5C7	GEN

Generator No: ON6904724
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

---

13 | ***13 of 13*** | ***SW/60.9*** | ***228.4 / -2.64*** | ***PARKLAND CORPORATION***
9950 MCLAUGHLIN RD
BRAMPTON ON | ***FST***

Inventory No: 10387352
Inventory Status: Active
Installation Year:
Capacity: 150000
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

---

14 | ***1 of 15*** | ***NE/54.6*** | ***235.9 / 4.85*** | ***PIONEER PETROLEUM***
675 MAIN ST N
BRAMPTON ON L6V1A1 | ***RST***

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054566363
List Name:
Description:

---

14 | ***2 of 15*** | ***NE/54.6*** | ***235.9 / 4.85*** | ***PIONEER PETROLEUM***
675 MAIN N
BRAMPTON ON | ***RST***

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054566363
List Name:
Description:

---

14 | ***3 of 15*** | ***NE/54.6*** | ***235.9 / 4.85*** | ***PIONEER PETROLEUMS***
675 MAIN ST N
BRAMPTON ON L6X 0G6 | ***RST***

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

---

14 | ***4 of 15*** | ***NE/54.6*** | ***235.9 / 4.85*** | ***PIONEER PETROLEUMS MANAGEMENT INC*****
675 MAIN ST N
BRAMPTON ON L6X 0G6 | ***FSTH***

License Issue Date: 3/22/2002

Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45400
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45400
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45400
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45400
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

14	5 of 15	NE/54.6	235.9 / 4.85	**PIONEER PETROLEUMS MANAGEMENT INC**** **675 MAIN ST N** **BRAMPTON ON L6X 0G6**	FSTH

License Issue Date: 3/22/2002
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45400
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45400
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 45400
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1989
Corrosion Protection:

Capacity: 45400
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

---

14 | ***6 of 15*** | ***NE/54.6*** | ***235.9 / 4.85*** | ***PIONEER ENERGY MANAGEMENT INC.***
675 MAIN ST N
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11442375
Status: EXPIRED
Instance ID: 84689
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

14 | ***7 of 15*** | ***NE/54.6*** | ***235.9 / 4.85*** | ***PIONEER ENERGY MANAGEMENT INC.***
675 MAIN ST N
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 64272903
Status: EXPIRED
Instance ID: 352181
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

14	*8 of 15*	*NE/54.6*	*235.9 / 4.85*	***PIONEER ENERGY MANAGEMENT INC.*** ***675 MAIN ST N*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 64272902
Status: EXPIRED
Instance ID: 353690
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

14	*9 of 15*	*NE/54.6*	*235.9 / 4.85*	***PARKLAND CORPORATION*** ***675 MAIN ST N*** ***BRAMPTON ON***	***FST***

Inventory No: 11442317
Inventory Status: active
Installation Year: 1989
Capacity: 45400

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel

Capacity Unit:	L			**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:		Single Wall UST			
Manufacturer:					
Model:					
Description:		2009VBS Mid			

---

14 **10 of 15** **NE/54.6** **235.9 / 4.85** **PARKLAND CORPORATION** **FST**
675 MAIN ST N
BRAMPTON ON

Inventory No:	11442355	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1989	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

14 **11 of 15** **NE/54.6** **235.9 / 4.85** **PARKLAND CORPORATION** **FST**
675 MAIN ST N
BRAMPTON ON

Inventory No:	11442338	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1989	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

14 **12 of 15** **NE/54.6** **235.9 / 4.85** **PARKLAND CORPORATION** **FST**
675 MAIN ST N
BRAMPTON ON

Inventory No:	10599019	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1989	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS Premium		

---

14 **13 of 15** **NE/54.6** **235.9 / 4.85** **PIONEER PETROLEUMS** **RST**
675 MAIN ST N
BRAMPTON ON L6X0G6

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS GASOLINE OIL & NATURAL
Phone:	9054566363
List Name:	
Description:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	14 of 15	NE/54.6	235.9 / 4.85	Pioneer Energy LP 675 Main Street North Brampton ON L6X 0G6	GEN

Generator No: ON4230276
SIC Code: 447110
SIC Description: 447110
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Alyssa Santiago
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-567-4444 Ext.1494
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	15 of 15	NE/54.6	235.9 / 4.85	PARKLAND CORPORATION 675 MAIN ST N BRAMPTON ON	FST

Inventory No: 9831772
Inventory Status: Active
Installation Year:
Capacity: 181600
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:
Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	1 of 4	SW/98.0	229.9 / -1.15	A&P PHARMACY 10088 MCLAUGLIN ROAD BRAMPTON ON L7A 2X6	GEN

Generator No: ON1587863
SIC Code:
SIC Description:
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		PHARMACEUTICALS			
15	2 of 4	SW/98.0	229.9 / -1.15	EM2 Corp. 10088 McLaughin Road Brampton ON L6V 1A1	GEN
Generator No:		ON3361950			
SIC Code:					
SIC Description:					
Approval Years:		As of Jan 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		263 L			
Waste Class Name:		Misc. waste organic chemicals			
15	3 of 4	SW/98.0	229.9 / -1.15	2563119 Ontraio Inc 10088 McLaughlin Road Unit 14 Brampton ON L7A 2X6	GEN
Generator No:		ON9884074			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
15	4 of 4	SW/98.0	229.9 / -1.15	2563119 Ontraio Inc 10088 McLaughlin Road Unit 14 Brampton ON L7A 2X6	GEN
Generator No:		ON9884074			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

16 ***1 of 2*** ***NE/0.9*** ***236.0 / 4.98*** ***PREET PETROLEUM***
HWY 7 HWY 10
BRAMPTON ON L3M 1V1
DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9824366
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 10/7/2009 14:28
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

16 ***2 of 2*** ***NE/0.9*** ***236.0 / 4.98*** ***Bovaird Drive & Hwy #10, Brampton ON***
INC

Incident No: 424494
Incident ID:
Instance No:
Status Code:
Incident Status:
Incident Severity:
Task No: 2984920
Attribute Category: FS-Perform L1 Incident Insp
Context:
Date of Occurrence: 2010/07/20 00:00:00
Time of Occurrence: NULL
Occr Insp Start Dt: 2010/07/27 00:00:00
Incident Creat On:
Instance Creat Dt:
Instance Install Dt:
Approx Quant Rel:

Any Health Impact: No
Any Enviro Impact: No
Service Intrp: No
Was Prop Damaged: No
Reside App. Type:
Commer App. Type:
Indus App. Type:
Institut App. Type:
Depth Ground Cover:
Operation Pressure:
Equipment Type:
Equipment Model:
Serial No:
Cylinder Capacity:
Cylinder Cap Units:
Cylinder Mat Type:

Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Other	**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Diesel	**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:	NULL	**Tank Storage Type:**	
Prc Escalation Req:	NULL	**Tank Location Type:**	

Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: Bovaird Drive & Hwy #10, Brampton - Spill
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: complaint re training
Operation Type Involved: Retail Fuel Station (FS, SS, Multifunctional)

17	1 of 18	NE/69.0	234.9 / 3.85	**1672237 ONTARIO LTD** **9 BOVAIRD DR HWY 7 & 10 BYPASS** **BRAMPTON ON**	FSTH

License Issue Date: 3/1/2006
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--

Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1983
Corrosion Protection:

Capacity: 25000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	2 of 18	NE/69.0	234.9 / 3.85	RAMKUMAR ENTERPRISES INC 9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	FSTH

License Issue Date: 10/23/2008 12:12:00 PM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	3 of 18	NE/69.0	234.9 / 3.85	RAMKUMAR ENTERPRISES INC 9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10600882	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	29878	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	4 of 18	NE/69.0	234.9 / 3.85	RAMKUMAR ENTERPRISES INC 9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10600930	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	30125	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

17	5 of 18	NE/69.0	234.9 / 3.85	RAMKUMAR ENTERPRISES INC 9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10600984
Status: EXPIRED
Instance ID: 30613
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

17	6 of 18	NE/69.0	234.9 / 3.85	RAMKUMAR ENTERPRISES INC 9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10601028
Status: EXPIRED
Instance ID: 30678

Expired Date:
Max Hazard Rank:
Facility Location:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

17	7 of 18	NE/69.0	234.9 / 3.85	**MAC'S CONVENIENCE STORES INC.** **9 BOVAIRD DR E** **BRAMPTON ON**	FST

Inventory No:	11616620	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

17	8 of 18	NE/69.0	234.9 / 3.85	**MAC'S CONVENIENCE STORES INC.** **9 BOVAIRD DR E** **BRAMPTON ON**	FST

Inventory No:	11616626	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	22700	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

17	9 of 18	NE/69.0	234.9 / 3.85	**MAC'S CONVENIENCE STORES INC.** **9 BOVAIRD DR E** **BRAMPTON ON**	FST

Inventory No:	11616606	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Installation Year:	2000	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

17 | **10 of 18** | **NE/69.0** | **234.9 / 3.85** | **MAC'S CONVENIENCE STORES INC.**
9 BOVAIRD DR E
BRAMPTON ON | **FST**

Inventory No:	11616614	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

17 | **11 of 18** | **NE/69.0** | **234.9 / 3.85** | **Mac's Convenience Stores Inc.**
9 Bovaird Drive
Brampton ON L6V 0A2 | **GEN**

Generator No:	ON8852762
SIC Code:	
SIC Description:	
Approval Years:	As of Jul 2020
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

---

17 | **12 of 18** | **NE/69.0** | **234.9 / 3.85** | **Mac's Convenience Stores Inc.**
9 Bovaird Drive
Brampton ON L6V 0A2 | **GEN**

Generator No:	ON8852762
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

17 | ***13 of 18*** | ***NE/69.0*** | ***234.9 / 3.85*** | ***Mac's Convenience Stores Inc.***
9 Bovaird Drive
Brampton ON L6V 0A2 | ***GEN***

Generator No: ON8852762
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

17 | ***14 of 18*** | ***NE/69.0*** | ***234.9 / 3.85*** | ***RAMKUMAR ENTERPRISES INC***
9 BOVAIRD DR E
BRAMPTON ON | ***EXP***

Inventory No: 10600906
Inventory Status: EXPIRED
Installation Year: 1983
Capacity: 50000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

17 | ***15 of 18*** | ***NE/69.0*** | ***234.9 / 3.85*** | ***RAMKUMAR ENTERPRISES INC***
9 BOVAIRD DR E
BRAMPTON ON | ***EXP***

Inventory No: 10600851
Inventory Status: EXPIRED
Installation Year: 1983
Capacity: 50000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

17 | ***16 of 18*** | ***NE/69.0*** | ***234.9 / 3.85*** | ***RAMKUMAR ENTERPRISES INC***
9 BOVAIRD DR E | ***EXP***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON	

Inventory No:	10600959	***Tank Material:***	Steel
Inventory Status:	EXPIRED	***Corrosion Protect:***	Sacrificial anode
Installation Year:	1983	***Overfill Protection:***	
Capacity:	25000	***Inventory Context:***	FS Liquid Fuel Tank
Capacity Unit:		***Inventory Item:***	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

17	***17 of 18***	***NE/69.0***	***234.9 / 3.85***	***RAMKUMAR ENTERPRISES INC*** ***9 BOVAIRD DR E*** ***BRAMPTON ON***	***EXP***

Inventory No:	10601003	***Tank Material:***	Steel
Inventory Status:	EXPIRED	***Corrosion Protect:***	Sacrificial anode
Installation Year:	1983	***Overfill Protection:***	
Capacity:	25000	***Inventory Context:***	FS Liquid Fuel Tank
Capacity Unit:		***Inventory Item:***	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Diesel		

17	***18 of 18***	***NE/69.0***	***234.9 / 3.85***	***MAC'S CONVENIENCE STORES INC.*** ***9 BOVAIRD DR E*** ***BRAMPTON ON***	***FST***

Inventory No:	9841622	***Tank Material:***	
Inventory Status:	Active	***Corrosion Protect:***	
Installation Year:		***Overfill Protection:***	
Capacity:	161900	***Inventory Context:***	Liquid Fuels
Capacity Unit:	L	***Inventory Item:***	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			
Description:			

18	***1 of 7***	***NE/95.1***	***236.9 / 5.93***	***Rexall Pharmacy Group Ltd.*** ***10035 Hurontario Street*** ***Brampton ON L6Z 0E6***	***GEN***

Generator No:	ON8297638
SIC Code:	446110
SIC Description:	446110
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Erik Botines
Choice of Contact:	CO_ADMIN
Phone No Admin:	9055017800 Ext.
Contaminated Facility:	No
MHSW Facility:	No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	2 of 7	NE/95.1	236.9 / 5.93	**Pharma Plus Drugmarts Ltd** **10035 Hurontario Street** **Brampton ON L6Z 0E6**	GEN

Generator No: ON8297638
SIC Code: 446110
SIC Description: 446110
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Erik Botines
Choice of Contact: CO_ADMIN
Phone No Admin: 9055017800 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	3 of 7	NE/95.1	236.9 / 5.93	**Pharma Plus Drugmarts Ltd** **10035 Hurontario Street** **Brampton ON L6Z 0E6**	GEN

Generator No: ON8297638
SIC Code: 446110
SIC Description: 446110
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Aaron Schrama
Choice of Contact: CO_ADMIN
Phone No Admin: 905-502-5965 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	4 of 7	NE/95.1	236.9 / 5.93	**Rexall Pharmacy Group Ltd.** **10035 Hurontario Street** **Brampton ON L6Z 0E6**	GEN

Generator No: ON8297638
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

18 | ***5 of 7*** | ***NE/95.1*** | ***236.9 / 5.93*** | ***Rexall Pharmacy Group Ltd.***
10035 Hurontario Street
Brampton ON L6Z 0E6 | ***GEN***

Generator No: ON8297638
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

---

18 | ***6 of 7*** | ***NE/95.1*** | ***236.9 / 5.93*** | ***Rexall Pharmacy Group Ltd.***
10035 Hurontario Street
Brampton ON L6Z 0E6 | ***GEN***

Generator No: ON8297638
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			

18	7 of 7	NE/95.1	236.9 / 5.93	**Rexall Pharmacy Group Ltd.** **10035 Hurontario Street** **Brampton ON L6Z 0E6**	GEN

Generator No: ON8297638
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Unplottable Summary

Total: 9 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
DTNK	BRAMPTON BRICK SALES	HURONTARIO ST	BRAMPTON ON	
DTNK	AECON CONSTRUCTION AND MATERIAL LIMITED	LOT 11 CON 2 CHINGUACOUSY TWP	BRAMPTON ON	
DTNK	AECON CONSTRUCTION AND MATERIAL LIMITED	LOT 11 CON 2 CHINGUACOUSY TWP	BRAMPTON ON	
DTNK	BRAMPTON BRICK SALES	HURONTARIO ST	BRAMPTON ON	
DTNK	AECON CONSTRUCTION AND MATERIAL LIMITED	LOT 11 CON 2 CHINGUACOUSY TWP	BRAMPTON ON	
EXP	AECON CONSTRUCTION AND MATERIAL LIMITED	LOT 11 CON 2 CHINGUACOUSY TWP	BRAMPTON ON	
EXP	AECON CONSTRUCTION AND MATERIAL LIMITED	LOT 11 CON 2 CHINGUACOUSY TWP	BRAMPTON ON	
GEN	Ranac Forming Limited	Part Lot 11, Conc. 1 WHS West Side Hurontario St.	Brampton ON	
GEN	DOUG CHALMERS INC. 12-647	HWY 10 NORTH OF BOVAIRD, BRAMPTON C/O BOX 280	GEORGETOWN ON	L7G 4Y5

Unplottable Report

Site: ***BRAMPTON BRICK SALES***
HURONTARIO ST BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	11099172	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	68842	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Tank		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Site: ***AECON CONSTRUCTION AND MATERIAL LIMITED***
LOT 11 CON 2 CHINGUACOUSY TWP BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10597723	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	30209	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	

Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Piping Underground:
Tank Underground:
Source:

Site: ***AECON CONSTRUCTION AND MATERIAL LIMITED***
LOT 11 CON 2 CHINGUACOUSY TWP BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10597763
Status: EXPIRED
Instance ID: 29913
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Site: ***BRAMPTON BRICK SALES***
HURONTARIO ST BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9902445
Status: EXPIRED
Instance ID: 396057
Instance Type: FS Facility
Instance Creation Dt:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:

Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Cylr Handling Facility
Original Source: EXP
Record Date: Up to Mar 2012

Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Site: ***AECON CONSTRUCTION AND MATERIAL LIMITED***
LOT 11 CON 2 CHINGUACOUSY TWP BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9456898
Status: EXPIRED
Instance ID: 383741
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Gasoline Station - Full Serve
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Site: ***AECON CONSTRUCTION AND MATERIAL LIMITED***
LOT 11 CON 2 CHINGUACOUSY TWP BRAMPTON ON

Database: ***EXP***

Inventory No: 10597743
Inventory Status: EXPIRED

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass

Installation Year: 1991
Capacity: 45460
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2010V site is a PFO
Previous Fuel Type: Diesel

Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***AECON CONSTRUCTION AND MATERIAL LIMITED***
LOT 11 CON 2 CHINGUACOUSY TWP BRAMPTON ON

Database: ***EXP***

Inventory No: 10597696
Inventory Status: EXPIRED
Installation Year: 1991
Capacity: 45460
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2010V site is a PFO
Previous Fuel Type: Diesel

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***Ranac Forming Limited***
Part Lot 11, Conc. 1 WHS West Side Hurontario St. Brampton ON

Database: ***GEN***

Generator No: ON5213152
SIC Code:
SIC Description:
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Site: ***DOUG CHALMERS INC. 12-647***
HWY 10 NORTH OF BOVAIRD, BRAMPTON C/O BOX 280 GEORGETOWN ON L7G 4Y5

Database: ***GEN***

Generator No: ON1498000
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146

Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Nov 2023

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Apr 2024

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Apr 30, 2024

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2022

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Apr 30, 2024

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -May 2024

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-May 2024

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Jun 30, 2024

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Aug 2023

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Apr 30, 2024

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Jun 30, 2024

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Apr 30, 2024

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Mar 31, 2024

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2023

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Mar 2024

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: Oct 31, 2021

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2022

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: 31 Oct, 2023

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2024

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2022

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory 1993-2020: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Sep 2020

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-May 31, 2024

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2023

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Jun 30, 2024

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011-Apr 30, 2024

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Sep 2020

Potential PFAS Handlers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Sep 2020

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Jun 30, 2024

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004-Jun 2024

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Apr 30, 2024

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests. This database includes spill incidents that occurred in Mar 2023-Mar 2024 in addition to those listed in the Government Publication Date.

Government Publication Date: 1988-Jan 2023; see description

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2021

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2023

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Apr 30, 2024

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Dec 31 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

ERIS

DATABASE REPORT

Project Property:	*Kennedy Rd HEIP* *Kennedy Rd HEIP* *Brampton ON L6W*
Project No:	*P24-6347*
Report Type:	*Quote - Custom-Build Your Own Report*
Order No:	*24060400429*
Requested by:	*EnVision Consultants Ltd.*
Date Completed:	*July 18, 2024*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....90
Map.....184
Aerial.....185
Topographic Map.....186
Detail Report.....187
Unplottable Summary.....701
Unplottable Report.....705
Appendix: Database Descriptions.....748
Definitions.....758

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*Kennedy Rd HEIP* *Kennedy Rd HEIP Brampton ON L6W*
Project No:	*P24-6347*

Order Information:

Order No:	*24060400429*
Date Requested:	*June 4, 2024*
Requested by:	*EnVision Consultants Ltd.*
Report Type:	*Quote - Custom-Build Your Own Report*

Historical/Products:

ERIS Xplorer	*ERIS Xplorer*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
AAGR	Abandoned Aggregate Inventory	N	-	-	-
AGR	Aggregate Inventory	N	-	-	-
AMIS	Abandoned Mine Information System	N	-	-	-
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	3	3
BORE	Borehole	N	-	-	-
CA	Certificates of Approval	N	-	-	-
CDRY	Dry Cleaning Facilities	Y	0	3	3
CFOT	Commercial Fuel Oil Tanks	Y	0	1	1
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	N	-	-	-
CNG	Compressed Natural Gas Stations	N	-	-	-
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	N	-	-	-
CPU	Certificates of Property Use	N	-	-	-
DRL	Drill Hole Database	N	-	-	-
DTNK	Delisted Fuel Tanks	Y	0	67	67
EASR	Environmental Activity and Sector Registry	N	-	-	-
EBR	Environmental Registry	N	-	-	-
ECA	Environmental Compliance Approval	N	-	-	-
EEM	Environmental Effects Monitoring	N	-	-	-
EHS	ERIS Historical Searches	N	-	-	-
EIIS	Environmental Issues Inventory System	N	-	-	-
EMHE	Emergency Management Historical Event	N	-	-	-
EPAR	Environmental Penalty Annual Report	N	-	-	-
EXP	List of Expired Fuels Safety Facilities	Y	0	47	47
FCON	Federal Convictions	N	-	-	-
FCS	Contaminated Sites on Federal Land	N	-	-	-
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	59	59
FSTH	Fuel Storage Tank - Historic	Y	0	24	24
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	604	604
GHG	Greenhouse Gas Emissions from Large Facilities	N	-	-	-
HINC	TSSA Historic Incidents	N	-	-	-

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	9	9
LIMO	Landfill Inventory Management Ontario	N	-	-	-
MINE	Canadian Mine Locations	N	-	-	-
MNR	Mineral Occurrences	N	-	-	-
NATE	National Analysis of Trends in Emergencies System (NATES)	N	-	-	-
NCPL	Non-Compliance Reports	N	-	-	-
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	N	-	-	-
NEBI	National Energy Board Pipeline Incidents	N	-	-	-
NEBP	National Energy Board Wells	N	-	-	-
NEES	National Environmental Emergencies System (NEES)	N	-	-	-
NPCB	National PCB Inventory	Y	0	13	13
NPR2	National Pollutant Release Inventory 1993-2020	N	-	-	-
NPRI	National Pollutant Release Inventory - Historic	N	-	-	-
OGWE	Oil and Gas Wells	N	-	-	-
OOGW	Ontario Oil and Gas Wells	N	-	-	-
OPCB	Inventory of PCB Storage Sites	N	-	-	-
ORD	Orders	N	-	-	-
PAP	Canadian Pulp and Paper	N	-	-	-
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	N	-	-	-
PFCH	NPRI Reporters - PFAS Substances	N	-	-	-
PFHA	Potential PFAS Handlers from NPRI	N	-	-	-
PINC	Pipeline Incidents	N	-	-	-
PRT	Private and Retail Fuel Storage Tanks	N	-	-	-
PTTW	Permit to Take Water	N	-	-	-
REC	Ontario Regulation 347 Waste Receivers Summary	N	-	-	-
RSC	Record of Site Condition	N	-	-	-
RST	Retail Fuel Storage Tanks	Y	0	32	32
SCT	Scott's Manufacturing Directory	Y	0	40	40
SPL	Ontario Spills	Y	4	142	146
SRDS	Wastewater Discharger Registration Database	N	-	-	-
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	N	-	-	-
WDS	Waste Disposal Sites - MOE CA Inventory	N	-	-	-
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	N	-	-	-
WWIS	Water Well Information System	N	-	-	-

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
Total:			4	1,044	1,048

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
4	SPL	TRANSPORT TRUCK	AT CORNER OF SUN FOREST & BOVAIROL DR. MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	SSE/0.4	-0.62	18
4	SPL	The Corporation of the City of Brampton	Sun Forest Drive and Bovaird Drive Brampton ON	SSE/0.4	-0.62	187
12	SPL		BRAMPTON ON	WSW/0.2	7.54	188
118	SPL	The Regional Municipality of Peel	Hutchinson Farm Lane Caledon ON	WNW/0.5	27.37	189

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	SPL	PRIVATE OWNER	CONNESTOGA DRIVE/BOVAIRD DRIVE MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	E/30.7	0.37	190
2	GEN	PEEL BLOCK CO. LTD	307 BOVAIRD DR, BOX 297 BRAMPTON ON L6V 2L1	E/10.6	0.37	191
2	GEN	PEEL BLOCK CO. (OUT OF BUSINESS)	307 BOVAIRD DR, BOX 297 BRAMPTON ON L6V 2L1	E/10.6	0.37	191
2	GEN	PEEL BLOCK CO. (OUT OF BUSINESS) 30-205	307 BOVAIRD DR, BOX 297 BRAMPTON ON L6V 2L1	E/10.6	0.37	191
3	SPL	OSHAWA FOODS	380 BOVAIRD DRIVE TRANSPORT TRUCK (CARGO) BRAMPTON CITY ON	ENE/86.8	2.37	192
3	SPL	OSHAWA FOODS	380 BOVAIRD DRIVE - CONNESTOGA FOOD CITY TRANSPORT TRUCK (CARGO) BRAMPTON CITY ON	ENE/86.8	2.37	192
3	SPL	OSHAWA FOODS	380 BOVAIRD DRIVE RETAIL STORE BRAMPTON CITY ON	ENE/86.8	2.37	193
3	GEN	PHARMA PLUS DRUGS LTD.	380 BOVAIRD ROAD, UNIT 26 BRAMPTON ON L6Z 2N7	ENE/86.8	2.37	194
3	GEN	PHARMA PLUS DRUGS LTD. 31-803	380 BOVAIRD RD. UNIT 26 C/O 5935 AIRPORT ROAD STE. #500 MISSISSAUGA ON L4V 1W5	ENE/86.8	2.37	194
3	GEN	Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	ENE/86.8	2.37	195
3	GEN	Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	ENE/86.8	2.37	195

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
3	GEN	conestoga pharmacy inc	26-380 bovaird dr e brampton ON L6Z2S8	ENE/86.8	2.37	196
3	GEN	conestoga pharmacy inc	26-380 bovaird dr e brampton ON L6Z2S8	ENE/86.8	2.37	196
3	GEN	Sehdev Drugs Limited	26-380 Bovaird Drive East Brampton ON L6Z 2S8	ENE/86.8	2.37	197
3	GEN	Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	ENE/86.8	2.37	197
3	GEN	Sehdev Drugs Limited	26-380 Bovaird Drive East Brampton ON L6Z 2S8	ENE/86.8	2.37	197
3	GEN	Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	ENE/86.8	2.37	198
3	GEN	Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	ENE/86.8	2.37	198
3	GEN	Sehdev Drugs Limited	26-380 Bovaird Drive East Brampton ON L6Z 2S8	ENE/86.8	2.37	199
3	GEN	Sehdev Drugs Limited	26-380 Bovaird Drive East Brampton ON L6Z 2S8	ENE/86.8	2.37	199
3	GEN	Conestoga Dental Centre	380 bovaird dr east suite 23 brampton ON L6Z 2S7	ENE/86.8	2.37	199
5	GEN	PLATIS & SONS CLEANERS	1 WEXFORD ROAD, UNIT 1 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	200
5	GEN	PLATIS & SONS CLEANERS	1 WEXFORD ROAD UNIT 1 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	200
5	GEN	PLATIS & SONS 1 HOUR CLEANERS	1 WEXFORD ROAD BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	200

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
5	GEN	HASTY MARKET 19-675	1 WEXFORD ROAD, UNIT 9 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	201
5	GEN	HASTY MARKET	1 WEXFORD ROAD, UNIT 9 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	201
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford St, Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	202
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	202
5	SPL		1 Wexford Rd Brampton ON	WSW/98.4	7.37	202
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON	WSW/98.4	7.37	203
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON	WSW/98.4	7.37	204
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	WSW/98.4	7.37	204
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON	WSW/98.4	7.37	204
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON	WSW/98.4	7.37	205
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	WSW/98.4	7.37	205
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON	WSW/98.4	7.37	206
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON	WSW/98.4	7.37	206

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	WSW/98.4	7.37	206
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	207
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	207
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON	WSW/98.4	7.37	207
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON	WSW/98.4	7.37	208
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON	WSW/98.4	7.37	208
5	GEN	First Choice MedCentre Inc.	1 Wexford Rd. Unit 8 Brampton ON	WSW/98.4	7.37	209
5	GEN	wexford square dental	1 wexford road ,unit #7 brampton ON L6Z2W1	WSW/98.4	7.37	209
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	209
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	WSW/98.4	7.37	210
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	210
5	GEN	wexford square dental	1 wexford road ,unit #7 brampton ON L6Z2W1	WSW/98.4	7.37	211
5	GEN	Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	WSW/98.4	7.37	211

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	WSW/98.4	7.37	211
5	GEN	Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	WSW/98.4	7.37	212
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	212
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	212
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	213
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	213
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	WSW/98.4	7.37	214
5	GEN	Dawson DCC-Wexford Square Dental	1 Wexford Road Unit 7 Brampton ON L6Z2W1	WSW/98.4	7.37	214
5	GEN	MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	214
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	WSW/98.4	7.37	215
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	215
5	GEN	Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	WSW/98.4	7.37	216
5	CDRY	Magic Touch Dry Cleaners	1 Wexford Rd Brampton ON L6Z2W1	WSW/98.4	7.37	216

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
5	GEN	Dawson DCC-Wexford Square Dental	1 Wexford Road Unit 7 Brampton ON L6Z2W1	WSW/98.4	7.37	216
5	GEN	Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	WSW/98.4	7.37	217
5	GEN	11244485 Canada Inc.	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	217
5	GEN	Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	WSW/98.4	7.37	217
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	218
5	GEN	11244485 Canada Inc.	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	218
5	GEN	Dawson DCC-Wexford Square Dental	1 Wexford Road Unit 7 Brampton ON L6Z2W1	WSW/98.4	7.37	218
5	GEN	Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	WSW/98.4	7.37	219
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	219
5	GEN	Mackenzie Medical Rehab	Mackenzie Medical Rehab 1 Wexford Road Unit 8 Brampton ON L6Z2W1	WSW/98.4	7.37	220
5	GEN	Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	WSW/98.4	7.37	220
5	GEN	Dawson DCC-Wexford Square Dental	1 Wexford Road Unit 7 Brampton ON L6Z2W1	WSW/98.4	7.37	220
5	GEN	11244485 Canada Inc.	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	WSW/98.4	7.37	221

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
5	GEN	Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	WSW/98.4	7.37	221
6	GEN	FORTINO'S SUPERMARKET LTD.	60 QUARRY EDGE DRIVE HIGHWAY 10 & BOVAIRD DRIVE BRAMPTON ON L6V 1K2	SSE/92.3	-1.60	221
6	SPL	Fortino's Supermarket<UNOFFICIAL>	#60 Quarry Edge Drive Brampton ON L6V 4K2	SSE/92.3	-1.60	222
6	SPL	Loblaw Properties Limited	60 Quarry Edge Dr Brampton ON L6V 4K2	SSE/92.3	-1.60	223
6	SPL	Loblaw Properties Limited	60 Quarry Edge Dr Brampton ON L6V 4K2	SSE/92.3	-1.60	223
6	SPL	Neelands Refrigeration Limited	60 Quarry Edge Brampton ON L6V 4K2	SSE/92.3	-1.60	224
6	SPL	Neelands Refrigeration Limited	60 Quarry Edge Dr Brampton ON L6V 4K2	SSE/92.3	-1.60	225
6	SPL	Fortinos (Highway 10 & Bovaird 2006) Ltd.	60 Quarry Edge Dr Brampton ON L6V 4K2	SSE/92.3	-1.60	226
6	SPL		60 Quarry Edge Brampton ON	SSE/92.3	-1.60	227
6	SPL	Fortino's Supermarket<UNOFFICIAL>	60 Quarry Edge Drive Brampton ON	SSE/92.3	-1.60	227
6	SPL	Neelands Refrigeration Limited	60 Quarry Edge Dr. Brampton ON	SSE/92.3	-1.60	228
6	SPL	Fortinos Supermarket Ltd<UNOFFICIAL>	60 Quarry Edge Dr Brampton ON	SSE/92.3	-1.60	229
6	SPL	Fortinos (Highway 10 & Bovaird 2006) Ltd.	60 Quarry Edge Dr Brampton ON L6V 4K2	SSE/92.3	-1.60	230

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
6	SPL	Neelands Refrigeration Limited	60 Quarry Edge Dr Brampton ON	SSE/92.3	-1.60	231
6	GEN	Loblaw Companies Inc	60 Quarry Edge Dr. Brampton ON L6V 4K2	SSE/92.3	-1.60	231
6	GEN	Loblaw Companies Inc	60 Quarry Edge Dr. Brampton ON L6V 4K2	SSE/92.3	-1.60	232
6	GEN	LOBLAWS INC. Fortinos	60 Quarry Edge Dr. Brampton ON L6V 4K2	SSE/92.3	-1.60	232
6	GEN	LOBLAWS INC. Fortinos	60 Quarry Edge Dr. Brampton ON L6V 4K2	SSE/92.3	-1.60	233
6	GEN	LOBLAWS INC. Fortinos	60 Quarry Edge Dr. Brampton ON L6V 4K2	SSE/92.3	-1.60	233
6	GEN	LOBLAWS INC. Fortinos	60 Quarry Edge Dr. Brampton ON L6V 4K2	SSE/92.3	-1.60	233
7	SPL		29 Parkholme Place Brampton ON L6V 4G3	E/41.6	3.37	234
8	SPL		67 Wildercroft Ave Brampton ON	E/98.4	2.33	235
9	SCT	Cribben Inc.	10025 Hurontario St Unit 11 Brampton ON L6Z 0E8	SSW/67.9	3.35	235
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	236
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	236
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	237

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON	SSW/67.9	3.35	237
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	237
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	238
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	238
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	239
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	239
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	240
9	GEN	Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	SSW/67.9	3.35	240
10	GEN	PETM Canada Corporation	76 Quarry Edge Dr brampton ON L6V4K2	S/49.5	1.37	241
10	GEN	PETM Canada Corporation	76 Quarry Edge Dr brampton ON L6V4K2	S/49.5	1.37	241
10	GEN	PETM Canada Corporation	76 Quarry Edge Dr brampton ON L6V4K2	S/49.5	1.37	242
11	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	SSW/73.7	4.44	243
11	GEN	Pharma Plus Drugmarts Ltd	10035 Hurontario Street Brampton ON L6Z 0E6	SSW/73.7	4.44	243

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	GEN	Pharma Plus Drugmarts Ltd	10035 Hurontario Street Brampton ON L6Z 0E6	SSW/73.7	4.44	243
11	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	SSW/73.7	4.44	244
11	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	SSW/73.7	4.44	244
11	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	SSW/73.7	4.44	245
11	GEN	Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	SSW/73.7	4.44	245
13	SPL	Emterra Environmental	136 Sandmere Avenue, Brampton Brampton ON	W/68.0	6.24	245
14	SPL	CANADIAN WASTE SERVICES	KENNEDY AND BOVAIRD MOTOR VEHICLE (CARGO) BRAMPTON CITY ON	ENE/9.3	6.50	246
15	RST	SHELL CANADA PRODUCTS LIMITED	10178 HURONTARIO ST BRAMPTON ON L6V1A1	WSW/67.1	7.85	247
15	RST	PENNZOIL 10 MINUTE OIL CHANGE	10178 HURONTARIO ST BRAMPTON ON L7A 0E4	WSW/67.1	7.85	247
15	FSTH	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON L7A 0E4	WSW/67.1	7.85	247
15	FSTH	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON L7A 0E4	WSW/67.1	7.85	248
15	DTNK	AUTO BATH INC	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	249
15	DTNK	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	249

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
15	DTNK	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	250
15	DTNK	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	251
15	FST	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST BRAMPTON ON	WSW/67.1	7.85	251
15	FST	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST BRAMPTON ON	WSW/67.1	7.85	251
15	RST	PENNZOIL 10 MINUTE OIL CHANGE	10178 HURONTARIO ST BRAMPTON ON L7A0E4	WSW/67.1	7.85	252
15	EXP	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	252
15	EXP	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	252
15	EXP	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	253
15	EXP	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	253
15	EXP	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	WSW/67.1	7.85	253
15	FST	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST BRAMPTON ON	WSW/67.1	7.85	253
16	GEN	CT REIT (Hurontario) Limited Partnership, by its g	10254 Hurontario Street Brampton ON L7A 0E4	WSW/54.1	6.29	254
16	GEN	CT REIT (Hurontario) Limited Partnership, by its g	10254 Hurontario Street Brampton ON L7A 0E4	WSW/54.1	6.29	254

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
17	SPL	Chester Cartage	10086 Hurontario Street Brampton ON	SW/80.5	6.83	255
17	GEN	The Sherwin-Williams Company	10086 Hurontario Street Units 15 & 16 Brampton ON L7A 1E5	SW/80.5	6.83	256
17	GEN	The Sherwin-Williams Company	10086 Hurontario Street Units 15 & 16 Brampton ON L7A 1E5	SW/80.5	6.83	256
18	RST	PEEL CO-OP TRUE VALUE	10064 HURONTARIO BRAMPTON ON L6V 1A1	SW/59.4	6.41	256
18	SPL	TRANSPORT TRUCK	10064 HURONTARIO STREET MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L6V 1A1	SW/59.4	6.41	256
18	RST	PEEL CO-OP TRUE VALUE	10064 HURONTARIO ST BRAMPTON ON L6V 1A1	SW/59.4	6.41	257
18	RST	PEEL SEED CO-OP	10064 HURONTARIO ST BRAMPTON ON L7A 0E4	SW/59.4	6.41	257
18	DTNK	PEEL SEED CO-OPERATIVE INC	10064 HURONTARIO ST BRAMPTON ON	SW/59.4	6.41	258
18	RST	PEEL SEED CO-OP	10064 HURONTARIO ST BRAMPTON ON	SW/59.4	6.41	258
19	FSTH	1672237 ONTARIO LTD	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	S/40.6	2.37	258
19	FSTH	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	S/40.6	2.37	259
19	DTNK	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	S/40.6	2.37	260
19	DTNK	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	S/40.6	2.37	260

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
19	DTNK	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	S/40.6	2.37	261
19	DTNK	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	S/40.6	2.37	262
19	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	262
19	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	263
19	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	263
19	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	263
19	GEN	Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	S/40.6	2.37	263
19	GEN	Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	S/40.6	2.37	264
19	GEN	Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	S/40.6	2.37	264
19	EXP	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	264
19	EXP	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	265
19	EXP	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	265
19	EXP	RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	265

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
19	FST	MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	S/40.6	2.37	265
20	SPL	WIMPEY	CONSTRUCTION SITE AT HWY #7 & HWY #10. PORTABLE FUEL STORAGE TANK BRAMPTON CITY ON	SSW/6.8	3.56	266
20	SPL	TRIMAC	10 SIDE RD. HWY 10 AND 7 TANK TRUCK (CARGO) BRAMPTON CITY ON	SSW/6.8	3.56	266
20	SPL		Hwy. 10 & Bovaird St. Brampton ON	SSW/6.8	3.56	267
20	SPL		SE corner of Highway 10 (Hurontario St.) and Highway 7 (Bovaird Dr.) Brampton ON	SSW/6.8	3.56	268
20	DTNK	PREET PETROLEUM	HWY 7 HWY 10 BRAMPTON ON L3M 1V1	SSW/6.8	3.56	269
20	INC		Bovaird Drive & Hwy #10, Brampton ON	SSW/6.8	3.56	269
20	SPL	Stewart Foodservice Inc.	NW corner of Bovaird Dr W & Hurontario St Brampton ON	SSW/6.8	3.56	270
21	SPL	Enbridge Gas Distribution Inc.	16 Tremblay Street Brampton ON	W/86.0	8.37	271
22	SPL	PRIVATE RESIDENCE	142 SIMMONS BLVD SEWAGE/SEPTIC SYSTEM BRAMPTON CITY ON L6V 3W4	ENE/88.3	4.45	272
23	RST	DAVE'S GAS DEPOT	30 HWY 7 W BRAMPTON ON	SSW/81.7	4.75	273
23	RST	DAVE'S GAS DEPOT	30 BOVAIRD DR W BRAMPTON ON L6V 1A1	SSW/81.7	4.75	273
23	GEN	Regionional Municipality of Peel	2 - 30 Bovaird Drive West Brampton ON L7A 0H3	SSW/81.7	4.75	273

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
23	SPL		30 Hwy 7 W now 30 Bovaird Drive Brampton ON	SSW/81.7	4.75	273
23	GEN	Regional Municipality of Peel	2 - 30 Bovaird Drive West Brampton ON L7A 0H3	SSW/81.7	4.75	274
23	GEN	Pinchin Ltd.	2-30 Bovaird Drive West Brampton ON L7A 0H3	SSW/81.7	4.75	274
24	RST	PIONEER PETROLEUM	675 MAIN ST N BRAMPTON ON L6V1A1	SSW/54.6	3.37	275
24	RST	PIONEER PETROLEUM	675 MAIN N BRAMPTON ON	SSW/54.6	3.37	275
24	RST	PIONEER PETROLEUMS	675 MAIN ST N BRAMPTON ON L6X 0G6	SSW/54.6	3.37	275
24	FSTH	PIONEER PETROLEUMS MANAGEMENT INC**	675 MAIN ST N BRAMPTON ON L6X 0G6	SSW/54.6	3.37	275
24	FSTH	PIONEER PETROLEUMS MANAGEMENT INC**	675 MAIN ST N BRAMPTON ON L6X 0G6	SSW/54.6	3.37	276
24	DTNK	PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	SSW/54.6	3.37	277
24	DTNK	PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	SSW/54.6	3.37	277
24	DTNK	PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	SSW/54.6	3.37	278
24	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	SSW/54.6	3.37	278
24	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	SSW/54.6	3.37	279

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
24	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	SSW/54.6	3.37	279
24	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	SSW/54.6	3.37	279
24	RST	PIONEER PETROLEUMS	675 MAIN ST N BRAMPTON ON L6X0G6	SSW/54.6	3.37	279
24	GEN	Pioneer Energy LP	675 Main Street North Brampton ON L6X 0G6	SSW/54.6	3.37	280
24	FST	PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	SSW/54.6	3.37	280
25	SPL	Enbridge Gas Distribution Inc.	10370 Hurontario Street Brampton ON	W/63.5	7.37	280
26	GEN	Mandarano/Vilone Property	10394 Hurontario Street North Brampton ON L7A 0E4	W/56.3	6.96	281
27	SPL		13 Crosswood Lane BRAMPTON ON	E/65.0	6.40	281
28	SPL	Enbridge Gas Distribution Inc.	23 Histon Cres. Brampton ON	E/80.8	7.37	282
29	GEN	New Image Car Wash	11 Fisherman Dr Brampton ON L7A2X9	W/80.9	6.29	283
30	GEN	MAYFIELD DRYWALL AND CONTRACTING	13 FISHERMAN DR BRAMPTON ON L7A 2X9	W/97.7	5.80	283
31	SPL	TRANSPORT TRUCK	FISCHERMAN DRIVE & HWY 10 MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	W/7.2	7.37	284
32	SPL		60 Buckland Way, Brampton, ON BRAMPTON ON	E/77.8	7.37	284

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
33	SCT	LAGRAN CANADA INC.	2 FISHERMAN DR SUITE 1102 BRAMPTON ON L7A 1B5	W/57.0	4.87	285
33	RST	PENNZOIL 10 MINUTE OIL CHANGE CENTRE	2 FISHERMAN DR BRAMPTON ON L7A 1B5	W/57.0	4.87	285
33	GEN	Centric Health	2 Fisherman Drive, Unit 7 Brampton ON	W/57.0	4.87	286
33	RST	PENNZOIL 10 MINUTE OIL CHANGE CENTRE	2 FISHERMAN DR BRAMPTON ON L7A1B5	W/57.0	4.87	286
33	GEN	Centric Health	2 Fisherman Drive, Unit 7 Brampton ON	W/57.0	4.87	286
33	GEN	Stephenson's Rental Services Inc.	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	W/57.0	4.87	286
33	GEN	Centric Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	W/57.0	4.87	287
33	GEN	Centric Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	W/57.0	4.87	287
33	GEN	Stephenson's Rental Services Inc.	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	W/57.0	4.87	288
33	GEN	Centric Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	W/57.0	4.87	288
33	GEN	Stephenson's Rental Services Inc. Brampton 109	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	W/57.0	4.87	289
33	GEN	Lifemark Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	W/57.0	4.87	289
33	GEN	Lifemark Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	W/57.0	4.87	290

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
33	GEN	Stephenson's Rental Services Inc. Brampton 109	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	W/57.0	4.87	290
33	GEN	Stephenson's Rental Services Inc. Brampton 109	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	W/57.0	4.87	291
33	GEN	Lifemark Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	W/57.0	4.87	292
33	GEN	Lifemark Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	W/57.0	4.87	292
33	GEN	Stephenson's Rental Services Inc. Brampton 109	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	W/57.0	4.87	292
34	SPL	Enbridge Gas Inc.	76 Blackthorn Lane Brampton ON	ESE/63.0	4.85	293
35	GEN	Belfor Property Restoration	10545 Hurontario Street Brampton ON L6Z 2V9	WNW/62.3	5.53	294
36	RST	PETRO CANADA	5 SANDALWOOD PKY W BRAMPTON ON L7A 1J6	WNW/77.5	0.69	294
36	FSTH	PAUL PAUAO	5 SANDALWOOD PKWY W BRAMPTON ON L7A 1J6	WNW/77.5	0.69	294
36	FSTH	PAUL PAUAO	5 SANDALWOOD PKWY W BRAMPTON ON L7A 1J6	WNW/77.5	0.69	295
36	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	WNW/77.5	0.69	295
36	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	WNW/77.5	0.69	295
36	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	WNW/77.5	0.69	296

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
36	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	WNW/77.5	0.69	296
36	RST	PETRO CANADA	5 SANDALWOOD PKY W BRAMPTON ON L7A1J6	WNW/77.5	0.69	296
36	SPL	Petro Canada Retail Fuel Facility<UNOFFICIAL>	5 Sandalwood Parkway Brampton ON	WNW/77.5	0.69	296
36	INC	SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	WNW/77.5	0.69	297
36	INC	SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKWY W,,BRAMPTON, ON,L7A 1J6,CA ON	WNW/77.5	0.69	298
36	SPL		5 Sandlewood Pkwy W, Brampton BRAMPTON ON	WNW/77.5	0.69	299
36	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	WNW/77.5	0.69	300
37	SPL	DOUG CHALMERS INC.	ETOBICOKE CREEK HURONTARIO/SANDALWOOD PARKWAY BRAMPTON STORAGE DEPOT HIGHWAY 10 BRAMPTON CITY ON	WNW/9.8	1.66	300
37	SPL	Canada Drayage<UNOFFICIAL>	HWY 10 & SANDALWOOD PKWY<UNOFFICIAL> Brampton ON	WNW/9.8	1.66	301
37	SPL		Sandalwood and Hurontario Brampton ON	WNW/9.8	1.66	302
38	SPL	The Regional Municipality of Peel	78 Skegby Rd Brampton ON L6V 2T9	ESE/63.6	2.37	302
39	SPL		338 Hansen Road North, Brampton BRAMPTON ON	ESE/78.5	1.45	303

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
40	GEN	CAT SEE & USE ON0007801 CATERPILLAR	100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	WNW/89.2	7.22	304
40	GEN	CATERPILLAR OF CANADA LTD.	100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	WNW/89.2	7.22	304
40	GEN	CATERPILLAR OF CANADA LTD. 09-075	100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	WNW/89.2	7.22	305
40	GEN	CATERPILLAR OF CANADA LIMITED	100 SANDALWOOD PARKWAY BRAMPTON ON L6V 3Y4	WNW/89.2	7.22	305
40	GEN	Exel Canada Ltd.	100 Sandalwood Parkway West. Brampton ON L7A 1A8	WNW/89.2	7.22	306
40	GEN	Orlando Corporation	100 Sandalwood Drive Brampton ON L7A 1A8	WNW/89.2	7.22	306
40	DTNK	CATERPILLAR OF CANADA LTD	100 SANDALWOOD PKWY CORNER OF HWY 1O BRAMPTON ON	WNW/89.2	7.22	306
40	GEN	Exel Logistics-Canada Inc	100 Sanalwood parkway Brampton ON	WNW/89.2	7.22	307
40	GEN	KELLOGG'S	100 SANDALWOOD PARKWAY WEST BRAMPTON ON L7A 1A8	WNW/89.2	7.22	307
40	SPL		100 Sandalwood Pkwy W, Brampton BRAMPTON ON	WNW/89.2	7.22	308
41	SPL	Enbridge Energy Distribution Inc.	36 Skegsby Rd Brampton ON	ESE/76.5	0.37	308
42	SPL	Alectra Utilities Corporation	17 Trewartha Cres Brampton ON	WNW/97.3	7.37	309

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
43	SPL		111 Greene Dr. Brampton, ON. BRAMPTON ON	ESE/24.6	-0.94	310
44	SPL	Enbridge Gas Distribution Inc.	40 Greene Drive Brampton ON L6V 2R7	ESE/78.7	-2.17	311
45	GEN	Kennedy Road Tabernacle	141 Kennedy Road N Brampton ON L6V 1X9	ESE/41.4	-2.63	312
46	SPL	Terra HX Inc.	39 Greene Drive, Brampton BRAMPTON ON	ESE/62.4	-2.63	312
47	SPL	PROVMAR FUELS INC.	140 KENNEDY ROAD TANK TRUCK (CARGO) BRAMPTON CITY ON	ESE/42.3	-2.63	313
47	RST	BASHAR ENTERPRISES INC	140 KENNEDY RD N BRAMPTON ON L6V2N4	ESE/42.3	-2.63	313
47	RST	ESSO MAXIMUM	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/42.3	-2.63	314
47	RST	MANN MANJIT	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/42.3	-2.63	314
47	FSTH	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/42.3	-2.63	314
47	FSTH	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON L6V 2N4	ESE/42.3	-2.63	315
47	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	316
47	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	316
47	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	317

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
47	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	318
47	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	318
47	DTNK	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	319
47	FST	MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	319
47	FST	MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	320
47	FST	MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	320
47	RST	MANN MANJIT	140 KENNEDY RD N BRAMPTON ON L6V2N4	ESE/42.3	-2.63	320
47	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	320
47	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	321
47	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	321
47	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	321
47	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	321
47	EXP	ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	322

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
47	FST	MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	ESE/42.3	-2.63	322
48	RST	PETRO-CANADA	KENNEDY N & VODDEN BRAMPTON ON L6V 1X7	ESE/19.3	-3.23	322
49	RST	KENNEDY & VODDEN PETRO CANADA	121 KENNEDY RD N BRAMPTON ON L6V 1X7	ESE/69.3	-3.63	322
49	RST	PERFECT LUBE	121 KENNEDY RD N BRAMPTON ON L6V 1X7	ESE/69.3	-3.63	322
49	DTNK	SIMCOE ENERGY & TECHNICAL SERVICES INC *	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	323
49	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	323
49	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	323
49	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	324
49	RST	KENNEDY & VODDEN PETRO CANADA	121 KENNEDY RD N BRAMPTON ON L6V1X7	ESE/69.3	-3.63	324
49	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	324
49	GEN	Suncor Energy Products	121 Kennedy Road N Brampton ON L6V1X	ESE/69.3	-3.63	324
49	GEN	Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	ESE/69.3	-3.63	325
49	GEN	Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	ESE/69.3	-3.63	325

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
49	GEN	Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	ESE/69.3	-3.63	326
49	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	326
49	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	326
49	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	327
49	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	327
49	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	ESE/69.3	-3.63	327
50	SPL	The Corporation of the City of Brampton	225 Vodden St E Brampton ON L6V 4M1	ESE/69.4	-3.63	327
51	GEN	PHARMA PLUS DRUGS LTD	227 VODDEN STREET BRAMPTON ON L6V 1N2	ESE/89.9	-3.63	328
51	GEN	PHARMA PLUS DRUGS LTD. 31-751	227 VODDEN ST., BRAMPTON C/O 5935 AIRPORT ROAD #500 MISSISSAUGA ON L4V 1W5	ESE/89.9	-3.63	329
51	GEN	PHARMA PLUS DRUGMARTS LTD.	227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	ESE/89.9	-3.63	329
51	GEN	GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.	FOOD BASICS #983 227 VODDEN STREET BRAMPTON ON L6V 1N2	ESE/89.9	-3.63	329
51	GEN	PHARMA PLUS DRUGS LTD.	227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	ESE/89.9	-3.63	330
51	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/89.9	-3.63	330

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
51	GEN	1723525 Ontario Inc.	227 Vodden Street East Unit 30B Brampton ON	ESE/89.9	-3.63	330
51	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/89.9	-3.63	331
51	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/89.9	-3.63	331
51	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON	ESE/89.9	-3.63	331
51	INC		227 VODDEN STREET EAST, BRAMPTON ON	ESE/89.9	-3.63	332
51	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/89.9	-3.63	333
51	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/89.9	-3.63	333
51	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/89.9	-3.63	333
51	GEN	Pharma Plus Drugmarts Ltd	227 Vodden Street East Brampton ON L6V 1N2	ESE/89.9	-3.63	334
51	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/89.9	-3.63	334
51	GEN	Pharma Plus Drugmarts Ltd	227 Vodden Street East Brampton ON L6V 1N2	ESE/89.9	-3.63	334
51	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/89.9	-3.63	335
51	GEN	Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	ESE/89.9	-3.63	335

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
51	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/89.9	-3.63	336
51	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/89.9	-3.63	336
51	GEN	Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	ESE/89.9	-3.63	336
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	337
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton, ON L7A 3R9	WNW/93.3	13.37	337
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	338
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton, ON L7A 3R9	WNW/93.3	13.37	338
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	338
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton, ON	WNW/93.3	13.37	339
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON	WNW/93.3	13.37	339
52	GEN	Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	WNW/93.3	13.37	339
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	WNW/93.3	13.37	340
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	WNW/93.3	13.37	340

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	340
52	GEN	Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	WNW/93.3	13.37	341
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	341
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	342
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton, ON L7A 3R9	WNW/93.3	13.37	342
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	WNW/93.3	13.37	342
52	GEN	Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	WNW/93.3	13.37	343
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	343
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	WNW/93.3	13.37	343
52	GEN	Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	WNW/93.3	13.37	344
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	344
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	345
52	GEN	Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	WNW/93.3	13.37	345

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
52	GEN	Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	WNW/93.3	13.37	345
52	GEN	Mulla/Suppal Prof Med Corp	A7 10886 Hurontario St, North Brampton ON L7A3R9	WNW/93.3	13.37	346
52	GEN	Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	WNW/93.3	13.37	346
52	GEN	Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	WNW/93.3	13.37	346
53	SPL		50 Settler Crescent, Brampton BRAMPTON ON	WNW/94.5	11.37	347
54	SCT	San/Luca Bakery & Restaurant Inc.	23 Conservation Dr Brampton ON L6Z 4R3	WNW/75.8	12.12	348
54	GEN	Heart Lake Veterinary Hospital Professional Corp	23 Conservation Drive # 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	348
54	GEN	Heart Lake Veterinary Hospital Professional Corp	23 Conservation Drive # 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	348
54	GEN	Heart Lake Veterinary Hospital Professional Corp	23 Conservation Drive # 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	349
54	GEN	Heart Lake Veterinary Hospital Professional Corp	23 Conservation Drive # 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	349
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON	WNW/75.8	12.12	350
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON	WNW/75.8	12.12	350
54	GEN	Michelle Omura Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	WNW/75.8	12.12	350

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
54	GEN	Michelle Omura Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	WNW/75.8	12.12	351
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	351
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	351
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	352
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	352
54	GEN	Michelle Omura Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	WNW/75.8	12.12	353
54	GEN	Michelle Omura Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	WNW/75.8	12.12	353
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	354
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	354
54	GEN	Wang Dagenais Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	WNW/75.8	12.12	354
54	GEN	123 Dentist Inc. o/a iSmile Dental Centre (North)	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	WNW/75.8	12.12	355
54	GEN	Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	WNW/75.8	12.12	355
55	GEN	2049078 ONTARIO INC.	87 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X7	ESE/42.2	-6.08	355

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
56	DTNK	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON L6V 1A1	WNW/61.8	13.44	356
56	DTNK	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	WNW/61.8	13.44	356
56	DTNK	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	WNW/61.8	13.44	357
56	DTNK	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	WNW/61.8	13.44	358
56	DTNK	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	WNW/61.8	13.44	358
56	EXP	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	WNW/61.8	13.44	359
56	EXP	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	WNW/61.8	13.44	359
56	EXP	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	WNW/61.8	13.44	359
56	EXP	ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	WNW/61.8	13.44	360
57	SPL	Hydro One Brampton Networks Inc.	8 Hambley Court Brampton ON	WNW/94.7	12.52	360
58	FST	MAC'S CONVENIENCE STORES INC.	230 WANLESS DR BRAMPTON ON	WNW/93.0	16.37	361
58	FST	MAC'S CONVENIENCE STORES INC.	230 WANLESS DR BRAMPTON ON	WNW/93.0	16.37	361
58	GEN	Peel Medical Centre	Unit 1- 230 Wanless Drive Brampton ON L7A 0X1	WNW/93.0	16.37	361

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
58	FST	MAC'S CONVENIENCE STORES INC.	230 WANLESS DR BRAMPTON ON	WNW/93.0	16.37	361
59	SPL	CONTRACTOR	HWY 10 && PERTH ST (N.O.S.) BRAMPTON ON	WNW/2.5	17.37	362
60	GEN	PEEL BOARD OF EDUCATION	CENTRAL PEEL S.S. 32 KENNEDY ROAD N. BRAMPTON ON L6V 1X4	ESE/70.7	-8.51	362
60	GEN	PEEL BOARD OF EDUCATION 30-189	CENTRAL PEEL SECONDARY SCHOOL 32 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	ESE/70.7	-8.51	363
60	GEN	PEEL DISTRICT SCHOOL BOARD	CENTRAL PEEL SECONDARY SCHOOL 32 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	ESE/70.7	-8.51	364
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	364
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON	ESE/70.7	-8.51	365
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON	ESE/70.7	-8.51	365
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON	ESE/70.7	-8.51	366
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	367
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON	ESE/70.7	-8.51	367
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	368

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	369
60	GEN	Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	369
60	GEN	Peel District School Board Human Resources Support Services	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	370
60	SPL	Peel District School Board	32 Kennedy Road N Brampton ON	ESE/70.7	-8.51	371
60	GEN	Peel District School Board Human Resources Support Services	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	371
60	INC	CENTRAL PEEL SECONDARY SCHOOL	32 KENNEDY RD N BRAMPTON ON	ESE/70.7	-8.51	372
60	GEN	Peel District School Board Human Resources Support Services	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	373
60	GEN	Peel District School Board Human Resources Support Services	32 Kennedy Road North Brampton ON L6V 1X4	ESE/70.7	-8.51	374
61	GEN	PEEL BOARD OF EDUCATION	INDEC NORTH 30 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	ESE/84.5	-8.69	374
61	GEN	PEEL DISTRICT SCHOOL BOARD	INDEC NORTH 30 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	ESE/84.5	-8.69	375
61	GEN	PEEL DISTRICT SCHOOL BOARD	INDEC NORTH 30 Kennedy Road BRAMPTON ON L6V 1X4	ESE/84.5	-8.69	375
62	GEN	Rosedale Dental Care	55 Kennedy Road North Brampton ON L6V 1X6	ESE/80.0	-8.02	376
63	CFOT	BELL CANADA	11450 HURONTARIO ST. BRAMPTON ON	WNW/51.0	17.37	376

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
64	SPL	2041409 Ontario Ltd.	11482 Hurontario St Brampton ON L7A 1E6	WNW/61.9	17.37	376
65	SPL		7 Charles Street Brampton ON	ESE/86.0	-8.71	377
66	SPL	Elias Gessen Eastown<UNOFFICIAL>	26 Kennedy Rd North Brampton ON L6V 1X4	ESE/97.4	-9.97	378
66	GEN	IRVING GARTEN	16-26 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	ESE/97.4	-9.97	379
67	GEN	Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	WNW/49.4	16.83	379
67	GEN	Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	WNW/49.4	16.83	379
67	GEN	Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	WNW/49.4	16.83	380
67	GEN	Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	WNW/49.4	16.83	380
67	GEN	Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON	WNW/49.4	16.83	380
67	GEN	Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	WNW/49.4	16.83	381
67	GEN	Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	WNW/49.4	16.83	381
67	GEN	Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	WNW/49.4	16.83	382
67	GEN	Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	WNW/49.4	16.83	382

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
67	GEN	Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	WNW/49.4	16.83	382
67	GEN	Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	WNW/49.4	16.83	383
67	GEN	Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	WNW/49.4	16.83	383
68	GEN	PARKINSON COACH LINES LTD.	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	ESE/41.4	-9.86	384
68	GEN	PARKINSON COACH LINES LTD.	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	ESE/41.4	-9.86	384
68	GEN	PARKINSON COACH LINES LTD. 30-262	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	ESE/41.4	-9.86	384
68	GEN	PARKINSON COACH LINES LTD.	10 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	ESE/41.4	-9.86	385
68	GEN	PARKINSON COACH LINES 2000 INC.	10 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	ESE/41.4	-9.86	385
68	FSTH	PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON L6V 1X4	ESE/41.4	-9.86	385
68	FSTH	PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON L6V 1X4	ESE/41.4	-9.86	386
68	GEN	PARKINSON COACH LINES 2000 INC.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	386
68	GEN	PARKINSON COACH LINES 2000 INC.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	386
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	387

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	387
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON	ESE/41.4	-9.86	387
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	388
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	388
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	389
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	389
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	389
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	390
68	GEN	Parkinson Coach	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	390
68	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	ESE/41.4	-9.86	391
68	EXP	PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON	ESE/41.4	-9.86	391
69	NPCB	CANADA CUP INC	228 QUEEN STREET EAST BRAMPTON ON L7YA9	ESE/95.3	-9.53	391
69	NPCB	CANADA CUP INC	228 QUEEN ST E BRAMPTON ON L6V 1B8	ESE/95.3	-9.53	392

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
70	SPL	SHELL CANADA PRODUCTS LTD.	230 QUEEN STREET EAST AT KENNEDY RD. SERVICE STATION BRAMPTON CITY ON L6V 1B8	ESE/77.0	-9.64	393
70	DTNK	SHELL CANADA PRODUCTS**	230 QUEEN ST E BRAMPTON ON	ESE/77.0	-9.64	393
70	EXP	SHELL CANADA PRODUCTS	230 QUEEN ST E BRAMPTON ON	ESE/77.0	-9.64	394
70	EXP	SHELL CANADA PRODUCTS	230 QUEEN ST E BRAMPTON ON	ESE/77.0	-9.64	394
71	SPL		238 Queen St East Brampton ON	ESE/9.5	-10.03	394
72	SPL	Brampton Transit<UNOFFICIAL>	Queen and Kennedy, Brampton Brampton ON	ESE/25.0	-10.42	395
73	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	ESE/50.6	-11.60	396
73	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	ESE/50.6	-11.60	396
73	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	ESE/50.6	-11.60	397
73	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON	ESE/50.6	-11.60	397
73	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	ESE/50.6	-11.60	398
73	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	ESE/50.6	-11.60	398
73	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	ESE/50.6	-11.60	398

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	GEN	i6 Building Corp	2 Kennedy Road South Brampton ON L6W 3E1	ESE/50.6	-11.60	399
73	GEN	i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	ESE/50.6	-11.60	399
73	GEN	i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	ESE/50.6	-11.60	399
73	GEN	i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	ESE/50.6	-11.60	400
74	SPL	LECLAIR FUELS LTD.	1 KENNEDY ROAD SOUTH CANADIAN TIRE TANK TRUCK (CARGO) BRAMPTON CITY ON	ESE/88.8	-10.51	400
74	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	ESE/88.8	-10.51	401
74	DTNK	2931621 CANADA INC O/A CANADIAN TIRE	1 KENNEDY RD S BRAMPTON ON	ESE/88.8	-10.51	401
74	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	ESE/88.8	-10.51	402
74	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	ESE/88.8	-10.51	402
74	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	ESE/88.8	-10.51	403
74	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	ESE/88.8	-10.51	403
74	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	ESE/88.8	-10.51	403
74	GEN	Dr Essam Michael Medicine Professional Corporation	1 Kennedy Road Brampton ON L6W 3C9	ESE/88.8	-10.51	404

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
74	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	ESE/88.8	-10.51	404
74	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	ESE/88.8	-10.51	404
74	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	ESE/88.8	-10.51	405
74	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	ESE/88.8	-10.51	405
74	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	ESE/88.8	-10.51	405
74	GEN	Dr Essam Michael Medicine Professional Corporation	1 Kennedy Road Brampton ON L6W 3C9	ESE/88.8	-10.51	406
74	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	ESE/88.8	-10.51	406
74	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	ESE/88.8	-10.51	407
74	GEN	Loblaw Companies Limited - Shoppers Drug Mart	1 Kennedy Rd S Brampton ON L6W 3C9	ESE/88.8	-10.51	407
74	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	ESE/88.8	-10.51	407
74	GEN	Athletes Care Brampton	1 Kennedy Rd S Unit 12 Brampton ON L6W 3C9	ESE/88.8	-10.51	408
75	GEN	Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	WNW/61.0	16.37	408
75	GEN	Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	WNW/61.0	16.37	409

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
75	GEN	Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	WNW/61.0	16.37	409
75	GEN	2244603 Ont inc	1-11670 Hurontario Street Brampton ON L7A1R2	WNW/61.0	16.37	409
75	GEN	BRINKLEY PHARMACY	11670 HURONTARIO Street Brampton ON L7A 1R2	WNW/61.0	16.37	410
75	GEN	Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	WNW/61.0	16.37	410
75	GEN	CBI Health	1-11670 Hurontario Street Brampton ON L7A1R2	WNW/61.0	16.37	410
75	GEN	CBI Health	1-11670 Hurontario Street Brampton ON L7A1R2	WNW/61.0	16.37	411
75	GEN	Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	WNW/61.0	16.37	411
75	GEN	Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	WNW/61.0	16.37	412
76	GEN	U.A.P. INC.	144-5 KENNEDY RD. BRAMPTON ON L6W 3G4	ESE/28.0	-11.01	412
76	GEN	U.A.P. INC.	BRAMPTON #170 144-5 KENNEDY RD. S. BRAMPTON ON L6W 3G4	ESE/28.0	-11.01	412
76	GEN	U.A.P. INC. 39-227	BRAMPTON #170 144-5 KENNEDY RD. S. BRAMPTON ON L6W 3G4	ESE/28.0	-11.01	413
76	GEN	UAP INC.	144-5 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	ESE/28.0	-11.01	413
77	RST	ALAGA ESSO	18 KENNEDY RD S BRAMPTON ON L6W 3E1	ESE/13.4	-11.63	413

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
77	DTNK	MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON L6W 3E1	ESE/13.4	-11.63	413
77	DTNK	MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	ESE/13.4	-11.63	414
77	DTNK	MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	ESE/13.4	-11.63	415
77	EXP	MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	ESE/13.4	-11.63	415
77	EXP	MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	ESE/13.4	-11.63	416
77	EXP	MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	ESE/13.4	-11.63	416
77	EXP	MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	ESE/13.4	-11.63	416
78	GEN	Queen Square Family Health Team Queen Square Family Health Team	11692 Hurontario Street Main Street North Brampton ON L7A 1K5	WNW/91.7	16.37	416
78	GEN	Queen Square Family Health Team Queen Square Family Health Team	11692 Hurontario Street Main Street North Brampton ON L7A 1K5	WNW/91.7	16.37	417
79	GEN	Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	ESE/47.3	-11.63	417
79	GEN	Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	ESE/47.3	-11.63	417
79	GEN	Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	ESE/47.3	-11.63	418

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
79	GEN	Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	ESE/47.3	-11.63	418
79	GEN	Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	ESE/47.3	-11.63	418
79	GEN	Swift Clinics	Swift Clinics 49 Hillcrest Avenue Unit 104 Brampton ON L6W 4V4	ESE/47.3	-11.63	419
79	GEN	Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	ESE/47.3	-11.63	419
80	SPL	TRANSPORT TRUCK	INTERSECTION AND CATCH BASIN AT KENNEDY RD AND EASTERN AVE TRANSPORT TRUCK (CARGO) BRAMPTON CITY ON	ESE/27.9	-11.63	420
81	SPL	Maple Leaf Foods Inc.	33 Kennedy Road S Brampton ON	ESE/60.8	-11.63	420
82	GEN	Alectra Utilities Corporation	67 Eastern Ave Brampton ON L6W 1X9	ESE/97.1	-12.63	421
82	GEN	Alectra Utilities Corporation	67 Eastern Ave Brampton ON L6W 1X9	ESE/97.1	-12.63	422
82	GEN	Alectra Utilities Corporation	67 Eastern Ave Brampton ON L6W 1X9	ESE/97.1	-12.63	422
82	GEN	Alectra Utilities Corporation	67 Eastern Ave Brampton ON L6W 1X9	ESE/97.1	-12.63	422
83	DTNK	QUEEN & KENNEDY CARWASH	24 KENNEDY RD S BRAMPTON ON L6W 3E2	ESE/19.8	-12.63	423
83	DTNK	KENNEDY & EASTERN PROPANE	24 KENNEDY RD S BRAMPTON ON	ESE/19.8	-12.63	423
83	DTNK	KENNEDY & EASTERN PROPANE	24 KENNEDY RD S BRAMPTON ON	ESE/19.8	-12.63	424

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
83	DTNK	KENNEDY & EASTERN PROPANE	24 KENNEDY RD S BRAMPTON ON	ESE/19.8	-12.63	424
84	FSTH	B & P AUTO CENTRE LTD	11865 HURONTARIO ST SNELGROVE BRAMPTON ON	WNW/31.2	17.37	425
84	FSTH	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	426
84	DTNK	PETROLEUM PLUS GROUP INC	11865 HWY 10 SNELGROVE ON L0P 1M0	WNW/31.2	17.37	427
84	DTNK	1319911 ONTAIRO INC O/A DAVE'S GAS BAR VARIETY	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	427
84	DTNK	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	428
84	DTNK	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	428
84	DTNK	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	429
84	DTNK	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	430
84	FST	GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	430
84	FST	GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	430
84	FST	GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	431
84	FST	GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	431

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
84	EXP	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	431
84	EXP	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	431
84	EXP	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	432
84	EXP	SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	432
84	FST	GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	WNW/31.2	17.37	432
85	GEN	STEPHENSON'S RENT-ALL LTD.	26 KENNEDY RD. S. BRAMPTON ON L6W 3E2	ESE/21.4	-12.63	432
85	GEN	STEPHENSON'S RENT-ALL LTD.	26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR. REXDALE ON L6W 3E2	ESE/21.4	-12.63	433
85	GEN	STEPHENSON'S RENT-ALL INC.	26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR. REXDALE ON L6W 3E2	ESE/21.4	-12.63	433
85	GEN	STEPHENSON'S RENT-ALL INC.	26 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2	ESE/21.4	-12.63	434
85	GEN	STEPHENSON'S RENT-ALL INC. 36-583	26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR. REXDALE ON L6W 3E2	ESE/21.4	-12.63	434
85	GEN	STEPHEN(OUT OF BUSINESS) C.	26 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2	ESE/21.4	-12.63	435
85	GEN	Stephenson's Rent-all (1998) Inc.	26 Kennedy Rd. South BRAMPTON ON L6W 3E2	ESE/21.4	-12.63	436

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
85	DTNK	STEPHENSONS RENT ALL INC ATTN JOHN FLINT	26 KENNEDY RD S BRAMPTON ON	ESE/21.4	-12.63	436
86	SCT	Cribben Inc.	11965 Hurontario St Brampton ON L6Z 4P7	WNW/96.4	17.37	436
86	GEN	Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	WNW/96.4	17.37	437
86	GEN	Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	WNW/96.4	17.37	437
86	GEN	Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	WNW/96.4	17.37	438
86	GEN	Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	WNW/96.4	17.37	438
86	GEN	Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	WNW/96.4	17.37	438
86	SPL	Alectra Utilities Corporation	11965 Hurontario St Brampton ON L6Z 4P7	WNW/96.4	17.37	439
86	GEN	Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	WNW/96.4	17.37	440
87	SPL	CANADIAN TIRE CORPORATION LTD.	30 KENNEDY ROAD RETAIL STORE BRAMPTON CITY ON	ESE/21.6	-12.63	440
87	GEN	P.O. MONTGOMERY ENT.	30 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2	ESE/21.6	-12.63	441
87	GEN	P.O. MONTGOMERY ENTERPRISES	30 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2	ESE/21.6	-12.63	441
87	GEN	Rochon Building Corporation	30 Kennedy Road South Brampton ON L6W 3E2	ESE/21.6	-12.63	442

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
87	DTNK	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	30 KENNEDY RD S BRAMPTON ON	ESE/21.6	-12.63	442
87	DTNK	P D MONTGOMERY ENTERPRISES INC CANADIAN TIRE AUTO CENTRE	30 KENNEDY RD S BRAMPTON ON	ESE/21.6	-12.63	442
87	DTNK	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	30 KENNEDY RD S BRAMPTON ON	ESE/21.6	-12.63	443
87	DTNK	P D MONTGOMERY ENTERPRISES INC CANADIAN TIRE AUTO CENTRE	30 KENNEDY RD S BRAMPTON ON	ESE/21.6	-12.63	444
87	GEN	Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	ESE/21.6	-12.63	444
87	GEN	Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	ESE/21.6	-12.63	445
87	GEN	Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	ESE/21.6	-12.63	445
87	GEN	Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	ESE/21.6	-12.63	446
87	GEN	Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	ESE/21.6	-12.63	446
88	SPL	The Corporation of Brampton (Transit)	Brampton ON	ESE/9.3	-12.63	447
89	FSTH	1205073 ONTARIO LTD	11980 HURONTARIO ST BRAMPTON ON L7A 1E6	WNW/54.5	18.37	448
89	DTNK	2124964 ONTARIO INC O/A PETRO-CANADA	11980 HURONTARIO ST (HWY 10) BRAMPTON ON L7A 1E6	WNW/54.5	18.37	448
89	SPL	Petro-Canada Fuels Inc.	11980 Hurontario St Brampton ON	WNW/54.5	18.37	449

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
89	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	WNW/54.5	18.37	450
89	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	WNW/54.5	18.37	450
89	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	WNW/54.5	18.37	450
89	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	WNW/54.5	18.37	450
89	INC	SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	WNW/54.5	18.37	451
89	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	WNW/54.5	18.37	451
90	SCT	GRUMMAN OLSON INDUSTRIES INC.	30A Kennedy Rd S Suite 201 Brampton ON L6W 3E2	ESE/35.8	-12.63	452
90	GEN	Austin Rehab Group	30A Kennedy Road South, Ste 1A Bramptom ON	ESE/35.8	-12.63	452
91	SPL	PEEL, REGIONAL MUNICIPALITY OF	INTERSECTION OF ORENDA DR & KENNEDY DR FORCEMAIN BRAMPTON CITY ON	ESE/22.6	-12.63	452
92	SPL	TRANSPORT TRUCK	HIGHWAY 10 - WEST SIDE - SOUTH OF MAYFIELD ROAD MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	WNW/2.1	18.37	453
92	SPL	ONTARIO HYDRO	CORNER OF HWY 10 & MAYFIELD RD. TRANSFORMER PEEL R.M. ON	WNW/2.1	18.37	454
92	SPL	Construction Site<UNOFFICIAL>	On Mayfield Rd. just east of Hurontario St. Brampton ON	WNW/2.1	18.37	455

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
92	DTNK	TWIN PETROLEUM PRODUCTS LTD	HWY 10 (MAYFIELD RD) SNELGROVE ON L0P 1M0	WNW/2.1	18.37	455
92	SPL	SD Towing	Hurontario St and Mayfield Rd Brampton ON	WNW/2.1	18.37	456
93	SPL	PETRO-CANADA	12011 HWY 10 IN VILLAGE OF SNELGROVE. TANK TRUCK (CARGO) CALEDON TOWN ON	WNW/48.7	19.04	457
93	RST	PETRO CANADA	12011 HURONTARIO ST BRAMPTON ON L6Z 4P8	WNW/48.7	19.04	458
93	FSTH	2074065 ONTARIO INC O/A GAS STN	12011 HURONTARIO ST HWY 10 BRAMPTON ON L6Z 4P8	WNW/48.7	19.04	458
93	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	WNW/48.7	19.04	458
93	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	WNW/48.7	19.04	459
93	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	WNW/48.7	19.04	459
93	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	WNW/48.7	19.04	459
93	RST	PETRO CANADA	12011 HURONTARIO ST BRAMPTON ON L6Z4P8	WNW/48.7	19.04	459
93	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	WNW/48.7	19.04	459
94	DTNK	ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON L7A 1E6	WNW/25.0	19.37	460
94	DTNK	ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	WNW/25.0	19.37	460

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
94	EXP	ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	WNW/25.0	19.37	461
94	EXP	ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	WNW/25.0	19.37	461
94	EXP	ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	WNW/25.0	19.37	461
94	EXP	ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	WNW/25.0	19.37	462
94	EXP	ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	WNW/25.0	19.37	462
95	GEN	City of Brampton	15 Orenda Road Brampton ON	ESE/59.5	-12.63	462
96	SCT	Maple Leaf Poultry	32 Kennedy Rd S Brampton ON L6W 3E3	ESE/32.6	-12.63	462
96	SPL	MAPLE LEAF FOODS INC.	BRAMPTON PLANT 32 KENNEDY ROAD SOUTH BRAMPTON CITY ON	ESE/32.6	-12.63	463
96	SPL	MAPLE LEAF FOODS INC.	32 KENNEDY ROAD SOUTH BRAMPTON PLANT 32 KENNEDY ROAD SOUTH BRAMPTON CITY ON L6W 3E3	ESE/32.6	-12.63	463
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	464
96	FSTH	THE POULTRY COMPANY ATTN FRANK TOIRKENS	32 KENNEDY RD S BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	465
96	FSTH	THE POULTRY COMPANY ATTN FRANK TOIRKENS	32 KENNEDY RD S BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	465
96	DTNK	G M F TRANSPORT	32 KENNEDY RD S BRAMPTON ON	ESE/32.6	-12.63	466

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
96	DTNK	G M F TRANSPORT	32 KENNEDY RD S BRAMPTON ON	ESE/32.6	-12.63	466
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	467
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	467
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	468
96	FST	THE POULTRY COMPANY ATTN FRANK TOIRKENS	32 KENNEDY RD S BRAMPTON ON	ESE/32.6	-12.63	469
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	469
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON	ESE/32.6	-12.63	469
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	470
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	471
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	471
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	472
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	472
96	SPL	Maple Leaf Foods Inc.	32 Kennedy Rd S Brampton ON L6W 3E3	ESE/32.6	-12.63	473

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	474
96	SPL		32 Kennedy Rd S Brampton ON L6W 3E3	ESE/32.6	-12.63	475
96	GEN	MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	ESE/32.6	-12.63	475
96	SPL		32 Kennedy Road South BRAMPTON ON	ESE/32.6	-12.63	476
96	SPL		32 Kennedy Rd S., Brampton BRAMPTON ON	ESE/32.6	-12.63	477
96	EXP	G M F TRANSPORT	32 KENNEDY RD S BRAMPTON ON	ESE/32.6	-12.63	478
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	478
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	479
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	480
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	480
97	SPL	IKO INDUSTRIES LTD.	BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	481
97	SPL	IKO INDUSTRIES LTD.	BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	482

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
97	SPL	IKO INDUSTRIES LTD.	CVM FILTER BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON	ESE/92.8	-12.63	483
97	SPL	IKO INDUSTRIES LTD.	BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	484
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA RD. BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	484
97	SCT	IKO Industries Ltd.	71 Orenda Rd Brampton ON L6W 1V8	ESE/92.8	-12.63	485
97	SCT	Sako Materials Limited	71 Orenda Rd Brampton ON L6W 1V8	ESE/92.8	-12.63	486
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	486
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	487
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	488
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	489
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	489
97	SPL	IKO INDUSTRIES LTD.	IN DITCH AT 71 ORENDA ROAD ON IKO INDUSTRIES' PROPERTY BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	490
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	491

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
97	SPL	IKO INDUSTRIES LTD.	IKO INDUSTRIES, 71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	492
97	SCT	IKO Industries Ltd.	71 Orenda Rd Brampton ON L6W 1V8	ESE/92.8	-12.63	493
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA RD. BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	493
97	SPL	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	ESE/92.8	-12.63	494
97	GEN	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	495
97	GEN	IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	495
97	GEN	IKO INDUSTRIES LTD. 21-132	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	496
97	GEN	IKO INDUSTRIES LTD	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	496
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	497
97	FSTH	IKO INDUSTRIES	71 ORENDA RD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	498
97	SPL	IKO Industries Ltd.	71 Orenda Road Brampton ON L6W 1V8	ESE/92.8	-12.63	498
97	SPL	IKO Industries Ltd.	71 Orenda Road Brampton ON L6W 1V8	ESE/92.8	-12.63	499
97	SPL	IKO Industries Ltd.	71 Orenda Road Brampton ON L6W 1V8	ESE/92.8	-12.63	500

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
97	SPL	IKO Industries	71 Orenda Road Brampton ON	ESE/92.8	-12.63	500
97	SPL	IKO Industries	71 Orenda Rd Brampton ON	ESE/92.8	-12.63	501
97	GEN	GH International	71 Orenda Road Brampton ON L6W 1V8	ESE/92.8	-12.63	502
97	FSTH	IKO INDUSTRIES	71 ORENDA RD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	502
97	DTNK	IKO INDUSTRIES LTD	71 ORENDA RD BRAMPTON ON	ESE/92.8	-12.63	503
97	DTNK	IKO INDUSTRIES LTD	71 ORENDA RD BRAMPTON ON	ESE/92.8	-12.63	503
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	504
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	504
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	505
97	FST	IKO INDUSTRIES LTD	71 ORENDA RD BRAMPTON ON	ESE/92.8	-12.63	506
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	506
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON	ESE/92.8	-12.63	507
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	508

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	509
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	510
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	510
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	512
97	SPL	IKO Industries Ltd.	71 Orenda Rd (IKO B2) Brampton ON L6W 1V8	ESE/92.8	-12.63	513
97	SPL	Flynn Canada Ltd.	71 Orenda Road Brampton ON	ESE/92.8	-12.63	514
97	INC	IKO INDUSTRIES LTD	71 ORENDA RD BRAMPTON ON	ESE/92.8	-12.63	515
97	SPL	IKO Industries Ltd.	71 Orenda Rd Brampton ON L6W 1V8	ESE/92.8	-12.63	515
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	516
97	SPL	IKO Industries Ltd.	71 Orenda Rd Brampton ON L6W 1V8	ESE/92.8	-12.63	517
97	GEN	IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	ESE/92.8	-12.63	518
97	SPL		71 Orenda Rd. Brampton, ON. BRAMPTON ON	ESE/92.8	-12.63	520
97	SPL		71 Orenda Rd, Brampton, ON L6W 1V8 BRAMPTON ON	ESE/92.8	-12.63	520

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
97	SPL		71 Orenda Rd, Brampton ON	ESE/92.8	-12.63	521
98	GEN	SAFE SELF STORAGE	17 ARDGLEN DRIVE BRAMPTON ON L6W 1V1	ESE/51.2	-14.83	522
98	GEN	SAFE SELF STORAGE(OUT OF BUSINESS)	17 ARDGLEN DRIVE BRAMPTON ON L6W 1V1	ESE/51.2	-14.83	522
99	GEN	CANADIAN PLASTICS CONCENTRATED LTD	ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	ESE/38.6	-15.56	523
99	GEN	CANADIAN PLASTICS(OUT OF BUS)	ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	ESE/38.6	-15.56	523
99	GEN	CANADIAN PLASTICS(OUT OF BUS) 08-301	ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	ESE/38.6	-15.56	523
99	GEN	CANADIAN PLASTICS(OUT OF BUSINESS)	ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	ESE/38.6	-15.56	524
100	GEN	BUDGET RENT A CAR	73 KENNEDY ROAD SOUTH BRAMPTON ON L6V 3E4	ESE/65.2	-16.30	524
100	GEN	BUDGET RENT A CAR O/A BRL REALTY 05-696	73 KENNEDY ROAD SOUTH, BRAMPTON C/O 5905 CAMPUS ROAD MISSISSAUGA ON L6W 3E4	ESE/65.2	-16.30	524
100	FSTH	BUDGET RENT A CAR	73 KENNEDY RD S BRAMPTON ON L6W 3E4	ESE/65.2	-16.30	525
100	FSTH	BUDGET RENT A CAR	73 KENNEDY RD S BRAMPTON ON L6W 3E4	ESE/65.2	-16.30	525
100	FST	BUDGET RENT A CAR	73 KENNEDY RD S BRAMPTON ON	ESE/65.2	-16.30	526

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
100	FST	BUDGET RENT A CAR	73 KENNEDY RD S BRAMPTON ON	ESE/65.2	-16.30	526
100	GEN	Budget Rental Car	73 Kennedy Rd S Brampton ON	ESE/65.2	-16.30	526
100	GEN	BRL REALTY LIMITED	73 KENNEDY ROAD SOUTH BRAMPTON ON L6W3E4	ESE/65.2	-16.30	526
100	GEN	Budget Rental Car	73 Kennedy Rd S Brampton ON L6W 3E4	ESE/65.2	-16.30	527
100	GEN	Budget Rental Car	73 Kennedy Rd S Brampton ON L6W 3E4	ESE/65.2	-16.30	527
101	GEN	NATHAN PHARMACY	147 Clarance Street, Unit 30 Brampton ON L6W 1T2	ESE/92.3	-16.63	528
101	GEN	NATHAN PHARMACY	147 Clarance Street, Unit 30 Brampton ON L6W 1T2	ESE/92.3	-16.63	528
102	DTNK	MANUEL FILIPE & FERNANDO MELO SERV CENTRE LTD	149 CLARENCE ST BRAMPTON ON L6W 1T2	ESE/67.4	-16.63	528
103	SPL		Hurontario Street and Inglewood Drive, Mississauga CALEDON;BRAMPTON ON	WNW/10.3	24.77	529
103	SPL		Hurontario St & Steeles Ave, Brampton CALEDON;BRAMPTON ON	WNW/10.3	24.77	530
104	GEN	SMARTES CLEANER	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	ESE/92.7	-16.63	531
104	GEN	SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	ESE/92.7	-16.63	531
104	GEN	SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	ESE/92.7	-16.63	531

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
104	GEN	SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	ESE/92.7	-16.63	532
104	GEN	SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	ESE/92.7	-16.63	532
104	GEN	SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	ESE/92.7	-16.63	532
104	GEN	Smartex Cleaners	29- 50 Kennedy Road South Brampton ON	ESE/92.7	-16.63	533
104	GEN	2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	ESE/92.7	-16.63	533
104	GEN	Smartex Cleaners	29- 50 Kennedy Road South Brampton ON L6W 3R7	ESE/92.7	-16.63	533
104	GEN	Smartex Cleaners	29- 50 Kennedy Road South Brampton ON L6W 3R7	ESE/92.7	-16.63	534
104	GEN	2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	ESE/92.7	-16.63	534
104	CDRY	Smartex Dry Cleaners	50 Kennedy Rd S #29 Brampton ON L6W3R7	ESE/92.7	-16.63	535
104	GEN	2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	ESE/92.7	-16.63	535
104	GEN	Exquizeet Tattoo & Piercing Studio	50 Kennedy Road South, Unit 20C Kennedy Square Mall Brampton ON L6W3R7	ESE/92.7	-16.63	535
104	GEN	2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	ESE/92.7	-16.63	536
104	GEN	Exquizeet Tattoo & Piercing Studio	50 Kennedy Road South, Unit 20C Kennedy Square Mall Brampton ON L6W3R7	ESE/92.7	-16.63	536

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
104	GEN	2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	ESE/92.7	-16.63	536
104	GEN	Exquizeet Tattoo & Piercing Studio	50 Kennedy Road South, Unit 20C Kennedy Square Mall Brampton ON L6W3R7	ESE/92.7	-16.63	537
105	SCT	Sure Print & Copy Centre	83 Kennedy Rd S Unit 12 Brampton ON L6W 3P3	ESE/60.8	-17.63	537
106	GEN	2205302 Ontario Limited	12197 Hurontario Street Brampton ON L6Z 4P8	WNW/83.5	22.50	538
107	SPL		84 Kennedy Road South Brampton ON L6W 3E7	ESE/31.4	-17.63	538
108	GEN	RADMAN THE	90 KENNEDY RD. SOUTH BRAMPTON ON L6W 3E7	ESE/19.1	-17.63	539
108	GEN	RADMAN THE 32-149	90 KENNEDY RD. SOUTH BRAMPTON ON L6W 3E7	ESE/19.1	-17.63	539
108	GEN	RADMAN, THE	90 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E7	ESE/19.1	-17.63	539
109	SPL	Rice Development	95 Kennedy Rd Brampton ON L6W 3G2	ESE/53.6	-18.63	539
110	SCT	GPrint	96 Kennedy Rd S Brampton ON L6W 3E7	ESE/18.9	-18.64	540
110	GEN	Ziebart	96 Kennedy Road South Brampton ON L6W 3E7	ESE/18.9	-18.64	541
111	SPL	MACTAC CANADA LTD.	100 KENNEDY ROAD SOUTH BRAMPTON PLANT 100 KENNEDY ROAD SOUTH BRAMPTON CITY ON L6W 3E8	ESE/89.1	-19.63	541

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
111	SCT	MACTAC CANADA LTD.	100 KENNEDY RD S BRAMPTON ON L6W 3E8	ESE/89.1	-19.63	542
111	SPL	MACTAC CANADA LTD.	100 KENNEDY RD SOUTH. BRAMPTON PLANT 100 KENNEDY ROAD SOUTH BRAMPTON CITY ON L6W 3E8	ESE/89.1	-19.63	542
111	GEN	MACTAC CANADA LTD/LTEE	100 KENNEDY RD. S. BRAMPTON ON L6W 3E8	ESE/89.1	-19.63	543
111	GEN	MACTAC CANADA LTD/LTEE 25-009	100 KENNEDY RD. S. BRAMPTON ON L6W 3E8	ESE/89.1	-19.63	544
111	GEN	MACTAC CANADA LTD./LTEE.	100 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E8	ESE/89.1	-19.63	544
111	GEN	MACTAC CANADA LTD./LTEE.	100 KENNEDY RD. S. BRAMPTON ON L6W 3E8	ESE/89.1	-19.63	545
111	GEN	MACtac, Bemis	100 Kennedy Road S. Brampton ON L6W 3E8	ESE/89.1	-19.63	545
111	AUWR	CROSS CANADA AUTO BODY SUPPLY LTD	100 KENNEDY RD S BRAMPTON ON L6W 3E8	ESE/89.1	-19.63	546
111	INC		100 KENNEDY ROAD SOUTH, BRAMPTON ON	ESE/89.1	-19.63	546
112	GEN	TRAVELWAYS SCHOOL TRANSIT LTD	12267 HUONTARIO STREET SNELGROVE ON L0P 1M0	WNW/86.6	23.99	547
112	GEN	LAIDLAW TRANSIT LTD.	12267 HURONTARIO ST. SNELGROVE ON L0P 1M0	WNW/86.6	23.99	547
112	GEN	LAIDLAW TRANSIT LTD.	12267 HURONTARIO ST., SNELGROVE C/O 30 HERITAGE RD. MARKHAM ON L3P 1M4	WNW/86.6	23.99	548
112	GEN	LAIDLAW TRANSIT LTD. 38-034	12267 HURONTARIO STREET BRAMPTON ON L6V 1A1	WNW/86.6	23.99	548

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
112	GEN	LAIDLAW TRANSIT LTD. 38-034	12267 HURONTARIO ST. C/O R.R. #2 BRAMPTON ON L6V 1A1	WNW/86.6	23.99	549
112	GEN	LAIDLAW TRANSIT LTD	12267 HURONTARIO STREET BRAMPTON ON L6V 1A1	WNW/86.6	23.99	549
112	GEN	LAIDLAW TRANSIT LTD.	12267 HURONTARIO STREET BRAMPTON ON L6V 1A1	WNW/86.6	23.99	550
112	GEN	LAIDLAW TRANSIT LTD.	12267 HURONTARIO STREET R.R.#2 BRAMPTON ON L6V 1A1	WNW/86.6	23.99	550
112	GEN	Ministry of Transportation	12267 Hurontario Street RR#2 Part Lot 19 1EHS Brampton ON L6V 1A0	WNW/86.6	23.99	551
112	DTNK	TRAVELWAYS LTD	12267 HURONTARIO ST SNELGROVE ON	WNW/86.6	23.99	551
112	DTNK	LAIDLAW TRANSIT LTD	12267 HURONTARIO ST BRAMPTON ON	WNW/86.6	23.99	552
112	DTNK	TRAVELWAYS LTD	12267 HURONTARIO ST SNELGROVE ON	WNW/86.6	23.99	553
113	SCT	PEEL FENCE SYSTEMS INC.	110 KENNEDY RD S UNIT A BRAMPTON ON L6W 3E7	ESE/14.8	-20.26	553
113	SCT	P.F.S. FENCE INC.	110 Kennedy Rd S Unit A Brampton ON L6W 3E7	ESE/14.8	-20.26	553
114	SCT	THE DOOR FACTORY II	114 KENNEDY RD S BRAMPTON ON L6W 3E7	ESE/59.7	-20.63	554
114	SCT	Baba Gifts and Distributors	114 Kennedy Rd S Brampton ON L6W 3E7	ESE/59.7	-20.63	554
115	SPL	The Regional Municipality of Peel	107 Kennedy Rd. South Brampton ON	ESE/78.0	-20.63	554

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
115	SPL		107 Kennedy Road South Brampton, ON BRAMPTON ON	ESE/78.0	-20.63	555
116	GEN	KENNEDY GALLERIES	FURNITURE CLINIC, DIVISION OF 109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	ESE/89.5	-20.63	556
116	GEN	KENNEDY GALLERIES, DIV.	109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	ESE/89.5	-20.63	556
116	GEN	KENNEDY GALLERIES 23-268	FURNITURE CLINIC, DIVISION OF 109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	ESE/89.5	-20.63	557
116	GEN	KENNEDY GALLERIES - A DIVISION OF	109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	ESE/89.5	-20.63	557
117	GEN	BRAMPTON LEASING & RENTALS LTD.	117 KENNEDY RD. S. BRAMPTON ON L6W 3G3	ESE/70.3	-20.99	558
117	GEN	BRAMPTON LEASING & RENTALS LTD.	117 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	ESE/70.3	-20.99	558
117	GEN	BRAMPTON LEASING & RENTALS LTD. 06-192	117 KENNEDY RD. S. BRAMPTON ON L6W 3G3	ESE/70.3	-20.99	558
117	GEN	HERTZ BRAMPTON LEASING & RENTALS LIMITED	117 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	ESE/70.3	-20.99	559
117	GEN	BRAMPTON LEASING & RENTALS LIMITED	117 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	ESE/70.3	-20.99	559
119	SPL	The Regional Municipality of Peel	119 Kennedy Road South Brampton ON	ESE/76.1	-21.63	560
120	GEN	AUTOMOTIVE FINISHES & SUPPLY INC.	5 STAFFORD DR. BRAMPTON C/O 726 KIPLING AVE. TORONTO ON L6W 1L3	ESE/36.2	-22.63	560

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
121	SCT	BUNS MASTER BAKERY	1 STAFFORD DR BRAMPTON ON L6W 1L3	ESE/21.0	-22.63	561
121	SCT	Grainery Bakery and Deli	1 Stafford Dr Brampton ON L6W 1L3	ESE/21.0	-22.63	561
122	DTNK	IMPERIAL OIL LTD	129 KENNEDY RD BRAMPTON ON	ESE/33.6	-22.63	561
123	GEN	Leisureworld Caregiving Centre Tullamore	133 Kennedy Rd South Brampton ON	ESE/88.9	-22.17	562
124	SPL	A.T PLASTICS INC.	134 KENNEDY ROAD SOUTH 134 KENNEDY ROAD SOUTH, PLASTIC FILMS BRAMPTON CITY ON L6W 3G5	ESE/72.3	-23.51	563
124	NPCB	C.I.L. INC.	BRAMPTON WORKS; 134 KENNEDY RD. S. BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	563
124	NPCB	AT PLACTICS INC.	BRAMPTON WORKS; 134 KENNEDY RD. S. BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	564
124	NPCB	CIL INC.	134 KENNEDY ROAD BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	564
124	SCT	AT PLASTICS INC.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	564
124	GEN	C.I.L. INC	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	565
124	GEN	C.I.L. INC(SEE&USE ON1133601)	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	565
124	GEN	C.I.L. INC(SEE&USE ON1133601) 10-046	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	565
124	GEN	AT PLASTICS INC.	134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	565

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
124	GEN	AT PLASTIC 10-046	134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	566
124	GEN	AT PLASTICS INCORPORATED	134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	567
124	GEN	SMURFIT-STONE FLEXIBLE PACKAGING GROUP	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	567
124	NPCB	AT PLASTICS INC.	134 KENNEDY RD. S. BRAMPTON WORKS Brampton ON L6W 3G5	ESE/72.3	-23.51	568
124	GEN	BLUEGRASS CONTAINER CANADA COMPANY	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	568
124	GEN	Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON	ESE/72.3	-23.51	569
124	NPCB	A.T.PLASTICS INC.	134 KENNEDY ROAD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	570
124	NPCB	AT PLASTICS INC.	134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	570
124	NPCB	AT PLASTICS INC.	BRAMPTON WORKS 134 KENNEDY RD. S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	570
124	SCT	Graphic Packaging Intl Canada	134 Kennedy Rd S Brampton ON L6W 3G5	ESE/72.3	-23.51	571
124	GEN	Graphic Packaging Int. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	571
124	GEN	Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	572

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
124	GEN	Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	573
124	GEN	Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	573
124	GEN	Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	ESE/72.3	-23.51	574
124	GEN	Infinity Asset Solutions	134 Kennedy Road Brampton ON L6W 3G5	ESE/72.3	-23.51	575
125	SPL	A.T. PLASTICS	142 KENNEDY ROAD 142 KENNEDY ROAD SOUTH BURLINGTON BRAMPTON CITY ON	ESE/46.9	-22.63	575
125	GEN	C-I-L INC.	142 KENNEDY RD. S. BRAMPTON ON L6W 3G4	ESE/46.9	-22.63	576
125	GEN	C-I-L INC. (SEE & USE ON1133600)	142 KENNEDY RD. S. BRAMPTON ON L6W 3G4	ESE/46.9	-22.63	576
125	GEN	C-I-L INC. (SEE & USE ON1133600) 10-292	142 KENNEDY RD. S. BRAMPTON ON L6W 3G4	ESE/46.9	-22.63	577
125	GEN	AT PLASTICS INC.	142 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	ESE/46.9	-22.63	577
125	GEN	AT PLASTICS INC. 10-292	142 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	ESE/46.9	-22.63	578
125	GEN	AT PLASTICS INCORPORATED	142 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	ESE/46.9	-22.63	578
125	SCT	AT Plastics Inc.	142 Kennedy Rd S Brampton ON L6W 3G4	ESE/46.9	-22.63	579
126	SPL	The Regional Municipality of Peel	165 Kennedy Road S Brampton ON	ESE/95.0	-22.63	579

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
127	SPL	UNI-CARE MCLAVERTY	144 KENNEDY RD, UNIT #2 MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	ESE/29.9	-22.63	580
127	SCT	PAPA'S CERAMICS LTD.	144 KENNEDY RD S UNIT 13 BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	581
127	SCT	Customwear Screenprinting Inc.	144 Kennedy Rd S Unit 15 Brampton ON L6W 3G4	ESE/29.9	-22.63	581
127	GEN	WARREN'S AUTO PARTS LTD	144 KENNEDY RD S BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	581
127	GEN	BRAMTECH EXTRUSIONS	144 KENNEDY RD., SOUTH UNIT 11 BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	582
127	GEN	BRAMTECH EXTRUSIONS 04-219	144 KENNEDY RD., SOUTH UNIT 11 BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	582
127	GEN	VERSAKLEEN DRYCLEANERS	144 KENNEDY RD. SOUTH BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	582
127	GEN	VERSAKLEEN DRYCLEANERS	144 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	583
127	GEN	VERSAKLEEN DRYCLEANERS 40-180	144 KENNEDY RD. SOUTH BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	583
127	GEN	1108456 ONTARIO INC.	144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	584
127	GEN	PREMIER CLEANERS	144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	584
127	GEN	1575601 ONTARIO INC	144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	ESE/29.9	-22.63	584
127	GEN	22138689 Ontario Inc.	144 Kennedy Road S. Brampton ON L6W 3G4	ESE/29.9	-22.63	585

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
127	GEN	2138689 Ontario Inc.	144 Kennedy Road S. Brampton ON L6W 3G4	ESE/29.9	-22.63	585
127	GEN	2138689 Ontario Inc.	144 Kennedy Road S. Brampton ON L6W 3G4	ESE/29.9	-22.63	585
127	SPL	Commercial Complex<UNOFFICIAL>	144 Kennedy Road South, Brampton Brampton ON	ESE/29.9	-22.63	586
127	CDRY	PREMIER CLEANERS	2,144 KENNEDY DR BRAMPTON ON L6W3G4	ESE/29.9	-22.63	586
128	SPL		22 Hesketh Crt Caledon ON NA	WNW/52.1	27.77	587
129	GEN	Brampton Christian School	12480 Hutchinson Farm Lane Caledon ON	WNW/96.6	27.94	588
129	GEN	Brampton Christian School	12480 Hutchinson Farm Lane Caledon ON	WNW/96.6	27.94	588
129	GEN	Brampton Christian School	12480 Hutchinson Farm Lane Caledon ON L7C 2B6	WNW/96.6	27.94	589
129	GEN	Brampton Christian School	12480 Hutchinson Farm Lane Caledon ON L7C 2B6	WNW/96.6	27.94	589
130	SCT	COMFORT MATTRESS MFG. LTD.	158 KENNEDY RD S UNITS 12-13 BRAMPTON ON L6W 3G7	ESE/28.9	-22.63	590
130	SCT	P-O-C PRINTING LTD.	158 KENNEDY RD S UNIT 11 BRAMPTON ON L6W 3G7	ESE/28.9	-22.63	590
130	SCT	E J MACHINE CO LTD	158 KENNEDY RD S BRAMPTON ON L6W 3G7	ESE/28.9	-22.63	591
130	SCT	Comfort Mattress Manufacturing Limited	158 Kennedy Rd S Unit 12-13 Brampton ON L6W 3G7	ESE/28.9	-22.63	591

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
130	SCT	POC Printing Services Inc.	158 Kennedy Rd S Unit 11 Brampton ON L6W 3G7	ESE/28.9	-22.63	591
130	GEN	E.J. (OUT OF BUS) 49-119	158 KENNEDY ROAD SOUTH UNIT 11 BRAMPTON ON L6W 3G7	ESE/28.9	-22.63	591
130	GEN	E.J. MACHINE CO. LTD. 49-119	158 KENNEDY ROAD SOUTH UNIT 11 BRAMPTON ON L6W 3G7	ESE/28.9	-22.63	592
130	SCT	POC Gem Printing Services	158 Kennedy Rd S Unit 11 Brampton ON L6W 3G7	ESE/28.9	-22.63	592
130	GEN	Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON	ESE/28.9	-22.63	592
130	GEN	Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	ESE/28.9	-22.63	593
130	GEN	Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	ESE/28.9	-22.63	593
130	GEN	Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	ESE/28.9	-22.63	594
130	GEN	Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	ESE/28.9	-22.63	594
130	GEN	Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	ESE/28.9	-22.63	595
130	GEN	Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	ESE/28.9	-22.63	595
130	GEN	Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	ESE/28.9	-22.63	595
131	SCT	Stitchsations Inc	287 Glidden Rd Unit 6 Brampton ON L6W 1H9	ESE/90.8	-22.63	596

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
131	SCT	Stitchsations Inc.	287 Glidden Rd Unit 6 Brampton ON L6W 1H9	ESE/90.8	-22.63	596
131	SCT	Amara Furniture Manufacturing Inc.	287 Glidden Rd Unit 12 Brampton ON L6W 1H9	ESE/90.8	-22.63	596
131	SCT	POC-Gem Printing Services Inc.	287 Glidden Rd Unit 3 Brampton ON L6W 1H9	ESE/90.8	-22.63	596
131	SCT	Torbram Electric Supply Ltd.	287 Glidden Rd Unit 1 Brampton ON L6W 1H9	ESE/90.8	-22.63	597
131	GEN	Cristall Group Investments Inc	287 Glidden Road Brampton ON L6W 1H9	ESE/90.8	-22.63	597
131	GEN	Cristall Group Investments Inc	287 Glidden Road Brampton ON L6W 1H9	ESE/90.8	-22.63	597
132	SPL	Hydro One Networks Inc.	12581 Hurontario ST Caledon ON	WNW/40.5	15.38	598
133	NPCB	BENSON & HEDGES LTD.	174 KENNEDY ROAD BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	599
133	SCT	Rothmans, Benson & Hedges Inc.	174 Kennedy Rd S Brampton ON L6W 3G6	ESE/45.6	-22.63	599
133	GEN	BENSON AND HEDGES (CANADA) INC.	PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	599
133	GEN	ROTHMANS BENSON & HEDGES INC.	PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	600
133	GEN	ROTHMANS BENSON & HEDGES INC. 05-086	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	600
133	GEN	ROTHMANS BENSON & HEDGES INC. 05-086	PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	601

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	601
133	SPL	Transport International Pool<UNOFFICIAL>	174 KENNEDY RD<UNOFFICIAL> Brampton ON	ESE/45.6	-22.63	602
133	SPL	McQuary Service<UNOFFICIAL>	174 Kennedy Rd S Brampton ON L6W 3G6	ESE/45.6	-22.63	603
133	NPCB	ROTHMANS, BENSON & HEDGES INC.	174 KEN NEDY RD. SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	604
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	604
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	605
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	607
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	608
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON	ESE/45.6	-22.63	609
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	610
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	611
133	GEN	ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	ESE/45.6	-22.63	612
133	GEN	JMX Contracting Inc	174 Kennedy Rd S Brampton ON L6W 3G6	ESE/45.6	-22.63	614

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
133	GEN	JMX Contracting Inc	174 Kennedy Rd S Brampton ON L6W 3G6	ESE/45.6	-22.63	614
134	GEN	Urban Clean Ltd	25 Rambler Drive, Unit 701 Brampton ON	ESE/98.3	-22.63	614
135	FSTH	JAGDEEP MERWAR O/A CHAKHRA ASSESSMENTS INC	253 KENNEDY RD S BRAMPTON ON L6W 3H1	ESE/69.4	-22.63	615
135	SPL		253 Kennedy Rd S and Rambler Brampton ON L6W 3H1	ESE/69.4	-22.63	615
135	FST	PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	ESE/69.4	-22.63	616
135	FST	PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	ESE/69.4	-22.63	616
135	FST	PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	ESE/69.4	-22.63	617
135	FST	PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	ESE/69.4	-22.63	617
135	GEN	Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON	ESE/69.4	-22.63	617
135	RST	HUSKY GAS STATION	253 KENNEDY RD S BRAMPTON ON L6W3H1	ESE/69.4	-22.63	617
135	GEN	Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON	ESE/69.4	-22.63	617
135	GEN	Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	ESE/69.4	-22.63	618
135	GEN	Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	ESE/69.4	-22.63	618

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
135	GEN	Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	ESE/69.4	-22.63	619
135	GEN	Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	ESE/69.4	-22.63	619
135	GEN	Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	ESE/69.4	-22.63	619
135	INC	PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	ESE/69.4	-22.63	620
135	DTNK		253 KENNEDY RD S BRAMPTON ON L6W 3H1	ESE/69.4	-22.63	621
135	GEN	Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	ESE/69.4	-22.63	621
135	GEN	Parkland Corporation	253 Kennedy Road South Brampton ON L6W 3H1	ESE/69.4	-22.63	622
135	EXP	PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	ESE/69.4	-22.63	622
135	FST	PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	ESE/69.4	-22.63	622
136	GEN	Maryam Saatian dpc	26 rambler drive brampton ON L6W1E2	ESE/81.9	-24.51	623
136	GEN	Maryam Saatian dpc	26 rambler drive brampton ON L6W1E2	ESE/81.9	-24.51	623
136	GEN	Maryam Saatian dpc	26 rambler drive brampton ON L6W1E2	ESE/81.9	-24.51	623
136	GEN	Maryam Saatian dpc	26 rambler drive brampton ON L6W1E2	ESE/81.9	-24.51	624

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
136	GEN	DENTISTRY@RAMBLER	26 Rambler Dr Brampton ON L6W 1E2	ESE/81.9	-24.51	624
136	GEN	DENTISTRY@RAMBLER	26 Rambler Dr Brampton ON L6W 1E2	ESE/81.9	-24.51	624
137	GEN	1 HOUR PHOTO PLUS 43-493	24 RAMBLER DRIVE BRAMPTON ON L6W 1E2	ESE/77.0	-24.24	625
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	625
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	626
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	626
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON	ESE/87.3	-24.25	626
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	627
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	627
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	628
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	628
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	628
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	629

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
138	GEN	Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	ESE/87.3	-24.25	629
139	GEN	Dr. sarbjeet singh	30 rambler drive brampton ON L6W1E2	ESE/93.2	-24.37	630
140	SCT	National Cable Specialists	300D Kennedy Rd S Brampton ON L6W 4V2	ESE/46.7	-25.63	630
140	SCT	Noramco Wire & Cable	300D Kennedy Rd S Brampton ON L6W 4V2	ESE/46.7	-25.63	630
140	GEN	OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON	ESE/46.7	-25.63	631
140	GEN	OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	ESE/46.7	-25.63	631
140	GEN	OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	ESE/46.7	-25.63	632
140	GEN	OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	ESE/46.7	-25.63	632
140	GEN	OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	ESE/46.7	-25.63	632
140	GEN	OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	ESE/46.7	-25.63	633
140	GEN	OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	ESE/46.7	-25.63	633
140	GEN	OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	ESE/46.7	-25.63	634
141	SCT	TST	365 Kennedy Rd S Unit 116 Brampton ON L6W 3H3	ESE/81.6	-23.63	634

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
141	SCT	T.S.T. Enterprises	365 Kennedy Rd S Suite 116 Brampton ON L6W 3H3	ESE/81.6	-23.63	635
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	635
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W 4V2	ESE/93.6	-24.63	636
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W 4V2	ESE/93.6	-24.63	636
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W 4V2	ESE/93.6	-24.63	637
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	637
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON	ESE/93.6	-24.63	638
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	638
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	639
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	640
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	641
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	642
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	644

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
142	GEN	Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	ESE/93.6	-24.63	645
143	SPL		3 Scotsdale Court Brampton ON	ESE/65.8	-22.64	646
144	GEN	Michaels Stores, Inc.	120 Resolution Dr Brampton ON L6W 4P9	ESE/13.9	-23.63	647
144	GEN	Michaels Stores, Inc.	120 Resolution Dr Brampton ON L6W 4P9	ESE/13.9	-23.63	648
144	GEN	Michaels Stores, Inc.	120 Resolution Dr Brampton ON L6W 4P9	ESE/13.9	-23.63	648
144	GEN	Michaels Stores, Inc.	120 Resolution Dr Brampton ON L6W 4P9	ESE/13.9	-23.63	649
145	EXP	DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	ESE/16.5	-22.82	650
146	NPCB	CHRYSLER (CANADA) INC.	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	ESE/16.5	-22.82	650
146	SPL	CHRYSLER CANADA LTD.	BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON CITY ON	ESE/16.5	-22.82	652
146	SPL	CHRYSLER CANADA LTD.	BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON CITY ON	ESE/16.5	-22.82	653
146	GEN	CHRYSLER CANADA LTD.	350 KENNEDY ROAD S. BRAMPTON ON L6V 2M3	ESE/16.5	-22.82	653
146	GEN	CHRYSLER CANADA LTD. 10-341	350 KENNEDY ROAD S. BRAMPTON ON L6W 4P1	ESE/16.5	-22.82	655
146	GEN	CHRYSLER CANADA LIMITED	BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON ON L6W 4P1	ESE/16.5	-22.82	656

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
146	GEN	AMERICAN MOTORS (CANADA) LTD.	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	ESE/16.5	-22.82	657
146	GEN	AMERICAN MOTORS SEE&USE ON0000608	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	ESE/16.5	-22.82	658
146	GEN	AMERICAN (SEE & USE ON0000608)	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	ESE/16.5	-22.82	659
146	GEN	AMERICAN (SEE & USE ON0000608) 03-063	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	ESE/16.5	-22.82	659
146	GEN	Rutherford Properties Ltd.	350 Kennedy Road South Brampton ON L5B 1M3	ESE/16.5	-22.82	659
146	NPCB	CHRYSLER (CANADA) INC.	350 KENNEDY RD S BRAMPTON ON L6V 2M3	ESE/16.5	-22.82	660
146	DTNK	DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	ESE/16.5	-22.82	660
146	DTNK	DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	ESE/16.5	-22.82	660
146	DTNK	DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	ESE/16.5	-22.82	661
146	DTNK	DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	ESE/16.5	-22.82	662
146	DTNK	DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	ESE/16.5	-22.82	662
147	GEN	TONY'S CUSTOM CLEANERS	400 STEELS AVE. E. BRAMPTON ON L6W 3R2	ESE/78.2	-23.27	663

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
147	GEN	TONY'S CUSTOM CLEANERS	400 STEELS AVE. E. BRAMPTON ON L6W 3R2	ESE/78.2	-23.27	663
147	GEN	TONY'S CUSTOM CLEANERS 38-332	400 STEELS AVE. E. BRAMPTON ON L6W 3R2	ESE/78.2	-23.27	664
147	GEN	TONY'S CUSTOM CLEANERS	400 STEELES AVENUE EAST BRAMPTON ON L6W 3R2	ESE/78.2	-23.27	664
147	SCT	Distributors Choice Chemical	400 Steeles Ave E Unit 231 Brampton ON L6W 3R2	ESE/78.2	-23.27	664
148	GEN	GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	ESE/99.4	-24.84	665
148	GEN	GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	ESE/99.4	-24.84	665
148	GEN	GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	ESE/99.4	-24.84	665
148	GEN	GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	ESE/99.4	-24.84	666
148	GEN	GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	ESE/99.4	-24.84	666
149	GEN	Rutherford Properties Ltd	410 Steeles Avenue Brampton ON	ESE/12.7	-23.88	667
150	SPL	Canadian Waste Services Inc.	Kennedy Road at Steeles Ave<UNOFFICIAL> Brampton ON	ESE/27.8	-24.42	667
150	SPL	Canada Cartage Diversified Gp. Inc.	Kennedy Road (50 feet north of Steeles Ave)<UNOFFICIAL> Brampton ON	ESE/27.8	-24.42	668
151	RST	SOLOMON ESSO	7995 KENNEDY RD BRAMPTON ON L6V3N2	ESE/27.6	-24.53	669

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
151	RST	KENNEDY ESSO	7995 KENNEDYS BRAMPTON ON	ESE/27.6	-24.53	669
151	FSTH	1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD S BRAMPTON ON	ESE/27.6	-24.53	669
151	DTNK	UNIPETRO INVESTMENTS INC ATTN AC CHOU	7995 KENNEDY RD S BRAMPTON ON L6V 3N2	ESE/27.6	-24.53	670
151	DTNK	IMPERIAL OIL LTD *** DO NOT USE	7995 KENNEDY RD S BRAMPTON ON L6V 3N2	ESE/27.6	-24.53	670
151	FST	MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	671
151	FST	MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	671
151	FST	MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	671
151	FST	MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	672
151	RST	KENNEDY ESSO	7995 KENNEDY RD BRAMPTON ON L6W0A2	ESE/27.6	-24.53	672
151	EXP	1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	672
151	EXP	1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	672
151	EXP	1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	673
151	EXP	1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	673

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
151	EXP	1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	673
151	FST	MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	ESE/27.6	-24.53	673
152	GEN	English Prestige	7980 KENNEDY ROAD SOUTH Brampton ON	ESE/62.8	-25.53	674
153	GEN	Dr. Amanpreet Chopra Dentistry Prof Corp	7-7990 Kennedy Road South Brampton ON L6W 0B3	ESE/95.3	-26.43	674
153	GEN	Dr. Amanpreet Chopra Dentistry Prof Corp	7-7990 Kennedy Road South Brampton ON L6W 0B3	ESE/95.3	-26.43	674
153	GEN	Dr. Amanpreet Chopra Dentistry Prof Corp	7-7990 Kennedy Road South Brampton ON L6W 0B3	ESE/95.3	-26.43	675
153	GEN	Dr. Amanpreet Chopra Dentistry Prof Corp	7-7990 Kennedy Road South Brampton ON L6W 0B3	ESE/95.3	-26.43	675
154	GEN	PEEL BOARD OF EDUCATION	J. A. TURNER S.S. 7935 KENNEDY RD. S. BRAMPTON ON L6V 3N2	ESE/81.8	-27.84	675
154	GEN	PEEL BOARD OF EDUCATION 30-190	TURNER FENTON SECONDARY SCHOOL 7935 KENNEDY ROAD SOUTH BRAMPTON ON L5B 1N7	ESE/81.8	-27.84	676
154	GEN	PEEL DISTRICT SCHOOL BOARD	TURNER FENTON SECONDARY SCHOOL 7935 KENNEDY ROAD SOUTH BRAMPTON ON L5B 1N7	ESE/81.8	-27.84	677
154	GEN	PEEL DISTRICT SCHOOL BOARD	7935 Kennedy Road South BRAMPTON ON L5B 1N7	ESE/81.8	-27.84	677
154	GEN	Peel District School Board	7935 Kennedy Road South Brampton ON	ESE/81.8	-27.84	678

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
154	GEN	Peel District School Board	7935 Kennedy Road South Brampton ON	ESE/81.8	-27.84	679
154	GEN	Peel District School Board	7935 Kennedy Road South Brampton ON	ESE/81.8	-27.84	680
154	GEN	Peel District School Board	7935 Kennedy Road South Brampton ON	ESE/81.8	-27.84	680
154	GEN	Peel District School Board	7935 Kennedy Road South Brampton ON	ESE/81.8	-27.84	681
154	GEN	Peel District School Board	7935 Kennedy Road South Brampton ON L5B 1N7	ESE/81.8	-27.84	682
154	GEN	Peel District School Board	7935 Kennedy Road South Brampton ON L5B 1N7	ESE/81.8	-27.84	683
154	GEN	Peel District School Board	7935 Kennedy Road South Brampton ON L5B 1N7	ESE/81.8	-27.84	683
154	GEN	Peel District School Board Human Resources Support Services	7935 Kennedy Road South Brampton ON L5B 1N7	ESE/81.8	-27.84	684
154	GEN	Peel District School Board Human Resources Support Services	7935 Kennedy Road South Brampton ON L5B 1N7	ESE/81.8	-27.84	685
154	GEN	Peel District School Board Human Resources Support Services	7935 Kennedy Road South Brampton ON L5B 1N7	ESE/81.8	-27.84	686
154	GEN	Peel District School Board Human Resources Support Services	7935 Kennedy Road South Brampton ON L5B 1N7	ESE/81.8	-27.84	686
155	GEN	PEEL BOARD OF EDUCATION	W.J. FENTON S.S. 7885 KENNEDY ROAD SOUTH, RR# 10 BRAMPTON ON L6V 3N2	ESE/94.8	-29.63	687
155	GEN	PEEL BOARD OF EDUCATION	W.J. FENTON SECONDARY SCHOOL 7885 KENNEDY ROAD SOUTH, RR# 10 BRAMPTON ON L6V 3N2	ESE/94.8	-29.63	688

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
155	GEN	PEEL (SEE & USE ON0359810) 30-594	W.J. FENTON SECONDARY SCHOOL 7885 KENNEDY ROAD SOUTH, RR# 10 BRAMPTON ON L6V 3N2	ESE/94.8	-29.63	688
155	GEN	PEEL (SEE & USE ON0359810)	W.J. FENTON SECONDARY SCHOOL 7885 KENNEDY ROAD SOUTH, RR# 10 BRAMPTON ON L6V 3N2	ESE/94.8	-29.63	689
156	SPL	Makkar Transport<UNOFFICIAL>	Hwy 10 @ Old School Road Caledon ON	WNW/17.6	35.39	690
156	SPL		hwy 10 southbound and Old School Road intersection in Brampton CALEDON ON	WNW/17.6	35.39	690
157	SPL	Super Sucker Hydro-Vac Service	BRAMPTON ON	ESE/66.4	-29.63	691
158	GEN	Arvin Meritor Canada	350 First Gulf Boulevard Brampton ON L6W 4T5	ESE/95.2	-31.35	692
158	GEN	Meritor Aftermarket Canada, Inc.	350 First Gulf Boulevard Brampton ON	ESE/95.2	-31.35	692
158	GEN	Arvin Meritor Canada Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	ESE/95.2	-31.35	693
158	GEN	Meritor Aftermarket Canada, Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	ESE/95.2	-31.35	693
158	GEN	Meritor Aftermarket Canada, Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	ESE/95.2	-31.35	694
158	GEN	Meritor Aftermarket Canada, Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	ESE/95.2	-31.35	694
158	GEN	Meritor Aftermarket Canada	350 First Gulf Boulevard Brampton ON	ESE/95.2	-31.35	695

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
158	GEN	Meritor Aftermarket Canada Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	ESE/95.2	-31.35	695
158	GEN	Meritor Aftermarket Canada Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	ESE/95.2	-31.35	696
158	GEN	Mascot Truck Parts	350 First Gulf Boulevard Brampton ON L6W 4T5	ESE/95.2	-31.35	696
158	SPL		350 First Gulf Blvd, Brampton ON	ESE/95.2	-31.35	697
159	SPL		8 Sifford Ct. BRAMPTON ON	ESE/34.2	-29.06	698
160	AUWR	ATL TOWING & SCRAP CAR REMOVAL	14 CASPER CRES BRAMPTON ON L6W 4N4	ESE/70.4	-29.63	698
160	AUWR	ATL TOWING & SCRAP CAR REMOVAL	14 CASPER CRES BRAMPTON ON L6W4N4	ESE/70.4	-29.63	699
161	SPL	Absolute Environmental (King Towing)	Hwy 10 200m N of Old School Rd., Caledon CALEDON ON	WNW/92.7	38.75	699

Executive Summary: Summary By Data Source

AUWR - Automobile Wrecking & Supplies

A search of the AUWR database, dated 1999-Apr 30, 2024 has found that there are 3 AUWR site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CROSS CANADA AUTO BODY SUPPLY LTD	100 KENNEDY RD S BRAMPTON ON L6W 3E8	89.1	111
ATL TOWING & SCRAP CAR REMOVAL	14 CASPER CRES BRAMPTON ON L6W 4N4	70.4	160
ATL TOWING & SCRAP CAR REMOVAL	14 CASPER CRES BRAMPTON ON L6W4N4	70.4	160

CDRY - Dry Cleaning Facilities

A search of the CDRY database, dated Jan 2004-Dec 2022 has found that there are 3 CDRY site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Magic Touch Dry Cleaners	1 Wexford Rd Brampton ON L6Z2W1	98.4	5
Smartex Dry Cleaners	50 Kennedy Rd S #29 Brampton ON L6W3R7	92.7	104
PREMIER CLEANERS	2,144 KENNEDY DR BRAMPTON ON L6W3G4	29.9	127

CFOT - Commercial Fuel Oil Tanks

A search of the CFOT database, dated Oct 2023 has found that there are 1 CFOT site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BELL CANADA	11450 HURONTARIO ST. BRAMPTON ON	51.0	63

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 67 DTNK site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
AUTO BATH INC	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
PEEL SEED CO-OPERATIVE INC	10064 HURONTARIO ST BRAMPTON ON	59.4	18
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	40.6	19
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	40.6	19
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	40.6	19
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	40.6	19

Site	Address	Distance (m)	Map Key
PREET PETROLEUM	HWY 7 HWY 10 BRAMPTON ON L3M 1V1	6.8	20
PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	54.6	24
PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	54.6	24
PIONEER ENERGY MANAGEMENT INC.	675 MAIN ST N BRAMPTON ON	54.6	24
CATERPILLAR OF CANADA LTD	100 SANDALWOOD PKWY CORNER OF HWY 1O BRAMPTON ON	89.2	40
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47

Site	Address	Distance (m)	Map Key
SIMCOE ENERGY & TECHNICAL SERVICES INC *	121 KENNEDY RD N BRAMPTON ON	69.3	49
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON L6V 1A1	61.8	56
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	61.8	56
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	61.8	56
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	61.8	56
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	61.8	56
SHELL CANADA PRODUCTS**	230 QUEEN ST E BRAMPTON ON	77.0	70
2931621 CANADA INC O/A CANADIAN TIRE	1 KENNEDY RD S BRAMPTON ON	88.8	74
MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON L6W 3E1	13.4	77
MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	13.4	77
MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	13.4	77
QUEEN & KENNEDY CARWASH	24 KENNEDY RD S BRAMPTON ON L6W 3E2	19.8	83

Site	Address	Distance (m)	Map Key
KENNEDY & EASTERN PROPANE	24 KENNEDY RD S BRAMPTON ON	19.8	83
KENNEDY & EASTERN PROPANE	24 KENNEDY RD S BRAMPTON ON	19.8	83
KENNEDY & EASTERN PROPANE	24 KENNEDY RD S BRAMPTON ON	19.8	83
PETROLEUM PLUS GROUP INC	11865 HWY 10 SNELGROVE ON L0P 1M0	31.2	84
1319911 ONTAIRO INC O/A DAVE'S GAS BAR VARIETY	11865 HURONTARIO ST BRAMPTON ON	31.2	84
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84
STEPHENSONS RENT ALL INC ATTN JOHN FLINT	26 KENNEDY RD S BRAMPTON ON	21.4	85
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	30 KENNEDY RD S BRAMPTON ON	21.6	87

Site	Address	Distance (m)	Map Key
P D MONTGOMERY ENTERPRISES INC CANADIAN TIRE AUTO CENTRE	30 KENNEDY RD S BRAMPTON ON	21.6	87
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	30 KENNEDY RD S BRAMPTON ON	21.6	87
P D MONTGOMERY ENTERPRISES INC CANADIAN TIRE AUTO CENTRE	30 KENNEDY RD S BRAMPTON ON	21.6	87
2124964 ONTARIO INC O/A PETRO-CANADA	11980 HURONTARIO ST (HWY 10) BRAMPTON ON L7A 1E6	54.5	89
TWIN PETROLEUM PRODUCTS LTD	HWY 10 (MAYFIELD RD) SNELGROVE ON L0P 1M0	2.1	92
ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON L7A 1E6	25.0	94
ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	25.0	94
G M F TRANSPORT	32 KENNEDY RD S BRAMPTON ON	32.6	96
G M F TRANSPORT	32 KENNEDY RD S BRAMPTON ON	32.6	96
IKO INDUSTRIES LTD	71 ORENDA RD BRAMPTON ON	92.8	97
IKO INDUSTRIES LTD	71 ORENDA RD BRAMPTON ON	92.8	97
MANUEL FILIPE & FERNANDO MELO SERV CENTRE LTD	149 CLARENCE ST BRAMPTON ON L6W 1T2	67.4	102

Site	Address	Distance (m)	Map Key
TRAVELWAYS LTD	12267 HURONTARIO ST SNELGROVE ON	86.6	112
LAIDLAW TRANSIT LTD	12267 HURONTARIO ST BRAMPTON ON	86.6	112
TRAVELWAYS LTD	12267 HURONTARIO ST SNELGROVE ON	86.6	112
IMPERIAL OIL LTD	129 KENNEDY RD BRAMPTON ON	33.6	122
	253 KENNEDY RD S BRAMPTON ON L6W 3H1	69.4	135
DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	16.5	146
DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	16.5	146
DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	16.5	146
DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	16.5	146
DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	16.5	146
UNIPETRO INVESTMENTS INC ATTN AC CHOU	7995 KENNEDY RD S BRAMPTON ON L6V 3N2	27.6	151

Site	Address	Distance (m)	Map Key
IMPERIAL OIL LTD *** DO NOT USE	7995 KENNEDY RD S BRAMPTON ON L6V 3N2	27.6	151

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Oct 2023 has found that there are 47 EXP site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON	67.1	15
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	40.6	19
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	40.6	19
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	40.6	19
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR E BRAMPTON ON	40.6	19

Site	Address	Distance (m)	Map Key
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON	42.3	47
2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	69.3	49
2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	69.3	49
2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	69.3	49
2124964 ONTARIO INC O/A PETRO-CANADA	121 KENNEDY RD N BRAMPTON ON	69.3	49
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	61.8	56

Site	Address	Distance (m)	Map Key
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	61.8	56
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	61.8	56
ESSO SELF SERVE	11005 HURONTARIO ST BRAMPTON ON	61.8	56
PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON	41.4	68
SHELL CANADA PRODUCTS	230 QUEEN ST E BRAMPTON ON	77.0	70
SHELL CANADA PRODUCTS	230 QUEEN ST E BRAMPTON ON	77.0	70
MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	13.4	77
MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	13.4	77
MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	13.4	77
MEL AND AUTO CENTRE INC	18 KENNEDY RD S BRAMPTON ON	13.4	77
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84

Site	Address	Distance (m)	Map Key
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84
ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	25.0	94
ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	25.0	94
ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	25.0	94
ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	25.0	94
ORMEAU DEVELOPMENTS	12004 HURONTARIO ST BRAMPTON ON	25.0	94
G M F TRANSPORT	32 KENNEDY RD S BRAMPTON ON	32.6	96
PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	69.4	135
DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT	350 KENNEDY RD S BRAMPTON ON	16.5	145
1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	27.6	151

Site	Address	Distance (m)	Map Key
1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	27.6	151
1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	27.6	151
1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	27.6	151
1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD BRAMPTON ON	27.6	151

FST - Fuel Storage Tank

A search of the FST database, dated Oct 2023 has found that there are 59 FST site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST BRAMPTON ON	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST BRAMPTON ON	67.1	15
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	40.6	19
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	40.6	19
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	40.6	19

Site	Address	Distance (m)	Map Key
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	40.6	19
MAC'S CONVENIENCE STORES INC.	9 BOVAIRD DR E BRAMPTON ON	40.6	19
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	24
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	24
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	24
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	24
PARKLAND CORPORATION	675 MAIN ST N BRAMPTON ON	54.6	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	77.5	36
SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	77.5	36
SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	77.5	36
SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	77.5	36

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	77.5	36
MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	42.3	47
MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	42.3	47
MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	42.3	47
MAC'S CONVENIENCE STORES INC.	140 KENNEDY RD N BRAMPTON ON	42.3	47
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	69.3	49
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	69.3	49
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	69.3	49
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	69.3	49
SUNCOR ENERGY PRODUCTS PARTNERSHIP	121 KENNEDY RD N BRAMPTON ON	69.3	49
MAC'S CONVENIENCE STORES INC.	230 WANLESS DR BRAMPTON ON	93.0	58
MAC'S CONVENIENCE STORES INC.	230 WANLESS DR BRAMPTON ON	93.0	58

Site	Address	Distance (m)	Map Key
MAC'S CONVENIENCE STORES INC.	230 WANLESS DR BRAMPTON ON	93.0	58
GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	31.2	84
GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	31.2	84
GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	31.2	84
GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	31.2	84
GURU KIRPA FUEL AND FOOD INC.	11865 HURONTARIO ST BRAMPTON ON	31.2	84
SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	54.5	89
SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	54.5	89
SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	54.5	89
SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	54.5	89
SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	54.5	89

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	48.7	93
SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	48.7	93
SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	48.7	93
SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	48.7	93
SUNCOR ENERGY PRODUCTS PARTNERSHIP	12011 HURONTARIO ST BRAMPTON ON	48.7	93
THE POULTRY COMPANY ATTN FRANK TOIRKENS	32 KENNEDY RD S BRAMPTON ON	32.6	96
IKO INDUSTRIES LTD	71 ORENDA RD BRAMPTON ON	92.8	97
BUDGET RENT A CAR	73 KENNEDY RD S BRAMPTON ON	65.2	100
BUDGET RENT A CAR	73 KENNEDY RD S BRAMPTON ON	65.2	100
PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	69.4	135
PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	69.4	135
PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	69.4	135

Site	Address	Distance (m)	Map Key
PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	69.4	135
PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	69.4	135
MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	27.6	151
MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	27.6	151
MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	27.6	151
MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	27.6	151
MAC'S CONVENIENCE STORES INC.	7995 KENNEDY RD BRAMPTON ON	27.6	151

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 24 FSTH site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON L7A 0E4	67.1	15
2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD	10178 HURONTARIO ST & WEXFORD BRAMPTON ON L7A 0E4	67.1	15

Site	Address	Distance (m)	Map Key
1672237 ONTARIO LTD	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	40.6	19
RAMKUMAR ENTERPRISES INC	9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	40.6	19
PIONEER PETROLEUMS MANAGEMENT INC**	675 MAIN ST N BRAMPTON ON L6X 0G6	54.6	24
PIONEER PETROLEUMS MANAGEMENT INC**	675 MAIN ST N BRAMPTON ON L6X 0G6	54.6	24
PAUL PAUAO	5 SANDALWOOD PKWY W BRAMPTON ON L7A 1J6	77.5	36
PAUL PAUAO	5 SANDALWOOD PKWY W BRAMPTON ON L7A 1J6	77.5	36
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON L6V 2N4	42.3	47
ESSO MAXIMUM ATTN MANJIT MANN	140 KENNEDY RD N BRAMPTON ON L6V 2N4	42.3	47
PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON L6V 1X4	41.4	68
PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON L6V 1X4	41.4	68
B & P AUTO CENTRE LTD	11865 HURONTARIO ST SNELGROVE BRAMPTON ON	31.2	84
SANTAK PIT STOP INC	11865 HURONTARIO ST BRAMPTON ON	31.2	84

Site	Address	Distance (m)	Map Key
1205073 ONTARIO LTD	11980 HURONTARIO ST BRAMPTON ON L7A 1E6	54.5	89
2074065 ONTARIO INC O/A GAS STN	12011 HURONTARIO ST HWY 10 BRAMPTON ON L6Z 4P8	48.7	93
THE POULTRY COMPANY ATTN FRANK TOIRKENS	32 KENNEDY RD S BRAMPTON ON L6W 3E3	32.6	96
THE POULTRY COMPANY ATTN FRANK TOIRKENS	32 KENNEDY RD S BRAMPTON ON L6W 3E3	32.6	96
IKO INDUSTRIES	71 ORENDA RD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES	71 ORENDA RD BRAMPTON ON L6W 1V8	92.8	97
BUDGET RENT A CAR	73 KENNEDY RD S BRAMPTON ON L6W 3E4	65.2	100
BUDGET RENT A CAR	73 KENNEDY RD S BRAMPTON ON L6W 3E4	65.2	100
JAGDEEP MERWAR O/A CHAKHRA ASSESSMENTS INC	253 KENNEDY RD S BRAMPTON ON L6W 3H1	69.4	135
1520348 ONTARIO LTD ATT FIDA ELDEBS	7995 KENNEDY RD S BRAMPTON ON	27.6	151

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 604 GEN site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PEEL BLOCK CO. LTD	307 BOVAIRD DR, BOX 297 BRAMPTON ON L6V 2L1	10.6	2
PEEL BLOCK CO. (OUT OF BUSINESS)	307 BOVAIRD DR, BOX 297 BRAMPTON ON L6V 2L1	10.6	2
PEEL BLOCK CO. (OUT OF BUSINESS) 30-205	307 BOVAIRD DR, BOX 297 BRAMPTON ON L6V 2L1	10.6	2
PHARMA PLUS DRUGS LTD.	380 BOVAIRD ROAD, UNIT 26 BRAMPTON ON L6Z 2N7	86.8	3
PHARMA PLUS DRUGS LTD. 31-803	380 BOVAIRD RD. UNIT 26 C/O 5935 AIRPORT ROAD STE. #500 MISSISSAUGA ON L4V 1W5	86.8	3
Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	86.8	3
Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	86.8	3
conestoga pharmacy inc	26-380 bovaird dr e brampton ON L6Z2S8	86.8	3
conestoga pharmacy inc	26-380 bovaird dr e brampton ON L6Z2S8	86.8	3
Sehdev Drugs Limited	26-380 Bovaird Drive East Brampton ON L6Z 2S8	86.8	3
Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	86.8	3

Site	Address	Distance (m)	Map Key
Sehdev Drugs Limited	26-380 Bovaird Drive East Brampton ON L6Z 2S8	86.8	3
Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	86.8	3
Dr. Allan M Bregman Dentistry PC	380 Bovaird Drive Brampton ON L6Z2S7	86.8	3
Sehdev Drugs Limited	26-380 Bovaird Drive East Brampton ON L6Z 2S8	86.8	3
Sehdev Drugs Limited	26-380 Bovaird Drive East Brampton ON L6Z 2S8	86.8	3
Conestoga Dental Centre	380 bovaird dr east suite 23 brampton ON L6Z 2S7	86.8	3
PLATIS & SONS CLEANERS	1 WEXFORD ROAD, UNIT 1 BRAMPTON ON L6Z 2W1	98.4	5
PLATIS & SONS CLEANERS	1 WEXFORD ROAD UNIT 1 BRAMPTON ON L6Z 2W1	98.4	5
PLATIS & SONS 1 HOUR CLEANERS	1 WEXFORD ROAD BRAMPTON ON L6Z 2W1	98.4	5
HASTY MARKET 19-675	1 WEXFORD ROAD, UNIT 9 BRAMPTON ON L6Z 2W1	98.4	5
HASTY MARKET	1 WEXFORD ROAD, UNIT 9 BRAMPTON ON L6Z 2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford St, Unit 10 Brampton ON L6Z 2W1	98.4	5

Site	Address	Distance (m)	Map Key
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON	98.4	5
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	98.4	5
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5

Site	Address	Distance (m)	Map Key
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON L6Z 2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON	98.4	5
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON	98.4	5
First Choice MedCentre Inc.	1 Wexford Rd. Unit 8 Brampton ON	98.4	5
wexford square dental	1 wexford road ,unit #7 brampton ON L6Z2W1	98.4	5
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5
wexford square dental	1 wexford road ,unit #7 brampton ON L6Z2W1	98.4	5
Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	98.4	5

Site	Address	Distance (m)	Map Key
Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD BRAMPTON ON L6Z 2W1	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	98.4	5
Dawson DCC-Wexford Square Dental	1 Wexford Road Unit 7 Brampton ON L6Z2W1	98.4	5
MAGIC TOUCH 1HR. CLEANERS	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5
Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	98.4	5

Site	Address	Distance (m)	Map Key
Dawson DCC-Wexford Square Dental	1 Wexford Road Unit 7 Brampton ON L6Z2W1	98.4	5
Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	98.4	5
11244485 Canada Inc.	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	98.4	5
Innomar-Strategies Inc.	1 Wexford Rd. Brampton ON L6Z 2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5
11244485 Canada Inc.	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	98.4	5
Dawson DCC-Wexford Square Dental	1 Wexford Road Unit 7 Brampton ON L6Z2W1	98.4	5
Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5
Mackenzie Medical Rehab	Mackenzie Medical Rehab 1 Wexford Road Unit 8 Brampton ON L6Z2W1	98.4	5
Emergency Veterinary Clinic - Highway 10	1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	98.4	5
Dawson DCC-Wexford Square Dental	1 Wexford Road Unit 7 Brampton ON L6Z2W1	98.4	5

Site	Address	Distance (m)	Map Key
11244485 Canada Inc.	1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	98.4	5
Wexford Medical Clinic	1 Wexford rd Brampton ON L6Z2W1	98.4	5
FORTINO'S SUPERMARKET LTD.	60 QUARRY EDGE DRIVE HIGHWAY 10 & BOVAIRD DRIVE BRAMPTON ON L6V 1K2	92.3	6
Loblaw Companies Inc	60 Quarry Edge Dr. Brampton ON L6V 4K2	92.3	6
Loblaw Companies Inc	60 Quarry Edge Dr. Brampton ON L6V 4K2	92.3	6
LOBLAWS INC. Fortinos	60 Quarry Edge Dr. Brampton ON L6V 4K2	92.3	6
LOBLAWS INC. Fortinos	60 Quarry Edge Dr. Brampton ON L6V 4K2	92.3	6
LOBLAWS INC. Fortinos	60 Quarry Edge Dr. Brampton ON L6V 4K2	92.3	6
LOBLAWS INC. Fortinos	60 Quarry Edge Dr. Brampton ON L6V 4K2	92.3	6
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9

Site	Address	Distance (m)	Map Key
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
Sherwin Williams Company	10025 Hurontario Street Brampton ON L6Z 0E6	67.9	9
PETM Canada Corporation	76 Quarry Edge Dr brampton ON L6V4K2	49.5	10
PETM Canada Corporation	76 Quarry Edge Dr brampton ON L6V4K2	49.5	10
PETM Canada Corporation	76 Quarry Edge Dr brampton ON L6V4K2	49.5	10

Site	Address	Distance (m)	Map Key
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	73.7	11
Pharma Plus Drugmarts Ltd	10035 Hurontario Street Brampton ON L6Z 0E6	73.7	11
Pharma Plus Drugmarts Ltd	10035 Hurontario Street Brampton ON L6Z 0E6	73.7	11
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	73.7	11
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	73.7	11
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	73.7	11
Rexall Pharmacy Group Ltd.	10035 Hurontario Street Brampton ON L6Z 0E6	73.7	11
CT REIT (Hurontario) Limited Partnership, by its g	10254 Hurontario Street Brampton ON L7A 0E4	54.1	16
CT REIT (Hurontario) Limited Partnership, by its g	10254 Hurontario Street Brampton ON L7A 0E4	54.1	16
The Sherwin-Williams Company	10086 Hurontario Street Units 15 & 16 Brampton ON L7A 1E5	80.5	17
The Sherwin-Williams Company	10086 Hurontario Street Units 15 & 16 Brampton ON L7A 1E5	80.5	17

Site	Address	Distance (m)	Map Key
Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	40.6	19
Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	40.6	19
Mac's Convenience Stores Inc.	9 Bovaird Drive Brampton ON L6V 0A2	40.6	19
Regionional Municipality of Peel	2 - 30 Bovaird Drive West Brampton ON L7A 0H3	81.7	23
Regional Municipality of Peel	2 - 30 Bovaird Drive West Brampton ON L7A 0H3	81.7	23
Pinchin Ltd.	2-30 Bovaird Drive West Brampton ON L7A 0H3	81.7	23
Pioneer Energy LP	675 Main Street North Brampton ON L6X 0G6	54.6	24
Mandarano/Vilone Property	10394 Hurontario Street North Brampton ON L7A 0E4	56.3	26
New Image Car Wash	11 Fisherman Dr Brampton ON L7A2X9	80.9	29
MAYFIELD DRYWALL AND CONTRACTING	13 FISHERMAN DR BRAMPTON ON L7A 2X9	97.7	30
Centric Health	2 Fisherman Drive, Unit 7 Brampton ON	57.0	33
Centric Health	2 Fisherman Drive, Unit 7 Brampton ON	57.0	33

Site	Address	Distance (m)	Map Key
Stephenson's Rental Services Inc.	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	57.0	33
Centric Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	57.0	33
Centric Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	57.0	33
Stephenson's Rental Services Inc.	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	57.0	33
Centric Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	57.0	33
Stephenson's Rental Services Inc. Brampton 109	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	57.0	33
Lifemark Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	57.0	33
Lifemark Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	57.0	33
Stephenson's Rental Services Inc. Brampton 109	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	57.0	33
Stephenson's Rental Services Inc. Brampton 109	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	57.0	33
Lifemark Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	57.0	33

Site	Address	Distance (m)	Map Key
Lifemark Health	2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	57.0	33
Stephenson's Rental Services Inc. Brampton 109	2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	57.0	33
Belfor Property Restoration	10545 Hurontario Street Brampton ON L6Z 2V9	62.3	35
CAT SEE & USE ON0007801 CATERPILLAR	100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	89.2	40
CATERPILLAR OF CANADA LTD.	100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	89.2	40
CATERPILLAR OF CANADA LTD. 09-075	100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	89.2	40
CATERPILLAR OF CANADA LIMITED	100 SANDALWOOD PARKWAY BRAMPTON ON L6V 3Y4	89.2	40
Exel Canada Ltd.	100 Sandalwood Parkway West. Brampton ON L7A 1A8	89.2	40
Orlando Corporation	100 Sandalwood Drive Brampton ON L7A 1A8	89.2	40
Exel Logistics-Canada Inc	100 Sanalwood parkway Brampton ON	89.2	40
KELLOGG'S	100 SANDALWOOD PARKWAY WEST BRAMPTON ON L7A 1A8	89.2	40
Kennedy Road Tabernacle	141 Kennedy Road N Brampton ON L6V 1X9	41.4	45

Site	Address	Distance (m)	Map Key
Suncor Energy Products	121 Kennedy Road N Brampton ON L6V1X	69.3	49
Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	69.3	49
Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	69.3	49
Suncor Energy Products Partnership	121 Kennedy Road N Brampton ON L6V1X	69.3	49
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	89.9	51
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	89.9	51
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	89.9	51
PHARMA PLUS DRUGS LTD	227 VODDEN STREET BRAMPTON ON L6V 1N2	89.9	51
PHARMA PLUS DRUGS LTD. 31-751	227 VODDEN ST., BRAMPTON C/O 5935 AIRPORT ROAD #500 MISSISSAUGA ON L4V 1W5	89.9	51
PHARMA PLUS DRUGMARTS LTD.	227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	89.9	51
GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.	FOOD BASICS #983 227 VODDEN STREET BRAMPTON ON L6V 1N2	89.9	51

Site	Address	Distance (m)	Map Key
PHARMA PLUS DRUGS LTD.	227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	89.9	51
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	89.9	51
1723525 Ontario Inc.	227 Vodden Street East Unit 30B Brampton ON	89.9	51
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	89.9	51
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	89.9	51
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON	89.9	51
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	89.9	51
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	89.9	51
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	89.9	51
Pharma Plus Drugmarts Ltd	227 Vodden Street East Brampton ON L6V 1N2	89.9	51
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	89.9	51
Pharma Plus Drugmarts Ltd	227 Vodden Street East Brampton ON L6V 1N2	89.9	51

Site	Address	Distance (m)	Map Key
Rexall Pharmacy Group Ltd.	227 Vodden Street East Brampton ON L6V 1N2	89.9	51
Exquizeet Tattoo & Piercing Studio	227 Vodden Street, Unit 30B Brampton ON L6V 1N2	89.9	51
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton, ON L7A 3R9	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton, ON L7A 3R9	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton, ON	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON	93.3	52
Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	93.3	52
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	93.3	52

Site	Address	Distance (m)	Map Key
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton, ON L7A 3R9	93.3	52
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	93.3	52
Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	93.3	52
Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52

Site	Address	Distance (m)	Map Key
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Kutty/Suppal Prof Med Corp	A7 10886 Hurontario Street, North Brampton ON L7A 3R9	93.3	52
Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	93.3	52
Mulla/Suppal Prof Med Corp	A7 10886 Hurontario St, North Brampton ON L7A3R9	93.3	52
Essence Medical Esthetics	9-10886 Hurontario St. North Brampton ON L7A 3R9	93.3	52
Chopra Dentistry Professional	10886 Hurontario St Unit A15 Brampton ON L7A3R9	93.3	52
Heart Lake Veterinary Hospital Professional Corp	23 Conservation Drive # 6 Brampton ON L6Z 4R3	75.8	54
Heart Lake Veterinary Hospital Professional Corp	23 Conservation Drive # 6 Brampton ON L6Z 4R3	75.8	54
Heart Lake Veterinary Hospital Professional Corp	23 Conservation Drive # 6 Brampton ON L6Z 4R3	75.8	54
Heart Lake Veterinary Hospital Professional Corp	23 Conservation Drive # 6 Brampton ON L6Z 4R3	75.8	54
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON	75.8	54

Site	Address	Distance (m)	Map Key
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON	75.8	54
Michelle Omura Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	75.8	54
Michelle Omura Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	75.8	54
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	75.8	54
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	75.8	54
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	75.8	54
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	75.8	54
Michelle Omura Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	75.8	54
Michelle Omura Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	75.8	54
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	75.8	54
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	75.8	54
Wang Dagenais Dentistry Professional Corporation	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	75.8	54

Site	Address	Distance (m)	Map Key
123 Dentist Inc. o/a iSmile Dental Centre (North)	23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	75.8	54
Cat Hospital of Brampton	23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	75.8	54
2049078 ONTARIO INC.	87 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X7	42.2	55
Peel Medical Centre	Unit 1- 230 Wanless Drive Brampton ON L7A 0X1	93.0	58
PEEL BOARD OF EDUCATION	CENTRAL PEEL S.S. 32 KENNEDY ROAD N. BRAMPTON ON L6V 1X4	70.7	60
PEEL BOARD OF EDUCATION 30-189	CENTRAL PEEL SECONDARY SCHOOL 32 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	70.7	60
PEEL DISTRICT SCHOOL BOARD	CENTRAL PEEL SECONDARY SCHOOL 32 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	70.7	60
Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
Peel District School Board	32 Kennedy Road North Brampton ON	70.7	60
Peel District School Board	32 Kennedy Road North Brampton ON	70.7	60
Peel District School Board	32 Kennedy Road North Brampton ON	70.7	60

Site	Address	Distance (m)	Map Key
Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
Peel District School Board	32 Kennedy Road North Brampton ON	70.7	60
Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
Peel District School Board	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
Peel District School Board Human Resources Support Services	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
Peel District School Board Human Resources Support Services	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
Peel District School Board Human Resources Support Services	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
Peel District School Board Human Resources Support Services	32 Kennedy Road North Brampton ON L6V 1X4	70.7	60
PEEL BOARD OF EDUCATION	INDEC NORTH 30 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	84.5	61
PEEL DISTRICT SCHOOL BOARD	INDEC NORTH 30 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	84.5	61
PEEL DISTRICT SCHOOL BOARD	INDEC NORTH 30 Kennedy Road BRAMPTON ON L6V 1X4	84.5	61

Site	Address	Distance (m)	Map Key
Rosedale Dental Care	55 Kennedy Road North Brampton ON L6V 1X6	80.0	62
IRVING GARTEN	16-26 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	97.4	66
Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON	49.4	67
Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontaio St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	49.4	67

Site	Address	Distance (m)	Map Key
Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	49.4	67
Snelgrove Verterinary Services	11526 Hurontario St. Brampton ON L7A1E6	49.4	67
PARKINSON COACH LINES LTD.	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	41.4	68
PARKINSON COACH LINES LTD.	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	41.4	68
PARKINSON COACH LINES LTD. 30-262	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	41.4	68
PARKINSON COACH LINES LTD.	10 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	41.4	68
PARKINSON COACH LINES 2000 INC.	10 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	41.4	68
PARKINSON COACH LINES 2000 INC.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH LINES 2000 INC.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68

Site	Address	Distance (m)	Map Key
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
Parkinson Coach	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	41.4	68
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	50.6	73
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	50.6	73

Site	Address	Distance (m)	Map Key
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	50.6	73
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON	50.6	73
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	50.6	73
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	50.6	73
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	50.6	73
i6 Building Corp	2 Kennedy Road South Brampton ON L6W 3E1	50.6	73
i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	50.6	73
i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	50.6	73
i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	50.6	73
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	88.8	74
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	88.8	74
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	88.8	74

Site	Address	Distance (m)	Map Key
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	88.8	74
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	88.8	74
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	88.8	74
Dr Essam Michael Medicine Professional Corporation	1 Kennedy Road Brampton ON L6W 3C9	88.8	74
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	88.8	74
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	88.8	74
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	88.8	74
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	88.8	74
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	88.8	74
Dr Essam Michael Medicine Professional Corporation	1 Kennedy Road Brampton ON L6W 3C9	88.8	74
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	88.8	74

Site	Address	Distance (m)	Map Key
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	88.8	74
Loblaw Companies Limited - Shoppers Drug Mart	1 Kennedy Rd S Brampton ON L6W 3C9	88.8	74
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	88.8	74
Athletes Care Brampton	1 Kennedy Rd S Unit 12 Brampton ON L6W 3C9	88.8	74
Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	61.0	75
Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	61.0	75
Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	61.0	75
2244603 Ont inc	1-11670 Hurontario Street Brampton ON L7A1R2	61.0	75
BRINKLEY PHARMACY	11670 HURONTARIO Street Brampton ON L7A 1R2	61.0	75
Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	61.0	75
CBI Health	1-11670 Hurontario Street Brampton ON L7A1R2	61.0	75
CBI Health	1-11670 Hurontario Street Brampton ON L7A1R2	61.0	75

Site	Address	Distance (m)	Map Key
Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	61.0	75
Dr. L. Corazza dentistry Proffessonal Corporation	11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	61.0	75
U.A.P. INC.	144-5 KENNEDY RD. BRAMPTON ON L6W 3G4	28.0	76
U.A.P. INC.	BRAMPTON #170 144-5 KENNEDY RD. S. BRAMPTON ON L6W 3G4	28.0	76
U.A.P. INC. 39-227	BRAMPTON #170 144-5 KENNEDY RD. S. BRAMPTON ON L6W 3G4	28.0	76
UAP INC.	144-5 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	28.0	76
Queen Square Family Health Team Queen Square Family Health Team	11692 Hurontario Street Main Street North Brampton ON L7A 1K5	91.7	78
Queen Square Family Health Team Queen Square Family Health Team	11692 Hurontario Street Main Street North Brampton ON L7A 1K5	91.7	78
Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	47.3	79
Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	47.3	79
Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	47.3	79

Site	Address	Distance (m)	Map Key
Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	47.3	79
Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	47.3	79
Swift Clinics	Swift Clinics 49 Hillcrest Avenue Unit 104 Brampton ON L6W 4V4	47.3	79
Kennedy Dental and Orthodontics	49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	47.3	79
Alectra Utilities Corporation	67 Eastern Ave Brampton ON L6W 1X9	97.1	82
Alectra Utilities Corporation	67 Eastern Ave Brampton ON L6W 1X9	97.1	82
Alectra Utilities Corporation	67 Eastern Ave Brampton ON L6W 1X9	97.1	82
Alectra Utilities Corporation	67 Eastern Ave Brampton ON L6W 1X9	97.1	82
STEPHENSON'S RENT-ALL LTD.	26 KENNEDY RD. S. BRAMPTON ON L6W 3E2	21.4	85
STEPHENSON'S RENT-ALL LTD.	26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR. REXDALE ON L6W 3E2	21.4	85
STEPHENSON'S RENT-ALL INC.	26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR. REXDALE ON L6W 3E2	21.4	85
STEPHENSON'S RENT-ALL INC.	26 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2	21.4	85

Site	Address	Distance (m)	Map Key
STEPHENSON'S RENT-ALL INC. 36-583	26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR. REXDALE ON L6W 3E2	21.4	85
STEPHEN(OUT OF BUSINESS)C.	26 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2	21.4	85
Stephenson's Rent-all (1998) Inc.	26 Kennedy Rd. South BRAMPTON ON L6W 3E2	21.4	85
Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	96.4	86
Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	96.4	86
Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	96.4	86
Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	96.4	86
Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	96.4	86
Sandra L. D'Souza Drugs Ltd.	11965 HURONTARIO ST BRAMPTON ON L6Z 4P7	96.4	86
P.O. MONTGOMERY ENT.	30 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2	21.6	87
P.O. MONTGOMERY ENTERPRISES	30 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2	21.6	87

Site	Address	Distance (m)	Map Key
Rochon Building Corporation	30 Kennedy Road South Brampton ON L6W 3E2	21.6	87
Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	21.6	87
Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	21.6	87
Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	21.6	87
Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	21.6	87
Canadian Tire Corporation, Limited	30 Kennedy Road S. Brampton ON L6W 3E2	21.6	87
Austin Rehab Group	30A Kennedy Road South, Ste 1A Bramptom ON	35.8	90
City of Brampton	15 Orenda Road Brampton ON	59.5	95
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96

Site	Address	Distance (m)	Map Key
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
MAPLE LEAF POULTRY	32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	32.6	96
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97

Site	Address	Distance (m)	Map Key
IKO INDUSTRIES LTD. 21-132	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
GH International	71 Orenda Road Brampton ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97

Site	Address	Distance (m)	Map Key
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
IKO INDUSTRIES LIMITED	71 ORENDA ROAD BRAMPTON ON L6W 1V8	92.8	97
SAFE SELF STORAGE	17 ARDGLEN DRIVE BRAMPTON ON L6W 1V1	51.2	98
SAFE SELF STORAGE(OUT OF BUSINESS)	17 ARDGLEN DRIVE BRAMPTON ON L6W 1V1	51.2	98
CANADIAN PLASTICS CONCENTRATED LTD	ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	38.6	99
CANADIAN PLASTICS(OUT OF BUS)	ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	38.6	99
CANADIAN PLASTICS(OUT OF BUS) 08-301	ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	38.6	99
CANADIAN PLASTICS(OUT OF BUSINESS)	ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	38.6	99
BUDGET RENT A CAR	73 KENNEDY ROAD SOUTH BRAMPTON ON L6V 3E4	65.2	100

Site	Address	Distance (m)	Map Key
BUDGET RENT A CAR O/A BRL REALTY 05-696	73 KENNEDY ROAD SOUTH, BRAMPTON C/O 5905 CAMPUS ROAD MISSISSAUGA ON L6W 3E4	65.2	100
Budget Rental Car	73 Kennedy Rd S Brampton ON	65.2	100
BRL REALTY LIMITED	73 KENNEDY ROAD SOUTH BRAMPTON ON L6W3E4	65.2	100
Budget Rental Car	73 Kennedy Rd S Brampton ON L6W 3E4	65.2	100
Budget Rental Car	73 Kennedy Rd S Brampton ON L6W 3E4	65.2	100
NATHAN PHARMACY	147 Clarance Street, Unit 30 Brampton ON L6W 1T2	92.3	101
NATHAN PHARMACY	147 Clarance Street, Unit 30 Brampton ON L6W 1T2	92.3	101
SMARTES CLEANER	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	92.7	104
SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	92.7	104
SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	92.7	104
SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	92.7	104
SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	92.7	104

Site	Address	Distance (m)	Map Key
SMARTEX DRY CLEANERS	50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7	92.7	104
Smartex Cleaners	29- 50 Kennedy Road South Brampton ON	92.7	104
2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	92.7	104
Smartex Cleaners	29- 50 Kennedy Road South Brampton ON L6W 3R7	92.7	104
Smartex Cleaners	29- 50 Kennedy Road South Brampton ON L6W 3R7	92.7	104
2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	92.7	104
2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	92.7	104
Exquizeet Tattoo & Piercing Studio	50 Kennedy Road South, Unit 20C Kennedy Square Mall Brampton ON L6W3R7	92.7	104
2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	92.7	104
Exquizeet Tattoo & Piercing Studio	50 Kennedy Road South, Unit 20C Kennedy Square Mall Brampton ON L6W3R7	92.7	104
2466102 Ontario Inc o/a Smartex Cleaners	50 Kennedy Road South Brampton ON L6W 3R7	92.7	104

Site	Address	Distance (m)	Map Key
Exquizeet Tattoo & Piercing Studio	50 Kennedy Road South, Unit 20C Kennedy Square Mall Brampton ON L6W3R7	92.7	104
2205302 Ontario Limited	12197 Hurontario Street Brampton ON L6Z 4P8	83.5	106
RADMAN THE	90 KENNEDY RD. SOUTH BRAMPTON ON L6W 3E7	19.1	108
RADMAN THE 32-149	90 KENNEDY RD. SOUTH BRAMPTON ON L6W 3E7	19.1	108
RADMAN, THE	90 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E7	19.1	108
Ziebart	96 Kennedy Road South Brampton ON L6W 3E7	18.9	110
MACTAC CANADA LTD/LTEE	100 KENNEDY RD. S. BRAMPTON ON L6W 3E8	89.1	111
MACTAC CANADA LTD/LTEE 25-009	100 KENNEDY RD. S. BRAMPTON ON L6W 3E8	89.1	111
MACTAC CANADA LTD./LTEE.	100 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E8	89.1	111
MACTAC CANADA LTD./LTEE.	100 KENNEDY RD. S. BRAMPTON ON L6W 3E8	89.1	111
MACtac, Bemis	100 Kennedy Road S. Brampton ON L6W 3E8	89.1	111
TRAVELWAYS SCHOOL TRANSIT LTD	12267 HUONTARIO STREET SNELGROVE ON L0P 1M0	86.6	112

Site	Address	Distance (m)	Map Key
LAIDLAW TRANSIT LTD.	12267 HURONTARIO ST. SNELGROVE ON L0P 1M0	86.6	112
LAIDLAW TRANSIT LTD.	12267 HURONTARIO ST., SNELGROVE C/O 30 HERITAGE RD. MARKHAM ON L3P 1M4	86.6	112
LAIDLAW TRANSIT LTD. 38-034	12267 HURONTARIO STREET BRAMPTON ON L6V 1A1	86.6	112
LAIDLAW TRANSIT LTD. 38-034	12267 HURONTARIO ST. C/O R.R. #2 BRAMPTON ON L6V 1A1	86.6	112
LAIDLAW TRANSIT LTD	12267 HURONTARIO STREET BRAMPTON ON L6V 1A1	86.6	112
LAIDLAW TRANSIT LTD.	12267 HURONTARIO STREET BRAMPTON ON L6V 1A1	86.6	112
LAIDLAW TRANSIT LTD.	12267 HURONTARIO STREET R.R.#2 BRAMPTON ON L6V 1A1	86.6	112
Ministry of Transportation	12267 Hurontario Street RR#2 Part Lot 19 1EHS Brampton ON L6V 1A0	86.6	112
KENNEDY GALLERIES	FURNITURE CLINIC, DIVISION OF 109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	89.5	116
KENNEDY GALLERIES, DIV.	109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	89.5	116
KENNEDY GALLERIES 23-268	FURNITURE CLINIC, DIVISION OF 109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	89.5	116

Site	Address	Distance (m)	Map Key
KENNEDY GALLERIES - A DIVISION OF	109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	89.5	116
HERTZ BRAMPTON LEASING & RENTALS LIMITED	117 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	70.3	117
BRAMPTON LEASING & RENTALS LIMITED	117 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	70.3	117
BRAMPTON LEASING & RENTALS LTD.	117 KENNEDY RD. S. BRAMPTON ON L6W 3G3	70.3	117
BRAMPTON LEASING & RENTALS LTD.	117 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	70.3	117
BRAMPTON LEASING & RENTALS LTD. 06-192	117 KENNEDY RD. S. BRAMPTON ON L6W 3G3	70.3	117
AUTOMOTIVE FINISHES & SUPPLY INC.	5 STAFFORD DR. BRAMPTON C/O 726 KIPLING AVE. TORONTO ON L6W 1L3	36.2	120
Leisureworld Caregiving Centre Tullamore	133 Kennedy Rd South Brampton ON	88.9	123
C.I.L. INC	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
C.I.L. INC(SEE&USE ON1133601)	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
C.I.L. INC(SEE&USE ON1133601) 10-046	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
AT PLASTICS INC.	134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	72.3	124

Site	Address	Distance (m)	Map Key
AT PLASTIC 10-046	134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	72.3	124
AT PLASTICS INCORPORATED	134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	72.3	124
SMURFIT-STONE FLEXIBLE PACKAGING GROUP	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
BLUEGRASS CONTAINER CANADA COMPANY	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON	72.3	124
Graphic Packaging Int. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
Graphic Packaging Flexible Can. Inc.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
Infinity Asset Solutions	134 Kennedy Road Brampton ON L6W 3G5	72.3	124

Site	Address	Distance (m)	Map Key
C-I-L INC.	142 KENNEDY RD. S. BRAMPTON ON L6W 3G4	46.9	125
C-I-L INC. (SEE & USE ON1133600)	142 KENNEDY RD. S. BRAMPTON ON L6W 3G4	46.9	125
C-I-L INC. (SEE & USE ON1133600) 10-292	142 KENNEDY RD. S. BRAMPTON ON L6W 3G4	46.9	125
AT PLASTICS INC.	142 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	46.9	125
AT PLASTICS INC. 10-292	142 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	46.9	125
AT PLASTICS INCORPORATED	142 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	46.9	125
WARREN'S AUTO PARTS LTD	144 KENNEDY RD S BRAMPTON ON L6W 3G4	29.9	127
BRAMTECH EXTRUSIONS	144 KENNEDY RD., SOUTH UNIT 11 BRAMPTON ON L6W 3G4	29.9	127
BRAMTECH EXTRUSIONS 04-219	144 KENNEDY RD., SOUTH UNIT 11 BRAMPTON ON L6W 3G4	29.9	127
VERSAKLEEN DRYCLEANERS	144 KENNEDY RD. SOUTH BRAMPTON ON L6W 3G4	29.9	127
VERSAKLEEN DRYCLEANERS	144 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	29.9	127
VERSAKLEEN DRYCLEANERS 40-180	144 KENNEDY RD. SOUTH BRAMPTON ON L6W 3G4	29.9	127

Site	Address	Distance (m)	Map Key
1108456 ONTARIO INC.	144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	29.9	127
PREMIER CLEANERS	144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	29.9	127
1575601 ONTARIO INC	144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	29.9	127
22138689 Ontario Inc.	144 Kennedy Road S. Brampton ON L6W 3G4	29.9	127
2138689 Ontario Inc.	144 Kennedy Road S. Brampton ON L6W 3G4	29.9	127
2138689 Ontario Inc.	144 Kennedy Road S. Brampton ON L6W 3G4	29.9	127
Brampton Christian School	12480 Hutchinson Farm Lane Caledon ON	96.6	129
Brampton Christian School	12480 Hutchinson Farm Lane Caledon ON	96.6	129
Brampton Christian School	12480 Hutchinson Farm Lane Caledon ON L7C 2B6	96.6	129
Brampton Christian School	12480 Hutchinson Farm Lane Caledon ON L7C 2B6	96.6	129
E.J. (OUT OF BUS) 49-119	158 KENNEDY ROAD SOUTH UNIT 11 BRAMPTON ON L6W 3G7	28.9	130

Site	Address	Distance (m)	Map Key
E.J. MACHINE CO. LTD. 49-119	158 KENNEDY ROAD SOUTH UNIT 11 BRAMPTON ON L6W 3G7	28.9	130
Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON	28.9	130
Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	28.9	130
Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	28.9	130
Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	28.9	130
Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	28.9	130
Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	28.9	130
Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	28.9	130
Elizabeth Ostrander Veterinary Professional Corp	158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	28.9	130
Cristall Group Investments Inc	287 Glidden Road Brampton ON L6W 1H9	90.8	131
Cristall Group Investments Inc	287 Glidden Road Brampton ON L6W 1H9	90.8	131
BENSON AND HEDGES (CANADA) INC.	PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133

Site	Address	Distance (m)	Map Key
ROTHMANS BENSON & HEDGES INC.	PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC. 05-086	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC. 05-086	PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON	45.6	133
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133

Site	Address	Distance (m)	Map Key
ROTHMANS BENSON & HEDGES INC.	174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	45.6	133
JMX Contracting Inc	174 Kennedy Rd S Brampton ON L6W 3G6	45.6	133
JMX Contracting Inc	174 Kennedy Rd S Brampton ON L6W 3G6	45.6	133
Urban Clean Ltd	25 Rambler Drive, Unit 701 Brampton ON	98.3	134
Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON	69.4	135
Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON	69.4	135
Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	69.4	135
Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	69.4	135
Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	69.4	135
Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	69.4	135
Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	69.4	135
Husky Oil Operations Ltd.	253 Kennedy Road South Brampton ON L6W 3H1	69.4	135

Site	Address	Distance (m)	Map Key
Parkland Corporation	253 Kennedy Road South Brampton ON L6W 3H1	69.4	135
Maryam Saatian dpc	26 rambler drive brampton ON L6W1E2	81.9	136
Maryam Saatian dpc	26 rambler drive brampton ON L6W1E2	81.9	136
Maryam Saatian dpc	26 rambler drive brampton ON L6W1E2	81.9	136
Maryam Saatian dpc	26 rambler drive brampton ON L6W1E2	81.9	136
DENTISTRY@RAMBLER	26 Rambler Dr Brampton ON L6W 1E2	81.9	136
DENTISTRY@RAMBLER	26 Rambler Dr Brampton ON L6W 1E2	81.9	136
1 HOUR PHOTO PLUS 43-493	24 RAMBLER DRIVE BRAMPTON ON L6W 1E2	77.0	137
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138

Site	Address	Distance (m)	Map Key
Peel Village Medical Centre	28 Rambler Drive Brampton ON	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Peel Village Medical Centre	28 Rambler Drive Brampton ON L6W 1E2	87.3	138
Dr. sarbjeet singh	30 rambler drive brampton ON L6W1E2	93.2	139
OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON	46.7	140
OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	46.7	140
OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	46.7	140

Site	Address	Distance (m)	Map Key
OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	46.7	140
OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	46.7	140
OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	46.7	140
OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	46.7	140
OHL Contract Logistics	300 Kennedy Road S - Unit B Brampton ON L6W 4V2	46.7	140
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W 4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W 4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W 4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON	93.6	142

Site	Address	Distance (m)	Map Key
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Lowe's Companies Canada, ULC	370 Kennedy Road South Brampton ON L6W4V2	93.6	142
Michaels Stores, Inc.	120 Resolution Dr Brampton ON L6W 4P9	13.9	144
Michaels Stores, Inc.	120 Resolution Dr Brampton ON L6W 4P9	13.9	144
Michaels Stores, Inc.	120 Resolution Dr Brampton ON L6W 4P9	13.9	144
Michaels Stores, Inc.	120 Resolution Dr Brampton ON L6W 4P9	13.9	144
CHRYSLER CANADA LTD.	350 KENNEDY ROAD S. BRAMPTON ON L6V 2M3	16.5	146

Site	Address	Distance (m)	Map Key
CHRYSLER CANADA LTD. 10-341	350 KENNEDY ROAD S. BRAMPTON ON L6W 4P1	16.5	146
CHRYSLER CANADA LIMITED	BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON ON L6W 4P1	16.5	146
AMERICAN MOTORS (CANADA) LTD.	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	16.5	146
AMERICAN MOTORS SEE&USE ON0000608	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	16.5	146
AMERICAN (SEE & USE ON0000608)	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	16.5	146
AMERICAN (SEE & USE ON0000608) 03-063	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	16.5	146
Rutherford Properties Ltd.	350 Kennedy Road South Brampton ON L5B 1M3	16.5	146
TONY'S CUSTOM CLEANERS	400 STEELS AVE. E. BRAMPTON ON L6W 3R2	78.2	147
TONY'S CUSTOM CLEANERS	400 STEELS AVE. E. BRAMPTON ON L6W 3R2	78.2	147
TONY'S CUSTOM CLEANERS 38-332	400 STEELS AVE. E. BRAMPTON ON L6W 3R2	78.2	147
TONY'S CUSTOM CLEANERS	400 STEELES AVENUE EAST BRAMPTON ON L6W 3R2	78.2	147

Site	Address	Distance (m)	Map Key
GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	99.4	148
GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	99.4	148
GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	99.4	148
GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	99.4	148
GTA Healthcare Management Inc (II)	90 Resolution Drive Unit 2 Brampton ON L6W 0A7	99.4	148
Rutherford Properties Ltd	410 Steeles Avenue Brampton ON	12.7	149
English Prestige	7980 KENNEDY ROAD SOUTH Brampton ON	62.8	152
Dr. Amanpreet Chopra Dentistry Prof Corp	7-7990 Kennedy Road South Brampton ON L6W 0B3	95.3	153
Dr. Amanpreet Chopra Dentistry Prof Corp	7-7990 Kennedy Road South Brampton ON L6W 0B3	95.3	153
Dr. Amanpreet Chopra Dentistry Prof Corp	7-7990 Kennedy Road South Brampton ON L6W 0B3	95.3	153
Dr. Amanpreet Chopra Dentistry Prof Corp	7-7990 Kennedy Road South Brampton ON L6W 0B3	95.3	153
PEEL BOARD OF EDUCATION	J. A. TURNER S.S. 7935 KENNEDY RD. S. BRAMPTON ON L6V 3N2	81.8	154

Site	Address	Distance (m)	Map Key
PEEL BOARD OF EDUCATION 30-190	TURNER FENTON SECONDARY SCHOOL 7935 KENNEDY ROAD SOUTH BRAMPTON ON L5B 1N7	81.8	154
PEEL DISTRICT SCHOOL BOARD	TURNER FENTON SECONDARY SCHOOL 7935 KENNEDY ROAD SOUTH BRAMPTON ON L5B 1N7	81.8	154
PEEL DISTRICT SCHOOL BOARD	7935 Kennedy Road South BRAMPTON ON L5B 1N7	81.8	154
Peel District School Board	7935 Kennedy Road South Brampton ON	81.8	154
Peel District School Board	7935 Kennedy Road South Brampton ON	81.8	154
Peel District School Board	7935 Kennedy Road South Brampton ON	81.8	154
Peel District School Board	7935 Kennedy Road South Brampton ON	81.8	154
Peel District School Board	7935 Kennedy Road South Brampton ON	81.8	154
Peel District School Board	7935 Kennedy Road South Brampton ON L5B 1N7	81.8	154
Peel District School Board	7935 Kennedy Road South Brampton ON L5B 1N7	81.8	154
Peel District School Board	7935 Kennedy Road South Brampton ON L5B 1N7	81.8	154

Site	Address	Distance (m)	Map Key
Peel District School Board Human Resources Support Services	7935 Kennedy Road South Brampton ON L5B 1N7	81.8	154
Peel District School Board Human Resources Support Services	7935 Kennedy Road South Brampton ON L5B 1N7	81.8	154
Peel District School Board Human Resources Support Services	7935 Kennedy Road South Brampton ON L5B 1N7	81.8	154
Peel District School Board Human Resources Support Services	7935 Kennedy Road South Brampton ON L5B 1N7	81.8	154
PEEL BOARD OF EDUCATION	W.J. FENTON S.S. 7885 KENNEDY ROAD SOUTH, RR# 10 BRAMPTON ON L6V 3N2	94.8	155
PEEL BOARD OF EDUCATION	W.J. FENTON SECONDARY SCHOOL 7885 KENNEDY ROAD SOUTH, RR# 10 BRAMPTON ON L6V 3N2	94.8	155
PEEL (SEE & USE ON0359810) 30-594	W.J. FENTON SECONDARY SCHOOL 7885 KENNEDY ROAD SOUTH, RR# 10 BRAMPTON ON L6V 3N2	94.8	155
PEEL (SEE & USE ON0359810)	W.J. FENTON SECONDARY SCHOOL 7885 KENNEDY ROAD SOUTH, RR# 10 BRAMPTON ON L6V 3N2	94.8	155
Arvin Meritor Canada	350 First Gulf Boulevard Brampton ON L6W 4T5	95.2	158
Meritor Aftermarket Canada, Inc.	350 First Gulf Boulevard Brampton ON	95.2	158
Arvin Meritor Canada Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	95.2	158
Meritor Aftermarket Canada, Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	95.2	158

Site	Address	Distance (m)	Map Key
Meritor Aftermarket Canada, Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	95.2	158
Meritor Aftermarket Canada, Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	95.2	158
Meritor Aftermarket Canada	350 First Gulf Boulevard Brampton ON	95.2	158
Meritor Aftermarket Canada Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	95.2	158
Meritor Aftermarket Canada Inc.	350 First Gulf Boulevard Brampton ON L6W 4T5	95.2	158
Mascot Truck Parts	350 First Gulf Boulevard Brampton ON L6W 4T5	95.2	158

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated 31 Oct, 2023 has found that there are 9 INC site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	Bovaird Drive & Hwy #10, Brampton ON	6.8	20
SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKY W BRAMPTON ON	77.5	36
SUNCOR ENERGY PRODUCTS PARTNERSHIP	5 SANDALWOOD PKWY W,,BRAMPTON, ON,L7A 1J6,CA ON	77.5	36

Site	Address	Distance (m)	Map Key
	227 VODDEN STREET EAST, BRAMPTON ON	89.9	51
CENTRAL PEEL SECONDARY SCHOOL	32 KENNEDY RD N BRAMPTON ON	70.7	60
SUNCOR ENERGY PRODUCTS PARTNERSHIP	11980 HURONTARIO ST BRAMPTON ON	54.5	89
IKO INDUSTRIES LTD	71 ORENDA RD BRAMPTON ON	92.8	97
	100 KENNEDY ROAD SOUTH, BRAMPTON ON	89.1	111
PARKLAND CORPORATION	253 KENNEDY RD S BRAMPTON ON	69.4	135

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 13 NPCB site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CANADA CUP INC	228 QUEEN STREET EAST BRAMPTON ON L7YA9	95.3	69
CANADA CUP INC	228 QUEEN ST E BRAMPTON ON L6V 1B8	95.3	69
C.I.L. INC.	BRAMPTON WORKS; 134 KENNEDY RD. S. BRAMPTON ON L6W 3G5	72.3	124
AT PLACTICS INC.	BRAMPTON WORKS; 134 KENNEDY RD. S. BRAMPTON ON L6W 3G5	72.3	124

Site	Address	Distance (m)	Map Key
CIL INC.	134 KENNEDY ROAD BRAMPTON ON L6W 3G5	72.3	124
AT PLASTICS INC.	134 KENNEDY RD. S. BRAMPTON WORKS Brampton ON L6W 3G5	72.3	124
A.T.PLASTICS INC.	134 KENNEDY ROAD S BRAMPTON ON L6W 3G5	72.3	124
AT PLASTICS INC.	134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	72.3	124
AT PLASTICS INC.	BRAMPTON WORKS 134 KENNEDY RD. S BRAMPTON ON L6W 3G5	72.3	124
BENSON & HEDGES LTD.	174 KENNEDY ROAD BRAMPTON ON L6W 3G6	45.6	133
ROTHMANS, BENSON & HEDGES INC.	174 KEN NEDY RD. SOUTH BRAMPTON ON L6W 3G6	45.6	133
CHRYSLER (CANADA) INC.	350 KENNEDY RD S BRAMPTON ON L6V 2M3	16.5	146
CHRYSLER (CANADA) INC.	350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3	16.5	146

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Apr 30, 2024 has found that there are 32 RST site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SHELL CANADA PRODUCTS LIMITED	10178 HURONTARIO ST BRAMPTON ON L6V1A1	67.1	15
PENNZOIL 10 MINUTE OIL CHANGE	10178 HURONTARIO ST BRAMPTON ON L7A 0E4	67.1	15
PENNZOIL 10 MINUTE OIL CHANGE	10178 HURONTARIO ST BRAMPTON ON L7A0E4	67.1	15
PEEL CO-OP TRUE VALUE	10064 HURONTARIO BRAMPTON ON L6V 1A1	59.4	18
PEEL CO-OP TRUE VALUE	10064 HURONTARIO ST BRAMPTON ON L6V 1A1	59.4	18
PEEL SEED CO-OP	10064 HURONTARIO ST BRAMPTON ON L7A 0E4	59.4	18
PEEL SEED CO-OP	10064 HURONTARIO ST BRAMPTON ON	59.4	18
DAVE'S GAS DEPOT	30 HWY 7 W BRAMPTON ON	81.7	23
DAVE'S GAS DEPOT	30 BOVAIRD DR W BRAMPTON ON L6V 1A1	81.7	23
PIONEER PETROLEUM	675 MAIN ST N BRAMPTON ON L6V1A1	54.6	24
PIONEER PETROLEUM	675 MAIN N BRAMPTON ON	54.6	24
PIONEER PETROLEUMS	675 MAIN ST N BRAMPTON ON L6X 0G6	54.6	24

Site	Address	Distance (m)	Map Key
PIONEER PETROLEUMS	675 MAIN ST N BRAMPTON ON L6X0G6	54.6	24
PENNZOIL 10 MINUTE OIL CHANGE CENTRE	2 FISHERMAN DR BRAMPTON ON L7A 1B5	57.0	33
PENNZOIL 10 MINUTE OIL CHANGE CENTRE	2 FISHERMAN DR BRAMPTON ON L7A1B5	57.0	33
PETRO CANADA	5 SANDALWOOD PKY W BRAMPTON ON L7A 1J6	77.5	36
PETRO CANADA	5 SANDALWOOD PKY W BRAMPTON ON L7A1J6	77.5	36
BASHAR ENTERPRISES INC	140 KENNEDY RD N BRAMPTON ON L6V2N4	42.3	47
ESSO MAXIMUM	140 KENNEDY RD N BRAMPTON ON L6V 2N4	42.3	47
MANN MANJIT	140 KENNEDY RD N BRAMPTON ON L6V 2N4	42.3	47
MANN MANJIT	140 KENNEDY RD N BRAMPTON ON L6V2N4	42.3	47
PETRO-CANADA	KENNEDY N & VODDEN BRAMPTON ON L6V 1X7	19.3	48
KENNEDY & VODDEN PETRO CANADA	121 KENNEDY RD N BRAMPTON ON L6V1X7	69.3	49

Site	Address	Distance (m)	Map Key
KENNEDY & VODDEN PETRO CANADA	121 KENNEDY RD N BRAMPTON ON L6V 1X7	69.3	49
PERFECT LUBE	121 KENNEDY RD N BRAMPTON ON L6V 1X7	69.3	49
ALAGA ESSO	18 KENNEDY RD S BRAMPTON ON L6W 3E1	13.4	77
PETRO CANADA	12011 HURONTARIO ST BRAMPTON ON L6Z 4P8	48.7	93
PETRO CANADA	12011 HURONTARIO ST BRAMPTON ON L6Z4P8	48.7	93
HUSKY GAS STATION	253 KENNEDY RD S BRAMPTON ON L6W3H1	69.4	135
SOLOMON ESSO	7995 KENNEDY RD BRAMPTON ON L6V3N2	27.6	151
KENNEDY ESSO	7995 KENNEDYS BRAMPTON ON	27.6	151
KENNEDY ESSO	7995 KENNEDY RD BRAMPTON ON L6W0A2	27.6	151

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 40 SCT site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Cribben Inc.	10025 Hurontario St Unit 11 Brampton ON L6Z 0E8	67.9	9

Site	Address	Distance (m)	Map Key
LAGRAN CANADA INC.	2 FISHERMAN DR SUITE 1102 BRAMPTON ON L7A 1B5	57.0	33
San/Luca Bakery & Restaurant Inc.	23 Conservation Dr Brampton ON L6Z 4R3	75.8	54
Cribben Inc.	11965 Hurontario St Brampton ON L6Z 4P7	96.4	86
GRUMMAN OLSON INDUSTRIES INC.	30A Kennedy Rd S Suite 201 Brampton ON L6W 3E2	35.8	90
Maple Leaf Poultry	32 Kennedy Rd S Brampton ON L6W 3E3	32.6	96
IKO Industries Ltd.	71 Orenda Rd Brampton ON L6W 1V8	92.8	97
IKO Industries Ltd.	71 Orenda Rd Brampton ON L6W 1V8	92.8	97
Sako Materials Limited	71 Orenda Rd Brampton ON L6W 1V8	92.8	97
Sure Print & Copy Centre	83 Kennedy Rd S Unit 12 Brampton ON L6W 3P3	60.8	105
GPrint	96 Kennedy Rd S Brampton ON L6W 3E7	18.9	110
MACTAC CANADA LTD.	100 KENNEDY RD S BRAMPTON ON L6W 3E8	89.1	111

Site	Address	Distance (m)	Map Key
PEEL FENCE SYSTEMS INC.	110 KENNEDY RD S UNIT A BRAMPTON ON L6W 3E7	14.8	113
P.F.S. FENCE INC.	110 Kennedy Rd S Unit A Brampton ON L6W 3E7	14.8	113
THE DOOR FACTORY II	114 KENNEDY RD S BRAMPTON ON L6W 3E7	59.7	114
Baba Gifts and Distributors	114 Kennedy Rd S Brampton ON L6W 3E7	59.7	114
BUNS MASTER BAKERY	1 STAFFORD DR BRAMPTON ON L6W 1L3	21.0	121
Grainery Bakery and Deli	1 Stafford Dr Brampton ON L6W 1L3	21.0	121
AT PLASTICS INC.	134 KENNEDY RD S BRAMPTON ON L6W 3G5	72.3	124
Graphic Packaging Intl Canada	134 Kennedy Rd S Brampton ON L6W 3G5	72.3	124
AT Plastics Inc.	142 Kennedy Rd S Brampton ON L6W 3G4	46.9	125
PAPA'S CERAMICS LTD.	144 KENNEDY RD S UNIT 13 BRAMPTON ON L6W 3G4	29.9	127
Customwear Screenprinting Inc.	144 Kennedy Rd S Unit 15 Brampton ON L6W 3G4	29.9	127
COMFORT MATTRESS MFG. LTD.	158 KENNEDY RD S UNITS 12-13 BRAMPTON ON L6W 3G7	28.9	130

Site	Address	Distance (m)	Map Key
P-O-C PRINTING LTD.	158 KENNEDY RD S UNIT 11 BRAMPTON ON L6W 3G7	28.9	130
E J MACHINE CO LTD	158 KENNEDY RD S BRAMPTON ON L6W 3G7	28.9	130
Comfort Mattress Manufacturing Limited	158 Kennedy Rd S Unit 12-13 Brampton ON L6W 3G7	28.9	130
POC Printing Services Inc.	158 Kennedy Rd S Unit 11 Brampton ON L6W 3G7	28.9	130
POC Gem Printing Services	158 Kennedy Rd S Unit 11 Brampton ON L6W 3G7	28.9	130
Stitchsations Inc	287 Glidden Rd Unit 6 Brampton ON L6W 1H9	90.8	131
Stitchsations Inc.	287 Glidden Rd Unit 6 Brampton ON L6W 1H9	90.8	131
Amara Furniture Manufacturing Inc.	287 Glidden Rd Unit 12 Brampton ON L6W 1H9	90.8	131
POC-Gem Printing Services Inc.	287 Glidden Rd Unit 3 Brampton ON L6W 1H9	90.8	131
Torbram Electric Supply Ltd.	287 Glidden Rd Unit 1 Brampton ON L6W 1H9	90.8	131
Rothmans, Benson & Hedges Inc.	174 Kennedy Rd S Brampton ON L6W 3G6	45.6	133

Site	Address	Distance (m)	Map Key
National Cable Specialists	300D Kennedy Rd S Brampton ON L6W 4V2	46.7	140
Noramco Wire & Cable	300D Kennedy Rd S Brampton ON L6W 4V2	46.7	140
T.S.T. Enterprises	365 Kennedy Rd S Suite 116 Brampton ON L6W 3H3	81.6	141
TST	365 Kennedy Rd S Unit 116 Brampton ON L6W 3H3	81.6	141
Distributors Choice Chemical	400 Steeles Ave E Unit 231 Brampton ON L6W 3R2	78.2	147

SPL - Ontario Spills

A search of the SPL database, dated 1988-Jan 2023; see description has found that there are 146 SPL site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PRIVATE OWNER	CONNESTOGA DRIVE/BOVAIRD DRIVE MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	30.7	1
OSHAWA FOODS	380 BOVAIRD DRIVE TRANSPORT TRUCK (CARGO) BRAMPTON CITY ON	86.8	3
OSHAWA FOODS	380 BOVAIRD DRIVE - CONNESTOGA FOOD CITY TRANSPORT TRUCK (CARGO) BRAMPTON CITY ON	86.8	3
OSHAWA FOODS	380 BOVAIRD DRIVE RETAIL STORE BRAMPTON CITY ON	86.8	3
TRANSPORT TRUCK	AT CORNER OF SUN FOREST & BOVAIROL DR. MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	0.4	4

Site	Address	Distance (m)	Map Key
The Corporation of the City of Brampton	Sun Forest Drive and Bovaird Drive Brampton ON	0.4	4
	1 Wexford Rd Brampton ON	98.4	5
Fortino's Supermarket<UNOFFICIAL>	60 Quarry Edge Drive Brampton ON	92.3	6
Neelands Refrigeration Limited	60 Quarry Edge Dr. Brampton ON	92.3	6
Fortinos Supermarket Ltd<UNOFFICIAL>	60 Quarry Edge Dr Brampton ON	92.3	6
Fortinos (Highway 10 & Bovaird 2006) Ltd.	60 Quarry Edge Dr Brampton ON L6V 4K2	92.3	6
Neelands Refrigeration Limited	60 Quarry Edge Dr Brampton ON	92.3	6
Fortino's Supermarket<UNOFFICIAL>	#60 Quarry Edge Drive Brampton ON L6V 4K2	92.3	6
Loblaw Properties Limited	60 Quarry Edge Dr Brampton ON L6V 4K2	92.3	6
Loblaw Properties Limited	60 Quarry Edge Dr Brampton ON L6V 4K2	92.3	6
Neelands Refrigeration Limited	60 Quarry Edge Brampton ON L6V 4K2	92.3	6

Site	Address	Distance (m)	Map Key
Neelands Refrigeration Limited	60 Quarry Edge Dr Brampton ON L6V 4K2	92.3	6
Fortinos (Highway 10 & Bovaird 2006) Ltd.	60 Quarry Edge Dr Brampton ON L6V 4K2	92.3	6
	60 Quarry Edge Brampton ON	92.3	6
	29 Parkholme Place Brampton ON L6V 4G3	41.6	7
	67 Wildercroft Ave Brampton ON	98.4	8
	BRAMPTON ON	0.2	12
Emterra Environmental	136 Sandmere Avenue, Brampton Brampton ON	68.0	13
CANADIAN WASTE SERVICES	KENNEDY AND BOVAIRD MOTOR VEHICLE (CARGO) BRAMPTON CITY ON	9.3	14
Chester Cartage	10086 Hurontario Street Brampton ON	80.5	17
TRANSPORT TRUCK	10064 HURONTARIO STREET MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L6V 1A1	59.4	18
WIMPEY	CONSTRUCTION SITE AT HWY #7 & HWY #10. PORTABLE FUEL STORAGE TANK BRAMPTON CITY ON	6.8	20
TRIMAC	10 SIDE RD. HWY 10 AND 7 TANK TRUCK (CARGO) BRAMPTON CITY ON	6.8	20

Site	Address	Distance (m)	Map Key
	Hwy. 10 & Bovaird St. Brampton ON	6.8	20
	SE corner of Highway 10 (Hurontario St.) and Highway 7 (Bovaird Dr.) Brampton ON	6.8	20
Stewart Foodservice Inc.	NW corner of Bovaird Dr W & Hurontario St Brampton ON	6.8	20
Enbridge Gas Distribution Inc.	16 Tremblay Street Brampton ON	86.0	21
PRIVATE RESIDENCE	142 SIMMONS BLVD SEWAGE/SEPTIC SYSTEM BRAMPTON CITY ON L6V 3W4	88.3	22
	30 Hwy 7 W now 30 Bovaird Drive Brampton ON	81.7	23
Enbridge Gas Distribution Inc.	10370 Hurontario Street Brampton ON	63.5	25
	13 Crosswood Lane BRAMPTON ON	65.0	27
Enbridge Gas Distribution Inc.	23 Histon Cres. Brampton ON	80.8	28
TRANSPORT TRUCK	FISCHERMAN DRIVE & HWY 10 MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	7.2	31
	60 Buckland Way, Brampton, ON BRAMPTON ON	77.8	32

Site	Address	Distance (m)	Map Key
Enbridge Gas Inc.	76 Blackthorn Lane Brampton ON	63.0	34
Petro Canada Retail Fuel Facility<UNOFFICIAL>	5 Sandalwood Parkway Brampton ON	77.5	36
	5 Sandlewood Pkwy W, Brampton BRAMPTON ON	77.5	36
DOUG CHALMERS INC.	ETOBICOKE CREEK HURONTARIO/SANDALWOOD PARKWAY BRAMPTON STORAGE DEPOT HIGHWAY 10 BRAMPTON CITY ON	9.8	37
Canada Drayage<UNOFFICIAL>	HWY 10 & SANDALWOOD PKWY<UNOFFICIAL> Brampton ON	9.8	37
	Sandalwood and Hurontario Brampton ON	9.8	37
The Regional Municipality of Peel	78 Skegby Rd Brampton ON L6V 2T9	63.6	38
	338 Hansen Road North, Brampton BRAMPTON ON	78.5	39
	100 Sandalwood Pkwy W, Brampton BRAMPTON ON	89.2	40
Enbridge Energy Distribution Inc.	36 Skegsby Rd Brampton ON	76.5	41
Alectra Utilities Corporation	17 Trewartha Cres Brampton ON	97.3	42

Site	Address	Distance (m)	Map Key
	111 Greene Dr. Brampton, ON. BRAMPTON ON	24.6	43
Enbridge Gas Distribution Inc.	40 Greene Drive Brampton ON L6V 2R7	78.7	44
Terra HX Inc.	39 Greene Drive, Brampton BRAMPTON ON	62.4	46
PROVMAR FUELS INC.	140 KENNEDY ROAD TANK TRUCK (CARGO) BRAMPTON CITY ON	42.3	47
The Corporation of the City of Brampton	225 Vodden St E Brampton ON L6V 4M1	69.4	50
	50 Settler Crescent, Brampton BRAMPTON ON	94.5	53
Hydro One Brampton Networks Inc.	8 Hambley Court Brampton ON	94.7	57
CONTRACTOR	HWY 10 && PERTH ST (N.O.S.) BRAMPTON ON	2.5	59
Peel District School Board	32 Kennedy Road N Brampton ON	70.7	60
2041409 Ontario Ltd.	11482 Hurontario St Brampton ON L7A 1E6	61.9	64
	7 Charles Street Brampton ON	86.0	65
Elias Gessen Eastown<UNOFFICIAL>	26 Kennedy Rd North Brampton ON L6V 1X4	97.4	66

Site	Address	Distance (m)	Map Key
SHELL CANADA PRODUCTS LTD.	230 QUEEN STREET EAST AT KENNEDY RD. SERVICE STATION BRAMPTON CITY ON L6V 1B8	77.0	70
	238 Queen St East Brampton ON	9.5	71
Brampton Transit<UNOFFICIAL>	Queen and Kennedy, Brampton Brampton ON	25.0	72
LECLAIR FUELS LTD.	1 KENNEDY ROAD SOUTH CANADIAN TIRE TANK TRUCK (CARGO) BRAMPTON CITY ON	88.8	74
TRANSPORT TRUCK	INTERSECTION AND CATCH BASIN AT KENNEDY RD AND EASTERN AVE TRANSPORT TRUCK (CARGO) BRAMPTON CITY ON	27.9	80
Maple Leaf Foods Inc.	33 Kennedy Road S Brampton ON	60.8	81
Alectra Utilities Corporation	11965 Hurontario St Brampton ON L6Z 4P7	96.4	86
CANADIAN TIRE CORPORATION LTD.	30 KENNEDY ROAD RETAIL STORE BRAMPTON CITY ON	21.6	87
The Corporation of Brampton (Transit)	Brampton ON	9.3	88
Petro-Canada Fuels Inc.	11980 Hurontario St Brampton ON	54.5	89
PEEL, REGIONAL MUNICIPALITY OF	INTERSECTION OF ORENDA DR & KENNEDY DR FORCEMAIN BRAMPTON CITY ON	22.6	91

Site	Address	Distance (m)	Map Key
TRANSPORT TRUCK	HIGHWAY 10 - WEST SIDE - SOUTH OF MAYFIELD ROAD MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	2.1	92
ONTARIO HYDRO	CORNER OF HWY 10 & MAYFIELD RD. TRANSFORMER PEEL R.M. ON	2.1	92
Construction Site<UNOFFICIAL>	On Mayfield Rd. just east of Hurontario St. Brampton ON	2.1	92
SD Towing	Hurontario St and Mayfield Rd Brampton ON	2.1	92
PETRO-CANADA	12011 HWY 10 IN VILLAGE OF SNELGROVE. TANK TRUCK (CARGO) CALEDON TOWN ON	48.7	93
MAPLE LEAF FOODS INC.	BRAMPTON PLANT 32 KENNEDY ROAD SOUTH BRAMPTON CITY ON	32.6	96
MAPLE LEAF FOODS INC.	32 KENNEDY ROAD SOUTH BRAMPTON PLANT 32 KENNEDY ROAD SOUTH BRAMPTON CITY ON L6W 3E3	32.6	96
Maple Leaf Foods Inc.	32 Kennedy Rd S Brampton ON L6W 3E3	32.6	96
	32 Kennedy Rd S Brampton ON L6W 3E3	32.6	96
	32 Kennedy Road South BRAMPTON ON	32.6	96
	32 Kennedy Rd S., Brampton BRAMPTON ON	32.6	96
IKO INDUSTRIES LTD.	71 ORENDA RD. BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97

Site	Address	Distance (m)	Map Key
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	IN DITCH AT 71 ORENDA ROAD ON IKO INDUSTRIES' PROPERTY BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	IKO INDUSTRIES, 71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA RD. BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO Industries Ltd.	71 Orenda Road Brampton ON L6W 1V8	92.8	97


Site	Address	Distance (m)	Map Key
IKO Industries Ltd.	71 Orenda Road Brampton ON L6W 1V8	92.8	97
IKO Industries Ltd.	71 Orenda Road Brampton ON L6W 1V8	92.8	97
IKO Industries	71 Orenda Road Brampton ON	92.8	97
IKO Industries	71 Orenda Rd Brampton ON	92.8	97
IKO Industries Ltd.	71 Orenda Rd (IKO B2) Brampton ON L6W 1V8	92.8	97
Flynn Canada Ltd.	71 Orenda Road Brampton ON	92.8	97
IKO Industries Ltd.	71 Orenda Rd Brampton ON L6W 1V8	92.8	97
IKO Industries Ltd.	71 Orenda Rd Brampton ON L6W 1V8	92.8	97
	71 Orenda Rd. Brampton, ON. BRAMPTON ON	92.8	97
	71 Orenda Rd, Brampton, ON L6W 1V8 BRAMPTON ON	92.8	97
	71 Orenda Rd, Brampton ON	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97

Site	Address	Distance (m)	Map Key
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	71 ORENDA ROAD BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
IKO INDUSTRIES LTD.	CVM FILTER BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON	92.8	97
IKO INDUSTRIES LTD.	BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8	92.8	97
	Hurontario Street and Inglewood Drive, Mississauga CALEDON;BRAMPTON ON	10.3	103
	Hurontario St & Steeles Ave, Brampton CALEDON;BRAMPTON ON	10.3	103
	84 Kennedy Road South Brampton ON L6W 3E7	31.4	107
Rice Development	95 Kennedy Rd Brampton ON L6W 3G2	53.6	109

Site	Address	Distance (m)	Map Key
MACTAC CANADA LTD.	100 KENNEDY ROAD SOUTH BRAMPTON PLANT 100 KENNEDY ROAD SOUTH BRAMPTON CITY ON L6W 3E8	89.1	111
MACTAC CANADA LTD.	100 KENNEDY RD SOUTH. BRAMPTON PLANT 100 KENNEDY ROAD SOUTH BRAMPTON CITY ON L6W 3E8	89.1	111
The Regional Municipality of Peel	107 Kennedy Rd. South Brampton ON	78.0	115
	107 Kennedy Road South Brampton, ON BRAMPTON ON	78.0	115
The Regional Municipality of Peel	Hutchinson Farm Lane Caledon ON	0.5	118
The Regional Municipality of Peel	119 Kennedy Road South Brampton ON	76.1	119
A.T PLASTICS INC.	134 KENNEDY ROAD SOUTH 134 KENNEDY ROAD SOUTH, PLASTIC FILMS BRAMPTON CITY ON L6W 3G5	72.3	124
A.T. PLASTICS	142 KENNEDY ROAD 142 KENNEDY ROAD SOUTH BURLINGTON BRAMPTON CITY ON	46.9	125
The Regional Municipality of Peel	165 Kennedy Road S Brampton ON	95.0	126
UNI-CARE MCLAVERTY	144 KENNEDY RD, UNIT #2 MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	29.9	127
Commercial Complex<UNOFFICIAL>	144 Kennedy Road South, Brampton Brampton ON	29.9	127
	22 Hesketh Crt Caledon ON NA	52.1	128

Site	Address	Distance (m)	Map Key
Hydro One Networks Inc.	12581 Hurontario ST Caledon ON	40.5	132
Transport International Pool<UNOFFICIAL>	174 KENNEDY RD<UNOFFICIAL> Brampton ON	45.6	133
McQuary Service<UNOFFICIAL>	174 Kennedy Rd S Brampton ON L6W 3G6	45.6	133
	253 Kennedy Rd S and Rambler Brampton ON L6W 3H1	69.4	135
	3 Scotsdale Court Brampton ON	65.8	143
CHRYSLER CANADA LTD.	BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON CITY ON	16.5	146
CHRYSLER CANADA LTD.	BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON CITY ON	16.5	146
Canadian Waste Services Inc.	Kennedy Road at Steeles Ave<UNOFFICIAL> Brampton ON	27.8	150
Canada Cartage Diversified Gp. Inc.	Kennedy Road (50 feet north of Steeles Ave) <UNOFFICIAL> Brampton ON	27.8	150
Makkar Transport<UNOFFICIAL>	Hwy 10 @ Old School Road Caledon ON	17.6	156
	hwy 10 southbound and Old School Road intersection in Brampton CALEDON ON	17.6	156

Site	Address	Distance (m)	Map Key
Super Sucker Hydro-Vac Service	BRAMPTON ON	66.4	157
	350 First Gulf Blvd, Brampton ON	95.2	158
	8 Sifford Ct. BRAMPTON ON	34.2	159
Absolute Environmental (King Towing)	Hwy 10 200m N of Old School Rd., Caledon CALEDON ON	92.7	161



Map: 0.1 Kilometer Radius

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 1

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 2

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 3

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 4

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 5

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 6

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 7

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 8

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 9

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 10

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 11

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 12

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 13

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 14

Order Number: 24060400429


Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Grid: 15

Order Number: 24060400429

Address: Kennedy Rd HEIP, Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Aerial


Year: 2022

Order Number: 24060400429

Address: Kennedy Rd HEIP, Brampton, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Order Number: 24060400429

Address: Kennedy Rd HEIP, ON

Source: ESRI World Topographic Map

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	1 of 2	SSE/0.4	231.9 / -0.62	TRANSPORT TRUCK AT CORNER OF SUN FOREST & BOVAIROL DR. MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON	SPL

Ref No:	151168	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	1/7/1998	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	1/7/1998	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	FD, PEEL R.M.

Site No:	
MOE Response:	
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	BRAMPTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	OTHER CONTAINER LEAK
Incident Preceding Spill:	
Environment Impact:	POSSIBLE
Health Env Consequence:	
Nature of Impact:	Water course or lake
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND / WATER
Incident Reason:	INTENTIONAL/PLANNED
Incident Summary:	ROCKWELL TRANSPORTATION - DIESEL FUEL DUMPED ON ROAD AT INTERSECTION.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	2 of 2	SSE/0.4	231.9 / -0.62	The Corporation of the City of Brampton Sun Forest Drive and Bovaird Drive	SPL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Brampton ON

Ref No:	2028-98KKFL	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11-JUN-13	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11-JUN-13	**Impact to Health:**	
Dt Document Closed:	03-JUL-13	**Agency Involved:**	

Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Brampton Transit Bus<UNOFFICIAL>
Site Address: Sun Forest Drive and Bovaird Drive
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Leak/Break
Incident Preceding Spill:
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 60 L
System Facility Address:
Client Name: The Corporation of the City of Brampton
Client Type:
Source Type:
Contaminant Code: 27
Contaminant Name: COOLANT N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Equipment Failure
Incident Summary: Brampton Transit 60L coolant to road and catchbasin cleaned
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Motor Vehicle
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	1 of 1	WSW/0.2	240.0 / 7.54		SPL

BRAMPTON ON

Ref No:	1-23EU5A	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	8/16/2022 9:00:53 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/16/2022 9:33:26 AM	**Impact to Health:**	0 No Impact
Dt Document Closed:		**Agency Involved:**	

Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office

Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	Container/Drum/Tote
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Unknown
Incident Summary:	Canadian Tire: hydraulic oil spill on pavement, contained
Activity Preceding Spill:	Normal operations
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HC-Humber - Don;02HB-Credit - 16 Mile
Sector Type:	DEPARTMENT STORES
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00002453800"],"wkts":["POINT (-79.7931474000 43.7103549000)"],"creation_date":"2022-08-16"}

118 | **1 of 1** | **WNW/0.5** | **259.9 / 27.37** | **The Regional Municipality of Peel**
Hutchinson Farm Lane
Caledon ON | **SPL**

Ref No:	2418-AYEL9P	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2018/05/03	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2018/05/03	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	

Site No:	NA
MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	illegal dumping Region of Peel property<UNOFFICIAL>
Site Address:	Hutchinson Farm Lane
Site Region:	Central
Site Municipality:	Caledon
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4843694
Easting:	593906
Incident Cause:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Preceding Spill:	Dumping
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	The Regional Municipality of Peel
Client Type:	Municipal Government
Source Type:	Unknown / N/A
Contaminant Code:	43
Contaminant Name:	CONTAMINATED SOIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Land
Incident Reason:	Deliberate Act
Incident Summary:	ROP: illegal dumping of soil
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Illegal Dumping Occurrences
Call Report Locatn Geodata:	

1	1 of 1	E/30.7	232.9 / 0.37	**PRIVATE OWNER** **CONNESTOGA DRIVE/BOVAIRD DRIVE MOTOR VEHICLE (OPERATING FLUID)** **BRAMPTON CITY ON**	SPL

Ref No:	111832	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	4/11/1995	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/11/1995	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	WORKS, PEEL REG.
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:	Water course or lake		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: EQUIPMENT FAILURE
Incident Summary: GRAHAM BROS.-5L HYDRAULICOIL ALONG RD FROM GRADER,HOSE RUPTURE, CLEANING UP
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

2	*1 of 3*	*E/10.6*	*232.9 / 0.37*	***PEEL BLOCK CO. LTD*** ***307 BOVAIRD DR, BOX 297*** ***BRAMPTON ON L6V 2L1***	***GEN***

Generator No: ON0627100
SIC Code: 3542
SIC Description: STRUCTURAL CONCRETE
Approval Years: 86,87,88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

2	*2 of 3*	*E/10.6*	*232.9 / 0.37*	***PEEL BLOCK CO. (OUT OF BUSINESS)*** ***307 BOVAIRD DR, BOX 297*** ***BRAMPTON ON L6V 2L1***	***GEN***

Generator No: ON0627100
SIC Code: 3542
SIC Description: STRUCTURAL CONCRETE
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

2	*3 of 3*	*E/10.6*	*232.9 / 0.37*	***PEEL BLOCK CO. (OUT OF BUSINESS) 30-205*** ***307 BOVAIRD DR, BOX 297*** ***BRAMPTON ON L6V 2L1***	***GEN***

Generator No: ON0627100
SIC Code: 3542
SIC Description: STRUCTURAL CONCRETE
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

3 | ***1 of 17*** | ***ENE/86.8*** | ***234.9 / 2.37*** | ***OSHAWA FOODS***
380 BOVAIRD DRIVE TRANSPORT TRUCK (CARGO)
BRAMPTON CITY ON | ***SPL***

Ref No: 127615
Year:
Incident Dt: 6/7/1996
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/10/1996
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Incident Reason: EQUIPMENT FAILURE
Incident Summary: CONESTOGA PRICE CHOPPER- 1 KG FREON R-12 TO ATM, COOLER LEAK,REPAIRED.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

---

3 | ***2 of 17*** | ***ENE/86.8*** | ***234.9 / 2.37*** | ***OSHAWA FOODS***
380 BOVAIRD DRIVE - CONNESTOGA FOOD CITY TRANSPORT TRUCK (CARGO)
BRAMPTON CITY ON | ***SPL***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	129425	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	7/18/1996	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	7/19/1996	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	COOLING SYSTEM LEAK		
Incident Preceding Spill:			
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	AIR		
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	OSHAWA FOODS- 150KG REFRIGERANT HP80 LOST TO ATMOSPHERE.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

3	***3 of 17***	***ENE/86.8***	***234.9 / 2.37***	***OSHAWA FOODS*** ***380 BOVAIRD DRIVE RETAIL STORE*** ***BRAMPTON CITY ON***	***SPL***

Ref No:	134222	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	11/8/1996	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	11/14/1996	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Address:	
Site Region:	
Site Municipality:	BRAMPTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE
Incident Preceding Spill:	
Environment Impact:	POSSIBLE
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	AIR
Incident Reason:	EQUIPMENT FAILURE
Incident Summary:	CONESTOGA IGA: 100KG OF PHP80 TO ATM, LEAK FROM TWO DIFFERENT LOCATIONS
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

3	***4 of 17***	***ENE/86.8***	***234.9 / 2.37***	***PHARMA PLUS DRUGS LTD.*** ***380 BOVAIRD ROAD, UNIT 26*** ***BRAMPTON ON L6Z 2N7***	***GEN***

Generator No:	ON1670622
SIC Code:	6031
SIC Description:	PHARMACIES
Approval Years:	92,93,97,98,99,00,01
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

3	***5 of 17***	***ENE/86.8***	***234.9 / 2.37***	***PHARMA PLUS DRUGS LTD. 31-803*** ***380 BOVAIRD RD. UNIT 26 C/O 5935 AIRPORT ROAD STE. #500***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				MISSISSAUGA ON L4V 1W5	

Generator No: ON1670622
SIC Code: 6031
SIC Description: PHARMACIES
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	6 of 17	ENE/86.8	234.9 / 2.37	***Dr. Allan M Bregman Dentistry PC*** ***380 Bovaird Drive*** ***Brampton ON L6Z2S7***	GEN

Generator No: ON2612566
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Debbie S Bregman
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-840-0000 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	7 of 17	ENE/86.8	234.9 / 2.37	***Dr. Allan M Bregman Dentistry PC*** ***380 Bovaird Drive*** ***Brampton ON L6Z2S7***	GEN

Generator No: ON2612566
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Debbie S Bregman
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-840-0000 Ext.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	8 of 17	ENE/86.8	234.9 / 2.37	conestoga pharmacy inc 26-380 bovaird dr e brampton ON L6Z2S8	GEN

Generator No: ON7405691
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	9 of 17	ENE/86.8	234.9 / 2.37	conestoga pharmacy inc 26-380 bovaird dr e brampton ON L6Z2S8	GEN

Generator No: ON7405691
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	10 of 17	ENE/86.8	234.9 / 2.37	Sehdev Drugs Limited 26-380 Bovaird Drive East Brampton ON L6Z 2S8	GEN

Generator No: ON7504480
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	11 of 17	ENE/86.8	234.9 / 2.37	Dr. Allan M Bregman Dentistry PC 380 Bovaird Drive Brampton ON L6Z2S7	GEN

Generator No: ON2612566
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	12 of 17	ENE/86.8	234.9 / 2.37	Sehdev Drugs Limited 26-380 Bovaird Drive East Brampton ON L6Z 2S8	GEN

Generator No: ON7504480
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

---

3 | ***13 of 17*** | ***ENE/86.8*** | ***234.9 / 2.37*** | ***Dr. Allan M Bregman Dentistry PC*** ***380 Bovaird Drive*** ***Brampton ON L6Z2S7*** | ***GEN***

Generator No: ON2612566
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

---

3 | ***14 of 17*** | ***ENE/86.8*** | ***234.9 / 2.37*** | ***Dr. Allan M Bregman Dentistry PC*** ***380 Bovaird Drive*** ***Brampton ON L6Z2S7*** | ***GEN***

Generator No: ON2612566
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	15 of 17	ENE/86.8	234.9 / 2.37	Sehdev Drugs Limited 26-380 Bovaird Drive East Brampton ON L6Z 2S8	GEN

Generator No: ON7504480
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	16 of 17	ENE/86.8	234.9 / 2.37	Sehdev Drugs Limited 26-380 Bovaird Drive East Brampton ON L6Z 2S8	GEN

Generator No: ON7504480
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	17 of 17	ENE/86.8	234.9 / 2.37	Conestoga Dental Centre 380 bovaird dr east suite 23 brampton ON L6Z 2S7	GEN

Generator No: ON9936073
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 L
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	1 of 56	WSW/98.4	239.9 / 7.37	PLATIS & SONS CLEANERS 1 WEXFORD ROAD, UNIT 1 BRAMPTON ON L6Z 2W1	GEN

Generator No: ON0564110
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS
Approval Years: 95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	2 of 56	WSW/98.4	239.9 / 7.37	PLATIS & SONS CLEANERS 1 WEXFORD ROAD UNIT 1 BRAMPTON ON L6Z 2W1	GEN

Generator No: ON0564110
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	3 of 56	WSW/98.4	239.9 / 7.37	PLATIS & SONS 1 HOUR CLEANERS 1 WEXFORD ROAD BRAMPTON ON L6Z 2W1	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON0564110
SIC Code: 812320
SIC Description: Dry Cleaning & Laundry Serv. (exc. Coin-Op.)
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

5	4 of 56	WSW/98.4	239.9 / 7.37	HASTY MARKET 19-675 1 WEXFORD ROAD, UNIT 9 BRAMPTON ON L6Z 2W1	GEN

Generator No: ON1571400
SIC Code: 6011
SIC Description: GROCERY FOOD STORES
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

5	5 of 56	WSW/98.4	239.9 / 7.37	HASTY MARKET 1 WEXFORD ROAD, UNIT 9 BRAMPTON ON L6Z 2W1	GEN

Generator No: ON1571400
SIC Code: 6011
SIC Description: GROCERY FOOD STORES
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	6 of 56	WSW/98.4	239.9 / 7.37	Emergency Veterinary Clinic - Highway 10 1 Wexford St, Unit 10 Brampton ON L6Z 2W1	GEN

Generator No: ON4024746
SIC Code:
SIC Description:
Approval Years: 02,03
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	7 of 56	WSW/98.4	239.9 / 7.37	Emergency Veterinary Clinic - Highway 10 1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	GEN

Generator No: ON4024746
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	8 of 56	WSW/98.4	239.9 / 7.37	1 Wexford Rd Brampton ON	SPL

Ref No: 3844-7RXHSW
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/11/2009
Dt Document Closed:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Wexford Plaza<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 10 L
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name: GASOLINE
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Other - Reason not otherwise defined
Incident Summary: Wexford Plaza: taxi gas leak 10 L to parking lot, clnd
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Motor Vehicle
SAC Action Class: Land Spills
Call Report Locatn Geodata:

5	9 of 56	WSW/98.4	239.9 / 7.37	MAGIC TOUCH 1HR. CLEANERS 1 WEXFORD ROAD BRAMPTON ON	GEN

Generator No: ON0564110
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	10 of 56	WSW/98.4	239.9 / 7.37	Emergency Veterinary Clinic - Highway 10 1 Wexford Rd. Unit 10 Brampton ON	GEN

Generator No: ON4024746
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	11 of 56	WSW/98.4	239.9 / 7.37	Innomar-Strategies Inc. 1 Wexford Rd. Brampton ON L6Z 2W1	GEN

Generator No: ON8769083
SIC Code: 623110
SIC Description: Nursing Care Facilities
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	12 of 56	WSW/98.4	239.9 / 7.37	Emergency Veterinary Clinic - Highway 10 1 Wexford Rd. Unit 10 Brampton ON	GEN

Generator No: ON4024746
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

5 | ***13 of 56*** | ***WSW/98.4*** | ***239.9 / 7.37*** | ***MAGIC TOUCH 1HR. CLEANERS***
1 WEXFORD ROAD
BRAMPTON ON | ***GEN***

Generator No: ON0564110
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

5 | ***14 of 56*** | ***WSW/98.4*** | ***239.9 / 7.37*** | ***Innomar-Strategies Inc.***
1 Wexford Rd.
Brampton ON L6Z 2W1 | ***GEN***

Generator No: ON8769083
SIC Code: 623110
SIC Description: Nursing Care Facilities
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	15 of 56	WSW/98.4	239.9 / 7.37	MAGIC TOUCH 1HR. CLEANERS 1 WEXFORD ROAD BRAMPTON ON	GEN

Generator No: ON0564110
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	16 of 56	WSW/98.4	239.9 / 7.37	Emergency Veterinary Clinic - Highway 10 1 Wexford Rd. Unit 10 Brampton ON	GEN

Generator No: ON4024746
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	17 of 56	WSW/98.4	239.9 / 7.37	Innomar-Strategies Inc. 1 Wexford Rd. Brampton ON L6Z 2W1	GEN

Generator No: ON8769083
SIC Code: 623110
SIC Description: Nursing Care Facilities
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

5	18 of 56	WSW/98.4	239.9 / 7.37	**Emergency Veterinary Clinic - Highway 10** **1 Wexford Rd. Unit 10** **Brampton ON L6Z 2W1**	GEN

Generator No: ON4024746
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

5	19 of 56	WSW/98.4	239.9 / 7.37	**MAGIC TOUCH 1HR. CLEANERS** **1 WEXFORD ROAD** **BRAMPTON ON L6Z 2W1**	GEN

Generator No: ON0564110
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

5	20 of 56	WSW/98.4	239.9 / 7.37	**Emergency Veterinary Clinic - Highway 10** **1 Wexford Rd. Unit 10**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON	

Generator No: ON4024746
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	21 of 56	WSW/98.4	239.9 / 7.37	**MAGIC TOUCH 1HR. CLEANERS** **1 WEXFORD ROAD** **BRAMPTON ON**	GEN

Generator No: ON0564110
SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	22 of 56	WSW/98.4	239.9 / 7.37	**Innomar-Strategies Inc.** **1 Wexford Rd.** **Brampton ON**	GEN

Generator No: ON8769083
SIC Code: 623110
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	23 of 56	WSW/98.4	239.9 / 7.37	First Choice MedCentre Inc. 1 Wexford Rd. Unit 8 Brampton ON	GEN

Generator No: ON8199308
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	24 of 56	WSW/98.4	239.9 / 7.37	wexford square dental 1 wexford road ,unit #7 brampton ON L6Z2W1	GEN

Generator No: ON6498241
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: ana p rantala
Choice of Contact: CO_OFFICIAL
Phone No Admin: 9058400013 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	25 of 56	WSW/98.4	239.9 / 7.37	MAGIC TOUCH 1HR. CLEANERS 1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	GEN

Generator No: ON0564110
SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years: 2016
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status:
Co Admin: Donghwan Kim
Choice of Contact: CO_ADMIN
Phone No Admin: 6473678271 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	26 of 56	WSW/98.4	239.9 / 7.37	***Innomar-Strategies Inc.*** ***1 Wexford Rd.*** ***Brampton ON L6Z 2W1***	GEN

Generator No: ON8769083
SIC Code: 623110
SIC Description: 623110
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	27 of 56	WSW/98.4	239.9 / 7.37	***Emergency Veterinary Clinic - Highway 10*** ***1 Wexford Rd. Unit 10*** ***Brampton ON L6Z 2W1***	GEN

Generator No: ON4024746
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Catherine Schell
Choice of Contact: CO_ADMIN
Phone No Admin: 905-495-9907 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

5 **28 of 56** **WSW/98.4** **239.9 / 7.37** **wexford square dental**
1 wexford road ,unit #7
brampton ON L6Z2W1
GEN

Generator No: ON6498241
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: ana p rantala
Choice of Contact: CO_OFFICIAL
Phone No Admin: 9058400013 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

5 **29 of 56** **WSW/98.4** **239.9 / 7.37** **Wexford Medical Clinic**
1 Wexford rd
Brampton ON L6Z2W1
GEN

Generator No: ON6424643
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Mariya mt Trusikova
Choice of Contact: CO_OFFICIAL
Phone No Admin: 9059701600 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

5 **30 of 56** **WSW/98.4** **239.9 / 7.37** **Innomar-Strategies Inc.**
1 Wexford Rd.
Brampton ON L6Z 2W1
GEN

Generator No: ON8769083
SIC Code: 623110
SIC Description: 623110
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	31 of 56	WSW/98.4	239.9 / 7.37	Wexford Medical Clinic 1 Wexford rd Brampton ON L6Z2W1	GEN

Generator No: ON6424643
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	32 of 56	WSW/98.4	239.9 / 7.37	Emergency Veterinary Clinic - Highway 10 1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	GEN

Generator No: ON4024746
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Catherine Schell
Choice of Contact: CO_ADMIN
Phone No Admin: 905-495-9907 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	33 of 56	WSW/98.4	239.9 / 7.37	MAGIC TOUCH 1HR. CLEANERS 1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	GEN

Generator No: ON0564110
SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Donghwan Kim
Choice of Contact: CO_OFFICIAL
Phone No Admin: 6473678271 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	34 of 56	WSW/98.4	239.9 / 7.37	Emergency Veterinary Clinic - Highway 10 1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	GEN

Generator No: ON4024746
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Catherine Schell
Choice of Contact: CO_ADMIN
Phone No Admin: 905-495-9907 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	35 of 56	WSW/98.4	239.9 / 7.37	MAGIC TOUCH 1HR. CLEANERS 1 WEXFORD ROAD BRAMPTON ON L6Z 2W1	GEN

Generator No: ON0564110
SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Donghwan Kim
Choice of Contact: CO_OFFICIAL
Phone No Admin: 4164206319 Ext.
Contaminated Facility: No
MHSW Facility: No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

5 | ***36 of 56*** | ***WSW/98.4*** | ***239.9 / 7.37*** | ***Innomar-Strategies Inc.***
1 Wexford Rd.
Brampton ON L6Z 2W1 | ***GEN***

Generator No: ON8769083
SIC Code: 623110
SIC Description: 623110
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

5 | ***37 of 56*** | ***WSW/98.4*** | ***239.9 / 7.37*** | ***Dawson DCC-Wexford Square Dental***
1 Wexford Road Unit 7
Brampton ON L6Z2W1 | ***GEN***

Generator No: ON6498241
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

5 | ***38 of 56*** | ***WSW/98.4*** | ***239.9 / 7.37*** | ***MAGIC TOUCH 1HR. CLEANERS***
1 WEXFORD ROAD, Unit 1
BRAMPTON ON L6Z 2W1 | ***GEN***

Generator No: ON0564110
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 H
Waste Class Name: Halogenated solvents and residues

---

5 | ***39 of 56*** | ***WSW/98.4*** | ***239.9 / 7.37*** | ***Innomar-Strategies Inc.***
1 Wexford Rd.
Brampton ON L6Z 2W1 | ***GEN***

Generator No: ON8769083
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

5 | ***40 of 56*** | ***WSW/98.4*** | ***239.9 / 7.37*** | ***Emergency Veterinary Clinic - Highway 10***
1 Wexford Rd. Unit 10
Brampton ON L6Z 2W1 | ***GEN***

Generator No: ON4024746
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	41 of 56	WSW/98.4	239.9 / 7.37	Wexford Medical Clinic 1 Wexford rd Brampton ON L6Z2W1	GEN

Generator No:	ON6424643
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	42 of 56	WSW/98.4	239.9 / 7.37	Magic Touch Dry Cleaners 1 Wexford Rd Brampton ON L6Z2W1	CDRY

Legal Name of Company:	
Region:	Ontario
Type of Reporter:	Dry Cleaner

Waste Quantity by Year

Reporting Year:	2021
Quantity of PERC (kg):	0
Total Waste Water (kg):	0
Total Waste Water (L):	0
Total Residue (kg):	0
Total Residue (L):	0
Total Mix (kg):	0
Total Mix (L):	0
Request for Confidentiality:	no
Reason For Confidentiality:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	43 of 56	WSW/98.4	239.9 / 7.37	Dawson DCC-Wexford Square Dental 1 Wexford Road Unit 7 Brampton ON L6Z2W1	GEN

Generator No:	ON6498241
SIC Code:	
SIC Description:	
Approval Years:	As of Jul 2020
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			

5	44 of 56	WSW/98.4	239.9 / 7.37	**Wexford Medical Clinic** **1 Wexford rd** **Brampton ON L6Z2W1**	GEN

Generator No: ON6424643
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

5	45 of 56	WSW/98.4	239.9 / 7.37	**11244485 Canada Inc.** **1 WEXFORD ROAD, Unit 1** **BRAMPTON ON L6Z 2W1**	GEN

Generator No: ON0564110
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 H
Waste Class Name: Halogenated solvents and residues

5	46 of 56	WSW/98.4	239.9 / 7.37	**Innomar-Strategies Inc.** **1 Wexford Rd.** **Brampton ON L6Z 2W1**	GEN

Generator No: ON8769083
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
MHSW Facility:					
Detail(s)					
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
5	***47 of 56***	***WSW/98.4***	***239.9 / 7.37***	***Emergency Veterinary Clinic - Highway 10*** ***1 Wexford Rd. Unit 10*** ***Brampton ON L6Z 2W1***	***GEN***
Generator No:		ON4024746			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
5	***48 of 56***	***WSW/98.4***	***239.9 / 7.37***	***11244485 Canada Inc.*** ***1 WEXFORD ROAD, Unit 1*** ***BRAMPTON ON L6Z 2W1***	***GEN***
Generator No:		ON0564110			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		241 H			
Waste Class Name:		Halogenated solvents and residues			
5	***49 of 56***	***WSW/98.4***	***239.9 / 7.37***	***Dawson DCC-Wexford Square Dental*** ***1 Wexford Road Unit 7*** ***Brampton ON L6Z2W1***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON6498241
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	50 of 56	WSW/98.4	239.9 / 7.37	Wexford Medical Clinic 1 Wexford rd Brampton ON L6Z2W1	GEN

Generator No: ON6424643
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	51 of 56	WSW/98.4	239.9 / 7.37	Emergency Veterinary Clinic - Highway 10 1 Wexford Rd. Unit 10 Brampton ON L6Z 2W1	GEN

Generator No: ON4024746
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			

5	52 of 56	WSW/98.4	239.9 / 7.37	**Mackenzie Medical Rehab** **Mackenzie Medical Rehab 1 Wexford Road Unit 8** **Brampton ON L6Z2W1**	GEN

Generator No: ON5916434
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

5	53 of 56	WSW/98.4	239.9 / 7.37	**Emergency Veterinary Clinic - Highway 10** **1 Wexford Rd. Unit 10** **Brampton ON L6Z 2W1**	GEN

Generator No: ON4024746
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

5	54 of 56	WSW/98.4	239.9 / 7.37	**Dawson DCC-Wexford Square Dental** **1 Wexford Road Unit 7** **Brampton ON L6Z2W1**	GEN

Generator No: ON6498241
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	55 of 56	WSW/98.4	239.9 / 7.37	11244485 Canada Inc. 1 WEXFORD ROAD, Unit 1 BRAMPTON ON L6Z 2W1	GEN

Generator No: ON0564110
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 H
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	56 of 56	WSW/98.4	239.9 / 7.37	Wexford Medical Clinic 1 Wexford rd Brampton ON L6Z2W1	GEN

Generator No: ON6424643
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	1 of 19	SSE/92.3	230.9 / -1.60	FORTINO'S SUPERMARKET LTD. 60 QUARRY EDGE DRIVE HIGHWAY 10 & BOVAIRD DRIVE BRAMPTON ON L6V 1K2	GEN

Generator No: ON1826009
SIC Code: 6571

SIC Description: CAMERA/PHOTO. SUPPLY
Approval Years: 96,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

6 | **2 of 19** | **SSE/92.3** | **230.9 / -1.60** | **Fortino's Supermarket<UNOFFICIAL>**
#60 Quarry Edge Drive
Brampton ON L6V 4K2 | **SPL**

Ref No: 8170-67TURY
Year:
Incident Dt: 12/19/2004
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/19/2004
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: FORTINO'S SUPERMARKET
Site Address:
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Incident Cause: Discharge or Emission to Air
Incident Preceding Spill:
Environment Impact: Possible
Health Env Consequence:
Nature of Impact: Air Pollution; Human Health/Safety
Contaminant Qty: 340.909090909091 Kg
System Facility Address:
Client Name: Fortino's Supermarket<UNOFFICIAL>
Client Type:
Source Type:
Contaminant Code: 38
Contaminant Name: FREON (CFC)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Incident Reason: Equipment Failure
Incident Summary: Fortino's (Brampton): 750 lbs freon air
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Gases/Particulate
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SAC Action Class:
Call Report Locatn Geodata:

---

6 **3 of 19** **SSE/92.3** **230.9 / -1.60** **Loblaw Properties Limited**
60 Quarry Edge Dr
Brampton ON L6V 4K2 **SPL**

Ref No: 6026-7BMVEC
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/8/2008
Dt Document Closed: 2/12/2008
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Fortinos Supermarket Ltd
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Incident Cause: Discharge or Emission to Air
Incident Preceding Spill:
Environment Impact: Possible
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: 136 kg
System Facility Address:
Client Name: Loblaw Properties Limited
Client Type:
Source Type:
Contaminant Code: 38
Contaminant Name: FREON R-507 (CFC)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Gasket/Joint Failure - Any point of connection (Except Weld/Seam)
Incident Summary: Fortinos #69 - 136kg R507 to atm from solenoid
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

---

6 **4 of 19** **SSE/92.3** **230.9 / -1.60** **Loblaw Properties Limited**
60 Quarry Edge Dr
Brampton ON L6V 4K2 **SPL**

Ref No: 6224-7HFRSF
Year:
Incident Dt:
Dt MOE Arvl on Scn:

MOE Reported Dt:	8/12/2008	***Impact to Health:***	
Dt Document Closed:	8/25/2008	***Agency Involved:***	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Fortinos Supermarket Ltd		
Site Address:			
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	NA		
Easting:	NA		
Incident Cause:	Discharge or Emission to Air		
Incident Preceding Spill:			
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:	136 kg		
System Facility Address:			
Client Name:	Loblaw Properties Limited		
Client Type:			
Source Type:			
Contaminant Code:	38		
Contaminant Name:	FREON, R507 (CFC)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Incident Reason:	Other - Reason not otherwise defined		
Incident Summary:	Fortinos: 135 R507 to atm from leak on vap. line		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Other		
SAC Action Class:	Air Spills - Gases and Vapours		
Call Report Locatn Geodata:			

6	***5 of 19***	***SSE/92.3***	***230.9 / -1.60***	***Neelands Refrigeration Limited*** ***60 Quarry Edge*** ***Brampton ON L6V 4K2***	***SPL***

Ref No:	3650-8H2RLW	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	5/20/2011	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	5/20/2011	***Impact to Health:***	
Dt Document Closed:	5/24/2011	***Agency Involved:***	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Fortino's Supermarket<UNOFFICIAL>		
Site Address:	60 Quarry Edge		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			

Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	Discharge or Emission to Air
Incident Preceding Spill:	
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	174 kg
System Facility Address:	
Client Name:	Neelands Refrigeration Limited
Client Type:	
Source Type:	
Contaminant Code:	38
Contaminant Name:	REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	Spill
Incident Summary:	Fortino Supermarket: 174 R22 released
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other
SAC Action Class:	Air Spills - Gases and Vapours
Call Report Locatn Geodata:	

---

6 | ***6 of 19*** | ***SSE/92.3*** | ***230.9 / -1.60*** | ***Neelands Refrigeration Limited***
60 Quarry Edge Dr
Brampton ON L6V 4K2 | ***SPL***

Ref No:	2264-8WLN28	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	26-JUL-12	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	27-JUL-12	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	

Site No:	
MOE Response:	
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	Fortinos (Hwy 10 & Bovaird 2006) Ltd.
Site Address:	60 Quarry Edge Dr
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4839904
Easting:	598114
Incident Cause:	Discharge or Emission to Air
Incident Preceding Spill:	
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	
System Facility Address:	
Client Name:	Neelands Refrigeration Limited

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Type:
Source Type:
Contaminant Code: n/a
Contaminant Name: REFRIGERANT GAS R22
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Incident Reason:
Incident Summary: Fortinos: R22 to atm, ~ 114.49 kg
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

6	7 of 19	SSE/92.3	230.9 / -1.60	**Fortinos (Highway 10 & Bovaird 2006) Ltd.** **60 Quarry Edge Dr** **Brampton ON L6V 4K2**	SPL

Ref No: 4367-8VXHJD
Year:
Incident Dt: 05-JUL-12
Dt MOE Arvl on Scn:
MOE Reported Dt: 06-JUL-12
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Fortinos Supermarket Ltd
Site Address: 60 Quarry Edge Dr
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Incident Cause: Valve / Fitting Leak Or Failure
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Air Pollution; Other Impact(s)
Contaminant Qty:
System Facility Address:
Client Name: Fortinos (Highway 10 & Bovaird 2006) Ltd.
Client Type:
Source Type:
Contaminant Code: 38
Contaminant Name: HYDROFLUOROCARBON (HFC)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Incident Reason: Unknown - Reason not determined
Incident Summary: Fortinos: 285.96kg R507 to atm
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:

Sector Type: Storage Facility
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

---

6 **8 of 19** **SSE/92.3** **230.9 / -1.60** **60 Quarry Edge**
Brampton ON **SPL**

Ref No: 2484-97JN2C
Year:
Incident Dt: 09-MAY-13
Dt MOE Arvl on Scn:
MOE Reported Dt: 09-MAY-13
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Fortinos<UNOFFICIAL>
Site Address: 60 Quarry Edge
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Leak/Break
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: 172.9 kg
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code: 38
Contaminant Name: REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Unknown / N/A
Incident Summary: Fortinos: loss 172.9 kg refrigerant
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

---

6 **9 of 19** **SSE/92.3** **230.9 / -1.60** **Fortino's Supermarket<UNOFFICIAL>**
60 Quarry Edge Drive
Brampton ON **SPL**

Ref No: 8454-966QFK
Year:
Incident Dt: 26-MAR-13
Dt MOE Arvl on Scn:

MOE Reported Dt:	26-MAR-13	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Fortino's Supermarket<UNOFFICIAL>		
Site Address:	60 Quarry Edge Drive		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	Leak/Break		
Incident Preceding Spill:			
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:	140 kg		
System Facility Address:			
Client Name:	Fortino's Supermarket<UNOFFICIAL>		
Client Type:			
Source Type:			
Contaminant Code:	38		
Contaminant Name:	REFRIGERANT GAS, N.O.S.		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Incident Reason:	Equipment Failure		
Incident Summary:	Fortino's: 140 kg R-507 to atmosphere from low temp rack		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Valve/Fitting/Piping		
SAC Action Class:	Air Spills - Gases and Vapours		
Call Report Locatn Geodata:			

6	***10 of 19***	***SSE/92.3***	***230.9 / -1.60***	***Neelands Refrigeration Limited*** ***60 Quarry Edge Dr.*** ***Brampton ON***	***SPL***

Ref No:	6552-9GPU72	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2014/02/26	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2014/02/26	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Fortino's Store #84<UNOFFICIAL>		
Site Address:	60 Quarry Edge Dr.		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			

Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	Leak/Break
Incident Preceding Spill:	
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	113.04 kg
System Facility Address:	
Client Name:	Neelands Refrigeration Limited
Client Type:	
Source Type:	
Contaminant Code:	38
Contaminant Name:	FREON R-22 (CFC)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	Equipment Failure
Incident Summary:	Fortino's Store #84: Freon (R-22) leak to atm.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Valve/Fitting/Piping
SAC Action Class:	Air Spills - Gases and Vapours
Call Report Locatn Geodata:	

6	11 of 19	SSE/92.3	230.9 / -1.60	Fortinos Supermarket Ltd<UNOFFICIAL> 60 Quarry Edge Dr Brampton ON	SPL

Ref No:	7458-9FUPTW	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2014/01/30	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2014/01/30	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			

Site Name:	Fortinos Supermarket Ltd
Site Address:	60 Quarry Edge Dr
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	NA
Easting:	NA
Incident Cause:	Leak/Break
Incident Preceding Spill:	
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	113.26 kg
System Facility Address:	
Client Name:	Fortinos Supermarket Ltd<UNOFFICIAL>

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Type:
Source Type:
Contaminant Code: 38
Contaminant Name: FREON R-22 (CFC)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Equipment Failure
Incident Summary: Fortinos: bakery case leak of Freon R22 113.26kg
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Structure
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

6	12 of 19	SSE/92.3	230.9 / -1.60	Fortinos (Highway 10 & Bovaird 2006) Ltd. 60 Quarry Edge Dr Brampton ON L6V 4K2	SPL

Ref No: 6583-9VYPKS
Year:
Incident Dt: 4/27/2015
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/27/2015
Dt Document Closed:
Site No: 1022-67ULSP
MOE Response: N
Site County/District:
Site Geo Ref Meth: NA
Site District Office:
Nearest Watercourse:
Site Name: Fortinos Supermarket Ltd
Site Address: 60 Quarry Edge Dr
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Incident Cause: Leak/Break
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact: Air
Contaminant Qty: 113.8 kg
System Facility Address:
Client Name: Fortinos (Highway 10 & Bovaird 2006) Ltd.
Client Type:
Source Type:
Contaminant Code: 38
Contaminant Name: FREON R-22 (CFC)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Equipment Failure
Incident Summary: Fortino's, 113.8kg R22 refrigerant by Neelands
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Sector Type:
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

---

6 | **13 of 19** | **SSE/92.3** | **230.9 / -1.60** | **Neelands Refrigeration Limited**
60 Quarry Edge Dr
Brampton ON | **SPL**

Ref No: 6688-9JGQNT
Year:
Incident Dt: 2014/04/24
Dt MOE Arvl on Scn:
MOE Reported Dt: 2014/04/24
Dt Document Closed:
Site No: NA
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Fortinos<UNOFFICIAL>
Site Address: 60 Quarry Edge Dr
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Leak/Break
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: 226.54 kg
System Facility Address:
Client Name: Neelands Refrigeration Limited
Client Type:
Source Type:
Contaminant Code: 38
Contaminant Name: REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Material Failure - Poor Design/Substandard Material
Incident Summary: Fortino's refrigerant
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Pipeline/Components
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

---

6 | **14 of 19** | **SSE/92.3** | **230.9 / -1.60** | **Loblaw Companies Inc**
60 Quarry Edge Dr.
Brampton ON L6V 4K2 | **GEN**

Generator No: ON4127444
SIC Code: 445110
SIC Description: SUPERMARKETS AND OTHER GROCERY (EXCEPT CONVENIENCE) STORES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: James Williams
Choice of Contact: CO_OFFICIAL
Phone No Admin: 6472883298 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

6 | ***15 of 19*** | ***SSE/92.3*** | ***230.9 / -1.60*** | ***Loblaw Companies Inc***
60 Quarry Edge Dr.
Brampton ON L6V 4K2 | ***GEN***

Generator No: ON4127444
SIC Code: 445110
SIC Description: SUPERMARKETS AND OTHER GROCERY (EXCEPT CONVENIENCE) STORES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: James Williams
Choice of Contact: CO_OFFICIAL
Phone No Admin: 6472883298 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

6 | ***16 of 19*** | ***SSE/92.3*** | ***230.9 / -1.60*** | ***LOBLAWS INC. Fortinos***
60 Quarry Edge Dr.
Brampton ON L6V 4K2 | ***GEN***

Generator No: ON4127444
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	17 of 19	SSE/92.3	230.9 / -1.60	LOBLAWS INC. Fortinos 60 Quarry Edge Dr. Brampton ON L6V 4K2	GEN

Generator No: ON4127444
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	18 of 19	SSE/92.3	230.9 / -1.60	LOBLAWS INC. Fortinos 60 Quarry Edge Dr. Brampton ON L6V 4K2	GEN

Generator No: ON4127444
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	19 of 19	SSE/92.3	230.9 / -1.60	LOBLAWS INC. Fortinos 60 Quarry Edge Dr. Brampton ON L6V 4K2	GEN

Generator No: ON4127444
SIC Code:

SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

---

7 | ***1 of 1*** | ***E/41.6*** | ***235.9 / 3.37*** | ***29 Parkholme Place Brampton ON L6V 4G3*** | ***SPL***

Ref No: 3405-8U7U4F
Year:
Incident Dt: 11-MAY-12
Dt MOE Arvl on Scn:
MOE Reported Dt: 11-MAY-12
Dt Document Closed:
Site No:
MOE Response: Referral to others
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Construction Site <UNOFFICIAL>
Site Address: 29 Parkholme Place
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Discharges
Incident Preceding Spill:
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Incident Reason: Error- Operator error
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Incident Summary:	TSSA - 1/2" natural gas line cut by contractor.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Pipeline
SAC Action Class:	TSSA - Fuel Safety Branch
Call Report Locatn Geodata:	

---

8 | **1 of 1** | **E/98.4** | **234.8 / 2.33** | **67 Wildercroft Ave Brampton ON** | **SPL**

Ref No:	0632-AQ32SY	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	8/8/2017	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/8/2017	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	9/18/2017	**Agency Involved:**	

Site No:	NA
MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	Etobicoke Creek
Site Name:	WMB<UNOFFICIAL>
Site Address:	67 Wildercroft Ave
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4840801
Easting:	598522
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	1 m^3
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	Structure
Contaminant Code:	99
Contaminant Name:	WATER
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Surface Water
Incident Reason:	Material Failure - Poor Design/Substandard Material
Incident Summary:	Watermain break 67 Wildercroft, Etobicoke Creek
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

---

9 | **1 of 12** | **SSW/67.9** | **235.8 / 3.35** | **Cribben Inc.**
10025 Hurontario St Unit 11
Brampton ON L6Z 0E8 | **SCT**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Established: 1/1/1990
Plant Size (ft²): 1000
Employment:

--Details--
Description: Graphic Design Services
SIC/NAICS Code: 541430

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Manifold Business Forms Printing
SIC/NAICS Code: 323116

Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: Other Printing
SIC/NAICS Code: 323119

9	2 of 12	SSW/67.9	235.8 / 3.35	**Sherwin Williams Company** **10025 Hurontario Street** **Brampton ON L6Z 0E6**	GEN

Generator No: ON5557080
SIC Code: 444120
SIC Description: Paint and Wallpaper Stores
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

9	3 of 12	SSW/67.9	235.8 / 3.35	**Sherwin Williams Company** **10025 Hurontario Street** **Brampton ON L6Z 0E6**	GEN

Generator No: ON5557080
SIC Code: 444120
SIC Description: Paint and Wallpaper Stores
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			

9	4 of 12	SSW/67.9	235.8 / 3.35	**Sherwin Williams Company** **10025 Hurontario Street** **Brampton ON L6Z 0E6**	GEN

Generator No: ON5557080
SIC Code: 444120
SIC Description: Paint and Wallpaper Stores
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

9	5 of 12	SSW/67.9	235.8 / 3.35	**Sherwin Williams Company** **10025 Hurontario Street** **Brampton ON**	GEN

Generator No: ON5557080
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

9	6 of 12	SSW/67.9	235.8 / 3.35	**Sherwin Williams Company** **10025 Hurontario Street** **Brampton ON L6Z 0E6**	GEN

Generator No: ON5557080
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Paula Braga
Choice of Contact: CO_ADMIN
Phone No Admin: 905-507-0166 Ext.101
Contaminated Facility: No

MHSW Facility: No

Detail(s)

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

9 | ***7 of 12*** | ***SSW/67.9*** | ***235.8 / 3.35*** | ***Sherwin Williams Company***
10025 Hurontario Street
Brampton ON L6Z 0E6 | ***GEN***

Generator No: ON5557080
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Paula Braga
Choice of Contact: CO_ADMIN
Phone No Admin: 905-507-0166 Ext.101
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

9 | ***8 of 12*** | ***SSW/67.9*** | ***235.8 / 3.35*** | ***Sherwin Williams Company***
10025 Hurontario Street
Brampton ON L6Z 0E6 | ***GEN***

Generator No: ON5557080
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Paula Braga
Choice of Contact: CO_ADMIN
Phone No Admin: 905-507-0166 Ext.101
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	9 of 12	SSW/67.9	235.8 / 3.35	Sherwin Williams Company 10025 Hurontario Street Brampton ON L6Z 0E6	GEN

Generator No: ON5557080
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 232 I
Waste Class Name: Polymeric resins

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	10 of 12	SSW/67.9	235.8 / 3.35	Sherwin Williams Company 10025 Hurontario Street Brampton ON L6Z 0E6	GEN

Generator No: ON5557080
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 232 I
Waste Class Name: Polymeric resins

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	11 of 12	SSW/67.9	235.8 / 3.35	Sherwin Williams Company 10025 Hurontario Street Brampton ON L6Z 0E6	GEN

Generator No: ON5557080
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 232 I
Waste Class Name: Polymeric resins

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	12 of 12	SSW/67.9	235.8 / 3.35	Sherwin Williams Company 10025 Hurontario Street Brampton ON L6Z 0E6	GEN

Generator No: ON5557080
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 232 I
Waste Class Name: POLYMERIC RESINS

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

10 **1 of 3** **S/49.5** **233.9 / 1.37** **PETM Canada Corporation**
76 Quarry Edge Dr
brampton ON L6V4K2 **GEN**

Generator No: ON6945202
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

10 **2 of 3** **S/49.5** **233.9 / 1.37** **PETM Canada Corporation**
76 Quarry Edge Dr
brampton ON L6V4K2 **GEN**

Generator No: ON6945202
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

10	***3 of 3***	***S/49.5***	***233.9 / 1.37***	***PETM Canada Corporation*** ***76 Quarry Edge Dr*** ***brampton ON L6V4K2***	***GEN***

Generator No: ON6945202
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 A
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263 A
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 269 T
Waste Class Name: NON-HALOGENATED PESTICIDES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 331 L
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

---

11 | **1 of 7** | **SSW/73.7** | **236.9 / 4.44** | **Rexall Pharmacy Group Ltd.**
10035 Hurontario Street
Brampton ON L6Z 0E6 | **GEN**

Generator No: ON8297638
SIC Code: 446110
SIC Description: 446110
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Erik Botines
Choice of Contact: CO_ADMIN
Phone No Admin: 9055017800 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

11 | **2 of 7** | **SSW/73.7** | **236.9 / 4.44** | **Pharma Plus Drugmarts Ltd**
10035 Hurontario Street
Brampton ON L6Z 0E6 | **GEN**

Generator No: ON8297638
SIC Code: 446110
SIC Description: 446110
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Erik Botines
Choice of Contact: CO_ADMIN
Phone No Admin: 9055017800 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

11 | **3 of 7** | **SSW/73.7** | **236.9 / 4.44** | **Pharma Plus Drugmarts Ltd**
10035 Hurontario Street
Brampton ON L6Z 0E6 | **GEN**

Generator No: ON8297638
SIC Code: 446110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: 446110
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Aaron Schrama
Choice of Contact: CO_ADMIN
Phone No Admin: 905-502-5965 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

11	*4 of 7*	*SSW/73.7*	*236.9 / 4.44*	***Rexall Pharmacy Group Ltd.*** ***10035 Hurontario Street*** ***Brampton ON L6Z 0E6***	*GEN*

Generator No: ON8297638
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

11	*5 of 7*	*SSW/73.7*	*236.9 / 4.44*	***Rexall Pharmacy Group Ltd.*** ***10035 Hurontario Street*** ***Brampton ON L6Z 0E6***	*GEN*

Generator No: ON8297638
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
11	6 of 7	SSW/73.7	236.9 / 4.44	**Rexall Pharmacy Group Ltd.** **10035 Hurontario Street** **Brampton ON L6Z 0E6**	GEN
Generator No:		ON8297638			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
11	7 of 7	SSW/73.7	236.9 / 4.44	**Rexall Pharmacy Group Ltd.** **10035 Hurontario Street** **Brampton ON L6Z 0E6**	GEN
Generator No:		ON8297638			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		261 A			
Waste Class Name:		PHARMACEUTICALS			
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
13	1 of 1	W/68.0	238.7 / 6.24	**Emterra Environmental** **136 Sandmere Avenue, Brampton** **Brampton ON**	SPL
Ref No:	5050-AKAQ23			**Municipality No:**	
Year:				**Nature of Damage:**	
Incident Dt:	3/9/2017			**Discharger Report:**	
Dt MOE Arvl on Scn:				**Material Group:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MOE Reported Dt:	3/9/2017	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Location of the spill<UNOFFICIAL>		
Site Address:	136 Sandmere Avenue, Brampton		
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4840574		
Easting:	597140		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	50 L		
System Facility Address:			
Client Name:	Emterra Environmental		
Client Type:	Corporation		
Source Type:	Other		
Contaminant Code:	15		
Contaminant Name:	HYDRAULIC OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	n/a		
Receiving Medium:	Land		
Incident Reason:	Equipment Failure		
Incident Summary:	Emterra: 50 L of hydraulic oil spill to road and catchbasin, cntd		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Miscellaneous Industrial		
SAC Action Class:			
Call Report Locatn Geodata:			

---

14 | ***1 of 1*** | ***ENE/9.3*** | ***239.0 / 6.50*** | ***CANADIAN WASTE SERVICES KENNEDY AND BOVAIRD MOTOR VEHICLE (CARGO) BRAMPTON CITY ON*** | ***SPL***

Ref No:	233333	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	7/25/2002	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	7/25/2002	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	OTHER CAUSE (N.O.S.)
Incident Preceding Spill:	
Environment Impact:	POSSIBLE
Health Env Consequence:	
Nature of Impact:	Soil contamination
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Incident Reason:	FIRE, EXPLOSION
Incident Summary:	CANADIAN WASTE TRUCK-- CONTENTS ON FIRE, HAD TO BE DUMPED ON ROAD TO EXT.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	1 of 17	WSW/67.1	240.3 / 7.85	SHELL CANADA PRODUCTS LIMITED 10178 HURONTARIO ST BRAMPTON ON L6V1A1	RST

Headcode:	1186800
Headcode Desc:	Service Stations-Gasoline, Oil & Natural Gas
Phone:	9058401588
List Name:	
Description:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	2 of 17	WSW/67.1	240.3 / 7.85	PENNZOIL 10 MINUTE OIL CHANGE 10178 HURONTARIO ST BRAMPTON ON L7A 0E4	RST

Headcode:	00921430
Headcode Desc:	OIL CHANGES & LUBRICATION SERVICE
Phone:	
List Name:	
Description:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	3 of 17	WSW/67.1	240.3 / 7.85	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD 10178 HURONTARIO ST & WEXFORD BRAMPTON ON L7A 0E4	FSTH

License Issue Date:	3/8/2005
Tank Status:	Licensed
Tank Status As Of:	August 2007
Operation Type:	Retail Fuel Outlet

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

15	***4 of 17***	***WSW/67.1***	***240.3 / 7.85***	***2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD*** ***10178 HURONTARIO ST & WEXFORD*** ***BRAMPTON ON L7A 0E4***	***FSTH***

License Issue Date: 3/8/2005 3:09:00 PM
Tank Status: Pending Renewal
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1987
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

---

15 | **5 of 17** | **WSW/67.1** | **240.3 / 7.85** | **AUTO BATH INC**
10178 HURONTARIO ST & WEXFORD
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No: 10155703
Status: EXPIRED
Instance ID: 12915
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Cylr Handling Facility
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

15 | **6 of 17** | **WSW/67.1** | **240.3 / 7.85** | **2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD**
10178 HURONTARIO ST & WEXFORD
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No: 11459331
Status: EXPIRED

Expired Date:
Max Hazard Rank:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance ID: 85852
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

15	***7 of 17***	***WSW/67.1***	***240.3 / 7.85***	***2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD*** ***10178 HURONTARIO ST & WEXFORD*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 64046607
Status: EXPIRED
Instance ID: 350919
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Original Source:		EXP			
Record Date:		Up to Mar 2012			

15	8 of 17	WSW/67.1	240.3 / 7.85	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD 10178 HURONTARIO ST & WEXFORD BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	64046606	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	351989	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

15	9 of 17	WSW/67.1	240.3 / 7.85	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD 10178 HURONTARIO ST BRAMPTON ON	FST

Inventory No:	64046608	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2004	**Overfill Protection:**	
Capacity:	90000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS Split Tank: 60000L Regular/ 30000L Premium		

15	10 of 17	WSW/67.1	240.3 / 7.85	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD 10178 HURONTARIO ST	FST

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON	

Inventory No: 64046609
Inventory Status: active
Installation Year: 2004
Capacity: 90000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS
Split Tank: 60000L Regular/ 30000L Diesel

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	11 of 17	WSW/67.1	240.3 / 7.85	**PENNZOIL 10 MINUTE OIL CHANGE** **10178 HURONTARIO ST** **BRAMPTON ON L7A0E4**	RST

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone: 9058404534
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	12 of 17	WSW/67.1	240.3 / 7.85	**2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD** **10178 HURONTARIO ST & WEXFORD** **BRAMPTON ON**	EXP

Inventory No: 11459273
Inventory Status: EXPIRED
Installation Year: 1987
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Mid
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	13 of 17	WSW/67.1	240.3 / 7.85	**2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD** **10178 HURONTARIO ST & WEXFORD** **BRAMPTON ON**	EXP

Inventory No: 11459251
Inventory Status: EXPIRED
Installation Year: 1987
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Mid
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	14 of 17	WSW/67.1	240.3 / 7.85	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD 10178 HURONTARIO ST & WEXFORD BRAMPTON ON	EXP

Inventory No: 10596289
Inventory Status: EXPIRED
Installation Year: 1987
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS Premium
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	15 of 17	WSW/67.1	240.3 / 7.85	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD 10178 HURONTARIO ST & WEXFORD BRAMPTON ON	EXP

Inventory No: 11459310
Inventory Status: EXPIRED
Installation Year: 1987
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	16 of 17	WSW/67.1	240.3 / 7.85	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD 10178 HURONTARIO ST & WEXFORD BRAMPTON ON	EXP

Inventory No: 11459291
Inventory Status: EXPIRED
Installation Year: 1987
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	17 of 17	WSW/67.1	240.3 / 7.85	2054267 ONTARIO INC O/A SHELL GAS HWY 10 WEXFORD 10178 HURONTARIO ST BRAMPTON ON	FST

Inventory No: 9793416
Inventory Status: Active
Installation Year:
Capacity: 180000
Capacity Unit: L
Tank Type:
Manufacturer:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Model:
Description:

---

16 ***1 of 2*** ***WSW/54.1*** ***238.8 / 6.29*** ***CT REIT (Hurontario) Limited Partnership, by its g*** ***GEN***
10254 Hurontario Street
Brampton ON L7A 0E4

Generator No:	ON8868731
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	331 L
Waste Class Name:	Waste compressed gases including cylinders
Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders
Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants

---

16 ***2 of 2*** ***WSW/54.1*** ***238.8 / 6.29*** ***CT REIT (Hurontario) Limited Partnership, by its g*** ***GEN***
10254 Hurontario Street
Brampton ON L7A 0E4

Generator No:	ON8868731
SIC Code:	
SIC Description:	
Approval Years:	As of Oct 2022
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	331 I
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	331 L

Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

17 | 1 of 3 | SW/80.5 | 239.3 / 6.83 | **Chester Cartage**
10086 Hurontario Street
Brampton ON | SPL

Ref No: 7623-8VWP87
Year:
Incident Dt: 05-JUL-12
Dt MOE Arvl on Scn:
MOE Reported Dt: 05-JUL-12
Dt Document Closed:
Site No:
MOE Response: Planned Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: General Paint<UNOFFICIAL>
Site Address: 10086 Hurontario Street
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Discharges
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty:
System Facility Address:
Client Name: Chester Cartage
Client Type:
Source Type:
Contaminant Code: 27
Contaminant Name: PAINT (WATER-BASED)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Incident Reason: Damage By Moving Equipment - Containers damaged by moving
Incident Summary: Chester Cars: 80L of Paint to Pavement, clnd
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	2 of 3	SW/80.5	239.3 / 6.83	The Sherwin-Williams Company 10086 Hurontario Street Units 15 & 16 Brampton ON L7A 1E5	GEN

Generator No: ON3524086
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Paula Braga
Choice of Contact: CO_ADMIN
Phone No Admin: 905-507-0166 Ext.101
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	3 of 3	SW/80.5	239.3 / 6.83	The Sherwin-Williams Company 10086 Hurontario Street Units 15 & 16 Brampton ON L7A 1E5	GEN

Generator No: ON3524086
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Paula Braga
Choice of Contact: CO_ADMIN
Phone No Admin: 905-507-0166 Ext.101
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	1 of 6	SW/59.4	238.9 / 6.41	PEEL CO-OP TRUE VALUE 10064 HURONTARIO BRAMPTON ON L6V 1A1	RST

Headcode: 1070540
Headcode Desc: Propane Gas-Tanks & Refilling
Phone: 9058462211
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	2 of 6	SW/59.4	238.9 / 6.41	TRANSPORT TRUCK 10064 HURONTARIO STREET MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON L6V 1A1	SPL

Ref No: 238159
Year:
Municipality No: 21101
Nature of Damage:

Incident Dt:	9/4/2002			**Discharger Report:**	
Dt MOE Arvl on Scn:				**Material Group:**	
MOE Reported Dt:	9/4/2002			**Impact to Health:**	
Dt Document Closed:				**Agency Involved:**	
Site No:					
MOE Response:					
Site County/District:					
Site Geo Ref Meth:					
Site District Office:					
Nearest Watercourse:					
Site Name:					
Site Address:					
Site Region:					
Site Municipality:		BRAMPTON CITY			
Site Lot:					
Site Conc:					
Site Geo Ref Accu:					
Site Map Datum:					
Northing:					
Easting:					
Incident Cause:		TRUCK/TRAILER OVERTURN			
Incident Preceding Spill:					
Environment Impact:		POSSIBLE			
Health Env Consequence:					
Nature of Impact:		Soil contamination			
Contaminant Qty:					
System Facility Address:					
Client Name:					
Client Type:					
Source Type:					
Contaminant Code:					
Contaminant Name:					
Contaminant Limit 1:					
Contam Limit Freq 1:					
Contaminant UN No 1:					
Receiving Medium:		LAND			
Incident Reason:		OTHER			
Incident Summary:		PETRELLA TRANSPORT TRUCK--ROLLED OVER AND SPILLED DIESEL & OIL ONTO PKG LOT			
Activity Preceding Spill:					
Property 2nd Watershed:					
Property Tertiary Watershed:					
Sector Type:					
SAC Action Class:					
Call Report Locatn Geodata:					

18	***3 of 6***	***SW/59.4***	***238.9 / 6.41***	***PEEL CO-OP TRUE VALUE 10064 HURONTARIO ST BRAMPTON ON L6V 1A1***	***RST***

Headcode:	1070540
Headcode Desc:	Propane Gas-Tanks & Refilling
Phone:	9058462211
List Name:	
Description:	

18	***4 of 6***	***SW/59.4***	***238.9 / 6.41***	***PEEL SEED CO-OP 10064 HURONTARIO ST BRAMPTON ON L7A 0E4***	***RST***

Headcode:	01070540
Headcode Desc:	PROPANE GAS-TANKS & REFILLING
Phone:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
List Name:					
Description:					

18	5 of 6	SW/59.4	238.9 / 6.41	PEEL SEED CO-OPERATIVE INC 10064 HURONTARIO ST BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11071611	Expired Date:	
Status:	EXPIRED	Max Hazard Rank:	
Instance ID:	66987	Facility Location:	
Instance Type:	FS Propane Tank	Facility Type:	
Instance Creation Dt:		Fuel Type 2:	
Instance Install Dt:		Fuel Type 3:	
Item Description:		Panam Related:	
Manufacturer:		Panam Venue Nm:	
Model:		External Identifier:	
Serial No:		Item:	
ULC Standard:		Piping Steel:	
Quantity:		Piping Galvanized:	
Unit of Measure:		Tank Single Wall St:	
Overfill Prot Type:		Piping Underground:	
Creation Date:		Tank Underground:	
Next Periodic Str DT:		Source:	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Tank		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

18	6 of 6	SW/59.4	238.9 / 6.41	PEEL SEED CO-OP 10064 HURONTARIO ST BRAMPTON ON	RST

Headcode:	00924800
Headcode Desc:	FUEL OIL
Phone:	9058462211
List Name:	
Description:	

19	1 of 18	S/40.6	234.9 / 2.37	1672237 ONTARIO LTD 9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	FSTH

License Issue Date:	3/1/2006
Tank Status:	Licensed
Tank Status As Of:	August 2007
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--

Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	50000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	50000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	25000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	25000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	2 of 18	S/40.6	234.9 / 2.37	***RAMKUMAR ENTERPRISES INC*** ***9 BOVAIRD DR HWY 7 & 10 BYPASS*** ***BRAMPTON ON***	***FSTH***

License Issue Date:	10/23/2008 12:12:00 PM
Tank Status:	Licensed
Tank Status As Of:	December 2008
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	50000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	50000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	25000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	25000
Tank Fuel Type:	Liquid Fuel Single Wall UST - Diesel
Status:	Active
Year of Installation:	2000

Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

19	*3 of 18*	*S/40.6*	*234.9 / 2.37*	***RAMKUMAR ENTERPRISES INC*** ***9 BOVAIRD DR HWY 7 & 10 BYPASS*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10600882
Status: EXPIRED
Instance ID: 29878
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

19	*4 of 18*	*S/40.6*	*234.9 / 2.37*	***RAMKUMAR ENTERPRISES INC*** ***9 BOVAIRD DR HWY 7 & 10 BYPASS***	***DTNK***

BRAMPTON ON

Delisted Expired Fuel Safety Facilities

Instance No:	10600930	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	30125	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

19	5 of 18	S/40.6	234.9 / 2.37	**RAMKUMAR ENTERPRISES INC** **9 BOVAIRD DR HWY 7 & 10 BYPASS** **BRAMPTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10600984	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	30613	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	6 of 18	S/40.6	234.9 / 2.37	RAMKUMAR ENTERPRISES INC 9 BOVAIRD DR HWY 7 & 10 BYPASS BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10601028
Status: EXPIRED
Instance ID: 30678
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	7 of 18	S/40.6	234.9 / 2.37	MAC'S CONVENIENCE STORES INC. 9 BOVAIRD DR E BRAMPTON ON	FST

Inventory No: 11616620
Inventory Status: active
Installation Year: 2000
Capacity: 46400
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	8 of 18	S/40.6	234.9 / 2.37	MAC'S CONVENIENCE STORES INC. 9 BOVAIRD DR E BRAMPTON ON	FST

Inventory No:	11616626	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	22700	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	9 of 18	S/40.6	234.9 / 2.37	MAC'S CONVENIENCE STORES INC. 9 BOVAIRD DR E BRAMPTON ON	FST

Inventory No:	11616606	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	10 of 18	S/40.6	234.9 / 2.37	MAC'S CONVENIENCE STORES INC. 9 BOVAIRD DR E BRAMPTON ON	FST

Inventory No:	11616614	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2000	**Overfill Protection:**	
Capacity:	46400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	11 of 18	S/40.6	234.9 / 2.37	Mac's Convenience Stores Inc. 9 Bovaird Drive Brampton ON L6V 0A2	GEN

Generator No:	ON8852762
SIC Code:	
SIC Description:	
Approval Years:	As of Jul 2020
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

19 | ***12 of 18*** | ***S/40.6*** | ***234.9 / 2.37*** | ***Mac's Convenience Stores Inc.*** ***9 Bovaird Drive*** ***Brampton ON L6V 0A2*** | ***GEN***

Generator No: ON8852762
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

19 | ***13 of 18*** | ***S/40.6*** | ***234.9 / 2.37*** | ***Mac's Convenience Stores Inc.*** ***9 Bovaird Drive*** ***Brampton ON L6V 0A2*** | ***GEN***

Generator No: ON8852762
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

19 | ***14 of 18*** | ***S/40.6*** | ***234.9 / 2.37*** | ***RAMKUMAR ENTERPRISES INC*** ***9 BOVAIRD DR E*** ***BRAMPTON ON*** | ***EXP***

Inventory No: 10600906
Inventory Status: EXPIRED
Installation Year: 1983
Capacity: 50000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Previous Fuel Type: Gasoline

---

19 | ***15 of 18*** | ***S/40.6*** | ***234.9 / 2.37*** | ***RAMKUMAR ENTERPRISES INC***
9 BOVAIRD DR E
BRAMPTON ON | ***EXP***

Inventory No:	10600851	***Tank Material:***	Steel
Inventory Status:	EXPIRED	***Corrosion Protect:***	Sacrificial anode
Installation Year:	1983	***Overfill Protection:***	
Capacity:	50000	***Inventory Context:***	FS Liquid Fuel Tank
Capacity Unit:		***Inventory Item:***	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

---

19 | ***16 of 18*** | ***S/40.6*** | ***234.9 / 2.37*** | ***RAMKUMAR ENTERPRISES INC***
9 BOVAIRD DR E
BRAMPTON ON | ***EXP***

Inventory No:	10600959	***Tank Material:***	Steel
Inventory Status:	EXPIRED	***Corrosion Protect:***	Sacrificial anode
Installation Year:	1983	***Overfill Protection:***	
Capacity:	25000	***Inventory Context:***	FS Liquid Fuel Tank
Capacity Unit:		***Inventory Item:***	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

---

19 | ***17 of 18*** | ***S/40.6*** | ***234.9 / 2.37*** | ***RAMKUMAR ENTERPRISES INC***
9 BOVAIRD DR E
BRAMPTON ON | ***EXP***

Inventory No:	10601003	***Tank Material:***	Steel
Inventory Status:	EXPIRED	***Corrosion Protect:***	Sacrificial anode
Installation Year:	1983	***Overfill Protection:***	
Capacity:	25000	***Inventory Context:***	FS Liquid Fuel Tank
Capacity Unit:		***Inventory Item:***	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Diesel		

---

19 | ***18 of 18*** | ***S/40.6*** | ***234.9 / 2.37*** | ***MAC'S CONVENIENCE STORES INC.***
9 BOVAIRD DR E
BRAMPTON ON | ***FST***

Inventory No:	9841622	***Tank Material:***	
Inventory Status:	Active	***Corrosion Protect:***	
Installation Year:		***Overfill Protection:***	
Capacity:	161900	***Inventory Context:***	Liquid Fuels
Capacity Unit:	L	***Inventory Item:***	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:					

20 | 1 of 7 | SSW/6.8 | 236.0 / 3.56 | WIMPEY
CONSTRUCTION SITE AT HWY #7 & HWY #10.
PORTABLE FUEL STORAGE TANK
BRAMPTON CITY ON | SPL

Ref No:	103307	Municipality No:	21101
Year:		Nature of Damage:	
Incident Dt:	7/28/1994	Discharger Report:	
Dt MOE Arvl on Scn:		Material Group:	
MOE Reported Dt:	7/28/1994	Impact to Health:	
Dt Document Closed:		Agency Involved:	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	OTHER CONTAINER LEAK		
Incident Preceding Spill:			
Environment Impact:	CONFIRMED		
Health Env Consequence:			
Nature of Impact:	Soil contamination		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	GEORGE WIMPEY- 14L DIESELTO DIRT FROM PORTABLE FUELSTORAGE TANK, CLEANED UP		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

20 | 2 of 7 | SSW/6.8 | 236.0 / 3.56 | TRIMAC
10 SIDE RD. HWY 10 AND 7 TANK TRUCK (CARGO)
BRAMPTON CITY ON | SPL

Ref No:	14127	Municipality No:	21101
Year:		Nature of Damage:	
Incident Dt:	1/25/1989	Discharger Report:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	1/25/1989	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	REG. OF PEEL
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	CONTAINER OVERFLOW		
Incident Preceding Spill:			
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Incident Reason:	UNKNOWN		
Incident Summary:	TANKER TRUCK		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

20	*3 of 7*	*SSW/6.8*	*236.0 / 3.56*	***Hwy. 10 & Bovaird St. Brampton ON***	***SPL***

Ref No:	6202-5LN5H5	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	4/15/2003	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	Oil
MOE Reported Dt:	4/15/2003	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	ETOBICOKE CREEK<UNOFFICIAL>		
Site Address:			
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			

Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Discharge Or Bypass To A Watercourse
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code: 15
Contaminant Name: PETROLEUM OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Water
Incident Reason:
Incident Summary: Source unknown - oil in Etobicoke Crk.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

20 | ***4 of 7*** | ***SSW/6.8*** | ***236.0 / 3.56*** | ***SE corner of Highway 10 (Hurontario St.) and Highway 7 (Bovaird Dr.)
Brampton ON*** | ***SPL***

Ref No: 2525-7XKRAW
Year:
Incident Dt:
Dt MOE Arvl on Scn: 11/11/2009
MOE Reported Dt: 11/7/2009
Dt Document Closed:
Site No:
MOE Response: Deferred Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Brampton Corners Shopping Mall<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Discharge Or Bypass To A Watercourse
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 4.32 m3/d
System Facility Address:
Client Name:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Type:	
Source Type:	
Contaminant Code:	44
Contaminant Name:	SEWAGE,RAW CHLORINATED
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	Other - Reason not otherwise defined
Incident Summary:	Brampton Corners: raw chlor'd sewage, manhole to storm sewer
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Sewer
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

20	5 of 7	SSW/6.8	236.0 / 3.56	**PREET PETROLEUM** **HWY 7 HWY 10** **BRAMPTON ON L3M 1V1**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9824366	**Expired Date:**	10/7/2009 14:28
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

20	6 of 7	SSW/6.8	236.0 / 3.56	**Bovaird Drive & Hwy #10, Brampton ON**	INC

Incident No:	424494	**Any Health Impact:**	No
Incident ID:		**Any Enviro Impact:**	No
Instance No:		**Service Intrp:**	No
Status Code:		**Was Prop Damaged:**	No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Status:		***Reside App. Type:***	
Incident Severity:		***Commer App. Type:***	
Task No:	2984920	***Indus App. Type:***	
Attribute Category:	FS-Perform L1 Incident Insp	***Institut App. Type:***	
Context:		***Depth Ground Cover:***	
Date of Occurrence:	2010/07/20 00:00:00	***Operation Pressure:***	
Time of Occurrence:	NULL	***Equipment Type:***	
Occr Insp Start Dt:	2010/07/27 00:00:00	***Equipment Model:***	
Incident Creat On:		***Serial No:***	
Instance Creat Dt:		***Cylinder Capacity:***	
Instance Install Dt:		***Cylinder Cap Units:***	
Approx Quant Rel:		***Cylinder Mat Type:***	
Tank Capacity:		***Pump Flow Rate Cap:***	
Fuels Occur Type:	Other	***Contam. Migrated:***	
Occur Type Rpt:		***Near Body of Water:***	
Occur Category:		***Drainage System:***	
Fuel Type Involved:	Diesel	***Sub Surface Contam:***	
Fuel Type Reported:		***Tank Material Type:***	
Enforcement Policy:	NULL	***Tank Storage Type:***	
Prc Escalation Req:	NULL	***Tank Location Type:***	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	Bovaird Drive & Hwy #10, Brampton - Spill		
Invent Postal Code:			
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:	complaint re training		
Operation Type Involved:	Retail Fuel Station (FS, SS, Multifunctional)		

---

20 | ***7 of 7*** | ***SSW/6.8*** | ***236.0 / 3.56*** | ***Stewart Foodservice Inc.***
 NW corner of Bovaird Dr W & Hurontario St
 Brampton ON | ***SPL***

Ref No:	6264-AJUNDH	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2/23/2017	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2/23/2017	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:	NA		
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	site<UNOFFICIAL>		
Site Address:	NW corner of Bovaird Dr W & Hurontario St		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			

Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4839816
Easting:	597664
Incident Cause:	
Incident Preceding Spill:	Collision/Accident
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	200 L
System Facility Address:	
Client Name:	Stewart Foodservice Inc.
Client Type:	
Source Type:	
Contaminant Code:	13
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Operator/Human Error
Incident Summary:	Steward Food: 200 L diesel to road, cntd & clng
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Highway Spills (usually highway accidents)
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	1 of 1	W/86.0	240.9 / 8.37	**Enbridge Gas Distribution Inc.** **16 Tremblay Street** **Brampton ON**	SPL

Ref No:	2552-A28RSG	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/10/2015	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/10/2015	**Impact to Health:**	
Dt Document Closed:	10/3/2015	**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Residential Site<UNOFFICIAL>		
Site Address:	16 Tremblay Street		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:			
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	0 other - see incident description		
System Facility Address:			
Client Name:	Enbridge Gas Distribution Inc.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Type:
Source Type:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Equipment Failure
Incident Summary: TSSA/Enbridge ½ inch plastic, line damage, made safe
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:

22	1 of 1	ENE/88.3	236.9 / 4.45	***PRIVATE RESIDENCE*** ***142 SIMMONS BLVD SEWAGE/SEPTIC SYSTEM*** ***BRAMPTON CITY ON L6V 3W4***	SPL

Ref No: 178614
Year:
Incident Dt: 3/18/2000
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/18/2000
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: WASTEWATER DISCHARGE TO WATERCOURSE
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: OTHER
Incident Summary: PRIVATE RESIDENCE:SEWAGE BACK-UP IN HOME, F.D. PUMPED TO DITCH OUTSIDE.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: F.D.,WORKS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Sector Type:					
SAC Action Class:					
Call Report Locatn Geodata:					

23	1 of 6	SSW/81.7	237.2 / 4.75	**DAVE'S GAS DEPOT** **30 HWY 7 W** **BRAMPTON ON**	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9057969131
List Name:
Description:

23	2 of 6	SSW/81.7	237.2 / 4.75	**DAVE'S GAS DEPOT** **30 BOVAIRD DR W** **BRAMPTON ON L6V 1A1**	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9057969131
List Name:
Description:

23	3 of 6	SSW/81.7	237.2 / 4.75	**Regionional Municipality of Peel** **2 - 30 Bovaird Drive West** **Brampton ON L7A 0H3**	GEN

Generator No: ON9867821
SIC Code: 913910
SIC Description: Other Local Municipal and Regional Public Administration
Approval Years: 05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

23	4 of 6	SSW/81.7	237.2 / 4.75	**30 Hwy 7 W now 30 Bovaird Drive** **Brampton ON**	SPL

Ref No: 8348-6EETER
Year:
Incident Dt: 7/18/2005
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/18/2005
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Municipality No:
Nature of Damage:
Discharger Report: 0
Material Group: Oil
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Gas Station<UNOFFICIAL>
Site Address:	
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	Soil Contamination
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	GASOLINE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	
Incident Summary:	Brampton-gas station leak to soil, old
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Service Station
SAC Action Class:	Spills to Land
Call Report Locatn Geodata:	

23	***5 of 6***	***SSW/81.7***	***237.2 / 4.75***	***Regional Municipality of Peel*** ***2 - 30 Bovaird Drive West*** ***Brampton ON L7A 0H3***	***GEN***

Generator No:	ON9867821
SIC Code:	913910
SIC Description:	Other Local Municipal and Regional Public Administ
Approval Years:	06
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

23	***6 of 6***	***SSW/81.7***	***237.2 / 4.75***	***Pinchin Ltd.*** ***2-30 Bovaird Drive West*** ***Brampton ON L7A 0H3***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON5696600
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

24	1 of 15	SSW/54.6	235.9 / 3.37	PIONEER PETROLEUM 675 MAIN ST N BRAMPTON ON L6V1A1	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054566363
List Name:
Description:

24	2 of 15	SSW/54.6	235.9 / 3.37	PIONEER PETROLEUM 675 MAIN N BRAMPTON ON	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054566363
List Name:
Description:

24	3 of 15	SSW/54.6	235.9 / 3.37	PIONEER PETROLEUMS 675 MAIN ST N BRAMPTON ON L6X 0G6	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

24	4 of 15	SSW/54.6	235.9 / 3.37	PIONEER PETROLEUMS MANAGEMENT INC** 675 MAIN ST N BRAMPTON ON L6X 0G6	FSTH

License Issue Date: 3/22/2002
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--

Status:	Active
Year of Installation:	1989
Corrosion Protection:	
Capacity:	45400
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1989
Corrosion Protection:	
Capacity:	45400
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1989
Corrosion Protection:	
Capacity:	45400
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1989
Corrosion Protection:	
Capacity:	45400
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	5 of 15	SSW/54.6	235.9 / 3.37	PIONEER PETROLEUMS MANAGEMENT INC** 675 MAIN ST N BRAMPTON ON L6X 0G6	FSTH

License Issue Date:	3/22/2002
Tank Status:	Licensed
Tank Status As Of:	December 2008
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	1989
Corrosion Protection:	
Capacity:	45400
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1989
Corrosion Protection:	
Capacity:	45400
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1989
Corrosion Protection:	
Capacity:	45400
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1989
Corrosion Protection:	
Capacity:	45400
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	6 of 15	SSW/54.6	235.9 / 3.37	PIONEER ENERGY MANAGEMENT INC. 675 MAIN ST N BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11442375	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	84689	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	7 of 15	SSW/54.6	235.9 / 3.37	PIONEER ENERGY MANAGEMENT INC. 675 MAIN ST N BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	64272903	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	352181	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

24 | ***8 of 15*** | ***SSW/54.6*** | ***235.9 / 3.37*** | ***PIONEER ENERGY MANAGEMENT INC.***
675 MAIN ST N
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 64272902
Status: EXPIRED
Instance ID: 353690
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

24 | ***9 of 15*** | ***SSW/54.6*** | ***235.9 / 3.37*** | ***PARKLAND CORPORATION***
675 MAIN ST N
BRAMPTON ON | ***FST***

Inventory No: 11442317
Inventory Status: active
Installation Year: 1989
Capacity: 45400
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:		2009VBS Mid			

---

24 | **10 of 15** | **SSW/54.6** | **235.9 / 3.37** | **PARKLAND CORPORATION**
675 MAIN ST N
BRAMPTON ON | **FST**

Inventory No:	11442355	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1989	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

24 | **11 of 15** | **SSW/54.6** | **235.9 / 3.37** | **PARKLAND CORPORATION**
675 MAIN ST N
BRAMPTON ON | **FST**

Inventory No:	11442338	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1989	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

24 | **12 of 15** | **SSW/54.6** | **235.9 / 3.37** | **PARKLAND CORPORATION**
675 MAIN ST N
BRAMPTON ON | **FST**

Inventory No:	10599019	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1989	**Overfill Protection:**	
Capacity:	45400	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS Premium		

---

24 | **13 of 15** | **SSW/54.6** | **235.9 / 3.37** | **PIONEER PETROLEUMS**
675 MAIN ST N
BRAMPTON ON L6X0G6 | **RST**

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS GASOLINE OIL & NATURAL
Phone:	9054566363
List Name:	
Description:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	14 of 15	SSW/54.6	235.9 / 3.37	Pioneer Energy LP 675 Main Street North Brampton ON L6X 0G6	GEN

Generator No: ON4230276
SIC Code: 447110
SIC Description: 447110
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Alyssa Santiago
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-567-4444 Ext.1494
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	15 of 15	SSW/54.6	235.9 / 3.37	PARKLAND CORPORATION 675 MAIN ST N BRAMPTON ON	FST

Inventory No: 9831772
Inventory Status: Active
Installation Year:
Capacity: 181600
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
25	1 of 1	W/63.5	239.9 / 7.37	Enbridge Gas Distribution Inc. 10370 Hurontario Street Brampton ON	SPL

Ref No: 4251-9XDH5B
Year:
Incident Dt: 6/10/2015
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/11/2015
Dt Document Closed:
Site No: NA
MOE Response: N
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Safe Storage Depot<UNOFFICIAL>
Site Address: 10370 Hurontario Street
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Leak/Break

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact: Air
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name: Enbridge Gas Distribution Inc.
Client Type:
Source Type:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Operator/Human Error
Incident Summary: TSSA: 1 inch damage, made safe
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

26	1 of 1	W/56.3	239.4 / 6.96	**Mandarano/Vilone Property** **10394 Hurontario Street North** **Brampton ON L7A 0E4**	GEN

Generator No: ON5794745
SIC Code: 444220
SIC Description: NURSERY AND GARDEN CENTRES, NURSERY STORES AND GARDEN CENTRES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

27	1 of 1	E/65.0	238.9 / 6.40	**13 Crosswood Lane** **BRAMPTON ON**	SPL

Ref No: 1-10A2HQ
Year:
Incident Dt: 7/20/2021 11:26:37 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/21/2021 12:26:43 AM
Dt Document Closed: 8/3/2021 10:11:39 AM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse: Etobicoke Creek
Site Name:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Site Address:	13 Crosswood Lane
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see notes
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	Water Supply
Contaminant Code:	
Contaminant Name:	SEDIMENT WATER CONTENT
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Surface Water
Incident Reason:	Unknown
Incident Summary:	Region of Peel: Watermain Break Sediment to Etobicoke Creek
Activity Preceding Spill:	Normal operations
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HC-Humber - Don
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001859480"],"wkts":["POINT (-79.7719827000 43.7117770000)"],"creation_date":"2021-07-21"}

---

28 | ***1 of 1*** | ***E/80.8*** | ***239.9 / 7.37*** | ***Enbridge Gas Distribution Inc.***
23 Histon Cres.
Brampton ON | ***SPL***

Ref No:	8516-AS7VFU	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2017/10/16	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2017/10/16	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2017/10/21	**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Half Inch Plastic Ip Line Strike<UNOFFICIAL>		
Site Address:	23 Histon Cres.		
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Environment Impact:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	Enbridge Gas Distribution Inc.
Client Type:	Corporation
Source Type:	Valve/Fitting/Piping
Contaminant Code:	35
Contaminant Name:	NATURAL GAS (METHANE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	1075
Receiving Medium:	Air
Incident Reason:	Operator/Human Error
Incident Summary:	TSSA/FSB: Enbridge 1/2" PL Ip Strike - Made Safe
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	1 of 1	W/80.9	238.8 / 6.29	**New Image Car Wash** **11 Fisherman Dr** **Brampton ON L7A2X9**	GEN

Generator No:	ON8928019
SIC Code:	
SIC Description:	
Approval Years:	As of Oct 2022
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251 L
Waste Class Name:	OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
30	1 of 1	W/97.7	238.3 / 5.80	**MAYFIELD DRYWALL AND CONTRACTING** **13 FISHERMAN DR** **BRAMPTON ON L7A 2X9**	GEN

Generator No:	ON9136249
SIC Code:	238320
SIC Description:	Painting and Wall Covering Contractors
Approval Years:	07,08
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

31 **1 of 1** **W/7.2** **239.9 / 7.37** **TRANSPORT TRUCK**
FISCHERMAN DRIVE & HWY 10 MOTOR VEHICLE (OPERATING FLUID)
BRAMPTON CITY ON **SPL**

Ref No: 72409
Year:
Incident Dt: 6/19/1992
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/20/1992
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND / WATER
Incident Reason: ERROR
Incident Summary: TRANSPORT TRUCK ACCIDENT:248 L DIESEL FUEL ONTO GRND & INTO CATCH BASIN.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: PD, FD, CITY, HAZ.MAT.UNIT

---

32 **1 of 1** **E/77.8** **239.9 / 7.37** **60 Buckland Way, Brampton, ON**
BRAMPTON ON **SPL**

Ref No: 1-CFV1M
Year:
Incident Dt: 4/16/2021 8:29:12 AM
Dt MOE Arvl on Scn:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MOE Reported Dt:	4/16/2021 11:23:22 AM	**Impact to Health:**	0 No Impact
Dt Document Closed:	4/26/2021 4:27:57 PM	**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	60 Buckland Way, Brampton, ON		
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:	Other (specify)		
Environment Impact:	0 No Impact		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	0 other - see notes		
System Facility Address:			
Client Name:			
Client Type:			
Source Type:	Pipeline/Components		
Contaminant Code:			
Contaminant Name:	METHANE		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Air		
Incident Reason:	Human error (Specify)		
Incident Summary:	TSSA FSB: 0.5" pl IP line strike, made safe & repaired.		
Activity Preceding Spill:	Construction or repair		
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula		
Property Tertiary Watershed:	02HC-Humber - Don		
Sector Type:	NATURAL GAS DISTRIBUTION		
SAC Action Class:			
Call Report Locatn Geodata:	{"integration_ids":["PR00001672834"],"wkts":["POINT (-79.7695025000 43.7119179000)","POINT (-79.7695025000 43.7119179000)"],"creation_date":"2021-04-16"}		

33	*1 of 18*	*W/57.0*	*237.4 / 4.87*	***LAGRAN CANADA INC.*** ***2 FISHERMAN DR SUITE 1102*** ***BRAMPTON ON L7A 1B5***	***SCT***

Established:	1951
Plant Size (ft²):	600
Employment:	2
--Details--	
Description:	PIECE GOODS, NOTIONS, AND OTHER DRY GOODS
SIC/NAICS Code:	5131

33	*2 of 18*	*W/57.0*	*237.4 / 4.87*	***PENNZOIL 10 MINUTE OIL CHANGE CENTRE*** ***2 FISHERMAN DR*** ***BRAMPTON ON L7A 1B5***	***RST***

Headcode:	00921430

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Headcode Desc:		OIL CHANGES & LUBRICATION SERVICE			
Phone:					
List Name:					
Description:					

33	3 of 18	W/57.0	237.4 / 4.87	**Centric Health** **2 Fisherman Drive, Unit 7** **Brampton ON**	GEN

Generator No:	ON5232397
SIC Code:	621340
SIC Description:	Offices of Physical Occupational and Speech Therapists and Audiologists
Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

33	4 of 18	W/57.0	237.4 / 4.87	**PENNZOIL 10 MINUTE OIL CHANGE CENTRE** **2 FISHERMAN DR** **BRAMPTON ON L7A1B5**	RST

Headcode:	00921430
Headcode Desc:	OIL CHANGES & LUBRICATION SERVICE
Phone:	9058405901
List Name:	
Description:	

33	5 of 18	W/57.0	237.4 / 4.87	**Centric Health** **2 Fisherman Drive, Unit 7** **Brampton ON**	GEN

Generator No:	ON5232397
SIC Code:	621340
SIC Description:	
Approval Years:	2013
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

33	6 of 18	W/57.0	237.4 / 4.87	**Stephenson's Rental Services Inc.** **2 Fisherman Drive Unit 17** **Brampton ON L7A 1B5**	GEN

Generator No:	ON4592837
SIC Code:	532490

SIC Description:	OTHER COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT RENTAL AND LEASING
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Mary Vaughan
Choice of Contact:	CO_ADMIN
Phone No Admin:	905-507-3650 Ext.206
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	221
Waste Class Name:	LIGHT FUELS
Waste Class:	253
Waste Class Name:	EMULSIFIED OILS
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	7 of 18	W/57.0	237.4 / 4.87	***Centric Health*** ***2 Fisherman Drive, Unit 7*** ***Brampton ON L7A1B5***	***GEN***

Generator No:	ON5232397
SIC Code:	621340
SIC Description:	621340
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	8 of 18	W/57.0	237.4 / 4.87	***Centric Health*** ***2 Fisherman Drive, Unit 7*** ***Brampton ON L7A1B5***	***GEN***

Generator No:	ON5232397
SIC Code:	621340
SIC Description:	621340

Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	9 of 18	W/57.0	237.4 / 4.87	**Stephenson's Rental Services Inc.** **2 Fisherman Drive Unit 17** **Brampton ON L7A 1B5**	GEN

Generator No: ON4592837
SIC Code: 532490
SIC Description: OTHER COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT RENTAL AND LEASING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Mary Vaughan
Choice of Contact: CO_ADMIN
Phone No Admin: 905-507-3650 Ext.206
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	10 of 18	W/57.0	237.4 / 4.87	**Centric Health** **2 Fisherman Drive, Unit 7** **Brampton ON L7A1B5**	GEN

Generator No: ON5232397
SIC Code: 621340
SIC Description: 621340
Approval Years: 2014

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	11 of 18	W/57.0	237.4 / 4.87	**Stephenson's Rental Services Inc. Brampton 109** **2 Fisherman Drive Unit 17** **Brampton ON L7A 1B5**	GEN

Generator No: ON4592837
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 253 L
Waste Class Name: Emulsified oils

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	12 of 18	W/57.0	237.4 / 4.87	**Lifemark Health** **2 Fisherman Drive, Unit 7** **Brampton ON L7A1B5**	GEN

Generator No: ON5232397
SIC Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 P
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

33	13 of 18	W/57.0	237.4 / 4.87	**Lifemark Health** **2 Fisherman Drive, Unit 7** **Brampton ON L7A1B5**	GEN

Generator No: ON5232397
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 P
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

33	14 of 18	W/57.0	237.4 / 4.87	**Stephenson's Rental Services Inc. Brampton 109** **2 Fisherman Drive Unit 17** **Brampton ON L7A 1B5**	GEN

Generator No: ON4592837
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	15 of 18	W/57.0	237.4 / 4.87	**Stephenson's Rental Services Inc. Brampton 109** **2 Fisherman Drive Unit 17** **Brampton ON L7A 1B5**	GEN

Generator No: ON4592837
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	16 of 18	W/57.0	237.4 / 4.87	Lifemark Health 2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	GEN

Generator No: ON5232397
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 P
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	17 of 18	W/57.0	237.4 / 4.87	Lifemark Health 2 Fisherman Drive, Unit 7 Brampton ON L7A1B5	GEN

Generator No: ON5232397
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 P
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	18 of 18	W/57.0	237.4 / 4.87	Stephenson's Rental Services Inc. Brampton 109 2 Fisherman Drive Unit 17 Brampton ON L7A 1B5	GEN

Generator No: ON4592837
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 253 L
Waste Class Name: EMULSIFIED OILS

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

---

34 | ***1 of 1*** | ***ESE/63.0*** | ***237.3 / 4.85*** | ***Enbridge Gas Inc.***
76 Blackthorn Lane
Brampton ON | ***SPL***

Ref No: 2882-BJGVPB
Year:
Incident Dt: 2019/12/02
Dt MOE Arvl on Scn:
MOE Reported Dt: 2019/12/02
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: half inch plastic IP line<UNOFFICIAL>
Site Address: 76 Blackthorn Lane
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name: Enbridge Gas Inc.
Client Type: Corporation
Source Type: Pipeline/Components
Contaminant Code: 35

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Contaminant Name:	NATURAL GAS (METHANE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	1075
Receiving Medium:	Air
Incident Reason:	Operator/Human Error
Incident Summary:	TSSA FSB - Spill - half inch plastic IP line hit by homeowner
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Unknown / N/A
SAC Action Class:	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:	

---

35 | ***1 of 1*** | ***WNW/62.3*** | ***238.0 / 5.53*** | ***Belfor Property Restoration*** ***10545 Hurontario Street*** ***Brampton ON L6Z 2V9*** | ***GEN***

Generator No:	ON3633461
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

---

36 | ***1 of 13*** | ***WNW/77.5*** | ***233.2 / 0.69*** | ***PETRO CANADA*** ***5 SANDALWOOD PKY W*** ***BRAMPTON ON L7A 1J6*** | ***RST***

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:	
List Name:	
Description:	

---

36 | ***2 of 13*** | ***WNW/77.5*** | ***233.2 / 0.69*** | ***PAUL PAUAO*** ***5 SANDALWOOD PKWY W*** ***BRAMPTON ON L7A 1J6*** | ***FSTH***

License Issue Date:	7/3/2007
Tank Status:	Licensed
Tank Status As Of:	August 2007
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	1997
Corrosion Protection:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

36	3 of 13	WNW/77.5	233.2 / 0.69	PAUL PAUAO 5 SANDALWOOD PKWY W BRAMPTON ON L7A 1J6	FSTH

License Issue Date: 7/3/2007 3:18:00 PM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

36	4 of 13	WNW/77.5	233.2 / 0.69	SUNCOR ENERGY PRODUCTS PARTNERSHIP 5 SANDALWOOD PKY W BRAMPTON ON	FST

Inventory No: 64198949
Inventory Status: active
Installation Year: 1997
Capacity: 35000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

36	5 of 13	WNW/77.5	233.2 / 0.69	SUNCOR ENERGY PRODUCTS PARTNERSHIP	FST

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				5 SANDALWOOD PKY W BRAMPTON ON	

Inventory No:	11494060	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1997	**Overfill Protection:**	
Capacity:	35000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	6 of 13	WNW/77.5	233.2 / 0.69	SUNCOR ENERGY PRODUCTS PARTNERSHIP 5 SANDALWOOD PKY W BRAMPTON ON	FST

Inventory No:	11494017	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1997	**Overfill Protection:**	
Capacity:	35000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBSSupreme		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	7 of 13	WNW/77.5	233.2 / 0.69	SUNCOR ENERGY PRODUCTS PARTNERSHIP 5 SANDALWOOD PKY W BRAMPTON ON	FST

Inventory No:	11494039	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1997	**Overfill Protection:**	
Capacity:	35000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBSMid		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	8 of 13	WNW/77.5	233.2 / 0.69	PETRO CANADA 5 SANDALWOOD PKY W BRAMPTON ON L7A1J6	RST

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone:	9058467880
List Name:	INFO-DIRECT(TM) BUSINESS FILE
Description:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
36	9 of 13	WNW/77.5	233.2 / 0.69	Petro Canada Retail Fuel Facility<UNOFFICIAL> 5 Sandalwood Parkway Brampton ON	SPL

Ref No:	8277-ABB8RA	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2016/06/27	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	

MOE Reported Dt:	2016/06/27	**Impact to Health:**	
Dt Document Closed:	2016/08/04	**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:	10-30 metres eg. Medium Quality GPS		
Site District Office:			
Nearest Watercourse:			
Site Name:	Gas Station<UNOFFICIAL>		
Site Address:	5 Sandalwood Parkway		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4841147		
Easting:	596408		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	100 L		
System Facility Address:			
Client Name:	Petro Canada Retail Fuel Facility<UNOFFICIAL>		
Client Type:			
Source Type:			
Contaminant Code:	12		
Contaminant Name:	GASOLINE		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Incident Reason:	Operator/Human Error		
Incident Summary:	Petro Canada Gas station: 100 L gasoline to grd and cb		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Unknown / N/A		
SAC Action Class:	Land Spills		
Call Report Locatn Geodata:			

---

36 | ***10 of 13*** | ***WNW/77.5*** | ***233.2 / 0.69*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP***
5 SANDALWOOD PKY W
BRAMPTON ON | ***INC***

Incident No:	1894002	**Any Health Impact:**	No
Incident ID:		**Any Enviro Impact:**	No
Instance No:	10188831	**Service Intrp:**	No
Status Code:		**Was Prop Damaged:**	No
Incident Status:	Causal Analysis Complete	**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:	6228765	**Indus App. Type:**	
Attribute Category:	FS-Incident	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	
Date of Occurrence:	6/27/2016	**Operation Pressure:**	
Time of Occurrence:	NULL	**Equipment Type:**	
Occr Insp Start Dt:	2016/07/05 00:00:00	**Equipment Model:**	
Incident Creat On:	6/28/2016	**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	

Fuels Occur Type:	Liquid Petroleum Spill	***Contam. Migrated:***	
Occur Type Rpt:	Liquid Petroleum Spill	***Near Body of Water:***	
Occur Category:		***Drainage System:***	
Fuel Type Involved:	Gasoline	***Sub Surface Contam:***	
Fuel Type Reported:	Transportation Fuel	***Tank Material Type:***	
Enforcement Policy:		***Tank Storage Type:***	
Prc Escalation Req:		***Tank Location Type:***	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	5 SANDALWOOD PKY W		
Invent Postal Code:	L7A 1J6		
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:	driver drove off with nozzle in car tank		
Operation Type Involved:	Retail Fuel Station (FS, SS, Multifunctional)		

36	***11 of 13***	***WNW/77.5***	***233.2 / 0.69***	***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** ***5 SANDALWOOD PKWY W,,BRAMPTON,ON,L7A 1J6,CA*** ***ON***	***INC***

Incident No:	1894002	***Any Health Impact:***	
Incident ID:		***Any Enviro Impact:***	
Instance No:		***Service Intrp:***	
Status Code:		***Was Prop Damaged:***	
Incident Status:		***Reside App. Type:***	
Incident Severity:		***Commer App. Type:***	
Task No:		***Indus App. Type:***	
Attribute Category:	FS-Incident	***Institut App. Type:***	
Context:		***Depth Ground Cover:***	
Date of Occurrence:	6/28/2016	***Operation Pressure:***	
Time of Occurrence:		***Equipment Type:***	
Occr Insp Start Dt:		***Equipment Model:***	
Incident Creat On:		***Serial No:***	
Instance Creat Dt:		***Cylinder Capacity:***	
Instance Install Dt:		***Cylinder Cap Units:***	
Approx Quant Rel:		***Cylinder Mat Type:***	
Tank Capacity:		***Pump Flow Rate Cap:***	
Fuels Occur Type:		***Contam. Migrated:***	
Occur Type Rpt:		***Near Body of Water:***	
Occur Category:		***Drainage System:***	
Fuel Type Involved:		***Sub Surface Contam:***	
Fuel Type Reported:		***Tank Material Type:***	
Enforcement Policy:		***Tank Storage Type:***	
Prc Escalation Req:		***Tank Location Type:***	
Item:	FS GASOLINE STATION - SELF SERVE		
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			

Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 5 SANDALWOOD PKWY W,,BRAMPTON,ON,L7A 1J6,CA
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative:
Operation Type Involved:

---

36 | ***12 of 13*** | ***WNW/77.5*** | ***233.2 / 0.69*** | ***5 Sandlewood Pkwy W, Brampton BRAMPTON ON*** | ***SPL***

Ref No: 1-1MG4MV
Year:
Incident Dt: 2/19/2022 6:50:00 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/19/2022 8:56:14 AM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 5 Sandlewood Pkwy W, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Line Strike
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name: ENBRIDGE CONSUMERS GAS
Client Type: Private Business
Source Type: Pipeline/Components
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Incident Reason: Human error (Specify)
Incident Summary: TSSA/Enbridge: gas supply line damaged at Petro Canada carwash
Activity Preceding Spill: Maintenance
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HB - Credit - 16 Mile

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Sector Type: NATURAL GAS DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001472173"],"wkts":["POINT (-79.8031788000 43.7170549000)"],"creation_date":"2022-02-19"}

---

36 | **13 of 13** | **WNW/77.5** | **233.2 / 0.69** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
5 SANDALWOOD PKY W
BRAMPTON ON | **FST**

Inventory No: 10188831
Inventory Status: Active
Installation Year:
Capacity: 140000
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

---

37 | **1 of 3** | **WNW/9.8** | **234.1 / 1.66** | **DOUG CHALMERS INC.**
ETOBICOKE CREEK
HURONTARIO/SANDALWOOD PARKWAY
BRAMPTON STORAGE DEPOT HIGHWAY 10
BRAMPTON CITY ON | **SPL**

Ref No: 65828
Year:
Incident Dt: 1/5/1992
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/5/1992
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: ABOVE-GROUND TANK LEAK
Incident Preceding Spill:
Environment Impact: CONFIRMED
Health Env Consequence:
Nature of Impact: Multi-media Pollution
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: PEEL R.M.

Receiving Medium: WATER
Incident Reason: VANDALISM
Incident Summary: CHALMERS FUELS: 600 L DIESEL FUEL TO CREEK
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

37 | **2 of 3** | **WNW/9.8** | **234.1 / 1.66** | **Canada Drayage<UNOFFICIAL>**
HWY 10 & SANDALWOOD PKWY<UNOFFICIAL>
Brampton ON | **SPL**

Ref No: 7120-5HYLWJ
Year:
Incident Dt: 1/20/2003
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/20/2003
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: HWY 10 & SANDALWOOD PKWY<UNOFFICIAL>
Site Address:
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Environment Impact: Possible
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 300 L
System Facility Address:
Client Name: Canada Drayage<UNOFFICIAL>
Client Type:
Source Type:
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason: Adverse Road Condition - Road faults
Incident Summary: Canada Drayage Inc.- 300 L diesel to rd, cleang.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Oil
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
37	3 of 3	WNW/9.8	234.1 / 1.66	Sandalwood and Hurontario Brampton ON	SPL

Ref No:	6222-ALRS4T	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	4/25/2017	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/25/2017	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Intersection<UNOFFICIAL>		
Site Address:	Sandalwood and Hurontario		
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4841232.34		
Easting:	596413.68		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	50 L		
System Facility Address:			
Client Name:			
Client Type:			
Source Type:	Motor Vehicle		
Contaminant Code:	15		
Contaminant Name:	HYDRAULIC OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	n/a		
Receiving Medium:	Land		
Incident Reason:	Equipment Failure		
Incident Summary:	Emterra - hydraulic fluid leak. ****Duplicate report -7022-ALRP89****		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Miscellaneous Communal		
SAC Action Class:			
Call Report Locatn Geodata:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	1 of 1	ESE/63.6	234.9 / 2.37	The Regional Municipality of Peel 78 Skegby Rd Brampton ON L6V 2T9	SPL

Ref No:	1708-BJMTLN	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2019/12/07	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2019/12/07	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2019/12/14	**Agency Involved:**	
Site No:	4360-BJPGWG		
MOE Response:	No		
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:	NA		

Site District Office:	Halton-Peel
Nearest Watercourse:	Etobicoke Creek
Site Name:	78 Skegby Road
Site Address:	78 Skegby Rd
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	NA
Site Geo Ref Accu:	NA
Site Map Datum:	NA
Northing:	NA
Easting:	NA
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	The Regional Municipality of Peel
Client Type:	Municipal Government
Source Type:	Water Supply
Contaminant Code:	43
Contaminant Name:	SEDIMENT(SUSPENDED SOLIDS/ SAND/ SILT)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Surface Water
Incident Reason:	Equipment Failure
Incident Summary:	Peel watermain break silt to Etobicoke Creek
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

39	1 of 1	ESE/78.5	233.9 / 1.45	338 Hansen Road North, Brampton BRAMPTON ON	SPL

Ref No:	1-H0GXY	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	5/30/2021 1:01:53 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	5/30/2021 2:54:51 PM	**Impact to Health:**	0 No Impact
Dt Document Closed:	8/7/2021 12:18:32 PM	**Agency Involved:**	
Site No:			

MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	
Site Address:	338 Hansen Road North, Brampton
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Line Strike

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see notes
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	Pipeline/Components
Contaminant Code:	
Contaminant Name:	METHANE GAS
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Incident Reason:	Human error (Specify)
Incident Summary:	FSB: 0.5" plastic IP line strike, made safe & repaired.
Activity Preceding Spill:	Construction or repair
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HC-Humber - Don
Sector Type:	NATURAL GAS DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001938978"],"wkts":["POINT (-79.7640493000 43.7077697000)"],"creation_date":"2021-05-30"}

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	1 of 10	WNW/89.2	239.7 / 7.22	CAT SEE & USE ON0007801 CATERPILLAR 100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	GEN

Generator No:	ON0007301
SIC Code:	0009
SIC Description:	*** ERROR RECORD ***
Approval Years:	92,93
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	2 of 10	WNW/89.2	239.7 / 7.22	CATERPILLAR OF CANADA LTD. 100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	GEN

Generator No:	ON0007801
SIC Code:	3192
SIC Description:	CONSTRTUCTION EQUIP.
Approval Years:	86,87,88,89,90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	3 of 10	WNW/89.2	239.7 / 7.22	CATERPILLAR OF CANADA LTD. 09-075 100 SANDALWOOD PKWY. P.O. BOX 5000 BRAMPTON ON L6V 3Y4	GEN

Generator No: ON0007801
SIC Code: 3192
SIC Description: CONSTRTUCTION EQUIP.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	4 of 10	WNW/89.2	239.7 / 7.22	CATERPILLAR OF CANADA LIMITED 100 SANDALWOOD PARKWAY BRAMPTON ON L6V 3Y4	GEN

Generator No: ON0007801
SIC Code: 3192
SIC Description: CONSTRTUCTION EQUIP.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

40 | **5 of 10** | **WNW/89.2** | **239.7 / 7.22** | **Exel Canada Ltd.**
100 Sandalwood Parkway West.
Brampton ON L7A 1A8 | **GEN**

Generator No: ON4431280
SIC Code:
SIC Description:
Approval Years: 03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

40 | **6 of 10** | **WNW/89.2** | **239.7 / 7.22** | **Orlando Corporation**
100 Sandalwood Drive
Brampton ON L7A 1A8 | **GEN**

Generator No: ON6093269
SIC Code: 531111
SIC Description: Lessors of Residential Buildings and Dwellings (except Social Housing Projects)
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

40 | **7 of 10** | **WNW/89.2** | **239.7 / 7.22** | **CATERPILLAR OF CANADA LTD**
100 SANDALWOOD PKWY CORNER OF HWY 1O
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No: 10017073
Status: EXPIRED
Instance ID: 10337
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:
Description: Fuels Safety Private Fuel Outlet - Self Serve
Original Source: EXP
Record Date: Up to Mar 2012

---

40 | ***8 of 10*** | ***WNW/89.2*** | ***239.7 / 7.22*** | ***Exel Logistics-Canada Inc***
100 Sanalwood parkway
Brampton ON | ***GEN***

Generator No: ON8141743
SIC Code: 493190
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

40 | ***9 of 10*** | ***WNW/89.2*** | ***239.7 / 7.22*** | ***KELLOGG'S***
100 SANDALWOOD PARKWAY WEST
BRAMPTON ON L7A 1A8 | ***GEN***

Generator No: ON7972383
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	10 of 10	WNW/89.2	239.7 / 7.22	100 Sandalwood Pkwy W, Brampton BRAMPTON ON	SPL

Ref No:	1-CRUZE	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	4/20/2021 3:00:00 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/20/2021 6:25:54 AM	**Impact to Health:**	0 No Impact
Dt Document Closed:		**Agency Involved:**	

Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 100 Sandalwood Pkwy W, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 40 litre (L)
System Facility Address:
Client Name:
Client Type:
Source Type: Truck - Transport/Hauling
Contaminant Code:
Contaminant Name: MOTOR OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason: Human error (Specify)
Incident Summary: Canada Cartage: motor fluids from truck on soil
Activity Preceding Spill: Transportation
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HC-Humber - Don
Sector Type: GENERAL FREIGHT TRUCKING, LONG DISTANCE, TRUCK-LOAD
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001932431"],"wkts":["POINT (-79.8076113000 43.7181290000)"],"creation_date":"2021-04-20"}

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	1 of 1	ESE/76.5	232.9 / 0.37	Enbridge Energy Distribution Inc. 36 Skegsby Rd Brampton ON	SPL

Ref No:	7180-BHVR25	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11/13/2019	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/13/2019	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	

Site No: NA
MOE Response: No

Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Line strike <UNOFFICIAL>
Site Address:	36 Skegsby Rd
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	Enbridge Energy Distribution Inc.
Client Type:	Corporation
Source Type:	Pipeline/Components
Contaminant Code:	35
Contaminant Name:	NATURAL GAS (METHANE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	1075
Receiving Medium:	Air
Incident Reason:	Operator/Human Error
Incident Summary:	TSSA FSB: 1 1/4" pl IP main, made safe, Brampton
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	
Call Report Locatn Geodata:	

---

42 | ***1 of 1*** | ***WNW/97.3*** | ***239.9 / 7.37*** | ***Alectra Utilities Corporation***
17 Trewartha Cres
Brampton ON | ***SPL***

Ref No:	3468-BLAM47	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2020/01/29	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2020/01/29	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:		**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	spill<UNOFFICIAL>		
Site Address:	17 Trewartha Cres		
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4841561		

Easting:	596217
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	60 L
System Facility Address:	
Client Name:	Alectra Utilities Corporation
Client Type:	Corporation
Source Type:	Transformer
Contaminant Code:	26
Contaminant Name:	TRANSFORMER OIL (GT 50 PPM PCB)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	2315
Receiving Medium:	Land
Incident Reason:	Material Failure - Poor Design/Substandard Material
Incident Summary:	Alectra Utilities 60 L transformer oil spill cleaned
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	

---

43 | **1 of 1** | **ESE/24.6** | **231.5 / -0.94** | **111 Greene Dr. Brampton, ON. BRAMPTON ON** | **SPL**

Ref No:	1-13WCY1	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	8/18/2021 8:00:00 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/20/2021 8:33:19 AM	**Impact to Health:**	0 No Impact
Dt Document Closed:		**Agency Involved:**	
Site No:			

MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	
Site Address:	111 Greene Dr. Brampton, ON.
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	100 litre (L)
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	Transformer
Contaminant Code:	
Contaminant Name:	TRANSFORMER OIL (GT 50 PPM PCB)
Contaminant Limit 1:	

Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Equipment failure/malfunction
Incident Summary:	Alectra: 100L of PCB Oil to Vault and Grass
Activity Preceding Spill:	Normal operations
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HC-Humber - Don
Sector Type:	HYDRO-ELECTRIC POWER GENERATION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001946528"],"wkts":["POINT (-79.7610758000 43.7049911000)"],"creation_date":"2021-08-20"}

---

44 | **1 of 1** | **ESE/78.7** | **230.3 / -2.17** | **Enbridge Gas Distribution Inc.**
40 Greene Drive
Brampton ON L6V 2R7 | **SPL**

Ref No:	0422-8LVK7K	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/20/2011	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/20/2011	**Impact to Health:**	
Dt Document Closed:	10/6/2011	**Agency Involved:**	

Site No:	
MOE Response:	Not MOE mandate
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	Pipeline<UNOFFICIAL>
Site Address:	40 Greene Drive
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	Pipe Or Hose Leak
Incident Preceding Spill:	
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Air Pollution; Human Health/Safety
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	Enbridge Gas Distribution Inc.
Client Type:	
Source Type:	
Contaminant Code:	35
Contaminant Name:	NATURAL GAS (METHANE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	Other - Reason not otherwise defined
Incident Summary:	TSSAfsb- 1 1/4" Plastic Main Strike
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Pipeline
SAC Action Class:	TSSA - Fuel Safety Branch
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
45	1 of 1	ESE/41.4	229.9 / -2.63	Kennedy Road Tabernacle 141 Kennedy Road N Brampton ON L6V 1X9	GEN

Generator No: ON2423454
SIC Code: 813110
SIC Description: Religious Organizations
Approval Years: 04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
46	1 of 1	ESE/62.4	229.9 / -2.63	Terra HX Inc. 39 Greene Drive, Brampton BRAMPTON ON	SPL

Ref No: 1-2AK8MS
Year:
Incident Dt: 12/1/2022 6:45:15 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/1/2022 11:34:15 AM
Dt Document Closed: 12/28/2022 9:36:50 AM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name: Terra HX Inc.
Site Address: 39 Greene Drive, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Accident/Collision
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 150 litre (L)
System Facility Address: 717 SAFARI RD, HAMILTON, ON L8B 1S3
Client Name: ALECTRA UTILITIES CORPORATION
Client Type: Private Business
Source Type: Transformer
Contaminant Code:
Contaminant Name: MINERAL OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason: Human error (Specify)
Incident Summary: Alectra: 100-150L non-PCB mineral oil to transformer foundation; clnd_39 Greene Drive, Brampton
Activity Preceding Spill:
Property 2nd Watershed: 02H | Northern Lake Ontario and Niagara River

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Property Tertiary Watershed: 02HC | Humber River - Don River
Sector Type: ELECTRIC POWER DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001675178"],"wkts":["POINT (-79.7587014000 43.7036216000)"],"creation_date":"2022-12-01"}

---

47 | **1 of 23** | **ESE/42.3** | **229.9 / -2.63** | **PROVMAR FUELS INC.**
140 KENNEDY ROAD TANK TRUCK (CARGO)
BRAMPTON CITY ON | **SPL**

Ref No: 126181
Year:
Incident Dt: 5/10/1996
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/10/1996
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: ERROR
Incident Summary: PROVMAR-5 L GASOLINE TO LOT,HOSE NOT TIGHTENED ,CONTAINED,CLEANED-UP.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

---

47 | **2 of 23** | **ESE/42.3** | **229.9 / -2.63** | **BASHAR ENTERPRISES INC**
140 KENNEDY RD N
BRAMPTON ON L6V2N4 | **RST**

Headcode: 1186800

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9057969898
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	3 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM 140 KENNEDY RD N BRAMPTON ON L6V 2N4	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054537140
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	4 of 23	ESE/42.3	229.9 / -2.63	MANN MANJIT 140 KENNEDY RD N BRAMPTON ON L6V 2N4	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	5 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON L6V 2N4	FSTH

License Issue Date: 12/14/2001
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 13600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 13600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

---

47 | ***6 of 23*** | ***ESE/42.3*** | ***229.9 / -2.63*** | ***ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON L6V 2N4*** | ***FSTH***

License Issue Date: 12/14/2001
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 13600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1981
Corrosion Protection:
Capacity: 13600
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 2000
Corrosion Protection:
Capacity: 46400

Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline
Status:	Active
Year of Installation:	2000
Corrosion Protection:	
Capacity:	46400
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline
Status:	Active
Year of Installation:	2000
Corrosion Protection:	
Capacity:	46400
Tank Fuel Type:	Liquid Fuel Double Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	7 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10596968	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	28431	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	8 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10597089	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance ID:	28999	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

47	**9 of 23**	**ESE/42.3**	**229.9 / -2.63**	**ESSO MAXIMUM ATTN MANJIT MANN** **140 KENNEDY RD N** **BRAMPTON ON**	**DTNK**

Delisted Expired Fuel Safety Facilities

Instance No:	10596884	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29942	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Record Date:		Up to Mar 2012			

47	10 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10597057	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29875	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

47	11 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10597015	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	30183	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	

Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

47 | ***12 of 23*** | ***ESE/42.3*** | ***229.9 / -2.63*** | ***ESSO MAXIMUM ATTN MANJIT MANN***
140 KENNEDY RD N
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10596928
Status: EXPIRED
Instance ID: 30448
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

47 | ***13 of 23*** | ***ESE/42.3*** | ***229.9 / -2.63*** | ***MAC'S CONVENIENCE STORES INC.***
140 KENNEDY RD N
BRAMPTON ON | ***FST***

Inventory No: 11623928
Inventory Status: active
Installation Year: 2000
Capacity: 46400
Capacity Unit: L
Tank Type: Double Wall UST

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Manufacturer:
Model:
Description: 2009VBSPremium

---

47 | **14 of 23** | **ESE/42.3** | **229.9 / -2.63** | **MAC'S CONVENIENCE STORES INC.**
140 KENNEDY RD N
BRAMPTON ON | **FST**

Inventory No: 11623937
Inventory Status: active
Installation Year: 2000
Capacity: 46400
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

47 | **15 of 23** | **ESE/42.3** | **229.9 / -2.63** | **MAC'S CONVENIENCE STORES INC.**
140 KENNEDY RD N
BRAMPTON ON | **FST**

Inventory No: 11623943
Inventory Status: active
Installation Year: 2000
Capacity: 46400
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

47 | **16 of 23** | **ESE/42.3** | **229.9 / -2.63** | **MANN MANJIT**
140 KENNEDY RD N
BRAMPTON ON L6V2N4 | **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 9054537140
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

47 | **17 of 23** | **ESE/42.3** | **229.9 / -2.63** | **ESSO MAXIMUM ATTN MANJIT MANN**
140 KENNEDY RD N
BRAMPTON ON | **EXP**

Inventory No: 10596993
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	18 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	EXP

Inventory No: 10596951
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	19 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	EXP

Inventory No: 10597083
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 13600
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	20 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	EXP

Inventory No: 10596909
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS Premium
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	21 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	EXP

Inventory No: 10596862
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Diesel

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	22 of 23	ESE/42.3	229.9 / -2.63	ESSO MAXIMUM ATTN MANJIT MANN 140 KENNEDY RD N BRAMPTON ON	EXP

Inventory No: 10597038
Inventory Status: EXPIRED
Installation Year: 1981
Capacity: 13600
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	23 of 23	ESE/42.3	229.9 / -2.63	MAC'S CONVENIENCE STORES INC. 140 KENNEDY RD N BRAMPTON ON	FST

Inventory No: 9510615
Inventory Status: Active
Installation Year:
Capacity: 139200
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:
Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	1 of 1	ESE/19.3	229.3 / -3.23	PETRO-CANADA KENNEDY N & VODDEN BRAMPTON ON L6V 1X7	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	1 of 17	ESE/69.3	228.9 / -3.63	KENNEDY & VODDEN PETRO CANADA 121 KENNEDY RD N BRAMPTON ON L6V 1X7	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
49	2 of 17	ESE/69.3	228.9 / -3.63	PERFECT LUBE 121 KENNEDY RD N BRAMPTON ON L6V 1X7	RST

Headcode: 921430
Headcode Desc: Oil Changes & Lubrication Service
Phone: 9058665711
List Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:					

49	3 of 17	ESE/69.3	228.9 / -3.63	SIMCOE ENERGY & TECHNICAL SERVICES INC * 121 KENNEDY RD N BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10110608	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	12170	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Cylr Handling Facility		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

49	4 of 17	ESE/69.3	228.9 / -3.63	SUNCOR ENERGY PRODUCTS PARTNERSHIP 121 KENNEDY RD N BRAMPTON ON	FST

Inventory No:	14848354	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2003	**Overfill Protection:**	
Capacity:	50000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

49	5 of 17	ESE/69.3	228.9 / -3.63	SUNCOR ENERGY PRODUCTS PARTNERSHIP 121 KENNEDY RD N BRAMPTON ON	FST

Inventory No:	14848353	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Installation Year:	2003	**Overfill Protection:**	
Capacity:	50000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

49 | **6 of 17** | **ESE/69.3** | **228.9 / -3.63** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
121 KENNEDY RD N
BRAMPTON ON | **FST**

Inventory No:	14848355	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2003	**Overfill Protection:**	
Capacity:	50000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS Premium		

---

49 | **7 of 17** | **ESE/69.3** | **228.9 / -3.63** | **KENNEDY & VODDEN PETRO CANADA**
121 KENNEDY RD N
BRAMPTON ON L6V1X7 | **RST**

Headcode:	01186800
Headcode Desc:	SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone:	9054555115
List Name:	INFO-DIRECT(TM) BUSINESS FILE
Description:	

---

49 | **8 of 17** | **ESE/69.3** | **228.9 / -3.63** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
121 KENNEDY RD N
BRAMPTON ON | **FST**

Inventory No:	64661039	**Tank Material:**	Flex
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2014	**Overfill Protection:**	Gravity
Capacity:	35000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:			

---

49 | **9 of 17** | **ESE/69.3** | **228.9 / -3.63** | **Suncor Energy Products**
121 Kennedy Road N
Brampton ON L6V1X | **GEN**

Generator No:	ON5693930
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

49 | ***10 of 17*** | ***ESE/69.3*** | ***228.9 / -3.63*** | ***Suncor Energy Products Partnership***
121 Kennedy Road N
Brampton ON L6V1X | ***GEN***

Generator No: ON5693930
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 150 L
Waste Class Name: Inert organic wastes

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

49 | ***11 of 17*** | ***ESE/69.3*** | ***228.9 / -3.63*** | ***Suncor Energy Products Partnership***
121 Kennedy Road N
Brampton ON L6V1X | ***GEN***

Generator No: ON5693930
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 150 L
Waste Class Name: Inert organic wastes

---

49 **12 of 17** **ESE/69.3** **228.9 / -3.63** **Suncor Energy Products Partnership** **GEN**
121 Kennedy Road N
Brampton ON L6V1X

Generator No: ON5693930
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150 L
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

49 **13 of 17** **ESE/69.3** **228.9 / -3.63** **2124964 ONTARIO INC O/A PETRO-CANADA** **EXP**
121 KENNEDY RD N
BRAMPTON ON

Inventory No: 64052023
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 27277
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS - Assumed to be correct
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

49 **14 of 17** **ESE/69.3** **228.9 / -3.63** **2124964 ONTARIO INC O/A PETRO-CANADA** **EXP**
121 KENNEDY RD N
BRAMPTON ON

Inventory No: 64052025
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 36369
Capacity Unit:
Tank Type:
Manufacturer:
Model:

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: 2009VBS - Assumed to be correct
Previous Fuel Type: Gasoline

---

49 | **15 of 17** | **ESE/69.3** | **228.9 / -3.63** | **2124964 ONTARIO INC O/A PETRO-CANADA**
121 KENNEDY RD N
BRAMPTON ON | **EXP**

Inventory No: 64052022
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 36369
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS - Assumed to be correct
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

49 | **16 of 17** | **ESE/69.3** | **228.9 / -3.63** | **2124964 ONTARIO INC O/A PETRO-CANADA**
121 KENNEDY RD N
BRAMPTON ON | **EXP**

Inventory No: 64052024
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 36369
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS - Assumed to be correct
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

49 | **17 of 17** | **ESE/69.3** | **228.9 / -3.63** | **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
121 KENNEDY RD N
BRAMPTON ON | **FST**

Inventory No: 9815312
Inventory Status: Active
Installation Year:
Capacity: 185000
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

---

50 | **1 of 1** | **ESE/69.4** | **228.9 / -3.63** | **The Corporation of the City of Brampton**
225 Vodden St E
Brampton ON L6V 4M1 | **SPL**

Ref No: 2700-BQH5K2
Year:
Incident Dt: 2020/06/11
Dt MOE Arvl on Scn:
MOE Reported Dt: 2020/06/11
Dt Document Closed: 2020/11/27
Site No: 7165-BQHGB8
MOE Response: No

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	NA
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	225 Vodden Street East
Site Address:	225 Vodden St E
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	NA
Site Geo Ref Accu:	NA
Site Map Datum:	NA
Northing:	NA
Easting:	NA
Incident Cause:	
Incident Preceding Spill:	Overflow/Surcharge
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	1 other - see incident description
System Facility Address:	
Client Name:	The Corporation of the City of Brampton
Client Type:	Municipal Government
Source Type:	Sewer (Private or Municipal)
Contaminant Code:	44
Contaminant Name:	SEWAGE,PRIMARY UNCHLORINATED
Contaminant Limit 1:	
Contam Limit Freq 1:	n/a
Contaminant UN No 1:	n/a
Receiving Medium:	Land; Surface Water; Source Water Zone
Incident Reason:	Blockage
Incident Summary:	RoP: Private side surcharging manhole, cleared
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Municipal Sewage
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	1 of 22	ESE/89.9	228.9 / -3.63	PHARMA PLUS DRUGS LTD 227 VODDEN STREET BRAMPTON ON L6V 1N2	GEN

Generator No:	ON1553392
SIC Code:	6031
SIC Description:	PHARMACIES
Approval Years:	92,93,97
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	2 of 22	ESE/89.9	228.9 / -3.63	PHARMA PLUS DRUGS LTD. 31-751 227 VODDEN ST., BRAMPTON C/O 5935 AIRPORT ROAD #500 MISSISSAUGA ON L4V 1W5	GEN

Generator No: ON1553392
SIC Code: 6031
SIC Description: PHARMACIES
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	3 of 22	ESE/89.9	228.9 / -3.63	PHARMA PLUS DRUGMARTS LTD. 227 VODDEN STREET EAST BRAMPTON ON L6V 1N2	GEN

Generator No: ON1553392
SIC Code: 6031
SIC Description: PHARMACIES
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	4 of 22	ESE/89.9	228.9 / -3.63	GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD. FOOD BASICS #983 227 VODDEN STREET BRAMPTON ON L6V 1N2	GEN

Generator No: ON2392168
SIC Code: 6571
SIC Description: CAMERA/PHOTO. SUPPLY
Approval Years: 98,99,00,01
PO Box No:
Country:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

51 ***5 of 22*** ***ESE/89.9*** ***228.9 / -3.63*** ***PHARMA PLUS DRUGS LTD.***
227 VODDEN STREET EAST
BRAMPTON ON L6V 1N2 ***GEN***

Generator No: ON1553392
SIC Code: 6031
SIC Description: PHARMACIES
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

51 ***6 of 22*** ***ESE/89.9*** ***228.9 / -3.63*** ***Exquizeet Tattoo & Piercing Studio***
227 Vodden Street, Unit 30B
Brampton ON L6V 1N2 ***GEN***

Generator No: ON6206863
SIC Code: 446199, 812190
SIC Description: All Other Health and Personal Care Stores, Other Personal Care Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

51 ***7 of 22*** ***ESE/89.9*** ***228.9 / -3.63*** ***1723525 Ontario Inc.***
227 Vodden Street East Unit 30B ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON	

Generator No: ON6483305
SIC Code: 812190
SIC Description: Other Personal Care Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

51	8 of 22	ESE/89.9	228.9 / -3.63	**Exquizeet Tattoo & Piercing Studio** **227 Vodden Street, Unit 30B** **Brampton ON L6V 1N2**	GEN

Generator No: ON6206863
SIC Code: 446199, 812190
SIC Description: All Other Health and Personal Care Stores, Other Personal Care Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

51	9 of 22	ESE/89.9	228.9 / -3.63	**Exquizeet Tattoo & Piercing Studio** **227 Vodden Street, Unit 30B** **Brampton ON L6V 1N2**	GEN

Generator No: ON6206863
SIC Code: 446199, 812190
SIC Description: All Other Health and Personal Care Stores, Other Personal Care Services
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

51	10 of 22	ESE/89.9	228.9 / -3.63	**Exquizeet Tattoo & Piercing Studio** **227 Vodden Street, Unit 30B**	GEN

Brampton ON

Generator No: ON6206863
SIC Code: 446199, 812190
SIC Description: ALL OTHER HEALTH AND PERSONAL CARE STORES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

51 ***11 of 22*** ***ESE/89.9*** ***228.9 / -3.63*** ***227 VODDEN STREET EAST, BRAMPTON ON*** ***INC***

Incident No: 1775464
Incident ID:
Instance No:
Status Code:
Incident Status:
Incident Severity:
Task No: 5983563
Attribute Category: FS-Perform L1 Incident Insp
Context:
Date of Occurrence: 2015/12/18 00:00:00
Time of Occurrence: 00:00:00
Occr Insp Start Dt: 2015/12/22 00:00:00
Incident Creat On:
Instance Creat Dt:
Instance Install Dt:
Approx Quant Rel:
Tank Capacity:
Fuels Occur Type: Vapour Release
Occur Type Rpt:
Occur Category:
Fuel Type Involved: Natural Gas
Fuel Type Reported:
Enforcement Policy: NULL
Prc Escalation Req: NULL
Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 227 VODDEN STREET EAST, BRAMPTON - VAPOUR RELEASE

Any Health Impact: No
Any Enviro Impact: No
Service Intrp: Yes
Was Prop Damaged: No
Reside App. Type:
Commer App. Type:
Indus App. Type:
Institut App. Type:
Depth Ground Cover:
Operation Pressure:
Equipment Type:
Equipment Model:
Serial No:
Cylinder Capacity:
Cylinder Cap Units:
Cylinder Mat Type:
Pump Flow Rate Cap:
Contam. Migrated:
Near Body of Water:
Drainage System:
Sub Surface Contam:
Tank Material Type:
Tank Storage Type:
Tank Location Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: inducer motor installed wrong voltage
Operation Type Involved: Commercial (e.g. restaurant, business unit, etc)

---

51 | **12 of 22** | **ESE/89.9** | **228.9 / -3.63** | **Rexall Pharmacy Group Ltd.**
227 Vodden Street East
Brampton ON L6V 1N2 | **GEN**

Generator No: ON9569543
SIC Code: 446110
SIC Description: 446110
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Erik Botines
Choice of Contact: CO_ADMIN
Phone No Admin: 905-502-5965 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

51 | **13 of 22** | **ESE/89.9** | **228.9 / -3.63** | **Exquizeet Tattoo & Piercing Studio**
227 Vodden Street, Unit 30B
Brampton ON L6V 1N2 | **GEN**

Generator No: ON6206863
SIC Code: 446199, 812190
SIC Description: ALL OTHER HEALTH AND PERSONAL CARE STORES, 812190
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

51 | **14 of 22** | **ESE/89.9** | **228.9 / -3.63** | **Exquizeet Tattoo & Piercing Studio**
227 Vodden Street, Unit 30B
Brampton ON L6V 1N2 | **GEN**

Generator No: ON6206863
SIC Code: 446199, 812190
SIC Description: ALL OTHER HEALTH AND PERSONAL CARE STORES, 812190

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

51 | ***15 of 22*** | ***ESE/89.9*** | ***228.9 / -3.63*** | ***Pharma Plus Drugmarts Ltd***
227 Vodden Street East
Brampton ON L6V 1N2 | ***GEN***

Generator No: ON9569543
SIC Code: 446110
SIC Description: 446110
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Erik Botines
Choice of Contact: CO_ADMIN
Phone No Admin: 905-502-5965 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

51 | ***16 of 22*** | ***ESE/89.9*** | ***228.9 / -3.63*** | ***Exquizeet Tattoo & Piercing Studio***
227 Vodden Street, Unit 30B
Brampton ON L6V 1N2 | ***GEN***

Generator No: ON6206863
SIC Code: 446199, 812190
SIC Description: ALL OTHER HEALTH AND PERSONAL CARE STORES, 812190
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

51 | ***17 of 22*** | ***ESE/89.9*** | ***228.9 / -3.63*** | ***Pharma Plus Drugmarts Ltd***
227 Vodden Street East | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON L6V 1N2	

Generator No: ON9569543
SIC Code: 446110
SIC Description: 446110
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Aaron Schrama
Choice of Contact: CO_ADMIN
Phone No Admin: 905-502-5965 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	18 of 22	ESE/89.9	228.9 / -3.63	**Rexall Pharmacy Group Ltd.** **227 Vodden Street East** **Brampton ON L6V 1N2**	GEN

Generator No: ON9569543
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
51	19 of 22	ESE/89.9	228.9 / -3.63	**Exquizeet Tattoo & Piercing Studio** **227 Vodden Street, Unit 30B** **Brampton ON L6V 1N2**	GEN

Generator No: ON6206863
SIC Code:
SIC Description:
Approval Years: As of Jun 2017
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

51	20 of 22	ESE/89.9	228.9 / -3.63	**Rexall Pharmacy Group Ltd.** **227 Vodden Street East** **Brampton ON L6V 1N2**	GEN

Generator No: ON9569543
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

51	21 of 22	ESE/89.9	228.9 / -3.63	**Rexall Pharmacy Group Ltd.** **227 Vodden Street East** **Brampton ON L6V 1N2**	GEN

Generator No: ON9569543
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

51	22 of 22	ESE/89.9	228.9 / -3.63	**Rexall Pharmacy Group Ltd.** **227 Vodden Street East** **Brampton ON L6V 1N2**	GEN

Generator No: ON9569543
SIC Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	1 of 27	WNW/93.3	245.9 / 13.37	Essence Medical Esthetics 9-10886 Hurontario St. North Brampton ON L7A 3R9	GEN

Generator No: ON2671524
SIC Code: 621110, 621510
SIC Description: Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	2 of 27	WNW/93.3	245.9 / 13.37	Kutty/Suppal Prof Med Corp A7 10886 Hurontario Street, North Brampton, ON L7A 3R9	GEN

Generator No: ON9261054
SIC Code: 621499
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	3 of 27	WNW/93.3	245.9 / 13.37	Essence Medical Esthetics 9-10886 Hurontario St. North Brampton ON L7A 3R9	GEN

Generator No: ON2671524
SIC Code: 621110, 621510
SIC Description: Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	4 of 27	WNW/93.3	245.9 / 13.37	Kutty/Suppal Prof Med Corp A7 10886 Hurontario Street, North Brampton, ON L7A 3R9	GEN

Generator No: ON9261054
SIC Code: 621499
SIC Description: All Other Out-Patient Care Centres
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	5 of 27	WNW/93.3	245.9 / 13.37	Essence Medical Esthetics 9-10886 Hurontario St. North Brampton ON L7A 3R9	GEN

Generator No: ON2671524
SIC Code: 621110, 621510
SIC Description: Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

52 | **6 of 27** | **WNW/93.3** | **245.9 / 13.37** | **Kutty/Suppal Prof Med Corp**
A7 10886 Hurontario Street, North
Brampton, ON | **GEN**

Generator No: ON9261054
SIC Code: 621499
SIC Description: ALL OTHER OUT-PATIENT CARE CENTRES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

52 | **7 of 27** | **WNW/93.3** | **245.9 / 13.37** | **Essence Medical Esthetics**
9-10886 Hurontario St. North
Brampton ON | **GEN**

Generator No: ON2671524
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

52 | **8 of 27** | **WNW/93.3** | **245.9 / 13.37** | **Chopra Dentistry Professional**
10886 Hurontario St Unit A15
Brampton ON L7A3R9 | **GEN**

Generator No: ON3839920
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:

Co Admin: Jessica Heleno
Choice of Contact: CO_ADMIN
Phone No Admin: 905-840-4949 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

52 | ***9 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Kutty/Suppal Prof Med Corp***
A7 10886 Hurontario Street, North
Brampton ON L7A 3R9 | ***GEN***

Generator No: ON9261054
SIC Code: 621499
SIC Description: ALL OTHER OUT-PATIENT CARE CENTRES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Rohit Suppal
Choice of Contact: CO_ADMIN
Phone No Admin: 9054955200 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

52 | ***10 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Kutty/Suppal Prof Med Corp***
A7 10886 Hurontario Street, North
Brampton ON L7A 3R9 | ***GEN***

Generator No: ON9261054
SIC Code: 621499
SIC Description: ALL OTHER OUT-PATIENT CARE CENTRES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Rohit Suppal
Choice of Contact: CO_ADMIN
Phone No Admin: 9054955200 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

52 | ***11 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Essence Medical Esthetics***
9-10886 Hurontario St. North
Brampton ON L7A 3R9 | ***GEN***

Generator No: ON2671524
SIC Code: 621110, 621510

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	12 of 27	WNW/93.3	245.9 / 13.37	Chopra Dentistry Professional 10886 Hurontario St Unit A15 Brampton ON L7A3R9	GEN

Generator No: ON3839920
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Jessica Heleno
Choice of Contact: CO_ADMIN
Phone No Admin: 905-840-4949 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	13 of 27	WNW/93.3	245.9 / 13.37	Essence Medical Esthetics 9-10886 Hurontario St. North Brampton ON L7A 3R9	GEN

Generator No: ON2671524
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

52 | **14 of 27** | **WNW/93.3** | **245.9 / 13.37** | **Essence Medical Esthetics**
9-10886 Hurontario St. North
Brampton ON L7A 3R9 | **GEN**

Generator No: ON2671524
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

52 | **15 of 27** | **WNW/93.3** | **245.9 / 13.37** | **Kutty/Suppal Prof Med Corp**
A7 10886 Hurontario Street, North
Brampton, ON L7A 3R9 | **GEN**

Generator No: ON9261054
SIC Code: 621499
SIC Description: ALL OTHER OUT-PATIENT CARE CENTRES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Rohit Suppal
Choice of Contact: CO_ADMIN
Phone No Admin: 9054955200 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

52 | **16 of 27** | **WNW/93.3** | **245.9 / 13.37** | **Kutty/Suppal Prof Med Corp**
A7 10886 Hurontario Street, North
Brampton ON L7A 3R9 | **GEN**

Generator No: ON9261054
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

52 | ***17 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Chopra Dentistry Professional***
10886 Hurontario St Unit A15
Brampton ON L7A3R9 | ***GEN***

Generator No: ON3839920
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

52 | ***18 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Essence Medical Esthetics***
9-10886 Hurontario St. North
Brampton ON L7A 3R9 | ***GEN***

Generator No: ON2671524
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

52 | ***19 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Kutty/Suppal Prof Med Corp***
A7 10886 Hurontario Street, North
Brampton ON L7A 3R9 | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON9261054
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

52	*20 of 27*	*WNW/93.3*	*245.9 / 13.37*	***Chopra Dentistry Professional*** ***10886 Hurontario St Unit A15*** ***Brampton ON L7A3R9***	*GEN*

Generator No: ON3839920
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

52	*21 of 27*	*WNW/93.3*	*245.9 / 13.37*	***Essence Medical Esthetics*** ***9-10886 Hurontario St. North*** ***Brampton ON L7A 3R9***	*GEN*

Generator No: ON2671524
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
52	22 of 27	WNW/93.3	245.9 / 13.37	**Essence Medical Esthetics** **9-10886 Hurontario St. North** **Brampton ON L7A 3R9**	GEN
Generator No:		ON2671524			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
52	23 of 27	WNW/93.3	245.9 / 13.37	**Kutty/Suppal Prof Med Corp** **A7 10886 Hurontario Street, North** **Brampton ON L7A 3R9**	GEN
Generator No:		ON9261054			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
52	24 of 27	WNW/93.3	245.9 / 13.37	**Chopra Dentistry Professional** **10886 Hurontario St Unit A15** **Brampton ON L7A3R9**	GEN
Generator No:		ON3839920			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

52 | ***25 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Mulla/Suppal Prof Med Corp***
A7 10886 Hurontario St, North
Brampton ON L7A3R9 | ***GEN***

Generator No: ON9261054
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

52 | ***26 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Essence Medical Esthetics***
9-10886 Hurontario St. North
Brampton ON L7A 3R9 | ***GEN***

Generator No: ON2671524
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

52 | ***27 of 27*** | ***WNW/93.3*** | ***245.9 / 13.37*** | ***Chopra Dentistry Professional***
10886 Hurontario St Unit A15
Brampton ON L7A3R9 | ***GEN***

Generator No: ON3839920
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

53 | ***1 of 1*** | ***WNW/94.5*** | ***243.9 / 11.37*** | ***50 Settler Crescent, Brampton BRAMPTON ON*** | ***SPL***

Ref No: 1-HZY0T
Year:
Incident Dt: 6/13/2021 3:39:19 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/13/2021 3:39:22 PM
Dt Document Closed: 8/7/2021 1:33:13 PM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 50 Settler Crescent, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Line Strike
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see notes
System Facility Address:
Client Name: ENBRIDGE CONSUMERS GAS
Client Type: Private Business
Source Type: Valve/Fitting/Piping
Contaminant Code:
Contaminant Name: NATURAL GAS
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Incident Reason: Human error (Specify)
Incident Summary: TSSA FSB: 1/2" pl IP service damage, made safe
Activity Preceding Spill: Construction or repair
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Property Tertiary Watershed: 02HC-Humber - Don
Sector Type: NATURAL GAS DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001938134"],"wkts":["POINT (-79.8120112000 43.7256196000)"],"creation_date":"2021-06-13"}

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	1 of 20	WNW/75.8	244.6 / 12.12	San/Luca Bakery & Restaurant Inc. 23 Conservation Dr Brampton ON L6Z 4R3	SCT

Established: 1997
Plant Size (ft²):
Employment: 2

--Details--
Description: Rendering and Meat Processing from Carcasses
SIC/NAICS Code: 311614

Description: Retail Bakeries
SIC/NAICS Code: 311811

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	2 of 20	WNW/75.8	244.6 / 12.12	Heart Lake Veterinary Hospital Professional Corp 23 Conservation Drive # 6 Brampton ON L6Z 4R3	GEN

Generator No: ON1578181
SIC Code: 622111
SIC Description: General (except Paediatric) Hospitals
Approval Years: 05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	3 of 20	WNW/75.8	244.6 / 12.12	Heart Lake Veterinary Hospital Professional Corp 23 Conservation Drive # 6 Brampton ON L6Z 4R3	GEN

Generator No: ON1578181
SIC Code: 622111
SIC Description: General (except Paediatric) Hospitals
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

54	4 of 20	WNW/75.8	244.6 / 12.12	**Heart Lake Veterinary Hospital Professional Corp** **23 Conservation Drive # 6** **Brampton ON L6Z 4R3**	GEN

Generator No: ON1578181
SIC Code: 622111
SIC Description: General (except Paediatric) Hospitals
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

54	5 of 20	WNW/75.8	244.6 / 12.12	**Heart Lake Veterinary Hospital Professional Corp** **23 Conservation Drive # 6** **Brampton ON L6Z 4R3**	GEN

Generator No: ON1578181
SIC Code: 622111
SIC Description: General (except Paediatric) Hospitals
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

54 **6 of 20** **WNW/75.8** **244.6 / 12.12** **Cat Hospital of Brampton**
23 Conservation Drive, Unit 6
Brampton ON **GEN**

Generator No: ON5475509
SIC Code: 622111
SIC Description: General (except Paediatric) Hospitals
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

54 **7 of 20** **WNW/75.8** **244.6 / 12.12** **Cat Hospital of Brampton**
23 Conservation Drive, Unit 6
Brampton ON **GEN**

Generator No: ON5475509
SIC Code: 622111
SIC Description: GENERAL (EXCEPT PAEDIATRIC) HOSPITALS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

54 **8 of 20** **WNW/75.8** **244.6 / 12.12** **Michelle Omura Dentistry Professional Corporation**
23 Conservation Drive, Unit 4
Brampton ON L6Z 4R3 **GEN**

Generator No: ON5838410
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

54	9 of 20	WNW/75.8	244.6 / 12.12	***Michelle Omura Dentistry Professional Corporation*** ***23 Conservation Drive, Unit 4*** ***Brampton ON L6Z 4R3***	GEN

Generator No: ON5838410
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

54	10 of 20	WNW/75.8	244.6 / 12.12	***Cat Hospital of Brampton*** ***23 Conservation Drive, Unit 6*** ***Brampton ON L6Z 4R3***	GEN

Generator No: ON5475509
SIC Code: 622111
SIC Description: GENERAL (EXCEPT PAEDIATRIC) HOSPITALS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Nicolo Piscitelli
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-495-4228 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

54	11 of 20	WNW/75.8	244.6 / 12.12	***Cat Hospital of Brampton*** ***23 Conservation Drive, Unit 6***	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON L6Z 4R3	

Generator No: ON5475509
SIC Code: 622111
SIC Description: GENERAL (EXCEPT PAEDIATRIC) HOSPITALS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Nicolo Piscitelli
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-495-4228 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

54	12 of 20	WNW/75.8	244.6 / 12.12	**Cat Hospital of Brampton** **23 Conservation Drive, Unit 6** **Brampton ON L6Z 4R3**	GEN

Generator No: ON5475509
SIC Code: 622111
SIC Description: GENERAL (EXCEPT PAEDIATRIC) HOSPITALS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Nicolo Piscitelli
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-495-4228 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

54	13 of 20	WNW/75.8	244.6 / 12.12	**Cat Hospital of Brampton** **23 Conservation Drive, Unit 6** **Brampton ON L6Z 4R3**	GEN

Generator No: ON5475509
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	14 of 20	WNW/75.8	244.6 / 12.12	Michelle Omura Dentistry Professional Corporation 23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	GEN

Generator No: ON5838410
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	15 of 20	WNW/75.8	244.6 / 12.12	Michelle Omura Dentistry Professional Corporation 23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	GEN

Generator No: ON5838410
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	16 of 20	WNW/75.8	244.6 / 12.12	Cat Hospital of Brampton 23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	GEN

Generator No:	ON5475509
SIC Code:	
SIC Description:	
Approval Years:	As of Oct 2019
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	17 of 20	WNW/75.8	244.6 / 12.12	Cat Hospital of Brampton 23 Conservation Drive, Unit 6 Brampton ON L6Z 4R3	GEN

Generator No:	ON5475509
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312 P
Waste Class Name:	Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
54	18 of 20	WNW/75.8	244.6 / 12.12	Wang Dagenais Dentistry Professional Corporation 23 Conservation Drive, Unit 4 Brampton ON L6Z 4R3	GEN

Generator No:	ON5838410
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

54 | ***19 of 20*** | ***WNW/75.8*** | ***244.6 / 12.12*** | ***123 Dentist Inc. o/a iSmile Dental Centre (North)***
23 Conservation Drive, Unit 4
Brampton ON L6Z 4R3 | ***GEN***

Generator No: ON5838410
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264 L
Waste Class Name: PHOTOPROCESSING WASTES

---

54 | ***20 of 20*** | ***WNW/75.8*** | ***244.6 / 12.12*** | ***Cat Hospital of Brampton***
23 Conservation Drive, Unit 6
Brampton ON L6Z 4R3 | ***GEN***

Generator No: ON5475509
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

55 | ***1 of 1*** | ***ESE/42.2*** | ***226.4 / -6.08*** | ***2049078 ONTARIO INC.***
87 KENNEDY ROAD NORTH
BRAMPTON ON L6V 1X7 | ***GEN***

Generator No: ON7540811
SIC Code: 531111
SIC Description: Lessors of Residential Buildings and Dwellings (except Social Housing Projects)

Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

56 ***1 of 9*** ***WNW/61.8*** ***245.9 / 13.44*** ***ESSO SELF SERVE***
11005 HURONTARIO ST
BRAMPTON ON L6V 1A1 ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9817590
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 3/17/1993
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

56 ***2 of 9*** ***WNW/61.8*** ***245.9 / 13.44*** ***ESSO SELF SERVE***
11005 HURONTARIO ST
BRAMPTON ON ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10596185
Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29710	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

56	*3 of 9*	*WNW/61.8*	*245.9 / 13.44*	***ESSO SELF SERVE*** ***11005 HURONTARIO ST*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10596142	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29920	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Original Source: EXP
Record Date: Up to Mar 2012

---

56 | **4 of 9** | **WNW/61.8** | **245.9 / 13.44** | **ESSO SELF SERVE**
11005 HURONTARIO ST
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No: 10596226
Status: EXPIRED
Instance ID: 29910
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

56 | **5 of 9** | **WNW/61.8** | **245.9 / 13.44** | **ESSO SELF SERVE**
11005 HURONTARIO ST
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No: 10596274
Status: EXPIRED
Instance ID: 30431
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:

Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

56 ***6 of 9*** ***WNW/61.8*** ***245.9 / 13.44*** ***ESSO SELF SERVE*** ***EXP***
11005 HURONTARIO ST
BRAMPTON ON

Inventory No: 10596161
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: DRY ICED AND LOCKE
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

56 ***7 of 9*** ***WNW/61.8*** ***245.9 / 13.44*** ***ESSO SELF SERVE*** ***EXP***
11005 HURONTARIO ST
BRAMPTON ON

Inventory No: 10596114
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 45400
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: DRY ICED AND LOCKED
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

56 ***8 of 9*** ***WNW/61.8*** ***245.9 / 13.44*** ***ESSO SELF SERVE*** ***EXP***
11005 HURONTARIO ST
BRAMPTON ON

Inventory No: 10596207
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: DRY ICED AND LOCKED
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
56	9 of 9	WNW/61.8	245.9 / 13.44	ESSO SELF SERVE 11005 HURONTARIO ST BRAMPTON ON	EXP

Inventory No: 10596253
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 22700
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: DRY ICED AND LOCKED
Previous Fuel Type: Gasoline
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
57	1 of 1	WNW/94.7	245.0 / 12.52	Hydro One Brampton Networks Inc. 8 Hambley Court Brampton ON	SPL

Ref No: 4800-AJG49W
Year:
Incident Dt: 2/10/2017
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/10/2017
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Transformer oil spill<UNOFFICIAL>
Site Address: 8 Hambley Court
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Collision/Accident
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 125 L
System Facility Address:
Client Name: Hydro One Brampton Networks Inc.
Client Type:
Source Type:
Contaminant Code: 15
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason: Weather Conditions
Incident Summary: Brampton Hydro - 125L of Transformer oil (mineral) to ground, ctnd
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Electric Power Generation
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SAC Action Class: Land Spills
Call Report Locatn Geodata:

---

58 **1 of 4** **WNW/93.0** **248.9 / 16.37** **MAC'S CONVENIENCE STORES INC.** **FST**
230 WANLESS DR
BRAMPTON ON

Inventory No: 64593023
Inventory Status: active
Installation Year: 2013
Capacity: 75000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description:

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection: Alarm
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

58 **2 of 4** **WNW/93.0** **248.9 / 16.37** **MAC'S CONVENIENCE STORES INC.** **FST**
230 WANLESS DR
BRAMPTON ON

Inventory No: 64593024
Inventory Status: active
Installation Year: 2013
Capacity: 65000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: compartment 40kL premium; 25kL diesel

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection: Alarm
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

58 **3 of 4** **WNW/93.0** **248.9 / 16.37** **Peel Medical Centre** **GEN**
Unit 1- 230 Wanless Drive
Brampton ON L7A 0X1

Generator No: ON7666298
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

58 **4 of 4** **WNW/93.0** **248.9 / 16.37** **MAC'S CONVENIENCE STORES INC.** **FST**
230 WANLESS DR
BRAMPTON ON

Inventory No: 64593022
Inventory Status: Active

Tank Material:
Corrosion Protect:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Installation Year:		**Overfill Protection:**		
Capacity:	140000	**Inventory Context:**	Liquid Fuels	
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve	
Tank Type:				
Manufacturer:				
Model:				
Description:				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
59	1 of 1	WNW/2.5	249.9 / 17.37	**CONTRACTOR** **HWY 10 && PERTH ST (N.O.S.)** **BRAMPTON ON**	SPL

Ref No:	182189	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	6/14/2000	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	6/14/2000	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:	Other		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND/WATER		
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	CORNERSTONE LANDSCAPING - 25 L OF TRANSMISSION OIL TO RD. & SEWER.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
60	1 of 18	ESE/70.7	224.0 / -8.51	**PEEL BOARD OF EDUCATION** **CENTRAL PEEL S.S. 32 KENNEDY ROAD N.** **BRAMPTON ON L6V 1X4**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON0359804
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

60	*2 of 18*	*ESE/70.7*	*224.0 / -8.51*	***PEEL BOARD OF EDUCATION 30-189*** ***CENTRAL PEEL SECONDARY SCHOOL 32*** ***KENNEDY ROAD NORTH*** ***BRAMPTON ON L6V 1X4***	*GEN*

Generator No: ON0359804
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 92,93,94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

60 | **3 of 18** | **ESE/70.7** | **224.0 / -8.51** | **PEEL DISTRICT SCHOOL BOARD**
CENTRAL PEEL SECONDARY SCHOOL 32
KENNEDY ROAD NORTH
BRAMPTON ON L6V 1X4 | **GEN**

Generator No: ON0359804
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 97,98,99,00,01,02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

60 | **4 of 18** | **ESE/70.7** | **224.0 / -8.51** | **Peel District School Board**
32 Kennedy Road North
Brampton ON L6V 1X4 | **GEN**

Generator No: ON0359804
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
60	5 of 18	ESE/70.7	224.0 / -8.51	**Peel District School Board** **32 Kennedy Road North** **Brampton ON**	GEN

Generator No: ON0359804
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
60	6 of 18	ESE/70.7	224.0 / -8.51	**Peel District School Board** **32 Kennedy Road North**	GEN

Brampton ON

Generator No: ON0359804
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

60	7 of 18	ESE/70.7	224.0 / -8.51	**Peel District School Board** **32 Kennedy Road North** **Brampton ON**	GEN

Generator No: ON0359804
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

60 | **8 of 18** | **ESE/70.7** | **224.0 / -8.51** | **Peel District School Board**
32 Kennedy Road North
Brampton ON L6V 1X4 | **GEN**

Generator No: ON0359804
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

60 | **9 of 18** | **ESE/70.7** | **224.0 / -8.51** | **Peel District School Board**
32 Kennedy Road North
Brampton ON | **GEN**

Generator No: ON0359804
SIC Code: 611710
SIC Description: EDUCATIONAL SUPPORT SERVICES
Approval Years: 2013

PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

60	10 of 18	ESE/70.7	224.0 / -8.51	Peel District School Board 32 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0359804
SIC Code: 611710
SIC Description: EDUCATIONAL SUPPORT SERVICES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Michael Leung
Choice of Contact: CO_OFFICIAL
Phone No Admin: 9058901010 Ext.2451
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

60 | **11 of 18** | **ESE/70.7** | **224.0 / -8.51** | **Peel District School Board**
32 Kennedy Road North
Brampton ON L6V 1X4 | **GEN**

Generator No: ON0359804
SIC Code: 611710
SIC Description: EDUCATIONAL SUPPORT SERVICES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Eva Hate
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-890-1010 Ext.2762
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

60 | **12 of 18** | **ESE/70.7** | **224.0 / -8.51** | **Peel District School Board**
32 Kennedy Road North
Brampton ON L6V 1X4 | **GEN**

Generator No: ON0359804
SIC Code: 611710
SIC Description: EDUCATIONAL SUPPORT SERVICES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Eva Hate
Choice of Contact: CO_ADMIN
Phone No Admin: 905-890-1010 Ext.2424

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

60 | ***13 of 18*** | ***ESE/70.7*** | ***224.0 / -8.51*** | ***Peel District School Board Human Resources Support Services***
32 Kennedy Road North
Brampton ON L6V 1X4 | ***GEN***

Generator No: ON0359804
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

60 | **14 of 18** | **ESE/70.7** | **224.0 / -8.51** | **Peel District School Board**
32 Kennedy Road N
Brampton ON | **SPL**

Ref No: 8768-AREL2Q
Year:
Incident Dt: 9/18/2017
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/21/2017
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: spill site - drainage ditch<UNOFFICIAL>
Site Address: 32 Kennedy Road N
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839193
Easting: 600561
Incident Cause:
Incident Preceding Spill: Dumping
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 5 L
System Facility Address:
Client Name: Peel District School Board
Client Type: Other (Describe)
Source Type: Unknown / N/A
Contaminant Code: 27
Contaminant Name: SEALANT (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium: Land
Incident Reason: Unknown / N/A
Incident Summary: R of Peel: 5 L of road sealant to dry drainage ditch
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Municipal Sewage
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 - No Impact
Agency Involved:

---

60 | **15 of 18** | **ESE/70.7** | **224.0 / -8.51** | **Peel District School Board Human Resources Support Services**
32 Kennedy Road North
Brampton ON L6V 1X4 | **GEN**

Generator No: ON0359804
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

---

60 | **16 of 18** | **ESE/70.7** | **224.0 / -8.51** | **CENTRAL PEEL SECONDARY SCHOOL**
32 KENNEDY RD N
BRAMPTON ON | **INC**

Incident No: 2152246
Incident ID:
Instance No: 64764539
Status Code:
Incident Status: Causal Analysis Complete
Incident Severity:
Task No:
Attribute Category: FS-Incident
Context:
Date of Occurrence: 9/11/2017
Time of Occurrence:
Occr Insp Start Dt:
Incident Creat On: 9/11/2017
Instance Creat Dt:
Instance Install Dt:
Approx Quant Rel:
Tank Capacity:
Fuels Occur Type: Vapour Release
Occur Type Rpt: Vapour Release
Occur Category:
Fuel Type Involved: Natural Gas

Any Health Impact:
Any Enviro Impact:
Service Intrp:
Was Prop Damaged:
Reside App. Type:
Commer App. Type:
Indus App. Type:
Institut App. Type:
Depth Ground Cover:
Operation Pressure:
Equipment Type:
Equipment Model:
Serial No:
Cylinder Capacity:
Cylinder Cap Units:
Cylinder Mat Type:
Pump Flow Rate Cap:
Contam. Migrated:
Near Body of Water:
Drainage System:
Sub Surface Contam:

Fuel Type Reported: Heating Fuel
Enforcement Policy:
Prc Escalation Req:
Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 32 KENNEDY RD N
Invent Postal Code: L6V 1X4
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: Minor leak on three (3") inch flange gasket
Operation Type Involved: Institution (including hospital, school, govt building, etc.)

Tank Material Type:
Tank Storage Type:
Tank Location Type:

---

60 | **17 of 18** | **ESE/70.7** | **224.0 / -8.51** | **Peel District School Board Human Resources Support Services**
32 Kennedy Road North
Brampton ON L6V 1X4 | **GEN**

Generator No: ON0359804
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 T
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 R
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

---

60 | ***18 of 18*** | ***ESE/70.7*** | ***224.0 / -8.51*** | ***Peel District School Board Human Resources Support Services 32 Kennedy Road North Brampton ON L6V 1X4*** | ***GEN***

Generator No: ON0359804
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 T
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 148 T
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 264 L
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 148 R
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

---

61 | ***1 of 3*** | ***ESE/84.5*** | ***223.8 / -8.69*** | ***PEEL BOARD OF EDUCATION INDEC NORTH 30 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4*** | ***GEN***

Generator No: ON0359877
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

61 | ***2 of 3*** | ***ESE/84.5*** | ***223.8 / -8.69*** | ***PEEL DISTRICT SCHOOL BOARD***
INDEC NORTH 30 KENNEDY ROAD NORTH
BRAMPTON ON L6V 1X4 | ***GEN***

Generator No: ON0359877
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

61 | ***3 of 3*** | ***ESE/84.5*** | ***223.8 / -8.69*** | ***PEEL DISTRICT SCHOOL BOARD***
INDEC NORTH 30 Kennedy Road
BRAMPTON ON L6V 1X4 | ***GEN***

Generator No: ON0359877
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
62	1 of 1	ESE/80.0	224.5 / -8.02	Rosedale Dental Care 55 Kennedy Road North Brampton ON L6V 1X6	GEN

Generator No: ON9218788
SIC Code: 621210
SIC Description: Offices of Dentists
Approval Years: 06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
63	1 of 1	WNW/51.0	249.9 / 17.37	BELL CANADA 11450 HURONTARIO ST. BRAMPTON ON	CFOT

Inventory No: 61730168
Inventory Status: Active
Installation Year: 2000
Capacity: 5073
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Fuel Oil Tank
Inventory Item: FS FUEL OIL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
64	1 of 1	WNW/61.9	249.9 / 17.37	2041409 Ontario Ltd. 11482 Hurontario St Brampton ON L7A 1E6	SPL

Ref No: 8768-AHJNHD
Year:
Incident Dt: 1/12/2017
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/12/2017
Dt Document Closed:
Site No: 3187-AHKHXZ
MOE Response: No
Site County/District:
Site Geo Ref Meth: 1-10 metres eg. Good Quality GPS
Site District Office:
Nearest Watercourse:
Site Name: Tire Link Auto Sales
Site Address: 11482 Hurontario St
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu: GIS Software
Site Map Datum: NAD83
Northing: 4842466
Easting: 595054
Incident Cause:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Incident Preceding Spill:	Dumping
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	50 L
System Facility Address:	
Client Name:	2041409 Ontario Ltd.
Client Type:	
Source Type:	
Contaminant Code:	41
Contaminant Name:	SOAP/WATER MIXTURRE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Deliberate Act
Incident Summary:	Tire Link Complete Auto: Tidol 199 to Road Ditch, Contained & Cleaning
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	

---

65 | ***1 of 1*** | ***ESE/86.0*** | ***223.8 / -8.71*** | ***7 Charles Street Brampton ON*** | ***SPL***

Ref No:	7000-AT6KMX	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2017/11/16	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2017/11/16	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2017/11/25	**Agency Involved:**	

Site No:	NA
MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Residential<UNOFFICIAL>
Site Address:	7 Charles Street
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	Valve/Fitting/Piping
Contaminant Code:	35
Contaminant Name:	NATURAL GAS (METHANE)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	1075

Receiving Medium: Air
Incident Reason: Operator/Human Error
Incident Summary: TSSA FSB: 1/2" plastic IP service damaged; made safe
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:

---

66 | ***1 of 2*** | ***ESE/97.4*** | ***222.5 / -9.97*** | ***Elias Gessen Eastown<UNOFFICIAL>***
26 Kennedy Rd North
Brampton ON L6V 1X4 | ***SPL***

Ref No: 8156-7GQ46N
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/19/2008
Dt Document Closed: 9/23/2008
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: The New Asia Food Centre<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Discharges
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty:
System Facility Address:
Client Name: Elias Gessen Eastown<UNOFFICIAL>
Client Type:
Source Type:
Contaminant Code: 44
Contaminant Name: SEWAGE,RAW UNCHLORINATED
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason:
Incident Summary: New Asia Food Centre: sewage to storm sewer
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	2 of 2	ESE/97.4	222.5 / -9.97	IRVING GARTEN 16-26 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	GEN

Generator No: ON7709653
SIC Code: 541990
SIC Description: ALL OTHER PROFESSIONAL, SCIENTIFIC AND TECHNICAL SERVICES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	1 of 12	WNW/49.4	249.3 / 16.83	Snelgrove Verterinary Services 11526 Hurontaio St. Brampton ON L7A1E6	GEN

Generator No: ON8539200
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	2 of 12	WNW/49.4	249.3 / 16.83	Snelgrove Verterinary Services 11526 Hurontaio St. Brampton ON L7A1E6	GEN

Generator No: ON8539200
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

67	*3 of 12*	*WNW/49.4*	*249.3 / 16.83*	***Snelgrove Verterinary Services*** ***11526 Hurontaio St.*** ***Brampton ON L7A1E6***	***GEN***

Generator No: ON8539200
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

67	*4 of 12*	*WNW/49.4*	*249.3 / 16.83*	***Snelgrove Verterinary Services*** ***11526 Hurontaio St.*** ***Brampton ON L7A1E6***	***GEN***

Generator No: ON8539200
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

67	*5 of 12*	*WNW/49.4*	*249.3 / 16.83*	***Snelgrove Verterinary Services*** ***11526 Hurontaio St.***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON	

Generator No: ON8539200
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	6 of 12	WNW/49.4	249.3 / 16.83	**Snelgrove Verterinary Services** **11526 Hurontario St.** **Brampton ON L7A1E6**	GEN

Generator No: ON8539200
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Helen Kriksic
Choice of Contact: CO_ADMIN
Phone No Admin: 905-846-3316 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	7 of 12	WNW/49.4	249.3 / 16.83	**Snelgrove Verterinary Services** **11526 Hurontario St.** **Brampton ON L7A1E6**	GEN

Generator No: ON8539200
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Helen Kriksic
Choice of Contact: CO_ADMIN
Phone No Admin: 905-846-3316 Ext.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

67	8 of 12	WNW/49.4	249.3 / 16.83	**Snelgrove Verterinary Services** **11526 Hurontaio St.** **Brampton ON L7A1E6**	GEN

Generator No: ON8539200
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Helen Kriksic
Choice of Contact: CO_ADMIN
Phone No Admin: 905-846-3316 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

67	9 of 12	WNW/49.4	249.3 / 16.83	**Snelgrove Verterinary Services** **11526 Hurontario St.** **Brampton ON L7A1E6**	GEN

Generator No: ON8539200
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

67	10 of 12	WNW/49.4	249.3 / 16.83	**Snelgrove Verterinary Services** **11526 Hurontario St.** **Brampton ON L7A1E6**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON8539200
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

67	11 of 12	WNW/49.4	249.3 / 16.83	***Snelgrove Verterinary Services*** ***11526 Hurontario St.*** ***Brampton ON L7A1E6***	GEN

Generator No: ON8539200
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

67	12 of 12	WNW/49.4	249.3 / 16.83	***Snelgrove Verterinary Services*** ***11526 Hurontario St.*** ***Brampton ON L7A1E6***	GEN

Generator No: ON8539200
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	1 of 21	ESE/41.4	222.6 / -9.86	PARKINSON COACH LINES LTD. 10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 86,87,88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	2 of 21	ESE/41.4	222.6 / -9.86	PARKINSON COACH LINES LTD. 10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	3 of 21	ESE/41.4	222.6 / -9.86	PARKINSON COACH LINES LTD. 30-262 10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | ***4 of 21*** | ***ESE/41.4*** | ***222.6 / -9.86*** | ***PARKINSON COACH LINES LTD.***
10 KENNEDY ROAD NORTH
BRAMPTON ON L6V 1X4 | ***GEN***

Generator No: ON0823600
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | ***5 of 21*** | ***ESE/41.4*** | ***222.6 / -9.86*** | ***PARKINSON COACH LINES 2000 INC.***
10 KENNEDY ROAD NORTH
BRAMPTON ON L6V 1X4 | ***GEN***

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | ***6 of 21*** | ***ESE/41.4*** | ***222.6 / -9.86*** | ***PARKINSON COACH LINES GEORGE MURRAY***
10 KENNEDY RD N
BRAMPTON ON L6V 1X4 | ***FSTH***

License Issue Date: 4/22/1991
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Active
Year of Installation: 1982
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

68	7 of 21	ESE/41.4	222.6 / -9.86	PARKINSON COACH LINES GEORGE MURRAY 10 KENNEDY RD N BRAMPTON ON L6V 1X4	FSTH

License Issue Date: 4/22/1991
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1982
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

68	8 of 21	ESE/41.4	222.6 / -9.86	PARKINSON COACH LINES 2000 INC. 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 485410
SIC Description: School and Employee Bus Transportation
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

68	9 of 21	ESE/41.4	222.6 / -9.86	PARKINSON COACH LINES 2000 INC. 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 485410
SIC Description: School and Employee Bus Transportation
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | ***10 of 21*** | ***ESE/41.4*** | ***222.6 / -9.86*** | ***PARKINSON COACH & TOURS LTD.*** ***10 Kennedy Road North*** ***Brampton ON L6V 1X4*** | ***GEN***

Generator No: ON0823600
SIC Code: 485410
SIC Description: School and Employee Bus Transportation
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | ***11 of 21*** | ***ESE/41.4*** | ***222.6 / -9.86*** | ***PARKINSON COACH & TOURS LTD.*** ***10 Kennedy Road North*** ***Brampton ON L6V 1X4*** | ***GEN***

Generator No: ON0823600
SIC Code: 485410
SIC Description: School and Employee Bus Transportation
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | ***12 of 21*** | ***ESE/41.4*** | ***222.6 / -9.86*** | ***PARKINSON COACH & TOURS LTD.*** ***10 Kennedy Road North*** ***Brampton ON*** | ***GEN***

Generator No: ON0823600
SIC Code: 485410
SIC Description:
Approval Years: 2013
PO Box No:
Country:

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 ***13 of 21*** ***ESE/41.4*** ***222.6 / -9.86*** ***PARKINSON COACH & TOURS LTD.*** ***GEN***
10 Kennedy Road North
Brampton ON L6V 1X4

Generator No: ON0823600
SIC Code: 485410
SIC Description: 485410
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Lynn Matthews
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-451-4776 Ext.236
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

68 ***14 of 21*** ***ESE/41.4*** ***222.6 / -9.86*** ***PARKINSON COACH & TOURS LTD.*** ***GEN***
10 Kennedy Road North
Brampton ON L6V 1X4

Generator No: ON0823600
SIC Code: 485410
SIC Description: 485410
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Lynn Matthews
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-451-4776 Ext.236
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			

68	15 of 21	ESE/41.4	222.6 / -9.86	**PARKINSON COACH & TOURS LTD.** **10 Kennedy Road North** **Brampton ON L6V 1X4**	GEN

Generator No: ON0823600
SIC Code: 485410
SIC Description: 485410
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Lynn Matthews
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-451-4776 Ext.236
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

68	16 of 21	ESE/41.4	222.6 / -9.86	**PARKINSON COACH & TOURS LTD.** **10 Kennedy Road North** **Brampton ON L6V 1X4**	GEN

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

68	17 of 21	ESE/41.4	222.6 / -9.86	**PARKINSON COACH & TOURS LTD.** **10 Kennedy Road North** **Brampton ON L6V 1X4**	GEN

Generator No: ON0823600
SIC Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

68	*18 of 21*	*ESE/41.4*	*222.6 / -9.86*	***PARKINSON COACH & TOURS LTD.*** ***10 Kennedy Road North*** ***Brampton ON L6V 1X4***	***GEN***

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 221 I
Waste Class Name: Light fuels

68	*19 of 21*	*ESE/41.4*	*222.6 / -9.86*	***Parkinson Coach*** ***10 Kennedy Road North*** ***Brampton ON L6V 1X4***	***GEN***

Generator No: ON4707497
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

---

68 | ***20 of 21*** | ***ESE/41.4*** | ***222.6 / -9.86*** | ***PARKINSON COACH & TOURS LTD.***
10 Kennedy Road North
Brampton ON L6V 1X4 | ***GEN***

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

---

68 | ***21 of 21*** | ***ESE/41.4*** | ***222.6 / -9.86*** | ***PARKINSON COACH LINES GEORGE MURRAY***
10 KENNEDY RD N
BRAMPTON ON | ***EXP***

Inventory No: 10596490
Inventory Status: EXPIRED
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type:
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

69 | ***1 of 2*** | ***ESE/95.3*** | ***222.9 / -9.53*** | ***CANADA CUP INC***
228 QUEEN STREET EAST
BRAMPTON ON L7YA9 | ***NPCB***

Company Code: F1119
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Label:
Serial No.:
PCB Type/Code: Unknown concentration
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 800.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 1200.00 KG

Label:
Serial No.:
PCB Type/Code: Unknown concentration
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 3319.00 KG

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 6336.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 6800.00 KG

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
69	2 of 2	ESE/95.3	222.9 / -9.53	CANADA CUP INC 228 QUEEN ST E BRAMPTON ON L6V 1B8	NPCB

Company Code: F1025
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	1 of 4	ESE/77.0	222.8 / -9.64	SHELL CANADA PRODUCTS LTD. 230 QUEEN STREET EAST AT KENNEDY RD. SERVICE STATION BRAMPTON CITY ON L6V 1B8	SPL

Ref No: 23963
Year:
Incident Dt: 8/19/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/20/1989
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: WASTEWATER DISCHARGE TO WATERCOURSE
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: WATER
Incident Reason: UNKNOWN
Incident Summary: SHELL SERVICE STN. -GAS TRICKLING INTO STORM SEWER.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
70	2 of 4	ESE/77.0	222.8 / -9.64	SHELL CANADA PRODUCTS** 230 QUEEN ST E BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10072729
Status: EXPIRED

Expired Date:
Max Hazard Rank:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance ID:	11486	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	Fuels Safety Private Fuel Outlet - Self Serve		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

70	3 of 4	ESE/77.0	222.8 / -9.64	**SHELL CANADA PRODUCTS** **230 QUEEN ST E** **BRAMPTON ON**	EXP

Inventory No:	11247028	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Coating
Installation Year:	NULL	**Overfill Protection:**	
Capacity:	4500	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	WASTE OIL		
Previous Fuel Type:	Other		

70	4 of 4	ESE/77.0	222.8 / -9.64	**SHELL CANADA PRODUCTS** **230 QUEEN ST E** **BRAMPTON ON**	EXP

Inventory No:	11247006	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Coating
Installation Year:	NULL	**Overfill Protection:**	
Capacity:	4500	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	BULK OIL		
Previous Fuel Type:	Other		

71	1 of 1	ESE/9.5	222.4 / -10.03	**238 Queen St East** **Brampton ON**	SPL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	0601-BATLJQ	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	4/1/2016	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/1/2019	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	4/6/2019	**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Xalta Restaurant<UNOFFICIAL>		
Site Address:	238 Queen St East		
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4838884.31		
Easting:	600765.51		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	20 L		
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:	16		
Contaminant Name:	COOKING OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	n/a		
Receiving Medium:	Land		
Incident Reason:	Improper Storage		
Incident Summary:	PIR waste cooking oil from restaurant leaking to neighbouring property		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:	Pollution Incident Reports (PIRs) and "Other" calls		
Call Report Locatn Geodata:			

---

72 | **1 of 1** | **ESE/25.0** | **222.1 / -10.42** | **Brampton Transit<UNOFFICIAL>**
Queen and Kennedy, Brampton
Brampton ON | **SPL**

Ref No:	3888-BQ294F	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2020/05/28	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2020/05/28	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2020/06/09	**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Queen and Kennedy, Brampton<UNOFFICIAL>		

Site Address:	Queen and Kennedy, Brampton
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4838828.46
Easting:	600769.94
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	Brampton Transit<UNOFFICIAL>
Client Type:	
Source Type:	Other
Contaminant Code:	27
Contaminant Name:	COOLANT N.O.S.
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Land; Surface Water; Source Water Zone
Incident Reason:	Equipment Failure
Incident Summary:	Brampton Transit: Coolant spill from bus, 0.5L to CB
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Communal
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	1 of 11	ESE/50.6	220.9 / -11.60	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No:	ON7809968
SIC Code:	621110, 621510
SIC Description:	Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years:	2010
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	2 of 11	ESE/50.6	220.9 / -11.60	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No:	ON7809968
SIC Code:	621110, 621510

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

73 | ***3 of 11*** | ***ESE/50.6*** | ***220.9 / -11.60*** | ***AIM Health Group LTD***
2 Kennedy Rd S, unit 2
Brampton ON L6W 3E1 | ***GEN***

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

73 | ***4 of 11*** | ***ESE/50.6*** | ***220.9 / -11.60*** | ***AIM Health Group LTD***
2 Kennedy Rd S, unit 2
Brampton ON | ***GEN***

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	5 of 11	ESE/50.6	220.9 / -11.60	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	6 of 11	ESE/50.6	220.9 / -11.60	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
73	7 of 11	ESE/50.6	220.9 / -11.60	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

73 **8 of 11** **ESE/50.6** **220.9 / -11.60** **i6 Building Corp** **GEN**
2 Kennedy Road South
Brampton ON L6W 3E1

Generator No: ON8407811
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

73 **9 of 11** **ESE/50.6** **220.9 / -11.60** **i6 Building Corp** **GEN**
2 Kennedy Road South Unit4A
Brampton ON L6W 3E1

Generator No: ON8407811
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

73 **10 of 11** **ESE/50.6** **220.9 / -11.60** **i6 Building Corp** **GEN**
2 Kennedy Road South Unit4A
Brampton ON L6W 3E1

Generator No: ON8407811
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

73 | ***11 of 11*** | ***ESE/50.6*** | ***220.9 / -11.60*** | ***i6 Building Corp***
2 Kennedy Road South Unit4A
Brampton ON L6W 3E1 | ***GEN***

Generator No: ON8407811
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

74 | ***1 of 20*** | ***ESE/88.8*** | ***222.0 / -10.51*** | ***LECLAIR FUELS LTD.***
1 KENNEDY ROAD SOUTH CANADIAN TIRE
TANK TRUCK (CARGO)
BRAMPTON CITY ON | ***SPL***

Ref No: 18384
Year:
Incident Dt: 5/12/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/12/1989
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Incident Reason:	ERROR
Incident Summary:	TRANSPORT TRUCK- UNKNOWN QUANTITY DRIVEWAY SEALANTTO PARKING LOT.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	2 of 20	ESE/88.8	222.0 / -10.51	**Astra Fertility Group-Brampton** **1 Kennedy Road** **Brampton ON L6W 3C9**	GEN

Generator No:	ON7914316
SIC Code:	621410
SIC Description:	Family Planning Centres
Approval Years:	05,06,07,08
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	3 of 20	ESE/88.8	222.0 / -10.51	**2931621 CANADA INC O/A CANADIAN TIRE** **1 KENNEDY RD S** **BRAMPTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10271843	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	14973	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Cylinder Exchange
Original Source: EXP
Record Date: Up to Mar 2012

74	4 of 20	ESE/88.8	222.0 / -10.51	**Astra Fertility Group-Brampton** **1 Kennedy Road** **Brampton ON**	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: Family Planning Centres
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

74	5 of 20	ESE/88.8	222.0 / -10.51	**Astra Fertility Group-Brampton** **1 Kennedy Road** **Brampton ON**	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: Family Planning Centres
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	6 of 20	ESE/88.8	222.0 / -10.51	Astra Fertility Group-Brampton 1 Kennedy Road Brampton ON	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: Family Planning Centres
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	7 of 20	ESE/88.8	222.0 / -10.51	Astra Fertility Group-Brampton 1 Kennedy Road Brampton ON L6W 3C9	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: Family Planning Centres
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	8 of 20	ESE/88.8	222.0 / -10.51	Astra Fertility Group-Brampton 1 Kennedy Road Brampton ON	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

74 **9 of 20** **ESE/88.8** **222.0 / -10.51** **Dr Essam Michael Medicine Professional Corporation**
1 Kennedy Road
Brampton ON L6W 3C9
GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: 621410
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

74 **10 of 20** **ESE/88.8** **222.0 / -10.51** **Domenic Romano Pharmacy Inc.**
1 KENNEDY ROAD SOUTH
Brampton ON L6W 3C9
GEN

Generator No: ON9475030
SIC Code: 446110
SIC Description: 446110
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Nastran Najafi-Fard
Choice of Contact: CO_ADMIN
Phone No Admin: 416-493-1220 Ext.3218
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

74 **11 of 20** **ESE/88.8** **222.0 / -10.51** **Astra Fertility Group-Brampton**
1 Kennedy Road
Brampton ON L6W 3C9
GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: 621410
Approval Years: 2015
PO Box No:
Country: Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

74	12 of 20	ESE/88.8	222.0 / -10.51	**Domenic Romano Pharmacy Inc.** **1 KENNEDY ROAD SOUTH** **Brampton ON L6W 3C9**	GEN

Generator No: ON9475030
SIC Code: 446110
SIC Description: 446110
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Nastran Najafi-Fard
Choice of Contact: CO_ADMIN
Phone No Admin: 416-493-1220 Ext.3218
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

74	13 of 20	ESE/88.8	222.0 / -10.51	**Astra Fertility Group-Brampton** **1 Kennedy Road** **Brampton ON L6W 3C9**	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: 621410
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

74	14 of 20	ESE/88.8	222.0 / -10.51	**Domenic Romano Pharmacy Inc.** **1 KENNEDY ROAD SOUTH**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON L6W 3C9	

Generator No: ON9475030
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

74	15 of 20	ESE/88.8	222.0 / -10.51	**Dr Essam Michael Medicine Professional Corporation** **1 Kennedy Road** **Brampton ON L6W 3C9**	GEN

Generator No: ON7914316
SIC Code:
SIC Description:
Approval Years: As of Dec 2017
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

74	16 of 20	ESE/88.8	222.0 / -10.51	**Domenic Romano Pharmacy Inc.** **1 KENNEDY ROAD SOUTH** **Brampton ON L6W 3C9**	GEN

Generator No: ON9475030
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	17 of 20	ESE/88.8	222.0 / -10.51	Domenic Romano Pharmacy Inc. 1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	GEN

Generator No: ON9475030
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	18 of 20	ESE/88.8	222.0 / -10.51	Loblaw Companies Limited - Shoppers Drug Mart 1 Kennedy Rd S Brampton ON L6W 3C9	GEN

Generator No: ON2867886
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
74	19 of 20	ESE/88.8	222.0 / -10.51	Domenic Romano Pharmacy Inc. 1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	GEN

Generator No: ON9475030
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

74	20 of 20	ESE/88.8	222.0 / -10.51	Athletes Care Brampton 1 Kennedy Rd S Unit 12 Brampton ON L6W 3C9	GEN

Generator No: ON4123559
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

75	1 of 10	WNW/61.0	248.9 / 16.37	Dr. L. Corazza dentistry Proffessonal Corporation 11670 Hurontario Street, Unit 5 Brampton ON L7A 1E6	GEN

Generator No: ON5581707
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

75 **2 of 10** **WNW/61.0** **248.9 / 16.37** **Dr. L. Corazza dentistry Proffessonal Corporation**
11670 Hurontario Street, Unit 5
Brampton ON L7A 1E6
GEN

Generator No: ON5581707
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

75 **3 of 10** **WNW/61.0** **248.9 / 16.37** **Dr. L. Corazza dentistry Proffessonal Corporation**
11670 Hurontario Street, Unit 5
Brampton ON L7A 1E6
GEN

Generator No: ON5581707
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

75 **4 of 10** **WNW/61.0** **248.9 / 16.37** **2244603 Ont inc**
1-11670 Hurontario Street
Brampton ON L7A1R2
GEN

Generator No: ON5799788
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

75 | ***5 of 10*** | ***WNW/61.0*** | ***248.9 / 16.37*** | ***BRINKLEY PHARMACY***
11670 HURONTARIO Street
Brampton ON L7A 1R2 | ***GEN***

Generator No: ON9256528
SIC Code:
SIC Description:
Approval Years: As of Dec 2017
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

75 | ***6 of 10*** | ***WNW/61.0*** | ***248.9 / 16.37*** | ***Dr. L. Corazza dentistry Proffessonal Corporation***
11670 Hurontario Street, Unit 5
Brampton ON L7A 1E6 | ***GEN***

Generator No: ON5581707
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

75 | ***7 of 10*** | ***WNW/61.0*** | ***248.9 / 16.37*** | ***CBI Health***
1-11670 Hurontario Street
Brampton ON L7A1R2 | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON5799788
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

75	8 of 10	WNW/61.0	248.9 / 16.37	**CBI Health** **1-11670 Hurontario Street** **Brampton ON L7A1R2**	GEN

Generator No: ON5799788
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

75	9 of 10	WNW/61.0	248.9 / 16.37	**Dr. L. Corazza dentistry Proffessonal Corporation** **11670 Hurontario Street, Unit 5** **Brampton ON L7A 1E6**	GEN

Generator No: ON5581707
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		Pathological wastes			
75	10 of 10	WNW/61.0	248.9 / 16.37	**Dr. L. Corazza dentistry Proffessonal Corporation** **11670 Hurontario Street, Unit 5** **Brampton ON L7A 1E6**	GEN
Generator No:		ON5581707			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
76	1 of 4	ESE/28.0	221.5 / -11.01	**U.A.P. INC.** **144-5 KENNEDY RD.** **BRAMPTON ON L6W 3G4**	GEN
Generator No:		ON0204206			
SIC Code:		0000			
SIC Description:		*** NOT DEFINED ***			
Approval Years:		86,87			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
76	2 of 4	ESE/28.0	221.5 / -11.01	**U.A.P. INC.** **BRAMPTON #170 144-5 KENNEDY RD. S.** **BRAMPTON ON L6W 3G4**	GEN
Generator No:		ON0204206			
SIC Code:		3251			
SIC Description:		VEHICLE ENGINE IND.			
Approval Years:		88,89,90			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		122			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
76	3 of 4	ESE/28.0	221.5 / -11.01	U.A.P. INC. 39-227 BRAMPTON #170 144-5 KENNEDY RD. S. BRAMPTON ON L6W 3G4	GEN
Generator No:		ON0204206			
SIC Code:		3251			
SIC Description:		VEHICLE ENGINE IND.			
Approval Years:		94,95,96			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
76	4 of 4	ESE/28.0	221.5 / -11.01	UAP INC. 144-5 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	GEN
Generator No:		ON0204206			
SIC Code:		3251			
SIC Description:		VEHICLE ENGINE IND.			
Approval Years:		98,99,00,01			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
77	1 of 8	ESE/13.4	220.8 / -11.63	ALAGA ESSO 18 KENNEDY RD S BRAMPTON ON L6W 3E1	RST
Headcode:		1186800			
Headcode Desc:		Service Stations-Gasoline, Oil & Natural Gas			
Phone:		9054540170			
List Name:					
Description:					
77	2 of 8	ESE/13.4	220.8 / -11.63	MEL AND AUTO CENTRE INC 18 KENNEDY RD S BRAMPTON ON L6W 3E1	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9803663	***Expired Date:***	2/7/2001
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:		***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
77	3 of 8	ESE/13.4	220.8 / -11.63	MEL AND AUTO CENTRE INC 18 KENNEDY RD S BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11629965	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	95209	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

77 | ***4 of 8*** | ***ESE/13.4*** | ***220.8 / -11.63*** | ***MEL AND AUTO CENTRE INC***
18 KENNEDY RD S
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11603149
Status: EXPIRED
Instance ID: 93538
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

77 | ***5 of 8*** | ***ESE/13.4*** | ***220.8 / -11.63*** | ***MEL AND AUTO CENTRE INC***
18 KENNEDY RD S
BRAMPTON ON | ***EXP***

Inventory No: 11603116
Inventory Status: EXPIRED
Installation Year: 1980
Capacity: 50000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: AS PER REPORT E053559
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Sacrificial anode
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
77	6 of 8	ESE/13.4	220.8 / -11.63	MEL AND AUTO CENTRE INC 18 KENNEDY RD S BRAMPTON ON	EXP

Inventory No:	11603178	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	1980	**Overfill Protection:**	
Capacity:	25000	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	AS PER REPORT E053559		
Previous Fuel Type:	Diesel		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
77	7 of 8	ESE/13.4	220.8 / -11.63	MEL AND AUTO CENTRE INC 18 KENNEDY RD S BRAMPTON ON	EXP

Inventory No:	11603131	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	1980	**Overfill Protection:**	
Capacity:	50000	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	AS PER REPORT E053559		
Previous Fuel Type:	Gasoline		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
77	8 of 8	ESE/13.4	220.8 / -11.63	MEL AND AUTO CENTRE INC 18 KENNEDY RD S BRAMPTON ON	EXP

Inventory No:	11603164	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Sacrificial anode
Installation Year:	1980	**Overfill Protection:**	
Capacity:	25000	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	AS PER REPORT E053559		
Previous Fuel Type:	Diesel		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
78	1 of 2	WNW/91.7	248.9 / 16.37	Queen Square Family Health Team Queen Square Family Health Team 11692 Hurontario Street Main Street North Brampton ON L7A 1K5	GEN

Generator No:	ON7424588
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

78 | ***2 of 2*** | ***WNW/91.7*** | ***248.9 / 16.37*** | ***Queen Square Family Health Team Queen Square Family Health Team 11692 Hurontario Street Main Street North Brampton ON L7A 1K5*** | ***GEN***

Generator No: ON7424588
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

79 | ***1 of 7*** | ***ESE/47.3*** | ***220.8 / -11.63*** | ***Kennedy Dental and Orthodontics 49 Hillcrest Ave Suite 102 Brampton ON L6W4V4*** | ***GEN***

Generator No: ON9052125
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Hanane Harouche
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-453-2440 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

79 | ***2 of 7*** | ***ESE/47.3*** | ***220.8 / -11.63*** | ***Kennedy Dental and Orthodontics 49 Hillcrest Ave Suite 102 Brampton ON L6W4V4*** | ***GEN***

Generator No: ON9052125
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country: Canada
Status:
Co Admin: Hanane Harouche
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-453-2440 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	3 of 7	ESE/47.3	220.8 / -11.63	Kennedy Dental and Orthodontics 49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	GEN

Generator No: ON9052125
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	4 of 7	ESE/47.3	220.8 / -11.63	Kennedy Dental and Orthodontics 49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	GEN

Generator No: ON9052125
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
79	5 of 7	ESE/47.3	220.8 / -11.63	Kennedy Dental and Orthodontics 49 Hillcrest Ave Suite 102 Brampton ON L6W4V4	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON9052125
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

79 | ***6 of 7*** | ***ESE/47.3*** | ***220.8 / -11.63*** | ***Swift Clinics***
Swift Clinics 49 Hillcrest Avenue Unit 104
Brampton ON L6W 4V4 | ***GEN***

Generator No: ON9513855
SIC Code:
SIC Description:
Approval Years: As of Jul 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

79 | ***7 of 7*** | ***ESE/47.3*** | ***220.8 / -11.63*** | ***Kennedy Dental and Orthodontics***
49 Hillcrest Ave Suite 102
Brampton ON L6W4V4 | ***GEN***

Generator No: ON9052125
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	1 of 1	ESE/27.9	220.8 / -11.63	TRANSPORT TRUCK INTERSECTION AND CATCH BASIN AT KENNEDY RD AND EASTERN AVE TRANSPORT TRUCK (CARGO) BRAMPTON CITY ON	SPL

Ref No: 169155
Year:
Incident Dt: 6/19/1999
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/19/1999
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND / WATER
Incident Reason: ERROR
Incident Summary: MED TEC ENVIRONMENTAL: TOTE OF BIO-MEDICAL WASTE FALLEN ONTO ROAD.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: WORKS,FIRE DEPT

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	1 of 1	ESE/60.8	220.8 / -11.63	Maple Leaf Foods Inc. 33 Kennedy Road S Brampton ON	SPL

Ref No: 4423-8K5KNP
Year:
Incident Dt: 7/26/2011
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/26/2011

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:

Dt Document Closed:	9/8/2011	**Agency Involved:**	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Maple Leaf <UNOFFICIAL>		
Site Address:	33 Kennedy Road S		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	Other Transport Accident		
Incident Preceding Spill:			
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Surface Water Pollution		
Contaminant Qty:	50 L		
System Facility Address:			
Client Name:	Maple Leaf Foods Inc.		
Client Type:			
Source Type:			
Contaminant Code:	13		
Contaminant Name:	DIESEL FUEL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Incident Reason:	Other - Reason not otherwise defined		
Incident Summary:	Maple Leaf Foods: 50 L diesel to conc., cb.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Transport Truck		
SAC Action Class:	Watercourse Spills		
Call Report Locatn Geodata:			

82	1 of 4	ESE/97.1	219.8 / -12.63	**Alectra Utilities Corporation** **67 Eastern Ave** **Brampton ON L6W 1X9**	GEN

Generator No:	ON7036874
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251 L
Waste Class Name:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	2 of 4	ESE/97.1	219.8 / -12.63	Alectra Utilities Corporation 67 Eastern Ave Brampton ON L6W 1X9	GEN

Generator No: ON7036874
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	3 of 4	ESE/97.1	219.8 / -12.63	Alectra Utilities Corporation 67 Eastern Ave Brampton ON L6W 1X9	GEN

Generator No: ON7036874
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	4 of 4	ESE/97.1	219.8 / -12.63	Alectra Utilities Corporation 67 Eastern Ave Brampton ON L6W 1X9	GEN

Generator No: ON7036874
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

83 ***1 of 4*** ***ESE/19.8*** ***219.8 / -12.63*** ***QUEEN & KENNEDY CARWASH*** ***DTNK***
24 KENNEDY RD S
BRAMPTON ON L6W 3E2

Delisted Expired Fuel Safety Facilities

Instance No: 9983667
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 11/22/1996
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

83 ***2 of 4*** ***ESE/19.8*** ***219.8 / -12.63*** ***KENNEDY & EASTERN PROPANE*** ***DTNK***
24 KENNEDY RD S
BRAMPTON ON

Delisted Expired Fuel Safety Facilities

Instance No: 9650413
Status: EXPIRED
Instance ID: 392216
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:

Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Refill Cntr - Cylr Fill
Original Source: EXP
Record Date: Up to Mar 2012

83	*3 of 4*	*ESE/19.8*	*219.8 / -12.63*	***KENNEDY & EASTERN PROPANE*** ***24 KENNEDY RD S*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10596543 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 29914 ***Facility Location:***
Instance Type: FS Propane Tank ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

83	*4 of 4*	*ESE/19.8*	*219.8 / -12.63*	***KENNEDY & EASTERN PROPANE*** ***24 KENNEDY RD S*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facilities

Instance No:	11571368	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	91463	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Tank		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

84	***1 of 17***	***WNW/31.2***	***249.9 / 17.37***	***B & P AUTO CENTRE LTD 11865 HURONTARIO ST SNELGROVE BRAMPTON ON***	***FSTH***

License Issue Date:	5/29/2007
Tank Status:	Licensed
Tank Status As Of:	August 2007
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Full Serve

--Details--

Status:	Active
Year of Installation:	1975
Corrosion Protection:	
Capacity:	22730
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1975
Corrosion Protection:	
Capacity:	22730
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1975
Corrosion Protection:	
Capacity:	22730
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1975
Corrosion Protection:	

Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
84	2 of 17	WNW/31.2	249.9 / 17.37	SANTAK PIT STOP INC 11865 HURONTARIO ST BRAMPTON ON	FSTH

License Issue Date: 8/25/2008 10:45:00 AM
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Full Serve

--Details--

Status: Active
Year of Installation: 1975
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1975
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1975
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1975
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1995
Corrosion Protection:
Capacity: 45000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1995
Corrosion Protection:
Capacity: 45000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1995
Corrosion Protection:
Capacity: 45000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

Status: Active
Year of Installation: 1995
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
84	3 of 17	WNW/31.2	249.9 / 17.37	PETROLEUM PLUS GROUP INC 11865 HWY 10 SNELGROVE ON L0P 1M0	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9802156	**Expired Date:**	2/1/1991
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
84	4 of 17	WNW/31.2	249.9 / 17.37	1319911 ONTAIRO INC O/A DAVE'S GAS BAR VARIETY 11865 HURONTARIO ST BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10166223	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	12998	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Refill Cntr - Cylr Fill
Original Source: EXP
Record Date: Up to Mar 2012

84	5 of 17	WNW/31.2	249.9 / 17.37	SANTAK PIT STOP INC 11865 HURONTARIO ST BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10969661 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 57430 ***Facility Location:***
Instance Type: FS Piping ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

84	6 of 17	WNW/31.2	249.9 / 17.37	SANTAK PIT STOP INC 11865 HURONTARIO ST BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10969628 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance ID: 57375
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

84	***7 of 17***	***WNW/31.2***	***249.9 / 17.37***	***SANTAK PIT STOP INC*** ***11865 HURONTARIO ST*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10969622
Status: EXPIRED
Instance ID: 57616
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Record Date:		Up to Mar 2012			

84	8 of 17	WNW/31.2	249.9 / 17.37	SANTAK PIT STOP INC 11865 HURONTARIO ST BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10969643	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	57863	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

84	9 of 17	WNW/31.2	249.9 / 17.37	GURU KIRPA FUEL AND FOOD INC. 11865 HURONTARIO ST BRAMPTON ON	FST

Inventory No:	11388802	**Tank Material:**	Steel
Inventory Status:	active	**Corrosion Protect:**	Sacrificial Anode
Installation Year:	1995	**Overfill Protection:**	
Capacity:	45500	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

84	10 of 17	WNW/31.2	249.9 / 17.37	GURU KIRPA FUEL AND FOOD INC. 11865 HURONTARIO ST BRAMPTON ON	FST

Inventory No:	11388815	**Tank Material:**	Steel
Inventory Status:	active	**Corrosion Protect:**	Sacrificial Anode
Installation Year:	1995	**Overfill Protection:**	
Capacity:	25000	**Inventory Context:**	FS Liquid Fuel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS Premium		

---

84 **11 of 17** **WNW/31.2** **249.9 / 17.37**

GURU KIRPA FUEL AND FOOD INC.
11865 HURONTARIO ST
BRAMPTON ON

FST

Inventory No:	11388809	**Tank Material:**	Steel
Inventory Status:	active	**Corrosion Protect:**	Sacrificial Anode
Installation Year:	1995	**Overfill Protection:**	
Capacity:	45500	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

84 **12 of 17** **WNW/31.2** **249.9 / 17.37**

GURU KIRPA FUEL AND FOOD INC.
11865 HURONTARIO ST
BRAMPTON ON

FST

Inventory No:	11388793	**Tank Material:**	Steel
Inventory Status:	active	**Corrosion Protect:**	Sacrificial Anode
Installation Year:	1995	**Overfill Protection:**	
Capacity:	45500	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

---

84 **13 of 17** **WNW/31.2** **249.9 / 17.37**

SANTAK PIT STOP INC
11865 HURONTARIO ST
BRAMPTON ON

EXP

Inventory No:	10969667	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Impressed Current
Installation Year:	1975	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

---

84 **14 of 17** **WNW/31.2** **249.9 / 17.37**

SANTAK PIT STOP INC
11865 HURONTARIO ST
BRAMPTON ON

EXP

Inventory No:	10969613	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Impressed Current
Installation Year:	1975	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

---

84 | **15 of 17** | **WNW/31.2** | **249.9 / 17.37** | **SANTAK PIT STOP INC**
11865 HURONTARIO ST
BRAMPTON ON | **EXP**

Inventory No: 10969637
Inventory Status: EXPIRED
Installation Year: 1975
Capacity: 22730
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

84 | **16 of 17** | **WNW/31.2** | **249.9 / 17.37** | **SANTAK PIT STOP INC**
11865 HURONTARIO ST
BRAMPTON ON | **EXP**

Inventory No: 10969652
Inventory Status: EXPIRED
Installation Year: 1975
Capacity: 22730
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

84 | **17 of 17** | **WNW/31.2** | **249.9 / 17.37** | **GURU KIRPA FUEL AND FOOD INC.**
11865 HURONTARIO ST
BRAMPTON ON | **FST**

Inventory No: 9856576
Inventory Status: Active
Installation Year:
Capacity: 161500
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Full Serve

---

85 | **1 of 8** | **ESE/21.4** | **219.8 / -12.63** | **STEPHENSON'S RENT-ALL LTD.**
26 KENNEDY RD. S.
BRAMPTON ON L6W 3E2 | **GEN**

Generator No: ON0467614
SIC Code: 6359
SIC Description: OTHER VEH. REPAIR
Approval Years: 86,87,88
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

85 | ***2 of 8*** | ***ESE/21.4*** | ***219.8 / -12.63*** | ***STEPHENSON'S RENT-ALL LTD.***
26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR.
REXDALE ON L6W 3E2 | ***GEN***

Generator No: ON0467614
SIC Code: 9911
SIC Description: IND. MACH. RENTAL
Approval Years: 89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

85 | ***3 of 8*** | ***ESE/21.4*** | ***219.8 / -12.63*** | ***STEPHENSON'S RENT-ALL INC.***
26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR.
REXDALE ON L6W 3E2 | ***GEN***

Generator No: ON0467614
SIC Code: 9911
SIC Description: IND. MACH. RENTAL
Approval Years: 90
PO Box No:
Country:
Status:

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

85 | ***4 of 8*** | ***ESE/21.4*** | ***219.8 / -12.63*** | ***STEPHENSON'S RENT-ALL INC.***
26 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E2 | ***GEN***

Generator No: ON0467614
SIC Code: 9911
SIC Description: IND. MACH. RENTAL
Approval Years: 92,93,95,96,97,98,99,00
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

85 | ***5 of 8*** | ***ESE/21.4*** | ***219.8 / -12.63*** | ***STEPHENSON'S RENT-ALL INC. 36-583***
26 KENNEDY RD. SOUTH, BRAMPTON C/O 55 WESTMORE DR.
REXDALE ON L6W 3E2 | ***GEN***

Generator No: ON0467614

SIC Code: 9911
SIC Description: IND. MACH. RENTAL
Approval Years: 94
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

85 | ***6 of 8*** | ***ESE/21.4*** | ***219.8 / -12.63*** | ***STEPHEN(OUT OF BUSINESS)C. 26 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E2*** | ***GEN***

Generator No: ON0467614
SIC Code: 9911
SIC Description: IND. MACH. RENTAL
Approval Years: 01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
85	7 of 8	ESE/21.4	219.8 / -12.63	Stephenson's Rent-all (1998) Inc. 26 Kennedy Rd. South BRAMPTON ON L6W 3E2	GEN

Generator No:	ON0467614
SIC Code:	
SIC Description:	
Approval Years:	02,03,04
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
85	8 of 8	ESE/21.4	219.8 / -12.63	STEPHENSONS RENT ALL INC ATTN JOHN FLINT 26 KENNEDY RD S BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9663548	Expired Date:	
Status:	EXPIRED	Max Hazard Rank:	
Instance ID:	388283	Facility Location:	
Instance Type:	FS Facility	Facility Type:	
Instance Creation Dt:		Fuel Type 2:	
Instance Install Dt:		Fuel Type 3:	
Item Description:		Panam Related:	
Manufacturer:		Panam Venue Nm:	
Model:		External Identifier:	
Serial No:		Item:	
ULC Standard:		Piping Steel:	
Quantity:		Piping Galvanized:	
Unit of Measure:		Tank Single Wall St:	
Overfill Prot Type:		Piping Underground:	
Creation Date:		Tank Underground:	
Next Periodic Str DT:		Source:	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Cylr Handling Facility		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
86	1 of 8	WNW/96.4	249.9 / 17.37	Cribben Inc. 11965 Hurontario St Brampton ON L6Z 4P7	SCT

Established:	01-JAN-90
Plant Size (ft²):	1000

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Employment:

--Details--

Description:	Graphic Design Services
SIC/NAICS Code:	541430
Description:	Digital Printing
SIC/NAICS Code:	323115
Description:	Manifold Business Forms Printing
SIC/NAICS Code:	323116
Description:	Support Activities for Printing
SIC/NAICS Code:	323120
Description:	Other Printing
SIC/NAICS Code:	323119

---

86 ***2 of 8*** ***WNW/96.4*** ***249.9 / 17.37*** ***Sandra L. D'Souza Drugs Ltd.***
11965 HURONTARIO ST
BRAMPTON ON L6Z 4P7 ***GEN***

Generator No:	ON2805779
SIC Code:	446110
SIC Description:	446110
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	NASTRAN NAJAFI-FARD
Choice of Contact:	CO_ADMIN
Phone No Admin:	4164931220 Ext.3218
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	261
Waste Class Name:	PHARMACEUTICALS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

86 ***3 of 8*** ***WNW/96.4*** ***249.9 / 17.37*** ***Sandra L. D'Souza Drugs Ltd.***
11965 HURONTARIO ST
BRAMPTON ON L6Z 4P7 ***GEN***

Generator No:	ON2805779
SIC Code:	446110
SIC Description:	446110
Approval Years:	2015
PO Box No:	
Country:	Canada
Status:	
Co Admin:	NASTRAN NAJAFI-FARD
Choice of Contact:	CO_ADMIN
Phone No Admin:	4164931220 Ext.3218
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

86 *4 of 8* *WNW/96.4* *249.9 / 17.37* **Sandra L. D'Souza Drugs Ltd.**
11965 HURONTARIO ST
BRAMPTON ON L6Z 4P7
GEN

Generator No: ON2805779
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

86 *5 of 8* *WNW/96.4* *249.9 / 17.37* **Sandra L. D'Souza Drugs Ltd.**
11965 HURONTARIO ST
BRAMPTON ON L6Z 4P7
GEN

Generator No: ON2805779
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

86 *6 of 8* *WNW/96.4* *249.9 / 17.37* **Sandra L. D'Souza Drugs Ltd.**
11965 HURONTARIO ST
BRAMPTON ON L6Z 4P7
GEN

Generator No: ON2805779

SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

86 | ***7 of 8*** | ***WNW/96.4*** | ***249.9 / 17.37*** | ***Alectra Utilities Corporation 11965 Hurontario St Brampton ON L6Z 4P7*** | ***SPL***

Ref No: 8810-BQERH6
Year:
Incident Dt: 2020/06/09
Dt MOE Arvl on Scn:
MOE Reported Dt: 2020/06/09
Dt Document Closed: 2020/07/07
Site No: 0824-BQHRZV
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: 11965 Hurontario Street
Site Address: 11965 Hurontario St
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 1 other - see incident description
System Facility Address:
Client Name: Alectra Utilities Corporation
Client Type: Corporation
Source Type: Transformer
Contaminant Code: 15
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1: n/a
Contaminant UN No 1: n/a
Receiving Medium: Land
Incident Reason: Equipment Failure
Incident Summary: RofPeel: unkn vol of transformer oil to grass

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Communal
SAC Action Class: Land Spills
Call Report Locatn Geodata:

---

86 | ***8 of 8*** | ***WNW/96.4*** | ***249.9 / 17.37*** | ***Sandra L. D'Souza Drugs Ltd.***
11965 HURONTARIO ST
BRAMPTON ON L6Z 4P7 | ***GEN***

Generator No: ON2805779
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

87 | ***1 of 13*** | ***ESE/21.6*** | ***219.8 / -12.63*** | ***CANADIAN TIRE CORPORATION LTD.***
30 KENNEDY ROAD RETAIL STORE
BRAMPTON CITY ON | ***SPL***

Ref No: 108455
Year:
Incident Dt: 12/20/1994
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/21/1994
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: UNDERGROUND TANK LEAK
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Nature of Impact:	Soil contamination
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Incident Reason:	UNKNOWN
Incident Summary:	CANADIAN TIRE-UKN QTY WASTE OIL TO GROUND FOUNDDURING EXCAVATION OF TANK
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

---

87 | ***2 of 13*** | ***ESE/21.6*** | ***219.8 / -12.63*** | ***P.O. MONTGOMERY ENT.***
30 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E2 | ***GEN***

Generator No:	ON2070900
SIC Code:	6341
SIC Description:	HOME/AUTO. SUPPLY
Approval Years:	95,96,97,98
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

---

87 | ***3 of 13*** | ***ESE/21.6*** | ***219.8 / -12.63*** | ***P.O. MONTGOMERY ENTERPRISES***
30 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E2 | ***GEN***

Generator No:	ON2070900
SIC Code:	6341
SIC Description:	HOME/AUTO. SUPPLY
Approval Years:	99,00,01
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
87	4 of 13	ESE/21.6	219.8 / -12.63	**Rochon Building Corporation** **30 Kennedy Road South** **Brampton ON L6W 3E2**	GEN
Generator No:		ON2738201			
SIC Code:		441310			
SIC Description:		Automotive Parts and Accessories Stores			
Approval Years:		04			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
87	5 of 13	ESE/21.6	219.8 / -12.63	**CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**** **30 KENNEDY RD S** **BRAMPTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9905906	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	398435	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Refill Cntr - Cylr Fill		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

87	6 of 13	ESE/21.6	219.8 / -12.63	**P D MONTGOMERY ENTERPRISES INC** **CANADIAN TIRE AUTO CENTRE** **30 KENNEDY RD S**	DTNK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON	

Delisted Expired Fuel Safety Facilities

Instance No:	9995807	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	399879	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Refill Cntr - Cylr Fill		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

87	*7 of 13*	*ESE/21.6*	*219.8 / -12.63*	***CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr***** ***30 KENNEDY RD S*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	11097541	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	69325	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	8 of 13	ESE/21.6	219.8 / -12.63	P D MONTGOMERY ENTERPRISES INC CANADIAN TIRE AUTO CENTRE 30 KENNEDY RD S BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 11151097
Status: EXPIRED
Instance ID: 70746
Instance Type: FS Propane Tank
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
87	9 of 13	ESE/21.6	219.8 / -12.63	Canadian Tire Corporation, Limited 30 Kennedy Road S. Brampton ON L6W 3E2	GEN

Generator No: ON3739143
SIC Code: 415290
SIC Description: OTHER NEW MOTOR VEHICLE PARTS AND ACCESSORIES WHOLESALER-DISTRIBUTORS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: John Sukundun

Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-796-5666 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

87 | ***10 of 13*** | ***ESE/21.6*** | ***219.8 / -12.63*** | ***Canadian Tire Corporation, Limited***
30 Kennedy Road S.
Brampton ON L6W 3E2 | ***GEN***

Generator No: ON3739143
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

87 | ***11 of 13*** | ***ESE/21.6*** | ***219.8 / -12.63*** | ***Canadian Tire Corporation, Limited***
30 Kennedy Road S.
Brampton ON L6W 3E2 | ***GEN***

Generator No: ON3739143
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

87 | **12 of 13** | **ESE/21.6** | **219.8 / -12.63** | **Canadian Tire Corporation, Limited**
30 Kennedy Road S.
Brampton ON L6W 3E2 | **GEN**

Generator No: ON3739143
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

87 | **13 of 13** | **ESE/21.6** | **219.8 / -12.63** | **Canadian Tire Corporation, Limited**
30 Kennedy Road S.
Brampton ON L6W 3E2 | **GEN**

Generator No: ON3739143
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 267 C
Waste Class Name: ORGANIC ACIDS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

88 | **1 of 1** | **ESE/9.3** | **219.8 / -12.63** | **The Corporation of Brampton (Transit)** | **SPL**

Brampton ON

Ref No: 7310-BC4PV5
Year:
Incident Dt: 5/12/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/12/2019
Dt Document Closed: 5/18/2019
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: 10 -100 metres eg. Topographic Map
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Kennedy Road northbound, 60-70m north of Orenda Rd<UNOFFICIAL>
Site Address:
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu: Map
Site Map Datum:
Northing: 4838542.42
Easting: 601079.4
Incident Cause:
Incident Preceding Spill: Collision/Accident
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 8 L
System Facility Address:
Client Name: The Corporation of Brampton (Transit)
Client Type: Municipal Government
Source Type: Motor Vehicle
Contaminant Code: 27
Contaminant Name: COOLANT N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1: n/a
Contaminant UN No 1: n/a
Receiving Medium: Surface Water
Incident Reason: Unknown / N/A
Incident Summary: Brampton Transit: est 8L coolant to road, cleaning
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Sector Type: Miscellaneous Communal
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:

---

89 | 1 of 9 | WNW/54.5 | 250.9 / 18.37 | **1205073 ONTARIO LTD**
11980 HURONTARIO ST
BRAMPTON ON L7A 1E6 | FSTH

License Issue Date: 11/17/2004
Tank Status: Pending Renewal
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Split Serve

--Details--
Status: Active
Year of Installation: 1999
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1999
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1999
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1999
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

---

89 | 2 of 9 | WNW/54.5 | 250.9 / 18.37 | **2124964 ONTARIO INC O/A PETRO-CANADA**
11980 HURONTARIO ST (HWY 10)
BRAMPTON ON L7A 1E6 | DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10264064
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:

Expired Date: 5/11/2010 15:13
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

---

89 | ***3 of 9*** | ***WNW/54.5*** | ***250.9 / 18.37*** | ***Petro-Canada Fuels Inc.***
11980 Hurontario St
Brampton ON | ***SPL***

Ref No: 3672-98SJ5J ***Municipality No:***
Year: ***Nature of Damage:***
Incident Dt: 18-JUN-13 ***Discharger Report:***
Dt MOE Arvl on Scn: ***Material Group:***
MOE Reported Dt: 18-JUN-13 ***Impact to Health:***
Dt Document Closed: ***Agency Involved:***
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: service station Petro Canada<UNOFFICIAL>
Site Address: 11980 Hurontario St
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Leak/Break
Incident Preceding Spill:
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 40 L
System Facility Address:
Client Name: Petro-Canada Fuels Inc.
Client Type:
Source Type:
Contaminant Code: 12
Contaminant Name: GASOLINE
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Unknown / N/A
Incident Summary: TSSA FSB: ~ 40 L gasoline to c/b's; cntnd & clng
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Service Station
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Call Report Locatn Geodata:

---

89 | ***4 of 9*** | ***WNW/54.5*** | ***250.9 / 18.37*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** ***11980 HURONTARIO ST*** ***BRAMPTON ON*** | ***FST***

Inventory No:	11584278	***Tank Material:***	Fiberglass (FRP)
Inventory Status:	active	***Corrosion Protect:***	Fiberglass
Installation Year:	1999	***Overfill Protection:***	
Capacity:	50000	***Inventory Context:***	FS Liquid Fuel
Capacity Unit:	L	***Inventory Item:***	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:			

---

89 | ***5 of 9*** | ***WNW/54.5*** | ***250.9 / 18.37*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** ***11980 HURONTARIO ST*** ***BRAMPTON ON*** | ***FST***

Inventory No:	11584305	***Tank Material:***	Fiberglass (FRP)
Inventory Status:	active	***Corrosion Protect:***	Fiberglass
Installation Year:	1999	***Overfill Protection:***	
Capacity:	50000	***Inventory Context:***	FS Liquid Fuel
Capacity Unit:	L	***Inventory Item:***	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:			

---

89 | ***6 of 9*** | ***WNW/54.5*** | ***250.9 / 18.37*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** ***11980 HURONTARIO ST*** ***BRAMPTON ON*** | ***FST***

Inventory No:	11584265	***Tank Material:***	Fiberglass (FRP)
Inventory Status:	active	***Corrosion Protect:***	Fiberglass
Installation Year:	1999	***Overfill Protection:***	
Capacity:	50000	***Inventory Context:***	FS Liquid Fuel
Capacity Unit:	L	***Inventory Item:***	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:			

---

89 | ***7 of 9*** | ***WNW/54.5*** | ***250.9 / 18.37*** | ***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** ***11980 HURONTARIO ST*** ***BRAMPTON ON*** | ***FST***

Inventory No:	11584295	***Tank Material:***	Fiberglass (FRP)
Inventory Status:	active	***Corrosion Protect:***	Fiberglass
Installation Year:	1999	***Overfill Protection:***	
Capacity:	50000	***Inventory Context:***	FS Liquid Fuel
Capacity Unit:	L	***Inventory Item:***	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	8 of 9	WNW/54.5	250.9 / 18.37	SUNCOR ENERGY PRODUCTS PARTNERSHIP 11980 HURONTARIO ST BRAMPTON ON	INC

Incident No:	1130990	**Any Health Impact:**	
Incident ID:		**Any Enviro Impact:**	
Instance No:	64495244	**Service Intrp:**	
Status Code:		**Was Prop Damaged:**	
Incident Status:	Causal Analysis Complete	**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:		**Indus App. Type:**	
Attribute Category:	FS-Incident	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	
Date of Occurrence:	6/18/2013	**Operation Pressure:**	
Time of Occurrence:		**Equipment Type:**	
Occr Insp Start Dt:		**Equipment Model:**	
Incident Creat On:	6/18/2013	**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Liquid Petroleum Spill	**Contam. Migrated:**	
Occur Type Rpt:	Leak	**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Gasoline	**Sub Surface Contam:**	
Fuel Type Reported:	Transportation Fuel	**Tank Material Type:**	
Enforcement Policy:		**Tank Storage Type:**	
Prc Escalation Req:		**Tank Location Type:**	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	11980 HURONTARIO ST		
Invent Postal Code:	L7A 1E6		
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:	NOZZLE NOT SHUT OFF		
Operation Type Involved:	Retail Fuel Station (FS, SS, Multifunctional)		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
89	9 of 9	WNW/54.5	250.9 / 18.37	SUNCOR ENERGY PRODUCTS PARTNERSHIP 11980 HURONTARIO ST BRAMPTON ON	FST

Inventory No:	64495244	**Tank Material:**	
Inventory Status:	Active	**Corrosion Protect:**	
Installation Year:		**Overfill Protection:**	
Capacity:	200000	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:					

90	1 of 2	ESE/35.8	219.8 / -12.63	GRUMMAN OLSON INDUSTRIES INC. 30A Kennedy Rd S Suite 201 Brampton ON L6W 3E2	SCT

Established: 1970
Plant Size (ft²): 0
Employment: 2

--Details--
Description: Motor Vehicle Body Manufacturing
SIC/NAICS Code: 336211

90	2 of 2	ESE/35.8	219.8 / -12.63	Austin Rehab Group 30A Kennedy Road South, Ste 1A Bramptom ON	GEN

Generator No: ON5660825
SIC Code: 621310, 621390
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

91	1 of 1	ESE/22.6	219.8 / -12.63	PEEL, REGIONAL MUNICIPALITY OF INTERSECTION OF ORENDA DR & KENNEDY DR FORCEMAIN BRAMPTON CITY ON	SPL

Ref No: 193825
Year:
Incident Dt: 1/24/2001
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/24/2001
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: CONTAINER OVERFLOW
Incident Preceding Spill:
Environment Impact: Not Anticipated

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason: OTHER
Incident Summary: REG.PEEL: SANITARY SEWER BACKUP CAUSED THIN LAYER OVERFLOW TO STREET.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

92 | ***1 of 5*** | ***WNW/2.1*** | ***250.9 / 18.37*** | ***TRANSPORT TRUCK HIGHWAY 10 - WEST SIDE - SOUTH OF MAYFIELD ROAD MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON*** | ***SPL***

Ref No: 113086
Year:
Incident Dt: 5/12/1995
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/12/1995
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Preceding Spill:
Environment Impact: CONFIRMED
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: FIRE, WORKS

Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: ERROR
Incident Summary: ROADWAY EXPRESS: 300 L DIESEL FUEL TO ROAD
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

92 | ***2 of 5*** | ***WNW/2.1*** | ***250.9 / 18.37*** | ***ONTARIO HYDRO CORNER OF HWY 10 & MAYFIELD RD. TRANSFORMER PEEL R.M. ON*** | ***SPL***

Ref No: 14495
Year:
Incident Dt: 2/5/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/5/1989
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: PEEL R.M.
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: ERROR
Incident Summary: TRANSFORMER
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21000
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: CALEDON EAST OPP, FIRE DEPT.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	3 of 5	WNW/2.1	250.9 / 18.37	Construction Site<UNOFFICIAL> On Mayfield Rd. just east of Hurontario St. Brampton ON	SPL

Ref No:	1750-6UMMSF	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	10/16/2006	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/16/2006	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Construction Site<UNOFFICIAL>		
Site Address:	On Mayfield Rd. just east of Hurontario St.		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:			
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	100 L		
System Facility Address:			
Client Name:			
Client Type:			
Source Type:	Other Motor Vehicle		
Contaminant Code:	13		
Contaminant Name:	HYDRAULIC OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Incident Reason:	Equipment Failure		
Incident Summary:	Brampton: Spill of DSL impacting Creek(unknown name)		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
92	4 of 5	WNW/2.1	250.9 / 18.37	TWIN PETROLEUM PRODUCTS LTD HWY 10 (MAYFIELD RD) SNELGROVE ON L0P 1M0	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9808140	**Expired Date:**	8/1/1990
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

92	5 of 5	WNW/2.1	250.9 / 18.37	**SD Towing** **Hurontario St and Mayfield Rd** **Brampton ON**	SPL

Ref No:	0377-AJXU7X	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	2/26/2017	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2/26/2017	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Location of the Spill<UNOFFICIAL>		
Site Address:	Hurontario St and Mayfield Rd		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4842976		
Easting:	594623		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	30 L		
System Facility Address:			
Client Name:	SD Towing		
Client Type:			
Source Type:			
Contaminant Code:	13		
Contaminant Name:	DIESEL FUEL		

Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason: Equipment Failure
Incident Summary: SD Towing: 30 L of diesel fuel to road and catchbasin, cntd and cln.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	1 of 9	WNW/48.7	251.5 / 19.04	PETRO-CANADA 12011 HWY 10 IN VILLAGE OF SNELGROVE. TANK TRUCK (CARGO) CALEDON TOWN ON	SPL

Ref No: 146476
Year:
Incident Dt: 9/15/1997
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/15/1997
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: CALEDON TOWN
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: ERROR
Incident Summary: PETRO CANADA-10 LITERS GASOLINE TO STATION LOT, CONTAINED.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21401
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	2 of 9	WNW/48.7	251.5 / 19.04	PETRO CANADA 12011 HURONTARIO ST BRAMPTON ON L6Z 4P8	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	3 of 9	WNW/48.7	251.5 / 19.04	2074065 ONTARIO INC O/A GAS STN 12011 HURONTARIO ST HWY 10 BRAMPTON ON L6Z 4P8	FSTH

License Issue Date: 1/4/2007
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 1997
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	4 of 9	WNW/48.7	251.5 / 19.04	SUNCOR ENERGY PRODUCTS PARTNERSHIP 12011 HURONTARIO ST BRAMPTON ON	FST

Inventory No: 11494172
Inventory Status: active
Installation Year: 1997
Capacity: 35000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	5 of 9	WNW/48.7	251.5 / 19.04	SUNCOR ENERGY PRODUCTS PARTNERSHIP 12011 HURONTARIO ST BRAMPTON ON	FST

Inventory No: 11494192
Inventory Status: active
Installation Year: 1997
Capacity: 35000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	6 of 9	WNW/48.7	251.5 / 19.04	SUNCOR ENERGY PRODUCTS PARTNERSHIP 12011 HURONTARIO ST BRAMPTON ON	FST

Inventory No: 11494233
Inventory Status: active
Installation Year: 1997
Capacity: 35000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	7 of 9	WNW/48.7	251.5 / 19.04	SUNCOR ENERGY PRODUCTS PARTNERSHIP 12011 HURONTARIO ST BRAMPTON ON	FST

Inventory No: 11494213
Inventory Status: active
Installation Year: 1997
Capacity: 35000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	8 of 9	WNW/48.7	251.5 / 19.04	PETRO CANADA 12011 HURONTARIO ST BRAMPTON ON L6Z4P8	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 9058461243
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
93	9 of 9	WNW/48.7	251.5 / 19.04	SUNCOR ENERGY PRODUCTS PARTNERSHIP 12011 HURONTARIO ST BRAMPTON ON	FST

Inventory No: 10189084
Tank Material:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory Status:	Active	**Corrosion Protect:**	
Installation Year:		**Overfill Protection:**	
Capacity:	140000	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			
Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
94	1 of 7	WNW/25.0	251.9 / 19.37	ORMEAU DEVELOPMENTS 12004 HURONTARIO ST BRAMPTON ON L7A 1E6	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9838126	**Expired Date:**	4/2/2009
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
94	2 of 7	WNW/25.0	251.9 / 19.37	ORMEAU DEVELOPMENTS 12004 HURONTARIO ST BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11332120	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	79228	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	

Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

94 **3 of 7** **WNW/25.0** **251.9 / 19.37** **ORMEAU DEVELOPMENTS**
12004 HURONTARIO ST
BRAMPTON ON
EXP

Inventory No:	10969579	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Impressed Current
Installation Year:	1972	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

94 **4 of 7** **WNW/25.0** **251.9 / 19.37** **ORMEAU DEVELOPMENTS**
12004 HURONTARIO ST
BRAMPTON ON
EXP

Inventory No:	10969594	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Impressed Current
Installation Year:	1984	**Overfill Protection:**	
Capacity:	50000	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Gasoline		

94 **5 of 7** **WNW/25.0** **251.9 / 19.37** **ORMEAU DEVELOPMENTS**
12004 HURONTARIO ST
BRAMPTON ON
EXP

Inventory No:	10969570	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Impressed Current
Installation Year:	1972	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel Tank

Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Inventory Item: FS LIQUID FUEL TANK

---

94 *6 of 7* *WNW/25.0* *251.9 / 19.37*

ORMEAU DEVELOPMENTS
12004 HURONTARIO ST
BRAMPTON ON

EXP

Inventory No: 10969603
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 25000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

94 *7 of 7* *WNW/25.0* *251.9 / 19.37*

ORMEAU DEVELOPMENTS
12004 HURONTARIO ST
BRAMPTON ON

EXP

Inventory No: 10969588
Inventory Status: EXPIRED
Installation Year: 1972
Capacity: 22730
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline
Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

95 *1 of 1* *ESE/59.5* *219.8 / -12.63*

City of Brampton
15 Orenda Road
Brampton ON

GEN

Generator No: ON4195123
SIC Code: 447110
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

96 *1 of 26* *ESE/32.6* *219.8 / -12.63*

Maple Leaf Poultry
32 Kennedy Rd S
Brampton ON L6W 3E3

SCT

Established: 1955
Plant Size (ft²):

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Employment:

--Details--
Description: Poultry Processing
SIC/NAICS Code: 311615

---

96 ***2 of 26*** ***ESE/32.6*** ***219.8 / -12.63*** ***MAPLE LEAF FOODS INC.***
BRAMPTON PLANT 32 KENNEDY ROAD SOUTH
BRAMPTON CITY ON ***SPL***

Ref No: 163618
Year:
Incident Dt: 1/13/1999
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/13/1999
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: EQUIPMENT FAILURE
Incident Summary: MAPLE LEAF FOODS:UNK QUA WASH WATER SPILLED AND CONTAINED ON PROPERTY.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

---

96 ***3 of 26*** ***ESE/32.6*** ***219.8 / -12.63*** ***MAPLE LEAF FOODS INC.***
32 KENNEDY ROAD SOUTH BRAMPTON PLANT
32 KENNEDY ROAD SOUTH
BRAMPTON CITY ON L6W 3E3 ***SPL***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	178666	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	3/20/2000	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	3/20/2000	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	BRAMPTON FD
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	AIR		
Incident Reason:	NEGLIGENCE (APPARENT)		
Incident Summary:	MAPLE LEAF FOODS: AMMONIARELEASE TO ATM. WHEN LINE CUT BY CONTRACTOR		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

96	*4 of 26*	***ESE/32.6***	***219.8 / -12.63***	***MAPLE LEAF POULTRY*** ***32 KENNEDY ROAD SOUTH*** ***BRAMPTON ON L6W 3E3***	***GEN***

Generator No:	ON0044245
SIC Code:	3351
SIC Description:	TELECOMMUNICATIONS
Approval Years:	01,02,03,04,05,06,07,08
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

96	5 of 26	ESE/32.6	219.8 / -12.63	THE POULTRY COMPANY ATTN FRANK TOIRKENS 32 KENNEDY RD S BRAMPTON ON L6W 3E3	FSTH

License Issue Date: 12/23/1991
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 9092
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

96	6 of 26	ESE/32.6	219.8 / -12.63	THE POULTRY COMPANY ATTN FRANK TOIRKENS 32 KENNEDY RD S BRAMPTON ON L6W 3E3	FSTH

License Issue Date: 12/23/1991
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1989
Corrosion Protection:
Capacity: 9092
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	7 of 26	ESE/32.6	219.8 / -12.63	G M F TRANSPORT 32 KENNEDY RD S BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9207393	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	381595	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	Fuels Safety Private Fuel Outlet - Self Serve		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	8 of 26	ESE/32.6	219.8 / -12.63	G M F TRANSPORT 32 KENNEDY RD S BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10596651	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	30441	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	

TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

96 | ***9 of 26*** | ***ESE/32.6*** | ***219.8 / -12.63*** | ***MAPLE LEAF POULTRY 32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3*** | ***GEN***

Generator No: ON0044245
SIC Code: 112390
SIC Description:
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

96 | ***10 of 26*** | ***ESE/32.6*** | ***219.8 / -12.63*** | ***MAPLE LEAF POULTRY 32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3*** | ***GEN***

Generator No: ON0044245
SIC Code: 112390
SIC Description:
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

96 | ***11 of 26*** | ***ESE/32.6*** | ***219.8 / -12.63*** | ***MAPLE LEAF POULTRY***
32 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E3 | ***GEN***

Generator No: ON0044245
SIC Code: 112390
SIC Description:
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	12 of 26	ESE/32.6	219.8 / -12.63	THE POULTRY COMPANY ATTN FRANK TOIRKENS 32 KENNEDY RD S BRAMPTON ON	FST

Inventory No: 10596671
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	13 of 26	ESE/32.6	219.8 / -12.63	MAPLE LEAF POULTRY 32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	GEN

Generator No: ON0044245
SIC Code: 112390
SIC Description:
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	14 of 26	ESE/32.6	219.8 / -12.63	MAPLE LEAF POULTRY 32 KENNEDY ROAD SOUTH BRAMPTON ON	GEN

Generator No: ON0044245
SIC Code: 112390
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

---

96 | ***15 of 26*** | ***ESE/32.6*** | ***219.8 / -12.63*** | ***MAPLE LEAF POULTRY***
32 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E3 | ***GEN***

Generator No: ON0044245
SIC Code: 112390
SIC Description: 112390
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Pauline Harvey
Choice of Contact: CO_ADMIN
Phone No Admin: 905-453-6262 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	16 of 26	ESE/32.6	219.8 / -12.63	MAPLE LEAF POULTRY 32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	GEN

Generator No: ON0044245
SIC Code: 112390
SIC Description: 112390
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Pauline Harvey
Choice of Contact: CO_ADMIN
Phone No Admin: 905-453-6262 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
96	17 of 26	ESE/32.6	219.8 / -12.63	MAPLE LEAF POULTRY 32 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E3	GEN

Generator No: ON0044245
SIC Code: 112390
SIC Description: 112390
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Pauline Harvey
Choice of Contact: CO_ADMIN
Phone No Admin: 905-453-6262 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

96 | **18 of 26** | **ESE/32.6** | **219.8 / -12.63** | **MAPLE LEAF POULTRY**
32 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E3 | **GEN**

Generator No: ON0044245
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

96 | **19 of 26** | **ESE/32.6** | **219.8 / -12.63** | **MAPLE LEAF POULTRY**
32 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E3 | **GEN**

Generator No: ON0044245
SIC Code:
SIC Description:
Approval Years: As of Jul 2020

PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 213 T
Waste Class Name: Petroleum distillates

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

96 ***20 of 26*** ***ESE/32.6*** ***219.8 / -12.63*** ***Maple Leaf Foods Inc.***
32 Kennedy Rd S
Brampton ON L6W 3E3 ***SPL***

Ref No: 3258-BE4TXD
Year:
Incident Dt: 7/15/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/15/2019
Dt Document Closed:
Site No: 3386-4GJRWR
MOE Response: No
Site County/District: Regional Municipality Of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Brampton Facility Maple Leaf Poultry
Site Address: 32 Kennedy Rd S
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Incident Cause:
Incident Preceding Spill: Overflow/Surcharge
Environment Impact:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	600 L
System Facility Address:	
Client Name:	Maple Leaf Foods Inc.
Client Type:	Corporation
Source Type:	Sewage Treatment
Contaminant Code:	41
Contaminant Name:	WASTEWATER (HIGH BOD)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Land
Incident Reason:	Blockage
Incident Summary:	Maple Leaf Foods: est. 600 L wastewater to 2 CB's. Kennedy Rd. S.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	

96	***21 of 26***	***ESE/32.6***	***219.8 / -12.63***	***MAPLE LEAF POULTRY*** ***32 KENNEDY ROAD SOUTH*** ***BRAMPTON ON L6W 3E3***	***GEN***

Generator No:	ON0044245
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders
Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	212 I
Waste Class Name:	Aliphatic solvents and residues
Waste Class:	213 T
Waste Class Name:	Petroleum distillates
Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants
Waste Class:	145 H
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	252 T
Waste Class Name:	Waste crankcase oils and lubricants
Waste Class:	213 I

Waste Class Name: Petroleum distillates

---

96 | **22 of 26** | **ESE/32.6** | **219.8 / -12.63** | **32 Kennedy Rd S**
Brampton ON L6W 3E3 | **SPL**

Ref No: 7603-BZ7JA3
Year:
Incident Dt: 2021/03/17
Dt MOE Arvl on Scn:
MOE Reported Dt: 2021/03/17
Dt Document Closed:
Site No: 3386-4GJRWR
MOE Response: No
Site County/District: Regional Municipality Of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Brampton Facility Maple Leaf Poultry
Site Address: 32 Kennedy Rd S
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Incident Cause:
Incident Preceding Spill: Process Upset/Malfunction
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 800 L
System Facility Address:
Client Name:
Client Type:
Source Type: Valve/Fitting/Piping
Contaminant Code: 41
Contaminant Name: WASTEWATER N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium: Land
Incident Reason: Equipment Failure
Incident Summary: Maple Leaf: 800 L waste water to site; contd & clng
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

---

96 | **23 of 26** | **ESE/32.6** | **219.8 / -12.63** | **MAPLE LEAF POULTRY**
32 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E3 | **GEN**

Generator No: ON0044245
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 213 T
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 145 H
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252 T
Waste Class Name: WASTE OILS & LUBRICANTS

---

96 | ***24 of 26*** | ***ESE/32.6*** | ***219.8 / -12.63*** | ***32 Kennedy Road South BRAMPTON ON*** | ***SPL***

Ref No: 1-23SSWE
Year:
Incident Dt: 8/19/2022 10:45:00 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/20/2022 8:09:25 AM
Dt Document Closed: 8/22/2022 8:04:43 AM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 32 Kennedy Road South
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Power Outage
Environment Impact: 1 Minor Impact
Health Env Consequence:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Nature of Impact:	
Contaminant Qty:	500 litre (L)
System Facility Address:	
Client Name:	MAPLE LEAF FOODS INC
Client Type:	Private Business
Source Type:	Sewage Treatment
Contaminant Code:	
Contaminant Name:	SECONDARY SLUDGE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Equipment failure/malfunction
Incident Summary:	Spill: Maple Leaf Foods- Aprox. 500 L Chicken Sewage to Ground and impacted c/b
Activity Preceding Spill:	Normal operations
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HB - Credit - 16 Mile
Sector Type:	POULTRY PROCESSING
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001793836"],"wkts":["POINT (-79.7438602000 43.6921875000)"],"creation_date":"2022-08-20"}

96 | ***25 of 26*** | ***ESE/32.6*** | ***219.8 / -12.63*** | ***32 Kennedy Rd S., Brampton BRAMPTON ON*** | ***SPL***

Ref No:	1-294QIU	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11/11/2022 7:30:17 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/11/2022 9:13:17 PM	**Impact to Health:**	0 No Impact
Dt Document Closed:		**Agency Involved:**	

Site No:	
MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	Cb
Site Name:	
Site Address:	32 Kennedy Rd S., Brampton
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	
Environment Impact:	0 No Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see notes
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	Tank - Underground
Contaminant Code:	
Contaminant Name:	CHICKEN OFFAL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land; Surface Water
Incident Reason:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Summary:	Maple Leaf Foods: Chicken waste to CB, Brampton
Activity Preceding Spill:	
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HB - Credit - 16 Mile
Sector Type:	POULTRY PROCESSING
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001793836"],"wkts":["POINT (-79.7438602000 43.6921875000)"],"creation_date":"2022-11-11"}

---

96 | ***26 of 26*** | ***ESE/32.6*** | ***219.8 / -12.63*** | ***G M F TRANSPORT***
32 KENNEDY RD S
BRAMPTON ON | ***EXP***

Inventory No:	10596624	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Fiberglass
Installation Year:	1981	**Overfill Protection:**	
Capacity:	22700	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	UNDERGROUND TANK		
Previous Fuel Type:	Diesel		

---

97 | ***1 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No:	112307	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	4/24/1995	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/24/1995	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839000.00		
Easting:	603800.00		
Incident Cause:	OTHER CAUSE (N.O.S.)		
Incident Preceding Spill:			
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Incident Reason: ERROR
Incident Summary: IKO INDUSTRIES-1 MINUTE BLACK SMOKE FROM ASPHALT TANK.ERROR-VALVE OPENED.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

97 | ***2 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No: 114123
Year:
Incident Dt: 6/6/1995
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/6/1995
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839000.00
Easting: 603800.00
Incident Cause: UNKNOWN
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: UNKNOWN
Incident Summary: IKO INDUSTRIES: 2 250 L ASPHALT TO GROUNDIN TANK FARM AREA
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Call Report Locatn Geodata:

---

97 | **3 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LTD.**
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | **SPL**

Ref No: 119583
Year:
Incident Dt: 10/12/1995
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/12/1995
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839000.00
Easting: 603800.00
Incident Cause: CONTAINER OVERFLOW
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: ERROR
Incident Summary: IKO INDUSTRIES LTD- < 50 L ASPHALT TO GROUND AT SCALE AREA.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

---

97 | **4 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LTD.**
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | **SPL**

Ref No: 119723
Year:
Incident Dt: 10/17/1995

Municipality No: 21101
Nature of Damage:
Discharger Report:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/17/1995	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839000.00		
Easting:	603800.00		
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Incident Reason:	UNKNOWN		
Incident Summary:	IKO-1.36 M3 ASPHALT TO GROUND FROM PIPE LEAK, CONTAINED,CLEANED-UP.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

---

97 | ***5 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD. BRAMPTON PLANT 71 ORENDA ROAD BRAMPTON CITY ON L6W 1V8*** | ***SPL***

Ref No:	15561	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	3/7/1989	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	3/7/1989	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		

Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4839000.00
Easting:	603800.00
Incident Cause:	PROCESS UPSET
Incident Preceding Spill:	
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	AIR
Incident Reason:	ERROR
Incident Summary:	IKO INDUSTRIES-SMOKE TO ATM.-POOR TRANSITION FROMGAS TO OIL-ONGOING.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

---

97 | ***6 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
BRAMPTON PLANT 71 ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No:	26547	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	10/14/1989	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/14/1989	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839000.00		
Easting:	603800.00		
Incident Cause:	PROCESS UPSET		
Incident Preceding Spill:			
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
System Facility Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Incident Reason: FIRE/EXPLOSION
Incident Summary: IKO - BLACK SMOKE TO ATM FROM FIRE IN ONE OF THE PRE-HEATHER,
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

97 | ***7 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
CVM FILTER BRAMPTON PLANT 71 ORENDA ROAD
BRAMPTON CITY ON | ***SPL***

Ref No: 32834
Year:
Incident Dt: 4/3/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/3/1990
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839000.00
Easting: 603800.00
Incident Cause: PROCESS UPSET
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: WATER / AIR
Incident Reason: FIRE/EXPLOSION
Incident Summary: IKO-SMOKE FROM FIRE OF CVM OXIDIZER FILTER.
Activity Preceding Spill:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: PEEL REGION, FD, MOE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

97 | **8 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LTD.**
BRAMPTON PLANT 71 ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | **SPL**

Ref No: 40691
Year:
Incident Dt: 9/13/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/13/1990
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839000.00
Easting: 603800.00
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Other
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: AIR
Incident Reason: OVERSTRESS/OVERPRESSURE
Incident Summary: IKO - FUMES LEAKING FROM ASPHALT LINE. WIND AWAY FROM RESIDENTIAL AREA.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

---

97 | **9 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LTD.**
71 ORENDA RD. BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | **SPL**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	66759	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	2/6/1992	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2/6/1992	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839000.00		
Easting:	603800.00		
Incident Cause:	OTHER CONTAINER LEAK		
Incident Preceding Spill:			
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Soil Contamination		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Incident Reason:	CORROSION		
Incident Summary:	IKO INDUSTRIES: 4500L ASPHALT LEAK FROM TANK TOGROUND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

97	***10 of 58***	***ESE/92.8***	***219.8 / -12.63***	***IKO Industries Ltd.*** ***71 Orenda Rd*** ***Brampton ON L6W 1V8***	***SCT***

Established:	1958
Plant Size (ft²):	
Employment:	

--Details--

Description:	All Other Textile Product Mills
SIC/NAICS Code:	314990
Description:	Shingle and Shake Mills
SIC/NAICS Code:	321112
Description:	Asphalt Shingle and Coating Material Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC/NAICS Code: 324122

Description: Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

Description: Other Rubber Product Manufacturing
SIC/NAICS Code: 326290

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

---

97 | ***11 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***Sako Materials Limited***
71 Orenda Rd
Brampton ON L6W 1V8 | ***SCT***

Established: 01-AUG-58
Plant Size (ft²):
Employment:

--Details--
Description: Shingle and Shake Mills
SIC/NAICS Code: 321112

Description: All Other Miscellaneous Chemical Product Manufacturing
SIC/NAICS Code: 325999

Description: Asphalt Shingle and Coating Material Manufacturing
SIC/NAICS Code: 324122

Description: Urethane and Other Foam Product (except Polystyrene) Manufacturing
SIC/NAICS Code: 326150

Description: Structural Wood Product Manufacturing
SIC/NAICS Code: 321215

---

97 | ***12 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No: 122197
Year:
Incident Dt: 1/3/1996
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/3/1996
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4839000.00
Easting:	603800.00
Incident Cause:	OTHER CONTAINER LEAK
Incident Preceding Spill:	
Environment Impact:	NOT ANTICIPATED
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Incident Reason:	WELD/SEAM FAILURE
Incident Summary:	IKO-4500 L ASPHALT TO CEMENT DYKED AREA; TANK LEAK.TO BE CLEANED.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

97 | ***13 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No:	122418	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	1/11/1996	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	1/11/1996	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839000.00		
Easting:	603800.00		
Incident Cause:	UNKNOWN		
Incident Preceding Spill:			
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Soil contamination		
Contaminant Qty:			
System Facility Address:			
Client Name:			

Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: UNKNOWN
Incident Summary: IKO-9 M3 SODIUM HYPOCHLORITE TO DYKED AREA,CONTAINED.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

97 | ***14 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No: 126872 ***Municipality No:*** 21101
Year: ***Nature of Damage:***
Incident Dt: 5/24/1996 ***Discharger Report:***
Dt MOE Arvl on Scn: ***Material Group:***
MOE Reported Dt: 5/24/1996 ***Impact to Health:***
Dt Document Closed: ***Agency Involved:***
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839000.00
Easting: 603800.00
Incident Cause: CONTAINER OVERFLOW
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: ERROR
Incident Summary: IKO-113 L ASPHALT OIL TO GROUND FROM TANK OVERFILL: CONTAINED,CLEANED UP
Activity Preceding Spill:
Property 2nd Watershed:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

97 | ***15 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No:	127395	***Municipality No:***	21101
Year:		***Nature of Damage:***	
Incident Dt:	6/4/1996	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	6/4/1996	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839000.00
Easting: 603800.00
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND / AIR
Incident Reason: EQUIPMENT FAILURE
Incident Summary: IK0-SMALL AMOUNT ASPHALT TO CONCRETE SURFACE. PIPELEAK. TO BE CLEANED.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

97 | ***16 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
71 ORENDA ROAD BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No:	152309	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	2/11/1998	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2/11/1998	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	F.D., MOE
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839000.00		
Easting:	603800.00		
Incident Cause:	OTHER CONTAINER LEAK		
Incident Preceding Spill:			
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Multi Media Pollution		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Incident Reason:	FIRE/EXPLOSION		
Incident Summary:	IKO: INDUSTRIAL FIRE INVOLVING ASPHALT TANK, RUN-OFF TO GROUND.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

97 | ***17 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
IN DITCH AT 71 ORENDA ROAD ON IKO
INDUSTRIES' PROPERTY BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No:	155040	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	4/27/1998	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/27/1998	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	BRAMPTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4839000.00
Easting:	603800.00
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE
Incident Preceding Spill:	
Environment Impact:	CONFIRMED
Health Env Consequence:	
Nature of Impact:	Water course or lake
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	WATER
Incident Reason:	EQUIPMENT FAILURE
Incident Summary:	IKO INDUSTRIES - 70 L OF DIESEL FUEL TO DITCH FROM PUMP, CONTAINED.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

97	*18 of 58*	*ESE/92.8*	*219.8 / -12.63*	***IKO INDUSTRIES LTD.*** ***71 ORENDA ROAD BRAMPTON PLANT 71*** ***ORENDA ROAD*** ***BRAMPTON CITY ON L6W 1V8***	*SPL*

Ref No:	159388	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	8/25/1998	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/25/1998	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839000.00		
Easting:	603800.00		
Incident Cause:	CONTAINER OVERFLOW		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: UNKNOWN
Incident Summary: IKO- 9L SPILL OF FERROUS CHLORIDE TO DITCH, AREA,CONTAINED AND CLEAN
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

97	19 of 58	ESE/92.8	219.8 / -12.63	**IKO INDUSTRIES LTD.** **IKO INDUSTRIES, 71 ORENDA ROAD** **BRAMPTON PLANT 71 ORENDA ROAD** **BRAMPTON CITY ON L6W 1V8**	SPL

Ref No: 175666
Year:
Incident Dt: 12/9/1999
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/9/1999
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4839000.00
Easting: 603800.00
Incident Cause: ABOVE-GROUND TANK LEAK
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: MATERIAL FAILURE
Incident Summary: IKO INDUSTRIES: SODIUM HYPOCHLORITE SPILL FROM TANK TO DYKED AREA.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

97 | ***20 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO Industries Ltd.***
71 Orenda Rd
Brampton ON L6W 1V8 | ***SCT***

Established: 01-JUL-58
Plant Size (ft²):
Employment:

--Details--
Description: Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

Description: Asphalt Shingle and Coating Material Manufacturing
SIC/NAICS Code: 324122

Description: Shingle and Shake Mills
SIC/NAICS Code: 321112

Description: Asphalt Shingle and Coating Material Manufacturing
SIC/NAICS Code: 324122

Description: Other Rubber Product Manufacturing
SIC/NAICS Code: 326290

Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

---

97 | ***21 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD.***
71 ORENDA RD. BRAMPTON PLANT 71
ORENDA ROAD
BRAMPTON CITY ON L6W 1V8 | ***SPL***

Ref No: 195470
Year:
Incident Dt: 2/24/2001
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/24/2001
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: FD

Nearest Watercourse:	
Site Name:	
Site Address:	
Site Region:	
Site Municipality:	BRAMPTON CITY
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4839000
Easting:	603800
Incident Cause:	ABOVE-GROUND TANK LEAK
Incident Preceding Spill:	
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air, Land
Incident Reason:	FIRE, EXPLOSION
Incident Summary:	IKO INDUSTRIES- TANK ON FIRE, TAR/RUNOFF TO DITCHFD ON SITE.REGION,ERP,EPS
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

97	***22 of 58***	***ESE/92.8***	***219.8 / -12.63***	***IKO INDUSTRIES LTD.*** ***71 ORENDA ROAD BRAMPTON PLANT 71*** ***ORENDA ROAD*** ***BRAMPTON CITY ON L6W 1V8***	***SPL***

Ref No:	211751	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	9/18/2001	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/18/2001	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	4839000		
Easting:	603800		
Incident Cause:	OTHER CAUSE (N.O.S.)		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Preceding Spill:	
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	Multi Media Pollution
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Incident Reason:	OTHER
Incident Summary:	IKO INDUSTRIES:FIRE IN THERMAL OXIDIZER, BLACK SMOKE TO AIR
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

97	***23 of 58***	***ESE/92.8***	***219.8 / -12.63***	***IKO INDUSTRIES LTD.*** ***71 ORENDA ROAD*** ***BRAMPTON ON L6W 1V8***	***GEN***

Generator No:	ON0224400
SIC Code:	2721
SIC Description:	ASPHALT ROOFING IND.
Approval Years:	86,87,88,89
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

97	***24 of 58***	***ESE/92.8***	***219.8 / -12.63***	***IKO INDUSTRIES LTD.*** ***71 ORENDA ROAD*** ***BRAMPTON ON L6W 1V8***	***GEN***

Generator No:	ON0224400
SIC Code:	2721
SIC Description:	ASPHALT ROOFING IND.
Approval Years:	90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

97 | ***25 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD. 21-132***
71 ORENDA ROAD
BRAMPTON ON L6W 1V8 | ***GEN***

Generator No: ON0224400
SIC Code: 2721
SIC Description: ASPHALT ROOFING IND.
Approval Years: 92,93,94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

97 | ***26 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD***
71 ORENDA ROAD
BRAMPTON ON L6W 1V8 | ***GEN***

Generator No: ON0224400
SIC Code: 2721
SIC Description: ASPHALT ROOFING IND.
Approval Years: 97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	27 of 58	ESE/92.8	219.8 / -12.63	IKO INDUSTRIES LIMITED 71 ORENDA ROAD BRAMPTON ON L6W 1V8	GEN

Generator No: ON0224400
SIC Code: 2721
SIC Description: ASPHALT ROOFING IND.
Approval Years: 98,99,00,01,02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

97 | **28 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES**
71 ORENDA RD
BRAMPTON ON L6W 1V8 | **FSTH**

License Issue Date: 11/8/2000
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1980
Corrosion Protection:
Capacity: 500
Tank Fuel Type: Liquid Fuel Single Wall AST - Diesel

---

97 | **29 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO Industries Ltd.**
71 Orenda Road
Brampton ON L6W 1V8 | **SPL**

Ref No: 3148-5S4P2U
Year:
Incident Dt: 10/7/2003
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/7/2003
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: IKO INDUSTRIES
Site Address:
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Incident Cause: Process Upset
Incident Preceding Spill:
Environment Impact: Possible
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: other - see incident description
System Facility Address:
Client Name: IKO Industries Ltd.
Client Type:
Source Type:
Contaminant Code: 31
Contaminant Name: SMOKE
Contaminant Limit 1:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Gases/Particulate
Impact to Health:
Agency Involved:

Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Incident Reason: Gasket/Joint Failure - Any point of connection (Except Weld/Seam)
Incident Summary: IKO Industries - Fire on top of empty asphalt tank
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Notification
Call Report Locatn Geodata:

---

97 | ***30 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO Industries Ltd.***
71 Orenda Road
Brampton ON L6W 1V8 | ***SPL***

Ref No: 4311-5JHRD2
Year:
Incident Dt: 1/27/2003
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/27/2003
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: 71 ORENDA ROAD
Site Address:
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Incident Cause:
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name: IKO Industries Ltd.
Client Type:
Source Type:
Contaminant Code:
Contaminant Name: OIL (PETROLEUM BASED, NOT SPECIFIED)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason:
Incident Summary: IKO-410 L Heat Transfer Oil to Grnd.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Oil
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	31 of 58	ESE/92.8	219.8 / -12.63	IKO Industries Ltd. 71 Orenda Road Brampton ON L6W 1V8	SPL

Ref No:	6545-5ZRNRF	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	6/8/2004	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	Oil
MOE Reported Dt:	6/8/2004	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	IKO INDUSTRIES		
Site Address:			
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:	NA		
Easting:	NA		
Incident Cause:	Valve / Fitting Leak Or Failure		
Incident Preceding Spill:			
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:	Soil Contamination; Surface Water Pollution		
Contaminant Qty:	15 L		
System Facility Address:			
Client Name:	IKO Industries Ltd.		
Client Type:			
Source Type:			
Contaminant Code:	13		
Contaminant Name:	FUEL OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land & Water		
Incident Reason:	Equipment Failure		
Incident Summary:	IKO Industries - 15 L combustion oil to sewer.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Other Plant		
SAC Action Class:			
Call Report Locatn Geodata:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	32 of 58	ESE/92.8	219.8 / -12.63	IKO Industries 71 Orenda Road Brampton ON	SPL

Ref No:	5188-6NFU3W	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	4/1/2006	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/1/2006	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			

Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	IKO Industries
Site Address:	71 Orenda Road
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	NA
Incident Cause:	
Incident Preceding Spill:	
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	not specified l
System Facility Address:	
Client Name:	IKO Industries Ltd.
Client Type:	
Source Type:	other plant
Contaminant Code:	14
Contaminant Name:	ASPHALT
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	
Incident Summary:	IKO-Fire in Plant,Asphalt to Lot & Ditch
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	33 of 58	ESE/92.8	219.8 / -12.63	**IKO Industries** **71 Orenda Rd** **Brampton ON**	SPL

Ref No:	7623-6VDJ2Q	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11/9/2006	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/9/2006	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	IKO Industries		
Site Address:	71 Orenda Rd		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			

Easting:	NA
Incident Cause:	
Incident Preceding Spill:	
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	5000 L
System Facility Address:	
Client Name:	IKO Industries Ltd.
Client Type:	
Source Type:	Pulp and Paper (MISA)
Contaminant Code:	46
Contaminant Name:	PAPER FIBRES & WATER
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	
Incident Summary:	IKO: overflow of water/paper fibre holding tank
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

97	***34 of 58***	***ESE/92.8***	***219.8 / -12.63***	***GH International*** ***71 Orenda Road*** ***Brampton ON L6W 1V8***	***GEN***

Generator No:	ON6533712
SIC Code:	323119
SIC Description:	Other Printing
Approval Years:	06
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS

97	***35 of 58***	***ESE/92.8***	***219.8 / -12.63***	***IKO INDUSTRIES*** ***71 ORENDA RD*** ***BRAMPTON ON L6W 1V8***	***FSTH***

License Issue Date:	11/8/2000
Tank Status:	Licensed
Tank Status As Of:	December 2008
Operation Type:	Private Fuel Outlet
Facility Type:	Gasoline Station - Self Serve

--Details--

Status:	Active
Year of Installation:	1980
Corrosion Protection:	

Capacity: 500
Tank Fuel Type: Liquid Fuel Single Wall AST - Diesel

---

97 | ***36 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD***
71 ORENDA RD
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	9906346	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	398627	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Refill Cntr - Cylr Fill		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

---

97 | ***37 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***IKO INDUSTRIES LTD***
71 ORENDA RD
BRAMPTON ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10599662	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	28494	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	

Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

97	*38 of 58*	*ESE/92.8*	*219.8 / -12.63*	***IKO INDUSTRIES LIMITED*** ***71 ORENDA ROAD*** ***BRAMPTON ON L6W 1V8***	***GEN***

Generator No: ON0224400
SIC Code: 324122
SIC Description: Asphalt Shingle and Coating Material Manufacturing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

97	*39 of 58*	*ESE/92.8*	*219.8 / -12.63*	***IKO INDUSTRIES LIMITED*** ***71 ORENDA ROAD*** ***BRAMPTON ON L6W 1V8***	***GEN***

Generator No: ON0224400
SIC Code: 324122
SIC Description: Asphalt Shingle and Coating Material Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

97	40 of 58	ESE/92.8	219.8 / -12.63	IKO INDUSTRIES LIMITED 71 ORENDA ROAD BRAMPTON ON L6W 1V8	GEN

Generator No: ON0224400
SIC Code: 324122
SIC Description: Asphalt Shingle and Coating Material Manufacturing
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148

Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

---

97 | **41 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LTD**
71 ORENDA RD
BRAMPTON ON | **FST**

Inventory No: 11619281
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:

Tank Material: Steel
Corrosion Protect: Painted
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

97 | **42 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LIMITED**
71 ORENDA ROAD
BRAMPTON ON L6W 1V8 | **GEN**

Generator No: ON0224400
SIC Code: 324122
SIC Description: Asphalt Shingle and Coating Material Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

97	43 of 58	ESE/92.8	219.8 / -12.63	IKO INDUSTRIES LIMITED 71 ORENDA ROAD BRAMPTON ON	GEN

Generator No: ON0224400
SIC Code: 324122
SIC Description: ASPHALT SHINGLE AND COATING MATERIAL MANUFACTURING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

---

97 | **44 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LIMITED**
71 ORENDA ROAD
BRAMPTON ON L6W 1V8 | **GEN**

Generator No: ON0224400
SIC Code: 324122
SIC Description: ASPHALT SHINGLE AND COATING MATERIAL MANUFACTURING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: JOANNE C LAING
Choice of Contact: CO_ADMIN
Phone No Admin: 905 457 2880 Ext.2234
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 222
Waste Class Name: HEAVY FUELS

---

97 | **45 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LIMITED**
71 ORENDA ROAD
BRAMPTON ON L6W 1V8 | **GEN**

Generator No: ON0224400
SIC Code: 324122
SIC Description: ASPHALT SHINGLE AND COATING MATERIAL MANUFACTURING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: JOANNE C LAING
Choice of Contact: CO_ADMIN
Phone No Admin: 905 457 2880 Ext.2234
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

97 | **46 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LIMITED**
71 ORENDA ROAD
BRAMPTON ON L6W 1V8 | **GEN**

Generator No: ON0224400
SIC Code: 324122
SIC Description: ASPHALT SHINGLE AND COATING MATERIAL MANUFACTURING
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: JOANNE C LAING
Choice of Contact: CO_ADMIN
Phone No Admin: 905 457 2880 Ext.2234
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 111
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

97 | **47 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO INDUSTRIES LIMITED**
71 ORENDA ROAD
BRAMPTON ON L6W 1V8 | **GEN**

Generator No: ON0224400

SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 111 C
Waste Class Name: Spent pickle liquor

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 211 L
Waste Class Name: Aromatic solvents and residues

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 222 L
Waste Class Name: Heavy fuels

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 I
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	48 of 58	ESE/92.8	219.8 / -12.63	IKO INDUSTRIES LIMITED 71 ORENDA ROAD BRAMPTON ON L6W 1V8	GEN

Generator No: ON0224400
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 252 I
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 211 L
Waste Class Name: Aromatic solvents and residues

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 111 C
Waste Class Name: Spent pickle liquor

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 222 L
Waste Class Name: Heavy fuels

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 113 L
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

---

97 | **49 of 58** | **ESE/92.8** | **219.8 / -12.63** | **IKO Industries Ltd.**
71 Orenda Rd (IKO B2)
Brampton ON L6W 1V8 | **SPL**

Ref No: 6856-BDFSJ5
Year:
Incident Dt: 6/24/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/24/2019
Dt Document Closed:
Site No: 4868-4SZT3H
MOE Response:
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: 1-10 metres eg. Good Quality GPS
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: 71 Orenda Road
Site Address: 71 Orenda Rd (IKO B2)
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: GPS
Site Map Datum: NAD83
Northing: 4838550
Easting: 601322
Incident Cause:
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name: IKO Industries Ltd.
Client Type: Corporation
Source Type:
Contaminant Code:
Contaminant Name:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason:
Incident Summary: Odour complaint
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

97 | ***50 of 58*** | ***ESE/92.8*** | ***219.8 / -12.63*** | ***Flynn Canada Ltd.***
71 Orenda Road
Brampton ON | ***SPL***

Ref No: 5563-BBWPA4
Year:
Incident Dt: 5/6/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/6/2019
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Road and Private Property<UNOFFICIAL>
Site Address: 71 Orenda Road
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4838449
Easting: 601347
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 60 kg
System Facility Address:
Client Name: Flynn Canada Ltd.
Client Type: Corporation
Source Type: Truck - Tanker
Contaminant Code: 14
Contaminant Name: ASPHALT
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium: Land
Incident Reason: Unknown / N/A
Incident Summary: FlynnCanadaLtd: ~ 60 kg of hot asphalt to road, cntd, clnup ongng
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	51 of 58	ESE/92.8	219.8 / -12.63	IKO INDUSTRIES LTD 71 ORENDA RD BRAMPTON ON	INC

Incident No:	683050	Any Health Impact:	
Incident ID:		Any Enviro Impact:	
Instance No:	10312854	Service Intrp:	
Status Code:		Was Prop Damaged:	
Incident Status:	Non Mandated	Reside App. Type:	
Incident Severity:		Commer App. Type:	
Task No:		Indus App. Type:	
Attribute Category:	FS-Incident	Institut App. Type:	
Context:		Depth Ground Cover:	
Date of Occurrence:	11/4/2011	Operation Pressure:	
Time of Occurrence:		Equipment Type:	
Occr Insp Start Dt:		Equipment Model:	
Incident Creat On:	11/4/2011	Serial No:	
Instance Creat Dt:		Cylinder Capacity:	
Instance Install Dt:		Cylinder Cap Units:	
Approx Quant Rel:		Cylinder Mat Type:	
Tank Capacity:		Pump Flow Rate Cap:	
Fuels Occur Type:		Contam. Migrated:	
Occur Type Rpt:	Liquid Petroleum Spill	Near Body of Water:	
Occur Category:		Drainage System:	
Fuel Type Involved:		Sub Surface Contam:	
Fuel Type Reported:	Transportation Fuel	Tank Material Type:	
Enforcement Policy:		Tank Storage Type:	
Prc Escalation Req:		Tank Location Type:	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	71 ORENDA RD		
Invent Postal Code:	L6W 1V8		
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:			
Operation Type Involved:	Private Fuel Outlet		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	52 of 58	ESE/92.8	219.8 / -12.63	IKO Industries Ltd. 71 Orenda Rd Brampton ON L6W 1V8	SPL

Ref No:	1348-BQTLDD	Municipality No:	
Year:		Nature of Damage:	
Incident Dt:	2020/06/22	Discharger Report:	
Dt MOE Arvl on Scn:		Material Group:	
MOE Reported Dt:	2020/06/22	Impact to Health:	2 - Minor Environment
Dt Document Closed:		Agency Involved:	
Site No:	6995-9T7NLC		

MOE Response:	No
Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	NA
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	IKO Industries Ltd.
Site Address:	71 Orenda Rd
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	NA
Site Geo Ref Accu:	NA
Site Map Datum:	NA
Northing:	NA
Easting:	NA
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	52000 kg
System Facility Address:	
Client Name:	IKO Industries Ltd.
Client Type:	Corporation
Source Type:	Tank - Above Ground
Contaminant Code:	14
Contaminant Name:	ASPHALT
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Land
Incident Reason:	Equipment Failure
Incident Summary:	IKO: asphalt spill to containment area, 58 tons
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	

97	***53 of 58***	***ESE/92.8***	***219.8 / -12.63***	***IKO INDUSTRIES LIMITED 71 ORENDA ROAD BRAMPTON ON L6W 1V8***	***GEN***

Generator No:	ON0224400
SIC Code:	
SIC Description:	
Approval Years:	As of Nov 2021
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	148 A
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	263 I

Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 211 L
Waste Class Name: Aromatic solvents and residues

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 252 I
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 113 L
Waste Class Name: Acid solutions - containing other metals and non-metals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 252 T
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 253 L
Waste Class Name: Emulsified oils

Waste Class: 111 C
Waste Class Name: Spent pickle liquor

Waste Class: 222 L
Waste Class Name: Heavy fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 148 L
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 221 L
Waste Class Name: Light fuels

97	***54 of 58***	***ESE/92.8***	***219.8 / -12.63***	***IKO Industries Ltd.*** ***71 Orenda Rd*** ***Brampton ON L6W 1V8***	***SPL***

Ref No: 7267-BQEQBE
Year:
Municipality No:
Nature of Damage:

Incident Dt:	2020/06/09	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2020/06/09	**Impact to Health:**	0 - No Impact
Dt Document Closed:		**Agency Involved:**	

Site No: 6995-9T7NLC
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: IKO Industries Ltd.
Site Address: 71 Orenda Rd
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Incident Cause:
Incident Preceding Spill: Overflow/Surcharge
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 260 L
System Facility Address:
Client Name: IKO Industries Ltd.
Client Type: Corporation
Source Type: Tank - Above Ground
Contaminant Code: 14
Contaminant Name: LIQUID ASPHALT (LIQUID TARS)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1999
Receiving Medium: Land
Incident Reason: Weather Conditions
Incident Summary: IKO: ~ 260 L of liquid asphalt to containment area on site, clnup ongng
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	55 of 58	ESE/92.8	219.8 / -12.63	IKO INDUSTRIES LIMITED 71 ORENDA ROAD BRAMPTON ON L6W 1V8	GEN

Generator No: ON0224400
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 T
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252 I
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 148 A
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211 L
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 111 C
Waste Class Name: SPENT PICKLE LIQUOR

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 113 L
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 121 C
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 263 A
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148 L
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 253 L
Waste Class Name: EMULSIFIED OILS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 222 L
Waste Class Name: HEAVY FUELS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	56 of 58	ESE/92.8	219.8 / -12.63	71 Orenda Rd. Brampton, ON. BRAMPTON ON	SPL

Ref No:	1-1A5TAL	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/24/2021 3:00:00 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/24/2021 8:26:33 AM	**Impact to Health:**	0 No Impact
Dt Document Closed:	11/30/2021 3:36:31 PM	**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	71 Orenda Rd. Brampton, ON.		
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Environment Impact:	1 Minor Impact		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	6 tonne (t)		
System Facility Address:			
Client Name:			
Client Type:			
Source Type:	Tank - Above Ground		
Contaminant Code:			
Contaminant Name:	ASPHALT		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Incident Reason:	Equipment failure/malfunction		
Incident Summary:	IKO: Aphalt Flux to Contaiment Area		
Activity Preceding Spill:	Normal operations		
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula		
Property Tertiary Watershed:	02HC-Humber - Don		
Sector Type:	ASPHALT PAVING MIXTURE AND BLOCK MANUFACTURING		
SAC Action Class:			
Call Report Locatn Geodata:	{"integration_ids":["PR00001791272"],"wkts":["POINT (-79.7422658000 43.6925245000)"],"creation_date":"2021-09-24"}		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	57 of 58	ESE/92.8	219.8 / -12.63	71 Orenda Rd, Brampton, ON L6W 1V8 BRAMPTON ON	SPL

Ref No:	1-Y6BP2	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	7/15/2021 11:00:04 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	7/16/2021 3:22:58 PM	**Impact to Health:**	0 No Impact
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			

Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	
Site Address:	71 Orenda Rd, Brampton, ON L6W 1V8
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	0 No Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Unknown
Incident Summary:	IKO industries: liquid asphalt, 760L to containment area, cleaning
Activity Preceding Spill:	
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HC-Humber - Don
Sector Type:	ASPHALT PAVING MIXTURE AND BLOCK MANUFACTURING
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001791272"],"wkts":["POINT (-79.7422658000 43.6925245000)"],"creation_date":"2021-07-16"}

97	58 of 58	ESE/92.8	219.8 / -12.63	71 Orenda Rd, Brampton ON	SPL

Ref No:	1-1EGWYS	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11/12/2021 1:30:00 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/12/2021 2:41:16 PM	**Impact to Health:**	0 No Impact
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:			
Site Name:			
Site Address:	71 Orenda Rd, Brampton		
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Preceding Spill:	
Environment Impact:	0 No Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	10000 litre (L)
System Facility Address:	
Client Name:	IKO INDUSTRIES LTD
Client Type:	Private Business
Source Type:	
Contaminant Code:	
Contaminant Name:	ASPHALT EMULSION
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	
Incident Summary:	IKO - est 10,000L of liquid asphalt to containment area
Activity Preceding Spill:	Loading and Unloading
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HC-Humber - Don
Sector Type:	ASPHALT PAVING MIXTURE AND BLOCK MANUFACTURING
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001791272"],"wkts":["POINT (-79.7422658000 43.6925245000)","POINT (-79.7422658000 43.6925245000)"],"creation_date":"2021-11-12"}

98	***1 of 2***	***ESE/51.2***	***217.7 / -14.83***	***SAFE SELF STORAGE*** ***17 ARDGLEN DRIVE*** ***BRAMPTON ON L6W 1V1***	***GEN***

Generator No:	ON2018700
SIC Code:	4799
SIC Description:	OTHER STOR./WARE.
Approval Years:	95,96,97
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES

98	***2 of 2***	***ESE/51.2***	***217.7 / -14.83***	***SAFE SELF STORAGE(OUT OF BUSINESS)*** ***17 ARDGLEN DRIVE*** ***BRAMPTON ON L6W 1V1***	***GEN***

Generator No:	ON2018700
SIC Code:	4799
SIC Description:	OTHER STOR./WARE.
Approval Years:	98,99
PO Box No:	
Country:	
Status:	
Co Admin:	

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

99 | ***1 of 4*** | ***ESE/38.6*** | ***216.9 / -15.56*** | ***CANADIAN PLASTICS CONCENTRATED LTD ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4*** | ***GEN***

Generator No: ON0242901
SIC Code: 0000
SIC Description: *** NOT DEFINED ***
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

99 | ***2 of 4*** | ***ESE/38.6*** | ***216.9 / -15.56*** | ***CANADIAN PLASTICS(OUT OF BUS) ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4*** | ***GEN***

Generator No: ON0242901
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

99 | ***3 of 4*** | ***ESE/38.6*** | ***216.9 / -15.56*** | ***CANADIAN PLASTICS(OUT OF BUS) 08-301 ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4*** | ***GEN***

Generator No: ON0242901
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
99	4 of 4	ESE/38.6	216.9 / -15.56	CANADIAN PLASTICS(OUT OF BUSINESS) ARGO DIVISION 67 KENNEDY ROAD, SOUTH BRAMPTON ON L6W 3E4	GEN

Generator No: ON0242901
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
100	1 of 10	ESE/65.2	216.2 / -16.30	BUDGET RENT A CAR 73 KENNEDY ROAD SOUTH BRAMPTON ON L6V 3E4	GEN

Generator No: ON0386607
SIC Code: 9921
SIC Description: AUTO./TRUCK RENTAL
Approval Years: 92,93,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
100	2 of 10	ESE/65.2	216.2 / -16.30	BUDGET RENT A CAR O/A BRL REALTY 05-696 73 KENNEDY ROAD SOUTH, BRAMPTON C/O 5905 CAMPUS ROAD MISSISSAUGA ON L6W 3E4	GEN

Generator No: ON0386607
SIC Code: 9921
SIC Description: AUTO./TRUCK RENTAL
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
100	3 of 10	ESE/65.2	216.2 / -16.30	BUDGET RENT A CAR 73 KENNEDY RD S BRAMPTON ON L6W 3E4	FSTH

License Issue Date: 11/26/1990
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 45460
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
100	4 of 10	ESE/65.2	216.2 / -16.30	BUDGET RENT A CAR 73 KENNEDY RD S BRAMPTON ON L6W 3E4	FSTH

License Issue Date: 11/26/1990
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 45460
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1984
Corrosion Protection:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

---

100 **5 of 10** **ESE/65.2** **216.2 / -16.30** **BUDGET RENT A CAR**
73 KENNEDY RD S
BRAMPTON ON
FST

Inventory No: 10596724
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

100 **6 of 10** **ESE/65.2** **216.2 / -16.30** **BUDGET RENT A CAR**
73 KENNEDY RD S
BRAMPTON ON
FST

Inventory No: 10596772
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

100 **7 of 10** **ESE/65.2** **216.2 / -16.30** **Budget Rental Car**
73 Kennedy Rd S
Brampton ON
GEN

Generator No: ON5449122
SIC Code: 488490
SIC Description: Other Support Activities for Road Transportation
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

100 **8 of 10** **ESE/65.2** **216.2 / -16.30** **BRL REALTY LIMITED**
73 KENNEDY ROAD SOUTH
BRAMPTON ON L6W3E4
GEN

Generator No: ON2922925
SIC Code: 419120
SIC Description: PETROLEUM PRODUCT AGENTS AND BROKERS, WHOLESALE TRADE AGENTS AND BROKERS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: RAFFAELE TOMASONE

Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-417-0011 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

100 | **9 of 10** | **ESE/65.2** | **216.2 / -16.30** | **Budget Rental Car**
73 Kennedy Rd S
Brampton ON L6W 3E4 | **GEN**

Generator No: ON5449122
SIC Code: 488490
SIC Description: OTHER SUPPORT ACTIVITIES FOR ROAD TRANSPORTATION
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

100 | **10 of 10** | **ESE/65.2** | **216.2 / -16.30** | **Budget Rental Car**
73 Kennedy Rd S
Brampton ON L6W 3E4 | **GEN**

Generator No: ON5449122
SIC Code: 488490
SIC Description: OTHER SUPPORT ACTIVITIES FOR ROAD TRANSPORTATION
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Trevor Howard
Choice of Contact: CO_OFFICIAL
Phone No Admin: 705 725 0940 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
101	1 of 2	ESE/92.3	215.8 / -16.63	NATHAN PHARMACY 147 Clarance Street, Unit 30 Brampton ON L6W 1T2	GEN

Generator No: ON6525268
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
101	2 of 2	ESE/92.3	215.8 / -16.63	NATHAN PHARMACY 147 Clarance Street, Unit 30 Brampton ON L6W 1T2	GEN

Generator No: ON6525268
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
102	1 of 1	ESE/67.4	215.8 / -16.63	MANUEL FILIPE & FERNANDO MELO SERV CENTRE LTD 149 CLARENCE ST BRAMPTON ON L6W 1T2	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9517024 **Expired Date:** 5/8/1992

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

103	1 of 2	WNW/10.3	257.2 / 24.77	**Hurontario Street and Inglewood Drive, Mississauga CALEDON;BRAMPTON ON**	SPL

Ref No:	1-18RRTU	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/9/2021 12:30:00 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/9/2021 2:53:59 PM	**Impact to Health:**	0 No Impact
Dt Document Closed:	9/13/2021 8:28:26 AM	**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel District Office		
Nearest Watercourse:	Credit River		
Site Name:			
Site Address:	Hurontario Street and Inglewood Drive, Mississauga		
Site Region:	REGIONAL MUNICIPALITY OF PEEL		
Site Municipality:	CALEDON;BRAMPTON		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:	Other (specify)		
Environment Impact:	2 Minor Impact &/or Mortality		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	2000 litre (L)		
System Facility Address:			
Client Name:	MOBILINX HURONTARIO SERVICES LTD.		
Client Type:	Private Business		
Source Type:	Sewer (Private or Municipal)		

Contaminant Code:
Contaminant Name: STORM WATER WITH SUSPENDED SOLIDS
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land; Surface Water
Incident Reason: Lack of training
Incident Summary: Mobilinx: 2,000L raw sewage to road and cb
Activity Preceding Spill: Construction or repair
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HC-Humber - Don
Sector Type: HIGHWAY, STREET AND BRIDGE CONSTRUCTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00002407601"],"wkts":["POINT (-79.8294686000 43.7372797000)"],"creation_date":"2021-09-09"}

---

103 | **2 of 2** | **WNW/10.3** | **257.2 / 24.77** | **Hurontario St & Steeles Ave, Brampton CALEDON;BRAMPTON ON** | **SPL**

Ref No: 1-14CDCA
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/26/2021 12:40:33 PM
Dt Document Closed: 8/26/2021 1:20:59 PM
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: Hurontario St & Steeles Ave, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: CALEDON;BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Unknown / N/A
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 litre (L)
System Facility Address:
Client Name:
Client Type:
Source Type: Truck - Transport/Hauling
Contaminant Code:
Contaminant Name: GREASE (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason:
Incident Summary: Region of Peel: garbage juice / grease on roadway
Activity Preceding Spill: Unknown
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HC-Humber - Don
Sector Type:
SAC Action Class:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Call Report Locatn Geodata:		{"integration_ids":["PR00002407601"],"wkts":["POINT (-79.8294686000 43.7372797000)"],"creation_date":"2021-08-26"}			

104 **1 of 18** **ESE/92.7** **215.8 / -16.63** **SMARTES CLEANER**
50 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3R7 **GEN**

Generator No: ON2287700
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS
Approval Years: 97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

104 **2 of 18** **ESE/92.7** **215.8 / -16.63** **SMARTEX DRY CLEANERS**
50 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3R7 **GEN**

Generator No: ON2287700
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

104 **3 of 18** **ESE/92.7** **215.8 / -16.63** **SMARTEX DRY CLEANERS**
50 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3R7 **GEN**

Generator No: ON2287700
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

104 ***4 of 18*** ***ESE/92.7*** ***215.8 / -16.63*** ***SMARTEX DRY CLEANERS 50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7*** ***GEN***

Generator No: ON2287700
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

104 ***5 of 18*** ***ESE/92.7*** ***215.8 / -16.63*** ***SMARTEX DRY CLEANERS 50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7*** ***GEN***

Generator No: ON2287700
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

104 ***6 of 18*** ***ESE/92.7*** ***215.8 / -16.63*** ***SMARTEX DRY CLEANERS 50 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3R7*** ***GEN***

Generator No: ON2287700
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2012
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	7 of 18	ESE/92.7	215.8 / -16.63	**Smartex Cleaners** **29- 50 Kennedy Road South** **Brampton ON**	GEN

Generator No: ON7941303
SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	8 of 18	ESE/92.7	215.8 / -16.63	**2466102 Ontario Inc o/a Smartex Cleaners** **50 Kennedy Road South** **Brampton ON L6W 3R7**	GEN

Generator No: ON7670877
SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	9 of 18	ESE/92.7	215.8 / -16.63	**Smartex Cleaners** **29- 50 Kennedy Road South** **Brampton ON L6W 3R7**	GEN

Generator No:	ON7941303
SIC Code:	812320
SIC Description:	DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years:	2015
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

---

104 ***10 of 18*** ***ESE/92.7*** ***215.8 / -16.63*** ***Smartex Cleaners***
29- 50 Kennedy Road South
Brampton ON L6W 3R7 ***GEN***

Generator No:	ON7941303
SIC Code:	812320
SIC Description:	DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)
Approval Years:	2014
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

---

104 ***11 of 18*** ***ESE/92.7*** ***215.8 / -16.63*** ***2466102 Ontario Inc o/a Smartex Cleaners***
50 Kennedy Road South
Brampton ON L6W 3R7 ***GEN***

Generator No:	ON7670877
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	241 H
Waste Class Name:	Halogenated solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	12 of 18	ESE/92.7	215.8 / -16.63	Smartex Dry Cleaners 50 Kennedy Rd S #29 Brampton ON L6W3R7	CDRY

Legal Name of Company: 2466102 Ontario Inc.
Region: Ontario
Type of Reporter:

Waste Quantity by Year

Reporting Year: 2019
Quantity of PERC (kg): 365
Total Waste Water (kg): 0
Total Waste Water (L): 80
Total Residue (kg): 0
Total Residue (L): 114
Total Mix (kg): 0
Total Mix (L): 0
Request for Confidentiality: no
Reason For Confidentiality:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	13 of 18	ESE/92.7	215.8 / -16.63	2466102 Ontario Inc o/a Smartex Cleaners 50 Kennedy Road South Brampton ON L6W 3R7	GEN

Generator No: ON7670877
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 H
Waste Class Name: Halogenated solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	14 of 18	ESE/92.7	215.8 / -16.63	Exquizeet Tattoo & Piercing Studio 50 Kennedy Road South, Unit 20C Kennedy Square Mall Brampton ON L6W3R7	GEN

Generator No: ON7895933
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
104	***15 of 18***	***ESE/92.7***	***215.8 / -16.63***	***2466102 Ontario Inc o/a Smartex Cleaners*** ***50 Kennedy Road South*** ***Brampton ON L6W 3R7***	***GEN***
Generator No:		ON7670877			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		241 H			
Waste Class Name:		Halogenated solvents and residues			
104	***16 of 18***	***ESE/92.7***	***215.8 / -16.63***	***Exquizeet Tattoo & Piercing Studio*** ***50 Kennedy Road South, Unit 20C Kennedy Square Mall*** ***Brampton ON L6W3R7***	***GEN***
Generator No:		ON7895933			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
104	***17 of 18***	***ESE/92.7***	***215.8 / -16.63***	***2466102 Ontario Inc o/a Smartex Cleaners*** ***50 Kennedy Road South*** ***Brampton ON L6W 3R7***	***GEN***
Generator No:		ON7670877			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241 H
Waste Class Name: HALOGENATED SOLVENTS

---

104 | ***18 of 18*** | ***ESE/92.7*** | ***215.8 / -16.63*** | ***Exquizeet Tattoo & Piercing Studio***
50 Kennedy Road South, Unit 20C Kennedy Square Mall
Brampton ON L6W3R7 | ***GEN***

Generator No: ON7895933
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

105 | ***1 of 1*** | ***ESE/60.8*** | ***214.8 / -17.63*** | ***Sure Print & Copy Centre***
83 Kennedy Rd S Unit 12
Brampton ON L6W 3P3 | ***SCT***

Established: 2000
Plant Size (ft²):
Employment: 2

--Details--
Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

Description: Office Supplies (except Paper) Manufacturing
SIC/NAICS Code: 339940

Description: Document Preparation Services
SIC/NAICS Code: 561410

Description: Business Service Centres
SIC/NAICS Code: 561430

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
106	1 of 1	WNW/83.5	255.0 / 22.50	2205302 Ontario Limited 12197 Hurontario Street Brampton ON L6Z 4P8	GEN

Generator No: ON8754994
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
107	1 of 1	ESE/31.4	214.8 / -17.63	84 Kennedy Road South Brampton ON L6W 3E7	SPL

Ref No: 5652-8F6MG4
Year:
Incident Dt: 3/21/2011
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/21/2011
Dt Document Closed: 5/19/2011
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Brampton Auto Service<UNOFFICIAL>
Site Address: 84 Kennedy Road South
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Pipe Or Hose Leak
Incident Preceding Spill:
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 40 L
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code: 15
Contaminant Name: OIL (PETROLEUM BASED, NOT SPECIFIED)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Spill
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Incident Summary:		Brampton Auto Service: 40L oil to ground, clning			
Activity Preceding Spill:					
Property 2nd Watershed:					
Property Tertiary Watershed:					
Sector Type:		Other			
SAC Action Class:		Land Spills			
Call Report Locatn Geodata:					

108	1 of 3	ESE/19.1	214.8 / -17.63	RADMAN THE 90 KENNEDY RD. SOUTH BRAMPTON ON L6W 3E7	GEN

Generator No:	ON1026700
SIC Code:	0000
SIC Description:	*** NOT DEFINED ***
Approval Years:	88,89,90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

108	2 of 3	ESE/19.1	214.8 / -17.63	RADMAN THE 32-149 90 KENNEDY RD. SOUTH BRAMPTON ON L6W 3E7	GEN

Generator No:	ON1026700
SIC Code:	0000
SIC Description:	*** NOT DEFINED ***
Approval Years:	92,93,94
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

108	3 of 3	ESE/19.1	214.8 / -17.63	RADMAN, THE 90 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3E7	GEN

Generator No:	ON1026700
SIC Code:	6359
SIC Description:	OTHER VEH. REPAIR
Approval Years:	99,00,01
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

109	1 of 1	ESE/53.6	213.8 / -18.63	Rice Development 95 Kennedy Rd Brampton ON L6W 3G2	SPL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No: 8401-BBJH6G
Year:
Incident Dt: 12/1/2018
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/11/2019
Dt Document Closed: 5/18/2019
Site No: 7592-95JJW7
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Rice Development
Site Address: 95 Kennedy Rd
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Incident Cause:
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name: Rice Development
Client Type: Corporation
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason:
Incident Summary: PIR: possible waste oil dumping
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	1 of 2	ESE/18.9	213.8 / -18.64	GPrint 96 Kennedy Rd S Brampton ON L6W 3E7	SCT

Established: 01-AUG-94
Plant Size (ft²):
Employment:

--Details--
Description: Digital Printing
SIC/NAICS Code: 323115

Description: Business Service Centres
SIC/NAICS Code: 561430

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	2 of 2	ESE/18.9	213.8 / -18.64	Ziebart 96 Kennedy Road South Brampton ON L6W 3E7	GEN

Generator No: ON4449972
SIC Code: 811111
SIC Description: General Automotive Repair
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
111	1 of 10	ESE/89.1	212.8 / -19.63	MACTAC CANADA LTD. 100 KENNEDY ROAD SOUTH BRAMPTON PLANT 100 KENNEDY ROAD SOUTH BRAMPTON CITY ON L6W 3E8	SPL

Ref No: 104905
Year:
Incident Dt: 9/6/1994
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/6/1994
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: CONTAINER OVERFLOW
Incident Preceding Spill:
Environment Impact: CONFIRMED
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: F.D. REGION OF PEEL

Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND / WATER
Incident Reason: NEGLIGENCE (APPARENT)
Incident Summary: MACTAC CANADA LTD: UNK QTY WASTE CHEMICALS TO GROUND & STORM SEWER.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

111 ***2 of 10*** ***ESE/89.1*** ***212.8 / -19.63*** ***MACTAC CANADA LTD.***
100 KENNEDY RD S
BRAMPTON ON L6W 3E8 ***SCT***

Established: 1963
Plant Size (ft²): 175000
Employment: 75

--Details--
Description: Stationery and Office Supplies Wholesaler-Distributors
SIC/NAICS Code: 418210

Description: Other Paper and Disposable Plastic Product Wholesaler-Distributors
SIC/NAICS Code: 418220

Description: COATED AND LAMINATED PAPER, NOT ELSEWHERE CLASSIFED
SIC/NAICS Code: 2672

Description: STATIONERY, TABLETS, AND RELATED PRODUCTS
SIC/NAICS Code: 2678

Description: CONVERTED PAPER AND PAPERBOARD PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2679

Description: UNSUPPORTED PLASTICS FILM AND SHEET
SIC/NAICS Code: 3081

Description: Paper Bag and Coated and Treated Paper Manufacturing
SIC/NAICS Code: 322220

Description: Stationery Product Manufacturing
SIC/NAICS Code: 322230

Description: All Other Converted Paper Product Manufacturing
SIC/NAICS Code: 322299

Description: Unsupported Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

---

111 ***3 of 10*** ***ESE/89.1*** ***212.8 / -19.63*** ***MACTAC CANADA LTD.***
100 KENNEDY RD SOUTH. BRAMPTON PLANT
100 KENNEDY ROAD SOUTH
BRAMPTON CITY ON L6W 3E8 ***SPL***

Ref No: 133632 ***Municipality No:*** 21101
Year: ***Nature of Damage:***

Incident Dt:	//	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/29/1996	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Environment Impact:	POSSIBLE		
Health Env Consequence:			
Nature of Impact:	Air Pollution		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	AIR		
Incident Reason:	UNKNOWN		
Incident Summary:	MACTAC CANADA-405 L TO- LUENE FOUND ON ROOF FROM INDOOR TANK VENTS, SHELL.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

111	*4 of 10*	***ESE/89.1***	***212.8 / -19.63***	***MACTAC CANADA LTD/LTEE*** ***100 KENNEDY RD. S.*** ***BRAMPTON ON L6W 3E8***	***GEN***

Generator No:	ON0117800
SIC Code:	3792
SIC Description:	ADHESIVES INDUSTRY
Approval Years:	86,87,88,89,90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

---

111 **5 of 10** **ESE/89.1** **212.8 / -19.63** **MACTAC CANADA LTD/LTEE 25-009**
100 KENNEDY RD. S.
BRAMPTON ON L6W 3E8
GEN

Generator No: ON0117800
SIC Code: 3792
SIC Description: ADHESIVES INDUSTRY
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 231
Waste Class Name: LATEX WASTES

---

111 **6 of 10** **ESE/89.1** **212.8 / -19.63** **MACTAC CANADA LTD./LTEE.**
100 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3E8
GEN

Generator No: ON0117800
SIC Code: 3792
SIC Description: ADHESIVES INDUSTRY
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

---

111 | ***7 of 10*** | ***ESE/89.1*** | ***212.8 / -19.63*** | ***MACTAC CANADA LTD./LTEE.***
100 KENNEDY RD. S.
BRAMPTON ON L6W 3E8 | ***GEN***

Generator No: ON0117800
SIC Code:
SIC Description:
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

---

111 | ***8 of 10*** | ***ESE/89.1*** | ***212.8 / -19.63*** | ***MACtac, Bemis***
100 Kennedy Road S.
Brampton ON L6W 3E8 | ***GEN***

Generator No: ON9093288
SIC Code:
SIC Description:
Approval Years: 04,05
PO Box No:
Country:
Status:

Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

111 | ***9 of 10*** | ***ESE/89.1*** | ***212.8 / -19.63*** | ***CROSS CANADA AUTO BODY SUPPLY LTD***
100 KENNEDY RD S
BRAMPTON ON L6W 3E8 | ***AUWR***

Headcode: 00096400
Headcode Desc: AUTOMOBILE PARTS & SUPPLIES-USED & REBUILT
Phone:
List Name:
Description:

---

111 | ***10 of 10*** | ***ESE/89.1*** | ***212.8 / -19.63*** | ***100 KENNEDY ROAD SOUTH, BRAMPTON ON*** | ***INC***

Incident No: 1998722
Incident ID:
Instance No:
Status Code:
Incident Status:
Incident Severity:
Task No: 6578048
Attribute Category: FS-Perform L1 Incident Insp
Context:
Date of Occurrence: 2028/12/12 00:00:00
Time of Occurrence: 11:00:00
Occr Insp Start Dt: 2028/12/12 00:00:00
Incident Creat On:
Instance Creat Dt:
Instance Install Dt:
Approx Quant Rel:
Tank Capacity:
Fuels Occur Type: CO Release
Occur Type Rpt:
Occur Category:
Fuel Type Involved: Propane
Fuel Type Reported:
Enforcement Policy: NULL
Prc Escalation Req: NULL
Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:

Any Health Impact: No
Any Enviro Impact: No
Service Intrp: Yes
Was Prop Damaged: No
Reside App. Type:
Commer App. Type:
Indus App. Type:
Institut App. Type:
Depth Ground Cover:
Operation Pressure:
Equipment Type:
Equipment Model:
Serial No:
Cylinder Capacity:
Cylinder Cap Units:
Cylinder Mat Type:
Pump Flow Rate Cap:
Contam. Migrated:
Near Body of Water:
Drainage System:
Sub Surface Contam:
Tank Material Type:
Tank Storage Type:
Tank Location Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 100 KENNEDY ROAD SOUTH, BRAMPTON - CO RELEASE
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: Hi CO output from 4 propane operated lift trucks
Operation Type Involved: Commercial (e.g. restaurant, business unit, etc)

---

112 | ***1 of 12*** | ***WNW/86.6*** | ***256.5 / 23.99*** | ***TRAVELWAYS SCHOOL TRANSIT LTD***
12267 HUONTARIO STREET
SNELGROVE ON L0P 1M0 | ***GEN***

Generator No: ON0222805
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

112 | ***2 of 12*** | ***WNW/86.6*** | ***256.5 / 23.99*** | ***LAIDLAW TRANSIT LTD.***
12267 HURONTARIO ST.
SNELGROVE ON L0P 1M0 | ***GEN***

Generator No: ON0222805
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

112 | ***3 of 12*** | ***WNW/86.6*** | ***256.5 / 23.99*** | ***LAIDLAW TRANSIT LTD.***
12267 HURONTARIO ST., SNELGROVE C/O 30 HERITAGE RD.
MARKHAM ON L3P 1M4 | ***GEN***

Generator No: ON0222805
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

112 | ***4 of 12*** | ***WNW/86.6*** | ***256.5 / 23.99*** | ***LAIDLAW TRANSIT LTD. 38-034***
12267 HURONTARIO STREET
BRAMPTON ON L6V 1A1 | ***GEN***

Generator No: ON0222805
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 92,93,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

112 **5 of 12** **WNW/86.6** **256.5 / 23.99**

LAIDLAW TRANSIT LTD. 38-034
12267 HURONTARIO ST. C/O R.R. #2
BRAMPTON ON L6V 1A1

GEN

Generator No: ON0222805
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 94
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

112 **6 of 12** **WNW/86.6** **256.5 / 23.99**

LAIDLAW TRANSIT LTD
12267 HURONTARIO STREET
BRAMPTON ON L6V 1A1

GEN

Generator No: ON0222805
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

112 | ***7 of 12*** | ***WNW/86.6*** | ***256.5 / 23.99*** | ***LAIDLAW TRANSIT LTD.***
12267 HURONTARIO STREET
BRAMPTON ON L6V 1A1 | ***GEN***

Generator No: ON0222805
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

112 | ***8 of 12*** | ***WNW/86.6*** | ***256.5 / 23.99*** | ***LAIDLAW TRANSIT LTD.***
12267 HURONTARIO STREET R.R.#2
BRAMPTON ON L6V 1A1 | ***GEN***

Generator No: ON0222805
SIC Code: 485410
SIC Description: School & Employee Bus Transportation
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

112 | ***9 of 12*** | ***WNW/86.6*** | ***256.5 / 23.99*** | ***Ministry of Transportation***
12267 Hurontario Street RR#2 Part Lot 19 1EHS
Brampton ON L6V 1A0 | ***GEN***

Generator No: ON6794884
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

112 | ***10 of 12*** | ***WNW/86.6*** | ***256.5 / 23.99*** | ***TRAVELWAYS LTD***
12267 HURONTARIO ST
SNELGROVE ON | ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9973530
Status: EXPIRED
Instance ID: 397339
Instance Type: FS Facility
Instance Creation Dt:
Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Refill Cntr - Cylr Fill
Original Source: EXP
Record Date: Up to Mar 2012
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

112	11 of 12	WNW/86.6	256.5 / 23.99	LAIDLAW TRANSIT LTD 12267 HURONTARIO ST BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10224030
Status: EXPIRED
Instance ID: 14359
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Vehicle Conv Centre
Original Source: EXP
Record Date: Up to Mar 2012
Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
112	12 of 12	WNW/86.6	256.5 / 23.99	TRAVELWAYS LTD 12267 HURONTARIO ST SNELGROVE ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11124645	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	70096	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Tank		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
113	1 of 2	ESE/14.8	212.2 / -20.26	PEEL FENCE SYSTEMS INC. 110 KENNEDY RD S UNIT A BRAMPTON ON L6W 3E7	SCT

Established:	1970
Plant Size (ft²):	0
Employment:	15

--Details--

Description:	MISCELLANEOUS FABRICATED WIRE PRODUCTS
SIC/NAICS Code:	3496

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
113	2 of 2	ESE/14.8	212.2 / -20.26	P.F.S. FENCE INC. 110 Kennedy Rd S Unit A Brampton ON L6W 3E7	SCT

Established:	1970
Plant Size (ft²):	0
Employment:	15

--Details--

Description:	Cutlery and Hand Tool Manufacturing
SIC/NAICS Code:	332210

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
114	1 of 2	ESE/59.7	211.8 / -20.63	THE DOOR FACTORY II 114 KENNEDY RD S BRAMPTON ON L6W 3E7	SCT

Established: 1956
Plant Size (ft²): 18000
Employment: 20

--Details--
Description: MILLWORK
SIC/NAICS Code: 2431

Description: PREFABRICATED WOOD BUILDINGS AND COMPONENTS
SIC/NAICS Code: 2452

Description: METAL DOORS, SASH, FRAMES, MOLDING, AND TRIM
SIC/NAICS Code: 3442

Description: Wood Window and Door Manufacturing
SIC/NAICS Code: 321911

Description: Metal Window and Door Manufacturing
SIC/NAICS Code: 332321

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
114	2 of 2	ESE/59.7	211.8 / -20.63	Baba Gifts and Distributors 114 Kennedy Rd S Brampton ON L6W 3E7	SCT

Established: 01-AUG-90
Plant Size (ft²): 10000
Employment:

--Details--
Description: Pottery, Ceramics and Plumbing Fixture Manufacturing
SIC/NAICS Code: 327110

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
115	1 of 2	ESE/78.0	211.8 / -20.63	The Regional Municipality of Peel 107 Kennedy Rd. South Brampton ON	SPL

Ref No: 8077-BB84FU
Year:
Incident Dt: 4/13/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/13/2019
Dt Document Closed: 5/18/2019
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Name:	Commercial Plaza<UNOFFICIAL>
Site Address:	107 Kennedy Rd. South
Site Region:	Central
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	4837804.12
Easting:	601758.4
Incident Cause:	
Incident Preceding Spill:	Overflow/Surcharge
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	The Regional Municipality of Peel
Client Type:	Municipal Government
Source Type:	Sewer (Private or Municipal)
Contaminant Code:	44
Contaminant Name:	SEWAGE,RAW UNCHLORINATED
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	n/a
Receiving Medium:	Land; Surface Water
Incident Reason:	Blockage
Incident Summary:	Region of Peel: Private-Side Sewer Backup
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Miscellaneous Industrial
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

---

115 | ***2 of 2*** | ***ESE/78.0*** | ***211.8 / -20.63*** | ***107 Kennedy Road South Brampton, ON BRAMPTON ON*** | ***SPL***

Ref No:	1-3SXOW7	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	9/3/2023 7:03:21 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	9/3/2023 7:29:21 PM	**Impact to Health:**	
Dt Document Closed:	9/5/2023 2:59:59 PM	**Agency Involved:**	

Site No:	
MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	
Site Address:	107 Kennedy Road South Brampton, ON
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	
Environment Impact:	
Health Env Consequence:	

Nature of Impact:	
Contaminant Qty:	0 other - see notes
System Facility Address:	
Client Name:	THE REGIONAL MUNICIPALITY OF PEEL
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	SEDIMENT
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	
Incident Summary:	RoP: watermain break Kennedy Rd, Brampton - minor impact to c/b; clng
Activity Preceding Spill:	
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HB - Credit - 16 Mile
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001889810"],"wkts":["POINT (-79.7375940000 43.6860716000)"],"creation_date":"2023-09-03"}

---

116 | ***1 of 4*** | ***ESE/89.5*** | ***211.8 / -20.63*** | ***KENNEDY GALLERIES FURNITURE CLINIC, DIVISION OF 109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3*** | ***GEN***

Generator No:	ON0889000
SIC Code:	2699
SIC Description:	OTHER FURN. & FIXT.
Approval Years:	86,87,88,89,90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS

---

116 | ***2 of 4*** | ***ESE/89.5*** | ***211.8 / -20.63*** | ***KENNEDY GALLERIES, DIV. 109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3*** | ***GEN***

Generator No:	ON0889000
SIC Code:	2699
SIC Description:	OTHER FURN. & FIXT.
Approval Years:	92,93,97,98
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

116 ***3 of 4*** ***ESE/89.5*** ***211.8 / -20.63*** ***KENNEDY GALLERIES 23-268 FURNITURE CLINIC, DIVISION OF 109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3*** ***GEN***

Generator No: ON0889000
SIC Code: 2699
SIC Description: OTHER FURN. & FIXT.
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

116 ***4 of 4*** ***ESE/89.5*** ***211.8 / -20.63*** ***KENNEDY GALLERIES - A DIVISION OF 109 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3*** ***GEN***

Generator No: ON0889000
SIC Code: 2699
SIC Description: OTHER FURN. & FIXT.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
117	1 of 5	ESE/70.3	211.5 / -20.99	BRAMPTON LEASING & RENTALS LTD. 117 KENNEDY RD. S. BRAMPTON ON L6W 3G3	GEN

Generator No: ON0694800
SIC Code: 9921
SIC Description: AUTO./TRUCK RENTAL
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
117	2 of 5	ESE/70.3	211.5 / -20.99	BRAMPTON LEASING & RENTALS LTD. 117 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G3	GEN

Generator No: ON0694800
SIC Code: 9921
SIC Description: AUTO./TRUCK RENTAL
Approval Years: 92,93,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
117	3 of 5	ESE/70.3	211.5 / -20.99	BRAMPTON LEASING & RENTALS LTD. 06-192 117 KENNEDY RD. S. BRAMPTON ON L6W 3G3	GEN

Generator No: ON0694800
SIC Code: 9921
SIC Description: AUTO./TRUCK RENTAL
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

117 | ***4 of 5*** | ***ESE/70.3*** | ***211.5 / -20.99*** | ***HERTZ BRAMPTON LEASING & RENTALS LIMITED***
117 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3G3 | ***GEN***

Generator No: ON0694800
SIC Code: 9921
SIC Description: AUTO./TRUCK RENTAL
Approval Years: 98,99,00
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

117 | ***5 of 5*** | ***ESE/70.3*** | ***211.5 / -20.99*** | ***BRAMPTON LEASING & RENTALS LIMITED***
117 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3G3 | ***GEN***

Generator No: ON0694800
SIC Code: 9921
SIC Description: AUTO./TRUCK RENTAL
Approval Years: 01,02,03,04,05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213

Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

119 | **1 of 1** | **ESE/76.1** | **210.8 / -21.63** | **The Regional Municipality of Peel**
119 Kennedy Road South
Brampton ON | **SPL**

Ref No: 0536-B2LLYS
Year:
Incident Dt: 2018/07/12
Dt MOE Arvl on Scn:
MOE Reported Dt: 2018/07/12
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Gas Station<UNOFFICIAL>
Site Address: 119 Kennedy Road South
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Overflow/Surcharge
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 L
System Facility Address:
Client Name: The Regional Municipality of Peel
Client Type: Municipal Government
Source Type: Sewer (Private or Municipal)
Contaminant Code: 44
Contaminant Name: GREY WATER
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium: Land; Surface Water
Incident Reason: Blockage
Incident Summary: RofP: manhole surcharge greywater to cb, clng.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Municipal Sewage
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

---

120 | **1 of 1** | **ESE/36.2** | **209.8 / -22.63** | **AUTOMOTIVE FINISHES & SUPPLY INC.**
5 STAFFORD DR. BRAMPTON C/O 726 KIPLING AVE.
TORONTO ON L6W 1L3 | **GEN**

Generator No: ON0635003
SIC Code: 0000

SIC Description: *** NOT DEFINED ***
Approval Years: 89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

121 | **1 of 2** | **ESE/21.0** | **209.8 / -22.63** | **BUNS MASTER BAKERY**
1 STAFFORD DR
BRAMPTON ON L6W 1L3 | **SCT**

Established: 1992
Plant Size (ft²): 14000
Employment: 12

--Details--
Description: BREAD AND OTHER BAKERY PRODUCTS, EXCEPT COOKIES AND CRACKERS
SIC/NAICS Code: 2051

Description: COOKIES AND CRACKERS
SIC/NAICS Code: 2052

---

121 | **2 of 2** | **ESE/21.0** | **209.8 / -22.63** | **Grainery Bakery and Deli**
1 Stafford Dr
Brampton ON L6W 1L3 | **SCT**

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Retail Bakeries
SIC/NAICS Code: 311811

Description: Caterers
SIC/NAICS Code: 722320

---

122 | **1 of 1** | **ESE/33.6** | **209.8 / -22.63** | **IMPERIAL OIL LTD**
129 KENNEDY RD
BRAMPTON ON | **DTNK**

Delisted Expired Fuel Safety Facilities

Instance No: 10000705 **Expired Date:**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	10022	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	Fuels Safety Private Fuel Outlet - Self Serve		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

123	*1 of 1*	***ESE/88.9***	***210.3 / -22.17***	***Leisureworld Caregiving Centre Tullamore*** ***133 Kennedy Rd South*** ***Brampton ON***	***GEN***

Generator No:	ON7317018
SIC Code:	623310
SIC Description:	
Approval Years:	2013
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS
Waste Class:	243
Waste Class Name:	PCBS
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	148

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

124 **1 of 25** **ESE/72.3** **209.0 / -23.51** **A.T PLASTICS INC.** **SPL**
134 KENNEDY ROAD SOUTH 134 KENNEDY ROAD SOUTH, PLASTIC FILMS
BRAMPTON CITY ON L6W 3G5

Ref No: 106541
Year:
Incident Dt: 9/22/1994
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/21/1994
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: UNDERGROUND TANK LEAK
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: CORROSION
Incident Summary: A.T. PLASTICS INC.: SOLVENT UST LEAKING :TANK BELOW WATER TABLE
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

---

124 **2 of 25** **ESE/72.3** **209.0 / -23.51** **C.I.L. INC.** **NPCB**
BRAMPTON WORKS; 134 KENNEDY RD. S.
BRAMPTON ON L6W 3G5

Company Code: O0313D
Industry: Other
Site Status:
Transaction Date: 8/17/1990
Inspection Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	3 of 25	ESE/72.3	209.0 / -23.51	AT PLACTICS INC. BRAMPTON WORKS; 134 KENNEDY RD. S. BRAMPTON ON L6W 3G5	NPCB

Company Code: O0681
Industry: Other
Site Status:
Transaction Date: 11/19/1993
Inspection Date: 11/19/1991

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	4 of 25	ESE/72.3	209.0 / -23.51	CIL INC. 134 KENNEDY ROAD BRAMPTON ON L6W 3G5	NPCB

Company Code: F1095
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code: High > 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 150.00 KG

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	5 of 25	ESE/72.3	209.0 / -23.51	AT PLASTICS INC. 134 KENNEDY RD S BRAMPTON ON L6W 3G5	SCT

Established: 1989
Plant Size (ft²): 0
Employment: 225

--Details--
Description: UNSUPPORTED PLASTICS FILM AND SHEET
SIC/NAICS Code: 3081

Description: Adhesive Manufacturing
SIC/NAICS Code: 325520

Description: Unsupported Plastic Bag Manufacturing
SIC/NAICS Code: 326111

Description: Unsupported Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: PLASTICS, FOIL, AND COATED PAPER BAGS
SIC/NAICS Code: 2673

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	6 of 25	ESE/72.3	209.0 / -23.51	C.I.L. INC 134 KENNEDY RD S BRAMPTON ON L6W 3G5	GEN

Generator No: ON0003906
SIC Code: 1631
SIC Description: PLASTIC FILM & SHEET.
Approval Years: 86,87,88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	7 of 25	ESE/72.3	209.0 / -23.51	C.I.L. INC(SEE&USE ON1133601) 134 KENNEDY RD S BRAMPTON ON L6W 3G5	GEN

Generator No: ON0003906
SIC Code: 1631
SIC Description: PLASTIC FILM & SHEET
Approval Years: 90,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	8 of 25	ESE/72.3	209.0 / -23.51	C.I.L. INC(SEE&USE ON1133601) 10-046 134 KENNEDY RD S BRAMPTON ON L6W 3G5	GEN

Generator No: ON0003906
SIC Code: 1631
SIC Description: PLASTIC FILM & SHEET
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	9 of 25	ESE/72.3	209.0 / -23.51	AT PLASTICS INC. 134 KENNEDY ROAD SOUTH	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON L6W 3G5	

Generator No: ON1133601
SIC Code: 1631
SIC Description: PLASTIC FILM & SHEET
Approval Years: 92,93,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

124	10 of 25	ESE/72.3	209.0 / -23.51	AT PLASTIC 10-046 134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	GEN

Generator No: ON1133601
SIC Code: 1631
SIC Description: PLASTIC FILM & SHEET
Approval Years: 94
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

124 | **11 of 25** | **ESE/72.3** | **209.0 / -23.51** | **AT PLASTICS INCORPORATED**
134 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3G5 | **GEN**

Generator No: ON1133601
SIC Code: 1631
SIC Description: PLASTIC FILM & SHEET.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

---

124 | **12 of 25** | **ESE/72.3** | **209.0 / -23.51** | **SMURFIT-STONE FLEXIBLE PACKAGING GROUP**
134 KENNEDY RD S
BRAMPTON ON L6W 3G5 | **GEN**

Generator No: ON1133601
SIC Code:
SIC Description:
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

124 | ***13 of 25*** | ***ESE/72.3*** | ***209.0 / -23.51*** | ***AT PLASTICS INC.***
134 KENNEDY RD. S. BRAMPTON WORKS
Brampton ON L6W 3G5 | ***NPCB***

Company Code: O0681
Industry: Other
Site Status: Stored for Disposal
Transaction Date:
Inspection Date: 11/19/1991

--Details--
Label:
Serial No.:
PCB Type/Code: Askarel/Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for disposal
Contents:

Label:
Serial No.:
PCB Type/Code: Askarel/Askarel
Location: BANK OF 5 CAPS. STORED OUTSIDE
Item/State:
No. of Items:
Manufacturer:
Status: Stored for disposal
Contents:

---

124 | ***14 of 25*** | ***ESE/72.3*** | ***209.0 / -23.51*** | ***BLUEGRASS CONTAINER CANADA COMPANY***
134 KENNEDY RD S
BRAMPTON ON L6W 3G5 | ***GEN***

Generator No: ON1133601
SIC Code: 561910
SIC Description: Packaging and Labelling Services
Approval Years: 05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

124	15 of 25	ESE/72.3	209.0 / -23.51	**Graphic Packaging Flexible Can. Inc.** **134 KENNEDY RD S** **BRAMPTON ON**	GEN

Generator No: ON1133601
SIC Code: 561910
SIC Description: PACKAGING AND LABELLING SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

124	16 of 25	ESE/72.3	209.0 / -23.51	A.T.PLASTICS INC. 134 KENNEDY ROAD S BRAMPTON ON L6W 3G5	NPCB

Company Code: F1013
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

124	17 of 25	ESE/72.3	209.0 / -23.51	AT PLASTICS INC. 134 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G5	NPCB

Company Code: O004996
Industry: OTHER
Site Status: STORAGE ONLY (NON FEDERAL)
Transaction Date:
Inspection Date:

124	18 of 25	ESE/72.3	209.0 / -23.51	AT PLASTICS INC. BRAMPTON WORKS 134 KENNEDY RD. S BRAMPTON ON L6W 3G5	NPCB

Company Code: O0681
Industry: OTHER
Site Status: POTENTIAL FOR INSPECTION (TR)
Transaction Date: 11/19/1993
Inspection Date: 11/19/1991

--Details--
Label: DO05064
Serial No.:
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: BARREL LIGHT BALLAST/FULL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

No. of Items: 130
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: KG

Label: OR00895
Serial No.: 4165
PCB Type/Code: ASKAREL/ASKAREL
Location:
Item/State: CAPACITOR/FULL
No. of Items: 5
Manufacturer:
Status: STORED FOR DISPOSAL
Contents: 43 L

---

124 | **19 of 25** | **ESE/72.3** | **209.0 / -23.51** | **Graphic Packaging Intl Canada**
134 Kennedy Rd S
Brampton ON L6W 3G5 | **SCT**

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

Description: Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

---

124 | **20 of 25** | **ESE/72.3** | **209.0 / -23.51** | **Graphic Packaging Int. Inc.**
134 KENNEDY RD S
BRAMPTON ON L6W 3G5 | **GEN**

Generator No: ON1133601
SIC Code: 561910
SIC Description: Packaging and Labelling Services
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

124	21 of 25	ESE/72.3	209.0 / -23.51	**Graphic Packaging Flexible Can. Inc.** **134 KENNEDY RD S** **BRAMPTON ON L6W 3G5**	GEN

Generator No: ON1133601
SIC Code: 561910
SIC Description: Packaging and Labelling Services
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	22 of 25	ESE/72.3	209.0 / -23.51	Graphic Packaging Flexible Can. Inc. 134 KENNEDY RD S BRAMPTON ON L6W 3G5	GEN

Generator No: ON1133601
SIC Code: 561910
SIC Description: Packaging and Labelling Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 243
Waste Class Name: PCBS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	23 of 25	ESE/72.3	209.0 / -23.51	Graphic Packaging Flexible Can. Inc. 134 KENNEDY RD S BRAMPTON ON L6W 3G5	GEN

Generator No: ON1133601
SIC Code: 561910
SIC Description: Packaging and Labelling Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
124	24 of 25	ESE/72.3	209.0 / -23.51	Graphic Packaging Flexible Can. Inc. 134 KENNEDY RD S BRAMPTON ON L6W 3G5	GEN

Generator No: ON1133601
SIC Code: 561910
SIC Description: Packaging and Labelling Services
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

124 | **25 of 25** | **ESE/72.3** | **209.0 / -23.51** | **Infinity Asset Solutions**
134 Kennedy Road
Brampton ON L6W 3G5 | **GEN**

Generator No: ON4276239
SIC Code: 417230
SIC Description: INDUSTRIAL MACHINERY, EQUIPMENT AND SUPPLIES WHOLESALER-DISTRIBUTORS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

125 | **1 of 8** | **ESE/46.9** | **209.8 / -22.63** | **A.T. PLASTICS**
142 KENNEDY ROAD 142 KENNEDY ROAD
SOUTH BURLINGTON
BRAMPTON CITY ON | **SPL**

Ref No: 180644
Year:
Incident Dt: 5/11/2000
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/11/2000
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: VALVE/FITTING LEAK OR FAILURE
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Water course or lake

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	WATER
Incident Reason:	EQUIPMENT FAILURE
Incident Summary:	A.T. PLASTICS- 30L SPILL ETHYLENE GLYCOL TO FLOOR DRAIN/C.B. 83% PUMPED.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

---

125 **2 of 8** **ESE/46.9** **209.8 / -22.63** **C-I-L INC.**
142 KENNEDY RD. S.
BRAMPTON ON L6W 3G4 **GEN**

Generator No:	ON0003916
SIC Code:	1699
SIC Description:	OTHER PLASTIC PROD.
Approval Years:	86,87,88
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	233
Waste Class Name:	OTHER POLYMERIC WASTES
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

---

125 **3 of 8** **ESE/46.9** **209.8 / -22.63** **C-I-L INC. (SEE & USE ON1133600)**
142 KENNEDY RD. S.
BRAMPTON ON L6W 3G4 **GEN**

Generator No:	ON0003916
SIC Code:	1699
SIC Description:	OTHER PLASTIC PROD.
Approval Years:	89,90,98
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

125 | ***4 of 8*** | ***ESE/46.9*** | ***209.8 / -22.63*** | ***C-I-L INC. (SEE & USE ON1133600) 10-292***
142 KENNEDY RD. S.
BRAMPTON ON L6W 3G4 | ***GEN***

Generator No: ON0003916
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

125 | ***5 of 8*** | ***ESE/46.9*** | ***209.8 / -22.63*** | ***AT PLASTICS INC.***
142 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3G4 | ***GEN***

Generator No: ON1133600
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 89,02,03,04,05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252

Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 243
Waste Class Name: PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
125	6 of 8	ESE/46.9	209.8 / -22.63	AT PLASTICS INC. 10-292 142 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	GEN

Generator No: ON1133600
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
125	7 of 8	ESE/46.9	209.8 / -22.63	AT PLASTICS INCORPORATED 142 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	GEN

Generator No: ON1133600
SIC Code: 1699
SIC Description: OTHER PLASTIC PROD.
Approval Years: 99,00,01
PO Box No:

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 233
Waste Class Name: OTHER POLYMERIC WASTES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

125 | ***8 of 8*** | ***ESE/46.9*** | ***209.8 / -22.63*** | ***AT Plastics Inc.***
142 Kennedy Rd S
Brampton ON L6W 3G4 | ***SCT***

Established: 1989
Plant Size (ft²):
Employment:

--Details--
Description: Resin and Synthetic Rubber Manufacturing
SIC/NAICS Code: 325210

Description: Plastic Film and Sheet Manufacturing
SIC/NAICS Code: 326114

---

126 | ***1 of 1*** | ***ESE/95.0*** | ***209.8 / -22.63*** | ***The Regional Municipality of Peel***
165 Kennedy Road S
Brampton ON | ***SPL***

Ref No: 3718-AA8J6L
Year:
Incident Dt: 2016/05/23
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/05/23
Dt Document Closed: 2016/06/04
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Watermain (6 Inch)<UNOFFICIAL>
Site Address: 165 Kennedy Road S
Site Region:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see incident description
System Facility Address:	
Client Name:	The Regional Municipality of Peel
Client Type:	
Source Type:	
Contaminant Code:	99
Contaminant Name:	DRINKING WATER (FULLY TREATED)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land; Surface Water
Incident Reason:	Equipment Failure
Incident Summary:	Brampton watermain break, silt to catch basin
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

---

127 | **1 of 17** | **ESE/29.9** | **209.8 / -22.63** | **UNI-CARE MCLAVERTY 144 KENNEDY RD, UNIT #2 MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON** | **SPL**

Ref No:	2101	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	4/5/1988	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/5/1988	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	REG.MUN.PEEL-WASTE MGT OF PUBL WKS
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			

Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: NEGLIGENCE (APPARENT)
Incident Summary: UNI-CARE - 225 L PERCHLORETHYLENE TO GRD. 5 TO 10 L. TO CATCH BASS
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

---

127 | ***2 of 17*** | ***ESE/29.9*** | ***209.8 / -22.63*** | ***PAPA'S CERAMICS LTD.***
144 KENNEDY RD S UNIT 13
BRAMPTON ON L6W 3G4 | ***SCT***

Established: 1995
Plant Size (ft²): 0
Employment: 2

--Details--
Description: POTTERY PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3269

Description: NONMETALLIC MINERAL PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3299

Description: Pottery, Ceramics and Plumbing Fixture Manufacturing
SIC/NAICS Code: 327110

---

127 | ***3 of 17*** | ***ESE/29.9*** | ***209.8 / -22.63*** | ***Customwear Screenprinting Inc.***
144 Kennedy Rd S Unit 15
Brampton ON L6W 3G4 | ***SCT***

Established: 1994
Plant Size (ft²):
Employment: 2

--Details--
Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

Description: Commercial Screen Printing
SIC/NAICS Code: 323113

Description: Graphic Design Services
SIC/NAICS Code: 541430

---

127 | ***4 of 17*** | ***ESE/29.9*** | ***209.8 / -22.63*** | ***WARREN'S AUTO PARTS LTD***
144 KENNEDY RD S
BRAMPTON ON L6W 3G4 | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON0281400
SIC Code: 0000
SIC Description: *** NOT DEFINED ***
Approval Years: 86,87,88,89,90,92,93,94
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

127	5 of 17	ESE/29.9	209.8 / -22.63	BRAMTECH EXTRUSIONS 144 KENNEDY RD., SOUTH UNIT 11 BRAMPTON ON L6W 3G4	GEN

Generator No: ON0917800
SIC Code: 1611
SIC Description: FOAMED & EXP. PLAS.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

127	6 of 17	ESE/29.9	209.8 / -22.63	BRAMTECH EXTRUSIONS 04-219 144 KENNEDY RD., SOUTH UNIT 11 BRAMPTON ON L6W 3G4	GEN

Generator No: ON0917800
SIC Code: 1611
SIC Description: FOAMED & EXP. PLAS.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

127	7 of 17	ESE/29.9	209.8 / -22.63	VERSAKLEEN DRYCLEANERS 144 KENNEDY RD. SOUTH BRAMPTON ON L6W 3G4	GEN

Generator No: ON1040100
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER
Approval Years: 88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
127	8 of 17	ESE/29.9	209.8 / -22.63	VERSAKLEEN DRYCLEANERS 144 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G4	GEN

Generator No: ON1040100
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER
Approval Years: 92,93,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
127	9 of 17	ESE/29.9	209.8 / -22.63	VERSAKLEEN DRYCLEANERS 40-180 144 KENNEDY RD. SOUTH BRAMPTON ON L6W 3G4	GEN

Generator No: ON1040100
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
127	10 of 17	ESE/29.9	209.8 / -22.63	1108456 ONTARIO INC. 144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	GEN

Generator No: ON2408900
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS
Approval Years: 98,99,00
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
127	11 of 17	ESE/29.9	209.8 / -22.63	PREMIER CLEANERS 144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	GEN

Generator No: ON2408900
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS
Approval Years: 01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
127	12 of 17	ESE/29.9	209.8 / -22.63	1575601 ONTARIO INC 144 KENNEDY ROAD SOUTH, UNIT #2 BRAMPTON ON L6W 3G4	GEN

Generator No: ON2408900
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

127 ***13 of 17*** ***ESE/29.9*** ***209.8 / -22.63*** ***22138689 Ontario Inc.*** ***144 Kennedy Road S.*** ***Brampton ON L6W 3G4*** ***GEN***

Generator No: ON4371720
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

127 ***14 of 17*** ***ESE/29.9*** ***209.8 / -22.63*** ***2138689 Ontario Inc.*** ***144 Kennedy Road S.*** ***Brampton ON L6W 3G4*** ***GEN***

Generator No: ON4371720
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

127 ***15 of 17*** ***ESE/29.9*** ***209.8 / -22.63*** ***2138689 Ontario Inc.*** ***144 Kennedy Road S.*** ***Brampton ON L6W 3G4*** ***GEN***

Generator No: ON4371720
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

127 | ***16 of 17*** | ***ESE/29.9*** | ***209.8 / -22.63*** | ***Commercial Complex<UNOFFICIAL>***
144 Kennedy Road South, Brampton
Brampton ON | ***SPL***

Ref No: 1207-A8QPD3
Year:
Incident Dt: 2016/04/05
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/04/05
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse: Etobicoke Creek
Site Name: 144 Kennedy Road South <UNOFFICIAL>
Site Address: 144 Kennedy Road South, Brampton
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4837507
Easting: 602171
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name: Commercial Complex<UNOFFICIAL>
Client Type:
Source Type:
Contaminant Code: 99
Contaminant Name: DRINKING WATER (FULLY TREATED)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Surface Water
Incident Reason: Equipment Failure
Incident Summary: ~3" Private Watermain Break, Sediment Spill to Etobicoke Creek
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:

---

127 | ***17 of 17*** | ***ESE/29.9*** | ***209.8 / -22.63*** | ***PREMIER CLEANERS***
2,144 KENNEDY DR | ***CDRY***

BRAMPTON ON L6W3G4

Legal Name of Company:
Region:
Type of Reporter:

Waste Quantity by Year

Reporting Year:	2007
Quantity of PERC (kg):	586
Total Waste Water (kg):	162
Total Waste Water (L):	-
Total Residue (kg):	0
Total Residue (L):	-
Total Mix (kg):	0
Total Mix (L):	-
Request for Confidentiality:	No
Reason For Confidentiality:	N/A

Reporting Year:	2006
Quantity of PERC (kg):	184
Total Waste Water (kg):	0
Total Waste Water (L):	-
Total Residue (kg):	184
Total Residue (L):	-
Total Mix (kg):	0
Total Mix (L):	-
Request for Confidentiality:	No
Reason For Confidentiality:	N/A

Reporting Year:	2005
Quantity of PERC (kg):	146
Total Waste Water (kg):	0
Total Waste Water (L):	-
Total Residue (kg):	0
Total Residue (L):	-
Total Mix (kg):	0
Total Mix (L):	-
Request for Confidentiality:	No
Reason For Confidentiality:	N/A

Reporting Year:	2004
Quantity of PERC (kg):	440
Total Waste Water (kg):	0
Total Waste Water (L):	368
Total Residue (kg):	-
Total Residue (L):	664
Total Mix (kg):	0
Total Mix (L):	-
Request for Confidentiality:	No
Reason For Confidentiality:	N/A

---

128 ***1 of 1*** ***WNW/52.1*** ***260.2 / 27.77*** ***22 Hesketh Crt Caledon ON NA*** ***SPL***

Ref No:	7030-BDGQB5	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	6/22/2019	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	6/25/2019	***Impact to Health:***	0 - No Impact
Dt Document Closed:		***Agency Involved:***	
Site No:	9158-BDGQCW		
MOE Response:	No		

Site County/District:	Regional Municipality of Peel
Site Geo Ref Meth:	NA
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Resident
Site Address:	22 Hesketh Crt
Site Region:	Central
Site Municipality:	Caledon
Site Lot:	
Site Conc:	NA
Site Geo Ref Accu:	NA
Site Map Datum:	NA
Northing:	NA
Easting:	NA
Incident Cause:	
Incident Preceding Spill:	
Environment Impact:	
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	
Incident Summary:	Dust complaint - nuisance report
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

129	*1 of 4*	*WNW/96.6*	*260.4 / 27.94*	***Brampton Christian School*** ***12480 Hutchinson Farm Lane*** ***Caledon ON***	***GEN***

Generator No:	ON5869236
SIC Code:	611690
SIC Description:	All Other Schools and Instruction
Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

129	*2 of 4*	*WNW/96.6*	*260.4 / 27.94*	***Brampton Christian School*** ***12480 Hutchinson Farm Lane*** ***Caledon ON***	***GEN***

Generator No:	ON5869236
SIC Code:	611690
SIC Description:	ALL OTHER SCHOOLS AND INSTRUCTION

Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

129 ***3 of 4*** ***WNW/96.6*** ***260.4 / 27.94*** ***Brampton Christian School***
12480 Hutchinson Farm Lane
Caledon ON L7C 2B6 ***GEN***

Generator No: ON2605469
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 135 I
Waste Class Name: Wastes containing other reactive anions

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 267 C
Waste Class Name: Organic acids

---

129 ***4 of 4*** ***WNW/96.6*** ***260.4 / 27.94*** ***Brampton Christian School***
12480 Hutchinson Farm Lane
Caledon ON L7C 2B6 ***GEN***

Generator No: ON2605469
SIC Code:
SIC Description:
Approval Years: As of Oct 2022

PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 135 I
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 267 C
Waste Class Name: ORGANIC ACIDS

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

130	*1 of 16*	*ESE/28.9*	*209.8 / -22.63*	***COMFORT MATTRESS MFG. LTD.*** ***158 KENNEDY RD S UNITS 12-13*** ***BRAMPTON ON L6W 3G7***	*SCT*

Established: 0000
Plant Size (ft²): 0
Employment: 4

--Details--
Description: Mattress Manufacturing
SIC/NAICS Code: 337910

130	*2 of 16*	*ESE/28.9*	*209.8 / -22.63*	***P-O-C PRINTING LTD.*** ***158 KENNEDY RD S UNIT 11*** ***BRAMPTON ON L6W 3G7***	*SCT*

Established: 1978
Plant Size (ft²): 1700
Employment: 4

--Details--
Description: COMMERCIAL PRINTING, LITHOGRAPHIC
SIC/NAICS Code: 2752

Description: COMMERCIAL PRINTING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2759

Description: Quick Printing
SIC/NAICS Code: 323114

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

---

130 | **3 of 16** | **ESE/28.9** | **209.8 / -22.63** | **E J MACHINE CO LTD**
158 KENNEDY RD S
BRAMPTON ON L6W 3G7 | **SCT**

Established: 1972
Plant Size (ft²): 1500
Employment: 6

--Details--
Description: MILLWORK
SIC/NAICS Code: 2431

Description: SPECIAL INDUSTRY MACHINERY, N.E.C.
SIC/NAICS Code: 3559

---

130 | **4 of 16** | **ESE/28.9** | **209.8 / -22.63** | **Comfort Mattress Manufacturing Limited**
158 Kennedy Rd S Unit 12-13
Brampton ON L6W 3G7 | **SCT**

Established:
Plant Size (ft²):
Employment: 4

---

130 | **5 of 16** | **ESE/28.9** | **209.8 / -22.63** | **POC Printing Services Inc.**
158 Kennedy Rd S Unit 11
Brampton ON L6W 3G7 | **SCT**

Established: 2002
Plant Size (ft²): 1700
Employment: 4

--Details--
Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

---

130 | **6 of 16** | **ESE/28.9** | **209.8 / -22.63** | **E.J. (OUT OF BUS) 49-119**
158 KENNEDY ROAD SOUTH UNIT 11
BRAMPTON ON L6W 3G7 | **GEN**

Generator No: ON1623600
SIC Code: 3081
SIC Description: MACHINE SHOP IND.
Approval Years: 92,93,96,97,98
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
130	7 of 16	ESE/28.9	209.8 / -22.63	E.J. MACHINE CO. LTD. 49-119 158 KENNEDY ROAD SOUTH UNIT 11 BRAMPTON ON L6W 3G7	GEN

Generator No: ON1623600
SIC Code: 3081
SIC Description: MACHINE SHOP IND.
Approval Years: 94,95
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
130	8 of 16	ESE/28.9	209.8 / -22.63	POC Gem Printing Services 158 Kennedy Rd S Unit 11 Brampton ON L6W 3G7	SCT

Established: 2002
Plant Size (ft²): 1700
Employment: 4

--Details--
Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
130	9 of 16	ESE/28.9	209.8 / -22.63	Elizabeth Ostrander Veterinary Professional Corp 158 Kennedy Rd S Unit 3 Brampton ON	GEN

Generator No: ON6678446
SIC Code: 541940

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: VETERINARY SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

130 | ***10 of 16*** | ***ESE/28.9*** | ***209.8 / -22.63*** | ***Elizabeth Ostrander Veterinary Professional Corp***
158 Kennedy Rd S Unit 3
Brampton ON L6W 3G7 | ***GEN***

Generator No: ON6678446
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

130 | ***11 of 16*** | ***ESE/28.9*** | ***209.8 / -22.63*** | ***Elizabeth Ostrander Veterinary Professional Corp***
158 Kennedy Rd S Unit 3
Brampton ON L6W 3G7 | ***GEN***

Generator No: ON6678446
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

130 | ***12 of 16*** | ***ESE/28.9*** | ***209.8 / -22.63*** | ***Elizabeth Ostrander Veterinary Professional Corp***
158 Kennedy Rd S Unit 3
Brampton ON L6W 3G7 | ***GEN***

Generator No: ON6678446
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

130 | ***13 of 16*** | ***ESE/28.9*** | ***209.8 / -22.63*** | ***Elizabeth Ostrander Veterinary Professional Corp***
158 Kennedy Rd S Unit 3
Brampton ON L6W 3G7 | ***GEN***

Generator No: ON6678446
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
130	14 of 16	ESE/28.9	209.8 / -22.63	Elizabeth Ostrander Veterinary Professional Corp 158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	GEN

Generator No: ON6678446
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
130	15 of 16	ESE/28.9	209.8 / -22.63	Elizabeth Ostrander Veterinary Professional Corp 158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	GEN

Generator No: ON6678446
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
130	16 of 16	ESE/28.9	209.8 / -22.63	Elizabeth Ostrander Veterinary Professional Corp 158 Kennedy Rd S Unit 3 Brampton ON L6W 3G7	GEN

Generator No: ON6678446
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

131 **1 of 7** **ESE/90.8** **209.8 / -22.63** **Stitchsations Inc**
287 Glidden Rd Unit 6
Brampton ON L6W 1H9
SCT

Established: 8/1/1985
Plant Size (ft²): 2500
Employment:

--Details--
Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

---

131 **2 of 7** **ESE/90.8** **209.8 / -22.63** **Stitchsations Inc.**
287 Glidden Rd Unit 6
Brampton ON L6W 1H9
SCT

Established: 01-AUG-85
Plant Size (ft²): 2500
Employment:

--Details--
Description: All Other Textile Product Mills
SIC/NAICS Code: 314990

---

131 **3 of 7** **ESE/90.8** **209.8 / -22.63** **Amara Furniture Manufacturing Inc.**
287 Glidden Rd Unit 12
Brampton ON L6W 1H9
SCT

Established: 1997
Plant Size (ft²):
Employment: 2

--Details--
Description: Other Wood Household Furniture Manufacturing
SIC/NAICS Code: 337123

---

131 **4 of 7** **ESE/90.8** **209.8 / -22.63** **POC-Gem Printing Services Inc.**
287 Glidden Rd Unit 3
Brampton ON L6W 1H9
SCT

Established: 01-JAN-78

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Plant Size (ft²): 2400
Employment:

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

---

131 | ***5 of 7*** | ***ESE/90.8*** | ***209.8 / -22.63*** | ***Torbram Electric Supply Ltd.***
287 Glidden Rd Unit 1
Brampton ON L6W 1H9 | ***SCT***

Established: 01-SEP-90
Plant Size (ft²):
Employment:

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

---

131 | ***6 of 7*** | ***ESE/90.8*** | ***209.8 / -22.63*** | ***Cristall Group Investments Inc***
287 Glidden Road
Brampton ON L6W 1H9 | ***GEN***

Generator No: ON3253358
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

131 | ***7 of 7*** | ***ESE/90.8*** | ***209.8 / -22.63*** | ***Cristall Group Investments Inc***
287 Glidden Road
Brampton ON L6W 1H9 | ***GEN***

Generator No: ON3253358
SIC Code:
SIC Description:
Approval Years: As of Jan 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

132 | ***1 of 1*** | ***WNW/40.5*** | ***247.9 / 15.38*** | ***Hydro One Networks Inc.*** ***12581 Hurontario ST*** ***Caledon ON*** | ***SPL***

Ref No: 4332-AQWDW4
Year:
Incident Dt: 9/5/2017
Dt MOE Arvl on Scn: 9/5/2017
MOE Reported Dt: 9/5/2017
Dt Document Closed:
Site No: NA
MOE Response: Yes
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Roadside swale, soil impacted <UNOFFICIAL>
Site Address: 12581 Hurontario ST
Site Region: Central
Site Municipality: Caledon
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4844474.96
Easting: 593135.52
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 55 L
System Facility Address:
Client Name: Hydro One Networks Inc.
Client Type: Other (Describe)
Source Type: Transformer
Contaminant Code: 13
Contaminant Name: MINERAL OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium: Land
Incident Reason: Weather Conditions
Incident Summary: Hydro One: 55L non-pcb mineral oil to grnd; cntnd & clning
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	1 of 20	ESE/45.6	209.8 / -22.63	BENSON & HEDGES LTD. 174 KENNEDY ROAD BRAMPTON ON L6W 3G6	NPCB

Company Code: F1071
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code: High > 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 150.00 KG

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	2 of 20	ESE/45.6	209.8 / -22.63	Rothmans, Benson & Hedges Inc. 174 Kennedy Rd S Brampton ON L6W 3G6	SCT

Established: 01-JUL-61
Plant Size (ft²): 266000
Employment:

--Details--
Description: Tobacco Stemming and Redrying
SIC/NAICS Code: 312210

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	3 of 20	ESE/45.6	209.8 / -22.63	BENSON AND HEDGES (CANADA) INC. PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	GEN

Generator No: ON0034800
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	4 of 20	ESE/45.6	209.8 / -22.63	ROTHMANS BENSON & HEDGES INC. PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	GEN

Generator No: ON0034800
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	5 of 20	ESE/45.6	209.8 / -22.63	ROTHMANS BENSON & HEDGES INC. 05-086 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	GEN

Generator No: ON0034800
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 92,93,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	6 of 20	ESE/45.6	209.8 / -22.63	ROTHMANS BENSON & HEDGES INC. 05-086 PLANT 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	GEN

Generator No: ON0034800
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 94,95
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	7 of 20	ESE/45.6	209.8 / -22.63	ROTHMANS BENSON & HEDGES INC. 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	GEN

Generator No: ON0034800
SIC Code: 1221
SIC Description: TOBACCI PROD. IND.
Approval Years: 98,99,00,01,02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class:	114
Waste Class Name:	OTHER INORGANIC ACID WASTES
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	232
Waste Class Name:	POLYMERIC RESINS
Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	243
Waste Class Name:	PCB'S
Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS
Waste Class:	265
Waste Class Name:	GRAPHIC ART WASTES
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS
Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	269
Waste Class Name:	NON-HALOGENATED PESTICIDES
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES

133	***8 of 20***	***ESE/45.6***	***209.8 / -22.63***	***Transport International Pool<UNOFFICIAL>*** ***174 KENNEDY RD<UNOFFICIAL>*** ***Brampton ON***	***SPL***

Ref No: 2300-5WYMEV ***Municipality No:***

Year:		**Nature of Damage:**	
Incident Dt:	3/10/2004	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	Oil
MOE Reported Dt:	3/11/2004	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	174 KENNEDY RD<UNOFFICIAL>		
Site Address:			
Site Region:	Central		
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	Other Discharges		
Incident Preceding Spill:			
Environment Impact:	Possible		
Health Env Consequence:			
Nature of Impact:	Soil Contamination		
Contaminant Qty:	91 L		
System Facility Address:			
Client Name:	Transport International Pool<UNOFFICIAL>		
Client Type:			
Source Type:			
Contaminant Code:	15		
Contaminant Name:	HYDRAULIC OIL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Incident Reason:	Weather		
Incident Summary:	Brampton - Diesel Fuel to Ground		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Transport Truck		
SAC Action Class:	Spill to Land		
Call Report Locatn Geodata:			

---

133 | **9 of 20** | **ESE/45.6** | **209.8 / -22.63** | **McQuary Service<UNOFFICIAL>**
174 Kennedy Rd S
Brampton ON L6W 3G6 | **SPL**

Ref No:	1117-6YZQDV	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	Gases/Particulate
MOE Reported Dt:	3/5/2007	**Impact to Health:**	
Dt Document Closed:	3/8/2007	**Agency Involved:**	
Site No:			
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Rothmans, Benson & Hedges Inc.		
Site Address:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	NA
Easting:	NA
Incident Cause:	Pipe Or Hose Leak
Incident Preceding Spill:	
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Air Pollution
Contaminant Qty:	800 lb
System Facility Address:	
Client Name:	McQuary Service<UNOFFICIAL>
Client Type:	
Source Type:	
Contaminant Code:	38
Contaminant Name:	REFRIGERANT GAS, N.O.S
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Incident Reason:	Other - Reason not otherwise defined
Incident Summary:	Rothmans, Benson & Hedges: 800 lbs 134A refrigerant leak
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other
SAC Action Class:	
Call Report Locatn Geodata:	

133	*10 of 20*	*ESE/45.6*	*209.8 / -22.63*	***ROTHMANS, BENSON & HEDGES INC.*** ***174 KEN NEDY RD. SOUTH*** ***BRAMPTON ON L6W 3G6***	***NPCB***

Company Code:	O005271
Industry:	OTHER
Site Status:	NO MORE PCB'S ON THIS SITE
Transaction Date:	
Inspection Date:	

133	*11 of 20*	*ESE/45.6*	*209.8 / -22.63*	***ROTHMANS BENSON & HEDGES INC.*** ***174 KENNEDY ROAD SOUTH*** ***BRAMPTON ON L6W 3G6***	***GEN***

Generator No:	ON0034800
SIC Code:	312220
SIC Description:	Tobacco Product Manufacturing
Approval Years:	2009
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	232
Waste Class Name:	POLYMERIC RESINS
Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	265
Waste Class Name:	GRAPHIC ART WASTES
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS
Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	114
Waste Class Name:	OTHER INORGANIC ACID WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	12 of 20	ESE/45.6	209.8 / -22.63	ROTHMANS BENSON & HEDGES INC. 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	GEN

Generator No:	ON0034800
SIC Code:	312220
SIC Description:	Tobacco Product Manufacturing
Approval Years:	2010
PO Box No:	
Country:	

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	13 of 20	ESE/45.6	209.8 / -22.63	ROTHMANS BENSON & HEDGES INC. 174 KENNEDY ROAD SOUTH BRAMPTON ON L6W 3G6	GEN

Generator No: ON0034800
SIC Code: 312220
SIC Description: Tobacco Product Manufacturing
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 112

Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

---

133 | **14 of 20** | **ESE/45.6** | **209.8 / -22.63** | **ROTHMANS BENSON & HEDGES INC.**
174 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3G6 | **GEN**

Generator No: ON0034800
SIC Code: 312220
SIC Description: Tobacco Product Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 212

Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

133	15 of 20	ESE/45.6	209.8 / -22.63	ROTHMANS BENSON & HEDGES INC. 174 KENNEDY ROAD SOUTH BRAMPTON ON	GEN

Generator No: ON0034800
SIC Code: 312220
SIC Description: TOBACCO PRODUCT MANUFACTURING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 331

Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

---

133 | **16 of 20** | **ESE/45.6** | **209.8 / -22.63** | **ROTHMANS BENSON & HEDGES INC.**
174 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3G6 | **GEN**

Generator No: ON0034800
SIC Code: 312220
SIC Description: TOBACCO PRODUCT MANUFACTURING
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Katherine A Ridings
Choice of Contact: CO_ADMIN
Phone No Admin: 905-595-6026 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 148

Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

133 | ***17 of 20*** | ***ESE/45.6*** | ***209.8 / -22.63*** | ***ROTHMANS BENSON & HEDGES INC.***
174 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3G6 | ***GEN***

Generator No: ON0034800
SIC Code: 312220
SIC Description: TOBACCO PRODUCT MANUFACTURING
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Katherine A Ridings
Choice of Contact: CO_ADMIN
Phone No Admin: 905-595-6026 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145

Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	232
Waste Class Name:	POLYMERIC RESINS
Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	265
Waste Class Name:	GRAPHIC ART WASTES
Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	267
Waste Class Name:	ORGANIC ACIDS
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS
Waste Class:	114
Waste Class Name:	OTHER INORGANIC ACID WASTES
Waste Class:	121
Waste Class Name:	ALKALINE WASTES - HEAVY METALS
Waste Class:	268
Waste Class Name:	AMINES
Waste Class:	211
Waste Class Name:	AROMATIC SOLVENTS

133 | ***18 of 20*** | ***ESE/45.6*** | ***209.8 / -22.63*** | ***ROTHMANS BENSON & HEDGES INC.***
174 KENNEDY ROAD SOUTH
BRAMPTON ON L6W 3G6 | ***GEN***

Generator No:	ON0034800
SIC Code:	312220
SIC Description:	TOBACCO PRODUCT MANUFACTURING
Approval Years:	2014
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Jennifer DeGraaf

Choice of Contact: CO_ADMIN
Phone No Admin: 9055953041 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	19 of 20	ESE/45.6	209.8 / -22.63	JMX Contracting Inc 174 Kennedy Rd S Brampton ON L6W 3G6	GEN

Generator No: ON9993975
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 268 I
Waste Class Name: Amines

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
133	20 of 20	ESE/45.6	209.8 / -22.63	JMX Contracting Inc 174 Kennedy Rd S Brampton ON L6W 3G6	GEN

Generator No: ON9993975
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 268 I
Waste Class Name: Amines

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
134	1 of 1	ESE/98.3	209.8 / -22.63	Urban Clean Ltd 25 Rambler Drive, Unit 701 Brampton ON	GEN

Generator No: ON3867480
SIC Code: 236110
SIC Description: Residential Building Construction

Approval Years:	2012
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	1 of 20	ESE/69.4	209.8 / -22.63	JAGDEEP MERWAR O/A CHAKHRA ASSESSMENTS INC 253 KENNEDY RD S BRAMPTON ON L6W 3H1	FSTH

License Issue Date:	9/26/2007 9:05:00 AM
Tank Status:	Licensed
Tank Status As Of:	December 2008
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Full Serve

--Details--

Status:	Active
Year of Installation:	1990
Corrosion Protection:	
Capacity:	22730
Tank Fuel Type:	Liquid Fuel Single Wall UST - Diesel

Status:	Active
Year of Installation:	1990
Corrosion Protection:	
Capacity:	22730
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1990
Corrosion Protection:	
Capacity:	36370
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1990
Corrosion Protection:	
Capacity:	36370
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	2 of 20	ESE/69.4	209.8 / -22.63	253 Kennedy Rd S and Rambler Brampton ON L6W 3H1	SPL

Ref No:	1305-8SS2NP	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	26-MAR-12	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	26-MAR-12	**Impact to Health:**	
Dt Document Closed:	29-MAY-12	**Agency Involved:**	
Site No:			
MOE Response:	Planned Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Husky Gas Station<UNOFFICIAL>		

Site Address:	253 Kennedy Rd S and Rambler
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	Unknown
Incident Preceding Spill:	
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Other Impact(s)
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	12
Contaminant Name:	GASOLINE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Sewage - Municipal/Private and Commercial
Incident Reason:	
Incident Summary:	HOTLINE:Husky, gas spill to cnrt
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Motor Vehicle
SAC Action Class:	Pollution Hotline Calls
Call Report Locatn Geodata:	

---

135 | ***3 of 20*** | ***ESE/69.4*** | ***209.8 / -22.63*** | ***PARKLAND CORPORATION***
253 KENNEDY RD S
BRAMPTON ON | ***FST***

Inventory No:	10597142	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1990	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS UNDERGROUND TANK premium		

---

135 | ***4 of 20*** | ***ESE/69.4*** | ***209.8 / -22.63*** | ***PARKLAND CORPORATION***
253 KENNEDY RD S
BRAMPTON ON | ***FST***

Inventory No:	10597190	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	1990	**Overfill Protection:**	
Capacity:	36700	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Single Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS UNDERGROUND TANK regular		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	5 of 20	ESE/69.4	209.8 / -22.63	PARKLAND CORPORATION 253 KENNEDY RD S BRAMPTON ON	FST

Inventory No: 10597232
Inventory Status: active
Installation Year: 1990
Capacity: 36700
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBS regular UNDERGROUND TANK

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	6 of 20	ESE/69.4	209.8 / -22.63	PARKLAND CORPORATION 253 KENNEDY RD S BRAMPTON ON	FST

Inventory No: 10597099
Inventory Status: active
Installation Year: 1990
Capacity: 22730
Capacity Unit: L
Tank Type: Single Wall UST
Manufacturer:
Model:
Description: 2009VBS UNDERGROUND TANK

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	7 of 20	ESE/69.4	209.8 / -22.63	Husky Oil Operations Ltd. 253 Kennedy Road South Brampton ON	GEN

Generator No: ON8217624
SIC Code: 447190
SIC Description: Other Gasoline Stations
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	8 of 20	ESE/69.4	209.8 / -22.63	HUSKY GAS STATION 253 KENNEDY RD S BRAMPTON ON L6W3H1	RST

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 9054516815
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
135	9 of 20	ESE/69.4	209.8 / -22.63	Husky Oil Operations Ltd. 253 Kennedy Road South Brampton ON	GEN

Generator No: ON8217624
SIC Code: 447190
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

135 ***10 of 20*** ***ESE/69.4*** ***209.8 / -22.63*** ***Husky Oil Operations Ltd.***
253 Kennedy Road South
Brampton ON L6W 3H1 ***GEN***

Generator No: ON8217624
SIC Code: 447190
SIC Description: 447190
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Karina Karina Kenigsberg
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-614-1978 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

135 ***11 of 20*** ***ESE/69.4*** ***209.8 / -22.63*** ***Husky Oil Operations Ltd.***
253 Kennedy Road South
Brampton ON L6W 3H1 ***GEN***

Generator No: ON8217624
SIC Code: 447190
SIC Description: 447190
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Kim Tan
Choice of Contact: CO_ADMIN
Phone No Admin: 905-614-1978 Ext.
Contaminated Facility: No
MHSW Facility: No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

135 | ***12 of 20*** | ***ESE/69.4*** | ***209.8 / -22.63*** | ***Husky Oil Operations Ltd.***
253 Kennedy Road South
Brampton ON L6W 3H1 | ***GEN***

Generator No: ON8217624
SIC Code: 447190
SIC Description: 447190
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Nicole Semper
Choice of Contact: CO_ADMIN
Phone No Admin: 905-614-1978 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

135 | ***13 of 20*** | ***ESE/69.4*** | ***209.8 / -22.63*** | ***Husky Oil Operations Ltd.***
253 Kennedy Road South
Brampton ON L6W 3H1 | ***GEN***

Generator No: ON8217624
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

135 | ***14 of 20*** | ***ESE/69.4*** | ***209.8 / -22.63*** | ***Husky Oil Operations Ltd.***
253 Kennedy Road South | ***GEN***

Brampton ON L6W 3H1

Generator No: ON8217624
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 221 L
Waste Class Name: Light fuels

---

135 | **15 of 20** | **ESE/69.4** | **209.8 / -22.63** | **PARKLAND CORPORATION**
253 KENNEDY RD S
BRAMPTON ON | **INC**

Incident No: 782374
Incident ID:
Instance No: 9532590
Status Code:
Incident Status: Non Mandated
Incident Severity:
Task No:
Attribute Category: FS-Incident
Context:
Date of Occurrence: 3/26/2012
Time of Occurrence:
Occr Insp Start Dt:
Incident Creat On: 3/27/2012
Instance Creat Dt:
Instance Install Dt:
Approx Quant Rel:
Tank Capacity:
Fuels Occur Type:
Occur Type Rpt: Liquid Petroleum Spill
Occur Category:
Fuel Type Involved:
Fuel Type Reported: Transportation Fuel
Enforcement Policy:
Prc Escalation Req:
Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:

Any Health Impact:
Any Enviro Impact:
Service Intrp:
Was Prop Damaged:
Reside App. Type:
Commer App. Type:
Indus App. Type:
Institut App. Type:
Depth Ground Cover:
Operation Pressure:
Equipment Type:
Equipment Model:
Serial No:
Cylinder Capacity:
Cylinder Cap Units:
Cylinder Mat Type:
Pump Flow Rate Cap:
Contam. Migrated:
Near Body of Water:
Drainage System:
Sub Surface Contam:
Tank Material Type:
Tank Storage Type:
Tank Location Type:

Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 253 KENNEDY RD S
Invent Postal Code: L6W 3H1
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative:
Operation Type Involved: Retail Fuel Station (FS, SS, Multifunctional)

---

135 | ***16 of 20*** | ***ESE/69.4*** | ***209.8 / -22.63*** | ***253 KENNEDY RD S BRAMPTON ON L6W 3H1*** | ***DTNK***

Delisted Fuel Storage Tank

Instance No: 9532590
Status: Active
Instance Type:
Fuel Type:
Cont Name:
Capacity:
Tank Material:
Corrosion Prot:
Tank Type:
Install Year:
Facility Type:
Device Installed Loc:
Fuel Type 2:
Fuel Type 3:
Item: FS GASOLINE STATION - FULL SERVE
Item Description:
Model:
Description:
Instance Creation Dt:
Instance Install Dt:
Manufacturer:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Parent Fac Type:
TSSA Base Sched Cycle 1:
TSSA Base Sched Cycle 2:
Original Source: FST
Record Date: 31-MAY-2021

Creation Date:
Overfill Prot Type:
Facility Location:
Piping SW Steel: 0
Piping SW Galvan: 0
Tanks SW Steel: 0
Piping Underground: 3
No Underground: 4
Max Hazard Rank:
Max Hazard Rank 1:
Nxt Period Start Dt:
Program Area 1:
Program Area 2:
Nxt Period Strt Dt 2:
Risk Based Periodic:
Vol of Directives:
Years in Service:
Created Date:
Federal Device:
Periodic Exempt:
Statutory Interval:
Rcomnd Insp Interval:
Recommended Toler:
Panam Venue Name:
External Identifier:

---

135 | ***17 of 20*** | ***ESE/69.4*** | ***209.8 / -22.63*** | ***Husky Oil Operations Ltd. 253 Kennedy Road South Brampton ON L6W 3H1*** | ***GEN***

Generator No: ON8217624
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 221 L
Waste Class Name: Light fuels

---

135 ***18 of 20*** ***ESE/69.4*** ***209.8 / -22.63*** ***Parkland Corporation***
253 Kennedy Road South
Brampton ON L6W 3H1 ***GEN***

Generator No: ON8217624
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 221 L
Waste Class Name: LIGHT FUELS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

---

135 ***19 of 20*** ***ESE/69.4*** ***209.8 / -22.63*** ***PARKLAND CORPORATION***
253 KENNEDY RD S
BRAMPTON ON ***EXP***

Inventory No: 2383
Inventory Status: Inactive
Installation Year:
Capacity: 118860
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Full Serve

---

135 ***20 of 20*** ***ESE/69.4*** ***209.8 / -22.63*** ***PARKLAND CORPORATION***
253 KENNEDY RD S
BRAMPTON ON ***FST***

Inventory No: 2384
Inventory Status: Active
Installation Year:

Tank Material:
Corrosion Protect:
Overfill Protection:

Capacity:	118860	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			
Description:			

---

136 *1 of 6* *ESE/81.9* *208.0 / -24.51*

Maryam Saatian dpc
26 rambler drive
brampton ON L6W1E2

GEN

Generator No:	ON9577907
SIC Code:	621210
SIC Description:	OFFICES OF DENTISTS
Approval Years:	2016
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Cinthya Couto Moscoso
Choice of Contact:	CO_ADMIN
Phone No Admin:	905-451-8211 Ext.
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

136 *2 of 6* *ESE/81.9* *208.0 / -24.51*

Maryam Saatian dpc
26 rambler drive
brampton ON L6W1E2

GEN

Generator No:	ON9577907
SIC Code:	621210
SIC Description:	OFFICES OF DENTISTS
Approval Years:	2015
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Cinthya Couto Moscoso
Choice of Contact:	CO_ADMIN
Phone No Admin:	905-451-8211 Ext.
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

---

136 *3 of 6* *ESE/81.9* *208.0 / -24.51*

Maryam Saatian dpc
26 rambler drive
brampton ON L6W1E2

GEN

Generator No:	ON9577907
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

136 | ***4 of 6*** | ***ESE/81.9*** | ***208.0 / -24.51*** | ***Maryam Saatian dpc***
26 rambler drive
brampton ON L6W1E2 | ***GEN***

Generator No: ON9577907
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

136 | ***5 of 6*** | ***ESE/81.9*** | ***208.0 / -24.51*** | ***DENTISTRY@RAMBLER***
26 Rambler Dr
Brampton ON L6W 1E2 | ***GEN***

Generator No: ON4303476
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

136 | ***6 of 6*** | ***ESE/81.9*** | ***208.0 / -24.51*** | ***DENTISTRY@RAMBLER***
26 Rambler Dr
Brampton ON L6W 1E2 | ***GEN***

Generator No: ON4303476

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code:
SIC Description:
Approval Years: As of Jan 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

137 | ***1 of 1*** | ***ESE/77.0*** | ***208.2 / -24.24*** | ***1 HOUR PHOTO PLUS 43-493***
24 RAMBLER DRIVE
BRAMPTON ON L6W 1E2 | ***GEN***

Generator No: ON1592500
SIC Code: 6571
SIC Description: CAMERA/PHOTO. SUPPLY
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

138 | ***1 of 11*** | ***ESE/87.3*** | ***208.2 / -24.25*** | ***Peel Village Medical Centre***
28 Rambler Drive
Brampton ON L6W 1E2 | ***GEN***

Generator No: ON6791848
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: PATHOLOGICAL WASTES

---

138 **2 of 11** **ESE/87.3** **208.2 / -24.25** **Peel Village Medical Centre** **GEN**
28 Rambler Drive
Brampton ON L6W 1E2

Generator No: ON6791848
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

138 **3 of 11** **ESE/87.3** **208.2 / -24.25** **Peel Village Medical Centre** **GEN**
28 Rambler Drive
Brampton ON L6W 1E2

Generator No: ON6791848
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

138 **4 of 11** **ESE/87.3** **208.2 / -24.25** **Peel Village Medical Centre** **GEN**
28 Rambler Drive
Brampton ON

Generator No: ON6791848
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2013
PO Box No:
Country:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

138 | ***5 of 11*** | ***ESE/87.3*** | ***208.2 / -24.25*** | ***Peel Village Medical Centre***
28 Rambler Drive
Brampton ON L6W 1E2 | ***GEN***

Generator No: ON6791848
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

138 | ***6 of 11*** | ***ESE/87.3*** | ***208.2 / -24.25*** | ***Peel Village Medical Centre***
28 Rambler Drive
Brampton ON L6W 1E2 | ***GEN***

Generator No: ON6791848
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

138 **7 of 11** **ESE/87.3** **208.2 / -24.25** **Peel Village Medical Centre**
28 Rambler Drive
Brampton ON L6W 1E2 **GEN**

Generator No: ON6791848
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

138 **8 of 11** **ESE/87.3** **208.2 / -24.25** **Peel Village Medical Centre**
28 Rambler Drive
Brampton ON L6W 1E2 **GEN**

Generator No: ON6791848
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

138 **9 of 11** **ESE/87.3** **208.2 / -24.25** **Peel Village Medical Centre**
28 Rambler Drive
Brampton ON L6W 1E2 **GEN**

Generator No: ON6791848
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

138 | ***10 of 11*** | ***ESE/87.3*** | ***208.2 / -24.25*** | ***Peel Village Medical Centre***
28 Rambler Drive
Brampton ON L6W 1E2 | ***GEN***

Generator No: ON6791848
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

138 | ***11 of 11*** | ***ESE/87.3*** | ***208.2 / -24.25*** | ***Peel Village Medical Centre***
28 Rambler Drive
Brampton ON L6W 1E2 | ***GEN***

Generator No: ON6791848
SIC Code:
SIC Description:
Approval Years: As of Jul 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

139 **1 of 1** **ESE/93.2** **208.1 / -24.37** **Dr. sarbjeet singh**
30 rambler drive
brampton ON L6W1E2 **GEN**

Generator No: ON9577907
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

140 **1 of 10** **ESE/46.7** **206.8 / -25.63** **National Cable Specialists**
300D Kennedy Rd S
Brampton ON L6W 4V2 **SCT**

Established: 01-AUG-84
Plant Size (ft²): 30000
Employment:

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Metal Service Centres
SIC/NAICS Code: 416210

Description: Electronic Components, Navigational and Communications Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417320

---

140 **2 of 10** **ESE/46.7** **206.8 / -25.63** **Noramco Wire & Cable**
300D Kennedy Rd S
Brampton ON L6W 4V2 **SCT**

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Electronic Components, Navigational and Communications Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417320

Description: Mining and Oil and Gas Well Machinery, Equipment and Supplies Wholesaler-Distributors

SIC/NAICS Code: 417220

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

---

140 ***3 of 10*** ***ESE/46.7*** ***206.8 / -25.63*** ***OHL Contract Logistics***
300 Kennedy Road S - Unit B
Brampton ON ***GEN***

Generator No: ON5282501
SIC Code: 493110
SIC Description: GENERAL WAREHOUSING AND STORAGE
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

140 ***4 of 10*** ***ESE/46.7*** ***206.8 / -25.63*** ***OHL Contract Logistics***
300 Kennedy Road S - Unit B
Brampton ON L6W 4V2 ***GEN***

Generator No: ON5282501
SIC Code: 493110
SIC Description: GENERAL WAREHOUSING AND STORAGE
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 263

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

140 | **5 of 10** | **ESE/46.7** | **206.8 / -25.63** | **OHL Contract Logistics**
300 Kennedy Road S - Unit B
Brampton ON L6W 4V2 | **GEN**

Generator No: ON5282501
SIC Code: 493110
SIC Description: GENERAL WAREHOUSING AND STORAGE
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

140 | **6 of 10** | **ESE/46.7** | **206.8 / -25.63** | **OHL Contract Logistics**
300 Kennedy Road S - Unit B
Brampton ON L6W 4V2 | **GEN**

Generator No: ON5282501
SIC Code: 493110
SIC Description: GENERAL WAREHOUSING AND STORAGE
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

---

140 | **7 of 10** | **ESE/46.7** | **206.8 / -25.63** | **OHL Contract Logistics**
300 Kennedy Road S - Unit B
Brampton ON L6W 4V2 | **GEN**

Generator No: ON5282501
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 261 L
Waste Class Name: Pharmaceuticals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

---

140 | ***8 of 10*** | ***ESE/46.7*** | ***206.8 / -25.63*** | ***OHL Contract Logistics***
300 Kennedy Road S - Unit B
Brampton ON L6W 4V2 | ***GEN***

Generator No: ON5282501
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 261 L
Waste Class Name: Pharmaceuticals

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

---

140 | ***9 of 10*** | ***ESE/46.7*** | ***206.8 / -25.63*** | ***OHL Contract Logistics***
300 Kennedy Road S - Unit B
Brampton ON L6W 4V2 | ***GEN***

Generator No: ON5282501

SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 121 C
Waste Class Name: Alkaline slutions - containing heavy metals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 261 L
Waste Class Name: Pharmaceuticals

---

140 | ***10 of 10*** | ***ESE/46.7*** | ***206.8 / -25.63*** | ***OHL Contract Logistics***
300 Kennedy Road S - Unit B
Brampton ON L6W 4V2 | ***GEN***

Generator No: ON5282501
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 L
Waste Class Name: PHARMACEUTICALS

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 121 C
Waste Class Name: ALKALINE WASTES - HEAVY METALS

---

141 | ***1 of 2*** | ***ESE/81.6*** | ***208.8 / -23.63*** | ***TST***
365 Kennedy Rd S Unit 116
Brampton ON L6W 3H3 | ***SCT***

Established: 1996
Plant Size (ft²):

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Employment: 3

--Details--
Description: Showcase, Partition, Shelving and Locker Manufacturing
SIC/NAICS Code: 337215

Description: Office Supplies (except Paper) Manufacturing
SIC/NAICS Code: 339940

Description: Sign Manufacturing
SIC/NAICS Code: 339950

---

141 ***2 of 2*** ***ESE/81.6*** ***208.8 / -23.63*** ***T.S.T. Enterprises*** ***SCT***
365 Kennedy Rd S Suite 116
Brampton ON L6W 3H3

Established: 1996
Plant Size (ft²):
Employment: 3

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: All Other Miscellaneous Chemical Product Manufacturing
SIC/NAICS Code: 325999

Description: Office Supplies (except Paper) Manufacturing
SIC/NAICS Code: 339940

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Stationery and Office Supplies Wholesaler-Distributors
SIC/NAICS Code: 418210

Description: All Other Wholesaler-Distributors
SIC/NAICS Code: 418990

Description: Machinery, Equipment and Supplies Agents and Brokers
SIC/NAICS Code: 419170

Description: Other Wholesale Agents and Brokers
SIC/NAICS Code: 419190

---

142 ***1 of 13*** ***ESE/93.6*** ***207.8 / -24.63*** ***Lowe's Companies Canada, ULC*** ***GEN***
370 Kennedy Road South
Brampton ON L6W4V2

Generator No: ON7488106
SIC Code: 444190 444110
SIC Description: Other Building Material Dealers, Home Centres
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
142	2 of 13	ESE/93.6	207.8 / -24.63	Lowe's Companies Canada, ULC 370 Kennedy Road South Brampton ON L6W 4V2	GEN

Generator No: ON7488106
SIC Code: 444190, 444110
SIC Description: Other Building Material Dealers, Home Centres
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
142	3 of 13	ESE/93.6	207.8 / -24.63	Lowe's Companies Canada, ULC 370 Kennedy Road South Brampton ON L6W 4V2	GEN

Generator No: ON7488106
SIC Code: 444190, 444110
SIC Description: Other Building Material Dealers, Home Centres
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

142 **4 of 13** **ESE/93.6** **207.8 / -24.63** **Lowe's Companies Canada, ULC**
370 Kennedy Road South
Brampton ON L6W 4V2 **GEN**

Generator No: ON7488106
SIC Code: 444190, 444110
SIC Description: Other Building Material Dealers, Home Centres
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 221
Waste Class Name: LIGHT FUELS

---

142 **5 of 13** **ESE/93.6** **207.8 / -24.63** **Lowe's Companies Canada, ULC**
370 Kennedy Road South
Brampton ON L6W4V2 **GEN**

Generator No: ON7488106
SIC Code: 444190, 444110
SIC Description: Other Building Material Dealers, Home Centres
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145

Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

---

142 | ***6 of 13*** | ***ESE/93.6*** | ***207.8 / -24.63*** | ***Lowe's Companies Canada, ULC***
370 Kennedy Road South
Brampton ON | ***GEN***

Generator No: ON7488106
SIC Code: 444190, 444110
SIC Description: OTHER BUILDING MATERIAL DEALERS, HOME CENTRES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

142 | ***7 of 13*** | ***ESE/93.6*** | ***207.8 / -24.63*** | ***Lowe's Companies Canada, ULC***
370 Kennedy Road South
Brampton ON L6W4V2 | ***GEN***

Generator No: ON7488106
SIC Code: 444190, 444110
SIC Description: OTHER BUILDING MATERIAL DEALERS, HOME CENTRES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:

Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

142	***8 of 13***	***ESE/93.6***	***207.8 / -24.63***	***Lowe's Companies Canada, ULC*** ***370 Kennedy Road South*** ***Brampton ON L6W4V2***	***GEN***

Generator No: ON7488106
SIC Code: 444190, 444110
SIC Description: OTHER BUILDING MATERIAL DEALERS, HOME CENTRES
Approval Years: 2016
PO Box No:

Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS
Waste Class:	262
Waste Class Name:	DETERGENTS/SOAPS
Waste Class:	269
Waste Class Name:	NON-HALOGENATED PESTICIDES
Waste Class:	242
Waste Class Name:	HALOGENATED PESTICIDES
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	221
Waste Class Name:	LIGHT FUELS
Waste Class:	261
Waste Class Name:	PHARMACEUTICALS
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS
Waste Class:	135
Waste Class Name:	REACTIVE ANION WASTES
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	146
Waste Class Name:	OTHER SPECIFIED INORGANICS
Waste Class:	112
Waste Class Name:	ACID WASTE - HEAVY METALS
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
142	9 of 13	ESE/93.6	207.8 / -24.63	**Lowe's Companies Canada, ULC** **370 Kennedy Road South** **Brampton ON L6W4V2**	GEN

Generator No:	ON7488106
SIC Code:	444190, 444110

SIC Description:	OTHER BUILDING MATERIAL DEALERS, HOME CENTRES
Approval Years:	2014
PO Box No:	
Country:	Canada
Status:	
Co Admin:	
Choice of Contact:	CO_OFFICIAL
Phone No Admin:	
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	135
Waste Class Name:	REACTIVE ANION WASTES
Waste Class:	148
Waste Class Name:	INORGANIC LABORATORY CHEMICALS
Waste Class:	145
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	331
Waste Class Name:	WASTE COMPRESSED GASES
Waste Class:	242
Waste Class Name:	HALOGENATED PESTICIDES
Waste Class:	221
Waste Class Name:	LIGHT FUELS
Waste Class:	263
Waste Class Name:	ORGANIC LABORATORY CHEMICALS

142	***10 of 13***	***ESE/93.6***	***207.8 / -24.63***	***Lowe's Companies Canada, ULC*** ***370 Kennedy Road South*** ***Brampton ON L6W4V2***	***GEN***

Generator No:	ON7488106
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	112 C
Waste Class Name:	Acid solutions - containing heavy metals
Waste Class:	122 C
Waste Class Name:	Alkaline slutions - containing other metals and non-metals (not cyanide)
Waste Class:	145 L

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	146 T
Waste Class Name:	Other specified inorganic sludges, slurries or solids
Waste Class:	148 A
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	148 C
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	148 I
Waste Class Name:	Misc. wastes and inorganic chemicals
Waste Class:	212 I
Waste Class Name:	Aliphatic solvents and residues
Waste Class:	213 I
Waste Class Name:	Petroleum distillates
Waste Class:	221 I
Waste Class Name:	Light fuels
Waste Class:	242 B
Waste Class Name:	Halogenated pesticides and herbicides
Waste Class:	242 T
Waste Class Name:	Halogenated pesticides and herbicides
Waste Class:	252 L
Waste Class Name:	Waste crankcase oils and lubricants
Waste Class:	261 L
Waste Class Name:	Pharmaceuticals
Waste Class:	262 L
Waste Class Name:	Detergents and soaps
Waste Class:	263 A
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	263 I
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	263 L
Waste Class Name:	Misc. waste organic chemicals
Waste Class:	269 T
Waste Class Name:	Organic non-halogenated pesticide and herbicide wastes
Waste Class:	331 I
Waste Class Name:	Waste compressed gases including cylinders
Waste Class:	331 L
Waste Class Name:	Waste compressed gases including cylinders

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
142	11 of 13	ESE/93.6	207.8 / -24.63	**Lowe's Companies Canada, ULC** **370 Kennedy Road South** **Brampton ON L6W4V2**	GEN

Generator No:	ON7488106
SIC Code:	
SIC Description:	
Approval Years:	As of Jul 2020
PO Box No:	

Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 242 B
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 242 T
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 112 C
Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 261 L

Waste Class Name: Pharmaceuticals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

142 | **12 of 13** | **ESE/93.6** | **207.8 / -24.63** | **Lowe's Companies Canada, ULC**
370 Kennedy Road South
Brampton ON L6W4V2 | **GEN**

Generator No: ON7488106
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 262 L
Waste Class Name: Detergents and soaps

Waste Class: 242 T
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 242 B
Waste Class Name: Halogenated pesticides and herbicides

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 213 I
Waste Class Name: Petroleum distillates

Waste Class: 148 I
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 112 C

Waste Class Name: Acid solutions - containing heavy metals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 269 T
Waste Class Name: Organic non-halogenated pesticide and herbicide wastes

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 261 L
Waste Class Name: Pharmaceuticals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

142	13 of 13	ESE/93.6	207.8 / -24.63	**Lowe's Companies Canada, ULC** **370 Kennedy Road South** **Brampton ON L6W4V2**	GEN

Generator No: ON7488106
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 242 T
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 112 C
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331 I

Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148 A
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 269 T
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 261 L
Waste Class Name: PHARMACEUTICALS

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 148 I
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263 A
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 213 I
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 262 L
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 242 B
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 331 L
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

---

143 | **1 of 1** | **ESE/65.8** | **209.8 / -22.64** | **3 Scotsdale Court Brampton ON** | **SPL**

Ref No: 0045-7U988L
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/24/2009
Dt Document Closed:
Site No:
MOE Response: No Field Response
Site County/District:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	Gasoline to CB<UNOFFICIAL>
Site Address:	
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	Other Discharges
Incident Preceding Spill:	
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Surface Water Pollution
Contaminant Qty:	0.25 L
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	GASOLINE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	Spill
Incident Summary:	Vehicle leaked gas to CB; cont and clnd.
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

---

144 **1 of 4** **ESE/13.9** **208.8 / -23.63** **Michaels Stores, Inc.**
120 Resolution Dr
Brampton ON L6W 4P9
GEN

Generator No:	ON7479479
SIC Code:	
SIC Description:	
Approval Years:	As of Dec 2018
PO Box No:	
Country:	Canada
Status:	Registered
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	145 I
Waste Class Name:	Wastes from the use of pigments, coatings and paints
Waste Class:	145 L
Waste Class Name:	Wastes from the use of pigments, coatings and paints

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
144	2 of 4	ESE/13.9	208.8 / -23.63	Michaels Stores, Inc. 120 Resolution Dr Brampton ON L6W 4P9	GEN

Generator No: ON7479479
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
144	3 of 4	ESE/13.9	208.8 / -23.63	Michaels Stores, Inc. 120 Resolution Dr	GEN

Brampton ON L6W 4P9

Generator No: ON7479479
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 331 I
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 122 C
Waste Class Name: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 263 L
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 331 L
Waste Class Name: Waste compressed gases including cylinders

Waste Class: 148 A
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 263 A
Waste Class Name: Misc. waste organic chemicals

Waste Class: 146 T
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 145 L
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

144 ***4 of 4*** ***ESE/13.9*** ***208.8 / -23.63*** ***Michaels Stores, Inc.***
120 Resolution Dr
Brampton ON L6W 4P9 ***GEN***

Generator No: ON7479479
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122 C
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 146 T
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 145 L
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331 I
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263 A
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 263 L
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 331 L
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 148 A
Waste Class Name: INORGANIC LABORATORY CHEMICALS

---

145 ***1 of 1*** ***ESE/16.5*** ***209.7 / -22.82*** ***DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT 350 KENNEDY RD S BRAMPTON ON*** ***EXP***

Inventory No: 10597276
Inventory Status: EXPIRED
Installation Year: 1974
Capacity: 47000
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

146 ***1 of 17*** ***ESE/16.5*** ***209.7 / -22.82*** ***CHRYSLER (CANADA) INC. 350 KENNEDY ROAD SOUTH BRAMPTON ON L6V 2M3*** ***NPCB***

Company Code: O0424
Industry: Other
Site Status:
Transaction Date: 8/30/1990
Inspection Date: 2/14/1989

--Details--
Label:
Serial No.:

PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Use
Contents: 1.50 L

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Use
Contents: 3.00 L

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Use
Contents: 4.50 L

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Use
Contents: 11.40 L

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Use
Contents: 22.80 L

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Use
Contents: 29.00 L

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Use

Contents: 38.60 L

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Use
Contents: 77.20 L

---

146 | ***2 of 17*** | ***ESE/16.5*** | ***209.7 / -22.82*** | ***CHRYSLER CANADA LTD. BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON CITY ON*** | ***SPL***

Ref No: 9913
Year:
Incident Dt: 9/30/1988
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/30/1988
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER CONTAINER LEAK
Incident Preceding Spill:
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: ERROR
Incident Summary: CHRYSLER- PUNCTURED DRUM LEAKED APPROX. 60 L TO DYKED AREA.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	3 of 17	ESE/16.5	209.7 / -22.82	CHRYSLER CANADA LTD. BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON CITY ON	SPL

Ref No:	125647	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	4/29/1996	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	4/29/1996	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	UNKNOWN		
Incident Preceding Spill:			
Environment Impact:	CONFIRMED		
Health Env Consequence:			
Nature of Impact:	Soil contamination		
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Incident Reason:	UNKNOWN		
Incident Summary:	CHRYSLER-25 L BODY WASHERSLUDGE TO GROUND.NONE TO DRAINS.EXCAVATING.		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	4 of 17	ESE/16.5	209.7 / -22.82	CHRYSLER CANADA LTD. 350 KENNEDY ROAD S. BRAMPTON ON L6V 2M3	GEN

Generator No:	ON0000608
SIC Code:	3231
SIC Description:	MOTOR VEHICLE IND.
Approval Years:	88,89,90
PO Box No:	
Country:	

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	5 of 17	ESE/16.5	209.7 / -22.82	CHRYSLER CANADA LTD. 10-341 350 KENNEDY ROAD S. BRAMPTON ON L6W 4P1	GEN

Generator No: ON0000608
SIC Code: 3231
SIC Description: MOTOR VEHICLE IND.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 131
Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
146	6 of 17	ESE/16.5	209.7 / -22.82	CHRYSLER CANADA LIMITED BRAMPTON ASSEMBLY PLANT 350 KENNEDY ROAD SOUTH BRAMPTON ON L6W 4P1	GEN

Generator No: ON0000608
SIC Code: 3231
SIC Description: MOTOR VEHICLE IND.
Approval Years: 98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 123
Waste Class Name: ALKALINE PHOSPHATES

Waste Class: 131

Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

146 | **7 of 17** | **ESE/16.5** | **209.7 / -22.82** | **AMERICAN MOTORS (CANADA) LTD.**
350 KENNEDY ROAD SOUTH
BRAMPTON ON L6V 2M3 | **GEN**

Generator No: ON0007700
SIC Code: 3231
SIC Description: MOTOR VEHICLE IND.
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221

Waste Class Name: LIGHT FUELS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

---

146 | ***8 of 17*** | ***ESE/16.5*** | ***209.7 / -22.82*** | ***AMERICAN MOTORS SEE&USE ON0000608***
350 KENNEDY ROAD SOUTH
BRAMPTON ON L6V 2M3 | ***GEN***

Generator No: ON0007700
SIC Code: 3231
SIC Description: MOTOR VEHICLE IND.
Approval Years: 88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 265
Waste Class Name: GRAPHIC ART WASTES

---

146 | **9 of 17** | **ESE/16.5** | **209.7 / -22.82** | **AMERICAN (SEE & USE ON0000608)**
350 KENNEDY ROAD SOUTH
BRAMPTON ON L6V 2M3 | **GEN**

Generator No: ON0007700
SIC Code: 3231
SIC Description: MOTOR VEHICLE IND.
Approval Years: 90,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

146 | **10 of 17** | **ESE/16.5** | **209.7 / -22.82** | **AMERICAN (SEE & USE ON0000608) 03-063**
350 KENNEDY ROAD SOUTH
BRAMPTON ON L6V 2M3 | **GEN**

Generator No: ON0007700
SIC Code: 3231
SIC Description: MOTOR VEHICLE IND.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

146 | **11 of 17** | **ESE/16.5** | **209.7 / -22.82** | **Rutherford Properties Ltd.**
350 Kennedy Road South
Brampton ON L5B 1M3 | **GEN**

Generator No: ON8281083
SIC Code: 238990
SIC Description: All Other Specialty Trade Contractors
Approval Years: 05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

146 **12 of 17** **ESE/16.5** **209.7 / -22.82** **CHRYSLER (CANADA) INC.**
350 KENNEDY RD S
BRAMPTON ON L6V 2M3
NPCB

Company Code: O0424
Industry: OTHER
Site Status: NO MORE PCB'S ON THIS SITE
Transaction Date: 8/15/1996
Inspection Date: 2/14/1989

---

146 **13 of 17** **ESE/16.5** **209.7 / -22.82** **DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT**
350 KENNEDY RD S
BRAMPTON ON
DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9379534
Status: EXPIRED
Instance ID: 385569
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: Fuels Safety Private Fuel Outlet - Self Serve
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

146 **14 of 17** **ESE/16.5** **209.7 / -22.82** **DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT**
350 KENNEDY RD S
BRAMPTON ON
DTNK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Delisted Expired Fuel Safety Facilities

Instance No:	9904231	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	397912	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Refill Cntr - Cylr Fill		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

146	***15 of 17***	***ESE/16.5***	***209.7 / -22.82***	***DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT 350 KENNEDY RD S BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10597304	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	30194	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

146 ***16 of 17*** ***ESE/16.5*** ***209.7 / -22.82*** ***DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT 350 KENNEDY RD S BRAMPTON ON*** ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10597323
Status: EXPIRED
Instance ID: 29744
Instance Type: FS Propane Tank
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

146 ***17 of 17*** ***ESE/16.5*** ***209.7 / -22.82*** ***DO NOT USE-CHRYSLER CANADA LTD ATTN LINDA BURNETT 350 KENNEDY RD S BRAMPTON ON*** ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10597345
Status: EXPIRED
Instance ID: 29904
Instance Type: FS Propane Tank
Instance Creation Dt:
Instance Install Dt:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:

Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Tank		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

147	***1 of 5***	***ESE/78.2***	***209.2 / -23.27***	***TONY'S CUSTOM CLEANERS*** ***400 STEELS AVE. E.*** ***BRAMPTON ON L6W 3R2***	***GEN***

Generator No:	ON0963000
SIC Code:	0000
SIC Description:	*** NOT DEFINED ***
Approval Years:	86,87,88
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	241
Waste Class Name:	HALOGENATED SOLVENTS

147	***2 of 5***	***ESE/78.2***	***209.2 / -23.27***	***TONY'S CUSTOM CLEANERS*** ***400 STEELS AVE. E.*** ***BRAMPTON ON L6W 3R2***	***GEN***

Generator No:	ON0963000
SIC Code:	9721
SIC Description:	POWER LAUND./CLEANER
Approval Years:	89,90
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

147 | ***3 of 5*** | ***ESE/78.2*** | ***209.2 / -23.27*** | ***TONY'S CUSTOM CLEANERS 38-332***
400 STEELS AVE. E.
BRAMPTON ON L6W 3R2 | ***GEN***

Generator No: ON0963000
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

147 | ***4 of 5*** | ***ESE/78.2*** | ***209.2 / -23.27*** | ***TONY'S CUSTOM CLEANERS***
400 STEELES AVENUE EAST
BRAMPTON ON L6W 3R2 | ***GEN***

Generator No: ON0963000
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

147 | ***5 of 5*** | ***ESE/78.2*** | ***209.2 / -23.27*** | ***Distributors Choice Chemical***
400 Steeles Ave E Unit 231
Brampton ON L6W 3R2 | ***SCT***

Established: 1989
Plant Size (ft²): 65000
Employment: 21

--Details--
Description: Soap and Cleaning Compound Manufacturing
SIC/NAICS Code: 325610

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: All Other Miscellaneous Chemical Product Manufacturing
SIC/NAICS Code: 325999

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

---

148 **1 of 5** **ESE/99.4** **207.6 / -24.84** **GTA Healthcare Management Inc (II)**
90 Resolution Drive Unit 2
Brampton ON L6W 0A7
GEN

Generator No: ON7230712
SIC Code: 621110, 621390
SIC Description: OFFICES OF PHYSICIANS, OFFICES OF ALL OTHER HEALTH PRACTITIONERS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Samir Patel
Choice of Contact: CO_OFFICIAL
Phone No Admin: 4168833877 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

148 **2 of 5** **ESE/99.4** **207.6 / -24.84** **GTA Healthcare Management Inc (II)**
90 Resolution Drive Unit 2
Brampton ON L6W 0A7
GEN

Generator No: ON7230712
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

148 **3 of 5** **ESE/99.4** **207.6 / -24.84** **GTA Healthcare Management Inc (II)**
90 Resolution Drive Unit 2
Brampton ON L6W 0A7
GEN

Generator No: ON7230712

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

148 *4 of 5* *ESE/99.4* *207.6 / -24.84* ***GTA Healthcare Management Inc (II)*** ***GEN***
90 Resolution Drive Unit 2
Brampton ON L6W 0A7

Generator No: ON7230712
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

---

148 *5 of 5* *ESE/99.4* *207.6 / -24.84* ***GTA Healthcare Management Inc (II)*** ***GEN***
90 Resolution Drive Unit 2
Brampton ON L6W 0A7

Generator No: ON7230712
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

---

149 | ***1 of 1*** | ***ESE/12.7*** | ***208.6 / -23.88*** | ***Rutherford Properties Ltd***
410 Steeles Avenue
Brampton ON | ***GEN***

Generator No: ON3033469
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

150 | ***1 of 2*** | ***ESE/27.8*** | ***208.1 / -24.42*** | ***Canadian Waste Services Inc.***
Kennedy Road at Steeles Ave<UNOFFICIAL>
Brampton ON | ***SPL***

Ref No: 7433-6FLM88
Year:
Incident Dt: 8/25/2005
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/25/2005
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Kennedy Road at Steeles Ave<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Tank (Underground) Leak

Municipality No:
Nature of Damage:
Discharger Report: 0
Material Group: Oil
Impact to Health:
Agency Involved:

Incident Preceding Spill:	
Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	Soil Contamination
Contaminant Qty:	150 L
System Facility Address:	
Client Name:	Canadian Waste Services Inc.
Client Type:	
Source Type:	
Contaminant Code:	
Contaminant Name:	HYDRAULIC OIL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Debris on Road
Incident Summary:	Canadian Waste: 150 L hydraulic oil to road and c/b
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other Motor Vehicle
SAC Action Class:	Spills to Land
Call Report Locatn Geodata:	

---

150 | ***2 of 2*** | ***ESE/27.8*** | ***208.1 / -24.42*** | ***Canada Cartage Diversified Gp. Inc.***
Kennedy Road (50 feet north of Steeles Ave)
<UNOFFICIAL>
Brampton ON | ***SPL***

Ref No:	0118-7HZ3FZ	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:		**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/29/2008	**Impact to Health:**	
Dt Document Closed:	9/12/2008	**Agency Involved:**	
Site No:			

MOE Response:	No Field Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	Kennedy Road (50 feet north of Steeles Ave)<UNOFFICIAL>
Site Address:	
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	Other Transport Accident
Incident Preceding Spill:	
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	150 L
System Facility Address:	
Client Name:	Canada Cartage Diversified Gp. Inc.
Client Type:	
Source Type:	
Contaminant Code:	13
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Equipment/Vehicles
Incident Summary: Canada Cartage, Transport Truck MVA, 150 L diesel to c/b
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:

151	*1 of 16*	*ESE/27.6*	*207.9 / -24.53*	***SOLOMON ESSO*** ***7995 KENNEDY RD*** ***BRAMPTON ON L6V3N2***	***RST***

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054559697
List Name:
Description:

151	*2 of 16*	*ESE/27.6*	*207.9 / -24.53*	***KENNEDY ESSO*** ***7995 KENNEDYS*** ***BRAMPTON ON***	***RST***

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9054519107
List Name:
Description:

151	*3 of 16*	*ESE/27.6*	*207.9 / -24.53*	***1520348 ONTARIO LTD ATT FIDA ELDEBS*** ***7995 KENNEDY RD S*** ***BRAMPTON ON***	***FSTH***

License Issue Date: 8/30/2002
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 2007
Corrosion Protection:
Capacity: 25000
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

Status: Active
Year of Installation: 2007
Corrosion Protection:
Capacity: 65000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2007
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

Status: Active
Year of Installation: 2007
Corrosion Protection:
Capacity: 65000
Tank Fuel Type: Liquid Fuel Double Wall UST - Gasoline

---

151 **4 of 16** **ESE/27.6** **207.9 / -24.53** **UNIPETRO INVESTMENTS INC ATTN AC CHOU**
7995 KENNEDY RD S
BRAMPTON ON L6V 3N2
DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 10030092
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 6/1/1991
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

151 **5 of 16** **ESE/27.6** **207.9 / -24.53** **IMPERIAL OIL LTD *** DO NOT USE**
7995 KENNEDY RD S
BRAMPTON ON L6V 3N2
DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9859167
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:

Expired Date: 12/2/1993
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:

Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

151 **6 of 16** **ESE/27.6** **207.9 / -24.53** **MAC'S CONVENIENCE STORES INC.** **FST**
7995 KENNEDY RD
BRAMPTON ON

Inventory No:	48892928	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2007	**Overfill Protection:**	
Capacity:	25000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS		

151 **7 of 16** **ESE/27.6** **207.9 / -24.53** **MAC'S CONVENIENCE STORES INC.** **FST**
7995 KENNEDY RD
BRAMPTON ON

Inventory No:	48892935	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2007	**Overfill Protection:**	
Capacity:	50000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			
Model:			
Description:	2009VBS Premium		

151 **8 of 16** **ESE/27.6** **207.9 / -24.53** **MAC'S CONVENIENCE STORES INC.** **FST**
7995 KENNEDY RD
BRAMPTON ON

Inventory No:	48892934	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active	**Corrosion Protect:**	Fiberglass
Installation Year:	2007	**Overfill Protection:**	
Capacity:	65000	**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L	**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:	Double Wall UST		
Manufacturer:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Model:
Description: 2009VBS

---

151 | **9 of 16** | **ESE/27.6** | **207.9 / -24.53** | **MAC'S CONVENIENCE STORES INC.**
7995 KENNEDY RD
BRAMPTON ON | **FST**

Inventory No: 48892936
Inventory Status: active
Installation Year: 2007
Capacity: 65000
Capacity Unit: L
Tank Type: Double Wall UST
Manufacturer:
Model:
Description: 2009VBS

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel
Inventory Item: FS Liquid Fuel Tank

---

151 | **10 of 16** | **ESE/27.6** | **207.9 / -24.53** | **KENNEDY ESSO**
7995 KENNEDY RD
BRAMPTON ON L6W0A2 | **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 9054519107
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

151 | **11 of 16** | **ESE/27.6** | **207.9 / -24.53** | **1520348 ONTARIO LTD ATT FIDA ELDEBS**
7995 KENNEDY RD
BRAMPTON ON | **EXP**

Inventory No: 11281340
Inventory Status: EXPIRED
Installation Year: 1985
Capacity: 22755
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Extra
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

151 | **12 of 16** | **ESE/27.6** | **207.9 / -24.53** | **1520348 ONTARIO LTD ATT FIDA ELDEBS**
7995 KENNEDY RD
BRAMPTON ON | **EXP**

Inventory No: 11281323
Inventory Status: EXPIRED
Installation Year: 1985
Capacity: 46419
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
E2000
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
151	13 of 16	ESE/27.6	207.9 / -24.53	1520348 ONTARIO LTD ATT FIDA ELDEBS 7995 KENNEDY RD BRAMPTON ON	EXP

Inventory No: 11281366
Inventory Status: EXPIRED
Installation Year: 1985
Capacity: 22755
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
151	14 of 16	ESE/27.6	207.9 / -24.53	1520348 ONTARIO LTD ATT FIDA ELDEBS 7995 KENNEDY RD BRAMPTON ON	EXP

Inventory No: 11281385
Inventory Status: EXPIRED
Installation Year: 1985
Capacity: 22755
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Diesel

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
151	15 of 16	ESE/27.6	207.9 / -24.53	1520348 ONTARIO LTD ATT FIDA ELDEBS 7995 KENNEDY RD BRAMPTON ON	EXP

Inventory No: 11281348
Inventory Status: EXPIRED
Installation Year: 1985
Capacity: 22755
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
151	16 of 16	ESE/27.6	207.9 / -24.53	MAC'S CONVENIENCE STORES INC. 7995 KENNEDY RD BRAMPTON ON	FST

Inventory No: 10077206
Inventory Status: Active
Installation Year:
Capacity: 205000
Capacity Unit: L
Tank Type:
Manufacturer:
Model:
Description:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: Liquid Fuels
Inventory Item: FS Gasoline Station - Self Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
152	1 of 1	ESE/62.8	206.9 / -25.53	English Prestige 7980 KENNEDY ROAD SOUTH Brampton ON	GEN

Generator No: ON5126099
SIC Code: 236220
SIC Description: COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 150
Waste Class Name: INERT INORGANIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	1 of 4	ESE/95.3	206.1 / -26.43	Dr. Amanpreet Chopra Dentistry Prof Corp 7-7990 Kennedy Road South Brampton ON L6W 0B3	GEN

Generator No: ON5464097
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
153	2 of 4	ESE/95.3	206.1 / -26.43	Dr. Amanpreet Chopra Dentistry Prof Corp 7-7990 Kennedy Road South Brampton ON L6W 0B3	GEN

Generator No: ON5464097
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

153 | ***3 of 4*** | ***ESE/95.3*** | ***206.1 / -26.43*** | ***Dr. Amanpreet Chopra Dentistry Prof Corp***
7-7990 Kennedy Road South
Brampton ON L6W 0B3 | ***GEN***

Generator No: ON5464097
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

153 | ***4 of 4*** | ***ESE/95.3*** | ***206.1 / -26.43*** | ***Dr. Amanpreet Chopra Dentistry Prof Corp***
7-7990 Kennedy Road South
Brampton ON L6W 0B3 | ***GEN***

Generator No: ON5464097
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

154 | ***1 of 16*** | ***ESE/81.8*** | ***204.6 / -27.84*** | ***PEEL BOARD OF EDUCATION***
J. A. TURNER S.S. 7935 KENNEDY RD. S.
BRAMPTON ON L6V 3N2 | ***GEN***

Generator No: ON0359810
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

154 | ***2 of 16*** | ***ESE/81.8*** | ***204.6 / -27.84*** | ***PEEL BOARD OF EDUCATION 30-190 TURNER FENTON SECONDARY SCHOOL 7935 KENNEDY ROAD SOUTH BRAMPTON ON L5B 1N7*** | ***GEN***

Generator No: ON0359810
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 92,93,94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
154	3 of 16	ESE/81.8	204.6 / -27.84	PEEL DISTRICT SCHOOL BOARD TURNER FENTON SECONDARY SCHOOL 7935 KENNEDY ROAD SOUTH BRAMPTON ON L5B 1N7	GEN

Generator No: ON0359810
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 97,98,99,00,01,02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
154	4 of 16	ESE/81.8	204.6 / -27.84	PEEL DISTRICT SCHOOL BOARD 7935 Kennedy Road South BRAMPTON ON L5B 1N7	GEN

Generator No: ON0359810
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 243
Waste Class Name: PCB'S

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

154 | **5 of 16** | **ESE/81.8** | **204.6 / -27.84** | **Peel District School Board**
7935 Kennedy Road South
Brampton ON | **GEN**

Generator No: ON0359810
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

---

154 | **6 of 16** | **ESE/81.8** | **204.6 / -27.84** | **Peel District School Board**
7935 Kennedy Road South
Brampton ON | **GEN**

Generator No: ON0359810
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
154	7 of 16	ESE/81.8	204.6 / -27.84	Peel District School Board 7935 Kennedy Road South Brampton ON	GEN

Generator No: ON0359810
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
154	8 of 16	ESE/81.8	204.6 / -27.84	Peel District School Board 7935 Kennedy Road South Brampton ON	GEN

Generator No: ON0359810
SIC Code: 611710
SIC Description: Educational Support Services
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
154	9 of 16	ESE/81.8	204.6 / -27.84	**Peel District School Board** **7935 Kennedy Road South** **Brampton ON**	GEN

Generator No: ON0359810
SIC Code: 611710
SIC Description: EDUCATIONAL SUPPORT SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

154 | **10 of 16** | **ESE/81.8** | **204.6 / -27.84** | **Peel District School Board**
7935 Kennedy Road South
Brampton ON L5B 1N7 | **GEN**

Generator No: ON0359810
SIC Code: 611710
SIC Description: EDUCATIONAL SUPPORT SERVICES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

154 **11 of 16** **ESE/81.8** **204.6 / -27.84** **Peel District School Board**
7935 Kennedy Road South
Brampton ON L5B 1N7 **GEN**

Generator No: ON0359810
SIC Code: 611710
SIC Description: EDUCATIONAL SUPPORT SERVICES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Eva Hate
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-890-1010 Ext.2762
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 243
Waste Class Name: PCBS

---

154 **12 of 16** **ESE/81.8** **204.6 / -27.84** **Peel District School Board**
7935 Kennedy Road South
Brampton ON L5B 1N7 **GEN**

Generator No: ON0359810
SIC Code: 611710
SIC Description: EDUCATIONAL SUPPORT SERVICES

Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Eva Hate
Choice of Contact: CO_ADMIN
Phone No Admin: 905-890-1010 Ext.2424
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

154	13 of 16	ESE/81.8	204.6 / -27.84	**Peel District School Board Human Resources Support Services** **7935 Kennedy Road South** **Brampton ON L5B 1N7**	GEN

Generator No: ON0359810
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 I

Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 243 D
Waste Class Name: PCB

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 263 R
Waste Class Name: Misc. waste organic chemicals

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

---

154 | ***14 of 16*** | ***ESE/81.8*** | ***204.6 / -27.84*** | ***Peel District School Board Human Resources Support Services***
7935 Kennedy Road South
Brampton ON L5B 1N7 | ***GEN***

Generator No: ON0359810
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 R
Waste Class Name: Misc. waste organic chemicals

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 243 D
Waste Class Name: PCB

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

---

154 | **15 of 16** | **ESE/81.8** | **204.6 / -27.84** | **Peel District School Board Human Resources Support Services**
7935 Kennedy Road South
Brampton ON L5B 1N7 | **GEN**

Generator No: ON0359810
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148 C
Waste Class Name: Misc. wastes and inorganic chemicals

Waste Class: 263 R
Waste Class Name: Misc. waste organic chemicals

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 145 I
Waste Class Name: Wastes from the use of pigments, coatings and paints

Waste Class: 263 I
Waste Class Name: Misc. waste organic chemicals

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 212 I
Waste Class Name: Aliphatic solvents and residues

Waste Class: 243 D
Waste Class Name: PCB

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

---

154 | **16 of 16** | **ESE/81.8** | **204.6 / -27.84** | **Peel District School Board Human Resources Support Services**
7935 Kennedy Road South
Brampton ON L5B 1N7 | **GEN**

Generator No: ON0359810
SIC Code:

SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 I
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 264 T
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 243 D
Waste Class Name: PCBS

Waste Class: 148 C
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 264 L
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 263 R
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 263 I
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145 I
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

155 | ***1 of 4*** | ***ESE/94.8*** | ***202.8 / -29.63*** | ***PEEL BOARD OF EDUCATION***
W.J. FENTON S.S. 7885 KENNEDY ROAD
SOUTH, RR# 10
BRAMPTON ON L6V 3N2 | ***GEN***

Generator No: ON0359805
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 86,87,88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

155 **2 of 4** **ESE/94.8** **202.8 / -29.63** **PEEL BOARD OF EDUCATION**
W.J. FENTON SECONDARY SCHOOL 7885
KENNEDY ROAD SOUTH, RR# 10
BRAMPTON ON L6V 3N2 **GEN**

Generator No: ON0359805
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

155 **3 of 4** **ESE/94.8** **202.8 / -29.63** **PEEL (SEE & USE ON0359810) 30-594**
W.J. FENTON SECONDARY SCHOOL 7885
KENNEDY ROAD SOUTH, RR# 10
BRAMPTON ON L6V 3N2 **GEN**

Generator No: ON0359805
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

---

155 | ***4 of 4*** | ***ESE/94.8*** | ***202.8 / -29.63*** | ***PEEL (SEE & USE ON0359810)***
W.J. FENTON SECONDARY SCHOOL 7885
KENNEDY ROAD SOUTH, RR# 10
BRAMPTON ON L6V 3N2 | ***GEN***

Generator No: ON0359805
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 242
Waste Class Name: HALOGENATED PESTICIDES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
156	1 of 2	WNW/17.6	267.9 / 35.39	Makkar Transport<UNOFFICIAL> Hwy 10 @ Old School Road Caledon ON	SPL

Ref No:	2806-9ZJSV3	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	8/19/2015	**Discharger Report:**	
Dt MOE Arvl on Scn:	8/20/2015	**Material Group:**	
MOE Reported Dt:	8/19/2015	**Impact to Health:**	
Dt Document Closed:	9/26/2015	**Agency Involved:**	
Site No:	NA		
MOE Response:	Yes		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	NE corner of Intersection<UNOFFICIAL>		
Site Address:	Hwy 10 @ Old School Road		
Site Region:			
Site Municipality:	Caledon		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:			
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	100 L		
System Facility Address:			
Client Name:	Makkar Transport<UNOFFICIAL>		
Client Type:			
Source Type:			
Contaminant Code:	13		
Contaminant Name:	DIESEL FUEL		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Incident Reason:	Operator/Human Error		
Incident Summary:	Makkar Transport 300 L dsl to rd, gravel shoulder, contained		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Unknown / N/A		
SAC Action Class:	Primary Assessment of Spills		
Call Report Locatn Geodata:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
156	2 of 2	WNW/17.6	267.9 / 35.39	hwy 10 southbound and Old School Road intersection in Brampton CALEDON ON	SPL

Ref No:	1-14BD4I	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	8/26/2021 8:00:00 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	8/26/2021 8:21:14 AM	**Impact to Health:**	0 No Impact
Dt Document Closed:	8/26/2021 2:22:46 PM	**Agency Involved:**	
Site No:			
MOE Response:	Desktop Response		

Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	
Site Address:	hwy 10 southbound and Old School Road intersection in Brampton
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	CALEDON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Accident/Collision
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	500 litre (L)
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	Truck - Only Saddle Tanks
Contaminant Code:	
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Unknown
Incident Summary:	Brampton: Diesel spill 400 L to 500 L
Activity Preceding Spill:	Transportation
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HC-Humber - Don
Sector Type:	GENERAL FREIGHT TRUCKING, LONG DISTANCE, TRUCK-LOAD
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00002456607"],"wkts":["POINT (-79.8514717356 43.7535885632)"],"creation_date":"2021-08-26"}

157	***1 of 1***	***ESE/66.4***	***202.8 / -29.63***	***Super Sucker Hydro-Vac Service***	***SPL***
				BRAMPTON ON	

Ref No:	1-2AKF1T	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	11/30/2022 2:00:00 PM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/30/2022 4:41:27 PM	**Impact to Health:**	0 No Impact
Dt Document Closed:	12/28/2022 9:28:23 AM	**Agency Involved:**	

Site No:	
MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	Super Sucker Hydro-Vac Service
Site Address:	
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	BRAMPTON
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	Leak/Break
Environment Impact:	0 No Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	40 litre (L)
System Facility Address:	466 HIGHWAY 52, HAMILTON, ON M3C 3L2
Client Name:	ALECTRA UTILITIES CORPORATION
Client Type:	Private Business
Source Type:	Transformer
Contaminant Code:	
Contaminant Name:	TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Land
Incident Reason:	Equipment failure/malfunction
Incident Summary:	Alectra Utilities: pad mount, up to 40 L (non PCB) - 78 Hartford Trail, Brampton
Activity Preceding Spill:	
Property 2nd Watershed:	02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed:	02HC | Humber River - Don River
Sector Type:	ELECTRIC POWER DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00001840522"],"wkts":["POINT (-79.7187837000 43.6722515000)"],"creation_date":"2022-11-30"}

158	***1 of 11***	***ESE/95.2***	***201.1 / -31.35***	***Arvin Meritor Canada*** ***350 First Gulf Boulevard*** ***Brampton ON L6W 4T5***	***GEN***

Generator No:	ON3674451
SIC Code:	336110
SIC Description:	Automobile and Light-Duty Motor Vehicle Manufacturing
Approval Years:	04,05,06,07,08
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

158	***2 of 11***	***ESE/95.2***	***201.1 / -31.35***	***Meritor Aftermarket Canada, Inc.*** ***350 First Gulf Boulevard*** ***Brampton ON***	***GEN***

Generator No:	ON3674451
SIC Code:	336110

SIC Description: AUTOMOBILE AND LIGHT-DUTY MOTOR VEHICLE MANUFACTURING
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

158 | ***3 of 11*** | ***ESE/95.2*** | ***201.1 / -31.35*** | ***Arvin Meritor Canada Inc.***
350 First Gulf Boulevard
Brampton ON L6W 4T5 | ***GEN***

Generator No: ON3674451
SIC Code: 336110
SIC Description: Automobile and Light-Duty Motor Vehicle Manufacturing
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

158 | ***4 of 11*** | ***ESE/95.2*** | ***201.1 / -31.35*** | ***Meritor Aftermarket Canada, Inc.***
350 First Gulf Boulevard
Brampton ON L6W 4T5 | ***GEN***

Generator No: ON3674451
SIC Code: 336110
SIC Description: Automobile and Light-Duty Motor Vehicle Manufacturing
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

158 | ***5 of 11*** | ***ESE/95.2*** | ***201.1 / -31.35*** | ***Meritor Aftermarket Canada, Inc.***
350 First Gulf Boulevard
Brampton ON L6W 4T5 | ***GEN***

Generator No: ON3674451
SIC Code: 336110
SIC Description: Automobile and Light-Duty Motor Vehicle Manufacturing
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

158 | ***6 of 11*** | ***ESE/95.2*** | ***201.1 / -31.35*** | ***Meritor Aftermarket Canada, Inc.***
350 First Gulf Boulevard
Brampton ON L6W 4T5 | ***GEN***

Generator No: ON3674451
SIC Code: 336110
SIC Description: Automobile and Light-Duty Motor Vehicle Manufacturing
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

158 **7 of 11** **ESE/95.2** **201.1 / -31.35** **Meritor Aftermarket Canada**
350 First Gulf Boulevard
Brampton ON **GEN**

Generator No: ON5322262
SIC Code: 415310
SIC Description: USED MOTOR VEHICLE PARTS AND ACCESSORIES WHOLESALER-DISTRIBUTORS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

---

158 **8 of 11** **ESE/95.2** **201.1 / -31.35** **Meritor Aftermarket Canada Inc.**
350 First Gulf Boulevard
Brampton ON L6W 4T5 **GEN**

Generator No: ON5322262
SIC Code: 415310
SIC Description: USED MOTOR VEHICLE PARTS AND ACCESSORIES WHOLESALER-DISTRIBUTORS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213

Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 267
Waste Class Name: ORGANIC ACIDS

---

158 | 9 of 11 | ESE/95.2 | 201.1 / -31.35 | **Meritor Aftermarket Canada Inc.**
350 First Gulf Boulevard
Brampton ON L6W 4T5 | GEN

Generator No: ON5322262
SIC Code: 415310
SIC Description: USED MOTOR VEHICLE PARTS AND ACCESSORIES WHOLESALER-DISTRIBUTORS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

158 | 10 of 11 | ESE/95.2 | 201.1 / -31.35 | **Mascot Truck Parts**
350 First Gulf Boulevard
Brampton ON L6W 4T5 | GEN

Generator No: ON5322262
SIC Code: 415310
SIC Description: USED MOTOR VEHICLE PARTS AND ACCESSORIES WHOLESALER-DISTRIBUTORS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No

MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

---

158 | ***11 of 11*** | ***ESE/95.2*** | ***201.1 / -31.35*** | ***350 First Gulf Blvd, Brampton ON*** | ***SPL***

Ref No: 1-1UP2GZ
Year:
Incident Dt: 6/21/2022 8:00:00 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/21/2022 1:21:56 PM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 350 First Gulf Blvd, Brampton
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill:
Environment Impact: 1 Minor Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 litre (L)
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name: OIL (PETROLEUM BASED, NOT SPECIFIED)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason:
Incident Summary: Automann Canada oil spilled in yard, responding
Activity Preceding Spill:
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:
Sector Type: OTHER NEW MOTOR VEHICLE PARTS AND ACCESSORIES MERCHANT WHOLESALERS
SAC Action Class:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Call Report Locatn Geodata: {"integration_ids":["PR00001913126"],"wkts":["POINT (-79.7163246000 43.6729734000)"],"creation_date":"2022-06-21"}

---

159 **1 of 1** **ESE/34.2** **203.4 / -29.06** **8 Sifford Ct.**
BRAMPTON ON **SPL**

Ref No: 1-1IZZGB
Year:
Incident Dt: 1/5/2022 3:53:00 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/5/2022 6:06:10 PM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 8 Sifford Ct.
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: BRAMPTON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Line Strike
Environment Impact: 0 No Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see notes
System Facility Address:
Client Name:
Client Type:
Source Type: Pipeline/Components
Contaminant Code:
Contaminant Name: NATURAL GAS
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Incident Reason:
Incident Summary: TSSA: 1/2" PL IP, Res, Brampton
Activity Preceding Spill:
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HC-Humber - Don
Sector Type: NATURAL GAS DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001876862"],"wkts":["POINT (-79.7173910000 43.6716992000)"],"creation_date":"2022-01-05"}

---

160 **1 of 2** **ESE/70.4** **202.8 / -29.63** **ATL TOWING & SCRAP CAR REMOVAL**
14 CASPER CRES
BRAMPTON ON L6W 4N4 **AUWR**

Headcode: 00098600
Headcode Desc: AUTOMOBILE WRECKING & RECYCLING
Phone:
List Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:					

160	2 of 2	ESE/70.4	202.8 / -29.63	ATL TOWING & SCRAP CAR REMOVAL 14 CASPER CRES BRAMPTON ON L6W4N4	AUWR

Headcode: 00098600
Headcode Desc: AUTOMOBILE WRECKING & RECYCLING
Phone: 4162712728
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

161	1 of 1	WNW/92.7	271.2 / 38.75	Absolute Environmental (King Towing) Hwy 10 200m N of Old School Rd., Caledon CALEDON ON	SPL

Ref No: 1-42DPHT
Year:
Incident Dt: 10/26/2023 9:51:59 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/26/2023 9:51:59 AM
Dt Document Closed:
Site No:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name: Absolute Environmental (King Towing)
Site Address: Hwy 10 200m N of Old School Rd., Caledon
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: CALEDON
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Accident/Collision
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 50 litre (L)
System Facility Address: 1625 SHAWSON DR, MISSISSAUGA, ON L4W 1T7
Client Name:
Client Type:
Source Type: Truck - Transport/Hauling
Contaminant Code:
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason:
Incident Summary: Region of Peel: TT MVA, diesel to damp ditch, Hwy 10 200m north of Old School Road, Caledon
Activity Preceding Spill:
Property 2nd Watershed: 02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed: 02HC | Humber River - Don River
Sector Type: GENERAL FREIGHT TRUCKING, LONG DISTANCE, TRUCK-LOAD
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001693217"],"wkts":["POINT (-79.8536951545 43.7555743523)"],"creation_date":"2023-

10-26"}

Unplottable Summary

Total: 81 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CHEM	AT PLASTICS INC.		BRAMPTON ON	
DTNK	DOUG CHALMERS INC	HWY 10 LOT 12 CON 1W CHINGUACOUSY	BRAMPTON ON	
DTNK	BLUE CIRCLE AGGREGATES CANADA INC	LOT 12 E 1/2 CON 1 W	CALEDON ON	
DTNK	STAR FEULS LTD	HWY 10 N	BRAMPTON ON	
DTNK	BRAMPTON BRICK SALES	HURONTARIO ST	BRAMPTON ON	
DTNK	BRAMPTON BRICK SALES	HURONTARIO ST	BRAMPTON ON	
DTNK	GO VACATIONS CANADA INC	HWY 7	BRAMPTON ON	
EXP	FRANCESCHINI BROS AGGREGATES LIMITED	PRT LOT 15 CON 1 WHS	CALEDON ON	
EXP	MARTIN AGRI DRAINAGE LTD	LOT 20 CON 1	PEEL TWP ON	
EXP	FRANCESCHINI BROS AGGREGATES LIMITED	PRT LOT 15 CON 1 WHS	CALEDON ON	
EXP	MARTIN AGRI DRAINAGE LTD	LOT 20 CON 1	PEEL TWP ON	
EXP	FRANCESCHINI BROS AGGREGATES LIMITED	PRT LOT 15 CON 1 WHS	CALEDON ON	
FST	CALEDON SAND & GRAVEL	LOT 12 CON 1	CALEDON ON	
FST	MINISTRY OF TRANSPORTATION	LOT 15 CON 1 E	CALEDON ON	
FST	MINISTRY OF TRANSPORTATION	LOT 15 CON 1 E	CALEDON ON	
FST	CBM	WEST SIDE HWY 10	CALEDON ON	
FST	CALEDON SAND & GRAVEL	LOT 12 CON 1	CALEDON ON	

FST	CALEDON SAND & GRAVEL	LOT 12 CON 1	CALEDON ON	
FSTH	MINISTRY OF TRANSPORTATION CENTRAL REGION DISTRICT 6 MAINTENANCE	LOT 15 CON 1 E	CALEDON ON	
FSTH	CBM	WEST SIDE HWY 10	CALEDON ON	
FSTH	MINISTRY OF TRANSPORTATION CENTRAL REGION DISTRICT 6 MAINTENANCE	LOT 15 CON 1 E	CALEDON ON	
FSTH	CALEDON SAND & GRAVEL	LOT 12 CON 1	CALEDON ON	
FSTH	CBM	WEST SIDE HWY 10	CALEDON ON	
FSTH	CALEDON SAND & GRAVEL	LOT 12 CON 1	CALEDON ON	
GEN	PETRO-CANADA PRODUCTS	HURONTARIO E/S CON. 1, EHS, PT. LOT 9	BRAMPTON ON	
GEN	CALEDON SAND & GRAVEL INC.	LOT 13, CONC. 1E HWY 10 SOUTH	CALEDON ON	L0P 1A0
GEN	CALEDON SAND & GRAVEL INC.	LOT 13, CONCESSION 1E HWY 10 SOUTH	CALEDON ON	L0N 1C0
GEN	CALEDON SAND & GRAVEL INC., A DIVISION	LOT 13, CONCESSION 1E R.R. #2, HIGHWAY 10 SOUTH	CALEDON ON	L0N 1C0
GEN	The Regional Municipality of Peel waste water	Mayfield Rd	Brampton ON	L7A 0C4
GEN	MINISTRY OF TRANSPORTATION	MTO CENTRAL REGION MULTIPLE GENERATING LOCATIONS	GTA/NIAGARA /DURHAM AREA ON	
GEN	Queen Lynch Co-Tenancy	Queen Street	Brampton ON	
GEN	CANADIAN NATIONAL RAILWAY	VARIOUS SITES WITHIN THE MOEE CENTRAL REGION	(SEE SCHEDULE "B") ON	
GEN	MINISTRY OF TRANSPORTATION	MTO CENTRAL REGION MULTIPLE GENERATING LOCATIONS	GTA/NIAGARA /DURHAM AREA ON	MULTIPL
GEN	Queen Lynch Co-Tenancy	Queen Street	Brampton ON	L6W 3X4
GEN	CANADIAN NATIONAL RAILWAY	VARIOUS SITES WITHIN THE MOEE CENTRAL REGION	(SEE SCHEDULE "B") ON	
GEN	CANADIAN NATIONAL RAILWAY	P.O.BOX 2039	BRAMALEA ON	L6T 3S3
GEN	MARTIN AGRI DRAINAGE LTD.	LOT 20, CONC 1,	PEEL TWP. ON	N0B 2S0
GEN	ESSO PETROLEUM CANADA	HWY 10 NORTH 1 MILE NORTH OF HWY 7	BRAMPTON ON	L6N 3N2

GEN	DOUG CHALMERS INC. 12-647	HWY 10 NORTH OF BOVAIRD, BRAMPTON C/O BOX 280	GEORGETOWN ON	L7G 4Y5
GEN	ESSO PETROLEUM CANADA	HIGHWAY 10 NORTH 1 MILE NORTH OF HIGHWAY 7	BRAMPTON ON	L6N 3N2
GEN	Canada Building Materials Company	RR#2 Highway 10, West Side	Caledon ON	L0N 1C0
GEN	Ranac Forming Limited	Part Lot 11, Conc. 1 WHS West Side Hurontario St.	Brampton ON	
GEN	Region of Peel	Williams Parkway (Centre St to Kennedy Rd)	Brampton ON	L6V 3L9
GEN	Queen Lynch Co-Tenancy	Queen Street	Brampton ON	L6W 3X4
GEN	MINISTRY OF TRANSPORTATION	MTO CENTRAL REGION MULTIPLE GENERATING LOCATIONS	GTA/NIAGARA /DURHAM AREA ON	MULTIPL
GEN	MINISTRY OF TRANSPORTATION	MTO CENTRAL REGION MULTIPLE GENERATING LOCATIONS	GTA/NIAGARA /DURHAM AREA ON	MULTIPL
GEN	Queen Lynch Co-Tenancy	Queen Street	Brampton ON	L6W 3X4
NPCB	UNITED AGGREGATES LTD.	WHS CONC. 1, LOT 14	CALEDON ON	
NPCB	UNITED AGGREGATES LTD.	WHS CONC. 1, LOT 14	CALEDON ON	
RST	PETRO-CANADA		BRAMPTON ON	
SCT	Eagle Stone Ltd.	Highway 7 W RR 8	Brampton ON	L6T 3Y7
SCT	UNITED AGGREGATES LTD	HWY 10	CALEDON VILLAGE ON	L0N 1C0
SCT	BLUE CIRCLE AGGREGATES	Hwy 10	Caledon Village ON	L0N 1C0
SCT	Caledon Sand & Gravel Inc.	Hwy 10	Caledon Village ON	L0N 1C0
SCT	Blue Circle Aggregates	Hwy 10	Caledon Village ON	L0N 1C0
SCT	Eagle Ornamental	Highway 7 W RR 8	Brampton ON	L6T 3Y7
SPL	TRIMAC	HWY #7, AT PEEL BLOCK FUEL TANK AREA TANK TRUCK (CARGO)	BRAMPTON CITY ON	
SPL	UNKNOWN	CREEK UNDER HWY 10, SOUTH OF SANDALWOOD PARKWAY	BRAMPTON CITY ON	
SPL	The Corporation of the City of Brampton	Highway 410	Brampton ON	NA
SPL	BELL CANADA	STORAGE DRUM/TANK	BRAMPTON CITY ON	
SPL	CANADIAN NATIONAL	TRAIN	BRAMPTON CITY ON	

	RAILWAY		
SPL	CANADIAN NATIONAL RAILWAY		BRAMPTON CITY ON
SPL	CHRYSLER CANADA LTD.	TRANSPORT TRUCK (CARGO)	BRAMPTON CITY ON
SPL	Brampton Transit<UNOFFICIAL>		Brampton ON
SPL	Emterra Environmental<UNOFFICIAL>		Brampton ON
SPL	Petro-Canada Gas Station<UNOFFICIAL>		Brampton ON
SPL	Canadian National Railway Company		Brampton ON
SPL		on Highway 10	Caledon ON
SPL		just north of Steeles Ave	Brampton ON
SPL	Fortinos (Highway 10 & Bovaird 2006) Ltd.		Brampton ON
SPL	Redacted S 21(1)(f) of FIPPA	First Golf Drive, just south of Steeles Ave	Brampton ON
SPL		Upstream of Bovaird Dr.	Brampton ON
SPL	Hydro One Brampton Networks Inc.		Brampton ON
SPL		Bovaird Dr	Brampton ON
SPL	Canadian National Transportation Limited		Brampton ON
SPL		Highway 10	Caledon ON
SPL	Andrews Trucking Limited	N of Hwy 7	Brampton ON
SPL	Daniel Contracting Ltd.	Bovaird Dr	Brampton ON
SPL	Southlake Blvd and Streamline Dr. <UNOFFICIAL>	near Williams Pkwy	Brampton ON
SPL	The Regional Municipality of Peel	Between Kennedy and 410 and Steeles and 407<UNOFFICIAL>	Brampton ON
SPL	PRIVATE OWNER	STAFFORD DRIVE MOTOR VEHICLE (OPERATING FLUID)	BRAMPTON CITY ON

Unplottable Report

Site: ***AT PLASTICS INC.***
BRAMPTON ON

Database: ***CHEM***

Headcode:		***Head Office Province:***	ON
Headcode Desc:		***Head Office Postal:***	L6W3G5
Phone:		***Mailing Address:***	134 KENNEDY ROAD SOUTH
List Name:		***Mailing Address 2:***	
Description:		***Mailing City:***	BRAMPTON

Site: ***DOUG CHALMERS INC***
HWY 10 LOT 12 CON 1W CHINGUACOUSY BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	9562282	***Expired Date:***	10/6/1993
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:		***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

Site: ***BLUE CIRCLE AGGREGATES CANADA INC***
LOT 12 E 1/2 CON 1 W CALEDON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	9862427	***Expired Date:***	12/3/2009 12:07
Status:	EXPIRED	***Max Hazard Rank:***	

Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Site: ***STAR FEULS LTD***
HWY 10 N BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 10447600
Status: EXPIRED
Instance ID: 17354
Instance Type: FS Highway Tank - Gas/Diesel
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Site: ***BRAMPTON BRICK SALES***
HURONTARIO ST BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	9902445	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	396057	***Facility Location:***	
Instance Type:	FS Facility	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Cylr Handling Facility		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Site: ***BRAMPTON BRICK SALES***
HURONTARIO ST BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	11099172	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	68842	***Facility Location:***	
Instance Type:	FS Propane Tank	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			

TSSA Program Area 2:
Description: FS Propane Tank
Original Source: EXP
Record Date: Up to Mar 2012

Site: ***GO VACATIONS CANADA INC***
HWY 7 BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 9560095
Status: EXPIRED
Instance ID: 390027
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Refill Cntr - Cylr Fill
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Site: ***FRANCESCHINI BROS AGGREGATES LIMITED***
PRT LOT 15 CON 1 WHS CALEDON ON

Database: ***EXP***

Inventory No: 10638129
Inventory Status: EXPIRED
Installation Year: 1965
Capacity: 4546
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK AS PER E070516
Previous Fuel Type: Diesel

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***MARTIN AGRI DRAINAGE LTD***
LOT 20 CON 1 PEEL TWP ON

Database: ***EXP***

Inventory No: 10913869
Inventory Status: Inactive
Installation Year: 1950
Capacity: 4546
Capacity Unit:

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Gasoline

Site: ***FRANCESCHINI BROS AGGREGATES LIMITED***
PRT LOT 15 CON 1 WHS CALEDON ON

Database: ***EXP***

Inventory No: 10638180
Inventory Status: EXPIRED
Installation Year: 1965
Capacity: 4546
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK as per e070516
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***MARTIN AGRI DRAINAGE LTD***
LOT 20 CON 1 PEEL TWP ON

Database: ***EXP***

Inventory No: 10913887
Inventory Status: Inactive
Installation Year: 1955
Capacity: 4546
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
Previous Fuel Type: Diesel

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***FRANCESCHINI BROS AGGREGATES LIMITED***
PRT LOT 15 CON 1 WHS CALEDON ON

Database: ***EXP***

Inventory No: 10638077
Inventory Status: EXPIRED
Installation Year: 1965
Capacity: 4546
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK AS PER E070516
Previous Fuel Type: Diesel

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***CALEDON SAND & GRAVEL***
LOT 12 CON 1 CALEDON ON

Database: ***FST***

Inventory No: 10637368
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***MINISTRY OF TRANSPORTATION***
LOT 15 CON 1 E CALEDON ON

Database: ***FST***

Inventory No: 11023590
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***MINISTRY OF TRANSPORTATION***
LOT 15 CON 1 E CALEDON ON

Database: ***FST***

Inventory No: 11023574
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***CBM***
WEST SIDE HWY 10 CALEDON ON

Database: ***FST***

Inventory No: 10638256
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***CALEDON SAND & GRAVEL***
LOT 12 CON 1 CALEDON ON

Database: ***FST***

Inventory No: 10637274
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Site: ***CALEDON SAND & GRAVEL***
LOT 12 CON 1 CALEDON ON

Database: ***FST***

Inventory No: 10637326
Inventory Status: Active
Installation Year:
Capacity:
Capacity Unit:
Tank Type:

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Manufacturer:
Model:
Description: UNDERGROUND TANK

Site: ***MINISTRY OF TRANSPORTATION CENTRAL REGION DISTRICT 6 MAINTENANCE***
LOT 15 CON 1 E CALEDON ON

Database: ***FSTH***

License Issue Date: 12/21/1990
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1976
Corrosion Protection:
Capacity: 9100
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1986
Corrosion Protection:
Capacity: 9100
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Site: ***CBM***
WEST SIDE HWY 10 CALEDON ON

Database: ***FSTH***

License Issue Date: 5/1/2002
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Site: ***MINISTRY OF TRANSPORTATION CENTRAL REGION DISTRICT 6 MAINTENANCE***
LOT 15 CON 1 E CALEDON ON

Database: ***FSTH***

License Issue Date: 12/21/1990
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1976
Corrosion Protection:
Capacity: 9100
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status: Active
Year of Installation: 1986
Corrosion Protection:

Capacity: 9100
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Site: ***CALEDON SAND & GRAVEL***
LOT 12 CON 1 CALEDON ON

Database: ***FSTH***

License Issue Date: 12/10/1990
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1990
Corrosion Protection:
Capacity: 35000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1976
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1976
Corrosion Protection:
Capacity: 9090
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Site: ***CBM***
WEST SIDE HWY 10 CALEDON ON

Database: ***FSTH***

License Issue Date: 5/1/2002
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1988
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Site: ***CALEDON SAND & GRAVEL***
LOT 12 CON 1 CALEDON ON

Database: ***FSTH***

License Issue Date: 12/10/1990
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1990
Corrosion Protection:
Capacity: 35000

Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1976
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1976
Corrosion Protection:
Capacity: 9090
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Site: ***PETRO-CANADA PRODUCTS***
HURONTARIO E/S CON. 1, EHS, PT. LOT 9 BRAMPTON ON

Database: ***GEN***

Generator No: ON0031053
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Site: ***CALEDON SAND & GRAVEL INC.***
LOT 13, CONC. 1E HWY 10 SOUTH CALEDON ON L0P 1A0

Database: ***GEN***

Generator No: ON0662802
SIC Code: 0821
SIC Description: SAND & GRAVEL PITS
Approval Years: 92,93
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Site: ***CALEDON SAND & GRAVEL INC.***
LOT 13, CONCESSION 1E HWY 10 SOUTH CALEDON ON L0N 1C0

Database: ***GEN***

Generator No: ON0662802
SIC Code: 0821

SIC Description: SAND & GRAVEL PITS
Approval Years: 97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Site: ***CALEDON SAND & GRAVEL INC., A DIVISION***
LOT 13, CONCESSION 1E R.R. #2, HIGHWAY 10 SOUTH CALEDON ON L0N 1C0

Database: ***GEN***

Generator No: ON0662802
SIC Code: 0821
SIC Description: SAND & GRAVEL PITS
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Site: ***The Regional Municipality of Peel waste water***
Mayfield Rd Brampton ON L7A 0C4

Database: ***GEN***

Generator No: ON9207702
SIC Code:
SIC Description:
Approval Years: As of Jun 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Site: ***MINISTRY OF TRANSPORTATION***
MTO CENTRAL REGION MULTIPLE GENERATING LOCATIONS GTA/NIAGARA /DURHAM AREA ON

Database: ***GEN***

Generator No: ON0124208
SIC Code: 912910
SIC Description: OTHER PROVINCIAL AND TERRITORIAL PUBLIC ADMINISTRATION
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 133
Waste Class Name: BRINES, CHLOR-ALKALI WASTES

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Site: ***Queen Lynch Co-Tenancy***
Queen Street Brampton ON

Database: ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: LESSORS OF NON-RESIDENTIAL BUILDINGS (EXCEPT MINI-WAREHOUSES)
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Site: ***CANADIAN NATIONAL RAILWAY***
VARIOUS SITES WITHIN THE MOEE CENTRAL REGION (SEE SCHEDULE "B") ON

Database: ***GEN***

Generator No: ONR000703
SIC Code: 482113
SIC Description: MAINLINE FREIGHT RAIL TRANSPORTATION
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 254
Waste Class Name: TRANSFER STATION OILS WASTES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Site: ***MINISTRY OF TRANSPORTATION***
MTO CENTRAL REGION MULTIPLE GENERATING LOCATIONS GTA/NIAGARA /DURHAM AREA ON MULTIPL

Database: ***GEN***

Generator No: ON0124208
SIC Code: 912910
SIC Description: Other Provincial and Territorial Public Administration
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 133
Waste Class Name: BRINES, CHLOR-ALKALI WASTES

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Site: ***Queen Lynch Co-Tenancy***
Queen Street Brampton ON L6W 3X4

Database: ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: Lessors of Non-Residential Buildings (except Mini-Warehouses)
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Site: ***CANADIAN NATIONAL RAILWAY***
VARIOUS SITES WITHIN THE MOEE CENTRAL REGION (SEE SCHEDULE "B") ON

Database: ***GEN***

Generator No: ONR000703
SIC Code: 482113
SIC Description: Mainline Freight Rail Transportation
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 114
Waste Class Name: OTHER INORGANIC ACID WASTES

Waste Class: 231
Waste Class Name: LATEX WASTES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 266
Waste Class Name: PHENOLIC WASTES

Waste Class: 121
Waste Class Name: ALKALINE WASTES - HEAVY METALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 268
Waste Class Name: AMINES

Waste Class: 269
Waste Class Name: NON-HALOGENATED PESTICIDES

Waste Class: 135
Waste Class Name: REACTIVE ANION WASTES

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 254
Waste Class Name: TRANSFER STATION OILS WASTES

Site: ***CANADIAN NATIONAL RAILWAY***
P.O.BOX 2039 BRAMALEA ON L6T 3S3

Database: ***GEN***

Generator No: ON0013125
SIC Code: 0007
SIC Description: LETTER ACKNOWLEDG.
Approval Years: 86,87
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Site: ***MARTIN AGRI DRAINAGE LTD.***
LOT 20, CONC 1, PEEL TWP. ON N0B 2S0

Database: ***GEN***

Generator No: ON1432600
SIC Code: 4213
SIC Description: SEPTIC TANK INSTAL.
Approval Years: 92,93,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Site: ***ESSO PETROLEUM CANADA***
HWY 10 NORTH 1 MILE NORTH OF HWY 7 BRAMPTON ON L6N 3N2

Database: ***GEN***

Generator No: ON1315743
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 92,93,97,98
PO Box No:

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Site: ***DOUG CHALMERS INC. 12-647***
HWY 10 NORTH OF BOVAIRD, BRAMPTON C/O BOX 280 GEORGETOWN ON L7G 4Y5

Database: ***GEN***

Generator No: ON1498000
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Site: ***ESSO PETROLEUM CANADA***
HIGHWAY 10 NORTH 1 MILE NORTH OF HIGHWAY 7 BRAMPTON ON L6N 3N2

Database: ***GEN***

Generator No: ON1315743
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146

Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Site: ***Canada Building Materials Company***
RR#2 Highway 10, West Side Caledon ON L0N 1C0

Database: ***GEN***

Generator No: ON4134996
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 270
Waste Class Name: OTHER SPECIFIED ORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Site: ***Ranac Forming Limited***
Part Lot 11, Conc. 1 WHS West Side Hurontario St. Brampton ON

Database: ***GEN***

Generator No: ON5213152
SIC Code:
SIC Description:
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Site: ***Region of Peel***
Williams Parkway (Centre St to Kennedy Rd) Brampton ON L6V 3L9

Database: ***GEN***

Generator No: ON8729353
SIC Code:
SIC Description:
Approval Years: As of Jun 2018
PO Box No:
Country: Canada

Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

---

Site: ***Queen Lynch Co-Tenancy***
Queen Street Brampton ON L6W 3X4

Database: ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: Lessors of Non-Residential Buildings (except Mini-Warehouses)
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Site: ***MINISTRY OF TRANSPORTATION***
MTO CENTRAL REGION MULTIPLE GENERATING LOCATIONS GTA/NIAGARA /DURHAM AREA ON MULTIPL

Database: ***GEN***

Generator No: ON0124208
SIC Code: 912910
SIC Description: Other Provincial and Territorial Public Administration
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 133
Waste Class Name: BRINES, CHLOR-ALKALI WASTES

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Site: ***MINISTRY OF TRANSPORTATION***
MTO CENTRAL REGION MULTIPLE GENERATING LOCATIONS GTA/NIAGARA /DURHAM AREA ON MULTIPL

Database: ***GEN***

Generator No: ON0124208
SIC Code: 912910
SIC Description: Other Provincial and Territorial Public Administration
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 112
Waste Class Name: ACID WASTE - HEAVY METALS

Waste Class: 222
Waste Class Name: HEAVY FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 122
Waste Class Name: ALKALINE WASTES - OTHER METALS

Waste Class: 243
Waste Class Name: PCBS

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Waste Class: 262
Waste Class Name: DETERGENTS/SOAPS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 133
Waste Class Name: BRINES, CHLOR-ALKALI WASTES

Waste Class: 232
Waste Class Name: POLYMERIC RESINS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Site: ***Queen Lynch Co-Tenancy***
Queen Street Brampton ON L6W 3X4

Database: ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: Lessors of Non-Residential Buildings (except Mini-Warehouses)
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Site: ***UNITED AGGREGATES LTD.***
WHS CONC. 1, LOT 14 CALEDON ON

Database: ***NPCB***

Company Code: F1020
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

Site: ***UNITED AGGREGATES LTD.***
WHS CONC. 1, LOT 14 CALEDON ON

Database: ***NPCB***

Company Code: F1055
Industry:
Site Status:
Transaction Date:
Inspection Date:

Site: ***PETRO-CANADA***
BRAMPTON ON

Database: ***RST***

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 9054532849
List Name:
Description:

Site: ***Eagle Stone Ltd.***
Highway 7 W RR 8 Brampton ON L6T 3Y7

Database: ***SCT***

Established: 1956
Plant Size (ft²): 18000
Employment: 12

--Details--
Description: Other Concrete Product Manufacturing
SIC/NAICS Code: 327390

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Description: Other Ornamental and Architectural Metal Products Manufacturing
SIC/NAICS Code: 332329

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Site: ***UNITED AGGREGATES LTD***
HWY 10 CALEDON VILLAGE ON L0N 1C0

Database: ***SCT***

Established: 1970
Plant Size (ft²): 0
Employment: 30

--Details--
Description: MINERALS AND EARTHS, GROUND OR OTHERWISE TREATED
SIC/NAICS Code: 3295

Site: ***BLUE CIRCLE AGGREGATES***
Hwy 10 Caledon Village ON L0N 1C0

Database: ***SCT***

Established: 1970
Plant Size (ft²): 0
Employment: 30

--Details--
Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Site: ***Caledon Sand & Gravel Inc.***
Hwy 10 Caledon Village ON L0N 1C0

Database: ***SCT***

Established: 01-JUL-55
Plant Size (ft²):
Employment:

--Details--
Description: Sand and Gravel Mining and Quarrying
SIC/NAICS Code: 212323

Description: Sand and Gravel Mining and Quarrying
SIC/NAICS Code: 212323

Site: ***Blue Circle Aggregates***
Hwy 10 Caledon Village ON L0N 1C0

Database: ***SCT***

Established: 1970
Plant Size (ft²):
Employment: 30

--Details--
Description: Sand and Gravel Mining and Quarrying
SIC/NAICS Code: 212323

Site: ***Eagle Ornamental***
Highway 7 W RR 8 Brampton ON L6T 3Y7

Database: ***SCT***

Established: 1956
Plant Size (ft²): 18000
Employment: 12

--Details--
Description: Other Ornamental and Architectural Metal Products Manufacturing
SIC/NAICS Code: 332329

Description: Other Specialty-Line Building Supplies Wholesaler-Distributors
SIC/NAICS Code: 416390

Description: Other Concrete Product Manufacturing
SIC/NAICS Code: 327390

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Site: ***TRIMAC***
HWY #7, AT PEEL BLOCK FUEL TANK AREA TANK TRUCK (CARGO) BRAMPTON CITY ON

Database: ***SPL***

Ref No:	15554	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	3/7/1989	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	3/7/1989	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	BRAMPTON CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Preceding Spill:			
Environment Impact:	NOT ANTICIPATED		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Incident Reason:	EQUIPMENT FAILURE		
Incident Summary:	TRIMAC LTD - TANKER TRUCK45 LITRES BUNKER SPILL TO GROUND		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

Site: ***UNKNOWN***
CREEK UNDER HWY 10, SOUTH OF SANDALWOOD PARKWAY BRAMPTON CITY ON

Database: ***SPL***

Ref No:	107427	**Municipality No:**	21101
Year:		**Nature of Damage:**	
Incident Dt:	11/16/1994	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	11/16/1994	**Impact to Health:**	
Dt Document Closed:		**Agency Involved:**	
Site No:			

MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: UNKNOWN
Incident Preceding Spill:
Environment Impact: CONFIRMED
Health Env Consequence:
Nature of Impact: Water course or lake
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: WATER
Incident Reason: UNKNOWN
Incident Summary: UNKNOWN SOURCE-ANTIFREEZETO CREEK AT HWY 10 & SANDALWOOD PARKWAY
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Site: ***The Corporation of the City of Brampton***
Highway 410 Brampton ON NA

Database: ***SPL***

Ref No: 3542-BJTQP6
Year:
Incident Dt: 2019/12/13
Dt MOE Arvl on Scn:
MOE Reported Dt: 2019/12/13
Dt Document Closed:
Site No: 8686-BJWLFD
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Highway 410
Site Address: Highway 410
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Incident Cause:
Incident Preceding Spill: Leak/Break

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 30 L
System Facility Address:
Client Name: The Corporation of the City of Brampton
Client Type: Municipal Government
Source Type: Motor Vehicle
Contaminant Code: 27
Contaminant Name: COOLANT N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1: n/a
Contaminant UN No 1: n/a
Receiving Medium: Land
Incident Reason: Equipment Failure
Incident Summary: Brampton Transit: 20-30 L coolant spill to cb, cntd.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class:
Call Report Locatn Geodata:

Site: ***BELL CANADA***
STORAGE DRUM/TANK BRAMPTON CITY ON

Database: ***SPL***

Ref No: 20437
Year:
Incident Dt: 5/9/1989
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/9/1989
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: CONTAINER OVERFLOW
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: ERROR
Incident Summary: BACKENTRY - BELL CANADA TANK OVERFLOW - UNKNOWN AMOUNT OF OIL SPILLED
Activity Preceding Spill:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Site: ***CANADIAN NATIONAL RAILWAY TRAIN BRAMPTON CITY ON***

Database: ***SPL***

Ref No: 32106
Year:
Incident Dt: 3/15/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/15/1990
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER CONTAINER LEAK
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Water course or lake
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: EQUIPMENT FAILURE
Incident Summary: CN RAIL - DIESEL FUEL TO GROUND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site: ***CANADIAN NATIONAL RAILWAY BRAMPTON CITY ON***

Database: ***SPL***

Ref No: 42950
Year:
Incident Dt: 11/2/1990
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/2/1990
Dt Document Closed:
Site No:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: ABOVE-GROUND TANK LEAK
Incident Preceding Spill:
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: OTHER
Incident Summary: CNR-2L. KEROSENE TO LAND:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Site: ***CHRYSLER CANADA LTD.***
TRANSPORT TRUCK (CARGO) BRAMPTON CITY ON

Database: ***SPL***

Ref No: 56340
Year:
Incident Dt: 8/29/1991
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/29/1991
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER CONTAINER LEAK
Incident Preceding Spill:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact: Water course or lake
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: DAMAGE BY MOVING EQUIPMENT
Incident Summary: CHRYSLER: 45L DIESEL FUELLEAK FROM SHUNT TRUCK'S SADDLE TANK
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Site: ***Brampton Transit<UNOFFICIAL>***
Brampton ON

Database: ***SPL***

Ref No: 8361-BG5KUC
Year:
Incident Dt: 9/18/2019
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/18/2019
Dt Document Closed: 11/16/2019
Site No: NA
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth:
Site District Office: Halton-Peel
Nearest Watercourse:
Site Name: Northbound on Bramalea Road, just south of Sandalwood<UNOFFICIAL>
Site Address:
Site Region: Central
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name: Brampton Transit<UNOFFICIAL>
Client Type:
Source Type: Motor Vehicle
Contaminant Code: 27
Contaminant Name: COOLANT (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Receiving Medium: Land
Incident Reason: Material Failure - Poor Design/Substandard Material
Incident Summary: Brampton Transit: Unknown quantity of coolant to roadway
Activity Preceding Spill:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Site: ***Emterra Environmental<UNOFFICIAL>*** ***Database:*** ***SPL***
Brampton ON

Ref No: 1238-AH4U7V
Year:
Incident Dt: 2016/12/29
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/12/29
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse: Unknown Name
Site Name: Corner of Soaring Rock Ct. and Ice Fields Rd.<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 25 L
System Facility Address:
Client Name: Emterra Environmental<UNOFFICIAL>
Client Type:
Source Type:
Contaminant Code: 15
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land; Surface Water
Incident Reason: Equipment Failure
Incident Summary: Region of Peel: 25L Hydraulic Fluid to CB Contained, Clean-up Continues
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Municipal Sewage
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site: ***Petro-Canada Gas Station<UNOFFICIAL>*** ***Database:*** ***SPL***
Brampton ON

Ref No: 5567-AEHLSE
Year:
Incident Dt: 10/7/2016
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/7/2016
Dt Document Closed: 10/13/2016
Site No: NA

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Private property - 354 Queen St. E. <UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause:
Incident Preceding Spill: Leak/Break
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name: Petro-Canada Gas Station<UNOFFICIAL>
Client Type:
Source Type:
Contaminant Code: 41
Contaminant Name: WATER/SEDIMENT
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Incident Reason: Unknown / N/A
Incident Summary: Region of Peel: watermain break; brown, murky water
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Municipal Sewage
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:

Site: ***Canadian National Railway Company***
Brampton ON

Database: ***SPL***

Ref No: 7831-9MWJNL
Year:
Incident Dt: 2014/08/11
Dt MOE Arvl on Scn:
MOE Reported Dt: 2014/08/12
Dt Document Closed: 2014/08/21
Site No: NA
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: CN Rail site not specified in CANUTEC report<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Leak/Break
Incident Preceding Spill:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name: Canadian National Railway Company
Client Type:
Source Type:
Contaminant Code: 97
Contaminant Name: N/A
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Operator/Human Error
Incident Summary: CN Rail: report from CANUTEC
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Container/Drum/Tote
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Site:
on Highway 10 Caledon ON

Database: ***SPL***

Ref No: 2883-9NKMUK
Year:
Incident Dt: 2014/09/02
Dt MOE Arvl on Scn: 2014/09/02
MOE Reported Dt: 2014/09/02
Dt Document Closed:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:
Site No: NA
MOE Response: Priority Field Response (ERP Callout)
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: MVA<UNOFFICIAL>
Site Address: on Highway 10
Site Region:
Site Municipality: Caledon
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Collision/Accident
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Unknown / N/A
Incident Summary: MVA: fatality fuel in ditch, water
Activity Preceding Spill:

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Truck - Transport/Hauling
SAC Action Class: Highway Spills (usually highway accidents)
Call Report Locatn Geodata:

Site: ***just north of Steeles Ave Brampton ON***

Database: ***SPL***

Ref No: 4086-9JEN2H
Year:
Incident Dt: 2014/04/22
Dt MOE Arvl on Scn:
MOE Reported Dt: 2014/04/22
Dt Document Closed:
Site No: NA
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Southbound lanes on airport Rd<UNOFFICIAL>
Site Address: just north of Steeles Ave
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Leak/Break
Incident Preceding Spill:
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty: 400 L
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Road Conditions
Incident Summary: Holmes Freight - 400 L diesel to road & c/b, clng
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Truck - Only Saddle Tanks
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site: ***Fortinos (Highway 10 & Bovaird 2006) Ltd. Brampton ON***

Database: ***SPL***

Ref No: 8213-9J2PUC
Year:
Incident Dt: 2014/04/10
Dt MOE Arvl on Scn:
MOE Reported Dt: 2014/04/10
Dt Document Closed:
Site No: NA

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Fortinos 60 Quarry Edge Dr.<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Leak/Break
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: 177.66 other - see incident description
System Facility Address:
Client Name: Fortinos (Highway 10 & Bovaird 2006) Ltd.
Client Type:
Source Type:
Contaminant Code: 38
Contaminant Name: FREON R-22 (CFC)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Equipment Failure
Incident Summary: Fortinos Supermarket: Freon to atm
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Pipeline/Components
SAC Action Class: Air Spills - Gases and Vapours
Call Report Locatn Geodata:

Site: ***Redacted S 21(1)(f) of FIPPA***
First Golf Drive, just south of Steeles Ave Brampton ON

Database: ***SPL***

Ref No: 0784-96ZNEL
Year:
Incident Dt: 22-APR-13
Dt MOE Arvl on Scn: 03-MAY-13
MOE Reported Dt: 22-APR-13
Dt Document Closed: 26-JUN-13
Site No:
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:
MOE Response: Planned Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Fuel storage tank<UNOFFICIAL>
Site Address: First Golf Drive, just south of Steeles Ave
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Unknown / N/A
Incident Preceding Spill:

Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 25 L
System Facility Address:
Client Name: Redacted S 21(1)(f) of FIPPA
Client Type:
Source Type:
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Unknown / N/A
Incident Summary: Redacted S21(1)(f) of FIPPA+U3877/RM Peel, 20-25 L diesel fuel to road, cleaned
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Tank - Above Ground
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Call Report Locatn Geodata:

Site:
Upstream of Bovaird Dr. Brampton ON

Database: ***SPL***

Ref No: 5450-8Y9UYA
Year:
Incident Dt: 18-SEP-12
Dt MOE Arvl on Scn:
MOE Reported Dt: 18-SEP-12
Dt Document Closed: 27-DEC-12
Site No:
MOE Response: Planned Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: East Huttonville Creek <UNOFFICIAL>
Site Address: Upstream of Bovaird Dr.
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code: 43
Contaminant Name: SEDIMENT(SUSPENDED SOLIDS/ SAND/ SILT)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Flooding
Incident Summary: Brampton - sediment to creek due to heavy rain.
Activity Preceding Spill:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:

Site: ***Hydro One Brampton Networks Inc.***
Brampton ON

Database: ***SPL***

Ref No: 7214-8TYJ8Z
Year:
Incident Dt: 01-MAY-12
Dt MOE Arvl on Scn:
MOE Reported Dt: 04-MAY-12
Dt Document Closed: 31-MAY-12
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 11 Tobey Terrace<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty:
System Facility Address:
Client Name: Hydro One Brampton Networks Inc.
Client Type:
Source Type:
Contaminant Code: 15
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Sewage - Municipal/Private and Commercial
Incident Reason: Unknown - Reason not determined
Incident Summary: Hydro One-75 L X-former Oil to Grass/asphalt.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transformer
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site:
Bovaird Dr Brampton ON

Database: ***SPL***

Ref No: 2305-8SNW56
Year:
Incident Dt: 23-MAR-12
Dt MOE Arvl on Scn:
MOE Reported Dt: 23-MAR-12
Dt Document Closed: 25-JUL-12
Site No:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

MOE Response:	Planned Field Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	Fletchers Creek<UNOFFICIAL>
Site Address:	Bovaird Dr
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	Unknown
Incident Preceding Spill:	
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Surface Water Pollution
Contaminant Qty:	
System Facility Address:	
Client Name:	
Client Type:	
Source Type:	
Contaminant Code:	13
Contaminant Name:	HYDROCARBON LIGHT
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Sewage - Municipal/Private and Commercial
Incident Reason:	
Incident Summary:	Sheen in Fletchers Creek
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Unknown
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	

Site: ***Canadian National Transportation Limited***
Brampton ON

Database: ***SPL***

Ref No:	0750-8F8GAL	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	3/23/2011	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	3/23/2011	***Impact to Health:***	
Dt Document Closed:	5/19/2011	***Agency Involved:***	

Site No:	
MOE Response:	No Field Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	
Nearest Watercourse:	
Site Name:	HWY 407 EB off ramp and Airport Road<UNOFFICIAL>
Site Address:	
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	
Incident Preceding Spill:	

Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty: 100 L
System Facility Address:
Client Name: Canadian National Transportation Limited
Client Type:
Source Type:
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason:
Incident Summary: CNTL: 100 litres diesel to rd, cntd clnd
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Highway Spills (usually highway accidents)
Call Report Locatn Geodata:

Site: ***Database:*** ***SPL***

Highway 10 Caledon ON

Ref No: 3563-8B95ZE
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/15/2010
Dt Document Closed: 11/19/2010
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Highway 10, 0.5km north of King<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Other Discharges
Incident Preceding Spill:
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 40 L
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name: Operating Fluid
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Other - Reason not otherwise defined
Incident Summary: MVA: Hwy 10, 40L of fluids to roadway
Activity Preceding Spill:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Motor Vehicle
SAC Action Class: Land Spills
Call Report Locatn Geodata:

Site: ***Andrews Trucking Limited***
N of Hwy 7 Brampton ON

Database: ***SPL***

Ref No: 4436-7UFKXU
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/30/2009
Dt Document Closed:
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Hwy 427<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality: Brampton
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: Unknown
Incident Preceding Spill:
Environment Impact: Not Anticipated
Health Env Consequence:
Nature of Impact: Other Impact(s)
Contaminant Qty: 0 other - see incident description
System Facility Address:
Client Name: Andrews Trucking Limited
Client Type:
Source Type:
Contaminant Code:
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Incident Reason: Unknown - Reason not determined
Incident Summary: Andrews Trucking Ltd: hydraulic oil to 427, N of 7
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Primary Assessment of Incident
Call Report Locatn Geodata:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site: ***Daniel Contracting Ltd.***
Bovaird Dr Brampton ON

Database: ***SPL***

Ref No: 6635-7CLRRM
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/10/2008
Dt Document Closed: 4/14/2008
Site No:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

MOE Response:	No Field Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel
Nearest Watercourse:	
Site Name:	unknown<UNOFFICIAL>
Site Address:	
Site Region:	
Site Municipality:	Brampton
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Incident Cause:	Other Transport Accident
Incident Preceding Spill:	
Environment Impact:	Not Anticipated
Health Env Consequence:	
Nature of Impact:	Soil Contamination
Contaminant Qty:	50 L
System Facility Address:	
Client Name:	Daniel Contracting Ltd.
Client Type:	
Source Type:	
Contaminant Code:	13
Contaminant Name:	DIESEL FUEL
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	Damage By Moving Equipment - Containers damaged by moving
Incident Summary:	Spill: MVA 20 - 50 L diesel, contained. Brampton
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Transport Truck
SAC Action Class:	Land Spills
Call Report Locatn Geodata:	

Site: ***Southlake Blvd and Streamline Dr. <UNOFFICIAL>***
near Williams Pkwy Brampton ON

Database: ***SPL***

Ref No:	4465-6MRMHH	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	3/10/2006	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	3/10/2006	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Southlake Blvd and Streamline Dr. <UNOFFICIAL>		
Site Address:	near Williams Pkwy		
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:			

Environment Impact:	Possible
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	Not Specfic Unknown
System Facility Address:	
Client Name:	The Corporation of the City of Brampton
Client Type:	
Source Type:	Other Motor Vehicle
Contaminant Code:	41
Contaminant Name:	DIESEL FUEL AND WATER MIXTURE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Incident Reason:	
Incident Summary:	Brampton: diesel in a stormwater pond
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	

Site: ***The Regional Municipality of Peel***
Between Kennedy and 410 and Steeles and 407<UNOFFICIAL> Brampton ON

Database: ***SPL***

Ref No:	1413-6FULF8	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	9/2/2005	***Discharger Report:***	0
Dt MOE Arvl on Scn:		***Material Group:***	Waste
MOE Reported Dt:	9/2/2005	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Between Kennedy and 410 and Steeles and 407<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Brampton		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:			
Incident Preceding Spill:			
Environment Impact:	Not Anticipated		
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:			
System Facility Address:			
Client Name:	The Regional Municipality of Peel		
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:	SEWAGE		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	Land		
Incident Reason:			
Incident Summary:	Sanitary sewage to ground from manholes, cleaning.		
Activity Preceding Spill:			

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Sewer
SAC Action Class: Spills to Land
Call Report Locatn Geodata:

Site: ***PRIVATE OWNER***
STAFFORD DRIVE MOTOR VEHICLE (OPERATING FLUID) BRAMPTON CITY ON

Database: ***SPL***

Ref No: 161585
Year:
Incident Dt: 10/30/1998
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/30/1998
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: BRAMPTON CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: PIPE/HOSE LEAK
Incident Preceding Spill:
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: OVERSTRESS/OVERPRESSURE
Incident Summary: BRAMALEA SCENTS- 130 L HYDRAULIC OIL TO RD FROM RUPTURED LINE ON FORKLIFT
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Municipality No: 21101
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: BRAMPTON W/D

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Nov 2023

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Apr 2024

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Apr 30, 2024

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2022

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Apr 30, 2024

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -May 2024

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-May 2024

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - May 31, 2024

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Aug 2023

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Apr 30, 2024

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - May 31, 2024

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Apr 30, 2024

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Mar 31, 2024

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2023

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Mar 2024

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: Oct 31, 2021

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2022

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: 31 Oct, 2023

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2024

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2022

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory 1993-2020: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Sep 2020

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-May 31, 2024

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2023

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - May 31, 2024

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011-Apr 30, 2024

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Sep 2020

Potential PFAS Handlers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Sep 2020

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - May 31, 2024

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004-Jun 2024

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Apr 30, 2024

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests. This database includes spill incidents that occurred in Mar 2023-Mar 2024 in addition to those listed in the Government Publication Date.

Government Publication Date: 1988-Jan 2023; see description

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2021

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2023

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Apr 30, 2024

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Dec 31 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

DATABASE REPORT

Project Property:	*Queen St (Centre to 410)* *Queen St (Centre to 410)* *Brampton ON*
Project No:	*P24-6347*
Report Type:	*Quote - Custom-Build Your Own Report*
Order No:	*24062700011*
Requested by:	*EnVision Consultants Ltd.*
Date Completed:	*July 23, 2024*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....30
Map.....56
Aerial.....57
Topographic Map.....58
Detail Report.....59
Unplottable Summary.....163
Unplottable Report.....164
Appendix: Database Descriptions.....167
Definitions.....177

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*Queen St (Centre to 410)* *Queen St (Centre to 410) Brampton ON*
Project No:	*P24-6347*

Order Information:

Order No:	*24062700011*
Date Requested:	*June 27, 2024*
Requested by:	*EnVision Consultants Ltd.*
Report Type:	*Quote - Custom-Build Your Own Report*

Historical/Products:

ERIS Xplorer	*ERIS Xplorer*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
AAGR	Abandoned Aggregate Inventory	N	-	-	-
AGR	Aggregate Inventory	N	-	-	-
AMIS	Abandoned Mine Information System	N	-	-	-
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	N	-	-	-
CA	Certificates of Approval	N	-	-	-
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	N	-	-	-
CNG	Compressed Natural Gas Stations	N	-	-	-
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	N	-	-	-
CONV	Compliance and Convictions	N	-	-	-
CPU	Certificates of Property Use	N	-	-	-
DRL	Drill Hole Database	N	-	-	-
DTNK	Delisted Fuel Tanks	Y	0	14	14
EASR	Environmental Activity and Sector Registry	N	-	-	-
EBR	Environmental Registry	N	-	-	-
ECA	Environmental Compliance Approval	N	-	-	-
EEM	Environmental Effects Monitoring	N	-	-	-
EHS	ERIS Historical Searches	N	-	-	-
EIIS	Environmental Issues Inventory System	N	-	-	-
EMHE	Emergency Management Historical Event	N	-	-	-
EPAR	Environmental Penalty Annual Report	N	-	-	-
EXP	List of Expired Fuels Safety Facilities	Y	0	18	18
FCON	Federal Convictions	N	-	-	-
FCS	Contaminated Sites on Federal Land	N	-	-	-
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	5	5
FSTH	Fuel Storage Tank - Historic	Y	0	4	4
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	204	204
GHG	Greenhouse Gas Emissions from Large Facilities	N	-	-	-
HINC	TSSA Historic Incidents	N	-	-	-

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	N	-	-	-
INC	Fuel Oil Spills and Leaks	Y	0	3	3
LIMO	Landfill Inventory Management Ontario	N	-	-	-
MINE	Canadian Mine Locations	N	-	-	-
MNR	Mineral Occurrences	N	-	-	-
NATE	National Analysis of Trends in Emergencies System (NATES)	N	-	-	-
NCPL	Non-Compliance Reports	N	-	-	-
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	N	-	-	-
NDWD	National Defence & Canadian Forces Waste Disposal Sites	N	-	-	-
NEBI	National Energy Board Pipeline Incidents	N	-	-	-
NEBP	National Energy Board Wells	N	-	-	-
NEES	National Environmental Emergencies System (NEES)	N	-	-	-
NPCB	National PCB Inventory	Y	0	2	2
NPR2	National Pollutant Release Inventory 1993-2020	N	-	-	-
NPRI	National Pollutant Release Inventory - Historic	N	-	-	-
OGWE	Oil and Gas Wells	N	-	-	-
OOGW	Ontario Oil and Gas Wells	N	-	-	-
OPCB	Inventory of PCB Storage Sites	N	-	-	-
ORD	Orders	N	-	-	-
PAP	Canadian Pulp and Paper	N	-	-	-
PCFT	Parks Canada Fuel Storage Tanks	N	-	-	-
PES	Pesticide Register	N	-	-	-
PFCH	NPRI Reporters - PFAS Substances	N	-	-	-
PFHA	Potential PFAS Handlers from NPRI	N	-	-	-
PINC	Pipeline Incidents	N	-	-	-
PRT	Private and Retail Fuel Storage Tanks	N	-	-	-
PTTW	Permit to Take Water	N	-	-	-
REC	Ontario Regulation 347 Waste Receivers Summary	N	-	-	-
RSC	Record of Site Condition	N	-	-	-
RST	Retail Fuel Storage Tanks	Y	0	2	2
SCT	Scott's Manufacturing Directory	Y	0	13	13
SPL	Ontario Spills	N	-	-	-
SRDS	Wastewater Discharger Registration Database	N	-	-	-
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	N	-	-	-
WDS	Waste Disposal Sites - MOE CA Inventory	N	-	-	-
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	N	-	-	-
WWIS	Water Well Information System	N	-	-	-

Database	Name	Searched	Project Property	Boundary to 0.10km	Total
Total:			0	265	265

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number

No records found in the selected databases for the project property.

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	GEN	Jakalo Investments	243 Queen Street EAst Brampton ON	SE/70.9	0.00	59
1	GEN	TORONTO CAR SALE AND AUTO SERVICE	243 QUEEN STREET EAST BRAMPTON ON	SE/70.9	0.00	59
2	GEN	BRAMGATE VOLKSWAGEN BRAMPTON LTD.	268 QUEEN STREET EAST BRAMPTON ON L6V 1B9	NW/82.2	0.00	59
3	GEN	Heart and Stroke Foundation	245 Queen Street East Unit 2 Brampton ON L6W 2B5	ESE/90.6	0.00	60
3	GEN	Rivlawn Holdings	245 Queen Street East Brampton ON L6W 2B5	ESE/90.6	0.00	60
4	GEN	PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON	N/58.3	0.00	60
4	GEN	PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON	N/58.3	0.00	61
4	GEN	PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON L6V 1B9	N/58.3	0.00	61
4	GEN	PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON L6V 1B9	N/58.3	0.00	61
4	GEN	PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON L6V 1B9	N/58.3	0.00	62
4	GEN	PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON L6V 1B9	N/58.3	0.00	62
5	GEN	Priestly Demolition Inc	247 Queen Street East Brampton ON L6W 2B5	ENE/25.7	-1.00	63

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
6	GEN	PPG Architectural Coatings Canada, Inc.	280 Queen Street East Store 8405 587 Brampton ON L6V 1B9	N/57.5	-0.70	63
7	GEN	JOHN LOGAN CHEV-OLDS	241 QUEEN STREET EAST BRAMPTON ON L6W 2B5	SSE/93.3	0.00	63
7	DTNK	JOHN LOGAN CHEVROLET OLDS INC	241 QUEEN ST E BRAMPTON ON	SSE/93.3	0.00	64
7	DTNK	JOHN LOGAN CHEVROLET OLDS INC	241 QUEEN ST E BRAMPTON ON	SSE/93.3	0.00	64
7	EXP	JOHN LOGAN CHEVROLET OLDS INC	241 QUEEN ST E BRAMPTON ON	SSE/93.3	0.00	65
8	GEN	Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	S/100.0	0.00	65
8	GEN	Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	S/100.0	0.00	66
8	GEN	Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	S/100.0	0.00	66
8	GEN	Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	S/100.0	0.00	66
8	GEN	Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	S/100.0	0.00	67
8	GEN	Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	S/100.0	0.00	67
8	GEN	FH Health	239 Queen St. East Brampton ON L6V1C2	S/100.0	0.00	68
8	GEN	FH Health Inc.	239 Queen Street East, Unit 24 Brampton ON L6V1C2	S/100.0	0.00	68

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
8	GEN	FH Health Inc.	239 Queen Street East, Unit 24 Brampton ON L6V1C2	S/100.0	0.00	69
9	GEN	CANADIAN TIRE PETROLEUM	252 QUEEN STREET EAST BRAMPTON ON L6V 1C1	WSW/71.0	1.93	69
9	SCT	Carvel Ice Cream Bakery	252 Queen St E Unit 6 Brampton ON L6V 1C1	WSW/71.0	1.93	69
9	SCT	Carvel Ice Cream	252 Queen St E Unit 6 Brampton ON L6V 1C1	WSW/71.0	1.93	70
9	DTNK	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	252 QUEEN ST E BRAMPTON ON L6V 1C1	WSW/71.0	1.93	70
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	70
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	71
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	71
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	71
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	71
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	72
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	72
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	72

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
9	EXP	CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	WSW/71.0	1.93	72
10	SCT	LA ROMANA BAKERY INC.	284 QUEEN ST E UNIT 112 BRAMPTON ON L6V 1C2	NNE/81.9	-0.99	73
10	GEN	EMDI Holdings Inc.	284 Queen St. East, Unit 236 Brampton ON L6V 1C2	NNE/81.9	-0.99	73
10	GEN	EMDI Holdings Inc.	284 Queen St. East, Unit 236 Brampton ON L6V 1C2	NNE/81.9	-0.99	73
10	GEN	EMDI Holdings Inc.	284 Queen St. East, Unit 236 Brampton ON L6V 1C2	NNE/81.9	-0.99	74
10	GEN	Dr. Young Pak Dentistry Profession	284 Queen Street East Suite 206 Brampton ON L6V 1C2	NNE/81.9	-0.99	74
10	GEN	EMDI Holdings Inc.	284 Queen St. East, Unit 236 Brampton ON L6V 1C2	NNE/81.9	-0.99	75
10	GEN	Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	NNE/81.9	-0.99	75
10	GEN	Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	NNE/81.9	-0.99	75
10	GEN	Dr Shane A Hunt	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	NNE/81.9	-0.99	76
10	GEN	Dr Shane A Hunt	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	NNE/81.9	-0.99	76
10	GEN	Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	NNE/81.9	-0.99	77
10	GEN	Dr Shane A Hunt	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	NNE/81.9	-0.99	77

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
10	GEN	Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	NNE/81.9	-0.99	77
10	GEN	Dr Shane A Hunt	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	NNE/81.9	-0.99	78
10	GEN	Dr. Nikita Khurana Dentistry Professional Corp	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	NNE/81.9	-0.99	78
10	GEN	Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	NNE/81.9	-0.99	78
10	GEN	1938370 Ontario Inc.	116-284 Queen Street East Brampton ON L6V1C2	NNE/81.9	-0.99	79
10	GEN	Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	NNE/81.9	-0.99	79
10	GEN	1938370 Ontario Inc.	116-284 Queen Street East Brampton ON L6V1C2	NNE/81.9	-0.99	80
10	GEN	Dr. Nikita Khurana Dentistry Professional Corp	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	NNE/81.9	-0.99	80
11	SCT	123 Computer Warehouse Inc.	253 Queen St E Unit 2 Brampton ON L6W 2B8	ENE/73.7	-2.00	80
11	SCT	Musclemag International	253 Queen St E Unit 23 Brampton ON L6W 2B8	ENE/73.7	-2.00	81
11	GEN	SHELLER-GLOBE OF CANADA LTD.	253 QUEEN ST. E. BRAMPTON ON L6W 2B8	ENE/73.7	-2.00	81
11	GEN	Sears Canada Inc.	253 Queen Street e Brampton ON L6W 2B8	ENE/73.7	-2.00	81
11	GEN	Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	82

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	GEN	Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	82
11	GEN	Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	82
11	GEN	Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	83
11	GEN	Homedale-Eagle Corporation	253 Queen Street East Brampton ON	ENE/73.7	-2.00	83
11	GEN	Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	84
11	GEN	Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	84
11	GEN	Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	84
11	GEN	253 Queen Street Inc.	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	85
11	GEN	253 Queen Street Inc.	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	85
11	GEN	253 Queen Street Inc.	253 Queen Street East Brampton ON L6W 2B8	ENE/73.7	-2.00	85
12	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	SW/52.9	1.04	86
12	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	SW/52.9	1.04	86
12	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	SW/52.9	1.04	87

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
12	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON	SW/52.9	1.04	87
12	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	SW/52.9	1.04	87
12	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	SW/52.9	1.04	88
12	GEN	AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	SW/52.9	1.04	88
12	GEN	i6 Building Corp	2 Kennedy Road South Brampton ON L6W 3E1	SW/52.9	1.04	88
12	GEN	i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	SW/52.9	1.04	89
12	GEN	i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	SW/52.9	1.04	89
12	GEN	i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	SW/52.9	1.04	89
13	GEN	PARKINSON COACH LINES LTD.	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	WSW/87.1	2.57	90
13	GEN	PARKINSON COACH LINES LTD.	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	WSW/87.1	2.57	90
13	GEN	PARKINSON COACH LINES LTD. 30-262	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	WSW/87.1	2.57	90
13	GEN	PARKINSON COACH LINES LTD.	10 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	WSW/87.1	2.57	91
13	GEN	PARKINSON COACH LINES 2000 INC.	10 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	WSW/87.1	2.57	91

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
13	FSTH	PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON L6V 1X4	WSW/87.1	2.57	92
13	FSTH	PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON L6V 1X4	WSW/87.1	2.57	92
13	GEN	PARKINSON COACH LINES 2000 INC.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	92
13	GEN	PARKINSON COACH LINES 2000 INC.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	92
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	93
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	93
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON	WSW/87.1	2.57	94
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	94
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	94
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	95
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	95
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	96
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	96

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
13	GEN	Parkinson Coach	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	97
13	GEN	PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	WSW/87.1	2.57	97
13	EXP	PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON	WSW/87.1	2.57	97
14	GEN	COLONY LINCOLN MERCURY SALES LTD.	300 QUEEN STREET EAST BRAMPTON ON L6V 1C2	NE/59.3	-0.91	98
14	DTNK	COLONY LINCOLN MERCURY SALES LTD	300 QUEEN ST E BRAMPTON ON	NE/59.3	-0.91	98
15	SCT	Counterfitters of Ontario Inc.	255 Queen St E Unit 5 Brampton ON L6W 2B8	NE/41.0	-2.00	99
15	GEN	AMSCO CANADA LIMITED	255 QUEEN ST. E. BRAMPTON ON L6W 2B8	NE/41.0	-2.00	99
15	GEN	AMSCO CANADA LIMITED 01-203	255 QUEEN ST. E. BRAMPTON ON L6W 2B8	NE/41.0	-2.00	99
15	GEN	AMSCO CANADA LIMITED	255 QUEEN STREET EAST BRAMPTON ON L6W 2B8	NE/41.0	-2.00	100
16	GEN	United Investments - 1898692 Ontario Inc	310 Queen Street East Brampton ON L6V 1C2	NE/57.0	-0.27	100
17	INC		263 QUEEN STREET EAST, BRAMPTON ON	ENE/72.2	-2.00	101
17	GEN	Bayer Inc.	Queens Center Plaza 263 Queen Street East Brampton ON L6W 4K6	ENE/72.2	-2.00	101
18	DTNK	SHELL CANADA PRODUCTS**	230 QUEEN ST E BRAMPTON ON	SW/56.6	2.95	102

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
18	EXP	SHELL CANADA PRODUCTS	230 QUEEN ST E BRAMPTON ON	SW/56.6	2.95	102
18	EXP	SHELL CANADA PRODUCTS	230 QUEEN ST E BRAMPTON ON	SW/56.6	2.95	103
19	NPCB	CANADA CUP INC	228 QUEEN STREET EAST BRAMPTON ON L7YA9	WSW/71.0	3.08	103
19	NPCB	CANADA CUP INC	228 QUEEN ST E BRAMPTON ON L6V 1B8	WSW/71.0	3.08	104
20	GEN	Viable Healthworks	312 Queen Street East Brampton ON L6V 1C2	NE/37.9	-0.47	104
20	GEN	AIM Health Group	312 Queen St E Brampton ON L6V 1C2	NE/37.9	-0.47	104
20	GEN	Viable Healthworks	312 Queen Street East Brampton ON L6V 1C2	NE/37.9	-0.47	105
20	GEN	Viable Healthworks	312 Queen Street East Brampton ON L6V 1C2	NE/37.9	-0.47	105
20	GEN	Viable Healthworks	312 Queen Street East Brampton ON L6V 1C2	NE/37.9	-0.47	105
20	GEN	NeuPath Health	312 Queen Street East Brampton ON L6V 1C2	NE/37.9	-0.47	106
21	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	SW/74.7	2.09	106
21	DTNK	2931621 CANADA INC O/A CANADIAN TIRE	1 KENNEDY RD S BRAMPTON ON	SW/74.7	2.09	107
21	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	SW/74.7	2.09	107

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
21	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	SW/74.7	2.09	108
21	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	SW/74.7	2.09	108
21	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	SW/74.7	2.09	108
21	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	SW/74.7	2.09	109
21	GEN	Dr Essam Michael Medicine Professional Corporation	1 Kennedy Road Brampton ON L6W 3C9	SW/74.7	2.09	109
21	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	SW/74.7	2.09	109
21	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	SW/74.7	2.09	110
21	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	SW/74.7	2.09	110
21	GEN	Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	SW/74.7	2.09	111
21	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	SW/74.7	2.09	111
21	GEN	Dr Essam Michael Medicine Professional Corporation	1 Kennedy Road Brampton ON L6W 3C9	SW/74.7	2.09	111
21	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	SW/74.7	2.09	112
21	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	SW/74.7	2.09	112

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
21	GEN	Loblaw Companies Limited - Shoppers Drug Mart	1 Kennedy Rd S Brampton ON L6W 3C9	SW/74.7	2.09	112
21	GEN	Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	SW/74.7	2.09	113
21	GEN	Athletes Care Brampton	1 Kennedy Rd S Unit 12 Brampton ON L6W 3C9	SW/74.7	2.09	113
22	GEN	2484667 Ontario Inc.	215 Queen Street East Unit 8 Brampton ON L6W 0A9	SW/40.0	2.29	114
22	GEN	2484667 Ontario Inc.	215 Queen Street East Unit 8 Brampton ON L6W 0A9	SW/40.0	2.29	114
23	GEN	MATTAMY (BRAMVIEW LTD)	209 QUEEN ST EAST BRAMPTON ON L6W 2B4	SW/18.0	2.76	114
23	DTNK	BRAMVIEW FORD SALES LTD	209 QUEEN ST E BRAMPTON ON L6W 2B4	SW/18.0	2.76	115
23	DTNK	BRAMVIEW FORD SALES LTD	209 QUEEN ST E BRAMPTON ON	SW/18.0	2.76	115
24	INC		261 QUEEN STREET EAST, BRAMPTON ON	NE/42.2	-2.00	116
25	GEN	FLOWERTOWN CLEANERS & LAUNDERERS	210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	SW/42.4	2.94	117
25	GEN	FLOWERTOWN CLEANERS & LAUNDERERS	210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	SW/42.4	2.94	117
25	GEN	FLOWERTOWN CLEANERS & LAUNDERERS 15-133	210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	SW/42.4	2.94	117
25	GEN	FLOWERTOWN CLEANERS AND LAUNDERERS_	210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	SW/42.4	2.94	118

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
25	GEN	FLOWERTOWN CLEANERS AND LAUNDERERS	210 Queen Street East Brampton ON L6V 1B7	SW/42.4	2.94	118
25	SCT	G. Print Ltd.	210 Queen St E Brampton ON L6V 1B7	SW/42.4	2.94	118
26	GEN	Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	119
26	GEN	Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	119
26	GEN	Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	119
26	GEN	Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	120
26	GEN	Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	120
26	GEN	Bramvet Ltd	265 queen St East Brampton ON	NE/39.4	-1.00	120
26	GEN	Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	121
26	GEN	Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	121
26	GEN	Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	122
26	GEN	Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	122
26	GEN	Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	122

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
26	GEN	Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	123
26	GEN	Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	NE/39.4	-1.00	123
27	GEN	Dr. R. Nayyar Dentistry Professional Corporation	4 Beech Street Brampton ON L6V1V1	SW/74.8	3.01	123
28	GEN	Louis Gregorich	10 Beech Street Brampton ON	WSW/98.4	3.00	124
29	GEN	2093893 ONTARIO INC	269 QUEEN STREET EAST BRAMPTON ON L6W 2C2	NE/89.3	-2.07	124
30	SCT	ROYAL MATTRESS MFG CO	338 QUEEN ST E BRAMPTON ON L6V 1C4	NE/59.8	0.00	124
31	GEN	MCLEAN'S RENTAL'S	279 QUEEN STREET EAST BRAMPTON ON L6W 2C2	NE/84.1	-3.13	125
31	GEN	MCLEAN'S EQUIPMENT RENTAL BRAMPTON INC.	279 QUEEN STREET EAST BRAMPTON ON L6W 2C2	NE/84.1	-3.13	125
31	GEN	MCLEAN'S EQUIPMENT RENTAL 26-359	(BRAMPTON) INC. 279 QUEEN ST. E. BRAMPTON ON L6W 2C2	NE/84.1	-3.13	125
31	GEN	McLean's Equipment Rental Brampton Inc.	279 Queen st. E Unit D&E Brampton ON L6W 2C2	NE/84.1	-3.13	126
32	SCT	Ipax Canada Ltd.	174 Queen St E Brampton ON L6V 1B3	SW/53.8	1.84	126
33	RST	PETRO CANADA	354 QUEEN ST E BRAMPTON ON L6V 1C3	NE/22.1	-0.85	126
33	DTNK	PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	126

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
33	DTNK	PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	127
33	DTNK	PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	128
33	DTNK	PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	128
33	DTNK	PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	129
33	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	129
33	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	130
33	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	130
33	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	130
33	RST	PETRO CANADA	354 QUEEN ST E BRAMPTON ON L6V1C3	NE/22.1	-0.85	130
33	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	131
33	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	131
33	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	131
33	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	131

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
33	EXP	2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	132
33	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	NE/22.1	-0.85	132
34	SCT	BRAMPTON GALLERIES	173 QUEEN ST E BRAMPTON ON L6W 2B2	SW/10.1	1.01	132
35	GEN	DALE'S PHARMACY BRAMPTON LTD. 12-710	164 QUEEN STREET EAST BRAMPTON ON L6V 1B4	SW/45.1	1.01	132
35	GEN	MCTU DIAGNOSTICS LIMITED	164 QUEEN STREET EAST, SUITE B3 BRAMPTON ON L6V 1B4	SW/45.1	1.01	133
35	GEN	MCTU DIAGNOSTICS LIMITED	164 QUEEN STREET EAST SUITE B3 BRAMPTON ON L6V 1B4	SW/45.1	1.01	133
35	GEN	MCTU DI(OUT OF BUSINESS)	164 QUEEN STREET EAST SUITE B3 BRAMPTON ON L6V 1B4	SW/45.1	1.01	134
35	GEN	Brampton Queen Equity Inc.	164 Queen St. E. Brampton ON L6V 1B4	SW/45.1	1.01	134
35	GEN	GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON	SW/45.1	1.01	134
35	GEN	GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON L6V 1B4	SW/45.1	1.01	135
35	GEN	GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON L6V 1B4	SW/45.1	1.01	135
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	SW/45.1	1.01	135
35	GEN	GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON L6V 1B4	SW/45.1	1.01	136

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	SW/45.1	1.01	136
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	SW/45.1	1.01	136
35	GEN	GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON L6V 1B4	SW/45.1	1.01	137
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON	SW/45.1	1.01	137
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	SW/45.1	1.01	137
35	GEN	Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L7A 1G9	SW/45.1	1.01	138
35	GEN	Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L7A 1G9	SW/45.1	1.01	138
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	SW/45.1	1.01	139
35	GEN	Goldbrite Trading Company	164 Queen Street E. Brampton ON L6V 1B4	SW/45.1	1.01	139
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	SW/45.1	1.01	139
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	SW/45.1	1.01	140
35	GEN	Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L7A 1G9	SW/45.1	1.01	140
35	GEN	farida jeejeebhoy medicine professional corp	164 Queen Street East, unit 209 brampton ON L6V1B4	SW/45.1	1.01	140

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
35	GEN	farida jeejeebhoy medicine professional corp	164 Queen Street East, unit 209 brampton ON L6V1B4	SW/45.1	1.01	141
35	GEN	Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L6V1B4	SW/45.1	1.01	141
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	SW/45.1	1.01	141
35	GEN	M.M.&K. Drug Enterprises Corp.	105-164 Queen st E Brampton ON L6V 1B4	SW/45.1	1.01	142
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 210 Brampton ON L6V 1B4	SW/45.1	1.01	142
35	GEN	farida jeejeebhoy medicine professional corp	164 Queen Street East, unit 209 brampton ON L6V1B4	SW/45.1	1.01	143
35	GEN	M.M.&K. Drug Enterprises Corp.	105-164 Queen st E Brampton ON L6V 1B4	SW/45.1	1.01	143
35	GEN	Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L6V1B4	SW/45.1	1.01	143
35	GEN	Karmy Medicine Professional Corporation	164 Queen Street East Suite 210 Brampton ON L6V 1B4	SW/45.1	1.01	144
35	GEN	M.M.&K. Drug Enterprises Corp.	105-164 Queen st E Brampton ON L6V 1B4	SW/45.1	1.01	144
35	GEN	Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L6V1B4	SW/45.1	1.01	144
36	GEN	2506907 ONTARIO	169 QUEEN ST EAST BRAMPTON ON L6W2B2	SW/24.7	1.01	145
36	GEN	2506907 ONTARIO	169 QUEEN ST EAST BRAMPTON ON L6W2B2	SW/24.7	1.01	145

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
36	GEN	2506907 ONTARIO	169 QUEEN ST EAST BRAMPTON ON L6W2B2	SW/24.7	1.01	145
37	GEN	North Peel Xray and Ultrasound	157 Queen Street East Brampton ON L6W 3X4	SW/15.3	1.01	146
37	GEN	Queen lynch Co Tenancy	157 Queen Street East Brampton ON	SW/15.3	1.01	146
37	GEN	Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	SW/15.3	1.01	147
37	GEN	Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	SW/15.3	1.01	147
37	GEN	Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	SW/15.3	1.01	147
37	GEN	Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	SW/15.3	1.01	148
37	GEN	Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	SW/15.3	1.01	148
37	GEN	Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	SW/15.3	1.01	148
38	GEN	BRAMPTON CYTOLOGY	DIV. OF BESTVIEW MEDICAL LABORATORIES 178 JOHN STREET BRAMPTON ON L6W 2A4	SW/57.7	1.01	149
38	GEN	BRAMPTON CYTOLOGY 05-096	DIV. OF BESTVIEW MEDICAL LABORATORIES 178 JOHN STREET BRAMPTON ON L6W 2A4	SW/57.7	1.01	149
38	GEN	CMLHealthCare	178 John Street Brampton ON	SW/57.7	1.01	150

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
38	GEN	CMLHealthCare	178 John Street Brampton ON	SW/57.7	1.01	150
38	GEN	CMLHealthCare	178 John Street Brampton ON	SW/57.7	1.01	150
38	GEN	Dr. Molnar & Dr. Najarali	178 John Street Unit 100 Brampton ON L6W 2A4	SW/57.7	1.01	151
38	GEN	Dr. Molnar & Dr. Najarali	178 John Street Unit 100 Brampton ON L6W 2A4	SW/57.7	1.01	151
39	GEN	D & I SPORTS INC.	382 QUEEN ST. E. BRAMPTON ON L6V 1C3	NE/82.6	0.00	151
39	GEN	D & I SPORTS INC.	382 QUEEN ST. E. BRAMPTON ON L6V 1C3	NE/82.6	0.00	152
39	GEN	D & I SPORTS INC. 12-268	382 QUEEN ST. E. BRAMPTON ON L6V 1C3	NE/82.6	0.00	152
39	GEN	D & I SPORTS INCORPORATED	382 QUEEN STREET EAST BRAMPTON ON L6V 1C3	NE/82.6	0.00	152
40	GEN	Elmbrook Management	145 Queen Street East Suite 400 Brampton ON L6W 3P8	SW/58.8	0.44	153
40	GEN	Dr Percy Segal	145 Queen St E #201 Brampton ON L6W 3P8	SW/58.8	0.44	153
40	GEN	Elmbrook Management	145 Queen Street East Suite 400 Brampton ON L6W 3P8	SW/58.8	0.44	154
40	GEN	Elmbrook Management	145 Queen Street East Suite 400 Brampton ON L6W 3P8	SW/58.8	0.44	154
41	SCT	Kronos Canada Inc.	295 Queen St E Suite 443 Brampton ON L6W 3W9	NE/63.7	0.00	154

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
41	SCT	New Home Services Inc.	295 Queen St E Unit 6 Suite 464 Brampton ON L6W 3W9	NE/63.7	0.00	155
41	SCT	Waymar Manufacturing Co.	457-295 Queen St E Brampton ON L6W 3W9	NE/63.7	0.00	155
42	FSTH	NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC	130 QUEEN ST BRAMPTON ON	SW/24.8	-4.59	155
42	FSTH	NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC	130 QUEEN ST BRAMPTON ON	SW/24.8	-4.59	156
42	DTNK	NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC	130 QUEEN ST BRAMPTON ON	SW/24.8	-4.59	157
43	GEN	Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	SW/84.3	-10.72	158
43	GEN	Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	SW/84.3	-10.72	158
43	GEN	Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	SW/84.3	-10.72	158
43	GEN	Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	SW/84.3	-10.72	159
43	GEN	Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	SW/84.3	-10.72	159
43	GEN	Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	SW/84.3	-10.72	160
44	GEN	Dr. Robert Sleightholm Professional Medicine Inc.	111 Queen Street East Unit 2-4 Brampton ON L6W2A9	SW/95.7	-11.03	160
44	GEN	Dr. Robert Sleightholm Professional Medicine Inc.	111 Queen Street East Unit 2-4 Brampton ON L6W2A9	SW/95.7	-11.03	160

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
44	GEN	Dr. Robert Sleightholm Professional Medicine Inc.	111 Queen Street East Unit 2-4 Brampton ON L6W2A9	SW/95.7	-11.03	161
44	GEN	Dr. Robert Sleightholm Professional Medicine Inc.	111 Queen Street East Unit 2-4 Brampton ON L6W2A9	SW/95.7	-11.03	161
45	INC		Queen Street & Scott Street, Brampton ON	SW/100.0	-10.33	162

Executive Summary: Summary By Data Source

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 14 DTNK site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
JOHN LOGAN CHEVROLET OLDS INC	241 QUEEN ST E BRAMPTON ON	93.3	7
JOHN LOGAN CHEVROLET OLDS INC	241 QUEEN ST E BRAMPTON ON	93.3	7
CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr**	252 QUEEN ST E BRAMPTON ON L6V 1C1	71.0	9
COLONY LINCOLN MERCURY SALES LTD	300 QUEEN ST E BRAMPTON ON	59.3	14
SHELL CANADA PRODUCTS**	230 QUEEN ST E BRAMPTON ON	56.6	18
2931621 CANADA INC O/A CANADIAN TIRE	1 KENNEDY RD S BRAMPTON ON	74.7	21
BRAMVIEW FORD SALES LTD	209 QUEEN ST E BRAMPTON ON	18.0	23
BRAMVIEW FORD SALES LTD	209 QUEEN ST E BRAMPTON ON L6W 2B4	18.0	23
PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	22.1	33

Site	Address	Distance (m)	Map Key
PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	22.1	33
PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	22.1	33
PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	22.1	33
PETRO-CANADA # 57624	354 QUEEN ST E BRAMPTON ON	22.1	33
NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC	130 QUEEN ST BRAMPTON ON	24.8	42

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Oct 2023 has found that there are 18 EXP site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
JOHN LOGAN CHEVROLET OLDS INC	241 QUEEN ST E BRAMPTON ON	93.3	7
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9

Site	Address	Distance (m)	Map Key
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9
CANADIAN TIRE CORPORATION LIMITED	252 QUEEN ST E BRAMPTON ON	71.0	9
PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON	87.1	13
SHELL CANADA PRODUCTS	230 QUEEN ST E BRAMPTON ON	56.6	18
SHELL CANADA PRODUCTS	230 QUEEN ST E BRAMPTON ON	56.6	18
2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	22.1	33
2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	22.1	33
2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	22.1	33

Site	Address	Distance (m)	Map Key
2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	22.1	33
2124964 ONTARIO INC O/A PETRO-CANADA	354 QUEEN ST E BRAMPTON ON	22.1	33

FST - Fuel Storage Tank

A search of the FST database, dated Oct 2023 has found that there are 5 FST site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	22.1	33
SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	22.1	33
SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	22.1	33
SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	22.1	33
SUNCOR ENERGY PRODUCTS PARTNERSHIP	354 QUEEN ST E BRAMPTON ON	22.1	33

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 4 FSTH site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON L6V 1X4	87.1	13

Site	Address	Distance (m)	Map Key
PARKINSON COACH LINES GEORGE MURRAY	10 KENNEDY RD N BRAMPTON ON L6V 1X4	87.1	13
NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC	130 QUEEN ST BRAMPTON ON	24.8	42
NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC	130 QUEEN ST BRAMPTON ON	24.8	42

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 213 GEN site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Jakalo Investments	243 Queen Street EAst Brampton ON	70.9	1
TORONTO CAR SALE AND AUTO SERVICE	243 QUEEN STREET EAST BRAMPTON ON	70.9	1
BRAMGATE VOLKSWAGEN BRAMPTON LTD.	268 QUEEN STREET EAST BRAMPTON ON L6V 1B9	82.2	2
Heart and Stroke Foundation	245 Queen Street East Unit 2 Brampton ON L6W 2B5	90.6	3
Rivlawn Holdings	245 Queen Street East Brampton ON L6W 2B5	90.6	3
PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON	58.3	4
PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON	58.3	4

Site	Address	Distance (m)	Map Key
PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON L6V 1B9	58.3	4
PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON L6V 1B9	58.3	4
PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON L6V 1B9	58.3	4
PPG Architectural Coatings Canada, Inc.	272 Queen Street East Store 587 Brampton ON L6V 1B9	58.3	4
Priestly Demolition Inc	247 Queen Street East Brampton ON L6W 2B5	25.7	5
PPG Architectural Coatings Canada, Inc.	280 Queen Street East Store 8405 587 Brampton ON L6V 1B9	57.5	6
JOHN LOGAN CHEV-OLDS	241 QUEEN STREET EAST BRAMPTON ON L6W 2B5	93.3	7
Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	100.0	8
Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	100.0	8
Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	100.0	8
Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	100.0	8

Site	Address	Distance (m)	Map Key
Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	100.0	8
Dr.Mujeeb S. Qazi Dentistry Professional Corporati	239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	100.0	8
FH Health	239 Queen St. East Brampton ON L6V1C2	100.0	8
FH Health Inc.	239 Queen Street East, Unit 24 Brampton ON L6V1C2	100.0	8
FH Health Inc.	239 Queen Street East, Unit 24 Brampton ON L6V1C2	100.0	8
CANADIAN TIRE PETROLEUM	252 QUEEN STREET EAST BRAMPTON ON L6V 1C1	71.0	9
EMDI Holdings Inc.	284 Queen St. East, Unit 236 Brampton ON L6V 1C2	81.9	10
EMDI Holdings Inc.	284 Queen St. East, Unit 236 Brampton ON L6V 1C2	81.9	10
EMDI Holdings Inc.	284 Queen St. East, Unit 236 Brampton ON L6V 1C2	81.9	10
Dr. Young Pak Dentistry Profession	284 Queen Street East Suite 206 Brampton ON L6V 1C2	81.9	10
EMDI Holdings Inc.	284 Queen St. East, Unit 236 Brampton ON L6V 1C2	81.9	10
Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	81.9	10

Site	Address	Distance (m)	Map Key
Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	81.9	10
Dr Shane A Hunt	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	81.9	10
Dr Shane A Hunt	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	81.9	10
Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	81.9	10
Dr Shane A Hunt	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	81.9	10
Dr. Nikita Khurana Dentistry Professional Corp	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	81.9	10
Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	81.9	10
1938370 Ontario Inc.	116-284 Queen Street East Brampton ON L6V1C2	81.9	10
Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	81.9	10
1938370 Ontario Inc.	116-284 Queen Street East Brampton ON L6V1C2	81.9	10
Dr. Nikita Khurana Dentistry Professional Corp	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	81.9	10

Site	Address	Distance (m)	Map Key
Dr Shane A Hunt	284 Queen St. E. Suite 120 Brampton ON L6V 1C2	81.9	10
Dr. Young Pak Dentistry Profession	284 Queen Street East Brampton ON L6V 1C2	81.9	10
SHELLER-GLOBE OF CANADA LTD.	253 QUEEN ST. E. BRAMPTON ON L6W 2B8	73.7	11
Sears Canada Inc.	253 Queen Street e Brampton ON L6W 2B8	73.7	11
Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	73.7	11
Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	73.7	11
Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	73.7	11
Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	73.7	11
Homedale-Eagle Corporation	253 Queen Street East Brampton ON	73.7	11
Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	73.7	11
Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	73.7	11
Homedale-Eagle Corporation	253 Queen Street East Brampton ON L6W 2B8	73.7	11

Site	Address	Distance (m)	Map Key
253 Queen Street Inc.	253 Queen Street East Brampton ON L6W 2B8	73.7	11
253 Queen Street Inc.	253 Queen Street East Brampton ON L6W 2B8	73.7	11
253 Queen Street Inc.	253 Queen Street East Brampton ON L6W 2B8	73.7	11
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	52.9	12
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	52.9	12
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	52.9	12
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON	52.9	12
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	52.9	12
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	52.9	12
AIM Health Group LTD	2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	52.9	12
i6 Building Corp	2 Kennedy Road South Brampton ON L6W 3E1	52.9	12

Site	Address	Distance (m)	Map Key
i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	52.9	12
i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	52.9	12
i6 Building Corp	2 Kennedy Road South Unit4A Brampton ON L6W 3E1	52.9	12
PARKINSON COACH LINES LTD.	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	87.1	13
PARKINSON COACH LINES LTD.	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	87.1	13
PARKINSON COACH LINES LTD. 30-262	10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	87.1	13
PARKINSON COACH LINES LTD.	10 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	87.1	13
PARKINSON COACH LINES 2000 INC.	10 KENNEDY ROAD NORTH BRAMPTON ON L6V 1X4	87.1	13
PARKINSON COACH LINES 2000 INC.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH LINES 2000 INC.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13

Site	Address	Distance (m)	Map Key
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
Parkinson Coach	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
PARKINSON COACH & TOURS LTD.	10 Kennedy Road North Brampton ON L6V 1X4	87.1	13
COLONY LINCOLN MERCURY SALES LTD.	300 QUEEN STREET EAST BRAMPTON ON L6V 1C2	59.3	14
AMSCO CANADA LIMITED	255 QUEEN ST. E. BRAMPTON ON L6W 2B8	41.0	15

Site	Address	Distance (m)	Map Key
AMSCO CANADA LIMITED 01-203	255 QUEEN ST. E. BRAMPTON ON L6W 2B8	41.0	15
AMSCO CANADA LIMITED	255 QUEEN STREET EAST BRAMPTON ON L6W 2B8	41.0	15
United Investments - 1898692 Ontario Inc	310 Queen Street East Brampton ON L6V 1C2	57.0	16
Bayer Inc.	Queens Center Plaza 263 Queen Street East Brampton ON L6W 4K6	72.2	17
Viable Healthworks	312 Queen Street East Brampton ON L6V 1C2	37.9	20
AIM Health Group	312 Queen St E Brampton ON L6V 1C2	37.9	20
Viable Healthworks	312 Queen Street East Brampton ON L6V 1C2	37.9	20
Viable Healthworks	312 Queen Street East Brampton ON L6V 1C2	37.9	20
Viable Healthworks	312 Queen Street East Brampton ON L6V 1C2	37.9	20
NeuPath Health	312 Queen Street East Brampton ON L6V 1C2	37.9	20
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	74.7	21
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	74.7	21

Site	Address	Distance (m)	Map Key
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	74.7	21
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	74.7	21
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	74.7	21
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON	74.7	21
Dr Essam Michael Medicine Professional Corporation	1 Kennedy Road Brampton ON L6W 3C9	74.7	21
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	74.7	21
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	74.7	21
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	74.7	21
Astra Fertility Group-Brampton	1 Kennedy Road Brampton ON L6W 3C9	74.7	21
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	74.7	21
Dr Essam Michael Medicine Professional Corporation	1 Kennedy Road Brampton ON L6W 3C9	74.7	21

Site	Address	Distance (m)	Map Key
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	74.7	21
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	74.7	21
Loblaw Companies Limited - Shoppers Drug Mart	1 Kennedy Rd S Brampton ON L6W 3C9	74.7	21
Domenic Romano Pharmacy Inc.	1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	74.7	21
Athletes Care Brampton	1 Kennedy Rd S Unit 12 Brampton ON L6W 3C9	74.7	21
2484667 Ontario Inc.	215 Queen Street East Unit 8 Brampton ON L6W 0A9	40.0	22
2484667 Ontario Inc.	215 Queen Street East Unit 8 Brampton ON L6W 0A9	40.0	22
MATTAMY (BRAMVIEW LTD)	209 QUEEN ST EAST BRAMPTON ON L6W 2B4	18.0	23
FLOWERTOWN CLEANERS & LAUNDERERS	210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	42.4	25
FLOWERTOWN CLEANERS & LAUNDERERS	210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	42.4	25
FLOWERTOWN CLEANERS & LAUNDERERS 15-133	210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	42.4	25
FLOWERTOWN CLEANERS AND LAUNDERERS_	210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	42.4	25

Site	Address	Distance (m)	Map Key
FLOWERTOWN CLEANERS AND LAUNDERERS	210 Queen Street East Brampton ON L6V 1B7	42.4	25
Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	39.4	26
Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	39.4	26
Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	39.4	26
Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	39.4	26
Bramvet Ltd	265 queen St East Brampton ON L6W 2C2	39.4	26
Bramvet Ltd	265 queen St East Brampton ON	39.4	26
Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	39.4	26
Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	39.4	26
Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	39.4	26
Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	39.4	26

Site	Address	Distance (m)	Map Key
Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	39.4	26
Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	39.4	26
Brampton Veterinary Hospital Professional Corp	265 queen St East Brampton ON L6W 2C2	39.4	26
Dr. R. Nayyar Dentistry Professional Corporation	4 Beech Street Brampton ON L6V1V1	74.8	27
Louis Gregorich	10 Beech Street Brampton ON	98.4	28
2093893 ONTARIO INC	269 QUEEN STREET EAST BRAMPTON ON L6W 2C2	89.3	29
MCLEAN'S RENTAL'S	279 QUEEN STREET EAST BRAMPTON ON L6W 2C2	84.1	31
MCLEAN'S EQUIPMENT RENTA L BRAMPTON INC.	279 QUEEN STREET EAST BRAMPTON ON L6W 2C2	84.1	31
MCLEAN'S EQUIPMENT RENTAL 26-359	(BRAMPTON) INC. 279 QUEEN ST. E. BRAMPTON ON L6W 2C2	84.1	31
McLean's Equipment Rental Brampton Inc.	279 Queen st. E Unit D&E Brampton ON L6W 2C2	84.1	31
DALE'S PHARMACY BRAMPTON LTD. 12-710	164 QUEEN STREET EAST BRAMPTON ON L6V 1B4	45.1	35
MCTU DIAGNOSTICS LIMITED	164 QUEEN STREET EAST, SUITE B3 BRAMPTON ON L6V 1B4	45.1	35

Site	Address	Distance (m)	Map Key
MCTU DIAGNOSTICS LIMITED	164 QUEEN STREET EAST SUITE B3 BRAMPTON ON L6V 1B4	45.1	35
MCTU DI(OUT OF BUSINESS)	164 QUEEN STREET EAST SUITE B3 BRAMPTON ON L6V 1B4	45.1	35
Brampton Queen Equity Inc.	164 Queen St. E. Brampton ON L6V 1B4	45.1	35
GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON	45.1	35
GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON L6V 1B4	45.1	35
GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON L6V 1B4	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	45.1	35
GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON L6V 1B4	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	45.1	35
GOEYECARE INC	164 Queen St., East Suite 210 Brampton ON L6V 1B4	45.1	35

Site	Address	Distance (m)	Map Key
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	45.1	35
Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L7A 1G9	45.1	35
Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L7A 1G9	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	45.1	35
Goldbrite Trading Company	164 Queen Street E. Brampton ON L6V 1B4	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	45.1	35
Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L7A 1G9	45.1	35
farida jeejeebhoy medicine professional corp	164 Queen Street East, unit 209 brampton ON L6V1B4	45.1	35
farida jeejeebhoy medicine professional corp	164 Queen Street East, unit 209 brampton ON L6V1B4	45.1	35
Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L6V1B4	45.1	35

Site	Address	Distance (m)	Map Key
Karmy Medicine Professional Corporation	164 Queen Street East Suite 110 Brampton ON L6V 1B4	45.1	35
M.M.&K. Drug Enterprises Corp.	105-164 Queen st E Brampton ON L6V 1B4	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 210 Brampton ON L6V 1B4	45.1	35
farida jeejeebhoy medicine professional corp	164 Queen Street East, unit 209 brampton ON L6V1B4	45.1	35
M.M.&K. Drug Enterprises Corp.	105-164 Queen st E Brampton ON L6V 1B4	45.1	35
Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L6V1B4	45.1	35
Karmy Medicine Professional Corporation	164 Queen Street East Suite 210 Brampton ON L6V 1B4	45.1	35
M.M.&K. Drug Enterprises Corp.	105-164 Queen st E Brampton ON L6V 1B4	45.1	35
Healthy smile dental hygiene	164 Queen street east unit 108a Brampton ON L6V1B4	45.1	35
2506907 ONTARIO	169 QUEEN ST EAST BRAMPTON ON L6W2B2	24.7	36
2506907 ONTARIO	169 QUEEN ST EAST BRAMPTON ON L6W2B2	24.7	36

Site	Address	Distance (m)	Map Key
2506907 ONTARIO	169 QUEEN ST EAST BRAMPTON ON L6W2B2	24.7	36
North Peel Xray and Ultrasound	157 Queen Street East Brampton ON L6W 3X4	15.3	37
Queen lynch Co Tenancy	157 Queen Street East Brampton ON	15.3	37
Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	15.3	37
Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	15.3	37
Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	15.3	37
Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	15.3	37
Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	15.3	37
Queen Lynch Co-Tenancy	157 Queen Street Brampton ON L6W 3X4	15.3	37
BRAMPTON CYTOLOGY	DIV. OF BESTVIEW MEDICAL LABORATORIES 178 JOHN STREET BRAMPTON ON L6W 2A4	57.7	38
BRAMPTON CYTOLOGY 05-096	DIV. OF BESTVIEW MEDICAL LABORATORIES 178 JOHN STREET BRAMPTON ON L6W 2A4	57.7	38
CMLHealthCare	178 John Street Brampton ON	57.7	38

Site	Address	Distance (m)	Map Key
CMLHealthCare	178 John Street Brampton ON	57.7	38
CMLHealthCare	178 John Street Brampton ON	57.7	38
Dr. Molnar & Dr. Najarali	178 John Street Unit 100 Brampton ON L6W 2A4	57.7	38
Dr. Molnar & Dr. Najarali	178 John Street Unit 100 Brampton ON L6W 2A4	57.7	38
D & I SPORTS INC. 12-268	382 QUEEN ST. E. BRAMPTON ON L6V 1C3	82.6	39
D & I SPORTS INCORPORATED	382 QUEEN STREET EAST BRAMPTON ON L6V 1C3	82.6	39
D & I SPORTS INC.	382 QUEEN ST. E. BRAMPTON ON L6V 1C3	82.6	39
D & I SPORTS INC.	382 QUEEN ST. E. BRAMPTON ON L6V 1C3	82.6	39
Elmbrook Management	145 Queen Street East Suite 400 Brampton ON L6W 3P8	58.8	40
Dr Percy Segal	145 Queen St E #201 Brampton ON L6W 3P8	58.8	40
Elmbrook Management	145 Queen Street East Suite 400 Brampton ON L6W 3P8	58.8	40

Site	Address	Distance (m)	Map Key
Elmbrook Management	145 Queen Street East Suite 400 Brampton ON L6W 3P8	58.8	40
Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	84.3	43
Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	84.3	43
Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	84.3	43
Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	84.3	43
Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	84.3	43
Dr Emil Svoboda Dentistry Professional Corporation	110 Queen Street East Brampton ON L6V 1B1	84.3	43
Dr. Robert Sleightholm Professional Medicine Inc.	111 Queen Street East Unit 2-4 Brampton ON L6W2A9	95.7	44
Dr. Robert Sleightholm Professional Medicine Inc.	111 Queen Street East Unit 2-4 Brampton ON L6W2A9	95.7	44
Dr. Robert Sleightholm Professional Medicine Inc.	111 Queen Street East Unit 2-4 Brampton ON L6W2A9	95.7	44
Dr. Robert Sleightholm Professional Medicine Inc.	111 Queen Street East Unit 2-4 Brampton ON L6W2A9	95.7	44

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated 31 Oct, 2023 has found that there are 3 INC site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	263 QUEEN STREET EAST, BRAMPTON ON	72.2	17
	261 QUEEN STREET EAST, BRAMPTON ON	42.2	24
	Queen Street & Scott Street, Brampton ON	100.0	45

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 2 NPCB site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CANADA CUP INC	228 QUEEN STREET EAST BRAMPTON ON L7YA9	71.0	19
CANADA CUP INC	228 QUEEN ST E BRAMPTON ON L6V 1B8	71.0	19

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Apr 30, 2024 has found that there are 2 RST site(s) within approximately 0.10 kilometers of the project property.


Site	Address	Distance (m)	Map Key
PETRO CANADA	354 QUEEN ST E BRAMPTON ON L6V1C3	22.1	33
PETRO CANADA	354 QUEEN ST E BRAMPTON ON L6V 1C3	22.1	33

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 13 SCT site(s) within approximately 0.10 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Carvel Ice Cream	252 Queen St E Unit 6 Brampton ON L6V 1C1	71.0	9
Carvel Ice Cream Bakery	252 Queen St E Unit 6 Brampton ON L6V 1C1	71.0	9
LA ROMANA BAKERY INC.	284 QUEEN ST E UNIT 112 BRAMPTON ON L6V 1C2	81.9	10
Musclemag International	253 Queen St E Unit 23 Brampton ON L6W 2B8	73.7	11
123 Computer Warehouse Inc.	253 Queen St E Unit 2 Brampton ON L6W 2B8	73.7	11
Counterfitters of Ontario Inc.	255 Queen St E Unit 5 Brampton ON L6W 2B8	41.0	15
G. Print Ltd.	210 Queen St E Brampton ON L6V 1B7	42.4	25
ROYAL MATTRESS MFG CO	338 QUEEN ST E BRAMPTON ON L6V 1C4	59.8	30
Ipax Canada Ltd.	174 Queen St E Brampton ON L6V 1B3	53.8	32
BRAMPTON GALLERIES	173 QUEEN ST E BRAMPTON ON L6W 2B2	10.1	34
Waymar Manufacturing Co.	457-295 Queen St E Brampton ON L6W 3W9	63.7	41

Site	Address	Distance (m)	Map Key
Kronos Canada Inc.	295 Queen St E Suite 443 Brampton ON L6W 3W9	63.7	41
New Home Services Inc.	295 Queen St E Unit 6 Suite 464 Brampton ON L6W 3W9	63.7	41



Map: 0.1 Kilometer Radius

Order Number: 24062700011


Address: Queen St (Centre to 410), Brampton, ON

ERIS

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Aerial


Year: 2022

Order Number: 24062700011

Address: Queen St (Centre to 410), Brampton, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Order Number: 24062700011

Address: Queen St (Centre to 410), ON

Source: ESRI World Topographic Map

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 2	SE/70.9	219.8 / 0.00	Jakalo Investments 243 Queen Street EAst Brampton ON	GEN

Generator No: ON8931600
SIC Code: 484221
SIC Description: BULK LIQUIDS TRUCKING, LOCAL
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	2 of 2	SE/70.9	219.8 / 0.00	TORONTO CAR SALE AND AUTO SERVICE 243 QUEEN STREET EAST BRAMPTON ON	GEN

Generator No: ON2924467
SIC Code: 541990
SIC Description: ALL OTHER PROFESSIONAL, SCIENTIFIC AND TECHNICAL SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 1	NW/82.2	219.8 / 0.00	BRAMGATE VOLKSWAGEN BRAMPTON LTD. 268 QUEEN STREET EAST BRAMPTON ON L6V 1B9	GEN

Generator No: ON2075600
SIC Code: 6311
SIC Description: NEW AUTO DEALERS
Approval Years: 95,96,97,98,99,00,01
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	1 of 2	ESE/90.6	219.8 / 0.00	Heart and Stroke Foundation 245 Queen Street East Unit 2 Brampton ON L6W 2B5	GEN

Generator No: ON9511497
SIC Code: 621494
SIC Description: 621494
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	2 of 2	ESE/90.6	219.8 / 0.00	Rivlawn Holdings 245 Queen Street East Brampton ON L6W 2B5	GEN

Generator No: ON5490540
SIC Code: 531120
SIC Description: LESSORS OF NON-RESIDENTIAL BUILDINGS (EXCEPT MINI-WAREHOUSES)
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	1 of 6	N/58.3	219.8 / 0.00	PPG Architectural Coatings Canada, Inc. 272 Queen Street East Store 587 Brampton ON	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON9407003
SIC Code: 444120
SIC Description: Paint and Wallpaper Stores
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

---

4 | **2 of 6** | **N/58.3** | **219.8 / 0.00** | **PPG Architectural Coatings Canada, Inc.**
272 Queen Street East Store 587
Brampton ON | **GEN**

Generator No: ON9407003
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

4 | **3 of 6** | **N/58.3** | **219.8 / 0.00** | **PPG Architectural Coatings Canada, Inc.**
272 Queen Street East Store 587
Brampton ON L6V 1B9 | **GEN**

Generator No: ON9407003
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

4 | **4 of 6** | **N/58.3** | **219.8 / 0.00** | **PPG Architectural Coatings Canada, Inc.**
272 Queen Street East Store 587
Brampton ON L6V 1B9 | **GEN**

Generator No: ON9407003

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	5 of 6	N/58.3	219.8 / 0.00	PPG Architectural Coatings Canada, Inc. 272 Queen Street East Store 587 Brampton ON L6V 1B9	GEN

Generator No: ON9407003
SIC Code: 444120
SIC Description: PAINT AND WALLPAPER STORES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	6 of 6	N/58.3	219.8 / 0.00	PPG Architectural Coatings Canada, Inc. 272 Queen Street East Store 587 Brampton ON L6V 1B9	GEN

Generator No: ON9407003
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
5	1 of 1	ENE/25.7	218.8 / -1.00	Priestly Demolition Inc 247 Queen Street East Brampton ON L6W 2B5	GEN

Generator No: ON7406576
SIC Code: 238910
SIC Description: Site Preparation Contractors
Approval Years: 05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	1 of 1	N/57.5	219.1 / -0.70	PPG Architectural Coatings Canada, Inc. 280 Queen Street East Store 8405 587 Brampton ON L6V 1B9	GEN

Generator No: ON9407003
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 145 H
Waste Class Name: Wastes from the use of pigments, coatings and paints

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
7	1 of 4	SSE/93.3	219.8 / 0.00	JOHN LOGAN CHEV-OLDS 241 QUEEN STREET EAST BRAMPTON ON L6W 2B5	GEN

Generator No: ON2016100
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)
Approval Years: 95,96,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

7 **2 of 4** **SSE/93.3** **219.8 / 0.00** **JOHN LOGAN CHEVROLET OLDS INC** **DTNK**
241 QUEEN ST E
BRAMPTON ON

Delisted Expired Fuel Safety Facilities

Instance No: 9431548
Status: EXPIRED
Instance ID: 387154
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: Fuels Safety Private Fuel Outlet - Self Serve
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

7 **3 of 4** **SSE/93.3** **219.8 / 0.00** **JOHN LOGAN CHEVROLET OLDS INC** **DTNK**
241 QUEEN ST E
BRAMPTON ON

Delisted Expired Fuel Safety Facilities

Instance No: 10600163
Status: EXPIRED
Instance ID: 30621
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:

Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

7 | ***4 of 4*** | ***SSE/93.3*** | ***219.8 / 0.00*** | ***JOHN LOGAN CHEVROLET OLDS INC***
241 QUEEN ST E
BRAMPTON ON | ***EXP***

Inventory No: 10600136
Inventory Status: EXPIRED
Installation Year: 1984
Capacity: 13638
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: UNDERGROUND TANK
AS PER E084124
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Impressed Current
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

8 | ***1 of 9*** | ***S/100.0*** | ***219.8 / 0.00*** | ***Dr.Mujeeb S. Qazi Dentistry Professional Corporati***
239 QUEEN STREET UNIT 9
BRAMPTON ON L6W2B6 | ***GEN***

Generator No: ON4034840
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: JONES SHERYL
Choice of Contact: CO_ADMIN
Phone No Admin: 9054578661 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	2 of 9	S/100.0	219.8 / 0.00	Dr.Mujeeb S. Qazi Dentistry Professional Corporati 239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	GEN

Generator No: ON4034840
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: JONES SHERYL
Choice of Contact: CO_ADMIN
Phone No Admin: 9054578661 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	3 of 9	S/100.0	219.8 / 0.00	Dr.Mujeeb S. Qazi Dentistry Professional Corporati 239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	GEN

Generator No: ON4034840
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: JONES SHERYL
Choice of Contact: CO_ADMIN
Phone No Admin: 9054578661 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	4 of 9	S/100.0	219.8 / 0.00	Dr.Mujeeb S. Qazi Dentistry Professional Corporati 239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON4034840
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	5 of 9	S/100.0	219.8 / 0.00	Dr.Mujeeb S. Qazi Dentistry Professional Corporati 239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	GEN

Generator No: ON4034840
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	6 of 9	S/100.0	219.8 / 0.00	Dr.Mujeeb S. Qazi Dentistry Professional Corporati 239 QUEEN STREET UNIT 9 BRAMPTON ON L6W2B6	GEN

Generator No: ON4034840
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 264 T
Waste Class Name: Photoprocessing wastes

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	7 of 9	S/100.0	219.8 / 0.00	**FH Health** **239 Queen St. East** **Brampton ON L6V1C2**	GEN

Generator No: ON4175734
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	8 of 9	S/100.0	219.8 / 0.00	**FH Health Inc.** **239 Queen Street East, Unit 24** **Brampton ON L6V1C2**	GEN

Generator No: ON5501680
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 B
Waste Class Name: Misc. waste organic chemicals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
8	9 of 9	S/100.0	219.8 / 0.00	FH Health Inc. 239 Queen Street East, Unit 24 Brampton ON L6V1C2	GEN

Generator No: ON5501680
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 263 B
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	1 of 13	WSW/71.0	221.8 / 1.93	CANADIAN TIRE PETROLEUM 252 QUEEN STREET EAST BRAMPTON ON L6V 1C1	GEN

Generator No: ON0049619
SIC Code: 6331
SIC Description: GASOLINE SERV. ST.
Approval Years: 94,95,96,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	2 of 13	WSW/71.0	221.8 / 1.93	Carvel Ice Cream Bakery 252 Queen St E Unit 6 Brampton ON L6V 1C1	SCT

Established: 1988
Plant Size (ft²):
Employment: 6

--Details--
Description: Ice Cream and Frozen Dessert Manufacturing
SIC/NAICS Code: 311520

Description: Commercial Bakeries and Frozen Bakery Product Manufacturing
SIC/NAICS Code: 311814

Description: Cookie and Cracker Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
SIC/NAICS Code:		311821			

9	3 of 13	WSW/71.0	221.8 / 1.93	Carvel Ice Cream 252 Queen St E Unit 6 Brampton ON L6V 1C1	SCT

Established: 1988
Plant Size (ft²): 1000
Employment: 6

--Details--
Description: Ice Cream and Frozen Dessert Manufacturing
SIC/NAICS Code: 311520

Description: Cookie and Cracker Manufacturing
SIC/NAICS Code: 311821

9	4 of 13	WSW/71.0	221.8 / 1.93	CANADIAN TIRE CORP LTD C/O Canadian Tire Petroleum 17 Flr** 252 QUEEN ST E BRAMPTON ON L6V 1C1	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	9467155	**Expired Date:**	7/17/1993
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:		**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:			
Original Source:	EXP		
Record Date:	Up to May 2013		

9	5 of 13	WSW/71.0	221.8 / 1.93	CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E BRAMPTON ON	EXP

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory No:	10600263	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Fiberglass
Installation Year:	1992	**Overfill Protection:**	
Capacity:	31822	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	LICENCED UNDERGROUND TANKS		
Previous Fuel Type:	Gasoline		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	6 of 13	WSW/71.0	221.8 / 1.93	CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E BRAMPTON ON	EXP

Inventory No:	10600268	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Fiberglass
Installation Year:	1992	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	LICENCED UNDERGROUND TANKS		
Previous Fuel Type:	Gasoline		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	7 of 13	WSW/71.0	221.8 / 1.93	CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E BRAMPTON ON	EXP

Inventory No:	10600275	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Fiberglass
Installation Year:	1992	**Overfill Protection:**	
Capacity:	22730	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	LICENCED UNDERGROUND TANKS		
Previous Fuel Type:	Gasoline		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	8 of 13	WSW/71.0	221.8 / 1.93	CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E BRAMPTON ON	EXP

Inventory No:	10600287	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Coating
Installation Year:	NULL	**Overfill Protection:**	
Capacity:	4546	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	LICENCED UNDERGROUND TANKS		
Previous Fuel Type:	Other		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	9 of 13	WSW/71.0	221.8 / 1.93	CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E BRAMPTON ON	EXP

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory No: 10600238
Inventory Status: EXPIRED
Installation Year: 1992
Capacity: 31822
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: LICENCED UNDERGROUND TANKS
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

9 | ***10 of 13*** | ***WSW/71.0*** | ***221.8 / 1.93*** | ***CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E BRAMPTON ON*** | ***EXP***

Inventory No: 10600214
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 0
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:
Previous Fuel Type: Gasoline

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

9 | ***11 of 13*** | ***WSW/71.0*** | ***221.8 / 1.93*** | ***CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E BRAMPTON ON*** | ***EXP***

Inventory No: 10600295
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 4546
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: LICENCED UNDERGROUND TANKS
Previous Fuel Type: Other

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

9 | ***12 of 13*** | ***WSW/71.0*** | ***221.8 / 1.93*** | ***CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E BRAMPTON ON*** | ***EXP***

Inventory No: 10600280
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 4546
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: LICENCED UNDERGROUND TANKS
Previous Fuel Type: Other

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

9 | ***13 of 13*** | ***WSW/71.0*** | ***221.8 / 1.93*** | ***CANADIAN TIRE CORPORATION LIMITED 252 QUEEN ST E*** | ***EXP***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON	

Inventory No: 10600302
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 4546
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: LICENCED UNDERGROUND TANKS
Previous Fuel Type: Other

Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

10 | **1 of 20** | **NNE/81.9** | **218.9 / -0.99** | **LA ROMANA BAKERY INC.**
284 QUEEN ST E UNIT 112
BRAMPTON ON L6V 1C2 | **SCT**

Established: 1972
Plant Size (ft²): 3800
Employment: 7

--Details--
Description: BREAD AND OTHER BAKERY PRODUCTS, EXCEPT COOKIES AND CRACKERS
SIC/NAICS Code: 2051

Description: COOKIES AND CRACKERS
SIC/NAICS Code: 2052

Description: GROCERIES & RELATED PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 5149

---

10 | **2 of 20** | **NNE/81.9** | **218.9 / -0.99** | **EMDI Holdings Inc.**
284 Queen St. East, Unit 236
Brampton ON L6V 1C2 | **GEN**

Generator No: ON8681150
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

10 | **3 of 20** | **NNE/81.9** | **218.9 / -0.99** | **EMDI Holdings Inc.**
284 Queen St. East, Unit 236
Brampton ON L6V 1C2 | **GEN**

Generator No: ON8681150
SIC Code: 621110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: Offices of Physicians
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

10 | ***4 of 20*** | ***NNE/81.9*** | ***218.9 / -0.99*** | ***EMDI Holdings Inc.***
284 Queen St. East, Unit 236
Brampton ON L6V 1C2 | ***GEN***

Generator No: ON8681150
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

10 | ***5 of 20*** | ***NNE/81.9*** | ***218.9 / -0.99*** | ***Dr. Young Pak Dentistry Profession***
284 Queen Street East Suite 206
Brampton ON L6V 1C2 | ***GEN***

Generator No: ON8185347
SIC Code: 621210
SIC Description: Offices of Dentists
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

10 | **6 of 20** | **NNE/81.9** | **218.9 / -0.99** | **EMDI Holdings Inc.**
284 Queen St. East, Unit 236
Brampton ON L6V 1C2 | **GEN**

Generator No: ON8681150
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

10 | **7 of 20** | **NNE/81.9** | **218.9 / -0.99** | **Dr. Young Pak Dentistry Profession**
284 Queen Street East
Brampton ON L6V 1C2 | **GEN**

Generator No: ON4030548
SIC Code: 621390
SIC Description: OFFICES OF ALL OTHER HEALTH PRACTITIONERS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Susy Grillo
Choice of Contact: CO_ADMIN
Phone No Admin: 905-456-0827 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

10 | **8 of 20** | **NNE/81.9** | **218.9 / -0.99** | **Dr. Young Pak Dentistry Profession**
284 Queen Street East
Brampton ON L6V 1C2 | **GEN**

Generator No: ON4030548
SIC Code: 621390
SIC Description: OFFICES OF ALL OTHER HEALTH PRACTITIONERS
Approval Years: 2015

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country: Canada
Status:
Co Admin: Susy Grillo
Choice of Contact: CO_ADMIN
Phone No Admin: 905-456-0827 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

---

10 | ***9 of 20*** | ***NNE/81.9*** | ***218.9 / -0.99*** | ***Dr Shane A Hunt***
284 Queen St. E. Suite 120
Brampton ON L6V 1C2 | ***GEN***

Generator No: ON8929211
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

10 | ***10 of 20*** | ***NNE/81.9*** | ***218.9 / -0.99*** | ***Dr Shane A Hunt***
284 Queen St. E. Suite 120
Brampton ON L6V 1C2 | ***GEN***

Generator No: ON8929211
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		PATHOLOGICAL WASTES			
10	11 of 20	NNE/81.9	218.9 / -0.99	**Dr. Young Pak Dentistry Profession** **284 Queen Street East** **Brampton ON L6V 1C2**	GEN
Generator No:		ON4030548			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2018			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		264 L			
Waste Class Name:		Photoprocessing wastes			
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
10	12 of 20	NNE/81.9	218.9 / -0.99	**Dr Shane A Hunt** **284 Queen St. E. Suite 120** **Brampton ON L6V 1C2**	GEN
Generator No:		ON8929211			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2018			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
10	13 of 20	NNE/81.9	218.9 / -0.99	**Dr. Young Pak Dentistry Profession** **284 Queen Street East** **Brampton ON L6V 1C2**	GEN
Generator No:		ON4030548			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

---

10 | ***14 of 20*** | ***NNE/81.9*** | ***218.9 / -0.99*** | ***Dr Shane A Hunt*** ***284 Queen St. E. Suite 120*** ***Brampton ON L6V 1C2*** | ***GEN***

Generator No: ON8929211
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

10 | ***15 of 20*** | ***NNE/81.9*** | ***218.9 / -0.99*** | ***Dr. Nikita Khurana Dentistry Professional Corp*** ***284 Queen St. E. Suite 120*** ***Brampton ON L6V 1C2*** | ***GEN***

Generator No: ON8929211
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

10 | ***16 of 20*** | ***NNE/81.9*** | ***218.9 / -0.99*** | ***Dr. Young Pak Dentistry Profession*** ***284 Queen Street East*** ***Brampton ON L6V 1C2*** | ***GEN***

Generator No: ON4030548

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264 L
Waste Class Name: Photoprocessing wastes

Waste Class: 312 P
Waste Class Name: Pathological wastes

10	17 of 20	NNE/81.9	218.9 / -0.99	***1938370 Ontario Inc.*** ***116-284 Queen Street East*** ***Brampton ON L6V1C2***	***GEN***

Generator No: ON7110306
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

10	18 of 20	NNE/81.9	218.9 / -0.99	***Dr. Young Pak Dentistry Profession*** ***284 Queen Street East*** ***Brampton ON L6V 1C2***	***GEN***

Generator No: ON4030548
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 264 L
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	19 of 20	NNE/81.9	218.9 / -0.99	1938370 Ontario Inc. 116-284 Queen Street East Brampton ON L6V1C2	GEN

Generator No: ON7110306
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	20 of 20	NNE/81.9	218.9 / -0.99	Dr. Nikita Khurana Dentistry Professional Corp 284 Queen St. E. Suite 120 Brampton ON L6V 1C2	GEN

Generator No: ON8929211
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	1 of 15	ENE/73.7	217.8 / -2.00	123 Computer Warehouse Inc. 253 Queen St E Unit 2 Brampton ON L6W 2B8	SCT

Established: 01-SEP-86
Plant Size (ft²): 1500
Employment:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: Electronic and Precision Equipment Repair and Maintenance
SIC/NAICS Code: 811210

Description: Computer Systems Design and Related Services
SIC/NAICS Code: 541510

Description: Computer, Computer Peripheral and Pre-Packaged Software Wholesaler-Distributors
SIC/NAICS Code: 417310

Description: Computer, Computer Peripheral and Pre-Packaged Software Wholesaler-Distributors
SIC/NAICS Code: 417310

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	2 of 15	ENE/73.7	217.8 / -2.00	**Musclemag International** **253 Queen St E Unit 23** **Brampton ON L6W 2B8**	SCT

Established:
Plant Size (ft²):
Employment: 5

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	3 of 15	ENE/73.7	217.8 / -2.00	**SHELLER-GLOBE OF CANADA LTD.** **253 QUEEN ST. E.** **BRAMPTON ON L6W 2B8**	GEN

Generator No: ON0158200
SIC Code: 0000
SIC Description: *** NOT DEFINED ***
Approval Years: 86,87,88,89,90,92,93,94
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	4 of 15	ENE/73.7	217.8 / -2.00	**Sears Canada Inc.** **253 Queen Street e** **Brampton ON L6W 2B8**	GEN

Generator No: ON9442409
SIC Code: 443110
SIC Description: Appliance Television and Other Electronics Stores
Approval Years: 04,05
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 148
Waste Class Name: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Name: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Name: PAINT/PIGMENT/COATING RESIDUES

---

11 ***5 of 15*** ***ENE/73.7*** ***217.8 / -2.00*** ***Homedale-Eagle Corporation***
253 Queen Street East
Brampton ON L6W 2B8 ***GEN***

Generator No: ON5877869
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 06
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

11 ***6 of 15*** ***ENE/73.7*** ***217.8 / -2.00*** ***Homedale-Eagle Corporation***
253 Queen Street East
Brampton ON L6W 2B8 ***GEN***

Generator No: ON5877869
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

11 ***7 of 15*** ***ENE/73.7*** ***217.8 / -2.00*** ***Homedale-Eagle Corporation***
253 Queen Street East
Brampton ON L6W 2B8 ***GEN***

Generator No: ON5877869
SIC Code: 531310

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: Real Estate Property Managers
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

11 | ***8 of 15*** | ***ENE/73.7*** | ***217.8 / -2.00*** | ***Homedale-Eagle Corporation***
253 Queen Street East
Brampton ON L6W 2B8 | ***GEN***

Generator No: ON5877869
SIC Code: 531310
SIC Description: Real Estate Property Managers
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

11 | ***9 of 15*** | ***ENE/73.7*** | ***217.8 / -2.00*** | ***Homedale-Eagle Corporation***
253 Queen Street East
Brampton ON | ***GEN***

Generator No: ON5877869
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	10 of 15	ENE/73.7	217.8 / -2.00	Homedale-Eagle Corporation 253 Queen Street East Brampton ON L6W 2B8	GEN

Generator No: ON5877869
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Rob Hoag
Choice of Contact: CO_ADMIN
Phone No Admin: 519-804-7408 Ext.301
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	11 of 15	ENE/73.7	217.8 / -2.00	Homedale-Eagle Corporation 253 Queen Street East Brampton ON L6W 2B8	GEN

Generator No: ON5877869
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Rob Hoag
Choice of Contact: CO_ADMIN
Phone No Admin: 519-804-7408 Ext.301
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	12 of 15	ENE/73.7	217.8 / -2.00	Homedale-Eagle Corporation 253 Queen Street East Brampton ON L6W 2B8	GEN

Generator No: ON5877869
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		241			
Waste Class Name:		HALOGENATED SOLVENTS			
11	13 of 15	ENE/73.7	217.8 / -2.00	253 Queen Street Inc. 253 Queen Street East Brampton ON L6W 2B8	GEN
Generator No:		ON5877869			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2018			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		146 L			
Waste Class Name:		Other specified inorganic sludges, slurries or solids			
Waste Class:		241 T			
Waste Class Name:		Halogenated solvents and residues			
11	14 of 15	ENE/73.7	217.8 / -2.00	253 Queen Street Inc. 253 Queen Street East Brampton ON L6W 2B8	GEN
Generator No:		ON5877869			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		146 L			
Waste Class Name:		Other specified inorganic sludges, slurries or solids			
Waste Class:		241 T			
Waste Class Name:		Halogenated solvents and residues			
11	15 of 15	ENE/73.7	217.8 / -2.00	253 Queen Street Inc. 253 Queen Street East Brampton ON L6W 2B8	GEN
Generator No:		ON5877869			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Waste Class: 241 T
Waste Class Name: Halogenated solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	1 of 11	SW/52.9	220.9 / 1.04	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	2 of 11	SW/52.9	220.9 / 1.04	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	3 of 11	SW/52.9	220.9 / 1.04	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: Offices of Physicians, Medical and Diagnostic Laboratories
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	4 of 11	SW/52.9	220.9 / 1.04	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON	GEN

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	5 of 11	SW/52.9	220.9 / 1.04	AIM Health Group LTD 2 Kennedy Rd S, unit 2 Brampton ON L6W 3E1	GEN

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

12 **6 of 11** **SW/52.9** **220.9 / 1.04** **AIM Health Group LTD**
2 Kennedy Rd S, unit 2
Brampton ON L6W 3E1 **GEN**

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

12 **7 of 11** **SW/52.9** **220.9 / 1.04** **AIM Health Group LTD**
2 Kennedy Rd S, unit 2
Brampton ON L6W 3E1 **GEN**

Generator No: ON7809968
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

12 **8 of 11** **SW/52.9** **220.9 / 1.04** **i6 Building Corp**
2 Kennedy Road South
Brampton ON L6W 3E1 **GEN**

Generator No: ON8407811
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	9 of 11	SW/52.9	220.9 / 1.04	i6 Building Corp 2 Kennedy Road South Unit4A Brampton ON L6W 3E1	GEN

Generator No: ON8407811
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	10 of 11	SW/52.9	220.9 / 1.04	i6 Building Corp 2 Kennedy Road South Unit4A Brampton ON L6W 3E1	GEN

Generator No: ON8407811
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	11 of 11	SW/52.9	220.9 / 1.04	i6 Building Corp 2 Kennedy Road South Unit4A Brampton ON L6W 3E1	GEN

Generator No: ON8407811
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	1 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH LINES LTD. 10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 86,87,88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	2 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH LINES LTD. 10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	3 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH LINES LTD. 30-262 10 KENNEDY ROAD, NORTH BRAMPTON ON L6V 1X4	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON0823600
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

13 ***4 of 21*** ***WSW/87.1*** ***222.4 / 2.57*** ***PARKINSON COACH LINES LTD.***
10 KENNEDY ROAD NORTH
BRAMPTON ON L6V 1X4 ***GEN***

Generator No: ON0823600
SIC Code: 4573
SIC Description: SCHOOL BUS OPER.
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

13 ***5 of 21*** ***WSW/87.1*** ***222.4 / 2.57*** ***PARKINSON COACH LINES 2000 INC.***
10 KENNEDY ROAD NORTH
BRAMPTON ON L6V 1X4 ***GEN***

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: 02,03,04,05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	6 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH LINES GEORGE MURRAY 10 KENNEDY RD N BRAMPTON ON L6V 1X4	FSTH

License Issue Date: 4/22/1991
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1982
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	7 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH LINES GEORGE MURRAY 10 KENNEDY RD N BRAMPTON ON L6V 1X4	FSTH

License Issue Date: 4/22/1991
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1982
Corrosion Protection:
Capacity: 22730
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	8 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH LINES 2000 INC. 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 485410
SIC Description: School and Employee Bus Transportation
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	9 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH LINES 2000 INC. 10 Kennedy Road North	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON L6V 1X4	

Generator No: ON0823600
SIC Code: 485410
SIC Description: School and Employee Bus Transportation
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

13	10 of 21	WSW/87.1	222.4 / 2.57	**PARKINSON COACH & TOURS LTD.** **10 Kennedy Road North** **Brampton ON L6V 1X4**	GEN

Generator No: ON0823600
SIC Code: 485410
SIC Description: School and Employee Bus Transportation
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

13	11 of 21	WSW/87.1	222.4 / 2.57	**PARKINSON COACH & TOURS LTD.** **10 Kennedy Road North** **Brampton ON L6V 1X4**	GEN

Generator No: ON0823600
SIC Code: 485410
SIC Description: School and Employee Bus Transportation
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
13	12 of 21	WSW/87.1	222.4 / 2.57	**PARKINSON COACH & TOURS LTD.** **10 Kennedy Road North** **Brampton ON**	GEN
Generator No:		ON0823600			
SIC Code:		485410			
SIC Description:					
Approval Years:		2013			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
13	13 of 21	WSW/87.1	222.4 / 2.57	**PARKINSON COACH & TOURS LTD.** **10 Kennedy Road North** **Brampton ON L6V 1X4**	GEN
Generator No:		ON0823600			
SIC Code:		485410			
SIC Description:		485410			
Approval Years:		2016			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:		Lynn Matthews			
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:		905-451-4776 Ext.236			
Contaminated Facility:		No			
MHSW Facility:		No			
Detail(s)					
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
Waste Class:		212			
Waste Class Name:		ALIPHATIC SOLVENTS			
13	14 of 21	WSW/87.1	222.4 / 2.57	**PARKINSON COACH & TOURS LTD.** **10 Kennedy Road North** **Brampton ON L6V 1X4**	GEN
Generator No:		ON0823600			
SIC Code:		485410			
SIC Description:		485410			
Approval Years:		2015			
PO Box No:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status:
Co Admin: Lynn Matthews
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-451-4776 Ext.236
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	15 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH & TOURS LTD. 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code: 485410
SIC Description: 485410
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Lynn Matthews
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-451-4776 Ext.236
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	16 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH & TOURS LTD. 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	17 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH & TOURS LTD. 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 I
Waste Class Name: Light fuels

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	18 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH & TOURS LTD. 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252 L
Waste Class Name: Waste crankcase oils and lubricants

Waste Class: 212 L
Waste Class Name: Aliphatic solvents and residues

Waste Class: 221 I
Waste Class Name: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	19 of 21	WSW/87.1	222.4 / 2.57	Parkinson Coach 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON4707497
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 L
Waste Class Name: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	20 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH & TOURS LTD. 10 Kennedy Road North Brampton ON L6V 1X4	GEN

Generator No: ON0823600
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221 I
Waste Class Name: LIGHT FUELS

Waste Class: 212 L
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 252 L
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	21 of 21	WSW/87.1	222.4 / 2.57	PARKINSON COACH LINES GEORGE MURRAY 10 KENNEDY RD N BRAMPTON ON	EXP

Inventory No: 10596490
Inventory Status: EXPIRED
Installation Year:
Capacity:
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: UNDERGROUND TANK
Previous Fuel Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	1 of 2	NE/59.3	218.9 / -0.91	COLONY LINCOLN MERCURY SALES LTD. 300 QUEEN STREET EAST BRAMPTON ON L6V 1C2	GEN

Generator No: ON2044800
SIC Code: 6311
SIC Description: NEW AUTO DEALERS
Approval Years: 95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
14	2 of 2	NE/59.3	218.9 / -0.91	COLONY LINCOLN MERCURY SALES LTD 300 QUEEN ST E BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9621534
Status: EXPIRED
Instance ID: 384860
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Propane Vehicle Conv Centre
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	1 of 4	NE/41.0	217.8 / -2.00	Counterfitters of Ontario Inc. 255 Queen St E Unit 5 Brampton ON L6W 2B8	SCT

Established: 1988
Plant Size (ft²):
Employment: 8

--Details--
Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code: 327990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	2 of 4	NE/41.0	217.8 / -2.00	AMSCO CANADA LIMITED 255 QUEEN ST. E. BRAMPTON ON L6W 2B8	GEN

Generator No: ON0026100
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND.
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
15	3 of 4	NE/41.0	217.8 / -2.00	AMSCO CANADA LIMITED 01-203 255 QUEEN ST. E. BRAMPTON ON L6W 2B8	GEN

Generator No: ON0026100
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND
Approval Years: 92,93,94,95,96,97
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

15 | ***4 of 4*** | ***NE/41.0*** | ***217.8 / -2.00*** | ***AMSCO CANADA LIMITED***
255 QUEEN STREET EAST
BRAMPTON ON L6W 2B8 | ***GEN***

Generator No: ON0026100
SIC Code: 3099
SIC Description: OTHER METAL FAB. IND.
Approval Years: 98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 113
Waste Class Name: ACID WASTE - OTHER METALS

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

Waste Class: 253
Waste Class Name: EMULSIFIED OILS

Waste Class: 331
Waste Class Name: WASTE COMPRESSED GASES

---

16 | ***1 of 1*** | ***NE/57.0*** | ***219.6 / -0.27*** | ***United Investments - 1898692 Ontario Inc***
310 Queen Street East
Brampton ON L6V 1C2 | ***GEN***

Generator No: ON6998560
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

MHSW Facility:

Detail(s)

Waste Class: 251 L
Waste Class Name: Waste oils/sludges (petroleum based)

---

17 ***1 of 2*** ***ENE/72.2*** ***217.8 / -2.00*** ***263 QUEEN STREET EAST, BRAMPTON ON*** ***INC***

Incident No:	1559876	***Any Health Impact:***	No
Incident ID:		***Any Enviro Impact:***	No
Instance No:		***Service Intrp:***	Yes
Status Code:		***Was Prop Damaged:***	No
Incident Status:		***Reside App. Type:***	
Incident Severity:		***Commer App. Type:***	
Task No:	5333228	***Indus App. Type:***	
Attribute Category:	FS-Perform L1 Incident Insp	***Institut App. Type:***	
Context:		***Depth Ground Cover:***	
Date of Occurrence:	2015/01/20 00:00:00	***Operation Pressure:***	
Time of Occurrence:	17:39:00	***Equipment Type:***	
Occr Insp Start Dt:	2015/01/22 00:00:00	***Equipment Model:***	
Incident Creat On:		***Serial No:***	
Instance Creat Dt:		***Cylinder Capacity:***	
Instance Install Dt:		***Cylinder Cap Units:***	
Approx Quant Rel:		***Cylinder Mat Type:***	
Tank Capacity:		***Pump Flow Rate Cap:***	
Fuels Occur Type:	CO Release	***Contam. Migrated:***	
Occur Type Rpt:		***Near Body of Water:***	
Occur Category:		***Drainage System:***	
Fuel Type Involved:	Natural Gas	***Sub Surface Contam:***	
Fuel Type Reported:		***Tank Material Type:***	
Enforcement Policy:	NULL	***Tank Storage Type:***	
Prc Escalation Req:	NULL	***Tank Location Type:***	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:			
Pipeline Involved:			
Pipe Material:			
Regulator Location:			
Regulator Type:			
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	263 QUEEN STREET EAST, BRAMPTON - CO RELEASE		
Invent Postal Code:			
Notes:			
Contact Natural Env:			
Aff Prop Use Water:			
Occurence Narrative:	Water heater installed in an unconditioned space		
Operation Type Involved:	Commercial (e.g. restaurant, business unit, etc)		

---

17 ***2 of 2*** ***ENE/72.2*** ***217.8 / -2.00*** ***Bayer Inc.***
Queens Center Plaza 263 Queen Street East
Brampton ON L6W 4K6 ***GEN***

Generator No: ON6299750

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code:	414510
SIC Description:	PHARMACEUTICALS AND PHARMACY SUPPLIES WHOLESALER-DISTRIBUTORS
Approval Years:	2014
PO Box No:	
Country:	Canada
Status:	
Co Admin:	Grace Wong
Choice of Contact:	CO_ADMIN
Phone No Admin:	905-282-5301 Ext.
Contaminated Facility:	No
MHSW Facility:	No

Detail(s)

Waste Class:	122
Waste Class Name:	ALKALINE WASTES - OTHER METALS

18	*1 of 3*	*SW/56.6*	*222.8 / 2.95*	***SHELL CANADA PRODUCTS** 230 QUEEN ST E BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10072729	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	11486	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	Fuels Safety Private Fuel Outlet - Self Serve		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

18	*2 of 3*	*SW/56.6*	*222.8 / 2.95*	***SHELL CANADA PRODUCTS 230 QUEEN ST E BRAMPTON ON***	***EXP***

Inventory No:	11247028	**Tank Material:**	Steel
Inventory Status:	EXPIRED	**Corrosion Protect:**	Coating
Installation Year:	NULL	**Overfill Protection:**	
Capacity:	4500	**Inventory Context:**	FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: WASTE OIL
Previous Fuel Type: Other
Inventory Item: FS LIQUID FUEL TANK

---

18 | ***3 of 3*** | ***SW/56.6*** | ***222.8 / 2.95*** | ***SHELL CANADA PRODUCTS***
230 QUEEN ST E
BRAMPTON ON | ***EXP***

Inventory No: 11247006
Inventory Status: EXPIRED
Installation Year: NULL
Capacity: 4500
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: BULK OIL
Previous Fuel Type: Other
Tank Material: Steel
Corrosion Protect: Coating
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

19 | ***1 of 2*** | ***WSW/71.0*** | ***222.9 / 3.08*** | ***CANADA CUP INC***
228 QUEEN STREET EAST
BRAMPTON ON L7YA9 | ***NPCB***

Company Code: F1119
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code: Unknown concentration
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 800.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 1200.00 KG

Label:
Serial No.:
PCB Type/Code: Unknown concentration
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal

Contents: 3319.00 KG

Label:
Serial No.:
PCB Type/Code: Askarel
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 6336.00 KG

Label:
Serial No.:
PCB Type/Code: Low 50 - 10,000 ppm
Location:
Item/State:
No. of Items:
Manufacturer:
Status: Stored for Disposal
Contents: 6800.00 KG

19	2 of 2	WSW/71.0	222.9 / 3.08	CANADA CUP INC 228 QUEEN ST E BRAMPTON ON L6V 1B8	NPCB

Company Code: F1025
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

20	1 of 6	NE/37.9	219.4 / -0.47	Viable Healthworks 312 Queen Street East Brampton ON L6V 1C2	GEN

Generator No: ON7419260
SIC Code: 621110, 621510
SIC Description: OFFICES OF PHYSICIANS, MEDICAL AND DIAGNOSTIC LABORATORIES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Olga Plesko
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-906-7640 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

20	2 of 6	NE/37.9	219.4 / -0.47	AIM Health Group 312 Queen St E Brampton ON L6V 1C2	GEN

Generator No: ON3438322
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

20	*3 of 6*	*NE/37.9*	*219.4 / -0.47*	***Viable Healthworks*** ***312 Queen Street East*** ***Brampton ON L6V 1C2***	***GEN***

Generator No: ON7419260
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

20	*4 of 6*	*NE/37.9*	*219.4 / -0.47*	***Viable Healthworks*** ***312 Queen Street East*** ***Brampton ON L6V 1C2***	***GEN***

Generator No: ON7419260
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

20	*5 of 6*	*NE/37.9*	*219.4 / -0.47*	***Viable Healthworks*** ***312 Queen Street East***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				Brampton ON L6V 1C2	

Generator No: ON7419260
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

20	6 of 6	NE/37.9	219.4 / -0.47	**NeuPath Health** **312 Queen Street East** **Brampton ON L6V 1C2**	GEN

Generator No: ON7419260
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

21	1 of 19	SW/74.7	221.9 / 2.09	**Astra Fertility Group-Brampton** **1 Kennedy Road** **Brampton ON L6W 3C9**	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: Family Planning Centres
Approval Years: 05,06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			

21	2 of 19	SW/74.7	221.9 / 2.09	2931621 CANADA INC O/A CANADIAN TIRE 1 KENNEDY RD S BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10271843	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	14973	**Facility Location:**	
Instance Type:	FS Facility	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Cylinder Exchange		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

21	3 of 19	SW/74.7	221.9 / 2.09	Astra Fertility Group-Brampton 1 Kennedy Road Brampton ON	GEN

Generator No:	ON7914316
SIC Code:	621410
SIC Description:	Family Planning Centres
Approval Years:	2009
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	4 of 19	SW/74.7	221.9 / 2.09	Astra Fertility Group-Brampton 1 Kennedy Road Brampton ON	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: Family Planning Centres
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	5 of 19	SW/74.7	221.9 / 2.09	Astra Fertility Group-Brampton 1 Kennedy Road Brampton ON	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: Family Planning Centres
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	6 of 19	SW/74.7	221.9 / 2.09	Astra Fertility Group-Brampton 1 Kennedy Road Brampton ON L6W 3C9	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: Family Planning Centres
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	7 of 19	SW/74.7	221.9 / 2.09	**Astra Fertility Group-Brampton** **1 Kennedy Road** **Brampton ON**	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description:
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	8 of 19	SW/74.7	221.9 / 2.09	**Dr Essam Michael Medicine Professional Corporation** **1 Kennedy Road** **Brampton ON L6W 3C9**	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: 621410
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	9 of 19	SW/74.7	221.9 / 2.09	**Domenic Romano Pharmacy Inc.** **1 KENNEDY ROAD SOUTH** **Brampton ON L6W 3C9**	GEN

Generator No: ON9475030
SIC Code: 446110
SIC Description: 446110
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Nastran Najafi-Fard

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact: CO_ADMIN
Phone No Admin: 416-493-1220 Ext.3218
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

21	10 of 19	SW/74.7	221.9 / 2.09	**Astra Fertility Group-Brampton** **1 Kennedy Road** **Brampton ON L6W 3C9**	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: 621410
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

21	11 of 19	SW/74.7	221.9 / 2.09	**Domenic Romano Pharmacy Inc.** **1 KENNEDY ROAD SOUTH** **Brampton ON L6W 3C9**	GEN

Generator No: ON9475030
SIC Code: 446110
SIC Description: 446110
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Nastran Najafi-Fard
Choice of Contact: CO_ADMIN
Phone No Admin: 416-493-1220 Ext.3218
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	12 of 19	SW/74.7	221.9 / 2.09	Astra Fertility Group-Brampton 1 Kennedy Road Brampton ON L6W 3C9	GEN

Generator No: ON7914316
SIC Code: 621410
SIC Description: 621410
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	13 of 19	SW/74.7	221.9 / 2.09	Domenic Romano Pharmacy Inc. 1 KENNEDY ROAD SOUTH Brampton ON L6W 3C9	GEN

Generator No: ON9475030
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	14 of 19	SW/74.7	221.9 / 2.09	Dr Essam Michael Medicine Professional Corporation 1 Kennedy Road Brampton ON L6W 3C9	GEN

Generator No: ON7914316
SIC Code:
SIC Description:
Approval Years: As of Dec 2017
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

21 | ***15 of 19*** | ***SW/74.7*** | ***221.9 / 2.09*** | ***Domenic Romano Pharmacy Inc.***
1 KENNEDY ROAD SOUTH
Brampton ON L6W 3C9 | ***GEN***

Generator No: ON9475030
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

---

21 | ***16 of 19*** | ***SW/74.7*** | ***221.9 / 2.09*** | ***Domenic Romano Pharmacy Inc.***
1 KENNEDY ROAD SOUTH
Brampton ON L6W 3C9 | ***GEN***

Generator No: ON9475030
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

---

21 | ***17 of 19*** | ***SW/74.7*** | ***221.9 / 2.09*** | ***Loblaw Companies Limited - Shoppers Drug Mart***
1 Kennedy Rd S
Brampton ON L6W 3C9 | ***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON2867886
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

21	18 of 19	SW/74.7	221.9 / 2.09	**Domenic Romano Pharmacy Inc.** **1 KENNEDY ROAD SOUTH** **Brampton ON L6W 3C9**	GEN

Generator No: ON9475030
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

21	19 of 19	SW/74.7	221.9 / 2.09	**Athletes Care Brampton** **1 Kennedy Rd S Unit 12** **Brampton ON L6W 3C9**	GEN

Generator No: ON4123559
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
22	1 of 2	SW/40.0	222.1 / 2.29	**2484667 Ontario Inc.** **215 Queen Street East Unit 8** **Brampton ON L6W 0A9**	GEN
Generator No:		ON5680157			
SIC Code:		446110			
SIC Description:		446110			
Approval Years:		2016			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:		Solai ssb pillai			
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:		9054577700 Ext.			
Contaminated Facility:		No			
MHSW Facility:		No			
Detail(s)					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
22	2 of 2	SW/40.0	222.1 / 2.29	**2484667 Ontario Inc.** **215 Queen Street East Unit 8** **Brampton ON L6W 0A9**	GEN
Generator No:		ON5680157			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2017			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
23	1 of 3	SW/18.0	222.6 / 2.76	**MATTAMY (BRAMVIEW LTD)** **209 QUEEN ST EAST** **BRAMPTON ON L6W 2B4**	GEN
Generator No:		ON5243826			
SIC Code:		236110			
SIC Description:		Residential Building Construction			
Approval Years:		05			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 221
Waste Class Name: LIGHT FUELS

23	2 of 3	SW/18.0	222.6 / 2.76	**BRAMVIEW FORD SALES LTD** **209 QUEEN ST E** **BRAMPTON ON L6W 2B4**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9557171
Status: EXPIRED
Instance ID:
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description:
Original Source: EXP
Record Date: Up to May 2013

Expired Date: 7/4/1997
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

23	3 of 3	SW/18.0	222.6 / 2.76	**BRAMVIEW FORD SALES LTD** **209 QUEEN ST E** **BRAMPTON ON**	DTNK

Delisted Expired Fuel Safety Facilities

Instance No: 9664383
Status: EXPIRED
Instance ID: 387692
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Propane Vehicle Conv Centre		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

24	1 of 1	NE/42.2	217.8 / -2.00	261 QUEEN STREET EAST, BRAMPTON ON	INC

Incident No:	248256	**Any Health Impact:**	
Incident ID:	2399614	**Any Enviro Impact:**	
Instance No:		**Service Intrp:**	
Status Code:	Causal Analysis Complete	**Was Prop Damaged:**	
Incident Status:		**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:		**Indus App. Type:**	
Attribute Category:	FS-Incident	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	3'
Date of Occurrence:		**Operation Pressure:**	IP
Time of Occurrence:		**Equipment Type:**	
Occr Insp Start Dt:		**Equipment Model:**	
Incident Creat On:		**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:		**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:		**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:		**Tank Storage Type:**	
Prc Escalation Req:		**Tank Location Type:**	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:	Service / Riser Distribution Pipeline		
Pipeline Involved:			
Pipe Material:	Plastic		
Regulator Location:	Outside		
Regulator Type:	Service Regulator (up to 60 psi intake)		
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			
Inventory Address:	261 QUEEN STREET EAST, BRAMPTON - 1" PIPELINE HIT		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative:
Operation Type Involved:

---

25 | ***1 of 6*** | ***SW/42.4*** | ***222.8 / 2.94*** | ***FLOWERTOWN CLEANERS & LAUNDERERS***
210 QUEEN STREET EAST
BRAMPTON ON L6V 1B7 | ***GEN***

Generator No: ON0518400
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS
Approval Years: 86,87,88,89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 | ***2 of 6*** | ***SW/42.4*** | ***222.8 / 2.94*** | ***FLOWERTOWN CLEANERS & LAUNDERERS***
210 QUEEN STREET EAST
BRAMPTON ON L6V 1B7 | ***GEN***

Generator No: ON0518400
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER
Approval Years: 92,93,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

---

25 | ***3 of 6*** | ***SW/42.4*** | ***222.8 / 2.94*** | ***FLOWERTOWN CLEANERS & LAUNDERERS 15-133***
210 QUEEN STREET EAST
BRAMPTON ON L6V 1B7 | ***GEN***

Generator No: ON0518400
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER
Approval Years: 94,95,96
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

25	4 of 6	SW/42.4	222.8 / 2.94	FLOWERTOWN CLEANERS AND LAUNDERERS_ 210 QUEEN STREET EAST BRAMPTON ON L6V 1B7	GEN

Generator No: ON0518400
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS
Approval Years: 99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 241
Waste Class Name: HALOGENATED SOLVENTS

25	5 of 6	SW/42.4	222.8 / 2.94	FLOWERTOWN CLEANERS AND LAUNDERERS 210 Queen Street East Brampton ON L6V 1B7	GEN

Generator No: ON0518400
SIC Code: 812310
SIC Description: Coin-Operated Laundries and Dry Cleaners
Approval Years: 04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

25	6 of 6	SW/42.4	222.8 / 2.94	G. Print Ltd. 210 Queen St E Brampton ON L6V 1B7	SCT

Established: 1994
Plant Size (ft²):
Employment:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

--Details--
Description: Digital Printing
SIC/NAICS Code: 323115

Description: Business Service Centres
SIC/NAICS Code: 561430

---

26 ***1 of 13*** ***NE/39.4*** ***218.8 / -1.00*** ***Bramvet Ltd***
265 queen St East
Brampton ON L6W 2C2
GEN

Generator No: ON3401035
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 06,07,08
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

26 ***2 of 13*** ***NE/39.4*** ***218.8 / -1.00*** ***Bramvet Ltd***
265 queen St East
Brampton ON L6W 2C2
GEN

Generator No: ON3401035
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

26 ***3 of 13*** ***NE/39.4*** ***218.8 / -1.00*** ***Bramvet Ltd***
265 queen St East
Brampton ON L6W 2C2
GEN

Generator No: ON3401035
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2010
PO Box No:
Country:

Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

26 ***4 of 13*** ***NE/39.4*** ***218.8 / -1.00*** ***Bramvet Ltd***
265 queen St East
Brampton ON L6W 2C2 ***GEN***

Generator No: ON3401035
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

26 ***5 of 13*** ***NE/39.4*** ***218.8 / -1.00*** ***Bramvet Ltd***
265 queen St East
Brampton ON L6W 2C2 ***GEN***

Generator No: ON3401035
SIC Code: 541940
SIC Description: Veterinary Services
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

26 ***6 of 13*** ***NE/39.4*** ***218.8 / -1.00*** ***Bramvet Ltd***
265 queen St East
Brampton ON ***GEN***

Generator No: ON3401035

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

26 | **7 of 13** | **NE/39.4** | **218.8 / -1.00** | **Brampton Veterinary Hospital Professional Corp**
265 queen St East
Brampton ON L6W 2C2 | **GEN**

Generator No: ON3401035
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

26 | **8 of 13** | **NE/39.4** | **218.8 / -1.00** | **Brampton Veterinary Hospital Professional Corp**
265 queen St East
Brampton ON L6W 2C2 | **GEN**

Generator No: ON3401035
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
26	9 of 13	NE/39.4	218.8 / -1.00	Brampton Veterinary Hospital Professional Corp 265 queen St East Brampton ON L6W 2C2	GEN

Generator No: ON3401035
SIC Code: 541940
SIC Description: VETERINARY SERVICES
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
26	10 of 13	NE/39.4	218.8 / -1.00	Brampton Veterinary Hospital Professional Corp 265 queen St East Brampton ON L6W 2C2	GEN

Generator No: ON3401035
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
26	11 of 13	NE/39.4	218.8 / -1.00	Brampton Veterinary Hospital Professional Corp 265 queen St East Brampton ON L6W 2C2	GEN

Generator No: ON3401035
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
26	**12 of 13**	**NE/39.4**	**218.8 / -1.00**	**Brampton Veterinary Hospital Professional Corp** **265 queen St East** **Brampton ON L6W 2C2**	**GEN**
Generator No:		ON3401035			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
26	**13 of 13**	**NE/39.4**	**218.8 / -1.00**	**Brampton Veterinary Hospital Professional Corp** **265 queen St East** **Brampton ON L6W 2C2**	**GEN**
Generator No:		ON3401035			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
27	**1 of 1**	**SW/74.8**	**222.9 / 3.01**	**Dr. R. Nayyar Dentistry Professional Corporation** **4 Beech Street** **Brampton ON L6V1V1**	**GEN**
Generator No:		ON2942241			
SIC Code:		621210			
SIC Description:		OFFICES OF DENTISTS			
Approval Years:		2015			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:					
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	1 of 1	WSW/98.4	222.9 / 3.00	Louis Gregorich 10 Beech Street Brampton ON	GEN

Generator No: ON9945933
SIC Code: 211113
SIC Description: Conventional Oil and Gas Extraction
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	1 of 1	NE/89.3	217.8 / -2.07	2093893 ONTARIO INC 269 QUEEN STREET EAST BRAMPTON ON L6W 2C2	GEN

Generator No: ON3392580
SIC Code: 211113
SIC Description: CONVENTIONAL OIL AND GAS EXTRACTION
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
30	1 of 1	NE/59.8	219.8 / 0.00	ROYAL MATTRESS MFG CO 338 QUEEN ST E BRAMPTON ON L6V 1C4	SCT

Established: 1993
Plant Size (ft²):
Employment: 3

--Details--
Description: MATTRESSES, FOUNDATIONS, & CONVERTIBLE BEDS
SIC/NAICS Code: 2515

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	1 of 4	NE/84.1	216.7 / -3.13	MCLEAN'S RENTAL'S 279 QUEEN STREET EAST BRAMPTON ON L6W 2C2	GEN

Generator No: ON1175200
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)
Approval Years: 89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	2 of 4	NE/84.1	216.7 / -3.13	MCLEAN'S EQUIPMENT RENTA L BRAMPTON INC. 279 QUEEN STREET EAST BRAMPTON ON L6W 2C2	GEN

Generator No: ON1175200
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)
Approval Years: 92,93,97,98,99,00,01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	3 of 4	NE/84.1	216.7 / -3.13	MCLEAN'S EQUIPMENT RENTAL 26-359 (BRAMPTON) INC. 279 QUEEN ST. E. BRAMPTON ON L6W 2C2	GEN

Generator No: ON1175200
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)
Approval Years: 94,95,96
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Detail(s)					
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
31	4 of 4	NE/84.1	216.7 / -3.13	***McLean's Equipment Rental Brampton Inc.*** ***279 Queen st. E Unit D&E*** ***Brampton ON L6W 2C2***	GEN
Generator No:		ON5165777			
SIC Code:					
SIC Description:					
Approval Years:		02,03,04			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
32	1 of 1	SW/53.8	221.7 / 1.84	***Ipax Canada Ltd.*** ***174 Queen St E*** ***Brampton ON L6V 1B3***	SCT
Established:		1978			
Plant Size (ft²):		1000			
Employment:		3			
--Details--					
Description:		Commercial and Service Industry Machinery Manufacturing			
SIC/NAICS Code:		333310			
Description:		Other Communications Equipment Manufacturing			
SIC/NAICS Code:		334290			
Description:		All Other Electrical Equipment and Component Manufacturing			
SIC/NAICS Code:		335990			
33	1 of 17	NE/22.1	219.0 / -0.85	***PETRO CANADA*** ***354 QUEEN ST E*** ***BRAMPTON ON L6V 1C3***	RST
Headcode:		01186800			
Headcode Desc:		SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS			
Phone:					
List Name:					
Description:					
33	2 of 17	NE/22.1	219.0 / -0.85	***PETRO-CANADA # 57624*** ***354 QUEEN ST E*** ***BRAMPTON ON***	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11302746	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	76620	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS Piping		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	3 of 17	NE/22.1	219.0 / -0.85	PETRO-CANADA # 57624 354 QUEEN ST E BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	11302734	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	77056	***Facility Location:***	
Instance Type:	FS Piping	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

33 ***4 of 17*** ***NE/22.1*** ***219.0 / -0.85*** ***PETRO-CANADA # 57624***
354 QUEEN ST E
BRAMPTON ON ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11534366
Status: EXPIRED
Instance ID: 88889
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

---

33 ***5 of 17*** ***NE/22.1*** ***219.0 / -0.85*** ***PETRO-CANADA # 57624***
354 QUEEN ST E
BRAMPTON ON ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11370995
Status: EXPIRED
Instance ID: 80428
Instance Type: FS Piping
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

33	*6 of 17*	*NE/22.1*	*219.0 / -0.85*	***PETRO-CANADA # 57624*** ***354 QUEEN ST E*** ***BRAMPTON ON***	***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No: 11398383 ***Expired Date:***
Status: EXPIRED ***Max Hazard Rank:***
Instance ID: 82198 ***Facility Location:***
Instance Type: FS Piping ***Facility Type:***
Instance Creation Dt: ***Fuel Type 2:***
Instance Install Dt: ***Fuel Type 3:***
Item Description: ***Panam Related:***
Manufacturer: ***Panam Venue Nm:***
Model: ***External Identifier:***
Serial No: ***Item:***
ULC Standard: ***Piping Steel:***
Quantity: ***Piping Galvanized:***
Unit of Measure: ***Tank Single Wall St:***
Overfill Prot Type: ***Piping Underground:***
Creation Date: ***Tank Underground:***
Next Periodic Str DT: ***Source:***
TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

33	*7 of 17*	*NE/22.1*	*219.0 / -0.85*	***SUNCOR ENERGY PRODUCTS PARTNERSHIP*** ***354 QUEEN ST E*** ***BRAMPTON ON***	***FST***

Inventory No:	44153974			**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active			**Corrosion Protect:**	Fiberglass
Installation Year:	2001			**Overfill Protection:**	
Capacity:	50000			**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L			**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:		Double Wall UST			
Manufacturer:					
Model:					
Description:		2009VBS Premium			

33	***8 of 17***	***NE/22.1***	***219.0 / -0.85***	***SUNCOR ENERGY PRODUCTS PARTNERSHIP 354 QUEEN ST E BRAMPTON ON***	***FST***

Inventory No:	44153975			**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active			**Corrosion Protect:**	Fiberglass
Installation Year:	2006			**Overfill Protection:**	
Capacity:	35000			**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L			**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:		Double Wall UST			
Manufacturer:					
Model:					
Description:		2009VBS			

33	***9 of 17***	***NE/22.1***	***219.0 / -0.85***	***SUNCOR ENERGY PRODUCTS PARTNERSHIP 354 QUEEN ST E BRAMPTON ON***	***FST***

Inventory No:	44153973			**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active			**Corrosion Protect:**	Fiberglass
Installation Year:	2001			**Overfill Protection:**	
Capacity:	50000			**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L			**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:		Double Wall UST			
Manufacturer:					
Model:					
Description:		2009VBS			

33	***10 of 17***	***NE/22.1***	***219.0 / -0.85***	***SUNCOR ENERGY PRODUCTS PARTNERSHIP 354 QUEEN ST E BRAMPTON ON***	***FST***

Inventory No:	11624486			**Tank Material:**	Fiberglass (FRP)
Inventory Status:	active			**Corrosion Protect:**	Fiberglass
Installation Year:	2001			**Overfill Protection:**	
Capacity:	50000			**Inventory Context:**	FS Liquid Fuel
Capacity Unit:	L			**Inventory Item:**	FS Liquid Fuel Tank
Tank Type:		Double Wall UST			
Manufacturer:					
Model:					
Description:		2009VBS			

33	***11 of 17***	***NE/22.1***	***219.0 / -0.85***	***PETRO CANADA 354 QUEEN ST E BRAMPTON ON L6V1C3***	***RST***

Headcode:	01186800	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 9054572214
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

33 | **12 of 17** | **NE/22.1** | **219.0 / -0.85** | **2124964 ONTARIO INC O/A PETRO-CANADA**
354 QUEEN ST E
BRAMPTON ON
EXP

Inventory No: 11302721
Inventory Status: EXPIRED
Installation Year: 1988
Capacity: 46419
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS Supreme
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

33 | **13 of 17** | **NE/22.1** | **219.0 / -0.85** | **2124964 ONTARIO INC O/A PETRO-CANADA**
354 QUEEN ST E
BRAMPTON ON
EXP

Inventory No: 11302742
Inventory Status: EXPIRED
Installation Year: 1988
Capacity: 27252
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS
Previous Fuel Type: Diesel

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

33 | **14 of 17** | **NE/22.1** | **219.0 / -0.85** | **2124964 ONTARIO INC O/A PETRO-CANADA**
354 QUEEN ST E
BRAMPTON ON
EXP

Inventory No: 11398371
Inventory Status: EXPIRED
Installation Year: 1988
Capacity: 27252
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description: 2009VBS Mid
Previous Fuel Type: Gasoline

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:
Inventory Context: FS Liquid Fuel Tank
Inventory Item: FS LIQUID FUEL TANK

---

33 | **15 of 17** | **NE/22.1** | **219.0 / -0.85** | **2124964 ONTARIO INC O/A PETRO-CANADA**
354 QUEEN ST E
BRAMPTON ON
EXP

Inventory No: 11302756
Inventory Status: EXPIRED
Installation Year: 1988

Tank Material: Fiberglass (FRP)
Corrosion Protect: Fiberglass
Overfill Protection:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity:	27252	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	2009VBS		
Previous Fuel Type:	Gasoline		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	16 of 17	NE/22.1	219.0 / -0.85	2124964 ONTARIO INC O/A PETRO-CANADA 354 QUEEN ST E BRAMPTON ON	EXP

Inventory No:	11534354	**Tank Material:**	Fiberglass (FRP)
Inventory Status:	EXPIRED	**Corrosion Protect:**	Fiberglass
Installation Year:	1988	**Overfill Protection:**	
Capacity:	27252	**Inventory Context:**	FS Liquid Fuel Tank
Capacity Unit:		**Inventory Item:**	FS LIQUID FUEL TANK
Tank Type:			
Manufacturer:			
Model:			
Description:	2009VBS		
Previous Fuel Type:	Gasoline		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	17 of 17	NE/22.1	219.0 / -0.85	SUNCOR ENERGY PRODUCTS PARTNERSHIP 354 QUEEN ST E BRAMPTON ON	FST

Inventory No:	9574606	**Tank Material:**	
Inventory Status:	Active	**Corrosion Protect:**	
Installation Year:		**Overfill Protection:**	
Capacity:	185000	**Inventory Context:**	Liquid Fuels
Capacity Unit:	L	**Inventory Item:**	FS Gasoline Station - Self Serve
Tank Type:			
Manufacturer:			
Model:			
Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
34	1 of 1	SW/10.1	220.9 / 1.01	BRAMPTON GALLERIES 173 QUEEN ST E BRAMPTON ON L6W 2B2	SCT

Established:	1969
Plant Size (ft²):	
Employment:	10

--Details--

Description:	FURNITURE
SIC/NAICS Code:	5021

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	1 of 34	SW/45.1	220.9 / 1.01	DALE'S PHARMACY BRAMPTON LTD. 12-710 164 QUEEN STREET EAST BRAMPTON ON L6V 1B4	GEN

Generator No:	ON1568100
SIC Code:	6031
SIC Description:	PHARMACIES
Approval Years:	92,93,94,95,96,97,98
PO Box No:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261
Waste Class Name: PHARMACEUTICALS

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

35 | ***2 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***MCTU DIAGNOSTICS LIMITED***
164 QUEEN STREET EAST, SUITE B3
BRAMPTON ON L6V 1B4 | ***GEN***

Generator No: ON1939801
SIC Code: 8682
SIC Description: RADIOLOGICAL LAB.
Approval Years: 94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

35 | ***3 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***MCTU DIAGNOSTICS LIMITED***
164 QUEEN STREET EAST SUITE B3
BRAMPTON ON L6V 1B4 | ***GEN***

Generator No: ON1939801
SIC Code: 8682
SIC Description: RADIOLOGICAL LAB.
Approval Years: 99,00
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	4 of 34	SW/45.1	220.9 / 1.01	MCTU DI(OUT OF BUSINESS) 164 QUEEN STREET EAST SUITE B3 BRAMPTON ON L6V 1B4	GEN

Generator No: ON1939801
SIC Code: 8682
SIC Description: RADIOLOGICAL LAB.
Approval Years: 01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	5 of 34	SW/45.1	220.9 / 1.01	Brampton Queen Equity Inc. 164 Queen St. E. Brampton ON L6V 1B4	GEN

Generator No: ON2702186
SIC Code:
SIC Description:
Approval Years: 03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	6 of 34	SW/45.1	220.9 / 1.01	GOEYECARE INC 164 Queen St., East Suite 210 Brampton ON	GEN

Generator No: ON5281830
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	7 of 34	SW/45.1	220.9 / 1.01	GOEYECARE INC 164 Queen St., East Suite 210 Brampton ON L6V 1B4	GEN

Generator No: ON5281830
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	8 of 34	SW/45.1	220.9 / 1.01	GOEYECARE INC 164 Queen St., East Suite 210 Brampton ON L6V 1B4	GEN

Generator No: ON5281830
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	9 of 34	SW/45.1	220.9 / 1.01	Karmy Medicine Professional Corporation 164 Queen Street East Suite 110 Brampton ON L6V 1B4	GEN

Generator No: ON5627646
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
35	10 of 34	SW/45.1	220.9 / 1.01	GOEYECARE INC 164 Queen St., East Suite 210 Brampton ON L6V 1B4	GEN
Generator No:		ON5281830			
SIC Code:		621110			
SIC Description:		Offices of Physicians			
Approval Years:		2011			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
35	11 of 34	SW/45.1	220.9 / 1.01	Karmy Medicine Professional Corporation 164 Queen Street East Suite 110 Brampton ON L6V 1B4	GEN
Generator No:		ON5627646			
SIC Code:		621110			
SIC Description:		Offices of Physicians			
Approval Years:		2011			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
35	12 of 34	SW/45.1	220.9 / 1.01	Karmy Medicine Professional Corporation 164 Queen Street East Suite 110 Brampton ON L6V 1B4	GEN
Generator No:		ON5627646			
SIC Code:		621110			
SIC Description:		Offices of Physicians			
Approval Years:		2012			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

35 | ***13 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***GOEYECARE INC***
164 Queen St., East Suite 210
Brampton ON L6V 1B4 | ***GEN***

Generator No: ON5281830
SIC Code: 621110
SIC Description: Offices of Physicians
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

35 | ***14 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Karmy Medicine Professional Corporation***
164 Queen Street East Suite 110
Brampton ON | ***GEN***

Generator No: ON5627646
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

35 | ***15 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Karmy Medicine Professional Corporation***
164 Queen Street East Suite 110
Brampton ON L6V 1B4 | ***GEN***

Generator No: ON5627646
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2016
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country: Canada
Status:
Co Admin: Melissa Butcher
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-456-6816 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

35 | ***16 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Healthy smile dental hygiene***
164 Queen street east unit 108a
Brampton ON L7A 1G9 | ***GEN***

Generator No: ON3914740
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Shannon Dundas
Choice of Contact: CO_OFFICIAL
Phone No Admin: 2897521340 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

---

35 | ***17 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Healthy smile dental hygiene***
164 Queen street east unit 108a
Brampton ON L7A 1G9 | ***GEN***

Generator No: ON3914740
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Shannon Dundas
Choice of Contact: CO_OFFICIAL
Phone No Admin: 2897521340 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	18 of 34	SW/45.1	220.9 / 1.01	Karmy Medicine Professional Corporation 164 Queen Street East Suite 110 Brampton ON L6V 1B4	GEN

Generator No: ON5627646
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Melissa Butcher
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-456-6816 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	19 of 34	SW/45.1	220.9 / 1.01	Goldbrite Trading Company 164 Queen Street E. Brampton ON L6V 1B4	GEN

Generator No: ON8188355
SIC Code: 533110
SIC Description: LESSORS OF NON-FINANCIAL INTANGIBLE ASSETS (EXCEPT COPYRIGHTED WORKS)
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: JR Lewis
Choice of Contact: CO_OFFICIAL
Phone No Admin: 647 463-6989 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	20 of 34	SW/45.1	220.9 / 1.01	Karmy Medicine Professional Corporation 164 Queen Street East Suite 110 Brampton ON L6V 1B4	GEN

Generator No: ON5627646
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin: Melissa Butcher
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-456-6816 Ext.
Contaminated Facility: No
MHSW Facility: No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

35	*21 of 34*	*SW/45.1*	*220.9 / 1.01*	***Karmy Medicine Professional Corporation*** ***164 Queen Street East Suite 110*** ***Brampton ON L6V 1B4***	***GEN***

Generator No: ON5627646
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

35	*22 of 34*	*SW/45.1*	*220.9 / 1.01*	***Healthy smile dental hygiene*** ***164 Queen street east unit 108a*** ***Brampton ON L7A 1G9***	***GEN***

Generator No: ON3914740
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

35	*23 of 34*	*SW/45.1*	*220.9 / 1.01*	***farida jeejeebhoy medicine professional corp*** ***164 Queen Street East, unit 209*** ***brampton ON L6V1B4***	***GEN***

Generator No: ON5308441
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

35 | ***24 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***farida jeejeebhoy medicine professional corp***
164 Queen Street East, unit 209
brampton ON L6V1B4 | ***GEN***

Generator No: ON5308441
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

35 | ***25 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Healthy smile dental hygiene***
164 Queen street east unit 108a
Brampton ON L6V1B4 | ***GEN***

Generator No: ON3914740
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

35 | ***26 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Karmy Medicine Professional Corporation***
164 Queen Street East Suite 110
Brampton ON L6V 1B4 | ***GEN***

Generator No: ON5627646
SIC Code:
SIC Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

35 | ***27 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***M.M.&K. Drug Enterprises Corp.***
105-164 Queen st E
Brampton ON L6V 1B4 | ***GEN***

Generator No: ON4427983
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

35 | ***28 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Karmy Medicine Professional Corporation***
164 Queen Street East Suite 210
Brampton ON L6V 1B4 | ***GEN***

Generator No: ON5627646
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	29 of 34	SW/45.1	220.9 / 1.01	farida jeejeebhoy medicine professional corp 164 Queen Street East, unit 209 brampton ON L6V1B4	GEN

Generator No: ON5308441
SIC Code:
SIC Description:
Approval Years: As of Jan 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	30 of 34	SW/45.1	220.9 / 1.01	M.M.&K. Drug Enterprises Corp. 105-164 Queen st E Brampton ON L6V 1B4	GEN

Generator No: ON4427983
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	31 of 34	SW/45.1	220.9 / 1.01	Healthy smile dental hygiene 164 Queen street east unit 108a Brampton ON L6V1B4	GEN

Generator No: ON3914740
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

35 | ***32 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Karmy Medicine Professional Corporation***
164 Queen Street East Suite 210
Brampton ON L6V 1B4 | ***GEN***

Generator No: ON5627646
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

35 | ***33 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***M.M.&K. Drug Enterprises Corp.***
105-164 Queen st E
Brampton ON L6V 1B4 | ***GEN***

Generator No: ON4427983
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

---

35 | ***34 of 34*** | ***SW/45.1*** | ***220.9 / 1.01*** | ***Healthy smile dental hygiene***
164 Queen street east unit 108a
Brampton ON L6V1B4 | ***GEN***

Generator No: ON3914740
SIC Code:
SIC Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

36	*1 of 3*	*SW/24.7*	*220.9 / 1.01*	***2506907 ONTARIO 169 QUEEN ST EAST BRAMPTON ON L6W2B2***	***GEN***

Generator No: ON5546248
SIC Code:
SIC Description:
Approval Years: As of Oct 2019
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 U
Waste Class Name: Pharmaceuticals

36	*2 of 3*	*SW/24.7*	*220.9 / 1.01*	***2506907 ONTARIO 169 QUEEN ST EAST BRAMPTON ON L6W2B2***	***GEN***

Generator No: ON5546248
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

36	*3 of 3*	*SW/24.7*	*220.9 / 1.01*	***2506907 ONTARIO 169 QUEEN ST EAST***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BRAMPTON ON L6W2B2	

Generator No: ON5546248
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 261 L
Waste Class Name: PHARMACEUTICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
37	1 of 8	SW/15.3	220.9 / 1.01	**North Peel Xray and Ultrasound** **157 Queen Street East** **Brampton ON L6W 3X4**	GEN

Generator No: ON2621195
SIC Code:
SIC Description:
Approval Years: 02,03,04
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 243
Waste Class Name: PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
37	2 of 8	SW/15.3	220.9 / 1.01	**Queen lynch Co Tenancy** **157 Queen Street East** **Brampton ON**	GEN

Generator No: ON4310875
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2013
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

---

37 | ***3 of 8*** | ***SW/15.3*** | ***220.9 / 1.01*** | ***Queen Lynch Co-Tenancy***
157 Queen Street
Brampton ON L6W 3X4 | ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: LESSORS OF NON-RESIDENTIAL BUILDINGS (EXCEPT MINI-WAREHOUSES)
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

37 | ***4 of 8*** | ***SW/15.3*** | ***220.9 / 1.01*** | ***Queen Lynch Co-Tenancy***
157 Queen Street
Brampton ON L6W 3X4 | ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: LESSORS OF NON-RESIDENTIAL BUILDINGS (EXCEPT MINI-WAREHOUSES)
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

37 | ***5 of 8*** | ***SW/15.3*** | ***220.9 / 1.01*** | ***Queen Lynch Co-Tenancy***
157 Queen Street
Brampton ON L6W 3X4 | ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: LESSORS OF NON-RESIDENTIAL BUILDINGS (EXCEPT MINI-WAREHOUSES)
Approval Years: 2014
PO Box No:
Country: Canada
Status:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

37	6 of 8	SW/15.3	220.9 / 1.01	Queen Lynch Co-Tenancy 157 Queen Street Brampton ON L6W 3X4	GEN

Generator No: ON2854318
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

37	7 of 8	SW/15.3	220.9 / 1.01	Queen Lynch Co-Tenancy 157 Queen Street Brampton ON L6W 3X4	GEN

Generator No: ON2854318
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

37	8 of 8	SW/15.3	220.9 / 1.01	Queen Lynch Co-Tenancy 157 Queen Street Brampton ON L6W 3X4	GEN

Generator No: ON2854318
SIC Code:
SIC Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

38	1 of 7	SW/57.7	220.9 / 1.01	***BRAMPTON CYTOLOGY*** ***DIV. OF BESTVIEW MEDICAL LABORATORIES*** ***178 JOHN STREET*** ***BRAMPTON ON L6W 2A4***	GEN

Generator No: ON0380400
SIC Code: 8681
SIC Description: MEDICAL LABORATORIES
Approval Years: 86,87,88,89,90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

38	2 of 7	SW/57.7	220.9 / 1.01	***BRAMPTON CYTOLOGY 05-096*** ***DIV. OF BESTVIEW MEDICAL LABORATORIES*** ***178 JOHN STREET*** ***BRAMPTON ON L6W 2A4***	GEN

Generator No: ON0380400
SIC Code: 8681
SIC Description: MEDICAL LABORATORIES
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 211
Waste Class Name: AROMATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	3 of 7	SW/57.7	220.9 / 1.01	CMLHealthCare 178 John Street Brampton ON	GEN

Generator No: ON8187826
SIC Code: 621510
SIC Description: Medical and Diagnostic Laboratories
Approval Years: 2009
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	4 of 7	SW/57.7	220.9 / 1.01	CMLHealthCare 178 John Street Brampton ON	GEN

Generator No: ON8187826
SIC Code: 621510
SIC Description: Medical and Diagnostic Laboratories
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
38	5 of 7	SW/57.7	220.9 / 1.01	CMLHealthCare 178 John Street Brampton ON	GEN

Generator No: ON8187826
SIC Code: 621510
SIC Description: Medical and Diagnostic Laboratories
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
38	6 of 7	SW/57.7	220.9 / 1.01	Dr. Molnar & Dr. Najarali 178 John Street Unit 100 Brampton ON L6W 2A4	GEN
Generator No:		ON5116414			
SIC Code:		621110			
SIC Description:		OFFICES OF PHYSICIANS			
Approval Years:		2016			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:					
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:					
Contaminated Facility:		No			
MHSW Facility:		No			
Detail(s)					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
38	7 of 7	SW/57.7	220.9 / 1.01	Dr. Molnar & Dr. Najarali 178 John Street Unit 100 Brampton ON L6W 2A4	GEN
Generator No:		ON5116414			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2017			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
39	1 of 4	NE/82.6	219.8 / 0.00	D & I SPORTS INC. 382 QUEEN ST. E. BRAMPTON ON L6V 1C3	GEN
Generator No:		ON0965900			
SIC Code:		0000			
SIC Description:		*** NOT DEFINED ***			
Approval Years:		86,87,88,89			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	2 of 4	NE/82.6	219.8 / 0.00	D & I SPORTS INC. 382 QUEEN ST. E. BRAMPTON ON L6V 1C3	GEN

Generator No: ON0965900
SIC Code: 6541
SIC Description: SPORTING GOODS STORE
Approval Years: 90
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	3 of 4	NE/82.6	219.8 / 0.00	D & I SPORTS INC. 12-268 382 QUEEN ST. E. BRAMPTON ON L6V 1C3	GEN

Generator No: ON0965900
SIC Code: 6541
SIC Description: SPORTING GOODS STORE
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	4 of 4	NE/82.6	219.8 / 0.00	D & I SPORTS INCORPORATED 382 QUEEN STREET EAST BRAMPTON ON L6V 1C3	GEN

Generator No: ON0965900
SIC Code: 6541
SIC Description: SPORTING GOODS STORE
Approval Years: 99,00,01
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	1 of 4	SW/58.8	220.3 / 0.44	Elmbrook Management 145 Queen Street East Suite 400 Brampton ON L6W 3P8	GEN

Generator No: ON3348359
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Claudia Zorzi
Choice of Contact: CO_OFFICIAL
Phone No Admin: 9054515855 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	2 of 4	SW/58.8	220.3 / 0.44	Dr Percy Segal 145 Queen St E #201 Brampton ON L6W 3P8	GEN

Generator No: ON8453019
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin:
Choice of Contact: CO_OFFICIAL
Phone No Admin:
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Waste Class: 264
Waste Class Name: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	3 of 4	SW/58.8	220.3 / 0.44	Elmbrook Management 145 Queen Street East Suite 400 Brampton ON L6W 3P8	GEN

Generator No: ON3348359
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Claudia Zorzi
Choice of Contact: CO_OFFICIAL
Phone No Admin: 9054515855 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	4 of 4	SW/58.8	220.3 / 0.44	Elmbrook Management 145 Queen Street East Suite 400 Brampton ON L6W 3P8	GEN

Generator No: ON3348359
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	1 of 3	NE/63.7	219.8 / 0.00	Kronos Canada Inc. 295 Queen St E Suite 443 Brampton ON L6W 3W9	SCT

Established: 1946
Plant Size (ft²):
Employment: 1

--Details--
Description: Paint, Glass and Wallpaper Wholesaler-Distributors
SIC/NAICS Code: 416340

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	2 of 3	NE/63.7	219.8 / 0.00	New Home Services Inc. 295 Queen St E Unit 6 Suite 464 Brampton ON L6W 3W9	SCT

Established: 01-NOV-00
Plant Size (ft²):
Employment:

--Details--
Description: Computer Systems Design and Related Services
SIC/NAICS Code: 541510

Description: Computer Systems Design and Related Services
SIC/NAICS Code: 541510

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	3 of 3	NE/63.7	219.8 / 0.00	Waymar Manufacturing Co. 457-295 Queen St E Brampton ON L6W 3W9	SCT

Established: 01-OCT-80
Plant Size (ft²):
Employment:

--Details--
Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance
SIC/NAICS Code: 811310

Description: Electronic and Precision Equipment Repair and Maintenance
SIC/NAICS Code: 811210

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	1 of 3	SW/24.8	215.3 / -4.59	NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC 130 QUEEN ST BRAMPTON ON	FSTH

License Issue Date: 4/1/2002
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Retail Fuel Outlet
Facility Type: Gasoline Station - Full Serve

--Details--
Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 22700
Tank Fuel Type: Liquid Fuel Single Wall UST - Gasoline

Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

42	***2 of 3***	***SW/24.8***	***215.3 / -4.59***	***NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC*** ***130 QUEEN ST*** ***BRAMPTON ON***	***FSTH***

License Issue Date:	4/1/2002
Tank Status:	Licensed
Tank Status As Of:	December 2008
Operation Type:	Retail Fuel Outlet
Facility Type:	Gasoline Station - Full Serve

--Details--

Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	

Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline
Status:	Active
Year of Installation:	1983
Corrosion Protection:	
Capacity:	22700
Tank Fuel Type:	Liquid Fuel Single Wall UST - Gasoline

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	3 of 3	SW/24.8	215.3 / -4.59	NARESH VERMA O/A SPEEDY FILL GAS & PETROLEUM PRODUCTS INC 130 QUEEN ST BRAMPTON ON	DTNK

Delisted Expired Fuel Safety Facilities

Instance No:	10600088	**Expired Date:**	
Status:	EXPIRED	**Max Hazard Rank:**	
Instance ID:	29180	**Facility Location:**	
Instance Type:	FS Piping	**Facility Type:**	
Instance Creation Dt:		**Fuel Type 2:**	
Instance Install Dt:		**Fuel Type 3:**	
Item Description:		**Panam Related:**	
Manufacturer:		**Panam Venue Nm:**	
Model:		**External Identifier:**	
Serial No:		**Item:**	
ULC Standard:		**Piping Steel:**	
Quantity:		**Piping Galvanized:**	
Unit of Measure:		**Tank Single Wall St:**	
Overfill Prot Type:		**Piping Underground:**	
Creation Date:		**Tank Underground:**	
Next Periodic Str DT:		**Source:**	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Piping
Original Source: EXP
Record Date: Up to Mar 2012

---

43 | ***1 of 6*** | ***SW/84.3*** | ***209.1 / -10.72*** | ***Dr Emil Svoboda Dentistry Professional Corporation, 110 Queen Street East, Brampton ON L6V 1B1*** | ***GEN***

Generator No: ON8076099
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2016
PO Box No:
Country: Canada
Status:
Co Admin: Anna Mantenone
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-866-6657 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

43 | ***2 of 6*** | ***SW/84.3*** | ***209.1 / -10.72*** | ***Dr Emil Svoboda Dentistry Professional Corporation, 110 Queen Street East, Brampton ON L6V 1B1*** | ***GEN***

Generator No: ON8076099
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Approval Years: 2015
PO Box No:
Country: Canada
Status:
Co Admin: Anna Mantenone
Choice of Contact: CO_OFFICIAL
Phone No Admin: 905-866-6657 Ext.
Contaminated Facility: No
MHSW Facility: No

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

---

43 | ***3 of 6*** | ***SW/84.3*** | ***209.1 / -10.72*** | ***Dr Emil Svoboda Dentistry Professional Corporation, 110 Queen Street East, Brampton ON L6V 1B1*** | ***GEN***

Generator No: ON8076099
SIC Code:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

43	*4 of 6*	*SW/84.3*	*209.1 / -10.72*	***Dr Emil Svoboda Dentistry Professional Corporation*** ***110 Queen Street East*** ***Brampton ON L6V 1B1***	*GEN*

Generator No: ON8076099
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

43	*5 of 6*	*SW/84.3*	*209.1 / -10.72*	***Dr Emil Svoboda Dentistry Professional Corporation*** ***110 Queen Street East*** ***Brampton ON L6V 1B1***	*GEN*

Generator No: ON8076099
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
43	6 of 6	SW/84.3	209.1 / -10.72	Dr Emil Svoboda Dentistry Professional Corporation 110 Queen Street East Brampton ON L6V 1B1	GEN

Generator No: ON8076099
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	1 of 4	SW/95.7	208.8 / -11.03	Dr. Robert Sleightholm Professional Medicine Inc. 111 Queen Street East Unit 2-4 Brampton ON L6W2A9	GEN

Generator No: ON4342958
SIC Code:
SIC Description:
Approval Years: As of Dec 2018
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	2 of 4	SW/95.7	208.8 / -11.03	Dr. Robert Sleightholm Professional Medicine Inc. 111 Queen Street East Unit 2-4 Brampton ON L6W2A9	GEN

Generator No: ON4342958
SIC Code:
SIC Description:
Approval Years: As of Jul 2020
PO Box No:
Country: Canada
Status: Registered
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

44 | ***3 of 4*** | ***SW/95.7*** | ***208.8 / -11.03*** | ***Dr. Robert Sleightholm Professional Medicine Inc.***
111 Queen Street East Unit 2-4
Brampton ON L6W2A9 | ***GEN***

Generator No: ON4342958
SIC Code:
SIC Description:
Approval Years: As of Nov 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: Pharmaceuticals

Waste Class: 312 P
Waste Class Name: Pathological wastes

---

44 | ***4 of 4*** | ***SW/95.7*** | ***208.8 / -11.03*** | ***Dr. Robert Sleightholm Professional Medicine Inc.***
111 Queen Street East Unit 2-4
Brampton ON L6W2A9 | ***GEN***

Generator No: ON4342958
SIC Code:
SIC Description:
Approval Years: As of Oct 2022
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 261 A
Waste Class Name: PHARMACEUTICALS

Waste Class: 312 P
Waste Class Name: PATHOLOGICAL WASTES

---

45 | **1 of 1** | **SW/100.0** | **209.5 / -10.33** | **Queen Street & Scott Street, Brampton ON** | **INC**

Incident No:	536932	**Any Health Impact:**	No
Incident ID:		**Any Enviro Impact:**	No
Instance No:		**Service Intrp:**	No
Status Code:		**Was Prop Damaged:**	No
Incident Status:		**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:	3238186	**Indus App. Type:**	
Attribute Category:	FS-Perform L1 Incident Insp	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	
Date of Occurrence:	2011/02/21 00:00:00	**Operation Pressure:**	
Time of Occurrence:	10:30:00	**Equipment Type:**	
Occr Insp Start Dt:	2011/02/21 00:00:00	**Equipment Model:**	
Incident Creat On:		**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Leak	**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Natural Gas	**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:	NULL	**Tank Storage Type:**	
Prc Escalation Req:	NULL	**Tank Location Type:**	

Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: Queen Street & Scott Street, Brampton - Vapour Release
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: NULL
Operation Type Involved: Other - Specify

Unplottable Summary

Total: 7 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
DTNK	STAR FEULS LTD	HWY 10 N	BRAMPTON ON	
GEN	Queen Lynch Co-Tenancy	Queen Street	Brampton ON	
GEN	Queen Lynch Co-Tenancy	Queen Street	Brampton ON	L6W 3X4
GEN	Queen Lynch Co-Tenancy	Queen Street	Brampton ON	L6W 3X4
GEN	Queen Lynch Co-Tenancy	Queen Street	Brampton ON	L6W 3X4
RST	PETRO-CANADA	QUEEN EAST KINGS CROSS	BRAMPTON ON	
RST	PETRO-CANADA		BRAMPTON ON	

Unplottable Report

Site: ***STAR FEULS LTD***
HWY 10 N BRAMPTON ON

Database: ***DTNK***

Delisted Expired Fuel Safety Facilities

Instance No:	10447600	***Expired Date:***	
Status:	EXPIRED	***Max Hazard Rank:***	
Instance ID:	17354	***Facility Location:***	
Instance Type:	FS Highway Tank - Gas/Diesel	***Facility Type:***	
Instance Creation Dt:		***Fuel Type 2:***	
Instance Install Dt:		***Fuel Type 3:***	
Item Description:		***Panam Related:***	
Manufacturer:		***Panam Venue Nm:***	
Model:		***External Identifier:***	
Serial No:		***Item:***	
ULC Standard:		***Piping Steel:***	
Quantity:		***Piping Galvanized:***	
Unit of Measure:		***Tank Single Wall St:***	
Overfill Prot Type:		***Piping Underground:***	
Creation Date:		***Tank Underground:***	
Next Periodic Str DT:		***Source:***	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Site: ***Queen Lynch Co-Tenancy***
Queen Street Brampton ON

Database: ***GEN***

Generator No:	ON2854318
SIC Code:	531120
SIC Description:	LESSORS OF NON-RESIDENTIAL BUILDINGS (EXCEPT MINI-WAREHOUSES)
Approval Years:	2013
PO Box No:	
Country:	
Status:	
Co Admin:	
Choice of Contact:	
Phone No Admin:	
Contaminated Facility:	
MHSW Facility:	

Detail(s)

Waste Class:	312
Waste Class Name:	PATHOLOGICAL WASTES

Site: ***Queen Lynch Co-Tenancy***
Queen Street Brampton ON L6W 3X4

Database: ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: Lessors of Non-Residential Buildings (except Mini-Warehouses)
Approval Years: 2012
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Site: ***Queen Lynch Co-Tenancy***
Queen Street Brampton ON L6W 3X4

Database: ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: Lessors of Non-Residential Buildings (except Mini-Warehouses)
Approval Years: 2011
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Site: ***Queen Lynch Co-Tenancy***
Queen Street Brampton ON L6W 3X4

Database: ***GEN***

Generator No: ON2854318
SIC Code: 531120
SIC Description: Lessors of Non-Residential Buildings (except Mini-Warehouses)
Approval Years: 2010
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 312
Waste Class Name: PATHOLOGICAL WASTES

Site: ***PETRO-CANADA***
QUEEN EAST KINGS CROSS BRAMPTON ON

Database: ***RST***

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 9057922325
List Name:
Description:

Site: ***PETRO-CANADA***
BRAMPTON ON

Database: ***RST***

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 9054532849
List Name:
Description:

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Nov 2023

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Apr 2024

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Apr 30, 2024

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2022

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Apr 30, 2024

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -May 2024

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-May 2024

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Jun 30, 2024

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Aug 2023

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Apr 30, 2024

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Jun 30, 2024

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Apr 30, 2024

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Mar 31, 2024

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2023

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Mar 2024

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: Oct 31, 2021

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2022

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: 31 Oct, 2023

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2024

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2022

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory 1993-2020: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Sep 2020

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-May 31, 2024

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2023

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Jun 30, 2024

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011-Apr 30, 2024

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Sep 2020

Potential PFAS Handlers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Sep 2020

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Jun 30, 2024

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004-Jun 2024

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Apr 30, 2024

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests. This database includes spill incidents that occurred in Mar 2023-Mar 2024 in addition to those listed in the Government Publication Date.

Government Publication Date: 1988-Jan 2023; see description

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2021

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2023

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Apr 30, 2024

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Dec 31 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.


Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX B:

Aerial Photographs



LEGEND

SITE BOUNDARY

100 m STUDY AREA

Data Source: County Atlas Project

TITLE

1877 HISTORICAL MAP OF PEEL COUNTY

PROJECT


CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-1.1


Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-1.1 1877.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: County Atlas Project

TITLE

1877 HISTORICAL MAP OF PEEL COUNTY

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-1.2

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12_GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-1.2 1877.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: County Atlas Project

TITLE

1877 HISTORICAL MAP OF PEEL COUNTY

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-1.3

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-1.3 1877.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: University of Toronto Map Library

TITLE

1954 AERIAL PHOTOGRAPH

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-2.1

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-2.1 1954.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: University of Toronto Map Library


TITLE

1954 AERIAL PHOTOGRAPH

PROJECT	CONTAMINANT OVERVIEW STUDY OLD SCHOOL ROAD, KENNEDY ROAD, QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET AND ORANGEVILLE BRAMPTON RAILWAY BRAMPTON, ONTARIO
CLIENT	REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-2.2


Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-2-2 1954.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: University of Toronto Map Library

TITLE

1954 AERIAL PHOTOGRAPH

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-2.3

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-2-3 1954.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton

TITLE

1994 AERIAL PHOTOGRAPH

PROJECT CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT
REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-3.1


Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-3.1 1994.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton

TITLE

1994 AERIAL PHOTOGRAPH


PROJECT CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT
REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-3.2

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-3.2 1994.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton


TITLE

1994 AERIAL PHOTOGRAPH

PROJECT: CONTAMINANT OVERVIEW STUDY OLD SCHOOL ROAD, KENNEDY ROAD, QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET AND ORANGEVILLE BRAMPTON RAILWAY BRAMPTON, ONTARIO				
CLIENT: REGION OF PEEL				
PROJECT NO. 24-0735b	DATE JULY 2025	PREPARED BY KN	APPROVED BY RO	FIGURE B-3.3

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-3.3 1994.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton, Town of Caledon

TITLE

2003/2004 AERIAL PHOTOGRAPH


PROJECT CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT
REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-4.1

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-4.1 2004.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton

TITLE

2004 AERIAL PHOTOGRAPH

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO


CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-4.2

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-4.2 2004.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton

TITLE

2004 AERIAL PHOTOGRAPH

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-4.3

Prepared By: KaitlynNg

C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-4.3 2004.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA

Data Source: City of Brampton, Town of Caledon

TITLE

2014 AERIAL PHOTOGRAPH

PROJECT

CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-5.1

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-5-1 2014.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton

TITLE

2014 AERIAL PHOTOGRAPH

PROJECT CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-5.2

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-5-2 2014.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton

TITLE

2014 AERIAL PHOTOGRAPH

PROJECT CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT

REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-5.3


Prepared By: KaitlynNg
C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-5-3 2014.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton, Town of Caledon

TITLE

2023 / 2024 AERIAL PHOTOGRAPH

PROJECT
CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT
REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-6.1

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-6-1 2024.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton

TITLE

2024 AERIAL PHOTOGRAPH

PROJECT CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT
REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-6.2

Prepared By: KaitlynNg


C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-6-2 2024.aprx



LEGEND

SITE BOUNDARY

100 m STUDY AREA



Data Source: City of Brampton

TITLE

2024 AERIAL PHOTOGRAPH

PROJECT CONTAMINANT OVERVIEW STUDY
OLD SCHOOL ROAD, KENNEDY ROAD,
QUEEN STREET EAST, BOVAIRD DRIVE, VODDEN STREET
AND ORANGEVILLE BRAMPTON RAILWAY
BRAMPTON, ONTARIO

CLIENT
REGION OF PEEL

PROJECT NO.	DATE	PREPARED BY	APPROVED BY	FIGURE
24-0735b	JULY 2025	KN	RO	B-6.3

Prepared By: KaitlynNg

C:\Users\KaitlynNg\OneDrive - EnVision Consultants\12. GIS\Projects\2024\24-0735b\APRX\Contaminant Overview Study\24-0735b Figure B-6-3 2024.aprx

APPENDIX C:

Site Photographs

Old School Road, Brampton, Ontario

24-0735b



PHOTO 1: View of intersection of Hurontario Street and Old School Road, facing north.



PHOTO 2: View of the Agricultural lands located in the north portion of the Project Area at Old School Road, facing north



PHOTO 3: Overview of the Old School Road, facing west.



PHOTO 4:View of the railway line located in the north portion intersecting the Old School Road, facing north.



PHOTO 5: View of the railway line located in the north portion intersecting the Old School Road, facing north.



PHOTO 6: View of the railway line located in the north portion of the Project Area at Wanless Drive, facing south



PHOTO 7: View of the railway line located in the central portion of the Project Area at sandalwood Drive, facing north.



PHOTO 8: View of the railway line path in the central portion of the Project Area, facing north.



PHOTO 9: View of the railway line located in the central portion of the Project Area at Vodden Drive, facing south.



PHOTO 10: View of the intersection of Bovaird Drive West and McLaughlin Road as well as adjacent gas stations.




PHOTO 11:View of Canadian Tire gas station in northeast corner of the intersection of Bovaird Drive West and McLaughlin Road.



PHOTO 12: View of ESSO gas station in northwest corner of the intersection of Bovaird Drive West and McLaughlin Road.



PHOTO 13:View of Brampton Crysler dealership, located at the central north adjacent of the Project Area, facing north.



PHOTO 14:View of the railway line path in the central portion of the Project Area, facing north.



PHOTO 15: View of the intersection of Bovaird Drive, facing west.



PHOTO 16: Overview of the Vodden street, facing west.



PHOTO 17: Overview of the central portion of the Vodden Street, facing east.



PHOTO 18: View of the railway line intersecting the central portion of the Project Area intersecting Vodden Street, facing south.



PHOTO 19: View of the intersection of Vodden Street and Kennedy Street, facing northeast.



PHOTO 20:View of the intersection located at Isabella Street and Vodden Street, facing east.



PHOTO 21: View of the intersection of Vodden Street and Kennedy Street, facing northeast.



PHOTO 22: View of Petro–Canada gas station located in the southwest corner of the intersection of Kennedy Road North and Vodden Street.



PHOTO 23: View of the intersection of Kennedy Road North and Queen Street East.



PHOTO 24: View of auto body shop located west adjacent of the Project Area along Kennedy Road South.



PHOTO 25: View of an auto service garage located east adjacent to the Kennedy Portion of the Project Area.



PHOTO 26: View of auto service garages located east adjacent to the Kennedy Portion of the Project Area.



PHOTO 27: View of the intersection of Kennedy Road South and Stafford Drive as well as an auto service garage in the northwest corner of the intersection.



PHOTO 28: View of the intersection of Kennedy Road South and Stafford Drive as well as an auto service garage in the northeast corner of the intersection.



PHOTO 29: View of the intersection of Kennedy Road South and Glidden Road.



PHOTO 30: View of the intersection of Kennedy Road South and Rambler Road as well as a Husky gas station located in the southeast corner of the intersection.



PHOTO 31: View of an ESSO gas station located in the southeast corner of the intersection of Steeles Avenue East and Kennedy Road South.



PHOTO 32: View of the tributary of the Etobicoke creek located south of the Kennedy road and steels avenue, facing east.



PHOTO 33: View of the intersection of Hansen Road South and Queen Street East.



PHOTO 34: View of Speedy Auto, an auto service garage, located south adjacent of the Queen Portion of the Project Area.



PHOTO 35: View an auto service garage located within an automotive dealership located north adjacent to the Queen Portion of the Project Area.



PHOTO 36: View of the intersection of Queen Street East and Rutherford Road South. A Mr. Lube auto service garage was observed southeast of the intersection.

FIGURES

APPENDIX A:

ERIS Reports

APPENDIX B:

Aerial Photographs

APPENDIX C:

Site Photographs