

EXP Services Inc.

*Municipal Class Environmental Assessment for Road Improvements near Derry Road East and Alstep Drive:
Environmental Study Report
June 30, 2022*

*Municipal Class Environmental Assessment for
Road Improvements near Derry Road East and Alstep Drive:
Environmental Study Report*

Appendix O: Tree Preservation Report



Tree Preservation Report c/w Tree Inventory & Protection Plan

Bombardier Aerospace – Pearson

Type of Document:

Tree Preservation Report
c/w Tree Inventory & Protection Plan

Project Name:

Municipal Class Environmental Assessment
for Road Improvements near
Derry Road East and Alstep Drive

Project Number:

STR-02018572-00

Date + time Submitted:

2022-04-28

Legal Notification

This Report was prepared by EXP Services Inc. for the account of **Bombardier Aerospace**.

Any use which a third party makes of this Report, or any reliance on or decisions to be made based on it, are the responsibility of such third parties. EXP Services Inc. accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this project.

Table of Contents

Legal Notification.....	1
1. Introduction	3
2. General Overview	3
3. Method of Evaluation	4
4. Vegetation Summary	4
5. Plant Valuation Process	5
6. General Tree Preservation Measures	6
7. Assumption & Limitations.....	6
Appendix A – Tree Inventory Chart	8

Drawing TIPP - Tree Inventory and Protection Plan

1. Introduction

This report has been prepared for industrial development on a parcel of land situated just north of the Toronto Pearson International Airport at 1890 Alstep Drive, Mississauga, Ontario. The land is owned by the Government of Canada and administered by the Greater Toronto Airports Authority (GTAA).

The industrial development will generate an increase in traffic, which will have an impact on the existing roadway network. To accommodate the increase in traffic demands, improvements to the infrastructures will be required. As such, the Region of Peel (Region), the City of Mississauga (City), and Bombardier Aerospace (Bombardier) are co-proponents to upgrade the local existing road network accordingly. The proposed road re-alignments consist of portions of the following roadways: Bramalea Road, Derry Road East, Telford Way, Alstep Drive, Menkes Drive and Menway Court.

This Report performs the following:

- Evaluates trees within the study area which may be impacted by the proposed road re-alignments.
- Evaluates the trees on adjacent private properties which may be impacted by the proposed road re-alignment.
- Determines the necessary remediation to permit the preservation of trees suitable for retention.
- Determines which trees are to be removed.

A tree inventory was conducted on June 25th, 2019.

2. General Overview




Figure 1: Class EA Project Study Area

The study area for this Class EA is primarily along Derry Road East (185 m west of Menkes Drive and 450 m east of Bramalea Road) and Bramalea Road (485 m south of Derry Road East and 410 m north of Derry Road East). It also includes three local roads: Menkes Drive, Alstep Drive, and Telford Way. The study area is depicted in Figure 1.

3. Method of Evaluation

The study area is governed by the City of Mississauga Tree Permit By-law Number 474-05 and Site Plan Control By-law.

Tree investigation was conducted for the following tree categories:

- All trees of any size on the municipal boulevards.
- Private trees 15cm or more in diameter (measured at 1.4m above existing grade) within 6 meters of the proposed construction for the road re-alignments.

Each tree location and associated identification number was denoted on Drawing TIPP for ease of reference. The trees were measured for DBH (Diameter at Breast Height) 1.4m above grade. For multiple stem trees, the total of the diameters of the three largest stems is considered the diameter of the trees.

The trees were assessed in accordance with the International Society of Arboriculture Methodology, by visual inspection from ground locations only. The tree was not climbed, nor was invasive assessment techniques (trunk boring) employed. The tree inventory and observations are summarized in Appendix A.

3.1 Assessment

Vegetation is assessed based on a visual inspection of the trunk and branch condition, structure, foliage condition, and evidence of abiotic (environmental, mechanical, and physical damage) and biotic (insects and disease) stressors.

3.2 Condition

Tree health and condition is evaluated as poor, fair, and good:

- Poor - Considerable dieback, contorted growth, diseased, or extensive physical damage, root damage, decay, cavities, and presence of secondary agents (harmful insects) that aid in the decline of the tree. The plant may have reached its normal life expectancy.
- Fair - some dieback, signs, and symptoms of stress both by non-living and living agents, aesthetic value is compromised; however, the tree continues to show healthy growth.
- Good - healthy, vigorous growth, strong branch attachment, and taper, no signs or symptoms of stress.

4. Vegetation Summary

Trees on Subject Study Area

In total, four hundred and thirty one (431) individual trees and five (5) tree groups were inventoried within the study area. All inventoried trees have been identified by both their scientific names and common names. The trees were identified on the TIPP. Trees present within the subject study area appear to be Basswood, Honeylocust, Austrian Pine, Jack Pine, White Spruce, Blue Spruce, Poplar, River Birch, Northern Catalpa, Lilac, Freeman Maple, Norway Maple, and Crabapple.

5. Plant Valuation Process

5.1 Study Criteria

The composition of individual trees and tree grouping were analyzed utilizing the following categories:

- Common and Botanical Classification
- General Health
- Size
- Species Potential for Preservation in an Urban Situation
- Site Potential to Support vegetation given proposed grading and drainage changes.

Recommendations for tree preservation or removal were suggested by considering all the above factors.

5.2 Removal & Preservation Recommendations

Trees will not thrive if major disruptions occur in their micro-environment. Changes in grade, drainage, and wind pattern can all contribute to their decline and eventual death. Dead trees can result in very costly removal fees once construction is completed around the trees. Therefore, extreme care must be taken with any trees scheduled for preservation. Removing trees prior to construction is cost-effective, but where possible, every effort should be made to preserve trees. The decision to maintain trees must be coupled with sound arboriculture methods to ensure the long-term health and survival of protected trees.

Trees Recommended for Removal

Total twenty-nine (29) trees are impacted and need to be removed for the proposed road re-alignments.

Please refer to Table 1, Appendix A – Tree Inventory Chart and drawing TIPP for detailed tree information.

Trees Recommended for Preservation

It is critical to protect all trees during demolition and construction; the protection can be accomplished by protecting the said trees with Tree Protection Hoardings. As an arboricultural standards practice, the minimal Tree Protection Zone (TPZ) radius is based on the diameter of the tree trunk (TPZ \approx 6 x DBH).

Total two hundred and seventy (270) trees and three (3) tree groups will be impacted and need to be protected during the proposed road re-alignments. City of Mississauga Tree Protection Detail is included on drawing TIPP.

Please refer to Table 1, Appendix A – Tree Inventory Chart and drawing TIPP for detailed tree information.

Table 1: Impacted Tree Chart

EA Study Segment	# of Trees Removed	# of Trees Protected/Preserved
Derry Road	13	119 individual trees and 3 tree groups (consist of 63 individual trees)
Menkes Drive / Telford Drive	3	40
Alstep Drive Extension	6	43 individual trees and 1 tree group (consist of 35 individual trees)

Bramalea Road	6	44 individual trees and 1 tree group (consist of 5 individual trees)
Alstep Drive (existing segment)	1	-
Menway Court	-	22

6. General Tree Preservation Measures

The following guidelines are to be observed where groups and individual trees are stated for preservation.

6.1 Construction Procedures

Construction procedures are very detrimental to the health of existing trees, and the below activities must be prevented:

- Burning of waste material in the vicinity of existing trees.
- Installation of rigging cables in the branches or around the trunks of existing trees.
- Flushing of cement or concrete mixing machines over the root systems.
- Storage of construction material and vehicles near existing trees.

6.2 Preservation Prescriptions

Where necessary tree preservation prescriptions shall be fulfilled to the following specifications:

Ground Injected Fertilizer

Fertilize with water suspended Plant Products 5 -10 - 15, Soil Injected Fertilizer 10-12 inches below grade and throughout the entire preserved root zone.

Install Partially Composted Woodchips

Install a layer of partially composted 150mm wood chips mulch over the protected root zone, to improve soil structure, protect the minimum preserved root zone, and conserve soil moisture levels.

Tree Pruning

Maintenance Prune the canopy of specified trees to remove dead, diseased and crossing branches 1-inch diameter and larger. Clearances prune the canopy to provide 1-1.5m feet of clearance to the construction site, and as necessary, elevate the canopy 2.4-3m feet above lawn areas.

7. Assumption & Limitations

This assessment and evaluation are limited to the assignment and purpose, as stated in the Introduction.

The assessment has been conducted using a visual examination of only the above-ground parts of trees. Unless specifically noted, trees were not cored, probed, sounded, or climbed. Parts of the trees below ground, unless specifically noted, were not inspected nor exposed by excavation for assessment.

Trees are living organisms that respond individually to outside influences such as climate, biotic changes, and abiotic changes. As such, this assessment is limited to the observations made at the time of inspection.

On behalf of EXP Services Inc.



Sally Wang, OALA, CSLA
Senior Landscape Architect
Landscape Team Lead, Central Ontario

Appendix A – Tree Inventory Chart

Project: BA Pearson - 1890 Alstep Drive, Mississauga, ON			Date of Field Work: Jun. 25, 2019					
Tree ID #	Botanical Name	Common Name	Quantity	DBH(cm)	Canopy (m)	Health Conditions	Action	Reasons for removal / Retain
1	<i>Pinus banksiana</i>	Jack Pine	1	17	5	Poor		
2	<i>Pinus banksiana</i>	Jack Pine	1	20	6	Poor	Protect	Sidewalk improvement
3	<i>Pinus banksiana</i>	Jack Pine	1	15	5	Fair	Protect	Sidewalk improvement
4	<i>Pinus banksiana</i>	Jack Pine	1	14	6	Fair	Protect	Sidewalk improvement
5	<i>Pinus banksiana</i>	Jack Pine	1	17	6	Fair	Remove	Sidewalk improvement
6	<i>Pinus banksiana</i>	Jack Pine	1	20	6	Fair	Remove	Sidewalk improvement
7	<i>Acer platanoides</i>	Norway Maple	1	21	7	Good	Protect	Sidewalk improvement
8	<i>Acer platanoides</i>	Norway Maple	1	15	6	Good	Protect	Sidewalk improvement
9	<i>Acere platanoides</i>	Norway Maple	1	10	5	Good	Protect	Sidewalk improvement
10	<i>Picea glauca</i>	White Spruce	1	25	5	Good	Protect	Sidewalk improvement
11	<i>Picea glauca</i>	White Spruce	1	27	6	Good	Protect	Sidewalk improvement
12	<i>Pinus banksiana</i>	Jack Pine	1	13, 10, 13	6	Poor	Remove	Sidewalk improvement
13	<i>Pinus banksiana</i>	Jack Pine	1	26	6.5	Fair	Remove	Sidewalk improvement
14	<i>Tilia americana</i>	Basswood	1	34	7	Good	Protect	Sidewalk improvement
15	<i>Tilia americana</i>	Basswood	1	28	7	Good	Protect	Sidewalk improvement
16	<i>Picea glauca</i>	White Spruce	1	25	5	Good	Protect	Sidewalk improvement
17	<i>Pinus banksiana</i>	Jack Pine	1	22	5	Fair	Remove	Sidewalk improvement
18	<i>Picea glauca</i>	White Spruce	1	29	6	Good	Protect	Sidewalk improvement
19	<i>Pinus banksiana</i>	Jack Pine	1	19	5.5	Fair	Remove	Sidewalk improvement
20	<i>Tilia americana</i>	Basswood	1	19	6	Good	Protect	Sidewalk improvement
21	<i>Tilia americana</i>	Basswood	1	22	6	Good	Protect	Sidewalk improvement
22	<i>Tilia americana</i>	Basswood	1	21	6.5	Good	Protect	Sidewalk improvement
23	<i>Pinus banksiana</i>	Jack Pine	1	19	6.5	Fair	Remove	Sidewalk improvement
24	<i>Pinus banksiana</i>	Jack Pine	1	19	6	Poor	Remove	Sidewalk improvement
25	<i>Picea glauca</i>	White Spruce	1	14	4	Good	Protect	Sidewalk improvement
26	<i>Picea glauca</i>	White Spruce	1	20	5	Good	Protect	Sidewalk improvement
27	<i>Pinus banksiana</i>	Jack Pine	1	18	6	Fair	Remove	Sidewalk improvement
28	<i>Picea glauca</i>	White Spruce	1	28	6	Good	Protect	Sidewalk improvement
29	Dead Tree							
30	<i>Malus spp.</i>	Crabapple	1	22	6	Fair	Protect	Sidewalk improvement
31	<i>Tilia americana</i>	Basswood	1	32	5	Good	Protect	Sidewalk improvement
32	<i>Tilia americana</i>	Basswood	1	22	7	Good	Protect	Sidewalk improvement
33	<i>Malus spp.</i>	Crabapple	1	29	6	Poor	Protect	Sidewalk improvement
34	<i>Tilia americana</i>	Basswood	1	32	8	Good	Protect	Sidewalk improvement
35	<i>Picea glauca</i>	White Spruce	1	28	7	Poor	Protect	Sidewalk improvement
36	<i>Malus spp.</i>	Crabapple	1	26	7	Fair	Protect	Sidewalk improvement
37	<i>Tilia americana</i>	Basswood	1	33	8	Good	Protect	Sidewalk improvement
38	Dead Tree							
39	<i>Tilia americana</i>	Basswood	1	30	8	Good	Protect	Sidewalk improvement
40	<i>Tilia americana</i>	Basswood	1	33	9	Good	Protect	Sidewalk improvement
41	<i>Malus spp.</i>	Crabapple	1	29	8	Good		
42	<i>Malus spp.</i>	Crabapple	1	27	7	Good		
43	<i>Malus spp.</i>	Crabapple	1	26	7	Good		
44	<i>Malus spp.</i>	Crabapple	1	33	8	Good		
45	<i>Malus spp.</i>	Crabapple	1	6	2	Good	Protect	Road curb re-alignment
46	<i>Malus spp.</i>	Crabapple	1	6	2	Good	Protect	Road curb re-alignment
47	<i>Malus spp.</i>	Crabapple	1	6	2.5	Good	Protect	Road curb re-alignment
48	<i>Malus spp.</i>	Crabapple	1	6	3	Good	Protect	Road curb re-alignment
49	<i>Malus spp.</i>	Crabapple	1	6	3	Good	Protect	Road curb re-alignment
50	<i>Malus spp.</i>	Crabapple	1	7	3	Good	Protect	Road curb re-alignment
51	<i>Malus spp.</i>	Crabapple	1	16	5	Fair		
52	<i>syringa reticulata</i>	Japanese Tree Lilac	1	4	0.8	Fair	Protect	Sidewalk improvement
53	<i>Malus spp.</i>	Crabapple	1	7	3	Good	Protect	Road curb re-alignment
54	Dead Tree						Protect	Road curb re-alignment
55	<i>Acer platanoides</i>	Norway Maple	1	19	6	Good	Protect	Sidewalk improvement
56	<i>Picea glauca</i>	White Spruce	1	32	7	Good		
57	<i>Malus spp.</i>	Crabapple	1	20	7	Good		
58	<i>Malus spp.</i>	Crabapple	1	19	7	Fair		
59	<i>Malus spp.</i>	Crabapple	1	29	8	Good		
60	<i>Picea glauca</i>	White Spruce	1	37	7	Fair		
61	<i>Tilia americana</i>	Basswood	1	26	8	Good		
62	<i>Tilia americana</i>	Basswood	1	21	7	Good	Protect	Sidewalk improvement
63	<i>Tilia americana</i>	Basswood	1	16	4.5	Fair	Protect	Sidewalk improvement
64	<i>Tilia americana</i>	Basswood	1	30	7	Good	Remove	Sidewalk improvement
65	<i>Pinus nigra</i>	Austrian Pine	1	28	8	Fair	Remove	Sidewalk improvement
66	<i>Pinus nigra</i>	Austrian Pine	1	30	8	Fair	Remove	Sidewalk improvement
67	<i>Pinus nigra</i>	Austrian Pine	1	25	7	Fair	Protect	Sidewalk improvement
68	<i>Gleditsia triacanthos</i>	Honeylocust	1	20	8	Good	Protect	Sidewalk improvement

69	<i>Gleditsia triacanthos</i>	Honeylocust	1	19	7.5	Good	Protect	Sidewalk improvement
70	<i>Gleditsia triacanthos</i>	Honeylocust	1	17	6	Good	Protect	Sidewalk improvement
71	<i>Gleditsia triacanthos</i>	Honeylocust	1	16.5	6	Good		
72	<i>Gleditsia triacanthos</i>	Honeylocust	1	17	7	Fair		
73	<i>Gleditsia triacanthos</i>	Honeylocust	1	19	7	Good	Protect	Sidewalk improvement
74	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	6	Fair	Protect	Sidewalk improvement
75	<i>Gleditsia triacanthos</i>	Honeylocust	1	23	8	Fair	Protect	Sidewalk improvement
76	<i>Pinus nigra</i>	Austrian Pine	1	30	8	Fair	Protect	Sidewalk improvement
77	<i>Pinus nigra</i>	Austrian Pine	1	23	6	Fair	Protect	Sidewalk improvement
78	<i>Pinus nigra</i>	Austrian Pine	1	31	8.5	Fair	Protect	Sidewalk improvement
79	<i>Malus spp.</i>	Crabapple	1	19	6	Fair		
80	<i>Picea glauca</i>	White Spruce	1	18	5	Fair		
81	<i>Acer platanoides</i>	Norway Maple	1	17	8	Good		
82	<i>Pinus nigra</i>	Austrian Pine	1	26	8	Fair	Protect	Sidewalk improvement
83	<i>Pinus nigra</i>	Austrian Pine	1	35	9	Fair	Protect	Sidewalk improvement
84	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	13	3	Good	Protect	Sidewalk improvement
85	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	13	3	Good		
86	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	11	3	Good		
87	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	13	3	Good	Protect	Sidewalk improvement
88	<i>Betula nigra</i>	River Birch	1	6, 7, 8, 6	3	Good	Protect	Sidewalk improvement
89	<i>Acer platanoides</i>	Norway Maple	1	26	7	Fair	Protect	Sidewalk improvement
90	<i>Acer platanoides</i>	Norway Maple	1	27	9	Good	Protect	Sidewalk improvement
91	<i>Pinus nigra</i>	Austrian Pine	1	37	8	Fair	Protect	Sidewalk improvement
92	<i>Pinus nigra</i>	Austrian Pine	1	22	6	Fair	Protect	Sidewalk improvement
93	<i>Pinus nigra</i>	Austrian Pine	1	32	8	Good	Protect	Sidewalk improvement
94	<i>Pinus nigra</i>	Austrian Pine	1	21	5	Fair	Protect	Sidewalk improvement
95	<i>Pinus nigra</i>	Austrian Pine	1	33	8	Poor	Protect	Sidewalk improvement
96	<i>Pinus nigra</i>	Austrian Pine	1	29	6	Fair	Protect	Sidewalk improvement
97	<i>Pinus nigra</i>	Austrian Pine	1	28	7	Fair	Protect	Sidewalk improvement
98	<i>Pinus nigra</i>	Austrian Pine	1	30, 24	8	Fair	Protect	Sidewalk improvement
99	<i>Pinus nigra</i>	Austrian Pine	1	29	7	Fair	Protect	Sidewalk improvement
100	<i>Acer platanoides</i>	Norway Maple	1	22	6	Poor	Protect	Sidewalk improvement
101	<i>Acer platanoides</i>	Norway Maple	1	34	8	Good	Protect	Sidewalk improvement
102	<i>Gleditsia triacanthos</i>	Honeylocust	1	29	8	Fair	Protect	Sidewalk improvement
103	<i>Gleditsia triacanthos</i>	Honeylocust	1	32	9	Fair	Protect	Sidewalk improvement
104	<i>Pinus nigra</i>	Austrian Pine	1	32	9	Fair	Protect	Sidewalk improvement
105	<i>Pinus nigra</i>	Austrian Pine	1	22	8	Fair	Protect	Sidewalk improvement
106	<i>Gleditsia triacanthos</i>	Honeylocust	1	33	9	Fair	Protect	Sidewalk improvement
107	<i>Gleditsia triacanthos</i>	Honeylocust	1	32	10	Fair	Protect	Sidewalk improvement
108	<i>Pinus nigra</i>	Austrian Pine	1	23	6	Fair	Protect	Sidewalk improvement
109	<i>Gleditsia triacanthos</i>	Honeylocust	1	31	10	Good	Protect	Sidewalk improvement
110	<i>Pinus nigra</i>	Austrian Pine	1	21	6	Fair	Protect	Sidewalk improvement
111	<i>Pinus nigra</i>	Austrian Pine	1	27	7	Fair	Protect	Sidewalk improvement
112	<i>Acer platanoides</i>	Norway Maple	1	23	7	Good	Protect	Sidewalk improvement
113	<i>Acer platanoides</i>	Norway Maple	1	28	9	Fair	Protect	Sidewalk improvement
114	<i>Acer platanoides</i>	Norway Maple	1	23	7	Fair	Protect	Sidewalk improvement
115	<i>Acer platanoides</i>	Norway Maple	1	21	7	Fair	Protect	Sidewalk improvement
116	<i>Acer platanoides</i>	Norway Maple	1	26	7	Fair	Protect	Sidewalk improvement
117	<i>Acer platanoides</i>	Norway Maple	1	31	7	Fair		
118	<i>Acer platanoides</i>	Norway Maple	1	28	7	Fair		
119	<i>Tilia americana</i>	Basswood	1	25	6	Fair		
120	<i>Acer platanoides</i>	Norway Maple	1	22	6	Fair		
121	<i>Picea pungens</i>	Blue Spruce	1	19	6	Fair		
122	<i>Acer platanoides</i>	Norway Maple	1	24	8	Good		
123	<i>Acer platanoides</i>	Norway Maple	1	23	8.5	Good		
124	<i>Picea pungens</i>	Blue Spruce	1	20	6.5	Fair		
125	Dead Tree							
126	<i>Acer platanoides</i>	Norway Maple	1	21	6	Fair		
127	<i>Acer platanoides</i>	Norway Maple	1	27	8	Good		
128	<i>Picea pungens</i>	Blue Spruce	1	25	5	Fair		
129	<i>Acer platanoides</i>	Norway Maple	1	23	7	Good		
130	<i>Acer platanoides</i>	Norway Maple	1	23	7	Good		
131	<i>Acer x freemanii</i>	Freeman Maple	1	6	2	Good	Protect	Sidewalk improvement
132	<i>Picea pungens</i>	Blue Spruce	1	7	3	Good	Protect	Sidewalk improvement
133	<i>Picea pungens</i>	Blue Spruce	1	6	2.5	Good	Protect	Sidewalk improvement
134	<i>Picea glauca</i>	White Spruce	1	7	3	Fair	Protect	Sidewalk improvement
135	<i>Populus spp.</i>	Poplar	1	5	1.8	Fair	Protect	Sidewalk improvement
136	<i>Populus spp.</i>	Poplar	1	5	1.5	Fair	Protect	Sidewalk improvement
137	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	7	1.2	Good	Protect	Sidewalk improvement
138	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	7	1.3	Good	Protect	Sidewalk improvement
139	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	7	0.8	Fair	Protect	Sidewalk improvement
140	<i>Liriodendron tulipifera</i>	Tulip Tree	1	7	1.3	Poor	Protect	Sidewalk improvement
141	<i>Liriodendron tulipifera</i>	Tulip Tree	1	7	1.2	Poor	Protect	Sidewalk improvement
142	<i>Liriodendron tulipifera</i>	Tulip Tree	1	7	1.3	Poor	Protect	Sidewalk improvement
143	<i>Picea glauca</i>	White Spruce	1	6	3.5	Fair	Protect	Sidewalk improvement
144	<i>Picea pungens</i>	Blue Spruce	1	7	3.2	Fair	Protect	Sidewalk improvement

145	<i>Picea pungens</i>	Blue Spruce	1	7	3.5	Fair	Protect	Sidewalk improvement
146	<i>Acer x freemainii</i>	Freeman Maple	1	6	2	Fair	Protect	Sidewalk improvement
147	<i>Acer x freemainii</i>	Freeman Maple	1	6.5	2.5	Fair	Protect	Sidewalk improvement
148	<i>Acer x freemainii</i>	Freeman Maple	1	7	3	Fair	Protect	Sidewalk improvement
149	<i>Acer x freemainii</i>	Freeman Maple	1	6	2.5	Good	Protect	Sidewalk improvement
150	<i>Acer x freemainii</i>	Freeman Maple	1	7	3	Good	Protect	Sidewalk improvement
151	<i>Acer x freemainii</i>	Freeman Maple	1	6.5	2.5	Good	Protect	Sidewalk improvement
152	<i>Picea glauca</i>	White Spruce	1	6	3.5	Good	Protect	Sidewalk improvement
153	<i>Picea glauca</i>	White Spruce	1	7	3.5	Fair	Protect	Sidewalk improvement
154	<i>Picea glauca</i>	White Spruce	1	6	3.5	Fair	Protect	Sidewalk improvement
155	<i>Picea glauca</i>	White Spruce	1	8	3.5	Good	Protect	Sidewalk improvement
156	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	6	0.8	Fair	Protect	Sidewalk improvement
157	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	6	2	Fair	Protect	Sidewalk improvement
158	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	6	2	Fair	Protect	Sidewalk improvement
159	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	6	2	Fair	Protect	Sidewalk improvement
160	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	5.5	1.8	Good		
161	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	5.5	2	Good		
162	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	6	1.8	Good		
163	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	7	1	Fair		
164	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	6.5	1.2	Fair		
165	<i>Quercus robur 'Fastigiata'</i>	Pyramidal English Oak	1	6	1.1	Fair	Protect	Multi-use path construction
166	<i>Pyrus spp.</i>	Ornamental Pear Tree	1	5	1.2	Good	Remove	Multi-use path construction
167	<i>Pyrus spp.</i>	Ornamental Pear Tree	1	6	1.5	Good	Remove	Multi-use path construction
168	<i>Pyrus spp.</i>	Ornamental Pear Tree	1	5	2	Good	Remove	Multi-use path construction
169	<i>Picea glauca</i>	White Spruce	1	8	2	Fair	Protect	Multi-use path construction
170	Dead Tree							
171	<i>Picea pungens</i>	Blue Spruce	1	7	2.5	Fair	Protect	Multi-use path construction
172	<i>Catalpa speciosa</i>	Northern Catalpa	1	5	0.8	Good	Protect	Multi-use path construction
173	<i>Catalpa speciosa</i>	Northern Catalpa	1	5	0.8	Good	Protect	Multi-use path construction
174	<i>Catalpa speciosa</i>	Northern Catalpa	1		0.8	Good	Protect	Multi-use path construction
175	<i>Picea pungens</i>	Blue Spruce	1	7	2.5	Fair	Protect	Multi-use path construction
176	<i>Picea pungens</i>	Blue Spruce	1	6.5	2.3	Fair	Protect	Multi-use path construction
177	Dead Tree							
178	<i>Populus spp.</i>	Poplar	1	5	1	Fair	Protect	Multi-use path construction
179	<i>Populus spp.</i>	Poplar	1	5	1.5	Good	Protect	Multi-use path construction
180	<i>Populus spp.</i>	Poplar	1	5	1.3	Good	Protect	Multi-use path construction
181	<i>Populus spp.</i>	Poplar	1	5	1.1	Good	Protect	Multi-use path construction
182	<i>Acer x freemainii</i>	Freeman Maple	1	6	1.8	Good	Protect	Multi-use path construction
183	<i>Acer x freemainii</i>	Freeman Maple	1	6	2	Good	Protect	Multi-use path construction
184	<i>Acer x freemainii</i>	Freeman Maple	1	6	2	Good	Protect	Multi-use path construction
185	<i>Acer x freemainii</i>	Freeman Maple	1	7	2	Good	Protect	Multi-use path construction
186	<i>Acer x freemainii</i>	Freeman Maple	1	6	1.5	Good	Protect	Multi-use path construction
187	<i>Catalpa speciosa</i>	Northern Catalpa	1	6	1.8	Fair	Protect	Multi-use path construction
188	<i>Catalpa speciosa</i>	Northern Catalpa	1	7	2	Fair	Protect	Multi-use path construction
189	<i>Catalpa speciosa</i>	Northern Catalpa	1	6	2	Fair	Protect	Multi-use path construction
190	<i>Acer x freemainii</i>	Freeman Maple	1	7	2	Good	Protect	Multi-use path construction
191	<i>Acer x freemainii</i>	Freeman Maple	1	6	1.8	Good	Protect	Multi-use path construction
192	<i>Acer x freemainii</i>	Freeman Maple	1	7	1.8	Good	Protect	Multi-use path construction
193	<i>Acer platanoides</i>	Norway Maple	1	18	5	Good		
194	<i>Picea glauca</i>	White Spruce	1	16	6	Good		
195	<i>Picea glauca</i>	White Spruce	1	17	6.5	Good		
196	<i>Picea glauca</i>	White Spruce	1	16	6			
197	<i>Acer rubrum</i>	Red Maple	1	11	2.8	Poor	Protect	Sidewalk improvement
198	<i>Acer rubrum</i>	Red Maple	1	12	4	Fair	Protect	Sidewalk improvement
199	<i>Acer rubrum</i>	Red Maple	1	7	3	Good	Protect	Sidewalk improvement
200	<i>Acer rubrum</i>	Red Maple	1	9	3.5	Good	Protect	Sidewalk improvement
201	<i>Acer rubrum</i>	Red Maple	1	7.5	4	Good	Protect	Sidewalk improvement
202	<i>Picea glauca</i>	White Spruce	1	24	9	Good	Protect	Sidewalk improvement
203	<i>Picea glauca</i>	White Spruce	1	25	8.5	Good	Protect	Sidewalk improvement
204	<i>Fraxinus pennsylvanica</i>	Green Ash	1	17	5	Poor	Protect	Sidewalk improvement
205	Dead Tree							
206	<i>Picea pungens</i>	Blue Spruce	1	18	6	Fair	Protect	Sidewalk improvement
207	<i>Gleditsia triacanthos</i>	Honeylocust	1	10	6	Good	Protect	Sidewalk improvement
208	<i>Gleditsia triacanthos</i>	Honeylocust	2	10	6.5	Good	Protect	Sidewalk improvement
209	<i>Picea pungens</i>	Blue Spruce	1	16	6	Good	Protect	Sidewalk improvement
210	<i>Picea glauca</i>	White Spruce	1	17	6.5	Good	Protect	Sidewalk improvement
211	<i>Picea pungens</i>	Blue Spruce	1	27	7	Good	Remove	Sidewalk improvement
212	<i>Picea glauca</i>	White Spruce	1	21	6	Good	Remove	Sidewalk improvement
213	<i>Gleditsia triacanthos</i>	Honeylocust	1	8	6	Fair	Remove	Sidewalk improvement
214	<i>Picea glauca</i>	White Spruce	1	15	6	Poor		
215	<i>Abies balsamea</i>	Balsam Fir	1	12	4.5	Good		
216	<i>Gleditsia triacanthos</i>	Honeylocust	1	9	7.5	Good	Remove	Sidewalk improvement
217	<i>Tilia americana</i>	Basswood	1	17	6	Good	Remove	Sidewalk improvement
218	<i>Picea glauca</i>	White Spruce	1	19	7	Good	Remove	Sidewalk improvement
219	<i>Picea pungens</i>	Blue Spruce	1	12	5.5	Poor	Protect	Sidewalk improvement

220	<i>Picea glauca</i>	White Spruce	1	12	4	Fair	Protect	Multi-use path construction
221	<i>Tilia americana</i>	Basswood	1	11	1.8	Poor	Protect	Multi-use path construction
222	<i>Tilia americana</i>	Basswood	1	13	4	Fair	Protect	Multi-use path construction
223	<i>Pinus nigra</i>	Austrian Pine	1	28	7	Good	Protect	Multi-use path construction
224	<i>Pinus nigra</i>	Austrian Pine	1	19	6	Fair	Protect	Multi-use path construction
225	<i>Pinus nigra</i>	Austrian Pine	1	15	4.5	Poor	Protect	Multi-use path construction
226	<i>Tilia americana</i>	Basswood	1	13	3	Poor	Protect	Multi-use path construction
227	<i>Tilia americana</i>	Basswood	1	15	3.5	Fair	Protect	Multi-use path construction
228	<i>Picea pungens</i>	Blue Spruce	1	17	6	Good	Protect	Multi-use path construction
229	<i>Picea pungens</i>	Blue Spruce	1	14	3.5	Fair	Protect	Multi-use path construction
230	<i>Picea pungens</i>	Blue Spruce	1	17	5	Fair	Protect	Multi-use path construction
231	<i>Gleditsia triacanthos</i>	Honeylocust	1	5	6	Good	Protect	Multi-use path construction
232	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	7	Good	Protect	Multi-use path construction
233	<i>Pinus nigra</i>	Austrian Pine	1	26	8	Fair	Protect	Multi-use path construction
234	<i>Pinus nigra</i>	Austrian Pine	1	26	6	Fair	Protect	Multi-use path construction
235	<i>Gleditsia triacanthos</i>	Honeylocust	1	12	6	Good	Protect	Multi-use path construction
236	<i>Gleditsia triacanthos</i>	Honeylocust	1	11	6.5	Good	Protect	Multi-use path construction
237	<i>Pinus nigra</i>	Austrian Pine	1	20	6	Fair	Protect	Multi-use path construction
238	<i>Pinus nigra</i>	Austrian Pine	1	29	8	Fair	Protect	Multi-use path construction
239	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	10	5	Fair	Protect	Multi-use path construction
240	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	17	6	Good	Protect	Multi-use path construction
241	<i>Picea glauca</i>	White Spruce	1	19	6	Fair	Protect	Multi-use path construction
242	<i>Picea glauca</i>	White Spruce	1	15	6	Good	Protect	Multi-use path construction
243	<i>Picea pungens</i>	Blue Spruce	1	17	6	Fair	Protect	Multi-use path construction
244	Dead Tree							
245	<i>Tilia americana</i>	Basswood	1	13	2.5	Poor		
246	<i>Gleditsia triacanthos</i>	Honeylocust	1	10	6	Fair		
247	<i>Gleditsia triacanthos</i>	Honeylocust	1	12	7	Fair		
248	<i>Tilia americana</i>	Basswood	1	20	6	Good		
249	<i>Picea pungens</i>	Blue Spruce	1	16	6	Good	Protect	Sidewalk improvement
250	<i>Acer platanoides</i>	Norway Maple	1	14	6	Good	Protect	Road curb re-alignment
251	<i>Acer platanoides</i>	Norway Maple	1	12	6	Good	Protect	Road curb re-alignment
252	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	18	8	Good		
253	<i>Acer platanoides</i>	Norway Maple	1	9	5	Good		
254	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	18	8	Good		
255	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	16	8	Good		
256	<i>Picea pungens</i>	Blue Spruce	1	18	7.5	Good		
257	<i>Picea pungens</i>	Blue Spruce	1	17	6	Good		
258	<i>Gleditsia triacanthos</i>	Honeylocust	1	18	8	Good		
259	<i>Picea glauca</i>	White Spruce	1	20	6	Good		
260	<i>Gleditsia triacanthos</i>	Honeylocust	1	22	8	Good		
261	<i>Picea glauca</i>	White Spruce	1	15	6.5	Good		
262	<i>Acer platanoides</i>	Norway Maple	1	12	5	Good		
263	<i>Acer platanoides</i>	Norway Maple	1	15	5	Good		
264	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	19	7	Good		
265	<i>Gleditsia triacanthos</i>	Honeylocust	1	23	10	Good	Protect	Road curb re-alignment
266	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	22	8	Good		
267	<i>Gleditsia triacanthos</i>	Honeylocust	1	21	8	Fair		
268	<i>Picea pungens</i>	Blue Spruce	1	27	7	Good		
269	<i>Gleditsia triacanthos</i>	Honeylocust	1	21	8	Fair	Protect	Road curb re-alignment
270	<i>Picea pungens</i>	Blue Spruce	1	24	6	Fair		
271	<i>Picea pungens</i>	Blue Spruce	1	22	6	Fair		
272	<i>Gleditsia triacanthos</i>	Honeylocust	1	23	10	Good	Protect	Road curb re-alignment
273	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	18	6.5	Good		
274	<i>Picea pungens</i>	Blue Spruce	1	25	9	Good		
275	<i>Picea pungens</i>	Blue Spruce	1	15	4	Poor		
276	<i>Tilia americana</i>	Basswood	1	20	7	Good		
277	<i>Tilia americana</i>	Basswood	1	10	5.5	Fair		
278	<i>Gleditsia triacanthos</i>	Honeylocust	1	23	8	Good	Protect	Road curb re-alignment
279	<i>Picea glauca</i>	White Spruce	1	18	6	Good		
280	<i>Gleditsia triacanthos</i>	Honeylocust	1	17	8	Good	Protect	Road curb re-alignment
281	<i>Picea glauca</i>	White Spruce	1	17	6	Good		
282	<i>Picea pungens</i>	Blue Spruce	1	15	5.5	Fair		
283	Dead Tree							
284	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	7	Good	Protect	Road curb re-alignment
285	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	6	Good	Protect	Road curb re-alignment
286	<i>Tilia americana</i>	Basswood	1	19	8	Good		
287	<i>Gleditsia triacanthos</i>	Honeylocust	1	16	8	Good	Protect	Road curb re-alignment
288	<i>Tilia americana</i>	Basswood	1	17	6	Good		
289	<i>Tilia americana</i>	Basswood	1	15	6	Good		
290	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	6	Good	Protect	Road curb re-alignment
291	<i>Gleditsia triacanthos</i>	Honeylocust	1	10	6	Good	Protect	Road curb re-alignment
292	<i>Gleditsia triacanthos</i>	Honeylocust	1	23	8	Good	Protect	Road curb re-alignment
293	<i>Gleditsia triacanthos</i>	Honeylocust	1	21	8	Fair	Protect	Sidewalk improvement
294	<i>Gleditsia triacanthos</i>	Honeylocust	1	19	6	Fair	Protect	Sidewalk improvement

295	<i>Picea glauca</i>	White Spruce	1	41	8	Good	Protect	Sidewalk improvement
296	<i>Acer platanoides</i>	Norway Maple	1	34	10	Good	Protect	Sidewalk improvement
297	<i>Acer platanoides</i>	Norway Maple	1	24	8	Fair	Protect	Sidewalk improvement
298	<i>Gleditsia triacanthos</i>	Honeylocust	1	16	7	Good	Protect	Sidewalk improvement
299	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	7	Good	Protect	Sidewalk improvement
300	<i>Gleditsia triacanthos</i>	Honeylocust	1	16	7	Good	Protect	Sidewalk improvement
301	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	7	Good		
302	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	8	Good		
303	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	8	Good		
304	<i>Gleditsia triacanthos</i>	Honeylocust	1	14	8	Good		
305	<i>Gleditsia triacanthos</i>	Honeylocust	1	18	8	Good		
306	<i>Gleditsia triacanthos</i>	Honeylocust	1	23	8	Good		
307	<i>Tilia americana</i>	Basswood	1	35	10	Good		
308	<i>Tilia americana</i>	Basswood	1	26	8	Good		
309	<i>Picea glauca</i>	White Spruce	1	18	6	Fair		
310	<i>Picea glauca</i>	White Spruce	1	19	6.5	Fair		
311	<i>Picea glauca</i>	White Spruce	1	19	7	Fair		
312	<i>Acer platanoides</i>	Norway Maple	1	25	8	Good		
313	<i>Acer platanoides</i>	Norway Maple	1	32,15,22	10	Good		
314	<i>Acer platanoides</i>	Norway Maple	1	42	12	Good		
315	<i>Acer platanoides</i>	Norway Maple	1	25	8	Fair		
316	<i>Picea glauca</i>	White Spruce	1	25	8	Fair		
317	<i>Picea glauca</i>	White Spruce	1	19	6	Fair		
318	<i>Picea glauca</i>	White Spruce	1	31	8	Fair		
319	<i>Acer platanoides</i>	Norway Maple	1	26	10	Good		
320	<i>Acer platanoides</i>	Norway Maple	1	31	9	Good		
321	<i>Acer platanoides</i>	Norway Maple	1	18	7	Good	Protect	Sidewalk improvement
322	Dead Tree							
323	Dead Tree							
324	<i>Acer platanoides</i>	Norway Maple	1	29	7	Good	Protect	Sidewalk improvement
325	<i>Gleditsia triacanthos</i>	Honeylocust	1	20	6	Good	Protect	Sidewalk improvement
326	<i>Gleditsia triacanthos</i>	Honeylocust	1	16	7	Fair	Protect	Sidewalk improvement
327	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	7	Fair	Protect	Sidewalk improvement
328	<i>Gleditsia triacanthos</i>	Honeylocust	1	16	7	Good	Protect	Sidewalk improvement
329	<i>Gleditsia triacanthos</i>	Honeylocust	1	21	8	Good	Protect	Sidewalk improvement
330	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	7	Good	Protect	Sidewalk improvement
331	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	8	Good	Protect	Sidewalk improvement
332	<i>Pinus nigra</i>	Austrian Pine	1	40	10	Fair	Protect	Sidewalk improvement
333	<i>Pinus nigra</i>	Austrian Pine	1	33	8	Fair	Protect	Sidewalk improvement
334	<i>Pinus nigra</i>	Austrian Pine	1	31	7	Fair	Protect	Sidewalk improvement
335	<i>Pinus nigra</i>	Austrian Pine	1	29	6	Fair	Protect	Sidewalk improvement
336	<i>Pinus nigra</i>	Austrian Pine	1	30	7	Fair	Protect	Sidewalk improvement
337	<i>Pinus nigra</i>	Austrian Pine	1	30	7.5	Fair	Protect	Sidewalk improvement
338	<i>Acer platanoides</i>	Norway Maple	1	19	6	Good	Protect	Sidewalk improvement
339	<i>Acer platanoides</i>	Norway Maple	1	20	7	Good	Protect	Sidewalk improvement
340	<i>Acer platanoides</i>	Norway Maple	1	22	6	Good	Protect	Sidewalk improvement
341	<i>Acer platanoides</i>	Norway Maple	1	22	8	Good	Protect	Sidewalk improvement
342	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	21	8	Fair	Protect	Sidewalk improvement
343	<i>Acer platanoides</i>	Norway Maple	1	21	7	Good	Protect	Sidewalk improvement
344	<i>Pinus nigra</i>	Austrian Pine	1	36	8	Fair	Protect	Sidewalk improvement
345	<i>Gleditsia triacanthos</i>	Honeylocust	1	16	6	Good	Protect	Sidewalk improvement
346	<i>Gleditsia triacanthos</i>	Honeylocust	1	12	6	Good	Protect	Sidewalk improvement
347	<i>Pinus nigra</i>	Austrian Pine	1	29	8	Fair	Protect	Sidewalk improvement
348	<i>Pinus nigra</i>	Austrian Pine	1	33	8	Fair	Protect	Sidewalk improvement
349	<i>Acer platanoides</i>	Norway Maple	1	19	7	Good		
350	<i>Pinus nigra</i>	Austrian Pine	1	36	8	Fair		
351	<i>Pinus nigra</i>	Austrian Pine	1	39	10	Fair		
352	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	39	9	Good	Protect	Sidewalk improvement
353	<i>Gleditsia triacanthos</i>	Honeylocust	1	19	8	Good	Protect	Sidewalk improvement
354	<i>Pinus nigra</i>	Austrian Pine	1	33	7	Fair	Remove	Sidewalk improvement
355	<i>Pinus nigra</i>	Austrian Pine	1	14	6	Fair	Remove	Sidewalk improvement
356	<i>Pinus nigra</i>	Austrian Pine	1	28	7	Fair	Protect	Sidewalk improvement
357	<i>Pinus nigra</i>	Austrian Pine	1	32	8	Fair		
358	<i>Picea pungens</i>	Blue Spruce	1	18	5	Fair		
359	<i>Gleditsia triacanthos</i>	Honeylocust	1	18	8	Good	Protect	Sidewalk improvement
360	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	18	9	Good	Remove	Sidewalk improvement
361	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	22	8	Good	Remove	Sidewalk improvement
362	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	16	5	Good	Protect	Sidewalk improvement
363	<i>Syringa reticulata</i>	Japanese Tree Lilac	1	14	5	Good	Protect	Sidewalk improvement
364	<i>Acer platanoides</i>	Norway Maple	1	24	8	Good	Remove	Sidewalk improvement
365	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	19	6	Good	Remove	Sidewalk improvement
366	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	18	6	Good	Remove	Sidewalk improvement
367	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	8	Good	Protect	Sidewalk improvement
368	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	6	Good	Protect	Sidewalk improvement
369	<i>Picea glauca</i>	White Spruce	1	20	5.5	Good	Protect	Sidewalk improvement
370	<i>Picea glauca</i>	White Spruce	1	19	5	Good	Protect	Sidewalk improvement

371	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	6	Good		
372	<i>Gleditsia triacanthos</i>	Honeylocust	1	22	8	Good		
373	<i>Tilia americana</i>	Basswood	1	22	9	Good		
374	<i>Tilia americana</i>	Basswood	1	27	8	Good		
375	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	7	Good	Protect	Road curb re-alignment
376	<i>Tilia americana</i>	Basswood	1	29	7	Good		
377	<i>Gleditsia triacanthos</i>	Honeylocust	1	19	7	Good	Protect	Road curb re-alignment
378	<i>Gleditsia triacanthos</i>	Honeylocust	1	12	6	Good	Protect	Road curb re-alignment
379	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	6	Good	Protect	Road curb re-alignment
380	<i>Gleditsia triacanthos</i>	Honeylocust	1	12	6	Good	Protect	Road curb re-alignment
381	<i>Gleditsia triacanthos</i>	Honeylocust	1	11	6	Good	Protect	Road curb re-alignment
382	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	6	Good	Protect	Road curb re-alignment
383	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	6	Good	Protect	Road curb re-alignment
384	<i>Gleditsia triacanthos</i>	Honeylocust	1	12	6.5	Good	Protect	Road curb re-alignment
385	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	6	Good	Protect	Road curb re-alignment
386	<i>Tilia americana</i>	Basswood	1	20	5	Fair		
387	<i>Tilia americana</i>	Basswood	1	21	6	Fair		
388	<i>Pinus nigra</i>	Austrian Pine	1	18	5	Good		
389	<i>Picea glauca</i>	White Spruce	1	17	5	Good	Protect	Sidewalk improvement
390	<i>Pinus nigra</i>	Austrian Pine	1	15	6	Good	Protect	Sidewalk improvement
391	<i>Tilia americana</i>	Basswood	1	19	6	Good		
392	<i>Gleditsia triacanthos</i>	Honeylocust	1	19	7	Good		
393	<i>Gleditsia triacanthos</i>	Honeylocust	1	16	6	Fair		
394	<i>Pinus nigra</i>	Austrian Pine	1	29	9	Good	Protect	Sidewalk improvement
395	<i>Pinus nigra</i>	Austrian Pine	1	29	8	Good	Protect	Sidewalk improvement
396	<i>Gleditsia triacanthos</i>	Honeylocust	1	15	7	Good	Protect	Sidewalk improvement
397	<i>Tilia americana</i>	Basswood	1	18	6	Good		
398	<i>Gleditsia triacanthos</i>	Honeylocust	1	13	6	Fair		
399	<i>Gleditsia triacanthos</i>	Honeylocust	1	12	7	Good		
400	<i>Pinus nigra</i>	Austrian Pine	1	28	8	Good	Protect	Sidewalk improvement
401	<i>Gleditsia triacanthos</i>	Honeylocust	1	20	7	Good	Protect	Sidewalk improvement
402	<i>Pinus nigra</i>	Austrian Pine	1	27	8	Good	Protect	Sidewalk improvement
403	<i>Gleditsia triacanthos</i>	Honeylocust	1	22	7	Good	Protect	Sidewalk improvement
404	<i>Picea pungens</i>	Blue Spruce	1	23	8	Good	Protect	Sidewalk improvement
405	<i>Picea pungens</i>	Blue Spruce	1	22	8	Good	Protect	Sidewalk improvement
406	<i>Tilia americana</i>	Basswood	1	22	7	Good	Protect	Sidewalk improvement
407	<i>Tilia americana</i>	Basswood	1	27	5	Good	Protect	Sidewalk improvement
408	<i>Malus spp.</i>	Crabapple	1	13	6	Fair	Protect	Sidewalk improvement
409	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	21	6	Good	Protect	Sidewalk improvement
410	<i>Malus spp.</i>	Crabapple	1	19	6	Good	Protect	Sidewalk improvement
411	Dead Tree							
412	<i>Malus spp.</i>	Crabapple	1	19	6	Good	Protect	Sidewalk improvement
413	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	21	6	Good	Protect	Sidewalk improvement
414	<i>Acer platanoides 'Crimson King'</i>	Crimson King Norway Maple	1	12	3	Fair	Remove	Multi-use path construction
415	<i>Acer platanoides</i>	Norway Maple	1	12	5	Fair	Protect	Multi-use path construction
416	<i>Acer platanoides</i>	Norway Maple	1	13	5	Fair	Protect	Multi-use path construction
417	<i>Acer platanoides</i>	Norway Maple	1	12	6	Fair	Protect	Multi-use path construction
418	<i>Picea pungens</i>	Blue Spruce	1	13	5.5	Fair		
419	<i>Picea pungens</i>	Blue Spruce	1	14	6	Fair		
420	<i>Picea pungens</i>	Blue Spruce	1	17	5	Fair		
421	<i>Picea pungens</i>	Blue Spruce	1	13	5.5	Fair	Protect	Multi-use path construction
422	<i>Picea glauca</i>	White Spruce	1	15	6	Fair	Protect	Multi-use path construction
423	Dead Tree							
424	<i>Acer platanoides</i>	Norway Maple	1	14	5.5	Fair	Protect	Multi-use path construction
425	<i>Acer platanoides</i>	Norway Maple	1	16	6	Good	Protect	Multi-use path construction
426	<i>Pinus nigra</i>	Austrian Pine	1	23	6	Fair	Protect	Multi-use path construction
427	<i>Pinus nigra</i>	Austrian Pine	1	27	7	Fair	Protect	Multi-use path construction
428	<i>Acer platanoides</i>	Norway Maple	1	19	6	Good	Protect	Multi-use path construction
429	<i>Acer platanoides</i>	Norway Maple	1	21	6	Good	Protect	Multi-use path construction
430	<i>Picea glauca</i>	White Spruce	1	18	4	Fair	Protect	Multi-use path construction
431	Dead Tree							
G1	<i>Picea pungens</i>	Blue Spruce	5	8 - 12	2 - 3	Poor to Fair		
G2	<i>Picea spp.</i>	Spruce Tree	17	8 - 10	2 - 3.5	Poor to Fair	Protect	Multi-use path construction
G3	<i>Picea spp.</i>	Spruce Tree	43	7 - 11	2.5 - 4	Poor to Fair	Protect	Multi-use path construction
G4	<i>Pinus nigra</i>	Austrian Pine	3	27 - 29	7 - 8	Fair	Protect	Sidewalk improvement
G5	<i>Picea spp.</i>	Spruce Tree	35	11 - 16	3 - 5	Dead to Fair		

